

Heat pumps eligible for high-efficiency heat pump and caulking work measure.

Start date: May 1st, 2025

To find a model, you can use CTRL+F

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216980816	1HVAC	ACIQ-60-HPD	ACIQ-60-ACL-B		36,000	\$5,040
216032303	1HVAC	ACIQ-36Z-HH-M5C	Combination heat pumps with or without ducts		31,400	\$4,396
216032301	1HVAC	ACIQ-36Z-HH-M5C	Heat pump without ducts		30,000	\$4,200
210857296	1HVAC	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MC		10,000	\$1,400
210857311	1HVAC	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MC		10,200	\$1,428
207825513	1HVAC	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MB		10,000	\$1,400
207825514	1HVAC	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MB		15,000	\$2,100
210857297	1HVAC	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MC		15,000	\$2,100
210857298	1HVAC	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MC		21,200	\$2,968
207825568	1HVAC	ACIQ-27Z-HH-M3B	Heat pump with ducts		27,000	\$3,780
210857363	1HVAC	ACIQ-55Z-HH-M5B	Heat pump with ducts		35,200	\$4,928
210857309	1HVAC	ACIQ-12ZPL-HP230B	SCC-1218-HH-M		9,500	\$1,330
210857310	1HVAC	ACIQ-18ZPL-HP230B	SCC-1218-HH-M		14,500	\$2,030
208106638	1HVAC	ACIQ-24-HPB	ACIQ-24-AHB		19,200	\$2,688
210857355	1HVAC	ACIQ-24ZPL-HP230B	ACIQ-24AHB-HH-M		16,900	\$2,366
210857354	1HVAC	ACIQ-18ZPL-HP230B	ACIQ-18AHB-HH-M		15,400	\$2,156
207825517	1HVAC	ACIQ-12ZPL-HP230B	ACIQ-12CC-HH-MB		9,900	\$1,386
207825523	1HVAC	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MB		9,600	\$1,344
207825521	1HVAC	ACIQ-18ZPL-HP230B	ACIQ-18CD-HH-MB		15,000	\$2,100
207825569	1HVAC	ACIQ-27Z-HH-M3B	Combination heat pumps with or without ducts		26,800	\$3,752
210857364	1HVAC	ACIQ-55Z-HH-M5B	Combination heat pumps with or without ducts		34,800	\$4,872
207825515	1HVAC	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MB		21,200	\$2,968
210857362	1HVAC	ACIQ-55Z-HH-M5B	Heat pump without ducts		34,400	\$4,816
207825564	1HVAC	ACIQ-18Z-HH-M2B	Heat pump without ducts		15,000	\$2,100
207825573	1HVAC	ACIQ-48Z-HH-M5B	Heat pump without ducts		36,000	\$5,040
207825567	1HVAC	ACIQ-27Z-HH-M3B	Heat pump without ducts		26,600	\$3,724
208106639	1HVAC	ACIQ-36-HPB	ACIQ-36-AHB		30,400	\$4,256
213492117	1HVAC	ACIQ-36-HPC	ACIQ-36-AHB		30,400	\$4,256
214810545	1HVAC	ACIQ-18-HPB	ACIQ-18-AHB		13,500	\$1,890

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207825520	1HVAC	ACIQ-12ZPL-HP230B	ACIQ-12CD-HH-MB		10,600	\$1,484
207825525	1HVAC	ACIQ-24ZPL-HP230B	ACIQ-24FM-HH-MB		19,000	\$2,660
207825574	1HVAC	ACIQ-48Z-HH-M5B	Heat pump with ducts		36,000	\$5,040
207825575	1HVAC	ACIQ-48Z-HH-M5B	Combination heat pumps with or without ducts		36,000	\$5,040
207825566	1HVAC	ACIQ-18Z-HH-M2B	Combination heat pumps with or without ducts		15,500	\$2,170
207825570	1HVAC	ACIQ-36Z-HH-M4B	Heat pump without ducts		33,000	\$4,620
207825565	1HVAC	ACIQ-18Z-HH-M2B	Heat pump with ducts		16,000	\$2,240
207825572	1HVAC	ACIQ-36Z-HH-M4B	Combination heat pumps with or without ducts		34,000	\$4,760
207825522	1HVAC	ACIQ-24ZPL-HP230B	ACIQ-24CD-HH-MB		21,000	\$2,940
215570366	1HVAC	ACIQ-30-HPB	ACIQ-30-AHB		21,000	\$2,940
212394312	1HVAC	ACIQ-24-HPB	ACIQ-24-ACL		21,000	\$2,940
216980821	1HVAC	ACIQ-18-HPD	ACIQ-18W-WMB		15,300	\$2,142
216980856	1HVAC	EZ-60-HPB	EZ-60-AHB		45,000	\$6,300
216980851	1HVAC	EZ-48-EHPB	EZ-48-AHB		32,400	\$4,536
216980855	1HVAC	EZ-48-HPB	EZ-48-AHB		37,000	\$5,180
216980854	1HVAC	EZ-36-HPB	EZ-36-AHB		31,800	\$4,452
216980849	1HVAC	EZ-24-EHPB	EZ-24-AHB		20,000	\$2,800
216980853	1HVAC	EZ-24-HPB	EZ-24-AHB		20,000	\$2,800
216980814	1HVAC	ACIQ-48-HPD	ACIQ-48-ACL-B		34,400	\$4,816
216980804	1HVAC	ACIQ-36-EHPD	ACIQ-36-ACL-B		24,200	\$3,388
216980803	1HVAC	ACIQ-36-EHPD	ACIQ-36-ACL-17-B		24,200	\$3,388
216980815	1HVAC	ACIQ-60-HPD	ACIQ-48-ACL-B		37,800	\$5,292
216980828	1HVAC	ACIQ-36-EHPD	ACIQ-36W-PB		24,600	\$3,444
216980811	1HVAC	ACIQ-30-HPD	ACIQ-36-ACL-B		25,000	\$3,500
216980810	1HVAC	ACIQ-30-HPD	ACIQ-36-ACL-17-B		25,000	\$3,500
216980813	1HVAC	ACIQ-36-HPD	ACIQ-36-ACL-B		29,200	\$4,088
216980812	1HVAC	ACIQ-36-HPD	ACIQ-36-ACL-17-B		29,200	\$4,088
216980800	1HVAC	ACIQ-24-EHPD	ACIQ-24-ACL-B		19,700	\$2,758
216980799	1HVAC	ACIQ-24-EHPD	ACIQ-24-ACL-14-B		19,700	\$2,758
216980808	1HVAC	ACIQ-24-HPD	ACIQ-24-ACL-B		19,700	\$2,758
216980807	1HVAC	ACIQ-24-HPD	ACIQ-24-ACL-14-B		19,700	\$2,758
216980806	1HVAC	ACIQ-18-HPD	ACIQ-24-ACL-B		15,200	\$2,128
216980805	1HVAC	ACIQ-18-HPD	ACIQ-24-ACL-14-B		15,200	\$2,128
216980832	1HVAC	ACIQ-36-HPD	ACIQ-36W-PB		31,200	\$4,368
216980831	1HVAC	ACIQ-30-HPD	ACIQ-30W-PB		24,000	\$3,360

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216980829	1HVAC	ACIQ-18-HPD	ACIQ-18W-PB		15,000	\$2,100
216980824	1HVAC	ACIQ-36-HPD	ACIQ-36W-WMB		30,200	\$4,228
216980823	1HVAC	ACIQ-30-HPD	ACIQ-30W-WMB		23,200	\$3,248
216980820	1HVAC	ACIQ-36-EHPD	ACIQ-36W-WMB		24,800	\$3,472
216032270	1HVAC	ACIQ-18ZPL-HP230C	ACIQ-18W-HH-MD		16,600	\$2,324
216032227	1HVAC	ACIQ-18-HPD	ACIQ-18-AHD		15,000	\$2,100
216032286	1HVAC	ACIQ-12ZPL-HP230C	ACIQ-12FM-HH-MD		9,800	\$1,372
216032269	1HVAC	ACIQ-12ZPL-HP230C	ACIQ-12W-HH-MD		9,800	\$1,372
216032228	1HVAC	ACIQ-24-HPD	ACIQ-24-AHD		20,000	\$2,800
216032230	1HVAC	ACIQ-36-HPD	ACIQ-36-AHD		31,800	\$4,452
216032225	1HVAC	ACIQ-48-EHPD	ACIQ-48-AHD		32,400	\$4,536
216032222	1HVAC	ACIQ-24-EHPD	ACIQ-24-AHD		20,000	\$2,800
216032229	1HVAC	ACIQ-30-HPD	ACIQ-30-AHD		23,800	\$3,332
216032233	1HVAC	ACIQ-60-HPD	ACIQ-60-AHD		45,000	\$6,300
216032232	1HVAC	ACIQ-48-HPD	ACIQ-48-AHD		37,000	\$5,180
216032231	1HVAC	ACIQ-42-HPD	ACIQ-42-AHD		37,000	\$5,180
216032234	1HVAC	ACIQ-18-HPD	ACIQ-18-PAH		14,700	\$2,058
216032237	1HVAC	ACIQ-36-HPD	ACIQ-36-PAH		31,000	\$4,340
216032238	1HVAC	ACIQ-48-HPD	ACIQ-48-PAH		34,000	\$4,760
216032236	1HVAC	ACIQ-30-HPD	ACIQ-30-PAH		24,000	\$3,360
216032235	1HVAC	ACIQ-24-HPD	ACIQ-24-PAH		19,000	\$2,660
216032239	1HVAC	ACIQ-60-HPD	ACIQ-60-PAH		35,000	\$4,900
216032271	1HVAC	ACIQ-24ZPL-HP230C	ACIQ-24W-HH-MD		21,000	\$2,940
216032273	1HVAC	ACIQ-12ZPL-HP230C	ACIQ-12CC-HH-MC		10,000	\$1,400
216032274	1HVAC	ACIQ-18ZPL-HP230C	ACIQ-18CC-HH-MC		14,900	\$2,086
216032275	1HVAC	ACIQ-24ZPL-HP230C	ACIQ-24CC-HH-MC		20,400	\$2,856
216032276	1HVAC	ACIQ-36ZPL-HP230C	ACIQ-36CC-HH-MC		30,600	\$4,284
216032277	1HVAC	ACIQ-48ZPL-HP230C	ACIQ-48CC-HH-MC		45,000	\$6,300
216032279	1HVAC	ACIQ-12ZPL-HP230C	ACIQ-12CD-HH-MC		10,200	\$1,428
216032280	1HVAC	ACIQ-18ZPL-HP230C	ACIQ-18CD-HH-MC		15,000	\$2,100
216032281	1HVAC	ACIQ-24ZPL-HP230C	ACIQ-24CD-HH-MC		21,600	\$3,024
216032282	1HVAC	ACIQ-36ZPL-HP230C	ACIQ-36CD-HH-MC		31,600	\$4,424
216032283	1HVAC	ACIQ-48ZPL-HP230C	ACIQ-48CD-HH-MC		45,000	\$6,300
216032284	1HVAC	ACIQ-60ZPL-HP230C	ACIQ-60CD-HH-MC		45,000	\$6,300
216032287	1HVAC	ACIQ-18ZPL-HP230C	ACIQ-18FM-HH-MD		14,400	\$2,016
216032288	1HVAC	ACIQ-24ZPL-HP230C	ACIQ-24FM-HH-MD		20,200	\$2,828
216032289	1HVAC	ACIQ-36ZPL-HP230C	ACIQ-36FM-HH-MD		30,200	\$4,228
216032290	1HVAC	ACIQ-48ZPL-HP230C	ACIQ-48FM-HH-MD		38,500	\$5,390

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216032291	1HVAC	ACIQ-60ZPL-HP230C	ACIQ-60FM-HH-MD		41,000	\$5,740
216032294	1HVAC	ACIQ-18ZPL-HP230C	SCC-1218-HH-MB		14,500	\$2,030
216032295	1HVAC	ACIQ-18Z-HH-M3C	Heat pump without ducts		17,600	\$2,464
216032296	1HVAC	ACIQ-18Z-HH-M3C	Heat pump with ducts		17,000	\$2,380
216032297	1HVAC	ACIQ-18Z-HH-M3C	Combination heat pumps with or without ducts		17,300	\$2,422
216032298	1HVAC	ACIQ-27Z-HH-M4C	Heat pump without ducts		25,000	\$3,500
216032299	1HVAC	ACIQ-27Z-HH-M4C	Heat pump with ducts		23,000	\$3,220
216032300	1HVAC	ACIQ-27Z-HH-M4C	Combination heat pumps with or without ducts		24,000	\$3,360
216032302	1HVAC	ACIQ-36Z-HH-M5C	Heat pump with ducts		33,000	\$4,620
216032304	1HVAC	ACIQ-48Z-HH-M6C	Heat pump without ducts		44,000	\$6,160
216032305	1HVAC	ACIQ-48Z-HH-M6C	Heat pump with ducts		44,500	\$6,230
216032306	1HVAC	ACIQ-48Z-HH-M6C	Combination heat pumps with or without ducts		44,000	\$6,160
216032307	1HVAC	ACIQ-55Z-HH-M6C	Heat pump without ducts		44,000	\$6,160
216032308	1HVAC	ACIQ-55Z-HH-M6C	Heat pump with ducts		45,000	\$6,300
216032309	1HVAC	ACIQ-55Z-HH-M6C	Combination heat pumps with or without ducts		44,500	\$6,230
216032320	1HVAC	ES-48Z-M6C	Heat pump with ducts		37,000	\$5,180
212394314	1HVAC	ACIQ-36-HPB	ACIQ-36-ACL		33,000	\$4,620
213492126	1HVAC	ACIQ-30-HPB	ACIQ-36-ACL-17		19,600	\$2,744
210857302	1HVAC	ACIQ-48ZPL-HP230B	ACIQ-48CD-HH-MB		39,500	\$5,530
210857300	1HVAC	ACIQ-48ZPL-HP230B	ACIQ-48CC-HH-MB		35,000	\$4,900
210857305	1HVAC	ACIQ-48ZPL-HP230B	ACIQ-48FM-HH-MB		35,000	\$4,900
210857299	1HVAC	ACIQ-36ZPL-HP230B	ACIQ-36CC-HH-MB		33,000	\$4,620
206315658	1HVAC	ACIQ-27Z-HH-M3	Heat pump without ducts		18,000	\$2,520
214810546	1HVAC	EZ-24-HP	EZ-24-AH		19,200	\$2,688
214810547	1HVAC	EZ-48-HP	EZ-48-AH		36,000	\$5,040
214810548	1HVAC	EZ-60-HP	EZ-60-AH		42,000	\$5,880
213492127	1HVAC	ACIQ-36-HPB	ACIQ-36-ACL-17		27,400	\$3,836
210857303	1HVAC	ACIQ-60ZPL-HP230B	ACIQ-60CD-HH-MB		40,000	\$5,600
213492120	1HVAC	ACIQ-36-HPC	ACIQ-36-ACL		27,000	\$3,780
213492118	1HVAC	ACIQ-36-HPC	ACIQ-36-ACL-17		27,000	\$3,780
213500936	1HVAC	ACIQ-36-HPC	ACIQ-36-AHB*		31,800	\$4,452
213492124	1HVAC	ACIQ-30-HPB	ACIQ-36-ACL		22,600	\$3,164
213433236	1HVAC	ACIQ-36-HPB	ACIQ-36W-P		32,800	\$4,592
213433234	1HVAC	ACIQ-24-HPB	ACIQ-24W-P		19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213433233	1HVAC	ACIQ-18-HPB	ACIQ-18W-P		13,500	\$1,890
213433235	1HVAC	ACIQ-30-HPB	ACIQ-30W-P		20,000	\$2,800
213433229	1HVAC	ACIQ-18-HPB	ACIQ-18W-WM		15,800	\$2,212
213433230	1HVAC	ACIQ-24-HPB	ACIQ-24W-WM		20,000	\$2,800
213433224	1HVAC	ACIQ-60HPB	ACIQ-60-ACL		37,000	\$5,180
207825571	1HVAC	ACIQ-36Z-HH-M4B	Heat pump with ducts		23,000	\$3,220
206315646	1HVAC	ACIQ-24-HP	ACIQ-24-AH		16,500	\$2,310
210857304	1HVAC	ACIQ-36ZPL-HP230B	ACIQ-36FM-HH-MB		32,000	\$4,480
210472740	1HVAC	HVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
210472741	1HVAC	HVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
210472793	1HVAC	HVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
210472794	1HVAC	HVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210472806	1HVAC	HVH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210473097	1HVAC	HVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
210473108	1HVAC	HVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210473240	1HVAC	HVH825GKA3*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210470120	1HVAC	HVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
210470121	1HVAC	HVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	31,800	\$4,452
206315660	1HVAC	ACIQ-48Z-HH-M5	Heat pump without ducts		30,000	\$4,200
210470125	1HVAC	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
210470131	1HVAC	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
210470190	1HVAC	HVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
210470191	1HVAC	HVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	31,600	\$4,424
210470195	1HVAC	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
210470196	1HVAC	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
210470201	1HVAC	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
210470203	1HVAC	HVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
210470204	1HVAC	HVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
210470208	1HVAC	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0701716A*	31,600	\$4,424
210470209	1HVAC	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
210470215	1HVAC	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	31,400	\$4,396
210470218	1HVAC	HVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
210470219	1HVAC	HVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
210470221	1HVAC	HVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
210470222	1HVAC	HVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	31,400	\$4,396
210470234	1HVAC	HVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	31,000	\$4,340
210470267	1HVAC	HVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	31,000	\$4,340
210470278	1HVAC	HVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL1352422A*	31,000	\$4,340

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210470377	1HVAC	HVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470388	1HVAC	HVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470432	1HVAC	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0701716A*	31,400	\$4,396
210470443	1HVAC	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470498	1HVAC	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0901716A*	31,200	\$4,368
210470520	1HVAC	HVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470531	1HVAC	HVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470553	1HVAC	HVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470564	1HVAC	HVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL1352422A*	31,200	\$4,368
210469930	1HVAC	HVH848GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	36,000	\$5,040
210469933	1HVAC	HVH848GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	36,000	\$5,040
210469936	1HVAC	HVH848GKA2*	EA*4X60L24A*+WALLCON	*97CMN1002122A*	36,000	\$5,040
210469937	1HVAC	HVH848GKA2*	EA*4X60L24A*+WALLCON	*96CTN1002122A*	36,000	\$5,040
210469983	1HVAC	HVH848GKA2*	EN(A,D)4X48L24**+WALLCON	*96CTN1202422A*	37,200	\$5,208
210470026	1HVAC	HVH848GKA2*	EHD4X48AAL+WALLCON	*80CSU0802120A*	37,200	\$5,208
210470027	1HVAC	HVH848GKA2*	EHD4X48AAL+WALLCON	*80CTL1352422A*	37,200	\$5,208
212394313	1HVAC	ACIQ-30-HPB	ACIQ-30-ACL		22,600	\$3,164
210857353	1HVAC	ACIQ-60HPB	ACIQ-60AHB		42,000	\$5,880
208106640	1HVAC	ACIQ-48-HPB	ACIQ-48-AHB		36,000	\$5,040
210857306	1HVAC	ACIQ-60ZPL-HP230B	ACIQ-60FM-HH-MB		40,000	\$5,600
217127818	AC PRO	SPHP-X-I060B	AIRH-XB-060C1B		45,000	\$6,300
217127809	AC PRO	SPHP-X-I060B	AIRH-XB-048C1B		39,500	\$5,530
217127808	AC PRO	SPHP-X-I036B	AIRH-XB-036C1B		28,200	\$3,948
217127807	AC PRO	SPHP-X-I036B	AIRH-XB-024C1B		20,600	\$2,884
216497951	AC PRO	MHPC-H-048BMB	Heat pump with ducts		37,000	\$5,180
216497957	AC PRO	SPHP-Y-V024BB	AIRH-Y-V02408CB		20,000	\$2,800
216497960	AC PRO	SPHP-Y-V048BB	AIRH-Y-V04816CB		32,400	\$4,536
216497962	AC PRO	SPHP-Z-V018BB	AIRH-Z-V018V06C		14,700	\$2,058
216497964	AC PRO	SPHP-Z-V030BB	AIRH-Z-V030V10C		24,000	\$3,360
216497963	AC PRO	SPHP-Z-V024BB	AIRH-Z-V024V08C		19,000	\$2,660
216497967	AC PRO	SPHP-Z-V060BB	AIRH-Z-V060V18C		35,000	\$4,900
216497966	AC PRO	SPHP-Z-V048BB	AIRH-Z-V048V16C		34,000	\$4,760
216497965	AC PRO	SPHP-Z-V036BB	AIRH-Z-V036V12C		24,600	\$3,444
207827152	AC PRO.COM	AOX330-12HFN1-MW5W	ACCA3U-12HRFN1-M		9,900	\$1,386
207827158	AC PRO.COM	AOX330-12HFN1-MW5W	AFAU-12HRFN1-M(C)		9,600	\$1,344
207827156	AC PRO.COM	AOX430-17HFN1-MT0W	ATIU-18HWFN1-M		15,000	\$2,100
207827155	AC PRO.COM	AOX330-12HFN1-MW5W	ATIU-12HWFN1-M		10,600	\$1,484

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213867387	AC PRO.COM	AOE30U-48HFN1-MP0(GA)	AUE-48HRFN1-M(C)		29,000	\$4,060
213386505	AC PRO.COM	AOE31U-36HFN1-M	AVBL-36HWFN1-MK3		32,800	\$4,592
213386503	AC PRO.COM	AOD30-24HFN1-MW	AVBL-24HWFN1-MI3		19,200	\$2,688
213386502	AC PRO.COM	AOX430U-18HFN1-M	AVBL-18HWFN1-MH3		13,500	\$1,890
213386504	AC PRO.COM	AOD30U-30HFN1-MR0(X)	AVBL-30HWFN1-MJ3		20,000	\$2,800
201863353	ACD	OCD24KCH20S-O	OCD24KCH20S-I		14,300	\$2,002
206428584	ACD	MUD18KCH23S-O	Heat pump without ducts		17,000	\$2,380
207497901	ACD	FXD-ACD36	AH224		16,000	\$2,240
202132789	ACD	UHD24KCH22S-O	UHD24KCH22S-I		15,500	\$2,170
206428585	ACD	MUD24KCH23S-O	Heat pump without ducts		17,900	\$2,506
211749866	ACD	UHD12KCH31S-O	UHD12KCH31SB-I		8,100	\$1,134
211749867	ACD	UHD18KCH25S-O	UHD18KCH25SB-I		14,200	\$1,988
211749868	ACD	UHD24KCH22S-O	UHD24KCH22SB-I		15,500	\$2,170
210534131	ACD	MPD42KCH21SB-O	Heat pump without ducts		35,600	\$4,984
210534130	ACD	MPD36KCH21SB-O	Heat pump without ducts		30,800	\$4,312
210534129	ACD	MPD30KCH21SB-O	Heat pump without ducts		27,200	\$3,808
210534128	ACD	MPD24KCH21SB-O	Heat pump without ducts		23,600	\$3,304
210534127	ACD	MPD18KCH21SB-O	Heat pump without ducts		14,700	\$2,058
211709660	ACD	PUD36KCH20S-O	PUD36KCH20S-I		22,000	\$3,080
211709659	ACD	PUD30KCH20S-O	PUD30KCH20S-I		17,500	\$2,450
210534144	ACD	PUD24KCH24S-O	PUD24KCH24S-I		15,000	\$2,100
202110485	ACD	UHD18KCH25S-O	UHD18KCH25S-I		14,200	\$1,988
202110484	ACD	UHD12KCH31S-O	UHD12KCH31S-I		8,100	\$1,134
210534143	ACD	PUD12KCH24S-O	PUD12KCH24S-I		7,000	\$980
211619266	ACD	PUD18KCH23S-O	PUD18KCH23S-I		10,800	\$1,512
206703383	ACD	OCD15KCH20S-O	OCD15KCH20S-I		10,100	\$1,414
214229583	ACD	PUD18KCH23S-O*	PUD18KCH23S-I*		10,800	\$1,512
207497902	ACD	FXD-ACD36	AH236		24,000	\$3,360
213164341	ACD	FXD-ACD60	GCAT60H/NAA		35,200	\$4,928
213164340	ACD	FXD-ACD60	GCAT48H/NAA		31,200	\$4,368
213164339	ACD	FXD-ACD36	GCAT36F/NAA		22,000	\$3,080
207497904	ACD	FXD-ACD60	AH260		36,000	\$5,040
207497903	ACD	FXD-ACD60	AH248		31,400	\$4,396
201863352	ACD	OCD18KCH20S-O	OCD18KCH20S-I		11,700	\$1,638
213164338	ACD	FXD-ACD36	GCAT24F/NAA		15,000	\$2,100
216980780	ACIQ	ACIQ-60-HPD	ACIQ-60-ACL-B		36,000	\$5,040

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216032369	ACIQ	ACIQ-36Z-HH-M5C	Combination heat pumps with or without ducts		31,400	\$4,396
216032367	ACIQ	ACIQ-36Z-HH-M5C	Heat pump without ducts		30,000	\$4,200
210857316	ACIQ	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MC		10,000	\$1,400
210857331	ACIQ	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MC		10,200	\$1,428
207825532	ACIQ	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MB		10,000	\$1,400
207825533	ACIQ	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MB		15,000	\$2,100
210857317	ACIQ	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MC		15,000	\$2,100
210857318	ACIQ	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MC		21,200	\$2,968
207825580	ACIQ	ACIQ-27Z-HH-M3B	Heat pump with ducts		27,000	\$3,780
210857381	ACIQ	ACIQ-55Z-HH-M5B	Heat pump with ducts		35,200	\$4,928
210857329	ACIQ	ACIQ-12ZPL-HP230B	SCC-1218-HH-M		9,500	\$1,330
210857330	ACIQ	ACIQ-18ZPL-HP230B	SCC-1218-HH-M		14,500	\$2,030
208106635	ACIQ	ACIQ-24-HPB	ACIQ-24-AHB		19,200	\$2,688
210857358	ACIQ	ACIQ-24ZPL-HP230B	ACIQ-24AHB-HH-M		16,900	\$2,366
210857357	ACIQ	ACIQ-18ZPL-HP230B	ACIQ-18AHB-HH-M		15,400	\$2,156
207825536	ACIQ	ACIQ-12ZPL-HP230B	ACIQ-12CC-HH-MB		9,900	\$1,386
207825542	ACIQ	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MB		9,600	\$1,344
207825540	ACIQ	ACIQ-18ZPL-HP230B	ACIQ-18CD-HH-MB		15,000	\$2,100
207825581	ACIQ	ACIQ-27Z-HH-M3B	Combination heat pumps with or without ducts		26,800	\$3,752
210857382	ACIQ	ACIQ-55Z-HH-M5B	Combination heat pumps with or without ducts		34,800	\$4,872
207825534	ACIQ	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MB		21,200	\$2,968
210857380	ACIQ	ACIQ-55Z-HH-M5B	Heat pump without ducts		34,400	\$4,816
207825576	ACIQ	ACIQ-18Z-HH-M2B	Heat pump without ducts		15,000	\$2,100
207825579	ACIQ	ACIQ-27Z-HH-M3B	Heat pump without ducts		26,600	\$3,724
207825585	ACIQ	ACIQ-48Z-HH-M5B	Heat pump without ducts		36,000	\$5,040
208106636	ACIQ	ACIQ-36-HPB	ACIQ-36-AHB		30,400	\$4,256
213492129	ACIQ	ACIQ-36-HPC	ACIQ-36-AHB		30,400	\$4,256
214810557	ACIQ	ACIQ-18-HPB	ACIQ-18-AHB		13,500	\$1,890
207825541	ACIQ	ACIQ-24ZPL-HP230B	ACIQ-24CD-HH-MB		21,000	\$2,940
207825578	ACIQ	ACIQ-18Z-HH-M2B	Combination heat pumps with or without ducts		15,500	\$2,170
207825582	ACIQ	ACIQ-36Z-HH-M4B	Heat pump without ducts		33,000	\$4,620
207825544	ACIQ	ACIQ-24ZPL-HP230B	ACIQ-24FM-HH-MB		19,000	\$2,660
207825577	ACIQ	ACIQ-18Z-HH-M2B	Heat pump with ducts		16,000	\$2,240
207825539	ACIQ	ACIQ-12ZPL-HP230B	ACIQ-12CD-HH-MB		10,600	\$1,484

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207825584	ACIQ	ACIQ-36Z-HH-M4B	Combination heat pumps with or without ducts		34,000	\$4,760
207825586	ACIQ	ACIQ-48Z-HH-M5B	Heat pump with ducts		36,000	\$5,040
207825587	ACIQ	ACIQ-48Z-HH-M5B	Combination heat pumps with or without ducts		36,000	\$5,040
215570365	ACIQ	ACIQ-30-HPB	ACIQ-30-AHB		21,000	\$2,940
212394323	ACIQ	ACIQ-24-HPB	ACIQ-24-ACL		21,000	\$2,940
216980785	ACIQ	ACIQ-18-HPD	ACIQ-18W-WMB		15,300	\$2,142
216980778	ACIQ	ACIQ-48-HPD	ACIQ-48-ACL-B		34,400	\$4,816
216980768	ACIQ	ACIQ-36-EHPD	ACIQ-36-ACL-B		24,200	\$3,388
216980767	ACIQ	ACIQ-36-EHPD	ACIQ-36-ACL-17-B		24,200	\$3,388
216980779	ACIQ	ACIQ-60-HPD	ACIQ-48-ACL-B		37,800	\$5,292
216980792	ACIQ	ACIQ-36-EHPD	ACIQ-36W-PB		24,600	\$3,444
216980775	ACIQ	ACIQ-30-HPD	ACIQ-36-ACL-B		25,000	\$3,500
216980774	ACIQ	ACIQ-30-HPD	ACIQ-36-ACL-17-B		25,000	\$3,500
216980777	ACIQ	ACIQ-36-HPD	ACIQ-36-ACL-B		29,200	\$4,088
216980776	ACIQ	ACIQ-36-HPD	ACIQ-36-ACL-17-B		29,200	\$4,088
216980764	ACIQ	ACIQ-24-EHPD	ACIQ-24-ACL-B		19,700	\$2,758
216980763	ACIQ	ACIQ-24-EHPD	ACIQ-24-ACL-14-B		19,700	\$2,758
216980772	ACIQ	ACIQ-24-HPD	ACIQ-24-ACL-B		19,700	\$2,758
216980771	ACIQ	ACIQ-24-HPD	ACIQ-24-ACL-14-B		19,700	\$2,758
216980770	ACIQ	ACIQ-18-HPD	ACIQ-24-ACL-B		15,200	\$2,128
216980769	ACIQ	ACIQ-18-HPD	ACIQ-24-ACL-14-B		15,200	\$2,128
216980796	ACIQ	ACIQ-36-HPD	ACIQ-36W-PB		31,200	\$4,368
216980795	ACIQ	ACIQ-30-HPD	ACIQ-30W-PB		24,000	\$3,360
216980793	ACIQ	ACIQ-18-HPD	ACIQ-18W-PB		15,000	\$2,100
216980788	ACIQ	ACIQ-36-HPD	ACIQ-36W-WMB		30,200	\$4,228
216980787	ACIQ	ACIQ-30-HPD	ACIQ-30W-WMB		23,200	\$3,248
216980784	ACIQ	ACIQ-36-EHPD	ACIQ-36W-WMB		24,800	\$3,472
216032336	ACIQ	ACIQ-18ZPL-HP230C	ACIQ-18W-HH-MD		16,600	\$2,324
216032246	ACIQ	ACIQ-18-HPD	ACIQ-18-AHD		15,000	\$2,100
216032352	ACIQ	ACIQ-12ZPL-HP230C	ACIQ-12FM-HH-MD		9,800	\$1,372
216032335	ACIQ	ACIQ-12ZPL-HP230C	ACIQ-12W-HH-MD		9,800	\$1,372
216032247	ACIQ	ACIQ-24-HPD	ACIQ-24-AHD		20,000	\$2,800
216032249	ACIQ	ACIQ-36-HPD	ACIQ-36-AHD		31,800	\$4,452
216032337	ACIQ	ACIQ-24ZPL-HP230C	ACIQ-24W-HH-MD		21,000	\$2,940
216032339	ACIQ	ACIQ-12ZPL-HP230C	ACIQ-12CC-HH-MC		10,000	\$1,400
216032340	ACIQ	ACIQ-18ZPL-HP230C	ACIQ-18CC-HH-MC		14,900	\$2,086

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216032341	ACIQ	ACIQ-24ZPL-HP230C	ACIQ-24CC-HH-MC		20,400	\$2,856
216032342	ACIQ	ACIQ-36ZPL-HP230C	ACIQ-36CC-HH-MC		30,600	\$4,284
216032343	ACIQ	ACIQ-48ZPL-HP230C	ACIQ-48CC-HH-MC		45,000	\$6,300
216032345	ACIQ	ACIQ-12ZPL-HP230C	ACIQ-12CD-HH-MC		10,200	\$1,428
216032346	ACIQ	ACIQ-18ZPL-HP230C	ACIQ-18CD-HH-MC		15,000	\$2,100
216032347	ACIQ	ACIQ-24ZPL-HP230C	ACIQ-24CD-HH-MC		21,600	\$3,024
216032348	ACIQ	ACIQ-36ZPL-HP230C	ACIQ-36CD-HH-MC		31,600	\$4,424
216032349	ACIQ	ACIQ-48ZPL-HP230C	ACIQ-48CD-HH-MC		45,000	\$6,300
216032350	ACIQ	ACIQ-60ZPL-HP230C	ACIQ-60CD-HH-MC		45,000	\$6,300
216032353	ACIQ	ACIQ-18ZPL-HP230C	ACIQ-18FM-HH-MD		14,400	\$2,016
216032354	ACIQ	ACIQ-24ZPL-HP230C	ACIQ-24FM-HH-MD		20,200	\$2,828
216032355	ACIQ	ACIQ-36ZPL-HP230C	ACIQ-36FM-HH-MD		30,200	\$4,228
216032356	ACIQ	ACIQ-48ZPL-HP230C	ACIQ-48FM-HH-MD		38,500	\$5,390
216032357	ACIQ	ACIQ-60ZPL-HP230C	ACIQ-60FM-HH-MD		41,000	\$5,740
216032360	ACIQ	ACIQ-18ZPL-HP230C	SCC-1218-HH-MB		14,500	\$2,030
216032361	ACIQ	ACIQ-18Z-HH-M3C	Heat pump without ducts		17,600	\$2,464
216032362	ACIQ	ACIQ-18Z-HH-M3C	Heat pump with ducts		17,000	\$2,380
216032363	ACIQ	ACIQ-18Z-HH-M3C	Combination heat pumps with or without ducts		17,300	\$2,422
216032364	ACIQ	ACIQ-27Z-HH-M4C	Heat pump without ducts		25,000	\$3,500
216032365	ACIQ	ACIQ-27Z-HH-M4C	Heat pump with ducts		23,000	\$3,220
216032366	ACIQ	ACIQ-27Z-HH-M4C	Combination heat pumps with or without ducts		24,000	\$3,360
216032368	ACIQ	ACIQ-36Z-HH-M5C	Heat pump with ducts		33,000	\$4,620
216032370	ACIQ	ACIQ-48Z-HH-M6C	Heat pump without ducts		44,000	\$6,160
216032371	ACIQ	ACIQ-48Z-HH-M6C	Heat pump with ducts		44,500	\$6,230
216032372	ACIQ	ACIQ-48Z-HH-M6C	Combination heat pumps with or without ducts		44,000	\$6,160
216032373	ACIQ	ACIQ-55Z-HH-M6C	Heat pump without ducts		44,000	\$6,160
216032374	ACIQ	ACIQ-55Z-HH-M6C	Heat pump with ducts		45,000	\$6,300
216032375	ACIQ	ACIQ-55Z-HH-M6C	Combination heat pumps with or without ducts		44,500	\$6,230
216032386	ACIQ	ES-48Z-M6C	Heat pump with ducts		37,000	\$5,180
216032244	ACIQ	ACIQ-48-EHPD	ACIQ-48-AHD		32,400	\$4,536
216032241	ACIQ	ACIQ-24-EHPD	ACIQ-24-AHD		20,000	\$2,800
216032248	ACIQ	ACIQ-30-HPD	ACIQ-30-AHD		23,800	\$3,332
216032252	ACIQ	ACIQ-60-HPD	ACIQ-60-AHD		45,000	\$6,300
216032251	ACIQ	ACIQ-48-HPD	ACIQ-48-AHD		37,000	\$5,180

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216032250	ACIQ	ACIQ-42-HPD	ACIQ-42-AHD		37,000	\$5,180
216032255	ACIQ	ACIQ-30-HPD	ACIQ-30-PAH		24,000	\$3,360
216032254	ACIQ	ACIQ-24-HPD	ACIQ-24-PAH		19,000	\$2,660
216032253	ACIQ	ACIQ-18-HPD	ACIQ-18-PAH		14,700	\$2,058
216032256	ACIQ	ACIQ-36-HPD	ACIQ-36-PAH		31,000	\$4,340
216032258	ACIQ	ACIQ-60-HPD	ACIQ-60-PAH		35,000	\$4,900
216032257	ACIQ	ACIQ-48-HPD	ACIQ-48-PAH		34,000	\$4,760
212394325	ACIQ	ACIQ-36-HPB	ACIQ-36-ACL		33,000	\$4,620
213492138	ACIQ	ACIQ-30-HPB	ACIQ-36-ACL-17		19,600	\$2,744
210857322	ACIQ	ACIQ-48ZPL-HP230B	ACIQ-48CD-HH-MB		39,500	\$5,530
210857319	ACIQ	ACIQ-36ZPL-HP230B	ACIQ-36CC-HH-MB		33,000	\$4,620
210857325	ACIQ	ACIQ-48ZPL-HP230B	ACIQ-48FM-HH-MB		35,000	\$4,900
210857320	ACIQ	ACIQ-48ZPL-HP230B	ACIQ-48CC-HH-MB		35,000	\$4,900
206315654	ACIQ	ACIQ-27Z-HH-M3	Heat pump without ducts		18,000	\$2,520
213492139	ACIQ	ACIQ-36-HPB	ACIQ-36-ACL-17		27,400	\$3,836
210857323	ACIQ	ACIQ-60ZPL-HP230B	ACIQ-60CD-HH-MB		40,000	\$5,600
213492132	ACIQ	ACIQ-36-HPC	ACIQ-36-ACL		27,000	\$3,780
213492131	ACIQ	ACIQ-36-HPC	ACIQ-36-ACL-17		27,000	\$3,780
213500937	ACIQ	ACIQ-36-HPC	ACIQ-36-AHB*		31,800	\$4,452
213433255	ACIQ	ACIQ-36-HPB	ACIQ-36W-P		32,800	\$4,592
213433253	ACIQ	ACIQ-24-HPB	ACIQ-24W-P		19,200	\$2,688
213433252	ACIQ	ACIQ-18-HPB	ACIQ-18W-P		13,500	\$1,890
213433254	ACIQ	ACIQ-30-HPB	ACIQ-30W-P		20,000	\$2,800
213433248	ACIQ	ACIQ-18-HPB	ACIQ-18W-WM		15,800	\$2,212
213433249	ACIQ	ACIQ-24-HPB	ACIQ-24W-WM		20,000	\$2,800
213433243	ACIQ	ACIQ-60HPB	ACIQ-60-ACL		37,000	\$5,180
213492136	ACIQ	ACIQ-30-HPB	ACIQ-36-ACL		22,600	\$3,164
207825583	ACIQ	ACIQ-36Z-HH-M4B	Heat pump with ducts		23,000	\$3,220
206315637	ACIQ	ACIQ-24-HP	ACIQ-24-AH		16,500	\$2,310
210857324	ACIQ	ACIQ-36ZPL-HP230B	ACIQ-36FM-HH-MB		32,000	\$4,480
206315656	ACIQ	ACIQ-48Z-HH-M5	Heat pump without ducts		30,000	\$4,200
212394324	ACIQ	ACIQ-30-HPB	ACIQ-30-ACL		22,600	\$3,164
210857356	ACIQ	ACIQ-60HPB	ACIQ-60AHB		42,000	\$5,880
208106637	ACIQ	ACIQ-48-HPB	ACIQ-48-AHB		36,000	\$5,040
210857326	ACIQ	ACIQ-60ZPL-HP230B	ACIQ-60FM-HH-MB		40,000	\$5,600
215792888	ADP	38MURAQ36AB3*	CDP36C15P	926TC48060V17***	28,400	\$3,976
215792887	ADP	38MURAQ36AB3*	CDP36A20P	926TC48060V17***	28,400	\$3,976
215792886	ADP	38MURAQ36AB3*	H,PE33936	926TC48060V17***	28,400	\$3,976

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215792885	ADP	38MURAQ36AB3*	CDP36B15P	926TC48060V17***	28,400	\$3,976
215792884	ADP	38MURAQ36AB3*	H,PE32936	926TC48060V17***	28,400	\$3,976
215792883	ADP	38MURAQ36AB3*	CDP36A15P	926TC48060V17***	28,400	\$3,976
215792882	ADP	38MURAQ36AB3*	H,PE34936	59TP6C060V17**16	28,400	\$3,976
215792881	ADP	38MURAQ36AB3*	CDP36C15P	59TP6C060V17**16	28,400	\$3,976
215792880	ADP	38MURAQ36AB3*	CDP36A20P	59TP6C060V17**16	28,400	\$3,976
215792879	ADP	38MURAQ36AB3*	H,PE33936	59TP6C060V17**16	28,400	\$3,976
215792878	ADP	38MURAQ36AB3*	CDP36B15P	59TP6C060V17**16	28,400	\$3,976
215792877	ADP	38MURAQ36AB3*	H,PE32936	59TP6C060V17**16	28,400	\$3,976
215792876	ADP	38MURAQ36AB3*	CDP36A15P	59TP6C060V17**16	28,400	\$3,976
214336192	ADP	AC036BXUDCH	F,PE*CC1937		35,000	\$4,900
213613883	ADP	TU60-48WADU	*E49960		34,200	\$4,788
213613882	ADP	TU36-24WADU	*G33936		21,000	\$2,940
213613881	ADP	WSEHV4860RA1-N	*E49960+TD		34,200	\$4,788
213613880	ADP	WSEHV4860RA1-N	*E49960		30,200	\$4,228
213613879	ADP	DLCURAH36ABK	H,GE34936+TD		26,400	\$3,696
213613878	ADP	DLCURAH36ABK	H,GE33936+TD		26,400	\$3,696
213613877	ADP	DLCURAH36ABK	H,GE32936+TD		26,400	\$3,696
213613891	ADP	GUD60W/A-D(U)	*G52960		30,200	\$4,228
213613890	ADP	GUD60W/A-D(U)	*E50960		30,200	\$4,228
213613889	ADP	GUD60W/A-D(U)	*E49960		30,200	\$4,228
213613899	ADP	GUD36W/A-D(U)	*G9J936		14,000	\$1,960
213613902	ADP	GUD36W/A-D(U)	*G8J936		14,000	\$1,960
213613888	ADP	GUD36W/A-D(U)	*G34936		14,000	\$1,960
213613887	ADP	FLEXX60HP230V1AO	*G52960		30,200	\$4,228
213613886	ADP	FLEXX60HP230V1AO	*E50960		30,200	\$4,228
213613885	ADP	FLEXX60HP230V1AO	*E49960		30,200	\$4,228
213613898	ADP	FLEXX36HP230V1AO	*G9J936		14,000	\$1,960
213613901	ADP	FLEXX36HP230V1AO	*G8J936		14,000	\$1,960
213613884	ADP	FLEXX36HP230V1AO	*G34936		14,000	\$1,960
213613866	ADP	38MURAQ36AB3	CDP36A15P+TD		26,400	\$3,696
213613862	ADP	38MURAQ24AB3	H,PG21924+TD		19,800	\$2,772
213613861	ADP	38MURAQ36AB3	H,PE32936+TD		26,400	\$3,696
213613860	ADP	38MURAQ36AB3	CDP36A15P+TD		26,400	\$3,696
213361093	ADP	SL25XPV-048-230A**	LD42/61Y9	EL297UH135XV60D*	40,500	\$5,670
213361092	ADP	SL25XPV-048-230A**	LD42/61Z9	EL297UH135XV60D*	40,500	\$5,670
213361091	ADP	SL25XPV-048-230A**	LP42/62W9	EL297UH110XV60C*	41,000	\$5,740
213361090	ADP	SL25XPV-048-230A**	LH42/62W9	EL297UH110XV60C*	41,000	\$5,740

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213361089	ADP	SL25XPV-048-230A**	L*42/60Z9	EL297UH110XV60C*	41,000	\$5,740
213361088	ADP	SL25XPV-048-230A**	LH40/61W9	EL297UH110XV60C*	44,500	\$6,230
213361087	ADP	SL25XPV-048-230A**	LD42/61Y9	EL297UH110XV60C*	44,500	\$6,230
213361086	ADP	SL25XPV-048-230A**	LD42/61Z9	EL297UH110XV60C*	44,500	\$6,230
213361082	ADP	SL25XPV-048-230A**	LH40/61W9	EL297UH110XV48C*	44,500	\$6,230
213361081	ADP	SL25XPV-048-230A**	LD42/61Y9	EL297UH110XV48C*	44,500	\$6,230
213361080	ADP	SL25XPV-048-230A**	LD42/61Z9	EL297UH110XV48C*	44,500	\$6,230
213361079	ADP	SL25XPV-048-230A**	LP42/62W9	EL297UH090XV60C*	41,000	\$5,740
213361078	ADP	SL25XPV-048-230A**	LH42/62W9	EL297UH090XV60C*	41,000	\$5,740
213361077	ADP	SL25XPV-048-230A**	L*42/60Z9	EL297UH090XV60C*	41,000	\$5,740
213361076	ADP	SL25XPV-048-230A**	LH40/61W9	EL297UH090XV60C*	44,500	\$6,230
213361075	ADP	SL25XPV-048-230A**	LD42/61Y9	EL297UH090XV60C*	44,500	\$6,230
213361074	ADP	SL25XPV-048-230A**	LD42/61Z9	EL297UH090XV60C*	44,500	\$6,230
213361070	ADP	SL25XPV-048-230A**	LH40/61W9	EL297UH090XV48C*	44,500	\$6,230
213361069	ADP	SL25XPV-048-230A**	LD42/61Y9	EL297UH090XV48C*	44,500	\$6,230
213361068	ADP	SL25XPV-048-230A**	LD42/61Z9	EL297UH090XV48C*	44,500	\$6,230
213360281	ADP	SL25XPV-036-230A**	L*23/37Z9	EL297UH110XV48C*	29,600	\$4,144
213360280	ADP	SL25XPV-036-230A**	LH23/37W9	EL297UH110XV48C*	29,600	\$4,144
213360279	ADP	SL25XPV-036-230A**	LH35/38F9	EL297UH110XV48C*	29,600	\$4,144
213360278	ADP	SL25XPV-036-230A**	LH35/38X9	EL297UH110XV48C*	29,600	\$4,144
213360277	ADP	SL25XPV-036-230A**	L*35/36S9	EL297UH110XV48C*	29,600	\$4,144
213360276	ADP	SL25XPV-036-230A**	L*35/36U9	EL297UH110XV48C*	29,600	\$4,144
213360275	ADP	SL25XPV-036-230A**	L*23/37Z9	EL297UH090XV60C*	29,400	\$4,116
213360274	ADP	SL25XPV-036-230A**	LH23/37W9	EL297UH090XV60C*	29,400	\$4,116
213360273	ADP	SL25XPV-036-230A**	LH35/38F9	EL297UH090XV60C*	29,400	\$4,116
213360272	ADP	SL25XPV-036-230A**	LH35/38X9	EL297UH090XV60C*	29,400	\$4,116
213360271	ADP	SL25XPV-036-230A**	L*35/36S9	EL297UH090XV60C*	29,400	\$4,116
213360270	ADP	SL25XPV-036-230A**	L*35/36U9	EL297UH090XV60C*	29,400	\$4,116
213360257	ADP	SL25XPV-036-230A**	L*23/37Z9	EL297UH070XV36B*	29,600	\$4,144
213360256	ADP	SL25XPV-036-230A**	L*35/36S9	EL297UH070XV36B*	32,200	\$4,508
213360255	ADP	SL25XPV-036-230A**	L*35/36U9	EL297UH070XV36B*	30,200	\$4,228
213360254	ADP	SL25XPV-036-230A**	LH35/36F9	EL297UH070XV36B*	30,200	\$4,228
213360253	ADP	SL25XPV-036-230A**	LD24/35Y9	EL297UH070XV36B*	30,200	\$4,228
213360251	ADP	SL25XPV-036-230A**	L*23/37Z9	EL297UH045XV36B*	30,200	\$4,228
213360250	ADP	SL25XPV-036-230A**	L*35/36S9	EL297UH045XV36B*	30,200	\$4,228
213360249	ADP	SL25XPV-036-230A**	L*35/36U9	EL297UH045XV36B*	30,200	\$4,228
213360248	ADP	SL25XPV-036-230A**	LH35/36F9	EL297UH045XV36B*	30,200	\$4,228
213360247	ADP	SL25XPV-036-230A**	LD24/35Y9	EL297UH045XV36B*	30,200	\$4,228

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213360245	ADP	SL25XPV-024-230A**	L*23/37Z9	EL297UH110XV48C*	22,800	\$3,192
213360244	ADP	SL25XPV-024-230A**	LH23/37W9	EL297UH110XV48C*	22,800	\$3,192
213360243	ADP	SL25XPV-024-230A**	LH35/38F9	EL297UH110XV48C*	22,800	\$3,192
213360242	ADP	SL25XPV-024-230A**	LH35/38X9	EL297UH110XV48C*	22,800	\$3,192
213360241	ADP	SL25XPV-024-230A**	L*35/36S9	EL297UH110XV48C*	22,800	\$3,192
213360240	ADP	SL25XPV-024-230A**	L*35/36U9	EL297UH110XV48C*	22,800	\$3,192
213360239	ADP	SL25XPV-024-230A**	LP36/37R9	EL297UH110XV48C*	22,800	\$3,192
213360238	ADP	SL25XPV-024-230A**	L*23/37Z9	EL297UH090XV48C*	22,600	\$3,164
213360237	ADP	SL25XPV-024-230A**	LH23/37W9	EL297UH090XV48C*	22,600	\$3,164
213360236	ADP	SL25XPV-024-230A**	LH35/38F9	EL297UH090XV48C*	22,600	\$3,164
213360235	ADP	SL25XPV-024-230A**	LH35/38X9	EL297UH090XV48C*	22,600	\$3,164
213360234	ADP	SL25XPV-024-230A**	L*35/36S9	EL297UH090XV48C*	22,600	\$3,164
213360233	ADP	SL25XPV-024-230A**	L*35/36U9	EL297UH090XV48C*	22,600	\$3,164
213360232	ADP	SL25XPV-024-230A**	LP36/37R9	EL297UH090XV48C*	22,600	\$3,164
213360231	ADP	SL25XPV-024-230A**	L*23/37Z9	EL297UH090XV36C*	22,800	\$3,192
213360230	ADP	SL25XPV-024-230A**	LH23/37W9	EL297UH090XV36C*	22,800	\$3,192
213360229	ADP	SL25XPV-024-230A**	LH35/38F9	EL297UH090XV36C*	22,800	\$3,192
213360228	ADP	SL25XPV-024-230A**	LH35/38X9	EL297UH090XV36C*	22,800	\$3,192
213360227	ADP	SL25XPV-024-230A**	L*35/36S9	EL297UH090XV36C*	22,800	\$3,192
213360226	ADP	SL25XPV-024-230A**	L*35/36U9	EL297UH090XV36C*	22,800	\$3,192
213360225	ADP	SL25XPV-024-230A**	LP36/37R9	EL297UH090XV36C*	22,800	\$3,192
213360224	ADP	SL25XPV-024-230A**	L*23/37Z9	EL297UH070XV36B*	22,400	\$3,136
213360223	ADP	SL25XPV-024-230A**	L*35/36S9	EL297UH070XV36B*	23,200	\$3,248
213360222	ADP	SL25XPV-024-230A**	L*35/36U9	EL297UH070XV36B*	23,200	\$3,248
213360221	ADP	SL25XPV-024-230A**	L*19/36S9	EL297UH070XV36B*	23,200	\$3,248
213360220	ADP	SL25XPV-024-230A**	LH35/36F9	EL297UH070XV36B*	23,200	\$3,248
213360219	ADP	SL25XPV-024-230A**	LH29/36F9	EL297UH070XV36B*	23,200	\$3,248
213360218	ADP	SL25XPV-024-230A**	LD24/35Y9	EL297UH070XV36B*	23,200	\$3,248
213360217	ADP	SL25XPV-024-230A**	LD19/36Y9	EL297UH070XV36B*	23,200	\$3,248
213360216	ADP	SL25XPV-024-230A**	LP36/37R9	EL297UH070XV36B*	22,400	\$3,136
213360215	ADP	SL25XPV-024-230A**	L*23/37Z9	EL297UH045XV36B*	22,400	\$3,136
213360214	ADP	SL25XPV-024-230A**	L*35/36S9	EL297UH045XV36B*	23,200	\$3,248
213360213	ADP	SL25XPV-024-230A**	L*35/36U9	EL297UH045XV36B*	23,200	\$3,248
213360212	ADP	SL25XPV-024-230A**	L*19/36S9	EL297UH045XV36B*	23,200	\$3,248
213360211	ADP	SL25XPV-024-230A**	LH35/36F9	EL297UH045XV36B*	23,200	\$3,248
213360210	ADP	SL25XPV-024-230A**	LH29/36F9	EL297UH045XV36B*	23,200	\$3,248
213360209	ADP	SL25XPV-024-230A**	LD24/35Y9	EL297UH045XV36B*	23,200	\$3,248
213360208	ADP	SL25XPV-024-230A**	LD19/36Y9	EL297UH045XV36B*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213360207	ADP	SL25XPV-024-230A**	LP36/37R9	EL297UH045XV36B*	22,400	\$3,136
212864643	ADP	HMH72B341	AD-32(P,U)*****9	TM9E080B12MP12	24,400	\$3,416
212608857	ADP	HMH72B341	SM6937		23,600	\$3,304
212517479	ADP	HMH72B341	CH367C9	TL8E100C20UH11	25,400	\$3,556
212517478	ADP	HMH72B341	CV365*9	TL8E100C20UH11	25,400	\$3,556
214311494	ADP	TZPLV182PA	H,RG21924+TD		13,600	\$1,904
214311501	ADP	TZPLV242PA	H,RE21924+TD		19,800	\$2,772
214311495	ADP	TZPLV242PA	H,RG21924+TD		19,800	\$2,772
214328275	ADP	WSEHV2436RA1-C	H,A,DE34936	WPV050T3AA	14,000	\$1,960
214328276	ADP	WSEHV2436RA1-C	H,A,DE35936	WPV050T3AA	14,000	\$1,960
214328277	ADP	WSEHV2436RA1-C	H,A,DG34936	WPV050T3AA	14,000	\$1,960
214328278	ADP	WSEHV2436RA1-C	H,A,DG35936	WPV050T3AA	14,000	\$1,960
214328279	ADP	WSEHV2436RA1-C	H,A,DE34936	WPV060T3AA	14,000	\$1,960
214328280	ADP	WSEHV2436RA1-C	H,A,DE35936	WPV060T3AA	14,000	\$1,960
214328281	ADP	WSEHV2436RA1-C	H,A,DG34936	WPV060T3AA	14,000	\$1,960
214328282	ADP	WSEHV2436RA1-C	H,A,DG35936	WPV060T3AA	14,000	\$1,960
214331201	ADP	WSEHV2436RA1-C	*E34936	WPV070T3AA	24,600	\$3,444
214331202	ADP	WSEHV2436RA1-C	*E35936	WPV070T3AA	24,600	\$3,444
214331203	ADP	WSEHV2436RA1-C	*G34936	WPV070T3AA	24,600	\$3,444
214331204	ADP	WSEHV2436RA1-C	*G35936	WPV070T3AA	24,600	\$3,444
214328283	ADP	WSEHV2436RA1-C	H,A,DE34936	WPV070T3AA	14,000	\$1,960
214328284	ADP	WSEHV2436RA1-C	H,A,DE35936	WPV070T3AA	14,000	\$1,960
214328285	ADP	WSEHV2436RA1-C	H,A,DG34936	WPV070T3AA	14,000	\$1,960
214328286	ADP	WSEHV2436RA1-C	H,A,DG35936	WPV070T3AA	14,000	\$1,960
214328287	ADP	WSEHV2436RA1-C	H,A,DE34936	WUV050T3AA	14,000	\$1,960
214328288	ADP	WSEHV2436RA1-C	H,A,DE35936	WUV050T3AA	14,000	\$1,960
214328289	ADP	WSEHV2436RA1-C	H,A,DG34936	WUV050T3AA	14,000	\$1,960
214328290	ADP	WSEHV2436RA1-C	H,A,DG35936	WUV050T3AA	14,000	\$1,960
214328291	ADP	WSEHV2436RA1-C	H,A,DE34936	WUV060T3AA	14,000	\$1,960
214328292	ADP	WSEHV2436RA1-C	H,A,DE35936	WUV060T3AA	14,000	\$1,960
214328293	ADP	WSEHV2436RA1-C	H,A,DG34936	WUV060T3AA	14,000	\$1,960
214328294	ADP	WSEHV2436RA1-C	H,A,DG35936	WUV060T3AA	14,000	\$1,960
214331205	ADP	WSEHV2436RA1-C	*E34936	WUV070T3AA	24,600	\$3,444
214331206	ADP	WSEHV2436RA1-C	*E35936	WUV070T3AA	24,600	\$3,444
214331207	ADP	WSEHV2436RA1-C	*G34936	WUV070T3AA	24,600	\$3,444
214331208	ADP	WSEHV2436RA1-C	*G35936	WUV070T3AA	24,600	\$3,444
214328295	ADP	WSEHV2436RA1-C	H,A,DE34936	WUV070T3AA	14,000	\$1,960
214328296	ADP	WSEHV2436RA1-C	H,A,DE35936	WUV070T3AA	14,000	\$1,960

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214328297	ADP	WSEHV2436RA1-C	H,A,DG34936	WUV070T3AA	14,000	\$1,960
214328298	ADP	WSEHV2436RA1-C	H,A,DG35936	WUV070T3AA	14,000	\$1,960
214328311	ADP	WSEHV2436RA1-N	H,A,DG33936	WPV050T3AA	14,000	\$1,960
214328312	ADP	WSEHV2436RA1-N	H,A,DG34936	WPV050T3AA	14,000	\$1,960
214328313	ADP	WSEHV2436RA1-N	H,A,DG33936	WPV060T3AA	14,000	\$1,960
214328314	ADP	WSEHV2436RA1-N	H,A,DG34936	WPV060T3AA	14,000	\$1,960
214331209	ADP	WSEHV2436RA1-N	*G33936	WPV070T3AA	24,600	\$3,444
214331210	ADP	WSEHV2436RA1-N	*G34936	WPV070T3AA	24,600	\$3,444
214328315	ADP	WSEHV2436RA1-N	H,A,DG33936	WPV070T3AA	14,000	\$1,960
214328316	ADP	WSEHV2436RA1-N	H,A,DG34936	WPV070T3AA	14,000	\$1,960
214328317	ADP	WSEHV2436RA1-N	H,A,DG33936	WUV050T3AA	14,000	\$1,960
214328318	ADP	WSEHV2436RA1-N	H,A,DG34936	WUV050T3AA	14,000	\$1,960
214328319	ADP	WSEHV2436RA1-N	H,A,DG33936	WUV060T3AA	14,000	\$1,960
214328320	ADP	WSEHV2436RA1-N	H,A,DG34936	WUV060T3AA	14,000	\$1,960
214331211	ADP	WSEHV2436RA1-N	*G33936	WUV070T3AA	24,600	\$3,444
214331212	ADP	WSEHV2436RA1-N	*G34936	WUV070T3AA	24,600	\$3,444
214328321	ADP	WSEHV2436RA1-N	H,A,DG33936	WUV070T3AA	14,000	\$1,960
214328322	ADP	WSEHV2436RA1-N	H,A,DG34936	WUV070T3AA	14,000	\$1,960
213369643	ADP	MOD30U-30HFN1-MR0(X)	*G32936+TD		21,600	\$3,024
213369642	ADP	MOD30U-30HFN1-MR0(X)	*E31930+TD		21,400	\$2,996
213608465	ADP	38MURAQ36AB3	H,PG8J936+TD		26,400	\$3,696
213608464	ADP	38MURAQ36AB3	CDP36J15P+TD		26,400	\$3,696
213608461	ADP	38MURAQ24AB3	H,PG30924+TD		20,000	\$2,800
213608460	ADP	38MURAQ24AB3	CDP24H15P+TD		20,000	\$2,800
213608459	ADP	38MURAQ24AB3	CDP24H13P+TD		20,000	\$2,800
213608458	ADP	38MURAQ24AB3	H,PE21924+TD		19,800	\$2,772
213608457	ADP	38MURAQ18AB3	H,PG21924+TD		13,600	\$1,904
213608456	ADP	38MURAQ36AB3	H,PG8J936+TD		26,400	\$3,696
213608455	ADP	38MURAQ36AB3	CDP36J15P+TD		26,400	\$3,696
213608451	ADP	38MURAQ24AB3	H,PG30924+TD		20,000	\$2,800
213608450	ADP	38MURAQ24AB3	CDP24H15P+TD		20,000	\$2,800
213608449	ADP	38MURAQ24AB3	CDP24H13P+TD		20,000	\$2,800
213608448	ADP	38MURAQ24AB3	H,PE21924+TD		19,800	\$2,772
213608447	ADP	38MURAQ24AB3	H,PG21924+TD		19,800	\$2,772
213608446	ADP	38MURAQ24AB3	H,PE20924+TD		19,800	\$2,772
213608445	ADP	38MURAQ18AB3	H,PG21924+TD		13,600	\$1,904

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213608444	ADP	38MURAQ18AB3	H,PE20924+TD		13,500	\$1,890
213608442	ADP	38MURAQ36AB3	H,PG33936+TD		26,400	\$3,696
213608441	ADP	38MURAQ36AB3	H,PG33936+TD		26,400	\$3,696
212396575	ADP	4TXD2060A10NU**	F,PE*CC4960		31,800	\$4,452
212396574	ADP	4TXD2060A10NU**	F,PE*CC9960		36,400	\$5,096
212396573	ADP	4TXD2060A10NU**	F,PE*CC7948		31,800	\$4,452
212396572	ADP	4TXD2060A10NU**	F,PE*UU1960		36,400	\$5,096
212396571	ADP	4TXD2060A10NU**	F,PE*CC7960		36,400	\$5,096
212396559	ADP	4TXD2060A10NU**	F,PE*CC4960		31,800	\$4,452
212396558	ADP	4TXD2060A10NU**	F,PE*CC9960		36,400	\$5,096
212396557	ADP	4TXD2060A10NU**	F,PE*CC7948		31,800	\$4,452
212396556	ADP	4TXD2060A10NU**	F,PE*UU1960		36,400	\$5,096
212396555	ADP	4TXD2060A10NU**	F,PE*CC7960		36,400	\$5,096
212396570	ADP	4TXD2036A10NU**	F,PE*G34925		15,000	\$2,100
212396569	ADP	4TXD2036A10NU**	F,PE*G34930		15,000	\$2,100
212396568	ADP	4TXD2036A10NU**	F,PE*G34936		24,200	\$3,388
212396567	ADP	4TXD2036A10NU**	F,PE*G33925		15,000	\$2,100
212396566	ADP	4TXD2036A10NU**	F,PE*G33930		15,000	\$2,100
212396565	ADP	4TXD2036A10NU**	F,PE*G33936		24,200	\$3,388
212396564	ADP	4TXD2036A10NU**	F,PE*E32924		15,000	\$2,100
212396563	ADP	4TXD2036A10NU**	F,PE*E32925		15,000	\$2,100
212396562	ADP	4TXD2036A10NU**	F,PE*E32930		15,000	\$2,100
212396561	ADP	4TXD2036A10NU**	F,PE*E32936		24,200	\$3,388
212396560	ADP	4TXD2036A10NU**	F,PE*BB8937		24,000	\$3,360
212396554	ADP	4TXD2036A10NU**	F,PE*G34925		15,000	\$2,100
212396553	ADP	4TXD2036A10NU**	F,PE*G34930		15,000	\$2,100
212396552	ADP	4TXD2036A10NU**	F,PE*G34936		24,200	\$3,388
212396551	ADP	4TXD2036A10NU**	F,PE*G33925		15,000	\$2,100
212396550	ADP	4TXD2036A10NU**	F,PE*G33930		15,000	\$2,100
212396549	ADP	4TXD2036A10NU**	F,PE*G33936		24,200	\$3,388
212396548	ADP	4TXD2036A10NU**	F,PE*E32924		15,000	\$2,100
212396547	ADP	4TXD2036A10NU**	F,PE*E32925		15,000	\$2,100
212396546	ADP	4TXD2036A10NU**	F,PE*E32930		15,000	\$2,100
212396545	ADP	4TXD2036A10NU**	F,PE*E32936		24,200	\$3,388
212396544	ADP	4TXD2036A10NU**	F,PE*BB8937		24,000	\$3,360
211715926	ADP	HMH72B341	H,YE35936	TM9Y100C20MP11	24,600	\$3,444
211715922	ADP	HMH72B341	H,YE35936	TM9Y080C16MP11	24,800	\$3,472
211715921	ADP	HMH72B341	H,YE34936	TM9Y080C16MP11	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211715920	ADP	HMH72B341	H,YE33936	TM9Y080C16MP11	25,800	\$3,612
211715919	ADP	HMH72B341	H,YE35936	TM9Y080B12MP11	24,800	\$3,472
211715918	ADP	HMH72B341	H,YE34936	TM9Y080B12MP11	25,800	\$3,612
211715917	ADP	HMH72B341	H,YE33936	TM9Y080B12MP11	25,800	\$3,612
211715916	ADP	HMH72B341	H,YE32936	TM9Y080B12MP11	25,800	\$3,612
211715915	ADP	HMH72B341	H,YE35936	TM9Y060B12MP11	24,600	\$3,444
211715914	ADP	HMH72B341	H,YE34936	TM9Y060B12MP11	25,600	\$3,584
211715913	ADP	HMH72B341	H,YE33936	TM9Y060B12MP11	25,600	\$3,584
211715912	ADP	HMH72B341	H,YE32936	TM9Y060B12MP11	25,600	\$3,584
211715911	ADP	HMH72B341	H,YE35936	TM9V100C20MP12	25,000	\$3,500
211715910	ADP	HMH72B341	H,YE34936	TM9V100C20MP12	26,000	\$3,640
211715909	ADP	HMH72B341	H,YE33936	TM9V100C20MP12	26,000	\$3,640
211715903	ADP	HMH72B341	H,YE34936	TM9V080C16MP12	25,200	\$3,528
211715902	ADP	HMH72B341	H,YE33936	TM9V080C16MP12	25,200	\$3,528
211715901	ADP	HMH72B341	H,YE32936	TM9V080C16MP12	25,200	\$3,528
211715900	ADP	HMH72B341	H,YE35936	TM9V080B12MP12	24,800	\$3,472
211715899	ADP	HMH72B341	H,YE34936	TM9V080B12MP12	25,600	\$3,584
211715898	ADP	HMH72B341	H,YE33936	TM9V080B12MP12	25,600	\$3,584
211715897	ADP	HMH72B341	H,YE32936	TM9V080B12MP12	25,600	\$3,584
211715896	ADP	HMH72B341	H,YE35936	TM9V060B12MP12	24,600	\$3,444
211715895	ADP	HMH72B341	H,YE34936	TM9V060B12MP12	25,400	\$3,556
211715894	ADP	HMH72B341	H,YE33936	TM9V060B12MP12	25,400	\$3,556
211715893	ADP	HMH72B341	H,YE32936	TM9V060B12MP12	25,400	\$3,556
211715892	ADP	HMH72B341	H,YE35936	TM9V040A10MP12	24,200	\$3,388
211715891	ADP	HMH72B341	H,YE34936	TM9V040A10MP12	24,800	\$3,472
211715890	ADP	HMH72B341	H,YE33936	TM9V040A10MP12	24,800	\$3,472
213369614	ADP	4TXD2036A10NU**	*G33936+TD		21,000	\$2,940
213369613	ADP	4TXD2036A10NU**	*G33936		14,000	\$1,960
213370126	ADP	TU60-48WADU	*E51960+TD		34,200	\$4,788
213370125	ADP	TU60-48WADU	*E51960		30,200	\$4,228
213370124	ADP	TU60-48WADU	*E50960+TD		34,200	\$4,788
213370123	ADP	TU60-48WADU	*E50960		30,200	\$4,228
213370120	ADP	TU36-24WADU	*G35936+TD		21,000	\$2,940
213370129	ADP	TU36-24WADU	*G35936		14,000	\$1,960
213370122	ADP	TU36-24WADU	*E35936+TD		21,000	\$2,940
213370121	ADP	TU36-24WADU	*E35936		14,000	\$1,960
213370119	ADP	TU36-24WADU	*E33936+TD		21,000	\$2,940
213370128	ADP	TU36-24WADU	*E33936		14,000	\$1,960

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213250280	ADP	WSEHV4860RA1-N	*G52960+TD		30,200	\$4,228
213250281	ADP	WSEHV4860RA1-N	*G52960		34,200	\$4,788
213369612	ADP	WSEHV4860RA1-N	*E50960+TD		34,200	\$4,788
213369611	ADP	WSEHV4860RA1-N	*E50960		30,200	\$4,228
213369610	ADP	WSEHV2436RA1-N	*G33936+TD		21,000	\$2,940
213369609	ADP	WSEHV2436RA1-N	*G33936		14,000	\$1,960
213369685	ADP	DMA30HOS20230E7	*G8J936+TD		21,600	\$3,024
213369684	ADP	DMA30HOS20230E7	*G7J936+TD		21,600	\$3,024
213369683	ADP	DMA30HOS20230E7	*G33936+TD		21,600	\$3,024
213369682	ADP	DMA30HOS20230E7	*E32936+TD		21,600	\$3,024
213369681	ADP	DMA30HOS20230E7	*E31930+TD		21,400	\$2,996
213369672	ADP	KU60UHO	*E51960+TD		30,200	\$4,228
213369607	ADP	KU60UHO	*E50960+TD		34,200	\$4,788
213369606	ADP	KU60UHO	*E50960		30,200	\$4,228
213369671	ADP	KU36UHO	*G35936+TD		14,000	\$1,960
213369605	ADP	KU36UHO	*G34936+TD		21,000	\$2,940
213369604	ADP	KU36UHO	*G34936		14,000	\$1,960
213369669	ADP	KU36UHO	*E33936+TD		14,000	\$1,960
213369668	ADP	A-KCD30SA-1	*E32936+TD		21,600	\$3,024
211750026	ADP	GUD60W/A-D(U)	*E50960+TD		34,200	\$4,788
213369603	ADP	GUD60W/A-D(U)	*E50948+TD		34,200	\$4,788
213369602	ADP	GUD60W/A-D(U)	*E50948		30,200	\$4,228
211750021	ADP	GUD36W/A-D(U)	*G33936+TD		21,000	\$2,940
213369601	ADP	GUD36W/A-D(U)	*G33936		14,000	\$1,960
211750030	ADP	FLEXX36HP230V1AO	*G33936+TD		21,000	\$2,940
213369600	ADP	FLEXX36HP230V1AO	*G33936		14,000	\$1,960
213369644	ADP	MOX430U-18HFN1-M	*G20924+TD		13,500	\$1,890
213369596	ADP	MOD30-24HFN1-MW	*G20924+TD		19,800	\$2,772
213369640	ADP	DIRM-30MAGICPRO20-OU	*E32936+TD		21,600	\$3,024
213369636	ADP	EVD-30-O	*G8J936+TD		21,600	\$3,024
213369635	ADP	EVD-30-O	*G33936+TD		21,600	\$3,024
213369634	ADP	EVD-30-O	*E32936+TD		21,600	\$3,024
213369633	ADP	EVD-30-O	*E31930+TD		21,400	\$2,996
213369595	ADP	WSEHV2436RA1-C	*G33936+TD		21,000	\$2,940
213369594	ADP	WSEHV2436RA1-C	*G33936		14,000	\$1,960
213369593	ADP	WSEHV2436RA1-C	*E7J936+TD		21,000	\$2,940
213369592	ADP	WSEHV2436RA1-C	*E7J936		14,000	\$1,960

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213164379	ADP	HMH72B341	CV367A9+AEF36AXP*		24,400	\$3,416
213164378	ADP	HMH72B341	CX363B935+AEF48BXP*		23,600	\$3,304
213164376	ADP	HMH72B341	CV365B9+AEF48BXP*		23,600	\$3,304
213164375	ADP	HMH72B341	CX361B935+AEF48BXP*		23,600	\$3,304
213164374	ADP	HMH72B341	CH365B9+AEF48BXP*		23,600	\$3,304
213164372	ADP	HMH72B341	CV363B9+AEF48BXP*		23,600	\$3,304
212920688	ADP	HMH72B341	AD-48(P,U)*****1+TXV	TM9V100C16MP12	24,400	\$3,416
212434806	ADP	HMH72B341	AD-32(P,U)*****9	TM8E080C16MP11	25,000	\$3,500
212394564	ADP	HMH72B341	H,YE35936	TM9E100C20MP12	24,000	\$3,360
212394563	ADP	HMH72B341	H,YE35936	TM9E100C16MP12	24,200	\$3,388
212394562	ADP	HMH72B341	H,YE34936	TM9E100C16MP12	25,200	\$3,528
212394561	ADP	HMH72B341	H,YE33936	TM9E100C16MP12	25,200	\$3,528
212394560	ADP	HMH72B341	H,YE32936	TM9E100C16MP12	25,200	\$3,528
212394559	ADP	HMH72B341	H,YE35936	TM9E080C16MP12	24,200	\$3,388
212394558	ADP	HMH72B341	H,YE34936	TM9E080C16MP12	25,200	\$3,528
212394557	ADP	HMH72B341	H,YE33936	TM9E080C16MP12	25,200	\$3,528
212394556	ADP	HMH72B341	H,YE32936	TM9E080C16MP12	25,200	\$3,528
212394555	ADP	HMH72B341	H,YE35936	TM9E080B12MP12	24,400	\$3,416
212394541	ADP	HMH72B341	H,YE35936	TM9Y100C16MP11	25,000	\$3,500
212394540	ADP	HMH72B341	H,YE34936	TM9Y100C16MP11	25,000	\$3,500
212394539	ADP	HMH72B341	H,YE33936	TM9Y100C16MP11	25,000	\$3,500
212394524	ADP	HMH72B341	H,YE35936	TM9V100C16MP12	24,400	\$3,416
212394523	ADP	HMH72B341	H,YE34936	TM9V100C16MP12	25,400	\$3,556
212394522	ADP	HMH72B341	H,YE33936	TM9V100C16MP12	25,400	\$3,556
212394521	ADP	HMH72B341	H,YE32936	TM9V100C16MP12	25,400	\$3,556
212394520	ADP	HMH72B341	H,YE35936	TM9V080C16MP12	24,400	\$3,416
212394505	ADP	HMH72B341	H,YE35936	TM9E100C20MP12	24,000	\$3,360
212394504	ADP	HMH72B341	H,YE35936	TM9E100C16MP12	24,200	\$3,388
212394503	ADP	HMH72B341	H,YE34936	TM9E100C16MP12	25,200	\$3,528
212394502	ADP	HMH72B341	H,YE33936	TM9E100C16MP12	25,200	\$3,528
212394501	ADP	HMH72B341	H,YE32936	TM9E100C16MP12	25,200	\$3,528
212394500	ADP	HMH72B341	H,YE35936	TM9E080C16MP12	24,200	\$3,388
212394499	ADP	HMH72B341	H,YE34936	TM9E080C16MP12	25,200	\$3,528
212394498	ADP	HMH72B341	H,YE33936	TM9E080C16MP12	25,200	\$3,528
212394497	ADP	HMH72B341	H,YE32936	TM9E080C16MP12	25,200	\$3,528
212394496	ADP	HMH72B341	H,YE35936	TM9E080B12MP12	24,400	\$3,416
211715942	ADP	HMH72B341	H,YE35936	YP9C100C16MP13	24,400	\$3,416
211715941	ADP	HMH72B341	H,YE34936	YP9C100C16MP13	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211715940	ADP	HMH72B341	H,YE33936	YP9C100C16MP13	25,400	\$3,556
211715939	ADP	HMH72B341	H,YE32936	YP9C100C16MP13	25,400	\$3,556
211715938	ADP	HMH72B341	H,YE35936	YP9C080C16MP13	24,400	\$3,416
211715925	ADP	HMH72B341	H,YE35936	TM9Y100C16MP11	25,000	\$3,500
211715924	ADP	HMH72B341	H,YE34936	TM9Y100C16MP11	25,000	\$3,500
211715923	ADP	HMH72B341	H,YE33936	TM9Y100C16MP11	25,000	\$3,500
211715908	ADP	HMH72B341	H,YE35936	TM9V100C16MP12	24,400	\$3,416
211715907	ADP	HMH72B341	H,YE34936	TM9V100C16MP12	25,400	\$3,556
211715906	ADP	HMH72B341	H,YE33936	TM9V100C16MP12	25,400	\$3,556
211715905	ADP	HMH72B341	H,YE32936	TM9V100C16MP12	25,400	\$3,556
211715904	ADP	HMH72B341	H,YE35936	TM9V080C16MP12	24,400	\$3,416
213249232	ADP	DIRM-30MAGICPRO20-OU	HG33936+TD		21,600	\$3,024
213250268	ADP	DIRM-30MAGICPRO20-OU	*G8J936+TD		21,600	\$3,024
213250270	ADP	DIRM-30MAGICPRO20-OU	*G33936+TD		21,600	\$3,024
213250267	ADP	DIRM-30MAGICPRO20-OU	*E31930+TD		21,400	\$2,996
212396762	ADP	4TXD2060A10NU**	BV**C9960		30,200	\$4,228
212396761	ADP	4TXD2060A10NU**	BV**C9(1,2)60+TXV		30,200	\$4,228
212396760	ADP	4TXD2060A10NU**	BV**C9960		30,200	\$4,228
212396759	ADP	4TXD2060A10NU**	BV**C9(1,2)60+TXV		30,200	\$4,228
211912012	ADP	38MURAQ24AB3*	CDP23H13P+TXV	59SC2D080E17**16	18,400	\$2,576
211871490	ADP	38MURAQ24AB3*	H,PE31(1,2)30+TXV	59SC2D060E17**14	18,400	\$2,576
212555856	ADP	4TXD2060A10NU**	H,TG52960		30,200	\$4,228
212555858	ADP	4TXD2060A10NU**	H,TE86960		30,200	\$4,228
212555859	ADP	4TXD2060A10NU**	H,TE88960		30,200	\$4,228
212544104	ADP	4TXD2036A10NU**	H,TG34936		15,800	\$2,212
212555857	ADP	4TXD2060A10NU**	H,TG52960		30,200	\$4,228
212555860	ADP	4TXD2060A10NU**	H,TE86960		30,200	\$4,228
212555861	ADP	4TXD2060A10NU**	H,TE88960		30,200	\$4,228
212396763	ADP	4TXD2036A10NU**	H,TG34936+TD		22,000	\$3,080
212396764	ADP	4TXD2060A10NU**	H,TG52960+TD		35,200	\$4,928
212396765	ADP	4TXD2060A10NU**	H,TE86960+TD		35,200	\$4,928
212396766	ADP	4TXD2060A10NU**	H,TE88960+TD		35,200	\$4,928
212396767	ADP	4TXD2036A10NU**	H,TG34936+TD		22,000	\$3,080
212396768	ADP	4TXD2060A10NU**	H,TG52960+TD		35,200	\$4,928

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212396769	ADP	4TXD2060A10NU**	H,TE86960+TD		35,200	\$4,928
212396770	ADP	4TXD2060A10NU**	H,TE88960+TD		35,200	\$4,928
212406525	ADP	4TXD2036A10NU**	H,TG34930+TD		15,800	\$2,212
212406526	ADP	4TXD2060A10NU**	H,TG52948+TD		30,200	\$4,228
212406527	ADP	4TXD2060A10NU**	H,TE86948+TD		30,200	\$4,228
212406528	ADP	4TXD2060A10NU**	H,TE88948+TD		30,200	\$4,228
212406529	ADP	4TXD2036A10NU**	H,TG34930+TD		15,800	\$2,212
212406530	ADP	4TXD2060A10NU**	H,TG52948+TD		30,200	\$4,228
212406531	ADP	4TXD2060A10NU**	H,TE86948+TD		30,200	\$4,228
212406532	ADP	4TXD2060A10NU**	H,TE88948+TD		30,200	\$4,228
212930527	ADP	MHD-24	HG21924+TD		20,800	\$2,912
212544102	ADP	4TXD2036A10NU**	H,TG34930		15,800	\$2,212
212897475	ADP	DIRM-30MAGICPRO20-OU	HE31930+TD		21,400	\$2,996
212897481	ADP	DIRM-30MAGICPRO20-OU	HG8J936+TD		21,600	\$3,024
212614016	ADP	DMA30HOS20230E7	HE31930+TD		21,400	\$2,996
212633392	ADP	FLEXX36HP230V1AO	CDP36K15P+TD		14,000	\$1,960
212925214	ADP	FLEXX36HP230V1AO	HG34936		13,400	\$1,876
212851768	ADP	AUH2436ZGDA*	HG34936+TD		21,000	\$2,940
212851779	ADP	AUH4860ZGDA*	HE49960+TD		34,200	\$4,788
212851783	ADP	AUH4860ZGDA*	HE50960+TD		34,200	\$4,788
212862155	ADP	AUH2436ZGDA*	HE7J924+TD		14,000	\$1,960
212862163	ADP	AUH4860ZGDA*	HE49948+TD		30,200	\$4,228
212862166	ADP	AUH4860ZGDA*	HE50948+TD		30,200	\$4,228
212862169	ADP	AUH4860ZGDA*	HE51948+TD		30,200	\$4,228
212862211	ADP	AUH4860ZGDA*	HE50960+TD		34,200	\$4,788
212862214	ADP	AUH4860ZGDA*	HE51960+TD		34,200	\$4,788
212862218	ADP	AUH4860ZGDA*	HG52960+TD		34,200	\$4,788
212862224	ADP	AUH4860ZGDA*	HE88960+TD		34,200	\$4,788
212862761	ADP	AUH2436ZGDA*	HE7J930+TD		14,000	\$1,960
212869777	ADP	AUH2436ZGDA*	HG33930+TD		14,000	\$1,960
213153604	ADP	WSEHV4860RA1-N	HG52960		34,200	\$4,788
213153602	ADP	WSEHV2436RA1-N	HG34936		21,000	\$2,940
213153601	ADP	WSEHV2436RA1-N	HG34936+TD		14,000	\$1,960
213153598	ADP	WSEHV2436RA1-C	HG34936		21,000	\$2,940
213153597	ADP	WSEHV2436RA1-C	HG34936+TD		14,000	\$1,960
217162313	AI AIR CONDITIONING	AO25-33N2-M1H	AAH-36N2-CM1		27,400	\$3,836

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
217162312	AI AIR CONDITIONING	AO25-24N2-M1H	AAH-24N2-BM1		16,900	\$2,366
217162311	AI AIR CONDITIONING	AO25-18N2-M1H	AAH-18N2-BM1		14,000	\$1,960
217162316	AI AIR CONDITIONING	ASO25-60N2-M2H	AAH-60N2-DM2		41,000	\$5,740
217162315	AI AIR CONDITIONING	ASO25-48N2-M2H	AAH-48N2-DM2		40,000	\$5,600
217162314	AI AIR CONDITIONING	ASO25-36N2-M2H	AAH-36N2-CM2		28,000	\$3,920
217162319	AI AIR CONDITIONING	AUO18-24N2-M3	AUA-24N2-A18		19,700	\$2,758
217162323	AI AIR CONDITIONING	AUO18-36N2-M3	AUA-36N2-B24		24,200	\$3,388
217162320	AI AIR CONDITIONING	AUO18-24N2-M3	AUA-24N2-B18		19,700	\$2,758
217162324	AI AIR CONDITIONING	AUO18-36N2-M3	AUA-36N2-C24		24,200	\$3,388
217162325	AI AIR CONDITIONING	AUO19-18N2-M3H	AUA-24N2-A18		15,200	\$2,128
217162326	AI AIR CONDITIONING	AUO19-24N2-M3H	AUA-24N2-A18		19,700	\$2,758
217162327	AI AIR CONDITIONING	AUO19-18N2-M3H	AUA-24N2-B18		15,200	\$2,128
217162328	AI AIR CONDITIONING	AUO19-24N2-M3H	AUA-24N2-B18		19,700	\$2,758
217162330	AI AIR CONDITIONING	AUO19-30N2-M3H	AUA-36N2-B24		25,000	\$3,500
217162331	AI AIR CONDITIONING	AUO19-36N2-M3H-S	AUA-36N2-B24		29,200	\$4,088
217162332	AI AIR CONDITIONING	AUO19-30N2-M3H	AUA-36N2-C24		25,000	\$3,500
217162333	AI AIR CONDITIONING	AUO19-36N2-M3H-S	AUA-36N2-C24		29,200	\$4,088
217162334	AI AIR CONDITIONING	AUO19-48N2-M3H	AUM-60N2-C28		34,400	\$4,816
217162335	AI AIR CONDITIONING	AUO19-60N2-M3H	AUM-60N2-C28		37,800	\$5,292
217162336	AI AIR CONDITIONING	AUO19-60N2-M3H	AUA-60N2-D28		36,000	\$5,040
217162341	AI AIR CONDITIONING	AUO19-18N2-M3H	AUE-18N2-MM3E		15,300	\$2,142
217162340	AI AIR CONDITIONING	AUO18-36N2-M3	AUE-36N2-LM3E		24,800	\$3,472
217162344	AI AIR CONDITIONING	AUO19-36N2-M3H-S	AUE-36N2-LM3E		30,200	\$4,228
217162343	AI AIR CONDITIONING	AUO19-30N2-M3H	AUE-30N2-LM3E		23,200	\$3,248
217162348	AI AIR CONDITIONING	AUO18-36N2-M3	AUP-36N2-KM3		24,600	\$3,444
217162349	AI AIR CONDITIONING	AUO19-18N2-M3H	AUP-18N2-HM3		15,000	\$2,100
217162352	AI AIR CONDITIONING	AUO19-36N2-M3H-S	AUP-36N2-KM3		31,200	\$4,368
217162351	AI AIR CONDITIONING	AUO19-30N2-M3H	AUP-30N2-JM3		24,000	\$3,360
215866737	AI AIR CONDITIONING	AO25-18N2-M1H	AW25-18N2-M1		14,400	\$2,016
215866736	AI AIR CONDITIONING	AO25-12N2-M1H	AW25-12N2-M1		10,000	\$1,400
213769950	AI AIR CONDITIONING	AO29-24N1-M1H	AW29-24N1-M1		21,200	\$2,968
213769948	AI AIR CONDITIONING	AO29-12N1-M1H	AW29-12N1-M1		11,400	\$1,596
213769952	AI AIR CONDITIONING	A2MO22-18N1-M1H	Heat pump without ducts		13,500	\$1,890
213769963	AI AIR CONDITIONING	A5MO22-48N1-M1H	Combination heat pumps with or without ducts		37,400	\$5,236
213769964	AI AIR CONDITIONING	A5MO22-55N1-M1H	Heat pump without ducts		34,800	\$4,872
213769965	AI AIR CONDITIONING	A5MO22-55N1-M1H	Heat pump with ducts		35,200	\$4,928

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213769966	AI AIR CONDITIONING	A5MO22-55N1-M1H	Combination heat pumps with or without ducts		35,000	\$4,900
213769922	AI AIR CONDITIONING	AUO18-18N1-M3H	AUH2-18N1-BM3E		13,500	\$1,890
213769923	AI AIR CONDITIONING	AUO18-24N1-M3H	AUH2-24N1-BM3E		19,200	\$2,688
213769924	AI AIR CONDITIONING	AUO18-30N1-M3H	AUH2-30N1-CM3E		21,000	\$2,940
213769944	AI AIR CONDITIONING	AO25-12N1-M1H	AW25-12N1-M1		10,300	\$1,442
213769945	AI AIR CONDITIONING	AO25-18N1-M1H	AW25-18N1-M1		11,100	\$1,554
213769946	AI AIR CONDITIONING	AO25-24N1-M1H	AW25-24N1-M1		18,900	\$2,646
213769949	AI AIR CONDITIONING	AO29-18N1-M1H	AW29-18N1-M1		12,300	\$1,722
213769954	AI AIR CONDITIONING	A2MO22-18N1-M1H	Combination heat pumps with or without ducts		14,700	\$2,058
213769961	AI AIR CONDITIONING	A5MO22-48N1-M1H	Heat pump without ducts		39,000	\$5,460
213769953	AI AIR CONDITIONING	A2MO22-18N1-M1H	Heat pump with ducts		16,000	\$2,240
213769962	AI AIR CONDITIONING	A5MO22-48N1-M1H	Heat pump with ducts		36,000	\$5,040
215866704	AI AIR CONDITIONING	AUO19-18N2-M3H	AUH2-18N2-BM3E		15,000	\$2,100
215866793	AI AIR CONDITIONING	AO25-12N2-M1H	AS-12N2-M1		9,800	\$1,372
215866705	AI AIR CONDITIONING	AUO19-24N2-M3H	AUH2-24N2-BM3E		20,000	\$2,800
215866708	AI AIR CONDITIONING	AUO19-36N2-M3H-S	AUH2-36N2-CM3E		31,800	\$4,452
215866791	AI AIR CONDITIONING	ASO25-60N2-M2H	AH-60N2-M1		45,000	\$6,300
215866790	AI AIR CONDITIONING	ASO25-48N2-M2H	AH-48N2-M1		45,000	\$6,300
215866789	AI AIR CONDITIONING	ASO25-36N2-M2H	AH-36N2-M1		31,600	\$4,424
215866788	AI AIR CONDITIONING	AO25-24N2-M1H	AH-24N2-M1		21,600	\$3,024
215866787	AI AIR CONDITIONING	AO25-18N2-M1H	AH-18N2-M1		15,000	\$2,100
215866784	AI AIR CONDITIONING	AO25-18N2-M1H	AL-18N2-M1		15,000	\$2,100
215866786	AI AIR CONDITIONING	AO25-12N2-M1H	AH-12N2-M1		10,200	\$1,428
215866783	AI AIR CONDITIONING	AO25-12N2-M1H	AL-12N2-M1		9,600	\$1,344
215866810	AI AIR CONDITIONING	A6MO21-48N2-M1	Heat pump with ducts		37,000	\$5,180
215866829	AI AIR CONDITIONING	A6MO23-55N2-M1H	Combination heat pumps with or without ducts		45,000	\$6,300
215866828	AI AIR CONDITIONING	A6MO23-55N2-M1H	Heat pump with ducts		45,000	\$6,300
215866827	AI AIR CONDITIONING	A6MO23-55N2-M1H	Heat pump without ducts		45,000	\$6,300
215866826	AI AIR CONDITIONING	A6MO23-48N2-M1H	Combination heat pumps with or without ducts		42,500	\$5,950
215866825	AI AIR CONDITIONING	A6MO23-48N2-M1H	Heat pump with ducts		44,500	\$6,230
215866824	AI AIR CONDITIONING	A6MO23-48N2-M1H	Heat pump without ducts		40,500	\$5,670
215866823	AI AIR CONDITIONING	A5MO23-36N2-M1H	Combination heat pumps with or without ducts		34,800	\$4,872
215866822	AI AIR CONDITIONING	A5MO23-36N2-M1H	Heat pump with ducts		33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215866821	AI AIR CONDITIONING	A5MO23-36N2-M1H	Heat pump without ducts		36,600	\$5,124
215866820	AI AIR CONDITIONING	A4MO23-27N2-M1H	Combination heat pumps with or without ducts		23,200	\$3,248
215866819	AI AIR CONDITIONING	A4MO23-27N2-M1H	Heat pump with ducts		23,000	\$3,220
215866818	AI AIR CONDITIONING	A4MO23-27N2-M1H	Heat pump without ducts		23,600	\$3,304
215866817	AI AIR CONDITIONING	A3MO23-18N2-M1H	Combination heat pumps with or without ducts		16,700	\$2,338
215866816	AI AIR CONDITIONING	A3MO23-18N2-M1H	Heat pump with ducts		17,000	\$2,380
215866815	AI AIR CONDITIONING	A3MO23-18N2-M1H	Heat pump without ducts		16,400	\$2,296
215866739	AI AIR CONDITIONING	AO25-33N2-M1H	AW25-33N2-M1		29,600	\$4,144
215866796	AI AIR CONDITIONING	AO25-24N2-M1H	AF-24N2-M1		20,200	\$2,828
215866774	AI AIR CONDITIONING	AO25-24N2-M1H	AC-24N2-M1		20,400	\$2,856
215866795	AI AIR CONDITIONING	AO25-18N2-M1H	AF-18N2-M1		14,400	\$2,016
215866794	AI AIR CONDITIONING	AO25-18N2-M1H	AS-16N2-M1		14,200	\$1,988
215866773	AI AIR CONDITIONING	AO25-18N2-M1H	AC-18N2-M1		14,900	\$2,086
215866780	AI AIR CONDITIONING	AO25-18N2-M1H	A1C-18N2-M1		14,500	\$2,030
215866772	AI AIR CONDITIONING	AO25-12N2-M1H	AC-12N2-M1		10,000	\$1,400
215866779	AI AIR CONDITIONING	AO25-12N2-M1H	A1C-12N2-M1		9,600	\$1,344
215866799	AI AIR CONDITIONING	ASO25-60N2-M2H	AF-60N2-M1		41,000	\$5,740
215866798	AI AIR CONDITIONING	ASO25-48N2-M2H	AF-48N2-M1		38,500	\$5,390
215866776	AI AIR CONDITIONING	ASO25-48N2-M2H	AC-48N2-M1		44,000	\$6,160
215866797	AI AIR CONDITIONING	ASO25-36N2-M2H	AF-36N2-M1		30,200	\$4,228
215866775	AI AIR CONDITIONING	ASO25-36N2-M2H	AC-36N2-M1		30,600	\$4,284
215866743	AI AIR CONDITIONING	AO35-18N2-M1H	AW35-18N2-M1		19,300	\$2,702
215866742	AI AIR CONDITIONING	AO35-12N2-M1H	AW35-12N2-M1		11,000	\$1,540
215866738	AI AIR CONDITIONING	AO25-24N2-M1H	AW25-24N2-M1		21,600	\$3,024
215866707	AI AIR CONDITIONING	AUO19-36N2-M3H	AUH2-36N2-CM3E		23,200	\$3,248
215866717	AI AIR CONDITIONING	AUO19-36N2-M3H-S	AUH3-36N2-BM3E		31,000	\$4,340
215866719	AI AIR CONDITIONING	AUO19-60N2-M3H	AUH3-60N2-CM3E		35,000	\$4,900
215866718	AI AIR CONDITIONING	AUO19-48N2-M3H	AUH3-48N2-CM3E		34,000	\$4,760
215866702	AI AIR CONDITIONING	AUO18-48N2-M3	AUH2-48N2-DM3E		32,400	\$4,536
215866699	AI AIR CONDITIONING	AUO18-24N2-M3	AUH2-24N2-BM3E		20,000	\$2,800
215866712	AI AIR CONDITIONING	AUO19-60N2-M3H	AUH2-60N2-DM3E		45,000	\$6,300
215866711	AI AIR CONDITIONING	AUO19-48N2-M3H-S	AUH2-60N2-DM3E		45,000	\$6,300
215866710	AI AIR CONDITIONING	AUO19-48N2-M3H	AUH2-48N2-DM3E		37,000	\$5,180
215866709	AI AIR CONDITIONING	AUO19-42N2-M3H-S	AUH2-48N2-DM3E		37,000	\$5,180
215866716	AI AIR CONDITIONING	AUO19-36N2-M3H	AUH3-36N2-BM3E		24,600	\$3,444
215866715	AI AIR CONDITIONING	AUO19-30N2-M3H	AUH3-30N2-BM3E		24,000	\$3,360

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215866706	AI AIR CONDITIONING	AUO19-30N2-M3H	AUH2-30N2-CM3E		23,800	\$3,332
215866714	AI AIR CONDITIONING	AUO19-24N2-M3H	AUH3-24N2-AM3E		19,000	\$2,660
215866713	AI AIR CONDITIONING	AUO19-18N2-M3H	AUH3-18N2-AM3E		14,700	\$2,058
213769925	AI AIR CONDITIONING	AUO18-36N1-M3H	AUH2-36N1-CM3E		31,800	\$4,452
213769927	AI AIR CONDITIONING	AUO18-60N1-M3H	AUH2-60N1-DM3E		42,000	\$5,880
213769926	AI AIR CONDITIONING	AUO18-48N1-M3H	AUH2-48N1-CM3E		36,000	\$5,040
213769960	AI AIR CONDITIONING	A4MO22-36N1-M1H	Combination heat pumps with or without ducts		28,600	\$4,004
213769958	AI AIR CONDITIONING	A4MO22-36N1-M1H	Heat pump without ducts		27,400	\$3,836
213769959	AI AIR CONDITIONING	A4MO22-36N1-M1H	Heat pump with ducts		30,000	\$4,200
213769957	AI AIR CONDITIONING	A3MO22-27N1-M1H	Combination heat pumps with or without ducts		22,600	\$3,164
213769955	AI AIR CONDITIONING	A3MO22-27N1-M1H	Heat pump without ducts		22,400	\$3,136
213769951	AI AIR CONDITIONING	AO29-33N1-M1H	AW29-33N1-M1		28,800	\$4,032
203446795	AIR-CON	ABXCI4H4S12	ABXEM4H4S12		7,500	\$1,050
203446800	AIR-CON	ABXCI4H4S24	ABXEM4H4S24		12,500	\$1,750
205150431	AIR-CON	AMSCI4H4S18	Heat pump with ducts		12,700	\$1,778
205150432	AIR-CON	AMSCI4H4S18	Heat pump without ducts		12,700	\$1,778
204462796	AIR-CON	AMSCI4H4S24	Combination heat pumps with or without ducts		14,800	\$2,072
204462794	AIR-CON	AMSCI4H4S24	Heat pump without ducts		15,000	\$2,100
204462799	AIR-CON	AMSCI4H4S36	Heat pump with ducts		23,000	\$3,220
204462795	AIR-CON	AMSCI4H4S36	Heat pump without ducts		22,400	\$3,136
205150427	AIR-CON	AMSCI4H4S42	Combination heat pumps with or without ducts		27,600	\$3,864
205150425	AIR-CON	AMSCI4H4S42	Heat pump with ducts		28,400	\$3,976
211583438	AIR-CON	ABHCI4H4S12	ABHEM4H4S12		6,800	\$952
211583435	AIR-CON	ABHCI4H4S18	ABHEM4H4S18		10,500	\$1,470
207026911	AIR-CON	ASDDI4H4S24	ASDVI4H4S24		16,000	\$2,240
207026916	AIR-CON	ASDDI4H4S48	ASDVI4H4S48		31,000	\$4,340
205129518	AIR-CON	ASLCI4H4S12	ASLEC4H4S12		7,600	\$1,064
205129519	AIR-CON	ASLCI4H4S18	ASLEC4H4S18		12,000	\$1,680
205129521	AIR-CON	ASLCI4H4S24	ASLEC4H4S24		19,000	\$2,660
205150423	AIR-CON	ASLCI4H4S36	ASLEC4H4S36		28,000	\$3,920
208106809	AirEase	4DHP2S48M-1P	Heat pump without ducts		36,000	\$5,040
216769823	AIREASE	A7SCP18V60P-**A	7EH60DX-***+TDR	A97US2V135D20S*	44,000	\$6,160
216769807	AIREASE	A7SCP18V60P-**A	7ED60DX-***+TDR	A97DS2V110C20S*	44,000	\$6,160
216769805	AIREASE	A7SCP18V60P-**A	7ED60DX-***+TDR	A97DS2V090C20S*	44,000	\$6,160

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216769803	AIREASE	A7SCP18V60P-**-A	7E[C,U]60DX-**-TDR	A97US2V135D20S*	44,000	\$6,160
216769801	AIREASE	A7SCP18V60P-**-A	7EH50/60CX-**-TDR	A97US2V090C20S*	44,500	\$6,230
216769799	AIREASE	A7SCP18V60P-**-A	7EH50/60CX-**-TDR	A97US2V110C20S*	44,000	\$6,160
216769797	AIREASE	A7SCP18V60P-**-A	7EH50/60CX-**-TDR	A97US2V080C20X*	44,500	\$6,230
216769795	AIREASE	A7SCP18V60P-**-A	7E[C,U]60CX-**-TDR	A97US2V090C20S*	44,000	\$6,160
216769793	AIREASE	A7SCP18V60P-**-A	7E[C,U]60CX-**-TDR	A97US2V110C20S*	43,500	\$6,090
216769791	AIREASE	A7SCP18V60P-**-A	7E[C,U]60CX-**-TDR	A97US2V080C20X*	44,000	\$6,160
216769769	AIREASE	A7SCP18V60P-**-A	7ED48CX-**-TDR	A97DS2V110C20S*	39,500	\$5,530
216769767	AIREASE	A7SCP18V60P-**-A	7ED48CX-**-TDR	A97DS2V090C20S*	39,500	\$5,530
216769763	AIREASE	A7SCP18V60P-**-A	7EH48CX-**-TDR	A97US2V110C20S*	39,500	\$5,530
216769761	AIREASE	A7SCP18V60P-**-A	7EH48CX-**-TDR	A97US2V080C20X*	39,500	\$5,530
216769759	AIREASE	A7SCP18V60P-**-A	7EH42CX-**-TDR	A97US2V090C20S*	39,500	\$5,530
216769757	AIREASE	A7SCP18V60P-**-A	7EH42CX-**-TDR	A97US2V110C20S*	39,500	\$5,530
216769755	AIREASE	A7SCP18V60P-**-A	7EH42CX-**-TDR	A97US2V080C20X*	39,500	\$5,530
216769753	AIREASE	A7SCP18V60P-**-A	7EH42CX-**-TDR	A97US2V080C16X*	39,500	\$5,530
216769751	AIREASE	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	A97US2V090C20S*	39,500	\$5,530
216769749	AIREASE	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	A97US2V110C20S*	39,000	\$5,460
216769747	AIREASE	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	A97US2V080C20X*	39,000	\$5,460
216769745	AIREASE	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	A97US2V080C16X*	39,000	\$5,460
216769743	AIREASE	A7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	A97US2V090C20S*	39,500	\$5,530
216769741	AIREASE	A7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	A97US2V110C20S*	39,500	\$5,530
216769739	AIREASE	A7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	A97US2V080C20X*	39,500	\$5,530
216769737	AIREASE	A7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	A97US2V080C16X*	39,500	\$5,530
216769765	AIREASE	A7SCP18V60P-**-A	7ED42BX-**-TDR	A97DS2V070B16S*	40,000	\$5,600
216769714	AIREASE	A7SCP18V36P-**-A	7ED42BX-**-TDR	A97DS2V070B16S*	29,000	\$4,060
216769712	AIREASE	A7SCP18V36P-**-A	7ED30/36BX-**-TDR	A97DS2V070B16S*	29,000	\$4,060
216769710	AIREASE	A7SCP18V36P-**-A	7EH36CX-**-TDR	A97US2V080C16X*	28,600	\$4,004
216769708	AIREASE	A7SCP18V36P-**-A	7EH36CX-**-TDR	A97US2V090C12S*	28,600	\$4,004
216769706	AIREASE	A7SCP18V36P-**-A	7EH36BX-**-TDR	A97US2V070B12S*	28,800	\$4,032
216769704	AIREASE	A7SCP18V36P-**-A	7EH36BX-**-TDR	A97US2V045B12S*	28,800	\$4,032
216769702	AIREASE	A7SCP18V36P-**-A	7EH36BX-**-TDR	A97US2V060B12X*	28,800	\$4,032
216769700	AIREASE	A7SCP18V36P-**-A	7EH36BX-**-TDR	A97US2V040B12X*	28,800	\$4,032
216769698	AIREASE	A7SCP18V36P-**-A	7EH30BX-**-TDR	A97US2V070B12S*	28,800	\$4,032
216769658	AIREASE	A7SCP18V24P-**-A	7EH30BX-**-TDR	A97US2V070B12S*	19,800	\$2,772
216769696	AIREASE	A7SCP18V36P-**-A	7EH30BX-**-TDR	A97US2V045B12S*	28,800	\$4,032
216769656	AIREASE	A7SCP18V24P-**-A	7EH30BX-**-TDR	A97US2V045B12S*	19,800	\$2,772
216769694	AIREASE	A7SCP18V36P-**-A	7EH30BX-**-TDR	A97US2V060B12X*	28,800	\$4,032
216769654	AIREASE	A7SCP18V24P-**-A	7EH30BX-**-TDR	A97US2V060B12X*	19,800	\$2,772

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216769692	AIREASE	A7SCP18V36P-**-A	7EH30BX-**-TDR	A97US2V040B12X*	28,800	\$4,032
216769652	AIREASE	A7SCP18V24P-**-A	7EH30BX-**-TDR	A97US2V040B12X*	19,800	\$2,772
216769650	AIREASE	A7SCP18V24P-**-A	7EH24BX-**-TDR	A97US2V070B12S*	19,800	\$2,772
216769648	AIREASE	A7SCP18V24P-**-A	7EH24BX-**-TDR	A97US2V045B12S*	19,800	\$2,772
216769646	AIREASE	A7SCP18V24P-**-A	7EH24BX-**-TDR	A97US2V060B12X*	19,800	\$2,772
216769644	AIREASE	A7SCP18V24P-**-A	7EH24BX-**-TDR	A97US2V040B12X*	19,800	\$2,772
216769690	AIREASE	A7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	A97US2V070B12S*	28,800	\$4,032
216769642	AIREASE	A7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	A97US2V070B12S*	19,800	\$2,772
216769688	AIREASE	A7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	A97US2V045B12S*	28,800	\$4,032
216769640	AIREASE	A7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	A97US2V045B12S*	19,800	\$2,772
216769686	AIREASE	A7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	A97US2V060B12X*	28,800	\$4,032
216769638	AIREASE	A7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	A97US2V060B12X*	19,800	\$2,772
216769684	AIREASE	A7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	A97US2V040B12X*	28,800	\$4,032
216769636	AIREASE	A7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	A97US2V040B12X*	19,800	\$2,772
216769682	AIREASE	A7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	A97US2V070B12S*	28,800	\$4,032
216769634	AIREASE	A7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	A97US2V070B12S*	19,800	\$2,772
216769680	AIREASE	A7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	A97US2V045B12S*	29,000	\$4,060
216769632	AIREASE	A7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	A97US2V045B12S*	19,800	\$2,772
216769678	AIREASE	A7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	A97US2V060B12X*	29,000	\$4,060
216769630	AIREASE	A7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	A97US2V060B12X*	19,800	\$2,772
216769676	AIREASE	A7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	A97US2V040B12X*	28,800	\$4,032
216769628	AIREASE	A7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	A97US2V040B12X*	19,800	\$2,772
216619067	AIREASE	A7SCP18V60P-**-A	7ED60DX-**-TDR		43,500	\$6,090
216619066	AIREASE	A7SCP18V60P-**-A	7ED50/60CX-**-TDR		43,500	\$6,090
216619065	AIREASE	A7SCP18V60P-**-A	7EH60DX-**-TDR		43,500	\$6,090
216619064	AIREASE	A7SCP18V60P-**-A	7EH50/60CX-**-TDR		43,500	\$6,090
216619063	AIREASE	A7SCP18V60P-**-A	7E[C,U]60DX-**-TDR		42,000	\$5,880
216619062	AIREASE	A7SCP18V60P-**-A	7ED48CX-**-TDR		40,000	\$5,600
216619061	AIREASE	A7SCP18V60P-**-A	7ED42BX-**-TDR		40,500	\$5,670
216619059	AIREASE	A7SCP18V60P-**-A	7EH48BX-**-TDR		40,500	\$5,670
216619058	AIREASE	A7SCP18V60P-**-A	7EH42CX-**-TDR		40,500	\$5,670
216619057	AIREASE	A7SCP18V60P-**-A	7EH42BX-**-TDR		40,000	\$5,600
216619056	AIREASE	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR		40,000	\$5,600
216619033	AIREASE	A7SCP18V60P-**-A	7AH2AV60PXC-**-		43,500	\$6,090
216619032	AIREASE	A7SCP18V60P-**-A	7AH1AE60PX-**-		43,000	\$6,020
216619031	AIREASE	A7SCP18V60P-**-A	7AH2AV48PXC-**-		38,000	\$5,320
216619030	AIREASE	A7SCP18V60P-**-A	7AH2AV42PXC-**-		38,500	\$5,390
216619029	AIREASE	A7SCP18V60P-**-A	7AH1AE48PX-**-		39,000	\$5,460

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216619028	AIREASE	A7SCP18V60P-**A	7AH1AV42PX-**		38,500	\$5,390
216619027	AIREASE	A7SCP18V60P-**A	7AH1AE42PX-**		39,000	\$5,460
216013461	AIREASE	A7SCP18V36P-**A	7AH1AV36PX-**		28,000	\$3,920
216619054	AIREASE	A7SCP18V36P-**A	7ED42BX-**+TDR		28,000	\$3,920
216619053	AIREASE	A7SCP18V36P-**A	7ED30/36BX-**+TDR		28,000	\$3,920
216619052	AIREASE	A7SCP18V36P-**A	7EH36CX-**+TDR		28,000	\$3,920
216619050	AIREASE	A7SCP18V36P-**A	7EH36AX-**+TDR		28,400	\$3,976
216619049	AIREASE	A7SCP18V36P-**A	7EH30BX-**+TDR		28,000	\$3,920
216619048	AIREASE	A7SCP18V36P-**A	7EH30AX-**+TDR		28,000	\$3,920
216619047	AIREASE	A7SCP18V36P-**A	7E[C,U]36AX-**+TDR		28,000	\$3,920
216619046	AIREASE	A7SCP18V36P-**A	7E[C,U]30BX-**+TDR		28,000	\$3,920
216619045	AIREASE	A7SCP18V36P-**A	7E[C,U]30AX-**+TDR		28,000	\$3,920
216619026	AIREASE	A7SCP18V36P-**A	7AH2AV42PXC-**		28,000	\$3,920
216619025	AIREASE	A7SCP18V36P-**A	7AH2AV36PXC-**		28,000	\$3,920
216619024	AIREASE	A7SCP18V36P-**A	7AH1AV42PX-**		28,000	\$3,920
216619023	AIREASE	A7SCP18V36P-**A	7AH1AE42PX-**		28,000	\$3,920
216619022	AIREASE	A7SCP18V36P-**A	7AH1AC42PX-**		28,400	\$3,976
216619021	AIREASE	A7SCP18V36P-**A	7AH1AE36PX-**		28,000	\$3,920
216619020	AIREASE	A7SCP18V36P-**A	7AH1AC36PX-**		28,400	\$3,976
216013460	AIREASE	A7SCP18V24P-**A	7AH1AV24PX-**		18,000	\$2,520
216619041	AIREASE	A7SCP18V24P-**A	7EH30AX-**+TDR		19,600	\$2,744
216619039	AIREASE	A7SCP18V24P-**A	7EH24AX-**+TDR		19,600	\$2,744
216619037	AIREASE	A7SCP18V24P-**A	7E[C,U]36BX-**+TDR		19,600	\$2,744
216619036	AIREASE	A7SCP18V24P-**A	7E[C,U]36AX-**+TDR		19,600	\$2,744
216619019	AIREASE	A7SCP18V24P-**A	7AH2AV30PXC-**		19,400	\$2,716
216619018	AIREASE	A7SCP18V24P-**A	7AH2AV24PXC-**		19,600	\$2,744
216619015	AIREASE	A7SCP18V24P-**A	7AH1AE24PX-**		19,200	\$2,688
216619014	AIREASE	A7SCP18V24P-**A	7AH1AC24PX-**		19,600	\$2,744
211729603	AIREASE	4SHP22LX124P-**A	BCE5E24M		14,100	\$1,974
211709579	AIREASE	4SHP22LX124P-**A	BCE7E30M*4X		14,300	\$2,002
216011729	AireForce	DXH12PSK3IH	DHH12PUK3IH		10,000	\$1,400
216011798	AireForce	DXH12PSK3IH	DKH12FMK3IH		10,000	\$1,400
215746285	AireForce	DXH18FMK3IH	Heat pump with ducts		15,000	\$2,100
215746280	AireForce	DXH18FMK3IH	Heat pump without ducts		16,000	\$2,240
215746286	AireForce	DXH18FMK3IH	Combination heat pumps with or without ducts		15,400	\$2,156
215746287	AireForce	DXH24FMK3IH	Heat pump with ducts		22,000	\$3,080
215746281	AireForce	DXH24FMK3IH	Heat pump without ducts		23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215746291	AireForce	DXH24FMK3IH	Combination heat pumps with or without ducts		22,800	\$3,192
215746288	AireForce	DXH30FMK3IH	Heat pump with ducts		27,200	\$3,808
215746282	AireForce	DXH30FMK3IH	Heat pump without ducts		28,000	\$3,920
215746292	AireForce	DXH30FMK3IH	Combination heat pumps with or without ducts		27,600	\$3,864
216011723	AireForce	DXH36ESK3IL	DHH36ESK3IL		27,400	\$3,836
215746289	AireForce	DXH36FMK3IH	Heat pump with ducts		36,000	\$5,040
215746283	AireForce	DXH36FMK3IH	Heat pump without ducts		36,000	\$5,040
215746293	AireForce	DXH36FMK3IH	Combination heat pumps with or without ducts		36,000	\$5,040
215746290	AireForce	DXH42FMK3IH	Heat pump with ducts		40,000	\$5,600
215746284	AireForce	DXH42FMK3IH	Heat pump without ducts		40,000	\$5,600
215746294	AireForce	DXH42FMK3IH	Combination heat pumps with or without ducts		40,000	\$5,600
211635187	AIREFORCE	GXH12(3.5)LSK4DH2	GHH12(3.5)LUK4DH2		10,000	\$1,400
211635192	AIREFORCE	GXH18(5.3)FMK4DH-1	Heat pump without ducts		15,000	\$2,100
211635193	AIREFORCE	GXH24(7.0)FMK4DH-1	Heat pump without ducts		23,600	\$3,304
211635194	AIREFORCE	GXH30(8.8)FMK4DH-1	Heat pump without ducts		27,200	\$3,808
211635195	AIREFORCE	GXH36(10.6)FMK4DH-1	Heat pump without ducts		30,800	\$4,312
211635196	AIREFORCE	GXH42(12.3)FMK4DH-1	Heat pump without ducts		35,600	\$4,984
206724404	AIREFORCE	GXH24-36MSK4DH	GMH24-**-MSK4DH1		20,000	\$2,800
206724405	AIREFORCE	GXH24-36MSK4DH	GMH**-36MSK4DH1		29,000	\$4,060
206724406	AIREFORCE	GXH48-60MSK4DH	GMH48-**-MSK4DH1		39,500	\$5,530
206724407	AIREFORCE	GXH48-60MSK4DH	GMH**-60MSK4DH1		44,000	\$6,160
215934367	AIRQUEST	H5H3V48*K*AAA*	EA*5X61M24A*+WALLCON	*97CMN0602120B*	40,500	\$5,670
215682836	AIRQUEST	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*80CSU1002120B*	56,000	\$7,840
215682286	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*97CTN1202422A*	46,000	\$6,440
215674147	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*96CTN1002122B*	42,500	\$5,950
215935657	AIRQUEST	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0902120B*	32,000	\$4,480
215939997	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN1002122A*	30,600	\$4,284
215676326	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL1352422B*	46,000	\$6,440

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215933227	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*96CTN0401410B*	30,000	\$4,200
215935647	AIRQUEST	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0901716B*	32,200	\$4,508
215939987	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN0802120A*	30,800	\$4,312
215676316	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL1102120B*	46,000	\$6,440
215682816	AIRQUEST	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*80CSU0601716B*	54,000	\$7,560
215682276	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*97CTN1002122A*	46,000	\$6,440
215933217	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN1202422B*	30,600	\$4,284
215682806	AIRQUEST	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*80CSU0401712B*	54,000	\$7,560
215682266	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*97CTN0802120A*	46,000	\$6,440
215674127	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN1002122B*	42,500	\$5,950
215939977	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN0801716A*	31,000	\$4,340
215676306	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL0902120B*	46,000	\$6,440
215935637	AIRQUEST	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0702120B*	32,200	\$4,508
215674117	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN0802120B*	42,500	\$5,950
215933207	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN1002122B*	30,600	\$4,284
215939967	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN0601716A*	31,400	\$4,396
215676296	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL0702120B*	46,500	\$6,510
215682796	AIRQUEST	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*96CTN0802120B*	56,000	\$7,840
215933197	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0802120B*	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215682256	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CSU1002120B*	46,000	\$6,440
215935627	AIRQUEST	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0701716B*	32,400	\$4,536
215682246	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CSU0802120B*	46,000	\$6,440
215939957	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*80CSU0601716B*	30,600	\$4,284
215676276	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*96CTN1202422B*	45,500	\$6,370
215674107	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN0801714B*	43,000	\$6,020
215935617	AIRQUEST	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0451712B*	33,000	\$4,620
215939947	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*80CSU0401712B*	30,600	\$4,284
215676266	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CMN1202422B*	45,500	\$6,370
215933187	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0801714B*	31,200	\$4,368
215674097	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN0602120B*	43,000	\$6,020
215682776	AIRQUEST	H5H0V60*K*AAA*	ESH5X60M12A*+WALLCON	*97CTN1002122A*	51,500	\$7,210
215935577	AIRQUEST	H5H3V36*K*AAA*	EVD5X36M17A*+WALLCON	*96CTN0601714B*	30,600	\$4,284
215933177	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0602120B*	31,000	\$4,340
215682236	AIRQUEST	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*96CTN0802120B*	46,000	\$6,440
215682766	AIRQUEST	H5H0V60*K*AAA*	ESH5X60M12A*+WALLCON	*97CTN0802120A*	51,500	\$7,210
215939937	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*96CTN0802120B*	30,800	\$4,312
215676256	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CMN0802120B*	45,500	\$6,370
215682226	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CTN1202422A*	45,500	\$6,370

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215674087	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*95CSU0802120B*	42,500	\$5,950
215935567	AIRQUEST	H5H3V36*K*AAA*	EVD5X36M17A*+WALLCON	*97CMN0601714B*	30,600	\$4,284
215934287	AIRQUEST	H5H3V48*K*AAA*	EA*5X61M21A*+WALLCON	*96CTN1002122B*	40,000	\$5,600
215939927	AIRQUEST	H5H3V36*K*AAA*	EA*5X61M24A*+WALLCON	*97CTN1202422A*	29,800	\$4,172
215933167	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0601714B*	30,200	\$4,228
215676246	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*95CSU1002122B*	45,500	\$6,370
215674077	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*95CSU0601716B*	43,000	\$6,020
215935557	AIRQUEST	H5H3V36*K*AAA*	EVD5X31M17A*+WALLCON	*96CTN0601714B*	31,800	\$4,452
215682216	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CTN1002122A*	45,500	\$6,370
215933157	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*95CSU1002122B*	30,400	\$4,256
215676236	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*95CSU0802120B*	46,000	\$6,440
215682206	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CTN0802120A*	46,000	\$6,440
215933147	AIRQUEST	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*95CSU0802120B*	30,800	\$4,312
215674067	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL1102120B*	42,500	\$5,950
215676226	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL1352422B*	45,500	\$6,370
215674057	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0902120B*	42,500	\$5,950
215682736	AIRQUEST	H5H0V60*K*AAA*	ESH5X60M12A*+WALLCON	*80CSU0601716B*	50,500	\$7,070
215676216	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL1102120B*	45,500	\$6,370
215674047	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0901716B*	42,500	\$5,950

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215676206	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL0902120B*	45,500	\$6,370
215674037	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0702120B*	42,500	\$5,950
215676196	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL0702120B*	46,000	\$6,440
215674027	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0701716B*	43,000	\$6,020
215676166	AIRQUEST	H5H0V48*K*AAA*	EVD5X48M21A*+WALLCON	*96CTN1002122B*	45,500	\$6,370
215674017	AIRQUEST	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0451712B*	43,500	\$6,090
215662864	AIRQUEST	H5H0V48*K*AAA*	FCMA5B48L0C*+WALLCON		42,000	\$5,880
207614978	AIRQUEST	DLCPRBH12AAK	DLFPHBH12XAK		10,400	\$1,456
207826653	AIRQUEST	DLCPRBH18AAK	DLFPHBH18XAK		20,200	\$2,828
206361915	AIRQUEST	DLCSR BH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361917	AIRQUEST	DLCSR BH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361916	AIRQUEST	DLCSR BH18AAK	DLFSHBH18XAK		11,100	\$1,554
210857463	AIRQUEST	DLCSR BH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857464	AIRQUEST	DLCSR BH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132708	AIRQUEST	DLCSR BH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948200	AIRQUEST	DLCSR BH12AAK	DLFSFBH12XAK		10,200	\$1,428
207683390	AIRQUEST	DLCSR BH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447687	AIRQUEST	DLCSR BH24AAK	DLFSCHH24XAK		21,200	\$2,968
208447691	AIRQUEST	DLCSR BH18AAK	DLFSCHH18XAK		15,000	\$2,100
208447686	AIRQUEST	DLCSR BH12AAK	DLFSCHH12XAK		10,000	\$1,400
206773905	AIRQUEST	HVH848GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	36,000	\$5,040
206773968	AIRQUEST	HVH848GKA2*	EA*4X60L24A*+WALLCON	*96CTN1002122A*	36,000	\$5,040
206773941	AIRQUEST	HVH848GKA2*	EA*4X60L24A*+WALLCON	*97CMN1002122A*	36,000	\$5,040
206774903	AIRQUEST	HVH848GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	36,000	\$5,040
211132748	AIRQUEST	DLCSR BH24AAK	DLFSDAH24XHK		21,000	\$2,940
206771903	AIRQUEST	HVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	31,400	\$4,396
206765557	AIRQUEST	HVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
211132706	AIRQUEST	DLCSR BH18AAK	DLFSDAH18XHK		15,700	\$2,198
206765548	AIRQUEST	HVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
206767544	AIRQUEST	HVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
206773529	AIRQUEST	HVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206767553	AIRQUEST	HVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206771723	AIRQUEST	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206774481	AIRQUEST	HVH848GKA2*	EHD4X48AAL+WALLCON	*80CTL1352422A*	37,200	\$5,208
206771273	AIRQUEST	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206771777	AIRQUEST	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206773421	AIRQUEST	HVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206773430	AIRQUEST	HVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	31,800	\$4,452
206773475	AIRQUEST	HVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206773520	AIRQUEST	HVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206771255	AIRQUEST	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206771354	AIRQUEST	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206773484	AIRQUEST	HVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	31,600	\$4,424
206774283	AIRQUEST	HVH848GKA2*	EN(A,D)4X48L24**+WALLCON	*96CTN1202422A*	37,200	\$5,208
206766034	AIRQUEST	HVH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
206771624	AIRQUEST	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206774822	AIRQUEST	HVH848GKA2*	EHD4X48AAL+WALLCON	*80CSU0802120A*	37,200	\$5,208
206771642	AIRQUEST	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206771858	AIRQUEST	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	31,400	\$4,396
206773511	AIRQUEST	HVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206773502	AIRQUEST	HVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206771894	AIRQUEST	HVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
215324774	AIRQUEST	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215323734	AIRQUEST	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215319155	AIRQUEST	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215319154	AIRQUEST	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215319153	AIRQUEST	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215319163	AIRQUEST	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215319161	AIRQUEST	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215319151	AIRQUEST	D5CURAH48AAK	D5FUAAH48XAK		32,400	\$4,536
215319148	AIRQUEST	D5CURAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215319146	AIRQUEST	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215319145	AIRQUEST	D5CUHAH60AAK	D5FUAAH60XAK		45,000	\$6,300
215319144	AIRQUEST	D5CUHAH48AAK	D5FUAAH48XAK		37,000	\$5,180
215319143	AIRQUEST	D5CUHAH36AAK	D5FUAAH36XAK		31,800	\$4,452
215319142	AIRQUEST	D5CUHAH30AAK	D5FUAAH30XAK		23,800	\$3,332
215319141	AIRQUEST	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215319140	AIRQUEST	D5CUHAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215319139	AIRQUEST	D5CUHAH18AAK	D5FUAAH18XAK		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215324785	AIRQUEST	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324784	AIRQUEST	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324781	AIRQUEST	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324779	AIRQUEST	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324777	AIRQUEST	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324776	AIRQUEST	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324775	AIRQUEST	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324772	AIRQUEST	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324771	AIRQUEST	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324770	AIRQUEST	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324769	AIRQUEST	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215413340	AIRQUEST	D5CPRAH18AA	D5FPHAH18XAK		19,300	\$2,702
215413339	AIRQUEST	D5CPRAH12AAK	D5FPHAH12XAK		11,000	\$1,540
215357579	AIRQUEST	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357578	AIRQUEST	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357577	AIRQUEST	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215324780	AIRQUEST	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324773	AIRQUEST	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215357605	AIRQUEST	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357588	AIRQUEST	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357587	AIRQUEST	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357586	AIRQUEST	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357585	AIRQUEST	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357584	AIRQUEST	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357583	AIRQUEST	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357582	AIRQUEST	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357581	AIRQUEST	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357580	AIRQUEST	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357576	AIRQUEST	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357575	AIRQUEST	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357574	AIRQUEST	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357570	AIRQUEST	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357569	AIRQUEST	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357568	AIRQUEST	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324822	AIRQUEST	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324820	AIRQUEST	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324819	AIRQUEST	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324817	AIRQUEST	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324816	AIRQUEST	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324783	AIRQUEST	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324778	AIRQUEST	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324823	AIRQUEST	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324821	AIRQUEST	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324818	AIRQUEST	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324768	AIRQUEST	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215319162	AIRQUEST	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215319158	AIRQUEST	D5CSHAH33AAK	D5FSAAH36XBK		27,400	\$3,836
215319157	AIRQUEST	D5CSHAH24AAK	D5FSAAH24XBK		16,900	\$2,366
215319156	AIRQUEST	D5CSHAH18AAK	D5FSAAH18XBK		14,000	\$1,960
212982627	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MSU0601716A*	23,200	\$3,248
212982939	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MSU0802120A*	23,200	\$3,248
212982399	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80MSU0401712A*	12,200	\$1,708
212982375	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80MSU0401712A*	12,200	\$1,708
213079180	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0601716A*	29,200	\$4,088
213079312	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0802120A*	29,200	\$4,088
212982363	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0401712A*	19,100	\$2,674
213078928	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	29,400	\$4,116
213078904	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU1002120A*	29,600	\$4,144
213078880	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MSU1002120A*	29,200	\$4,088
212988098	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	23,600	\$3,304
212988062	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96MSN1002120A*	23,600	\$3,304
212982387	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80MSU0401712A*	12,400	\$1,736
212982699	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MSU0601716A*	19,000	\$2,660
212982435	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU0401712A*	12,300	\$1,722
212982219	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80MSU0401712A*	23,400	\$3,276
212981679	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	23,600	\$3,304
212982423	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU0401712A*	12,400	\$1,736
212982663	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MSU0601716A*	23,200	\$3,248
212982999	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	23,600	\$3,304
212982135	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80MSU0401712A*	23,400	\$3,276
212982171	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MSU0401712A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079060	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0401712A*	29,400	\$4,116
213079048	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80MSU0401712A*	29,200	\$4,088
213078988	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MSU0401712A*	29,000	\$4,060
213078952	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80MSU0401712A*	29,400	\$4,116
212988038	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96MSN1002120A*	23,400	\$3,276
212982339	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU0401712A*	19,100	\$2,674
213079324	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0802120A*	29,200	\$4,088
213079144	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MSU0601716A*	29,000	\$4,060
212981595	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MSU1002120A*	23,200	\$3,248
213078856	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MSU1002120A*	29,200	\$4,088
213079276	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MSU0802120A*	29,000	\$4,060
213079012	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MSU0401712A*	29,000	\$4,060
212988050	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*96MSN1002120A*	23,600	\$3,304
212982723	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0601716A*	19,000	\$2,660
212981619	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MSU1002120A*	23,200	\$3,248
212981535	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MSU1002120A*	29,000	\$4,060
212982243	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80MSU0401712A*	19,400	\$2,716
212981607	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80MSU1002120A*	23,600	\$3,304
212982711	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80MSU0601716A*	18,600	\$2,604
212982687	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	23,400	\$3,276
212982639	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80MSU0601716A*	23,400	\$3,276
212982411	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80MSU0401712A*	12,300	\$1,722
212982351	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU0401712A*	19,100	\$2,674
212982327	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU0401712A*	19,400	\$2,716
212982303	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80MSU0401712A*	18,800	\$2,632
212982291	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MSU0401712A*	19,100	\$2,674
212982279	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80MSU0401712A*	19,000	\$2,660
212982267	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80MSU0401712A*	19,100	\$2,674
209852142	AIRQUEST	DLCURAH36ABK	DLFUAAH36XAK		30,400	\$4,256
213079252	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MSU0802120A*	29,000	\$4,060
213079240	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MSU0802120A*	29,400	\$4,116
213079228	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MSU0802120A*	29,400	\$4,116
213079216	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MSU0802120A*	29,000	\$4,060
212982975	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MSU0802120A*	23,200	\$3,248
212982315	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80MSU0401712A*	18,700	\$2,618
212982159	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80MSU0401712A*	23,400	\$3,276
213079168	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	29,400	\$4,116
213079108	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MSU0601716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982255	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80MSU0401712A*	18,600	\$2,604
212982147	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MSU0401712A*	23,200	\$3,248
213079300	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	29,400	\$4,116
213079084	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MSU0601716A*	29,400	\$4,116
213079096	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MSU0601716A*	29,000	\$4,060
213079204	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MSU0802120A*	29,400	\$4,116
213080449	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002122A*	29,200	\$4,088
213080377	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002122A*	29,400	\$4,116
213080306	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002120A*	29,400	\$4,116
213079264	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MSU0802120A*	29,000	\$4,060
213078940	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU1002120A*	29,200	\$4,088
213079000	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MSU0401712A*	29,400	\$4,116
212969728	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412B*	19,300	\$2,702
213080404	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002122A*	29,400	\$4,116
213078964	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MSU0401712A*	29,400	\$4,116
210470565	AIRQUEST	HVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL1352422A*	31,200	\$4,368
213080440	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002122A*	29,200	\$4,088
213080413	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002122A*	29,200	\$4,088
213080354	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002120A*	29,200	\$4,088
213080342	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	29,400	\$4,116
213079156	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU0601716A*	29,600	\$4,144
210470532	AIRQUEST	HVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470378	AIRQUEST	HVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470433	AIRQUEST	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0701716A*	31,400	\$4,396
213078868	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MSU1002120A*	29,400	\$4,116
213080431	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002122A*	29,400	\$4,116
213080318	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002120A*	29,200	\$4,088
213080294	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002120A*	29,400	\$4,116
213080282	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002120A*	29,200	\$4,088
213080270	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002120A*	29,400	\$4,116
212982087	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MSU0401712A*	28,800	\$4,032
213079132	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MSU0601716A*	29,000	\$4,060
213079072	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0401712A*	29,200	\$4,088
212988014	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002120A*	29,000	\$4,060
212988002	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002120A*	29,000	\$4,060
212988217	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002122A*	29,000	\$4,060
210473241	AIRQUEST	HVH825GKA3*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
213080395	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002122A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080386	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002122A*	29,200	\$4,088
213080366	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002120A*	29,200	\$4,088
213078832	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MSU1002120A*	29,400	\$4,116
212988226	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002122A*	29,000	\$4,060
212988074	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96MSN1002120A*	23,200	\$3,248
210470521	AIRQUEST	HVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470389	AIRQUEST	HVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470499	AIRQUEST	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0901716A*	31,200	\$4,368
210470235	AIRQUEST	HVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	31,000	\$4,340
210470268	AIRQUEST	HVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	31,000	\$4,340
210473098	AIRQUEST	HVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
210470444	AIRQUEST	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210473109	AIRQUEST	HVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210470554	AIRQUEST	HVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470246	AIRQUEST	HVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU1002122A*	31,000	\$4,340
210470279	AIRQUEST	HVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL1352422A*	31,000	\$4,340
213078976	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80MSU0401712A*	29,200	\$4,088
211712154	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*95ESN1002120A*	23,600	\$3,304
211712142	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ESU1002120A*	23,200	\$3,248
211712130	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*95ESU1002120A*	23,400	\$3,276
211712119	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80VSL0701716A*	23,400	\$3,276
211712108	AIRQUEST	DLCURAH30ABK	EA*4X36L21A*	*80ESU1002120A*	23,600	\$3,304
211712096	AIRQUEST	DLCURAH30ABK	EA*4X36L21A*	*95ESU1002120A*	23,600	\$3,304
211709686	AIRQUEST	DLCURAH30ABK	FJMA4*30L*B*		23,400	\$3,276
213353857	AIRQUEST	DLCURAH36ABK	F5MA4*42L*C*		29,200	\$4,088
213353847	AIRQUEST	DLCURAH36ABK	F5MA4*36L*B*		29,400	\$4,116
213249337	AIRQUEST	DLCURAH36ABK	FEVA0036**+NAVA43601CK		29,400	\$4,116
213080875	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU0802120A*	29,200	\$4,088
213080863	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0802120A*	29,200	\$4,088
213080851	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	29,400	\$4,116
213080839	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*95MSU0802120A*	29,600	\$4,144
213080827	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95MSU0802120A*	29,200	\$4,088
213080815	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95MSU0802120A*	29,400	\$4,116
213080803	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95MSU0802120A*	29,400	\$4,116
213080791	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95MSU0802120A*	29,200	\$4,088
213080779	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95MSU0802120A*	29,400	\$4,116
213080767	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0601716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080755	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	29,600	\$4,144
213080743	AIRQUEST	DLCURAH36ABK	END4X42L17**	*95MSU0601716A*	29,400	\$4,116
213080707	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95MSU0601716A*	29,200	\$4,088
213080695	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95MSU0601716A*	29,400	\$4,116
213080683	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95MSU0601716A*	29,200	\$4,088
213080671	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*95MSU0601716A*	29,400	\$4,116
213080659	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95MSU0601716A*	29,400	\$4,116
213080647	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*95MSU0601716A*	29,600	\$4,144
213080635	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0401712A*	29,400	\$4,116
213080623	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0401712A*	29,600	\$4,144
213080611	AIRQUEST	DLCURAH36ABK	END4X42L17**	*95MSU0401712A*	29,400	\$4,116
213080575	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95MSU0401712A*	29,200	\$4,088
213080563	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95MSU0401712A*	29,200	\$4,088
211274897	AIRQUEST	DLCURAH30ABK	FVM4X48***L		23,000	\$3,220
213080551	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95MSU0401712A*	29,600	\$4,144
213080539	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95MSU0401712A*	29,200	\$4,088
213080527	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*95MSU0401712A*	29,400	\$4,116
213080515	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95MSU0401712A*	29,600	\$4,144
213080503	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*95MSU0401712A*	29,600	\$4,144
213080493	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1402422A*	29,200	\$4,088
213080483	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96MSN1402422A*	29,400	\$4,116
213080471	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1202422A*	29,200	\$4,088
213080459	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96MSN1202422A*	29,400	\$4,116
213080258	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN0802120A*	29,200	\$4,088
213080246	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0802120A*	29,200	\$4,088
213080234	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0802120A*	29,400	\$4,116
211222779	AIRQUEST	DLCURAH30ABK	FVM4X24***L		23,600	\$3,304
213080210	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96MSN0802120A*	29,000	\$4,060
213080198	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96MSN0802120A*	29,000	\$4,060
211222763	AIRQUEST	DLCURAH30ABK	FMA4X36**AL*		23,800	\$3,332
213080186	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96MSN0802120A*	29,200	\$4,088
213080174	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96MSN0802120A*	29,400	\$4,116
211222755	AIRQUEST	DLCURAH30ABK	FMA4X30**AL*		23,800	\$3,332
213080162	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96MSN0802120A*	29,400	\$4,116
213080150	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96MSN0802120A*	29,200	\$4,088
213080138	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96MSN0802120A*	29,600	\$4,144
211222747	AIRQUEST	DLCURAH30ABK	FM(C,U)4Z36**AL*		23,600	\$3,304
213080126	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0801716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080114	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	29,600	\$4,144
211222739	AIRQUEST	DLCURAH30ABK	FM(C,U)4Z30**AL*		23,600	\$3,304
213080102	AIRQUEST	DLCURAH36ABK	END4X42L17**	*96MSN0801716A*	29,400	\$4,116
211222723	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	OMV098J12*	23,200	\$3,248
211222715	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	OLV098A12*	23,200	\$3,248
213080066	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96MSN0801716A*	29,000	\$4,060
213080054	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96MSN0801716A*	29,200	\$4,088
211222707	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122A*	23,000	\$3,220
213080042	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96MSN0801716A*	29,400	\$4,116
213080030	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96MSN0801716A*	29,200	\$4,088
211222699	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120A*	23,200	\$3,248
213080018	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96MSN0801716A*	29,400	\$4,116
213080006	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96MSN0801716A*	29,600	\$4,144
211222691	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120A*	23,000	\$3,220
213079994	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*96MSN0801716A*	29,600	\$4,144
213079984	AIRQUEST	DLCURAH36ABK	END4X42L17**	*96MSN0601412A*	29,600	\$4,144
213079964	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96MSN0601412A*	29,400	\$4,116
211222683	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VTN0601714A*	23,200	\$3,248
213079954	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*96MSN0601412A*	29,600	\$4,144
213079943	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1202420A*	29,200	\$4,088
211222675	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*95ESU0601716A*	23,400	\$3,276
213079932	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*92MSN1202420A*	29,000	\$4,060
211222667	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*95ESU0401712A*	23,200	\$3,248
213079921	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*92MSN1202420A*	29,400	\$4,116
213079911	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002122A*	29,200	\$4,088
211222659	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120A*	23,200	\$3,248
213079902	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002122A*	29,200	\$4,088
213079893	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002122A*	29,400	\$4,116
211222651	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120A*	23,000	\$3,220
213079875	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002122A*	29,000	\$4,060
211222643	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716A*	23,200	\$3,248
213079866	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002122A*	29,400	\$4,116
213079857	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002122A*	29,400	\$4,116
213079848	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002122A*	29,000	\$4,060
211222635	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VSN0601714A*	23,200	\$3,248
213079839	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002122A*	29,400	\$4,116
213079828	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002120A*	29,200	\$4,088
211222627	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*95ESN0802120A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079816	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002120A*	29,200	\$4,088
213079804	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	29,400	\$4,116
211222619	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*95ESN0601714A*	23,200	\$3,248
213079792	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN1002120A*	29,600	\$4,144
213079780	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002120A*	29,000	\$4,060
211222611	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*92ESN1002120A*	23,200	\$3,248
213079768	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002120A*	29,400	\$4,116
213079756	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002120A*	29,400	\$4,116
211222603	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*92ESN0802120A*	23,200	\$3,248
213079744	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002120A*	29,000	\$4,060
211222595	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*92ESN0801716A*	23,400	\$3,276
213079732	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002120A*	29,400	\$4,116
213079722	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN0802120A*	29,200	\$4,088
211222587	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*92ESN0601714A*	23,400	\$3,276
213079712	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0802120A*	29,200	\$4,088
213079702	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	29,400	\$4,116
211222563	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122A*	23,200	\$3,248
213079692	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN0802120A*	29,600	\$4,144
213079682	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92MSN0802120A*	29,200	\$4,088
211222555	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120A*	23,200	\$3,248
213079672	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*92MSN0802120A*	29,400	\$4,116
213079662	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92MSN0802120A*	29,400	\$4,116
211222547	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716A*	23,200	\$3,248
213079652	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92MSN0802120A*	29,200	\$4,088
213079642	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92MSN0802120A*	29,400	\$4,116
211222539	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ESU0802120A	23,400	\$3,276
213079630	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0801716A*	29,200	\$4,088
213079618	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0801716A*	29,400	\$4,116
211222531	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ESU0601716A	23,200	\$3,248
213079606	AIRQUEST	DLCURAH36ABK	END4X42L17**	*92MSN0801716A*	29,200	\$4,088
211222523	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ESU0401712A*	23,200	\$3,248
211222515	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VSL0902120A*	23,200	\$3,248
213079570	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92MSN0801716A*	29,000	\$4,060
213079558	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92MSN0801716A*	29,400	\$4,116
211222507	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VSL0702120A*	23,200	\$3,248
213079546	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92MSN0801716A*	29,000	\$4,060
213079534	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*92MSN0801716A*	29,400	\$4,116
211222499	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VSL0701716A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079522	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92MSN0801716A*	29,400	\$4,116
213079510	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*92MSN0801716A*	29,400	\$4,116
211222491	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VSL0451716A*	23,200	\$3,248
213079498	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0601714A*	29,200	\$4,088
213079486	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0601714A*	29,400	\$4,116
211222483	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	23,200	\$3,248
213079474	AIRQUEST	DLCURAH36ABK	END4X42L17**	*92MSN0601714A*	29,400	\$4,116
211222475	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
211222467	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
213079438	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92MSN0601714A*	29,200	\$4,088
213079426	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92MSN0601714A*	29,400	\$4,116
211222459	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
213079412	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92MSN0601714A*	29,200	\$4,088
213079400	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601714A*	29,400	\$4,116
211222451	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
213079388	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92MSN0601714A*	29,400	\$4,116
213079376	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601714A*	29,400	\$4,116
211222443	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
213079366	AIRQUEST	DLCURAH36ABK	END4X42L17**	*92MSN0601412A*	29,400	\$4,116
213079346	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601412A*	29,400	\$4,116
211222435	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
213079336	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601412A*	29,600	\$4,144
211222395	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	OMV098J12*	23,400	\$3,276
211222387	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*96VTN0601714A*	23,400	\$3,276
211222379	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*95ESU0601716A*	23,400	\$3,276
211222371	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*95ESU0401712A*	23,400	\$3,276
211222363	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716A*	23,400	\$3,276
211222355	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*95ESN0601714A*	23,400	\$3,276
213079192	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0601716A*	29,200	\$4,088
211222347	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*92ESN0801716A*	23,400	\$3,276
211222339	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601714A*	23,400	\$3,276
213079120	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MSU0601716A*	29,200	\$4,088
211222331	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601412A*	23,400	\$3,276
211222323	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716A*	23,200	\$3,248
211222315	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412A*	23,400	\$3,276
211222307	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80ESU0601716A*	23,400	\$3,276
211222299	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80ESU0401712A*	23,400	\$3,276
211222291	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451716A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211222283	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412A*	23,400	\$3,276
211222275	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	23,200	\$3,248
211222267	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	23,400	\$3,276
213078916	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80MSU1002120A*	29,400	\$4,116
213078892	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	29,600	\$4,144
213078844	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80MSU1002120A*	29,400	\$4,116
213078820	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80MSU1002120A*	29,600	\$4,144
213078810	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1552420A*	29,200	\$4,088
211222259	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	23,400	\$3,276
213078800	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1552420A*	29,000	\$4,060
213078790	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	29,400	\$4,116
213078779	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1352420A*	29,200	\$4,088
213078768	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	29,400	\$4,116
213078758	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102420A*	29,200	\$4,088
213078748	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102420A*	29,000	\$4,060
213078738	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	29,400	\$4,116
213078726	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102120A*	29,200	\$4,088
213078714	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)1102120A*	29,200	\$4,088
213078702	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	29,400	\$4,116
213078678	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078666	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078654	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078642	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078630	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078618	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078606	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078596	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902420A*	29,200	\$4,088
213078587	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	29,400	\$4,116
213078577	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902120A*	29,200	\$4,088
213078566	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902120A*	29,200	\$4,088
213078555	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	29,400	\$4,116
211222145	AIRQUEST	DLCURAH30ABK	EA*4X36L21A*	*92ESN1002120A*	23,400	\$3,276
213078533	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
211222135	AIRQUEST	DLCURAH30ABK	EA*4X36L21A*	*92ESN0802120A*	23,400	\$3,276
213078522	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078511	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078500	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078489	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078478	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902116A*	29,200	\$4,088
211712501	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078467	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902116A*	29,200	\$4,088
213078456	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	29,400	\$4,116
213078434	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
211712488	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	23,400	\$3,276
213078423	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078412	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078401	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
211712475	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078390	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078378	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0901714A*	29,200	\$4,088
213078366	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0901714A*	29,400	\$4,116
211712462	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	23,400	\$3,276
213078354	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0901714A*	29,200	\$4,088
213078318	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
213078306	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078294	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
213078282	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
211221996	AIRQUEST	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078270	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078258	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078248	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0702116A*	29,200	\$4,088
213078238	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0702116A*	29,200	\$4,088
213078228	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0702116A*	29,400	\$4,116
211712425	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122A*	23,400	\$3,276
213078208	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
213078198	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078188	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
211221979	AIRQUEST	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078178	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
213078168	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078156	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701716A*	29,200	\$4,088
213078144	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	29,400	\$4,116
213078132	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701716A*	29,400	\$4,116
213078120	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	29,600	\$4,144
213078108	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	29,600	\$4,144
213078096	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078084	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078072	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078060	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078048	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078036	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	29,600	\$4,144
213078025	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701712A*	29,200	\$4,088
213078014	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	29,400	\$4,116
213078003	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701712A*	29,400	\$4,116
211712380	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80VTLO701716A*	23,400	\$3,276
213077970	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077959	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077948	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077937	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077926	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077915	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
211712368	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*95ESN1002120A*	23,600	\$3,304
213077903	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701412A*	29,400	\$4,116
213077879	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
211712538	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*92ESN0802120A*	23,400	\$3,276
213077867	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
213077855	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0451412A*	29,400	\$4,116
211712356	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*95ESN0802120A*	23,400	\$3,276
213077831	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	29,400	\$4,116
213077818	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	29,600	\$4,144
213077807	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422B*	29,200	\$4,088
213077795	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422B*	29,400	\$4,116
213077783	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122B*	29,200	\$4,088
213077773	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122B*	29,200	\$4,088
213077763	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	29,400	\$4,116
213077753	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN1002122B*	29,600	\$4,144
213077743	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122B*	29,000	\$4,060
213077733	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122B*	29,400	\$4,116
213077723	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122B*	29,400	\$4,116
213077713	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122B*	29,000	\$4,060
213077703	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122B*	29,400	\$4,116
213077692	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120B*	29,200	\$4,088
213077679	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120B*	29,200	\$4,088
213077666	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712330	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80ESU0401712A*	23,400	\$3,276
213077640	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120B*	29,000	\$4,060
213077627	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120B*	29,400	\$4,116
213077614	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120B*	29,400	\$4,116
213077601	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120B*	29,000	\$4,060
213077588	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120B*	29,400	\$4,116
211712550	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*92ESN1002120A*	23,400	\$3,276
213077576	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120B*	29,200	\$4,088
213077565	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120B*	29,200	\$4,088
211712318	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80ESU1002120A*	23,600	\$3,304
213077554	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	29,400	\$4,116
213077543	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN0802120B*	29,600	\$4,144
213077532	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120B*	29,000	\$4,060
213077521	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120B*	29,200	\$4,088
213077510	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120B*	29,400	\$4,116
213077499	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120B*	29,400	\$4,116
213077488	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120B*	29,200	\$4,088
213077477	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120B*	29,400	\$4,116
213077465	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0801716B*	29,200	\$4,088
213077452	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0801716B*	29,600	\$4,144
213077439	AIRQUEST	DLCURAH36ABK	END4X42L17**	*96VTN0801716B*	29,400	\$4,116
211712294	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*95ESU1002120A*	23,600	\$3,304
213077400	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VTN0801716B*	29,200	\$4,088
213077387	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716B*	29,400	\$4,116
213077374	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VTN0801716B*	29,200	\$4,088
213077361	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96VTN0801716B*	29,400	\$4,116
213077348	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VTN0801716B*	29,400	\$4,116
213077335	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*96VTN0801716B*	29,600	\$4,144
213077323	AIRQUEST	DLCURAH36ABK	END4X42L17**	*96VTN0601412B*	29,400	\$4,116
211712273	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80VSL0702120A*	23,400	\$3,276
213077301	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601412B*	29,400	\$4,116
213077290	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601412B*	29,600	\$4,144
211712562	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*95ESN0601714A*	23,600	\$3,304
213077279	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0401712B*	29,400	\$4,116
213077268	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VTN0401712B*	29,200	\$4,088
213077257	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422B*	29,200	\$4,088
213077247	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422B*	29,000	\$4,060
213077237	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077227	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120B*	29,200	\$4,088
213077217	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120B*	29,200	\$4,088
213077207	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	29,400	\$4,116
213077187	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120B*	29,000	\$4,060
213077177	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120B*	29,000	\$4,060
213077167	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120B*	29,400	\$4,116
213077157	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120B*	29,400	\$4,116
213077147	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120B*	29,000	\$4,060
213077137	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120B*	29,400	\$4,116
213077127	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120B*	29,200	\$4,088
213077117	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120B*	29,200	\$4,088
213077107	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	29,400	\$4,116
213077097	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*96VSN0802120B*	29,600	\$4,144
213077087	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120B*	29,000	\$4,060
213077077	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120B*	29,200	\$4,088
213077067	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120B*	29,400	\$4,116
213077057	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120B*	29,400	\$4,116
213077047	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120B*	29,200	\$4,088
213077037	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120B*	29,400	\$4,116
213077027	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716B*	29,200	\$4,088
211712231	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	23,600	\$3,304
213077017	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716B*	29,600	\$4,144
213077007	AIRQUEST	DLCURAH36ABK	END4X42L17**	*96VSN0801716B*	29,400	\$4,116
213076977	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716B*	29,200	\$4,088
213076967	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716B*	29,400	\$4,116
213076957	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716B*	29,200	\$4,088
213076947	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716B*	29,400	\$4,116
213076937	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716B*	29,400	\$4,116
213076927	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716B*	29,600	\$4,144
213076917	AIRQUEST	DLCURAH36ABK	END4X42L17**	*96VSN0601412B*	29,400	\$4,116
213076897	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412B*	29,400	\$4,116
213076887	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601412B*	29,600	\$4,144
211712208	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*96VSN0801716A*	23,400	\$3,276
213076877	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0401712B*	29,400	\$4,116
213076867	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VSN0401712B*	29,200	\$4,088
213076850	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122B*	29,200	\$4,088
213076838	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122B*	29,200	\$4,088
213076826	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076802	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122B*	29,000	\$4,060
213076790	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122B*	29,000	\$4,060
211712586	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80ESU0601716A	23,400	\$3,276
213076778	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122B*	29,200	\$4,088
213076766	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122B*	29,400	\$4,116
213076754	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122B*	29,400	\$4,116
213076742	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122B*	29,200	\$4,088
213076730	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122B*	29,400	\$4,116
213076719	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120B*	29,200	\$4,088
213076708	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120B*	29,200	\$4,088
213076697	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	29,400	\$4,116
213076686	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*80VTL0902120B*	29,600	\$4,144
213076675	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120B*	29,200	\$4,088
213076664	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120B*	29,400	\$4,116
213076653	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120B*	29,400	\$4,116
213076642	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120B*	29,200	\$4,088
211712166	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
213076631	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120B*	29,400	\$4,116
211712658	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80VSL0702120A*	23,400	\$3,276
213076576	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716B*	29,200	\$4,088
213076565	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	29,400	\$4,116
213076554	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80VTL0701716B*	29,400	\$4,116
213076521	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716B*	29,000	\$4,060
211712678	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902420A*	23,400	\$3,276
213076510	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716B*	29,400	\$4,116
213076499	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716B*	29,000	\$4,060
213076488	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716B*	29,400	\$4,116
213076477	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716B*	29,400	\$4,116
213076466	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716B*	29,400	\$4,116
211712688	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80VSL1102422A*	23,400	\$3,276
213076446	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80VTL0451412B*	29,400	\$4,116
213076422	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412B*	29,200	\$4,088
213076410	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412B*	29,400	\$4,116
213076335	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002122A*	29,200	\$4,088
213076326	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002122A*	29,200	\$4,088
211712699	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*95ESU1002120A*	23,600	\$3,304
213076317	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002122A*	29,400	\$4,116
213076299	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002122A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076290	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002122A*	29,000	\$4,060
213076281	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002122A*	29,000	\$4,060
213076272	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002122A*	29,400	\$4,116
213076263	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002122A*	29,400	\$4,116
213076254	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002122A*	29,000	\$4,060
211712711	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80ESU1002120A*	23,600	\$3,304
213076245	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002122A*	29,400	\$4,116
213075997	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002120A*	29,200	\$4,088
213075985	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002120A*	29,200	\$4,088
213075973	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002120A*	29,400	\$4,116
213075949	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002120A*	29,000	\$4,060
213075937	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002120A*	29,000	\$4,060
213075925	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002120A*	29,000	\$4,060
213075913	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002120A*	29,400	\$4,116
213075901	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002120A*	29,400	\$4,116
213075889	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002120A*	29,000	\$4,060
213075877	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002120A*	29,400	\$4,116
212989504	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95MSU0802120A*	29,000	\$4,060
212989492	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95MSU0802120A*	29,000	\$4,060
211712737	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*95ESN0802120A*	23,400	\$3,276
212988976	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95MSU0601716A*	29,000	\$4,060
212988404	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96MSN1402422A*	29,000	\$4,060
212988320	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96MSN1202422A*	29,000	\$4,060
211712749	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*95ESN1002120A*	23,600	\$3,304
212985517	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002122A*	29,000	\$4,060
212985508	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002122A*	29,000	\$4,060
212985242	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002120A*	28,800	\$4,032
212985230	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002120A*	28,800	\$4,032
212984952	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*92MSN0802120A*	28,800	\$4,032
212984942	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92MSN0802120A*	28,800	\$4,032
212984412	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92MSN0801716A*	29,000	\$4,060
212983872	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92MSN0601714A*	29,000	\$4,060
212982603	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MSU0601716A*	28,800	\$4,032
212981209	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1352420A*	29,000	\$4,060
212980690	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902420A*	29,000	\$4,060
212980489	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980478	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980170	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902116A*	28,800	\$4,032

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980159	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902116A*	28,800	\$4,032
212979656	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
212979414	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0702116A*	28,800	\$4,032
212979404	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0702116A*	28,800	\$4,032
212978966	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701716A*	29,000	\$4,060
212978480	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
212977254	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422B*	29,000	\$4,060
212977090	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122B*	28,800	\$4,032
211712795	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122A*	23,400	\$3,276
212977080	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122B*	28,800	\$4,032
212976809	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120B*	29,000	\$4,060
212976796	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120B*	29,000	\$4,060
212976527	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120B*	28,800	\$4,032
212976301	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VTN0801716B*	29,000	\$4,060
212974414	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120B*	29,000	\$4,060
212974194	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120B*	28,800	\$4,032
212974054	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716B*	29,000	\$4,060
212972244	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120B*	29,000	\$4,060
212972233	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120B*	29,000	\$4,060
212971877	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716B*	29,000	\$4,060
211712819	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	23,600	\$3,304
212970738	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120B*	29,200	\$4,088
212970728	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120B*	29,200	\$4,088
212970718	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	29,400	\$4,116
212970708	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*80VSL0902120B*	29,600	\$4,144
212970698	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120B*	29,000	\$4,060
212970688	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120B*	29,000	\$4,060
212970678	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120B*	29,200	\$4,088
211712832	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	23,400	\$3,276
212970668	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120B*	29,400	\$4,116
212970658	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120B*	29,400	\$4,116
212970648	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120B*	29,200	\$4,088
212970638	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120B*	29,400	\$4,116
212970478	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716B*	29,200	\$4,088
212970468	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	29,400	\$4,116
212970458	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80VSL0701716B*	29,400	\$4,116
211712845	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	23,400	\$3,276
212970428	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716B*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212970418	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716B*	29,200	\$4,088
212970408	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716B*	29,400	\$4,116
212970398	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716B*	29,200	\$4,088
212970388	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716B*	29,400	\$4,116
212970378	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716B*	29,600	\$4,144
212970368	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716B*	29,600	\$4,144
211712858	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	23,600	\$3,304
212969958	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80VSL0451412B*	29,400	\$4,116
212969938	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412B*	29,200	\$4,088
212969928	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412B*	29,400	\$4,116
212390900	AIRQUEST	DLCURAH36ABK	FJMA4*36L*B*		29,400	\$4,116
212384853	AIRQUEST	DLCURAH36ABK	FVM4X36***L		29,400	\$4,116
211712871	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	23,400	\$3,276
212384829	AIRQUEST	DLCURAH36ABK	FJMA4*42L*C*		29,200	\$4,088
212384789	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0801716A*	29,200	\$4,088
212384777	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701716A*	29,200	\$4,088
212384766	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV112A16A	29,600	\$4,144
212384756	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV112K14A	29,400	\$4,116
212384746	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV098A12*	29,600	\$4,144
211712884	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	23,600	\$3,304
212384736	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV098J12*	29,600	\$4,144
212384725	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	29,400	\$4,116
212384713	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0802120A	29,600	\$4,144
212384701	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0601714A*	29,400	\$4,116
212384689	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	29,400	\$4,116
212384677	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	29,400	\$4,116
212384665	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0801716A*	29,400	\$4,116
211712897	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*92ESN0802120A*	23,400	\$3,276
212384653	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0601714A*	29,400	\$4,116
212384640	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	29,400	\$4,116
212384627	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	29,400	\$4,116
212384614	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701712A*	29,600	\$4,144
212384601	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0451712A*	29,400	\$4,116
211712909	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*92ESN1002120A*	23,400	\$3,276
212384590	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	29,400	\$4,116
212384579	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120A*	29,600	\$4,144
212384568	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	29,400	\$4,116
212384556	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384545	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120A*	29,400	\$4,116
212384530	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	29,400	\$4,116
212384518	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	29,400	\$4,116
211712955	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	OLV154F20A	23,600	\$3,304
211712965	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	OMV154L20A	23,600	\$3,304
211712975	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VSN0601714A*	23,200	\$3,248
211712985	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120A*	23,000	\$3,220
211712995	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120A*	23,200	\$3,248
211713005	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716A*	23,200	\$3,248
211713016	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*95ESU0401712A*	23,200	\$3,248
211713028	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
211713040	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122A*	23,000	\$3,220
211713050	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VSL0451716A*	23,200	\$3,248
211713060	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VSL0701716A*	23,200	\$3,248
211713070	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VSL0702120A*	23,200	\$3,248
211713080	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VSL0902120A*	23,200	\$3,248
211713091	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*95ESU1002120A*	23,400	\$3,276
211713103	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*95ESU0601716A*	23,400	\$3,276
211713115	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ESU1002120A*	23,400	\$3,276
211713127	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ESU0401712A*	23,200	\$3,248
213353885	AIRQUEST	DLCURAH60ABK	F5MA4*60L*D*		37,800	\$5,292
213607815	AIRQUEST	DLCURAH60ABK	FTMA4B60L0D*		37,400	\$5,236
211713142	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120A*	23,200	\$3,248
211713153	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*95ESN0802120A*	23,200	\$3,248
211713165	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*95ESN1002120A*	23,600	\$3,304
211713177	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716A*	23,200	\$3,248
211713189	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VTN0601714A*	23,200	\$3,248
211713200	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120A*	23,000	\$3,220
211713211	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120A*	23,200	\$3,248
211713222	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122A*	23,200	\$3,248
210025750	AIRQUEST	DLCURAH60ABK	DLFUAAH60XAK		42,000	\$5,880
211713233	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
212384506	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	29,400	\$4,116
212384495	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120A*	29,400	\$4,116
212384485	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	29,400	\$4,116
212384475	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716A*	29,400	\$4,116
212384465	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002122A*	29,600	\$4,144
212384455	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002122A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713246	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
212384445	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002122A*	29,600	\$4,144
212384434	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	29,400	\$4,116
212384423	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	29,400	\$4,116
212384413	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	29,400	\$4,116
212384403	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120A*	29,400	\$4,116
212384393	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0601714A*	29,400	\$4,116
211713259	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
212384383	AIRQUEST	DLCURAH36ABK	END4X42L17**	OMV112K14A	29,400	\$4,116
212384373	AIRQUEST	DLCURAH36ABK	END4X42L17**	OLV098A12*	29,400	\$4,116
212384363	AIRQUEST	DLCURAH36ABK	END4X42L17**	OMV098J12*	29,400	\$4,116
212384352	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80ESU0601716A	29,400	\$4,116
212384339	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701412A*	29,400	\$4,116
211713272	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
212384327	AIRQUEST	DLCURAH36ABK	END4X42L17**	*92ESN0801716A*	29,200	\$4,088
212384315	AIRQUEST	DLCURAH36ABK	END4X42L17**	*92ESN0601714A*	29,200	\$4,088
212384303	AIRQUEST	DLCURAH36ABK	END4X42L17**	*92ESN0601412A*	29,400	\$4,116
212384290	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0901714A*	29,400	\$4,116
212384277	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701712A*	29,400	\$4,116
211713285	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
212384264	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451712A*	29,400	\$4,116
212384251	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451412A*	29,600	\$4,144
212384237	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80VTL0451412A*	29,400	\$4,116
212384226	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80VSL0701716A*	29,200	\$4,088
211713298	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
212384216	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80VSL0451716A*	29,400	\$4,116
212384205	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701716A*	29,200	\$4,088
212384141	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*80ESU0802120A	29,800	\$4,172
211713311	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	23,400	\$3,276
212384129	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002120A*	29,600	\$4,144
212384117	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN0802120A*	29,600	\$4,144
211713324	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*92ESN0601714A*	23,000	\$3,220
211713336	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*92ESN0801716A*	23,400	\$3,276
211713348	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*92ESN0802120A*	23,200	\$3,248
211713360	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*92ESN1002120A*	23,200	\$3,248
212383810	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESU1002122A*	29,800	\$4,172
212383800	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESN1002122A*	29,800	\$4,172
212383790	AIRQUEST	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002122A*	29,800	\$4,172

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713372	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*95ESN0601714A*	23,200	\$3,248
211713384	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ESU0802120A	23,400	\$3,276
211713396	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80ESU0601716A	23,200	\$3,248
212383483	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701716A*	29,000	\$4,060
212383471	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92ESN0801716A*	29,000	\$4,060
212383459	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
212383448	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	OLV112A16A	29,400	\$4,116
211713407	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	OMV098J12*	23,200	\$3,248
212383437	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002120A*	29,200	\$4,088
212383426	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120A*	29,000	\$4,060
212383414	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95ESU0601716A*	29,200	\$4,088
212383402	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
211713417	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	OLV098A12*	23,200	\$3,248
212383390	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80ESU0601716A	29,200	\$4,088
212383378	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ESU0601716A	29,400	\$4,116
212383366	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ESU0802120A	29,600	\$4,144
212383354	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002120A*	29,400	\$4,116
212383342	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92ESN0802120A*	29,400	\$4,116
212383330	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92ESN0801716A*	29,400	\$4,116
212383317	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
212383304	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
212383291	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	29,600	\$4,144
212383278	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
212383267	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122A*	29,600	\$4,144
212383256	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VTN0601714A*	29,600	\$4,144
212383244	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716A*	29,400	\$4,116
212383232	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95ESN0802120A*	29,600	\$4,144
212383221	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120A*	29,400	\$4,116
212383209	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002120A*	29,400	\$4,116
212383198	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120A*	29,400	\$4,116
212383188	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VSL0702120A*	29,400	\$4,116
212383178	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716A*	29,400	\$4,116
212383167	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95ESU0802120A*	29,800	\$4,172
212383156	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002122A*	29,600	\$4,144
212383145	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
212383134	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716A*	29,400	\$4,116
212383124	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120A*	29,400	\$4,116
212383114	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383104	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VSN0601714A*	29,600	\$4,144
212383094	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	OLV098A12*	29,600	\$4,144
212383084	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	OMV098J12*	29,600	\$4,144
212383073	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80ESU0601716A	29,600	\$4,144
212383060	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	29,600	\$4,144
212383048	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*95ESN0601714A*	29,600	\$4,144
212383036	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*92ESN0801716A*	29,400	\$4,116
212383024	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601714A*	29,400	\$4,116
212383012	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601412A*	29,600	\$4,144
212382999	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	29,600	\$4,144
212382986	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	29,600	\$4,144
212382973	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	29,600	\$4,144
212382960	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	29,800	\$4,172
212382949	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601714A*	29,600	\$4,144
212382937	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716A*	29,400	\$4,116
212382920	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412A*	29,600	\$4,144
212382908	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*95ESU0601716A*	29,400	\$4,116
212382897	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716A*	29,400	\$4,116
212382887	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451716A*	29,600	\$4,144
212382876	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
212382865	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716A*	29,400	\$4,116
212382855	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601714A*	29,600	\$4,144
212382845	AIRQUEST	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412A*	29,600	\$4,144
211230928	AIRQUEST	DLCURAH36ABK	FXM4X48**AL		29,000	\$4,060
211230917	AIRQUEST	DLCURAH36ABK	FXM4X42**AL		29,000	\$4,060
211230896	AIRQUEST	DLCURAH36ABK	FVM4X48***L		28,600	\$4,004
211230885	AIRQUEST	DLCURAH36ABK	FMA4X36**AL*		29,600	\$4,144
211230863	AIRQUEST	DLCURAH36ABK	FM(C,U)4Z36**AL*		29,600	\$4,144
211230807	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	OMV154L20A	29,200	\$4,088
211230798	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	OLV154F20A	29,400	\$4,116
211230789	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	OLV112A16A	29,200	\$4,088
211230780	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422A*	29,200	\$4,088
211230770	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122A*	29,200	\$4,088
211230761	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120A*	29,200	\$4,088
211230751	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120A*	29,200	\$4,088
211230741	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002122A*	29,400	\$4,116
211230731	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002120A*	29,200	\$4,088
211230720	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU0802120A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230710	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422A*	29,200	\$4,088
211230701	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120A*	29,200	\$4,088
211230692	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120A*	29,200	\$4,088
211230682	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1402422A*	29,400	\$4,116
211230671	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1202422A*	29,400	\$4,116
211230661	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002122A*	29,400	\$4,116
211230651	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002120A*	29,200	\$4,088
211230640	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN0802120A*	29,400	\$4,116
211230629	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1202420A*	29,200	\$4,088
211230619	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002122A*	29,400	\$4,116
211230609	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002120A*	29,200	\$4,088
211230598	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN0802120A*	29,000	\$4,060
211230568	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122A*	29,200	\$4,088
211230558	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120A*	29,200	\$4,088
211230547	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU1002120A*	29,200	\$4,088
211230536	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU0802120A*	29,400	\$4,116
211230526	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL1102422A*	29,200	\$4,088
211230517	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902420A*	29,200	\$4,088
211230508	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120A*	29,200	\$4,088
211230499	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0702120A*	29,200	\$4,088
211230490	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1552420A*	29,200	\$4,088
211230478	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1352420A*	29,200	\$4,088
211230466	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102420A*	29,200	\$4,088
211230454	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102120A*	29,200	\$4,088
211230442	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902420A*	29,200	\$4,088
211230430	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902120A*	29,200	\$4,088
211230418	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902116A*	29,200	\$4,088
211230406	AIRQUEST	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0702116A*	29,200	\$4,088
211230378	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV112K14A	29,200	\$4,088
211230369	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV098J12*	29,200	\$4,088
211230360	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV112A16A	29,200	\$4,088
211230351	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV098A12*	29,200	\$4,088
211230342	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122A*	29,200	\$4,088
211230333	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120A*	29,200	\$4,088
211230323	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120A*	29,200	\$4,088
211230313	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0601714A*	29,400	\$4,116
211230293	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002122A*	29,400	\$4,116
211230283	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230272	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0802120A*	29,600	\$4,144
211230261	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0601716A*	29,200	\$4,088
211230251	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120A*	29,200	\$4,088
211230242	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120A*	29,200	\$4,088
211230233	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716A*	29,200	\$4,088
211230224	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0601714A*	29,200	\$4,088
211230206	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002122A*	29,400	\$4,116
211230196	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002120A*	29,200	\$4,088
211230185	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0802120A*	29,400	\$4,116
211230174	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0801716A*	29,200	\$4,088
211230163	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0601714A*	29,200	\$4,088
211230153	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002122A*	29,400	\$4,116
211230143	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002120A*	29,200	\$4,088
211230132	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0802120A*	29,000	\$4,060
211230121	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0601714A*	29,200	\$4,088
211230084	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122A*	29,200	\$4,088
211230074	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120A*	29,200	\$4,088
211230062	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716A*	29,200	\$4,088
211230051	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU1002120A*	29,200	\$4,088
211230040	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0802120A	29,400	\$4,116
211230029	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0601716A	29,000	\$4,060
211230018	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0401712A*	29,600	\$4,144
211230008	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120A*	29,200	\$4,088
211229999	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0702120A*	29,200	\$4,088
211229990	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716A*	29,200	\$4,088
211229981	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0451716A*	29,200	\$4,088
211229970	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)1102120A*	29,200	\$4,088
211229958	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902120A*	29,200	\$4,088
211229946	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902116A*	29,200	\$4,088
211229934	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0901714A*	29,200	\$4,088
211229922	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0702116A*	29,200	\$4,088
211229910	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701712A*	29,400	\$4,116
211229898	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0451712A*	29,200	\$4,088
211229852	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	29,400	\$4,116
211229843	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120A*	29,400	\$4,116
211229833	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0601714A*	29,600	\$4,144
211229822	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002120A*	29,400	\$4,116
211229801	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0451716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229790	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	29,400	\$4,116
211229778	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	29,400	\$4,116
211229766	AIRQUEST	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	29,400	\$4,116
211229747	AIRQUEST	DLCURAH36ABK	END4X42L17**	*96VTN0601714A*	29,400	\$4,116
211229736	AIRQUEST	DLCURAH36ABK	END4X42L17**	*95ESU0601716A*	29,200	\$4,088
211229726	AIRQUEST	DLCURAH36ABK	END4X42L17**	*96VSN0801716A*	29,400	\$4,116
211229717	AIRQUEST	DLCURAH36ABK	END4X42L17**	*96VSN0601714A*	29,400	\$4,116
211229689	AIRQUEST	DLCURAH36ABK	END4X42L17**	*95ESN0601714A*	29,400	\$4,116
211229670	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80VTL0701716A*	29,200	\$4,088
211229658	AIRQUEST	DLCURAH36ABK	END4X42L17**	*80VSL0451412A*	29,400	\$4,116
211229649	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	OMV154L20A	29,000	\$4,060
211229640	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	OLV154F20A	29,200	\$4,088
211229631	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	OLV112A16A	29,000	\$4,060
211229622	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422A*	29,000	\$4,060
211229612	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122A*	28,800	\$4,032
211714016	AIRQUEST	DLCURAH30ABK	EN(A,D)4X36L21**	*80ESU0802120A*	23,600	\$3,304
211229603	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120A*	29,000	\$4,060
211229593	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120A*	28,800	\$4,032
211229583	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002122A*	29,200	\$4,088
211229573	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002120A*	29,000	\$4,060
211229562	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95ESU0802120A*	29,400	\$4,116
211229552	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422A*	29,000	\$4,060
211229543	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120A*	29,000	\$4,060
211229534	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120A*	29,000	\$4,060
211229524	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95ESN1402422A*	29,200	\$4,088
211229513	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95ESN1202422A*	29,200	\$4,088
211714039	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80VSL0451412A*	23,400	\$3,276
211229503	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002122A*	29,200	\$4,088
211229493	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002120A*	29,000	\$4,060
211229482	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*95ESN0802120A*	29,200	\$4,088
211229471	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*92ESN1202420A*	29,000	\$4,060
211229461	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002122A*	29,200	\$4,088
211714049	AIRQUEST	DLCURAH30ABK	END4X42L17**	*96VSN0801716A*	23,400	\$3,276
211229451	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002120A*	28,800	\$4,032
211229440	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*92ESN0802120A*	28,800	\$4,032
211229410	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122A*	29,000	\$4,060
211229400	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120A*	28,800	\$4,032
211714060	AIRQUEST	DLCURAH30ABK	END4X42L17**	*95ESU0401712A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229389	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ESU1002120A*	29,000	\$4,060
211229378	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ESU0802120A	29,200	\$4,088
211229368	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80VSL1102422A*	28,800	\$4,032
211229359	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902420A*	28,800	\$4,032
211229350	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120A*	28,800	\$4,032
211229341	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80VSL0702120A*	29,000	\$4,060
211714072	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701716A*	23,600	\$3,304
211229332	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1552420A*	29,200	\$4,088
211229320	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1352420A*	29,000	\$4,060
211229308	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102420A*	28,800	\$4,032
211229296	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102120A*	29,000	\$4,060
211714083	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80VSL0451716A*	23,400	\$3,276
211229284	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902420A*	29,000	\$4,060
211229272	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902120A*	29,000	\$4,060
211229260	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902116A*	29,000	\$4,060
211229248	AIRQUEST	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0702116A*	28,800	\$4,032
211714093	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80VSL0701716A*	23,400	\$3,276
211229220	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	OMV112K14A	29,000	\$4,060
211229211	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	OMV098J12*	29,000	\$4,060
211229202	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	OLV112A16A	29,000	\$4,060
211229193	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	OLV098A12*	29,000	\$4,060
211229184	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122A*	28,800	\$4,032
211714104	AIRQUEST	DLCURAH30ABK	END4X42L17**	*95ESU0601716A*	23,600	\$3,304
211229175	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120A*	29,000	\$4,060
211229165	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120A*	29,000	\$4,060
211229155	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VTN0601714A*	29,200	\$4,088
211229145	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002122A*	29,200	\$4,088
211229135	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002120A*	29,000	\$4,060
211714116	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80ESU0401712A*	23,400	\$3,276
211229124	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95ESU0802120A*	29,400	\$4,116
211229113	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95ESU0601716A*	29,000	\$4,060
211229103	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120A*	29,000	\$4,060
211229094	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120A*	29,000	\$4,060
211229085	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716A*	29,000	\$4,060
211229076	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*96VSN0601714A*	29,000	\$4,060
211714128	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80VTL0451412A*	23,400	\$3,276
211229058	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002122A*	29,200	\$4,088
211229048	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002120A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229037	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95ESN0802120A*	29,200	\$4,088
211229026	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95ESN0801716A*	29,000	\$4,060
211229015	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*95ESN0601714A*	29,000	\$4,060
211229005	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002122A*	29,200	\$4,088
211228995	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002120A*	28,800	\$4,032
211714145	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80VTL0701716A*	23,400	\$3,276
211228984	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92ESN0802120A*	28,800	\$4,032
211228973	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92ESN0801716A*	29,000	\$4,060
211228962	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*92ESN0601714A*	29,000	\$4,060
211228925	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122A*	29,000	\$4,060
211228915	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120A*	28,800	\$4,032
211228903	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716A*	29,000	\$4,060
211714157	AIRQUEST	DLCURAH30ABK	END4X42L17**	*96VTN0601714A*	23,400	\$3,276
211228892	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ESU1002120A*	29,000	\$4,060
211228881	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ESU0802120A	29,200	\$4,088
211228870	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ESU0601716A	29,000	\$4,060
211228859	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ESU0401712A*	29,400	\$4,116
211714168	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0451412A*	23,400	\$3,276
211228849	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120A*	28,800	\$4,032
211228840	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VSL0702120A*	29,000	\$4,060
211228831	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716A*	29,000	\$4,060
211228822	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80VSL0451716A*	29,000	\$4,060
211228811	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)1102120A*	29,000	\$4,060
211228799	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902120A*	29,000	\$4,060
211228787	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211714181	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701712A*	23,400	\$3,276
211228775	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0901714A*	29,000	\$4,060
211228763	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0702116A*	28,800	\$4,032
211228751	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701712A*	29,000	\$4,060
211228739	AIRQUEST	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228693	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	OMV112K14A	29,200	\$4,088
211714194	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0901714A*	23,400	\$3,276
211228684	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	OMV098J12*	29,200	\$4,088
211228675	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	OLV112A16A	29,200	\$4,088
211228666	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	OLV098A12*	29,200	\$4,088
211228657	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122A*	29,000	\$4,060
211228648	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120A*	29,200	\$4,088
211228638	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714207	AIRQUEST	DLCURAH30ABK	END4X42L17**	*92ESN0601412A*	23,400	\$3,276
211228628	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VTN0601714A*	29,200	\$4,088
211228608	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002122A*	29,200	\$4,088
211228598	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002120A*	29,000	\$4,060
211228587	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95ESU0802120A*	29,400	\$4,116
211714219	AIRQUEST	DLCURAH30ABK	END4X42L17**	*92ESN0601714A*	23,200	\$3,248
211228576	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95ESU0601716A*	29,200	\$4,088
211228566	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120A*	29,000	\$4,060
211228557	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120A*	29,000	\$4,060
211228548	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716A*	29,200	\$4,088
211714231	AIRQUEST	DLCURAH30ABK	END4X42L17**	*92ESN0801716A*	23,200	\$3,248
211228539	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*96VSN0601714A*	29,200	\$4,088
211228521	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002122A*	29,200	\$4,088
211228511	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002120A*	29,200	\$4,088
211228500	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95ESN0802120A*	29,200	\$4,088
211714243	AIRQUEST	DLCURAH30ABK	END4X42L17**	*95ESN0601714A*	23,400	\$3,276
211228478	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*95ESN0601714A*	29,400	\$4,116
211228468	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002122A*	29,400	\$4,116
211228458	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002120A*	29,200	\$4,088
211714255	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701412A*	23,200	\$3,248
211228447	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92ESN0802120A*	29,200	\$4,088
211228436	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*92ESN0601714A*	29,000	\$4,060
211228399	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122A*	29,200	\$4,088
211228389	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120A*	29,000	\$4,060
211714268	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80ESU0601716A	23,400	\$3,276
211228377	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716A*	29,000	\$4,060
211228366	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ESU1002120A*	29,000	\$4,060
211228355	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ESU0802120A	29,200	\$4,088
211714279	AIRQUEST	DLCURAH30ABK	END4X42L17**	OMV098J12*	23,400	\$3,276
211228344	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ESU0601716A	29,200	\$4,088
211228333	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ESU0401712A*	29,400	\$4,116
211714289	AIRQUEST	DLCURAH30ABK	END4X42L17**	OLV098A12*	23,400	\$3,276
211228323	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120A*	29,000	\$4,060
211228314	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VSL0702120A*	29,000	\$4,060
211228305	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716A*	29,200	\$4,088
211228296	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80VSL0451716A*	29,200	\$4,088
211228285	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211714309	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228273	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211228261	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211714319	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	23,400	\$3,276
211228249	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211228237	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211228225	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211228213	AIRQUEST	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228167	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	OMV154L20A	29,400	\$4,116
211714342	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	23,600	\$3,304
211714354	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	23,400	\$3,276
211714384	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	23,400	\$3,276
211714405	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	23,600	\$3,304
211714417	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	23,600	\$3,304
212970758	AIRQUEST	DLCURAH48AAK	EA*4X48L24A*	*80VSL0902120B*	32,600	\$4,564
212970748	AIRQUEST	DLCURAH48AAK	EA*4X48L21A*	*80VSL0902120B*	32,600	\$4,564
211714429	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	23,600	\$3,304
211714441	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0401712A*	23,400	\$3,276
212970798	AIRQUEST	DLCURAH48ABK	EA*4X48L21A*	*80VSL0902120B*	31,400	\$4,396
212970808	AIRQUEST	DLCURAH48ABK	EA*4X48L24A*	*80VSL0902120B*	31,400	\$4,396
212970818	AIRQUEST	DLCURAH48ABK	EA*4X60L24A*	*80VSL0902120B*	31,000	\$4,340
212970828	AIRQUEST	DLCURAH48ABK	EA*4X61L21A*	*80VSL0902120B*	31,000	\$4,340
212970838	AIRQUEST	DLCURAH48ABK	EA*4X61L24A*	*80VSL0902120B*	31,000	\$4,340
211714467	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	23,400	\$3,276
211714479	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	23,400	\$3,276
211714512	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	23,400	\$3,276
211714536	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	23,600	\$3,304
211714549	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	23,400	\$3,276
211714562	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	23,600	\$3,304
211714575	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	23,400	\$3,276
211714588	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	23,600	\$3,304
211714625	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	23,400	\$3,276
211714637	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	23,400	\$3,276
211714661	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	23,400	\$3,276
211714686	AIRQUEST	DLCURAH30ABK	FJMA4*36L*B*		23,400	\$3,276
212969878	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412B*	23,400	\$3,276
212969918	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80VSL0451412B*	23,400	\$3,276
212970278	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80VSL0701716B*	23,400	\$3,276
212970298	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80VSL0701716B*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212970348	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80VSL0701716B*	23,400	\$3,276
212970358	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	23,600	\$3,304
212970588	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80VSL0902120B*	23,600	\$3,304
212970598	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902120B*	23,600	\$3,304
212970628	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	23,600	\$3,304
212971293	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412B*	23,400	\$3,276
212971341	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80VTL0451412B*	23,400	\$3,276
212971778	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716B*	23,400	\$3,276
212971789	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716B*	23,200	\$3,248
212971800	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716B*	23,600	\$3,304
212971811	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716B*	23,200	\$3,248
212971855	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80VTL0701716B*	23,400	\$3,276
212971866	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	23,600	\$3,304
212972167	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120B*	23,200	\$3,248
212972178	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80VTL0902120B*	23,600	\$3,304
212972189	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80VTL0902120B*	23,600	\$3,304
212972200	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120B*	23,200	\$3,248
212972222	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	23,600	\$3,304
212972449	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122B*	23,400	\$3,276
212972461	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122B*	23,400	\$3,276
212972473	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122B*	23,400	\$3,276
212972485	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122B*	23,200	\$3,248
212973644	AIRQUEST	DLCURAH30ABK	END4X42L17**	*96VSN0601412B*	23,600	\$3,304
212973964	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716B*	23,400	\$3,276
212973974	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716B*	23,400	\$3,276
212973994	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716B*	23,200	\$3,248
212974034	AIRQUEST	DLCURAH30ABK	END4X42L17**	*96VSN0801716B*	23,400	\$3,276
212974134	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120B*	23,200	\$3,248
212974144	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*96VSN0802120B*	23,400	\$3,276
212974154	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96VSN0802120B*	23,400	\$3,276
212974164	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120B*	23,200	\$3,248
212974184	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	23,600	\$3,304
212974354	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120B*	23,200	\$3,248
212974364	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*96VSN1002120B*	23,600	\$3,304
212974374	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96VSN1002120B*	23,600	\$3,304
212974384	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120B*	23,200	\$3,248
212974404	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	23,600	\$3,304
212974524	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96VSN1202422B*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975763	AIRQUEST	DLCURAH30ABK	END4X42L17**	*96VTN0601412B*	23,600	\$3,304
212976178	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*96VTN0801716B*	23,400	\$3,276
212976191	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VTN0801716B*	23,400	\$3,276
212976217	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VTN0801716B*	23,200	\$3,248
212976269	AIRQUEST	DLCURAH30ABK	END4X42L17**	*96VTN0801716B*	23,400	\$3,276
212976445	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120B*	23,200	\$3,248
212976459	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*96VTN0802120B*	23,400	\$3,276
212976473	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96VTN0802120B*	23,400	\$3,276
212976487	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120B*	23,200	\$3,248
212976514	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	23,600	\$3,304
212976718	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120B*	23,200	\$3,248
212976731	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002120B*	23,600	\$3,304
212976744	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002120B*	23,600	\$3,304
212976757	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120B*	23,200	\$3,248
212976783	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	23,600	\$3,304
212977020	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122B*	23,200	\$3,248
212977030	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002122B*	23,400	\$3,276
212977040	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002122B*	23,400	\$3,276
212977050	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122B*	23,200	\$3,248
212977070	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	23,400	\$3,276
212977242	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96VTN1202422B*	23,600	\$3,304
212977517	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	23,400	\$3,276
212977553	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0451412A*	23,400	\$3,276
212978021	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	23,400	\$3,276
212978069	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701412A*	23,400	\$3,276
212978524	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978535	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978546	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978557	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978601	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701712A*	23,400	\$3,276
212978612	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	23,400	\$3,276
212979014	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	23,400	\$3,276
212979026	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979038	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	23,600	\$3,304
212979050	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979098	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701716A*	23,400	\$3,276
212979110	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	23,600	\$3,304
212979434	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979444	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979454	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979464	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	23,200	\$3,248
212979704	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979716	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979728	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979740	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979788	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0901714A*	23,400	\$3,276
212980192	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980225	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980247	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	23,600	\$3,304
212980511	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980522	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	23,600	\$3,304
212980544	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980566	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	23,600	\$3,304
212980699	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	23,600	\$3,304
212980901	AIRQUEST	DLCURAH30ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980913	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980925	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980937	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980949	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980973	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	23,600	\$3,304
212981111	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	23,400	\$3,276
212981220	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	23,600	\$3,304
212981321	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	23,400	\$3,276
212981583	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*80MSU1002120A*	23,400	\$3,276
212981667	AIRQUEST	DLCURAH30ABK	END4X42L17**	*80MSU1002120A*	23,400	\$3,276
212982651	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*80MSU0601716A*	23,400	\$3,276
212983469	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601412A*	23,400	\$3,276
212983499	AIRQUEST	DLCURAH30ABK	END4X42L17**	*92MSN0601412A*	23,600	\$3,304
212983920	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601714A*	23,400	\$3,276
212983932	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*92MSN0601714A*	23,200	\$3,248
212983956	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*92MSN0601714A*	23,200	\$3,248
212984004	AIRQUEST	DLCURAH30ABK	END4X42L17**	*92MSN0601714A*	23,400	\$3,276
212984460	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*92MSN0801716A*	23,400	\$3,276
212984472	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*92MSN0801716A*	23,200	\$3,248
212984484	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*92MSN0801716A*	23,400	\$3,276
212984496	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*92MSN0801716A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984544	AIRQUEST	DLCURAH30ABK	END4X42L17**	*92MSN0801716A*	23,400	\$3,276
212984972	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*92MSN0802120A*	23,200	\$3,248
212984982	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*92MSN0802120A*	23,400	\$3,276
212984992	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*92MSN0802120A*	23,400	\$3,276
212985002	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*92MSN0802120A*	23,200	\$3,248
212985022	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	23,600	\$3,304
212985266	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*92MSN1002120A*	23,200	\$3,248
212985278	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*92MSN1002120A*	23,400	\$3,276
212985290	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*92MSN1002120A*	23,400	\$3,276
212985302	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*92MSN1002120A*	23,600	\$3,304
212985326	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	23,600	\$3,304
212985615	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*92MSN1202420A*	23,400	\$3,276
212985746	AIRQUEST	DLCURAH30ABK	END4X42L17**	*96MSN0261410A*	23,600	\$3,304
212986850	AIRQUEST	DLCURAH30ABK	END4X42L17**	*96MSN0601412A*	23,600	\$3,304
212987258	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*96MSN0801716A*	23,400	\$3,276
212987270	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96MSN0801716A*	23,200	\$3,248
212987294	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96MSN0801716A*	23,400	\$3,276
212987342	AIRQUEST	DLCURAH30ABK	END4X42L17**	*96MSN0801716A*	23,600	\$3,304
212987354	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	23,600	\$3,304
212987726	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*96MSN0802120A*	23,200	\$3,248
212987750	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96MSN0802120A*	23,400	\$3,276
212987762	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*96MSN0802120A*	23,200	\$3,248
212988332	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96MSN1202422A*	23,400	\$3,276
212988414	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*96MSN1402422A*	23,600	\$3,304
212988580	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*95MSU0401712A*	23,600	\$3,304
212988592	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*95MSU0401712A*	23,200	\$3,248
212988616	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*95MSU0401712A*	23,200	\$3,248
212988628	AIRQUEST	DLCURAH30ABK	END4X42L17**	*95MSU0401712A*	23,600	\$3,304
212989024	AIRQUEST	DLCURAH30ABK	EA*4X37L17A*	*95MSU0601716A*	23,400	\$3,276
212989036	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*95MSU0601716A*	23,200	\$3,248
212989048	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*95MSU0601716A*	23,600	\$3,304
212989060	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*95MSU0601716A*	23,200	\$3,248
212989108	AIRQUEST	DLCURAH30ABK	END4X42L17**	*95MSU0601716A*	23,400	\$3,276
212989120	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	23,600	\$3,304
212989528	AIRQUEST	DLCURAH30ABK	EA*4X37L21A*	*95MSU0802120A*	23,200	\$3,248
212989540	AIRQUEST	DLCURAH30ABK	EA*4X42L21A*	*95MSU0802120A*	23,600	\$3,304
212989552	AIRQUEST	DLCURAH30ABK	EA*4X42L24A*	*95MSU0802120A*	23,600	\$3,304
212989564	AIRQUEST	DLCURAH30ABK	EA*4X43L21A*	*95MSU0802120A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989588	AIRQUEST	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	23,600	\$3,304
213249293	AIRQUEST	DLCURAH30ABK	FEVA0036**+NAVA43601CK		23,600	\$3,304
213353809	AIRQUEST	DLCURAH30ABK	F5MA4*30L*B*		23,400	\$3,276
213353819	AIRQUEST	DLCURAH30ABK	F5MA4*36L*B*		23,600	\$3,304
211226261	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	29,600	\$4,144
211226273	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	29,600	\$4,144
211226285	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211226296	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80VSL0451716A*	29,600	\$4,144
211226306	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*80ESU1002120A*	29,400	\$4,116
211226328	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92ESN0601714A*	29,400	\$4,116
211226338	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002122A*	29,600	\$4,144
211226348	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95ESN0601714A*	29,400	\$4,116
211226359	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95ESN0801716A*	29,400	\$4,116
211226370	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002120A*	29,600	\$4,144
211226380	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002122A*	29,600	\$4,144
211226390	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*95ESU0601716A*	29,400	\$4,116
211226401	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120A*	29,400	\$4,116
211226411	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120A*	29,600	\$4,144
211226420	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122A*	29,400	\$4,116
211226429	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	OLV098A12*	29,600	\$4,144
211226438	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	OLV112A16A	29,600	\$4,144
211226447	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	OMV098J12*	29,600	\$4,144
211226456	AIRQUEST	DLCURAH36ABK	EA*4X36L21A*	OMV112K14A	29,600	\$4,144
211226484	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	29,400	\$4,116
211226496	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	29,200	\$4,088
211226508	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701712A*	29,400	\$4,116
211226520	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
211226531	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226542	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412A*	29,400	\$4,116
211226551	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451716A*	29,400	\$4,116
211226560	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716A*	29,400	\$4,116
211226581	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412A*	29,400	\$4,116
211226593	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716A*	29,400	\$4,116
211226614	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601412A*	29,400	\$4,116
211226625	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601714A*	29,200	\$4,088
211226636	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*92ESN0801716A*	29,400	\$4,116
211226658	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*95ESN0601714A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226668	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412A*	29,400	\$4,116
211226677	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601714A*	29,400	\$4,116
211226686	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716A*	29,400	\$4,116
211226696	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*95ESU0601716A*	29,400	\$4,116
211226707	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601714A*	29,400	\$4,116
211226716	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	OLV098A12*	29,400	\$4,116
211226725	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	OMV098J12*	29,400	\$4,116
211226734	AIRQUEST	DLCURAH36ABK	EA*4X37L17A*	OMV112K14A	29,400	\$4,116
211226792	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211226804	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211226816	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226828	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211226840	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211226852	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211226863	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VSL0451716A*	29,200	\$4,088
211226872	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716A*	29,200	\$4,088
211226881	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VSL0702120A*	29,000	\$4,060
211226890	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120A*	29,000	\$4,060
211226900	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ESU0401712A*	29,400	\$4,116
211226911	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ESU0601716A	29,200	\$4,088
211226922	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ESU0802120A	29,400	\$4,116
211226933	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80ESU1002120A*	29,000	\$4,060
211226944	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716A*	29,000	\$4,060
211226956	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122A*	29,200	\$4,088
211226993	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92ESN0601714A*	29,000	\$4,060
211227004	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92ESN0801716A*	29,000	\$4,060
211227015	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92ESN0802120A*	29,200	\$4,088
211227025	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002122A*	29,400	\$4,116
211227035	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95ESN0601714A*	29,400	\$4,116
211227057	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95ESN0802120A*	29,200	\$4,088
211227068	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002120A*	29,200	\$4,088
211227078	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002122A*	29,200	\$4,088
211227096	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VSN0601714A*	29,200	\$4,088
211227105	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716A*	29,200	\$4,088
211227114	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120A*	29,000	\$4,060
211227123	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120A*	29,000	\$4,060
211227133	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95ESU0802120A*	29,400	\$4,116
211227144	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002120A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227154	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002122A*	29,200	\$4,088
211227174	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VTN0601714A*	29,200	\$4,088
211227184	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120A*	29,200	\$4,088
211227194	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120A*	29,200	\$4,088
211227203	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122A*	29,000	\$4,060
211227212	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	OLV098A12*	29,200	\$4,088
211227221	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	OLV112A16A	29,200	\$4,088
211227230	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	OMV098J12*	29,200	\$4,088
211227239	AIRQUEST	DLCURAH36ABK	EA*4X37L21A*	OMV112K14A	29,200	\$4,088
211227285	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0451712A*	29,400	\$4,116
211227297	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701712A*	29,400	\$4,116
211227309	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
211227320	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227332	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	29,400	\$4,116
211227344	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227356	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227368	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227379	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VSL0451716A*	29,400	\$4,116
211227388	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716A*	29,400	\$4,116
211227397	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VSL0702120A*	29,400	\$4,116
211227406	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120A*	29,400	\$4,116
211227427	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ESU0601716A	29,200	\$4,088
211227438	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ESU0802120A	29,600	\$4,144
211227449	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80ESU1002120A*	29,400	\$4,116
211227460	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716A*	29,400	\$4,116
211227472	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120A*	29,400	\$4,116
211227482	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122A*	29,400	\$4,116
211227510	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92ESN0601714A*	29,400	\$4,116
211227521	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92ESN0801716A*	29,400	\$4,116
211227532	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92ESN0802120A*	29,200	\$4,088
211227543	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002120A*	29,200	\$4,088
211227553	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002122A*	29,600	\$4,144
211227563	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95ESN0601714A*	29,400	\$4,116
211227574	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95ESN0802120A*	29,400	\$4,116
211227584	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95ESN1002122A*	29,600	\$4,144
211227593	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VSN0601714A*	29,400	\$4,116
211227602	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716A*	29,400	\$4,116
211227611	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227620	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120A*	29,400	\$4,116
211227630	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95ESU0601716A*	29,400	\$4,116
211227641	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95ESU0802120A*	29,600	\$4,144
211227652	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002120A*	29,400	\$4,116
211227662	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002122A*	29,600	\$4,144
211227672	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VTN0601714A*	29,600	\$4,144
211227682	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716A*	29,400	\$4,116
211227692	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120A*	29,400	\$4,116
211227702	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120A*	29,400	\$4,116
211227711	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122A*	29,200	\$4,088
211227720	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	OLV098A12*	29,400	\$4,116
211227729	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	OMV098J12*	29,400	\$4,116
211227738	AIRQUEST	DLCURAH36ABK	EA*4X42L21A*	OMV112K14A	29,400	\$4,116
211227766	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227778	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227790	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227802	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	29,400	\$4,116
211227814	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227826	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	29,200	\$4,088
211227838	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	29,400	\$4,116
211227850	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1552420A*	29,400	\$4,116
211227859	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80VSL0702120A*	29,400	\$4,116
211227868	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120A*	29,400	\$4,116
211227877	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902420A*	29,400	\$4,116
211227886	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80VSL1102422A*	29,200	\$4,088
211227896	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ESU0802120A	29,600	\$4,144
211227907	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80ESU1002120A*	29,400	\$4,116
211227918	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120A*	29,400	\$4,116
211227928	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122A*	29,400	\$4,116
211227958	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*92ESN0802120A*	29,200	\$4,088
211227969	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002120A*	29,200	\$4,088
211227979	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002122A*	29,600	\$4,144
211227989	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*92ESN1202420A*	29,400	\$4,116
211228000	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95ESN0802120A*	29,400	\$4,116
211228011	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002120A*	29,400	\$4,116
211228021	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002122A*	29,600	\$4,144
211228031	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95ESN1202422A*	29,600	\$4,144
211228042	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95ESN1402422A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228052	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120A*	29,400	\$4,116
211228061	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120A*	29,400	\$4,116
211228070	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422A*	29,400	\$4,116
211228080	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95ESU0802120A*	29,600	\$4,144
211228091	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002120A*	29,400	\$4,116
211228101	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002122A*	29,600	\$4,144
211228111	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120A*	29,400	\$4,116
211228121	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120A*	29,400	\$4,116
211228130	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122A*	29,200	\$4,088
211228140	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422A*	29,400	\$4,116
211228149	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	OLV112A16A	29,400	\$4,116
211228158	AIRQUEST	DLCURAH36ABK	EA*4X42L24A*	OLV154F20A	29,600	\$4,144
213353779	AIRQUEST	DLCURAH24ABK	F5MA4*30L*B*		19,100	\$2,674
213353769	AIRQUEST	DLCURAH24ABK	F5MA4*24L*B*		19,300	\$2,702
213249271	AIRQUEST	DLCURAH24ABK	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076399	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601716B*	19,400	\$2,716
213076373	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601716B*	19,400	\$2,716
213076362	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002122A*	19,100	\$2,674
213076344	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95MSU1002122A*	19,000	\$2,660
213076117	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002120A*	19,200	\$2,688
213076105	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*95MSU1002120A*	18,500	\$2,590
212989624	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0802120A*	19,100	\$2,674
212989612	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*95MSU0802120A*	18,600	\$2,604
212989600	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95MSU0802120A*	19,100	\$2,674
212989252	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0601716A*	19,100	\$2,674
212989240	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0601716A*	19,100	\$2,674
212989228	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0601716A*	19,100	\$2,674
212989216	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0601716A*	19,400	\$2,716
212989204	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*95MSU0601716A*	18,700	\$2,618
212989192	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*95MSU0601716A*	18,900	\$2,646
212989180	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95MSU0601716A*	19,100	\$2,674
212989168	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95MSU0601716A*	19,100	\$2,674
212989156	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95MSU0601716A*	19,100	\$2,674
212989144	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*95MSU0601716A*	18,600	\$2,604
212989132	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95MSU0601716A*	19,400	\$2,716
212988760	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0401712A*	19,200	\$2,688
212988748	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0401712A*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988736	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0401712A*	19,200	\$2,688
212988724	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0401712A*	19,500	\$2,730
212988712	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*95MSU0401712A*	18,600	\$2,604
212988700	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*95MSU0401712A*	18,800	\$2,632
212988688	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95MSU0401712A*	19,000	\$2,660
212988676	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95MSU0401712A*	19,100	\$2,674
212988664	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95MSU0401712A*	19,200	\$2,688
212988652	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*95MSU0401712A*	18,700	\$2,618
212988640	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95MSU0401712A*	19,500	\$2,730
212987822	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0802120A*	19,100	\$2,674
212987810	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96MSN0802120A*	18,700	\$2,618
212987798	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96MSN0802120A*	19,100	\$2,674
212987486	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0801716A*	19,200	\$2,688
212987474	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0801716A*	19,200	\$2,688
212987462	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0801716A*	19,200	\$2,688
212987450	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0801716A*	19,500	\$2,730
212987438	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96MSN0801716A*	19,800	\$2,772
212987426	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96MSN0801716A*	18,800	\$2,632
212987414	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96MSN0801716A*	19,000	\$2,660
212987402	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96MSN0801716A*	19,100	\$2,674
212987390	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96MSN0801716A*	19,200	\$2,688
212987378	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96MSN0801716A*	18,700	\$2,618
212987366	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96MSN0801716A*	19,400	\$2,716
212986970	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0601412A*	19,200	\$2,688
212986960	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0601412A*	19,200	\$2,688
212986950	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0601412A*	19,200	\$2,688
212986940	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0601412A*	19,500	\$2,730
212986930	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0601412A*	19,500	\$2,730
212986920	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96MSN0601412A*	18,800	\$2,632
212986910	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96MSN0601412A*	19,100	\$2,674
212986900	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96MSN0601412A*	19,100	\$2,674
212986890	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96MSN0601412A*	19,200	\$2,688
212986880	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96MSN0601412A*	18,700	\$2,618
212986870	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96MSN0601412A*	19,400	\$2,716
212986860	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96MSN0601412A*	19,400	\$2,716
212986646	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0401712A*	19,100	\$2,674
212986634	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401712A*	19,100	\$2,674
212986622	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401712A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986610	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401712A*	19,700	\$2,758
211289630	AIRQUEST	DLCURAH60ABK	FVM4X60***L		37,800	\$5,292
213607740	AIRQUEST	DLCURAH36ABK	FTMA4B48L0C*		28,800	\$4,032
213607725	AIRQUEST	DLCURAH36ABK	FTMA4B36L0C*		29,400	\$4,116
213607680	AIRQUEST	DLCURAH30ABK	FTMA4B36L0C*		23,600	\$3,304
213607650	AIRQUEST	DLCURAH24ABK	FTMA4X24L0B*		19,300	\$2,702
213607635	AIRQUEST	DLCURAH24ABK	FTMA4B36L0C*		19,100	\$2,674
213607590	AIRQUEST	DLCURAH18ABK	FTMA4X24L0B*		12,400	\$1,736
212986598	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96MSN0401712A*	18,800	\$2,632
212986586	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401712A*	19,000	\$2,660
212986574	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96MSN0401712A*	19,200	\$2,688
212986562	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401712A*	19,200	\$2,688
212986550	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401712A*	19,200	\$2,688
212986538	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401712A*	18,900	\$2,646
212986526	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401712A*	19,500	\$2,730
212986262	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401410A*	19,200	\$2,688
212986142	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401410A*	19,500	\$2,730
212986130	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96MSN0401410A*	19,500	\$2,730
212985866	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0261410A*	19,000	\$2,660
212985856	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0261410A*	19,000	\$2,660
212985846	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0261410A*	19,100	\$2,674
212985836	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0261410A*	19,500	\$2,730
212985826	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0261410A*	19,500	\$2,730
212985816	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96MSN0261410A*	18,800	\$2,632
212985806	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96MSN0261410A*	19,100	\$2,674
212985796	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96MSN0261410A*	19,100	\$2,674
212985786	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96MSN0261410A*	19,200	\$2,688
212985776	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96MSN0261410A*	18,700	\$2,618
212985766	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96MSN0261410A*	19,500	\$2,730
212985756	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96MSN0261410A*	19,500	\$2,730
212985362	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN1002120A*	19,100	\$2,674
212985350	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*92MSN1002120A*	18,700	\$2,618
212985338	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92MSN1002120A*	19,100	\$2,674
212985052	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0802120A*	19,000	\$2,660
212985042	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*92MSN0802120A*	18,900	\$2,646
212985032	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92MSN0802120A*	19,000	\$2,660
212984688	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0801716A*	19,100	\$2,674
212984676	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0801716A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984664	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0801716A*	19,100	\$2,674
212984652	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0801716A*	19,500	\$2,730
212984640	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*92MSN0801716A*	18,400	\$2,576
212984628	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*92MSN0801716A*	18,900	\$2,646
212984616	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92MSN0801716A*	19,000	\$2,660
212984604	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*92MSN0801716A*	19,000	\$2,660
212984592	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*92MSN0801716A*	19,100	\$2,674
212984580	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*92MSN0801716A*	18,500	\$2,590
212984568	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*92MSN0801716A*	19,300	\$2,702
212984148	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0601714A*	19,100	\$2,674
212984136	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601714A*	19,100	\$2,674
212984124	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601714A*	19,100	\$2,674
212984112	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601714A*	19,400	\$2,716
212984100	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*92MSN0601714A*	18,700	\$2,618
212984088	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601714A*	18,900	\$2,646
212984076	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92MSN0601714A*	19,100	\$2,674
212984064	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601714A*	19,100	\$2,674
212984052	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601714A*	19,100	\$2,674
212984040	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601714A*	18,700	\$2,618
212984028	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601714A*	19,400	\$2,716
212983619	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601412A*	19,200	\$2,688
212983609	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601412A*	19,200	\$2,688
212983599	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*92MSN0601412A*	19,200	\$2,688
212983589	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601412A*	19,500	\$2,730
212983579	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*92MSN0601412A*	19,500	\$2,730
212983569	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601412A*	19,000	\$2,660
212983559	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601412A*	19,200	\$2,688
212983549	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601412A*	19,200	\$2,688
212983539	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*92MSN0601412A*	19,200	\$2,688
212983529	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601412A*	18,800	\$2,632
212983519	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601412A*	19,500	\$2,730
212983509	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*92MSN0601412A*	19,500	\$2,730
212983242	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0401712A*	19,200	\$2,688
212983231	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0401712A*	19,200	\$2,688
212983220	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0401712A*	19,200	\$2,688
212983209	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0401712A*	19,600	\$2,744
212983198	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*92MSN0401712A*	18,800	\$2,632
212983187	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*92MSN0401712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983176	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92MSN0401712A*	19,200	\$2,688
212983165	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*92MSN0401712A*	19,200	\$2,688
212983154	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*92MSN0401712A*	19,300	\$2,702
212983143	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*92MSN0401712A*	18,800	\$2,632
212983132	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*92MSN0401712A*	19,500	\$2,730
212981811	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU1002120A*	19,100	\$2,674
212981799	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	19,200	\$2,688
212981787	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU1002120A*	19,200	\$2,688
212981775	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU1002120A*	19,500	\$2,730
212981751	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80MSU1002120A*	18,800	\$2,632
212981739	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MSU1002120A*	19,100	\$2,674
212981727	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80MSU1002120A*	19,000	\$2,660
212981715	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80MSU1002120A*	19,100	\$2,674
212981703	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80MSU1002120A*	18,700	\$2,618
212981691	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80MSU1002120A*	19,500	\$2,730
212981009	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)1102120A*	19,100	\$2,674
212980997	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	18,800	\$2,632
212980985	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	19,000	\$2,660
212980599	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902120A*	19,100	\$2,674
212980588	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	18,600	\$2,604
212980577	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	19,100	\$2,674
212980280	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902116A*	19,100	\$2,674
212980269	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	18,600	\$2,604
212980258	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	19,000	\$2,660
212979932	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0901714A*	19,100	\$2,674
212979920	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979908	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979896	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	19,500	\$2,730
212979884	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979872	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979860	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979848	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979836	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979824	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	18,600	\$2,604
212979812	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	19,400	\$2,716
212979514	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0702116A*	19,200	\$2,688
212979504	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	18,600	\$2,604
212979494	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979242	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	19,100	\$2,674
212979230	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979218	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979206	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701716A*	19,400	\$2,716
212979194	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979182	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979170	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979158	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979146	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979134	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212978645	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978634	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	18,600	\$2,604
212978623	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	19,400	\$2,716
212978213	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978201	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978189	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	19,100	\$2,674
212978177	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	19,400	\$2,716
212978165	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	19,400	\$2,716
212978153	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	18,700	\$2,618
212978141	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	19,000	\$2,660
212978129	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978117	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978105	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	18,600	\$2,604
212978093	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	19,400	\$2,716
212978081	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	19,300	\$2,702
212977697	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977685	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977673	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	19,000	\$2,660
212977661	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	19,500	\$2,730
212977649	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	19,500	\$2,730
212977637	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977625	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977613	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977601	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977589	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977577	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977565	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977000	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122B*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976980	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122B*	19,100	\$2,674
212976692	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120B*	19,100	\$2,674
212976679	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002120B*	18,600	\$2,604
212976666	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120B*	19,000	\$2,660
212976417	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120B*	19,200	\$2,688
212976403	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120B*	18,600	\$2,604
212976390	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120B*	19,100	\$2,674
212976126	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716B*	18,900	\$2,646
212976113	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716B*	18,900	\$2,646
212976100	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716B*	18,900	\$2,646
212976087	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716B*	19,500	\$2,730
212976061	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716B*	19,000	\$2,660
212976048	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716B*	19,000	\$2,660
212976035	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716B*	19,000	\$2,660
212976022	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716B*	19,100	\$2,674
212976009	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VTN0801716B*	18,800	\$2,632
212975996	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716B*	19,500	\$2,730
212975752	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412B*	19,100	\$2,674
212975741	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412B*	19,100	\$2,674
212975730	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412B*	19,000	\$2,660
212975719	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412B*	19,500	\$2,730
212975708	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412B*	19,500	\$2,730
212975697	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412B*	18,800	\$2,632
212975686	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412B*	19,100	\$2,674
212975675	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412B*	19,100	\$2,674
212975664	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412B*	19,100	\$2,674
212975653	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412B*	18,600	\$2,604
212975642	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412B*	19,400	\$2,716
212975631	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412B*	19,400	\$2,716
212975367	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712B*	19,200	\$2,688
212975356	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712B*	19,200	\$2,688
212975345	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712B*	19,200	\$2,688
212975334	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712B*	19,600	\$2,744
212975323	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712B*	18,900	\$2,646
212975312	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401712B*	18,900	\$2,646
212975301	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712B*	19,100	\$2,674
212975290	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712B*	19,100	\$2,674
212975279	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712B*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975268	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712B*	18,800	\$2,632
212975257	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712B*	19,500	\$2,730
212975058	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410B*	19,200	\$2,688
212975045	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410B*	19,200	\$2,688
212975032	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410B*	19,100	\$2,674
212975019	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410B*	19,600	\$2,744
212975006	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410B*	19,600	\$2,744
212974993	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410B*	18,800	\$2,632
212974980	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410B*	19,200	\$2,688
212974967	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410B*	19,200	\$2,688
212974954	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410B*	19,200	\$2,688
212974941	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401410B*	18,700	\$2,618
212974928	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410B*	19,500	\$2,730
212974915	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410B*	19,500	\$2,730
212974324	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VSN1002120B*	18,900	\$2,646
212974314	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120B*	19,000	\$2,660
212974114	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120B*	19,200	\$2,688
212974104	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VSN0802120B*	18,600	\$2,604
212974094	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120B*	19,100	\$2,674
212973924	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716B*	18,900	\$2,646
212973914	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716B*	18,900	\$2,646
212973904	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716B*	18,900	\$2,646
212973894	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716B*	19,500	\$2,730
212973874	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716B*	19,000	\$2,660
212973864	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716B*	19,000	\$2,660
212973854	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716B*	19,000	\$2,660
212973844	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716B*	19,100	\$2,674
212973834	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VSN0801716B*	18,800	\$2,632
212973824	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716B*	19,500	\$2,730
212973634	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412B*	19,100	\$2,674
212973624	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412B*	19,100	\$2,674
212973614	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412B*	19,000	\$2,660
212973604	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412B*	19,500	\$2,730
212973594	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412B*	19,500	\$2,730
212973584	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412B*	18,800	\$2,632
212973574	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412B*	19,100	\$2,674
212973564	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412B*	19,100	\$2,674
212973554	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412B*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973544	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412B*	18,600	\$2,604
212973534	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412B*	19,400	\$2,716
212973524	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412B*	19,400	\$2,716
212973284	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712B*	19,200	\$2,688
212973274	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712B*	19,200	\$2,688
212973264	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712B*	19,200	\$2,688
212973254	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712B*	19,600	\$2,744
212973244	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712B*	18,900	\$2,646
212973234	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401712B*	18,900	\$2,646
212973224	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712B*	19,100	\$2,674
212973214	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712B*	19,100	\$2,674
212973204	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712B*	19,200	\$2,688
212973194	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712B*	18,800	\$2,632
212973184	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712B*	19,500	\$2,730
212973004	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410B*	19,200	\$2,688
212972994	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410B*	19,200	\$2,688
212972984	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410B*	19,200	\$2,688
212972974	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410B*	19,500	\$2,730
212972964	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410B*	19,500	\$2,730
212972954	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410B*	19,000	\$2,660
212972944	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410B*	19,200	\$2,688
212972934	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410B*	19,200	\$2,688
212972924	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410B*	19,200	\$2,688
212972914	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401410B*	18,800	\$2,632
212972904	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410B*	19,500	\$2,730
212972894	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410B*	19,500	\$2,730
212972425	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122B*	19,200	\$2,688
212972413	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122B*	18,800	\$2,632
212972401	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122B*	19,100	\$2,674
212972145	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120B*	19,100	\$2,674
212972134	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80VTL0902120B*	18,900	\$2,646
212972123	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120B*	19,100	\$2,674
212971734	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716B*	19,100	\$2,674
212971723	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716B*	19,100	\$2,674
212971712	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716B*	19,100	\$2,674
212971701	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716B*	19,500	\$2,730
212971690	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80VTL0701716B*	18,700	\$2,618
212971679	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716B*	18,700	\$2,618

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971668	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716B*	19,100	\$2,674
212971657	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716B*	19,100	\$2,674
212971646	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716B*	19,100	\$2,674
212971635	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80VTL0701716B*	18,600	\$2,604
212971624	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716B*	19,400	\$2,716
212971245	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412B*	19,100	\$2,674
212971233	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412B*	19,100	\$2,674
212971221	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412B*	19,000	\$2,660
212971209	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412B*	19,500	\$2,730
212971197	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412B*	19,500	\$2,730
212971185	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412B*	18,700	\$2,618
212971173	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412B*	19,000	\$2,660
212971161	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412B*	19,100	\$2,674
212969838	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412B*	19,100	\$2,674
212969828	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412B*	19,100	\$2,674
212969818	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412B*	19,000	\$2,660
212969808	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412B*	19,500	\$2,730
212969798	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412B*	19,500	\$2,730
212969788	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451412B*	18,700	\$2,618
212969778	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412B*	19,000	\$2,660
212969768	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412B*	19,100	\$2,674
212969758	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412B*	19,100	\$2,674
212969748	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80VSL0451412B*	18,500	\$2,590
212969738	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412B*	19,300	\$2,702
211245982	AIRQUEST	DLCURAH24ABK	FVM4X36***L		19,000	\$2,660
211245972	AIRQUEST	DLCURAH24ABK	FVM4X24***L		19,000	\$2,660
211245961	AIRQUEST	DLCURAH24ABK	FM(C,U)4Z36**AL*		19,300	\$2,702
211245950	AIRQUEST	DLCURAH24ABK	FM(C,U)4Z30**AL*		19,300	\$2,702
211245939	AIRQUEST	DLCURAH24ABK	FM(C,U)4Z24**AL*		19,500	\$2,730
211245928	AIRQUEST	DLCURAH24ABK	FM(C,U)4X36**AL*		19,900	\$2,786
211245917	AIRQUEST	DLCURAH24ABK	FM(C,U)4X30**AL*		19,900	\$2,786
211245906	AIRQUEST	DLCURAH24ABK	FMA4X36**AL*		19,600	\$2,744
211245895	AIRQUEST	DLCURAH24ABK	FMA4X30**AL*		19,600	\$2,744
211245884	AIRQUEST	DLCURAH24ABK	FMA4X24**AL*		19,600	\$2,744
211245862	AIRQUEST	DLCURAH24ABK	FMA4P24**AL*		19,900	\$2,786
211245851	AIRQUEST	DLCURAH24ABK	FXM4X36**AL		18,500	\$2,590
211245840	AIRQUEST	DLCURAH24ABK	FXM4X30**AL		19,100	\$2,674
211245829	AIRQUEST	DLCURAH24ABK	FXM4X24**AL		19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245818	AIRQUEST	DLCURAH24ABK	FEM4X30**BL		19,100	\$2,674
211245806	AIRQUEST	DLCURAH24ABK	FEM4X24**CL		19,000	\$2,660
211245794	AIRQUEST	DLCURAH24ABK	FEM4P30**AL		19,100	\$2,674
211245783	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	OLV112A16A	19,300	\$2,702
211245774	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	OMV112K14A	19,200	\$2,688
211245765	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	OLV098A12*	18,900	\$2,646
211245756	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	OMV098J12*	19,000	\$2,660
211245746	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0601716A	19,300	\$2,702
211245735	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0802120A	19,100	\$2,674
211245724	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0401712A*	19,100	\$2,674
211245713	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0801716A*	19,500	\$2,730
211245702	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0601714A*	19,400	\$2,716
211245691	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN1002120A*	19,300	\$2,702
211245680	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0802120A*	19,300	\$2,702
211245669	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0801716A*	19,100	\$2,674
211245658	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0601714A*	19,100	\$2,674
211245646	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)1102120A*	19,400	\$2,716
211245634	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0902120A*	19,300	\$2,702
211245622	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0901714A*	19,200	\$2,688
211245610	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0702116A*	19,100	\$2,674
211245598	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701712A*	19,200	\$2,688
211245586	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0451712A*	19,100	\$2,674
211245576	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122A*	19,000	\$2,660
211245566	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120A*	19,000	\$2,660
211245556	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120A*	18,900	\$2,646
211245546	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0601714A*	19,100	\$2,674
211245535	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0401712A*	19,400	\$2,716
211245525	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716A*	19,100	\$2,674
211245515	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716A*	19,100	\$2,674
211245504	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0802120A*	19,300	\$2,702
211245494	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712A*	19,000	\$2,660
211245484	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120A*	19,000	\$2,660
211245471	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0401712A*	19,000	\$2,660
211245460	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0601716A*	19,100	\$2,674
211245450	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0902120A*	19,000	\$2,660
211245441	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0702120A*	19,300	\$2,702
211245432	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0701716A*	19,000	\$2,660
211245423	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0451716A*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245378	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122A*	18,900	\$2,646
211245368	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701716A*	19,400	\$2,716
211245357	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0401712A*	19,000	\$2,660
211245347	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716A*	19,100	\$2,674
211245338	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712A*	19,000	\$2,660
211245329	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN1002120A*	19,000	\$2,660
211245320	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120A*	19,000	\$2,660
211245311	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0601714A*	18,900	\$2,646
211245275	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV112K14A	19,200	\$2,688
211245266	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	OLV098A12*	18,900	\$2,646
211245257	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV098J12*	19,000	\$2,660
211245247	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0601716A	19,300	\$2,702
211245235	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211245224	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401712A*	19,100	\$2,674
211245213	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401410A*	19,400	\$2,716
211245202	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0801716A*	19,500	\$2,730
211245191	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601714A*	19,400	\$2,716
211245180	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0801716A*	19,100	\$2,674
211245169	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601714A*	19,100	\$2,674
211245158	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601412A*	18,900	\$2,646
211245146	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211245134	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211245122	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211245110	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211245100	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601714A*	19,100	\$2,674
211245089	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0261410A*	18,900	\$2,646
211245079	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412A*	19,000	\$2,660
211245069	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410A*	19,000	\$2,660
211245058	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601412A*	19,400	\$2,716
211245047	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401712A*	19,400	\$2,716
211245036	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401410A*	19,500	\$2,730
211245026	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716A*	19,100	\$2,674
211245016	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716A*	19,100	\$2,674
211245006	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712A*	19,000	\$2,660
211244992	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412A*	19,100	\$2,674
211244981	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0401712A*	19,000	\$2,660
211244970	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0601716A*	19,100	\$2,674
211244960	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0701716A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244951	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451716A*	19,200	\$2,688
211244923	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244912	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0401712A*	19,000	\$2,660
211244902	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716A*	19,100	\$2,674
211244893	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412A*	19,000	\$2,660
211244884	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712A*	19,000	\$2,660
211244875	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410A*	19,000	\$2,660
211244866	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601714A*	18,900	\$2,646
211244848	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412A*	18,900	\$2,646
211244839	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	OMV112K14A	19,200	\$2,688
211244830	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	OLV098A12*	18,900	\$2,646
211244821	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	OMV098J12*	19,000	\$2,660
213372195	AIRQUEST	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372191	AIRQUEST	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
211244811	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0601716A	19,300	\$2,702
211244799	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211244788	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401712A*	19,100	\$2,674
211244777	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401410A*	19,400	\$2,716
211244766	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0801716A*	19,500	\$2,730
211244755	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601714A*	19,400	\$2,716
211244744	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0801716A*	19,100	\$2,674
211244733	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601714A*	19,100	\$2,674
211244722	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601412A*	18,900	\$2,646
211244710	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211244698	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211244686	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211244674	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211244664	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601714A*	19,100	\$2,674
211244653	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0261410A*	18,900	\$2,646
211244643	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412A*	19,000	\$2,660
211244633	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410A*	19,000	\$2,660
211244622	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601412A*	19,400	\$2,716
211244611	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401712A*	19,400	\$2,716
211244600	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401410A*	19,500	\$2,730
211244590	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716A*	19,100	\$2,674
211244580	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716A*	19,100	\$2,674
211244570	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712A*	19,000	\$2,660
211244556	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244545	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0401712A*	19,000	\$2,660
211244534	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0601716A*	19,100	\$2,674
211244524	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0701716A*	19,000	\$2,660
211244515	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451716A*	19,200	\$2,688
211244487	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244476	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0401712A*	19,000	\$2,660
211244466	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716A*	19,100	\$2,674
211244457	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412A*	19,000	\$2,660
211244448	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712A*	19,000	\$2,660
211244439	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410A*	19,000	\$2,660
211244430	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601714A*	18,900	\$2,646
211244412	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412A*	18,900	\$2,646
211244401	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	19,100	\$2,674
211244390	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0401410A*	19,400	\$2,716
211244379	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0601412A*	18,900	\$2,646
211244367	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	19,300	\$2,702
211244356	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0261410A*	19,500	\$2,730
211244346	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412A*	19,000	\$2,660
211244336	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410A*	19,100	\$2,674
211244325	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0601412A*	19,400	\$2,716
211244314	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0401410A*	19,500	\$2,730
211244302	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412A*	19,100	\$2,674
211244292	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412A*	19,000	\$2,660
211244283	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410A*	19,100	\$2,674
211244274	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412A*	19,200	\$2,688
211244265	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	OMV112K14A	19,700	\$2,758
211244256	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	OLV098A12*	19,300	\$2,702
211244247	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	OMV098J12*	19,400	\$2,716
211244237	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0601716A	19,600	\$2,744
211244225	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	19,500	\$2,730
211244214	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401712A*	19,500	\$2,730
211244203	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401410A*	19,700	\$2,758
211244192	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0801716A*	19,800	\$2,772
211244181	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601714A*	19,700	\$2,758
211244170	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0801716A*	19,400	\$2,716
211244159	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601714A*	19,500	\$2,730
211244148	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601412A*	19,600	\$2,744
211244136	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0901714A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244124	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	19,500	\$2,730
211244112	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	19,400	\$2,716
211244100	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	19,600	\$2,744
211244090	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601714A*	19,400	\$2,716
211244079	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0261410A*	19,900	\$2,786
211244069	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412A*	19,300	\$2,702
211244059	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410A*	19,500	\$2,730
211244048	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601412A*	19,700	\$2,758
211244037	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401712A*	19,700	\$2,758
211244026	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401410A*	19,800	\$2,772
211244016	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716A*	19,400	\$2,716
211244006	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716A*	19,500	\$2,730
211243996	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712A*	19,700	\$2,758
211243982	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412A*	19,500	\$2,730
211243971	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0401712A*	19,300	\$2,702
211243960	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0601716A*	19,400	\$2,716
211243950	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0701716A*	19,400	\$2,716
211243941	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451716A*	19,500	\$2,730
211243913	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701716A*	19,700	\$2,758
211243902	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0401712A*	19,300	\$2,702
211243892	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716A*	19,500	\$2,730
211243883	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412A*	19,300	\$2,702
211243874	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712A*	19,700	\$2,758
211243865	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410A*	19,500	\$2,730
211243856	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601714A*	19,500	\$2,730
211243838	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412A*	19,500	\$2,730
211243827	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	19,500	\$2,730
211243816	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0401410A*	19,700	\$2,758
211243805	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0601412A*	19,600	\$2,744
211243793	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	19,600	\$2,744
211243782	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0261410A*	19,900	\$2,786
211243772	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412A*	19,300	\$2,702
211243762	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410A*	19,500	\$2,730
211243751	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0601412A*	19,700	\$2,758
211243740	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0401410A*	19,800	\$2,772
211243728	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412A*	19,500	\$2,730
211243718	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412A*	19,300	\$2,702
211243709	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243700	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412A*	19,500	\$2,730
211243673	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	OLV098A12*	18,400	\$2,576
211243484	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122A*	18,500	\$2,590
211243464	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120A*	18,400	\$2,576
211243402	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712A*	18,500	\$2,590
211243286	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002122A*	18,400	\$2,576
211243246	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712A*	18,500	\$2,590
211243174	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	OLV098A12*	18,700	\$2,618
211243165	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	OMV098J12*	18,800	\$2,632
211243143	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	18,900	\$2,646
211243132	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*92ESN0401712A*	18,900	\$2,646
211243088	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*92ESN0801716A*	18,900	\$2,646
211243077	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*92ESN0601714A*	18,900	\$2,646
211243030	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0451712A*	18,900	\$2,646
211243008	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601714A*	18,900	\$2,646
211242987	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412A*	18,700	\$2,618
211242977	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410A*	18,900	\$2,646
211242934	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716A*	18,800	\$2,632
211242924	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716A*	18,900	\$2,646
211242900	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412A*	18,900	\$2,646
211242889	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80ESU0401712A*	18,700	\$2,618
211242878	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*95ESU0601716A*	18,900	\$2,646
211242868	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80VSL0701716A*	18,800	\$2,632
211242859	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451716A*	19,000	\$2,660
211242820	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*95ESU0401712A*	18,700	\$2,618
211242810	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716A*	18,900	\$2,646
211242801	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412A*	18,700	\$2,618
211242783	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410A*	18,900	\$2,646
211242774	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601714A*	19,000	\$2,660
211242747	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	OLV112A16A	19,200	\$2,688
211242738	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	OMV112K14A	19,100	\$2,674
211242729	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	OLV098A12*	18,900	\$2,646
211242720	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	OMV098J12*	18,900	\$2,646
211242710	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ESU0601716A	19,300	\$2,702
211242699	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ESU0802120A	19,100	\$2,674
211242688	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92ESN0401712A*	19,100	\$2,674
211242677	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95ESN0801716A*	19,400	\$2,716
211242666	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95ESN0601714A*	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242655	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92ESN1002120A*	19,300	\$2,702
211242644	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92ESN0802120A*	19,300	\$2,702
211242633	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92ESN0801716A*	19,100	\$2,674
211242622	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*92ESN0601714A*	19,100	\$2,674
211242610	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	19,400	\$2,716
211242598	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	19,200	\$2,688
211242586	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242574	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	19,100	\$2,674
211242562	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	18,800	\$2,632
211242550	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242540	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122A*	18,900	\$2,646
211242530	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120A*	19,000	\$2,660
211242520	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120A*	18,900	\$2,646
211242510	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN0601714A*	19,100	\$2,674
211242499	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95ESN0401712A*	19,300	\$2,702
211242489	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716A*	19,000	\$2,660
211242479	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716A*	19,100	\$2,674
211242468	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95ESN0802120A*	19,300	\$2,702
211242458	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712A*	19,000	\$2,660
211242448	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120A*	19,000	\$2,660
211242435	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ESU0401712A*	18,900	\$2,646
211242424	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95ESU0601716A*	19,100	\$2,674
211242414	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VSL0902120A*	19,000	\$2,660
211242405	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VSL0702120A*	19,300	\$2,702
211242396	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VSL0701716A*	19,000	\$2,660
211242387	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80VSL0451716A*	18,800	\$2,632
211242342	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122A*	18,900	\$2,646
211242332	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	19,400	\$2,716
211242321	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*95ESU0401712A*	18,900	\$2,646
211242311	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716A*	19,100	\$2,674
211242302	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712A*	19,000	\$2,660
211242293	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120A*	18,900	\$2,646
211242284	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120A*	19,000	\$2,660
211242275	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*96VSN0601714A*	18,900	\$2,646
211242239	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	OMV112K14A	19,200	\$2,688
211242230	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	OLV098A12*	18,900	\$2,646
211242221	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	OMV098J12*	18,900	\$2,646
211242211	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80ESU0601716A	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242199	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	19,100	\$2,674
211242188	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401712A*	19,100	\$2,674
211242177	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401410A*	19,400	\$2,716
211242166	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95ESN0801716A*	19,400	\$2,716
211242155	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601714A*	19,300	\$2,702
211242144	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*92ESN0801716A*	19,100	\$2,674
211242133	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601714A*	19,100	\$2,674
211242122	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601412A*	18,800	\$2,632
211242110	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242098	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211242086	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242074	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	19,300	\$2,702
211242064	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601714A*	19,100	\$2,674
211242053	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95ESN0261410A*	18,900	\$2,646
211242043	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412A*	18,900	\$2,646
211242033	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410A*	18,900	\$2,646
211242022	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601412A*	19,300	\$2,702
211242011	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401712A*	19,300	\$2,702
211242000	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401410A*	19,400	\$2,716
211241990	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716A*	19,000	\$2,660
211241980	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716A*	19,100	\$2,674
211241970	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712A*	18,900	\$2,646
211241956	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412A*	19,100	\$2,674
211241945	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80ESU0401712A*	18,900	\$2,646
211241934	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95ESU0601716A*	19,100	\$2,674
211241924	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80VSL0701716A*	19,000	\$2,660
211241915	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451716A*	19,100	\$2,674
211241887	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241876	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*95ESU0401712A*	18,900	\$2,646
211241866	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716A*	19,100	\$2,674
211241857	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412A*	18,900	\$2,646
211241848	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712A*	18,900	\$2,646
211241839	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410A*	18,900	\$2,646
211241830	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601714A*	18,900	\$2,646
211241812	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412A*	18,800	\$2,632
211241803	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	OMV112K14A	19,200	\$2,688
211241794	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	OLV098A12*	18,900	\$2,646
211241785	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	OMV098J12*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241775	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80ESU0601716A	19,300	\$2,702
211241763	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241752	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401712A*	19,100	\$2,674
211241741	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401410A*	19,400	\$2,716
211241730	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95ESN0801716A*	19,500	\$2,730
211241719	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601714A*	19,400	\$2,716
211241708	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*92ESN0801716A*	19,100	\$2,674
211241697	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601714A*	19,200	\$2,688
211241686	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601412A*	18,900	\$2,646
211241674	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211241662	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211241650	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211241638	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	19,400	\$2,716
211241628	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601714A*	19,100	\$2,674
211241617	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95ESN0261410A*	18,900	\$2,646
211241607	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412A*	19,000	\$2,660
211241597	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410A*	19,000	\$2,660
211241586	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601412A*	19,400	\$2,716
211241575	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401712A*	19,400	\$2,716
211241564	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401410A*	19,500	\$2,730
211241554	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716A*	19,100	\$2,674
211241544	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716A*	19,200	\$2,688
211241534	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712A*	19,000	\$2,660
211241520	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412A*	19,200	\$2,688
211241509	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80ESU0401712A*	19,000	\$2,660
211241498	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95ESU0601716A*	19,100	\$2,674
211241488	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80VSL0701716A*	19,100	\$2,674
211241479	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451716A*	19,200	\$2,688
211241451	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241440	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*95ESU0401712A*	19,000	\$2,660
211241430	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716A*	19,200	\$2,688
211241421	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412A*	19,000	\$2,660
211241412	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712A*	19,000	\$2,660
211241403	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410A*	19,000	\$2,660
211241394	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601714A*	18,900	\$2,646
211241376	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412A*	18,900	\$2,646
211241365	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241354	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*92ESN0401410A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241343	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*92ESN0601412A*	18,900	\$2,646
211241331	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	19,300	\$2,702
211241320	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*95ESN0261410A*	19,600	\$2,744
211241310	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412A*	19,000	\$2,660
211241300	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410A*	19,100	\$2,674
211241289	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*95ESN0601412A*	19,400	\$2,716
211241278	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*95ESN0401410A*	19,500	\$2,730
211241266	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*80VTL0451412A*	19,100	\$2,674
211241256	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412A*	19,000	\$2,660
211241247	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410A*	19,100	\$2,674
211241238	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412A*	19,200	\$2,688
211241220	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	OLV098A12*	18,600	\$2,604
211241211	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	OMV098J12*	18,600	\$2,604
211241112	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*92ESN0601412A*	18,500	\$2,590
211241033	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412A*	18,600	\$2,604
211240960	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712A*	18,600	\$2,604
211240935	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80ESU0401712A*	18,600	\$2,604
211240914	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*80VSL0701716A*	18,700	\$2,618
211240866	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*95ESU0401712A*	18,600	\$2,604
211240847	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412A*	18,600	\$2,604
211240838	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712A*	18,600	\$2,604
211240793	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	OMV112K14A	19,500	\$2,730
211240784	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	OLV098A12*	19,200	\$2,688
211240775	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	OMV098J12*	19,300	\$2,702
211240765	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80ESU0601716A	19,600	\$2,744
211240753	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240742	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401712A*	19,400	\$2,716
211240731	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401410A*	19,700	\$2,758
211240720	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95ESN0801716A*	19,700	\$2,758
211240709	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601714A*	19,600	\$2,744
211240698	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*92ESN0801716A*	19,400	\$2,716
211240687	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601714A*	19,400	\$2,716
211240676	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601412A*	19,200	\$2,688
211240664	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0901714A*	19,500	\$2,730
211240652	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	19,500	\$2,730
211240640	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	19,400	\$2,716
211240628	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240618	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601714A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240607	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95ESN0261410A*	19,800	\$2,772
211240597	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412A*	19,300	\$2,702
211240587	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410A*	19,400	\$2,716
211240576	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601412A*	19,600	\$2,744
211240565	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401712A*	19,700	\$2,758
211240554	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401410A*	19,700	\$2,758
211240544	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716A*	19,300	\$2,702
211240534	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716A*	19,400	\$2,716
211240524	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712A*	19,300	\$2,702
211240510	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80VTL0451412A*	19,400	\$2,716
211240499	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80ESU0401712A*	19,300	\$2,702
211240488	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95ESU0601716A*	19,400	\$2,716
211240478	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80VSL0701716A*	19,300	\$2,702
211240469	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451716A*	19,400	\$2,716
211240441	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701716A*	19,700	\$2,758
211240430	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*95ESU0401712A*	19,300	\$2,702
211240420	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716A*	19,400	\$2,716
211240411	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412A*	19,300	\$2,702
211240402	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712A*	19,300	\$2,702
211240393	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410A*	19,400	\$2,716
211240384	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601714A*	19,500	\$2,730
211240366	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412A*	19,500	\$2,730
211240355	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240344	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*92ESN0401410A*	19,700	\$2,758
211240333	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*92ESN0601412A*	19,600	\$2,744
211240321	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240310	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*95ESN0261410A*	19,800	\$2,772
211240300	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412A*	19,300	\$2,702
211240290	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410A*	19,400	\$2,716
211240279	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*95ESN0601412A*	19,600	\$2,744
211240268	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*95ESN0401410A*	19,700	\$2,758
211240256	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*80VTL0451412A*	19,400	\$2,716
211240246	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412A*	19,300	\$2,702
211240237	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410A*	19,400	\$2,716
211240228	AIRQUEST	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412A*	19,500	\$2,730
211239223	AIRQUEST	DLCURAH24ABK	FJMA4*24L*B*		19,200	\$2,688
213353739	AIRQUEST	DLCURAH18ABK	F5MA4*24L*B*		12,500	\$1,750
213353729	AIRQUEST	DLCURAH18ABK	F5MA4*18L*A*		12,800	\$1,792

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213249249	AIRQUEST	DLCURAH18ABK	FEVA0024**+NAVA43601CK		12,300	\$1,722
213076386	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601716B*	12,400	\$1,736
212989324	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0601716A*	12,200	\$1,708
212989312	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0601716A*	12,300	\$1,722
212989300	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*95MSU0601716A*	12,200	\$1,708
212989288	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*95MSU0601716A*	12,000	\$1,680
212989276	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*95MSU0601716A*	12,300	\$1,722
212989264	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*95MSU0601716A*	12,100	\$1,694
212988832	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0401712A*	12,200	\$1,708
212988820	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0401712A*	12,500	\$1,750
212988808	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*95MSU0401712A*	12,200	\$1,708
212988796	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*95MSU0401712A*	12,000	\$1,680
212988784	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*95MSU0401712A*	12,300	\$1,722
212988772	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*95MSU0401712A*	12,100	\$1,694
212987558	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0601716A*	12,200	\$1,708
212987546	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0801716A*	12,500	\$1,750
212987534	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96MSN0801716A*	12,100	\$1,694
212987522	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96MSN0801716A*	12,200	\$1,708
212987510	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96MSN0801716A*	12,500	\$1,750
212987498	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96MSN0801716A*	12,300	\$1,722
212987080	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0601412A*	12,200	\$1,708
212987070	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0601412A*	12,200	\$1,708
212987060	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0601412A*	12,300	\$1,722
212987050	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0601412A*	12,300	\$1,722
212987040	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0601412A*	12,500	\$1,750
212987030	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96MSN0601412A*	12,200	\$1,708
212987020	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96MSN0601412A*	12,200	\$1,708
212987010	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96MSN0601412A*	12,000	\$1,680
212987000	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96MSN0601412A*	12,300	\$1,722
212986990	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96MSN0601412A*	12,300	\$1,722
212986980	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96MSN0601412A*	12,100	\$1,694
212986718	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401712A*	12,300	\$1,722
212986706	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401712A*	12,500	\$1,750
212986694	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401712A*	12,300	\$1,722
212986682	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96MSN0401712A*	12,100	\$1,694
212986670	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401712A*	12,300	\$1,722
212986658	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401712A*	12,100	\$1,694

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986382	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401410A*	12,300	\$1,722
212986370	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0401410A*	12,300	\$1,722
212986358	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401410A*	12,400	\$1,736
212986346	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0401410A*	12,400	\$1,736
212986334	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0401410A*	12,400	\$1,736
212986322	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401410A*	12,300	\$1,722
212986310	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96MSN0401410A*	12,300	\$1,722
212986298	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401410A*	12,400	\$1,736
212986286	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96MSN0401410A*	12,400	\$1,736
212986274	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401410A*	12,200	\$1,708
212985976	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0261410A*	12,300	\$1,722
212985966	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0261410A*	12,200	\$1,708
212985956	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0261410A*	12,300	\$1,722
212985946	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0261410A*	12,300	\$1,722
212985936	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0261410A*	12,500	\$1,750
212985926	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96MSN0261410A*	12,200	\$1,708
212985916	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96MSN0261410A*	12,200	\$1,708
212985906	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96MSN0261410A*	12,100	\$1,694
212985896	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96MSN0261410A*	12,300	\$1,722
212985886	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96MSN0261410A*	12,300	\$1,722
212985876	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96MSN0261410A*	12,100	\$1,694
212984760	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0801716A*	12,100	\$1,694
212984748	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0801716A*	12,500	\$1,750
212984736	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*92MSN0801716A*	12,400	\$1,736
212984724	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*92MSN0801716A*	12,200	\$1,708
212984712	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*92MSN0801716A*	12,500	\$1,750
212984700	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*92MSN0801716A*	12,300	\$1,722
212984220	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601714A*	12,300	\$1,722
212984208	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601714A*	12,400	\$1,736
212984196	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601714A*	12,300	\$1,722
212984184	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601714A*	12,200	\$1,708
212984172	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601714A*	12,400	\$1,736
212984160	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601714A*	12,200	\$1,708
212983730	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601412A*	12,200	\$1,708
212983720	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*92MSN0601412A*	12,200	\$1,708
212983709	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601412A*	12,400	\$1,736
212983699	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*92MSN0601412A*	12,400	\$1,736
212983689	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*92MSN0601412A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983679	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601412A*	12,200	\$1,708
212983669	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*92MSN0601412A*	12,300	\$1,722
212983659	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601412A*	12,000	\$1,680
212983649	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601412A*	12,400	\$1,736
212983639	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*92MSN0601412A*	12,400	\$1,736
212983629	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601412A*	12,100	\$1,694
212983308	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0401712A*	12,300	\$1,722
212983297	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0401712A*	12,400	\$1,736
212983286	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*92MSN0401712A*	12,200	\$1,708
212983275	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*92MSN0401712A*	12,100	\$1,694
212983264	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*92MSN0401712A*	12,300	\$1,722
212983253	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*92MSN0401712A*	12,200	\$1,708
212981883	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU1002120A*	12,300	\$1,722
212981871	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU1002120A*	12,600	\$1,764
212981859	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80MSU1002120A*	12,300	\$1,722
212981847	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80MSU1002120A*	12,100	\$1,694
212981835	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80MSU1002120A*	12,300	\$1,722
212981823	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80MSU1002120A*	12,200	\$1,708
212980004	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	12,300	\$1,722
212979992	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	12,400	\$1,736
212979980	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	12,300	\$1,722
212979968	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212979956	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	12,400	\$1,736
212979944	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212978799	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978788	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978777	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978766	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978755	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978744	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978347	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	12,200	\$1,708
212978335	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	12,200	\$1,708
212978323	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	12,400	\$1,736
212978311	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978299	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978285	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	12,100	\$1,694
212978273	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	12,300	\$1,722
212978261	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978249	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978237	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978225	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212977829	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	12,300	\$1,722
212977817	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	12,300	\$1,722
212977805	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	12,400	\$1,736
212977793	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977781	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977769	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977757	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977745	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	12,100	\$1,694
212977733	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	12,400	\$1,736
212977721	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977709	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0451412A*	12,200	\$1,708
212975840	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716B*	12,200	\$1,708
212975827	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716B*	12,500	\$1,750
212975814	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716B*	12,200	\$1,708
212975801	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716B*	12,000	\$1,680
212975788	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716B*	12,300	\$1,722
212975775	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716B*	12,100	\$1,694
212975488	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412B*	12,200	\$1,708
212975477	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412B*	12,200	\$1,708
212975466	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412B*	12,400	\$1,736
212975455	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412B*	12,400	\$1,736
212975444	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412B*	12,400	\$1,736
212975433	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412B*	12,200	\$1,708
212975422	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412B*	12,200	\$1,708
212975411	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412B*	12,000	\$1,680
212975400	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412B*	12,300	\$1,722
212975389	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412B*	12,200	\$1,708
212975378	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412B*	12,100	\$1,694
212975125	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712B*	12,200	\$1,708
212975114	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712B*	12,500	\$1,750
212975103	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712B*	12,200	\$1,708
212975092	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712B*	12,100	\$1,694
212975081	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712B*	12,300	\$1,722
212975070	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712B*	12,100	\$1,694
212974746	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410B*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974733	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410B*	12,200	\$1,708
212974720	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410B*	12,400	\$1,736
212974707	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410B*	12,400	\$1,736
212974694	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410B*	12,400	\$1,736
212974681	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410B*	12,200	\$1,708
212974668	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410B*	12,200	\$1,708
212974655	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410B*	12,100	\$1,694
212974642	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410B*	12,300	\$1,722
212974629	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410B*	12,400	\$1,736
212974616	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410B*	12,100	\$1,694
212973704	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716B*	12,200	\$1,708
212973694	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716B*	12,500	\$1,750
212973684	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716B*	12,200	\$1,708
212973674	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716B*	12,000	\$1,680
212973664	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716B*	12,300	\$1,722
212973654	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716B*	12,100	\$1,694
212973394	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412B*	12,200	\$1,708
212973384	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412B*	12,200	\$1,708
212973374	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412B*	12,400	\$1,736
212973364	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412B*	12,400	\$1,736
212973354	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412B*	12,400	\$1,736
212973344	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412B*	12,200	\$1,708
212973334	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412B*	12,200	\$1,708
212973324	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412B*	12,000	\$1,680
212973314	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412B*	12,300	\$1,722
212973304	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412B*	12,200	\$1,708
212973294	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412B*	12,100	\$1,694
212973064	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712B*	12,200	\$1,708
212973054	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712B*	12,500	\$1,750
212973044	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712B*	12,200	\$1,708
212973034	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712B*	12,100	\$1,694
212973024	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712B*	12,300	\$1,722
212973014	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712B*	12,100	\$1,694
212972764	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410B*	12,200	\$1,708
212972754	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410B*	12,200	\$1,708
212972744	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410B*	12,400	\$1,736
212972734	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410B*	12,400	\$1,736
212972724	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410B*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972714	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410B*	12,200	\$1,708
212972704	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410B*	12,200	\$1,708
212972694	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410B*	12,100	\$1,694
212972684	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410B*	12,300	\$1,722
212972674	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410B*	12,300	\$1,722
212972664	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410B*	12,100	\$1,694
212971492	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716B*	12,300	\$1,722
212971481	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716B*	12,400	\$1,736
212971470	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716B*	12,300	\$1,722
212971459	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716B*	12,100	\$1,694
212971448	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716B*	12,400	\$1,736
212971437	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716B*	12,200	\$1,708
212969598	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412B*	12,200	\$1,708
212969588	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412B*	12,200	\$1,708
212969578	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412B*	12,500	\$1,750
212969568	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412B*	12,500	\$1,750
212969558	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412B*	12,500	\$1,750
212969548	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412B*	12,400	\$1,736
212969538	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412B*	12,200	\$1,708
212969528	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412B*	12,500	\$1,750
212969518	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412B*	12,500	\$1,750
212969508	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412B*	12,300	\$1,722
211265033	AIRQUEST	DLCURAH18ABK	FVM4X24***L		12,400	\$1,736
211265012	AIRQUEST	DLCURAH18ABK	FM(C,U)4Z30**AL*		12,400	\$1,736
211264990	AIRQUEST	DLCURAH18ABK	FM(C,U)4Z24**AL*		12,500	\$1,750
211264968	AIRQUEST	DLCURAH18ABK	FM(C,U)4Z18**AL*		12,500	\$1,750
211264946	AIRQUEST	DLCURAH18ABK	FMA4X24**AL*		12,400	\$1,736
211264924	AIRQUEST	DLCURAH18ABK	FMA4X18**AL*		12,400	\$1,736
211264903	AIRQUEST	DLCURAH18ABK	FXM4X30**AL		12,400	\$1,736
211264881	AIRQUEST	DLCURAH18ABK	FXM4X24**AL		12,400	\$1,736
211264760	AIRQUEST	DLCURAH18ABK	FEM4P18**AL		12,300	\$1,722
211264736	AIRQUEST	DLCURAH18ABK	FJMA4*18L*A*		12,700	\$1,778
211264710	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	OMV112K14A	12,600	\$1,764
211264692	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	OLV098A12*	12,600	\$1,764
211264674	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	OMV098J12*	12,600	\$1,764
211264654	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0601716A	12,700	\$1,778
211264630	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	12,300	\$1,722
211264607	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401712A*	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211264586	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401410A*	12,500	\$1,750
211264564	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601714A*	12,300	\$1,722
211264542	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601412A*	12,500	\$1,750
211264517	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	12,500	\$1,750
211264494	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	12,400	\$1,736
211264469	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	12,500	\$1,750
211264449	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601714A*	12,400	\$1,736
211264425	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0261410A*	12,600	\$1,764
211264403	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412A*	12,400	\$1,736
211264366	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410A*	12,300	\$1,722
211264302	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0601412A*	12,400	\$1,736
211264271	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401712A*	12,200	\$1,708
211264236	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401410A*	12,400	\$1,736
211264203	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716A*	12,200	\$1,708
211264170	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716A*	12,200	\$1,708
211264138	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712A*	12,400	\$1,736
211264107	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0451412A*	12,300	\$1,722
211264085	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0401712A*	12,700	\$1,778
211264065	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0701716A*	12,200	\$1,708
211264047	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451716A*	12,300	\$1,722
211264002	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESU0401712A*	12,400	\$1,736
211263982	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716A*	12,200	\$1,708
211263964	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412A*	12,400	\$1,736
211263947	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712A*	12,400	\$1,736
211263928	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410A*	12,300	\$1,722
211263910	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601714A*	12,400	\$1,736
211263873	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412A*	12,400	\$1,736
211263850	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	12,300	\$1,722
211263827	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0401410A*	12,500	\$1,750
211263806	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0601412A*	12,500	\$1,750
211263781	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	12,500	\$1,750
211263758	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0261410A*	12,500	\$1,750
211263738	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412A*	12,400	\$1,736
211263717	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410A*	12,200	\$1,708
211263692	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0601412A*	12,400	\$1,736
211263669	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0401410A*	12,400	\$1,736
211263644	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*80VTL0451412A*	12,300	\$1,722
211263623	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263604	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410A*	12,200	\$1,708
211263586	AIRQUEST	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412A*	12,400	\$1,736
211263568	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	OMV112K14A	12,800	\$1,792
211263549	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	OLV098A12*	12,700	\$1,778
211263530	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	OMV098J12*	12,800	\$1,792
211263509	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0601716A	12,800	\$1,792
211263484	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	12,400	\$1,736
211263461	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401712A*	12,600	\$1,764
211263438	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401410A*	12,600	\$1,764
211263415	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0801716A*	12,900	\$1,806
211263392	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601714A*	12,400	\$1,736
211263370	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601412A*	12,600	\$1,764
211263345	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	12,600	\$1,764
211263320	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	12,900	\$1,806
211263295	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	12,600	\$1,764
211263274	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601714A*	12,500	\$1,750
211263248	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0261410A*	12,700	\$1,778
211263228	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412A*	12,500	\$1,750
211263207	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410A*	12,300	\$1,722
211263182	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0601412A*	12,500	\$1,750
211263160	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401712A*	12,300	\$1,722
211263138	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401410A*	12,500	\$1,750
211263121	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716A*	12,300	\$1,722
211263102	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716A*	12,300	\$1,722
211263080	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712A*	12,500	\$1,750
211263052	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0451412A*	12,400	\$1,736
211263031	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0401712A*	12,700	\$1,778
211263009	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0601716A*	12,900	\$1,806
211262989	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0701716A*	12,300	\$1,722
211262971	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451716A*	12,400	\$1,736
211262916	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0401712A*	12,400	\$1,736
211262897	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716A*	12,300	\$1,722
211262879	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412A*	12,500	\$1,750
211262862	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712A*	12,500	\$1,750
211262844	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410A*	12,300	\$1,722
211262826	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601714A*	12,400	\$1,736
211262790	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412A*	12,400	\$1,736
211262768	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262746	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0401410A*	12,600	\$1,764
211262723	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0601412A*	12,600	\$1,764
211262699	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262677	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0261410A*	12,700	\$1,778
211262657	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412A*	12,500	\$1,750
211262636	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410A*	12,300	\$1,722
211262613	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0601412A*	12,500	\$1,750
211262591	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0401410A*	12,500	\$1,750
211262566	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*80VTL0451412A*	12,400	\$1,736
211262546	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412A*	12,500	\$1,750
211262528	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410A*	12,300	\$1,722
211262510	AIRQUEST	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412A*	12,400	\$1,736
211262488	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262466	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0401410A*	12,600	\$1,764
211262445	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0601412A*	12,600	\$1,764
211262421	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262399	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0261410A*	12,700	\$1,778
211262378	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412A*	12,500	\$1,750
211262358	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410A*	12,300	\$1,722
211262334	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0601412A*	12,500	\$1,750
211262312	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0401410A*	12,500	\$1,750
211262289	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*80VTL0451412A*	12,400	\$1,736
211262269	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412A*	12,500	\$1,750
211262251	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410A*	12,300	\$1,722
211262234	AIRQUEST	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412A*	12,500	\$1,750
211262215	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	OMV112K14A	12,600	\$1,764
211262198	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	OLV098A12*	12,600	\$1,764
211262180	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	OMV098J12*	12,600	\$1,764
211262158	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	12,300	\$1,722
211262137	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401712A*	12,500	\$1,750
211262116	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401410A*	12,500	\$1,750
211262094	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601714A*	12,300	\$1,722
211262072	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601412A*	12,500	\$1,750
211262049	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	12,500	\$1,750
211262022	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	12,400	\$1,736
211261996	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261975	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601714A*	12,400	\$1,736
211261949	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*95ESN0261410A*	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261932	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412A*	12,500	\$1,750
211261916	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410A*	12,200	\$1,708
211261890	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*95ESN0601412A*	12,400	\$1,736
211261863	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401712A*	12,200	\$1,708
211261842	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401410A*	12,400	\$1,736
211261827	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716A*	12,200	\$1,708
211261810	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716A*	12,200	\$1,708
211261788	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712A*	12,400	\$1,736
211261761	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80VTL0451412A*	12,300	\$1,722
211261739	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80ESU0401712A*	12,700	\$1,778
211261719	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80VSL0701716A*	12,200	\$1,708
211261701	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451716A*	12,300	\$1,722
211261646	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*95ESU0401712A*	12,300	\$1,722
211261626	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716A*	12,200	\$1,708
211261608	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412A*	12,500	\$1,750
211261590	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712A*	12,400	\$1,736
211261572	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410A*	12,200	\$1,708
211261554	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601714A*	12,400	\$1,736
211261519	AIRQUEST	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451412A*	12,400	\$1,736
211261497	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211261475	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*92ESN0401410A*	12,500	\$1,750
211261454	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*92ESN0601412A*	12,500	\$1,750
211261430	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261408	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*95ESN0261410A*	12,500	\$1,750
211261388	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412A*	12,400	\$1,736
211261368	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410A*	12,200	\$1,708
211261346	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*95ESN0601412A*	12,400	\$1,736
211261324	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*95ESN0401410A*	12,400	\$1,736
211261300	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*80VTL0451412A*	12,300	\$1,722
211261279	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412A*	12,400	\$1,736
211261262	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410A*	12,200	\$1,708
211261243	AIRQUEST	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412A*	12,400	\$1,736
211261224	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	OMV112K14A	12,500	\$1,750
211261206	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	OLV098A12*	12,500	\$1,750
211261181	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	OMV098J12*	12,500	\$1,750
211261149	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80ESU0601716A	12,600	\$1,764
211261106	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701412A*	12,100	\$1,694
211261061	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401712A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261047	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401410A*	12,400	\$1,736
211261034	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601714A*	12,200	\$1,708
211261021	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601412A*	12,400	\$1,736
211261007	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211260992	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211260978	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211260966	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601714A*	12,200	\$1,708
211260951	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*95ESN0261410A*	12,400	\$1,736
211260939	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412A*	12,300	\$1,722
211260927	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410A*	12,100	\$1,694
211260912	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*95ESN0601412A*	12,300	\$1,722
211260898	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401712A*	12,100	\$1,694
211260885	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401410A*	12,300	\$1,722
211260873	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716A*	12,000	\$1,680
211260861	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716A*	12,100	\$1,694
211260847	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712A*	12,300	\$1,722
211260830	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80VTL0451412A*	12,200	\$1,708
211260815	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80ESU0401712A*	12,500	\$1,750
211260804	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80VSL0701716A*	12,100	\$1,694
211260792	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451716A*	12,200	\$1,708
211260759	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*95ESU0401712A*	12,200	\$1,708
211260746	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716A*	12,100	\$1,694
211260736	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412A*	12,300	\$1,722
211260725	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712A*	12,300	\$1,722
211260714	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410A*	12,100	\$1,694
211260704	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601714A*	12,200	\$1,708
211260683	AIRQUEST	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412A*	12,200	\$1,708
211260672	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	OMV112K14A	12,700	\$1,778
211260662	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	OLV098A12*	12,700	\$1,778
211260651	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	OMV098J12*	12,700	\$1,778
211260640	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80ESU0601716A	12,800	\$1,792
211260625	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	12,400	\$1,736
211260614	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401712A*	12,600	\$1,764
211260602	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401410A*	12,600	\$1,764
211260590	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601714A*	12,400	\$1,736
211260577	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601412A*	12,600	\$1,764
211260562	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	12,600	\$1,764
211260548	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	12,900	\$1,806

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260534	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260522	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601714A*	12,400	\$1,736
211260508	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*95ESN0261410A*	12,700	\$1,778
211260496	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412A*	12,500	\$1,750
211260484	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410A*	12,300	\$1,722
211260469	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*95ESN0601412A*	12,500	\$1,750
211260456	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401712A*	12,300	\$1,722
211260443	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401410A*	12,500	\$1,750
211260431	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716A*	12,200	\$1,708
211260419	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716A*	12,300	\$1,722
211260406	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712A*	12,500	\$1,750
211260389	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80VTL0451412A*	12,400	\$1,736
211260376	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80ESU0401712A*	12,700	\$1,778
211260364	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80VSL0701716A*	12,300	\$1,722
211260353	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451716A*	12,400	\$1,736
211260319	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*95ESU0401712A*	12,400	\$1,736
211260307	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716A*	12,300	\$1,722
211260296	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412A*	12,500	\$1,750
211260286	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712A*	12,500	\$1,750
211260275	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410A*	12,300	\$1,722
211260264	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601714A*	12,400	\$1,736
211260243	AIRQUEST	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412A*	12,400	\$1,736
211260230	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211260217	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*92ESN0401410A*	12,600	\$1,764
211260203	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*92ESN0601412A*	12,600	\$1,764
211260187	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260175	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*95ESN0261410A*	12,600	\$1,764
211260165	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412A*	12,500	\$1,750
211260155	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410A*	12,300	\$1,722
211260140	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*95ESN0601412A*	12,500	\$1,750
211260124	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*95ESN0401410A*	12,500	\$1,750
211260110	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*80VTL0451412A*	12,400	\$1,736
211260097	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412A*	12,500	\$1,750
211260084	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410A*	12,300	\$1,722
211260070	AIRQUEST	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412A*	12,400	\$1,736
211260057	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	OMV112K14A	12,600	\$1,764
211260043	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	OLV098A12*	12,500	\$1,750
211260029	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	OMV098J12*	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260014	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80ESU0601716A	12,700	\$1,778
211259998	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701412A*	12,200	\$1,708
211259982	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401712A*	12,400	\$1,736
211259967	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401410A*	12,400	\$1,736
211259950	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601714A*	12,200	\$1,708
211259936	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601412A*	12,500	\$1,750
211259920	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211259904	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211259889	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211259875	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601714A*	12,300	\$1,722
211259858	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*95ESN0261410A*	12,500	\$1,750
211259845	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412A*	12,400	\$1,736
211259834	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410A*	12,100	\$1,694
211259822	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*95ESN0601412A*	12,300	\$1,722
211259809	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401712A*	12,100	\$1,694
211259797	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401410A*	12,400	\$1,736
211259787	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716A*	12,000	\$1,680
211259776	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716A*	12,100	\$1,694
211259764	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712A*	12,300	\$1,722
211259746	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80VTL0451412A*	12,200	\$1,708
211259731	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80ESU0401712A*	12,600	\$1,764
211259718	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80VSL0701716A*	12,100	\$1,694
211259705	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451716A*	12,200	\$1,708
211259666	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*95ESU0401712A*	12,200	\$1,708
211259652	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716A*	12,100	\$1,694
211259640	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412A*	12,400	\$1,736
211259628	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712A*	12,300	\$1,722
211259616	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410A*	12,100	\$1,694
211259603	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601714A*	12,300	\$1,722
211259578	AIRQUEST	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412A*	12,300	\$1,722
211257336	AIRQUEST	DLCURAH18ABK	FJMA4*24L*B*		12,800	\$1,792
205921381	AIRQUEST	DLCSRAH24AAK	DLFSAAH24XAK		17,500	\$2,450
206350485	AIRQUEST	DLCSRBH12AAK	DLFSFAH12XAK		8,400	\$1,176
206350483	AIRQUEST	DLCSRBH12AAK	DLFSCAH12XAK		7,900	\$1,106
206396159	AIRQUEST	DLCSRAH12AAK	DLFSHBH12XAK		7,500	\$1,050
206350484	AIRQUEST	DLCSRBH12AAK	DLFSDAH12XAK		8,300	\$1,162
206350490	AIRQUEST	DLCSRBH24AAK	DLFSDAH24XAK		14,500	\$2,030
206350487	AIRQUEST	DLCSRBH18AAK	DLFSDAH18XAK		12,700	\$1,778

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206188344	AIRQUEST	DLCSRBH24AAK	DLFSAAH24XAK		16,500	\$2,310
206350491	AIRQUEST	DLCSRBH24AAK	DLFSFAH24XAK		14,500	\$2,030
206350489	AIRQUEST	DLCSRBH24AAK	DLFSCAH24XAK		14,500	\$2,030
206350488	AIRQUEST	DLCSRBH18AAK	DLFSFAH18XAK		12,000	\$1,680
207643190	AIRQUEST	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340
207643193	AIRQUEST	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643184	AIRQUEST	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207643192	AIRQUEST	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220
207643183	AIRQUEST	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643189	AIRQUEST	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207643191	AIRQUEST	DLCMHBH36DAK	Heat pump without ducts		22,000	\$3,080
207643188	AIRQUEST	DLCMHBH48EAK	Heat pump without ducts		34,000	\$4,760
207643182	AIRQUEST	DLCMHBH30DAK	Heat pump without ducts		18,500	\$2,590
211222787	AIRQUEST	DLCURAH30ABK	FXM4X36**AL		23,200	\$3,248
211230817	AIRQUEST	DLCURAH36ABK	FEM4P42**AL		29,200	\$4,088
211230828	AIRQUEST	DLCURAH36ABK	FEM4P48**AL		29,400	\$4,116
211230840	AIRQUEST	DLCURAH36ABK	FEM4X42**BL		29,200	\$4,088
211230852	AIRQUEST	DLCURAH36ABK	FEM4X48**BL		29,400	\$4,116
211230874	AIRQUEST	DLCURAH36ABK	FMA4P36**AL*		29,800	\$4,172
211230906	AIRQUEST	DLCURAH36ABK	FXM4X36**AL		29,000	\$4,060
211719728	AIRQUEST	DLCURAH18ABK	FMA4P18**AL*		12,700	\$1,778
211264859	AIRQUEST	DLCURAH18ABK	FXM4X18**AL		12,300	\$1,722
211264837	AIRQUEST	DLCURAH18ABK	FEM4X24**CL		12,100	\$1,694
211264805	AIRQUEST	DLCURAH18ABK	FEM4X18**BL		12,300	\$1,722
211264782	AIRQUEST	DLCURAH18ABK	FEM4P24**AL		12,300	\$1,722
209852135	AIRQUEST	DLCURAH18ABK	DLFUAH18XAK		13,500	\$1,890
209852136	AIRQUEST	DLCURAH24ABK	DLFUAH24XAK		19,200	\$2,688
209852138	AIRQUEST	DLCURAH48ABK	DLFUAH48XAK		36,000	\$5,040
212978656	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978667	AIRQUEST	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978678	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	18,700	\$2,618
212978689	AIRQUEST	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	18,500	\$2,590
212978700	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	19,400	\$2,716
212978711	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	18,900	\$2,646
212978722	AIRQUEST	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701712A*	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978733	AIRQUEST	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701712A*	19,000	\$2,660
212979122	AIRQUEST	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701716A*	19,400	\$2,716
212986154	AIRQUEST	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401410A*	18,800	\$2,632
212986166	AIRQUEST	DLCURAH24ABK	EA*4X30L14A*	*96MSN0401410A*	19,200	\$2,688
212986178	AIRQUEST	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401410A*	19,200	\$2,688
212986190	AIRQUEST	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401410A*	19,200	\$2,688
212986202	AIRQUEST	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401410A*	18,800	\$2,632
212986214	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0401410A*	19,500	\$2,730
212986226	AIRQUEST	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401410A*	19,500	\$2,730
212986238	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0401410A*	19,200	\$2,688
212986250	AIRQUEST	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401410A*	19,200	\$2,688
207801577	AIRQUEST	DLCSRBH18AAK	DLFSDAH24XAK		12,600	\$1,764
207826613	AIRQUEST	DLCSRBH18AAK	DLFSABH18XBK		12,000	\$1,680
217138205	AIRTEMP	UXH48-60MSK3IH	UMD60MSK3IH		45,000	\$6,300
217138204	AIRTEMP	UXH48-60MSK3IH	UMD48MSK3IH		39,500	\$5,530
217138203	AIRTEMP	UXH24-36MSK3IH	UMD36MSK3IH		28,200	\$3,948
217138202	AIRTEMP	UXH24-36MSK3IH	UMD24MSK3IH		20,600	\$2,884
206724408	AIRTEMP	GXH24-36MSK4DH	GMH24-**MSK4DH1		20,000	\$2,800
206724409	AIRTEMP	GXH24-36MSK4DH	GMH**-36MSK4DH1		29,000	\$4,060
206724410	AIRTEMP	GXH48-60MSK4DH	GMH48-**MSK4DH1		39,500	\$5,530
206724411	AIRTEMP	GXH48-60MSK4DH	GMH**-60MSK4DH1		44,000	\$6,160
210276803	AIRTEMP	GXH36(10.6)FMK4DH-1	Heat pump without ducts		30,800	\$4,312
210276804	AIRTEMP	GXH42(12.3)FMK4DH-1	Heat pump without ducts		35,600	\$4,984
210276805	AIRTEMP	GXH18(5.3)FMK4DH-1	Heat pump without ducts		15,000	\$2,100
210276806	AIRTEMP	GXH24(7.0)FMK4DH-1	Heat pump without ducts		23,600	\$3,304
210276807	AIRTEMP	GXH30(8.8)FMK4DH-1	Heat pump without ducts		27,200	\$3,808
210534162	AIRTEMP	GXH12(3.5)LSK4DH2	GHH12(3.5)LUK4DH2		10,000	\$1,400
210534164	AIRTEMP	GXH30(8.8)LSK4DH2	GHH30(8.8)LUK4DH2		24,000	\$3,360
210534165	AIRTEMP	GXH36(10.6)LSK4DH2	GHH36(10.6)LUK4DH2		27,800	\$3,892
211497140	AIRTEMP	GXH18(5.3)LSK4DH2	GHH18(5.3)LUK4DH2		10,800	\$1,512
216011802	AIRTEMP	DXH12PSK3IH	DKH12FMK3IH		10,000	\$1,400
216011758	AIRTEMP	DXH30ESK3IL	DHH30ESK3IL		24,000	\$3,360
216011757	AIRTEMP	DXH12PSK3IH	DHH12PUK3IH		10,000	\$1,400
216011751	AIRTEMP	DXH36ESK3IL	DHH36ESK3IL		27,400	\$3,836
215746309	AIRTEMP	DXH42FMK3IH	Combination heat pumps with or without ducts		40,000	\$5,600
215746308	AIRTEMP	DXH36FMK3IH	Combination heat pumps with or without ducts		36,000	\$5,040

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215746307	AIRTEMP	DXH30FMK3IH	Combination heat pumps with or without ducts		27,600	\$3,864
215746306	AIRTEMP	DXH24FMK3IH	Combination heat pumps with or without ducts		22,800	\$3,192
215746305	AIRTEMP	DXH42FMK3IH	Heat pump with ducts		40,000	\$5,600
215746304	AIRTEMP	DXH36FMK3IH	Heat pump with ducts		36,000	\$5,040
215746303	AIRTEMP	DXH30FMK3IH	Heat pump with ducts		27,200	\$3,808
215746302	AIRTEMP	DXH24FMK3IH	Heat pump with ducts		22,000	\$3,080
215746301	AIRTEMP	DXH18FMK3IH	Combination heat pumps with or without ducts		15,400	\$2,156
215746300	AIRTEMP	DXH18FMK3IH	Heat pump with ducts		15,000	\$2,100
215746299	AIRTEMP	DXH42FMK3IH	Heat pump without ducts		40,000	\$5,600
215746298	AIRTEMP	DXH36FMK3IH	Heat pump without ducts		36,000	\$5,040
215746297	AIRTEMP	DXH30FMK3IH	Heat pump without ducts		28,000	\$3,920
215746296	AIRTEMP	DXH24FMK3IH	Heat pump without ducts		23,600	\$3,304
215746295	AIRTEMP	DXH18FMK3IH	Heat pump without ducts		16,000	\$2,240
208106794	Allied	4DHP2S48M-1P	Heat pump without ducts		36,000	\$5,040
213307912	ALSETRIA	M4OX630-36HFN1-M1X	Heat pump without ducts		27,400	\$3,836
213307913	ALSETRIA	M4OX630-36HFN1-M1X	Heat pump with ducts		30,000	\$4,200
213307914	ALSETRIA	M4OX630-36HFN1-M1X	Combination heat pumps with or without ducts		28,600	\$4,004
208121904	Alsetria	MOD30-24HFN1-MU0W	MSEPD-24HRFN1-MU0W		21,200	\$2,968
211644040	Alsetria	MOD30-24HFN1-MU0W	MTIU-24HWFN1-M		21,000	\$2,940
211644047	Alsetria	MOE30U-36HFN1-M(GA)	MCD1-36HRFN1-M(GA)		33,000	\$4,620
211644048	Alsetria	MOE30U-48HFN1-M-[X](GA)	MCD1-48HRFN1-M(GA)		35,000	\$4,900
208121902	Alsetria	MOX330-12HFN1-MW5W	MSEPB-12HRFN1-MW5W(GA)		10,000	\$1,400
211644038	Alsetria	MOX330-12HFN1-MW5W	MTIU-12HWFN1-M		10,600	\$1,484
211644044	Alsetria	MOX330-12HFN1-MW5W	CCA3U-12HRFN1-M(C)		9,900	\$1,386
211644100	Alsetria	MOX330-12HFN1-MW5W	MCBU-12HRFN1-MV0W		9,500	\$1,330
208121903	Alsetria	MOX430-17HFN1-MT0W	MSEPC-18HRFN1-MU0W		15,000	\$2,100
211644039	Alsetria	MOX430-17HFN1-MT0W	MTIU-18HWFN1-M		15,000	\$2,100
211644101	Alsetria	MOX430-17HFN1-MT0W	MCBU-18HRFN1-MU2W		14,500	\$2,030
211644107	Alsetria	MOD30-24HFN1-MU0W	MVC-23HWFN1-M		16,900	\$2,366
208130392	Alsetria	MOD30-24HFN1-MW	MVC-24HWFN1-M		19,200	\$2,688
213081456	ALSETRIA	MOD30-24HFN1-MW	MVBE-24HWFN1-MM3E		20,000	\$2,800
208130393	ALSETRIA	MOD30U-30HFN1-MR0(X)	MVC-30HWFN1-M		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213363367	ALSETRIA	MOE30U-45HFN1-M	MAC-60HWDN1-MN0		37,000	\$5,180
208130395	Alsetria	MOE30U-48HFN1-M-[X1]	MVC-48HWFN1-M		36,000	\$5,040
213081455	ALSETRIA	MOE30U-55HFN1-M	MVC-60HWFN1-M		42,000	\$5,880
208130394	ALSETRIA	MOE31U-36HFN1-M	MVC-36HWFN1-M		30,400	\$4,256
213386485	Alsetria	MOE31U-36HFN1-M	MVB-36B23T4N1		27,400	\$3,836
211644106	Alsetria	MOX430-17HFN1-MT0W	MVC-18HWFN1-MW(GA)		15,400	\$2,156
208130391	Alsetria	MOX430U-18HFN1-M	MVC-18HWFN1-M		13,500	\$1,890
213307910	ALSETRIA	MOX430U-18HFN1-M	MVBE-18HWFN1-MM3E		15,800	\$2,212
213386486	ALSETRIA	MOX630-36HFN1-M3X	MVB-36B23T4N1		27,000	\$3,780
213386487	ALSETRIA	MOX630-36HFN1-M3X	MAC-36HWDN1-MN0		27,000	\$3,780
213485861	ALSETRIA	MOX630-36HFN1-M3X	MVC-36HWFN1-M		31,800	\$4,452
216699887	AMANA	AZV9SA361CA*	CHPEA4830*3A*	A*VM970804CNA*	30,800	\$4,312
216699885	AMANA	AZV9SA361CA*	CHPEA4830*3A*	A*VM971005CNA*	30,800	\$4,312
216699883	AMANA	AZV9SA361CA*	CHPEA4830*3A*	A*VS800805CUA*	30,800	\$4,312
216699881	AMANA	AZV9SA361CA*	CHPEA4830*3A*	A*VT800804C*A*	30,800	\$4,312
216699879	AMANA	AZV9SA361CA*	CHPEA4830*3A*	A*VT800805C*A*	30,800	\$4,312
216699877	AMANA	AZV9SA361CA*	CHPEA4830*3A*	A*VT801005C*A*	30,800	\$4,312
216699875	AMANA	AZV9SA361CA*	CHPEA4830*3A*	A*VT960804CNA*	30,800	\$4,312
216699873	AMANA	AZV9SA361CA*	CHPEA4830*3A*	A*VT961005CNA*	30,800	\$4,312
216699871	AMANA	AZV9SA361CA*	CHPEA4830*3A*+MBVK16C P1X00A*		30,800	\$4,312
216699794	AMANA	AZV9SA361CA*	CAHEA3630C3A*+MBVK16C H*X00A*		34,200	\$4,788
216699793	AMANA	AZV9SA241CA*	CAHEA3630C3A*+MBVK16C H*X00A*		24,000	\$3,360
216699888	AMANA	AZV9SA361CA*	CA*EA6030*3A*	A*VM970804CNA*	31,000	\$4,340
216699886	AMANA	AZV9SA361CA*	CA*EA6030*3A*	A*VM971005CNA*	31,000	\$4,340
216699884	AMANA	AZV9SA361CA*	CA*EA6030*3A*	A*VS800805CUA*	31,000	\$4,340
216699882	AMANA	AZV9SA361CA*	CA*EA6030*3A*	A*VT800804C*A*	31,000	\$4,340
216699880	AMANA	AZV9SA361CA*	CA*EA6030*3A*	A*VT800805C*A*	31,000	\$4,340
216699878	AMANA	AZV9SA361CA*	CA*EA6030*3A*	A*VT801005C*A*	31,000	\$4,340
216699876	AMANA	AZV9SA361CA*	CA*EA6030*3A*	A*VT960804CNA*	31,000	\$4,340
216699874	AMANA	AZV9SA361CA*	CA*EA6030*3A*	A*VT961005CNA*	31,000	\$4,340
216699872	AMANA	AZV9SA361CA*	CA*EA6030*3A*+MBVK16CP 1X00A*		31,000	\$4,340
216699870	AMANA	AZV9SA361CA*	AHVE48CP0300A*		32,000	\$4,480
216699869	AMANA	AZV9SA361CA*	AHVE48CP1300A*		32,000	\$4,480
216699868	AMANA	AZV9SA361CA*	AHVE48DP0300A*		32,000	\$4,480

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216699867	AMANA	AZV9SA361CA*	AHVE48DP1300A*		32,000	\$4,480
216699866	AMANA	AZV9SA361CA*	AHVE60DP0300A*		32,000	\$4,480
216699865	AMANA	AZV9SA361CA*	AHVE60DP1300A*		32,000	\$4,480
216699864	AMANA	AZV9SA241CA*	CA*EA4830*3A*	A*VM970804CNA*	22,000	\$3,080
216699863	AMANA	AZV9SA241CA*	CHPEA4830*3A*	A*VM970804CNA*	21,000	\$2,940
216699862	AMANA	AZV9SA241CA*	CA*EA4830*3A*	A*VM971005CNA*	22,000	\$3,080
216699861	AMANA	AZV9SA241CA*	CHPEA4830*3A*	A*VM971005CNA*	21,000	\$2,940
216699860	AMANA	AZV9SA241CA*	CA*EA4830*3A*	A*VS800805CUA*	22,000	\$3,080
216699859	AMANA	AZV9SA241CA*	CHPEA4830*3A*	A*VS800805CUA*	21,000	\$2,940
216699858	AMANA	AZV9SA241CA*	CA*EA4830*3A*	A*VS960805CUA*	22,000	\$3,080
216699857	AMANA	AZV9SA241CA*	CHPEA4830*3A*	A*VS960805CUA*	21,000	\$2,940
216699856	AMANA	AZV9SA241CA*	CA*EA4830*3A*	A*VT800804C*A*	22,000	\$3,080
216699855	AMANA	AZV9SA241CA*	CHPEA4830*3A*	A*VT800804C*A*	21,000	\$2,940
216699854	AMANA	AZV9SA241CA*	CA*EA4830*3A*	A*VT800805C*A*	22,000	\$3,080
216699853	AMANA	AZV9SA241CA*	CHPEA4830*3A*	A*VT800805C*A*	21,000	\$2,940
216699852	AMANA	AZV9SA241CA*	CA*EA4830*3A*	A*VT801005C*A*	22,000	\$3,080
216699851	AMANA	AZV9SA241CA*	CHPEA4830*3A*	A*VT801005C*A*	21,000	\$2,940
216699850	AMANA	AZV9SA241CA*	CA*EA4830*3A*	A*VT960804CNA*	22,000	\$3,080
216699849	AMANA	AZV9SA241CA*	CHPEA4830*3A*	A*VT960804CNA*	21,000	\$2,940
216699848	AMANA	AZV9SA241CA*	CA*EA4830*3A*	A*VT961005CNA*	22,000	\$3,080
216699847	AMANA	AZV9SA241CA*	CHPEA4830*3A*	A*VT961005CNA*	21,000	\$2,940
216699846	AMANA	AZV9SA241CA*	CA*EA4830*3A*+MBVK16CP1X00A*		22,000	\$3,080
216699845	AMANA	AZV9SA241CA*	CHPEA4830*3A*+MBVK16CP1X00A*		21,000	\$2,940
216699844	AMANA	AZV9SA241CA*	AHVE48CP0300A*		23,000	\$3,220
216699843	AMANA	AZV9SA241CA*	AHVE48CP1300A*		23,000	\$3,220
216835180	AMANA	AZV7SA6010A*	CAHEA3630C3A*+MBVK16CHX00A*		33,400	\$4,676
216835178	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VM971005CNA*	33,400	\$4,676
216835175	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VM971005CNA*	33,400	\$4,676
216835172	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VM971205DNA*	33,400	\$4,676
216835169	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VM971205DNA*	33,400	\$4,676
216835167	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VS800805CUA*	33,400	\$4,676
216835164	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VS800805CUA*	33,400	\$4,676
216835161	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VT800804C*A*	33,400	\$4,676
216835159	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VT800804C*A*	33,400	\$4,676
216835156	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VT800805C*A*	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216835154	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VT800805C*A*	33,400	\$4,676
216835151	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VT800805D*A*	33,400	\$4,676
216835149	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VT800805D*A*	33,400	\$4,676
216835147	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VT801005C*A*	33,400	\$4,676
216835144	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VT801005C*A*	33,400	\$4,676
216835142	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VT960804CNA*	33,400	\$4,676
216835140	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VT960804CNA*	33,400	\$4,676
216835138	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VT961005CNA*	33,400	\$4,676
216835133	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VT961005CNA*	33,400	\$4,676
216835131	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VT961005DNA*	33,400	\$4,676
216835129	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VT961005DNA*	33,400	\$4,676
216835125	AMANA	AZV7SA6010A*	CA*EA6030*3A*	A*VT961205DNA*	33,400	\$4,676
216835123	AMANA	AZV7SA6010A*	CHPEA6030*3A*	A*VT961205DNA*	33,400	\$4,676
216835119	AMANA	AZV7SA6010A*	CA*EA6030*3A*+MBVK16CP1X00A*		33,400	\$4,676
216835116	AMANA	AZV7SA6010A*	CHPEA6030*3A*+MBVK16CP1X00A*		33,400	\$4,676
216835114	AMANA	AZV7SA6010A*	CA*EA6030*3A*+MBVK20DP1X00A*		33,400	\$4,676
216835109	AMANA	AZV7SA6010A*	CHPEA6030*3A*+MBVK20DP1X00A*		33,400	\$4,676
216835107	AMANA	AZV7SA6010A*	AHVE60DP0300A*		33,400	\$4,676
216835066	AMANA	AZV7SA6010A*	AHVE60DP1300A*		33,400	\$4,676
213872277	AMANA	ASZS60481EA*	CA*EA6030*4A*	A*VC801005C*A*	28,000	\$3,920
214491768	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VS800604BUA*	10,800	\$1,512
214491769	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VC800603B*A*	10,800	\$1,512
214491770	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VC800604B*A*	10,800	\$1,512
214491771	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VC800803B*A*	10,800	\$1,512
214491772	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VS960603BUA*	10,800	\$1,512
214491773	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VC960403BNB*	10,800	\$1,512
214491774	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VC960603BNB*	10,800	\$1,512
214491775	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VC960803BNB*	10,800	\$1,512
214491776	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VM970603BNB*	10,800	\$1,512
214491777	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VM970803BNB*	10,800	\$1,512
214491778	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VS800805CUA*	10,800	\$1,512
214491779	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VC800804C*A*	10,800	\$1,512
214491780	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VC800805C*A*	10,800	\$1,512
214491781	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VS960805CUA*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214491782	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VC960804CNB*	10,800	\$1,512
214491783	AMANA	ASZS601810A*	CA*EA1818*4B*	A*VM970804CNB*	10,800	\$1,512
214491784	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VS800604BUA*	10,800	\$1,512
214491785	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VC800603B*A*	10,800	\$1,512
214491786	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VC800604B*A*	10,800	\$1,512
214491787	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VC800803B*A*	10,800	\$1,512
214491788	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VS960603BUA*	10,800	\$1,512
214491789	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VC960403BNB*	10,800	\$1,512
214491790	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VC960603BNB*	10,800	\$1,512
214491791	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VC960803BNB*	10,800	\$1,512
214491792	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VM970603BNB*	10,800	\$1,512
214491793	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VM970803BNB*	10,800	\$1,512
214491794	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VS800805CUA*	10,800	\$1,512
214491795	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VC800804C*A*	10,800	\$1,512
214491796	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VC800805C*A*	10,800	\$1,512
214491797	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VS960805CUA*	10,800	\$1,512
214491798	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VC960804CNB*	10,800	\$1,512
214491799	AMANA	ASZS601810A*	CA*EA2422*4B*	A*VM970804CNB*	10,800	\$1,512
214491892	AMANA	ASZS601810A*	CA*EA1818*4B*+MBVC1200* *-1A*		10,800	\$1,512
214491893	AMANA	ASZS601810A*	CA*EA1818*4B*+MBVC1600* *-1A*		10,800	\$1,512
214491894	AMANA	ASZS601810A*	CA*EA2422*4B*+MBVC1200* *-1A*		10,800	\$1,512
214491895	AMANA	ASZS601810A*	CA*EA2422*4B*+MBVC1600* *-1A*		10,800	\$1,512
214500320	AMANA	ASZS601810A*	CA*EA1818*4B*+MBVK12BP 1X00A*		10,800	\$1,512
214500321	AMANA	ASZS601810A*	CA*EA1818*4B*+MBVK16CP 1X00A*		10,800	\$1,512
214500322	AMANA	ASZS601810A*	CA*EA2422*4B*+MBVK12BP 1X00A*		10,800	\$1,512
214500323	AMANA	ASZS601810A*	CA*EA2422*4B*+MBVK16CP 1X00A*		10,800	\$1,512
214505274	AMANA	ASZS60241EA*	CA*EA2422*4B*+MBVC1200* *-1A*		16,000	\$2,240
214505276	AMANA	ASZS60241EA*	CA*EA2422*4B*+MBVC1600* *-1A*		16,000	\$2,240
214505279	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC800603B*A*	16,000	\$2,240

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214505282	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC800604B*A*	16,000	\$2,240
214505284	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VS800604BUA*	16,000	\$2,240
214505287	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC800803B*A*	16,000	\$2,240
214505290	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC800804C*A*	16,000	\$2,240
214505293	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC800805C*A*	16,000	\$2,240
214505296	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VS800805CUA*	16,000	\$2,240
214505299	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC801005C*A*	16,000	\$2,240
214505302	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC960403BNB*	16,000	\$2,240
214505305	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC960603BNB*	16,000	\$2,240
214505308	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VS960603BUA*	16,000	\$2,240
214505310	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC960803BNB*	16,000	\$2,240
214505313	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC960804CNB*	16,000	\$2,240
214505316	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VS960805CUA*	16,000	\$2,240
214505319	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VC961005CNB*	16,000	\$2,240
214505322	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VM970603BNB*	16,000	\$2,240
214505325	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VM970803BNB*	16,000	\$2,240
214505328	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VM970804CNB*	16,000	\$2,240
214505331	AMANA	ASZS60241EA*	CA*EA2422*4B*	A*VM971005CNB*	16,000	\$2,240
214505334	AMANA	ASZS60241EA*	CA*EA3026*4B*+MBVC1200* *-1A*		16,000	\$2,240
214505336	AMANA	ASZS60241EA*	CA*EA3026*4B*+MBVC1600* *-1A*		16,000	\$2,240
214505339	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC800603B*A*	16,000	\$2,240
214505341	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC800604B*A*	16,000	\$2,240
214505344	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VS800604BUA*	16,000	\$2,240
214505346	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC800803B*A*	16,000	\$2,240
214505349	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC800804C*A*	16,000	\$2,240
214505352	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC800805C*A*	16,000	\$2,240
214505355	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VS800805CUA*	16,000	\$2,240
214505358	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC801005C*A*	16,000	\$2,240
214505361	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC960403BNB*	16,000	\$2,240
214505364	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC960603BNB*	16,000	\$2,240
214505367	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VS960603BUA*	16,000	\$2,240
214505369	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC960803BNB*	16,000	\$2,240
214505372	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC960804CNB*	16,000	\$2,240
214505375	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VS960805CUA*	16,000	\$2,240
214505378	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VC961005CNB*	16,000	\$2,240
214505381	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VM970603BNB*	16,000	\$2,240

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214505384	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VM970803BNB*	16,000	\$2,240
214505387	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VM970804CNB*	16,000	\$2,240
214505389	AMANA	ASZS60241EA*	CA*EA3026*4B*	A*VM971005CNB*	16,000	\$2,240
214505411	AMANA	ASZS60241EA*	CA*EA2422*4B*+MBVK12BP1X00A*		16,000	\$2,240
214505414	AMANA	ASZS60241EA*	CA*EA2422*4B*+MBVK16CP1X00A*		16,000	\$2,240
214505416	AMANA	ASZS60241EA*	CA*EA3026*4B*+MBVK12BP1X00A*		16,000	\$2,240
214505419	AMANA	ASZS60241EA*	CA*EA3026*4B*+MBVK16CP1X00A*		16,000	\$2,240
215487772	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VM971205DNB*	29,000	\$4,060
215487771	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VC961205DNB*	29,000	\$4,060
215487770	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VC800805D*A*	29,000	\$4,060
215487769	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VM971005CNB*	29,000	\$4,060
215487768	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VM970804CNB*	29,000	\$4,060
215487767	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VC961005CNB*	29,000	\$4,060
215487766	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VC960804CNB*	29,000	\$4,060
215487765	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VC801005C*A*	29,000	\$4,060
215487764	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VC800805C*A*	29,000	\$4,060
215487763	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VC800804C*A*	29,000	\$4,060
215487762	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VM971205DNB*	28,400	\$3,976
215487761	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VC961205DNB*	28,400	\$3,976
215487760	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VC800805D*A*	28,400	\$3,976
215487759	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VM971005CNB*	28,400	\$3,976
215487758	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VM970804CNB*	28,400	\$3,976
215487757	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VC961005CNB*	28,400	\$3,976
215487756	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VC960804CNB*	28,400	\$3,976
215487755	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VC801005C*A*	28,400	\$3,976
215487754	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VC800805C*A*	28,400	\$3,976
215487753	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VC800804C*A*	28,400	\$3,976
215487752	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VM971205DNB*	29,000	\$4,060
215487751	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VC961205DNB*	29,000	\$4,060
215487750	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VC800805D*A*	29,000	\$4,060
215487749	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VM971005CNB*	29,000	\$4,060
215487748	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VM970804CNB*	29,000	\$4,060
215487747	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VC961005CNB*	29,000	\$4,060
215487746	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VC960804CNB*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215487745	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VC801005C*A*	29,000	\$4,060
215487744	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VC800805C*A*	29,000	\$4,060
215487743	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VC800804C*A*	29,000	\$4,060
215487742	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VC961205DNB*	28,000	\$3,920
215487741	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VC961005CNB*	28,000	\$3,920
215487740	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VC960804CNB*	28,000	\$3,920
215487739	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VC801005C*A*	28,000	\$3,920
215487738	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VC800805D*A*	28,000	\$3,920
215487737	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VC800805C*A*	28,000	\$3,920
215487736	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VC800804C*A*	28,000	\$3,920
215487735	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VM971205DNB*	28,000	\$3,920
215487734	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VM971005CNB*	28,000	\$3,920
215487733	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VM970804CNB*	28,000	\$3,920
215487732	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VC961205DNB*	28,000	\$3,920
215487731	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VC961005CNB*	28,000	\$3,920
215487730	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VC960804CNB*	28,000	\$3,920
215487729	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VC801005C*A*	28,000	\$3,920
215487728	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VC800805D*A*	28,000	\$3,920
215487727	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VC800805C*A*	28,000	\$3,920
215487726	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VC800804C*A*	28,000	\$3,920
215487725	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VM971205DNB*	28,000	\$3,920
215487724	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VM971005CNB*	28,000	\$3,920
215487723	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VM970804CNB*	28,000	\$3,920
215487722	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VC961205DNB*	28,000	\$3,920
215487721	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VC961005CNB*	28,000	\$3,920
215487720	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VC960804CNB*	28,000	\$3,920
215487719	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VC801005C*A*	28,000	\$3,920
215487718	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VC800805D*A*	28,000	\$3,920
215487717	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VC800805C*A*	28,000	\$3,920
215487716	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VC800804C*A*	28,000	\$3,920
215487715	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VM971205DNB*	28,000	\$3,920
215487714	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VM971005CNB*	28,000	\$3,920
215487713	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VM970804CNB*	28,000	\$3,920
215487712	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VM970804CNB*	22,000	\$3,080
215487711	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VM971005CNB*	22,000	\$3,080
215487710	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VM971205DNB*	22,000	\$3,080
215487709	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VC800804C*A*	22,000	\$3,080
215487708	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VC800805C*A*	22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215487707	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VC800805D*A*	22,000	\$3,080
215487706	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VC801005C*A*	22,000	\$3,080
215487705	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VC960804CNB*	22,000	\$3,080
215487704	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VC961005CNB*	22,000	\$3,080
215487703	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VC961205DNB*	22,000	\$3,080
215487702	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VC800804C*A*	22,000	\$3,080
215487701	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VC800805C*A*	22,000	\$3,080
215487700	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VC800805D*A*	22,000	\$3,080
215487699	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VC801005C*A*	22,000	\$3,080
215487698	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VM970804CNB*	22,000	\$3,080
215487697	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VM971005CNB*	22,000	\$3,080
215487696	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VM971205DNB*	22,000	\$3,080
215487695	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VC800804C*A*	22,000	\$3,080
215487694	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VC800805C*A*	22,000	\$3,080
215487693	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VC800805D*A*	22,000	\$3,080
215487692	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VC801005C*A*	22,000	\$3,080
215487691	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VC960804CNB*	22,000	\$3,080
215487690	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VC961005CNB*	22,000	\$3,080
215487689	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VC961205DNB*	22,000	\$3,080
215487688	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC961005CNB*	15,800	\$2,212
215487687	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC960804CNB*	15,800	\$2,212
215487686	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC960803BNB*	15,800	\$2,212
215487685	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC960603BNB*	15,800	\$2,212
215487684	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC960403BNB*	15,800	\$2,212
215487683	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC801005C*A*	15,800	\$2,212
215487682	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC800805C*A*	15,800	\$2,212
215487681	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC800804C*A*	15,800	\$2,212
215487680	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC800803B*A*	15,800	\$2,212
215487679	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC800604B*A*	15,800	\$2,212
215487678	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VC800603B*A*	15,800	\$2,212
215487677	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VM971005CNB*	15,800	\$2,212
215487676	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VM970804CNB*	15,800	\$2,212
215487675	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VM970803BNB*	15,800	\$2,212
215487674	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VM970603BNB*	15,800	\$2,212
215487673	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC961005CNB*	15,800	\$2,212
215487672	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC960804CNB*	15,800	\$2,212
215487671	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC960803BNB*	15,800	\$2,212
215487670	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC960603BNB*	15,800	\$2,212

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215487669	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC960403BNB*	15,800	\$2,212
215487668	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC801005C*A*	15,800	\$2,212
215487667	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC800805C*A*	15,800	\$2,212
215487666	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC800804C*A*	15,800	\$2,212
215487665	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC800803B*A*	15,800	\$2,212
215487664	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC800604B*A*	15,800	\$2,212
215487663	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VC800603B*A*	15,800	\$2,212
215487662	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VM971005CNB*	15,800	\$2,212
215487661	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VM970804CNB*	15,800	\$2,212
215487660	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VM970803BNB*	15,800	\$2,212
215487659	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VM970603BNB*	15,800	\$2,212
215487658	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC961005CNB*	15,800	\$2,212
215487657	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC960804CNB*	15,800	\$2,212
215487656	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC960803BNB*	15,800	\$2,212
215487655	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC960603BNB*	15,800	\$2,212
215487654	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC960403BNB*	15,800	\$2,212
215487653	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC801005C*A*	15,800	\$2,212
215487652	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC800805C*A*	15,800	\$2,212
215487651	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC800804C*A*	15,800	\$2,212
215487650	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC800803B*A*	15,800	\$2,212
215487649	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VC800603B*A*	15,800	\$2,212
215487648	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VM971005CNB*	15,800	\$2,212
215487647	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VM970804CNB*	15,800	\$2,212
215487646	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VM970803BNB*	15,800	\$2,212
215487645	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VM970603BNB*	15,800	\$2,212
215439717	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VM970603BNA*	10,800	\$1,512
215439716	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VM970603BNA*	10,800	\$1,512
215439715	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VM970603BNA*	10,800	\$1,512
215439714	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VM970803BNA*	10,800	\$1,512
215439713	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VM970803BNA*	10,800	\$1,512
215439712	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VM970803BNA*	10,800	\$1,512
215439711	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VM970804CNA*	10,800	\$1,512
215439710	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VM970804CNA*	10,800	\$1,512
215439699	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VT800603B*A*	10,800	\$1,512
215439698	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VT800603B*A*	10,800	\$1,512
215439697	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VT800603B*A*	10,800	\$1,512
215439696	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VT800604B*A*	10,800	\$1,512
215439695	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VT800604B*A*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215439694	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VT800604B*A*	10,800	\$1,512
215439693	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VT800803B*A*	10,800	\$1,512
215439692	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VT800803B*A*	10,800	\$1,512
215439691	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VT800803B*A*	10,800	\$1,512
215439690	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VT800804C*A*	10,800	\$1,512
215439689	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VT800804C*A*	10,800	\$1,512
215439688	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VT800805C*A*	10,800	\$1,512
215439687	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VT800805C*A*	10,800	\$1,512
215439686	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VT960403BNA*	10,800	\$1,512
215439685	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VT960403BNA*	10,800	\$1,512
215439684	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VT960403BNA*	10,800	\$1,512
215439683	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VT960603BNA*	10,800	\$1,512
215439682	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VT960603BNA*	10,800	\$1,512
215439681	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VT960603BNA*	10,800	\$1,512
215439680	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VT960803BNA*	10,800	\$1,512
215439679	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VT960803BNA*	10,800	\$1,512
215439678	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VT960803BNA*	10,800	\$1,512
215439677	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VT960804CNA*	10,800	\$1,512
215439676	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VT960804CNA*	10,800	\$1,512
215487804	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VM970603BNB*	10,800	\$1,512
215487803	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VM970603BNB*	10,800	\$1,512
215487802	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VM970603BNB*	10,800	\$1,512
215487801	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VM970803BNB*	10,800	\$1,512
215487800	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VM970803BNB*	10,800	\$1,512
215487799	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VM970803BNB*	10,800	\$1,512
215487798	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VM970804CNB*	10,800	\$1,512
215487797	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VM970804CNB*	10,800	\$1,512
215439709	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VS800604BUA*	10,800	\$1,512
215439708	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VS800604BUA*	10,800	\$1,512
215439707	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VS800604BUA*	10,800	\$1,512
215439706	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VS800805CUA*	10,800	\$1,512
215439705	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VS800805CUA*	10,800	\$1,512
215439704	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VS960603BUA*	10,800	\$1,512
215439703	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VS960603BUA*	10,800	\$1,512
215439702	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VS960603BUA*	10,800	\$1,512
215439701	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VS960805CUA*	10,800	\$1,512
215439700	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VS960805CUA*	10,800	\$1,512
215487796	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VC800603B*A*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215487795	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VC800603B*A*	10,800	\$1,512
215487794	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VC800603B*A*	10,800	\$1,512
215487793	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VC800604B*A*	10,800	\$1,512
215487792	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VC800604B*A*	10,800	\$1,512
215487791	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VC800604B*A*	10,800	\$1,512
215487790	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VC800803B*A*	10,800	\$1,512
215487789	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VC800803B*A*	10,800	\$1,512
215487788	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VC800803B*A*	10,800	\$1,512
215487787	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VC800804C*A*	10,800	\$1,512
215487786	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VC800804C*A*	10,800	\$1,512
215487785	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VC800805C*A*	10,800	\$1,512
215487784	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VC800805C*A*	10,800	\$1,512
215487783	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VC960403BNB*	10,800	\$1,512
215487782	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VC960403BNB*	10,800	\$1,512
215487781	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VC960403BNB*	10,800	\$1,512
215487780	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VC960603BNB*	10,800	\$1,512
215487779	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VC960603BNB*	10,800	\$1,512
215487778	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VC960603BNB*	10,800	\$1,512
215487777	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VC960803BNB*	10,800	\$1,512
215487776	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VC960803BNB*	10,800	\$1,512
215487775	AMANA	AZV6SA1810A*	CHPEA2422*3A*	A*VC960803BNB*	10,800	\$1,512
215487774	AMANA	AZV6SA1810A*	CA*EA2418*3A*	A*VC960804CNB*	10,800	\$1,512
215487773	AMANA	AZV6SA1810A*	CA*EA3022*3A*	A*VC960804CNB*	10,800	\$1,512
215439769	AMANA	AZV6SA1810A*	CA*EA2418*3A*+MBVK12BP1X00A*		10,800	\$1,512
215439768	AMANA	AZV6SA1810A*	CA*EA3022*3A*+MBVK12BP1X00A*		10,800	\$1,512
215439767	AMANA	AZV6SA1810A*	CHPEA2422*3A*+MBVK12BP1X00A*		10,800	\$1,512
215439766	AMANA	AZV6SA1810A*	CA*EA2418*3A*+MBVK16CP1X00A*		10,800	\$1,512
215439765	AMANA	AZV6SA1810A*	CA*EA3022*3A*+MBVK16CP1X00A*		10,800	\$1,512
215429768	AMANA	AZV6SA1810A*	AHVE24BP0300A*		10,800	\$1,512
215429180	AMANA	AZV6SA1810A*	AHVE24BP1300A*		10,800	\$1,512
215433958	AMANA	AZV7SA4810A*	CHPEA6030*3A*+MBVK20DP1X00A*		29,000	\$4,060
215434425	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VM971205DNA*	29,000	\$4,060
215434424	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VT961205DNA*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434423	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VT961005DNA*	29,000	\$4,060
215434422	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VT800805D*A*	29,000	\$4,060
215433957	AMANA	AZV7SA4810A*	CHPEA6030*3A*+MBVK16C P1X00A*		29,000	\$4,060
215434421	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VM971005CNA*	29,000	\$4,060
215434420	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VM970804CNA*	29,000	\$4,060
215434419	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VT961005CNA*	29,000	\$4,060
215434418	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VT960804CNA*	29,000	\$4,060
215434417	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VS960805CUA*	29,000	\$4,060
215434416	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VT801005C*A*	29,000	\$4,060
215434415	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VT800805C*A*	29,000	\$4,060
215434414	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VT800804C*A*	29,000	\$4,060
215434413	AMANA	AZV7SA4810A*	CHPEA6030*3A*	A*VS800805CUA*	29,000	\$4,060
215433956	AMANA	AZV7SA4810A*	CHPEA4830*3A*+MBVK20D P1X00A*		28,400	\$3,976
215434412	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VM971205DNA*	28,400	\$3,976
215434411	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VT961205DNA*	28,400	\$3,976
215434410	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VT961005DNA*	28,400	\$3,976
215434409	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VT800805D*A*	28,400	\$3,976
215433955	AMANA	AZV7SA4810A*	CHPEA4830*3A*+MBVK16C P1X00A*		28,400	\$3,976
215434408	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VM971005CNA*	28,400	\$3,976
215434407	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VM970804CNA*	28,400	\$3,976
215434406	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VT961005CNA*	28,400	\$3,976
215434405	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VT960804CNA*	28,400	\$3,976
215434404	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VS960805CUA*	28,400	\$3,976
215434403	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VT801005C*A*	28,400	\$3,976
215434402	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VT800805C*A*	28,400	\$3,976
215434401	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VT800804C*A*	28,400	\$3,976
215434400	AMANA	AZV7SA4810A*	CHPEA4830*3A*	A*VS800805CUA*	28,400	\$3,976
215433954	AMANA	AZV7SA4810A*	CA*EA6030*3A*+MBVK20DP 1X00A*		29,000	\$4,060
215434399	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VM971205DNA*	29,000	\$4,060
215434398	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VT961205DNA*	29,000	\$4,060
215434397	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VT961005DNA*	29,000	\$4,060
215434396	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VT800805D*A*	29,000	\$4,060
215433953	AMANA	AZV7SA4810A*	CA*EA6030*3A*+MBVK16CP 1X00A*		29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434395	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VM971005CNA*	29,000	\$4,060
215434394	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VM970804CNA*	29,000	\$4,060
215434393	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VT961005CNA*	29,000	\$4,060
215434392	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VT960804CNA*	29,000	\$4,060
215434391	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VS960805CUA*	29,000	\$4,060
215434390	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VT801005C*A*	29,000	\$4,060
215434389	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VT800805C*A*	29,000	\$4,060
215434388	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VT800804C*A*	29,000	\$4,060
215434387	AMANA	AZV7SA4810A*	CA*EA6030*3A*	A*VS800805CUA*	29,000	\$4,060
215429750	AMANA	AZV7SA4810A*	AHVE60DP0300A*		29,000	\$4,060
215429189	AMANA	AZV7SA4810A*	AHVE60DP1300A*		29,000	\$4,060
215433940	AMANA	AZV7SA4210A*	CHPEA6030*3A*+MBVK20D P1X00A*		28,000	\$3,920
215433939	AMANA	AZV7SA4210A*	CHPEA6030*3A*+MBVK16C P1X00A*		28,000	\$3,920
215434308	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VT961205DNA*	28,000	\$3,920
215434307	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VT961005DNA*	28,000	\$3,920
215434306	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VT961005CNA*	28,000	\$3,920
215434305	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VT960804CNA*	28,000	\$3,920
215434304	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VT801005C*A*	28,000	\$3,920
215434303	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VT800805D*A*	28,000	\$3,920
215434302	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VT800805C*A*	28,000	\$3,920
215434301	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VT800804C*A*	28,000	\$3,920
215434300	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VS960805CUA*	28,000	\$3,920
215434299	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VS800805CUA*	28,000	\$3,920
215434298	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VM971205DNA*	28,000	\$3,920
215434297	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VM971005CNA*	28,000	\$3,920
215434296	AMANA	AZV7SA4210A*	CHPEA6030*3A*	A*VM970804CNA*	28,000	\$3,920
215433938	AMANA	AZV7SA4210A*	CHPEA4830*3A*+MBVK20D P1X00A*		28,000	\$3,920
215433937	AMANA	AZV7SA4210A*	CHPEA4830*3A*+MBVK16C P1X00A*		28,000	\$3,920
215434295	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VT961205DNA*	28,000	\$3,920
215434294	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VT961005DNA*	28,000	\$3,920
215434293	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VT961005CNA*	28,000	\$3,920
215434292	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VT960804CNA*	28,000	\$3,920
215434291	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VT801005C*A*	28,000	\$3,920
215434290	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VT800805D*A*	28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434289	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VT800805C*A*	28,000	\$3,920
215434288	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VT800804C*A*	28,000	\$3,920
215434287	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VS960805CUA*	28,000	\$3,920
215434286	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VS800805CUA*	28,000	\$3,920
215434285	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VM971205DNA*	28,000	\$3,920
215434284	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VM971005CNA*	28,000	\$3,920
215434283	AMANA	AZV7SA4210A*	CHPEA4830*3A*	A*VM970804CNA*	28,000	\$3,920
215433936	AMANA	AZV7SA4210A*	CA*EA6030*3A*+MBVK20DP1X00A*		28,000	\$3,920
215433935	AMANA	AZV7SA4210A*	CA*EA6030*3A*+MBVK16CP1X00A*		28,000	\$3,920
215434282	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VT961205DNA*	28,000	\$3,920
215434281	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VT961005DNA*	28,000	\$3,920
215434280	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VT961005CNA*	28,000	\$3,920
215434279	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VT960804CNA*	28,000	\$3,920
215434278	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VT801005C*A*	28,000	\$3,920
215434277	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VT800805D*A*	28,000	\$3,920
215434276	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VT800805C*A*	28,000	\$3,920
215434275	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VT800804C*A*	28,000	\$3,920
215434274	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VS960805CUA*	28,000	\$3,920
215434273	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VS800805CUA*	28,000	\$3,920
215434272	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VM971205DNA*	28,000	\$3,920
215434271	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VM971005CNA*	28,000	\$3,920
215434270	AMANA	AZV7SA4210A*	CA*EA6030*3A*	A*VM970804CNA*	28,000	\$3,920
215429749	AMANA	AZV7SA4210A*	AHVE60DP0300A*		28,000	\$3,920
215429188	AMANA	AZV7SA4210A*	AHVE60DP1300A*		28,000	\$3,920
215434198	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VM970804CNA*	22,000	\$3,080
215434197	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VM971005CNA*	22,000	\$3,080
215434196	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VM971205DNA*	22,000	\$3,080
215434195	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VS800805CUA*	22,000	\$3,080
215434194	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VS960805CUA*	22,000	\$3,080
215434193	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VT800804C*A*	22,000	\$3,080
215434192	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VT800805C*A*	22,000	\$3,080
215434191	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VT800805D*A*	22,000	\$3,080
215434190	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VT801005C*A*	22,000	\$3,080
215434189	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VT960804CNA*	22,000	\$3,080
215434188	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VT961005CNA*	22,000	\$3,080
215434187	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VT961005DNA*	22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434186	AMANA	AZV7SA3610A*	CHPEA4830*3A*	A*VT961205DNA*	22,000	\$3,080
215433922	AMANA	AZV7SA3610A*	CHPEA4830*3A*+MBVK16CP1X00A*		22,000	\$3,080
215433921	AMANA	AZV7SA3610A*	CHPEA4830*3A*+MBVK20DP1X00A*		22,000	\$3,080
215434185	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VS800805CUA*	22,000	\$3,080
215434184	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VS960805CUA*	22,000	\$3,080
215434183	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VT800804C*A*	22,000	\$3,080
215434182	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VT800805C*A*	22,000	\$3,080
215434181	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VT800805D*A*	22,000	\$3,080
215434180	AMANA	AZV7SA3610A*	CA*EA6030*3A*	A*VT801005C*A*	22,000	\$3,080
215433920	AMANA	AZV7SA3610A*	CA*EA6030*3A*+MBVK16CP1X00A*		22,000	\$3,080
215433919	AMANA	AZV7SA3610A*	CA*EA6030*3A*+MBVK20DP1X00A*		22,000	\$3,080
215434179	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VM970804CNA*	22,000	\$3,080
215434178	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VM971005CNA*	22,000	\$3,080
215434177	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VM971205DNA*	22,000	\$3,080
215434176	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VS800805CUA*	22,000	\$3,080
215434175	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VS960805CUA*	22,000	\$3,080
215434174	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VT800804C*A*	22,000	\$3,080
215434173	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VT800805C*A*	22,000	\$3,080
215434172	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VT800805D*A*	22,000	\$3,080
215434171	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VT801005C*A*	22,000	\$3,080
215434170	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VT960804CNA*	22,000	\$3,080
215434169	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VT961005CNA*	22,000	\$3,080
215434168	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VT961005DNA*	22,000	\$3,080
215434167	AMANA	AZV7SA3610A*	CA*EA4830*3A*	A*VT961205DNA*	22,000	\$3,080
215433918	AMANA	AZV7SA3610A*	CA*EA4830*3A*+MBVK16CP1X00A*		22,000	\$3,080
215433917	AMANA	AZV7SA3610A*	CA*EA4830*3A*+MBVK20DP1X00A*		22,000	\$3,080
215429741	AMANA	AZV7SA3610A*	AHVE60DP0300A*		22,000	\$3,080
215429740	AMANA	AZV7SA3610A*	AHVE60DP1300A*		22,000	\$3,080
215429739	AMANA	AZV7SA3610A*	AHVE48CP0300A*		22,000	\$3,080
215429738	AMANA	AZV7SA3610A*	AHVE48CP1300A*		22,000	\$3,080
215429737	AMANA	AZV7SA3610A*	AHVE42CP0300A*		22,000	\$3,080
215429736	AMANA	AZV7SA3610A*	AHVE42CP1300A*		22,000	\$3,080
215429735	AMANA	AZV7SA3610A*	AHVE48DP0300A*		22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215429187	AMANA	AZV7SA3610A*	AHVE48DP1300A*		22,000	\$3,080
215433904	AMANA	AZV7SA2410A*	CHPEA3026*3A*+MBVK16C P1X00A*		15,800	\$2,212
215433903	AMANA	AZV7SA2410A*	CHPEA3026*3A*+MBVK12B P1X00A*		15,800	\$2,212
215434078	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT961005CNA*	15,800	\$2,212
215434077	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT960804CNA*	15,800	\$2,212
215434076	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT960803BNA*	15,800	\$2,212
215434075	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT960603BNA*	15,800	\$2,212
215434074	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT960403BNA*	15,800	\$2,212
215434073	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT801005C*A*	15,800	\$2,212
215434072	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT800805C*A*	15,800	\$2,212
215434071	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT800804C*A*	15,800	\$2,212
215434070	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT800803B*A*	15,800	\$2,212
215434069	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT800604B*A*	15,800	\$2,212
215434068	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VT800603B*A*	15,800	\$2,212
215434067	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VS960805CUA*	15,800	\$2,212
215434066	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VS960603BUA*	15,800	\$2,212
215434065	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VS800805CUA*	15,800	\$2,212
215434064	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VS800604BUA*	15,800	\$2,212
215434063	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VM971005CNA*	15,800	\$2,212
215434062	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VM970804CNA*	15,800	\$2,212
215434061	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VM970803BNA*	15,800	\$2,212
215434060	AMANA	AZV7SA2410A*	CHPEA3026*3A*	A*VM970603BNA*	15,800	\$2,212
215433902	AMANA	AZV7SA2410A*	CA*EA3626*3A*+MBVK16CP 1X00A*		15,800	\$2,212
215433901	AMANA	AZV7SA2410A*	CA*EA3626*3A*+MBVK12BP 1X00A*		15,800	\$2,212
215434059	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT961005CNA*	15,800	\$2,212
215434058	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT960804CNA*	15,800	\$2,212
215434057	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT960803BNA*	15,800	\$2,212
215434056	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT960603BNA*	15,800	\$2,212
215434055	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT960403BNA*	15,800	\$2,212
215434054	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT801005C*A*	15,800	\$2,212
215434053	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT800805C*A*	15,800	\$2,212
215434052	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT800804C*A*	15,800	\$2,212
215434051	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT800803B*A*	15,800	\$2,212
215434050	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT800604B*A*	15,800	\$2,212

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434049	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VT800603B*A*	15,800	\$2,212
215434048	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VS960805CUA*	15,800	\$2,212
215434047	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VS960603BUA*	15,800	\$2,212
215434046	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VS800805CUA*	15,800	\$2,212
215434045	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VS800604BUA*	15,800	\$2,212
215434044	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VM971005CNA*	15,800	\$2,212
215434043	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VM970804CNA*	15,800	\$2,212
215434042	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VM970803BNA*	15,800	\$2,212
215434041	AMANA	AZV7SA2410A*	CA*EA3626*3A*	A*VM970603BNA*	15,800	\$2,212
215433900	AMANA	AZV7SA2410A*	CA*EA3022*3A*+MBVK16CP1X00A*		15,800	\$2,212
215433899	AMANA	AZV7SA2410A*	CA*EA3022*3A*+MBVK12BP1X00A*		15,800	\$2,212
215434040	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT961005CNA*	15,800	\$2,212
215434039	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT960804CNA*	15,800	\$2,212
215434038	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT960603BNA*	15,800	\$2,212
215434037	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT960603BNA*	15,800	\$2,212
215434036	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT960403BNA*	15,800	\$2,212
215434035	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT801005C*A*	15,800	\$2,212
215434034	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT800805C*A*	15,800	\$2,212
215434033	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT800804C*A*	15,800	\$2,212
215434032	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT800803B*A*	15,800	\$2,212
215434031	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VT800603B*A*	15,800	\$2,212
215434030	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VS960805CUA*	15,800	\$2,212
215434029	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VS960603BUA*	15,800	\$2,212
215434028	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VS800805CUA*	15,800	\$2,212
215434027	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VS800604BUA*	15,800	\$2,212
215434026	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VM971005CNA*	15,800	\$2,212
215434025	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VM970804CNA*	15,800	\$2,212
215434024	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VM970803BNA*	15,800	\$2,212
215434023	AMANA	AZV7SA2410A*	CA*EA3022*3A*	A*VM970603BNA*	15,800	\$2,212
215429733	AMANA	AZV7SA2410A*	AHVE36CP0300A*		15,800	\$2,212
215429186	AMANA	AZV7SA2410A*	AHVE36CP1300A*		15,800	\$2,212
213156957	AMANA	ASZS60481EA*	CA*EA6030*4A*	A*VC800805D*A*	28,000	\$3,920
213156956	AMANA	ASZS60421EA*	CA*EA6030*4A*	A*VC800805D*A*	28,000	\$3,920
210692524	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VM971205DNB*	21,400	\$2,996
210692523	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VM971005CNB*	21,400	\$2,996
210692522	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VM970804CNB*	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210609969	AMANA	ASZV903610A*	AMVE48DP1400A*		21,400	\$2,996
213815741	AMANA	ASZS60481EA*	CAPEA6030*4A*+MBVK20D P1X00A*		28,000	\$3,920
213815740	AMANA	ASZS60421EA*	CAPEA6030*4A*+MBVK20D P1X00A*		28,000	\$3,920
213815739	AMANA	ASZS60361EA*	CAPEA4830*4A*+MBVK16C P1X00A*		23,000	\$3,220
213815738	AMANA	ASZS60361EA*	CAPEA6030*4A*+MBVK20D P1X00A*		23,000	\$3,220
213815737	AMANA	ASZS60241EA*	CAPEA3026*4A*+MBVK16C P1X00A*		16,000	\$2,240
213815736	AMANA	ASZS60241EA*	CAPEA3026*4A*+MBVK12B P1X00A*		16,000	\$2,240
213815735	AMANA	ASZS60241EA*	CAPEA2422*4A*+MBVK16C P1X00A*		16,000	\$2,240
213815734	AMANA	ASZS60241EA*	CAPEA2422*4A*+MBVK12B P1X00A*		16,000	\$2,240
213613306	AMANA	ASZS60361EA*	AHVE42CP1400B*		23,000	\$3,220
213613304	AMANA	ASZS60481EA*	AHVE60DP1400B*		28,000	\$3,920
213613303	AMANA	ASZS60421EA*	AHVE60DP1400B*		28,000	\$3,920
213613302	AMANA	ASZS60361EA*	AHVE48DP1400B*		23,000	\$3,220
213613305	AMANA	ASZS60361EA*	AHVE60DP1400B*		23,000	\$3,220
213613301	AMANA	ASZS60241EA*	AHVE36CP1400B*		16,000	\$2,240
213872274	AMANA	ASZS60481EA*	CA*EA6030*4A*	A*VC960804CNB*	28,000	\$3,920
213872272	AMANA	ASZS60481EA*	CA*EA6030*4A*	A*VC961005CNB*	28,000	\$3,920
213872270	AMANA	ASZS60481EA*	CA*EA6030*4A*	A*VM970804CNB*	28,000	\$3,920
213872268	AMANA	ASZS60481EA*	CA*EA6030*4A*	A*VM971005CNB*	28,000	\$3,920
213872266	AMANA	ASZS60421EA*	CA*EA6030*4A*	A*VC960804CNB*	28,000	\$3,920
213872264	AMANA	ASZS60421EA*	CA*EA6030*4A*	A*VC961005CNB*	28,000	\$3,920
213872262	AMANA	ASZS60421EA*	CA*EA6030*4A*	A*VM970804CNB*	28,000	\$3,920
213872260	AMANA	ASZS60421EA*	CA*EA6030*4A*	A*VM971005CNB*	28,000	\$3,920
213255525	AMANA	ASZS601810A*	AHVE24BP0400A*		10,800	\$1,512
212614868	AMANA	ASZS60241EA*	AHVE36CP1400A*		16,000	\$2,240
212614943	AMANA	ASZS60241EA*	AHVE36CP0400A*		16,000	\$2,240
212614944	AMANA	ASZS60241EA*	CA*EA2422*4A*+MBVC1200* *-1A*		16,000	\$2,240
212614945	AMANA	ASZS60241EA*	CA*EA2422*4A*+MBVC1600* *-1A*		16,000	\$2,240
212614946	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC800603B*A*	16,000	\$2,240

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212614947	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC800604B*A*	16,000	\$2,240
212614948	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VS800604BUA*	16,000	\$2,240
212614949	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC800803B*A*	16,000	\$2,240
212614950	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC800804C*A*	16,000	\$2,240
212614951	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC800805C*A*	16,000	\$2,240
212614952	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VS800805CUA*	16,000	\$2,240
212614953	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC801005C*A*	16,000	\$2,240
212614954	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC960403BNB*	16,000	\$2,240
212614955	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC960603BNB*	16,000	\$2,240
212614956	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VS960603BUA*	16,000	\$2,240
212614957	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC960803BNB*	16,000	\$2,240
212614958	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC960804CNB*	16,000	\$2,240
212614959	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VS960805CUA*	16,000	\$2,240
212614960	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VC961005CNB*	16,000	\$2,240
212614961	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VM970603BNB*	16,000	\$2,240
212614962	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VM970803BNB*	16,000	\$2,240
212614963	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VM970804CNB*	16,000	\$2,240
212614964	AMANA	ASZS60241EA*	CA*EA2422*4A*	A*VM971005CNB*	16,000	\$2,240
212614965	AMANA	ASZS60241EA*	CA*EA3026*4A*+MBVC1200* *-1A*		16,000	\$2,240
212614966	AMANA	ASZS60241EA*	CA*EA3026*4A*+MBVC1600* *-1A*		16,000	\$2,240
212614967	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC800603B*A*	16,000	\$2,240
212614968	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC800604B*A*	16,000	\$2,240
212614969	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VS800604BUA*	16,000	\$2,240
212614970	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC800803B*A*	16,000	\$2,240
212614971	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC800804C*A*	16,000	\$2,240
212614972	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC800805C*A*	16,000	\$2,240
212614973	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VS800805CUA*	16,000	\$2,240
212614974	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC801005C*A*	16,000	\$2,240
212614975	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC960403BNB*	16,000	\$2,240
212614976	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC960603BNB*	16,000	\$2,240
212614977	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VS960603BUA*	16,000	\$2,240
212614978	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC960803BNB*	16,000	\$2,240
212614979	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC960804CNB*	16,000	\$2,240
212614980	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VS960805CUA*	16,000	\$2,240
212614981	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VC961005CNB*	16,000	\$2,240
212614982	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VM970603BNB*	16,000	\$2,240

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212614983	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VM970803BNB*	16,000	\$2,240
212614984	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VM970804CNB*	16,000	\$2,240
212614985	AMANA	ASZS60241EA*	CA*EA3026*4A*	A*VM971005CNB*	16,000	\$2,240
212615010	AMANA	ASZS60481EA*	CA*EA6030*4A*	A*VC961205DNB*	28,000	\$3,920
212615009	AMANA	ASZS60481EA*	CA*EA6030*4A*	A*VM971205DNB*	28,000	\$3,920
212615008	AMANA	ASZS60481EA*	CA*EA6030*4A*+MBVC2000*-1A*		28,000	\$3,920
212615007	AMANA	ASZS60481EA*	AHVE60DP0400A*		28,000	\$3,920
212614871	AMANA	ASZS60481EA*	AHVE60DP1400A*		28,000	\$3,920
212615006	AMANA	ASZS60421EA*	CA*EA6030*4A*	A*VC961205DNB*	28,000	\$3,920
212615005	AMANA	ASZS60421EA*	CA*EA6030*4A*	A*VM971205DNB*	28,000	\$3,920
212615004	AMANA	ASZS60421EA*	CA*EA6030*4A*+MBVC2000*-1A*		28,000	\$3,920
212615003	AMANA	ASZS60421EA*	AHVE60DP0400A*		28,000	\$3,920
212614870	AMANA	ASZS60421EA*	AHVE60DP1400A*		28,000	\$3,920
212928696	AMANA	ASZS60361EA*	AHVE42CP1400A*		23,000	\$3,220
212928697	AMANA	ASZS60361EA*	AHVE42CP0400A*		23,000	\$3,220
212615002	AMANA	ASZS60361EA*	CA*EA4830*4A*	A*VS960805CUA*	23,000	\$3,220
212615001	AMANA	ASZS60361EA*	CA*EA4830*4A*	A*VS800805CUA*	23,000	\$3,220
212614993	AMANA	ASZS60361EA*	CA*EA4830*4A*	A*VM970804CNB*	23,000	\$3,220
212615000	AMANA	ASZS60361EA*	CA*EA4830*4A*	A*VC800804C*A*	23,000	\$3,220
212614999	AMANA	ASZS60361EA*	CA*EA4830*4A*	A*VC800805C*A*	23,000	\$3,220
212614998	AMANA	ASZS60361EA*	CA*EA6030*4A*	A*VC800805D*A*	23,000	\$3,220
212614997	AMANA	ASZS60361EA*	CA*EA4830*4A*	A*VC801005C*A*	23,000	\$3,220
212614996	AMANA	ASZS60361EA*	CA*EA4830*4A*	A*VC960804CNB*	23,000	\$3,220
212614995	AMANA	ASZS60361EA*	CA*EA4830*4A*	A*VC961005CNB*	23,000	\$3,220
212614994	AMANA	ASZS60361EA*	CA*EA6030*4A*	A*VC961205DNB*	23,000	\$3,220
212614992	AMANA	ASZS60361EA*	CA*EA4830*4A*	A*VM971005CNB*	23,000	\$3,220
212614991	AMANA	ASZS60361EA*	CA*EA6030*4A*	A*VM971205DNB*	23,000	\$3,220
212614990	AMANA	ASZS60361EA*	CA*EA4830*4A*+MBVC1600*-1A*		23,000	\$3,220
212614989	AMANA	ASZS60361EA*	CA*EA6030*4A*+MBVC2000*-1A*		23,000	\$3,220
212614988	AMANA	ASZS60361EA*	AHVE48DP0400A*		23,000	\$3,220
212614987	AMANA	ASZS60361EA*	AHVE60DP0400A*		23,000	\$3,220
212614986	AMANA	ASZS60361EA*	AHVE60DP1400A*		23,000	\$3,220
212614869	AMANA	ASZS60361EA*	AHVE48DP1400A*		23,000	\$3,220
210609968	AMANA	ASZV903610A*	AMVE36CP1400A*		21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210692496	AMANA	ASZV903610A*	CA*F3137*6A*+MBVC1201** 1A*+TXV		21,600	\$3,024
210692499	AMANA	ASZV903610A*	CA*F3137*6A*+TXV	A*VC960403BNB*	21,600	\$3,024
210692500	AMANA	ASZV903610A*	CA*F3137*6A*+TXV	A*VS960603BUA*	21,600	\$3,024
210692501	AMANA	ASZV903610A*	CA*F3137*6A*+TXV	A*VC960603BNB*	21,600	\$3,024
210692502	AMANA	ASZV903610A*	CA*F3137*6A*+TXV	A*VC960803BNB*	21,600	\$3,024
210692503	AMANA	ASZV903610A*	CA*F3137*6A*+TXV	A*VM970603BNB*	21,600	\$3,024
210692504	AMANA	ASZV903610A*	CA*F3137*6A*+TXV	A*VM970803BNB*	21,600	\$3,024
210692505	AMANA	ASZV903610A*	CA*F3743*6D*+MBVC1201** 1A*+TXV		21,600	\$3,024
210607578	AMANA	ASZV903610A*	CA*F3743*6D*+MBVC1601** 1A*+TX		21,600	\$3,024
210692512	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VC960403BNB*	21,600	\$3,024
210692513	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VS960603BUA*	21,600	\$3,024
210692514	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VC960603BNB*	21,600	\$3,024
210692515	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VC960803BNB*	21,600	\$3,024
210692516	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VC960804CNB*	21,600	\$3,024
210692517	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VS960805CUA*	21,600	\$3,024
210692518	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VC961005CNB*	21,600	\$3,024
210692519	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VC961205DNB*	21,600	\$3,024
210692520	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VM970603BNB*	21,600	\$3,024
210692521	AMANA	ASZV903610A*	CA*F3743*6D*+TXV	A*VM970803BNB*	21,600	\$3,024
210692525	AMANA	ASZV903610A*	CHPF3642C6C*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210692526	AMANA	ASZV903610A*	CHPF3642C6C*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210692533	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VC960403BNB*	21,600	\$3,024
210692534	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VS960603BUA*	21,600	\$3,024
210692535	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VC960603BNB*	21,600	\$3,024
210692536	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VC960803BNB*	21,600	\$3,024
210692537	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VC960804CNB*	21,600	\$3,024
210692538	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VS960805CUA*	21,600	\$3,024
210692539	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VC961005CNB*	21,600	\$3,024
210692540	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VM970603BNB*	21,600	\$3,024
210692541	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VM970803BNB*	21,600	\$3,024
210692542	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VM970804CNB*	21,600	\$3,024
210692543	AMANA	ASZV903610A*	CHPF3642C6C*+TXV	A*VM971005CNB*	21,600	\$3,024
210692544	AMANA	ASZV903610A*	CHPF3743C6B*+MBVC1201* *-1A*+TXV		21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210692545	AMANA	ASZV903610A*	CHPF3743C6B*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210692552	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VC960403BNB*	21,600	\$3,024
210692553	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VS960603BUA*	21,600	\$3,024
210692554	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VC960603BNB*	21,600	\$3,024
210692555	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VC960803BNB*	21,600	\$3,024
210692556	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VC960804CNB*	21,600	\$3,024
210692557	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VS960805CUA*	21,600	\$3,024
210692558	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VC961005CNB*	21,600	\$3,024
210692559	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VM970603BNB*	21,600	\$3,024
210692560	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VM970803BNB*	21,600	\$3,024
210692561	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VM970804CNB*	21,600	\$3,024
210692562	AMANA	ASZV903610A*	CHPF3743C6B*+TXV	A*VM971005CNB*	21,600	\$3,024
210692563	AMANA	ASZV903610A*	CSCF3642N6D*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210692564	AMANA	ASZV903610A*	CSCF3642N6D*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210692571	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VC960403BNB*	21,600	\$3,024
210692572	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VS960603BUA*	21,600	\$3,024
210692573	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VC960603BNB*	21,600	\$3,024
210692574	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VC960803BNB*	21,600	\$3,024
210692575	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VC960804CNB*	21,600	\$3,024
210692576	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VS960805CUA*	21,600	\$3,024
210692577	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VC961005CNB*	21,600	\$3,024
210692578	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VC961205DNB*	21,600	\$3,024
210692579	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VM970603BNB*	21,600	\$3,024
210692580	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VM970803BNB*	21,600	\$3,024
210692581	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VM970804CNB*	21,600	\$3,024
210692582	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VM971005CNB*	21,600	\$3,024
210692583	AMANA	ASZV903610A*	CSCF3642N6D*+TXV	A*VM971205DNB*	21,600	\$3,024
210773171	AMANA	ASZS601810A*	AHVE24BP1400A*		10,800	\$1,512
210798394	AMANA	ASZS601810A*	CA*EA1818*4A*	A*VC960403BNB*	10,800	\$1,512
210798395	AMANA	ASZS601810A*	CA*EA1818*4A*	A*VC960603BNB*	10,800	\$1,512
210798396	AMANA	ASZS601810A*	CA*EA1818*4A*	A*VC960803BNB*	10,800	\$1,512
210798404	AMANA	ASZS601810A*	CA*EA1818*4A*	A*VC960804CNB*	10,800	\$1,512
210798397	AMANA	ASZS601810A*	CA*EA1818*4A*	A*VM970603BNB*	10,800	\$1,512
210798398	AMANA	ASZS601810A*	CA*EA1818*4A*	A*VM970803BNB*	10,800	\$1,512
210798405	AMANA	ASZS601810A*	CA*EA1818*4A*	A*VM970804CNB*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210798393	AMANA	ASZS601810A*	CA*EA1818*4A*	A*VS960603BUA*	10,800	\$1,512
210798403	AMANA	ASZS601810A*	CA*EA1818*4A*	A*VS960805CUA*	10,800	\$1,512
210854807	AMANA	ASZS601810A*	CA*EA1818*4A*+MBVC1200* *-1A*		10,800	\$1,512
210854808	AMANA	ASZS601810A*	CA*EA1818*4A*+MBVC1600* *-1A*		10,800	\$1,512
210798412	AMANA	ASZS601810A*	CA*EA2422*4A*	A*VC960403BNB*	10,800	\$1,512
210798413	AMANA	ASZS601810A*	CA*EA2422*4A*	A*VC960603BNB*	10,800	\$1,512
210798414	AMANA	ASZS601810A*	CA*EA2422*4A*	A*VC960803BNB*	10,800	\$1,512
210798422	AMANA	ASZS601810A*	CA*EA2422*4A*	A*VC960804CNB*	10,800	\$1,512
210798415	AMANA	ASZS601810A*	CA*EA2422*4A*	A*VM970603BNB*	10,800	\$1,512
210798416	AMANA	ASZS601810A*	CA*EA2422*4A*	A*VM970803BNB*	10,800	\$1,512
210798423	AMANA	ASZS601810A*	CA*EA2422*4A*	A*VM970804CNB*	10,800	\$1,512
210798411	AMANA	ASZS601810A*	CA*EA2422*4A*	A*VS960603BUA*	10,800	\$1,512
210798421	AMANA	ASZS601810A*	CA*EA2422*4A*	A*VS960805CUA*	10,800	\$1,512
210854809	AMANA	ASZS601810A*	CA*EA2422*4A*+MBVC1200* *-1A*		10,800	\$1,512
210854810	AMANA	ASZS601810A*	CA*EA2422*4A*+MBVC1600* *-1A*		10,800	\$1,512
213815250	AMANA	ASZS601810A*	CA*EA2422*4A*+MBVK16CP 1X00A*		10,800	\$1,512
213815249	AMANA	ASZS601810A*	CA*EA2422*4A*+MBVK12BP 1X00A*		10,800	\$1,512
213815248	AMANA	ASZS601810A*	CA*EA1818*4A*+MBVK16CP 1X00A*		10,800	\$1,512
213815247	AMANA	ASZS601810A*	CA*EA1818*4A*+MBVK12BP 1X00A*		10,800	\$1,512
213613279	AMANA	ASZS601810A*	AHVE24BP1400B*		10,800	\$1,512
215865074	AMERICAN STANDARD	5A6V8X60A1	5TXCC007AS3	P0V0C000M50SD+LRP	50,000	\$7,000
215864986	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	S9V2C100U5PSC+LRP	42,000	\$5,880
215864980	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	S9V2C100U4VSB+LRP	42,000	\$5,880
215864982	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	S9V2C080U5PSC+LRP	42,500	\$5,950
215864984	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	S8V2D120M5PDB	42,500	\$5,950
215864996	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	S8V2D120M5PCB	42,500	\$5,950
215864988	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	S8V2C100M5PDB	42,500	\$5,950
215864990	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	S8V2C100M5PCB	42,500	\$5,950
215864992	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	S8V2C080M5PDB	42,000	\$5,880
215864994	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	S8V2C080M5PCB	42,000	\$5,880
215865114	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	P0V0D000M50SD+LRP	41,500	\$5,810

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215865112	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864978	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	L8V1C100U5VSB+LRP	42,000	\$5,880
215864976	AMERICAN STANDARD	5A6V8X48A1	5TXCD010AS3	*UHMD120CCV5+LRP	42,000	\$5,880
215864958	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	S9V2C100U5PSC+LRP	42,500	\$5,950
215864960	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	S9V2C100U4VSB+LRP	42,500	\$5,950
215864962	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	S9V2C080U5PSC+LRP	43,000	\$6,020
215864964	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	S8V2D120M5PDB	42,500	\$5,950
215864966	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	S8V2D120M5PCB	42,500	\$5,950
215864968	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	S8V2C100M5PDB	42,500	\$5,950
215864970	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	S8V2C100M5PCB	42,500	\$5,950
215864972	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	S8V2C080M5PDB	42,500	\$5,950
215864974	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	S8V2C080M5PCB	42,500	\$5,950
215865110	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	P0V0D000M50SD+LRP	42,500	\$5,950
215865108	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	P0V0C000M50SD+LRP	42,500	\$5,950
215864954	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	L8V1C100U5VSB+LRP	42,500	\$5,950
215864956	AMERICAN STANDARD	5A6V8X48A1	5TXCD008AS3	*UHMD120CCV5+LRP	42,500	\$5,950
215864946	AMERICAN STANDARD	5A6V8X48A1	5TXCC009AS3	S9V2C100U5PSC+LRP	42,500	\$5,950
215864940	AMERICAN STANDARD	5A6V8X48A1	5TXCC009AS3	S9V2C100U4VSB+LRP	42,500	\$5,950
215864942	AMERICAN STANDARD	5A6V8X48A1	5TXCC009AS3	S8V2C100M5PDB	42,500	\$5,950
215864944	AMERICAN STANDARD	5A6V8X48A1	5TXCC009AS3	S8V2C100M5PCB	42,500	\$5,950
215864952	AMERICAN STANDARD	5A6V8X48A1	5TXCC009AS3	S8V2C080M5PCB	42,000	\$5,880
215865106	AMERICAN STANDARD	5A6V8X48A1	5TXCC009AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864948	AMERICAN STANDARD	5A6V8X48A1	5TXCC009AS3	L8V1C100U5VSB+LRP	42,000	\$5,880
215864950	AMERICAN STANDARD	5A6V8X48A1	5TXCC009AS3	*UHMC100CCV4+LRP	42,000	\$5,880
215869123	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	S9V2C100U5VSB+LRP	43,000	\$6,020
215864924	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	S9V2C100U5PSC+LRP	43,000	\$6,020
215864926	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	S9V2C100U4VSB+LRP	43,000	\$6,020
215864928	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	S9V2C080U5PSC+LRP	43,000	\$6,020
215864930	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	S8V2C100M5PDB	43,000	\$6,020
215864932	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	S8V2C100M5PCB	43,000	\$6,020
215864934	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	S8V2C080M5PDB	42,500	\$5,950
215864936	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	S8V2C080M5PCB	42,500	\$5,950
215865104	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	P0V0C000M50SD+LRP	42,500	\$5,950
215864922	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	L8V1C100U5VSB+LRP	42,500	\$5,950
215864938	AMERICAN STANDARD	5A6V8X48A1	5TXCC007AS3	*UHMC100CCV4+LRP	42,500	\$5,950
215865070	AMERICAN STANDARD	5A6V8X48A1	5TXCC005AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864666	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	S9V2B080U4VSB+LRP	43,000	\$6,020
215864668	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	S9V2B080U4PSC+LRP	43,000	\$6,020

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215869121	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	S9V2B060U4VSB+LRP	43,000	\$6,020
215864670	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	S9V2B060U4PSC+LRP	43,000	\$6,020
215864672	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	S8V2B080M4PDB	43,000	\$6,020
215864674	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	S8V2B080M4PCB	43,000	\$6,020
215864676	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	S8V2B060M4PDB	43,000	\$6,020
215864678	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	S8V2B060M4PCB	43,000	\$6,020
215865068	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	P0V0B000M40SD+LRP	42,500	\$5,950
215864664	AMERICAN STANDARD	5A6V8X48A1	5TXCB006AS3	L8V1B080U4VSB+LRP	43,000	\$6,020
215865044	AMERICAN STANDARD	5A6V8X48A1	5TEMCD07AV51+TD	N/A	42,000	\$5,880
215865042	AMERICAN STANDARD	5A6V8X48A1	5TEMCD05AV41+TD	N/A	42,000	\$5,880
216057015	AMERICAN STANDARD	5A6V8X48A1	5TAMXD07AV51	N/A	41,500	\$5,810
216057013	AMERICAN STANDARD	5A6V8X48A1	5TAMXD06AV41	N/A	42,500	\$5,950
216057011	AMERICAN STANDARD	5A6V8X48A1	5TAMXD05AV41	N/A	42,500	\$5,950
215864910	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	S9V2C100D5PSC+LRP	42,000	\$5,880
215864906	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	S9V2C100D4VSB+LRP	42,000	\$5,880
215864908	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	S8V2D120M5PDB	42,500	\$5,950
215864920	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	S8V2D120M5PCB	42,500	\$5,950
215864912	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	S8V2C100M5PDB	42,000	\$5,880
215864914	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	S8V2C100M5PCB	42,000	\$5,880
215864916	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	S8V2C080M5PDB	42,000	\$5,880
215864918	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	S8V2C080M5PCB	42,000	\$5,880
215865102	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	P0V0D000M50SD+LRP	41,500	\$5,810
215865100	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864904	AMERICAN STANDARD	5A6V8X48A1	5PX*DD10AS3	*DHMC100CCV4+LRP	42,000	\$5,880
215864890	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	S9V2C100U5PSC+LRP	42,000	\$5,880
215864892	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	S9V2C100U4VSB+LRP	42,000	\$5,880
215864894	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	S9V2C080U5PSC+LRP	42,000	\$5,880
215864896	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	S8V2D120M5PDB	42,500	\$5,950
215864898	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	S8V2D120M5PCB	42,500	\$5,950
215864900	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	S8V2C100M5PDB	42,000	\$5,880
215864902	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	S8V2C100M5PCB	42,000	\$5,880
215864888	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	S8V2C080M5PDB	42,000	\$5,880
215864882	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	S8V2C080M5PCB	42,000	\$5,880
215865096	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	P0V0D000M50SD+LRP	41,500	\$5,810
215865098	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864884	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	L8V1C100U5VSB+LRP	42,000	\$5,880
215864886	AMERICAN STANDARD	5A6V8X48A1	5PX*D010AS3	*UHMD120CCV5+LRP	42,000	\$5,880
215864868	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	S9V2C100U5PSC+LRP	42,500	\$5,950

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864878	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	S9V2C100U4VSB+LRP	42,500	\$5,950
215864876	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	S9V2C080U5PSC+LRP	43,000	\$6,020
215864874	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	S8V2D120M5PDB	42,500	\$5,950
215864872	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	S8V2D120M5PCB	42,500	\$5,950
215864870	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	S8V2C100M5PDB	42,500	\$5,950
215864880	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	S8V2C100M5PCB	42,500	\$5,950
215864866	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	S8V2C080M5PDB	42,500	\$5,950
215864860	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	S8V2C080M5PCB	42,500	\$5,950
215865092	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	P0V0D000M50SD+LRP	42,500	\$5,950
215865094	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	P0V0C000M50SD+LRP	42,500	\$5,950
215864862	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	L8V1C100U5VSB+LRP	42,500	\$5,950
215864864	AMERICAN STANDARD	5A6V8X48A1	5PX*D008AS3	*UHMD120CCV5+LRP	42,500	\$5,950
215864846	AMERICAN STANDARD	5A6V8X48A1	5PX*CD09AS3	S9V2C100D5PSC+LRP	42,500	\$5,950
215864858	AMERICAN STANDARD	5A6V8X48A1	5PX*CD09AS3	S9V2C100D4VSB+LRP	42,500	\$5,950
215864856	AMERICAN STANDARD	5A6V8X48A1	5PX*CD09AS3	S8V2C100M5PDB	42,500	\$5,950
215864854	AMERICAN STANDARD	5A6V8X48A1	5PX*CD09AS3	S8V2C100M5PCB	42,500	\$5,950
215864852	AMERICAN STANDARD	5A6V8X48A1	5PX*CD09AS3	S8V2C080M5PDB	42,000	\$5,880
215864850	AMERICAN STANDARD	5A6V8X48A1	5PX*CD09AS3	S8V2C080M5PCB	42,000	\$5,880
215865090	AMERICAN STANDARD	5A6V8X48A1	5PX*CD09AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864848	AMERICAN STANDARD	5A6V8X48A1	5PX*CD09AS3	*DHMC100CCV4+LRP	42,000	\$5,880
215864842	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	S9V2C100U5PSC+LRP	42,500	\$5,950
215864828	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	S9V2C100U4VSB+LRP	42,500	\$5,950
215864830	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	S9V2C080U5PSC+LRP	42,500	\$5,950
215864832	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	S8V2C100M5PDB	42,500	\$5,950
215864834	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	S8V2C100M5PCB	42,500	\$5,950
215864836	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	S8V2C080M5PDB	42,000	\$5,880
215864838	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	S8V2C080M5PCB	42,000	\$5,880
215865088	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864840	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	L8V1C100U5VSB+LRP	42,000	\$5,880
215864844	AMERICAN STANDARD	5A6V8X48A1	5PX*C009AS3	*UHMC100CCV4+LRP	42,000	\$5,880
215869119	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	S9V2C100U5VSB+LRP	43,000	\$6,020
215864650	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	S9V2C100U5PSC+LRP	43,000	\$6,020
215864652	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	S9V2C100U4VSB+LRP	43,000	\$6,020
215869117	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	S9V2C080U5VSB+LRP	43,000	\$6,020
215864654	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	S9V2C080U5PSC+LRP	43,000	\$6,020
215864656	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	S8V2C100M5PDB	43,000	\$6,020
215864658	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	S8V2C100M5PCB	43,000	\$6,020
215864660	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	S8V2C080M5PDB	42,500	\$5,950

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864662	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	S8V2C080M5PCB	43,000	\$6,020
215865066	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	P0V0C000M50SD+LRP	42,500	\$5,950
215864648	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	L8V1C100U5VSB+LRP	42,500	\$5,950
215864646	AMERICAN STANDARD	5A6V8X48A1	5PX*C007AS3	*UHMC100CCV4+LRP	42,500	\$5,950
215864812	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	S9V2B080U4VSB+LRP	43,000	\$6,020
215864814	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	S9V2B080U4PSC+LRP	43,000	\$6,020
215869115	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	S9V2B060U4VSB+LRP	43,000	\$6,020
215864816	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	S9V2B060U4PSC+LRP	43,000	\$6,020
215864818	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	S8V2B080M4PDB	43,000	\$6,020
215864826	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	S8V2B080M4PCB	43,000	\$6,020
215864822	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	S8V2B060M4PDB	43,000	\$6,020
215864824	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	S8V2B060M4PCB	43,000	\$6,020
215865086	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	P0V0B000M40SD+LRP	42,500	\$5,950
215864820	AMERICAN STANDARD	5A6V8X48A1	5PX*B006AS3	L8V1B080U4VSB+LRP	43,000	\$6,020
216571325	AMERICAN STANDARD	5A6V8X36A1	5TXCD010AS3	S8V2D120M5PDB	31,000	\$4,340
216571323	AMERICAN STANDARD	5A6V8X36A1	5TXCD010AS3	S8V2D120M5PCB	31,000	\$4,340
216571319	AMERICAN STANDARD	5A6V8X36A1	5TXCD008AS3	S8V2D120M5PDB	31,200	\$4,368
216571321	AMERICAN STANDARD	5A6V8X36A1	5TXCD008AS3	S8V2D120M5PCB	31,200	\$4,368
216571309	AMERICAN STANDARD	5A6V8X36A1	5TXCC009AS3	S8V2C100M5PDB	31,000	\$4,340
216571311	AMERICAN STANDARD	5A6V8X36A1	5TXCC009AS3	S8V2C100M5PCB	31,000	\$4,340
216571313	AMERICAN STANDARD	5A6V8X36A1	5TXCC009AS3	S8V2C080M5PDB	30,800	\$4,312
216571315	AMERICAN STANDARD	5A6V8X36A1	5TXCC009AS3	S8V2C080M5PCB	30,800	\$4,312
216571317	AMERICAN STANDARD	5A6V8X36A1	5TXCC009AS3	*UHMC100CCV4+LRP	30,800	\$4,312
215869113	AMERICAN STANDARD	5A6V8X36A1	5TXCC007AS3	S9V2C100U5VSB+LRP	31,200	\$4,368
215869111	AMERICAN STANDARD	5A6V8X36A1	5TXCC007AS3	S9V2C080U5VSB+LRP	31,200	\$4,368
216571303	AMERICAN STANDARD	5A6V8X36A1	5TXCC007AS3	S8V2C100M5PDB	31,200	\$4,368
216571299	AMERICAN STANDARD	5A6V8X36A1	5TXCC007AS3	S8V2C100M5PCB	31,200	\$4,368
216571305	AMERICAN STANDARD	5A6V8X36A1	5TXCC007AS3	S8V2C080M5PDB	31,000	\$4,340
216571307	AMERICAN STANDARD	5A6V8X36A1	5TXCC007AS3	S8V2C080M5PCB	31,000	\$4,340
216571301	AMERICAN STANDARD	5A6V8X36A1	5TXCC007AS3	*UHMC100CCV4+LRP	31,000	\$4,340
215869109	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	S9V2C100U5VSB+LRP	31,200	\$4,368
215864638	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	S9V2C100U5PSC+LRP	31,000	\$4,340
215864632	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	S9V2C100U4VSB+LRP	31,200	\$4,368
215869107	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	S9V2C080U5VSB+LRP	31,000	\$4,340
215864630	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	S9V2C080U5PSC+LRP	31,000	\$4,340
215864634	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	S8V2C100M5PDB	31,000	\$4,340
215864636	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	S8V2C100M5PCB	31,400	\$4,396
215864644	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	S8V2C080M5PDB	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864640	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	S8V2C080M5PCB	31,200	\$4,368
215865064	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	P0V0C000M50SD+LRP	31,000	\$4,340
215864642	AMERICAN STANDARD	5A6V8X36A1	5TXCC005AS3	*UHMC100CCV4+LRP	30,800	\$4,312
215864600	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S9V2B080U4VSB+LRP	31,200	\$4,368
215864602	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S9V2B080U4PSC+LRP	31,200	\$4,368
215869105	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S9V2B060U4VSB+LRP	31,400	\$4,396
215864604	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S9V2B060U4PSC+LRP	31,400	\$4,396
215864606	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S9V2B060U3VSB+LRP	31,400	\$4,396
215864608	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S9V2B040U3VSB+LRP	31,400	\$4,396
215864610	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S9V2B040U3PSC+LRP	31,400	\$4,396
215864612	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S8V2B080M4PDB	31,400	\$4,396
215864614	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S8V2B080M4PCB	31,400	\$4,396
215864628	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S8V2B060M4PDB	31,200	\$4,368
215864626	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S8V2B060M4PCB	31,200	\$4,368
215864624	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S8V2A040M3PDB	31,200	\$4,368
215864622	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	S8V2A040M3PCB	31,200	\$4,368
215865062	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	P0V0A000M30SD+LRP	31,200	\$4,368
215864620	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	L8V1B080U4VSB+LRP	31,400	\$4,396
215864618	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	L8V1A060U3VSB+LRP	31,400	\$4,396
215864616	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	L8V1A040U3VSB+LRP	31,400	\$4,396
215864598	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	*UHMB080CCV3+LRP	31,200	\$4,368
215864596	AMERICAN STANDARD	5A6V8X36A1	5TXCB006AS3	*UHMB060CCV3+LRP	31,400	\$4,396
215864592	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S9V2B080U4VSB+LRP	31,000	\$4,340
215864594	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S9V2B080U4PSC+LRP	31,000	\$4,340
215869103	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S9V2B060U4VSB+LRP	30,800	\$4,312
215864590	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S9V2B060U4PSC+LRP	31,200	\$4,368
215864570	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S9V2B060U3VSB+LRP	31,200	\$4,368
215864572	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S9V2B040U3VSB+LRP	30,800	\$4,312
215864574	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S9V2B040U3PSC+LRP	31,000	\$4,340
215864576	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S8V2B080M4PDB	31,200	\$4,368
215864578	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S8V2B080M4PCB	31,200	\$4,368
215864580	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S8V2B060M4PDB	31,000	\$4,340
215864582	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	S8V2B060M4PCB	31,000	\$4,340
215865060	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	P0V0A000M30SD+LRP	31,000	\$4,340
215864584	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	L8V1B080U4VSB+LRP	31,200	\$4,368
216571297	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	L8V1A060U3VSB+LRP	31,200	\$4,368
215864586	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	*UHMB080CCV3+LRP	31,000	\$4,340
215864588	AMERICAN STANDARD	5A6V8X36A1	5TXCB004AS3	*UHMB060CCV3+LRP	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215865040	AMERICAN STANDARD	5A6V8X36A1	5TEMCD05AV41+TD	N/A	31,000	\$4,340
215865038	AMERICAN STANDARD	5A6V8X36A1	5TEMCB03AV31+TD	N/A	32,200	\$4,508
216057009	AMERICAN STANDARD	5A6V8X36A1	5TAMXD07AV51	N/A	30,400	\$4,256
216057007	AMERICAN STANDARD	5A6V8X36A1	5TAMXD06AV41	N/A	31,200	\$4,368
216057005	AMERICAN STANDARD	5A6V8X36A1	5TAMXD05AV41	N/A	31,000	\$4,340
216057003	AMERICAN STANDARD	5A6V8X36A1	5TAMXD04AV31	N/A	31,000	\$4,340
216057001	AMERICAN STANDARD	5A6V8X36A1	5TAMXC03AV31	N/A	31,600	\$4,424
216571293	AMERICAN STANDARD	5A6V8X36A1	5PX*DD10AS3	S8V2D120M5PDB	30,800	\$4,312
216571295	AMERICAN STANDARD	5A6V8X36A1	5PX*DD10AS3	S8V2D120M5PCB	30,800	\$4,312
216571291	AMERICAN STANDARD	5A6V8X36A1	5PX*D010AS3	S8V2D120M5PDB	30,800	\$4,312
216571289	AMERICAN STANDARD	5A6V8X36A1	5PX*D010AS3	S8V2D120M5PCB	30,800	\$4,312
216571287	AMERICAN STANDARD	5A6V8X36A1	5PX*D008AS3	S8V2D120M5PDB	31,200	\$4,368
216571285	AMERICAN STANDARD	5A6V8X36A1	5PX*D008AS3	S8V2D120M5PCB	31,200	\$4,368
216571279	AMERICAN STANDARD	5A6V8X36A1	5PX*CD09AS3	S8V2C100M5PDB	31,000	\$4,340
216571283	AMERICAN STANDARD	5A6V8X36A1	5PX*CD09AS3	S8V2C100M5PCB	31,000	\$4,340
216571277	AMERICAN STANDARD	5A6V8X36A1	5PX*CD09AS3	S8V2C080M5PDB	30,800	\$4,312
216571281	AMERICAN STANDARD	5A6V8X36A1	5PX*CD09AS3	S8V2C080M5PCB	30,800	\$4,312
216571275	AMERICAN STANDARD	5A6V8X36A1	5PX*CD09AS3	*DHMC100CCV4+LRP	30,800	\$4,312
215864806	AMERICAN STANDARD	5A6V8X36A1	5PX*CD07AS3	S8V2C100M5PDB	31,800	\$4,452
215864808	AMERICAN STANDARD	5A6V8X36A1	5PX*CD07AS3	S8V2C100M5PCB	31,800	\$4,452
215864810	AMERICAN STANDARD	5A6V8X36A1	5PX*CD07AS3	S8V2C080M5PDB	31,600	\$4,424
215864804	AMERICAN STANDARD	5A6V8X36A1	5PX*CD07AS3	S8V2C080M5PCB	31,600	\$4,424
215864802	AMERICAN STANDARD	5A6V8X36A1	5PX*CD07AS3	*DHMC100CCV4+LRP	31,600	\$4,424
215869101	AMERICAN STANDARD	5A6V8X36A1	5PX*CD05AS3	S9V2C100D5VSB+LRP	31,600	\$4,424
215864566	AMERICAN STANDARD	5A6V8X36A1	5PX*CD05AS3	S9V2C100D5PSC+LRP	31,600	\$4,424
215864556	AMERICAN STANDARD	5A6V8X36A1	5PX*CD05AS3	S9V2C100D4VSB+LRP	31,600	\$4,424
215864558	AMERICAN STANDARD	5A6V8X36A1	5PX*CD05AS3	S8V2C100M5PDB	31,800	\$4,452
215864560	AMERICAN STANDARD	5A6V8X36A1	5PX*CD05AS3	S8V2C100M5PCB	31,800	\$4,452
215864562	AMERICAN STANDARD	5A6V8X36A1	5PX*CD05AS3	S8V2C080M5PDB	31,600	\$4,424
215864564	AMERICAN STANDARD	5A6V8X36A1	5PX*CD05AS3	S8V2C080M5PCB	31,600	\$4,424
215864568	AMERICAN STANDARD	5A6V8X36A1	5PX*CD05AS3	*DHMC100CCV4+LRP	31,800	\$4,452
216571269	AMERICAN STANDARD	5A6V8X36A1	5PX*C009AS3	S8V2C100M5PDB	31,000	\$4,340
216571267	AMERICAN STANDARD	5A6V8X36A1	5PX*C009AS3	S8V2C100M5PCB	31,000	\$4,340
216571271	AMERICAN STANDARD	5A6V8X36A1	5PX*C009AS3	S8V2C080M5PDB	30,800	\$4,312
216571265	AMERICAN STANDARD	5A6V8X36A1	5PX*C009AS3	S8V2C080M5PCB	30,800	\$4,312
216571273	AMERICAN STANDARD	5A6V8X36A1	5PX*C009AS3	*UHMC100CCV4+LRP	30,800	\$4,312
215869097	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	S9V2C100U5VSB+LRP	31,200	\$4,368
215864554	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	S9V2C100U5PSC+LRP	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864546	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	S9V2C100U4VSB+LRP	31,200	\$4,368
215869099	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	S9V2C080U5VSB+LRP	31,200	\$4,368
215864544	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	S9V2C080U5PSC+LRP	31,200	\$4,368
215864542	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	S8V2C100M5PDB	31,200	\$4,368
215864540	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	S8V2C100M5PCB	31,200	\$4,368
215864552	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	S8V2C080M5PDB	31,000	\$4,340
215864548	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	S8V2C080M5PCB	31,000	\$4,340
215865058	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	P0V0C000M50SD+LRP	31,000	\$4,340
215864550	AMERICAN STANDARD	5A6V8X36A1	5PX*C007AS3	*UHMC100CCV4+LRP	31,000	\$4,340
215869093	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	S9V2C100U5VSB+LRP	31,000	\$4,340
215864538	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	S9V2C100U5PSC+LRP	30,800	\$4,312
215864536	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	S9V2C100U4VSB+LRP	30,800	\$4,312
215869095	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	S9V2C080U5VSB+LRP	31,000	\$4,340
215864534	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	S9V2C080U5PSC+LRP	31,000	\$4,340
215864532	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	S8V2C100M5PDB	31,000	\$4,340
215864530	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	S8V2C100M5PCB	31,000	\$4,340
215864528	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	S8V2C080M5PDB	31,000	\$4,340
215864526	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	S8V2C080M5PCB	31,000	\$4,340
215865056	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	P0V0C000M50SD+LRP	30,800	\$4,312
215864524	AMERICAN STANDARD	5A6V8X36A1	5PX*C005AS3	*UHMC100CCV4+LRP	30,800	\$4,312
215864800	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	S9V2B080D4VSB+LRP	31,800	\$4,452
215864798	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	S9V2B060D3VSB+LRP	31,800	\$4,452
215864796	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	S9V2B040D3PSC+LRP	32,000	\$4,480
215864794	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	S8V2B080M4PDB	32,000	\$4,480
215864792	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	S8V2B080M4PCB	32,000	\$4,480
215864790	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	S8V2B060M4PDB	32,000	\$4,480
215864788	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	S8V2B060M4PCB	32,000	\$4,480
215864786	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	S8V2A040M3PDB	31,800	\$4,452
215864784	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	S8V2A040M3PCB	31,800	\$4,452
215864782	AMERICAN STANDARD	5A6V8X36A1	5PX*BD06AS3	*DHMB080CCV3+LRP	31,800	\$4,452
215864512	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S9V2B080D4VSB+LRP	31,800	\$4,452
215864500	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S9V2B080D4PSC+LRP	31,800	\$4,452
215864502	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S9V2B060D3VSB+LRP	31,800	\$4,452
215864504	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S9V2B060D3PSC+LRP	31,800	\$4,452
215869091	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S9V2B040D3VSB+LRP	32,000	\$4,480
215864506	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S9V2B040D3PSC+LRP	32,000	\$4,480
215864508	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S8V2B080M4PDB	32,000	\$4,480
215864510	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S8V2B080M4PCB	32,000	\$4,480

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864522	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S8V2B060M4PDB	32,000	\$4,480
215864514	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S8V2B060M4PCB	32,000	\$4,480
216571263	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S8V2A040M3PDB	31,800	\$4,452
215864516	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	S8V2A040M3PCB	31,800	\$4,452
215865054	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	P0V0A000M30SD+LRP	31,800	\$4,452
215864518	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	*DHMB080CCV3+LRP	31,800	\$4,452
215864520	AMERICAN STANDARD	5A6V8X36A1	5PX*BD04AS3	*DHMB060CCV3+LRP	32,000	\$4,480
215869089	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	S9V2B060U4VSB+LRP	31,400	\$4,396
216571245	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	S8V2B080M4PDB	31,400	\$4,396
216571247	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	S8V2B080M4PCB	31,400	\$4,396
216571249	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	S8V2B060M4PDB	31,200	\$4,368
216571251	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	S8V2B060M4PCB	31,200	\$4,368
216571253	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	S8V2A040M3PDB	31,200	\$4,368
216571255	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	S8V2A040M3PCB	31,200	\$4,368
216571257	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	L8V1B080U4VSB+LRP	31,400	\$4,396
216571259	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	L8V1A060U3VSB+LRP	31,400	\$4,396
216571261	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	L8V1A040U3VSB+LRP	31,400	\$4,396
216571243	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	*UHMB080CCV3+LRP	31,200	\$4,368
216571241	AMERICAN STANDARD	5A6V8X36A1	5PX*B006AS3	*UHMB060CCV3+LRP	31,400	\$4,396
215864478	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S9V2B080U4VSB+LRP	31,000	\$4,340
215864480	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S9V2B080U4PSC+LRP	31,000	\$4,340
215869087	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S9V2B060U4VSB+LRP	30,800	\$4,312
215864482	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S9V2B060U4PSC+LRP	31,200	\$4,368
215864484	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S9V2B060U3VSB+LRP	31,200	\$4,368
215864486	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S9V2B040U3VSB+LRP	30,600	\$4,284
215864488	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S9V2B040U3PSC+LRP	31,000	\$4,340
215864490	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S8V2B080M4PDB	31,200	\$4,368
215864492	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S8V2B080M4PCB	31,200	\$4,368
215864494	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S8V2B060M4PDB	31,000	\$4,340
215864496	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	S8V2B060M4PCB	31,000	\$4,340
215865052	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	P0V0A000M30SD+LRP	31,000	\$4,340
215864498	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	L8V1B080U4VSB+LRP	31,200	\$4,368
216571239	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	L8V1A060U3VSB+LRP	31,200	\$4,368
215864476	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	*UHMB080CCV3+LRP	31,000	\$4,340
215864474	AMERICAN STANDARD	5A6V8X36A1	5PX*B004AS3	*UHMB060CCV3+LRP	31,200	\$4,368
215865036	AMERICAN STANDARD	5A6V8X24A1	5TEMCB03AV31+TD	N/A	22,400	\$3,136
216056999	AMERICAN STANDARD	5A6V8X24A1	5TAMXD04AV31	N/A	22,400	\$3,136
216056997	AMERICAN STANDARD	5A6V8X24A1	5TAMXC03AV31	N/A	22,600	\$3,164

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216569817	AMERICAN STANDARD	5A6V8X24A1	5TAMXB02AV21	N/A	23,000	\$3,220
216599682	AMERICAN STANDARD	5A6V8X24A1	5PX*BD06AS3	S9V2B080D4PSC+LRP	23,200	\$3,248
216571211	AMERICAN STANDARD	5A6V8X24A1	5PX*BD06AS3	S8V2B080M4PDB	23,200	\$3,248
216571213	AMERICAN STANDARD	5A6V8X24A1	5PX*BD06AS3	S8V2B080M4PCB	23,200	\$3,248
216571215	AMERICAN STANDARD	5A6V8X24A1	5PX*BD06AS3	S8V2B060M4PDB	23,000	\$3,220
216571217	AMERICAN STANDARD	5A6V8X24A1	5PX*BD06AS3	S8V2B060M4PCB	23,000	\$3,220
216571223	AMERICAN STANDARD	5A6V8X24A1	5PX*BD06AS3	S8V2A040M3PDB	23,000	\$3,220
216571221	AMERICAN STANDARD	5A6V8X24A1	5PX*BD06AS3	S8V2A040M3PCB	23,000	\$3,220
216571219	AMERICAN STANDARD	5A6V8X24A1	5PX*BD06AS3	*DHMB080CCV3+LRP	23,200	\$3,248
216571225	AMERICAN STANDARD	5A6V8X24A1	5PX*BD06AS3	*DHMB060CCV3+LRP	23,000	\$3,220
216599680	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	S9V2B080U4PSC+LRP	22,800	\$3,192
216571201	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	S8V2B080M4PDB	22,800	\$3,192
216571203	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	S8V2B080M4PCB	22,800	\$3,192
216571205	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	S8V2B060M4PDB	22,600	\$3,164
216571207	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	S8V2B060M4PCB	22,600	\$3,164
216571199	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	S8V2A040M3PDB	22,600	\$3,164
216571209	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	S8V2A040M3PCB	22,600	\$3,164
216571197	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	L8V1B080U4VSB+LRP	22,600	\$3,164
216571195	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	L8V1A060U3VSB+LRP	22,800	\$3,192
216571193	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	L8V1A040U3VSB+LRP	22,800	\$3,192
216571191	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	*UHMB080CCV3+LRP	22,400	\$3,136
216571189	AMERICAN STANDARD	5A6V8X24A1	5PX*B006AS3	*UHMB060CCV3+LRP	22,600	\$3,164
216453138	AMERICAN STANDARD	5A6V0X36A1	5TXCD010AS3	S8V2D120M5PDB	31,200	\$4,368
216453140	AMERICAN STANDARD	5A6V0X36A1	5TXCD010AS3	S8V2D120M5PCB	31,200	\$4,368
216440217	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	S9V2C100U5VSB+LRP	30,400	\$4,256
216440227	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	S9V2C100U5PSC+LRP	30,400	\$4,256
216440225	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	S9V2C100U4VSB+LRP	30,400	\$4,256
216440219	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	S9V2C080U5VSB+LRP	30,400	\$4,256
216440223	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	S9V2C080U5PSC+LRP	30,400	\$4,256
216571073	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	S8V2C100M5PDB	31,400	\$4,396
216571077	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	S8V2C100M5PCB	31,400	\$4,396
216571069	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	S8V2C080M5PDB	31,200	\$4,368
216571071	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	S8V2C080M5PCB	31,200	\$4,368
216440221	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	P0V0C000M50SD+LRP	30,400	\$4,256
216571075	AMERICAN STANDARD	5A6V0X36A1	5TXCC009AS3	*UHMC100CCV4+LRP	31,000	\$4,340
216440119	AMERICAN STANDARD	5A6V0X36A1	5TEMCD05AV41+TD	N/A	31,600	\$4,424
216440115	AMERICAN STANDARD	5A6V0X36A1	5TAMXD06AV41	N/A	31,600	\$4,424
216440113	AMERICAN STANDARD	5A6V0X36A1	5TAMXD05AV41	N/A	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216453114	AMERICAN STANDARD	5A6V0X36A1	5PX*DD10AS3	S8V2D120M5PDB	31,200	\$4,368
216453116	AMERICAN STANDARD	5A6V0X36A1	5PX*DD10AS3	S8V2D120M5PCB	31,200	\$4,368
216453110	AMERICAN STANDARD	5A6V0X36A1	5PX*D010AS3	S8V2D120M5PDB	31,200	\$4,368
216453112	AMERICAN STANDARD	5A6V0X36A1	5PX*D010AS3	S8V2D120M5PCB	31,200	\$4,368
216571017	AMERICAN STANDARD	5A6V0X36A1	5PX*CD09AS3	S8V2C100M5PDB	31,400	\$4,396
216571015	AMERICAN STANDARD	5A6V0X36A1	5PX*CD09AS3	S8V2C100M5PCB	31,400	\$4,396
216571013	AMERICAN STANDARD	5A6V0X36A1	5PX*CD09AS3	S8V2C080M5PDB	31,200	\$4,368
216571011	AMERICAN STANDARD	5A6V0X36A1	5PX*CD09AS3	S8V2C080M5PCB	31,200	\$4,368
216571009	AMERICAN STANDARD	5A6V0X36A1	5PX*CD09AS3	*DHMC100CCV4+LRP	31,000	\$4,340
216440097	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	S9V2C100U5VSB+LRP	30,400	\$4,256
216440089	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	S9V2C100U5PSC+LRP	30,400	\$4,256
216440099	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	S9V2C100U4VSB+LRP	30,400	\$4,256
216440095	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	S9V2C080U5VSB+LRP	30,400	\$4,256
216440091	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	S9V2C080U5PSC+LRP	30,400	\$4,256
216571001	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	S8V2C100M5PDB	31,400	\$4,396
216570999	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	S8V2C100M5PCB	31,400	\$4,396
216570997	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	S8V2C080M5PDB	31,200	\$4,368
216570995	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	S8V2C080M5PCB	31,200	\$4,368
216440093	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	P0V0C000M50SD+LRP	30,400	\$4,256
216570993	AMERICAN STANDARD	5A6V0X36A1	5PX*C009AS3	*UHMC100CCV4+LRP	31,000	\$4,340
216612218	AMERICAN STANDARD	5A6V0X24A1	5TXCB006AS3	S9V2B080U4VSB+LRP	22,000	\$3,080
216612216	AMERICAN STANDARD	5A6V0X24A1	5TXCB006AS3	S9V2B080U4PSC+LRP	22,000	\$3,080
216612214	AMERICAN STANDARD	5A6V0X24A1	5TXCB006AS3	S9V2B060U4VSB+LRP	22,200	\$3,108
216612224	AMERICAN STANDARD	5A6V0X24A1	5TXCB006AS3	S9V2B060U4PSC+LRP	22,200	\$3,108
216612222	AMERICAN STANDARD	5A6V0X24A1	5TXCB006AS3	S8V2B080M4PCB	22,000	\$3,080
216612220	AMERICAN STANDARD	5A6V0X24A1	5TXCB006AS3	S8V2B060M4PCB	22,000	\$3,080
216612226	AMERICAN STANDARD	5A6V0X24A1	5TXCB006AS3	L8V1B080U4VSB+LRP	22,000	\$3,080
216439977	AMERICAN STANDARD	5A6V0X24A1	5TEMCB03AV31+TD	N/A	22,800	\$3,192
216439975	AMERICAN STANDARD	5A6V0X24A1	5TAMXD04AV31	N/A	21,800	\$3,052
216439973	AMERICAN STANDARD	5A6V0X24A1	5TAMXC03AV31	N/A	22,000	\$3,080
216569815	AMERICAN STANDARD	5A6V0X24A1	5TAMXB02AV21	N/A	22,200	\$3,108
216612212	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S9V2B080D4VSB+LRP	22,400	\$3,136
216599674	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S9V2B080D4PSC+LRP	22,400	\$3,136
216439971	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S9V2B040D3VSB+LRP	21,800	\$3,052
216439969	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S9V2B040D3PSC+LRP	21,800	\$3,052
216453084	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S8V2B080M4PDB	22,400	\$3,136
216453082	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S8V2B080M4PCB	22,400	\$3,136
216570893	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S8V2B060M4PDB	22,400	\$3,136

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216570895	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S8V2B060M4PCB	22,400	\$3,136
216570901	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S8V2A040M3PDB	22,400	\$3,136
216570899	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	S8V2A040M3PCB	22,400	\$3,136
216448741	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	P0V0A000M30SD+LRP	21,800	\$3,052
216570903	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	*DHMB080CCV3+LRP	22,400	\$3,136
216570897	AMERICAN STANDARD	5A6V0X24A1	5PX*BD06AS3	*DHMB060CCV3+LRP	22,400	\$3,136
216612202	AMERICAN STANDARD	5A6V0X24A1	5PX*BD04AS3	S9V2B080D4VSB+LRP	22,200	\$3,108
216612210	AMERICAN STANDARD	5A6V0X24A1	5PX*BD04AS3	S8V2B080M4PDB	22,200	\$3,108
216612208	AMERICAN STANDARD	5A6V0X24A1	5PX*BD04AS3	S8V2B080M4PCB	22,200	\$3,108
216612204	AMERICAN STANDARD	5A6V0X24A1	5PX*BD04AS3	S8V2B060M4PDB	22,200	\$3,108
216612206	AMERICAN STANDARD	5A6V0X24A1	5PX*BD04AS3	S8V2B060M4PCB	22,200	\$3,108
216612200	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S9V2B080U4VSB+LRP	22,000	\$3,080
216599672	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S9V2B080U4PSC+LRP	22,000	\$3,080
216439961	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S9V2B060U4VSB+LRP	22,200	\$3,108
216439959	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S9V2B060U4PSC+LRP	22,200	\$3,108
216439965	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S9V2B060U3VSB+LRP	21,200	\$2,968
216439963	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S9V2B040U3VSB+LRP	21,000	\$2,940
216439967	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S9V2B040U3PSC+LRP	21,000	\$2,940
216453078	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S8V2B080M4PDB	22,000	\$3,080
216453080	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S8V2B080M4PCB	22,000	\$3,080
216570877	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S8V2B060M4PDB	22,000	\$3,080
216570879	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S8V2B060M4PCB	22,000	\$3,080
216570881	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S8V2A040M3PDB	21,800	\$3,052
216570883	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	S8V2A040M3PCB	21,800	\$3,052
216570885	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	L8V1B080U4VSB+LRP	22,000	\$3,080
216570887	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	L8V1A060U3VSB+LRP	22,200	\$3,108
216570889	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	L8V1A040U3VSB+LRP	22,200	\$3,108
216570875	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	*UHMB080CCV3+LRP	21,800	\$3,052
216570891	AMERICAN STANDARD	5A6V0X24A1	5PX*B006AS3	*UHMB060CCV3+LRP	21,800	\$3,052
216766755	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9X2D120U5PSB	33,600	\$4,704
216766765	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9X2C100U5PSB	34,400	\$4,816
216766767	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9X2C080U5PSB	34,200	\$4,788
216766779	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9X1D120U5PSB	33,600	\$4,704
216766751	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9X1C100U5PSB	34,400	\$4,816
216766773	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9X1C080U5PSB	34,200	\$4,788
216764106	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9V2D120U5VSB	34,000	\$4,760
216764104	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9V2D120U5PSC	34,000	\$4,760
216766775	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9V2C080U5VSB	34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764094	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S9V2C080U5PSC	34,000	\$4,760
216764902	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8X2D120M5PTC	33,800	\$4,732
216764904	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8X2D120M5PSC	33,800	\$4,732
216764900	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8X2C100M5PTC	34,200	\$4,788
216764908	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8X2C100M5PSC	34,200	\$4,788
216764906	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8X2C080M5PTC	34,000	\$4,760
216764096	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8X1D120M5PSC	33,800	\$4,732
216764898	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8X1C100M5PTC	34,200	\$4,788
216764098	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8X1C100M5PSC	34,200	\$4,788
216764896	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8X1C080M5PTC	34,000	\$4,760
216766763	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8V2D120M5PDB	33,800	\$4,732
216766777	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8V2D120M5PCB	33,800	\$4,732
216766769	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8V2C100M5PDB	34,000	\$4,760
216766753	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8V2C100M5PCB	34,000	\$4,760
216766771	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8V2C080M5PDB	34,000	\$4,760
216766757	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	S8V2C080M5PCB	34,000	\$4,760
216764100	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	L9X1C100U5VSA	34,400	\$4,816
216764102	AMERICAN STANDARD	5A6H7060A1	5TXCD010AS3	L8V1C100U5VSB	34,000	\$4,760
216766737	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9X2D120U5PSB	34,000	\$4,760
216766739	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9X2C100U5PSB	34,200	\$4,788
216766741	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9X2C080U5PSB	34,400	\$4,816
216766721	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9X1D120U5PSB	34,000	\$4,760
216766723	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9X1C100U5PSB	34,200	\$4,788
216766725	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9X1C080U5PSB	34,400	\$4,816
216770079	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9V2D120U5VSB	34,200	\$4,788
216770085	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9V2D120U5PSC	34,200	\$4,788
216766727	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9V2C100U5VSB	34,800	\$4,872
216766729	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S9V2C080U5VSB	34,200	\$4,788
216770077	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8X2D120M5PTC	34,400	\$4,816
216770075	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8X2D120M5PSC	34,400	\$4,816
216770073	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8X1D120M5PTC	34,400	\$4,816
216770081	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8X1D120M5PSC	34,400	\$4,816
216766745	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8V2D120M5PDB	34,000	\$4,760
216766731	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8V2D120M5PCB	34,000	\$4,760
216766747	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8V2C100M5PDB	34,400	\$4,816
216766733	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8V2C100M5PCB	34,400	\$4,816
216766749	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8V2C080M5PDB	34,400	\$4,816
216766743	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	S8V2C080M5PCB	34,400	\$4,816

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764090	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	N/A	34,800	\$4,872
216770083	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	L8V1C100U5VSB	34,200	\$4,788
216764092	AMERICAN STANDARD	5A6H7060A1	5TXCD008AS3	*UHMD120CCV5	34,600	\$4,844
216764088	AMERICAN STANDARD	5A6H7060A1	5TEMCD07AV51+TD	N/A	33,600	\$4,704
216764086	AMERICAN STANDARD	5A6H7060A1	5TEMCD06AV41+TD	N/A	33,600	\$4,704
216764084	AMERICAN STANDARD	5A6H7060A1	5TEM6D07AV51+TD	N/A	33,400	\$4,676
216764082	AMERICAN STANDARD	5A6H7060A1	5TEM6D06AV41+TD	N/A	33,400	\$4,676
216770071	AMERICAN STANDARD	5A6H7060A1	5TAMXD07AV51	N/A	33,600	\$4,704
216770069	AMERICAN STANDARD	5A6H7060A1	5TAMXD06AV41	N/A	34,000	\$4,760
216770067	AMERICAN STANDARD	5A6H7060A1	5TAM5D07AC51	N/A	34,400	\$4,816
216770065	AMERICAN STANDARD	5A6H7060A1	5TAM5D06AC41	N/A	33,600	\$4,704
216766699	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S9X2D120D5PSB	33,800	\$4,732
216766707	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S9X2C100D5PSB	34,000	\$4,760
216766705	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S9X1D120D5PSB	33,800	\$4,732
216766719	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S9X1C100D5PSB	34,000	\$4,760
216766713	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S9V2D120D5VSB	33,800	\$4,732
216764078	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S9V2D120D5PSC	33,800	\$4,732
216764894	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X2D120M5PTC	33,800	\$4,732
216764886	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X2D120M5PSC	33,800	\$4,732
216764892	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X2C100M5PTC	34,000	\$4,760
216764884	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X2C100M5PSC	34,000	\$4,760
216764890	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X2C080M5PTC	34,000	\$4,760
216764882	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X2C080M5PSC	34,000	\$4,760
216764880	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X1D120M5PTC	33,800	\$4,732
216764076	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X1D120M5PSC	33,800	\$4,732
216764878	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X1C100M5PTC	34,000	\$4,760
216764080	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X1C100M5PSC	34,000	\$4,760
216764888	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X1C080M5PTC	34,000	\$4,760
216764072	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8X1C080M5PSC	34,000	\$4,760
216766709	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8V2D120M5PDB	33,600	\$4,704
216766715	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8V2D120M5PCB	33,600	\$4,704
216766711	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8V2C100M5PDB	34,000	\$4,760
216766717	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8V2C100M5PCB	34,000	\$4,760
216766701	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8V2C080M5PDB	34,000	\$4,760
216766695	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	S8V2C080M5PCB	34,000	\$4,760
216764074	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	N/A	34,200	\$4,788
216770063	AMERICAN STANDARD	5A6H7060A1	5PX*DD10AS3	*DHMD120CCV5	34,000	\$4,760
216766687	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9X2D120U5PSB	33,600	\$4,704

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766685	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9X2C100U5PSB	34,400	\$4,816
216766683	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9X2C080U5PSB	34,200	\$4,788
216766669	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9X1D120U5PSB	33,600	\$4,704
216766671	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9X1C100U5PSB	34,400	\$4,816
216766673	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9X1C080U5PSB	34,200	\$4,788
216764054	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9V2D120U5VSB	33,800	\$4,732
216764056	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9V2D120U5PSC	33,800	\$4,732
216766675	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9V2C080U5VSB	33,800	\$4,732
216764058	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S9V2C080U5PSC	33,800	\$4,732
216764868	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X2D120M5PTC	34,000	\$4,760
216764876	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X2D120M5PSC	34,000	\$4,760
216764870	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X2C100M5PTC	34,000	\$4,760
216764864	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X2C100M5PSC	34,000	\$4,760
216764872	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X2C080M5PTC	34,000	\$4,760
216764866	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X2C080M5PSC	34,000	\$4,760
216764874	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X1D120M5PTC	34,000	\$4,760
216764060	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X1D120M5PSC	34,000	\$4,760
216764860	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X1C100M5PTC	34,000	\$4,760
216764062	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X1C100M5PSC	34,000	\$4,760
216764862	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X1C080M5PTC	34,000	\$4,760
216764064	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8X1C080M5PSC	34,000	\$4,760
216766693	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8V2D120M5PDB	33,800	\$4,732
216766677	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8V2D120M5PCB	33,800	\$4,732
216766667	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8V2C100M5PDB	34,000	\$4,760
216766679	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8V2C100M5PCB	34,000	\$4,760
216766681	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	S8V2C080M5PCB	34,000	\$4,760
216764066	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	N/A	34,400	\$4,816
216764068	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	L9X1C100U5VSA	34,400	\$4,816
216764070	AMERICAN STANDARD	5A6H7060A1	5PX*D010AS3	L8V1C100U5VSB	33,800	\$4,732
216766637	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9X2D120U5PSB	34,000	\$4,760
216766665	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9X2C100U5PSB	34,200	\$4,788
216766663	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9X2C080U5PSB	34,400	\$4,816
216766655	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9X1D120U5PSB	34,000	\$4,760
216766653	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9X1C100U5PSB	34,200	\$4,788
216766651	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9X1C080U5PSB	34,400	\$4,816
216764034	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9V2D120U5VSB	34,200	\$4,788
216764036	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9V2D120U5PSC	34,200	\$4,788
216766649	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9V2C100U5VSB	34,800	\$4,872

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764038	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9V2C100U5PSC	34,800	\$4,872
216766647	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9V2C080U5VSB	34,200	\$4,788
216764040	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S9V2C080U5PSC	34,200	\$4,788
216764852	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X2D120M5PTC	34,400	\$4,816
216764858	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X2D120M5PSC	34,400	\$4,816
216764854	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X2C100M5PTC	34,400	\$4,816
216764844	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X2C100M5PSC	34,400	\$4,816
216764856	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X2C080M5PTC	34,400	\$4,816
216764842	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X2C080M5PSC	34,400	\$4,816
216764846	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X1D120M5PTC	34,400	\$4,816
216764052	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X1D120M5PSC	34,400	\$4,816
216764848	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X1C100M5PTC	34,400	\$4,816
216764044	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X1C100M5PSC	34,400	\$4,816
216764850	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X1C080M5PTC	34,400	\$4,816
216764046	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8X1C080M5PSC	34,400	\$4,816
216766661	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8V2D120M5PDB	34,000	\$4,760
216766645	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8V2D120M5PCB	34,000	\$4,760
216766659	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8V2C100M5PDB	34,400	\$4,816
216766643	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8V2C100M5PCB	34,400	\$4,816
216766657	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8V2C080M5PDB	34,400	\$4,816
216766641	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	S8V2C080M5PCB	34,400	\$4,816
216764048	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	N/A	34,800	\$4,872
216764042	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	L9X1C100U5VSA	34,800	\$4,872
216764050	AMERICAN STANDARD	5A6H7060A1	5PX*D008AS3	L8V1C100U5VSB	34,200	\$4,788
216766603	AMERICAN STANDARD	5A6H7048A1	5TXCD008AS3	S9X2C080U5PSB	30,200	\$4,228
216766585	AMERICAN STANDARD	5A6H7048A1	5TXCD008AS3	S9X1C080U5PSB	30,200	\$4,228
216766569	AMERICAN STANDARD	5A6H7048A1	5TXCC009AS3	S9V2C100U5VSB	29,400	\$4,116
216770039	AMERICAN STANDARD	5A6H7048A1	5TXCC009AS3	S9V2C100U5PSC	29,400	\$4,116
216770019	AMERICAN STANDARD	5A6H7048A1	5TXCC009AS3	L9X1C100U5VSA	30,200	\$4,228
216763974	AMERICAN STANDARD	5A6H7048A1	5PX*D010AS3	N/A	29,800	\$4,172
216763976	AMERICAN STANDARD	5A6H7048A1	5PX*D010AS3	L9X1C100U5VSA	30,200	\$4,228
216766487	AMERICAN STANDARD	5A6H7048A1	5PX*D008AS3	S9X2C080U5PSB	30,200	\$4,228
216766491	AMERICAN STANDARD	5A6H7048A1	5PX*D008AS3	S9X1C080U5PSB	30,200	\$4,228
216766443	AMERICAN STANDARD	5A6H7048A1	5PX*C009AS3	S9V2C100U5VSB	29,400	\$4,116
216763936	AMERICAN STANDARD	5A6H7048A1	5PX*C009AS3	S9V2C100U5PSC	29,400	\$4,116
216763926	AMERICAN STANDARD	5A6H7048A1	5PX*C009AS3	L9X1C100U5VSA	30,200	\$4,228
216766429	AMERICAN STANDARD	5A6H7036A1	5TXCD010AS3	S9X2D120U5PSB	21,200	\$2,968
216766433	AMERICAN STANDARD	5A6H7036A1	5TXCD010AS3	S9X1D120U5PSB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763920	AMERICAN STANDARD	5A6H7036A1	5TXCD010AS3	S9V2D120U5VSB	21,200	\$2,968
216763922	AMERICAN STANDARD	5A6H7036A1	5TXCD010AS3	S9V2D120U5PSC	21,200	\$2,968
216766435	AMERICAN STANDARD	5A6H7036A1	5TXCD010AS3	S8V2D120M5PDB	21,200	\$2,968
216766431	AMERICAN STANDARD	5A6H7036A1	5TXCD010AS3	S8V2D120M5PCB	21,200	\$2,968
216763918	AMERICAN STANDARD	5A6H7036A1	5TXCD010AS3	*UHMD120CCV5	21,200	\$2,968
216766427	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S9X2D120U5PSB	21,200	\$2,968
216766421	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S9X2D120D5PSB	21,000	\$2,940
216766425	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S9X1D120U5PSB	21,200	\$2,968
216766419	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S9X1D120D5PSB	21,000	\$2,940
216770005	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S9V2D120U5PSC	21,400	\$2,996
216769999	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S8X2D120M5PTC	21,000	\$2,940
216769997	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S8X2D120M5PSC	21,000	\$2,940
216770003	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S8X1D120M5PTC	21,000	\$2,940
216770001	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S8X1D120M5PSC	21,000	\$2,940
216766417	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S8V2D120M5PDB	21,400	\$2,996
216766423	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	S8V2D120M5PCB	21,400	\$2,996
216763914	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	N/A	21,800	\$3,052
216763912	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	*UHMD120CCV5	21,200	\$2,968
216763916	AMERICAN STANDARD	5A6H7036A1	5TXCD008AS3	*DHMD120CCV5	21,000	\$2,940
216766401	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S9X2C100U5PSB	21,200	\$2,968
216766399	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S9X2C080U5PSB	21,400	\$2,996
216766415	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S9X1C100U5PSB	21,200	\$2,968
216766413	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S9X1C080U5PSB	21,400	\$2,996
216766411	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S9V2C100U5VSB	21,200	\$2,968
216769995	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S9V2C100U5PSC	21,200	\$2,968
216769981	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S9V2C100U4VSB	21,200	\$2,968
216766409	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S9V2C080U5VSB	21,200	\$2,968
216769979	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S9V2C080U5PSC	21,200	\$2,968
216769977	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8X2C100M5PTC	21,400	\$2,996
216769975	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8X2C100M5PSC	21,400	\$2,996
216769993	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8X2C080M5PTC	21,200	\$2,968
216769991	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8X2C080M5PSC	21,200	\$2,968
216769989	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8X1C100M5PTC	21,400	\$2,996
216769987	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8X1C100M5PSC	21,400	\$2,996
216769985	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8X1C080M5PTC	21,200	\$2,968
216769983	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8X1C080M5PSC	21,200	\$2,968
216766397	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8V2C100M5PDB	21,200	\$2,968
216766407	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8V2C100M5PCB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766395	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8V2C080M5PDB	21,400	\$2,996
216766405	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	S8V2C080M5PCB	21,400	\$2,996
2167663910	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	N/A	21,600	\$3,024
216769973	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	L9X1C100U5VSA	21,200	\$2,968
216769971	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	L8V1C100U5VSB	21,200	\$2,968
216763908	AMERICAN STANDARD	5A6H7036A1	5TXCC009AS3	*UHMC100CCV4	21,000	\$2,940
216766367	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9X2C100U5PSB	21,400	\$2,996
216766371	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9X2C100D5PSB	21,000	\$2,940
216766369	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9X2C080U5PSB	21,600	\$3,024
216766381	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9X1C100U5PSB	21,400	\$2,996
216766377	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9X1C100D5PSB	21,000	\$2,940
216766383	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9X1C080U5PSB	21,600	\$3,024
216766385	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9V2C100U5VSB	21,400	\$2,996
216763898	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9V2C100U5PSC	21,400	\$2,996
216763900	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9V2C100U4VSB	21,400	\$2,996
216766379	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9V2C100D5VSB	21,000	\$2,940
216763906	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9V2C100D5PSC	21,000	\$2,940
216763904	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9V2C100D4VSB	21,000	\$2,940
216766387	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9V2C080U5VSB	21,400	\$2,996
216763902	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S9V2C080U5PSC	21,400	\$2,996
216764748	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8X2C100M5PTC	21,200	\$2,968
216764750	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8X2C100M5PSC	21,200	\$2,968
216764752	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8X2C080M5PTC	21,400	\$2,996
216764746	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8X2C080M5PSC	21,400	\$2,996
216764754	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8X1C100M5PTC	21,200	\$2,968
216763886	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8X1C100M5PSC	21,200	\$2,968
216764756	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8X1C080M5PTC	21,400	\$2,996
216763888	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8X1C080M5PSC	21,400	\$2,996
216766373	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8V2C100M5PDB	21,400	\$2,996
216766389	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8V2C100M5PCB	21,400	\$2,996
216766375	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8V2C080M5PDB	21,400	\$2,996
216766391	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	S8V2C080M5PCB	21,400	\$2,996
216763890	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	N/A	21,800	\$3,052
216763892	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	L9X1C100U5VSA	21,200	\$2,968
216763894	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	L8V1C100U5VSB	21,400	\$2,996
216763896	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	*UHMC100CCV4	21,200	\$2,968
216763884	AMERICAN STANDARD	5A6H7036A1	5TXCC007AS3	*DHMC100CCV4	21,000	\$2,940
216766357	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S9X2C100U5PSB	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766365	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S9X2C080U5PSB	21,200	\$2,968
216766359	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S9X1C100U5PSB	21,400	\$2,996
216766353	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S9X1C080U5PSB	21,200	\$2,968
216766351	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S9V2C100U5VSB	21,000	\$2,940
216769953	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S9V2C100U5PSC	21,000	\$2,940
216769955	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S9V2C100U4VSB	21,000	\$2,940
216766349	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S9V2C080U5VSB	21,000	\$2,940
216769957	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S9V2C080U5PSC	21,000	\$2,940
216769959	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8X2C100M5PTC	21,000	\$2,940
216769961	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8X2C100M5PSC	21,000	\$2,940
216769963	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8X2C080M5PTC	21,200	\$2,968
216769965	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8X2C080M5PSC	21,200	\$2,968
216769967	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8X1C100M5PTC	21,000	\$2,940
216769969	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8X1C100M5PSC	21,000	\$2,940
216769951	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8X1C080M5PTC	21,200	\$2,968
216769943	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8X1C080M5PSC	21,200	\$2,968
216766361	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8V2C100M5PDB	21,200	\$2,968
216766347	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8V2C100M5PCB	21,200	\$2,968
216766363	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8V2C080M5PDB	21,400	\$2,996
216766345	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	S8V2C080M5PCB	21,400	\$2,996
216763882	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	N/A	22,000	\$3,080
216769945	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	L9X1C100U5VSA	21,200	\$2,968
216769947	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	L8V1C100U5VSB	21,400	\$2,996
216769949	AMERICAN STANDARD	5A6H7036A1	5TXCC005AS3	*UHMC100CCV4	21,000	\$2,940
216766307	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X2B080U4PSB	21,600	\$3,024
216766335	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X2B080D4PSB	21,000	\$2,940
216766309	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X2B060U4PSB	21,400	\$2,996
216766337	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X2B060D3PSB	21,000	\$2,940
216766311	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X2B040U3PSB	21,400	\$2,996
216766305	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X2B040D3PSB	21,400	\$2,996
216766329	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X1B080U4PSB	21,600	\$3,024
216766301	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X1B080D4PSB	21,000	\$2,940
216766333	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X1B060U4PSB	21,400	\$2,996
216766303	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X1B060D3PSB	21,000	\$2,940
216766331	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X1B040U3PSB	21,400	\$2,996
216766325	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9X1B040D3PSB	21,400	\$2,996
216763853	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B080U4VSB	21,400	\$2,996
216763855	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B080U4PSC	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763839	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B080D4VSB	20,800	\$2,912
216763841	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B080D4PSC	20,800	\$2,912
216766313	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B060U4VSB	21,200	\$2,968
216763857	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B060U4PSC	21,200	\$2,968
216763859	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B060U3VSB	21,200	\$2,968
216763843	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B060D3VSB	20,800	\$2,912
216763845	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B060D3PSC	20,800	\$2,912
216763861	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B040U3VSB	21,200	\$2,968
216763880	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B040U3PSC	21,200	\$2,968
216766327	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B040D3VSB	20,800	\$2,912
216763847	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S9V2B040D3PSC	20,800	\$2,912
216764730	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X2B080M4PTC	21,400	\$2,996
216764742	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X2B080M4PSC	21,400	\$2,996
216764734	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X2B060M4PTC	21,400	\$2,996
216764740	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X2B060M4PSC	21,400	\$2,996
216764728	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X2A040M3PTC	21,200	\$2,968
216764732	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X2A040M3PSC	21,200	\$2,968
216764736	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X1B080M4PTC	21,400	\$2,996
216763878	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X1B080M4PSC	21,400	\$2,996
216764738	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X1B060M4PTC	21,400	\$2,996
216763876	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X1B060M4PSC	21,400	\$2,996
216764744	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X1A040M3PTC	21,200	\$2,968
216763874	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8X1A040M3PSC	21,200	\$2,968
216766339	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8V2B080M4PDB	21,400	\$2,996
216766315	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8V2B080M4PCB	21,400	\$2,996
216766341	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8V2B060M4PDB	21,200	\$2,968
216766317	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8V2B060M4PCB	21,200	\$2,968
216766343	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8V2A040M3PDB	21,400	\$2,996
216766319	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	S8V2A040M3PCB	21,400	\$2,996
216763872	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	N/A	21,800	\$3,052
216763870	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	L9X1B070U4VSA	21,600	\$3,024
216763868	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	L9X1A050U3VSA	21,600	\$3,024
216763866	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	L8V1B080U4VSB	21,200	\$2,968
216763863	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	L8V1A060U3VSB	21,200	\$2,968
216763851	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	L8V1A040U3VSB	21,400	\$2,996
216763835	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	*UHMB080CCV3	21,200	\$2,968
216763837	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	*UHMB060CCV3	21,200	\$2,968
216763849	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	*DHMB080CCV3	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763833	AMERICAN STANDARD	5A6H7036A1	5TXCB006AS3	*DHMB060CCV3	21,200	\$2,968
216766283	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9X2B080U4PSB	21,000	\$2,940
216766285	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9X2B060U4PSB	21,400	\$2,996
216766287	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9X2B040U3PSB	21,200	\$2,968
216766275	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9X1B080U4PSB	21,000	\$2,940
216766277	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9X1B060U4PSB	21,400	\$2,996
216766279	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9X1B040U3PSB	21,200	\$2,968
216763821	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9V2B080U4VSB	21,200	\$2,968
216763819	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9V2B080U4PSC	21,200	\$2,968
216766281	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9V2B060U4VSB	21,200	\$2,968
216763817	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9V2B060U4PSC	21,200	\$2,968
216763815	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9V2B060U3VSB	21,200	\$2,968
216763813	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9V2B040U3VSB	21,200	\$2,968
216763811	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S9V2B040U3PSC	21,200	\$2,968
216764716	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X2B080M4PTC	21,600	\$3,024
216764720	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X2B080M4PSC	21,600	\$3,024
216764724	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X2B060M4PTC	21,200	\$2,968
216764714	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X2B060M4PSC	21,200	\$2,968
216764710	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X2A040M3PTC	21,400	\$2,996
216764712	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X2A040M3PSC	21,400	\$2,996
216764718	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X1B080M4PTC	21,600	\$3,024
216763809	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X1B080M4PSC	21,600	\$3,024
216764722	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X1B060M4PTC	21,200	\$2,968
216763825	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X1B060M4PSC	21,200	\$2,968
216764726	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X1A040M3PTC	21,400	\$2,996
216763823	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8X1A040M3PSC	21,400	\$2,996
216766299	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8V2B080M4PDB	21,200	\$2,968
216766293	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8V2B080M4PCB	21,200	\$2,968
216766291	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8V2B060M4PDB	21,200	\$2,968
216766295	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8V2B060M4PCB	21,200	\$2,968
216766289	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8V2A040M3PDB	21,200	\$2,968
216766297	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	S8V2A040M3PCB	21,200	\$2,968
216763807	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	N/A	21,600	\$3,024
216763805	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	L9X1B070U4VSA	21,600	\$3,024
216763803	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	L9X1A050U3VSA	21,800	\$3,052
216763801	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	L8V1B080U4VSB	21,200	\$2,968
216763799	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	L8V1A060U3VSB	21,000	\$2,940
216763831	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	L8V1A040U3VSB	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763829	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	*UHMB080CCV3	21,000	\$2,940
216763827	AMERICAN STANDARD	5A6H7036A1	5TXCB004AS3	*UHMB060CCV3	21,000	\$2,940
216763797	AMERICAN STANDARD	5A6H7036A1	5TEMCD07AV51+TD	N/A	21,000	\$2,940
216763795	AMERICAN STANDARD	5A6H7036A1	5TEMCD06AV41+TD	N/A	21,000	\$2,940
216763793	AMERICAN STANDARD	5A6H7036A1	5TEMCD05AV41+TD	N/A	21,200	\$2,968
216763791	AMERICAN STANDARD	5A6H7036A1	5TEMCD04AV31+TD	N/A	21,200	\$2,968
216763787	AMERICAN STANDARD	5A6H7036A1	5TEM6D07AV51+TD	N/A	21,000	\$2,940
216763785	AMERICAN STANDARD	5A6H7036A1	5TEM6D06AV41+TD	N/A	21,000	\$2,940
216763783	AMERICAN STANDARD	5A6H7036A1	5TEM6D05AV41+TD	N/A	21,200	\$2,968
216763781	AMERICAN STANDARD	5A6H7036A1	5TEM6D04AV31+TD	N/A	21,200	\$2,968
216763777	AMERICAN STANDARD	5A6H7036A1	5TAMXD07AV51	N/A	21,000	\$2,940
216763775	AMERICAN STANDARD	5A6H7036A1	5TAMXD06AV41	N/A	21,400	\$2,996
216763773	AMERICAN STANDARD	5A6H7036A1	5TAMXD05AV41	N/A	21,200	\$2,968
216763769	AMERICAN STANDARD	5A6H7036A1	5TAMXC03AV31	N/A	21,400	\$2,996
216763767	AMERICAN STANDARD	5A6H7036A1	5TAM5D05AC31	N/A	21,400	\$2,996
216766263	AMERICAN STANDARD	5A6H7036A1	5PX*DD10AS3	S9X2D120D5PSB	21,200	\$2,968
216766269	AMERICAN STANDARD	5A6H7036A1	5PX*DD10AS3	S9X1D120D5PSB	21,200	\$2,968
216766265	AMERICAN STANDARD	5A6H7036A1	5PX*DD10AS3	S8V2D120M5PDB	21,200	\$2,968
216766267	AMERICAN STANDARD	5A6H7036A1	5PX*DD10AS3	S8V2D120M5PCB	21,200	\$2,968
216763761	AMERICAN STANDARD	5A6H7036A1	5PX*DD10AS3	N/A	21,600	\$3,024
216769941	AMERICAN STANDARD	5A6H7036A1	5PX*DD10AS3	*DHMD120CCV5	20,800	\$2,912
216766259	AMERICAN STANDARD	5A6H7036A1	5PX*D010AS3	S9X2D120U5PSB	21,000	\$2,940
216766261	AMERICAN STANDARD	5A6H7036A1	5PX*D010AS3	S9X1D120U5PSB	21,000	\$2,940
216763757	AMERICAN STANDARD	5A6H7036A1	5PX*D010AS3	S9V2D120U5VSB	21,200	\$2,968
216763755	AMERICAN STANDARD	5A6H7036A1	5PX*D010AS3	S9V2D120U5PSC	21,200	\$2,968
216766255	AMERICAN STANDARD	5A6H7036A1	5PX*D010AS3	S8V2D120M5PDB	21,200	\$2,968
216766257	AMERICAN STANDARD	5A6H7036A1	5PX*D010AS3	S8V2D120M5PCB	21,200	\$2,968
216763753	AMERICAN STANDARD	5A6H7036A1	5PX*D010AS3	N/A	21,600	\$3,024
216763759	AMERICAN STANDARD	5A6H7036A1	5PX*D010AS3	*UHMD120CCV5	21,000	\$2,940
216766251	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S9X2D120U5PSB	21,200	\$2,968
216766253	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S9X2D120D5PSB	21,000	\$2,940
216766245	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S9X1D120U5PSB	21,200	\$2,968
216766247	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S9X1D120D5PSB	21,000	\$2,940
216763751	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S9V2D120U5VSB	21,400	\$2,996
216763747	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S9V2D120U5PSC	21,400	\$2,996
216764704	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S8X2D120M5PTC	21,000	\$2,940
216764708	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S8X2D120M5PSC	21,000	\$2,940
216764706	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S8X1D120M5PTC	21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763749	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S8X1D120M5PSC	21,000	\$2,940
216766249	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S8V2D120M5PDB	21,400	\$2,996
216766243	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	S8V2D120M5PCB	21,400	\$2,996
216763745	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	N/A	21,800	\$3,052
216769939	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	*UHMD120CCV5	21,200	\$2,968
216769937	AMERICAN STANDARD	5A6H7036A1	5PX*D008AS3	*DHMD120CCV5	21,000	\$2,940
216766237	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S9X2C100D5PSB	21,400	\$2,996
216766227	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S9X1C100D5PSB	21,400	\$2,996
216766229	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S9V2C100D5VSB	21,000	\$2,940
216763737	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S9V2C100D5PSC	21,000	\$2,940
216763739	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S9V2C100D4VSB	21,000	\$2,940
216769935	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8X2C100M5PTC	21,400	\$2,996
216769933	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8X2C100M5PSC	21,400	\$2,996
216764700	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8X2C080M5PTC	21,200	\$2,968
216764702	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8X2C080M5PSC	21,200	\$2,968
216769931	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8X1C100M5PTC	21,400	\$2,996
216769929	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8X1C100M5PSC	21,400	\$2,996
216764698	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8X1C080M5PTC	21,200	\$2,968
216763741	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8X1C080M5PSC	21,200	\$2,968
216766241	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8V2C100M5PDB	21,200	\$2,968
216766231	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8V2C100M5PCB	21,200	\$2,968
216766239	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8V2C080M5PDB	21,200	\$2,968
216766233	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	S8V2C080M5PCB	21,200	\$2,968
216763743	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	N/A	21,800	\$3,052
216769927	AMERICAN STANDARD	5A6H7036A1	5PX*CD09AS3	*DHMC100CCV4	21,000	\$2,940
216766225	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S9X2C100D5PSB	21,800	\$3,052
216766215	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S9X1C100D5PSB	21,800	\$3,052
216766217	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S9V2C100D5VSB	21,600	\$3,024
216763733	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S9V2C100D5PSC	21,600	\$3,024
216763735	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S9V2C100D4VSB	21,600	\$3,024
216764692	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S8X2C100M5PTC	21,400	\$2,996
216764688	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S8X2C100M5PSC	21,400	\$2,996
216764694	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S8X1C100M5PTC	21,400	\$2,996
216763729	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S8X1C100M5PSC	21,400	\$2,996
216766211	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S8V2C100M5PDB	21,800	\$3,052
216766219	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S8V2C100M5PCB	21,800	\$3,052
216766213	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S8V2C080M5PDB	21,800	\$3,052
216766223	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	S8V2C080M5PCB	21,800	\$3,052

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763727	AMERICAN STANDARD	5A6H7036A1	5PX*CD07AS3	N/A	21,800	\$3,052
216766205	AMERICAN STANDARD	5A6H7036A1	5PX*CD05AS3	S8V2C100M5PDB	21,600	\$3,024
216766197	AMERICAN STANDARD	5A6H7036A1	5PX*CD05AS3	S8V2C100M5PCB	21,600	\$3,024
216766207	AMERICAN STANDARD	5A6H7036A1	5PX*CD05AS3	S8V2C080M5PDB	21,600	\$3,024
216766199	AMERICAN STANDARD	5A6H7036A1	5PX*CD05AS3	S8V2C080M5PCB	21,600	\$3,024
216763719	AMERICAN STANDARD	5A6H7036A1	5PX*CD05AS3	N/A	22,000	\$3,080
216766193	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S9X2C100U5PSB	21,200	\$2,968
216766191	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S9X2C080U5PSB	21,400	\$2,996
216766173	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S9X1C100U5PSB	21,200	\$2,968
216766187	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S9X1C080U5PSB	21,400	\$2,996
216766177	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S9V2C100U5VSB	21,200	\$2,968
216763711	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S9V2C100U5PSC	21,200	\$2,968
216763713	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S9V2C100U4VSB	21,200	\$2,968
216766179	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S9V2C080U5VSB	21,200	\$2,968
216763715	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S9V2C080U5PSC	21,200	\$2,968
216769921	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8X2C100M5PTC	21,400	\$2,996
216769923	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8X2C100M5PSC	21,400	\$2,996
216764674	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8X2C080M5PTC	21,200	\$2,968
216764676	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8X2C080M5PSC	21,200	\$2,968
216769925	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8X1C100M5PTC	21,400	\$2,996
216769919	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8X1C100M5PSC	21,400	\$2,996
216764678	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8X1C080M5PTC	21,200	\$2,968
216763717	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8X1C080M5PSC	21,200	\$2,968
216766175	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8V2C100M5PDB	21,200	\$2,968
216766181	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8V2C100M5PCB	21,200	\$2,968
216766189	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8V2C080M5PDB	21,400	\$2,996
216766183	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	S8V2C080M5PCB	21,400	\$2,996
216763709	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	N/A	21,600	\$3,024
216769915	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	L9X1C100U5VSA	21,200	\$2,968
216763707	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	L8V1C100U5VSB	21,200	\$2,968
216769917	AMERICAN STANDARD	5A6H7036A1	5PX*C009AS3	*UHMC100CCV4	21,000	\$2,940
216766169	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9X2C100U5PSB	21,400	\$2,996
216766157	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9X2C100D5PSB	21,200	\$2,968
216766167	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9X2C080U5PSB	21,600	\$3,024
216766149	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9X1C100U5PSB	21,400	\$2,996
216766153	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9X1C100D5PSB	21,200	\$2,968
216766147	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9X1C080U5PSB	21,600	\$3,024
216766145	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9V2C100U5VSB	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763703	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9V2C100U5PSC	21,400	\$2,996
216763701	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9V2C100U4VSB	21,400	\$2,996
216766151	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9V2C100D5VSB	21,000	\$2,940
216763687	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9V2C100D5PSC	21,000	\$2,940
216763705	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9V2C100D4VSB	21,000	\$2,940
216766159	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9V2C080U5VSB	21,400	\$2,996
216763699	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S9V2C080U5PSC	21,400	\$2,996
216764668	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8X2C100M5PTC	21,600	\$3,024
216764664	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8X2C100M5PSC	21,600	\$3,024
216764666	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8X2C080M5PTC	21,400	\$2,996
216764662	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8X2C080M5PSC	21,400	\$2,996
216764672	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8X1C100M5PTC	21,600	\$3,024
216763697	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8X1C100M5PSC	21,600	\$3,024
216764670	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8X1C080M5PTC	21,400	\$2,996
216763695	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8X1C080M5PSC	21,400	\$2,996
216766155	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8V2C100M5PDB	21,400	\$2,996
216766161	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8V2C100M5PCB	21,400	\$2,996
216766171	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8V2C080M5PDB	21,400	\$2,996
216766163	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	S8V2C080M5PCB	21,400	\$2,996
216763693	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	N/A	21,800	\$3,052
216763691	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	L9X1C100U5VSA	21,200	\$2,968
216763689	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	L8V1C100U5VSB	21,400	\$2,996
216769911	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	*UHMC100CCV4	21,200	\$2,968
216769913	AMERICAN STANDARD	5A6H7036A1	5PX*C007AS3	*DHMC100CCV4	21,000	\$2,940
216766141	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S9X2C100U5PSB	21,200	\$2,968
216766143	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S9X2C080U5PSB	21,200	\$2,968
216766135	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S9X1C100U5PSB	21,200	\$2,968
216766139	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S9X1C080U5PSB	21,200	\$2,968
216766137	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S9V2C100U5VSB	21,000	\$2,940
216763681	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S9V2C100U5PSC	21,000	\$2,940
216763671	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S9V2C100U4VSB	21,000	\$2,940
216766127	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S9V2C080U5VSB	21,000	\$2,940
216763673	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S9V2C080U5PSC	21,000	\$2,940
216764656	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8X2C100M5PTC	21,000	\$2,940
216764652	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8X2C100M5PSC	21,000	\$2,940
216764650	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8X2C080M5PTC	21,600	\$3,024
216764654	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8X2C080M5PSC	21,600	\$3,024
216764660	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8X1C100M5PTC	21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763675	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8X1C100M5PSC	21,000	\$2,940
216764658	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8X1C080M5PTC	21,600	\$3,024
216763677	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8X1C080M5PSC	21,600	\$3,024
216766133	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8V2C100M5PDB	21,200	\$2,968
216766123	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8V2C100M5PCB	21,200	\$2,968
216766125	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8V2C080M5PDB	21,400	\$2,996
216766131	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	S8V2C080M5PCB	21,400	\$2,996
216763683	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	N/A	22,000	\$3,080
216763685	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	L9X1C100U5VSA	21,800	\$3,052
216763679	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	L8V1C100U5VSB	21,400	\$2,996
216769909	AMERICAN STANDARD	5A6H7036A1	5PX*C005AS3	*UHMC100CCV4	21,000	\$2,940
216766109	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S9X2B040D3PSB	22,000	\$3,080
216766105	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S9X1B040D3PSB	22,000	\$3,080
216763655	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S9V2B060D3VSB	21,600	\$3,024
216763653	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S9V2B060D3PSC	21,600	\$3,024
216766107	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S9V2B040D3VSB	21,600	\$3,024
216763667	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S9V2B040D3PSC	21,600	\$3,024
216764634	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8X2B080M4PTC	21,800	\$3,052
216764640	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8X2B080M4PSC	21,800	\$3,052
216764632	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8X2A040M3PTC	21,800	\$3,052
216764648	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8X2A040M3PSC	21,800	\$3,052
216764636	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8X1B080M4PTC	21,800	\$3,052
216763661	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8X1B080M4PSC	21,800	\$3,052
216764646	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8X1A040M3PTC	21,800	\$3,052
216763663	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8X1A040M3PSC	21,800	\$3,052
216766119	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8V2B080M4PDB	21,400	\$2,996
216766115	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8V2B080M4PCB	21,400	\$2,996
216766095	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8V2B060M4PDB	21,600	\$3,024
216766093	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8V2B060M4PCB	21,600	\$3,024
216766117	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8V2A040M3PDB	21,400	\$2,996
216766121	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	S8V2A040M3PCB	21,400	\$2,996
216763669	AMERICAN STANDARD	5A6H7036A1	5PX*BD06AS3	N/A	21,800	\$3,052
216766087	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9X2B080D4PSB	21,600	\$3,024
216766089	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9X2B060D3PSB	21,800	\$3,052
216766091	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9X2B040D3PSB	22,000	\$3,080
216766071	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9X1B080D4PSB	21,600	\$3,024
216766073	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9X1B060D3PSB	21,800	\$3,052
216766075	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9X1B040D3PSB	22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763651	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9V2B080D4VSB	21,600	\$3,024
216763649	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9V2B080D4PSC	21,600	\$3,024
216763647	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9V2B060D3VSB	21,600	\$3,024
216763643	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9V2B060D3PSC	21,600	\$3,024
216766085	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9V2B040D3VSB	21,800	\$3,052
216763645	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S9V2B040D3PSC	21,800	\$3,052
216764614	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S8X2A040M3PTC	21,800	\$3,052
216764622	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S8X2A040M3PSC	21,800	\$3,052
216764626	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S8X1A040M3PTC	21,800	\$3,052
216763639	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S8X1A040M3PSC	21,800	\$3,052
216766067	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S8V2B080M4PDB	21,600	\$3,024
216766077	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S8V2B080M4PCB	21,600	\$3,024
216766069	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S8V2B060M4PDB	21,600	\$3,024
216766079	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	S8V2B060M4PCB	21,600	\$3,024
216763641	AMERICAN STANDARD	5A6H7036A1	5PX*BD04AS3	N/A	22,000	\$3,080
216766059	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9X2B080U4PSB	21,600	\$3,024
216766061	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9X2B060U4PSB	21,400	\$2,996
216766035	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9X2B060D3PSB	21,200	\$2,968
216766063	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9X2B040U3PSB	21,400	\$2,996
216766041	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9X1B080U4PSB	21,600	\$3,024
216766043	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9X1B060U4PSB	21,400	\$2,996
216766037	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9X1B060D3PSB	21,200	\$2,968
216766045	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9X1B040U3PSB	21,400	\$2,996
216763615	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B080U4VSB	21,200	\$2,968
216763613	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B080U4PSC	21,200	\$2,968
216763621	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B080D4VSB	21,200	\$2,968
216763619	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B080D4PSC	21,200	\$2,968
216766047	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B060U4VSB	21,400	\$2,996
216763623	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B060U4PSC	21,200	\$2,968
216763625	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B060U3VSB	21,200	\$2,968
216763627	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B040U3VSB	21,200	\$2,968
216763629	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B040U3PSC	21,200	\$2,968
216766039	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B040D3VSB	21,400	\$2,996
216763617	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S9V2B040D3PSC	21,400	\$2,996
216764602	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X2B080M4PTC	21,400	\$2,996
216764608	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X2B080M4PSC	21,400	\$2,996
216764596	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X2B060M4PTC	21,400	\$2,996
216764610	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X2B060M4PSC	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764604	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X2A040M3PTC	21,200	\$2,968
216764612	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X2A040M3PSC	21,200	\$2,968
216764598	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X1B080M4PTC	21,400	\$2,996
216763607	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X1B080M4PSC	21,400	\$2,996
216764600	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X1B060M4PTC	21,400	\$2,996
216763609	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X1B060M4PSC	21,400	\$2,996
216764606	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X1A040M3PTC	21,200	\$2,968
216763611	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8X1A040M3PSC	21,200	\$2,968
216766055	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8V2B080M4PDB	21,400	\$2,996
216766049	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8V2B080M4PCB	21,400	\$2,996
216766033	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8V2B060M4PDB	21,400	\$2,996
216766051	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8V2B060M4PCB	21,400	\$2,996
216766031	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8V2A040M3PDB	21,200	\$2,968
216766053	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	S8V2A040M3PCB	21,200	\$2,968
216763599	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	N/A	21,800	\$3,052
216763633	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	L9X1B070U4VSA	21,600	\$3,024
216763603	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	L9X1A050U3VSA	21,400	\$2,996
216763605	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	L8V1B080U4VSB	21,200	\$2,968
216763601	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	L8V1A060U3VSB	21,200	\$2,968
216763631	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	L8V1A040U3VSB	21,200	\$2,968
216769905	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	*UHMB080CCV3	21,200	\$2,968
216769903	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	*UHMB060CCV3	21,200	\$2,968
216769907	AMERICAN STANDARD	5A6H7036A1	5PX*B006AS3	*DHMB080CCV3	21,200	\$2,968
216766001	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9X2B080U4PSB	21,000	\$2,940
216766029	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9X2B060U4PSB	21,400	\$2,996
216766003	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9X2B040U3PSB	21,200	\$2,968
216766005	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9X1B080U4PSB	21,000	\$2,940
216766013	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9X1B060U4PSB	21,400	\$2,996
216766015	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9X1B040U3PSB	21,200	\$2,968
216763581	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9V2B080U4VSB	21,200	\$2,968
216763569	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9V2B080U4PSC	21,200	\$2,968
216766017	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9V2B060U4VSB	21,200	\$2,968
216763585	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9V2B060U4PSC	21,200	\$2,968
216763587	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9V2B060U3VSB	21,200	\$2,968
216763589	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9V2B040U3VSB	21,200	\$2,968
216763591	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S9V2B040U3PSC	21,200	\$2,968
216764592	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X2B080M4PTC	21,600	\$3,024
216764580	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X2B080M4PSC	21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764590	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X2B060M4PTC	21,200	\$2,968
216764588	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X2A040M3PTC	21,400	\$2,996
216764582	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X2A040M3PSC	21,400	\$2,996
216764584	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X1B080M4PTC	21,600	\$3,024
216763593	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X1B080M4PSC	21,600	\$3,024
216764594	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X1B060M4PTC	21,200	\$2,968
216763595	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X1B060M4PSC	21,200	\$2,968
216764586	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X1A040M3PTC	21,400	\$2,996
216763597	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8X1A040M3PSC	21,400	\$2,996
216766011	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8V2B080M4PDB	21,200	\$2,968
216766019	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8V2B080M4PCB	21,200	\$2,968
216766009	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8V2B060M4PDB	21,200	\$2,968
216766021	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8V2B060M4PCB	21,200	\$2,968
216766007	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8V2A040M3PDB	21,200	\$2,968
216766027	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	S8V2A040M3PCB	21,200	\$2,968
216763583	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	N/A	21,600	\$3,024
216763571	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	L9X1B070U4VSA	21,600	\$3,024
216763573	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	L9X1A050U3VSA	21,800	\$3,052
216763575	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	L8V1B080U4VSB	21,200	\$2,968
216763577	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	L8V1A060U3VSB	20,800	\$2,912
216763579	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	L8V1A040U3VSB	21,400	\$2,996
216769899	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	*UHMB080CCV3	21,000	\$2,940
216769901	AMERICAN STANDARD	5A6H7036A1	5PX*B004AS3	*UHMB060CCV3	21,000	\$2,940
216769895	AMERICAN STANDARD	5A6H7024A1	5TXCC009AS3	*UHMC100CCV4	15,100	\$2,114
216769897	AMERICAN STANDARD	5A6H7024A1	5TXCC009AS3	*DHMC100CCV4	14,800	\$2,072
216769893	AMERICAN STANDARD	5A6H7024A1	5TXCC007AS3	*UHMC100CCV4	15,200	\$2,128
216763567	AMERICAN STANDARD	5A6H7024A1	5TXCC007AS3	*DHMC100CCV4	14,900	\$2,086
216763565	AMERICAN STANDARD	5A6H7024A1	5TXCC005AS3	N/A	15,800	\$2,212
216769889	AMERICAN STANDARD	5A6H7024A1	5TXCC005AS3	*UHMC100CCV4	15,000	\$2,100
216769891	AMERICAN STANDARD	5A6H7024A1	5TXCC005AS3	*DHMC100CCV4	15,100	\$2,114
216765965	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X2B080D4PSB	15,100	\$2,114
216765971	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X2B060U4PSB	15,400	\$2,156
216765967	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X2B060D3PSB	15,000	\$2,100
216765973	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X2B040U3PSB	15,500	\$2,170
216765969	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X2B040D3PSB	15,100	\$2,114
216765975	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X1B080D4PSB	15,100	\$2,114
216765999	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X1B060U4PSB	15,400	\$2,156
216765977	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X1B060D3PSB	15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216765985	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X1B040U3PSB	15,500	\$2,170
216765979	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9X1B040D3PSB	15,100	\$2,114
216763551	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B080U4VSB	15,500	\$2,170
216763549	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B080U4PSC	15,500	\$2,170
216763555	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B080D4VSB	15,200	\$2,128
216763557	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B080D4PSC	15,200	\$2,128
216765987	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B060U4VSB	15,500	\$2,170
216763547	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B060U4PSC	15,500	\$2,170
216763545	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B060U3VSB	15,500	\$2,170
216763559	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B060D3VSB	14,900	\$2,086
216763561	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B060D3PSC	14,900	\$2,086
216763543	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B040U3VSB	15,500	\$2,170
216763541	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B040U3PSC	15,500	\$2,170
216765981	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B040D3VSB	15,200	\$2,128
216763563	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S9V2B040D3PSC	15,200	\$2,128
216765983	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S8V2B080M4PDB	15,500	\$2,170
216765989	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S8V2B080M4PCB	15,500	\$2,170
216765961	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S8V2B060M4PDB	15,400	\$2,156
216765991	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S8V2B060M4PCB	15,400	\$2,156
216765963	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S8V2A040M3PDB	15,500	\$2,170
216765993	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	S8V2A040M3PCB	15,500	\$2,170
216763539	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	L8V1B080U4VSB	15,400	\$2,156
216763537	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	L8V1A060U3VSB	15,500	\$2,170
216763535	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	L8V1A040U3VSB	15,500	\$2,170
216763531	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	*UHMB080CCV3	15,400	\$2,156
216763529	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	*UHMB060CCV3	15,400	\$2,156
216763533	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	*DHMB080CCV3	15,100	\$2,114
216763553	AMERICAN STANDARD	5A6H7024A1	5TXCB006AS3	*DHMB060CCV3	15,100	\$2,114
216765931	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X2B080D4PSB	15,000	\$2,100
216765937	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X2B060U4PSB	15,300	\$2,142
216765933	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X2B060D3PSB	15,100	\$2,114
216765939	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X2B040U3PSB	15,300	\$2,142
216765935	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X2B040D3PSB	15,000	\$2,100
216765927	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X1B080D4PSB	15,000	\$2,100
216765945	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X1B060U4PSB	15,300	\$2,142
216765929	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X1B060D3PSB	15,100	\$2,114
216765955	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X1B040U3PSB	15,300	\$2,142
216765941	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9X1B040D3PSB	15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763485	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B080U4VSB	15,300	\$2,142
216763483	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B080U4PSC	15,300	\$2,142
216763515	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B080D4VSB	15,000	\$2,100
216763517	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B080D4PSC	15,000	\$2,100
216765951	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B060U4VSB	15,300	\$2,142
216763481	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B060U4PSC	15,300	\$2,142
216763489	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B060U3VSB	15,300	\$2,142
216763519	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B060D3VSB	15,100	\$2,114
216763521	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B060D3PSC	15,200	\$2,128
216763491	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B040U3VSB	15,300	\$2,142
216763493	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B040U3PSC	15,400	\$2,156
216765943	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B040D3VSB	15,100	\$2,114
216763523	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S9V2B040D3PSC	15,100	\$2,114
216764570	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X2B080M4PTC	15,100	\$2,114
216764568	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X2B080M4PSC	15,100	\$2,114
216764578	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X2B060M4PTC	15,200	\$2,128
216764574	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X2B060M4PSC	15,200	\$2,128
216764572	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X2A040M3PTC	15,300	\$2,142
216764576	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X2A040M3PSC	15,300	\$2,142
216764560	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X1B080M4PTC	15,100	\$2,114
216763495	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X1B080M4PSC	15,100	\$2,114
216764562	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X1B060M4PTC	15,200	\$2,128
216763497	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X1B060M4PSC	15,200	\$2,128
216764564	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X1B040M2PTC	15,200	\$2,128
216763499	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X1B040M2PSC	15,200	\$2,128
216764566	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X1A040M3PTC	15,300	\$2,142
216763501	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8X1A040M3PSC	15,300	\$2,142
216765953	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8V2B080M4PDB	15,300	\$2,142
216765949	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8V2B080M4PCB	15,300	\$2,142
216765921	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8V2B060M4PDB	15,400	\$2,156
216765947	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8V2B060M4PCB	15,400	\$2,156
216765923	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8V2A040M3PDB	15,400	\$2,156
216765957	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	S8V2A040M3PCB	15,400	\$2,156
216763503	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	L9X1B070U4VSA	15,200	\$2,128
216763505	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	L9X1A050U3VSA	15,700	\$2,198
216763507	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	L8V1B080U4VSB	15,400	\$2,156
216763509	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	L8V1A060U3VSB	15,400	\$2,156
216763513	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	L8V1A040U3VSB	15,400	\$2,156

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763511	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	*UHMB080CCV3	15,300	\$2,142
216763527	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	*UHMB060CCV3	15,300	\$2,142
216763525	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	*DHMB080CCV3	15,100	\$2,114
216763487	AMERICAN STANDARD	5A6H7024A1	5TXCB004AS3	*DHMB060CCV3	15,200	\$2,128
216763479	AMERICAN STANDARD	5A6H7024A1	5TEMCD05AV41+TD	N/A	15,200	\$2,128
216763477	AMERICAN STANDARD	5A6H7024A1	5TEMCD04AV31+TD	N/A	15,200	\$2,128
216763475	AMERICAN STANDARD	5A6H7024A1	5TEMCB03AV31+TD	N/A	15,500	\$2,170
216763473	AMERICAN STANDARD	5A6H7024A1	5TEMCB02AV21+TD	N/A	15,600	\$2,184
216763471	AMERICAN STANDARD	5A6H7024A1	5TEM6D05AV41+TD	N/A	15,400	\$2,156
216763469	AMERICAN STANDARD	5A6H7024A1	5TEM6D04AV31+TD	N/A	15,400	\$2,156
216763467	AMERICAN STANDARD	5A6H7024A1	5TEM6B03AV21+TD	N/A	15,600	\$2,184
216763465	AMERICAN STANDARD	5A6H7024A1	5TEM6B02AV21+TD	N/A	15,600	\$2,184
216763463	AMERICAN STANDARD	5A6H7024A1	5TAMXD05AV41	N/A	15,200	\$2,128
216763461	AMERICAN STANDARD	5A6H7024A1	5TAMXD04AV31	N/A	15,300	\$2,142
216763459	AMERICAN STANDARD	5A6H7024A1	5TAMXC03AV31	N/A	15,300	\$2,142
216769887	AMERICAN STANDARD	5A6H7024A1	5TAM5C04AC31	N/A	15,200	\$2,128
216763457	AMERICAN STANDARD	5A6H7024A1	5TAM5C03AC21	N/A	15,100	\$2,114
216769885	AMERICAN STANDARD	5A6H7024A1	5PX*CD09AS3	*DHMC100CCV4	15,100	\$2,114
216769883	AMERICAN STANDARD	5A6H7024A1	5PX*CD07AS3	*DHMC100CCV4	15,300	\$2,142
216763455	AMERICAN STANDARD	5A6H7024A1	5PX*CD05AS3	N/A	15,800	\$2,212
216769881	AMERICAN STANDARD	5A6H7024A1	5PX*C009AS3	*UHMC100CCV4	15,100	\$2,114
216763453	AMERICAN STANDARD	5A6H7024A1	5PX*C009AS3	*DHMC100CCV4	14,800	\$2,072
216769879	AMERICAN STANDARD	5A6H7024A1	5PX*C007AS3	*UHMC100CCV4	15,200	\$2,128
216763451	AMERICAN STANDARD	5A6H7024A1	5PX*C007AS3	*DHMC100CCV4	15,200	\$2,128
216763447	AMERICAN STANDARD	5A6H7024A1	5PX*C005AS3	N/A	15,800	\$2,212
216769877	AMERICAN STANDARD	5A6H7024A1	5PX*C005AS3	*UHMC100CCV4	15,000	\$2,100
216763449	AMERICAN STANDARD	5A6H7024A1	5PX*C005AS3	*DHMC100CCV4	15,100	\$2,114
216765901	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9X2B080D4PSB	15,400	\$2,156
216765893	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9X2B060D3PSB	15,500	\$2,170
216765891	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9X2B040D3PSB	15,400	\$2,156
216765897	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9X1B080D4PSB	15,400	\$2,156
216765899	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9X1B060D3PSB	15,500	\$2,170
216765915	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9X1B040D3PSB	15,400	\$2,156
216763441	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9V2B080D4VSB	15,500	\$2,170
216763445	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9V2B080D4PSC	15,500	\$2,170
216763433	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9V2B060D3VSB	15,500	\$2,170
216763439	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9V2B060D3PSC	15,500	\$2,170
216765903	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9V2B040D3VSB	15,500	\$2,170

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763437	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S9V2B040D3PSC	15,400	\$2,156
216765889	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S8V2B080M4PDB	15,500	\$2,170
216765905	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S8V2B080M4PCB	15,500	\$2,170
216765887	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S8V2B060M4PDB	15,500	\$2,170
216765907	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S8V2B060M4PCB	15,500	\$2,170
216765895	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S8V2A040M3PDB	15,600	\$2,184
216765909	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	S8V2A040M3PCB	15,600	\$2,184
216763435	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	*DHMB080CCV3	15,500	\$2,170
216763443	AMERICAN STANDARD	5A6H7024A1	5PX*BD06AS3	*DHMB060CCV3	15,600	\$2,184
216765871	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S9X2B060D3PSB	15,400	\$2,156
216765873	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S9X1B060D3PSB	15,400	\$2,156
216763423	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S9V2B080D4VSB	15,300	\$2,142
216763425	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S9V2B080D4PSC	15,300	\$2,142
216765885	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S9V2B040D3VSB	15,400	\$2,156
216763427	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S9V2B040D3PSC	15,400	\$2,156
216765879	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S8V2B080M4PDB	15,300	\$2,142
216765877	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S8V2B080M4PCB	15,300	\$2,142
216765881	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S8V2B060M4PDB	15,400	\$2,156
216765875	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S8V2B060M4PCB	15,400	\$2,156
216765883	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S8V2A040M3PDB	15,400	\$2,156
216765867	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	S8V2A040M3PCB	15,400	\$2,156
216763431	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	N/A	15,800	\$2,212
216763429	AMERICAN STANDARD	5A6H7024A1	5PX*BD04AS3	*DHMB060CCV3	15,400	\$2,156
216765847	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X2B080D4PSB	15,100	\$2,114
216765841	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X2B060U4PSB	15,400	\$2,156
216765845	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X2B060D3PSB	15,200	\$2,128
216765839	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X2B040U3PSB	15,500	\$2,170
216765843	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X2B040D3PSB	15,100	\$2,114
216765831	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X1B080D4PSB	15,100	\$2,114
216765863	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X1B060U4PSB	15,400	\$2,156
216765829	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X1B060D3PSB	15,200	\$2,128
216765861	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X1B040U3PSB	15,500	\$2,170
216765827	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9X1B040D3PSB	15,100	\$2,114
216763399	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B080U4VSB	15,500	\$2,170
216763397	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B080U4PSC	15,500	\$2,170
216763417	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B080D4VSB	15,200	\$2,128
216763419	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B080D4PSC	15,200	\$2,128
216765859	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B060U4VSB	15,500	\$2,170

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763395	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B060U4PSC	15,500	\$2,170
216763393	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B060U3VSB	15,500	\$2,170
216763389	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B060D3VSB	15,300	\$2,142
216763421	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B060D3PSC	15,300	\$2,142
216763391	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B040U3VSB	15,500	\$2,170
216763413	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B040U3PSC	15,500	\$2,170
216765865	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B040D3VSB	15,200	\$2,128
216763387	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S9V2B040D3PSC	15,200	\$2,128
216765837	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S8V2B080M4PDB	15,500	\$2,170
216765857	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S8V2B080M4PCB	15,500	\$2,170
216765835	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S8V2B060M4PDB	15,500	\$2,170
216765855	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S8V2B060M4PCB	15,500	\$2,170
216765833	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S8V2A040M3PDB	15,600	\$2,184
216765853	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	S8V2A040M3PCB	15,600	\$2,184
216763411	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	L8V1B080U4VSB	15,400	\$2,156
216763409	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	L8V1A060U3VSB	15,500	\$2,170
216763415	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	L8V1A040U3VSB	15,500	\$2,170
216763407	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	*UHMB080CCV3	15,400	\$2,156
216763405	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	*UHMB060CCV3	15,400	\$2,156
216763403	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	*DHMB080CCV3	15,300	\$2,142
216763401	AMERICAN STANDARD	5A6H7024A1	5PX*B006AS3	*DHMB060CCV3	15,200	\$2,128
216765815	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X2B080D4PSB	15,000	\$2,100
216765809	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X2B060U4PSB	15,300	\$2,142
216765813	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X2B060D3PSB	15,100	\$2,114
216765807	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X2B040U3PSB	15,300	\$2,142
216765811	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X2B040D3PSB	15,000	\$2,100
216765789	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X1B080D4PSB	15,000	\$2,100
216765817	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X1B060U4PSB	15,300	\$2,142
216765823	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X1B060D3PSB	15,100	\$2,114
216765787	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X1B040U3PSB	15,300	\$2,142
216765821	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9X1B040D3PSB	15,000	\$2,100
216763365	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B080U4VSB	15,300	\$2,142
216763363	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B080U4PSC	15,300	\$2,142
216763381	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B080D4VSB	15,000	\$2,100
216763377	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B080D4PSC	15,000	\$2,100
216765825	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B060U4VSB	15,400	\$2,156
216763361	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B060U4PSC	15,300	\$2,142
216763359	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B060U3VSB	15,300	\$2,142

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763375	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B060D3VSB	15,100	\$2,114
216763373	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B060D3PSC	15,100	\$2,114
216763357	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B040U3VSB	15,300	\$2,142
216763355	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B040U3PSC	15,400	\$2,156
216765819	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B040D3VSB	15,000	\$2,100
216763371	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S9V2B040D3PSC	15,000	\$2,100
216764542	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X2B080M4PTC	15,100	\$2,114
216764540	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X2B080M4PSC	15,100	\$2,114
216764544	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X2B060M4PTC	15,200	\$2,128
216764556	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X2B060M4PSC	15,200	\$2,128
216764546	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X2A040M3PTC	15,300	\$2,142
216764548	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X2A040M3PSC	15,300	\$2,142
216764558	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X1B080M4PTC	15,100	\$2,114
216763353	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X1B080M4PSC	15,100	\$2,114
216764550	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X1B060M4PTC	15,200	\$2,128
216763351	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X1B060M4PSC	15,200	\$2,128
216764552	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X1B040M2PTC	15,200	\$2,128
216763349	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X1B040M2PSC	15,200	\$2,128
216764554	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X1A040M3PTC	15,300	\$2,142
216763347	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8X1A040M3PSC	15,300	\$2,142
216765803	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8V2B080M4PDB	15,300	\$2,142
216765793	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8V2B080M4PCB	15,300	\$2,142
216765801	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8V2B060M4PDB	15,400	\$2,156
216765791	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8V2B060M4PCB	15,400	\$2,156
216765805	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8V2A040M3PDB	15,400	\$2,156
216765797	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	S8V2A040M3PCB	15,400	\$2,156
216763383	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	N/A	15,800	\$2,212
216763345	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	L9X1B070U4VSA	15,200	\$2,128
216763343	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	L9X1A050U3VSA	15,700	\$2,198
216763341	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	L8V1B080U4VSB	15,500	\$2,170
216763339	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	L8V1A060U3VSB	15,400	\$2,156
216763337	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	L8V1A040U3VSB	15,400	\$2,156
216763385	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	*UHMB080CCV3	15,300	\$2,142
216763379	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	*UHMB060CCV3	15,300	\$2,142
216763369	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	*DHMB080CCV3	15,100	\$2,114
216763367	AMERICAN STANDARD	5A6H7024A1	5PX*B004AS3	*DHMB060CCV3	15,200	\$2,128
216772260	AMERICAN STANDARD	5HCL5036A1	5TEM5B04AC31		31,200	\$4,368
9150128	AMERICAN STANDARD	4TXK3824A10NU**	4MXW3824A10NU**		20,000	\$2,800

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9150126	AMERICAN STANDARD	4TXK3818A10NU**	4MXW3818A10NU**		15,100	\$2,114
9150124	AMERICAN STANDARD	4TXK3812A10NU**	4MXW3812A10NU**		10,300	\$1,442
214056975	AMERICAN STANDARD	4TXD2036A10NU**	D(A,C,E)36B34+TDR		15,000	\$2,100
214056974	AMERICAN STANDARD	4TXD2036A10NU**	D(A,C,E)24A44+TDR		14,900	\$2,086
202703127	AMERICAN STANDARD	4TXK2324A10N0**	4MXW2324A10N0**	N/A	14,600	\$2,044
212361357	AMERICAN STANDARD	4TXD2036A10NU**	4RXCB024AS3HC**		16,800	\$2,352
204340535	AMERICAN STANDARD	4TXM2318A12NU**	Heat pump without ducts	N/A	17,000	\$2,380
204340537	AMERICAN STANDARD	4TXM2324A13NU**	Heat pump without ducts	N/A	17,900	\$2,506
210435423	AMERICAN STANDARD	4TXM2136A14N0**	Heat pump without ducts		30,800	\$4,312
210435424	AMERICAN STANDARD	4TXM2142A15N0**	Heat pump without ducts		35,600	\$4,984
208141275	AMERICAN STANDARD	4TXD2060A10NU**	4MXA2060A10NU**	N/A	36,000	\$5,040
208141273	AMERICAN STANDARD	4TXD2036A10NU**	4MXA2036A10NU**	N/A	24,000	\$3,360
208141274	AMERICAN STANDARD	4TXD2060A10NU**	4MXA2048A10NU**	N/A	32,000	\$4,480
208141276	AMERICAN STANDARD	4TXD2036A10NU**	4MXA2024A10NU**	N/A	16,300	\$2,282
211749861	AMERISTAR	E4HL5048A1000A	E4AH5E48A1K30A		38,000	\$5,320
212617026	AMERISTAR	E4HL5042A1000A	E4AH5E36A1J30A		30,000	\$4,200
211749860	AMERISTAR	E4HL5042A1000A	E4AH5E48A1K30A		33,000	\$4,620
213894047	AMERISTAR	E4HL5030A1000A	A4AH5V30A1B3 + DF		18,000	\$2,520
212617025	AMERISTAR	E4HL5048A1000A	E4AH5E36A1J30A		30,000	\$4,200
212510759	AMERISTAR	E4HL5018A1000A	4TXCB003DS3	A801X040BM2SCA	20,000	\$2,800
212510760	AMERISTAR	E4HL5018A1000A	4TXCB003DS3	A951X040BU3SAB	20,000	\$2,800
212510761	AMERISTAR	E4HL5018A1000A	4TXCB003DS3	A952V040BU3SAD	20,000	\$2,800
212510762	AMERISTAR	E4HL5024A1000A	4TXCB003DS3	A801X060BM4SCA	20,000	\$2,800
212510766	AMERISTAR	E4HL5024A1000A	4TXCB003DS3	A951X040BU3SAB	20,000	\$2,800
212510763	AMERISTAR	E4HL5024A1000A	4TXCB003DS3	A951X060BU4SAB	20,000	\$2,800
212510764	AMERISTAR	E4HL5024A1000A	4TXCB003DS3	A952V060BU4SAD	20,000	\$2,800
212510765	AMERISTAR	E4HL5024A1000A	4TXCB003DS3	A952V040BU3SAD	20,000	\$2,800
211749857	AMERISTAR	E4HL5024A1000A	E4AH5E24A1J30A		19,100	\$2,674
211749856	AMERISTAR	E4HL5018A1000A	E4AH5E24A1J30A		15,000	\$2,100
212394376	AMERISTAR	E4HL5024A1000A	4TXCB004DS3		20,000	\$2,800
212394377	AMERISTAR	E4HL5024A1000A	4TXCB003DS3		20,000	\$2,800
212400613	AMERISTAR	E4HL5018A1000A	4TXCB003DS3		20,000	\$2,800
203162806	AMERISTAR	M4THS1824A11N**	M4MHW1824A1N0**		14,600	\$2,044
210488262	AMERISTAR	M4THM1936A14N**	Heat pump without ducts		30,800	\$4,312
210488263	AMERISTAR	M4THM1942A15N**	Heat pump without ducts		35,600	\$4,984
213894046	AMERISTAR	E4HL5024A1000A	A4AH5V36A1C3 + DF		19,100	\$2,674
213894045	AMERISTAR	E4HL5018A1000A	A4AH5V24A1B3 + DF		14,000	\$1,960

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215935658	ARCOAIRE	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0902120B*	32,000	\$4,480
215939998	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN1002122A*	30,600	\$4,284
215934368	ARCOAIRE	H5H3V48*K*AAA*	EA*5X61M24A*+WALLCON	*97CMN0602120B*	40,500	\$5,670
215676327	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL1352422B*	46,000	\$6,440
215933228	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*96CTN0401410B*	30,000	\$4,200
215682287	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*97CTN1202422A*	46,000	\$6,440
215682817	ARCOAIRE	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*80CSU0601716B*	54,000	\$7,560
215682277	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*97CTN1002122A*	46,000	\$6,440
215935648	ARCOAIRE	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0901716B*	32,200	\$4,508
215939988	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN0802120A*	30,800	\$4,312
215676317	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL1102120B*	46,000	\$6,440
215674128	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN1002122B*	42,500	\$5,950
215933218	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN1202422B*	30,600	\$4,284
215939978	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN0801716A*	31,000	\$4,340
215676307	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL0902120B*	46,000	\$6,440
215935638	ARCOAIRE	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0702120B*	32,200	\$4,508
215682807	ARCOAIRE	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*80CSU0401712B*	54,000	\$7,560
215682267	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*97CTN0802120A*	46,000	\$6,440
215933208	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN1002122B*	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215682797	ARCOAIRE	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*96CTN0802120B*	56,000	\$7,840
215682257	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CSU1002120B*	46,000	\$6,440
215674118	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN0802120B*	42,500	\$5,950
215939968	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN0601716A*	31,400	\$4,396
215676297	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL0702120B*	46,500	\$6,510
215933198	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0802120B*	30,600	\$4,284
215935628	ARCOAIRE	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0701716B*	32,400	\$4,536
215939958	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*80CSU0601716B*	30,600	\$4,284
215676277	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*96CTN1202422B*	45,500	\$6,370
215674108	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN0801714B*	43,000	\$6,020
215682247	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CSU0802120B*	46,000	\$6,440
215933188	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0801714B*	31,200	\$4,368
215935618	ARCOAIRE	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0451712B*	33,000	\$4,620
215682777	ARCOAIRE	H5H0V60*K*AAA*	ESH5X60M12A*+WALLCON	*97CTN1002122A*	51,500	\$7,210
215939948	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*80CSU0401712B*	30,600	\$4,284
215676267	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CMN1202422B*	45,500	\$6,370
215682237	ARCOAIRE	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*96CTN0802120B*	46,000	\$6,440
215674098	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN0602120B*	43,000	\$6,020
215935578	ARCOAIRE	H5H3V36*K*AAA*	EVD5X36M17A*+WALLCON	*96CTN0601714B*	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215939938	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*96CTN0802120B*	30,800	\$4,312
215933178	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0602120B*	31,000	\$4,340
215676257	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CMN0802120B*	45,500	\$6,370
215674088	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*95CSU0802120B*	42,500	\$5,950
215935568	ARCOAIRE	H5H3V36*K*AAA*	EVD5X36M17A*+WALLCON	*97CMN0601714B*	30,600	\$4,284
215682767	ARCOAIRE	H5H0V60*K*AAA*	ESH5X60M12A*+WALLCON	*97CTN0802120A*	51,500	\$7,210
215934288	ARCOAIRE	H5H3V48*K*AAA*	EA*5X61M21A*+WALLCON	*96CTN1002122B*	40,000	\$5,600
215933168	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0601714B*	30,200	\$4,228
215682227	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CTN1202422A*	45,500	\$6,370
215939928	ARCOAIRE	H5H3V36*K*AAA*	EA*5X61M24A*+WALLCON	*97CTN1202422A*	29,800	\$4,172
215676247	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*95CSU1002122B*	45,500	\$6,370
215682217	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CTN1002122A*	45,500	\$6,370
215674078	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*95CSU0601716B*	43,000	\$6,020
215935558	ARCOAIRE	H5H3V36*K*AAA*	EVD5X31M17A*+WALLCON	*96CTN0601714B*	31,800	\$4,452
215676237	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*95CSU0802120B*	46,000	\$6,440
215933158	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*95CSU1002122B*	30,400	\$4,256
215674068	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL1102120B*	42,500	\$5,950
215935548	ARCOAIRE	H5H3V36*K*AAA*	EVD5X31M17A*+WALLCON	*97CMN0601714B*	31,800	\$4,452
215933148	ARCOAIRE	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*95CSU0802120B*	30,800	\$4,312

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215682207	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CTN0802120A*	46,000	\$6,440
215676227	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL1352422B*	45,500	\$6,370
215682737	ARCOAIRE	H5H0V60*K*AAA*	ESH5X60M12A*+WALLCON	*80CSU0601716B*	50,500	\$7,070
215682197	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CSU1002120B*	45,500	\$6,370
215676217	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL1102120B*	45,500	\$6,370
215674058	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0902120B*	42,500	\$5,950
215674048	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0901716B*	42,500	\$5,950
215676207	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL0902120B*	45,500	\$6,370
215674038	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0702120B*	42,500	\$5,950
215676197	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL0702120B*	46,000	\$6,440
215674028	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0701716B*	43,000	\$6,020
215676167	ARCOAIRE	H5H0V48*K*AAA*	EVD5X48M21A*+WALLCON	*96CTN1002122B*	45,500	\$6,370
215674018	ARCOAIRE	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0451712B*	43,500	\$6,090
215662867	ARCOAIRE	H5H0V48*K*AAA*	FCMA5B48L0C*+WALLCON		42,000	\$5,880
207614960	ARCOAIRE	DLCPRBH12AAK	DLFPHBH12XAK		10,400	\$1,456
207826644	ARCOAIRE	DLCPRBH18AAK	DLFPHBH18XAK		20,200	\$2,828
206361870	ARCOAIRE	DLCSR BH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361872	ARCOAIRE	DLCSR BH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361871	ARCOAIRE	DLCSR BH18AAK	DLFSHBH18XAK		11,100	\$1,554
210857427	ARCOAIRE	DLCSR BH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857428	ARCOAIRE	DLCSR BH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132681	ARCOAIRE	DLCSR BH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948191	ARCOAIRE	DLCSR BH12AAK	DLFSFBH12XAK		10,200	\$1,428
207683327	ARCOAIRE	DLCSR BH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447615	ARCOAIRE	DLCSR BH24AAK	DLFSCH24XAK		21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208447619	ARCOAIRE	DLCSRBH18AAK	DLFSHCH18XAK		15,000	\$2,100
208447614	ARCOAIRE	DLCSRBH12AAK	DLFSHCH12XAK		10,000	\$1,400
206773906	ARCOAIRE	HVH848GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	36,000	\$5,040
206773942	ARCOAIRE	HVH848GKA2*	EA*4X60L24A*+WALLCON	*97CMN1002122A*	36,000	\$5,040
206773969	ARCOAIRE	HVH848GKA2*	EA*4X60L24A*+WALLCON	*96CTN1002122A*	36,000	\$5,040
206774904	ARCOAIRE	HVH848GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	36,000	\$5,040
206771760	ARCOAIRE	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0701716A*	31,600	\$4,424
211132712	ARCOAIRE	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
211132679	ARCOAIRE	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
206771904	ARCOAIRE	HVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	31,400	\$4,396
206767554	ARCOAIRE	HVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
206767545	ARCOAIRE	HVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
206765549	ARCOAIRE	HVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
206765558	ARCOAIRE	HVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
206773530	ARCOAIRE	HVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206771256	ARCOAIRE	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206771355	ARCOAIRE	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206771625	ARCOAIRE	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206773422	ARCOAIRE	HVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206773521	ARCOAIRE	HVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206774284	ARCOAIRE	HVH848GKA2*	EN(A,D)4X48L24**+WALLCON	*96CTN1202422A*	37,200	\$5,208
206771274	ARCOAIRE	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206773476	ARCOAIRE	HVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206773485	ARCOAIRE	HVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	31,600	\$4,424
206773431	ARCOAIRE	HVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	31,800	\$4,452
206774482	ARCOAIRE	HVH848GKA2*	EHD4X48AAL+WALLCON	*80CTL1352422A*	37,200	\$5,208
206766035	ARCOAIRE	HVH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
206771778	ARCOAIRE	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206774823	ARCOAIRE	HVH848GKA2*	EHD4X48AAL+WALLCON	*80CSU0802120A*	37,200	\$5,208
206771643	ARCOAIRE	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206773503	ARCOAIRE	HVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206773512	ARCOAIRE	HVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206771859	ARCOAIRE	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	31,400	\$4,396
206771895	ARCOAIRE	HVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
215324117	ARCOAIRE	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215324124	ARCOAIRE	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324122	ARCOAIRE	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215324120	ARCOAIRE	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324119	ARCOAIRE	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324118	ARCOAIRE	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324115	ARCOAIRE	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324114	ARCOAIRE	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324113	ARCOAIRE	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324112	ARCOAIRE	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215324111	ARCOAIRE	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215323725	ARCOAIRE	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215324126	ARCOAIRE	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324125	ARCOAIRE	D5CSHAH24AAK	D5FSCAH24XAK		20,400	\$2,856
215324121	ARCOAIRE	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324128	ARCOAIRE	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324127	ARCOAIRE	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215413214	ARCOAIRE	D5CPRAH18AA	D5FPHAH18XAK		19,300	\$2,702
215413213	ARCOAIRE	D5CPRAH12AAK	D5FPHAH12XAK		11,000	\$1,540
215357145	ARCOAIRE	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357143	ARCOAIRE	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357141	ARCOAIRE	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215357185	ARCOAIRE	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357162	ARCOAIRE	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357160	ARCOAIRE	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357158	ARCOAIRE	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357156	ARCOAIRE	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357154	ARCOAIRE	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357152	ARCOAIRE	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357150	ARCOAIRE	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357149	ARCOAIRE	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357147	ARCOAIRE	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357139	ARCOAIRE	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357138	ARCOAIRE	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357136	ARCOAIRE	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357129	ARCOAIRE	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357127	ARCOAIRE	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357125	ARCOAIRE	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324165	ARCOAIRE	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324163	ARCOAIRE	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324162	ARCOAIRE	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324160	ARCOAIRE	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324159	ARCOAIRE	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324166	ARCOAIRE	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324164	ARCOAIRE	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324161	ARCOAIRE	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324123	ARCOAIRE	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324116	ARCOAIRE	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215318903	ARCOAIRE	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215318902	ARCOAIRE	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215318901	ARCOAIRE	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215318911	ARCOAIRE	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215318909	ARCOAIRE	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215318899	ARCOAIRE	D5CURAH48AAK	D5FUAH48XAK		32,400	\$4,536
215318896	ARCOAIRE	D5CURAH24AAK	D5FUAH24XAK		20,000	\$2,800
215318894	ARCOAIRE	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215318893	ARCOAIRE	D5CUHAH60AAK	D5FUAH60XAK		45,000	\$6,300
215318892	ARCOAIRE	D5CUHAH48AAK	D5FUAH48XAK		37,000	\$5,180
215318891	ARCOAIRE	D5CUHAH36AAK	D5FUAH36XAK		31,800	\$4,452
215318890	ARCOAIRE	D5CUHAH30AAK	D5FUAH30XAK		23,800	\$3,332
215318889	ARCOAIRE	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215318888	ARCOAIRE	D5CUHAH24AAK	D5FUAH24XAK		20,000	\$2,800
215318887	ARCOAIRE	D5CUHAH18AAK	D5FUAH18XAK		15,000	\$2,100
215318910	ARCOAIRE	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215318906	ARCOAIRE	D5CSHAH33AAK	D5FSAH36XBK		27,400	\$3,836
215318905	ARCOAIRE	D5CSHAH24AAK	D5FSAH24XBK		16,900	\$2,366
215318904	ARCOAIRE	D5CSHAH18AAK	D5FSAH18XBK		14,000	\$1,960
212982400	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80MSU0401712A*	12,200	\$1,708
212982940	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MSU0802120A*	23,200	\$3,248
212982628	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MSU0601716A*	23,200	\$3,248
212982376	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80MSU0401712A*	12,200	\$1,708
212982388	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80MSU0401712A*	12,400	\$1,736
213078881	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MSU1002120A*	29,200	\$4,088
212982436	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU0401712A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982712	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80MSU0601716A*	18,600	\$2,604
212982700	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MSU0601716A*	19,000	\$2,660
213079181	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0601716A*	29,200	\$4,088
212982364	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0401712A*	19,100	\$2,674
213079325	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0802120A*	29,200	\$4,088
212982724	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0601716A*	19,000	\$2,660
212982640	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80MSU0601716A*	23,400	\$3,276
212982412	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80MSU0401712A*	12,300	\$1,722
212982340	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU0401712A*	19,100	\$2,674
212982328	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU0401712A*	19,400	\$2,716
213078857	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MSU1002120A*	29,200	\$4,088
212983000	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	23,600	\$3,304
212982172	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MSU0401712A*	23,200	\$3,248
213079061	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0401712A*	29,400	\$4,116
212981680	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	23,600	\$3,304
212981620	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MSU1002120A*	23,200	\$3,248
212988051	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*96MSN1002120A*	23,600	\$3,304
212982220	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80MSU0401712A*	23,400	\$3,276
212982304	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80MSU0401712A*	18,800	\$2,632
212982268	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80MSU0401712A*	19,100	\$2,674
213079313	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0802120A*	29,200	\$4,088
212982136	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80MSU0401712A*	23,400	\$3,276
213078905	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU1002120A*	29,600	\$4,144
212988099	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	23,600	\$3,304
213079277	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MSU0802120A*	29,000	\$4,060
213079049	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80MSU0401712A*	29,200	\$4,088
213078989	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MSU0401712A*	29,000	\$4,060
212982664	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MSU0601716A*	23,200	\$3,248
212982352	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU0401712A*	19,100	\$2,674
212982244	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80MSU0401712A*	19,400	\$2,716
213079145	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MSU0601716A*	29,000	\$4,060
212981596	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MSU1002120A*	23,200	\$3,248
213078929	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	29,400	\$4,116
212988063	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96MSN1002120A*	23,600	\$3,304
213079013	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MSU0401712A*	29,000	\$4,060
212982688	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	23,400	\$3,276
213078953	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80MSU0401712A*	29,400	\$4,116
212988039	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96MSN1002120A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982424	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU0401712A*	12,400	\$1,736
212982292	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MSU0401712A*	19,100	\$2,674
212982280	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80MSU0401712A*	19,000	\$2,660
212981536	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MSU1002120A*	29,000	\$4,060
212981608	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80MSU1002120A*	23,600	\$3,304
209852043	ARCOAIRE	DLCURAH36ABK	DLFUAH36XAK		30,400	\$4,256
213079253	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MSU0802120A*	29,000	\$4,060
213079241	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MSU0802120A*	29,400	\$4,116
213079217	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MSU0802120A*	29,000	\$4,060
213079169	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	29,400	\$4,116
212982316	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80MSU0401712A*	18,700	\$2,618
213079301	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	29,400	\$4,116
213079229	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MSU0802120A*	29,400	\$4,116
213079109	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MSU0601716A*	29,200	\$4,088
213079097	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MSU0601716A*	29,000	\$4,060
213079085	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MSU0601716A*	29,400	\$4,116
212982148	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MSU0401712A*	23,200	\$3,248
212982976	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MSU0802120A*	23,200	\$3,248
213079205	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MSU0802120A*	29,400	\$4,116
212982160	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80MSU0401712A*	23,400	\$3,276
212982256	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80MSU0401712A*	18,600	\$2,604
213080450	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002122A*	29,200	\$4,088
213080378	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002122A*	29,400	\$4,116
212988015	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002120A*	29,000	\$4,060
213079001	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MSU0401712A*	29,400	\$4,116
210470522	ARCOAIRE	HVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470500	ARCOAIRE	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0901716A*	31,200	\$4,368
210470379	ARCOAIRE	HVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
213080396	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002122A*	29,400	\$4,116
213080343	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	29,400	\$4,116
213080319	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002120A*	29,200	\$4,088
213079265	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MSU0802120A*	29,000	\$4,060
212988227	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002122A*	29,000	\$4,060
212982088	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MSU0401712A*	28,800	\$4,032
213078965	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MSU0401712A*	29,400	\$4,116
210470269	ARCOAIRE	HVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	31,000	\$4,340
213080441	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002122A*	29,200	\$4,088
213080414	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002122A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080367	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002120A*	29,200	\$4,088
213080355	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002120A*	29,200	\$4,088
213080295	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002120A*	29,400	\$4,116
213079133	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MSU0601716A*	29,000	\$4,060
213078941	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU1002120A*	29,200	\$4,088
213078869	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MSU1002120A*	29,400	\$4,116
213080405	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002122A*	29,400	\$4,116
212988218	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002122A*	29,000	\$4,060
210470434	ARCOAIRE	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0701716A*	31,400	\$4,396
210470533	ARCOAIRE	HVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
213080432	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002122A*	29,400	\$4,116
213080387	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002122A*	29,200	\$4,088
213080307	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002120A*	29,400	\$4,116
213080283	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002120A*	29,200	\$4,088
213080271	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002120A*	29,400	\$4,116
213079073	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0401712A*	29,200	\$4,088
213078833	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MSU1002120A*	29,400	\$4,116
212988075	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96MSN1002120A*	23,200	\$3,248
212988003	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002120A*	29,000	\$4,060
213079157	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU0601716A*	29,600	\$4,144
212969729	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412B*	19,300	\$2,702
210473242	ARCOAIRE	HVH825GKA3*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210470566	ARCOAIRE	HVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL1352422A*	31,200	\$4,368
210470390	ARCOAIRE	HVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470236	ARCOAIRE	HVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	31,000	\$4,340
210473110	ARCOAIRE	HVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210470247	ARCOAIRE	HVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU1002122A*	31,000	\$4,340
210470555	ARCOAIRE	HVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470445	ARCOAIRE	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470280	ARCOAIRE	HVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL1352422A*	31,000	\$4,340
210473099	ARCOAIRE	HVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
213078977	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80MSU0401712A*	29,200	\$4,088
211712143	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ESU1002120A*	23,200	\$3,248
211712131	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*95ESU1002120A*	23,400	\$3,276
211712120	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80VSL0701716A*	23,400	\$3,276
211712109	ARCOAIRE	DLCURAH30ABK	EA*4X36L21A*	*80ESU1002120A*	23,600	\$3,304
211712097	ARCOAIRE	DLCURAH30ABK	EA*4X36L21A*	*95ESU1002120A*	23,600	\$3,304
211709687	ARCOAIRE	DLCURAH30ABK	FJMA4*30L*B*		23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213353858	ARCOAIRE	DLCURAH36ABK	F5MA4*42L*C*		29,200	\$4,088
213353848	ARCOAIRE	DLCURAH36ABK	F5MA4*36L*B*		29,400	\$4,116
213249338	ARCOAIRE	DLCURAH36ABK	FEVA0036***NAVA43601CK		29,400	\$4,116
213080876	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU0802120A*	29,200	\$4,088
213080864	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0802120A*	29,200	\$4,088
213080852	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	29,400	\$4,116
213080840	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*95MSU0802120A*	29,600	\$4,144
213080828	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95MSU0802120A*	29,200	\$4,088
213080816	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95MSU0802120A*	29,400	\$4,116
213080804	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95MSU0802120A*	29,400	\$4,116
213080792	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95MSU0802120A*	29,200	\$4,088
213080780	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95MSU0802120A*	29,400	\$4,116
213080768	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0601716A*	29,200	\$4,088
213080756	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	29,600	\$4,144
213080744	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*95MSU0601716A*	29,400	\$4,116
213080708	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95MSU0601716A*	29,200	\$4,088
213080696	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95MSU0601716A*	29,400	\$4,116
213080684	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95MSU0601716A*	29,200	\$4,088
213080672	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*95MSU0601716A*	29,400	\$4,116
213080660	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95MSU0601716A*	29,400	\$4,116
213080648	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*95MSU0601716A*	29,600	\$4,144
213080636	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0401712A*	29,400	\$4,116
213080624	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0401712A*	29,600	\$4,144
213080612	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*95MSU0401712A*	29,400	\$4,116
213080576	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95MSU0401712A*	29,200	\$4,088
213080564	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95MSU0401712A*	29,200	\$4,088
211274898	ARCOAIRE	DLCURAH30ABK	FVM4X48***L		23,000	\$3,220
213080552	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95MSU0401712A*	29,600	\$4,144
213080540	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95MSU0401712A*	29,200	\$4,088
213080528	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*95MSU0401712A*	29,400	\$4,116
213080516	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95MSU0401712A*	29,600	\$4,144
213080504	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*95MSU0401712A*	29,600	\$4,144
213080494	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1402422A*	29,200	\$4,088
213080484	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96MSN1402422A*	29,400	\$4,116
213080472	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1202422A*	29,200	\$4,088
213080460	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96MSN1202422A*	29,400	\$4,116
213080259	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN0802120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080247	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0802120A*	29,200	\$4,088
213080235	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0802120A*	29,400	\$4,116
211222780	ARCOAIRE	DLCURAH30ABK	FVM4X24***L		23,600	\$3,304
213080211	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96MSN0802120A*	29,000	\$4,060
213080199	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96MSN0802120A*	29,000	\$4,060
211222764	ARCOAIRE	DLCURAH30ABK	FMA4X36**AL*		23,800	\$3,332
213080187	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96MSN0802120A*	29,200	\$4,088
213080175	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96MSN0802120A*	29,400	\$4,116
211222756	ARCOAIRE	DLCURAH30ABK	FMA4X30**AL*		23,800	\$3,332
213080163	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96MSN0802120A*	29,400	\$4,116
213080151	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96MSN0802120A*	29,200	\$4,088
211222748	ARCOAIRE	DLCURAH30ABK	FM(C,U)4Z36**AL*		23,600	\$3,304
213080139	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96MSN0802120A*	29,600	\$4,144
213080127	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0801716A*	29,200	\$4,088
211222740	ARCOAIRE	DLCURAH30ABK	FM(C,U)4Z30**AL*		23,600	\$3,304
213080115	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	29,600	\$4,144
213080103	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*96MSN0801716A*	29,400	\$4,116
211222724	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	OMV098J12*	23,200	\$3,248
211222716	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	OLV098A12*	23,200	\$3,248
213080067	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96MSN0801716A*	29,000	\$4,060
213080055	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96MSN0801716A*	29,200	\$4,088
211222708	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122A*	23,000	\$3,220
213080043	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96MSN0801716A*	29,400	\$4,116
213080031	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96MSN0801716A*	29,200	\$4,088
211222700	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120A*	23,200	\$3,248
213080019	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96MSN0801716A*	29,400	\$4,116
213080007	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96MSN0801716A*	29,600	\$4,144
211222692	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120A*	23,000	\$3,220
213079995	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*96MSN0801716A*	29,600	\$4,144
213079985	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*96MSN0601412A*	29,600	\$4,144
213079965	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96MSN0601412A*	29,400	\$4,116
211222684	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VTN0601714A*	23,200	\$3,248
213079955	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*96MSN0601412A*	29,600	\$4,144
213079944	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1202420A*	29,200	\$4,088
211222676	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*95ESU0601716A*	23,400	\$3,276
213079933	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*92MSN1202420A*	29,000	\$4,060
211222668	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*95ESU0401712A*	23,200	\$3,248
213079922	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*92MSN1202420A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079912	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002122A*	29,200	\$4,088
211222660	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120A*	23,200	\$3,248
213079903	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002122A*	29,200	\$4,088
213079894	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002122A*	29,400	\$4,116
211222652	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120A*	23,000	\$3,220
213079876	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002122A*	29,000	\$4,060
211222644	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716A*	23,200	\$3,248
213079867	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002122A*	29,400	\$4,116
213079858	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002122A*	29,400	\$4,116
213079849	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002122A*	29,000	\$4,060
211222636	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0601714A*	23,200	\$3,248
213079840	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002122A*	29,400	\$4,116
213079829	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002120A*	29,200	\$4,088
211222628	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*95ESN0802120A*	23,200	\$3,248
213079817	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002120A*	29,200	\$4,088
213079805	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	29,400	\$4,116
211222620	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*95ESN0601714A*	23,200	\$3,248
213079793	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN1002120A*	29,600	\$4,144
213079781	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002120A*	29,000	\$4,060
211222612	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*92ESN1002120A*	23,200	\$3,248
213079769	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002120A*	29,400	\$4,116
213079757	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002120A*	29,400	\$4,116
211222604	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*92ESN0802120A*	23,200	\$3,248
213079745	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002120A*	29,000	\$4,060
211222596	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*92ESN0801716A*	23,400	\$3,276
213079733	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002120A*	29,400	\$4,116
213079723	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN0802120A*	29,200	\$4,088
211222588	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*92ESN0601714A*	23,400	\$3,276
213079713	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0802120A*	29,200	\$4,088
213079703	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	29,400	\$4,116
211222564	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122A*	23,200	\$3,248
213079693	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN0802120A*	29,600	\$4,144
213079683	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92MSN0802120A*	29,200	\$4,088
211222556	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120A*	23,200	\$3,248
213079673	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*92MSN0802120A*	29,400	\$4,116
213079663	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92MSN0802120A*	29,400	\$4,116
211222548	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716A*	23,200	\$3,248
213079653	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92MSN0802120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079643	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92MSN0802120A*	29,400	\$4,116
211222540	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ESU0802120A	23,400	\$3,276
213079631	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0801716A*	29,200	\$4,088
213079619	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0801716A*	29,400	\$4,116
211222532	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ESU0601716A	23,200	\$3,248
213079607	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*92MSN0801716A*	29,200	\$4,088
211222524	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ESU0401712A*	23,200	\$3,248
211222516	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VSL0902120A*	23,200	\$3,248
213079571	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92MSN0801716A*	29,000	\$4,060
213079559	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92MSN0801716A*	29,400	\$4,116
211222508	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VSL0702120A*	23,200	\$3,248
213079547	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92MSN0801716A*	29,000	\$4,060
213079535	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*92MSN0801716A*	29,400	\$4,116
211222500	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VSL0701716A*	23,200	\$3,248
213079523	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92MSN0801716A*	29,400	\$4,116
213079511	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*92MSN0801716A*	29,400	\$4,116
211222492	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VSL0451716A*	23,200	\$3,248
213079499	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0601714A*	29,200	\$4,088
213079487	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0601714A*	29,400	\$4,116
211222484	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	23,200	\$3,248
213079475	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*92MSN0601714A*	29,400	\$4,116
211222476	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
211222468	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
213079439	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92MSN0601714A*	29,200	\$4,088
213079427	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92MSN0601714A*	29,400	\$4,116
211222460	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
213079414	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92MSN0601714A*	29,200	\$4,088
213079401	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601714A*	29,400	\$4,116
211222452	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
213079389	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92MSN0601714A*	29,400	\$4,116
213079377	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601714A*	29,400	\$4,116
211222444	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
213079367	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*92MSN0601412A*	29,400	\$4,116
213079347	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601412A*	29,400	\$4,116
211222436	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
213079337	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601412A*	29,600	\$4,144
211222396	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	OMV098J12*	23,400	\$3,276
211222388	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*96VTN0601714A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211222380	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*95ESU0601716A*	23,400	\$3,276
211222372	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*95ESU0401712A*	23,400	\$3,276
211222364	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716A*	23,400	\$3,276
211222356	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*95ESN0601714A*	23,400	\$3,276
213079193	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0601716A*	29,200	\$4,088
211222348	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*92ESN0801716A*	23,400	\$3,276
211222340	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601714A*	23,400	\$3,276
211222332	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601412A*	23,400	\$3,276
213079121	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MSU0601716A*	29,200	\$4,088
211222324	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716A*	23,200	\$3,248
211222316	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412A*	23,400	\$3,276
211222308	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80ESU0601716A	23,400	\$3,276
211222300	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80ESU0401712A*	23,400	\$3,276
211222292	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451716A*	23,400	\$3,276
211222284	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412A*	23,400	\$3,276
211222276	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	23,200	\$3,248
211222268	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	23,400	\$3,276
213078917	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80MSU1002120A*	29,400	\$4,116
213078893	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	29,600	\$4,144
213078845	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80MSU1002120A*	29,400	\$4,116
213078821	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80MSU1002120A*	29,600	\$4,144
213078811	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1552420A*	29,200	\$4,088
211222260	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	23,400	\$3,276
213078801	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1552420A*	29,000	\$4,060
213078791	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	29,400	\$4,116
213078780	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1352420A*	29,200	\$4,088
213078769	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	29,400	\$4,116
213078759	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102420A*	29,200	\$4,088
213078749	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102420A*	29,000	\$4,060
213078739	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	29,400	\$4,116
213078727	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102120A*	29,200	\$4,088
213078715	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)1102120A*	29,200	\$4,088
213078703	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	29,400	\$4,116
213078679	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078667	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078655	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078643	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078631	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078619	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078607	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078597	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902420A*	29,200	\$4,088
213078588	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	29,400	\$4,116
213078578	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902120A*	29,200	\$4,088
213078567	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902120A*	29,200	\$4,088
213078556	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	29,400	\$4,116
211222147	ARCOAIRE	DLCURAH30ABK	EA*4X36L21A*	*92ESN1002120A*	23,400	\$3,276
211222136	ARCOAIRE	DLCURAH30ABK	EA*4X36L21A*	*92ESN0802120A*	23,400	\$3,276
213078534	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078523	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078512	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078501	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078490	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078479	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902116A*	29,200	\$4,088
211712502	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078468	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902116A*	29,200	\$4,088
213078457	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	29,400	\$4,116
213078435	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
211712489	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	23,400	\$3,276
213078424	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078413	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078402	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
211712476	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078391	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078379	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0901714A*	29,200	\$4,088
213078367	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0901714A*	29,400	\$4,116
211712463	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	23,400	\$3,276
213078355	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0901714A*	29,200	\$4,088
213078319	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
213078307	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078295	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
213078283	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
211221997	ARCOAIRE	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078271	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078259	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078249	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0702116A*	29,200	\$4,088
213078239	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0702116A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078229	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0702116A*	29,400	\$4,116
211712426	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122A*	23,400	\$3,276
213078209	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
213078199	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	29,400	\$4,116
211221980	ARCOAIRE	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078189	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078179	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
213078169	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078157	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701716A*	29,200	\$4,088
213078145	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	29,400	\$4,116
213078133	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701716A*	29,400	\$4,116
213078121	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	29,600	\$4,144
213078109	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	29,600	\$4,144
213078097	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078085	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078073	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078061	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078049	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078037	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	29,600	\$4,144
213078026	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701712A*	29,200	\$4,088
213078015	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	29,400	\$4,116
213078004	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701712A*	29,400	\$4,116
211712381	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716A*	23,400	\$3,276
213077971	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077960	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077949	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077938	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077927	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
211712369	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*95ESN1002120A*	23,600	\$3,304
213077916	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077904	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701412A*	29,400	\$4,116
213077880	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
213077868	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
211712539	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*92ESN0802120A*	23,400	\$3,276
213077856	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0451412A*	29,400	\$4,116
211712357	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*95ESN0802120A*	23,400	\$3,276
213077832	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	29,400	\$4,116
213077819	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077808	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422B*	29,200	\$4,088
213077796	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422B*	29,400	\$4,116
213077784	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122B*	29,200	\$4,088
213077774	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122B*	29,200	\$4,088
213077764	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	29,400	\$4,116
213077754	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN1002122B*	29,600	\$4,144
213077744	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122B*	29,000	\$4,060
213077734	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122B*	29,400	\$4,116
213077724	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122B*	29,400	\$4,116
213077714	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122B*	29,000	\$4,060
213077704	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122B*	29,400	\$4,116
213077693	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120B*	29,200	\$4,088
213077680	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120B*	29,200	\$4,088
213077667	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	29,400	\$4,116
211712331	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80ESU0401712A*	23,400	\$3,276
213077641	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120B*	29,000	\$4,060
213077628	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120B*	29,400	\$4,116
213077615	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120B*	29,400	\$4,116
213077602	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120B*	29,000	\$4,060
213077589	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120B*	29,400	\$4,116
213077577	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120B*	29,200	\$4,088
213077566	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120B*	29,200	\$4,088
211712319	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80ESU1002120A*	23,600	\$3,304
213077555	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	29,400	\$4,116
213077544	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN0802120B*	29,600	\$4,144
213077533	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120B*	29,000	\$4,060
211712551	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*92ESN1002120A*	23,400	\$3,276
213077522	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120B*	29,200	\$4,088
213077511	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120B*	29,400	\$4,116
213077500	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120B*	29,400	\$4,116
213077489	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120B*	29,200	\$4,088
213077478	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120B*	29,400	\$4,116
213077466	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0801716B*	29,200	\$4,088
213077453	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0801716B*	29,600	\$4,144
213077440	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*96VTN0801716B*	29,400	\$4,116
211712295	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*95ESU1002120A*	23,600	\$3,304
213077401	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VTN0801716B*	29,200	\$4,088
213077388	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077375	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VTN0801716B*	29,200	\$4,088
213077362	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96VTN0801716B*	29,400	\$4,116
213077349	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VTN0801716B*	29,400	\$4,116
213077336	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*96VTN0801716B*	29,600	\$4,144
213077324	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*96VTN0601412B*	29,400	\$4,116
211712274	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80VSL0702120A*	23,400	\$3,276
213077302	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601412B*	29,400	\$4,116
213077291	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601412B*	29,600	\$4,144
213077280	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0401712B*	29,400	\$4,116
211712563	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*95ESN0601714A*	23,600	\$3,304
213077269	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0401712B*	29,200	\$4,088
213077258	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422B*	29,200	\$4,088
213077248	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422B*	29,000	\$4,060
213077238	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422B*	29,400	\$4,116
213077228	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120B*	29,200	\$4,088
213077218	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120B*	29,200	\$4,088
213077208	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	29,400	\$4,116
213077188	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120B*	29,000	\$4,060
213077178	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120B*	29,000	\$4,060
213077168	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120B*	29,400	\$4,116
213077158	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120B*	29,400	\$4,116
213077148	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120B*	29,000	\$4,060
213077138	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120B*	29,400	\$4,116
213077128	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120B*	29,200	\$4,088
213077118	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120B*	29,200	\$4,088
213077108	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	29,400	\$4,116
213077098	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*96VSN0802120B*	29,600	\$4,144
213077088	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120B*	29,000	\$4,060
213077078	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120B*	29,200	\$4,088
213077068	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120B*	29,400	\$4,116
213077058	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120B*	29,400	\$4,116
213077048	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120B*	29,200	\$4,088
213077038	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120B*	29,400	\$4,116
211712232	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	23,600	\$3,304
213077028	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716B*	29,200	\$4,088
213077018	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716B*	29,600	\$4,144
213077008	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*96VSN0801716B*	29,400	\$4,116
213076978	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716B*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076968	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716B*	29,400	\$4,116
213076958	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716B*	29,200	\$4,088
213076948	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716B*	29,400	\$4,116
213076938	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716B*	29,400	\$4,116
213076928	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716B*	29,600	\$4,144
213076918	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*96VSN0601412B*	29,400	\$4,116
213076898	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412B*	29,400	\$4,116
213076888	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601412B*	29,600	\$4,144
211712209	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*96VSN0801716A*	23,400	\$3,276
213076878	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0401712B*	29,400	\$4,116
213076868	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0401712B*	29,200	\$4,088
213076851	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122B*	29,200	\$4,088
213076839	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122B*	29,200	\$4,088
213076827	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122B*	29,400	\$4,116
213076803	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122B*	29,000	\$4,060
213076791	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122B*	29,000	\$4,060
211712587	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80ESU0601716A	23,400	\$3,276
213076779	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122B*	29,200	\$4,088
213076767	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122B*	29,400	\$4,116
213076755	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122B*	29,400	\$4,116
213076743	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122B*	29,200	\$4,088
213076731	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122B*	29,400	\$4,116
213076720	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120B*	29,200	\$4,088
213076709	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120B*	29,200	\$4,088
213076698	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	29,400	\$4,116
213076687	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*80VTL0902120B*	29,600	\$4,144
213076676	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120B*	29,200	\$4,088
213076665	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120B*	29,400	\$4,116
213076654	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120B*	29,400	\$4,116
211712167	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
213076643	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120B*	29,200	\$4,088
213076632	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120B*	29,400	\$4,116
211712659	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80VSL0702120A*	23,400	\$3,276
213076577	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716B*	29,200	\$4,088
211712155	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*95ESN1002120A*	23,600	\$3,304
213076566	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	29,400	\$4,116
213076555	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80VTL0701716B*	29,400	\$4,116
213076522	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716B*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076511	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716B*	29,400	\$4,116
211712679	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902420A*	23,400	\$3,276
213076500	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716B*	29,000	\$4,060
213076489	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716B*	29,400	\$4,116
213076478	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716B*	29,400	\$4,116
213076467	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716B*	29,400	\$4,116
211712689	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80VSL1102422A*	23,400	\$3,276
213076447	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80VTL0451412B*	29,400	\$4,116
213076423	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412B*	29,200	\$4,088
213076411	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412B*	29,400	\$4,116
213076336	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002122A*	29,200	\$4,088
213076327	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002122A*	29,200	\$4,088
213076318	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002122A*	29,400	\$4,116
211712700	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*95ESU1002120A*	23,600	\$3,304
213076300	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002122A*	29,000	\$4,060
213076291	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002122A*	29,000	\$4,060
213076282	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002122A*	29,000	\$4,060
213076273	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002122A*	29,400	\$4,116
213076264	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002122A*	29,400	\$4,116
213076255	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002122A*	29,000	\$4,060
211712712	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80ESU1002120A*	23,600	\$3,304
213076246	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002122A*	29,400	\$4,116
213075998	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002120A*	29,200	\$4,088
213075986	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002120A*	29,200	\$4,088
213075974	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002120A*	29,400	\$4,116
213075950	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002120A*	29,000	\$4,060
213075938	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002120A*	29,000	\$4,060
213075926	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002120A*	29,000	\$4,060
213075914	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002120A*	29,400	\$4,116
213075902	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002120A*	29,400	\$4,116
213075890	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002120A*	29,000	\$4,060
213075878	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002120A*	29,400	\$4,116
212989505	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95MSU0802120A*	29,000	\$4,060
212989493	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95MSU0802120A*	29,000	\$4,060
211712738	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*95ESN0802120A*	23,400	\$3,276
212988977	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95MSU0601716A*	29,000	\$4,060
212988405	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96MSN1402422A*	29,000	\$4,060
212988321	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96MSN1202422A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712750	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*95ESN1002120A*	23,600	\$3,304
212985518	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002122A*	29,000	\$4,060
212985509	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002122A*	29,000	\$4,060
212985243	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002120A*	28,800	\$4,032
212985231	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002120A*	28,800	\$4,032
212984953	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*92MSN0802120A*	28,800	\$4,032
212984943	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92MSN0802120A*	28,800	\$4,032
212984413	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92MSN0801716A*	29,000	\$4,060
212983873	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92MSN0601714A*	29,000	\$4,060
212982604	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MSU0601716A*	28,800	\$4,032
212981210	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1352420A*	29,000	\$4,060
212980691	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902420A*	29,000	\$4,060
212980490	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980479	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980171	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902116A*	28,800	\$4,032
212980160	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902116A*	28,800	\$4,032
212979657	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
212979415	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0702116A*	28,800	\$4,032
212979405	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0702116A*	28,800	\$4,032
212978967	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701716A*	29,000	\$4,060
212978481	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
212977255	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422B*	29,000	\$4,060
212977091	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122B*	28,800	\$4,032
211712796	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122A*	23,400	\$3,276
212977081	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122B*	28,800	\$4,032
212976810	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120B*	29,000	\$4,060
212976797	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120B*	29,000	\$4,060
212976528	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120B*	28,800	\$4,032
212976303	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0801716B*	29,000	\$4,060
212974415	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120B*	29,000	\$4,060
212974195	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120B*	28,800	\$4,032
212974055	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716B*	29,000	\$4,060
212972245	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120B*	29,000	\$4,060
212972234	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120B*	29,000	\$4,060
212971878	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716B*	29,000	\$4,060
212970739	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120B*	29,200	\$4,088
211712820	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	23,600	\$3,304
212970729	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120B*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212970719	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	29,400	\$4,116
212970709	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*80VSL0902120B*	29,600	\$4,144
212970699	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120B*	29,000	\$4,060
212970689	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120B*	29,000	\$4,060
212970679	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120B*	29,200	\$4,088
212970669	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120B*	29,400	\$4,116
211712833	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	23,400	\$3,276
212970659	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120B*	29,400	\$4,116
212970649	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120B*	29,200	\$4,088
212970639	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120B*	29,400	\$4,116
212970479	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716B*	29,200	\$4,088
212970469	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	29,400	\$4,116
212970459	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80VSL0701716B*	29,400	\$4,116
211712846	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	23,400	\$3,276
212970429	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716B*	29,000	\$4,060
212970419	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716B*	29,200	\$4,088
212970409	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716B*	29,400	\$4,116
212970399	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716B*	29,200	\$4,088
212970389	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716B*	29,400	\$4,116
212970379	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716B*	29,600	\$4,144
212970369	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716B*	29,600	\$4,144
212969959	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80VSL0451412B*	29,400	\$4,116
211712859	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	23,600	\$3,304
212969939	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412B*	29,200	\$4,088
212969929	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412B*	29,400	\$4,116
212390901	ARCOAIRE	DLCURAH36ABK	FJMA4*36L*B*		29,400	\$4,116
212384854	ARCOAIRE	DLCURAH36ABK	FVM4X36***L		29,400	\$4,116
212384830	ARCOAIRE	DLCURAH36ABK	FJMA4*42L*C*		29,200	\$4,088
211712872	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	23,400	\$3,276
212384790	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0801716A*	29,200	\$4,088
212384778	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701716A*	29,200	\$4,088
212384767	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV112A16A	29,600	\$4,144
212384757	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV112K14A	29,400	\$4,116
212384747	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV098A12*	29,600	\$4,144
212384737	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV098J12*	29,600	\$4,144
211712885	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	23,600	\$3,304
212384726	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	29,400	\$4,116
212384714	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0802120A	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384702	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0601714A*	29,400	\$4,116
212384690	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	29,400	\$4,116
212384678	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	29,400	\$4,116
212384666	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0801716A*	29,400	\$4,116
211712898	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*92ESN0802120A*	23,400	\$3,276
212384654	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0601714A*	29,400	\$4,116
212384641	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	29,400	\$4,116
212384628	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	29,400	\$4,116
212384615	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701712A*	29,600	\$4,144
212384602	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0451712A*	29,400	\$4,116
211712910	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*92ESN1002120A*	23,400	\$3,276
212384591	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	29,400	\$4,116
212384580	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120A*	29,600	\$4,144
212384569	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	29,400	\$4,116
212384557	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	29,600	\$4,144
212384546	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120A*	29,400	\$4,116
212384531	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	29,400	\$4,116
212384519	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	29,400	\$4,116
211712956	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	OLV154F20A	23,600	\$3,304
211712966	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	OMV154L20A	23,600	\$3,304
211712976	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0601714A*	23,200	\$3,248
211712986	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120A*	23,000	\$3,220
211712996	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120A*	23,200	\$3,248
211713006	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716A*	23,200	\$3,248
211713017	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*95ESU0401712A*	23,200	\$3,248
211713029	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
211713041	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122A*	23,000	\$3,220
211713051	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VSL0451716A*	23,200	\$3,248
211713061	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VSL0701716A*	23,200	\$3,248
211713071	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VSL0702120A*	23,200	\$3,248
211713081	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VSL0902120A*	23,200	\$3,248
211713092	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*95ESU1002120A*	23,400	\$3,276
211713104	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*95ESU0601716A*	23,400	\$3,276
211713116	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ESU1002120A*	23,400	\$3,276
211713128	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ESU0401712A*	23,200	\$3,248
213353886	ARCOAIRE	DLCURAH60ABK	F5MA4*60L*D*		37,800	\$5,292
213607816	ARCOAIRE	DLCURAH60ABK	FTMA4B60L0D*		37,400	\$5,236
211713143	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713154	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*95ESN0802120A*	23,200	\$3,248
211713166	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*95ESN1002120A*	23,600	\$3,304
211713178	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716A*	23,200	\$3,248
211713190	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VTN0601714A*	23,200	\$3,248
211713201	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120A*	23,000	\$3,220
211713212	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120A*	23,200	\$3,248
211713223	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122A*	23,200	\$3,248
210025741	ARCOAIRE	DLCURAH60ABK	DLFUAAH60XAK		42,000	\$5,880
212384507	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	29,400	\$4,116
211713234	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
212384496	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120A*	29,400	\$4,116
212384486	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	29,400	\$4,116
212384476	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716A*	29,400	\$4,116
212384466	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002122A*	29,600	\$4,144
212384456	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002122A*	29,600	\$4,144
212384446	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002122A*	29,600	\$4,144
211713247	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
212384435	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	29,400	\$4,116
212384424	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	29,400	\$4,116
212384414	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	29,400	\$4,116
212384404	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120A*	29,400	\$4,116
212384394	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0601714A*	29,400	\$4,116
212384384	ARCOAIRE	DLCURAH36ABK	END4X42L17**	OMV112K14A	29,400	\$4,116
211713260	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
212384374	ARCOAIRE	DLCURAH36ABK	END4X42L17**	OLV098A12*	29,400	\$4,116
212384364	ARCOAIRE	DLCURAH36ABK	END4X42L17**	OMV098J12*	29,400	\$4,116
212384353	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80ESU0601716A	29,400	\$4,116
212384340	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701412A*	29,400	\$4,116
212384328	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*92ESN0801716A*	29,200	\$4,088
211713273	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
212384316	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*92ESN0601714A*	29,200	\$4,088
212384304	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*92ESN0601412A*	29,400	\$4,116
212384291	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0901714A*	29,400	\$4,116
212384278	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701712A*	29,400	\$4,116
211713286	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
212384265	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451712A*	29,400	\$4,116
212384252	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451412A*	29,600	\$4,144
212384238	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80VTL0451412A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384227	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80VSL0701716A*	29,200	\$4,088
211713299	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
212384217	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80VSL0451716A*	29,400	\$4,116
212384206	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701716A*	29,200	\$4,088
212384142	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*80ESU0802120A	29,800	\$4,172
212384130	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002120A*	29,600	\$4,144
211713312	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	23,400	\$3,276
212384118	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN0802120A*	29,600	\$4,144
211713325	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*92ESN0601714A*	23,000	\$3,220
211713337	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*92ESN0801716A*	23,400	\$3,276
211713349	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*92ESN0802120A*	23,200	\$3,248
211713361	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*92ESN1002120A*	23,200	\$3,248
212383811	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESU1002122A*	29,800	\$4,172
212383801	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESN1002122A*	29,800	\$4,172
212383791	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002122A*	29,800	\$4,172
211713373	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*95ESN0601714A*	23,200	\$3,248
211713385	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ESU0802120A	23,400	\$3,276
212383484	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701716A*	29,000	\$4,060
211713397	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80ESU0601716A	23,200	\$3,248
212383472	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92ESN0801716A*	29,000	\$4,060
212383460	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
212383449	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	OLV112A16A	29,400	\$4,116
212383438	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002120A*	29,200	\$4,088
211713408	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	OMV098J12*	23,200	\$3,248
212383427	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120A*	29,000	\$4,060
212383415	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95ESU0601716A*	29,200	\$4,088
212383403	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
212383391	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80ESU0601716A	29,200	\$4,088
211713418	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	OLV098A12*	23,200	\$3,248
212383379	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ESU0601716A	29,400	\$4,116
212383367	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ESU0802120A	29,600	\$4,144
212383355	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002120A*	29,400	\$4,116
212383343	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92ESN0802120A*	29,400	\$4,116
212383331	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92ESN0801716A*	29,400	\$4,116
212383318	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
212383305	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
212383292	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	29,600	\$4,144
212383279	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383268	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122A*	29,600	\$4,144
212383257	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VTN0601714A*	29,600	\$4,144
212383245	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716A*	29,400	\$4,116
212383233	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95ESN0802120A*	29,600	\$4,144
212383222	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120A*	29,400	\$4,116
212383210	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002120A*	29,400	\$4,116
212383199	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120A*	29,400	\$4,116
212383189	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0702120A*	29,400	\$4,116
212383179	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716A*	29,400	\$4,116
212383168	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95ESU0802120A*	29,800	\$4,172
212383157	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002122A*	29,600	\$4,144
212383146	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
212383135	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716A*	29,400	\$4,116
212383125	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120A*	29,400	\$4,116
212383115	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120A*	29,400	\$4,116
212383105	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0601714A*	29,600	\$4,144
212383095	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	OLV098A12*	29,600	\$4,144
212383085	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	OMV098J12*	29,600	\$4,144
212383074	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80ESU0601716A	29,600	\$4,144
212383061	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	29,600	\$4,144
212383049	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*95ESN0601714A*	29,600	\$4,144
212383037	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*92ESN0801716A*	29,400	\$4,116
212383025	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601714A*	29,400	\$4,116
212383013	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601412A*	29,600	\$4,144
212383000	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	29,600	\$4,144
212382987	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	29,600	\$4,144
212382974	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	29,600	\$4,144
212382961	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	29,800	\$4,172
212382950	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601714A*	29,600	\$4,144
212382938	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716A*	29,400	\$4,116
212382921	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412A*	29,600	\$4,144
212382909	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*95ESU0601716A*	29,400	\$4,116
212382898	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716A*	29,400	\$4,116
212382888	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451716A*	29,600	\$4,144
212382877	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
212382866	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716A*	29,400	\$4,116
212382856	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601714A*	29,600	\$4,144
212382846	ARCOAIRE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230929	ARCOAIRE	DLCURAH36ABK	FXM4X48**AL		29,000	\$4,060
211230918	ARCOAIRE	DLCURAH36ABK	FXM4X42**AL		29,000	\$4,060
211230897	ARCOAIRE	DLCURAH36ABK	FVM4X48***L		28,600	\$4,004
211230886	ARCOAIRE	DLCURAH36ABK	FMA4X36**AL*		29,600	\$4,144
211230864	ARCOAIRE	DLCURAH36ABK	FM(C,U)4Z36**AL*		29,600	\$4,144
211230808	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	OMV154L20A	29,200	\$4,088
211230799	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	OLV154F20A	29,400	\$4,116
211230790	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	OLV112A16A	29,200	\$4,088
211230781	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422A*	29,200	\$4,088
211230771	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122A*	29,200	\$4,088
211230762	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120A*	29,200	\$4,088
211230752	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120A*	29,200	\$4,088
211230742	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002122A*	29,400	\$4,116
211230732	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002120A*	29,200	\$4,088
211230721	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU0802120A*	29,600	\$4,144
211230711	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422A*	29,200	\$4,088
211230702	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120A*	29,200	\$4,088
211230693	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120A*	29,200	\$4,088
211230683	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1402422A*	29,400	\$4,116
211230672	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1202422A*	29,400	\$4,116
211230662	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002122A*	29,400	\$4,116
211230652	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002120A*	29,200	\$4,088
211230641	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN0802120A*	29,400	\$4,116
211230630	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1202420A*	29,200	\$4,088
211230620	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002122A*	29,400	\$4,116
211230610	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002120A*	29,200	\$4,088
211230599	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN0802120A*	29,000	\$4,060
211230569	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122A*	29,200	\$4,088
211230559	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120A*	29,200	\$4,088
211230548	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU1002120A*	29,200	\$4,088
211230537	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU0802120A	29,400	\$4,116
211230527	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL1102422A*	29,200	\$4,088
211230518	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902420A*	29,200	\$4,088
211230509	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120A*	29,200	\$4,088
211230500	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0702120A*	29,200	\$4,088
211230491	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1552420A*	29,200	\$4,088
211230479	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1352420A*	29,200	\$4,088
211230467	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102420A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230455	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102120A*	29,200	\$4,088
211230443	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902420A*	29,200	\$4,088
211230431	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902120A*	29,200	\$4,088
211230419	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902116A*	29,200	\$4,088
211230407	ARCOAIRE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0702116A*	29,200	\$4,088
211230379	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV112K14A	29,200	\$4,088
211230370	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV098J12*	29,200	\$4,088
211230361	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV112A16A	29,200	\$4,088
211230352	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV098A12*	29,200	\$4,088
211230343	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122A*	29,200	\$4,088
211230334	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120A*	29,200	\$4,088
211230324	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120A*	29,200	\$4,088
211230314	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0601714A*	29,400	\$4,116
211230294	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002122A*	29,400	\$4,116
211230284	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002120A*	29,200	\$4,088
211230273	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0802120A*	29,600	\$4,144
211230262	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0601716A*	29,200	\$4,088
211230252	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120A*	29,200	\$4,088
211230243	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120A*	29,200	\$4,088
211230234	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716A*	29,200	\$4,088
211230225	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0601714A*	29,200	\$4,088
211230207	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002122A*	29,400	\$4,116
211230197	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002120A*	29,200	\$4,088
211230186	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0802120A*	29,400	\$4,116
211230175	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0801716A*	29,200	\$4,088
211230164	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0601714A*	29,200	\$4,088
211230154	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002122A*	29,400	\$4,116
211230144	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002120A*	29,200	\$4,088
211230133	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0802120A*	29,000	\$4,060
211230122	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0601714A*	29,200	\$4,088
211230085	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122A*	29,200	\$4,088
211230075	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120A*	29,200	\$4,088
211230063	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716A*	29,200	\$4,088
211230052	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU1002120A*	29,200	\$4,088
211230041	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0802120A	29,400	\$4,116
211230030	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0601716A	29,000	\$4,060
211230019	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0401712A*	29,600	\$4,144
211230009	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230000	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0702120A*	29,200	\$4,088
211229991	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716A*	29,200	\$4,088
211229982	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0451716A*	29,200	\$4,088
211229971	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)1102120A*	29,200	\$4,088
211229959	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902120A*	29,200	\$4,088
211229947	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902116A*	29,200	\$4,088
211229935	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0901714A*	29,200	\$4,088
211229923	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0702116A*	29,200	\$4,088
211229911	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701712A*	29,400	\$4,116
211229899	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0451712A*	29,200	\$4,088
211229853	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	29,400	\$4,116
211229844	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120A*	29,400	\$4,116
211229834	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0601714A*	29,600	\$4,144
211229823	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002120A*	29,400	\$4,116
211229802	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0451716A*	29,400	\$4,116
211229791	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	29,400	\$4,116
211229779	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	29,400	\$4,116
211229767	ARCOAIRE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	29,400	\$4,116
211229748	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*96VTN0601714A*	29,400	\$4,116
211229737	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*95ESU0601716A*	29,200	\$4,088
211229727	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*96VSN0801716A*	29,400	\$4,116
211229718	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*96VSN0601714A*	29,400	\$4,116
211229690	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*95ESN0601714A*	29,400	\$4,116
211229671	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80VTL0701716A*	29,200	\$4,088
211229659	ARCOAIRE	DLCURAH36ABK	END4X42L17**	*80VSL0451412A*	29,400	\$4,116
211229650	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	OMV154L20A	29,000	\$4,060
211229641	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	OLV154F20A	29,200	\$4,088
211229632	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	OLV112A16A	29,000	\$4,060
211229623	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422A*	29,000	\$4,060
211229613	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122A*	28,800	\$4,032
211714017	ARCOAIRE	DLCURAH30ABK	EN(A,D)4X36L21**	*80ESU0802120A	23,600	\$3,304
211229604	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120A*	29,000	\$4,060
211229594	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120A*	28,800	\$4,032
211229584	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002122A*	29,200	\$4,088
211229574	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002120A*	29,000	\$4,060
211229563	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95ESU0802120A*	29,400	\$4,116
211229553	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422A*	29,000	\$4,060
211229544	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229535	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120A*	29,000	\$4,060
211229525	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95ESN1402422A*	29,200	\$4,088
211229514	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95ESN1202422A*	29,200	\$4,088
211229504	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002122A*	29,200	\$4,088
211714040	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80VSL0451412A*	23,400	\$3,276
211229494	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002120A*	29,000	\$4,060
211229483	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*95ESN0802120A*	29,200	\$4,088
211229472	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*92ESN1202420A*	29,000	\$4,060
211229462	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002122A*	29,200	\$4,088
211714050	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*96VSN0801716A*	23,400	\$3,276
211229452	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002120A*	28,800	\$4,032
211229441	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*92ESN0802120A*	28,800	\$4,032
211229411	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122A*	29,000	\$4,060
211229401	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120A*	28,800	\$4,032
211229390	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ESU1002120A*	29,000	\$4,060
211714061	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*95ESU0401712A*	23,400	\$3,276
211229379	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ESU0802120A	29,200	\$4,088
211229369	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80VSL1102422A*	28,800	\$4,032
211229360	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902420A*	28,800	\$4,032
211229351	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120A*	28,800	\$4,032
211229342	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80VSL0702120A*	29,000	\$4,060
211229333	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1552420A*	29,200	\$4,088
211714073	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701716A*	23,600	\$3,304
211229321	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1352420A*	29,000	\$4,060
211229309	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102420A*	28,800	\$4,032
211229297	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102120A*	29,000	\$4,060
211229285	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902420A*	29,000	\$4,060
211714084	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80VSL0451716A*	23,400	\$3,276
211229273	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902120A*	29,000	\$4,060
211229261	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902116A*	29,000	\$4,060
211229249	ARCOAIRE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0702116A*	28,800	\$4,032
211229221	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	OMV112K14A	29,000	\$4,060
211714094	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80VSL0701716A*	23,400	\$3,276
211229212	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	OMV098J12*	29,000	\$4,060
211229203	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	OLV112A16A	29,000	\$4,060
211229194	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	OLV098A12*	29,000	\$4,060
211229185	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122A*	28,800	\$4,032
211229176	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714105	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*95ESU0601716A*	23,600	\$3,304
211229166	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120A*	29,000	\$4,060
211229156	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0601714A*	29,200	\$4,088
211229146	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002122A*	29,200	\$4,088
211229136	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002120A*	29,000	\$4,060
211229125	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95ESU0802120A*	29,400	\$4,116
211714117	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80ESU0401712A*	23,400	\$3,276
211229114	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95ESU0601716A*	29,000	\$4,060
211229104	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120A*	29,000	\$4,060
211229095	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120A*	29,000	\$4,060
211229086	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716A*	29,000	\$4,060
211229077	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0601714A*	29,000	\$4,060
211714129	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80VTL0451412A*	23,400	\$3,276
211229059	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002122A*	29,200	\$4,088
211229049	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002120A*	29,000	\$4,060
211229038	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95ESN0802120A*	29,200	\$4,088
211229027	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95ESN0801716A*	29,000	\$4,060
211229016	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*95ESN0601714A*	29,000	\$4,060
211229006	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002122A*	29,200	\$4,088
211228996	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002120A*	28,800	\$4,032
211228985	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92ESN0802120A*	28,800	\$4,032
211714146	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80VTL0701716A*	23,400	\$3,276
211228974	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92ESN0801716A*	29,000	\$4,060
211228963	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*92ESN0601714A*	29,000	\$4,060
211228926	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122A*	29,000	\$4,060
211228916	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120A*	28,800	\$4,032
211228904	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716A*	29,000	\$4,060
211714158	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*96VTN0601714A*	23,400	\$3,276
211228893	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ESU1002120A*	29,000	\$4,060
211228882	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ESU0802120A	29,200	\$4,088
211228871	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ESU0601716A	29,000	\$4,060
211228860	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ESU0401712A*	29,400	\$4,116
211228850	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120A*	28,800	\$4,032
211714169	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0451412A*	23,400	\$3,276
211228841	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0702120A*	29,000	\$4,060
211228832	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716A*	29,000	\$4,060
211228823	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0451716A*	29,000	\$4,060
211228812	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)1102120A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228800	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902120A*	29,000	\$4,060
211228788	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211714182	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701712A*	23,400	\$3,276
211228776	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0901714A*	29,000	\$4,060
211228764	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0702116A*	28,800	\$4,032
211228752	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701712A*	29,000	\$4,060
211228740	ARCOAIRE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228694	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	OMV112K14A	29,200	\$4,088
211228685	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	OMV098J12*	29,200	\$4,088
211714195	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0901714A*	23,400	\$3,276
211228676	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	OLV112A16A	29,200	\$4,088
211228667	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	OLV098A12*	29,200	\$4,088
211228658	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122A*	29,000	\$4,060
211228649	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120A*	29,200	\$4,088
211228639	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120A*	29,200	\$4,088
211228629	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VTN0601714A*	29,200	\$4,088
211714208	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*92ESN0601412A*	23,400	\$3,276
211228609	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002122A*	29,200	\$4,088
211228599	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002120A*	29,000	\$4,060
211228588	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95ESU0802120A*	29,400	\$4,116
211714220	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*92ESN0601714A*	23,200	\$3,248
211228577	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95ESU0601716A*	29,200	\$4,088
211228567	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120A*	29,000	\$4,060
211228558	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120A*	29,000	\$4,060
211228549	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716A*	29,200	\$4,088
211714232	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*92ESN0801716A*	23,200	\$3,248
211228540	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0601714A*	29,200	\$4,088
211228522	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002122A*	29,200	\$4,088
211228512	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002120A*	29,200	\$4,088
211228501	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95ESN0802120A*	29,200	\$4,088
211714244	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*95ESN0601714A*	23,400	\$3,276
211228479	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*95ESN0601714A*	29,400	\$4,116
211228469	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002122A*	29,400	\$4,116
211228459	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002120A*	29,200	\$4,088
211228448	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92ESN0802120A*	29,200	\$4,088
211714256	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701412A*	23,200	\$3,248
211228437	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*92ESN0601714A*	29,000	\$4,060
211228400	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228390	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120A*	29,000	\$4,060
211714269	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80ESU0601716A	23,400	\$3,276
211228378	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716A*	29,000	\$4,060
211228367	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ESU1002120A*	29,000	\$4,060
211228356	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ESU0802120A	29,200	\$4,088
211714280	ARCOAIRE	DLCURAH30ABK	END4X42L17**	OMV098J12*	23,400	\$3,276
211228345	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ESU0601716A	29,200	\$4,088
211228334	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ESU0401712A*	29,400	\$4,116
211714290	ARCOAIRE	DLCURAH30ABK	END4X42L17**	OLV098A12*	23,400	\$3,276
211228324	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120A*	29,000	\$4,060
211228315	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0702120A*	29,000	\$4,060
211228306	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716A*	29,200	\$4,088
211228297	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0451716A*	29,200	\$4,088
211228286	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211714310	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	23,400	\$3,276
211228274	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211228262	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211228250	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211714320	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	23,400	\$3,276
211228238	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211228226	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211228214	ARCOAIRE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228168	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	OMV154L20A	29,400	\$4,116
211714343	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	23,600	\$3,304
211714355	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	23,400	\$3,276
211714385	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	23,400	\$3,276
211714406	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	23,600	\$3,304
212970759	ARCOAIRE	DLCURAH48AAK	EA*4X48L24A*	*80VSL0902120B*	32,600	\$4,564
211714418	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	23,600	\$3,304
212970749	ARCOAIRE	DLCURAH48AAK	EA*4X48L21A*	*80VSL0902120B*	32,600	\$4,564
211714430	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	23,600	\$3,304
211714442	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0401712A*	23,400	\$3,276
212970799	ARCOAIRE	DLCURAH48ABK	EA*4X48L21A*	*80VSL0902120B*	31,400	\$4,396
212970809	ARCOAIRE	DLCURAH48ABK	EA*4X48L24A*	*80VSL0902120B*	31,400	\$4,396
212970819	ARCOAIRE	DLCURAH48ABK	EA*4X60L24A*	*80VSL0902120B*	31,000	\$4,340
212970839	ARCOAIRE	DLCURAH48ABK	EA*4X61L24A*	*80VSL0902120B*	31,000	\$4,340
212970829	ARCOAIRE	DLCURAH48ABK	EA*4X61L21A*	*80VSL0902120B*	31,000	\$4,340
211714468	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714480	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	23,400	\$3,276
211714513	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	23,400	\$3,276
211714537	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	23,600	\$3,304
211714550	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	23,400	\$3,276
211714563	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	23,600	\$3,304
211714576	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	23,400	\$3,276
211714589	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	23,600	\$3,304
211714626	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	23,400	\$3,276
211714638	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	23,400	\$3,276
211714662	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	23,400	\$3,276
211714687	ARCOAIRE	DLCURAH30ABK	FJMA4*36L*B*		23,400	\$3,276
212969879	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412B*	23,400	\$3,276
212969919	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80VSL0451412B*	23,400	\$3,276
212970279	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80VSL0701716B*	23,400	\$3,276
212970299	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80VSL0701716B*	23,600	\$3,304
212970349	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80VSL0701716B*	23,400	\$3,276
212970359	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	23,600	\$3,304
212970589	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80VSL0902120B*	23,600	\$3,304
212970599	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902120B*	23,600	\$3,304
212970629	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	23,600	\$3,304
212971294	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412B*	23,400	\$3,276
212971342	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80VTL0451412B*	23,400	\$3,276
212971779	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716B*	23,400	\$3,276
212971790	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716B*	23,200	\$3,248
212971801	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716B*	23,600	\$3,304
212971812	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716B*	23,200	\$3,248
212971856	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80VTL0701716B*	23,400	\$3,276
212971867	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	23,600	\$3,304
212972168	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120B*	23,200	\$3,248
212972179	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80VTL0902120B*	23,600	\$3,304
212972190	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80VTL0902120B*	23,600	\$3,304
212972201	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120B*	23,200	\$3,248
212972223	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	23,600	\$3,304
212972450	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122B*	23,400	\$3,276
212972462	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122B*	23,400	\$3,276
212972474	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122B*	23,400	\$3,276
212972486	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122B*	23,200	\$3,248
212973645	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*96VSN0601412B*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973965	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716B*	23,400	\$3,276
212973975	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716B*	23,400	\$3,276
212973995	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716B*	23,200	\$3,248
212974035	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*96VSN0801716B*	23,400	\$3,276
212974135	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120B*	23,200	\$3,248
212974145	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*96VSN0802120B*	23,400	\$3,276
212974155	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96VSN0802120B*	23,400	\$3,276
212974165	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120B*	23,200	\$3,248
212974185	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	23,600	\$3,304
212974355	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120B*	23,200	\$3,248
212974365	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*96VSN1002120B*	23,600	\$3,304
212974375	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96VSN1002120B*	23,600	\$3,304
212974385	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120B*	23,200	\$3,248
212974405	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	23,600	\$3,304
212974525	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96VSN1202422B*	23,600	\$3,304
212975764	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*96VTN0601412B*	23,600	\$3,304
212976179	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*96VTN0801716B*	23,400	\$3,276
212976192	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VTN0801716B*	23,400	\$3,276
212976218	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VTN0801716B*	23,200	\$3,248
212976270	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*96VTN0801716B*	23,400	\$3,276
212976446	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120B*	23,200	\$3,248
212976461	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*96VTN0802120B*	23,400	\$3,276
212976474	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96VTN0802120B*	23,400	\$3,276
212976489	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120B*	23,200	\$3,248
212976515	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	23,600	\$3,304
212976719	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120B*	23,200	\$3,248
212976732	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002120B*	23,600	\$3,304
212976745	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002120B*	23,600	\$3,304
212976758	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120B*	23,200	\$3,248
212976784	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	23,600	\$3,304
212977021	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122B*	23,200	\$3,248
212977031	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002122B*	23,400	\$3,276
212977041	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002122B*	23,400	\$3,276
212977051	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122B*	23,200	\$3,248
212977071	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	23,400	\$3,276
212977243	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96VTN1202422B*	23,600	\$3,304
212977518	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	23,400	\$3,276
212977554	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0451412A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978022	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	23,400	\$3,276
212978070	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701412A*	23,400	\$3,276
212978525	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978536	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978547	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978558	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978602	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701712A*	23,400	\$3,276
212978613	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	23,400	\$3,276
212979015	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	23,400	\$3,276
212979027	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979039	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	23,600	\$3,304
212979051	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979099	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701716A*	23,400	\$3,276
212979111	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	23,600	\$3,304
212979435	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	23,200	\$3,248
212979445	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979455	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979465	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	23,200	\$3,248
212979705	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979717	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979729	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979741	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979789	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0901714A*	23,400	\$3,276
212980193	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980226	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980248	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	23,600	\$3,304
212980512	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980523	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	23,600	\$3,304
212980545	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980567	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	23,600	\$3,304
212980700	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	23,600	\$3,304
212980902	ARCOAIRE	DLCURAH30ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980914	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980926	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980938	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980950	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980974	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	23,600	\$3,304
212981112	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212981221	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	23,600	\$3,304
212981322	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	23,400	\$3,276
212981584	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*80MSU1002120A*	23,400	\$3,276
212981668	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*80MSU1002120A*	23,400	\$3,276
212982652	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*80MSU0601716A*	23,400	\$3,276
212983470	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601412A*	23,400	\$3,276
212983500	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*92MSN0601412A*	23,600	\$3,304
212983921	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601714A*	23,400	\$3,276
212983933	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*92MSN0601714A*	23,200	\$3,248
212983957	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*92MSN0601714A*	23,200	\$3,248
212984005	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*92MSN0601714A*	23,400	\$3,276
212984461	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*92MSN0801716A*	23,400	\$3,276
212984473	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*92MSN0801716A*	23,200	\$3,248
212984485	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*92MSN0801716A*	23,400	\$3,276
212984497	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*92MSN0801716A*	23,200	\$3,248
212984545	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*92MSN0801716A*	23,400	\$3,276
212984973	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*92MSN0802120A*	23,200	\$3,248
212984983	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*92MSN0802120A*	23,400	\$3,276
212984993	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*92MSN0802120A*	23,400	\$3,276
212985003	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*92MSN0802120A*	23,200	\$3,248
212985023	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	23,600	\$3,304
212985267	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*92MSN1002120A*	23,200	\$3,248
212985279	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*92MSN1002120A*	23,400	\$3,276
212985291	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*92MSN1002120A*	23,400	\$3,276
212985303	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*92MSN1002120A*	23,600	\$3,304
212985327	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	23,600	\$3,304
212985616	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*92MSN1202420A*	23,400	\$3,276
212985747	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*96MSN0261410A*	23,600	\$3,304
212986851	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*96MSN0601412A*	23,600	\$3,304
212987259	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*96MSN0801716A*	23,400	\$3,276
212987271	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96MSN0801716A*	23,200	\$3,248
212987295	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96MSN0801716A*	23,400	\$3,276
212987343	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*96MSN0801716A*	23,600	\$3,304
212987355	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	23,600	\$3,304
212987727	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*96MSN0802120A*	23,200	\$3,248
212987751	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96MSN0802120A*	23,400	\$3,276
212987763	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*96MSN0802120A*	23,200	\$3,248
212988333	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96MSN1202422A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988415	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*96MSN1402422A*	23,600	\$3,304
212988581	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*95MSU0401712A*	23,600	\$3,304
212988593	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*95MSU0401712A*	23,200	\$3,248
212988617	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*95MSU0401712A*	23,200	\$3,248
212988629	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*95MSU0401712A*	23,600	\$3,304
212989025	ARCOAIRE	DLCURAH30ABK	EA*4X37L17A*	*95MSU0601716A*	23,400	\$3,276
212989037	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*95MSU0601716A*	23,200	\$3,248
212989049	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*95MSU0601716A*	23,600	\$3,304
212989061	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*95MSU0601716A*	23,200	\$3,248
212989109	ARCOAIRE	DLCURAH30ABK	END4X42L17**	*95MSU0601716A*	23,400	\$3,276
212989121	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	23,600	\$3,304
212989529	ARCOAIRE	DLCURAH30ABK	EA*4X37L21A*	*95MSU0802120A*	23,200	\$3,248
212989541	ARCOAIRE	DLCURAH30ABK	EA*4X42L21A*	*95MSU0802120A*	23,600	\$3,304
212989553	ARCOAIRE	DLCURAH30ABK	EA*4X42L24A*	*95MSU0802120A*	23,600	\$3,304
212989565	ARCOAIRE	DLCURAH30ABK	EA*4X43L21A*	*95MSU0802120A*	23,200	\$3,248
212989589	ARCOAIRE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	23,600	\$3,304
213249294	ARCOAIRE	DLCURAH30ABK	FEVA0036**+NAVA43601CK		23,600	\$3,304
213353810	ARCOAIRE	DLCURAH30ABK	F5MA4*30L*B*		23,400	\$3,276
213353820	ARCOAIRE	DLCURAH30ABK	F5MA4*36L*B*		23,600	\$3,304
211226262	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	29,600	\$4,144
211226274	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	29,600	\$4,144
211226286	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211226297	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0451716A*	29,600	\$4,144
211226307	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*80ESU1002120A*	29,400	\$4,116
211226329	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92ESN0601714A*	29,400	\$4,116
211226339	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002122A*	29,600	\$4,144
211226349	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95ESN0601714A*	29,400	\$4,116
211226360	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95ESN0801716A*	29,400	\$4,116
211226371	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002120A*	29,600	\$4,144
211226381	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002122A*	29,600	\$4,144
211226391	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*95ESU0601716A*	29,400	\$4,116
211226402	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120A*	29,400	\$4,116
211226412	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120A*	29,600	\$4,144
211226421	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122A*	29,400	\$4,116
211226430	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	OLV098A12*	29,600	\$4,144
211226439	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	OLV112A16A	29,600	\$4,144
211226448	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	OMV098J12*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226457	ARCOAIRE	DLCURAH36ABK	EA*4X36L21A*	OMV112K14A	29,600	\$4,144
211226485	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	29,400	\$4,116
211226497	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	29,200	\$4,088
211226509	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701712A*	29,400	\$4,116
211226521	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
211226532	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226543	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412A*	29,400	\$4,116
211226552	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451716A*	29,400	\$4,116
211226561	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716A*	29,400	\$4,116
211226582	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412A*	29,400	\$4,116
211226594	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716A*	29,400	\$4,116
211226615	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601412A*	29,400	\$4,116
211226626	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601714A*	29,200	\$4,088
211226637	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*92ESN0801716A*	29,400	\$4,116
211226659	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*95ESN0601714A*	29,400	\$4,116
211226669	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412A*	29,400	\$4,116
211226678	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601714A*	29,400	\$4,116
211226687	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716A*	29,400	\$4,116
211226697	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*95ESU0601716A*	29,400	\$4,116
211226708	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601714A*	29,400	\$4,116
211226717	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	OLV098A12*	29,400	\$4,116
211226726	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	OMV098J12*	29,400	\$4,116
211226735	ARCOAIRE	DLCURAH36ABK	EA*4X37L17A*	OMV112K14A	29,400	\$4,116
211226793	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211226805	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211226817	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226829	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211226841	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211226853	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211226864	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0451716A*	29,200	\$4,088
211226873	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716A*	29,200	\$4,088
211226882	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0702120A*	29,000	\$4,060
211226891	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120A*	29,000	\$4,060
211226901	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ESU0401712A*	29,400	\$4,116
211226912	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ESU0601716A	29,200	\$4,088
211226923	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ESU0802120A	29,400	\$4,116
211226934	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80ESU1002120A*	29,000	\$4,060
211226945	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226957	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122A*	29,200	\$4,088
211226994	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92ESN0601714A*	29,000	\$4,060
211227005	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92ESN0801716A*	29,000	\$4,060
211227016	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92ESN0802120A*	29,200	\$4,088
211227026	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002122A*	29,400	\$4,116
211227036	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95ESN0601714A*	29,400	\$4,116
211227058	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95ESN0802120A*	29,200	\$4,088
211227069	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002120A*	29,200	\$4,088
211227079	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002122A*	29,200	\$4,088
211227097	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0601714A*	29,200	\$4,088
211227106	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716A*	29,200	\$4,088
211227115	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120A*	29,000	\$4,060
211227124	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120A*	29,000	\$4,060
211227134	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95ESU0802120A*	29,400	\$4,116
211227145	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002120A*	29,000	\$4,060
211227155	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002122A*	29,200	\$4,088
211227175	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VTN0601714A*	29,200	\$4,088
211227185	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120A*	29,200	\$4,088
211227195	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120A*	29,200	\$4,088
211227204	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122A*	29,000	\$4,060
211227213	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	OLV098A12*	29,200	\$4,088
211227222	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	OLV112A16A	29,200	\$4,088
211227231	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	OMV098J12*	29,200	\$4,088
211227240	ARCOAIRE	DLCURAH36ABK	EA*4X37L21A*	OMV112K14A	29,200	\$4,088
211227286	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0451712A*	29,400	\$4,116
211227298	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701712A*	29,400	\$4,116
211227310	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
211227321	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227333	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	29,400	\$4,116
211227345	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227357	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227369	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227380	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0451716A*	29,400	\$4,116
211227389	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716A*	29,400	\$4,116
211227398	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0702120A*	29,400	\$4,116
211227407	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120A*	29,400	\$4,116
211227428	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ESU0601716A	29,200	\$4,088
211227439	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ESU0802120A	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227450	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80ESU1002120A*	29,400	\$4,116
211227461	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716A*	29,400	\$4,116
211227473	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120A*	29,400	\$4,116
211227483	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122A*	29,400	\$4,116
211227511	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92ESN0601714A*	29,400	\$4,116
211227522	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92ESN0801716A*	29,400	\$4,116
211227533	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92ESN0802120A*	29,200	\$4,088
211227544	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002120A*	29,200	\$4,088
211227554	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002122A*	29,600	\$4,144
211227564	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95ESN0601714A*	29,400	\$4,116
211227575	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95ESN0802120A*	29,400	\$4,116
211227585	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95ESN1002122A*	29,600	\$4,144
211227594	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0601714A*	29,400	\$4,116
211227603	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716A*	29,400	\$4,116
211227612	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120A*	29,400	\$4,116
211227621	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120A*	29,400	\$4,116
211227631	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95ESU0601716A*	29,400	\$4,116
211227642	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95ESU0802120A*	29,600	\$4,144
211227653	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002120A*	29,400	\$4,116
211227663	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002122A*	29,600	\$4,144
211227673	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0601714A*	29,600	\$4,144
211227683	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716A*	29,400	\$4,116
211227693	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120A*	29,400	\$4,116
211227703	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120A*	29,400	\$4,116
211227712	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122A*	29,200	\$4,088
211227721	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	OLV098A12*	29,400	\$4,116
211227730	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	OMV098J12*	29,400	\$4,116
211227739	ARCOAIRE	DLCURAH36ABK	EA*4X42L21A*	OMV112K14A	29,400	\$4,116
211227767	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227779	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227791	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227803	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	29,400	\$4,116
211227815	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227827	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	29,200	\$4,088
211227839	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	29,400	\$4,116
211227851	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1552420A*	29,400	\$4,116
211227860	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80VSL0702120A*	29,400	\$4,116
211227869	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227878	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902420A*	29,400	\$4,116
211227887	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80VSL1102422A*	29,200	\$4,088
211227897	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ESU0802120A	29,600	\$4,144
211227908	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80ESU1002120A*	29,400	\$4,116
211227919	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120A*	29,400	\$4,116
211227929	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122A*	29,400	\$4,116
211227959	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*92ESN0802120A*	29,200	\$4,088
211227970	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002120A*	29,200	\$4,088
211227980	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002122A*	29,600	\$4,144
211227990	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*92ESN1202420A*	29,400	\$4,116
211228001	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95ESN0802120A*	29,400	\$4,116
211228012	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002120A*	29,400	\$4,116
211228022	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002122A*	29,600	\$4,144
211228032	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95ESN1202422A*	29,600	\$4,144
211228043	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95ESN1402422A*	29,600	\$4,144
211228053	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120A*	29,400	\$4,116
211228062	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120A*	29,400	\$4,116
211228071	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422A*	29,400	\$4,116
211228081	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95ESU0802120A*	29,600	\$4,144
211228092	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002120A*	29,400	\$4,116
211228102	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002122A*	29,600	\$4,144
211228112	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120A*	29,400	\$4,116
211228122	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120A*	29,400	\$4,116
211228131	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122A*	29,200	\$4,088
211228141	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422A*	29,400	\$4,116
211228150	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	OLV112A16A	29,400	\$4,116
211228159	ARCOAIRE	DLCURAH36ABK	EA*4X42L24A*	OLV154F20A	29,600	\$4,144
213353780	ARCOAIRE	DLCURAH24ABK	F5MA4*30L*B*		19,100	\$2,674
213353770	ARCOAIRE	DLCURAH24ABK	F5MA4*24L*B*		19,300	\$2,702
213249272	ARCOAIRE	DLCURAH24ABK	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076400	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601716B*	19,400	\$2,716
213076374	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601716B*	19,400	\$2,716
213076363	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002122A*	19,100	\$2,674
213076345	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95MSU1002122A*	19,000	\$2,660
213076118	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002120A*	19,200	\$2,688
213076106	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*95MSU1002120A*	18,500	\$2,590
212989625	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0802120A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989613	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*95MSU0802120A*	18,600	\$2,604
212989601	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95MSU0802120A*	19,100	\$2,674
212989253	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0601716A*	19,100	\$2,674
212989241	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0601716A*	19,100	\$2,674
212989229	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0601716A*	19,100	\$2,674
212989217	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0601716A*	19,400	\$2,716
212989205	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*95MSU0601716A*	18,700	\$2,618
212989193	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*95MSU0601716A*	18,900	\$2,646
212989181	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95MSU0601716A*	19,100	\$2,674
212989169	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95MSU0601716A*	19,100	\$2,674
212989157	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95MSU0601716A*	19,100	\$2,674
212989145	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*95MSU0601716A*	18,600	\$2,604
212989133	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95MSU0601716A*	19,400	\$2,716
212988761	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0401712A*	19,200	\$2,688
212988749	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0401712A*	19,200	\$2,688
212988737	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0401712A*	19,200	\$2,688
212988725	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0401712A*	19,500	\$2,730
212988713	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*95MSU0401712A*	18,600	\$2,604
212988701	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*95MSU0401712A*	18,800	\$2,632
212988689	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95MSU0401712A*	19,000	\$2,660
212988677	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95MSU0401712A*	19,100	\$2,674
212988665	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95MSU0401712A*	19,200	\$2,688
212988653	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*95MSU0401712A*	18,700	\$2,618
212988641	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95MSU0401712A*	19,500	\$2,730
212987823	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0802120A*	19,100	\$2,674
212987811	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96MSN0802120A*	18,700	\$2,618
212987799	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96MSN0802120A*	19,100	\$2,674
212987487	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0801716A*	19,200	\$2,688
212987475	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0801716A*	19,200	\$2,688
212987463	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0801716A*	19,200	\$2,688
212987451	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0801716A*	19,500	\$2,730
212987439	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96MSN0801716A*	19,800	\$2,772
212987427	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0801716A*	18,800	\$2,632
212987415	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96MSN0801716A*	19,000	\$2,660
212987403	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0801716A*	19,100	\$2,674
212987391	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0801716A*	19,200	\$2,688
212987379	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0801716A*	18,700	\$2,618
212987367	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0801716A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986971	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0601412A*	19,200	\$2,688
212986961	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0601412A*	19,200	\$2,688
212986951	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0601412A*	19,200	\$2,688
212986941	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0601412A*	19,500	\$2,730
212986931	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0601412A*	19,500	\$2,730
212986921	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0601412A*	18,800	\$2,632
212986911	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0601412A*	19,100	\$2,674
212986901	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0601412A*	19,100	\$2,674
212986891	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96MSN0601412A*	19,200	\$2,688
212986881	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0601412A*	18,700	\$2,618
212986871	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0601412A*	19,400	\$2,716
212986861	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96MSN0601412A*	19,400	\$2,716
212986647	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0401712A*	19,100	\$2,674
212986635	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401712A*	19,100	\$2,674
212986623	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401712A*	19,100	\$2,674
212986611	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401712A*	19,700	\$2,758
211289631	ARCOAIRE	DLCURAH60ABK	FVM4X60***L		37,800	\$5,292
213607741	ARCOAIRE	DLCURAH36ABK	FTMA4B48L0C*		28,800	\$4,032
213607726	ARCOAIRE	DLCURAH36ABK	FTMA4B36L0C*		29,400	\$4,116
213607681	ARCOAIRE	DLCURAH30ABK	FTMA4B36L0C*		23,600	\$3,304
213607651	ARCOAIRE	DLCURAH24ABK	FTMA4X24L0B*		19,300	\$2,702
213607636	ARCOAIRE	DLCURAH24ABK	FTMA4B36L0C*		19,100	\$2,674
213607591	ARCOAIRE	DLCURAH18ABK	FTMA4X24L0B*		12,400	\$1,736
212986599	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96MSN0401712A*	18,800	\$2,632
212986587	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401712A*	19,000	\$2,660
212986575	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96MSN0401712A*	19,200	\$2,688
212986563	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401712A*	19,200	\$2,688
212986551	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401712A*	19,200	\$2,688
212986539	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401712A*	18,900	\$2,646
212986527	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401712A*	19,500	\$2,730
212986263	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401410A*	19,200	\$2,688
212986143	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401410A*	19,500	\$2,730
212986131	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96MSN0401410A*	19,500	\$2,730
212985867	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0261410A*	19,000	\$2,660
212985857	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0261410A*	19,000	\$2,660
212985847	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0261410A*	19,100	\$2,674
212985837	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0261410A*	19,500	\$2,730
212985827	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0261410A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212985817	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0261410A*	18,800	\$2,632
212985807	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0261410A*	19,100	\$2,674
212985797	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0261410A*	19,100	\$2,674
212985787	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96MSN0261410A*	19,200	\$2,688
212985777	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0261410A*	18,700	\$2,618
212985767	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0261410A*	19,500	\$2,730
212985757	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96MSN0261410A*	19,500	\$2,730
212985363	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN1002120A*	19,100	\$2,674
212985351	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*92MSN1002120A*	18,700	\$2,618
212985339	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92MSN1002120A*	19,100	\$2,674
212985053	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0802120A*	19,000	\$2,660
212985043	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*92MSN0802120A*	18,900	\$2,646
212985033	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92MSN0802120A*	19,000	\$2,660
212984689	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0801716A*	19,100	\$2,674
212984677	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0801716A*	19,100	\$2,674
212984665	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0801716A*	19,100	\$2,674
212984653	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0801716A*	19,500	\$2,730
212984641	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*92MSN0801716A*	18,400	\$2,576
212984629	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*92MSN0801716A*	18,900	\$2,646
212984617	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92MSN0801716A*	19,000	\$2,660
212984605	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*92MSN0801716A*	19,000	\$2,660
212984593	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*92MSN0801716A*	19,100	\$2,674
212984581	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*92MSN0801716A*	18,500	\$2,590
212984569	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*92MSN0801716A*	19,300	\$2,702
212984149	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0601714A*	19,100	\$2,674
212984137	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601714A*	19,100	\$2,674
212984125	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601714A*	19,100	\$2,674
212984113	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601714A*	19,400	\$2,716
212984101	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*92MSN0601714A*	18,700	\$2,618
212984089	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601714A*	18,900	\$2,646
212984077	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92MSN0601714A*	19,100	\$2,674
212984065	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601714A*	19,100	\$2,674
212984053	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601714A*	19,100	\$2,674
212984041	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601714A*	18,700	\$2,618
212984029	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601714A*	19,400	\$2,716
212983620	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601412A*	19,200	\$2,688
212983610	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601412A*	19,200	\$2,688
212983600	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*92MSN0601412A*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983590	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601412A*	19,500	\$2,730
212983580	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*92MSN0601412A*	19,500	\$2,730
212983570	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601412A*	19,000	\$2,660
212983560	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601412A*	19,200	\$2,688
212983550	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601412A*	19,200	\$2,688
212983540	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*92MSN0601412A*	19,200	\$2,688
212983530	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601412A*	18,800	\$2,632
212983520	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601412A*	19,500	\$2,730
212983510	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*92MSN0601412A*	19,500	\$2,730
212983243	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0401712A*	19,200	\$2,688
212983232	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0401712A*	19,200	\$2,688
212983221	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0401712A*	19,200	\$2,688
212983210	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0401712A*	19,600	\$2,744
212983199	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*92MSN0401712A*	18,800	\$2,632
212983188	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*92MSN0401712A*	19,000	\$2,660
212983177	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92MSN0401712A*	19,200	\$2,688
212983166	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*92MSN0401712A*	19,200	\$2,688
212983155	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*92MSN0401712A*	19,300	\$2,702
212983144	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*92MSN0401712A*	18,800	\$2,632
212983133	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*92MSN0401712A*	19,500	\$2,730
212981812	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU1002120A*	19,100	\$2,674
212981800	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	19,200	\$2,688
212981788	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU1002120A*	19,200	\$2,688
212981776	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU1002120A*	19,500	\$2,730
212981752	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80MSU1002120A*	18,800	\$2,632
212981740	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MSU1002120A*	19,100	\$2,674
212981728	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80MSU1002120A*	19,000	\$2,660
212981716	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80MSU1002120A*	19,100	\$2,674
212981704	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80MSU1002120A*	18,700	\$2,618
212981692	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80MSU1002120A*	19,500	\$2,730
212981010	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)1102120A*	19,100	\$2,674
212980998	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	18,800	\$2,632
212980986	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	19,000	\$2,660
212980600	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902120A*	19,100	\$2,674
212980589	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	18,600	\$2,604
212980578	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	19,100	\$2,674
212980281	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902116A*	19,100	\$2,674
212980270	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980259	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	19,000	\$2,660
212979933	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0901714A*	19,100	\$2,674
212979921	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979909	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979897	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	19,500	\$2,730
212979885	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979873	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979861	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979849	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979837	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979825	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	18,600	\$2,604
212979813	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	19,400	\$2,716
212979515	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0702116A*	19,200	\$2,688
212979505	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	18,600	\$2,604
212979495	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	19,100	\$2,674
212979243	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	19,100	\$2,674
212979231	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979219	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979207	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701716A*	19,400	\$2,716
212979195	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979183	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979171	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979159	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979147	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979135	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212978646	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978635	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	18,600	\$2,604
212978624	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	19,400	\$2,716
212978214	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978202	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978190	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	19,100	\$2,674
212978178	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	19,400	\$2,716
212978166	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	19,400	\$2,716
212978154	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	18,700	\$2,618
212978142	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	19,000	\$2,660
212978130	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978118	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978106	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978094	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	19,400	\$2,716
212978082	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	19,300	\$2,702
212977698	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977686	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977674	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	19,000	\$2,660
212977662	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	19,500	\$2,730
212977650	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	19,500	\$2,730
212977638	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977626	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977614	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977602	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977590	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977578	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977566	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977001	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122B*	19,200	\$2,688
212976981	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122B*	19,100	\$2,674
212976693	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120B*	19,100	\$2,674
212976680	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002120B*	18,600	\$2,604
212976667	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120B*	19,000	\$2,660
212976419	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120B*	19,200	\$2,688
212976404	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120B*	18,600	\$2,604
212976391	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120B*	19,100	\$2,674
212976127	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716B*	18,900	\$2,646
212976114	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716B*	18,900	\$2,646
212976101	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716B*	18,900	\$2,646
212976088	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716B*	19,500	\$2,730
212976062	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716B*	19,000	\$2,660
212976049	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716B*	19,000	\$2,660
212976036	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716B*	19,000	\$2,660
212976023	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716B*	19,100	\$2,674
212976010	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0801716B*	18,800	\$2,632
212975997	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716B*	19,500	\$2,730
212975753	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412B*	19,100	\$2,674
212975742	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412B*	19,100	\$2,674
212975731	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412B*	19,000	\$2,660
212975720	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412B*	19,500	\$2,730
212975709	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412B*	19,500	\$2,730
212975698	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412B*	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975687	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412B*	19,100	\$2,674
212975676	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412B*	19,100	\$2,674
212975665	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412B*	19,100	\$2,674
212975654	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412B*	18,600	\$2,604
212975643	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412B*	19,400	\$2,716
212975632	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412B*	19,400	\$2,716
212975368	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712B*	19,200	\$2,688
212975357	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712B*	19,200	\$2,688
212975346	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712B*	19,200	\$2,688
212975335	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712B*	19,600	\$2,744
212975324	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712B*	18,900	\$2,646
212975313	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401712B*	18,900	\$2,646
212975302	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712B*	19,100	\$2,674
212975291	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712B*	19,100	\$2,674
212975280	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712B*	19,200	\$2,688
212975269	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712B*	18,800	\$2,632
212975258	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712B*	19,500	\$2,730
212975059	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410B*	19,200	\$2,688
212975046	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410B*	19,200	\$2,688
212975033	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410B*	19,100	\$2,674
212975020	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410B*	19,600	\$2,744
212975007	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410B*	19,600	\$2,744
212974994	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410B*	18,800	\$2,632
212974981	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410B*	19,200	\$2,688
212974968	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410B*	19,200	\$2,688
212974955	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410B*	19,200	\$2,688
212974942	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401410B*	18,700	\$2,618
212974929	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410B*	19,500	\$2,730
212974916	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410B*	19,500	\$2,730
212974325	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VSN1002120B*	18,900	\$2,646
212974315	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120B*	19,000	\$2,660
212974115	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120B*	19,200	\$2,688
212974105	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VSN0802120B*	18,600	\$2,604
212974095	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120B*	19,100	\$2,674
212973925	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716B*	18,900	\$2,646
212973915	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716B*	18,900	\$2,646
212973905	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716B*	18,900	\$2,646
212973895	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716B*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973875	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716B*	19,000	\$2,660
212973865	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716B*	19,000	\$2,660
212973855	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716B*	19,000	\$2,660
212973845	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716B*	19,100	\$2,674
212973835	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0801716B*	18,800	\$2,632
212973825	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716B*	19,500	\$2,730
212973635	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412B*	19,100	\$2,674
212973625	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412B*	19,100	\$2,674
212973615	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412B*	19,000	\$2,660
212973605	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412B*	19,500	\$2,730
212973595	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412B*	19,500	\$2,730
212973585	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412B*	18,800	\$2,632
212973575	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412B*	19,100	\$2,674
212973565	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412B*	19,100	\$2,674
212973555	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412B*	19,100	\$2,674
212973545	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412B*	18,600	\$2,604
212973535	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412B*	19,400	\$2,716
212973525	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412B*	19,400	\$2,716
212973285	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712B*	19,200	\$2,688
212973275	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712B*	19,200	\$2,688
212973265	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712B*	19,200	\$2,688
212973255	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712B*	19,600	\$2,744
212973245	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712B*	18,900	\$2,646
212973235	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401712B*	18,900	\$2,646
212973225	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712B*	19,100	\$2,674
212973215	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712B*	19,100	\$2,674
212973205	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712B*	19,200	\$2,688
212973195	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712B*	18,800	\$2,632
212973185	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712B*	19,500	\$2,730
212973005	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410B*	19,200	\$2,688
212972995	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410B*	19,200	\$2,688
212972985	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410B*	19,200	\$2,688
212972975	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410B*	19,500	\$2,730
212972965	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410B*	19,500	\$2,730
212972955	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410B*	19,000	\$2,660
212972945	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410B*	19,200	\$2,688
212972935	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410B*	19,200	\$2,688
212972925	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410B*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972915	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401410B*	18,800	\$2,632
212972905	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410B*	19,500	\$2,730
212972895	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410B*	19,500	\$2,730
212972426	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122B*	19,200	\$2,688
212972414	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122B*	18,800	\$2,632
212972402	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122B*	19,100	\$2,674
212972146	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120B*	19,100	\$2,674
212972135	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80VTL0902120B*	18,900	\$2,646
212972124	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120B*	19,100	\$2,674
212971735	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716B*	19,100	\$2,674
212971724	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716B*	19,100	\$2,674
212971713	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716B*	19,100	\$2,674
212971702	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716B*	19,500	\$2,730
212971691	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80VTL0701716B*	18,700	\$2,618
212971680	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716B*	18,700	\$2,618
212971669	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716B*	19,100	\$2,674
212971658	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716B*	19,100	\$2,674
212971647	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716B*	19,100	\$2,674
212971636	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80VTL0701716B*	18,600	\$2,604
212971625	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716B*	19,400	\$2,716
212971246	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412B*	19,100	\$2,674
212971234	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412B*	19,100	\$2,674
212971222	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412B*	19,000	\$2,660
212971210	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412B*	19,500	\$2,730
212971198	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412B*	19,500	\$2,730
212971186	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412B*	18,700	\$2,618
212971174	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412B*	19,000	\$2,660
212971162	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412B*	19,100	\$2,674
212969839	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412B*	19,100	\$2,674
212969829	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412B*	19,100	\$2,674
212969819	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412B*	19,000	\$2,660
212969809	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412B*	19,500	\$2,730
212969799	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412B*	19,500	\$2,730
212969789	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451412B*	18,700	\$2,618
212969779	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412B*	19,000	\$2,660
212969769	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412B*	19,100	\$2,674
212969759	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412B*	19,100	\$2,674
212969749	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80VSL0451412B*	18,500	\$2,590

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
2112969739	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412B*	19,300	\$2,702
211245983	ARCOAIRE	DLCURAH24ABK	FVM4X36***L		19,000	\$2,660
211245973	ARCOAIRE	DLCURAH24ABK	FVM4X24***L		19,000	\$2,660
211245962	ARCOAIRE	DLCURAH24ABK	FM(C,U)4Z36**AL*		19,300	\$2,702
211245951	ARCOAIRE	DLCURAH24ABK	FM(C,U)4Z30**AL*		19,300	\$2,702
211245940	ARCOAIRE	DLCURAH24ABK	FM(C,U)4Z24**AL*		19,500	\$2,730
211245929	ARCOAIRE	DLCURAH24ABK	FM(C,U)4X36**AL*		19,900	\$2,786
211245918	ARCOAIRE	DLCURAH24ABK	FM(C,U)4X30**AL*		19,900	\$2,786
211245907	ARCOAIRE	DLCURAH24ABK	FMA4X36**AL*		19,600	\$2,744
211245896	ARCOAIRE	DLCURAH24ABK	FMA4X30**AL*		19,600	\$2,744
211245885	ARCOAIRE	DLCURAH24ABK	FMA4X24**AL*		19,600	\$2,744
211245863	ARCOAIRE	DLCURAH24ABK	FMA4P24**AL*		19,900	\$2,786
211245852	ARCOAIRE	DLCURAH24ABK	FXM4X36**AL		18,500	\$2,590
211245841	ARCOAIRE	DLCURAH24ABK	FXM4X30**AL		19,100	\$2,674
211245830	ARCOAIRE	DLCURAH24ABK	FXM4X24**AL		19,100	\$2,674
211245819	ARCOAIRE	DLCURAH24ABK	FEM4X30**BL		19,100	\$2,674
211245807	ARCOAIRE	DLCURAH24ABK	FEM4X24**CL		19,000	\$2,660
211245795	ARCOAIRE	DLCURAH24ABK	FEM4P30**AL		19,100	\$2,674
211245784	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	OLV112A16A	19,300	\$2,702
211245775	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	OMV112K14A	19,200	\$2,688
211245766	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	OLV098A12*	18,900	\$2,646
211245757	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	OMV098J12*	19,000	\$2,660
211245747	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0601716A	19,300	\$2,702
211245736	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0802120A	19,100	\$2,674
211245725	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0401712A*	19,100	\$2,674
211245714	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0801716A*	19,500	\$2,730
211245703	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0601714A*	19,400	\$2,716
211245692	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN1002120A*	19,300	\$2,702
211245681	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0802120A*	19,300	\$2,702
211245670	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0801716A*	19,100	\$2,674
211245659	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0601714A*	19,100	\$2,674
211245647	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)1102120A*	19,400	\$2,716
211245635	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0902120A*	19,300	\$2,702
211245623	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0901714A*	19,200	\$2,688
211245611	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0702116A*	19,100	\$2,674
211245599	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701712A*	19,200	\$2,688
211245587	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0451712A*	19,100	\$2,674
211245577	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245567	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120A*	19,000	\$2,660
211245557	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120A*	18,900	\$2,646
211245547	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0601714A*	19,100	\$2,674
211245536	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0401712A*	19,400	\$2,716
211245526	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716A*	19,100	\$2,674
211245516	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716A*	19,100	\$2,674
211245505	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0802120A*	19,300	\$2,702
211245495	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712A*	19,000	\$2,660
211245485	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120A*	19,000	\$2,660
211245472	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0401712A*	19,000	\$2,660
211245461	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0601716A*	19,100	\$2,674
211245451	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0902120A*	19,000	\$2,660
211245442	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0702120A*	19,300	\$2,702
211245433	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0701716A*	19,000	\$2,660
211245424	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0451716A*	19,200	\$2,688
211245379	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122A*	18,900	\$2,646
211245369	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701716A*	19,400	\$2,716
211245358	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0401712A*	19,000	\$2,660
211245348	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716A*	19,100	\$2,674
211245339	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712A*	19,000	\$2,660
211245330	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN1002120A*	19,000	\$2,660
211245321	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120A*	19,000	\$2,660
211245312	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0601714A*	18,900	\$2,646
211245276	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV112K14A	19,200	\$2,688
211245267	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	OLV098A12*	18,900	\$2,646
211245258	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV098J12*	19,000	\$2,660
211245248	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0601716A	19,300	\$2,702
211245236	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211245225	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401712A*	19,100	\$2,674
211245214	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401410A*	19,400	\$2,716
211245203	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0801716A*	19,500	\$2,730
211245192	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601714A*	19,400	\$2,716
211245181	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0801716A*	19,100	\$2,674
211245170	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601714A*	19,100	\$2,674
211245159	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601412A*	18,900	\$2,646
211245147	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211245135	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211245123	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451712A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245111	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211245101	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601714A*	19,100	\$2,674
211245090	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0261410A*	18,900	\$2,646
211245080	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412A*	19,000	\$2,660
211245070	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410A*	19,000	\$2,660
211245059	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601412A*	19,400	\$2,716
211245048	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401712A*	19,400	\$2,716
211245037	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401410A*	19,500	\$2,730
211245027	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716A*	19,100	\$2,674
211245017	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716A*	19,100	\$2,674
211245007	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712A*	19,000	\$2,660
211244993	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412A*	19,100	\$2,674
211244982	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0401712A*	19,000	\$2,660
211244971	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0601716A*	19,100	\$2,674
211244961	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0701716A*	19,000	\$2,660
211244952	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451716A*	19,200	\$2,688
211244924	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244913	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0401712A*	19,000	\$2,660
211244903	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716A*	19,100	\$2,674
211244894	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412A*	19,000	\$2,660
211244885	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712A*	19,000	\$2,660
211244876	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410A*	19,000	\$2,660
211244867	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601714A*	18,900	\$2,646
211244849	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412A*	18,900	\$2,646
211244840	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	OMV112K14A	19,200	\$2,688
211244831	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	OLV098A12*	18,900	\$2,646
211244822	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	OMV098J12*	19,000	\$2,660
213372123	ARCOAIRE	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372119	ARCOAIRE	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
211244812	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0601716A	19,300	\$2,702
211244800	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211244789	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401712A*	19,100	\$2,674
211244778	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401410A*	19,400	\$2,716
211244767	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0801716A*	19,500	\$2,730
211244756	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601714A*	19,400	\$2,716
211244745	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0801716A*	19,100	\$2,674
211244734	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601714A*	19,100	\$2,674
211244723	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601412A*	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244711	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211244699	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211244687	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211244675	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211244665	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601714A*	19,100	\$2,674
211244654	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0261410A*	18,900	\$2,646
211244644	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412A*	19,000	\$2,660
211244634	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410A*	19,000	\$2,660
211244623	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601412A*	19,400	\$2,716
211244612	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401712A*	19,400	\$2,716
211244601	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401410A*	19,500	\$2,730
211244591	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716A*	19,100	\$2,674
211244581	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716A*	19,100	\$2,674
211244571	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712A*	19,000	\$2,660
211244557	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412A*	19,100	\$2,674
211244546	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0401712A*	19,000	\$2,660
211244535	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0601716A*	19,100	\$2,674
211244525	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0701716A*	19,000	\$2,660
211244516	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451716A*	19,200	\$2,688
211244488	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244477	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0401712A*	19,000	\$2,660
211244467	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716A*	19,100	\$2,674
211244458	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412A*	19,000	\$2,660
211244449	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712A*	19,000	\$2,660
211244440	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410A*	19,000	\$2,660
211244431	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601714A*	18,900	\$2,646
211244413	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412A*	18,900	\$2,646
211244402	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	19,100	\$2,674
211244391	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0401410A*	19,400	\$2,716
211244380	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0601412A*	18,900	\$2,646
211244368	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	19,300	\$2,702
211244357	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0261410A*	19,500	\$2,730
211244347	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412A*	19,000	\$2,660
211244337	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410A*	19,100	\$2,674
211244326	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0601412A*	19,400	\$2,716
211244315	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0401410A*	19,500	\$2,730
211244303	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412A*	19,100	\$2,674
211244293	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244284	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410A*	19,100	\$2,674
211244275	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412A*	19,200	\$2,688
211244266	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	OMV112K14A	19,700	\$2,758
211244257	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	OLV098A12*	19,300	\$2,702
211244248	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	OMV098J12*	19,400	\$2,716
211244238	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0601716A	19,600	\$2,744
211244226	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	19,500	\$2,730
211244215	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401712A*	19,500	\$2,730
211244204	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401410A*	19,700	\$2,758
211244193	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0801716A*	19,800	\$2,772
211244182	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601714A*	19,700	\$2,758
211244171	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0801716A*	19,400	\$2,716
211244160	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601714A*	19,500	\$2,730
211244149	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601412A*	19,600	\$2,744
211244137	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0901714A*	19,500	\$2,730
211244125	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	19,500	\$2,730
211244113	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	19,400	\$2,716
211244101	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	19,600	\$2,744
211244091	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601714A*	19,400	\$2,716
211244080	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0261410A*	19,900	\$2,786
211244070	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412A*	19,300	\$2,702
211244060	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410A*	19,500	\$2,730
211244049	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601412A*	19,700	\$2,758
211244038	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401712A*	19,700	\$2,758
211244027	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401410A*	19,800	\$2,772
211244017	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716A*	19,400	\$2,716
211244007	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716A*	19,500	\$2,730
211243997	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712A*	19,700	\$2,758
211243983	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412A*	19,500	\$2,730
211243972	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0401712A*	19,300	\$2,702
211243961	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0601716A*	19,400	\$2,716
211243951	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0701716A*	19,400	\$2,716
211243942	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451716A*	19,500	\$2,730
211243914	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701716A*	19,700	\$2,758
211243903	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0401712A*	19,300	\$2,702
211243893	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716A*	19,500	\$2,730
211243884	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412A*	19,300	\$2,702
211243875	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712A*	19,700	\$2,758

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243866	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410A*	19,500	\$2,730
211243857	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601714A*	19,500	\$2,730
211243839	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412A*	19,500	\$2,730
211243828	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	19,500	\$2,730
211243817	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0401410A*	19,700	\$2,758
211243806	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0601412A*	19,600	\$2,744
211243794	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	19,600	\$2,744
211243783	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0261410A*	19,900	\$2,786
211243773	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412A*	19,300	\$2,702
211243763	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410A*	19,500	\$2,730
211243752	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0601412A*	19,700	\$2,758
211243741	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0401410A*	19,800	\$2,772
211243729	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412A*	19,500	\$2,730
211243719	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412A*	19,300	\$2,702
211243710	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410A*	19,500	\$2,730
211243701	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412A*	19,500	\$2,730
211243674	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	OLV098A12*	18,400	\$2,576
211243485	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122A*	18,500	\$2,590
211243465	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120A*	18,400	\$2,576
211243403	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712A*	18,500	\$2,590
211243287	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002122A*	18,400	\$2,576
211243247	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712A*	18,500	\$2,590
211243175	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	OLV098A12*	18,700	\$2,618
211243166	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	OMV098J12*	18,800	\$2,632
211243144	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	18,900	\$2,646
211243133	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*92ESN0401712A*	18,900	\$2,646
211243089	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*92ESN0801716A*	18,900	\$2,646
211243078	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*92ESN0601714A*	18,900	\$2,646
211243031	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0451712A*	18,900	\$2,646
211243009	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601714A*	18,900	\$2,646
211242988	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412A*	18,700	\$2,618
211242978	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410A*	18,900	\$2,646
211242935	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716A*	18,800	\$2,632
211242925	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716A*	18,900	\$2,646
211242901	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412A*	18,900	\$2,646
211242890	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80ESU0401712A*	18,700	\$2,618
211242879	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*95ESU0601716A*	18,900	\$2,646
211242869	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80VSL0701716A*	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242860	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451716A*	19,000	\$2,660
211242821	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*95ESU0401712A*	18,700	\$2,618
211242811	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716A*	18,900	\$2,646
211242802	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412A*	18,700	\$2,618
211242784	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410A*	18,900	\$2,646
211242775	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601714A*	19,000	\$2,660
211242748	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	OLV112A16A	19,200	\$2,688
211242739	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	OMV112K14A	19,100	\$2,674
211242730	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	OLV098A12*	18,900	\$2,646
211242721	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	OMV098J12*	18,900	\$2,646
211242711	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ESU0601716A	19,300	\$2,702
211242700	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ESU0802120A	19,100	\$2,674
211242689	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92ESN0401712A*	19,100	\$2,674
211242678	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95ESN0801716A*	19,400	\$2,716
211242667	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95ESN0601714A*	19,300	\$2,702
211242656	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92ESN1002120A*	19,300	\$2,702
211242645	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92ESN0802120A*	19,300	\$2,702
211242634	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92ESN0801716A*	19,100	\$2,674
211242623	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*92ESN0601714A*	19,100	\$2,674
211242611	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	19,400	\$2,716
211242599	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	19,200	\$2,688
211242587	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242575	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	19,100	\$2,674
211242563	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	18,800	\$2,632
211242551	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242541	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122A*	18,900	\$2,646
211242531	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120A*	19,000	\$2,660
211242521	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120A*	18,900	\$2,646
211242511	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0601714A*	19,100	\$2,674
211242500	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95ESN0401712A*	19,300	\$2,702
211242490	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716A*	19,000	\$2,660
211242480	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716A*	19,100	\$2,674
211242469	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95ESN0802120A*	19,300	\$2,702
211242459	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712A*	19,000	\$2,660
211242449	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120A*	19,000	\$2,660
211242436	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ESU0401712A*	18,900	\$2,646
211242425	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95ESU0601716A*	19,100	\$2,674
211242415	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VSL0902120A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242406	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VSL0702120A*	19,300	\$2,702
211242397	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VSL0701716A*	19,000	\$2,660
211242388	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80VSL0451716A*	18,800	\$2,632
211242343	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122A*	18,900	\$2,646
211242333	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	19,400	\$2,716
211242322	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*95ESU0401712A*	18,900	\$2,646
211242312	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716A*	19,100	\$2,674
211242303	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712A*	19,000	\$2,660
211242294	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120A*	18,900	\$2,646
211242285	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120A*	19,000	\$2,660
211242276	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0601714A*	18,900	\$2,646
211242240	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	OMV112K14A	19,200	\$2,688
211242231	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	OLV098A12*	18,900	\$2,646
211242222	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	OMV098J12*	18,900	\$2,646
211242212	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80ESU0601716A	19,300	\$2,702
211242200	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	19,100	\$2,674
211242189	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401712A*	19,100	\$2,674
211242178	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401410A*	19,400	\$2,716
211242167	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0801716A*	19,400	\$2,716
211242156	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601714A*	19,300	\$2,702
211242145	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0801716A*	19,100	\$2,674
211242134	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601714A*	19,100	\$2,674
211242123	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601412A*	18,800	\$2,632
211242111	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242099	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211242087	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242075	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	19,300	\$2,702
211242065	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601714A*	19,100	\$2,674
211242054	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0261410A*	18,900	\$2,646
211242044	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412A*	18,900	\$2,646
211242034	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410A*	18,900	\$2,646
211242023	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601412A*	19,300	\$2,702
211242012	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401712A*	19,300	\$2,702
211242001	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401410A*	19,400	\$2,716
211241991	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716A*	19,000	\$2,660
211241981	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716A*	19,100	\$2,674
211241971	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712A*	18,900	\$2,646
211241957	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241946	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80ESU0401712A*	18,900	\$2,646
211241935	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95ESU0601716A*	19,100	\$2,674
211241925	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80VSL0701716A*	19,000	\$2,660
211241916	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451716A*	19,100	\$2,674
211241888	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241877	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*95ESU0401712A*	18,900	\$2,646
211241867	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716A*	19,100	\$2,674
211241858	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412A*	18,900	\$2,646
211241849	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712A*	18,900	\$2,646
211241840	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410A*	18,900	\$2,646
211241831	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601714A*	18,900	\$2,646
211241813	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412A*	18,800	\$2,632
211241804	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	OMV112K14A	19,200	\$2,688
211241795	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	OLV098A12*	18,900	\$2,646
211241786	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	OMV098J12*	19,000	\$2,660
211241776	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80ESU0601716A	19,300	\$2,702
211241764	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241753	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401712A*	19,100	\$2,674
211241742	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401410A*	19,400	\$2,716
211241731	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0801716A*	19,500	\$2,730
211241720	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601714A*	19,400	\$2,716
211241709	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0801716A*	19,100	\$2,674
211241698	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601714A*	19,200	\$2,688
211241687	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601412A*	18,900	\$2,646
211241675	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211241663	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211241651	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211241639	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	19,400	\$2,716
211241629	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601714A*	19,100	\$2,674
211241618	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0261410A*	18,900	\$2,646
211241608	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412A*	19,000	\$2,660
211241598	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410A*	19,000	\$2,660
211241587	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601412A*	19,400	\$2,716
211241576	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401712A*	19,400	\$2,716
211241565	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401410A*	19,500	\$2,730
211241555	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716A*	19,100	\$2,674
211241545	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716A*	19,200	\$2,688
211241535	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241521	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412A*	19,200	\$2,688
211241510	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80ESU0401712A*	19,000	\$2,660
211241499	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95ESU0601716A*	19,100	\$2,674
211241489	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80VSL0701716A*	19,100	\$2,674
211241480	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451716A*	19,200	\$2,688
211241452	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241441	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*95ESU0401712A*	19,000	\$2,660
211241431	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716A*	19,200	\$2,688
211241422	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412A*	19,000	\$2,660
211241413	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712A*	19,000	\$2,660
211241404	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410A*	19,000	\$2,660
211241395	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601714A*	18,900	\$2,646
211241377	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412A*	18,900	\$2,646
211241366	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241355	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*92ESN0401410A*	19,400	\$2,716
211241344	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*92ESN0601412A*	18,900	\$2,646
211241332	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	19,300	\$2,702
211241321	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*95ESN0261410A*	19,600	\$2,744
211241311	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412A*	19,000	\$2,660
211241301	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410A*	19,100	\$2,674
211241290	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*95ESN0601412A*	19,400	\$2,716
211241279	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*95ESN0401410A*	19,500	\$2,730
211241267	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*80VTL0451412A*	19,100	\$2,674
211241257	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412A*	19,000	\$2,660
211241248	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410A*	19,100	\$2,674
211241239	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412A*	19,200	\$2,688
211241221	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	OLV098A12*	18,600	\$2,604
211241212	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	OMV098J12*	18,600	\$2,604
211241113	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*92ESN0601412A*	18,500	\$2,590
211241034	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412A*	18,600	\$2,604
211240961	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712A*	18,600	\$2,604
211240936	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80ESU0401712A*	18,600	\$2,604
211240915	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*80VSL0701716A*	18,700	\$2,618
211240867	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*95ESU0401712A*	18,600	\$2,604
211240848	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412A*	18,600	\$2,604
211240839	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712A*	18,600	\$2,604
211240794	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	OMV112K14A	19,500	\$2,730
211240785	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	OLV098A12*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240776	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	OMV098J12*	19,300	\$2,702
211240766	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80ESU0601716A	19,600	\$2,744
211240754	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240743	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401712A*	19,400	\$2,716
211240732	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401410A*	19,700	\$2,758
211240721	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0801716A*	19,700	\$2,758
211240710	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601714A*	19,600	\$2,744
211240699	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0801716A*	19,400	\$2,716
211240688	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601714A*	19,400	\$2,716
211240677	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601412A*	19,200	\$2,688
211240665	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0901714A*	19,500	\$2,730
211240653	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	19,500	\$2,730
211240641	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	19,400	\$2,716
211240629	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240619	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601714A*	19,400	\$2,716
211240608	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0261410A*	19,800	\$2,772
211240598	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412A*	19,300	\$2,702
211240588	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410A*	19,400	\$2,716
211240577	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601412A*	19,600	\$2,744
211240566	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401712A*	19,700	\$2,758
211240555	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401410A*	19,700	\$2,758
211240545	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716A*	19,300	\$2,702
211240535	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716A*	19,400	\$2,716
211240525	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712A*	19,300	\$2,702
211240511	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80VTL0451412A*	19,400	\$2,716
211240500	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80ESU0401712A*	19,300	\$2,702
211240489	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95ESU0601716A*	19,400	\$2,716
211240479	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80VSL0701716A*	19,300	\$2,702
211240470	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451716A*	19,400	\$2,716
211240442	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701716A*	19,700	\$2,758
211240431	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*95ESU0401712A*	19,300	\$2,702
211240421	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716A*	19,400	\$2,716
211240412	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412A*	19,300	\$2,702
211240403	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712A*	19,300	\$2,702
211240394	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410A*	19,400	\$2,716
211240385	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601714A*	19,500	\$2,730
211240367	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412A*	19,500	\$2,730
211240356	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240345	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*92ESN0401410A*	19,700	\$2,758
211240334	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*92ESN0601412A*	19,600	\$2,744
211240322	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240311	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*95ESN0261410A*	19,800	\$2,772
211240301	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412A*	19,300	\$2,702
211240291	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410A*	19,400	\$2,716
211240280	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*95ESN0601412A*	19,600	\$2,744
211240269	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*95ESN0401410A*	19,700	\$2,758
211240257	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*80VTL0451412A*	19,400	\$2,716
211240247	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412A*	19,300	\$2,702
211240238	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410A*	19,400	\$2,716
211240229	ARCOAIRE	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412A*	19,500	\$2,730
211239224	ARCOAIRE	DLCURAH24ABK	FJMA4*24L*B*		19,200	\$2,688
213353740	ARCOAIRE	DLCURAH18ABK	F5MA4*24L*B*		12,500	\$1,750
213353730	ARCOAIRE	DLCURAH18ABK	F5MA4*18L*A*		12,800	\$1,792
213249250	ARCOAIRE	DLCURAH18ABK	FEVA0024**+NAVA43601CK		12,300	\$1,722
213076387	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601716B*	12,400	\$1,736
212989325	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0601716A*	12,200	\$1,708
212989313	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0601716A*	12,300	\$1,722
212989301	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*95MSU0601716A*	12,200	\$1,708
212989289	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*95MSU0601716A*	12,000	\$1,680
212989277	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*95MSU0601716A*	12,300	\$1,722
212989265	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*95MSU0601716A*	12,100	\$1,694
212988833	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0401712A*	12,200	\$1,708
212988821	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0401712A*	12,500	\$1,750
212988809	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*95MSU0401712A*	12,200	\$1,708
212988797	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*95MSU0401712A*	12,000	\$1,680
212988785	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*95MSU0401712A*	12,300	\$1,722
212988773	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*95MSU0401712A*	12,100	\$1,694
212987559	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0801716A*	12,200	\$1,708
212987547	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0801716A*	12,500	\$1,750
212987535	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0801716A*	12,100	\$1,694
212987523	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96MSN0801716A*	12,200	\$1,708
212987511	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0801716A*	12,500	\$1,750
212987499	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0801716A*	12,300	\$1,722
212987081	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0601412A*	12,200	\$1,708
212987071	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0601412A*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212987061	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0601412A*	12,300	\$1,722
212987051	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0601412A*	12,300	\$1,722
212987041	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0601412A*	12,500	\$1,750
212987031	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0601412A*	12,200	\$1,708
212987021	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96MSN0601412A*	12,200	\$1,708
212987011	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96MSN0601412A*	12,000	\$1,680
212987001	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0601412A*	12,300	\$1,722
212986991	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96MSN0601412A*	12,300	\$1,722
212986981	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0601412A*	12,100	\$1,694
212986719	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401712A*	12,300	\$1,722
212986707	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401712A*	12,500	\$1,750
212986695	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401712A*	12,300	\$1,722
212986683	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96MSN0401712A*	12,100	\$1,694
212986671	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401712A*	12,300	\$1,722
212986659	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401712A*	12,100	\$1,694
212986383	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401410A*	12,300	\$1,722
212986371	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0401410A*	12,300	\$1,722
212986359	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401410A*	12,400	\$1,736
212986347	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0401410A*	12,400	\$1,736
212986335	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0401410A*	12,400	\$1,736
212986323	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401410A*	12,300	\$1,722
212986311	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96MSN0401410A*	12,300	\$1,722
212986299	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401410A*	12,400	\$1,736
212986287	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96MSN0401410A*	12,400	\$1,736
212986275	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401410A*	12,200	\$1,708
212985977	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0261410A*	12,300	\$1,722
212985967	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0261410A*	12,200	\$1,708
212985957	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0261410A*	12,300	\$1,722
212985947	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0261410A*	12,300	\$1,722
212985937	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0261410A*	12,500	\$1,750
212985927	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0261410A*	12,200	\$1,708
212985917	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96MSN0261410A*	12,200	\$1,708
212985907	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96MSN0261410A*	12,100	\$1,694
212985897	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0261410A*	12,300	\$1,722
212985887	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96MSN0261410A*	12,300	\$1,722
212985877	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0261410A*	12,100	\$1,694
212984761	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0801716A*	12,100	\$1,694
212984749	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0801716A*	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984737	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*92MSN0801716A*	12,400	\$1,736
212984725	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*92MSN0801716A*	12,200	\$1,708
212984713	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*92MSN0801716A*	12,500	\$1,750
212984701	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*92MSN0801716A*	12,300	\$1,722
212984221	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601714A*	12,300	\$1,722
212984209	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601714A*	12,400	\$1,736
212984197	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601714A*	12,300	\$1,722
212984185	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601714A*	12,200	\$1,708
212984173	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601714A*	12,400	\$1,736
212984161	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601714A*	12,200	\$1,708
212983731	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601412A*	12,200	\$1,708
212983721	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*92MSN0601412A*	12,200	\$1,708
212983710	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601412A*	12,400	\$1,736
212983700	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*92MSN0601412A*	12,400	\$1,736
212983690	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*92MSN0601412A*	12,400	\$1,736
212983680	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601412A*	12,200	\$1,708
212983670	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*92MSN0601412A*	12,300	\$1,722
212983660	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601412A*	12,000	\$1,680
212983650	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601412A*	12,400	\$1,736
212983640	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*92MSN0601412A*	12,400	\$1,736
212983630	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601412A*	12,100	\$1,694
212983309	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0401712A*	12,300	\$1,722
212983298	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0401712A*	12,400	\$1,736
212983287	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*92MSN0401712A*	12,200	\$1,708
212983276	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*92MSN0401712A*	12,100	\$1,694
212983265	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*92MSN0401712A*	12,300	\$1,722
212983254	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*92MSN0401712A*	12,200	\$1,708
212981884	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU1002120A*	12,300	\$1,722
212981872	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU1002120A*	12,600	\$1,764
212981860	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80MSU1002120A*	12,300	\$1,722
212981848	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80MSU1002120A*	12,100	\$1,694
212981836	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80MSU1002120A*	12,300	\$1,722
212981824	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80MSU1002120A*	12,200	\$1,708
212980005	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	12,300	\$1,722
212979993	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	12,400	\$1,736
212979981	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	12,300	\$1,722
212979969	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212979957	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979945	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212978800	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978789	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978778	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978767	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978756	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978745	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978348	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	12,200	\$1,708
212978336	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	12,200	\$1,708
212978324	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	12,400	\$1,736
212978312	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978300	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978286	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	12,100	\$1,694
212978274	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	12,300	\$1,722
212978262	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212978250	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978238	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978226	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212977830	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	12,300	\$1,722
212977818	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	12,300	\$1,722
212977806	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	12,400	\$1,736
212977794	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977782	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977770	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977758	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977746	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	12,100	\$1,694
212977734	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	12,400	\$1,736
212977722	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977710	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0451412A*	12,200	\$1,708
212975841	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716B*	12,200	\$1,708
212975828	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716B*	12,500	\$1,750
212975815	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716B*	12,200	\$1,708
212975802	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716B*	12,000	\$1,680
212975789	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716B*	12,300	\$1,722
212975776	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716B*	12,100	\$1,694
212975489	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412B*	12,200	\$1,708
212975478	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412B*	12,200	\$1,708
212975467	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412B*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975456	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412B*	12,400	\$1,736
212975445	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412B*	12,400	\$1,736
212975434	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412B*	12,200	\$1,708
212975423	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412B*	12,200	\$1,708
212975412	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412B*	12,000	\$1,680
212975401	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412B*	12,300	\$1,722
212975390	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412B*	12,200	\$1,708
212975379	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412B*	12,100	\$1,694
212975126	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712B*	12,200	\$1,708
212975115	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712B*	12,500	\$1,750
212975104	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712B*	12,200	\$1,708
212975093	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712B*	12,100	\$1,694
212975082	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712B*	12,300	\$1,722
212975071	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712B*	12,100	\$1,694
212974747	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410B*	12,200	\$1,708
212974734	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410B*	12,200	\$1,708
212974721	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410B*	12,400	\$1,736
212974708	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410B*	12,400	\$1,736
212974695	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410B*	12,400	\$1,736
212974682	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410B*	12,200	\$1,708
212974669	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410B*	12,200	\$1,708
212974656	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410B*	12,100	\$1,694
212974643	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410B*	12,300	\$1,722
212974630	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410B*	12,400	\$1,736
212974617	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410B*	12,100	\$1,694
212973705	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716B*	12,200	\$1,708
212973695	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716B*	12,500	\$1,750
212973685	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716B*	12,200	\$1,708
212973675	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716B*	12,000	\$1,680
212973665	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716B*	12,300	\$1,722
212973655	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716B*	12,100	\$1,694
212973395	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412B*	12,200	\$1,708
212973385	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412B*	12,200	\$1,708
212973375	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412B*	12,400	\$1,736
212973365	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412B*	12,400	\$1,736
212973355	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412B*	12,400	\$1,736
212973345	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412B*	12,200	\$1,708
212973335	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412B*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973325	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412B*	12,000	\$1,680
212973315	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412B*	12,300	\$1,722
212973305	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412B*	12,200	\$1,708
212973295	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412B*	12,100	\$1,694
212973065	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712B*	12,200	\$1,708
212973055	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712B*	12,500	\$1,750
212973045	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712B*	12,200	\$1,708
212973035	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712B*	12,100	\$1,694
212973025	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712B*	12,300	\$1,722
212973015	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712B*	12,100	\$1,694
212972765	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410B*	12,200	\$1,708
212972755	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410B*	12,200	\$1,708
212972745	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410B*	12,400	\$1,736
212972735	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410B*	12,400	\$1,736
212972725	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410B*	12,400	\$1,736
212972715	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410B*	12,200	\$1,708
212972705	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410B*	12,200	\$1,708
212972695	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410B*	12,100	\$1,694
212972685	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410B*	12,300	\$1,722
212972675	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410B*	12,300	\$1,722
212972665	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410B*	12,100	\$1,694
212971493	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716B*	12,300	\$1,722
212971482	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716B*	12,400	\$1,736
212971471	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716B*	12,300	\$1,722
212971460	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716B*	12,100	\$1,694
212971449	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716B*	12,400	\$1,736
212971438	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716B*	12,200	\$1,708
212969599	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412B*	12,200	\$1,708
212969589	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412B*	12,200	\$1,708
212969579	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412B*	12,500	\$1,750
212969569	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412B*	12,500	\$1,750
212969559	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412B*	12,500	\$1,750
212969549	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412B*	12,400	\$1,736
212969539	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412B*	12,200	\$1,708
212969529	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412B*	12,500	\$1,750
212969519	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412B*	12,500	\$1,750
212969509	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412B*	12,300	\$1,722
211265035	ARCOAIRE	DLCURAH18ABK	FVM4X24***L		12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211265014	ARCOAIRE	DLCURAH18ABK	FM(C,U)4Z30**AL*		12,400	\$1,736
211264992	ARCOAIRE	DLCURAH18ABK	FM(C,U)4Z24**AL*		12,500	\$1,750
211264970	ARCOAIRE	DLCURAH18ABK	FM(C,U)4Z18**AL*		12,500	\$1,750
211264948	ARCOAIRE	DLCURAH18ABK	FMA4X24**AL*		12,400	\$1,736
211264926	ARCOAIRE	DLCURAH18ABK	FMA4X18**AL*		12,400	\$1,736
211264905	ARCOAIRE	DLCURAH18ABK	FXM4X30**AL		12,400	\$1,736
211264883	ARCOAIRE	DLCURAH18ABK	FXM4X24**AL		12,400	\$1,736
211264762	ARCOAIRE	DLCURAH18ABK	FEM4P18**AL		12,300	\$1,722
211264738	ARCOAIRE	DLCURAH18ABK	FJMA4*18L*A*		12,700	\$1,778
211264712	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	OMV112K14A	12,600	\$1,764
211264694	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	OLV098A12*	12,600	\$1,764
211264676	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	OMV098J12*	12,600	\$1,764
211264656	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0601716A	12,700	\$1,778
211264632	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	12,300	\$1,722
211264609	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401712A*	12,500	\$1,750
211264588	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401410A*	12,500	\$1,750
211264566	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601714A*	12,300	\$1,722
211264544	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601412A*	12,500	\$1,750
211264520	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	12,500	\$1,750
211264496	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	12,400	\$1,736
211264471	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	12,500	\$1,750
211264451	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601714A*	12,400	\$1,736
211264427	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0261410A*	12,600	\$1,764
211264405	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412A*	12,400	\$1,736
211264374	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410A*	12,300	\$1,722
211264310	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0601412A*	12,400	\$1,736
211264275	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401712A*	12,200	\$1,708
211264239	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401410A*	12,400	\$1,736
211264206	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716A*	12,200	\$1,708
211264172	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716A*	12,200	\$1,708
211264140	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712A*	12,400	\$1,736
211264109	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0451412A*	12,300	\$1,722
211264087	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0401712A*	12,700	\$1,778
211264067	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0701716A*	12,200	\$1,708
211264049	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451716A*	12,300	\$1,722
211264004	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESU0401712A*	12,400	\$1,736
211263984	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716A*	12,200	\$1,708
211263966	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263949	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712A*	12,400	\$1,736
211263930	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410A*	12,300	\$1,722
211263912	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601714A*	12,400	\$1,736
211263875	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412A*	12,400	\$1,736
211263852	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	12,300	\$1,722
211263829	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0401410A*	12,500	\$1,750
211263808	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0601412A*	12,500	\$1,750
211263783	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	12,500	\$1,750
211263760	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0261410A*	12,500	\$1,750
211263740	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412A*	12,400	\$1,736
211263719	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410A*	12,200	\$1,708
211263694	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0601412A*	12,400	\$1,736
211263671	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0401410A*	12,400	\$1,736
211263646	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*80VTL0451412A*	12,300	\$1,722
211263625	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412A*	12,400	\$1,736
211263606	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410A*	12,200	\$1,708
211263588	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412A*	12,400	\$1,736
211263570	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	OMV112K14A	12,800	\$1,792
211263551	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	OLV098A12*	12,700	\$1,778
211263532	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	OMV098J12*	12,800	\$1,792
211263511	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0601716A	12,800	\$1,792
211263486	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	12,400	\$1,736
211263463	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401712A*	12,600	\$1,764
211263440	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401410A*	12,600	\$1,764
211263417	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0801716A*	12,900	\$1,806
211263394	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601714A*	12,400	\$1,736
211263372	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601412A*	12,600	\$1,764
211263347	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	12,600	\$1,764
211263322	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	12,900	\$1,806
211263297	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	12,600	\$1,764
211263276	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601714A*	12,500	\$1,750
211263250	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0261410A*	12,700	\$1,778
211263230	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412A*	12,500	\$1,750
211263209	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410A*	12,300	\$1,722
211263185	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0601412A*	12,500	\$1,750
211263162	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401712A*	12,300	\$1,722
211263139	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401410A*	12,500	\$1,750
211263123	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263103	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716A*	12,300	\$1,722
211263082	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712A*	12,500	\$1,750
211263054	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0451412A*	12,400	\$1,736
211263032	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0401712A*	12,700	\$1,778
211263011	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0601716A*	12,900	\$1,806
211262991	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0701716A*	12,300	\$1,722
211262973	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451716A*	12,400	\$1,736
211262918	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0401712A*	12,400	\$1,736
211262899	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716A*	12,300	\$1,722
211262881	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412A*	12,500	\$1,750
211262864	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712A*	12,500	\$1,750
211262846	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410A*	12,300	\$1,722
211262828	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601714A*	12,400	\$1,736
211262792	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412A*	12,400	\$1,736
211262770	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262748	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0401410A*	12,600	\$1,764
211262725	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0601412A*	12,600	\$1,764
211262701	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262679	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0261410A*	12,700	\$1,778
211262659	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412A*	12,500	\$1,750
211262638	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410A*	12,300	\$1,722
211262615	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0601412A*	12,500	\$1,750
211262592	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0401410A*	12,500	\$1,750
211262568	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*80VTL0451412A*	12,400	\$1,736
211262549	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412A*	12,500	\$1,750
211262530	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410A*	12,300	\$1,722
211262512	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412A*	12,400	\$1,736
211262490	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262468	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0401410A*	12,600	\$1,764
211262447	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0601412A*	12,600	\$1,764
211262423	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262401	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0261410A*	12,700	\$1,778
211262380	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412A*	12,500	\$1,750
211262360	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410A*	12,300	\$1,722
211262336	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0601412A*	12,500	\$1,750
211262314	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0401410A*	12,500	\$1,750
211262290	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*80VTL0451412A*	12,400	\$1,736
211262271	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412A*	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262253	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410A*	12,300	\$1,722
211262236	ARCOAIRE	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412A*	12,500	\$1,750
211262217	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	OMV112K14A	12,600	\$1,764
211262200	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	OLV098A12*	12,600	\$1,764
211262182	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	OMV098J12*	12,600	\$1,764
211262160	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	12,300	\$1,722
211262139	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401712A*	12,500	\$1,750
211262118	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401410A*	12,500	\$1,750
211262096	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601714A*	12,300	\$1,722
211262074	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601412A*	12,500	\$1,750
211262051	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	12,500	\$1,750
211262025	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	12,400	\$1,736
211261998	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261977	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601714A*	12,400	\$1,736
211261951	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*95ESN0261410A*	12,600	\$1,764
211261933	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412A*	12,500	\$1,750
211261918	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410A*	12,200	\$1,708
211261893	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*95ESN0601412A*	12,400	\$1,736
211261865	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401712A*	12,200	\$1,708
211261844	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401410A*	12,400	\$1,736
211261829	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716A*	12,200	\$1,708
211261812	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716A*	12,200	\$1,708
211261790	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712A*	12,400	\$1,736
211261763	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80VTL0451412A*	12,300	\$1,722
211261741	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80ESU0401712A*	12,700	\$1,778
211261721	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80VSL0701716A*	12,200	\$1,708
211261703	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451716A*	12,300	\$1,722
211261648	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*95ESU0401712A*	12,300	\$1,722
211261628	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716A*	12,200	\$1,708
211261610	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412A*	12,500	\$1,750
211261592	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712A*	12,400	\$1,736
211261574	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410A*	12,200	\$1,708
211261556	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601714A*	12,400	\$1,736
211261521	ARCOAIRE	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451412A*	12,400	\$1,736
211261499	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211261477	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*92ESN0401410A*	12,500	\$1,750
211261455	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*92ESN0601412A*	12,500	\$1,750
211261432	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261410	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*95ESN0261410A*	12,500	\$1,750
211261390	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412A*	12,400	\$1,736
211261370	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410A*	12,200	\$1,708
211261348	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*95ESN0601412A*	12,400	\$1,736
211261326	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*95ESN0401410A*	12,400	\$1,736
211261302	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*80VTL0451412A*	12,300	\$1,722
211261281	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412A*	12,400	\$1,736
211261264	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410A*	12,200	\$1,708
211261245	ARCOAIRE	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412A*	12,400	\$1,736
211261226	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	OMV112K14A	12,500	\$1,750
211261208	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	OLV098A12*	12,500	\$1,750
211261184	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	OMV098J12*	12,500	\$1,750
211261152	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80ESU0601716A	12,600	\$1,764
211261110	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701412A*	12,100	\$1,694
211261064	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401712A*	12,400	\$1,736
211261048	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401410A*	12,400	\$1,736
211261035	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601714A*	12,200	\$1,708
211261022	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601412A*	12,400	\$1,736
211261008	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211260994	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211260979	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211260967	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601714A*	12,200	\$1,708
211260952	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*95ESN0261410A*	12,400	\$1,736
211260940	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412A*	12,300	\$1,722
211260928	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410A*	12,100	\$1,694
211260913	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*95ESN0601412A*	12,300	\$1,722
211260899	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401712A*	12,100	\$1,694
211260886	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401410A*	12,300	\$1,722
211260874	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716A*	12,000	\$1,680
211260862	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716A*	12,100	\$1,694
211260848	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712A*	12,300	\$1,722
211260831	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80VTL0451412A*	12,200	\$1,708
211260817	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80ESU0401712A*	12,500	\$1,750
211260805	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80VSL0701716A*	12,100	\$1,694
211260794	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451716A*	12,200	\$1,708
211260760	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*95ESU0401712A*	12,200	\$1,708
211260748	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716A*	12,100	\$1,694
211260737	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260726	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712A*	12,300	\$1,722
211260716	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410A*	12,100	\$1,694
211260705	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601714A*	12,200	\$1,708
211260684	ARCOAIRE	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412A*	12,200	\$1,708
211260673	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	OMV112K14A	12,700	\$1,778
211260663	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	OLV098A12*	12,700	\$1,778
211260652	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	OMV098J12*	12,700	\$1,778
211260641	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80ESU0601716A	12,800	\$1,792
211260627	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	12,400	\$1,736
211260615	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401712A*	12,600	\$1,764
211260603	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401410A*	12,600	\$1,764
211260591	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601714A*	12,400	\$1,736
211260578	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601412A*	12,600	\$1,764
211260564	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	12,600	\$1,764
211260549	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	12,900	\$1,806
211260535	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260523	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601714A*	12,400	\$1,736
211260509	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*95ESN0261410A*	12,700	\$1,778
211260497	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412A*	12,500	\$1,750
211260485	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410A*	12,300	\$1,722
211260471	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*95ESN0601412A*	12,500	\$1,750
211260458	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401712A*	12,300	\$1,722
211260444	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401410A*	12,500	\$1,750
211260432	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716A*	12,200	\$1,708
211260420	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716A*	12,300	\$1,722
211260407	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712A*	12,500	\$1,750
211260390	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80VTL0451412A*	12,400	\$1,736
211260377	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80ESU0401712A*	12,700	\$1,778
211260365	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80VSL0701716A*	12,300	\$1,722
211260354	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451716A*	12,400	\$1,736
211260320	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*95ESU0401712A*	12,400	\$1,736
211260308	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716A*	12,300	\$1,722
211260297	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412A*	12,500	\$1,750
211260287	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712A*	12,500	\$1,750
211260276	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410A*	12,300	\$1,722
211260265	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601714A*	12,400	\$1,736
211260244	ARCOAIRE	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412A*	12,400	\$1,736
211260231	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260218	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*92ESN0401410A*	12,600	\$1,764
211260205	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*92ESN0601412A*	12,600	\$1,764
211260188	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260176	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*95ESN0261410A*	12,600	\$1,764
211260166	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412A*	12,500	\$1,750
211260156	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410A*	12,300	\$1,722
211260141	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*95ESN0601412A*	12,500	\$1,750
211260126	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*95ESN0401410A*	12,500	\$1,750
211260111	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*80VTL0451412A*	12,400	\$1,736
211260099	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412A*	12,500	\$1,750
211260085	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410A*	12,300	\$1,722
211260072	ARCOAIRE	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412A*	12,400	\$1,736
211260059	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	OMV112K14A	12,600	\$1,764
211260045	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	OLV098A12*	12,500	\$1,750
211260031	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	OMV098J12*	12,600	\$1,764
211260015	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80ESU0601716A	12,700	\$1,778
211260000	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701412A*	12,200	\$1,708
211259983	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401712A*	12,400	\$1,736
211259968	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401410A*	12,400	\$1,736
211259953	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601714A*	12,200	\$1,708
211259937	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601412A*	12,500	\$1,750
211259921	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211259906	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211259890	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211259876	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601714A*	12,300	\$1,722
211259859	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*95ESN0261410A*	12,500	\$1,750
211259847	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412A*	12,400	\$1,736
211259835	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410A*	12,100	\$1,694
211259823	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*95ESN0601412A*	12,300	\$1,722
211259810	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401712A*	12,100	\$1,694
211259799	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401410A*	12,400	\$1,736
211259788	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716A*	12,000	\$1,680
211259777	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716A*	12,100	\$1,694
211259765	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712A*	12,300	\$1,722
211259748	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80VTL0451412A*	12,200	\$1,708
211259733	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80ESU0401712A*	12,600	\$1,764
211259719	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80VSL0701716A*	12,100	\$1,694
211259706	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451716A*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211259667	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*95ESU0401712A*	12,200	\$1,708
211259654	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716A*	12,100	\$1,694
211259642	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412A*	12,400	\$1,736
211259629	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712A*	12,300	\$1,722
211259617	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410A*	12,100	\$1,694
211259604	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601714A*	12,300	\$1,722
211259580	ARCOAIRE	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412A*	12,300	\$1,722
211257337	ARCOAIRE	DLCURAH18ABK	FJMA4*24L*B*		12,800	\$1,792
201835533	ARCOAIRE	DLCSRAH12AAK	DLFSCAH12XAK		8,200	\$1,148
201835537	ARCOAIRE	DLCSRAH18AAK	DLFSCAH18XAK		12,000	\$1,680
201835535	ARCOAIRE	DLCSRAH12AAK	DLFSDAH12XAK		8,100	\$1,134
201835539	ARCOAIRE	DLCSRAH24AAK	DLFSFAH24XAK		17,200	\$2,408
201835544	ARCOAIRE	DLCLRAH48AAK	DLFLFAH48XAK		35,000	\$4,900
201835518	ARCOAIRE	DLCSRAH24AAK	DLFSHAH24XAK		15,000	\$2,100
201835517	ARCOAIRE	DLCSRAH18AAK	DLFSHAH18XAK		11,900	\$1,666
201835538	ARCOAIRE	DLCSRAH24AAK	DLFSDAH24XAK		17,400	\$2,436
202463643	ARCOAIRE	DLCPRAH24AAK	DLFPHAH24XAK		15,450	\$2,163
201835540	ARCOAIRE	DLCSRAH24AAK	DLFSCAH24XAK		16,200	\$2,268
205921372	ARCOAIRE	DLCSRAH24AAK	DLFSAAH24XAK		17,500	\$2,450
206350386	ARCOAIRE	DLCSRBH12AAK	DLFSFAH12XAK		8,400	\$1,176
206350384	ARCOAIRE	DLCSRBH12AAK	DLFSCAH12XAK		7,900	\$1,106
206396069	ARCOAIRE	DLCSRAH12AAK	DLFSHBH12XAK		7,500	\$1,050
206350391	ARCOAIRE	DLCSRBH24AAK	DLFSDAH24XAK		14,500	\$2,030
206350385	ARCOAIRE	DLCSRBH12AAK	DLFSDAH12XAK		8,300	\$1,162
206350388	ARCOAIRE	DLCSRBH18AAK	DLFSDAH18XAK		12,700	\$1,778
206188288	ARCOAIRE	DLCSRBH24AAK	DLFSAAH24XAK		16,500	\$2,310
206350390	ARCOAIRE	DLCSRBH24AAK	DLFSCAH24XAK		14,500	\$2,030
206350389	ARCOAIRE	DLCSRBH18AAK	DLFSFAH18XAK		12,000	\$1,680
206350392	ARCOAIRE	DLCSRBH24AAK	DLFSFAH24XAK		14,500	\$2,030
207643001	ARCOAIRE	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340
207643004	ARCOAIRE	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643000	ARCOAIRE	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207642995	ARCOAIRE	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207642994	ARCOAIRE	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643003	ARCOAIRE	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207643002	ARCOAIRE	DLCMH36DAK	Heat pump without ducts		22,000	\$3,080
207642999	ARCOAIRE	DLCMH36EAK	Heat pump without ducts		34,000	\$4,760
207642993	ARCOAIRE	DLCMH36DAK	Heat pump without ducts		18,500	\$2,590
211222788	ARCOAIRE	DLCURAH30ABK	FXM4X36**AL		23,200	\$3,248
211230818	ARCOAIRE	DLCURAH36ABK	FEM4P42**AL		29,200	\$4,088
211230829	ARCOAIRE	DLCURAH36ABK	FEM4P48**AL		29,400	\$4,116
211230841	ARCOAIRE	DLCURAH36ABK	FEM4X42**BL		29,200	\$4,088
211230853	ARCOAIRE	DLCURAH36ABK	FEM4X48**BL		29,400	\$4,116
211230875	ARCOAIRE	DLCURAH36ABK	FMA4P36**AL*		29,800	\$4,172
211230907	ARCOAIRE	DLCURAH36ABK	FXM4X36**AL		29,000	\$4,060
211719729	ARCOAIRE	DLCURAH18ABK	FMA4P18**AL*		12,700	\$1,778
211264861	ARCOAIRE	DLCURAH18ABK	FXM4X18**AL		12,300	\$1,722
211264839	ARCOAIRE	DLCURAH18ABK	FEM4X24**CL		12,100	\$1,694
211264808	ARCOAIRE	DLCURAH18ABK	FEM4X18**BL		12,300	\$1,722
211264784	ARCOAIRE	DLCURAH18ABK	FEM4P24**AL		12,300	\$1,722
209852036	ARCOAIRE	DLCURAH18ABK	DLFUAH18XAK		13,500	\$1,890
209852037	ARCOAIRE	DLCURAH24ABK	DLFUAH24XAK		19,200	\$2,688
209852039	ARCOAIRE	DLCURAH48ABK	DLFUAH48XAK		36,000	\$5,040
212978657	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978668	ARCOAIRE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978679	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	18,700	\$2,618
212978690	ARCOAIRE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	18,500	\$2,590
212978701	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	19,400	\$2,716
212978712	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	18,900	\$2,646
212978723	ARCOAIRE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701712A*	18,900	\$2,646
212978734	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701712A*	19,000	\$2,660
212979123	ARCOAIRE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701716A*	19,400	\$2,716
212986155	ARCOAIRE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401410A*	18,800	\$2,632
212986167	ARCOAIRE	DLCURAH24ABK	EA*4X30L14A*	*96MSN0401410A*	19,200	\$2,688
212986179	ARCOAIRE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401410A*	19,200	\$2,688
212986191	ARCOAIRE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401410A*	19,200	\$2,688
212986203	ARCOAIRE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401410A*	18,800	\$2,632
212986215	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0401410A*	19,500	\$2,730
212986227	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401410A*	19,500	\$2,730
212986239	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0401410A*	19,200	\$2,688
212986251	ARCOAIRE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401410A*	19,200	\$2,688
207801568	ARCOAIRE	DLCRBH18AAK	DLFSDAH24XAK		12,600	\$1,764
207826595	ARCOAIRE	DLCRBH18AAK	DLFSABH18XBK		12,000	\$1,680

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208106824	Armstrong Air	4DHP2S48M-1P	Heat pump without ducts		36,000	\$5,040
216769822	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH60DX-**-TDR	A97US2V135D20S*	44,000	\$6,160
216769806	ARMSTRONG AIR	A7SCP18V60P-**-A	7ED60DX-**-TDR	A97DS2V110C20S*	44,000	\$6,160
216769804	ARMSTRONG AIR	A7SCP18V60P-**-A	7ED60DX-**-TDR	A97DS2V090C20S*	44,000	\$6,160
216769802	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]60DX-**-TDR	A97US2V135D20S*	44,000	\$6,160
216769800	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH50/60CX-**-TDR	A97US2V090C20S*	44,500	\$6,230
216769798	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH50/60CX-**-TDR	A97US2V110C20S*	44,000	\$6,160
216769796	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH50/60CX-**-TDR	A97US2V080C20X*	44,500	\$6,230
216769794	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]60CX-**-TDR	A97US2V090C20S*	44,000	\$6,160
216769792	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]60CX-**-TDR	A97US2V110C20S*	43,500	\$6,090
216769790	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]60CX-**-TDR	A97US2V080C20X*	44,000	\$6,160
216769768	ARMSTRONG AIR	A7SCP18V60P-**-A	7ED48CX-**-TDR	A97DS2V110C20S*	39,500	\$5,530
216769766	ARMSTRONG AIR	A7SCP18V60P-**-A	7ED48CX-**-TDR	A97DS2V090C20S*	39,500	\$5,530
216769762	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH48CX-**-TDR	A97US2V110C20S*	39,500	\$5,530
216769760	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH48CX-**-TDR	A97US2V080C20X*	39,500	\$5,530
216769758	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH42CX-**-TDR	A97US2V090C20S*	39,500	\$5,530
216769756	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH42CX-**-TDR	A97US2V110C20S*	39,500	\$5,530
216769754	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH42CX-**-TDR	A97US2V080C20X*	39,500	\$5,530
216769752	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH42CX-**-TDR	A97US2V080C16X*	39,500	\$5,530
216769750	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	A97US2V090C20S*	39,500	\$5,530
216769748	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	A97US2V110C20S*	39,000	\$5,460
216769746	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	A97US2V080C20X*	39,000	\$5,460
216769744	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	A97US2V080C16X*	39,000	\$5,460
216769742	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	A97US2V090C20S*	39,500	\$5,530
216769740	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	A97US2V110C20S*	39,500	\$5,530
216769738	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	A97US2V080C20X*	39,500	\$5,530
216769736	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	A97US2V080C16X*	39,500	\$5,530
216769764	ARMSTRONG AIR	A7SCP18V60P-**-A	7ED42BX-**-TDR	A97DS2V070B16S*	40,000	\$5,600
216769713	ARMSTRONG AIR	A7SCP18V36P-**-A	7ED42BX-**-TDR	A97DS2V070B16S*	29,000	\$4,060
216769711	ARMSTRONG AIR	A7SCP18V36P-**-A	7ED30/36BX-**-TDR	A97DS2V070B16S*	29,000	\$4,060
216769709	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH36CX-**-TDR	A97US2V080C16X*	28,600	\$4,004
216769707	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH36CX-**-TDR	A97US2V090C12S*	28,600	\$4,004
216769705	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH36BX-**-TDR	A97US2V070B12S*	28,800	\$4,032
216769703	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH36BX-**-TDR	A97US2V045B12S*	28,800	\$4,032
216769701	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH36BX-**-TDR	A97US2V060B12X*	28,800	\$4,032
216769699	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH36BX-**-TDR	A97US2V040B12X*	28,800	\$4,032
216769697	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH30BX-**-TDR	A97US2V070B12S*	28,800	\$4,032
216769657	ARMSTRONG AIR	A7SCP18V24P-**-A	7EH30BX-**-TDR	A97US2V070B12S*	19,800	\$2,772

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216769695	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH30BX-**-TDR	A97US2V045B12S*	28,800	\$4,032
216769655	ARMSTRONG AIR	A7SCP18V24P-**-A	7EH30BX-**-TDR	A97US2V045B12S*	19,800	\$2,772
216769693	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH30BX-**-TDR	A97US2V060B12X*	28,800	\$4,032
216769653	ARMSTRONG AIR	A7SCP18V24P-**-A	7EH30BX-**-TDR	A97US2V060B12X*	19,800	\$2,772
216769691	ARMSTRONG AIR	A7SCP18V36P-**-A	7EH30BX-**-TDR	A97US2V040B12X*	28,800	\$4,032
216769651	ARMSTRONG AIR	A7SCP18V24P-**-A	7EH30BX-**-TDR	A97US2V040B12X*	19,800	\$2,772
216769649	ARMSTRONG AIR	A7SCP18V24P-**-A	7EH24BX-**-TDR	A97US2V070B12S*	19,800	\$2,772
216769647	ARMSTRONG AIR	A7SCP18V24P-**-A	7EH24BX-**-TDR	A97US2V045B12S*	19,800	\$2,772
216769645	ARMSTRONG AIR	A7SCP18V24P-**-A	7EH24BX-**-TDR	A97US2V060B12X*	19,800	\$2,772
216769643	ARMSTRONG AIR	A7SCP18V24P-**-A	7EH24BX-**-TDR	A97US2V040B12X*	19,800	\$2,772
216769689	ARMSTRONG AIR	A7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	A97US2V070B12S*	28,800	\$4,032
216769641	ARMSTRONG AIR	A7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	A97US2V070B12S*	19,800	\$2,772
216769687	ARMSTRONG AIR	A7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	A97US2V045B12S*	28,800	\$4,032
216769639	ARMSTRONG AIR	A7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	A97US2V045B12S*	19,800	\$2,772
216769685	ARMSTRONG AIR	A7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	A97US2V060B12X*	28,800	\$4,032
216769637	ARMSTRONG AIR	A7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	A97US2V060B12X*	19,800	\$2,772
216769683	ARMSTRONG AIR	A7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	A97US2V040B12X*	28,800	\$4,032
216769635	ARMSTRONG AIR	A7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	A97US2V040B12X*	19,800	\$2,772
216769681	ARMSTRONG AIR	A7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	A97US2V070B12S*	28,800	\$4,032
216769633	ARMSTRONG AIR	A7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	A97US2V070B12S*	19,800	\$2,772
216769679	ARMSTRONG AIR	A7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	A97US2V045B12S*	29,000	\$4,060
216769631	ARMSTRONG AIR	A7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	A97US2V045B12S*	19,800	\$2,772
216769677	ARMSTRONG AIR	A7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	A97US2V060B12X*	29,000	\$4,060
216769629	ARMSTRONG AIR	A7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	A97US2V060B12X*	19,800	\$2,772
216769675	ARMSTRONG AIR	A7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	A97US2V040B12X*	28,800	\$4,032
216769627	ARMSTRONG AIR	A7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	A97US2V040B12X*	19,800	\$2,772
216619011	ARMSTRONG AIR	A7SCP18V60P-**-A	7ED60DX-**-TDR		43,500	\$6,090
216619010	ARMSTRONG AIR	A7SCP18V60P-**-A	7ED50/60CX-**-TDR		43,500	\$6,090
216619009	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH60DX-**-TDR		43,500	\$6,090
216619008	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH50/60CX-**-TDR		43,500	\$6,090
216619007	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]60DX-**-TDR		42,000	\$5,880
216619006	ARMSTRONG AIR	A7SCP18V60P-**-A	7ED48CX-**-TDR		40,000	\$5,600
216619005	ARMSTRONG AIR	A7SCP18V60P-**-A	7ED42BX-**-TDR		40,500	\$5,670
216619003	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH48BX-**-TDR		40,500	\$5,670
216619002	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH42CX-**-TDR		40,500	\$5,670
216619001	ARMSTRONG AIR	A7SCP18V60P-**-A	7EH42BX-**-TDR		40,000	\$5,600
216619000	ARMSTRONG AIR	A7SCP18V60P-**-A	7E[C,U]49CX-**-TDR		40,000	\$5,600
216618977	ARMSTRONG AIR	A7SCP18V60P-**-A	7AH2AV60PXC-**-		43,500	\$6,090

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216618976	ARMSTRONG AIR	A7SCP18V60P-**A	7AH1AE60PX-**		43,000	\$6,020
216618975	ARMSTRONG AIR	A7SCP18V60P-**A	7AH2AV48PXC-**		38,000	\$5,320
216618974	ARMSTRONG AIR	A7SCP18V60P-**A	7AH2AV42PXC-**		38,500	\$5,390
216618973	ARMSTRONG AIR	A7SCP18V60P-**A	7AH1AE48PX-**		39,000	\$5,460
216618972	ARMSTRONG AIR	A7SCP18V60P-**A	7AH1AV42PX-**		38,500	\$5,390
216618971	ARMSTRONG AIR	A7SCP18V60P-**A	7AH1AE42PX-**		39,000	\$5,460
216010756	ARMSTRONG AIR	A7SCP18V36P-**A	7AH1AV36PX-**		28,000	\$3,920
216618998	ARMSTRONG AIR	A7SCP18V36P-**A	7ED42BX-***+TDR		28,000	\$3,920
216618997	ARMSTRONG AIR	A7SCP18V36P-**A	7ED30/36BX-***+TDR		28,000	\$3,920
216618996	ARMSTRONG AIR	A7SCP18V36P-**A	7EH36CX-***+TDR		28,000	\$3,920
216618994	ARMSTRONG AIR	A7SCP18V36P-**A	7EH36AX-***+TDR		28,400	\$3,976
216618993	ARMSTRONG AIR	A7SCP18V36P-**A	7EH30BX-***+TDR		28,000	\$3,920
216618992	ARMSTRONG AIR	A7SCP18V36P-**A	7EH30AX-***+TDR		28,000	\$3,920
216618991	ARMSTRONG AIR	A7SCP18V36P-**A	7E[C,U]36AX-***+TDR		28,000	\$3,920
216618990	ARMSTRONG AIR	A7SCP18V36P-**A	7E[C,U]30BX-***+TDR		28,000	\$3,920
216618989	ARMSTRONG AIR	A7SCP18V36P-**A	7E[C,U]30AX-***+TDR		28,000	\$3,920
216618970	ARMSTRONG AIR	A7SCP18V36P-**A	7AH2AV42PXC-**		28,000	\$3,920
216618969	ARMSTRONG AIR	A7SCP18V36P-**A	7AH2AV36PXC-**		28,000	\$3,920
216618968	ARMSTRONG AIR	A7SCP18V36P-**A	7AH1AV42PX-**		28,000	\$3,920
216618967	ARMSTRONG AIR	A7SCP18V36P-**A	7AH1AE42PX-**		28,000	\$3,920
216618966	ARMSTRONG AIR	A7SCP18V36P-**A	7AH1AC42PX-**		28,400	\$3,976
216618965	ARMSTRONG AIR	A7SCP18V36P-**A	7AH1AE36PX-**		28,000	\$3,920
216618964	ARMSTRONG AIR	A7SCP18V36P-**A	7AH1AC36PX-**		28,400	\$3,976
216010755	ARMSTRONG AIR	A7SCP18V24P-**A	7AH1AV24PX-**		18,000	\$2,520
216618985	ARMSTRONG AIR	A7SCP18V24P-**A	7EH30AX-***+TDR		19,600	\$2,744
216618983	ARMSTRONG AIR	A7SCP18V24P-**A	7EH24AX-***+TDR		19,600	\$2,744
216618981	ARMSTRONG AIR	A7SCP18V24P-**A	7E[C,U]36BX-***+TDR		19,600	\$2,744
216618980	ARMSTRONG AIR	A7SCP18V24P-**A	7E[C,U]36AX-***+TDR		19,600	\$2,744
216618963	ARMSTRONG AIR	A7SCP18V24P-**A	7AH2AV30PXC-**		19,400	\$2,716
216618962	ARMSTRONG AIR	A7SCP18V24P-**A	7AH2AV24PXC-**		19,600	\$2,744
216618959	ARMSTRONG AIR	A7SCP18V24P-**A	7AH1AE24PX-**		19,200	\$2,688
216618958	ARMSTRONG AIR	A7SCP18V24P-**A	7AH1AC24PX-**		19,600	\$2,744
211729605	ARMSTRONG AIR	4SHP22LX124P-**A	BCE5E24M		14,100	\$1,974
211709429	ARMSTRONG AIR	4SHP22LX124P-**A	BCE7E30M*4X		14,300	\$2,002
208101262	AURORA	AU-LXU24-2A-O	AU-LCU24-2A-I		19,200	\$2,688
208101261	AURORA	AU-LXU18-2A-O	AU-LCU18-2A-I		13,500	\$1,890
208101259	AURORA	AU-CX24HR-2A-O	AU-BS24HR-2A-I		18,900	\$2,646
208101258	AURORA	AU-CX18HR-2A-O	AU-BS18HR-2A-I		11,100	\$1,554

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208101257	AURORA	AU-CX12HR-2A-O	AU-BS12HR-2A-I		10,300	\$1,442
214232454	AURORA	AU-CX12HR-2A-O	AU-LCS12-2A-I		10,200	\$1,428
208101263	AURORA	AU-LXU30-2A-O	AU-LCU30-2A-I		21,000	\$2,940
208101264	AURORA	AU-LXU36-2A-O	AU-LCU36-2A-I		30,400	\$4,256
214232452	AURORA	AU-LXU36-2A-O	AU-36B23T4N1		27,400	\$3,836
214232451	AURORA	AU-LXU60-2A-OI	AU-LCU60-2A-I		42,000	\$5,880
208101265	AURORA	AU-LXU48-2A-O	AU-LCU48-2A-I		36,000	\$5,040
216765700	AUX	AUM20SW24HP230V1/O	AUM20SW24HP230V1/H		20,800	\$2,912
216032397	AUX	AHU60HPV1BO	AHU60HPV1BI		48,000	\$6,720
216032396	AUX	AHU48HPV1BO	AHU48HPV1BI		45,000	\$6,300
216032395	AUX	AHU36HPV1BO	AHU36HPV1BI		38,000	\$5,320
216032394	AUX	AHU30HPV1BO	AHU30HPV1BI		33,000	\$4,620
216032393	AUX	AHU24HPV1BO	AHU24HPV1BI		24,000	\$3,360
216032392	AUX	AHU18HPV1BO	AHU18HPV1BI		20,000	\$2,800
216030574	AUX	AHU60HPV1AO	AHU60HPV1AI		48,000	\$6,720
216030573	AUX	AHU48HPV1AO	AHU48HPV1AI		45,000	\$6,300
216030570	AUX	AHU24HPV1AO	AHU24HPV1AI		19,000	\$2,660
214290023	AUX	AFEB24HP230V1CO	AFEB24HP230V1CH		22,400	\$3,136
214290029	AUX	AJAN24HP230V1CO	AJAN24HP230V1CH		20,800	\$2,912
214290022	AUX	AMAR18HP230V1CO	AMAR18HP230V1CH		16,000	\$2,240
214291431	AUX	ASUM24HPMULO	Heat pump without ducts		27,600	\$3,864
214291428	AUX	ASUM18HPMULO	Heat pump without ducts		18,100	\$2,534
216050939	AUX	ASUM18HPMULO	Combination heat pumps with or without ducts		18,500	\$2,590
216032437	AUX	ASUM18HPMULO	Heat pump with ducts		19,000	\$2,660
214291427	AUX	ASPR42HPMULO	Heat pump without ducts		35,600	\$4,984
205662517	AZUR	AZ-36HPA	AH-36		25,000	\$3,500
213769907	BLUEFIN	BFMS12PR-01O	BFMS12PL-01I		10,300	\$1,442
213769911	BLUEFIN	BFMS18PR-01O	BFMS18PL-01I		11,100	\$1,554
213769902	BLUEFIN	BFMS24PR-01O	BFMS24PL-01I		18,900	\$2,646
215853987	BLUERIDGE	BMMZ36HHC	Combination heat pumps with or without ducts		31,400	\$4,396
216997625	BLUERIDGE	BXM3A36UC0	Combination heat pumps with or without ducts		31,400	\$4,396
215853985	BLUERIDGE	BMMZ36HHC	Heat pump without ducts		30,000	\$4,200
216997623	BLUERIDGE	BXM3A36UC0	Heat pump without ducts		30,000	\$4,200
207339184	BLUERIDGE	BMV12HH26C	BMV12HH26WM		10,000	\$1,400
207339185	BLUERIDGE	BMV18HH22C	BMV18HH22WM		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207339186	BLUERIDGE	BMV24HH22C	BMV24HH22WM		21,200	\$2,968
207571388	BLUERIDGE	BMV12HH26C	BM12MCC		9,900	\$1,386
207571389	BLUERIDGE	BMV12HH26C	BM12M22CNS		9,600	\$1,344
207571390	BLUERIDGE	BMV18HH22C	BM18MCD		15,000	\$2,100
209550310	BLUERIDGE	BMV18HH22C	BMM18CC2		14,500	\$2,030
209550309	BLUERIDGE	BMV12HH26C	BMM12CC2		9,500	\$1,330
209550311	BLUERIDGE	BMV12HH26C	BMM12LW		10,200	\$1,428
207641294	BLUERIDGE	BMM27HHC	Heat pump with ducts		27,000	\$3,780
208650623	BLUERIDGE	BMM55HHC	Heat pump with ducts		35,200	\$4,928
208101242	BLUERIDGE	BMAH1820C	BMAH1820I		13,500	\$1,890
208101243	BLUERIDGE	BMAH2420C	BMAH2420I		19,200	\$2,688
207641302	BLUERIDGE	BMM48HHC	Combination heat pumps with or without ducts		37,400	\$5,236
207641296	BLUERIDGE	BMM27HHC	Combination heat pumps with or without ducts		26,200	\$3,668
208650624	BLUERIDGE	BMM55HHC	Combination heat pumps with or without ducts		35,000	\$4,900
208650622	BLUERIDGE	BMM55HHC	Heat pump without ducts		34,800	\$4,872
207641291	BLUERIDGE	BMM18HHC	Heat pump without ducts		13,500	\$1,890
207641295	BLUERIDGE	BMM27HHC	Heat pump without ducts		25,600	\$3,584
208101244	BLUERIDGE	BMAH3018C	BMAH3018I		21,000	\$2,940
208101245	BLUERIDGE	BMAH3618C	BMAH3618I		30,400	\$4,256
215359195	BLUERIDGE	BMV24HH22C	BMAHM2420I		16,900	\$2,366
215359194	BLUERIDGE	BMV18HH22C	BMAHM1820I		15,400	\$2,156
215359200	BLUERIDGE	BMAH2420C	BMAHC24B		21,000	\$2,940
207571394	BLUERIDGE	BMV24HH22C	BM24MFCC		19,000	\$2,660
207641300	BLUERIDGE	BMM48HHC	Heat pump without ducts		39,000	\$5,460
207641301	BLUERIDGE	BMM48HHC	Heat pump with ducts		36,000	\$5,040
207641292	BLUERIDGE	BMM18HHC	Heat pump with ducts		16,000	\$2,240
207571393	BLUERIDGE	BMV24HH22C	BM24MCD		21,000	\$2,940
207641293	BLUERIDGE	BMM18HHC	Combination heat pumps with or without ducts		14,700	\$2,058
207641297	BLUERIDGE	BMM36HHC	Heat pump without ducts		35,000	\$4,900
207571387	BLUERIDGE	BMV12HH26C	BM12MCD		10,600	\$1,484
207641299	BLUERIDGE	BMM36HHC	Combination heat pumps with or without ducts		35,000	\$4,900
216997506	BLUERIDGE	BNG3A30UCN	BNGFA30DH2		23,800	\$3,332
216997505	BLUERIDGE	BNG3A24UCN	BNGFA24DH2		20,000	\$2,800

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216997504	BLUERIDGE	BNG3A18UCN	BNGFA18DH2		15,000	\$2,100
216997497	BLUERIDGE	BXS5A33UC0	BNHFA36DH0		27,400	\$3,836
216997496	BLUERIDGE	BXS5A24UC0	BNHFA24DH0		16,900	\$2,366
216997495	BLUERIDGE	BXS5A18UC0	BNHFA18DH0		14,000	\$1,960
216997513	BLUERIDGE	BNG3A36UCN	BNG3A36DH3		31,000	\$4,340
216997502	BLUERIDGE	BNG2A48SCN	BNGFA48DH2		32,400	\$4,536
216997499	BLUERIDGE	BNG2A24SCN	BNGFA24DH2		20,000	\$2,800
216997509	BLUERIDGE	BNG3A60UCN	BNGFA60DH2		45,000	\$6,300
216997508	BLUERIDGE	BNG3A48UCN	BNGFA48DH2		37,000	\$5,180
216997507	BLUERIDGE	BNG3A36UCN	BNGFA36DH2		31,800	\$4,452
216997512	BLUERIDGE	BNG3A30UCN	BNG3A30DH3		24,000	\$3,360
216997511	BLUERIDGE	BNG3A24UCN	BNG3A24DH3		19,000	\$2,660
216997510	BLUERIDGE	BNG3A18UCN	BNG3A18DH3		14,700	\$2,058
216997515	BLUERIDGE	BNG3A60UCN	BNG3A60DH3		35,000	\$4,900
216997514	BLUERIDGE	BNG3A48UCN	BNG3A48DH3		34,000	\$4,760
216997644	BLUERIDGE	BDM1A55SC0	Combination heat pumps with or without ducts		43,000	\$6,020
216997600	BLUERIDGE	BDS3A12UC0	BDAFA12WM0		8,900	\$1,246
216997601	BLUERIDGE	BDS3A18UC0	BDAFA18WM0		15,200	\$2,128
216997643	BLUERIDGE	BDM1A55SC0	Heat pump with ducts		42,500	\$5,950
216997642	BLUERIDGE	BDM1A55SC0	Heat pump without ducts		44,000	\$6,160
216997587	BLUERIDGE	BXL2A60UC0	BXALA60CDH		45,000	\$6,300
216997586	BLUERIDGE	BXL2A48UC0	BXALA48CDH		45,000	\$6,300
216997585	BLUERIDGE	BXL2A36UC0	BXALA36CDH		31,600	\$4,424
216997569	BLUERIDGE	BXS5A24UC0	BXAFA24CDH		21,600	\$3,024
216997568	BLUERIDGE	BXS5A18UC0	BXAFA18CDH		15,000	\$2,100
216997565	BLUERIDGE	BXS5A18UC0	BXAFA18CDL		15,000	\$2,100
216997567	BLUERIDGE	BXS5A12UC0	BXAFA12CDH		10,200	\$1,428
216997564	BLUERIDGE	BXS5A12UC0	BXAFA12CDL		9,600	\$1,344
216997612	BLUERIDGE	BXM1A48SC0	Heat pump with ducts		37,000	\$5,180
216997631	BLUERIDGE	BXM3A55UC0	Combination heat pumps with or without ducts		44,500	\$6,230
216997630	BLUERIDGE	BXM3A55UC0	Heat pump with ducts		45,000	\$6,300
216997629	BLUERIDGE	BXM3A55UC0	Heat pump without ducts		44,000	\$6,160
216997628	BLUERIDGE	BXM3A48UC0	Combination heat pumps with or without ducts		44,000	\$6,160
216997627	BLUERIDGE	BXM3A48UC0	Heat pump with ducts		44,500	\$6,230
216997626	BLUERIDGE	BXM3A48UC0	Heat pump without ducts		44,000	\$6,160

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216997624	BLUERIDGE	BXM3A36UC0	Heat pump with ducts		33,000	\$4,620
216997622	BLUERIDGE	BXM3A27UC0	Combination heat pumps with or without ducts		24,000	\$3,360
216997621	BLUERIDGE	BXM3A27UC0	Heat pump with ducts		23,000	\$3,220
216997620	BLUERIDGE	BXM3A27UC0	Heat pump without ducts		25,000	\$3,500
216997619	BLUERIDGE	BXM3A18UC0	Combination heat pumps with or without ducts		17,300	\$2,422
216997618	BLUERIDGE	BXM3A18UC0	Heat pump with ducts		17,000	\$2,380
216997617	BLUERIDGE	BXM3A18UC0	Heat pump without ducts		17,600	\$2,464
216997574	BLUERIDGE	BXS5A24UC0	BXAFA24FC0		20,200	\$2,828
216997558	BLUERIDGE	BXS5A24UC0	BXAFA24CC4		20,400	\$2,856
216997573	BLUERIDGE	BXS5A18UC0	BXAFA18FC0		14,400	\$2,016
216997572	BLUERIDGE	BXS5A18UC0	BXAFA16LW0		14,200	\$1,988
216997557	BLUERIDGE	BXS5A18UC0	BXAFA18CC4		14,900	\$2,086
216997562	BLUERIDGE	BXS5A18UC0	BXAFA18CC1		14,500	\$2,030
216997529	BLUERIDGE	BXS5A18UC0	BXAFA18WM0		15,000	\$2,100
216997571	BLUERIDGE	BXS5A12UC0	BXAFA12LW0		9,800	\$1,372
216997556	BLUERIDGE	BXS5A12UC0	BXAFA12CC4		10,000	\$1,400
216997561	BLUERIDGE	BXS5A12UC0	BXAFA12CC1		9,600	\$1,344
216997528	BLUERIDGE	BXS5A12UC0	BXAFA12WM0		9,800	\$1,372
216997590	BLUERIDGE	BXL2A60UC0	BXALA60FC0		41,000	\$5,740
216997589	BLUERIDGE	BXL2A48UC0	BXALA48FC0		38,500	\$5,390
216997584	BLUERIDGE	BXL2A48UC0	BXALA48CC4		44,000	\$6,160
216997588	BLUERIDGE	BXL2A36UC0	BXALA36FC0		30,200	\$4,228
216997583	BLUERIDGE	BXL2A36UC0	BXALA36CC4		30,600	\$4,284
216997531	BLUERIDGE	BXS5A33UC0	BXAFA33WM0		30,000	\$4,200
216997530	BLUERIDGE	BXS5A24UC0	BXAFA24WM0		21,000	\$2,940
216997535	BLUERIDGE	BXS6A18UC0	BXS6A18WM0		19,300	\$2,702
216997534	BLUERIDGE	BXS6A12UC0	BXS6A12WM0		11,000	\$1,540
215853904	BLUERIDGE	BMS1821HHYC	BMC18HHYW		16,600	\$2,324
215853869	BLUERIDGE	BMSAH18HHC	BMS2AH18I		15,000	\$2,100
215853947	BLUERIDGE	BMS1225HHYC	BMC12LW		9,800	\$1,372
215853903	BLUERIDGE	BMS1225HHYC	BMC12HHYW		9,800	\$1,372
215853870	BLUERIDGE	BMSAH24HHC	BMS2AH24I		20,000	\$2,800
215853872	BLUERIDGE	BMSAH36HHC	BMS2AH36I		31,800	\$4,452
207571385	BLUERIDGE	BMV48UC	BM48MFCC		29,000	\$4,060
215853963	BLUERIDGE	BMS60HHUYC	BMS60HCD		45,000	\$6,300
215853962	BLUERIDGE	BMS48HHUYC	BMS48HCD		45,000	\$6,300

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853961	BLUERIDGE	BMS36HHUYC	BMS36HCD		31,600	\$4,424
215853945	BLUERIDGE	BMS2421HHYC	BMC24HCD		21,600	\$3,024
215853944	BLUERIDGE	BMS1821HHYC	BMC18HCD		15,000	\$2,100
215853941	BLUERIDGE	BMS1821HHYC	BMC18LCD		15,000	\$2,100
215853943	BLUERIDGE	BMS1225HHYC	BMC12HCD		10,200	\$1,428
215853940	BLUERIDGE	BMS1225HHYC	BMC12LCD		9,600	\$1,344
215853977	BLUERIDGE	BMMZ48C	Heat pump with ducts		37,000	\$5,180
215853993	BLUERIDGE	BMMZ55HHC	Combination heat pumps with or without ducts		44,500	\$6,230
215853992	BLUERIDGE	BMMZ55HHC	Heat pump with ducts		45,000	\$6,300
215853991	BLUERIDGE	BMMZ55HHC	Heat pump without ducts		44,000	\$6,160
215853990	BLUERIDGE	BMMZ48HHC	Combination heat pumps with or without ducts		44,000	\$6,160
215853989	BLUERIDGE	BMMZ48HHC	Heat pump with ducts		44,500	\$6,230
215853988	BLUERIDGE	BMMZ48HHC	Heat pump without ducts		44,000	\$6,160
215853986	BLUERIDGE	BMMZ36HHC	Heat pump with ducts		33,000	\$4,620
215853984	BLUERIDGE	BMMZ27HHC	Combination heat pumps with or without ducts		24,000	\$3,360
215853983	BLUERIDGE	BMMZ27HHC	Heat pump with ducts		23,000	\$3,220
215853982	BLUERIDGE	BMMZ27HHC	Heat pump without ducts		25,000	\$3,500
215853981	BLUERIDGE	BMMZ18HHC	Combination heat pumps with or without ducts		17,300	\$2,422
215853980	BLUERIDGE	BMMZ18HHC	Heat pump with ducts		17,000	\$2,380
215853979	BLUERIDGE	BMMZ18HHC	Heat pump without ducts		17,600	\$2,464
215853950	BLUERIDGE	BMS2421HHYC	BMC24FCC		20,200	\$2,828
215853933	BLUERIDGE	BMS2421HHYC	BMC24CC		20,400	\$2,856
215853949	BLUERIDGE	BMS1821HHYC	BMC18FCC		14,400	\$2,016
215853948	BLUERIDGE	BMS1821HHYC	BMC16LW		14,200	\$1,988
215853932	BLUERIDGE	BMS1821HHYC	BMC18CC		14,900	\$2,086
215853937	BLUERIDGE	BMS1821HHYC	BMC18CC2		14,500	\$2,030
215853931	BLUERIDGE	BMS1225HHYC	BMC12CC		10,000	\$1,400
215853936	BLUERIDGE	BMS1225HHYC	BMC12CC2		9,600	\$1,344
215853966	BLUERIDGE	BMS60HHUYC	BMS60FCC		41,000	\$5,740
215853965	BLUERIDGE	BMS48HHUYC	BMS48FCC		38,500	\$5,390
215853960	BLUERIDGE	BMS48HHUYC	BMS48CC		44,000	\$6,160
215853964	BLUERIDGE	BMS36HHUYC	BMS36FCC		30,200	\$4,228
215853959	BLUERIDGE	BMS36HHUYC	BMS36CC		30,600	\$4,284
215853878	BLUERIDGE	BMSAH36HHC	BMS3AH36I		31,000	\$4,340

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853880	BLUERIDGE	BMSAH60HHC	BMS3AH60I		35,000	\$4,900
215853879	BLUERIDGE	BMSAH48HHC	BMS3AH48I		34,000	\$4,760
215853867	BLUERIDGE	BMSAHS4816C	BMS2AH48I		32,400	\$4,536
215853864	BLUERIDGE	BMSAHS2418C	BMS2AH24I		20,000	\$2,800
215853874	BLUERIDGE	BMSAH60HHC	BMS2AH60I		45,000	\$6,300
215853873	BLUERIDGE	BMSAH48HHC	BMS2AH48I		37,000	\$5,180
215853877	BLUERIDGE	BMSAH30HHC	BMS3AH30I		24,000	\$3,360
215853871	BLUERIDGE	BMSAH30HHC	BMS2AH30I		23,800	\$3,332
215853876	BLUERIDGE	BMSAH24HHC	BMS3AH24I		19,000	\$2,660
215853875	BLUERIDGE	BMSAH18HHC	BMS3AH18I		14,700	\$2,058
215853862	BLUERIDGE	BMS3320HHYC	BMMZAH36I		27,400	\$3,836
215853861	BLUERIDGE	BMS2421HHYC	BMMZAH24I		16,900	\$2,366
215853860	BLUERIDGE	BMS1821HHYC	BMMZAH18I		14,000	\$1,960
215359201	BLUERIDGE	BMAH3018C	BMAHC36B		19,600	\$2,744
208650627	BLUERIDGE	BM48HHUC	BM48MFCC		35,000	\$4,900
206905350	BLUERIDGE	BMHH27M22C	Heat pump without ducts		18,000	\$2,520
202918821	BLUERIDGE	BMHH27M18C	Heat pump without ducts		18,000	\$2,520
215359208	BLUERIDGE	BM48HHUC	BM36MCC		33,000	\$4,620
215359203	BLUERIDGE	BMAH3618C	BMAHC36B		27,400	\$3,836
215359206	BLUERIDGE	BMAH6016C	BMAHC60D		37,000	\$5,180
215359204	BLUERIDGE	BMAH3618C	BMAHC36C		33,000	\$4,620
215359202	BLUERIDGE	BMAH3018C	BMAHC36C		22,600	\$3,164
212360178	BLUERIDGE	BMM27HH2C	Heat pump without ducts		23,000	\$3,220
213363376	BLUERIDGE	BMM36HH2C	Heat pump without ducts		27,400	\$3,836
213363378	BLUERIDGE	BMM36HH2C	Combination heat pumps with or without ducts		28,600	\$4,004
213363377	BLUERIDGE	BMM36HH2C	Heat pump with ducts		30,000	\$4,200
207641298	BLUERIDGE	BMM36HHC	Heat pump with ducts		23,000	\$3,220
206905357	BLUERIDGE	BMHH48M22C	Heat pump with ducts		28,000	\$3,920
212360180	BLUERIDGE	BMM27HH2C	Combination heat pumps with or without ducts		23,000	\$3,220
208650626	BLUERIDGE	BM48HHUC	BM36MFCC		32,000	\$4,480
206905356	BLUERIDGE	BMHH48M22C	Heat pump without ducts		30,000	\$4,200
211911408	BLUERIDGE	BM48HHUC	BM48MFCC		28,800	\$4,032
210025757	BLUERIDGE	BMAH6016C	BMAH6016I		42,000	\$5,880
208101246	BLUERIDGE	BMAH4816C	BMAH4816I		36,000	\$5,040
210191032	BLUERIDGE	BM48HHUC	BM60MFCC		40,000	\$5,600
208130266	BOREAL	ENVBR60HPJ10A	ENVBR48HPJ11B		32,000	\$4,480

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208130267	BOREAL	ENVBR60HPJ1OA	ENVBR60HPJ1IB		36,000	\$5,040
208130264	BOREAL	ENVBR36HPJ1OA	ENVBR24HPJ1IB		16,300	\$2,282
208130265	BOREAL	ENVBR36HPJ1OA	ENVBR36HPJ1IB		24,000	\$3,360
212436229	BOREAL	ENVBR36HPJ1OA	ENVBR24C		15,000	\$2,100
207760042	BOSCH	BMS500-AAM048-1CSXHC	Heat pump without ducts		36,000	\$5,040
207760033	BOSCH	BMS500-AAM018-1CSXHC	Heat pump without ducts		15,000	\$2,100
207759996	BOSCH	BMS500-AAS018-1CSXHC	BMS500-AAU018-1AHWXC		15,000	\$2,100
207760018	BOSCH	BMS500-AAS024-1CSXHC	BMS500-AAU024-1AHCXC		21,000	\$2,940
207760005	BOSCH	BMS500-AAS018-1CSXHC	BMS500-AAU018-1AHDXB		15,000	\$2,100
203991183	BOSCH	BMS500-AAM027-1CSXHB	Heat pump without ducts		18,000	\$2,520
204014470	BOSCH	BMS500-AAS024-1CSXHB	BMS500-AAU024-1AHDXB		23,000	\$3,220
207760014	BOSCH	BMS500-AAS012-1CSXHC	BMS500-AAU012-1AHCXB		9,900	\$1,386
207759995	BOSCH	BMS500-AAS012-1CSXHC	BMS500-AAU012-1AHWXC		10,000	\$1,400
207759997	BOSCH	BMS500-AAS024-1CSXHC	BMS500-AAU024-1AHWXC		21,200	\$2,968
207760008	BOSCH	BMS500-AAS024-1CSXHC	BMS500-AAU024-1AHDXB		21,000	\$2,940
207760043	BOSCH	BMS500-AAM048-1CSXHC	Heat pump with ducts		36,000	\$5,040
207760003	BOSCH	BMS500-AAS012-1CSXHC	BMS500-AAU012-1AHDXB		10,600	\$1,484
207760034	BOSCH	BMS500-AAM018-1CSXHC	Heat pump with ducts		16,000	\$2,240
207760039	BOSCH	BMS500-AAM036-1CSXHC	Heat pump without ducts		33,000	\$4,620
207760044	BOSCH	BMS500-AAM048-1CSXHC	Combination heat pumps with or without ducts		36,000	\$5,040
207760035	BOSCH	BMS500-AAM018-1CSXHC	Combination heat pumps with or without ducts		15,500	\$2,170

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207760041	BOSCH	BMS500-AAM036-1CSXHC	Combination heat pumps with or without ducts		34,000	\$4,760
215225109	BOSCH	BOVA-60RXB-M15S	BIVA-36RCB-M20X		34,200	\$4,788
215225116	BOSCH	BOVA-60RXB-M15S	BIVA-36RXB-M15X		28,400	\$3,976
215223338	BOSCH	BMS500-AAM048-1CSXRD	Heat pump with ducts		37,000	\$5,180
215223327	BOSCH	BMS500-AAM048-1CSXHD	Combination heat pumps with or without ducts		44,000	\$6,160
215223326	BOSCH	BMS500-AAM048-1CSXHD	Heat pump with ducts		44,500	\$6,230
215223325	BOSCH	BMS500-AAM048-1CSXHD	Heat pump without ducts		44,000	\$6,160
215223324	BOSCH	BMS500-AAM036-1CSXHD	Combination heat pumps with or without ducts		31,400	\$4,396
215223323	BOSCH	BMS500-AAM036-1CSXHD	Heat pump with ducts		33,000	\$4,620
215223322	BOSCH	BMS500-AAM036-1CSXHD	Heat pump without ducts		30,000	\$4,200
215223321	BOSCH	BMS500-AAM027-1CSXHD	Combination heat pumps with or without ducts		24,000	\$3,360
215223320	BOSCH	BMS500-AAM027-1CSXHD	Heat pump with ducts		23,000	\$3,220
215223319	BOSCH	BMS500-AAM027-1CSXHD	Heat pump without ducts		25,000	\$3,500
215223318	BOSCH	BMS500-AAM018-1CSXHD	Combination heat pumps with or without ducts		17,300	\$2,422
215223317	BOSCH	BMS500-AAM018-1CSXHD	Heat pump with ducts		17,000	\$2,380
215223316	BOSCH	BMS500-AAM018-1CSXHD	Heat pump without ducts		17,600	\$2,464
215223291	BOSCH	BMS500-AAS024-1CSXHD	BMS500-AAU024-1AHDXD		21,600	\$3,024
215223289	BOSCH	BMS500-AAS018-1CSXHD	BMS500-AAU018-1AHDXD		15,000	\$2,100
215223285	BOSCH	BMS500-AAS012-1CSXHD	BMS500-AAU012-1AHDXD		9,600	\$1,344
215223292	BOSCH	BMS500-AAS024-1CSXHD	BMS500-AAU024-1AHCXD		20,400	\$2,856

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215223288	BOSCH	BMS500-AAS018-1CSXHD	BMS500-AAU018-1AHCXD		14,900	\$2,086
215223287	BOSCH	BMS500-AAS018-1CSXHD	BMS500-AAU018-1AHZXD		14,500	\$2,030
215223286	BOSCH	BMS500-AAS018-1CSXHD	BMS500-AAU018-1AHWXD		15,000	\$2,100
215223284	BOSCH	BMS500-AAS012-1CSXHD	BMS500-AAU012-1AHCXD		10,000	\$1,400
215223283	BOSCH	BMS500-AAS012-1CSXHD	BMS500-AAU012-1AHZXD		9,600	\$1,344
215223282	BOSCH	BMS500-AAS012-1CSXHD	BMS500-AAU012-1AHWXD		9,800	\$1,372
215223290	BOSCH	BMS500-AAS024-1CSXHD	BMS500-AAU024-1AHWXD		21,000	\$2,940
214825961	BOSCH	BOVA-60MTB-M19E	BIVA-48MCB-M19X		48,500	\$6,790
214825974	BOSCH	BOVA-60MTB-M19E	BMAC4860DBTA	BGH96M120D5C	53,000	\$7,420
214825973	BOSCH	BOVA-60MTB-M19E	BMAC4860DBTA	BGH96M100D5C	53,000	\$7,420
214825975	BOSCH	BOVA-60MTB-M19E	BMAC4860CBTA	BGH96M100C5C	52,000	\$7,280
214825972	BOSCH	BOVA-60MTB-M19E	BMAC4248DBTA	BGH96M120D5C	47,500	\$6,650
214825971	BOSCH	BOVA-60MTB-M19E	BMAC4248DBTA	BGH96M100D5C	47,000	\$6,580
214825970	BOSCH	BOVA-60MTB-M19E	BMAC4248CBTA	BGH96M100C5C	47,000	\$6,580
214825969	BOSCH	BOVA-60MTB-M19E	BMAC4248CBTA	BGH96M080C4C	46,000	\$6,440
214825968	BOSCH	BOVA-60MTB-M19E	BMAC4248BBTA	BGH96M080B3C	46,000	\$6,440
214825967	BOSCH	BOVA-60MTB-M19E	BMAC4860DBTA		52,000	\$7,280
214825966	BOSCH	BOVA-60MTB-M19E	BMAC4860CBTA		52,000	\$7,280
214825965	BOSCH	BOVA-60MTB-M19E	BMAC4248DBTA		46,000	\$6,440
214825964	BOSCH	BOVA-60MTB-M19E	BMAC4248CBTA		46,000	\$6,440
214825963	BOSCH	BOVA-60MTB-M19E	BMAC4248BBTA		45,500	\$6,370
214825962	BOSCH	BOVA-60MTB-M19E	BIVA-60MCB-M19X		55,000	\$7,700
10333757	BOSCH	BOVA-60HDN1-M18M	BVA-36WN1-M18B		24,000	\$3,360
208157118	BOSCH	BMS500-AAS018-1CSXHC	BMS500-AAU018-1AHWXB		10,900	\$1,526
215449807	BREEZE33	BZ33-HYP365Z2-454-G3-P	Combination heat pumps with or without ducts		31,400	\$4,396
215449805	BREEZE33	BZ33-HYP365Z2-454-G3-P	Heat pump without ducts		30,000	\$4,200
207862071	Breeze33	BZ33-HYP12OUT2-G2-P	BZ33-HYP12WALL2-G2-P		10,000	\$1,400
207862072	Breeze33	BZ33-HYP18OUT2-G2-P	BZ33-HYP18WALL2-G2-P		15,000	\$2,100
207862102	BREEZE33	BZ33-HYP273Z2-G2-P	Heat pump with ducts		27,000	\$3,780

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208130312	Breeze33	BZ33-HYP24OUT2-G2-P	BZ33-MSAHU24-G2-P		16,900	\$2,366
208130311	Breeze33	BZ33-HYP18OUT2-G2-P	BZ33-MSAHU18-G2-P		15,400	\$2,156
207862077	Breeze33	BZ33-HYP12OUT2-G2-P	BZ33-CASS12-P		9,900	\$1,386
211277597	BREEZE33	HSZ18H424ZMO	AH18H424ZMI		15,400	\$2,156
211277596	BREEZE33	HSZ24H424ZMO	AH24H424ZMI		16,900	\$2,366
207862082	Breeze33	BZ33-HYP12OUT2-G2-P	BZ33-ICM12-G2-P		9,600	\$1,344
207862081	Breeze33	BZ33-HYP18OUT2-G2-P	BZ33-DIDU18-P		15,000	\$2,100
211277584	Breeze33	HSZ12H424ZMO	CA12H424ZMI		9,900	\$1,386
211277590	Breeze33	HSZ18H424ZMO	D18H424ZMI		15,000	\$2,100
211277593	Breeze33	HSZ24H424ZMO	CA24H424ZMI		21,000	\$2,940
211277587	Breeze33	HSZ12H424ZMO	C12H424ZMI		10,200	\$1,428
211277585	Breeze33	HSZ12H424ZMO	SCA12H424ZMI		9,500	\$1,330
211273235	Breeze33	BZ33-HYP12OUT2-G2-P	BZ33-OWCASS12-G2-P		9,500	\$1,330
211273236	Breeze33	BZ33-HYP18OUT2-G2-P	BZ33-OWCASS18-G2-P		14,500	\$2,030
211277589	Breeze33	HSZ18H424ZMO	SCA18H424ZMI		14,500	\$2,030
207862103	BREEZE33	BZ33-HYP273Z2-G2-P	Combination heat pumps with or without ducts		26,800	\$3,752
207862078	Breeze33	BZ33-HYP24OUT2-G2-P	BZ33-CASS24-G2-P		21,000	\$2,940
207862073	Breeze33	BZ33-HYP24OUT2-G2-P	BZ33-HYP24WALL2-G2-P		21,200	\$2,968
207862107	BREEZE33	BZ33-HYP485Z2-G2-P	Heat pump without ducts		36,000	\$5,040
207862101	BREEZE33	BZ33-HYP273Z2-G2-P	Heat pump without ducts		26,600	\$3,724
207862098	BREEZE33	BZ33-HYP182Z2-G2-P	Heat pump without ducts		15,000	\$2,100
211277594	Breeze33	HSZ24H424ZMO	D24H424ZMI		21,000	\$2,940
207862099	BREEZE33	BZ33-HYP182Z2-G2-P	Heat pump with ducts		16,000	\$2,240
207862100	BREEZE33	BZ33-HYP182Z2-G2-P	Combination heat pumps with or without ducts		15,500	\$2,170
207862106	BREEZE33	BZ33-HYP364Z2-G2-P	Combination heat pumps with or without ducts		34,000	\$4,760
207862109	BREEZE33	BZ33-HYP485Z2-G2-P	Combination heat pumps with or without ducts		36,000	\$5,040
207862084	Breeze33	BZ33-HYP24OUT2-G2-P	BZ33-IFMU24-G2-P		19,000	\$2,660
207862108	BREEZE33	BZ33-HYP485Z2-G2-P	Heat pump with ducts		36,000	\$5,040
211277595	Breeze33	HSZ24H424ZMO	FC24H424ZMI		19,000	\$2,660
207862080	Breeze33	BZ33-HYP12OUT2-G2-P	BZ33-DIDU12-P		10,600	\$1,484
211277586	Breeze33	HSZ12H424ZMO	D12H424ZMI		10,600	\$1,484
213732640	BREEZE33	BZ33-INV24OUT2-J	BZ33-MS24B-J		21,000	\$2,940
215449760	BREEZE33	BZ33-HYP18OUT2-454-G3-P	BZ33-HYP18WALL2-454-G3-P		16,600	\$2,324

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216012012	BREEZE33	BZ33-INV18OUT2-454-G3-J	BZ33-INVAHU18-454-G3-J		15,000	\$2,100
215449780	BREEZE33	BZ33-HYP12OUT2-454-G3-P	BZ33-ICM12-454-G3-P		9,800	\$1,372
215449759	BREEZE33	BZ33-HYP12OUT2-454-G3-P	BZ33-HYP12WALL2-454-G3-P		9,800	\$1,372
216012013	BREEZE33	BZ33-INV24OUT2-454-G3-J	BZ33-INVAHU24-454-G3-J		20,000	\$2,800
216012015	BREEZE33	BZ33-INV36OUT2-454-G3-J	BZ33-INVAHU36-454-G3-J		31,800	\$4,452
216012016	BREEZE33	BZ33-INV48OUT2-454-G3-J	BZ33-INVAHU48-454-G3-J		37,000	\$5,180
216012014	BREEZE33	BZ33-INV30OUT2-454-G3-J	BZ33-INVAHU30-454-G3-J		23,800	\$3,332
216012017	BREEZE33	BZ33-INV60OUT2-454-G3-J	BZ33-INVAHU60-454-G3-J		45,000	\$6,300
213732642	BREEZE33	BZ33-INV36OUT2-J	BZ33-MS36C-J		33,000	\$4,620
215449747	BREEZE33	BZ33-INV36OUT2-454-G3-J	BZ33-AHU36-454-G3-J		31,000	\$4,340
215449767	BREEZE33	BZ33-HYP36OUT2-454-G3-P	BZ33-CASS36-454-G3-P		30,600	\$4,284
215449762	BREEZE33	BZ33-HYP33OUT2-454-G3-P	BZ33-HYP33WALL2-454-G3-P		30,000	\$4,200
215449761	BREEZE33	BZ33-HYP24OUT2-454-G3-P	BZ33-HYP24WALL2-454-G3-P		21,000	\$2,940
215449768	BREEZE33	BZ33-HYP48OUT2-454-G3-P	BZ33-CASS48-454-G3-P		44,000	\$6,160
215449749	BREEZE33	BZ33-INV60OUT2-454-G3-J	BZ33-AHU60-454-G3-J		35,000	\$4,900
215449748	BREEZE33	BZ33-INV48OUT2-454-G3-J	BZ33-AHU48-454-G3-J		34,000	\$4,760
215449746	BREEZE33	BZ33-INV30OUT2-454-G3-J	BZ33-AHU30-454-G3-J		24,000	\$3,360
215449745	BREEZE33	BZ33-INV24OUT2-454-G3-J	BZ33-AHU24-454-G3-J		19,000	\$2,660
215449744	BREEZE33	BZ33-INV18OUT2-454-G3-J	BZ33-AHU18-454-G3-J		14,700	\$2,058
215449754	BREEZE33	BZ33-HYP55OUT2-454-G3-P	BZ33-MSAHU55-454-G3-P		41,000	\$5,740

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215449753	BREEZE33	BZ33-HYP48OUT2-454-G3-P	BZ33-MSAHU48-454-G3-P		40,000	\$5,600
215449752	BREEZE33	BZ33-HYP36OUT2-454-G3-P	BZ33-MSAHU36-454-G3-P		28,000	\$3,920
215449751	BREEZE33	BZ33-HYP24OUT2-454-G3-P	BZ33-MSAHU24-454-G3-P		16,900	\$2,366
215449750	BREEZE33	BZ33-HYP18OUT2-454-G3-P	BZ33-MSAHU18-454-G3-P		14,000	\$1,960
215449778	BREEZE33	BZ33-HYP55OUT2-454-G3-P	BZ33-DIDU60-454-G3-P		45,000	\$6,300
215449777	BREEZE33	BZ33-HYP48OUT2-454-G3-P	BZ33-DIDU48-454-G3-P		45,000	\$6,300
215449776	BREEZE33	BZ33-HYP36OUT2-454-G3-P	BZ33-DIDU36-454-G3-P		31,600	\$4,424
215449775	BREEZE33	BZ33-HYP24OUT2-454-G3-P	BZ33-DIDU24-454-G3-P		21,600	\$3,024
215449774	BREEZE33	BZ33-HYP18OUT2-454-G3-P	BZ33-DIDU18-454-G3-P		15,000	\$2,100
215449773	BREEZE33	BZ33-HYP12OUT2-454-G3-P	BZ33-DIDU12-454-G3-P		9,600	\$1,344
215449797	BREEZE33	BZ33-HP486Z2-454-G3-P	Heat pump with ducts		37,000	\$5,180
215449813	BREEZE33	BZ33-HYP556Z2-454-G3-P	Combination heat pumps with or without ducts		44,500	\$6,230
215449812	BREEZE33	BZ33-HYP556Z2-454-G3-P	Heat pump with ducts		45,000	\$6,300
215449811	BREEZE33	BZ33-HYP556Z2-454-G3-P	Heat pump without ducts		44,000	\$6,160
215449810	BREEZE33	BZ33-HYP486Z2-454-G3-P	Combination heat pumps with or without ducts		44,000	\$6,160
215449809	BREEZE33	BZ33-HYP486Z2-454-G3-P	Heat pump with ducts		44,500	\$6,230
215449808	BREEZE33	BZ33-HYP486Z2-454-G3-P	Heat pump without ducts		44,000	\$6,160
215449806	BREEZE33	BZ33-HYP365Z2-454-G3-P	Heat pump with ducts		33,000	\$4,620
215449804	BREEZE33	BZ33-HYP274Z2-454-G3-P	Combination heat pumps with or without ducts		24,000	\$3,360
215449803	BREEZE33	BZ33-HYP274Z2-454-G3-P	Heat pump with ducts		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215449802	BREEZE33	BZ33-HYP274Z2-454-G3-P	Heat pump without ducts		25,000	\$3,500
215449801	BREEZE33	BZ33-HYP183Z2-454-G3-P	Combination heat pumps with or without ducts		17,300	\$2,422
215449800	BREEZE33	BZ33-HYP183Z2-454-G3-P	Heat pump with ducts		17,000	\$2,380
215449799	BREEZE33	BZ33-HYP183Z2-454-G3-P	Heat pump without ducts		17,600	\$2,464
215449783	BREEZE33	BZ33-HYP24OUT2-454-G3-P	BZ33-IFCM24-454-G3-P		20,200	\$2,828
215449766	BREEZE33	BZ33-HYP24OUT2-454-G3-P	BZ33-CASS24-454-G3-P		20,400	\$2,856
215449782	BREEZE33	BZ33-HYP18OUT2-454-G3-P	BZ33-IFCM18-454-G3-P		14,400	\$2,016
215449781	BREEZE33	BZ33-HYP18OUT2-454-G3-P	BZ33-ICM16-454-G3-P		14,200	\$1,988
215449765	BREEZE33	BZ33-HYP18OUT2-454-G3-P	BZ33-CASS18-454-G3-P		14,900	\$2,086
215449764	BREEZE33	BZ33-HYP12OUT2-454-G3-P	BZ33-CASS12-454-G3-P		10,000	\$1,400
215449771	BREEZE33	BZ33-HYP12OUT2-454-G3-P	BZ33-OWCASS12-454-G3-P		9,600	\$1,344
215449786	BREEZE33	BZ33-HYP55OUT2-454-G3-P	BZ33-IFCM60-454-G3-P		41,000	\$5,740
215449785	BREEZE33	BZ33-HYP48OUT2-454-G3-P	BZ33-IFCM48-454-G3-P		38,500	\$5,390
215449784	BREEZE33	BZ33-HYP36OUT2-454-G3-P	BZ33-IFCM36-454-G3-P		30,200	\$4,228
214391152	BREEZE33	BZ33-INV30OUT2-J	BZ33-MS36B-J		19,600	\$2,744
211273238	Breeze33	BZ33-HYP48OUT2-G2-P	BZ33-MSAHU48-G2-P		38,000	\$5,320
215338141	BREEZE33	BZ33-HYP48OUT2-G2-P	BZ33-DIDU48-P		39,500	\$5,530
215338144	BREEZE33	BZ33-HYP48OUT2-G2-P	BZ33-CASS48-G2-P		35,000	\$4,900
215338139	BREEZE33	BZ33-HYP48OUT2-G2-P	BZ33-IFMU48-G2-P		35,000	\$4,900
215338142	BREEZE33	BZ33-HYP36OUT2-G2-P	BZ33-CASS36-G2-P		33,000	\$4,620
215338137	BREEZE33	BZ33-HYP36OUT2-G2-P	BZ33-IFMU36-G2-P		32,000	\$4,480
213732641	BREEZE33	BZ33-INV36OUT2-J	BZ33-MS36B-J		27,400	\$3,836
214391153	BREEZE33	BZ33-INV30OUT2-J	BZ33-MS36C-J		22,600	\$3,164
214391154	BREEZE33	BZ33-INV60OUT2-J	BZ33-MS60D-J		37,000	\$5,180
214389568	BREEZE33	BZ33-INV24OUT2-J	BZ33-WMAHU24-J		20,000	\$2,800

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214389567	BREEZE33	BZ33-INV18OUT2-J	BZ33-WMAHU18-J		15,800	\$2,212
207862105	BREEZE33	BZ33-HYP364Z2-G2-P	Heat pump with ducts		23,000	\$3,220
212361762	BREEZE33	BZ33-HYP33OUT2-G2-P	BZ33-HYP33OUT2-G2-P		28,800	\$4,032
211273237	Breeze33	BZ33-HYP36OUT2-G2-P	BZ33-MSAHU36-G2-P		28,600	\$4,004
207683299	Bryant	38MARBQ24AA3	40MBCAQ24XA3		21,000	\$2,940
207614952	Bryant	38MPRBQ12AA3	619PHBQ12XA3		10,400	\$1,456
207826657	Bryant	38MPRBQ18AA3	619PHBQ18XA3		20,200	\$2,828
208447894	BRYANT	38MURAQ18AB3	40MUAAQ18XA3		13,500	\$1,890
208447896	BRYANT	38MURAQ24AB3	40MUAAQ24XA3		19,200	\$2,688
208447892	BRYANT	38MURAQ36AB3	40MUAAQ36XA3		30,400	\$4,256
215323756	BRYANT	37MAHAQ18AA3	615AHAQ18XA3		16,600	\$2,324
215323874	BRYANT	37MAHAQ18AA3	45MBDAQ18XA3		15,000	\$2,100
215323872	BRYANT	37MAHAQ18AA3	45MBFAQ16XA3		14,200	\$1,988
215323871	BRYANT	37MAHAQ18AA3	45MBCAQ18XA3		14,900	\$2,086
215323870	BRYANT	37MAHAQ18AA3	45MCCAQ18XA3		14,500	\$2,030
215323868	BRYANT	37MAHAQ12AA3	45MBDAQ12XA3		9,600	\$1,344
215323867	BRYANT	37MAHAQ12AA3	45MBFAQ12XA3		9,800	\$1,372
215323866	BRYANT	37MAHAQ12AA3	45MBCAQ12XA3		10,000	\$1,400
215323865	BRYANT	37MAHAQ12AA3	45MCCAQ12XA3		9,600	\$1,344
215323755	BRYANT	37MAHAQ12AA3	615AHAQ12XA3		9,800	\$1,372
215323721	BRYANT	37MUHAQ36AA3	45MUHAQ36XX3		31,000	\$4,340
215323877	BRYANT	37MAHAQ24AA3	45MCFAQ24XA3		20,200	\$2,828
215323876	BRYANT	37MAHAQ24AA3	45MBCAQ24XA3		20,400	\$2,856
215323873	BRYANT	37MAHAQ18AA3	45MCFAQ18XA3		14,400	\$2,016
215323910	BRYANT	37MBHAQ58AA3	45MBDAQ58XH3		45,000	\$6,300
215323908	BRYANT	37MBHAQ48AA3	45MBDAQ48XH3		45,000	\$6,300
215323905	BRYANT	37MBHAQ36AA3	45MBDAQ36XH3		31,600	\$4,424
215323758	BRYANT	37MAHAQ33AA3	615AHAQ33XA3		30,000	\$4,200
215323878	BRYANT	37MAHAQ24AA3	45MBDAQ24XH3		21,600	\$3,024
215323757	BRYANT	37MAHAQ24AA3	615AHAQ24XA3		21,000	\$2,940
215413150	BRYANT	37MPRAQ18AA3	615PHAQ18XA3		19,300	\$2,702
215413149	BRYANT	37MPRAQ12AA3	615PHAQ12XA3		11,000	\$1,540
215357117	BRYANT	37MGHAQ30EA3	Combination heat pumps with or without ducts		31,400	\$4,396
215357116	BRYANT	37MGHAQ30EA3	Heat pump with ducts		33,000	\$4,620
215357115	BRYANT	37MGHAQ30EA3	Heat pump without ducts		30,000	\$4,200
215357166	BRYANT	37MGRAQ48FA3	Heat pump with ducts		37,000	\$5,180

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357128	BRYANT	37MGHAQ55FA3	Combination heat pumps with or without ducts		44,500	\$6,230
215357126	BRYANT	37MGHAQ55FA3	Heat pump with ducts		45,000	\$6,300
215357124	BRYANT	37MGHAQ55FA3	Heat pump without ducts		44,000	\$6,160
215357123	BRYANT	37MGHAQ48FA3	Combination heat pumps with or without ducts		44,000	\$6,160
215357122	BRYANT	37MGHAQ48FA3	Heat pump with ducts		44,500	\$6,230
215357121	BRYANT	37MGHAQ48FA3	Heat pump without ducts		44,000	\$6,160
215357120	BRYANT	37MGHAQ36EA3	Combination heat pumps with or without ducts		31,400	\$4,396
215357119	BRYANT	37MGHAQ36EA3	Heat pump with ducts		33,000	\$4,620
215357118	BRYANT	37MGHAQ36EA3	Heat pump without ducts		30,000	\$4,200
215357114	BRYANT	37MGHAQ27DA3	Combination heat pumps with or without ducts		24,000	\$3,360
215357113	BRYANT	37MGHAQ27DA3	Heat pump with ducts		23,000	\$3,220
215357112	BRYANT	37MGHAQ27DA3	Heat pump without ducts		25,000	\$3,500
215357108	BRYANT	37MGHAQ18CA3	Combination heat pumps with or without ducts		17,300	\$2,422
215357107	BRYANT	37MGHAQ18CA3	Heat pump with ducts		17,000	\$2,380
215357106	BRYANT	37MGHAQ18CA3	Heat pump without ducts		17,600	\$2,464
215323875	BRYANT	37MAHAQ18AA3	45MBDAQ18XH3		15,000	\$2,100
215323869	BRYANT	37MAHAQ12AA3	45MBDAQ12XH3		10,200	\$1,428
215323909	BRYANT	37MBHAQ58AA3	45MCFAQ58XA3		41,000	\$5,740
215323907	BRYANT	37MBHAQ48AA3	45MCFAQ48XA3		38,500	\$5,390
215323906	BRYANT	37MBHAQ48AA3	45MBCAQ48XA3		44,000	\$6,160
215323904	BRYANT	37MBHAQ36AA3	45MCFAQ36XA3		30,200	\$4,228
215323903	BRYANT	37MBHAQ36AA3	45MBCAQ36XA3		30,600	\$4,284
215318791	BRYANT	37MUHAQ48AA3	45MUHAQ60XX3		34,000	\$4,760
215318790	BRYANT	37MUHAQ30AA3	45MUHAQ36XX3		24,000	\$3,360
215318789	BRYANT	37MUHAQ18AA3	45MUHAQ24XX3		14,700	\$2,058
215318799	BRYANT	37MBHAQ58AA3	45MBAAQ60XA3		41,000	\$5,740
215318797	BRYANT	37MBHAQ36AA3	45MBAAQ36XA3		28,000	\$3,920
215318787	BRYANT	37MURAQ48AA3	45MUAAQ48XX3		32,400	\$4,536
215318784	BRYANT	37MURAQ24AA3	45MUAAQ24XX3		20,000	\$2,800
215318782	BRYANT	37MUHAQ60AA3	45MUHAQ60XX3		35,000	\$4,900
215318781	BRYANT	37MUHAQ60AA3	45MUAAQ60XX3		45,000	\$6,300
215318780	BRYANT	37MUHAQ48AA3	45MUAAQ48XX3		37,000	\$5,180
215318779	BRYANT	37MUHAQ36AA3	45MUAAQ36XX3		31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215318778	BRYANT	37MUHAQ30AA3	45MUAAQ30XX3		23,800	\$3,332
215318777	BRYANT	37MUHAQ24AA3	45MUHAQ24XX3		19,000	\$2,660
215318776	BRYANT	37MUHAQ24AA3	45MUAAQ24XX3		20,000	\$2,800
215318775	BRYANT	37MUHAQ18AA3	45MUAAQ18XX3		15,000	\$2,100
215318798	BRYANT	37MBHAQ48AA3	45MBAAQ48XA3		40,000	\$5,600
215318794	BRYANT	37MAHAQ33AA3	45MBAAQ36XB3		27,400	\$3,836
215318793	BRYANT	37MAHAQ24AA3	45MBAAQ24XB3		16,900	\$2,366
215318792	BRYANT	37MAHAQ18AA3	45MBAAQ18XB3		14,000	\$1,960
213372219	BRYANT	38MURAQ60AB3	40MULAQ60DX + CI		37,000	\$5,180
213372215	BRYANT	38MURAQ30AB3	40MULAQ36XCX + CI		22,600	\$3,164
201863364	BRYANT	38VMA036HDS3-1	Heat pump with ducts		25,000	\$3,500
205282605	BRYANT	38VMB036HDS3-1	Heat pump with ducts		25,000	\$3,500
201863366	BRYANT	38VMA048HDS3-1	Heat pump with ducts		34,000	\$4,760
205282608	BRYANT	38VMB048HDS3-1	Heat pump with ducts		34,000	\$4,760
204722812	BRYANT	38MGRQ30D--3	Combination heat pumps with or without ducts		20,200	\$2,828
204722813	BRYANT	38MGRQ36D--3	Combination heat pumps with or without ducts		23,800	\$3,332
204711113	BRYANT	38MGRQ30D--3	Heat pump with ducts		23,000	\$3,220
202345973	BRYANT	38MGRQ36D--3	Heat pump with ducts		24,600	\$3,444
200059144	BRYANT	38MAQB24R--3	40MBDQ24---3		17,300	\$2,422
200059154	BRYANT	38MAQB12R--3	40MBCQ12---3		8,700	\$1,218
201847028	BRYANT	38MAQB24R--3	40MBFQ24---3		17,200	\$2,408
201847030	BRYANT	38MBRQ48A--3	40MBFQ48---3		35,000	\$4,900
202463637	BRYANT	38MPRAQ24AA3	619PHAQ24XA3		15,450	\$2,163
205282609	BRYANT	38VMB048HDS3-1	Combination heat pumps with or without ducts		34,000	\$4,760
205282606	BRYANT	38VMB036HDS3-1	Combination heat pumps with or without ducts		25,000	\$3,500
8738645	BRYANT	38MAQB12R--3	619PEQ012BBMA		7,800	\$1,092
205921388	BRYANT	38MAQB24R--3	40MBAAQ24XA3		17,500	\$2,450
206350342	BRYANT	38MARBQ12AA3	40MBFQ12--3		8,400	\$1,176
206350340	BRYANT	38MARBQ12AA3	40MBCQ12--3		7,900	\$1,106
206396038	BRYANT	38MAQB12R--3	619AHBQ12XA3		7,500	\$1,050
206350341	BRYANT	38MARBQ12AA3	40MBDQ12--3		8,300	\$1,162
206350347	BRYANT	38MARBQ24AA3	40MBDQ24--3		14,500	\$2,030
206350345	BRYANT	38MARBQ18AA3	40MBFQ18--3		12,000	\$1,680
206350348	BRYANT	38MARBQ24AA3	40MBFQ24--3		14,500	\$2,030

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206350346	BRYANT	38MARBQ24AA3	40MBCQ24--3		14,500	\$2,030
206348145	BRYANT	38MARBQ24AA3	619AHBQ24XA3		19,800	\$2,772
206348144	BRYANT	38MARBQ18AA3	619AHBQ18XA3		10,800	\$1,512
206188260	BRYANT	38MARBQ24AA3	40MBAAQ24XA3		16,500	\$2,310
206350344	BRYANT	38MARBQ18AA3	40MBDQ18--3		12,700	\$1,778
201846964	BRYANT	38MAQB12R--3	40MBDQ12---3		8,500	\$1,190
207642911	BRYANT	38MGHBQ48EA3	Combination heat pumps with or without ducts		29,000	\$4,060
207642905	BRYANT	38MGHBQ30DA3	Combination heat pumps with or without ducts		18,200	\$2,548
207642913	BRYANT	38MGHBQ36DA3	Heat pump with ducts		23,000	\$3,220
207642904	BRYANT	38MGHBQ30DA3	Heat pump with ducts		19,000	\$2,660
207642914	BRYANT	38MGHBQ36DA3	Combination heat pumps with or without ducts		23,000	\$3,220
207642910	BRYANT	38MGHBQ48EA3	Heat pump with ducts		28,000	\$3,920
205274128	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	986TC66100C21***	33,600	\$4,704
205274127	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	986TC60080C21***	33,800	\$4,732
205274126	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	987MB66120C24***	33,800	\$4,732
205274125	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	987MB66100C21***	33,600	\$4,704
205274124	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	987MB60080C21***	33,800	\$4,732
203380999	BRYANT	38MAQB18R--3	FM(C,U)4Z18**AL*		12,600	\$1,764
203381000	BRYANT	38MAQB24R--3	FM(C,U)4Z24**AL*		15,000	\$2,100
203380984	BRYANT	38MAQB18R--3	FMA4X18**AL*		10,800	\$1,512
204344195	BRYANT	38MAQB18R--3	FV4CNF002		11,000	\$1,540
204344196	BRYANT	38MAQB24R--3	FV4CNF002		14,000	\$1,960
204344197	BRYANT	38MAQB30R--3	FV4CN(B,F)003		20,200	\$2,828
205273717	BRYANT	284ANV024*0**A*	FE4AN(B,F)003L+UI		24,200	\$3,388
205273718	BRYANT	284ANV024*0**A*	FE4AN(B,F)005L+UI		23,600	\$3,304
205273797	BRYANT	284ANV024*0**A*	CNPV*6024AL*+UI	88*TA60110C21***	23,800	\$3,332
205273802	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	987MB66100C21***	24,200	\$3,388
205273804	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	88*TA36070C14***	24,200	\$3,388
205273803	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	987MB66120C24***	24,200	\$3,388
205273805	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	88*TA48090C17***	24,200	\$3,388
205273806	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	88*TA60110C21***	24,200	\$3,388
205273892	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	986TC42060C17***	24,200	\$3,388
205273893	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	986TC42080C17***	24,200	\$3,388
205273894	BRYANT	284ANV024*0**A*	CNPV*4824AL*+UI	88*TA60070C21***	24,200	\$3,388
205273895	BRYANT	284ANV024*0**A*	CNPV*4824AL*+UI	88*TA60090C21***	24,000	\$3,360

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205273897	BRYANT	284ANV024*0**A*	CNPV*4824AL*+UI	986TC66120C24***	24,000	\$3,360
205273898	BRYANT	284ANV024*0**A*	CNPV*6024AL*+UI	88*TA60070C21***	23,800	\$3,332
205273900	BRYANT	284ANV024*0**A*	CNPV*6024AL*+UI	88*TA66135C24***	23,800	\$3,332
205273896	BRYANT	284ANV024*0**A*	CNPV*4824AL*+UI	88*TA66135C24***	24,000	\$3,360
205273899	BRYANT	284ANV024*0**A*	CNPV*6024AL*+UI	88*TA60090C21***	23,800	\$3,332
205273901	BRYANT	284ANV024*0**A*	CNPV*6024AL*+UI	986TC66120C24***	23,800	\$3,332
205273903	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	88*TA48070C17***	24,200	\$3,388
205273904	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	88*TA60070C21***	24,200	\$3,388
205273902	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	88*TA36045C17***	24,400	\$3,416
205273907	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	986TC42060C17***	24,400	\$3,416
205273905	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	88*TA60090C21***	24,200	\$3,388
205273906	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	88*TA66135C24***	24,200	\$3,388
205273908	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	986TC42080C17***	24,400	\$3,416
205273910	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	88*TA36045C17***	24,400	\$3,416
205273909	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	986TC66120C24***	24,200	\$3,388
205273912	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	88*TA60070C21***	24,200	\$3,388
205273911	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	88*TA48070C17***	24,200	\$3,388
205273914	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	88*TA66135C24***	24,000	\$3,360
205273913	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	88*TA60090C21***	24,000	\$3,360
205273915	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	986TC42060C17***	24,400	\$3,416
205273916	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	986TC42080C17***	24,200	\$3,388
205273923	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	986TC42060C17***	24,200	\$3,388
205273918	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	88*TA36045C17***	24,200	\$3,388
205273917	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	986TC66120C24***	24,200	\$3,388
205273919	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	88*TA48070C17***	24,200	\$3,388
205273920	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	88*TA60070C21***	24,200	\$3,388
205273921	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	88*TA60090C21***	24,000	\$3,360
205273922	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	88*TA66135C24***	24,000	\$3,360
205273925	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	986TC66120C24***	24,000	\$3,360
205273924	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	986TC42080C17***	24,200	\$3,388
205273927	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	88*TA48070C17***	23,800	\$3,332
205273926	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	88*TA36045C17***	24,000	\$3,360
205273929	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	88*TA60090C21***	23,800	\$3,332
205273928	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	88*TA60070C21***	23,800	\$3,332
205273931	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	986TC42060C17***	24,000	\$3,360
205273930	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	88*TA66135C24***	23,800	\$3,332
205273932	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	986TC42080C17***	24,000	\$3,360
205273933	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	986TC66120C24***	23,800	\$3,332

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205273716	BRYANT	284ANV024*0**A*	FE4ANF002L+UI		24,400	\$3,416
205273721	BRYANT	284ANV024*0**A*	CAP**3617AL*+UI	88*TA36070C14***	24,400	\$3,416
205273726	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	987MB60080C21***	24,200	\$3,388
205273722	BRYANT	284ANV024*0**A*	CAP**3617AL*+UI	88*TA48090C17***	24,200	\$3,388
205273728	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	88*TA48090C17***	24,200	\$3,388
205273727	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	987MB66100C21***	24,200	\$3,388
205273729	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	88*TA60110C21***	24,200	\$3,388
205273733	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	987MB60080C21***	24,200	\$3,388
205273734	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	987MB66100C21***	24,200	\$3,388
205273735	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	88*TA48090C17***	24,200	\$3,388
205273736	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	88*TA60110C21***	24,200	\$3,388
205273743	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	987MB42080C17***	24,000	\$3,360
205273738	BRYANT	284ANV024*0**A*	CAP**4224AL*+UI	987MB60080C21***	24,200	\$3,388
205273740	BRYANT	284ANV024*0**A*	CAP**4224AL*+UI	987MB66120C24***	24,200	\$3,388
205273739	BRYANT	284ANV024*0**A*	CAP**4224AL*+UI	987MB66100C21***	24,200	\$3,388
205273741	BRYANT	284ANV024*0**A*	CAP**4224AL*+UI	88*TA60110C21***	24,200	\$3,388
205273744	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	987MB60060C21***	24,000	\$3,360
205273745	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	987MB60080C21***	24,000	\$3,360
205273746	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	987MB66100C21***	24,000	\$3,360
205273747	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	88*TA48090C17***	23,800	\$3,332
205273748	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	88*TA60110C21***	23,800	\$3,332
205273749	BRYANT	284ANV024*0**A*	CAP**4824AL*+UI	987MB60060C21***	24,000	\$3,360
205273750	BRYANT	284ANV024*0**A*	CAP**4824AL*+UI	987MB60080C21***	24,000	\$3,360
205273751	BRYANT	284ANV024*0**A*	CAP**4824AL*+UI	987MB66100C21***	23,800	\$3,332
205273752	BRYANT	284ANV024*0**A*	CAP**4824AL*+UI	987MB66120C24***	24,000	\$3,360
205273753	BRYANT	284ANV024*0**A*	CAP**4824AL*+UI	88*TA60110C21***	23,800	\$3,332
205273758	BRYANT	284ANV024*0**A*	CAP**6024AL*+UI	88*TA60110C21***	23,600	\$3,304
205273755	BRYANT	284ANV024*0**A*	CAP**6024AL*+UI	987MB60080C21***	23,600	\$3,304
205273754	BRYANT	284ANV024*0**A*	CAP**6024AL*+UI	987MB60060C21***	23,800	\$3,332
205273756	BRYANT	284ANV024*0**A*	CAP**6024AL*+UI	987MB66100C21***	23,600	\$3,304
205273757	BRYANT	284ANV024*0**A*	CAP**6024AL*+UI	987MB66120C24***	23,600	\$3,304
205273761	BRYANT	284ANV024*0**A*	CNPV*3617AL*+UI	88*TA36070C14***	24,400	\$3,416
205273762	BRYANT	284ANV024*0**A*	CNPV*3617AL*+UI	88*TA48090C17***	24,200	\$3,388
205273766	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	987MB60080C21***	24,400	\$3,416
205273767	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	987MB66100C21***	24,400	\$3,416
205273768	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	88*TA48090C17***	24,200	\$3,388
205273769	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	88*TA60110C21***	24,200	\$3,388
205273772	BRYANT	284ANV024*0**A*	CNPV*4217AL*+UI	88*TA36070C14***	24,200	\$3,388

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205273773	BRYANT	284ANV024*0**A*	CNPV*4217AL*+UI	88*TA48090C17***	24,200	\$3,388
205273777	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	987MB60080C21***	24,200	\$3,388
205273778	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	987MB66100C21***	24,200	\$3,388
205273779	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	88*TA48090C17***	24,200	\$3,388
205273780	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	88*TA60110C21***	24,200	\$3,388
205273782	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	987MB42080C17***	24,200	\$3,388
205273786	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	88*TA48090C17***	24,000	\$3,360
205273783	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	987MB60060C21***	24,200	\$3,388
205273784	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	987MB60080C21***	24,000	\$3,360
205273785	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	987MB66100C21***	24,000	\$3,360
205273789	BRYANT	284ANV024*0**A*	CNPV*4824AL*+UI	987MB60080C21***	24,000	\$3,360
205273787	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	88*TA60110C21***	24,000	\$3,360
205273788	BRYANT	284ANV024*0**A*	CNPV*4824AL*+UI	987MB60060C21***	24,200	\$3,388
205273790	BRYANT	284ANV024*0**A*	CNPV*4824AL*+UI	987MB66100C21***	24,000	\$3,360
205273791	BRYANT	284ANV024*0**A*	CNPV*4824AL*+UI	987MB66120C24***	24,000	\$3,360
205273792	BRYANT	284ANV024*0**A*	CNPV*4824AL*+UI	88*TA60110C21***	24,000	\$3,360
205273794	BRYANT	284ANV024*0**A*	CNPV*6024AL*+UI	987MB60080C21***	23,800	\$3,332
205273793	BRYANT	284ANV024*0**A*	CNPV*6024AL*+UI	987MB60060C21***	24,000	\$3,360
205273796	BRYANT	284ANV024*0**A*	CNPV*6024AL*+UI	987MB66120C24***	23,800	\$3,332
205273795	BRYANT	284ANV024*0**A*	CNPV*6024AL*+UI	987MB66100C21***	23,800	\$3,332
205273936	BRYANT	284ANV036*0**A*	FE4ANB006L+UI		32,400	\$4,536
205273934	BRYANT	284ANV036*0**A*	FE4AN(B,F)005L+UI		32,800	\$4,592
205273810	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	987MB60080C21***	24,200	\$3,388
205273812	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	987MB66120C24***	24,200	\$3,388
205273819	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	987MB60080C21***	24,000	\$3,360
205273811	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	987MB66100C21***	24,000	\$3,360
205273813	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	88*TA36070C14***	24,200	\$3,388
205273815	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	88*TA60110C21***	24,000	\$3,360
205273814	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	88*TA48090C17***	24,000	\$3,360
205273820	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	987MB66100C21***	24,000	\$3,360
205273822	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	88*TA36070C14***	24,200	\$3,388
205273821	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	987MB66120C24***	24,000	\$3,360
205273823	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	88*TA48090C17***	24,000	\$3,360
205273826	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	987MB42080C17***	24,000	\$3,360
205273824	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	88*TA60110C21***	24,000	\$3,360
205273828	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	987MB60080C21***	23,800	\$3,332
205273829	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	987MB66100C21***	23,800	\$3,332
205273830	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	987MB66120C24***	23,800	\$3,332

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205273827	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	987MB60060C21***	23,800	\$3,332
205273831	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	88*TA36070C14***	23,800	\$3,332
205273833	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	88*TA60110C21***	23,800	\$3,332
205273832	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	88*TA48090C17***	23,800	\$3,332
205273834	BRYANT	284ANV024*0**A*	CAP**3617AL*+UI	88*TA36045C17***	24,400	\$3,416
205273835	BRYANT	284ANV024*0**A*	CAP**3617AL*+UI	88*TA48070C17***	24,400	\$3,416
205273836	BRYANT	284ANV024*0**A*	CAP**3617AL*+UI	986TC42060C17***	24,400	\$3,416
205273837	BRYANT	284ANV024*0**A*	CAP**3617AL*+UI	986TC42080C17***	24,400	\$3,416
205273839	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	88*TA48070C17***	24,200	\$3,388
205273838	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	88*TA36045C17***	24,400	\$3,416
205273841	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	88*TA60090C21***	24,200	\$3,388
205273840	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	88*TA60070C21***	24,200	\$3,388
205273843	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	986TC42080C17***	24,400	\$3,416
205273842	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	986TC42060C17***	24,400	\$3,416
205273844	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	88*TA36045C17***	24,400	\$3,416
205273845	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	88*TA48070C17***	24,200	\$3,388
205273847	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	88*TA60090C21***	24,200	\$3,388
205273846	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	88*TA60070C21***	24,200	\$3,388
205273848	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	986TC42060C17***	24,400	\$3,416
205273849	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	986TC42080C17***	24,400	\$3,416
205273850	BRYANT	284ANV024*0**A*	CAP**4224AL*+UI	88*TA60070C21***	24,200	\$3,388
205273851	BRYANT	284ANV024*0**A*	CAP**4224AL*+UI	88*TA60090C21***	24,200	\$3,388
205273853	BRYANT	284ANV024*0**A*	CAP**4224AL*+UI	986TC66120C24***	24,200	\$3,388
205273852	BRYANT	284ANV024*0**A*	CAP**4224AL*+UI	88*TA66135C24***	24,000	\$3,360
205273854	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	88*TA36045C17***	24,200	\$3,388
205273855	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	88*TA48070C17***	24,000	\$3,360
205273856	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	88*TA60070C21***	24,000	\$3,360
205273857	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	88*TA60090C21***	23,800	\$3,332
205273858	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	986TC42060C17***	24,200	\$3,388
205273859	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	986TC42080C17***	24,000	\$3,360
205273860	BRYANT	284ANV024*0**A*	CAP**4824AL*+UI	88*TA60070C21***	24,000	\$3,360
205273861	BRYANT	284ANV024*0**A*	CAP**4824AL*+UI	88*TA60090C21***	23,800	\$3,332
205273862	BRYANT	284ANV024*0**A*	CAP**4824AL*+UI	88*TA66135C24***	23,800	\$3,332
205273865	BRYANT	284ANV024*0**A*	CAP**6024AL*+UI	88*TA60090C21***	23,600	\$3,304
205273864	BRYANT	284ANV024*0**A*	CAP**6024AL*+UI	88*TA60070C21***	23,600	\$3,304
205273863	BRYANT	284ANV024*0**A*	CAP**4824AL*+UI	986TC66120C24***	24,000	\$3,360
205273866	BRYANT	284ANV024*0**A*	CAP**6024AL*+UI	88*TA66135C24***	23,600	\$3,304
205273867	BRYANT	284ANV024*0**A*	CAP**6024AL*+UI	986TC66120C24***	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205273868	BRYANT	284ANV024*0**A*	CNPV*3617AL*+UI	88*TA36045C17***	24,600	\$3,444
205273869	BRYANT	284ANV024*0**A*	CNPV*3617AL*+UI	88*TA48070C17***	24,400	\$3,416
205273870	BRYANT	284ANV024*0**A*	CNPV*3617AL*+UI	986TC42060C17***	24,600	\$3,444
205273871	BRYANT	284ANV024*0**A*	CNPV*3617AL*+UI	986TC42080C17***	24,400	\$3,416
205273873	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	88*TA48070C17***	24,400	\$3,416
205273872	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	88*TA36045C17***	24,600	\$3,444
205273875	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	88*TA60090C21***	24,200	\$3,388
205273878	BRYANT	284ANV024*0**A*	CNPV*4217AL*+UI	88*TA36045C17***	24,400	\$3,416
205273874	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	88*TA60070C21***	24,400	\$3,416
205273876	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	986TC42060C17***	24,600	\$3,444
205273877	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	986TC42080C17***	24,400	\$3,416
205273879	BRYANT	284ANV024*0**A*	CNPV*4217AL*+UI	88*TA48070C17***	24,200	\$3,388
205273880	BRYANT	284ANV024*0**A*	CNPV*4217AL*+UI	986TC42060C17***	24,400	\$3,416
205273881	BRYANT	284ANV024*0**A*	CNPV*4217AL*+UI	986TC42080C17***	24,400	\$3,416
205273882	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	88*TA36045C17***	24,400	\$3,416
205273884	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	88*TA60070C21***	24,200	\$3,388
205273883	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	88*TA48070C17***	24,400	\$3,416
205273885	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	88*TA60090C21***	24,200	\$3,388
205273889	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	88*TA48070C17***	24,200	\$3,388
205273886	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	986TC42060C17***	24,400	\$3,416
205273887	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	986TC42080C17***	24,400	\$3,416
205273888	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	88*TA36045C17***	24,200	\$3,388
205273890	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	88*TA60070C21***	24,200	\$3,388
205273891	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	88*TA60090C21***	24,000	\$3,360
205273808	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	987MB42080C17***	24,200	\$3,388
205273809	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	987MB60060C21***	24,200	\$3,388
205273988	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	88*TA48090C17***	33,600	\$4,704
205273989	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	88*TA60110C21***	33,400	\$4,676
205274007	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	88*TA60090C21***	33,200	\$4,648
205274008	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	88*TA66135C24***	33,000	\$4,620
205274015	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	88*TA60110C21***	33,200	\$4,648
205274018	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	88*TA60090C21***	32,800	\$4,592
205274019	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	88*TA66135C24***	32,600	\$4,564
205274020	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	986TC66120C24***	32,800	\$4,592
205274021	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	987MB60080C21***	33,000	\$4,620
205274022	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	987MB66100C21***	32,800	\$4,592
205274023	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	987MB66120C24***	33,000	\$4,620
205274024	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	986TC60080C21***	33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205274025	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	986TC66100C21***	32,800	\$4,592
205274026	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	88*TA60110C21***	32,800	\$4,592
205274029	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	88*TA48070C17***	33,400	\$4,676
205274031	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	88*TA60090C21***	33,000	\$4,620
205274030	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	88*TA60070C21***	33,200	\$4,648
205274037	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	987MB66100C21***	33,000	\$4,620
205274036	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	987MB60080C21***	33,200	\$4,648
205274038	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	986TC60080C21***	33,200	\$4,648
205274041	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	88*TA60110C21***	33,000	\$4,620
205274043	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	88*TA60070C21***	33,200	\$4,648
205274040	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	88*TA48090C17***	33,200	\$4,648
205274039	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	986TC66100C21***	33,000	\$4,620
205274044	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	88*TA60090C21***	33,000	\$4,620
205274045	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	88*TA66135C24***	32,800	\$4,592
205274047	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	987MB60080C21***	33,200	\$4,648
205274049	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	987MB66120C24***	33,000	\$4,620
205274046	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	986TC66120C24***	33,000	\$4,620
205274048	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	987MB66100C21***	33,000	\$4,620
205274050	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	986TC60080C21***	33,200	\$4,648
205274052	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	88*TA60110C21***	33,000	\$4,620
205274051	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	986TC66100C21***	33,000	\$4,620
205274071	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	987MB66100C21***	33,800	\$4,732
205274080	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	88*TA60090C21***	33,400	\$4,676
205274088	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	986TC66100C21***	33,400	\$4,676
205274079	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	88*TA60070C21***	33,600	\$4,704
205274085	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	987MB60080C21***	33,600	\$4,704
205274086	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	987MB66100C21***	33,400	\$4,676
205274087	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	986TC60080C21***	33,600	\$4,704
205274090	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	88*TA60110C21***	33,400	\$4,676
205274089	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	88*TA48090C17***	33,400	\$4,676
205274092	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	88*TA60070C21***	33,600	\$4,704
205274093	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	88*TA60090C21***	33,400	\$4,676
205274095	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	986TC66120C24***	33,400	\$4,676
205274094	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	88*TA66135C24***	33,200	\$4,648
205274097	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	987MB66100C21***	33,400	\$4,676
205274101	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	88*TA60110C21***	33,400	\$4,676
205274096	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	987MB60080C21***	33,600	\$4,704
205274098	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	987MB66120C24***	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205274099	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	986TC60080C21***	33,600	\$4,704
205274100	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	986TC66100C21***	33,400	\$4,676
205274103	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	88*TA60070C21***	33,200	\$4,648
205274104	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	88*TA60090C21***	33,000	\$4,620
205274109	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	987MB66120C24***	33,200	\$4,648
205274107	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	987MB60080C21***	33,200	\$4,648
205274105	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	88*TA66135C24***	32,800	\$4,592
205274106	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	986TC66120C24***	33,000	\$4,620
205274108	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	987MB66100C21***	33,000	\$4,620
205274110	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	986TC60080C21***	33,200	\$4,648
205274111	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	986TC66100C21***	33,000	\$4,620
205274112	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	88*TA60110C21***	33,000	\$4,620
205274113	BRYANT	284ANV036*0**A*	CNPV*6024AL*+UI	987MB60060C21***	33,600	\$4,704
205274175	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	88*TA66135C24***	32,800	\$4,592
205274174	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	88*TA60090C21***	32,800	\$4,592
205274182	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	987MB66100C21***	33,000	\$4,620
205274178	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	986TC66120C24***	33,000	\$4,620
205274185	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	986TC66100C21***	33,000	\$4,620
205274187	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	88*TA48090C17***	33,000	\$4,620
205274188	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	88*TA60110C21***	33,000	\$4,620
205273719	BRYANT	284ANV024*0**A*	CAP**3617AL*+UI	987MB42060C17***	24,600	\$3,444
205273720	BRYANT	284ANV024*0**A*	CAP**3617AL*+UI	987MB42080C17***	24,400	\$3,416
205273723	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	987MB42060C17***	24,400	\$3,416
205273725	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	987MB60060C21***	24,400	\$3,416
205273724	BRYANT	284ANV024*0**A*	CAP**3621AL*+UI	987MB42080C17***	24,400	\$3,416
205273732	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	987MB60060C21***	24,200	\$3,388
205273730	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	987MB42060C17***	24,400	\$3,416
205273742	BRYANT	284ANV024*0**A*	CAP**4821AL*+UI	987MB42060C17***	24,200	\$3,388
205273731	BRYANT	284ANV024*0**A*	CAP**4221AL*+UI	987MB42080C17***	24,400	\$3,416
205273737	BRYANT	284ANV024*0**A*	CAP**4224AL*+UI	987MB60060C21***	24,200	\$3,388
205273759	BRYANT	284ANV024*0**A*	CNPV*3617AL*+UI	987MB42060C17***	24,600	\$3,444
205273760	BRYANT	284ANV024*0**A*	CNPV*3617AL*+UI	987MB42080C17***	24,400	\$3,416
205273763	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	987MB42060C17***	24,600	\$3,444
205273764	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	987MB42080C17***	24,400	\$3,416
205273774	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	987MB42060C17***	24,400	\$3,416
205273770	BRYANT	284ANV024*0**A*	CNPV*4217AL*+UI	987MB42060C17***	24,400	\$3,416
205273765	BRYANT	284ANV024*0**A*	CNPV*3621AL*+UI	987MB60060C21***	24,400	\$3,416
205273771	BRYANT	284ANV024*0**A*	CNPV*4217AL*+UI	987MB42080C17***	24,400	\$3,416

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205273775	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	987MB42080C17***	24,400	\$3,416
205273798	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	987MB42060C17***	24,400	\$3,416
205273776	BRYANT	284ANV024*0**A*	CNPV*4221AL*+UI	987MB60060C21***	24,400	\$3,416
205273781	BRYANT	284ANV024*0**A*	CNPV*4821AL*+UI	987MB42060C17***	24,400	\$3,416
205273800	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	987MB60060C21***	24,400	\$3,416
205273801	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	987MB60080C21***	24,200	\$3,388
205273799	BRYANT	284ANV024*0**A*	CSPH*3612AL*+UI	987MB42080C17***	24,400	\$3,416
205273807	BRYANT	284ANV024*0**A*	CSPH*4212AL*+UI	987MB42060C17***	24,400	\$3,416
205273817	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	987MB42080C17***	24,200	\$3,388
205273818	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	987MB60060C21***	24,200	\$3,388
205273816	BRYANT	284ANV024*0**A*	CSPH*4812AL*+UI	987MB42060C17***	24,400	\$3,416
205273825	BRYANT	284ANV024*0**A*	CSPH*6012AL*+UI	987MB42060C17***	24,000	\$3,360
205273935	BRYANT	284ANV036*0**A*	FE4AN(B,F)003L+UI		33,000	\$4,620
205273947	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	987MB66100C21***	33,600	\$4,704
205273950	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	88*TA48090C17***	33,600	\$4,704
205273949	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	986TC66100C21***	33,600	\$4,704
205273987	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	986TC66100C21***	33,400	\$4,676
205273980	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	88*TA60090C21***	33,400	\$4,676
205273985	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	987MB66100C21***	33,400	\$4,676
205273951	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	88*TA60110C21***	33,600	\$4,704
205274147	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	986TC66100C21***	33,400	\$4,676
205274146	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	986TC60080C21***	33,600	\$4,704
205274150	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	88*TA60110C21***	33,400	\$4,676
205274149	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	88*TA48090C17***	33,600	\$4,704
205274153	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	88*TA48070C17***	33,800	\$4,732
205274154	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	88*TA60070C21***	33,600	\$4,704
205274156	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	88*TA66135C24***	33,200	\$4,648
205274155	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	88*TA60090C21***	33,400	\$4,676
205274159	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	986TC66120C24***	33,400	\$4,676
205274162	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	987MB60080C21***	33,600	\$4,704
205274164	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	987MB66120C24***	33,600	\$4,704
205274163	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	987MB66100C21***	33,400	\$4,676
205274165	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	986TC60080C21***	33,600	\$4,704
205274166	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	986TC66100C21***	33,400	\$4,676
205274168	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	88*TA48090C17***	33,400	\$4,676
205274169	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	88*TA60110C21***	33,400	\$4,676
205274172	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	88*TA48070C17***	33,400	\$4,676
205274183	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	987MB66120C24***	33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205274173	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	88*TA60070C21***	33,200	\$4,648
205274177	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	986TC42080C17***	33,600	\$4,704
205274180	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	987MB42080C17***	33,600	\$4,704
205274184	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	986TC60080C21***	33,000	\$4,620
205274181	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	987MB60080C21***	33,000	\$4,620
205274186	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	88*TA36070C14***	33,600	\$4,704
205274189	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	987MB60060C21***	33,400	\$4,676
205273941	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	88*TA60070C21***	33,800	\$4,732
205273939	BRYANT	284ANV036*0**A*	CAP**3717AL*+UI	88*TA48090C17***	33,800	\$4,732
205273940	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	88*TA48070C17***	34,000	\$4,760
205273942	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	88*TA60090C21***	33,400	\$4,676
205273948	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	986TC60080C21***	33,600	\$4,704
205273946	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	987MB60080C21***	33,600	\$4,704
205273956	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	88*TA60090C21***	33,600	\$4,704
205273952	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	987MB60060C21***	34,000	\$4,760
205273965	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	88*TA60110C21***	33,800	\$4,732
205273968	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	88*TA60090C21***	33,600	\$4,704
205273969	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	88*TA66135C24***	33,600	\$4,704
205273976	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	88*TA60110C21***	33,600	\$4,704
205273984	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	987MB60080C21***	33,600	\$4,704
205273978	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	88*TA48070C17***	33,800	\$4,732
205273983	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	987MB42080C17***	34,000	\$4,760
205273979	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	88*TA60070C21***	33,600	\$4,704
205273986	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	986TC60080C21***	33,600	\$4,704
205273990	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	987MB60060C21***	34,000	\$4,760
205273992	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	88*TA48070C17***	33,800	\$4,732
205274000	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	987MB66100C21***	33,400	\$4,676
205273994	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	88*TA60090C21***	33,200	\$4,648
205274001	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	986TC60080C21***	33,400	\$4,676
205274003	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	88*TA48090C17***	33,400	\$4,676
205274002	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	986TC66100C21***	33,400	\$4,676
205274004	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	88*TA60110C21***	33,400	\$4,676
205274009	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	986TC66120C24***	33,200	\$4,648
205274006	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	88*TA60070C21***	33,400	\$4,676
205274011	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	987MB66100C21***	33,200	\$4,648
205274014	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	986TC66100C21***	33,200	\$4,648
205274016	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	987MB60060C21***	33,800	\$4,732
205274017	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	88*TA60070C21***	33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205274027	BRYANT	284ANV036*0**A*	CAP**6024AL*+UI	987MB60060C21***	33,400	\$4,676
205274028	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	88*TA36045C17***	33,800	\$4,732
205274032	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	986TC42060C17***	34,000	\$4,760
205274035	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	987MB42080C17***	33,800	\$4,732
205274033	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	986TC42080C17***	33,800	\$4,732
205274042	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	987MB60060C21***	33,600	\$4,704
205274053	BRYANT	284ANV036*0**A*	CAP**6124AL*+UI	987MB60060C21***	33,600	\$4,704
205274070	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	987MB60080C21***	34,000	\$4,760
205274055	BRYANT	284ANV036*0**A*	CNPV*4217AL*+UI	88*TA48070C17***	34,200	\$4,788
205274061	BRYANT	284ANV036*0**A*	CNPV*4217AL*+UI	88*TA48090C17***	33,800	\$4,732
205274073	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	986TC66100C21***	33,800	\$4,732
205274065	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	88*TA60090C21***	33,800	\$4,732
205274072	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	986TC60080C21***	34,000	\$4,760
205274075	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	88*TA60110C21***	33,800	\$4,732
205274074	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	88*TA48090C17***	33,800	\$4,732
205274078	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	88*TA48070C17***	33,800	\$4,732
205274084	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	987MB42080C17***	34,000	\$4,760
205274091	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	987MB60060C21***	34,000	\$4,760
205274082	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	986TC42080C17***	34,000	\$4,760
205274117	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	88*TA60090C21***	33,600	\$4,704
205274102	BRYANT	284ANV036*0**A*	CNPV*4824AL*+UI	987MB60060C21***	34,000	\$4,760
205274121	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	986TC66120C24***	33,600	\$4,704
205274118	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	88*TA66135C24***	33,400	\$4,676
205274135	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	88*TA60070C21***	33,600	\$4,704
205274130	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	88*TA48090C17***	33,800	\$4,732
205274131	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	88*TA60110C21***	33,600	\$4,704
205274136	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	88*TA60090C21***	33,400	\$4,676
205274137	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	88*TA66135C24***	33,400	\$4,676
205274140	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	986TC66120C24***	33,400	\$4,676
205274143	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	987MB60080C21***	33,600	\$4,704
205274144	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	987MB66100C21***	33,400	\$4,676
205274145	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	987MB66120C24***	33,600	\$4,704
205273958	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	987MB42060C17***	34,600	\$4,844
205273953	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	88*TA36045C17***	34,600	\$4,844
205273967	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	88*TA60070C21***	33,800	\$4,732
205274114	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	88*TA36045C17***	34,600	\$4,844
205274122	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	987MB42060C17***	34,400	\$4,816
205273937	BRYANT	284ANV036*0**A*	CAP**3717AL*+UI	88*TA48070C17***	34,200	\$4,788

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205273938	BRYANT	284ANV036*0**A*	CAP**3717AL*+UI	88*TA36070C14***	34,000	\$4,760
205273943	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	986TC42060C17***	34,400	\$4,816
205273945	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	987MB42080C17***	34,000	\$4,760
205273954	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	88*TA48070C17***	34,200	\$4,788
205273944	BRYANT	284ANV036*0**A*	CAP**3721AL*+UI	986TC42080C17***	34,200	\$4,788
205273955	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	88*TA60070C21***	34,000	\$4,760
205273960	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	987MB60080C21***	33,800	\$4,732
205273957	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	986TC42060C17***	34,600	\$4,844
205273959	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	987MB42080C17***	34,400	\$4,816
205273963	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	986TC66100C21***	33,800	\$4,732
205273962	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	986TC60080C21***	33,800	\$4,732
205273961	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	987MB66100C21***	33,800	\$4,732
205273966	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	987MB60060C21***	34,200	\$4,788
205273964	BRYANT	284ANV036*0**A*	CAP**4221AL*+UI	88*TA48090C17***	33,800	\$4,732
205273971	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	987MB60080C21***	33,800	\$4,732
205273970	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	986TC66120C24***	33,600	\$4,704
205273974	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	986TC60080C21***	33,800	\$4,732
205273973	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	987MB66120C24***	33,800	\$4,732
205273972	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	987MB66100C21***	33,600	\$4,704
205273982	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	986TC42080C17***	34,200	\$4,788
205273975	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	986TC66100C21***	33,600	\$4,704
205273977	BRYANT	284ANV036*0**A*	CAP**4224AL*+UI	987MB60060C21***	34,200	\$4,788
205273981	BRYANT	284ANV036*0**A*	CAP**4321AL*+UI	986TC42060C17***	34,400	\$4,816
205273991	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	88*TA36045C17***	34,200	\$4,788
205273993	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	88*TA60070C21***	33,600	\$4,704
205273995	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	986TC42060C17***	34,200	\$4,788
205273996	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	986TC42080C17***	34,000	\$4,760
205273997	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	987MB42060C17***	34,000	\$4,760
205273999	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	987MB60080C21***	33,400	\$4,676
205273998	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	987MB42080C17***	33,800	\$4,732
205274005	BRYANT	284ANV036*0**A*	CAP**4821AL*+UI	987MB60060C21***	33,800	\$4,732
205274010	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	987MB60080C21***	33,400	\$4,676
205274012	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	987MB66120C24***	33,400	\$4,676
205274013	BRYANT	284ANV036*0**A*	CAP**4824AL*+UI	986TC60080C21***	33,400	\$4,676
205274034	BRYANT	284ANV036*0**A*	CAP**6121AL*+UI	987MB42060C17***	33,600	\$4,704
205274058	BRYANT	284ANV036*0**A*	CNPV*4217AL*+UI	987MB42060C17***	34,400	\$4,816
205274056	BRYANT	284ANV036*0**A*	CNPV*4217AL*+UI	986TC42060C17***	34,600	\$4,844
205274054	BRYANT	284ANV036*0**A*	CNPV*4217AL*+UI	88*TA36045C17***	34,600	\$4,844

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205274057	BRYANT	284ANV036*0**A*	CNPV*4217AL*+UI	986TC42080C17***	34,400	\$4,816
205274063	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	88*TA48070C17***	34,200	\$4,788
205274059	BRYANT	284ANV036*0**A*	CNPV*4217AL*+UI	987MB42080C17***	34,200	\$4,788
205274062	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	88*TA36045C17***	34,800	\$4,872
205274060	BRYANT	284ANV036*0**A*	CNPV*4217AL*+UI	88*TA36070C14***	34,200	\$4,788
205274064	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	88*TA60070C21***	34,000	\$4,760
205274067	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	986TC42080C17***	34,600	\$4,844
205274066	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	986TC42060C17***	34,600	\$4,844
205274068	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	987MB42060C17***	34,600	\$4,844
205274069	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	987MB42080C17***	34,400	\$4,816
205274076	BRYANT	284ANV036*0**A*	CNPV*4221AL*+UI	987MB60060C21***	34,400	\$4,816
205274077	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	88*TA36045C17***	34,200	\$4,788
205274083	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	987MB42060C17***	34,200	\$4,788
205274081	BRYANT	284ANV036*0**A*	CNPV*4821AL*+UI	986TC42060C17***	34,400	\$4,816
205274115	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	88*TA48070C17***	34,000	\$4,760
205274116	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	88*TA60070C21***	33,800	\$4,732
205274119	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	986TC42060C17***	34,600	\$4,844
205274133	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	88*TA36045C17***	34,400	\$4,816
205274123	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	987MB42080C17***	34,200	\$4,788
205274120	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	986TC42080C17***	34,400	\$4,816
205274129	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	88*TA36070C14***	34,200	\$4,788
205274132	BRYANT	284ANV036*0**A*	CSPH*3612AL*+UI	987MB60060C21***	34,200	\$4,788
205274134	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	88*TA48070C17***	34,000	\$4,760
205274139	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	986TC42080C17***	34,200	\$4,788
205274141	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	987MB42060C17***	34,200	\$4,788
205274138	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	986TC42060C17***	34,400	\$4,816
205274142	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	987MB42080C17***	34,200	\$4,788
205274151	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	987MB60060C21***	34,000	\$4,760
205274148	BRYANT	284ANV036*0**A*	CSPH*4212AL*+UI	88*TA36070C14***	34,000	\$4,760
205274157	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	986TC42060C17***	34,200	\$4,788
205274152	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	88*TA36045C17***	34,400	\$4,816
205274160	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	987MB42060C17***	34,200	\$4,788
205274158	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	986TC42080C17***	34,200	\$4,788
205274167	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	88*TA36070C14***	34,000	\$4,760
205274161	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	987MB42080C17***	34,000	\$4,760
205274171	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	88*TA36045C17***	33,800	\$4,732
205274170	BRYANT	284ANV036*0**A*	CSPH*4812AL*+UI	987MB60060C21***	34,000	\$4,760
205274176	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	986TC42060C17***	33,800	\$4,732

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205274179	BRYANT	284ANV036*0**A*	CSPH*6012AL*+UI	987MB42060C17***	33,800	\$4,732
9893760	BRYANT	280ANV060000	FE4ANB006L+UI		52,500	\$7,350
9893754	BRYANT	280ANV048*0**A*	CNPV*6024AL*+UI & 98(6*B,7*A)66100V21***		48,500	\$6,790
9893753	BRYANT	280ANV048*0**A*	CNPV*6024AL*+UI & 98(6*B,7*A)60080V21***		49,000	\$6,860
9893748	BRYANT	280ANV048*0**A*	CNPV*4821AL*+UI & 98(6*B,7*A)66100V21***		48,000	\$6,720
9893745	BRYANT	280ANV048*0**A*	CAP**6024AL*+UI & 98(6*B,7*A)66100V21***		48,000	\$6,720
9893742	BRYANT	280ANV048*0**A*	CAP**6021AL*+UI & 98(6*B,7*A)66100V21***		48,000	\$6,720
9893731	BRYANT	280ANV048*0**A*	CNPV*6024AL*+UI & 98(6*B,7*A)66120V24***		49,000	\$6,860
9893699	BRYANT	280ANV048000	FE4ANB006L+UI		47,500	\$6,650
9893727	BRYANT	280ANV048000	FE4AN(B,F)005L+UI		48,500	\$6,790
9893697	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI & 98(6*B,7*A)60080V21***		32,000	\$4,480
9893698	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI & 98(6*B,7*A)66100V21***		32,000	\$4,480
9893696	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI & 98(6*B,7MA)60060V21***		32,200	\$4,508
9893695	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI & 98(6*B,7*A)66100V21***		30,000	\$4,200
9893693	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI & 98(6*B,7MA)60060V21***		30,400	\$4,256
9893692	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI & 98(6*B,7*A)66100V21***		30,000	\$4,200
9893694	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI & 98(6*B,7*A)60080V21***		30,000	\$4,200
9893691	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI & 98(6*B,7*A)60080V21***		30,200	\$4,228
9893690	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI & 98(6*B,7MA)60060V21***		30,400	\$4,256
9893689	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI & 98(6*B,7*A)66100V21***		30,200	\$4,228
9893688	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI & 98(6*B,7*A)60080V21***		30,200	\$4,228

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9893686	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI & 98(6*B,7*A)66100V21***		32,000	\$4,480
9893684	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI & 98(6*B,7MA)60060V21***		32,400	\$4,536
9893683	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI & 98(6*B,7*A)66100V21***		30,000	\$4,200
9893685	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI & 98(6*B,7*A)60080V21***		32,200	\$4,508
9893682	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI & 98(6*B,7*A)60080V21***		30,000	\$4,200
9893681	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI & 98(6*B,7MA)60060V21***		30,400	\$4,256
9893680	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI & 98(6*B,7*A)66100V21***		30,000	\$4,200
9893679	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI & 98(6*B,7*A)60080V21***		30,000	\$4,200
9893677	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI & 98(6*B,7*A)66100V21***		30,200	\$4,228
9893678	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI & 98(6*B,7MA)60060V21***		30,400	\$4,256
9893676	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI & 98(6*B,7*A)60080V21***		30,400	\$4,256
9893674	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI & 98(6*B,7*A)66100V21***		31,800	\$4,452
9893672	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI & 98(6*B,7MA)60060V21***		32,200	\$4,508
9893673	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI & 98(6*B,7*A)60080V21***		31,800	\$4,452
9893670	BRYANT	280ANV036*0**A*	CAP**6021AL*+UI & 98(6*B,7*A)60080V21***		31,800	\$4,452
9893669	BRYANT	280ANV036*0**A*	CAP**6021AL*+UI & 98(6*B,7MA)60060V21***		32,200	\$4,508
9893671	BRYANT	280ANV036*0**A*	CAP**6021AL*+UI & 98(6*B,7*A)66100V21***		31,800	\$4,452
9893668	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI & 98(6*B,7*A)66100V21***		29,800	\$4,172
9893667	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI & 98(6*B,7*A)60080V21***		29,800	\$4,172

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9893666	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI & 98(6*B,7MA)60060V21***		30,200	\$4,228
9893665	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI & 98(6*B,7*A)66100V21***		29,800	\$4,172
9893664	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI & 98(6*B,7*A)60080V21***		30,000	\$4,200
9893663	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI & 98(6*B,7MA)60060V21***		30,200	\$4,228
9893662	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI & 98(6*B,7*A)66100V21***		30,200	\$4,228
9893661	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI & 98(6*B,7*A)60080V21***		30,200	\$4,228
9893658	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI & 98(6*B,7*A)60080V21***		30,200	\$4,228
9893659	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI & 98(6*B,7*A)66100V21***		30,200	\$4,228
9893656	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI & 98(6*B,7*A)66100V21***		30,200	\$4,228
9893655	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI & 98(6*B,7*A)60080V21***		30,400	\$4,256
9893654	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI & 98(6*B,7MA)60060V21***		30,600	\$4,284
9893653	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI & 98(6*B,7*A)66120V24***		32,000	\$4,480
9893650	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI & 98(6*B,7*A)66120V24***		32,200	\$4,508
9893651	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI & 98(6*B,7*A)42060V17***		32,600	\$4,564
9893652	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI & 98(6*B,7*A)42080V17***		32,400	\$4,536
9893649	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI & 98(6*B,7*A)42080V17***		32,800	\$4,592
9893647	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI & 98(6*B,7*A)66120V24***		30,200	\$4,228
9893646	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI & 98(6*B,7*A)42080V17***		30,600	\$4,284
9893644	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI & 98(6*B,7*A)66120V24***		30,400	\$4,256

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9893641	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI & 98(6*B,7*A)66120V24***		32,200	\$4,508
9893640	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI & 98(6*B,7*A)66120V24***		32,200	\$4,508
9893639	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI & 98(6*B,7*A)42080V17***		32,600	\$4,564
9893629	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI & 98(6*B,7*A)66120V24***		31,600	\$4,424
9893628	BRYANT	280ANV036*0**A*	CAP**6021AL*+UI & 98(6*B,7*A)42080V17***		32,000	\$4,480
9893625	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI & 98(6*B,7*A)42080V17***		32,600	\$4,564
9893626	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI & 98(6*B,7*A)66120V24***		32,000	\$4,480
9893614	BRYANT	280ANV036000	FE4AN(B,F)005L+UI		31,600	\$4,424
9893621	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI & 98(6*B,7*A)66120V24***		30,200	\$4,228
9893556	BRYANT	280ANV036000	FE4ANB006L+UI		31,600	\$4,424
9893555	BRYANT	280ANV024*0**A*	CSPH*6012AL*+UI & 98(6*B,7*A)60080V21***		25,000	\$3,500
9893554	BRYANT	280ANV024*0**A*	CSPH*6012AL*+UI & 98(6*B,7MA)60060V21***		25,000	\$3,500
9893553	BRYANT	280ANV024*0**A*	CSPH*4812AL*+UI & 98(6*B,7*A)66100V21***		24,800	\$3,472
9893552	BRYANT	280ANV024*0**A*	CSPH*4812AL*+UI & 98(6*B,7*A)60080V21***		25,000	\$3,500
9893551	BRYANT	280ANV024*0**A*	CSPH*4812AL*+UI & 98(6*B,7MA)60060V21***		25,000	\$3,500
9893550	BRYANT	280ANV024*0**A*	CSPH*4212AL*+UI & 98(6*B,7*A)66100V21***		25,000	\$3,500
9893547	BRYANT	280ANV024*0**A*	CSPH*3612AL*+UI & 98(6*B,7*A)66100V21***		25,000	\$3,500
9893548	BRYANT	280ANV024*0**A*	CSPH*4212AL*+UI & 98(6*B,7MA)60060V21***		25,000	\$3,500
9893549	BRYANT	280ANV024*0**A*	CSPH*4212AL*+UI & 98(6*B,7*A)60080V21***		25,000	\$3,500
9893546	BRYANT	280ANV024*0**A*	CSPH*3612AL*+UI & 98(6*B,7*A)60080V21***		25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9893545	BRYANT	280ANV024*0**A*	CSPH*3612AL*+UI & 98(6*B,7MA)60060V21***		25,200	\$3,528
9893544	BRYANT	280ANV024*0**A*	CNPV*6024AL*+UI & 98(6*B,7*A)66100V21***		25,000	\$3,500
9893543	BRYANT	280ANV024*0**A*	CNPV*6024AL*+UI & 98(6*B,7*A)60080V21***		25,000	\$3,500
9893541	BRYANT	280ANV024*0**A*	CNPV*4824AL*+UI & 98(6*B,7*A)66100V21***		25,000	\$3,500
9893542	BRYANT	280ANV024*0**A*	CNPV*6024AL*+UI & 98(6*B,7MA)60060V21***		25,000	\$3,500
9893540	BRYANT	280ANV024*0**A*	CNPV*4824AL*+UI & 98(6*B,7*A)60080V21***		25,000	\$3,500
9893538	BRYANT	280ANV024*0**A*	CNPV*4221AL*+UI & 98(6*B,7*A)66100V21***		25,000	\$3,500
9893539	BRYANT	280ANV024*0**A*	CNPV*4824AL*+UI & 98(6*B,7MA)60060V21***		25,000	\$3,500
9893537	BRYANT	280ANV024*0**A*	CNPV*4221AL*+UI & 98(6*B,7*A)60080V21***		25,200	\$3,528
9893536	BRYANT	280ANV024*0**A*	CNPV*4221AL*+UI & 98(6*B,7MA)60060V21***		25,200	\$3,528
9893535	BRYANT	280ANV024*0**A*	CNPV*3621AL*+UI & 98(6*B,7*A)66100V21***		25,200	\$3,528
9893533	BRYANT	280ANV024*0**A*	CNPV*3621AL*+UI & 98(6*B,7MA)60060V21***		25,200	\$3,528
9893534	BRYANT	280ANV024*0**A*	CNPV*3621AL*+UI & 98(6*B,7*A)60080V21***		25,200	\$3,528
9893532	BRYANT	280ANV024*0**A*	CAP**6024AL*+UI & 98(6*B,7*A)66100V21***		24,800	\$3,472
9893531	BRYANT	280ANV024*0**A*	CAP**6024AL*+UI & 98(6*B,7*A)60080V21***		24,800	\$3,472
9893530	BRYANT	280ANV024*0**A*	CAP**6024AL*+UI & 98(6*B,7MA)60060V21***		24,800	\$3,472
9893528	BRYANT	280ANV024*0**A*	CAP**6021AL*+UI & 98(6*B,7*A)60080V21***		24,800	\$3,472
9893527	BRYANT	280ANV024*0**A*	CAP**6021AL*+UI & 98(6*B,7MA)60060V21***		24,800	\$3,472
9893529	BRYANT	280ANV024*0**A*	CAP**6021AL*+UI & 98(6*B,7*A)66100V21***		24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9893526	BRYANT	280ANV024*0**A*	CAP**4824AL*+UI & 98(6*B,7*A)66100V21***		24,800	\$3,472
9893525	BRYANT	280ANV024*0**A*	CAP**4824AL*+UI & 98(6*B,7*A)60080V21***		24,800	\$3,472
9893524	BRYANT	280ANV024*0**A*	CAP**4824AL*+UI & 98(6*B,7MA)60060V21***		24,800	\$3,472
9893523	BRYANT	280ANV024*0**A*	CAP**4821AL*+UI & 98(6*B,7*A)66100V21***		24,800	\$3,472
9893522	BRYANT	280ANV024*0**A*	CAP**4821AL*+UI & 98(6*B,7*A)60080V21***		24,800	\$3,472
9893520	BRYANT	280ANV024*0**A*	CAP**4224AL*+UI & 98(6*B,7*A)66100V21***		25,000	\$3,500
9893519	BRYANT	280ANV024*0**A*	CAP**4224AL*+UI & 98(6*B,7*A)60080V21***		25,000	\$3,500
9893521	BRYANT	280ANV024*0**A*	CAP**4821AL*+UI & 98(6*B,7MA)60060V21***		24,800	\$3,472
9893517	BRYANT	280ANV024*0**A*	CAP**4221AL*+UI & 98(6*B,7*A)66100V21***		25,000	\$3,500
9893516	BRYANT	280ANV024*0**A*	CAP**4221AL*+UI & 98(6*B,7*A)60080V21***		25,000	\$3,500
9893514	BRYANT	280ANV024*0**A*	CAP**3621AL*+UI & 98(6*B,7*A)66100V21***		25,000	\$3,500
9893513	BRYANT	280ANV024*0**A*	CAP**3621AL*+UI & 98(6*B,7*A)60080V21***		25,000	\$3,500
9893512	BRYANT	280ANV024*0**A*	CAP**3621AL*+UI & 98(6*B,7MA)60060V21***		25,200	\$3,528
9893511	BRYANT	280ANV024*0**A*	CSPH*6012AL*+UI & 98(6*B,7*A)66120V24***		25,000	\$3,500
9893510	BRYANT	280ANV024*0**A*	CSPH*6012AL*+UI & 98(6*B,7*A)42080V17***		25,000	\$3,500
9893509	BRYANT	280ANV024*0**A*	CSPH*6012AL*+UI & 98(6*B,7*A)42060V17***		25,000	\$3,500
9893508	BRYANT	280ANV024*0**A*	CSPH*4812AL*+UI & 98(6*B,7*A)66120V24***		25,000	\$3,500
9893507	BRYANT	280ANV024*0**A*	CSPH*4812AL*+UI & 98(6*B,7*A)42080V17***		25,000	\$3,500
9893506	BRYANT	280ANV024*0**A*	CSPH*4812AL*+UI & 98(6*B,7*A)42060V17***		25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9893504	BRYANT	280ANV024*0**A*	CSPH*4212AL*+UI & 98(6*B,7*A)42080V17***		25,000	\$3,500
9893505	BRYANT	280ANV024*0**A*	CSPH*4212AL*+UI & 98(6*B,7*A)66120V24***		25,000	\$3,500
9893503	BRYANT	280ANV024*0**A*	CSPH*4212AL*+UI & 98(6*B,7*A)42060V17***		25,200	\$3,528
9893502	BRYANT	280ANV024*0**A*	CSPH*3612AL*+UI & 98(6*B,7*A)66120V24***		25,000	\$3,500
9893501	BRYANT	280ANV024*0**A*	CSPH*3612AL*+UI & 98(6*B,7*A)42080V17***		25,200	\$3,528
9893500	BRYANT	280ANV024*0**A*	CSPH*3612AL*+UI & 98(6*B,7*A)42060V17***		25,200	\$3,528
9893499	BRYANT	280ANV024*0**A*	CNPV*6024AL*+UI & 98(6*B,7*A)66120V24***		25,000	\$3,500
9893496	BRYANT	280ANV024*0**A*	CNPV*4821AL*+UI & 98(6*B,7*A)42060V17***		25,000	\$3,500
9893498	BRYANT	280ANV024*0**A*	CNPV*4824AL*+UI & 98(6*B,7*A)66120V24***		25,000	\$3,500
9893497	BRYANT	280ANV024*0**A*	CNPV*4821AL*+UI & 98(6*B,7*A)42080V17***		25,000	\$3,500
9893495	BRYANT	280ANV024*0**A*	CNPV*4221AL*+UI & 98(6*B,7*A)42080V17***		25,200	\$3,528
9893494	BRYANT	280ANV024*0**A*	CNPV*4221AL*+UI & 98(6*B,7*A)42060V17***		25,200	\$3,528
9893493	BRYANT	280ANV024*0**A*	CNPV*4217AL*+UI & 98(6*B,7*A)42080V17***		25,200	\$3,528
9893492	BRYANT	280ANV024*0**A*	CNPV*4217AL*+UI & 98(6*B,7*A)42060V17***		25,200	\$3,528
9893491	BRYANT	280ANV024*0**A*	CNPV*3621AL*+UI & 98(6*B,7*A)42080V17***		25,200	\$3,528
9893490	BRYANT	280ANV024*0**A*	CNPV*3621AL*+UI & 98(6*B,7*A)42060V17***		25,400	\$3,556
9893489	BRYANT	280ANV024*0**A*	CNPV*3617AL*+UI & 98(6*B,7*A)42080V17***		25,200	\$3,528
9893488	BRYANT	280ANV024*0**A*	CNPV*3617AL*+UI & 98(6*B,7*A)42060V17***		25,400	\$3,556
9893487	BRYANT	280ANV024*0**A*	CAP**6024AL*+UI & 98(6*B,7*A)66120V24***		24,400	\$3,416

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9893486	BRYANT	280ANV024*0**A*	CAP**6021AL*+UI & 98(6*B,7*A)42080V17***		24,600	\$3,444
9893485	BRYANT	280ANV024*0**A*	CAP**6021AL*+UI & 98(6*B,7*A)42060V17***		24,600	\$3,444
9893484	BRYANT	280ANV024*0**A*	CAP**4824AL*+UI & 98(6*B,7*A)66120V24***		24,800	\$3,472
9893483	BRYANT	280ANV024*0**A*	CAP**4821AL*+UI & 98(6*B,7*A)42080V17***		24,800	\$3,472
9893482	BRYANT	280ANV024*0**A*	CAP**4821AL*+UI & 98(6*B,7*A)42060V17***		25,000	\$3,500
9893479	BRYANT	280ANV024*0**A*	CAP**4224AL*+UI & 98(6*B,7*A)66120V24***		25,000	\$3,500
9893478	BRYANT	280ANV024*0**A*	CAP**4221AL*+UI & 98(6*B,7*A)42080V17***		25,200	\$3,528
9893477	BRYANT	280ANV024*0**A*	CAP**4221AL*+UI & 98(6*B,7*A)42060V17***		25,200	\$3,528
9893476	BRYANT	280ANV024*0**A*	CAP**3621AL*+UI & 98(6*B,7*A)42080V17***		25,200	\$3,528
9893475	BRYANT	280ANV024*0**A*	CAP**3621AL*+UI & 98(6*B,7*A)42060V17***		25,200	\$3,528
9893474	BRYANT	280ANV024*0**A*	CAP**3617AL*+UI & 98(6*B,7*A)42080V17***		25,200	\$3,528
9893473	BRYANT	280ANV024*0**A*	CAP**3617AL*+UI & 98(6*B,7*A)42060V17***		25,200	\$3,528
9893463	BRYANT	280ANV024000	FE4AN(B,F)003+UI		25,000	\$3,500
9893462	BRYANT	280ANV024000	FE4ANF002L+UI		25,200	\$3,528
9893411	BRYANT	280ANV024*0**A*	FE4ANB006L+UI		24,800	\$3,472
9893607	BRYANT	280ANV036000	FE4ANF002L+UI		30,600	\$4,284
9893608	BRYANT	280ANV036000	FE4AN(B,F)003L+UI		30,200	\$4,228
204430008	BRYANT	280ANV024*0**A*	CAP**4224AL*+UI	88*TA60090C21***	22,000	\$3,080
204430000	BRYANT	280ANV024*0**A*	CAP**4221AL*+UI	88*TA60110C21***	22,000	\$3,080
204430065	BRYANT	280ANV024*0**A*	CNPV*4221AL*+UI	986TC42080C17***	22,400	\$3,136
204429902	BRYANT	280ANV024*0**A*	CAP**3617AL*+UI	88*TA48090C17***	21,600	\$3,024
204430020	BRYANT	280ANV024*0**A*	CAP**4224AL*+UI	986TC60080C21***	22,200	\$3,108
204430103	BRYANT	280ANV024*0**A*	CSPH*3012AL*+UI	986TC66120C24***	23,000	\$3,220
204430056	BRYANT	280ANV024*0**A*	CNPV*3621AL*+UI	987MB66100C21***	24,200	\$3,388
204430073	BRYANT	280ANV024*0**A*	CNPV*4221AL*+UI	88*TA48090C17***	22,200	\$3,108
204430112	BRYANT	280ANV024*0**A*	CSPH*3012AL*+UI	987MB66100C21***	23,000	\$3,220
204430120	BRYANT	280ANV024*0**A*	CSPH*3012AL*+UI	986TC66100C21***	23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430075	BRYANT	280ANV024*0**A*	CNPV*4221AL*+UI	987MB60060C21***	22,400	\$3,136
204429878	BRYANT	280ANV024*0**A*	CAP**3617AL*+UI	986TC42060C17***	21,600	\$3,024
204430097	BRYANT	280ANV024*0**A*	CSPH*3012AL*+UI	88*TA60090C21***	23,000	\$3,220
204430025	BRYANT	280ANV024*0**A*	CNPV*3014AL*+UI	88*TA36070C14***	21,400	\$2,996
204429968	BRYANT	280ANV024*0**A*	CAP**4221AL*+UI	88*TA60070C21***	22,200	\$3,108
204430396	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	88*TA66135C24***	32,400	\$4,536
204429925	BRYANT	280ANV024*0**A*	CAP**3621AL*+UI	986TC42060C17***	21,600	\$3,024
204429916	BRYANT	280ANV024*0**A*	CAP**3621AL*+UI	88*TA60070C21***	21,600	\$3,024
204430050	BRYANT	280ANV024*0**A*	CNPV*3621AL*+UI	986TC42080C17***	21,400	\$2,996
204430427	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	88*TA66135C24***	32,000	\$4,480
204431323	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	986TC66120C24***	32,200	\$4,508
204431315	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	88*TA66135C24***	32,200	\$4,508
204430430	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	986TC66120C24***	32,200	\$4,508
204430781	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	986TC66120C24***	32,600	\$4,564
204431334	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	987MB66100C21***	32,200	\$4,508
204430778	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	88*TA66135C24***	32,600	\$4,564
204430874	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	986TC66120C24***	32,400	\$4,536
204430884	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	987MB60080C21***	32,400	\$4,536
204430892	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	987MB66100C21***	32,400	\$4,536
204430818	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	88*TA60110C21***	32,600	\$4,564
204430774	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	88*TA60090C21***	32,600	\$4,564
204431236	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	88*TA66135C24***	32,600	\$4,564
204430714	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	88*TA60090C21***	32,600	\$4,564
204430754	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	88*TA60110C21***	32,600	\$4,564
204430095	BRYANT	280ANV024*0**A*	CSPH*3012AL*+UI	88*TA60070C21***	23,000	\$3,220
204430905	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	986TC60080C21***	32,400	\$4,536
204430844	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	88*TA60090C21***	32,400	\$4,536
204430856	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	88*TA66135C24***	32,200	\$4,508
204430896	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	987MB66120C24***	32,400	\$4,536
204430424	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	88*TA60090C21***	32,000	\$4,480
204430924	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	88*TA60110C21***	32,400	\$4,536
204430460	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	88*TA60090C21***	32,200	\$4,508
204430912	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	986TC66100C21***	32,400	\$4,536
204430510	BRYANT	280ANV036*0**A*	CAP**6124AL*+UI	986TC66100C21***	32,200	\$4,508
204429894	BRYANT	280ANV024*0**A*	CAP**3617AL*+UI	987MB42080C17***	21,600	\$3,024
204430610	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	88*TA60090C21***	32,600	\$4,564
204430343	BRYANT	280ANV036*0**A*	CAP**4321AL*+UI	987MB60080C21***	32,800	\$4,592
204430246	BRYANT	280ANV036*0**A*	CAP**3721AL*+UI	88*TA60090C21***	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430491	BRYANT	280ANV036*0**A*	CAP**6124AL*+UI	986TC66120C24***	32,200	\$4,508
204430693	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	88*TA60110C21***	32,600	\$4,564
204431312	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	88*TA60090C21***	32,200	\$4,508
204430501	BRYANT	280ANV036*0**A*	CAP**6124AL*+UI	987MB66100C21***	32,200	\$4,508
204430402	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	987MB60080C21***	32,600	\$4,564
204430371	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	987MB60080C21***	32,600	\$4,564
204430373	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	987MB66100C21***	32,600	\$4,564
204431331	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	987MB60080C21***	32,400	\$4,536
204430405	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	987MB66100C21***	32,400	\$4,536
204430435	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	987MB66100C21***	32,200	\$4,508
204430432	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	987MB60080C21***	32,200	\$4,508
204430421	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	88*TA60070C21***	32,200	\$4,508
204430282	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	987MB60080C21***	32,600	\$4,564
204431756	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	986TC66120C24***	55,000	\$7,700
204431308	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	88*TA60070C21***	32,400	\$4,536
204430313	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	987MB60080C21***	32,600	\$4,564
204430285	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	987MB66100C21***	32,600	\$4,564
204430310	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	986TC66120C24***	32,400	\$4,536
204430399	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	986TC66120C24***	32,400	\$4,536
204430307	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	88*TA66135C24***	32,400	\$4,536
204430828	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	987MB60060C21***	33,000	\$4,620
204430759	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	987MB60060C21***	33,000	\$4,620
204430316	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	987MB66100C21***	32,400	\$4,536
204430769	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	88*TA60070C21***	32,800	\$4,592
204430707	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	88*TA60070C21***	32,800	\$4,592
204431158	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	987MB66100C21***	32,800	\$4,592
204431107	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	88*TA60070C21***	32,800	\$4,592
204431133	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	986TC66120C24***	32,600	\$4,564
204430791	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	987MB66100C21***	32,600	\$4,564
204430735	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	987MB60080C21***	32,800	\$4,592
204431151	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	987MB60080C21***	32,800	\$4,592
204430787	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	987MB60080C21***	32,800	\$4,592
204431268	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	987MB60080C21***	32,800	\$4,592
204431220	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	88*TA60070C21***	32,800	\$4,592
204431119	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	88*TA66135C24***	32,600	\$4,564
204431351	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	88*TA36070C14***	32,600	\$4,564
204431271	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	987MB66100C21***	32,600	\$4,564
204430738	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	987MB66100C21***	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430449	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	987MB60060C21***	32,600	\$4,564
204431256	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	986TC66120C24***	32,600	\$4,564
204431360	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	987MB60060C21***	32,600	\$4,564
204430649	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	987MB60080C21***	32,600	\$4,564
204430661	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	987MB66100C21***	32,600	\$4,564
204431007	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	987MB66100C21***	32,800	\$4,592
204430977	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	88*TA66135C24***	32,800	\$4,592
204430996	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	986TC66120C24***	32,800	\$4,592
204430931	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	987MB60060C21***	32,800	\$4,592
204430803	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	986TC60080C21***	32,800	\$4,592
204430216	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	987MB66100C21***	32,200	\$4,508
204430594	BRYANT	280ANV036*0**A*	CNPV*4217AL*+UI	88*TA48090C17***	33,000	\$4,620
204430798	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	987MB66120C24***	32,800	\$4,592
204430704	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	88*TA48070C17***	33,000	\$4,620
204430742	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	986TC60080C21***	32,800	\$4,592
204431198	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	88*TA60110C21***	32,600	\$4,564
204430834	BRYANT	280ANV036*0**A*	CNPV*6024AL*+UI	88*TA60070C21***	32,600	\$4,564
204430751	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	88*TA48090C17***	32,600	\$4,564
204430809	BRYANT	280ANV036*0**A*	CNPV*4824AL*+UI	986TC66100C21***	32,600	\$4,564
204431111	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	88*TA60090C21***	32,600	\$4,564
204430748	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	986TC66100C21***	32,600	\$4,564
204431296	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	88*TA60110C21***	32,600	\$4,564
204431228	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	88*TA60090C21***	32,600	\$4,564
204430251	BRYANT	280ANV036*0**A*	CAP**3721AL*+UI	986TC42080C17***	33,200	\$4,648
204431526	BRYANT	280ANV048*0**A*	CAP**6124AL*+UI	986TC66100C21***	48,500	\$6,790
204430188	BRYANT	280ANV036*0**A*	CAP**3617AL*+UI	987MB42080C17***	32,800	\$4,592
204431637	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	88*TA66135C24***	53,500	\$7,490
204430279	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	987MB42060C17***	33,200	\$4,648
204430633	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	987MB42060C17***	33,400	\$4,676
204431411	BRYANT	280ANV048*0**A*	CAP**4824AL*+UI	986TC60080C21***	50,500	\$7,070
204431472	BRYANT	280ANV048*0**A*	CAP**6024AL*+UI	88*TA60110C21***	48,500	\$6,790
204431374	BRYANT	280ANV048*0**A*	CAP**4821AL*+UI	986TC60080C21***	49,500	\$6,930
204430185	BRYANT	280ANV036*0**A*	CAP**3617AL*+UI	987MB42060C17***	33,000	\$4,620
204431774	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	88*TA60110C21***	55,000	\$7,700
204431378	BRYANT	280ANV048*0**A*	CAP**4821AL*+UI	88*TA48090C17***	50,500	\$7,070
204431771	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	986TC66100C21***	55,000	\$7,700
204431749	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	88*TA60090C21***	55,000	\$7,700
204431401	BRYANT	280ANV048*0**A*	CAP**4824AL*+UI	987MB66120C24***	50,500	\$7,070

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431381	BRYANT	280ANV048*0**A*	CAP**4821AL*+UI	88*TA60110C21***	50,500	\$7,070
204431684	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	88*TA60070C21***	54,000	\$7,560
204431708	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	986TC60080C21***	54,000	\$7,560
204431704	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	987MB66120C24***	55,000	\$7,700
204431697	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	987MB60080C21***	54,000	\$7,560
204431671	BRYANT	280ANV060*0**A*	CAP**6121AL*+UI	987MB66100C21***	55,000	\$7,700
204431681	BRYANT	280ANV060*0**A*	CAP**6121AL*+UI	88*TA60110C21***	55,000	\$7,700
204431710	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	986TC66100C21***	55,000	\$7,700
204431678	BRYANT	280ANV060*0**A*	CAP**6121AL*+UI	986TC66100C21***	55,000	\$7,700
204431694	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	986TC66120C24***	55,000	\$7,700
204431666	BRYANT	280ANV060*0**A*	CAP**6121AL*+UI	88*TA60090C21***	55,000	\$7,700
204431713	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	88*TA60110C21***	55,000	\$7,700
204431691	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	88*TA66135C24***	55,000	\$7,700
204431701	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	987MB66100C21***	55,000	\$7,700
204430264	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	88*TA36045C17***	33,200	\$4,648
204431088	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	88*TA36045C17***	33,400	\$4,676
204431743	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	88*TA60110C21***	56,000	\$7,840
204431740	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	986TC66100C21***	56,000	\$7,840
204431719	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	88*TA60090C21***	56,000	\$7,840
204431659	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	88*TA60110C21***	53,500	\$7,490
204431687	BRYANT	280ANV060*0**A*	CAP**6124AL*+UI	88*TA60090C21***	55,000	\$7,700
204431656	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	986TC66100C21***	53,500	\$7,490
204430943	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	88*TA36045C17***	33,600	\$4,704
204431736	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	986TC60080C21***	54,500	\$7,630
204430173	BRYANT	280ANV036*0**A*	CAP**3617AL*+UI	88*TA36045C17***	33,000	\$4,620
204431633	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	88*TA60090C21***	53,500	\$7,490
204431716	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	88*TA60070C21***	56,000	\$7,840
204430194	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	88*TA36045C17***	32,800	\$4,592
204430161	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	987MB42060C17***	31,200	\$4,368
204431734	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	987MB66120C24***	54,500	\$7,630
204430998	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	987MB42060C17***	33,600	\$4,704
204431260	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	987MB42060C17***	33,400	\$4,676
204431137	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	987MB42060C17***	33,400	\$4,676
204430179	BRYANT	280ANV036*0**A*	CAP**3617AL*+UI	986TC42060C17***	33,000	\$4,620
204431761	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	987MB66100C21***	55,000	\$7,700
204430518	BRYANT	280ANV036*0**A*	CNPV*3617AL*+UI	986TC42060C17***	32,800	\$4,592
204430154	BRYANT	280ANV036*0**A*	CNPV*3617AL*+UI	987MB42060C17***	31,400	\$4,396
204431642	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	987MB60080C21***	54,000	\$7,560

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431646	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	987MB66100C21***	53,500	\$7,490
204431675	BRYANT	280ANV060*0**A*	CAP**6121AL*+UI	986TC60080C21***	55,500	\$7,770
204431652	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	986TC60080C21***	54,000	\$7,560
204431639	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	986TC66120C24***	53,500	\$7,490
204431725	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	986TC66120C24***	56,000	\$7,840
204431767	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	986TC60080C21***	55,500	\$7,770
204431669	BRYANT	280ANV060*0**A*	CAP**6121AL*+UI	987MB60080C21***	55,500	\$7,770
204431662	BRYANT	280ANV060*0**A*	CAP**6121AL*+UI	88*TA60070C21***	54,000	\$7,560
204431745	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	88*TA60070C21***	55,500	\$7,770
204431758	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	987MB60080C21***	55,500	\$7,770
204431630	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	88*TA60070C21***	54,000	\$7,560
204431765	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	987MB66120C24***	55,500	\$7,770
204430146	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	987MB42060C17***	31,000	\$4,340
204431650	BRYANT	280ANV060*0**A*	CAP**6024AL*+UI	987MB66120C24***	53,500	\$7,490
204431728	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	987MB60080C21***	54,500	\$7,630
204430455	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	88*TA48070C17***	32,600	\$4,564
204431285	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	986TC66100C21***	32,600	\$4,564
204430410	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	986TC60080C21***	32,600	\$4,564
204430384	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	88*TA60110C21***	32,400	\$4,536
204430379	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	986TC66100C21***	32,600	\$4,564
204430488	BRYANT	280ANV036*0**A*	CAP**6124AL*+UI	88*TA60070C21***	32,400	\$4,536
204430457	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	88*TA60070C21***	32,400	\$4,536
204430407	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	987MB66120C24***	32,600	\$4,564
204430357	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	88*TA60090C21***	32,400	\$4,536
204430393	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	88*TA60090C21***	32,400	\$4,536
204430438	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	987MB66120C24***	32,200	\$4,508
204430416	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	88*TA60110C21***	32,400	\$4,536
204430413	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	986TC66100C21***	32,400	\$4,536
204430444	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	986TC66100C21***	32,200	\$4,508
204430441	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	986TC60080C21***	32,200	\$4,508
204430446	BRYANT	280ANV036*0**A*	CAP**6024AL*+UI	88*TA60110C21***	32,000	\$4,480
204431341	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	986TC60080C21***	32,400	\$4,536
204431337	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	987MB66120C24***	32,400	\$4,536
204430382	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	88*TA48090C17***	32,600	\$4,564
204430498	BRYANT	280ANV036*0**A*	CAP**6124AL*+UI	987MB60080C21***	32,200	\$4,508
204430482	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	986TC66100C21***	32,200	\$4,508
204430479	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	986TC60080C21***	32,400	\$4,536
204430474	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	987MB60080C21***	32,400	\$4,536

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430507	BRYANT	280ANV036*0**A*	CAP**6124AL*+UI	986TC60080C21***	32,200	\$4,508
204430477	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	987MB66100C21***	32,200	\$4,508
204431355	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	88*TA60110C21***	32,200	\$4,508
204430676	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	986TC66100C21***	32,600	\$4,564
204430602	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	88*TA48070C17***	32,800	\$4,592
204430287	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	986TC60080C21***	32,600	\$4,564
204430685	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	88*TA48090C17***	32,600	\$4,564
204430080	BRYANT	280ANV024*0**A*	CSPH*2412AL*+UI	986TC42060C17***	22,800	\$3,192
204430667	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	986TC60080C21***	32,600	\$4,564
204430504	BRYANT	280ANV036*0**A*	CAP**6124AL*+UI	987MB66120C24***	32,200	\$4,508
204431345	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	986TC66100C21***	32,200	\$4,508
204430225	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	88*TA48090C17***	32,200	\$4,508
204430321	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	986TC60080C21***	32,600	\$4,564
204430222	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	986TC66100C21***	32,200	\$4,508
204430219	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	986TC60080C21***	32,200	\$4,508
204430202	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	88*TA60090C21***	32,000	\$4,480
204430551	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	986TC60080C21***	32,200	\$4,508
204430227	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	88*TA60110C21***	32,200	\$4,508
204430561	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	88*TA60110C21***	32,200	\$4,508
204430191	BRYANT	280ANV036*0**A*	CAP**3617AL*+UI	88*TA48090C17***	32,400	\$4,536
204431509	BRYANT	280ANV048*0**A*	CAP**6124AL*+UI	88*TA66135C24***	48,500	\$6,790
204430291	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	986TC66100C21***	32,600	\$4,564
204430318	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	987MB66120C24***	32,600	\$4,564
204430362	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	986TC42080C17***	33,000	\$4,620
204430354	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	88*TA60070C21***	32,600	\$4,564
204430558	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	88*TA48090C17***	32,200	\$4,508
204430390	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	88*TA60070C21***	32,600	\$4,564
204430555	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	986TC66100C21***	32,200	\$4,508
204431302	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	88*TA36045C17***	33,000	\$4,620
204430527	BRYANT	280ANV036*0**A*	CNPV*3617AL*+UI	88*TA48090C17***	32,200	\$4,508
204431250	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	986TC42080C17***	33,200	\$4,648
204431505	BRYANT	280ANV048*0**A*	CAP**6124AL*+UI	88*TA60090C21***	48,500	\$6,790
204430387	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	987MB60060C21***	33,000	\$4,620
204430302	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	88*TA60070C21***	32,600	\$4,564
204430727	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	986TC42080C17***	33,200	\$4,648
204430419	BRYANT	280ANV036*0**A*	CAP**4824AL*+UI	987MB60060C21***	32,800	\$4,592
204431289	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	88*TA36070C14***	33,000	\$4,620
204430166	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	987MB42080C17***	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431317	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	986TC42060C17***	33,000	\$4,620
204430269	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	88*TA60070C21***	32,800	\$4,592
204431441	BRYANT	280ANV048*0**A*	CAP**6024AL*+UI	88*TA66135C24***	48,500	\$6,790
204430332	BRYANT	280ANV036*0**A*	CAP**4321AL*+UI	88*TA48070C17***	33,000	\$4,620
204431320	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	986TC42080C17***	32,800	\$4,592
204430299	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	987MB60060C21***	33,000	\$4,620
204431044	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	88*TA36070C14***	33,200	\$4,648
204430230	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	987MB60060C21***	32,600	\$4,564
204430329	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	987MB60060C21***	32,800	\$4,592
204430604	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	88*TA60070C21***	32,800	\$4,592
204431130	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	986TC42080C17***	33,200	\$4,648
204431002	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	987MB60080C21***	33,000	\$4,620
204431204	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	987MB60060C21***	33,200	\$4,648
204430965	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	88*TA60070C21***	33,000	\$4,620
204430547	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	987MB66100C21***	32,200	\$4,508
204430214	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	987MB60080C21***	32,200	\$4,508
204431298	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	987MB60060C21***	33,000	\$4,620
204431601	BRYANT	280ANV048*0**A*	CSPH*6012AL*+UI	88*TA66135C24***	48,500	\$6,790
204430573	BRYANT	280ANV036*0**A*	CNPV*4217AL*+UI	88*TA48070C17***	33,200	\$4,648
204431189	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	88*TA36070C14***	33,200	\$4,648
204430293	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	88*TA48090C17***	32,600	\$4,564
204431017	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	987MB66120C24***	33,000	\$4,620
204431025	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	986TC60080C21***	33,000	\$4,620
204430532	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	88*TA60070C21***	32,400	\$4,536
204431036	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	986TC66100C21***	32,800	\$4,592
204430327	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	88*TA60110C21***	32,400	\$4,536
204430304	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	88*TA60090C21***	32,400	\$4,536
204430272	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	88*TA60090C21***	32,400	\$4,536
204431098	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	88*TA48070C17***	33,000	\$4,620
204431069	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	88*TA60110C21***	32,800	\$4,592
204430970	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	88*TA60090C21***	32,800	\$4,592
204431215	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	88*TA48070C17***	33,000	\$4,620
204430463	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	986TC42060C17***	33,000	\$4,620
204430238	BRYANT	280ANV036*0**A*	CAP**3717AL*+UI	88*TA48090C17***	33,000	\$4,620
204431054	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	88*TA48090C17***	32,800	\$4,592
204431193	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	88*TA48090C17***	32,800	\$4,592
204431180	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	986TC66100C21***	32,800	\$4,592
204430296	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	88*TA60110C21***	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430324	BRYANT	280ANV036*0**A*	CAP**4224AL*+UI	986TC66100C21***	32,400	\$4,536
204431174	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	986TC60080C21***	32,800	\$4,592
204431169	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	987MB66120C24***	32,800	\$4,592
204430261	BRYANT	280ANV036*0**A*	CAP**3721AL*+UI	987MB60060C21***	33,000	\$4,620
204431279	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	986TC60080C21***	32,800	\$4,592
204431275	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	987MB66120C24***	32,800	\$4,592
204430352	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	88*TA48070C17***	32,800	\$4,592
204431328	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	987MB42080C17***	32,800	\$4,592
204431293	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	88*TA48090C17***	32,600	\$4,564
204430241	BRYANT	280ANV036*0**A*	CAP**3721AL*+UI	88*TA48070C17***	33,000	\$4,620
204430466	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	986TC42080C17***	32,800	\$4,592
204430485	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	987MB60060C21***	32,600	\$4,564
204430512	BRYANT	280ANV036*0**A*	CAP**6124AL*+UI	987MB60060C21***	32,600	\$4,564
204430335	BRYANT	280ANV036*0**A*	CAP**4321AL*+UI	88*TA60070C21***	32,800	\$4,592
204430346	BRYANT	280ANV036*0**A*	CAP**4321AL*+UI	987MB60060C21***	33,000	\$4,620
204430471	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	987MB42080C17***	32,800	\$4,592
204430256	BRYANT	280ANV036*0**A*	CAP**3721AL*+UI	987MB60080C21***	32,800	\$4,592
204430376	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	986TC60080C21***	32,600	\$4,564
204430259	BRYANT	280ANV036*0**A*	CAP**3721AL*+UI	986TC60080C21***	32,800	\$4,592
204431305	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	88*TA48070C17***	32,600	\$4,564
204430243	BRYANT	280ANV036*0**A*	CAP**3721AL*+UI	88*TA60070C21***	32,800	\$4,592
204430211	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	987MB42080C17***	32,600	\$4,564
204430543	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	987MB60080C21***	32,200	\$4,508
204430639	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	987MB42080C17***	33,200	\$4,648
204430266	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	88*TA48070C17***	32,800	\$4,592
204430176	BRYANT	280ANV036*0**A*	CAP**3617AL*+UI	88*TA48070C17***	32,600	\$4,564
204431522	BRYANT	280ANV048*0**A*	CAP**6124AL*+UI	986TC60080C21***	49,000	\$6,860
204431516	BRYANT	280ANV048*0**A*	CAP**6124AL*+UI	987MB60080C21***	49,000	\$6,860
204431520	BRYANT	280ANV048*0**A*	CAP**6124AL*+UI	987MB66100C21***	48,500	\$6,790
204431529	BRYANT	280ANV048*0**A*	CAP**6124AL*+UI	88*TA60110C21***	48,500	\$6,790
204430197	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	88*TA48070C17***	32,400	\$4,536
204430564	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	987MB60060C21***	32,600	\$4,564
204430529	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	88*TA48070C17***	32,400	\$4,536
204430515	BRYANT	280ANV036*0**A*	CNPV*3617AL*+UI	88*TA48070C17***	32,600	\$4,564
204430539	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	987MB42080C17***	32,600	\$4,564
204430349	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	88*TA36045C17***	33,200	\$4,648
204431416	BRYANT	280ANV048*0**A*	CAP**4824AL*+UI	986TC66100C21***	50,500	\$7,070
204431458	BRYANT	280ANV048*0**A*	CAP**6024AL*+UI	987MB66120C24***	49,000	\$6,860

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431367	BRYANT	280ANV048*0**A*	CAP**4821AL*+UI	88*TA60090C21***	50,500	\$7,070
204431423	BRYANT	280ANV048*0**A*	CAP**4824AL*+UI	88*TA60110C21***	50,500	\$7,070
204431502	BRYANT	280ANV048*0**A*	CAP**6124AL*+UI	88*TA60070C21***	49,000	\$6,860
204431496	BRYANT	280ANV048*0**A*	CAP**6121AL*+UI	88*TA48090C17***	49,000	\$6,860
204431477	BRYANT	280ANV048*0**A*	CAP**6121AL*+UI	88*TA60070C21***	49,000	\$6,860
204431439	BRYANT	280ANV048*0**A*	CAP**6024AL*+UI	88*TA60090C21***	48,500	\$6,790
204431485	BRYANT	280ANV048*0**A*	CAP**6121AL*+UI	987MB66100C21***	48,500	\$6,790
204431499	BRYANT	280ANV048*0**A*	CAP**6121AL*+UI	88*TA60110C21***	48,500	\$6,790
204431513	BRYANT	280ANV048*0**A*	CAP**6124AL*+UI	986TC66120C24***	48,500	\$6,790
204431492	BRYANT	280ANV048*0**A*	CAP**6121AL*+UI	986TC66100C21***	48,500	\$6,790
204431480	BRYANT	280ANV048*0**A*	CAP**6121AL*+UI	88*TA60090C21***	48,500	\$6,790
204431626	BRYANT	280ANV048*0**A*	CSPH*6012AL*+UI	88*TA48090C17***	49,000	\$6,860
204431623	BRYANT	280ANV048*0**A*	CSPH*6012AL*+UI	986TC66100C21***	49,000	\$6,860
204431620	BRYANT	280ANV048*0**A*	CSPH*6012AL*+UI	986TC60080C21***	49,000	\$6,860
204430700	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	88*TA36045C17***	33,400	\$4,676
204431616	BRYANT	280ANV048*0**A*	CSPH*6012AL*+UI	987MB66120C24***	49,000	\$6,860
204430360	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	986TC42060C17***	33,200	\$4,648
204430452	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	88*TA36045C17***	33,000	\$4,620
204431384	BRYANT	280ANV048*0**A*	CAP**4824AL*+UI	88*TA60070C21***	50,500	\$7,070
204431390	BRYANT	280ANV048*0**A*	CAP**4824AL*+UI	987MB60080C21***	50,500	\$7,070
204431364	BRYANT	280ANV048*0**A*	CAP**4821AL*+UI	88*TA60070C21***	50,500	\$7,070
204431210	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	88*TA36045C17***	33,400	\$4,676
204431371	BRYANT	280ANV048*0**A*	CAP**4821AL*+UI	987MB60080C21***	49,500	\$6,930
204431394	BRYANT	280ANV048*0**A*	CAP**4824AL*+UI	987MB66100C21***	50,500	\$7,070
204431387	BRYANT	280ANV048*0**A*	CAP**4824AL*+UI	986TC66120C24***	50,500	\$7,070
204431451	BRYANT	280ANV048*0**A*	CAP**6024AL*+UI	987MB60080C21***	49,000	\$6,860
204431432	BRYANT	280ANV048*0**A*	CAP**6024AL*+UI	88*TA60070C21***	50,000	\$7,000
204431444	BRYANT	280ANV048*0**A*	CAP**6024AL*+UI	986TC66120C24***	48,500	\$6,790
204431605	BRYANT	280ANV048*0**A*	CSPH*6012AL*+UI	986TC66120C24***	48,500	\$6,790
204430986	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	986TC42060C17***	33,600	\$4,704
204430576	BRYANT	280ANV036*0**A*	CNPV*4217AL*+UI	986TC42060C17***	33,600	\$4,704
204430598	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	88*TA36045C17***	33,400	\$4,676
204430274	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	986TC42060C17***	33,200	\$4,648
204430568	BRYANT	280ANV036*0**A*	CNPV*4217AL*+UI	88*TA36045C17***	33,600	\$4,704
204430993	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	986TC42080C17***	33,400	\$4,676
204430592	BRYANT	280ANV036*0**A*	CNPV*4217AL*+UI	88*TA36070C14***	33,200	\$4,648
204430208	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	986TC42080C17***	32,600	\$4,564
204430583	BRYANT	280ANV036*0**A*	CNPV*4217AL*+UI	986TC42080C17***	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431079	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	987MB60060C21***	33,200	\$4,648
204431126	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	986TC42060C17***	33,400	\$4,676
204430724	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	986TC42060C17***	33,200	\$4,648
204431246	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	986TC42060C17***	33,200	\$4,648
204430149	BRYANT	280ANV036*0**A*	CAP**4221AL*+UI	987MB42080C17***	30,600	\$4,284
204430164	BRYANT	280ANV036*0**A*	CNPV*4217AL*+UI	987MB42060C17***	31,000	\$4,340
204431722	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	88*TA66135C24***	55,500	\$7,770
204431752	BRYANT	280ANV060*0**A*	CSPH*6012AL*+UI	88*TA66135C24***	55,000	\$7,700
204430200	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	88*TA60070C21***	32,400	\$4,536
204431612	BRYANT	280ANV048*0**A*	CSPH*6012AL*+UI	987MB66100C21***	49,000	\$6,860
204431488	BRYANT	280ANV048*0**A*	CAP**6121AL*+UI	986TC60080C21***	49,000	\$6,860
204431599	BRYANT	280ANV048*0**A*	CSPH*6012AL*+UI	88*TA60070C21***	49,000	\$6,860
204431608	BRYANT	280ANV048*0**A*	CSPH*6012AL*+UI	987MB60080C21***	49,000	\$6,860
204430138	BRYANT	280ANV036*0**A*	CNPV*3617AL*+UI	986TC42080C17***	33,600	\$4,704
204430141	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	88*TA60090C21***	33,000	\$4,620
204430617	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	986TC42060C17***	33,400	\$4,676
204430626	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	986TC42080C17***	33,200	\$4,648
204430535	BRYANT	280ANV036*0**A*	CNPV*3621AL*+UI	986TC42080C17***	32,600	\$4,564
204430182	BRYANT	280ANV036*0**A*	CAP**3617AL*+UI	986TC42080C17***	32,800	\$4,592
204430696	BRYANT	280ANV036*0**A*	CNPV*4221AL*+UI	987MB60060C21***	33,000	\$4,620
204430954	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	88*TA48070C17***	33,200	\$4,648
204430588	BRYANT	280ANV036*0**A*	CNPV*4217AL*+UI	987MB42080C17***	33,400	\$4,676
204431000	BRYANT	280ANV036*0**A*	CSPH*3612AL*+UI	987MB42080C17***	33,400	\$4,676
204430205	BRYANT	280ANV036*0**A*	CAP**3621AL*+UI	986TC42060C17***	32,800	\$4,592
204431264	BRYANT	280ANV036*0**A*	CSPH*4812AL*+UI	987MB42080C17***	33,200	\$4,648
204431146	BRYANT	280ANV036*0**A*	CSPH*4212AL*+UI	987MB42080C17***	33,200	\$4,648
204430731	BRYANT	280ANV036*0**A*	CNPV*4821AL*+UI	987MB42060C17***	33,400	\$4,676
204430365	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	987MB42060C17***	33,200	\$4,648
204430235	BRYANT	280ANV036*0**A*	CAP**3717AL*+UI	88*TA36070C14***	33,400	\$4,676
204430248	BRYANT	280ANV036*0**A*	CAP**3721AL*+UI	986TC42060C17***	33,400	\$4,676
204430233	BRYANT	280ANV036*0**A*	CAP**3717AL*+UI	88*TA48070C17***	33,200	\$4,648
204431325	BRYANT	280ANV036*0**A*	CSPH*6012AL*+UI	987MB42060C17***	33,000	\$4,620
204430368	BRYANT	280ANV036*0**A*	CAP**4821AL*+UI	987MB42080C17***	33,000	\$4,620
204430157	BRYANT	280ANV036*0**A*	CNPV*3617AL*+UI	987MB42080C17***	31,000	\$4,340
204430338	BRYANT	280ANV036*0**A*	CAP**4321AL*+UI	986TC42080C17***	33,200	\$4,648
204431731	BRYANT	280ANV060*0**A*	CNPV*6024AL*+UI	987MB66100C21***	56,000	\$7,840
204430468	BRYANT	280ANV036*0**A*	CAP**6121AL*+UI	987MB42060C17***	33,000	\$4,620
204430524	BRYANT	280ANV036*0**A*	CNPV*3617AL*+UI	88*TA36070C14***	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431467	BRYANT	280ANV048*0**A*	CAP**6024AL*+UI	986TC60080C21***	49,000	\$6,860
204430340	BRYANT	280ANV036*0**A*	CAP**4321AL*+UI	987MB42080C17***	33,200	\$4,648
204430254	BRYANT	280ANV036*0**A*	CAP**3721AL*+UI	987MB42080C17***	33,200	\$4,648
207642912	BRYANT	38MGHBQ36DA3	Heat pump without ducts		23,200	\$3,248
207642909	BRYANT	38MGHBQ48EA3	Heat pump without ducts		30,000	\$4,200
207642903	BRYANT	38MGHBQ30DA3	Heat pump without ducts		17,500	\$2,450
206790019	BRYANT	284ANV024*0**B*	FE4AN(B,F)005L+UI		23,800	\$3,332
9118474	BRYANT	38MGRQ36D--3	Heat pump without ducts		23,200	\$3,248
9854627	BRYANT	38MGRQ30D--3	Heat pump without ducts		17,400	\$2,436
208447891	BRYANT	38MURQA48AB3	40MUAAQ48XA3		36,000	\$5,040
207801579	BRYANT	38MARBQ18AA3	40MBDQ24---3		12,600	\$1,764
207826664	BRYANT	38MARBQ18AA3	40MBABQ18XB3		12,000	\$1,680
206348143	BRYANT	38MARBQ12AA3	619AHBQ12XA3		7,500	\$1,050
206790263	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	FE4AN(B,F)003L+UI		32,200	\$4,508
206790264	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	FE4ANB006L+UI		29,800	\$4,172
206790270	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	986TC42060C17***	31,000	\$4,340
206790271	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	986TC42080C17***	31,000	\$4,340
206790272	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	987MB42080C17***	31,000	\$4,340
206790279	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	987MB60060C21***	31,000	\$4,340
206790283	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	986TC42060C17***	32,200	\$4,508
206790284	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	987MB42080C17***	32,200	\$4,508
206790291	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	987MB60060C21***	32,200	\$4,508
206790295	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	986TC66120C24***	32,000	\$4,480
206790298	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	987MB66120C24***	32,000	\$4,480
206790302	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	987MB60060C21***	32,200	\$4,508
206790306	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	986TC42060C17***	31,000	\$4,340

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206790307	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	986TC42080C17***	31,000	\$4,340
206790308	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	987MB42080C17***	31,000	\$4,340
206790315	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	987MB60060C21***	31,000	\$4,340
206790319	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	986TC42060C17***	31,200	\$4,368
206790320	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	986TC42080C17***	31,200	\$4,368
206790321	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	987MB42080C17***	31,200	\$4,368
206790328	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	987MB60060C21***	31,200	\$4,368
206790332	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	986TC66120C24***	30,800	\$4,312
206790335	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	987MB66120C24***	31,000	\$4,340
206790339	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	987MB60060C21***	31,000	\$4,340
206790343	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	986TC66120C24***	30,000	\$4,200
206790346	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	987MB66120C24***	30,200	\$4,228
206790350	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	987MB60060C21***	30,200	\$4,228
206790354	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	986TC42060C17***	30,400	\$4,256
206790355	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	986TC42080C17***	30,200	\$4,228
206790356	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	987MB42080C17***	30,200	\$4,228
206790363	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	987MB60060C21***	30,200	\$4,228
206790503	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	83*CA36040C17***	30,800	\$4,312
206790504	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	83*CA48060C17***	30,800	\$4,312

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206790367	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	986TC66120C24***	30,000	\$4,200
206790506	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	83*CA60100C21***	30,800	\$4,312
206790370	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	987MB66120C24***	30,000	\$4,200
206790507	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	83*CA36040C17***	31,000	\$4,340
206790374	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	987MB60060C21***	30,200	\$4,228
206790508	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	83*CA48060C17***	31,000	\$4,340
206790510	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	83*CA60100C21***	31,000	\$4,340
206790376	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4217AL*+UI	986TC42060C17***	32,000	\$4,480
206790377	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4217AL*+UI	986TC42080C17***	31,800	\$4,452
206790512	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	83*CA60100C21***	31,000	\$4,340
206790378	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4217AL*+UI	987MB42080C17***	31,800	\$4,452
206790513	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4217AL*+UI	83*CA36040C17***	31,600	\$4,424
206790514	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4217AL*+UI	83*CA48060C17***	31,800	\$4,452
206790516	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4221AL*+UI	83*CA60100C21***	32,200	\$4,508
206790383	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4221AL*+UI	986TC42060C17***	32,400	\$4,536
206790518	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4821AL*+UI	83*CA60100C21***	31,400	\$4,396
206790519	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	83*CA36040C17***	31,600	\$4,424
206790384	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4221AL*+UI	986TC42080C17***	32,200	\$4,508
206790520	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	83*CA48060C17***	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206790385	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4221AL*+UI	987MB42080C17***	32,200	\$4,508
206790521	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	83*CA60100C21***	31,600	\$4,424
206790392	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4221AL*+UI	987MB60060C21***	32,200	\$4,508
206790522	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	83*CA36040C17***	31,200	\$4,368
206790523	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	83*CA48060C17***	31,200	\$4,368
206790396	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4821AL*+UI	986TC42060C17***	31,600	\$4,424
206790525	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	83*CA60100C21***	31,200	\$4,368
206790397	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4821AL*+UI	986TC42080C17***	31,400	\$4,396
206790526	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	83*CA36040C17***	31,000	\$4,340
206790398	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4821AL*+UI	987MB42080C17***	31,400	\$4,396
206790527	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	83*CA48060C17***	31,200	\$4,368
206790529	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	83*CA60100C21***	31,200	\$4,368
206790405	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4821AL*+UI	987MB60060C21***	31,400	\$4,396
206790409	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4824AL*+UI	986TC66120C24***	31,200	\$4,368
206790412	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4824AL*+UI	987MB66120C24***	31,400	\$4,396
206790416	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4824AL*+UI	987MB60060C21***	31,400	\$4,396
206790420	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*6024AL*+UI	986TC66120C24***	30,600	\$4,284
206790423	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*6024AL*+UI	987MB66120C24***	30,600	\$4,284
206790427	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*6024AL*+UI	987MB60060C21***	30,800	\$4,312

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206790432	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	986TC42060C17***	31,800	\$4,452
206790433	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	986TC42080C17***	31,800	\$4,452
206790434	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	986TC66120C24***	31,600	\$4,424
206790435	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	987MB42080C17***	31,800	\$4,452
206790438	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	987MB66120C24***	31,600	\$4,424
206790443	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	987MB60060C21***	31,800	\$4,452
206790549	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4221AL*+UI	935CA66100C21***	32,000	\$4,480
206790448	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	986TC42060C17***	31,400	\$4,396
206790449	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	986TC42080C17***	31,400	\$4,396
206790450	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	986TC66120C24***	31,200	\$4,368
206790451	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	987MB42080C17***	31,400	\$4,396
206790454	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	987MB66120C24***	31,200	\$4,368
206790555	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	935CA48060C17***	31,400	\$4,396
206790459	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	987MB60060C21***	31,400	\$4,396
206790464	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	986TC42060C17***	31,400	\$4,396
206790465	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	986TC42080C17***	31,200	\$4,368
206790466	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	986TC66120C24***	31,000	\$4,340
206790467	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	987MB42080C17***	31,200	\$4,368
206790470	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	987MB66120C24***	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206790475	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	987MB60060C21***	31,200	\$4,368
206790480	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	986TC42060C17***	30,600	\$4,284
206790481	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	986TC42080C17***	30,600	\$4,284
206790482	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	986TC66120C24***	30,200	\$4,228
206790483	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	987MB42080C17***	30,600	\$4,284
206790571	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	987MB42060C17***	32,400	\$4,536
206790486	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	987MB66120C24***	30,400	\$4,256
206790572	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	987MB42060C17***	31,400	\$4,396
206790573	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	987MB42060C17***	30,600	\$4,284
206790491	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	987MB60060C21***	30,400	\$4,256
206790574	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4217AL*+UI	987MB42060C17***	32,000	\$4,480
206790492	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	83*CA36040C17***	31,200	\$4,368
206790575	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4221AL*+UI	987MB42060C17***	32,400	\$4,536
206790493	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	83*CA48060C17***	31,400	\$4,396
206790494	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	83*CA36040C17***	30,800	\$4,312
206790576	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4821AL*+UI	987MB42060C17***	31,600	\$4,424
206790495	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	83*CA48060C17***	30,800	\$4,312
206790577	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	987MB42060C17***	32,000	\$4,480
206790578	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	987MB42060C17***	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206790496	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	83*CA60100C21***	30,800	\$4,312
206790497	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	83*CA36040C17***	32,000	\$4,480
206790579	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	987MB42060C17***	31,400	\$4,396
206790498	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	83*CA48060C17***	32,000	\$4,480
206790580	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	987MB42060C17***	30,600	\$4,284
206790500	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	83*CA60100C21***	32,000	\$4,480
206790502	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	83*CA60100C21***	32,000	\$4,480
206790017	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	FE4ANF002L+UI		24,800	\$3,472
206790022	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3617AL*+UI	88*TA36070C14***	24,800	\$3,472
206790023	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3617AL*+UI	88*TA48090C17***	24,800	\$3,472
206790029	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3621AL*+UI	88*TA48090C17***	24,800	\$3,472
206790036	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4221AL*+UI	88*TA48090C17***	24,600	\$3,444
206790062	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3617AL*+UI	88*TA36070C14***	25,000	\$3,500
206790063	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3617AL*+UI	88*TA48090C17***	24,800	\$3,472
206790069	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3621AL*+UI	88*TA48090C17***	24,800	\$3,472
206790073	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4217AL*+UI	88*TA36070C14***	24,800	\$3,472
206790074	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4217AL*+UI	88*TA48090C17***	24,600	\$3,444
206790080	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4221AL*+UI	88*TA48090C17***	24,800	\$3,472
206790105	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3612AL*+UI	88*TA36070C14***	24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206790106	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3612AL*+UI	88*TA48090C17***	24,600	\$3,444
206790114	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*4212AL*+UI	88*TA36070C14***	24,600	\$3,444
206790115	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*4212AL*+UI	88*TA48090C17***	24,600	\$3,444
206790135	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3617AL*+UI	88*TA36045C17***	25,200	\$3,528
206790136	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3617AL*+UI	88*TA48070C17***	25,000	\$3,500
206790139	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3621AL*+UI	88*TA36045C17***	25,000	\$3,500
206790140	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3621AL*+UI	88*TA48070C17***	24,800	\$3,472
206790145	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4221AL*+UI	88*TA36045C17***	25,000	\$3,500
206790146	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4221AL*+UI	88*TA48070C17***	24,800	\$3,472
206790170	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3617AL*+UI	88*TA48070C17***	25,000	\$3,500
206790173	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3621AL*+UI	88*TA36045C17***	25,200	\$3,528
206790174	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3621AL*+UI	88*TA48070C17***	25,000	\$3,500
206790179	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4217AL*+UI	88*TA36045C17***	25,000	\$3,500
206790180	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4217AL*+UI	88*TA48070C17***	24,800	\$3,472
206790183	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4221AL*+UI	88*TA36045C17***	25,000	\$3,500
206790184	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4221AL*+UI	88*TA48070C17***	24,800	\$3,472
206790203	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3612AL*+UI	88*TA36045C17***	25,000	\$3,500
206790204	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3612AL*+UI	88*TA48070C17***	24,800	\$3,472
206790211	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*4212AL*+UI	88*TA36045C17***	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206790212	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*4212AL*+UI	88*TA48070C17***	24,800	\$3,472
206790251	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3617AL*+UI	935CA48060C17***	25,000	\$3,500
206790252	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3621AL*+UI	935CA48060C17***	25,000	\$3,500
206790253	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3621AL*+UI	935CA60080C21***	24,800	\$3,472
206790254	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3621AL*+UI	935CA66100C21***	24,800	\$3,472
206790255	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3617AL*+UI	935CA48060C17***	25,200	\$3,528
206790256	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3621AL*+UI	935CA48060C17***	25,200	\$3,528
206790257	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3621AL*+UI	935CA60080C21***	24,800	\$3,472
206790258	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3621AL*+UI	935CA66100C21***	24,800	\$3,472
206790259	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3612AL*+UI	935CA48060C17***	25,000	\$3,500
206790260	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3612AL*+UI	935CA60080C21***	24,800	\$3,472
206790261	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3612AL*+UI	935CA66100C21***	24,800	\$3,472
206790587	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	FE4ANB006L+UI		42,500	\$5,950
206790589	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**4821AL*+UI	88*TA60090C21***	43,500	\$6,090
206790591	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**4824AL*+UI	88*TA66135C24***	43,000	\$6,020
206790592	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6024AL*+UI	88*TA66135C24***	43,000	\$6,020
206790593	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6121AL*+UI	88*TA60090C21***	43,500	\$6,090
206790595	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6124AL*+UI	88*TA66135C24***	43,000	\$6,020
206790598	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CSPH*6012AL*+UI	88*TA60090C21***	43,000	\$6,020

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206790599	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CSPH*6012AL*+UI	88*TA66135C24***	43,000	\$6,020
206790644	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**4821AL*+UI	935CA60080C21***	43,500	\$6,090
206790645	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**4821AL*+UI	935CA66100C21***	43,500	\$6,090
206790646	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**4824AL*+UI	935CA60080C21***	43,500	\$6,090
206790647	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**4824AL*+UI	935CA66100C21***	43,500	\$6,090
206790648	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6024AL*+UI	935CA60080C21***	43,000	\$6,020
206790649	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6024AL*+UI	935CA66100C21***	43,000	\$6,020
206790650	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6121AL*+UI	935CA60080C21***	43,500	\$6,090
206790651	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6121AL*+UI	935CA66100C21***	43,000	\$6,020
206790652	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6124AL*+UI	935CA60080C21***	43,500	\$6,090
206790653	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6124AL*+UI	935CA66100C21***	43,000	\$6,020
206790654	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CSPH*6012AL*+UI	935CA60080C21***	43,500	\$6,090
206790655	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CSPH*6012AL*+UI	935CA66100C21***	43,000	\$6,020
204456364	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2417AL*+UI	88*TA36045C17***	21,200	\$2,968
204456373	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2417AL*+UI	88*TA48070C17***	21,000	\$2,940
204456409	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2417AL*+UI	987MB42080C17***	21,200	\$2,968
204456418	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2417AL*+UI	88*TA36070C14***	21,000	\$2,940
204456427	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2417AL*+UI	88*TA48090C17***	21,000	\$2,940
204456436	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2517AL*+UI	88*TA36045C17***	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204456445	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2517AL*+UI	88*TA48070C17***	20,600	\$2,884
204456463	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2517AL*+UI	986TC42080C17***	20,600	\$2,884
204456508	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3014AL*+UI	88*TA36070C14***	20,800	\$2,912
204456526	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3017AL*+UI	88*TA48070C17***	20,800	\$2,912
204456571	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3017AL*+UI	88*TA36070C14***	20,800	\$2,912
204456598	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3617AL*+UI	88*TA48070C17***	20,800	\$2,912
204456616	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3617AL*+UI	986TC42080C17***	20,800	\$2,912
204456634	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3617AL*+UI	987MB42080C17***	20,800	\$2,912
204456652	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3617AL*+UI	88*TA48090C17***	20,600	\$2,884
204456661	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3621AL*+UI	88*TA36045C17***	20,800	\$2,912
204456697	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3621AL*+UI	986TC42060C17***	20,800	\$2,912
204456724	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3621AL*+UI	987MB42080C17***	20,800	\$2,912
204456779	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3621AL*+UI	986TC66100C21***	20,600	\$2,884
204456806	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3621AL*+UI	987MB60060C21***	20,800	\$2,912
204456815	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3717AL*+UI	88*TA36045C17***	20,800	\$2,912
204456824	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3717AL*+UI	88*TA48070C17***	20,800	\$2,912
204456833	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3717AL*+UI	986TC42060C17***	20,800	\$2,912
204456842	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3717AL*+UI	986TC42080C17***	20,800	\$2,912
204456852	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3717AL*+UI	987MB42060C17***	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204456870	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3717AL*+UI	88*TA36070C14***	20,600	\$2,884
204456888	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3721AL*+UI	88*TA36045C17***	20,800	\$2,912
204456892	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3721AL*+UI	986TC42060C17***	20,600	\$2,884
204456894	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3721AL*+UI	987MB42060C17***	20,800	\$2,912
204456895	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3721AL*+UI	987MB42080C17***	20,600	\$2,884
204456975	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*2417AL*+UI	88*TA48090C17***	21,000	\$2,940
204459232	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3012AL*+UI	88*TA36070C14***	20,800	\$2,912
204459277	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	88*TA48070C17***	20,800	\$2,912
204459304	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	88*TA66135C24***	20,800	\$2,912
204459331	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	986TC66120C24***	20,600	\$2,884
204459403	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	88*TA36070C14***	20,600	\$2,884
206133315	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2517AL*+UI	83*CA36040C17***	20,600	\$2,884
206133345	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3017AL*+UI	83*CA48060C17***	20,800	\$2,912
206133365	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3617AL*+UI	83*CA48060C17***	20,800	\$2,912
206133385	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3621AL*+UI	83*CA48060C17***	20,800	\$2,912
206133415	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3717AL*+UI	83*CA36040C17***	20,600	\$2,884
206133465	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3721AL*+UI	83*CA60100C21***	20,600	\$2,884
206133687	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	83*CA36040C17***	20,600	\$2,884
206133697	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	83*CA48060C17***	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206133727	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**2417AL*+UI	935CA48060C17***	21,200	\$2,968
206133747	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3017AL*+UI	935CA48060C17***	20,800	\$2,912
206133777	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3621AL*+UI	935CA60080C21***	20,600	\$2,884
206133787	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**3621AL*+UI	935CA66100C21***	20,600	\$2,884
206133953	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3012AL*+UI	935CA60080C21***	21,000	\$2,940
206133993	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	935CA66100C21***	20,600	\$2,884
206765404	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**2414AL*+UI	88*TA36070C14***	21,000	\$2,940
206765422	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**2417AL*+UI	88*TA48070C17***	21,000	\$2,940
206765476	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**2417AL*+UI	88*TA48090C17***	21,000	\$2,940
206765555	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**2517AL*+UI	88*TA48090C17***	20,600	\$2,884
206765564	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**3014AL*+UI	88*TA36070C14***	20,800	\$2,912
206765636	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**3017AL*+UI	88*TA48090C17***	20,800	\$2,912
206765645	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**3617AL*+UI	88*TA36045C17***	20,800	\$2,912
206765924	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**3721AL*+UI	88*TA36045C17***	20,800	\$2,912
206766140	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*3014AL*+UI	88*TA36070C14***	20,800	\$2,912
206766230	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*3617AL*+UI	88*TA48070C17***	20,800	\$2,912
206766275	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*3617AL*+UI	88*TA36070C14***	20,800	\$2,912
206766302	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*3621AL*+UI	88*TA48070C17***	20,800	\$2,912
206766862	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*3012AL*+UI	88*TA36070C14***	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206766871	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*3012AL*+UI	88*TA48090C17***	20,800	\$2,912
206766907	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*3612AL*+UI	88*TA48070C17***	20,800	\$2,912
206766934	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*3612AL*+UI	88*TA66135C24***	20,800	\$2,912
206767461	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**2417AL*+UI	935CA48060C17***	21,200	\$2,968
206767470	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**2517AL*+UI	935CA48060C17***	20,800	\$2,912
206767479	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**3017AL*+UI	935CA48060C17***	20,800	\$2,912
206767506	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**3621AL*+UI	935CA60080C21***	20,600	\$2,884
206767569	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*3017AL*+UI	935CA48060C17***	20,800	\$2,912
206767578	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*3617AL*+UI	935CA48060C17***	20,800	\$2,912
206767587	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*3621AL*+UI	935CA48060C17***	20,800	\$2,912
206767605	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*3621AL*+UI	935CA66100C21***	20,800	\$2,912
206767666	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*3012AL*+UI	935CA60080C21***	21,000	\$2,940
204298576	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3617AL*+UI	88*TA48070C17***	31,400	\$4,396
204298626	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3617AL*+UI	88*TA36070C14***	31,400	\$4,396
204298636	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3617AL*+UI	88*TA48090C17***	31,200	\$4,368
204298656	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3621AL*+UI	88*TA48070C17***	31,200	\$4,368
204298676	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3621AL*+UI	88*TA60090C21***	31,200	\$4,368
204298766	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3621AL*+UI	88*TA48090C17***	31,000	\$4,340
204298878	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3721AL*+UI	88*TA48070C17***	32,000	\$4,480

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204298882	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3721AL*+UI	88*TA60090C21***	31,800	\$4,452
204298900	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3721AL*+UI	88*TA48090C17***	31,800	\$4,452
204298916	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4221AL*+UI	88*TA48070C17***	31,400	\$4,396
204298936	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4221AL*+UI	88*TA60090C21***	31,400	\$4,396
204299026	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4221AL*+UI	88*TA48090C17***	31,200	\$4,368
204299066	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4224AL*+UI	88*TA60090C21***	31,400	\$4,396
204299076	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4224AL*+UI	88*TA66135C24***	31,200	\$4,368
204299168	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4321AL*+UI	88*TA48070C17***	32,000	\$4,480
204299172	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4321AL*+UI	88*TA60090C21***	31,800	\$4,452
204299190	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4321AL*+UI	88*TA48090C17***	31,800	\$4,452
204299206	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4821AL*+UI	88*TA48070C17***	31,600	\$4,424
204299226	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4821AL*+UI	88*TA60090C21***	31,400	\$4,396
204299316	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4821AL*+UI	88*TA48090C17***	31,400	\$4,396
204299356	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4824AL*+UI	88*TA60090C21***	31,400	\$4,396
204299366	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4824AL*+UI	88*TA66135C24***	31,400	\$4,396
204299496	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4217AL*+UI	88*TA48070C17***	31,600	\$4,424
204299546	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4217AL*+UI	88*TA36070C14***	31,600	\$4,424
204299556	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4217AL*+UI	88*TA48090C17***	31,400	\$4,396
204299726	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4821AL*+UI	88*TA48070C17***	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204299746	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4821AL*+UI	88*TA60090C21***	31,600	\$4,424
204299836	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4821AL*+UI	88*TA48090C17***	31,400	\$4,396
204299876	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4824AL*+UI	88*TA60090C21***	31,600	\$4,424
204299886	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4824AL*+UI	88*TA66135C24***	31,400	\$4,396
204299926	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4824AL*+UI	987MB66120C24***	31,600	\$4,424
204299946	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4824AL*+UI	986TC66100C21***	31,400	\$4,396
204299966	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4824AL*+UI	987MB60060C21***	31,800	\$4,452
204300050	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	88*TA48070C17***	31,800	\$4,452
204300070	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	88*TA60090C21***	31,600	\$4,424
204300080	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	88*TA66135C24***	31,400	\$4,396
204300110	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	986TC66120C24***	31,600	\$4,424
204300150	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	987MB66100C21***	31,600	\$4,424
204300160	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	987MB66120C24***	31,600	\$4,424
204300180	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	986TC66100C21***	31,600	\$4,424
204300190	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	88*TA36070C14***	31,600	\$4,424
204300200	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	88*TA48090C17***	31,600	\$4,424
204300240	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	88*TA48070C17***	31,800	\$4,452
204300260	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	88*TA60090C21***	31,600	\$4,424
204300270	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	88*TA66135C24***	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204300300	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	986TC66120C24***	31,600	\$4,424
204300340	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	987MB66100C21***	31,600	\$4,424
204300350	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	987MB66120C24***	31,600	\$4,424
204300370	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	986TC66100C21***	31,600	\$4,424
204300380	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	88*TA36070C14***	31,800	\$4,452
204300390	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	88*TA48090C17***	31,600	\$4,424
204300410	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	987MB60060C21***	31,800	\$4,452
204300430	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	88*TA48070C17***	31,800	\$4,452
204300450	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	88*TA60090C21***	31,600	\$4,424
204300460	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	88*TA66135C24***	31,600	\$4,424
204300490	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	986TC66120C24***	31,600	\$4,424
204300530	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	987MB66100C21***	31,600	\$4,424
204300540	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	987MB66120C24***	31,800	\$4,452
204300560	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	986TC66100C21***	31,600	\$4,424
204300570	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	88*TA36070C14***	31,800	\$4,452
204300580	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	88*TA48090C17***	31,600	\$4,424
204300600	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	987MB60060C21***	32,000	\$4,480
206135643	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3617AL*+UI	83*CA36040C17***	31,200	\$4,368
206135653	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3721AL*+UI	83*CA36040C17***	31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206135663	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3721AL*+UI	83*CA48060C17***	32,000	\$4,480
206135673	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3721AL*+UI	83*CA60100C21***	31,800	\$4,452
206135683	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4221AL*+UI	83*CA48060C17***	31,400	\$4,396
206135713	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4224AL*+UI	83*CA60100C21***	31,400	\$4,396
206135723	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4321AL*+UI	83*CA36040C17***	31,800	\$4,452
206135733	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4321AL*+UI	83*CA48060C17***	31,800	\$4,452
206135753	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4321AL*+UI	83*CA60100C21***	31,800	\$4,452
206135763	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4821AL*+UI	83*CA36040C17***	31,400	\$4,396
206135773	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4821AL*+UI	83*CA48060C17***	31,600	\$4,424
206135793	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4821AL*+UI	83*CA60100C21***	31,600	\$4,424
206135813	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4824AL*+UI	83*CA60100C21***	31,400	\$4,396
206135873	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4217AL*+UI	83*CA36040C17***	31,600	\$4,424
206135883	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4217AL*+UI	83*CA48060C17***	31,600	\$4,424
206135923	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4821AL*+UI	83*CA60100C21***	31,600	\$4,424
206135965	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	83*CA36040C17***	31,600	\$4,424
206135975	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	83*CA48060C17***	31,800	\$4,452
206135995	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	83*CA60100C21***	31,600	\$4,424
206136005	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	83*CA36040C17***	31,600	\$4,424
206136015	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	83*CA48060C17***	31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206136035	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	83*CA60100C21***	31,800	\$4,452
206136075	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3721AL*+UI	935CA60080C21***	31,800	\$4,452
206136085	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3721AL*+UI	935CA66100C21***	31,800	\$4,452
206136105	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4221AL*+UI	935CA66100C21***	31,200	\$4,368
206136115	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4224AL*+UI	935CA60080C21***	31,200	\$4,368
206136125	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4224AL*+UI	935CA66100C21***	31,200	\$4,368
206136135	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4321AL*+UI	935CA60080C21***	31,800	\$4,452
206136145	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4321AL*+UI	935CA66100C21***	31,600	\$4,424
206136165	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4821AL*+UI	935CA60080C21***	31,400	\$4,396
206136175	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4821AL*+UI	935CA66100C21***	31,400	\$4,396
206136185	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4824AL*+UI	935CA60080C21***	31,400	\$4,396
206136195	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4824AL*+UI	935CA66100C21***	31,400	\$4,396
206136275	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4821AL*+UI	935CA60080C21***	31,400	\$4,396
206136285	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4821AL*+UI	935CA66100C21***	31,400	\$4,396
206136321	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	935CA66100C21***	31,400	\$4,396
206136331	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	935CA60080C21***	31,600	\$4,424
206136341	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4212AL*+UI	935CA66100C21***	31,600	\$4,424
206136351	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	935CA60080C21***	31,600	\$4,424
206136361	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*4812AL*+UI	935CA66100C21***	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206770974	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3617AL*+UI	88*TA48070C17***	31,400	\$4,396
206771019	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3617AL*+UI	88*TA36070C14***	31,400	\$4,396
206771028	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3617AL*+UI	88*TA48090C17***	31,200	\$4,368
206771046	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	88*TA48070C17***	31,200	\$4,368
206771064	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	88*TA60090C21***	31,200	\$4,368
206771082	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	986TC42080C17***	31,400	\$4,396
206771100	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	987MB42080C17***	31,400	\$4,396
206771118	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	987MB66100C21***	31,200	\$4,368
206771136	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	986TC66100C21***	31,200	\$4,368
206771145	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	88*TA48090C17***	31,000	\$4,340
206771163	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	987MB60060C21***	31,400	\$4,396
206771253	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	88*TA48070C17***	32,000	\$4,480
206771271	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	88*TA60090C21***	31,800	\$4,452
206771325	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	987MB66100C21***	31,800	\$4,452
206771343	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	986TC66100C21***	31,800	\$4,452
206771352	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	88*TA48090C17***	31,800	\$4,452
206771388	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	88*TA48070C17***	31,400	\$4,396
206771406	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	88*TA60090C21***	31,400	\$4,396
206771424	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	986TC42080C17***	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206771442	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	987MB42080C17***	31,600	\$4,424
206771460	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	987MB66100C21***	31,200	\$4,368
206771478	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	986TC66100C21***	31,200	\$4,368
206771487	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	88*TA48090C17***	31,200	\$4,368
206771505	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	987MB60060C21***	31,600	\$4,424
206771523	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	88*TA60090C21***	31,400	\$4,396
206771532	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	88*TA66135C24***	31,200	\$4,368
206771541	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	986TC66120C24***	31,200	\$4,368
206771559	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	987MB66100C21***	31,200	\$4,368
206771568	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	987MB66120C24***	31,400	\$4,396
206771586	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	986TC66100C21***	31,200	\$4,368
206771604	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	987MB60060C21***	31,600	\$4,424
206771622	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	88*TA48070C17***	32,000	\$4,480
206771640	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	88*TA60090C21***	31,800	\$4,452
206771694	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	987MB66100C21***	31,800	\$4,452
206771712	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	986TC66100C21***	31,800	\$4,452
206771721	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	88*TA48090C17***	31,800	\$4,452
206771757	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	88*TA48070C17***	31,600	\$4,424
206771775	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	88*TA60090C21***	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206771793	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	986TC42080C17***	31,800	\$4,452
206771829	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	987MB66100C21***	31,400	\$4,396
206771847	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	986TC66100C21***	31,400	\$4,396
206771856	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	88*TA48090C17***	31,400	\$4,396
206771874	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	987MB60060C21***	31,800	\$4,452
206771892	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	88*TA60090C21***	31,400	\$4,396
206771901	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	88*TA66135C24***	31,400	\$4,396
206771910	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	986TC66120C24***	31,400	\$4,396
206771928	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	987MB66100C21***	31,400	\$4,396
206771937	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	987MB66120C24***	31,400	\$4,396
206771955	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	986TC66100C21***	31,400	\$4,396
206771973	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	987MB60060C21***	31,600	\$4,424
206771982	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*3617AL*+UI	88*TA48090C17***	31,200	\$4,368
206771991	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*3621AL*+UI	88*TA48090C17***	31,000	\$4,340
206772018	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4217AL*+UI	88*TA48070C17***	31,600	\$4,424
206772063	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4217AL*+UI	88*TA36070C14***	31,600	\$4,424
206772072	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4217AL*+UI	88*TA48090C17***	31,400	\$4,396
206772090	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4221AL*+UI	88*TA48070C17***	31,600	\$4,424
206772108	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4221AL*+UI	88*TA60090C21***	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206772162	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4221AL*+UI	987MB66100C21***	31,400	\$4,396
206772180	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4221AL*+UI	986TC66100C21***	31,400	\$4,396
206772189	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4221AL*+UI	88*TA48090C17***	31,400	\$4,396
206772225	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	88*TA48070C17***	31,600	\$4,424
206772243	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	88*TA60090C21***	31,600	\$4,424
206772261	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	986TC42080C17***	31,800	\$4,452
206772279	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	987MB42080C17***	31,800	\$4,452
206772297	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	987MB66100C21***	31,400	\$4,396
206772315	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	986TC66100C21***	31,400	\$4,396
206772324	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	88*TA48090C17***	31,400	\$4,396
206772342	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	987MB60060C21***	31,800	\$4,452
206772360	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	88*TA60090C21***	31,600	\$4,424
206772369	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	88*TA66135C24***	31,400	\$4,396
206772378	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	986TC66120C24***	31,400	\$4,396
206772396	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	987MB66100C21***	31,400	\$4,396
206772405	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	987MB66120C24***	31,600	\$4,424
206772423	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	986TC66100C21***	31,400	\$4,396
206772441	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	987MB60060C21***	31,800	\$4,452
206772523	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	88*TA48070C17***	31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206772541	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	88*TA60090C21***	31,600	\$4,424
206772550	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	88*TA66135C24***	31,400	\$4,396
206772577	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	986TC66120C24***	31,600	\$4,424
206772613	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	987MB66100C21***	31,600	\$4,424
206772622	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	987MB66120C24***	31,600	\$4,424
206772640	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	986TC66100C21***	31,600	\$4,424
206772649	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	88*TA36070C14***	31,600	\$4,424
206772658	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	88*TA48090C17***	31,600	\$4,424
206772694	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	88*TA48070C17***	31,800	\$4,452
206772712	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	88*TA60090C21***	31,600	\$4,424
206772721	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	88*TA66135C24***	31,600	\$4,424
206772748	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	986TC66120C24***	31,600	\$4,424
206772784	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	987MB66100C21***	31,600	\$4,424
206772793	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	987MB66120C24***	31,600	\$4,424
206772811	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	986TC66100C21***	31,600	\$4,424
206772820	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	88*TA36070C14***	31,800	\$4,452
206772829	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	88*TA48090C17***	31,600	\$4,424
206772847	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	987MB60060C21***	31,800	\$4,452
206772865	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	88*TA48070C17***	31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206772883	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	88*TA60090C21***	31,600	\$4,424
206772892	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	88*TA66135C24***	31,600	\$4,424
206772919	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	986TC66120C24***	31,600	\$4,424
206772955	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	987MB66100C21***	31,600	\$4,424
206772964	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	987MB66120C24***	31,800	\$4,452
206772982	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	986TC66100C21***	31,600	\$4,424
206772991	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	88*TA36070C14***	31,800	\$4,452
206773000	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	88*TA48090C17***	31,600	\$4,424
206773018	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	987MB60060C21***	32,000	\$4,480
206773027	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3617AL*+UI	83*CA36040C17***	31,200	\$4,368
206773036	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	83*CA36040C17***	31,800	\$4,452
206773045	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	83*CA48060C17***	32,000	\$4,480
206773054	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	83*CA60100C21***	31,800	\$4,452
206773063	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	83*CA48060C17***	31,400	\$4,396
206773090	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	83*CA60100C21***	31,400	\$4,396
206773099	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	83*CA36040C17***	31,800	\$4,452
206773108	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	83*CA48060C17***	31,800	\$4,452
206773126	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	83*CA60100C21***	31,800	\$4,452
206773135	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	83*CA36040C17***	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206773144	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	83*CA48060C17***	31,600	\$4,424
206773162	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	83*CA60100C21***	31,600	\$4,424
206773180	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	83*CA60100C21***	31,400	\$4,396
206773234	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4217AL*+UI	83*CA36040C17***	31,600	\$4,424
206773243	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4217AL*+UI	83*CA48060C17***	31,600	\$4,424
206773261	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4221AL*+UI	83*CA60100C21***	31,400	\$4,396
206773279	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	83*CA60100C21***	31,600	\$4,424
206773320	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	83*CA36040C17***	31,600	\$4,424
206773329	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	83*CA48060C17***	31,800	\$4,452
206773347	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	83*CA60100C21***	31,600	\$4,424
206773356	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	83*CA36040C17***	31,600	\$4,424
206773365	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	83*CA48060C17***	31,800	\$4,452
206773383	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	83*CA60100C21***	31,800	\$4,452
206773419	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	935CA60080C21***	31,800	\$4,452
206773428	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3721AL*+UI	935CA66100C21***	31,800	\$4,452
206773446	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	935CA66100C21***	31,200	\$4,368
206773455	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	935CA60080C21***	31,200	\$4,368
206773464	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4224AL*+UI	935CA66100C21***	31,200	\$4,368
206773473	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	935CA60080C21***	31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206773482	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4321AL*+UI	935CA66100C21***	31,600	\$4,424
206773500	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	935CA60080C21***	31,400	\$4,396
206773509	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4821AL*+UI	935CA66100C21***	31,400	\$4,396
206773518	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	935CA60080C21***	31,400	\$4,396
206773527	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4824AL*+UI	935CA66100C21***	31,400	\$4,396
206773554	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*3621AL*+UI	935CA60080C21***	31,200	\$4,368
206773563	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*3621AL*+UI	935CA66100C21***	31,000	\$4,340
206773581	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4221AL*+UI	935CA60080C21***	31,400	\$4,396
206773590	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4221AL*+UI	935CA66100C21***	31,400	\$4,396
206773599	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	935CA60080C21***	31,400	\$4,396
206773608	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	935CA66100C21***	31,400	\$4,396
206773642	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	935CA66100C21***	31,400	\$4,396
206773651	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	935CA60080C21***	31,600	\$4,424
206773660	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4212AL*+UI	935CA66100C21***	31,600	\$4,424
206773669	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	935CA60080C21***	31,600	\$4,424
206773678	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*4812AL*+UI	935CA66100C21***	31,600	\$4,424
212982937	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	83*SB60080M21***	23,200	\$3,248
212982373	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	83*SB36040M17***	12,200	\$1,708
212982625	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	83*SB48060M17***	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982397	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	83*SB36040M17***	12,200	\$1,708
213079322	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	83*SB60080M21***	29,200	\$4,088
212982433	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	83*SB36040M17***	12,300	\$1,722
212982385	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	83*SB36040M17***	12,400	\$1,736
212988096	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	916SA60100M21***	23,600	\$3,304
213079178	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	83*SB48060M17***	29,200	\$4,088
212982697	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	83*SB48060M17***	19,000	\$2,660
212982361	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	83*SB36040M17***	19,100	\$2,674
212981533	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	83*SB60100M21***	29,000	\$4,060
212982349	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	83*SB36040M17***	19,100	\$2,674
213078902	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	83*SB60100M21***	29,600	\$4,144
213078854	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	83*SB60100M21***	29,200	\$4,088
212982301	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	83*SB36040M17***	18,800	\$2,632
212982709	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	83*SB48060M17***	18,600	\$2,604
212981605	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	83*SB60100M21***	23,600	\$3,304
212981593	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	83*SB60100M21***	23,200	\$3,248
212982421	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	83*SB36040M17***	12,400	\$1,736
212982169	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	83*SB36040M17***	23,200	\$3,248
213079274	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	83*SB60080M21***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079046	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	83*SB36040M17***	29,200	\$4,088
213079010	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	83*SB36040M17***	29,000	\$4,060
213078986	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	83*SB36040M17***	29,000	\$4,060
212981617	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	83*SB60100M21***	23,200	\$3,248
212982721	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	83*SB48060M17***	19,000	\$2,660
212982637	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	83*SB48060M17***	23,400	\$3,276
212982409	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	83*SB36040M17***	12,300	\$1,722
212982337	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	83*SB36040M17***	19,100	\$2,674
212982265	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	83*SB36040M17***	19,100	\$2,674
213079142	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	83*SB48060M17***	29,000	\$4,060
213078926	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	83*SB60100M21***	29,400	\$4,116
212988060	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	916SA60100M21***	23,600	\$3,304
212982685	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	83*SB48060M17***	23,400	\$3,276
213078950	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	83*SB36040M17***	29,400	\$4,116
212982217	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	83*SB36040M17***	23,400	\$3,276
212981677	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	83*SB60100M21***	23,600	\$3,304
212982661	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	83*SB48060M17***	23,200	\$3,248
212982289	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	83*SB36040M17***	19,100	\$2,674
212982241	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	83*SB36040M17***	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982133	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	83*SB36040M17***	23,400	\$3,276
213079310	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	83*SB60080M21***	29,200	\$4,088
213078878	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	83*SB60100M21***	29,200	\$4,088
212982997	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	83*SB60080M21***	23,600	\$3,304
213079058	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	83*SB36040M17***	29,400	\$4,116
212988048	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	916SA60100M21***	23,600	\$3,304
212988036	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	916SA60100M21***	23,400	\$3,276
212982325	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	83*SB36040M17***	19,400	\$2,716
212982277	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	83*SB36040M17***	19,000	\$2,660
213079250	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	83*SB60080M21***	29,000	\$4,060
213079082	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	83*SB48060M17***	29,400	\$4,116
212982313	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	83*SB36040M17***	18,700	\$2,618
213079166	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	83*SB48060M17***	29,400	\$4,116
213079202	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	83*SB60080M21***	29,400	\$4,116
212982253	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	83*SB36040M17***	18,600	\$2,604
213079214	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	83*SB60080M21***	29,000	\$4,060
213079106	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	83*SB48060M17***	29,200	\$4,088
213079094	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	83*SB48060M17***	29,000	\$4,060
213079238	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	83*SB60080M21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079226	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	83*SB60080M21***	29,400	\$4,116
212982973	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	83*SB60080M21***	23,200	\$3,248
213079298	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	83*SB60080M21***	29,400	\$4,116
212982157	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	83*SB36040M17***	23,400	\$3,276
212982145	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	83*SB36040M17***	23,200	\$3,248
213080364	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	916SA60100M21***	29,200	\$4,088
213080352	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	916SA60100M21***	29,200	\$4,088
213080292	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	916SA60100M21***	29,400	\$4,116
213080280	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	916SA60100M21***	29,200	\$4,088
213079070	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	83*SB36040M17***	29,200	\$4,088
213078998	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	83*SB36040M17***	29,400	\$4,116
212969727	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	82*SB36045V14***	19,300	\$2,702
213080403	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	916SA66100M21***	29,400	\$4,116
212988216	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	916SA66100M21***	29,000	\$4,060
213080448	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	916SA66100M21***	29,200	\$4,088
213080439	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	916SA66100M21***	29,200	\$4,088
213080394	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	916SA66100M21***	29,400	\$4,116
213080268	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	916SA60100M21***	29,400	\$4,116
213079262	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	83*SB60080M21***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988012	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	916SA60100M21***	29,000	\$4,060
213079154	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	83*SB48060M17***	29,600	\$4,144
213078962	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	83*SB36040M17***	29,400	\$4,116
213080412	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	916SA66100M21***	29,200	\$4,088
213080385	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	916SA66100M21***	29,200	\$4,088
213080340	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	916SA60100M21***	29,400	\$4,116
213080316	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	916SA60100M21***	29,200	\$4,088
212982085	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	83*SB36040M17***	28,800	\$4,032
213078938	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	83*SB60100M21***	29,200	\$4,088
212988000	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	916SA60100M21***	29,000	\$4,060
213080430	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	916SA66100M21***	29,400	\$4,116
213080376	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	916SA66100M21***	29,400	\$4,116
213080304	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	916SA60100M21***	29,400	\$4,116
213079130	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	83*SB48060M17***	29,000	\$4,060
213078866	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	83*SB60100M21***	29,400	\$4,116
213078830	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	83*SB60100M21***	29,400	\$4,116
212988225	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	916SA66100M21***	29,000	\$4,060
212988072	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	916SA60100M21***	23,200	\$3,248
213078974	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	83*SB36040M17***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785387	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	987MC42060C17***	33,200	\$4,648
213785345	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3617AL*+UI	987MC42060C17***	34,400	\$4,816
211712152	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	915SB60100E21***	23,600	\$3,304
211712140	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	83*SA60100E21***	23,200	\$3,248
211712128	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	935SA60100E21***	23,400	\$3,276
211712118	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*SA48070V17***	23,400	\$3,276
211712106	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3621AL*	83*SA60100E21***	23,600	\$3,304
211712094	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3621AL*	935SA60100E21***	23,600	\$3,304
211709696	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	PF4MN*B30L*		23,400	\$3,276
211295841	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926TB66100V21***	23,000	\$3,220
211295840	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926TB60100V21***	23,200	\$3,248
211295839	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926TB60080V21***	23,000	\$3,220
211295838	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926TB42060V17***	23,200	\$3,248
211295837	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	935SA48060E17***	23,400	\$3,276
211295836	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	935SA36040E17***	23,200	\$3,248
211295835	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926SA60100V21***	23,200	\$3,248
211295834	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926SA60080V21***	23,000	\$3,220
211295833	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926SA48080V17***	23,200	\$3,248
211295832	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926SA42060V17***	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211295831	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	915SB60080E21***	23,200	\$3,248
211295830	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	915SB42060E17***	23,200	\$3,248
211295829	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	912SD60100E21***	23,200	\$3,248
211295828	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	912SD60080E21***	23,200	\$3,248
211295827	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	912SD48080E17***	23,400	\$3,276
211295826	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	912SD42060E17***	23,400	\$3,276
211295823	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*TA66110V21***	23,200	\$3,248
211295822	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*TA60090V21***	23,200	\$3,248
211295821	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*TA48090V17***	23,200	\$3,248
211295820	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*TA48070V17***	23,200	\$3,248
211295819	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	83*SA60080E21***	23,400	\$3,276
211295818	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	83*SA48060E17***	23,200	\$3,248
211295817	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	83*SA36040E17***	23,200	\$3,248
211295816	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*SA60090V21***	23,200	\$3,248
211295815	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*SA60070V21***	23,200	\$3,248
211295814	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*SA48070V17***	23,200	\$3,248
211295813	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*SA48045V17***	23,200	\$3,248
211295812	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SA60110E21***	23,200	\$3,248
211295811	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SA60090E21***	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211295810	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SA48090E21***	23,400	\$3,276
211295809	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SA42090E17***	23,200	\$3,248
211295808	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SA48070E21***	23,200	\$3,248
211295807	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SA48070E17***	23,400	\$3,276
211295806	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SA36070E17***	23,200	\$3,248
211295801	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	926TB42060V17***	23,400	\$3,276
211295800	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	935SA48060E17***	23,400	\$3,276
211295799	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	935SA36040E17***	23,400	\$3,276
211295798	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	926SA48080V17***	23,400	\$3,276
211295797	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	915SB42060E17***	23,400	\$3,276
211295796	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	912SD48080E17***	23,400	\$3,276
211295795	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	912SD42060E17***	23,400	\$3,276
211295794	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	912SD36060E14***	23,400	\$3,276
211295793	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*TA48090V17***	23,400	\$3,276
213353856	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	F54AA*C42L*		29,200	\$4,088
211295792	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*TA48070V17***	23,200	\$3,248
211295791	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*TA36070V14***	23,400	\$3,276
213300342	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	F54AA*B36L*		29,400	\$4,116
211295790	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*TA36045V14***	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211295789	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	83*SA48060E17***	23,400	\$3,276
213249335	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FEVA0036***+NAVA43601CK		29,400	\$4,116
211295788	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	83*SA36040E17***	23,400	\$3,276
211295787	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*SA48045V17***	23,400	\$3,276
211295786	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*SA36045V14***	23,400	\$3,276
213080873	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	935SB60080M21***	29,200	\$4,088
211295785	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	8(0,1)*SA42090E17***	23,200	\$3,248
211295784	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	8(0,1)*SA48070E17***	23,400	\$3,276
213080861	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	935SB60080M21***	29,200	\$4,088
211295783	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	8(0,1)*SA36045E14***	23,400	\$3,276
213080849	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	935SB60080M21***	29,400	\$4,116
213080837	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	935SB60080M21***	29,600	\$4,144
213080825	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	935SB60080M21***	29,200	\$4,088
213080813	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	935SB60080M21***	29,400	\$4,116
211295771	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3621AL*	912SD60100E21***	23,400	\$3,276
211295770	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3621AL*	912SD60080E21***	23,400	\$3,276
213080801	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	935SB60080M21***	29,400	\$4,116
213080789	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	935SB60080M21***	29,200	\$4,088
213080777	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	935SB60080M21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080765	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	935SB48060M17***	29,200	\$4,088
213080753	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	935SB48060M17***	29,600	\$4,144
213080741	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	935SB48060M17***	29,400	\$4,116
211295754	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3621AL*	8(0,1)*SA60110E21***	23,600	\$3,304
211295752	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3621AL*	8(0,1)*SA48090E21***	23,600	\$3,304
213080705	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	935SB48060M17***	29,200	\$4,088
213080693	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	935SB48060M17***	29,400	\$4,116
213080681	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	935SB48060M17***	29,200	\$4,088
213080669	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	935SB48060M17***	29,400	\$4,116
213080657	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	935SB48060M17***	29,400	\$4,116
213080645	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	935SB48060M17***	29,600	\$4,144
213080633	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	935SB36040M17***	29,400	\$4,116
213080621	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	935SB36040M17***	29,600	\$4,144
213080609	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	935SB36040M17***	29,400	\$4,116
213080573	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	935SB36040M17***	29,200	\$4,088
213080561	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	935SB36040M17***	29,200	\$4,088
213080549	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	935SB36040M17***	29,600	\$4,144
211274895	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FV4CN(B,F)005L		23,000	\$3,220
213080537	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	935SB36040M17***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080525	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	935SB36040M17***	29,400	\$4,116
213080513	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	935SB36040M17***	29,600	\$4,144
213080501	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	935SB36040M17***	29,600	\$4,144
213080491	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	916SA66140M24***	29,200	\$4,088
213080481	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	916SA66140M24***	29,400	\$4,116
213080469	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	916SA66120M24***	29,200	\$4,088
213080457	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	916SA66120M24***	29,400	\$4,116
213080256	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	916SA60080M21***	29,200	\$4,088
213080244	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	916SA60080M21***	29,200	\$4,088
213080232	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	916SA60080M21***	29,400	\$4,116
213080208	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	916SA60080M21***	29,000	\$4,060
213080196	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	916SA60080M21***	29,000	\$4,060
213080184	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	916SA60080M21***	29,200	\$4,088
213080172	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	916SA60080M21***	29,400	\$4,116
213080160	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	916SA60080M21***	29,400	\$4,116
213080148	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	916SA60080M21***	29,200	\$4,088
213080136	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	916SA60080M21***	29,600	\$4,144
213080124	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	916SA48080M17***	29,200	\$4,088
213080112	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	916SA48080M17***	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080100	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	916SA48080M17***	29,400	\$4,116
213080064	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	916SA48080M17***	29,000	\$4,060
213080052	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	916SA48080M17***	29,200	\$4,088
213080040	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	916SA48080M17***	29,400	\$4,116
213080028	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	916SA48080M17***	29,200	\$4,088
213080016	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	916SA48080M17***	29,400	\$4,116
213080004	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	916SA48080M17***	29,600	\$4,144
213079992	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	916SA48080M17***	29,600	\$4,144
213079982	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	916SA36060M14***	29,600	\$4,144
213079962	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	916SA36060M14***	29,400	\$4,116
213079952	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	916SA36060M14***	29,600	\$4,144
213079941	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	912SE60120M24***	29,200	\$4,088
213079930	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	912SE60120M24***	29,000	\$4,060
213079919	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	912SE60120M24***	29,400	\$4,116
213079910	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	912SE66100M21***	29,200	\$4,088
213079901	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SE66100M21***	29,200	\$4,088
213079892	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SE66100M21***	29,400	\$4,116
213079874	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SE66100M21***	29,000	\$4,060
213079865	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	912SE66100M21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079856	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SE66100M21***	29,400	\$4,116
213079847	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SE66100M21***	29,000	\$4,060
213079838	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SE66100M21***	29,400	\$4,116
213079826	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	912SE60100M21***	29,200	\$4,088
213079814	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SE60100M21***	29,200	\$4,088
213079802	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SE60100M21***	29,400	\$4,116
213079790	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	912SE60100M21***	29,600	\$4,144
213079778	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SE60100M21***	29,000	\$4,060
213079766	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	912SE60100M21***	29,400	\$4,116
213079754	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SE60100M21***	29,400	\$4,116
213079742	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SE60100M21***	29,000	\$4,060
213079730	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SE60100M21***	29,400	\$4,116
213079720	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	912SE60080M21***	29,200	\$4,088
213079710	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SE60080M21***	29,200	\$4,088
213079700	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SE60080M21***	29,400	\$4,116
213079690	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	912SE60080M21***	29,600	\$4,144
213079680	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SE60080M21***	29,200	\$4,088
213079670	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	912SE60080M21***	29,400	\$4,116
213079660	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SE60080M21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079650	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SE60080M21***	29,200	\$4,088
213079640	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SE60080M21***	29,400	\$4,116
213079628	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SE48080M17***	29,200	\$4,088
213079616	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SE48080M17***	29,400	\$4,116
213079604	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	912SE48080M17***	29,200	\$4,088
213079568	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SE48080M17***	29,000	\$4,060
213079556	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SE48080M17***	29,400	\$4,116
213079544	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SE48080M17***	29,000	\$4,060
213079532	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	912SE48080M17***	29,400	\$4,116
213079520	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SE48080M17***	29,400	\$4,116
213079508	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	912SE48080M17***	29,400	\$4,116
213079496	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SE42060M17***	29,200	\$4,088
213079484	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SE42060M17***	29,400	\$4,116
213079472	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	912SE42060M17***	29,400	\$4,116
213079436	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SE42060M17***	29,200	\$4,088
213079424	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SE42060M17***	29,400	\$4,116
213079410	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SE42060M17***	29,200	\$4,088
213079398	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	912SE42060M17***	29,400	\$4,116
213079386	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SE42060M17***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079374	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	912SE42060M17***	29,400	\$4,116
213079364	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	912SE36060M14***	29,400	\$4,116
213079344	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	912SE36060M14***	29,400	\$4,116
213079334	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	912SE36060M14***	29,600	\$4,144
213079190	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	83*SB48060M17***	29,200	\$4,088
213079118	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	83*SB48060M17***	29,200	\$4,088
213078914	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	83*SB60100M21***	29,400	\$4,116
213078890	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3617AL*	83*SB60100M21***	29,600	\$4,144
213078842	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	83*SB60100M21***	29,400	\$4,116
213078818	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	83*SB60100M21***	29,600	\$4,144
213078808	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SB60155M24***	29,200	\$4,088
213078798	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SB60155M24***	29,000	\$4,060
213078788	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SB60155M24***	29,400	\$4,116
213078777	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SB60135M24***	29,200	\$4,088
213078766	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SB60135M24***	29,400	\$4,116
213078756	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SB60110M24***	29,200	\$4,088
213078746	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SB60110M24***	29,000	\$4,060
213078736	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SB60110M24***	29,400	\$4,116
213078724	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SB60110M21***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078712	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SB60110M21***	29,200	\$4,088
213078700	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SB60110M21***	29,400	\$4,116
213078676	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SB60110M21***	29,000	\$4,060
213078664	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SB60110M21***	29,000	\$4,060
213078652	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SB60110M21***	29,000	\$4,060
213078640	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SB60110M21***	29,400	\$4,116
213078628	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SB60110M21***	29,400	\$4,116
213078616	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SB60110M21***	29,000	\$4,060
213078604	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SB60110M21***	29,400	\$4,116
213078595	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SB60090M24***	29,200	\$4,088
213078586	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SB60090M24***	29,400	\$4,116
213078575	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SB60090M21***	29,200	\$4,088
213078564	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SB60090M21***	29,200	\$4,088
213078553	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SB60090M21***	29,400	\$4,116
213078531	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SB60090M21***	29,200	\$4,088
213078520	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SB60090M21***	29,400	\$4,116
213078509	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SB60090M21***	29,400	\$4,116
213078498	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SB60090M21***	29,200	\$4,088
213078487	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SB60090M21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078476	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SB48090M21***	29,200	\$4,088
211712499	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SA60110E21***	23,600	\$3,304
213078465	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SB48090M21***	29,200	\$4,088
213078454	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SB48090M21***	29,400	\$4,116
213078432	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SB48090M21***	29,000	\$4,060
211712486	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SA60090E21***	23,400	\$3,276
213078421	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SB48090M21***	29,400	\$4,116
213078410	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SB48090M21***	29,400	\$4,116
213078399	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SB48090M21***	29,000	\$4,060
211712473	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SA48090E21***	23,600	\$3,304
213078388	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SB48090M21***	29,400	\$4,116
213078376	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SB42090M17***	29,200	\$4,088
213078364	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SB42090M17***	29,400	\$4,116
213078352	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SB42090M17***	29,200	\$4,088
211712460	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SA42090E17***	23,400	\$3,276
213078316	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SB42090M17***	29,000	\$4,060
213078304	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SB42090M17***	29,400	\$4,116
213078292	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SB42090M17***	29,000	\$4,060
213078280	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SB42090M17***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078268	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SB42090M17***	29,400	\$4,116
213078256	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SB42090M17***	29,400	\$4,116
213078246	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SB48070M21***	29,200	\$4,088
213078236	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SB48070M21***	29,200	\$4,088
213078226	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SB48070M21***	29,400	\$4,116
213078206	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SB48070M21***	29,000	\$4,060
213078196	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SB48070M21***	29,400	\$4,116
211712423	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	82*TA66110V21***	23,400	\$3,276
213078186	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SB48070M21***	29,400	\$4,116
213078176	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SB48070M21***	29,000	\$4,060
213078166	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SB48070M21***	29,400	\$4,116
213078154	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SB48070M17***	29,200	\$4,088
213078142	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SB48070M17***	29,400	\$4,116
213078130	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SB48070M17***	29,400	\$4,116
213078118	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	8(0,1)*SB48070M17***	29,600	\$4,144
213078106	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3617AL*	8(0,1)*SB48070M17***	29,600	\$4,144
213078094	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SB48070M17***	29,200	\$4,088
213078082	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SB48070M17***	29,400	\$4,116
213078070	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SB48070M17***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078058	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SB48070M17***	29,400	\$4,116
213078046	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SB48070M17***	29,400	\$4,116
213078034	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SB48070M17***	29,600	\$4,144
213078023	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SB36070M17***	29,200	\$4,088
213078012	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SB36070M17***	29,400	\$4,116
213078001	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SB36070M17***	29,400	\$4,116
213077968	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SB36070M17***	29,000	\$4,060
211712378	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	82*TA48070V17***	23,400	\$3,276
213077957	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SB36070M17***	29,400	\$4,116
213077946	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SB36070M17***	29,000	\$4,060
213077935	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SB36070M17***	29,400	\$4,116
213077924	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SB36070M17***	29,400	\$4,116
213077913	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SB36070M17***	29,400	\$4,116
213077901	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SB36070M14***	29,400	\$4,116
211712536	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	912SD60080E21***	23,400	\$3,276
211712366	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	915SB60100E21***	23,600	\$3,304
213077877	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SB36070M14***	29,400	\$4,116
213077865	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SB36070M14***	29,400	\$4,116
213077853	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SB36045M14***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712354	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	915SB60080E21***	23,400	\$3,276
213077829	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SB36045M14***	29,400	\$4,116
213077816	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SB36045M14***	29,600	\$4,144
213077805	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926TC66120V24***	29,200	\$4,088
213077793	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926TC66120V24***	29,400	\$4,116
213077782	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926TC66100V21***	29,200	\$4,088
213077772	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TC66100V21***	29,200	\$4,088
213077762	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926TC66100V21***	29,400	\$4,116
213077752	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	926TC66100V21***	29,600	\$4,144
213077742	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926TC66100V21***	29,000	\$4,060
213077732	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926TC66100V21***	29,400	\$4,116
213077722	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926TC66100V21***	29,400	\$4,116
213077712	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926TC66100V21***	29,000	\$4,060
213077702	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926TC66100V21***	29,400	\$4,116
213077690	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926TC60100V21***	29,200	\$4,088
213077677	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TC60100V21***	29,200	\$4,088
213077664	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926TC60100V21***	29,400	\$4,116
211712548	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	912SD60100E21***	23,400	\$3,276
213077638	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926TC60100V21***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712328	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	83*SA36040E17***	23,400	\$3,276
213077625	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926TC60100V21***	29,400	\$4,116
213077612	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926TC60100V21***	29,400	\$4,116
213077599	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926TC60100V21***	29,000	\$4,060
213077586	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926TC60100V21***	29,400	\$4,116
213077574	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926TC60080V21***	29,200	\$4,088
213077563	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TC60080V21***	29,200	\$4,088
213077552	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926TC60080V21***	29,400	\$4,116
211712316	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	83*SA60100E21***	23,600	\$3,304
213077541	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	926TC60080V21***	29,600	\$4,144
213077530	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TC60080V21***	29,000	\$4,060
213077519	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926TC60080V21***	29,200	\$4,088
213077508	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926TC60080V21***	29,400	\$4,116
213077497	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926TC60080V21***	29,400	\$4,116
213077486	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926TC60080V21***	29,200	\$4,088
213077475	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926TC60080V21***	29,400	\$4,116
213077463	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TC48080V17***	29,200	\$4,088
213077450	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926TC48080V17***	29,600	\$4,144
213077437	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	926TC48080V17***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712292	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	935SA60100E21***	23,600	\$3,304
213077398	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926TC48080V17***	29,200	\$4,088
213077385	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926TC48080V17***	29,400	\$4,116
213077372	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926TC48080V17***	29,200	\$4,088
213077359	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926TC48080V17***	29,400	\$4,116
213077346	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926TC48080V17***	29,400	\$4,116
211712560	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	915SB42060E17***	23,600	\$3,304
213077333	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	926TC48080V17***	29,600	\$4,144
213077321	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	926TC36060V14***	29,400	\$4,116
213077299	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926TC36060V14***	29,400	\$4,116
211712272	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	82*SA60070V21***	23,400	\$3,276
213077288	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	926TC36060V14***	29,600	\$4,144
213077277	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TC36040V17***	29,400	\$4,116
213077266	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TC36040V17***	29,200	\$4,088
213077256	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926SB66120V24***	29,200	\$4,088
213077246	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926SB66120V24***	29,000	\$4,060
213077236	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926SB66120V24***	29,400	\$4,116
213077226	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926SB60100V21***	29,200	\$4,088
213077216	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926SB60100V21***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077206	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926SB60100V21***	29,400	\$4,116
213077186	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926SB60100V21***	29,000	\$4,060
213077176	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926SB60100V21***	29,000	\$4,060
213077166	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926SB60100V21***	29,400	\$4,116
213077156	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926SB60100V21***	29,400	\$4,116
213077146	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926SB60100V21***	29,000	\$4,060
213077136	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926SB60100V21***	29,400	\$4,116
213077126	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926SB60080V21***	29,200	\$4,088
213077116	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926SB60080V21***	29,200	\$4,088
213077106	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926SB60080V21***	29,400	\$4,116
213077096	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	926SB60080V21***	29,600	\$4,144
213077086	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926SB60080V21***	29,000	\$4,060
213077076	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926SB60080V21***	29,200	\$4,088
213077066	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926SB60080V21***	29,400	\$4,116
213077056	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926SB60080V21***	29,400	\$4,116
213077046	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926SB60080V21***	29,200	\$4,088
213077036	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926SB60080V21***	29,400	\$4,116
213077026	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926SB48080V17***	29,200	\$4,088
213077016	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926SB48080V17***	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712229	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SA48070E17***	23,600	\$3,304
213077006	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	926SB48080V17***	29,400	\$4,116
213076976	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926SB48080V17***	29,200	\$4,088
213076966	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926SB48080V17***	29,400	\$4,116
213076956	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926SB48080V17***	29,200	\$4,088
213076946	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926SB48080V17***	29,400	\$4,116
213076936	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926SB48080V17***	29,400	\$4,116
213076926	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	926SB48080V17***	29,600	\$4,144
213076916	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	926SB36060V14***	29,400	\$4,116
213076896	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926SB36060V14***	29,400	\$4,116
213076886	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	926SB36060V14***	29,600	\$4,144
211712207	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	926SA48080V17***	23,400	\$3,276
213076876	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926SB36040V17***	29,400	\$4,116
213076866	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926SB36040V17***	29,200	\$4,088
213076863	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*TB66135V24***	29,200	\$4,088
213076860	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*TB66135V24***	29,400	\$4,116
213076848	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*TB66110V21***	29,200	\$4,088
213076836	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*TB66110V21***	29,200	\$4,088
213076824	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*TB66110V21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076800	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*TB66110V21***	29,000	\$4,060
213076788	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*TB66110V21***	29,000	\$4,060
211712584	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	83*SA48060E17***	23,400	\$3,276
213076776	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*TB66110V21***	29,200	\$4,088
213076764	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*TB66110V21***	29,400	\$4,116
213076752	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*TB66110V21***	29,400	\$4,116
213076740	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*TB66110V21***	29,200	\$4,088
213076728	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*TB66110V21***	29,400	\$4,116
213076717	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*TB60090V21***	29,200	\$4,088
213076706	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*TB60090V21***	29,200	\$4,088
213076695	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*TB60090V21***	29,400	\$4,116
213076684	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	82*TB60090V21***	29,600	\$4,144
213076673	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*TB60090V21***	29,200	\$4,088
213076662	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*TB60090V21***	29,400	\$4,116
213076651	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*TB60090V21***	29,400	\$4,116
213076640	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*TB60090V21***	29,200	\$4,088
213076629	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*TB60090V21***	29,400	\$4,116
211712164	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SA36045E17***	23,400	\$3,276
213076625	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*TB48090V17***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076621	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*TB48090V17***	29,400	\$4,116
213076617	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*TB48090V17***	29,400	\$4,116
213076605	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*TB48090V17***	29,000	\$4,060
213076601	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*TB48090V17***	29,400	\$4,116
211712657	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	82*SA60070V21***	23,400	\$3,276
213076597	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*TB48090V17***	29,000	\$4,060
213076593	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*TB48090V17***	29,400	\$4,116
213076589	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*TB48090V17***	29,400	\$4,116
213076585	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*TB48090V17***	29,400	\$4,116
213076574	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*TB48070V17***	29,200	\$4,088
213076563	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*TB48070V17***	29,400	\$4,116
213076552	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*TB48070V17***	29,400	\$4,116
211712677	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	82*SA60090V24***	23,400	\$3,276
213076519	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*TB48070V17***	29,000	\$4,060
213076508	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*TB48070V17***	29,400	\$4,116
213076497	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*TB48070V17***	29,000	\$4,060
213076486	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*TB48070V17***	29,400	\$4,116
213076475	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*TB48070V17***	29,400	\$4,116
211201016	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FV4CNF002L		23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076464	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*TB48070V17***	29,400	\$4,116
211712687	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	82*SA66110V24***	23,400	\$3,276
213076462	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*TB36045V14***	29,400	\$4,116
211201013	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FMA4X36**AL*		23,800	\$3,332
213076458	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*TB36045V14***	29,200	\$4,088
213076456	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*TB36045V14***	29,400	\$4,116
211201012	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FMA4X30**AL*		23,800	\$3,332
211201010	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FM(C,U)4Z36**AL*		23,600	\$3,304
211201009	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FM(C,U)4Z30**AL*		23,600	\$3,304
211201006	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	OVMAAB036098	23,200	\$3,248
211201005	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	OVLAAB036098	23,200	\$3,248
211201003	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	OVMAAB036098	23,400	\$3,276
211712697	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	935SA60100E21***	23,600	\$3,304
213076334	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	935SB66100M21***	29,200	\$4,088
213076325	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	935SB66100M21***	29,200	\$4,088
213076316	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	935SB66100M21***	29,400	\$4,116
213076298	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	935SB66100M21***	29,000	\$4,060
213076289	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	935SB66100M21***	29,000	\$4,060
213076280	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	935SB66100M21***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076271	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	935SB66100M21***	29,400	\$4,116
213076262	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	935SB66100M21***	29,400	\$4,116
211712709	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	83*SA60100E21***	23,600	\$3,304
213076253	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	935SB66100M21***	29,000	\$4,060
213076244	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	935SB66100M21***	29,400	\$4,116
213075995	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	935SB60100M21***	29,200	\$4,088
213075983	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	935SB60100M21***	29,200	\$4,088
213075971	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	935SB60100M21***	29,400	\$4,116
213075947	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	935SB60100M21***	29,000	\$4,060
213075935	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	935SB60100M21***	29,000	\$4,060
213075923	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	935SB60100M21***	29,000	\$4,060
213075911	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	935SB60100M21***	29,400	\$4,116
213075899	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	935SB60100M21***	29,400	\$4,116
213075887	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	935SB60100M21***	29,000	\$4,060
213075875	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	935SB60100M21***	29,400	\$4,116
212989502	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	935SB60080M21***	29,000	\$4,060
211712735	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	915SB60080E21***	23,400	\$3,276
212989490	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	935SB60080M21***	29,000	\$4,060
212988974	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	935SB48060M17***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988402	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	916SA66140M24***	29,000	\$4,060
212988318	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	916SA66120M24***	29,000	\$4,060
211712747	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	915SB60100E21***	23,600	\$3,304
212985516	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	912SE66100M21***	29,000	\$4,060
212985507	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SE66100M21***	29,000	\$4,060
212985240	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	912SE60100M21***	28,800	\$4,032
212985228	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SE60100M21***	28,800	\$4,032
212984950	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	912SE60080M21***	28,800	\$4,032
212984940	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SE60080M21***	28,800	\$4,032
212984410	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SE48080M17***	29,000	\$4,060
212983870	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SE42060M17***	29,000	\$4,060
212982601	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	83*SB48060M17***	28,800	\$4,032
212981207	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SB60135M24***	29,000	\$4,060
212980689	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SB60090M24***	29,000	\$4,060
212980487	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SB60090M21***	29,000	\$4,060
212980476	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SB60090M21***	29,000	\$4,060
212980168	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SB48090M21***	28,800	\$4,032
212980157	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SB48090M21***	28,800	\$4,032
212979654	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SB42090M17***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979412	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SB48070M21***	28,800	\$4,032
212979402	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SB48070M21***	28,800	\$4,032
212978964	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SB48070M17***	29,000	\$4,060
212978478	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SB36070M17***	29,000	\$4,060
212977252	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926TC66120V24***	29,000	\$4,060
211712793	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	82*TA66110V21***	23,400	\$3,276
212977089	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926TC66100V21***	28,800	\$4,032
212977079	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TC66100V21***	28,800	\$4,032
212976807	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926TC60100V21***	29,000	\$4,060
212976794	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TC60100V21***	29,000	\$4,060
212976525	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926TC60080V21***	28,800	\$4,032
212976298	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TC48080V17***	29,000	\$4,060
212974413	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926SB60100V21***	29,000	\$4,060
212974193	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926SB60080V21***	28,800	\$4,032
212974053	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926SB48080V17***	29,000	\$4,060
212972642	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*TB66135V24***	29,000	\$4,060
211184349	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FJ4DN*B30L*		23,400	\$3,276
212972242	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*TB60090V21***	29,000	\$4,060
210450237	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	926TB48080V17***	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972231	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*TB60090V21***	29,000	\$4,060
212972068	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*TB48090V17***	29,000	\$4,060
211712817	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SA48090E21***	23,600	\$3,304
210450235	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	926TB36060V14***	23,600	\$3,304
212971875	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*TB48070V17***	29,000	\$4,060
210450234	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	926TB48080V17***	23,400	\$3,276
212970737	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*SB60090V21***	29,200	\$4,088
212970727	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*SB60090V21***	29,200	\$4,088
212970717	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*SB60090V21***	29,400	\$4,116
212970707	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	82*SB60090V21***	29,600	\$4,144
212970697	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*SB60090V21***	29,000	\$4,060
210450223	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926TB48080V17***	23,200	\$3,248
212970687	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*SB60090V21***	29,000	\$4,060
210450221	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	926TB48080V17***	23,600	\$3,304
211712830	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SA60090E21***	23,400	\$3,276
212970677	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*SB60090V21***	29,200	\$4,088
210450219	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926TB48080V17***	23,200	\$3,248
212970667	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*SB60090V21***	29,400	\$4,116
210450217	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	926TB36060V14***	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212970657	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*SB60090V21***	29,400	\$4,116
210450216	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	926TB48080V17***	23,400	\$3,276
212970647	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*SB60090V21***	29,200	\$4,088
212970637	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*SB60090V21***	29,400	\$4,116
212970477	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*SB48070V17***	29,200	\$4,088
212970467	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*SB48070V17***	29,400	\$4,116
212970457	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*SB48070V17***	29,400	\$4,116
211712843	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SA60090E24***	23,400	\$3,276
212970427	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*SB48070V17***	29,000	\$4,060
212970417	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*SB48070V17***	29,200	\$4,088
212970407	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*SB48070V17***	29,400	\$4,116
212970397	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*SB48070V17***	29,200	\$4,088
212970387	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*SB48070V17***	29,400	\$4,116
211712856	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SA60110E21***	23,600	\$3,304
212970377	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*SB48070V17***	29,600	\$4,144
212970367	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*SB48070V17***	29,600	\$4,144
212969957	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*SB36045V14***	29,400	\$4,116
212969937	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*SB36045V14***	29,200	\$4,088
212969927	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*SB36045V14***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384851	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FV4CN(B,F)003L		29,400	\$4,116
211712869	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SA60110E24***	23,400	\$3,276
212384826	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	PF4MN*C42L*		29,200	\$4,088
212384825	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FJ4DN*C42L*		29,200	\$4,088
212384787	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SD48080E17***	29,200	\$4,088
212384775	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SA48070E17***	29,200	\$4,088
212384765	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	OVLAAB048112	29,600	\$4,144
212384755	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	OVMAAB042112	29,400	\$4,116
211712882	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SA60135E24***	23,600	\$3,304
212384745	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	OVLAAB036098	29,600	\$4,144
212384735	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	OVMAAB036098	29,600	\$4,144
212384723	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	83*SA48060E17***	29,400	\$4,116
212384711	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	83*SA60080E21***	29,600	\$4,144
212384699	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	915SB42060E17***	29,400	\$4,116
212384687	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SD60100E21***	29,400	\$4,116
211712895	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	912SD60080E21***	23,400	\$3,276
212384675	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SD60080E21***	29,400	\$4,116
212384663	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SD48080E17***	29,400	\$4,116
212384651	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SD42060E17***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384638	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SA60110E21***	29,400	\$4,116
212384625	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SA48070E21***	29,400	\$4,116
213361582	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	FE4BNXB24L*+UI		25,000	\$3,500
212384612	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SA36070E17***	29,600	\$4,144
211712907	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	912SD60100E21***	23,400	\$3,276
213361580	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	FE4BN(B,X)C36L*+UI		24,800	\$3,472
212384599	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SA36045E17***	29,400	\$4,116
212384588	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*TA66110V21***	29,400	\$4,116
212384577	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926TB60080V21***	29,600	\$4,144
212384566	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*TA48070V17***	29,400	\$4,116
212384554	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	915SB60080E21***	29,600	\$4,144
212384543	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*TA60090V21***	29,400	\$4,116
212384540	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*TA48090V17***	29,400	\$4,116
212384528	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	83*SA60100E21***	29,400	\$4,116
212384516	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	935SA48060E17***	29,400	\$4,116
211712954	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	OVLAAB060154	23,600	\$3,304
211712964	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	OVMAAB060154	23,600	\$3,304
211712974	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926SA42060V17***	23,200	\$3,248
211712984	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926SA60080V21***	23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712994	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926SA60100V21***	23,200	\$3,248
211713004	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926SA48080V17***	23,200	\$3,248
211713014	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	935SA36040E17***	23,200	\$3,248
211713026	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SA48070E17***	23,400	\$3,276
211713039	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926TB66100V21***	23,000	\$3,220
211713049	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*SA48045V17***	23,200	\$3,248
211713059	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*SA48070V17***	23,200	\$3,248
211713069	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*SA60070V21***	23,200	\$3,248
211713079	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*SA60090V21***	23,200	\$3,248
211713089	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	935SA60100E21***	23,400	\$3,276
211713101	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	935SA48060E17***	23,400	\$3,276
211713113	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	83*SA60100E21***	23,400	\$3,276
211713125	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	83*SA36040E17***	23,200	\$3,248
213353884	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ60AB3*	F54AA*D60L*		37,800	\$5,292
213607811	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ60AB3*	FT4BNBD60L*		37,400	\$5,236
213607812	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ60AB3*	FG4ANBD60L*		37,400	\$5,236
213607813	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ60AB3*	PF4TNBD60L*		37,400	\$5,236
211713137	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*TA48090V17***	23,000	\$3,220
211713140	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*TA60090V21***	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713151	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	915SB60080E21***	23,200	\$3,248
211713163	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	915SB60100E21***	23,600	\$3,304
211713175	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*TA48070V17***	23,200	\$3,248
211713187	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926TB42060V17***	23,200	\$3,248
211713198	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926TB60080V21***	23,000	\$3,220
211713209	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926TB60100V21***	23,200	\$3,248
211713220	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*TA66110V21***	23,200	\$3,248
211713231	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SA36045E17***	23,400	\$3,276
212384504	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	935SA60100E21***	29,400	\$4,116
212384494	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*SA60090V21***	29,400	\$4,116
212384484	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*SA60070V21***	29,400	\$4,116
212384474	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*SA48070V17***	29,400	\$4,116
212384464	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	935SA66100E21***	29,600	\$4,144
211713244	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SA36070E17***	23,200	\$3,248
212384454	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	915SB66100E21***	29,600	\$4,144
212384444	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	912SD66100E21***	29,600	\$4,144
212384432	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SA48070E17***	29,400	\$4,116
212384422	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926SA48080V17***	29,400	\$4,116
212384412	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926SA60100V21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384402	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926SA60080V21***	29,400	\$4,116
211713257	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SA48070E21***	23,200	\$3,248
212384392	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926SA42060V17***	29,400	\$4,116
212384382	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	OVMAAB042112	29,400	\$4,116
212384372	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	OVLAAB036098	29,400	\$4,116
212384362	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	OVMAAB036098	29,400	\$4,116
212384350	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	83*SA48060E17***	29,400	\$4,116
211713270	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SA42090E17***	23,200	\$3,248
212384337	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SA36070E14***	29,400	\$4,116
212384325	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	912SD48080E17***	29,200	\$4,088
212384313	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	912SD42060E17***	29,200	\$4,088
212384301	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	912SD36060E14***	29,400	\$4,116
212384288	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SA42090E17***	29,400	\$4,116
211713283	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SA48090E21***	23,400	\$3,276
212384275	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SA36070E17***	29,400	\$4,116
212384262	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SA36045E17***	29,400	\$4,116
212384249	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SA36045E14***	29,600	\$4,144
212384246	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*TA48090V17***	29,400	\$4,116
212384235	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*TA36045V14***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713296	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SA60090E21***	23,200	\$3,248
212384225	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*SA48070V17***	29,200	\$4,088
212384215	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*SA48045V17***	29,400	\$4,116
212384203	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	8(0,1)*SA48070E17***	29,200	\$4,088
211713309	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SA60110E21***	23,400	\$3,276
212384139	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	83*SA60080E21***	29,800	\$4,172
212384127	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	912SD60100E21***	29,600	\$4,144
212384115	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	912SD60080E21***	29,600	\$4,144
211713322	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	912SD42060E17***	23,000	\$3,220
211713334	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	912SD48080E17***	23,400	\$3,276
211713346	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	912SD60080E21***	23,200	\$3,248
211713358	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	912SD60100E21***	23,200	\$3,248
212383809	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	935SA66100E21***	29,800	\$4,172
212383799	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	915SB66100E21***	29,800	\$4,172
212383789	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*3621AL*	912SD66100E21***	29,800	\$4,172
211713370	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	915SB42060E17***	23,200	\$3,248
211713382	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	83*SA60080E21***	23,400	\$3,276
211713394	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	83*SA48060E17***	23,200	\$3,248
212383481	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SA48070E17***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383469	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SD48080E17***	29,000	\$4,060
212383457	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SA48070E17***	29,200	\$4,088
212383447	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	OVLAAB048112	29,400	\$4,116
211713406	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	OVMAAB036098	23,200	\$3,248
212383435	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SD60100E21***	29,200	\$4,088
212383424	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*TA60090V21***	29,000	\$4,060
212383412	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	935SA48060E17***	29,200	\$4,088
212383400	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SA48070E17***	29,200	\$4,088
211713416	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	OVLAAB036098	23,200	\$3,248
212383388	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	83*SA48060E17***	29,200	\$4,088
212383376	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	83*SA48060E17***	29,400	\$4,116
212383364	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	83*SA60080E21***	29,600	\$4,144
212383352	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SD60100E21***	29,400	\$4,116
212383340	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SD60080E21***	29,400	\$4,116
212383328	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SD48080E17***	29,400	\$4,116
212383315	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SA60090E21***	29,400	\$4,116
212383302	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SA48090E21***	29,400	\$4,116
212383289	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SA42090E17***	29,600	\$4,144
212383276	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SA48070E21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383265	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*TA66110V21***	29,600	\$4,144
212383254	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926TB42060V17***	29,600	\$4,144
212383242	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*TA48070V17***	29,400	\$4,116
212383230	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	915SB60080E21***	29,600	\$4,144
212383219	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*TA60090V21***	29,400	\$4,116
212383207	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	935SA60100E21***	29,400	\$4,116
212383197	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*SA60090V21***	29,400	\$4,116
212383187	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*SA60070V21***	29,400	\$4,116
212383177	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*SA48070V17***	29,400	\$4,116
212383165	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	935SA60080E21***	29,800	\$4,172
212383155	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	935SA66100E21***	29,600	\$4,144
212383143	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SA48070E17***	29,400	\$4,116
212383133	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926SA48080V17***	29,400	\$4,116
212383123	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926SA60100V21***	29,400	\$4,116
212383113	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926SA60080V21***	29,400	\$4,116
212383103	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926SA42060V17***	29,600	\$4,144
212383093	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	OVLAAB036098	29,600	\$4,144
212383083	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	OVMAAB036098	29,600	\$4,144
212383071	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	83*SA48060E17***	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383058	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SA36070E14***	29,600	\$4,144
212383046	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	915SB42060E17***	29,600	\$4,144
212383034	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	912SD48080E17***	29,400	\$4,116
212383022	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	912SD42060E17***	29,400	\$4,116
212383010	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	912SD36060E14***	29,600	\$4,144
212382997	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SA42090E17***	29,600	\$4,144
212382984	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SA36070E17***	29,600	\$4,144
212382971	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SA36045E17***	29,600	\$4,144
212382958	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SA36045E14***	29,800	\$4,172
212382947	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	926TB42060V17***	29,600	\$4,144
212382935	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*TA48070V17***	29,400	\$4,116
212382932	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*TA48090V17***	29,400	\$4,116
212382929	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*TA36070V14***	29,400	\$4,116
212382918	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*TA36045V14***	29,600	\$4,144
212382906	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	935SA48060E17***	29,400	\$4,116
212382896	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*SA48070V17***	29,400	\$4,116
212382886	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*SA48045V17***	29,600	\$4,144
212382874	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	8(0,1)*SA48070E17***	29,400	\$4,116
212382864	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	926SA48080V17***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212382854	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	926SA42060V17***	29,600	\$4,144
212382844	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*SA36045V14***	29,600	\$4,144
211468637	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	PF4MN*B36L*		29,400	\$4,116
211230926	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FX4DN(B,F)049L		29,000	\$4,060
211230915	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FX4DN(B,F)043L		29,000	\$4,060
211230894	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FV4CN(B,F)005L		28,600	\$4,004
211230883	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FMA4X36**AL*		29,600	\$4,144
211230861	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FM(C,U)4Z36**AL*		29,600	\$4,144
211230806	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	OVMAAB060154	29,200	\$4,088
211230797	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	OVLAAB060154	29,400	\$4,116
211230788	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	OVLAAB048112	29,200	\$4,088
211230778	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926TB66120V24***	29,200	\$4,088
211230769	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926TB66100V21***	29,200	\$4,088
211230759	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926TB60100V21***	29,200	\$4,088
211230749	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926TB60080V21***	29,200	\$4,088
211230740	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	935SA66100E21***	29,400	\$4,116
211230729	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	935SA60100E21***	29,200	\$4,088
211230718	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	935SA60080E21***	29,600	\$4,144
211230709	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926SA66120V24***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230700	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926SA60100V21***	29,200	\$4,088
211230691	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	926SA60080V21***	29,200	\$4,088
211230680	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	915SB66140E24***	29,400	\$4,116
211230669	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	915SB66120E24***	29,400	\$4,116
211230660	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	915SB66100E21***	29,400	\$4,116
211230649	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	915SB60100E21***	29,200	\$4,088
211230638	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	915SB60080E21***	29,400	\$4,116
211230627	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	912SD60120E24***	29,200	\$4,088
211230618	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	912SD66100E21***	29,400	\$4,116
211230607	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	912SD60100E21***	29,200	\$4,088
211230596	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	912SD60080E21***	29,000	\$4,060
211230576	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*TA66135V24***	29,200	\$4,088
211230566	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*TA66110V21***	29,200	\$4,088
211230556	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*TA60090V21***	29,200	\$4,088
211230545	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	83*SA60100E21***	29,200	\$4,088
211230534	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	83*SA60080E21***	29,400	\$4,116
211230525	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*SA66110V24***	29,200	\$4,088
211230516	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*SA60090V24***	29,200	\$4,088
211230507	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*SA60090V21***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230498	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	82*SA60070V21***	29,200	\$4,088
211230488	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SA60155E24***	29,200	\$4,088
211230476	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SA60135E24***	29,200	\$4,088
211230464	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SA60110E24***	29,200	\$4,088
211230452	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SA60110E21***	29,200	\$4,088
211230440	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SA60090E24***	29,200	\$4,088
211230428	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SA60090E21***	29,200	\$4,088
211230416	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SA48090E21***	29,200	\$4,088
211230404	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4824AL*	8(0,1)*SA48070E21***	29,200	\$4,088
211230377	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	OVMAAB042112	29,200	\$4,088
211230368	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	OVMAAB036098	29,200	\$4,088
211230359	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	OVLAAB048112	29,200	\$4,088
211230350	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	OVLAAB036098	29,200	\$4,088
211230341	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TB66100V21***	29,200	\$4,088
211230331	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TB60100V21***	29,200	\$4,088
211230321	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TB60080V21***	29,200	\$4,088
211230311	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TB42060V17***	29,400	\$4,116
211230292	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	935SA66100E21***	29,400	\$4,116
211230281	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	935SA60100E21***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230270	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	935SA60080E21***	29,600	\$4,144
211230259	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	935SA48060E17***	29,200	\$4,088
211230250	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926SA60100V21***	29,200	\$4,088
211230241	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926SA60080V21***	29,200	\$4,088
211230232	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926SA48080V17***	29,200	\$4,088
211230223	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926SA42060V17***	29,200	\$4,088
211230205	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	915SB66100E21***	29,400	\$4,116
211230194	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	915SB60100E21***	29,200	\$4,088
211230183	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	915SB60080E21***	29,400	\$4,116
211230172	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	915SB48080E17***	29,200	\$4,088
211230161	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	915SB42060E17***	29,200	\$4,088
211230152	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SD66100E21***	29,400	\$4,116
211230141	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SD60100E21***	29,200	\$4,088
211230130	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SD60080E21***	29,000	\$4,060
211230119	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	912SD42060E17***	29,200	\$4,088
211230082	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*TA66110V21***	29,200	\$4,088
211230072	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*TA60090V21***	29,200	\$4,088
211230070	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*TA48090V17***	29,200	\$4,088
211230060	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*TA48070V17***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230049	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	83*SA60100E21***	29,200	\$4,088
211230038	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	83*SA60080E21***	29,400	\$4,116
211230027	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	83*SA48060E17***	29,000	\$4,060
211230016	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	83*SA36040E17***	29,600	\$4,144
211230007	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*SA60090V21***	29,200	\$4,088
211229998	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*SA60070V21***	29,200	\$4,088
211229989	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*SA48070V17***	29,200	\$4,088
211229980	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	82*SA48045V17***	29,200	\$4,088
211229968	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SA60110E21***	29,200	\$4,088
211229956	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SA60090E21***	29,200	\$4,088
211229944	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SA48090E21***	29,200	\$4,088
211229932	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SA42090E17***	29,200	\$4,088
211229920	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SA48070E21***	29,200	\$4,088
211229908	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SA36070E17***	29,400	\$4,116
211229896	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	8(0,1)*SA36045E17***	29,200	\$4,088
211229851	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926TB66100V21***	29,400	\$4,116
211229841	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926TB60100V21***	29,400	\$4,116
211229831	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926TB42060V17***	29,600	\$4,144
211229820	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	915SB60100E21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229800	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	82*SA48045V17***	29,400	\$4,116
211229788	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SA60090E21***	29,400	\$4,116
211229776	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SA48090E21***	29,400	\$4,116
211229764	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	8(0,1)*SA42090E17***	29,400	\$4,116
211229745	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	926TB42060V17***	29,400	\$4,116
211229734	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	935SA48060E17***	29,200	\$4,088
211229725	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	926SA48080V17***	29,400	\$4,116
211229716	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	926SA42060V17***	29,400	\$4,116
211229687	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	915SB42060E17***	29,400	\$4,116
211229668	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*TA48070V17***	29,200	\$4,088
211229666	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*TA36070V14***	29,400	\$4,116
211229657	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*SA36045V14***	29,400	\$4,116
211229648	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	OVMAAB060154	29,000	\$4,060
211229639	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	OVLAAB060154	29,200	\$4,088
211229630	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	OVLAAB048112	29,000	\$4,060
211229620	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926TB66120V24***	29,000	\$4,060
211714014	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*3621AL*	83*SA60080E21***	23,600	\$3,304
211229611	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926TB66100V21***	28,800	\$4,032
211229601	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926TB60100V21***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229591	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926TB60080V21***	28,800	\$4,032
211229582	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	935SA66100E21***	29,200	\$4,088
211229571	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	935SA60100E21***	29,000	\$4,060
211229560	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	935SA60080E21***	29,400	\$4,116
211229551	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926SA66120V24***	29,000	\$4,060
211229542	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926SA60100V21***	29,000	\$4,060
211229533	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	926SA60080V21***	29,000	\$4,060
211229522	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	915SB66140E24***	29,200	\$4,088
211229511	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	915SB66120E24***	29,200	\$4,088
211714038	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*SA36045V14***	23,400	\$3,276
211229502	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	915SB66100E21***	29,200	\$4,088
211229491	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	915SB60100E21***	29,000	\$4,060
211229480	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	915SB60080E21***	29,200	\$4,088
211229469	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	912SD60120E24***	29,000	\$4,060
211714048	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	926SA48080V17***	23,400	\$3,276
211229460	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	912SD66100E21***	29,200	\$4,088
211229449	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	912SD60100E21***	28,800	\$4,032
211229438	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	912SD60080E21***	28,800	\$4,032
211229418	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*TA66135V24***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229408	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*TA66110V21***	29,000	\$4,060
211714058	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	935SA36040E17***	23,400	\$3,276
211229398	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*TA60090V21***	28,800	\$4,032
211229387	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	83*SA60100E21***	29,000	\$4,060
211229376	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	83*SA60080E21***	29,200	\$4,088
211229367	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*SA66110V24***	28,800	\$4,032
211229358	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*SA60090V24***	28,800	\$4,032
211229349	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*SA60090V21***	28,800	\$4,032
211714070	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SA48070E17***	23,600	\$3,304
211229340	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	82*SA60070V21***	29,000	\$4,060
211229330	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SA60155E24***	29,200	\$4,088
211229318	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SA60135E24***	29,000	\$4,060
211229306	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SA60110E24***	28,800	\$4,032
211229294	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SA60110E21***	29,000	\$4,060
211714082	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*SA48045V17***	23,400	\$3,276
211229282	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SA60090E24***	29,000	\$4,060
211229270	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SA60090E21***	29,000	\$4,060
211229258	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SA48090E21***	29,000	\$4,060
211714092	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*SA48070V17***	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229246	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4824AL*	8(0,1)*SA48070E21***	28,800	\$4,032
211229219	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	OVMAAB042112	29,000	\$4,060
211229210	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	OVMAAB036098	29,000	\$4,060
211229201	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	OVLAAB048112	29,000	\$4,060
211229192	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	OVLAAB036098	29,000	\$4,060
211229183	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TB66100V21***	28,800	\$4,032
211714102	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	935SA48060E17***	23,600	\$3,304
211229173	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TB60100V21***	29,000	\$4,060
211229163	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TB60080V21***	29,000	\$4,060
211229153	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TB42060V17***	29,200	\$4,088
211229144	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	935SA66100E21***	29,200	\$4,088
211714114	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	83*SA36040E17***	23,400	\$3,276
211229133	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	935SA60100E21***	29,000	\$4,060
211229122	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	935SA60080E21***	29,400	\$4,116
211229111	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	935SA48060E17***	29,000	\$4,060
211229102	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926SA60100V21***	29,000	\$4,060
211229093	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926SA60080V21***	29,000	\$4,060
211229084	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926SA48080V17***	29,000	\$4,060
211714126	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*TA36045V14***	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229075	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926SA42060V17***	29,000	\$4,060
211229057	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	915SB66100E21***	29,200	\$4,088
211229046	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	915SB60100E21***	29,000	\$4,060
211229035	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	915SB60080E21***	29,200	\$4,088
211714137	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*TA36070V14***	23,200	\$3,248
211229024	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	915SB48080E17***	29,000	\$4,060
211714140	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*TA48090V17***	23,400	\$3,276
211229013	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	915SB42060E17***	29,000	\$4,060
211229004	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SD66100E21***	29,200	\$4,088
211714143	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*TA48070V17***	23,400	\$3,276
211228993	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SD60100E21***	28,800	\$4,032
211228982	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SD60080E21***	28,800	\$4,032
211228971	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SD48080E17***	29,000	\$4,060
211228960	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	912SD42060E17***	29,000	\$4,060
211228923	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*TA66110V21***	29,000	\$4,060
211714155	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	926TB42060V17***	23,400	\$3,276
211228913	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*TA60090V21***	28,800	\$4,032
211228911	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*TA48090V17***	29,000	\$4,060
211228901	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*TA48070V17***	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228890	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	83*SA60100E21***	29,000	\$4,060
211228879	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	83*SA60080E21***	29,200	\$4,088
211228868	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	83*SA48060E17***	29,000	\$4,060
211714166	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SA36045E14***	23,400	\$3,276
211228857	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	83*SA36040E17***	29,400	\$4,116
211228848	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*SA60090V21***	28,800	\$4,032
211228839	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*SA60070V21***	29,000	\$4,060
211228830	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*SA48070V17***	29,000	\$4,060
211228821	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	82*SA48045V17***	29,000	\$4,060
211228809	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SA60110E21***	29,000	\$4,060
211714179	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SA36070E17***	23,400	\$3,276
211228797	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SA60090E21***	29,000	\$4,060
211228785	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SA48090E21***	29,000	\$4,060
211228773	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SA42090E17***	29,000	\$4,060
211228761	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SA48070E21***	28,800	\$4,032
211228749	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SA36070E17***	29,000	\$4,060
211228737	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	8(0,1)*SA36045E17***	29,000	\$4,060
211714192	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SA42090E17***	23,400	\$3,276
211228692	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	OVMAAB042112	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228683	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	OVMAAB036098	29,200	\$4,088
211228674	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	OVLAAB048112	29,200	\$4,088
211228665	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	OVLAAB036098	29,200	\$4,088
211228656	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926TB66100V21***	29,000	\$4,060
211228646	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926TB60100V21***	29,200	\$4,088
211714205	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	912SD36060E14***	23,400	\$3,276
211228636	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926TB60080V21***	29,200	\$4,088
211228626	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926TB42060V17***	29,200	\$4,088
211228607	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	935SA66100E21***	29,200	\$4,088
211228596	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	935SA60100E21***	29,000	\$4,060
211714217	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	912SD42060E17***	23,200	\$3,248
211228585	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	935SA60080E21***	29,400	\$4,116
211228574	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	935SA48060E17***	29,200	\$4,088
211228565	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926SA60100V21***	29,000	\$4,060
211228556	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926SA60080V21***	29,000	\$4,060
211714229	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	912SD48080E17***	23,200	\$3,248
211228547	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926SA48080V17***	29,200	\$4,088
211228538	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926SA42060V17***	29,200	\$4,088
211228520	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	915SB66100E21***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228509	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	915SB60100E21***	29,200	\$4,088
211714241	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	915SB42060E17***	23,400	\$3,276
211228498	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	915SB60080E21***	29,200	\$4,088
211228476	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	915SB42060E17***	29,400	\$4,116
211228467	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SD66100E21***	29,400	\$4,116
211228456	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SD60100E21***	29,200	\$4,088
211714253	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SA36070E14***	23,200	\$3,248
211228445	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SD60080E21***	29,200	\$4,088
211228434	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	912SD42060E17***	29,000	\$4,060
211228397	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*TA66110V21***	29,200	\$4,088
211714266	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	83*SA48060E17***	23,400	\$3,276
211228387	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*TA60090V21***	29,000	\$4,060
211228385	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*TA48090V17***	29,000	\$4,060
211228375	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*TA48070V17***	29,000	\$4,060
211228364	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	83*SA60100E21***	29,000	\$4,060
211714278	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	OVMAAB036098	23,400	\$3,276
211228353	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	83*SA60080E21***	29,200	\$4,088
211228342	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	83*SA48060E17***	29,200	\$4,088
211714288	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	OVLAAB036098	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228331	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	83*SA36040E17***	29,400	\$4,116
211228322	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*SA60090V21***	29,000	\$4,060
211228313	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*SA60070V21***	29,000	\$4,060
211228304	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*SA48070V17***	29,200	\$4,088
211228295	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	82*SA48045V17***	29,200	\$4,088
211228283	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SA60110E21***	29,200	\$4,088
211714308	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	926SA60100V21***	23,400	\$3,276
211228271	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SA60090E21***	29,200	\$4,088
211228259	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SA48090E21***	29,000	\$4,060
211714318	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	926SA48080V17***	23,400	\$3,276
211228247	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SA42090E17***	29,200	\$4,088
211228235	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SA48070E21***	29,200	\$4,088
211228223	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SA36070E17***	29,200	\$4,088
211228211	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	8(0,1)*SA36045E17***	29,000	\$4,060
211228166	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	OVMAAB060154	29,400	\$4,116
211714340	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SA48070E17***	23,600	\$3,304
211714353	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	926TB66100V21***	23,400	\$3,276
211714383	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	82*SA60070V21***	23,400	\$3,276
211714403	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	935SA60100E21***	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714415	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	935SA48060E17***	23,600	\$3,304
212970757	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ48AA3*	CAP**4824AL*	82*SB60090V21***	32,600	\$4,564
212970747	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ48AA3*	CAP**4821AL*	82*SB60090V21***	32,600	\$4,564
211714427	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	83*SA60100E21***	23,600	\$3,304
211714439	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	83*SA36040E17***	23,400	\$3,276
212970797	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ48AB3*	CAP**4821AL*	82*SB60090V21***	31,400	\$4,396
212970807	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ48AB3*	CAP**4824AL*	82*SB60090V21***	31,400	\$4,396
212970817	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ48AB3*	CAP**6024AL*	82*SB60090V21***	31,000	\$4,340
212970827	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ48AB3*	CAP**6121AL*	82*SB60090V21***	31,000	\$4,340
212970837	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ48AB3*	CAP**6124AL*	82*SB60090V21***	31,000	\$4,340
211714465	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	915SB60080E21***	23,400	\$3,276
211714477	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	82*TA48070V17***	23,400	\$3,276
211714510	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	82*TA66110V21***	23,400	\$3,276
211714534	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SA48070E21***	23,600	\$3,304
211714547	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SA42090E17***	23,400	\$3,276
211714560	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SA48090E21***	23,600	\$3,304
211714573	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SA60090E21***	23,400	\$3,276
211714586	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SA60110E21***	23,600	\$3,304
211714623	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	912SD60080E21***	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714635	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	912SD60100E21***	23,400	\$3,276
211714659	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	83*SA48060E17***	23,400	\$3,276
211714682	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FJ4DN*B36L*		23,400	\$3,276
211714683	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	PF4MN*B36L*		23,400	\$3,276
212969877	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*SB36045V14***	23,400	\$3,276
212969917	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*SB36045V14***	23,400	\$3,276
212970277	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*SB48070V17***	23,400	\$3,276
212970297	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	82*SB48070V17***	23,600	\$3,304
212970347	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*SB48070V17***	23,400	\$3,276
212970357	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	82*SB48070V17***	23,600	\$3,304
212970587	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	82*SB60090V21***	23,600	\$3,304
212970597	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	82*SB60090V21***	23,600	\$3,304
212970627	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	82*SB60090V21***	23,600	\$3,304
212971425	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*TB36045V14***	23,400	\$3,276
212971433	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*TB36045V14***	23,400	\$3,276
212971776	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*TB48070V17***	23,400	\$3,276
212971787	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*TB48070V17***	23,200	\$3,248
212971798	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	82*TB48070V17***	23,600	\$3,304
212971809	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*TB48070V17***	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971853	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*TB48070V17***	23,400	\$3,276
212971864	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	82*TB48070V17***	23,600	\$3,304
212972032	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*TB48090V17***	23,400	\$3,276
212972036	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*TB48090V17***	23,200	\$3,248
212972044	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*TB48090V17***	23,200	\$3,248
212972060	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*TB48090V17***	23,400	\$3,276
212972064	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	82*TB48090V17***	23,600	\$3,304
212972165	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*TB60090V21***	23,200	\$3,248
212972176	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	82*TB60090V21***	23,600	\$3,304
212972187	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	82*TB60090V21***	23,600	\$3,304
212972198	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*TB60090V21***	23,200	\$3,248
212972220	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	82*TB60090V21***	23,600	\$3,304
212972447	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	82*TB66110V21***	23,400	\$3,276
212972459	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	82*TB66110V21***	23,400	\$3,276
212972471	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	82*TB66110V21***	23,400	\$3,276
212972483	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	82*TB66110V21***	23,200	\$3,248
212973643	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	926SB36060V14***	23,600	\$3,304
212973963	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	926SB48080V17***	23,400	\$3,276
212973973	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926SB48080V17***	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973993	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926SB48080V17***	23,200	\$3,248
212974033	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	926SB48080V17***	23,400	\$3,276
212974133	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926SB60080V21***	23,200	\$3,248
212974143	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	926SB60080V21***	23,400	\$3,276
212974153	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	926SB60080V21***	23,400	\$3,276
212974163	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926SB60080V21***	23,200	\$3,248
212974183	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	926SB60080V21***	23,600	\$3,304
212974353	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926SB60100V21***	23,200	\$3,248
212974363	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	926SB60100V21***	23,600	\$3,304
212974373	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	926SB60100V21***	23,600	\$3,304
212974383	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926SB60100V21***	23,200	\$3,248
212974403	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	926SB60100V21***	23,600	\$3,304
212974523	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	926SB66120V24***	23,600	\$3,304
212975761	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	926TC36060V14***	23,600	\$3,304
212976176	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	926TC48080V17***	23,400	\$3,276
212976189	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926TC48080V17***	23,400	\$3,276
212976215	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926TC48080V17***	23,200	\$3,248
212976267	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	926TC48080V17***	23,400	\$3,276
212976442	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926TC60080V21***	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976457	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	926TC60080V21***	23,400	\$3,276
212976470	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	926TC60080V21***	23,400	\$3,276
212976484	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926TC60080V21***	23,200	\$3,248
212976512	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	926TC60080V21***	23,600	\$3,304
212976716	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926TC60100V21***	23,200	\$3,248
212976729	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	926TC60100V21***	23,600	\$3,304
212976742	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	926TC60100V21***	23,600	\$3,304
212976755	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926TC60100V21***	23,200	\$3,248
212976781	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	926TC60100V21***	23,600	\$3,304
212977019	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	926TC66100V21***	23,200	\$3,248
212977029	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	926TC66100V21***	23,400	\$3,276
212977039	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	926TC66100V21***	23,400	\$3,276
212977049	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	926TC66100V21***	23,200	\$3,248
212977069	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	926TC66100V21***	23,400	\$3,276
212977240	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	926TC66120V24***	23,600	\$3,304
212977515	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	8(0,1)*SB36045M14***	23,400	\$3,276
212977551	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SB36045M14***	23,400	\$3,276
212978019	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	8(0,1)*SB36070M14***	23,400	\$3,276
212978067	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SB36070M14***	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978522	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	8(0,1)*SB36070M17***	23,400	\$3,276
212978533	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SB36070M17***	23,200	\$3,248
212978544	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SB36070M17***	23,400	\$3,276
212978555	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SB36070M17***	23,200	\$3,248
212978599	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SB36070M17***	23,400	\$3,276
212978610	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SB36070M17***	23,400	\$3,276
212979012	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	8(0,1)*SB48070M17***	23,400	\$3,276
212979024	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SB48070M17***	23,200	\$3,248
212979036	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SB48070M17***	23,600	\$3,304
212979048	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SB48070M17***	23,200	\$3,248
212979096	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SB48070M17***	23,400	\$3,276
212979108	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SB48070M17***	23,600	\$3,304
212979432	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SB48070M21***	23,200	\$3,248
212979442	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SB48070M21***	23,400	\$3,276
212979452	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SB48070M21***	23,400	\$3,276
212979462	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SB48070M21***	23,200	\$3,248
212979702	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	8(0,1)*SB42090M17***	23,400	\$3,276
212979714	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SB42090M17***	23,200	\$3,248
212979726	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SB42090M17***	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979738	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SB42090M17***	23,200	\$3,248
212979786	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	8(0,1)*SB42090M17***	23,400	\$3,276
212980190	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SB48090M21***	23,200	\$3,248
212980223	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SB48090M21***	23,200	\$3,248
212980245	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SB48090M21***	23,600	\$3,304
212980509	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SB60090M21***	23,200	\$3,248
212980520	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SB60090M21***	23,600	\$3,304
212980542	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SB60090M21***	23,200	\$3,248
212980564	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SB60090M21***	23,600	\$3,304
212980698	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SB60090M24***	23,600	\$3,304
212980899	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3621AL*	8(0,1)*SB60110M21***	23,600	\$3,304
212980911	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	8(0,1)*SB60110M21***	23,200	\$3,248
212980923	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	8(0,1)*SB60110M21***	23,600	\$3,304
212980935	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SB60110M21***	23,600	\$3,304
212980947	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	8(0,1)*SB60110M21***	23,200	\$3,248
212980971	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	8(0,1)*SB60110M21***	23,600	\$3,304
212981109	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SB60110M24***	23,400	\$3,276
212981218	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SB60135M24***	23,600	\$3,304
212981319	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	8(0,1)*SB60155M24***	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212981581	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	83*SB60100M21***	23,400	\$3,276
212981665	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	83*SB60100M21***	23,400	\$3,276
212982649	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	83*SB48060M17***	23,400	\$3,276
212983467	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	912SE36060M14***	23,400	\$3,276
212983497	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	912SE36060M14***	23,600	\$3,304
212983918	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	912SE42060M17***	23,400	\$3,276
212983930	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	912SE42060M17***	23,200	\$3,248
212983954	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	912SE42060M17***	23,200	\$3,248
212984002	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	912SE42060M17***	23,400	\$3,276
212984458	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	912SE48080M17***	23,400	\$3,276
212984470	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	912SE48080M17***	23,200	\$3,248
212984482	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	912SE48080M17***	23,400	\$3,276
212984494	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	912SE48080M17***	23,200	\$3,248
212984542	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	912SE48080M17***	23,400	\$3,276
212984970	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	912SE60080M21***	23,200	\$3,248
212984980	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	912SE60080M21***	23,400	\$3,276
212984990	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	912SE60080M21***	23,400	\$3,276
212985000	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	912SE60080M21***	23,200	\$3,248
212985020	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	912SE60080M21***	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212985264	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	912SE60100M21***	23,200	\$3,248
212985276	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	912SE60100M21***	23,400	\$3,276
212985288	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	912SE60100M21***	23,400	\$3,276
212985300	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	912SE60100M21***	23,600	\$3,304
212985324	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	912SE60100M21***	23,600	\$3,304
212985613	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	912SE60120M24***	23,400	\$3,276
212985744	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	916SA30026M14***	23,600	\$3,304
212986848	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	916SA36060M14***	23,600	\$3,304
212987256	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	916SA48080M17***	23,400	\$3,276
212987268	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	916SA48080M17***	23,200	\$3,248
212987292	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	916SA48080M17***	23,400	\$3,276
212987340	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	916SA48080M17***	23,600	\$3,304
212987352	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	916SA48080M17***	23,600	\$3,304
212987724	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	916SA60080M21***	23,200	\$3,248
212987748	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	916SA60080M21***	23,400	\$3,276
212987760	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	916SA60080M21***	23,200	\$3,248
212988330	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	916SA66120M24***	23,400	\$3,276
212988412	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	916SA66140M24***	23,600	\$3,304
212988578	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	935SB36040M17***	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988590	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	935SB36040M17***	23,200	\$3,248
212988614	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	935SB36040M17***	23,200	\$3,248
212988626	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	935SB36040M17***	23,600	\$3,304
212989022	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	935SB48060M17***	23,400	\$3,276
212989034	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	935SB48060M17***	23,200	\$3,248
212989046	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	935SB48060M17***	23,600	\$3,304
212989058	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	935SB48060M17***	23,200	\$3,248
212989106	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	935SB48060M17***	23,400	\$3,276
212989118	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	935SB48060M17***	23,600	\$3,304
212989526	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3721AL*	935SB60080M21***	23,200	\$3,248
212989538	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4221AL*	935SB60080M21***	23,600	\$3,304
212989550	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4224AL*	935SB60080M21***	23,600	\$3,304
212989562	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**4321AL*	935SB60080M21***	23,200	\$3,248
212989586	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4221AL*	935SB60080M21***	23,600	\$3,304
213249291	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FEVA0036**+NAVA43601CK		23,600	\$3,304
213353808	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	F54AA*B30L*		23,400	\$3,276
213353818	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	F54AA*B36L*		23,600	\$3,304
210450239	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	926TB48080V17***	29,600	\$4,144
210450240	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	926TB36060V14***	29,800	\$4,172

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210450242	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926TB48080V17***	29,600	\$4,144
210450244	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926TB48080V17***	29,400	\$4,116
210450245	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926TB36060V14***	29,600	\$4,144
210450247	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926TB48080V17***	29,200	\$4,088
210450249	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4321AL*	926TB48080V17***	29,200	\$4,088
210450251	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4821AL*	926TB48080V17***	29,000	\$4,060
210450258	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	926TB48080V17***	29,400	\$4,116
210450259	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	926TB36060V14***	29,600	\$4,144
210450261	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4221AL*	926TB48080V17***	29,400	\$4,116
210450263	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4821AL*	926TB48080V17***	29,200	\$4,088
211225660	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FJ4DN*B36L*		29,400	\$4,116
211226259	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SA36045E17***	29,600	\$4,144
211226271	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SA36070E17***	29,600	\$4,144
211226283	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	8(0,1)*SA60110E21***	29,400	\$4,116
211226295	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*SA48045V17***	29,600	\$4,144
211226304	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	83*SA60100E21***	29,400	\$4,116
211226315	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	82*TA48090V17***	29,400	\$4,116
211226326	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SD42060E17***	29,400	\$4,116
211226337	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	912SD66100E21***	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226346	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	915SB42060E17***	29,400	\$4,116
211226357	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	915SB48080E17***	29,400	\$4,116
211226368	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	915SB60100E21***	29,600	\$4,144
211226379	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	915SB66100E21***	29,600	\$4,144
211226388	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	935SA48060E17***	29,400	\$4,116
211226399	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926TB60080V21***	29,400	\$4,116
211226409	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926TB60100V21***	29,600	\$4,144
211226419	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	926TB66100V21***	29,400	\$4,116
211226428	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	OVLAAB036098	29,600	\$4,144
211226437	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	OVLAAB048112	29,600	\$4,144
211226446	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	OVMAAB036098	29,600	\$4,144
211226455	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3621AL*	OVMAAB042112	29,600	\$4,144
211226482	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SA36045E14***	29,400	\$4,116
211226494	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SA36070E14***	29,200	\$4,088
211226506	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SA36070E17***	29,400	\$4,116
211226518	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SA48070E17***	29,400	\$4,116
211226529	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	8(0,1)*SA42090E17***	29,200	\$4,088
211226541	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*SA36045V14***	29,400	\$4,116
211226550	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*SA48045V17***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226559	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*SA48070V17***	29,400	\$4,116
211226579	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*TA36045V14***	29,400	\$4,116
211226589	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*TA36070V14***	29,200	\$4,088
211226591	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*TA48070V17***	29,400	\$4,116
211226601	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*TA48090V17***	29,200	\$4,088
211226612	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	912SD36060E14***	29,400	\$4,116
211226623	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	912SD42060E17***	29,200	\$4,088
211226634	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	912SD48080E17***	29,400	\$4,116
211226656	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	915SB42060E17***	29,400	\$4,116
211226667	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926SA36060V14***	29,400	\$4,116
211226676	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926SA42060V17***	29,400	\$4,116
211226685	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926SA48080V17***	29,400	\$4,116
211226694	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	935SA48060E17***	29,400	\$4,116
211226705	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	926TB42060V17***	29,400	\$4,116
211226715	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	OVLAAB036098	29,400	\$4,116
211226724	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	OVMAAB036098	29,400	\$4,116
211226733	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	OVMAAB042112	29,400	\$4,116
211226790	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SA36070E17***	29,200	\$4,088
211226802	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SA48070E21***	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226814	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SA42090E17***	29,200	\$4,088
211226826	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SA48090E21***	29,000	\$4,060
211226838	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SA60090E21***	29,200	\$4,088
211226850	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	8(0,1)*SA60110E21***	29,200	\$4,088
211226862	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*SA48045V17***	29,200	\$4,088
211226871	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*SA48070V17***	29,200	\$4,088
211226880	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*SA60070V21***	29,000	\$4,060
211226889	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*SA60090V21***	29,000	\$4,060
211226898	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	83*SA36040E17***	29,400	\$4,116
211226909	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	83*SA48060E17***	29,200	\$4,088
211226920	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	83*SA60080E21***	29,400	\$4,116
211226931	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	83*SA60100E21***	29,000	\$4,060
211226942	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*TA48070V17***	29,000	\$4,060
211226952	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*TA48090V17***	29,000	\$4,060
211226954	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	82*TA66110V21***	29,200	\$4,088
211226991	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SD42060E17***	29,000	\$4,060
211227002	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SD48080E17***	29,000	\$4,060
211227013	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SD60080E21***	29,200	\$4,088
211227024	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	912SD66100E21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227033	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	915SB42060E17***	29,400	\$4,116
211227055	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	915SB60080E21***	29,200	\$4,088
211227066	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	915SB60100E21***	29,200	\$4,088
211227077	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	915SB66100E21***	29,200	\$4,088
211227095	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926SA42060V17***	29,200	\$4,088
211227104	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926SA48080V17***	29,200	\$4,088
211227113	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926SA60080V21***	29,000	\$4,060
211227122	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926SA60100V21***	29,000	\$4,060
211227131	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	935SA60080E21***	29,400	\$4,116
211227142	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	935SA60100E21***	29,000	\$4,060
211227153	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	935SA66100E21***	29,200	\$4,088
211227172	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926TB42060V17***	29,200	\$4,088
211227182	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926TB60080V21***	29,200	\$4,088
211227192	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926TB60100V21***	29,200	\$4,088
211227202	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	926TB66100V21***	29,000	\$4,060
211227211	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	OVLAAB036098	29,200	\$4,088
211227220	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	OVLAAB048112	29,200	\$4,088
211227229	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	OVMAAB036098	29,200	\$4,088
211227238	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3721AL*	OVMAAB042112	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227283	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SA36045E17***	29,400	\$4,116
211227295	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SA36070E17***	29,400	\$4,116
211227307	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SA48070E17***	29,400	\$4,116
211227318	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SA48070E21***	29,400	\$4,116
211227330	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SA42090E17***	29,400	\$4,116
211227342	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SA48090E21***	29,400	\$4,116
211227354	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SA60090E21***	29,400	\$4,116
211227366	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	8(0,1)*SA60110E21***	29,400	\$4,116
211227378	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*SA48045V17***	29,400	\$4,116
211227387	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*SA48070V17***	29,400	\$4,116
211227396	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*SA60070V21***	29,400	\$4,116
211227405	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*SA60090V21***	29,400	\$4,116
211227425	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	83*SA48060E17***	29,200	\$4,088
211227436	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	83*SA60080E21***	29,600	\$4,144
211227447	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	83*SA60100E21***	29,400	\$4,116
211227458	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*TA48070V17***	29,400	\$4,116
211227468	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*TA48090V17***	29,400	\$4,116
211227470	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*TA60090V21***	29,400	\$4,116
211227480	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	82*TA66110V21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227508	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SD42060E17***	29,400	\$4,116
211227519	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SD48080E17***	29,400	\$4,116
211227530	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SD60080E21***	29,200	\$4,088
211227541	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SD60100E21***	29,200	\$4,088
211227552	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	912SD66100E21***	29,600	\$4,144
211227561	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	915SB42060E17***	29,400	\$4,116
211227572	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	915SB60080E21***	29,400	\$4,116
211227583	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	915SB66100E21***	29,600	\$4,144
211227592	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926SA42060V17***	29,400	\$4,116
211227601	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926SA48080V17***	29,400	\$4,116
211227610	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926SA60080V21***	29,400	\$4,116
211227619	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926SA60100V21***	29,400	\$4,116
211227628	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	935SA48060E17***	29,400	\$4,116
211227639	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	935SA60080E21***	29,600	\$4,144
211227650	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	935SA60100E21***	29,400	\$4,116
211227661	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	935SA66100E21***	29,600	\$4,144
211227670	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926TB42060V17***	29,600	\$4,144
211227680	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926TB48080V17***	29,400	\$4,116
211227690	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926TB60080V21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227700	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926TB60100V21***	29,400	\$4,116
211227710	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	926TB66100V21***	29,200	\$4,088
211227719	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	OVLAAB036098	29,400	\$4,116
211227728	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	OVMAAB036098	29,400	\$4,116
211227737	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4221AL*	OVMAAB042112	29,400	\$4,116
211227764	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SA48070E21***	29,400	\$4,116
211227776	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SA48090E21***	29,400	\$4,116
211227788	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SA60090E21***	29,400	\$4,116
211227800	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SA60090E24***	29,400	\$4,116
211227812	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SA60110E21***	29,400	\$4,116
211227824	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SA60110E24***	29,200	\$4,088
211227836	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SA60135E24***	29,400	\$4,116
211227848	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	8(0,1)*SA60155E24***	29,400	\$4,116
211227858	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*SA60070V21***	29,400	\$4,116
211227867	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*SA60090V21***	29,400	\$4,116
211227876	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*SA60090V24***	29,400	\$4,116
211227885	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*SA66110V24***	29,200	\$4,088
211227894	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	83*SA60080E21***	29,600	\$4,144
211227905	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	83*SA60100E21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227916	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*TA60090V21***	29,400	\$4,116
211227926	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*TA66110V21***	29,400	\$4,116
211227936	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	82*TA66135V24***	29,400	\$4,116
211227956	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	912SD60080E21***	29,200	\$4,088
211227967	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	912SD60100E21***	29,200	\$4,088
211227978	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	912SD66100E21***	29,600	\$4,144
211227987	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	912SD60120E24***	29,400	\$4,116
211227998	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	915SB60080E21***	29,400	\$4,116
211228009	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	915SB60100E21***	29,400	\$4,116
211228020	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	915SB66100E21***	29,600	\$4,144
211228029	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	915SB66120E24***	29,600	\$4,144
211228040	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	915SB66140E24***	29,600	\$4,144
211228051	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926SA60080V21***	29,400	\$4,116
211228060	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926SA60100V21***	29,400	\$4,116
211228069	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926SA66120V24***	29,400	\$4,116
211228078	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	935SA60080E21***	29,600	\$4,144
211228089	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	935SA60100E21***	29,400	\$4,116
211228100	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	935SA66100E21***	29,600	\$4,144
211228109	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926TB60080V21***	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228119	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926TB60100V21***	29,400	\$4,116
211228129	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926TB66100V21***	29,200	\$4,088
211228138	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	926TB66120V24***	29,400	\$4,116
211228148	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	OVLAAB048112	29,400	\$4,116
211228157	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**4224AL*	OVLAAB060154	29,600	\$4,144
213353778	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	F54AA*B30L*		19,100	\$2,674
213353768	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	F54AA*B24L*		19,300	\$2,702
213249269	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076397	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TC48060V17***	19,400	\$2,716
213076371	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TC48060V17***	19,400	\$2,716
213076361	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	935SB66100M21***	19,100	\$2,674
213076343	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	935SB66100M21***	19,000	\$2,660
213076115	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	935SB60100M21***	19,200	\$2,688
212989622	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	935SB60080M21***	19,100	\$2,674
212989610	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	935SB60080M21***	18,600	\$2,604
212989598	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	935SB60080M21***	19,100	\$2,674
212989250	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	935SB48060M17***	19,100	\$2,674
212989238	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	935SB48060M17***	19,100	\$2,674
212989226	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	935SB48060M17***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989214	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	935SB48060M17***	19,400	\$2,716
212989202	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	935SB48060M17***	18,700	\$2,618
212989190	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	935SB48060M17***	18,900	\$2,646
212989178	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	935SB48060M17***	19,100	\$2,674
212989166	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	935SB48060M17***	19,100	\$2,674
212989154	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	935SB48060M17***	19,100	\$2,674
212989142	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	935SB48060M17***	18,600	\$2,604
212989130	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	935SB48060M17***	19,400	\$2,716
212988758	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	935SB36040M17***	19,200	\$2,688
212988746	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	935SB36040M17***	19,200	\$2,688
212988734	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	935SB36040M17***	19,200	\$2,688
212988722	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	935SB36040M17***	19,500	\$2,730
212988710	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	935SB36040M17***	18,600	\$2,604
212988698	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	935SB36040M17***	18,800	\$2,632
212988686	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	935SB36040M17***	19,000	\$2,660
212988674	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	935SB36040M17***	19,100	\$2,674
212988662	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	935SB36040M17***	19,200	\$2,688
212988650	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	935SB36040M17***	18,700	\$2,618
212988638	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	935SB36040M17***	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212987820	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	916SA60080M21***	19,100	\$2,674
212987808	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	916SA60080M21***	18,700	\$2,618
212987796	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	916SA60080M21***	19,100	\$2,674
212987484	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	916SA48080M17***	19,200	\$2,688
212987472	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	916SA48080M17***	19,200	\$2,688
212987460	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	916SA48080M17***	19,200	\$2,688
212987448	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	916SA48080M17***	19,500	\$2,730
212987436	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	916SA48080M17***	19,800	\$2,772
212987424	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	916SA48080M17***	18,800	\$2,632
212987412	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	916SA48080M17***	19,000	\$2,660
212987400	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	916SA48080M17***	19,100	\$2,674
212987388	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	916SA48080M17***	19,200	\$2,688
212987376	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	916SA48080M17***	18,700	\$2,618
212987364	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	916SA48080M17***	19,400	\$2,716
212986968	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	916SA36060M14***	19,200	\$2,688
212986958	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	916SA36060M14***	19,200	\$2,688
212986948	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	916SA36060M14***	19,200	\$2,688
212986938	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	916SA36060M14***	19,500	\$2,730
212986928	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	916SA36060M14***	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986918	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	916SA36060M14***	18,800	\$2,632
212986908	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	916SA36060M14***	19,100	\$2,674
212986898	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	916SA36060M14***	19,100	\$2,674
212986888	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	916SA36060M14***	19,200	\$2,688
212986878	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	916SA36060M14***	18,700	\$2,618
212986868	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	916SA36060M14***	19,400	\$2,716
212986858	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	916SA36060M14***	19,400	\$2,716
212986644	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	916SA36040M17***	19,100	\$2,674
212986632	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	916SA36040M17***	19,100	\$2,674
212986620	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	916SA36040M17***	19,100	\$2,674
212986608	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	916SA36040M17***	19,700	\$2,758
211289628	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ60AB3*	FV4CNB006L		37,800	\$5,292
213607738	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	PF4TNXC48L*		28,800	\$4,032
213607737	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FG4ANXC48L*		28,800	\$4,032
213607736	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FT4BN(B,X)C48L*		28,800	\$4,032
213607723	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	PF4TNXC36L*		29,400	\$4,116
213607722	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FG4ANXC36L*		29,400	\$4,116
213607721	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FT4BN(B,X)C36L*		29,400	\$4,116
213607678	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	PF4TNXC36L*		23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213607677	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FG4ANXC36L*		23,600	\$3,304
213607676	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FT4BN(B,X)C36L*		23,600	\$3,304
213607648	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	PF4TNXB24L*		19,300	\$2,702
213607647	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FG4ANXB24L*		19,300	\$2,702
213607646	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FT4BNXB24L*		19,300	\$2,702
213607633	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	PF4TNXC36L*		19,100	\$2,674
213607632	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FG4ANXC36L*		19,100	\$2,674
213607631	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FT4BN(B,X)C36L*		19,100	\$2,674
213607588	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	PF4TNXB24L*		12,400	\$1,736
213607587	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FG4ANXB24L*		12,400	\$1,736
213607586	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FT4BNXB24L*		12,400	\$1,736
212986596	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	916SA36040M17***	18,800	\$2,632
212986584	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	916SA36040M17***	19,000	\$2,660
212986572	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	916SA36040M17***	19,200	\$2,688
212986560	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	916SA36040M17***	19,200	\$2,688
212986548	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	916SA36040M17***	19,200	\$2,688
212986536	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	916SA36040M17***	18,900	\$2,646
212986524	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	916SA36040M17***	19,500	\$2,730
212986260	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	916SA30040M14***	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986140	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	916SA30040M14***	19,500	\$2,730
212986128	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	916SA30040M14***	19,500	\$2,730
212985864	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	916SA30026M14***	19,000	\$2,660
212985854	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	916SA30026M14***	19,000	\$2,660
212985844	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	916SA30026M14***	19,100	\$2,674
212985834	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	916SA30026M14***	19,500	\$2,730
212985824	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	916SA30026M14***	19,500	\$2,730
212985814	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	916SA30026M14***	18,800	\$2,632
212985804	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	916SA30026M14***	19,100	\$2,674
212985794	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	916SA30026M14***	19,100	\$2,674
212985784	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	916SA30026M14***	19,200	\$2,688
212985774	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	916SA30026M14***	18,700	\$2,618
212985764	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	916SA30026M14***	19,500	\$2,730
212985754	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	916SA30026M14***	19,500	\$2,730
212985360	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SE60100M21***	19,100	\$2,674
212985348	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	912SE60100M21***	18,700	\$2,618
212985336	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SE60100M21***	19,100	\$2,674
212985050	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SE60080M21***	19,000	\$2,660
212985040	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	912SE60080M21***	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212985030	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SE60080M21***	19,000	\$2,660
212984686	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SE48080M17***	19,100	\$2,674
212984674	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	912SE48080M17***	19,100	\$2,674
212984662	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	912SE48080M17***	19,100	\$2,674
212984650	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	912SE48080M17***	19,500	\$2,730
212984638	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	912SE48080M17***	18,400	\$2,576
212984626	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	912SE48080M17***	18,900	\$2,646
212984614	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SE48080M17***	19,000	\$2,660
212984602	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	912SE48080M17***	19,000	\$2,660
212984590	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	912SE48080M17***	19,100	\$2,674
212984578	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	912SE48080M17***	18,500	\$2,590
212984566	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	912SE48080M17***	19,300	\$2,702
212984146	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SE42060M17***	19,100	\$2,674
212984134	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	912SE42060M17***	19,100	\$2,674
212984122	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	912SE42060M17***	19,100	\$2,674
212984110	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	912SE42060M17***	19,400	\$2,716
212984098	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	912SE42060M17***	18,700	\$2,618
212984086	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	912SE42060M17***	18,900	\$2,646
212984074	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SE42060M17***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984062	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	912SE42060M17***	19,100	\$2,674
212984050	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	912SE42060M17***	19,100	\$2,674
212984038	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	912SE42060M17***	18,700	\$2,618
212984026	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	912SE42060M17***	19,400	\$2,716
212983617	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	912SE36060M14***	19,200	\$2,688
212983607	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	912SE36060M14***	19,200	\$2,688
212983597	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	912SE36060M14***	19,200	\$2,688
212983587	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	912SE36060M14***	19,500	\$2,730
212983577	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	912SE36060M14***	19,500	\$2,730
212983567	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	912SE36060M14***	19,000	\$2,660
212983557	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	912SE36060M14***	19,200	\$2,688
212983547	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	912SE36060M14***	19,200	\$2,688
212983537	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	912SE36060M14***	19,200	\$2,688
212983527	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	912SE36060M14***	18,800	\$2,632
212983517	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	912SE36060M14***	19,500	\$2,730
212983507	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	912SE36060M14***	19,500	\$2,730
212983240	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SE36040M17***	19,200	\$2,688
212983229	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	912SE36040M17***	19,200	\$2,688
212983218	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	912SE36040M17***	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983207	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	912SE36040M17***	19,600	\$2,744
212983196	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	912SE36040M17***	18,800	\$2,632
212983185	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	912SE36040M17***	19,000	\$2,660
212983174	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SE36040M17***	19,200	\$2,688
212983163	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	912SE36040M17***	19,200	\$2,688
212983152	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	912SE36040M17***	19,300	\$2,702
212983141	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	912SE36040M17***	18,800	\$2,632
212983130	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	912SE36040M17***	19,500	\$2,730
212981809	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	83*SB60100M21***	19,100	\$2,674
212981797	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	83*SB60100M21***	19,200	\$2,688
212981785	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	83*SB60100M21***	19,200	\$2,688
212981773	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	83*SB60100M21***	19,500	\$2,730
212981749	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	83*SB60100M21***	18,800	\$2,632
212981737	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	83*SB60100M21***	19,100	\$2,674
212981725	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	83*SB60100M21***	19,000	\$2,660
212981713	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	83*SB60100M21***	19,100	\$2,674
212981701	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	83*SB60100M21***	18,700	\$2,618
212981689	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	83*SB60100M21***	19,500	\$2,730
212981007	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SB60110M21***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980995	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	8(0,1)*SB60110M21***	18,800	\$2,632
212980983	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SB60110M21***	19,000	\$2,660
212980597	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SB60090M21***	19,100	\$2,674
212980586	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	8(0,1)*SB60090M21***	18,600	\$2,604
212980575	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SB60090M21***	19,100	\$2,674
212980278	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SB48090M21***	19,100	\$2,674
212980267	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	8(0,1)*SB48090M21***	18,600	\$2,604
212980256	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SB48090M21***	19,000	\$2,660
212979930	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SB42090M17***	19,100	\$2,674
212979918	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SB42090M17***	19,100	\$2,674
212979906	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SB42090M17***	19,100	\$2,674
212979894	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SB42090M17***	19,500	\$2,730
212979882	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	8(0,1)*SB42090M17***	18,700	\$2,618
212979870	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	8(0,1)*SB42090M17***	18,700	\$2,618
212979858	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SB42090M17***	19,100	\$2,674
212979846	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SB42090M17***	19,100	\$2,674
212979834	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SB42090M17***	19,100	\$2,674
212979822	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	8(0,1)*SB42090M17***	18,600	\$2,604
212979810	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SB42090M17***	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979512	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SB48070M21***	19,200	\$2,688
212979502	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	8(0,1)*SB48070M21***	18,600	\$2,604
212979492	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SB48070M21***	19,100	\$2,674
212979240	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SB48070M17***	19,100	\$2,674
212979228	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SB48070M17***	19,100	\$2,674
212979216	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SB48070M17***	19,100	\$2,674
212979204	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SB48070M17***	19,400	\$2,716
212979192	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	8(0,1)*SB48070M17***	18,700	\$2,618
212979180	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	8(0,1)*SB48070M17***	18,700	\$2,618
212979168	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SB48070M17***	19,100	\$2,674
212979156	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SB48070M17***	19,100	\$2,674
212979144	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SB48070M17***	19,100	\$2,674
212979132	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	8(0,1)*SB48070M17***	18,700	\$2,618
212978643	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SB36070M17***	19,000	\$2,660
212978632	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	8(0,1)*SB36070M17***	18,600	\$2,604
212978621	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SB36070M17***	19,400	\$2,716
212978211	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SB36070M14***	19,000	\$2,660
212978199	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SB36070M14***	19,000	\$2,660
212978187	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	8(0,1)*SB36070M14***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978175	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SB36070M14***	19,400	\$2,716
212978163	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	8(0,1)*SB36070M14***	19,400	\$2,716
212978151	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	8(0,1)*SB36070M14***	18,700	\$2,618
212978139	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SB36070M14***	19,000	\$2,660
212978127	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SB36070M14***	19,100	\$2,674
212978115	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	8(0,1)*SB36070M14***	19,100	\$2,674
212978103	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	8(0,1)*SB36070M14***	18,600	\$2,604
212978091	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SB36070M14***	19,400	\$2,716
212978079	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	8(0,1)*SB36070M14***	19,300	\$2,702
212977695	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SB36045M14***	19,100	\$2,674
212977683	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SB36045M14***	19,100	\$2,674
212977671	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	8(0,1)*SB36045M14***	19,000	\$2,660
212977659	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SB36045M14***	19,500	\$2,730
212977647	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	8(0,1)*SB36045M14***	19,500	\$2,730
212977635	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	8(0,1)*SB36045M14***	18,700	\$2,618
212977623	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SB36045M14***	19,100	\$2,674
212977611	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SB36045M14***	19,100	\$2,674
212977599	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	8(0,1)*SB36045M14***	19,100	\$2,674
212977587	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	8(0,1)*SB36045M14***	18,700	\$2,618

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212977575	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SB36045M14***	19,400	\$2,716
212977563	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	8(0,1)*SB36045M14***	19,400	\$2,716
212976999	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TC66100V21***	19,200	\$2,688
212976979	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TC66100V21***	19,100	\$2,674
212976690	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TC60100V21***	19,100	\$2,674
212976677	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926TC60100V21***	18,600	\$2,604
212976664	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TC60100V21***	19,000	\$2,660
212976414	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TC60080V21***	19,200	\$2,688
212976401	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926TC60080V21***	18,600	\$2,604
212976387	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TC60080V21***	19,100	\$2,674
212976124	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TC48080V17***	18,900	\$2,646
212976111	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926TC48080V17***	18,900	\$2,646
212976098	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926TC48080V17***	18,900	\$2,646
212976085	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TC48080V17***	19,500	\$2,730
212976059	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926TC48080V17***	19,000	\$2,660
212976046	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TC48080V17***	19,000	\$2,660
212976033	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926TC48080V17***	19,000	\$2,660
212976020	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926TC48080V17***	19,100	\$2,674
212976007	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926TC48080V17***	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975994	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TC48080V17***	19,500	\$2,730
212975750	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926TC36060V14***	19,100	\$2,674
212975739	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926TC36060V14***	19,100	\$2,674
212975728	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	926TC36060V14***	19,000	\$2,660
212975717	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TC36060V14***	19,500	\$2,730
212975706	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	926TC36060V14***	19,500	\$2,730
212975695	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926TC36060V14***	18,800	\$2,632
212975684	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926TC36060V14***	19,100	\$2,674
212975673	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926TC36060V14***	19,100	\$2,674
212975662	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	926TC36060V14***	19,100	\$2,674
212975651	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926TC36060V14***	18,600	\$2,604
212975640	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TC36060V14***	19,400	\$2,716
212975629	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	926TC36060V14***	19,400	\$2,716
212975365	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TC36040V17***	19,200	\$2,688
212975354	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926TC36040V17***	19,200	\$2,688
212975343	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926TC36040V17***	19,200	\$2,688
212975332	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TC36040V17***	19,600	\$2,744
212975321	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926TC36040V17***	18,900	\$2,646
212975310	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926TC36040V17***	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975299	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TC36040V17***	19,100	\$2,674
212975288	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926TC36040V17***	19,100	\$2,674
212975277	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926TC36040V17***	19,200	\$2,688
212975266	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926TC36040V17***	18,800	\$2,632
212975255	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TC36040V17***	19,500	\$2,730
212975056	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926TC30040V14***	19,200	\$2,688
212975043	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926TC30040V14***	19,200	\$2,688
212975030	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	926TC30040V14***	19,100	\$2,674
212975017	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TC30040V14***	19,600	\$2,744
212975004	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	926TC30040V14***	19,600	\$2,744
212974991	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926TC30040V14***	18,800	\$2,632
212974978	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926TC30040V14***	19,200	\$2,688
212974965	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926TC30040V14***	19,200	\$2,688
212974952	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	926TC30040V14***	19,200	\$2,688
212974939	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926TC30040V14***	18,700	\$2,618
212974926	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TC30040V14***	19,500	\$2,730
212974913	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	926TC30040V14***	19,500	\$2,730
212974323	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926SB60100V21***	18,900	\$2,646
212974313	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926SB60100V21***	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974113	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926SB60080V21***	19,200	\$2,688
212974103	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926SB60080V21***	18,600	\$2,604
212974093	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926SB60080V21***	19,100	\$2,674
212973923	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926SB48080V17***	18,900	\$2,646
212973913	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926SB48080V17***	18,900	\$2,646
212973903	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926SB48080V17***	18,900	\$2,646
212973893	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926SB48080V17***	19,500	\$2,730
212973873	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926SB48080V17***	19,000	\$2,660
212973863	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926SB48080V17***	19,000	\$2,660
212973853	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926SB48080V17***	19,000	\$2,660
212973843	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926SB48080V17***	19,100	\$2,674
212973833	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926SB48080V17***	18,800	\$2,632
212973823	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926SB48080V17***	19,500	\$2,730
212973633	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926SB36060V14***	19,100	\$2,674
212973623	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926SB36060V14***	19,100	\$2,674
212973613	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	926SB36060V14***	19,000	\$2,660
212973603	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926SB36060V14***	19,500	\$2,730
212973593	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	926SB36060V14***	19,500	\$2,730
212973583	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926SB36060V14***	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973573	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926SB36060V14***	19,100	\$2,674
212973563	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926SB36060V14***	19,100	\$2,674
212973553	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	926SB36060V14***	19,100	\$2,674
212973543	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926SB36060V14***	18,600	\$2,604
212973533	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926SB36060V14***	19,400	\$2,716
212973523	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	926SB36060V14***	19,400	\$2,716
212973283	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926SB36040V17***	19,200	\$2,688
212973273	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926SB36040V17***	19,200	\$2,688
212973263	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926SB36040V17***	19,200	\$2,688
212973253	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926SB36040V17***	19,600	\$2,744
212973243	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926SB36040V17***	18,900	\$2,646
212973233	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926SB36040V17***	18,900	\$2,646
212973223	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926SB36040V17***	19,100	\$2,674
212973213	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926SB36040V17***	19,100	\$2,674
212973203	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926SB36040V17***	19,200	\$2,688
212973193	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926SB36040V17***	18,800	\$2,632
212973183	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926SB36040V17***	19,500	\$2,730
212973003	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926SB30040V14***	19,200	\$2,688
212972993	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926SB30040V14***	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972983	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	926SB30040V14***	19,200	\$2,688
212972973	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926SB30040V14***	19,500	\$2,730
212972963	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	926SB30040V14***	19,500	\$2,730
212972953	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926SB30040V14***	19,000	\$2,660
212972943	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926SB30040V14***	19,200	\$2,688
212972933	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926SB30040V14***	19,200	\$2,688
212972923	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	926SB30040V14***	19,200	\$2,688
212972913	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926SB30040V14***	18,800	\$2,632
212972903	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926SB30040V14***	19,500	\$2,730
212972893	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	926SB30040V14***	19,500	\$2,730
212972423	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*TB66110V21***	19,200	\$2,688
212972411	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	82*TB66110V21***	18,800	\$2,632
212972399	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*TB66110V21***	19,100	\$2,674
212972143	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*TB60090V21***	19,100	\$2,674
212972132	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	82*TB60090V21***	18,900	\$2,646
212972121	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*TB60090V21***	19,100	\$2,674
212972016	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*TB48090V17***	19,100	\$2,674
212972012	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*TB48090V17***	19,100	\$2,674
212972008	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*TB48090V17***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972004	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*TB48090V17***	19,500	\$2,730
212972000	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	82*TB48090V17***	18,600	\$2,604
212971996	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*TB48090V17***	18,800	\$2,632
212971992	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*TB48090V17***	19,000	\$2,660
212971988	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*TB48090V17***	19,000	\$2,660
212971984	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*TB48090V17***	19,100	\$2,674
212971980	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	82*TB48090V17***	18,700	\$2,618
212971976	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*TB48090V17***	19,400	\$2,716
212971732	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*TB48070V17***	19,100	\$2,674
212971721	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*TB48070V17***	19,100	\$2,674
212971710	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*TB48070V17***	19,100	\$2,674
212971699	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*TB48070V17***	19,500	\$2,730
212971688	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	82*TB48070V17***	18,700	\$2,618
212971677	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*TB48070V17***	18,700	\$2,618
212971666	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*TB48070V17***	19,100	\$2,674
212971655	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*TB48070V17***	19,100	\$2,674
212971644	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*TB48070V17***	19,100	\$2,674
212971633	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	82*TB48070V17***	18,600	\$2,604
212971622	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*TB48070V17***	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971417	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*TB36045V14***	19,100	\$2,674
212971415	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*TB36045V14***	19,100	\$2,674
212971413	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	82*TB36045V14***	19,100	\$2,674
212971411	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*TB36045V14***	19,400	\$2,716
212971409	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	82*TB36045V14***	19,400	\$2,716
212971407	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*TB36045V14***	18,700	\$2,618
212971405	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*TB36045V14***	19,100	\$2,674
212971403	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*TB36045V14***	19,100	\$2,674
212971401	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	82*TB36045V14***	19,000	\$2,660
212971399	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	82*TB36045V14***	18,600	\$2,604
212971397	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*TB36045V14***	19,400	\$2,716
212971395	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	82*TB36045V14***	19,400	\$2,716
212969837	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*SB36045V14***	19,100	\$2,674
212969827	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*SB36045V14***	19,100	\$2,674
212969817	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	82*SB36045V14***	19,000	\$2,660
212969807	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*SB36045V14***	19,500	\$2,730
212969797	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	82*SB36045V14***	19,500	\$2,730
212969787	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*SB36045V14***	18,700	\$2,618
212969777	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*SB36045V14***	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212969767	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*SB36045V14***	19,100	\$2,674
212969757	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	82*SB36045V14***	19,100	\$2,674
212969747	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	82*SB36045V14***	18,500	\$2,590
212969737	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*SB36045V14***	19,300	\$2,702
211727051	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	PF4MN*B24L*		19,200	\$2,688
211245980	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FV4CN(B,F)003L		19,000	\$2,660
211245970	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FV4CNF002L		19,000	\$2,660
211245959	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FM(C,U)4Z36**AL*		19,300	\$2,702
211245948	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FM(C,U)4Z30**AL*		19,300	\$2,702
211245937	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FM(C,U)4Z24**AL*		19,500	\$2,730
211245926	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FM(C,U)4X36**AL*		19,900	\$2,786
211245915	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FM(C,U)4X30**AL*		19,900	\$2,786
211245904	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FMA4X36**AL*		19,600	\$2,744
211245893	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FMA4X30**AL*		19,600	\$2,744
211245882	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FMA4X24**AL*		19,600	\$2,744
211245860	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FMA4P24**AL*		19,900	\$2,786
211245849	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FX4DN(B,F)037L		18,500	\$2,590
211245838	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FX4DNF031L		19,100	\$2,674
211245827	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FX4DNF025L		19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245815	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FB4CNP030L		19,100	\$2,674
211245803	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FB4CNP025L		19,000	\$2,660
211245792	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FB4CNF030L		19,100	\$2,674
211245791	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FZ4ANP036L		19,000	\$2,660
211245782	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	OVLAAB048112	19,300	\$2,702
211245773	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	OVMAAB042112	19,200	\$2,688
211245764	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	OVLAAB036098	18,900	\$2,646
211245755	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	OVMAAB036098	19,000	\$2,660
211245744	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	83*SA48060E17***	19,300	\$2,702
211245733	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	83*SA60080E21***	19,100	\$2,674
211245722	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SD36040E17***	19,100	\$2,674
211245711	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	915SB48080E17***	19,500	\$2,730
211245700	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	915SB42060E17***	19,400	\$2,716
211245689	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SD60100E21***	19,300	\$2,702
211245678	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SD60080E21***	19,300	\$2,702
211245667	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SD48080E17***	19,100	\$2,674
211245656	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	912SD42060E17***	19,100	\$2,674
211245644	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SA60110E21***	19,400	\$2,716
211245632	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SA60090E21***	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245620	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SA42090E17***	19,200	\$2,688
211245608	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SA48070E21***	19,100	\$2,674
211245596	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SA36070E17***	19,200	\$2,688
211245584	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SA36045E17***	19,100	\$2,674
211245574	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*TA66110V21***	19,000	\$2,660
211245564	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TB60100V21***	19,000	\$2,660
211245554	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TB60080V21***	18,900	\$2,646
211245544	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TB42060V17***	19,100	\$2,674
211245533	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	915SB36040E17***	19,400	\$2,716
211245523	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*TA48070V17***	19,100	\$2,674
211245513	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TB48080V17***	19,100	\$2,674
211245502	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	915SB60080E21***	19,300	\$2,702
211245492	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TB36040V17***	19,000	\$2,660
211245482	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*TA60090V21***	19,000	\$2,660
211245480	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*TA48090V17***	19,000	\$2,660
211245469	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	83*SA36040E17***	19,000	\$2,660
211245458	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	935SA48060E17***	19,100	\$2,674
211245449	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*SA60090V21***	19,000	\$2,660
211245440	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*SA60070V21***	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245431	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*SA48070V17***	19,000	\$2,660
211245422	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	82*SA48045V17***	19,200	\$2,688
211245377	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926TB66100V21***	18,900	\$2,646
211245366	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SA48070E17***	19,400	\$2,716
211245355	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	935SA36040E17***	19,000	\$2,660
211245346	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926SA48080V17***	19,100	\$2,674
211245337	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926SA36040V17***	19,000	\$2,660
211245328	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926SA60100V21***	19,000	\$2,660
211245319	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926SA60080V21***	19,000	\$2,660
211245310	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	926SA42060V17***	18,900	\$2,646
211245274	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	OVMAAB042112	19,200	\$2,688
211245265	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	OVLAAB036098	18,900	\$2,646
211245256	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	OVMAAB036098	19,000	\$2,660
211245245	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	83*SA48060E17***	19,300	\$2,702
211245233	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SA36070E14***	19,100	\$2,674
211245222	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	912SD36040E17***	19,100	\$2,674
211245211	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	912SD30040E14***	19,400	\$2,716
211245200	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	915SB48080E17***	19,500	\$2,730
211245189	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	915SB42060E17***	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245178	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	912SD48080E17***	19,100	\$2,674
211245167	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	912SD42060E17***	19,100	\$2,674
211245156	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	912SD36060E14***	18,900	\$2,646
211245144	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SA42090E17***	19,200	\$2,688
211245132	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SA36070E17***	19,200	\$2,688
211245120	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SA36045E17***	19,100	\$2,674
211245108	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SA36045E14***	19,300	\$2,702
211245098	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926TB42060V17***	19,100	\$2,674
211245087	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	915SB30026E14***	18,900	\$2,646
211245077	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926TB36060V14***	19,000	\$2,660
211245067	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926TB30040V14***	19,000	\$2,660
211245056	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	915SB36060E14***	19,400	\$2,716
211245045	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	915SB36040E17***	19,400	\$2,716
211245034	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	915SB30040E14***	19,500	\$2,730
211245024	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*TA48070V17***	19,100	\$2,674
211245014	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926TB48080V17***	19,100	\$2,674
211245004	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926TB36040V17***	19,000	\$2,660
211245002	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*TA48090V17***	19,000	\$2,660
211245000	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*TA36070V14***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244990	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*TA36045V14***	19,100	\$2,674
211244979	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	83*SA36040E17***	19,000	\$2,660
211244968	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	935SA48060E17***	19,100	\$2,674
211244959	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*SA48070V17***	19,000	\$2,660
211244950	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*SA48045V17***	19,200	\$2,688
211244921	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SA48070E17***	19,400	\$2,716
211244910	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	935SA36040E17***	19,000	\$2,660
211244901	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926SA48080V17***	19,100	\$2,674
211244892	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926SA36060V14***	19,000	\$2,660
211244883	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926SA36040V17***	19,000	\$2,660
211244874	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926SA30040V14***	19,000	\$2,660
211244865	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	926SA42060V17***	18,900	\$2,646
211244847	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*SA36045V14***	18,900	\$2,646
211244838	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	OVMAAB042112	19,200	\$2,688
211244829	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	OVLAAB036098	18,900	\$2,646
211244820	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	OVMAAB036098	19,000	\$2,660
211244809	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	83*SA48060E17***	19,300	\$2,702
211244797	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SA36070E14***	19,100	\$2,674
211244786	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	912SD36040E17***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244775	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	912SD30040E14***	19,400	\$2,716
211244764	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	915SB48080E17***	19,500	\$2,730
211244753	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	915SB42060E17***	19,400	\$2,716
211244742	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	912SD48080E17***	19,100	\$2,674
211244731	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	912SD42060E17***	19,100	\$2,674
211244720	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	912SD36060E14***	18,900	\$2,646
211244708	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SA42090E17***	19,200	\$2,688
211244696	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SA36070E17***	19,200	\$2,688
211244684	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SA36045E17***	19,100	\$2,674
211244672	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SA36045E14***	19,300	\$2,702
211244662	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926TB42060V17***	19,100	\$2,674
211244651	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	915SB30026E14***	18,900	\$2,646
211244641	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926TB36060V14***	19,000	\$2,660
211244631	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926TB30040V14***	19,000	\$2,660
211244620	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	915SB36060E14***	19,400	\$2,716
211244609	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	915SB36040E17***	19,400	\$2,716
211244598	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	915SB30040E14***	19,500	\$2,730
211244588	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*TA48070V17***	19,100	\$2,674
211244578	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926TB48080V17***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244568	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926TB36040V17***	19,000	\$2,660
211244566	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*TA48090V17***	19,000	\$2,660
211244564	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*TA36070V14***	19,100	\$2,674
211244554	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*TA36045V14***	19,100	\$2,674
211244543	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	83*SA36040E17***	19,000	\$2,660
211244532	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	935SA48060E17***	19,100	\$2,674
211244523	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*SA48070V17***	19,000	\$2,660
211244514	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*SA48045V17***	19,200	\$2,688
211244485	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SA48070E17***	19,400	\$2,716
211244474	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	935SA36040E17***	19,000	\$2,660
211244465	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926SA48080V17***	19,100	\$2,674
211244456	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926SA36060V14***	19,000	\$2,660
211244447	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926SA36040V17***	19,000	\$2,660
211244438	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926SA30040V14***	19,000	\$2,660
211244429	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	926SA42060V17***	18,900	\$2,646
211244411	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*SA36045V14***	18,900	\$2,646
211244399	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	8(0,1)*SA36070E14***	19,100	\$2,674
211244388	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	912SD30040E14***	19,400	\$2,716
211244377	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	912SD36060E14***	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244365	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	8(0,1)*SA36045E14***	19,300	\$2,702
211244354	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	915SB30026E14***	19,500	\$2,730
211244344	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	926TB36060V14***	19,000	\$2,660
211244334	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	926TB30040V14***	19,100	\$2,674
211244323	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	915SB36060E14***	19,400	\$2,716
211244312	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	915SB30040E14***	19,500	\$2,730
211244310	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	82*TA36070V14***	19,100	\$2,674
211244300	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	82*TA36045V14***	19,100	\$2,674
211244291	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	926SA36060V14***	19,000	\$2,660
211244282	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	926SA30040V14***	19,100	\$2,674
211244273	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	82*SA36045V14***	19,200	\$2,688
211244264	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	OVMAAB042112	19,700	\$2,758
211244255	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	OVLAAB036098	19,300	\$2,702
211244246	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	OVMAAB036098	19,400	\$2,716
211244235	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	83*SA48060E17***	19,600	\$2,744
211244223	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SA36070E14***	19,500	\$2,730
211244212	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	912SD36040E17***	19,500	\$2,730
211244201	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	912SD30040E14***	19,700	\$2,758
211244190	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	915SB48080E17***	19,800	\$2,772

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244179	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	915SB42060E17***	19,700	\$2,758
211244168	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	912SD48080E17***	19,400	\$2,716
211244157	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	912SD42060E17***	19,500	\$2,730
211244146	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	912SD36060E14***	19,600	\$2,744
211244134	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SA42090E17***	19,500	\$2,730
211244122	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SA36070E17***	19,500	\$2,730
211244110	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SA36045E17***	19,400	\$2,716
211244098	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SA36045E14***	19,600	\$2,744
211244088	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TB42060V17***	19,400	\$2,716
211244077	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	915SB30026E14***	19,900	\$2,786
211244067	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TB36060V14***	19,300	\$2,702
211244057	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TB30040V14***	19,500	\$2,730
211244046	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	915SB36060E14***	19,700	\$2,758
211244035	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	915SB36040E17***	19,700	\$2,758
211244024	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	915SB30040E14***	19,800	\$2,772
211244014	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*TA48070V17***	19,400	\$2,716
211244004	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TB48080V17***	19,500	\$2,730
211243994	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926TB36040V17***	19,700	\$2,758
211243992	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*TA48090V17***	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243990	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*TA36070V14***	19,500	\$2,730
211243980	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*TA36045V14***	19,500	\$2,730
211243969	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	83*SA36040E17***	19,300	\$2,702
211243958	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	935SA48060E17***	19,400	\$2,716
211243949	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*SA48070V17***	19,400	\$2,716
211243940	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*SA48045V17***	19,500	\$2,730
211243911	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SA48070E17***	19,700	\$2,758
211243900	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	935SA36040E17***	19,300	\$2,702
211243891	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926SA48080V17***	19,500	\$2,730
211243882	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926SA36060V14***	19,300	\$2,702
211243873	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926SA36040V17***	19,700	\$2,758
211243864	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926SA30040V14***	19,500	\$2,730
211243855	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	926SA42060V17***	19,500	\$2,730
211243837	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*SA36045V14***	19,500	\$2,730
211243825	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	8(0,1)*SA36070E14***	19,500	\$2,730
211243814	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	912SD30040E14***	19,700	\$2,758
211243803	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	912SD36060E14***	19,600	\$2,744
211243791	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	8(0,1)*SA36045E14***	19,600	\$2,744
211243780	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	915SB30026E14***	19,900	\$2,786

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243770	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	926TB36060V14***	19,300	\$2,702
211243760	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	926TB30040V14***	19,500	\$2,730
211243749	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	915SB36060E14***	19,700	\$2,758
211243738	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	915SB30040E14***	19,800	\$2,772
211243736	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	82*TA36070V14***	19,500	\$2,730
211243726	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	82*TA36045V14***	19,500	\$2,730
211243717	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	926SA36060V14***	19,300	\$2,702
211243708	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	926SA30040V14***	19,500	\$2,730
211243699	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	82*SA36045V14***	19,500	\$2,730
211243672	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	OVLAAB036098	18,400	\$2,576
211243482	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	82*TA66110V21***	18,500	\$2,590
211243462	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926TB60080V21***	18,400	\$2,576
211243400	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926TB36040V17***	18,500	\$2,590
211243285	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926TB66100V21***	18,400	\$2,576
211243245	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	926SA36040V17***	18,500	\$2,590
211243173	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	OVLAAB036098	18,700	\$2,618
211243164	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	OVMAAB036098	18,800	\$2,632
211243141	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	8(0,1)*SA36070E14***	18,900	\$2,646
211243130	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	912SD36040E17***	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243086	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	912SD48080E17***	18,900	\$2,646
211243075	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	912SD42060E17***	18,900	\$2,646
211243028	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	8(0,1)*SA36045E17***	18,900	\$2,646
211243006	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926TB42060V17***	18,900	\$2,646
211242985	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926TB36060V14***	18,700	\$2,618
211242975	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926TB30040V14***	18,900	\$2,646
211242932	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*TA48070V17***	18,800	\$2,632
211242922	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926TB48080V17***	18,900	\$2,646
211242910	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*TA48090V17***	18,700	\$2,618
211242898	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*TA36045V14***	18,900	\$2,646
211242887	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	83*SA36040E17***	18,700	\$2,618
211242876	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	935SA48060E17***	18,900	\$2,646
211242867	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*SA48070V17***	18,800	\$2,632
211242858	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*SA48045V17***	19,000	\$2,660
211242818	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	935SA36040E17***	18,700	\$2,618
211242809	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926SA48080V17***	18,900	\$2,646
211242800	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926SA36060V14***	18,700	\$2,618
211242782	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926SA30040V14***	18,900	\$2,646
211242773	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	926SA42060V17***	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242746	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	OVLAAB048112	19,200	\$2,688
211242737	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	OVMAAB042112	19,100	\$2,674
211242728	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	OVLAAB036098	18,900	\$2,646
211242719	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	OVMAAB036098	18,900	\$2,646
211242708	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	83*SA48060E17***	19,300	\$2,702
211242697	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	83*SA60080E21***	19,100	\$2,674
211242686	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SD36040E17***	19,100	\$2,674
211242675	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	915SB48080E17***	19,400	\$2,716
211242664	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	915SB42060E17***	19,300	\$2,702
211242653	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SD60100E21***	19,300	\$2,702
211242642	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SD60080E21***	19,300	\$2,702
211242631	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SD48080E17***	19,100	\$2,674
211242620	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	912SD42060E17***	19,100	\$2,674
211242608	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SA60110E21***	19,400	\$2,716
211242596	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SA60090E21***	19,200	\$2,688
211242584	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SA42090E17***	19,200	\$2,688
211242572	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SA48070E21***	19,100	\$2,674
211242560	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SA36070E17***	18,800	\$2,632
211242548	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SA36045E17***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242538	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*TA66110V21***	18,900	\$2,646
211242528	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TB60100V21***	19,000	\$2,660
211242518	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TB60080V21***	18,900	\$2,646
211242508	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TB42060V17***	19,100	\$2,674
211242497	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	915SB36040E17***	19,300	\$2,702
211242487	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*TA48070V17***	19,000	\$2,660
211242477	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TB48080V17***	19,100	\$2,674
211242466	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	915SB60080E21***	19,300	\$2,702
211242456	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TB36040V17***	19,000	\$2,660
211242446	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*TA60090V21***	19,000	\$2,660
211242444	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*TA48090V17***	19,000	\$2,660
211242433	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	83*SA36040E17***	18,900	\$2,646
211242422	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	935SA48060E17***	19,100	\$2,674
211242413	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*SA60090V21***	19,000	\$2,660
211242404	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*SA60070V21***	19,300	\$2,702
211242395	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*SA48070V17***	19,000	\$2,660
211242386	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	82*SA48045V17***	18,800	\$2,632
211242341	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926TB66100V21***	18,900	\$2,646
211242330	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SA48070E17***	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242319	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	935SA36040E17***	18,900	\$2,646
211242310	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926SA48080V17***	19,100	\$2,674
211242301	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926SA36040V17***	19,000	\$2,660
211242292	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926SA60100V21***	18,900	\$2,646
211242283	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926SA60080V21***	19,000	\$2,660
211242274	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	926SA42060V17***	18,900	\$2,646
211242238	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	OVMAAB042112	19,200	\$2,688
211242229	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	OVLAAB036098	18,900	\$2,646
211242220	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	OVMAAB036098	18,900	\$2,646
211242209	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	83*SA48060E17***	19,300	\$2,702
211242197	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SA36070E14***	19,100	\$2,674
211242186	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	912SD36040E17***	19,100	\$2,674
211242175	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	912SD30040E14***	19,400	\$2,716
211242164	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	915SB48080E17***	19,400	\$2,716
211242153	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	915SB42060E17***	19,300	\$2,702
211242142	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	912SD48080E17***	19,100	\$2,674
211242131	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	912SD42060E17***	19,100	\$2,674
211242120	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	912SD36060E14***	18,800	\$2,632
211242108	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SA42090E17***	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242096	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SA36070E17***	19,200	\$2,688
211242084	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SA36045E17***	19,100	\$2,674
211242072	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SA36045E14***	19,300	\$2,702
211242062	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926TB42060V17***	19,100	\$2,674
211242051	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	915SB30026E14***	18,900	\$2,646
211242041	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926TB36060V14***	18,900	\$2,646
211242031	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926TB30040V14***	18,900	\$2,646
211242020	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	915SB36060E14***	19,300	\$2,702
211242009	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	915SB36040E17***	19,300	\$2,702
211241998	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	915SB30040E14***	19,400	\$2,716
211241988	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*TA48070V17***	19,000	\$2,660
211241978	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926TB48080V17***	19,100	\$2,674
211241968	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926TB36040V17***	18,900	\$2,646
211241966	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*TA48090V17***	18,900	\$2,646
211241964	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*TA36070V14***	19,100	\$2,674
211241954	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*TA36045V14***	19,100	\$2,674
211241943	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	83*SA36040E17***	18,900	\$2,646
211241932	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	935SA48060E17***	19,100	\$2,674
211241923	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*SA48070V17***	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241914	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*SA48045V17***	19,100	\$2,674
211241885	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SA48070E17***	19,400	\$2,716
211241874	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	935SA36040E17***	18,900	\$2,646
211241865	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926SA48080V17***	19,100	\$2,674
211241856	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926SA36060V14***	18,900	\$2,646
211241847	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926SA36040V17***	18,900	\$2,646
211241838	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926SA30040V14***	18,900	\$2,646
211241829	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	926SA42060V17***	18,900	\$2,646
211241811	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*SA36045V14***	18,800	\$2,632
211241802	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	OVMAAB042112	19,200	\$2,688
211241793	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	OVLAAB036098	18,900	\$2,646
211241784	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	OVMAAB036098	19,000	\$2,660
211241773	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	83*SA48060E17***	19,300	\$2,702
211241761	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SA36070E14***	19,200	\$2,688
211241750	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	912SD36040E17***	19,100	\$2,674
211241739	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	912SD30040E14***	19,400	\$2,716
211241728	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	915SB48080E17***	19,500	\$2,730
211241717	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	915SB42060E17***	19,400	\$2,716
211241706	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	912SD48080E17***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241695	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	912SD42060E17***	19,200	\$2,688
211241684	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	912SD36060E14***	18,900	\$2,646
211241672	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SA42090E17***	19,200	\$2,688
211241660	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SA36070E17***	19,200	\$2,688
211241648	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SA36045E17***	19,100	\$2,674
211241636	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SA36045E14***	19,400	\$2,716
211241626	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926TB42060V17***	19,100	\$2,674
211241615	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	915SB30026E14***	18,900	\$2,646
211241605	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926TB36060V14***	19,000	\$2,660
211241595	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926TB30040V14***	19,000	\$2,660
211241584	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	915SB36060E14***	19,400	\$2,716
211241573	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	915SB36040E17***	19,400	\$2,716
211241562	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	915SB30040E14***	19,500	\$2,730
211241552	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*TA48070V17***	19,100	\$2,674
211241542	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926TB48080V17***	19,200	\$2,688
211241532	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926TB36040V17***	19,000	\$2,660
211241530	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*TA48090V17***	19,000	\$2,660
211241528	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*TA36070V14***	19,200	\$2,688
211241518	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*TA36045V14***	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241507	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	83*SA36040E17***	19,000	\$2,660
211241496	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	935SA48060E17***	19,100	\$2,674
211241487	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*SA48070V17***	19,100	\$2,674
211241478	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*SA48045V17***	19,200	\$2,688
211241449	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	8(0,1)*SA48070E17***	19,400	\$2,716
211241438	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	935SA36040E17***	19,000	\$2,660
211241429	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926SA48080V17***	19,200	\$2,688
211241420	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926SA36060V14***	19,000	\$2,660
211241411	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926SA36040V17***	19,000	\$2,660
211241402	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926SA30040V14***	19,000	\$2,660
211241393	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	926SA42060V17***	18,900	\$2,646
211241375	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*SA36045V14***	18,900	\$2,646
211241363	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	8(0,1)*SA36070E14***	19,200	\$2,688
211241352	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	912SD30040E14***	19,400	\$2,716
211241341	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	912SD36060E14***	18,900	\$2,646
211241329	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	8(0,1)*SA36045E14***	19,300	\$2,702
211241318	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	915SB30026E14***	19,600	\$2,744
211241308	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	926TB36060V14***	19,000	\$2,660
211241298	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	926TB30040V14***	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241287	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	915SB36060E14***	19,400	\$2,716
211241276	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	915SB30040E14***	19,500	\$2,730
211241274	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	82*TA36070V14***	19,200	\$2,688
211241264	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	82*TA36045V14***	19,100	\$2,674
211241255	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	926SA36060V14***	19,000	\$2,660
211241246	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	926SA30040V14***	19,100	\$2,674
211241237	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	82*SA36045V14***	19,200	\$2,688
211241219	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	OVLAAB036098	18,600	\$2,604
211241210	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	OVMAAB036098	18,600	\$2,604
211241110	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	912SD36060E14***	18,500	\$2,590
211241031	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926TB36060V14***	18,600	\$2,604
211240958	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926TB36040V17***	18,600	\$2,604
211240956	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	82*TA48090V17***	18,600	\$2,604
211240933	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	83*SA36040E17***	18,600	\$2,604
211240913	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	82*SA48070V17***	18,700	\$2,618
211240864	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	935SA36040E17***	18,600	\$2,604
211240846	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926SA36060V14***	18,600	\$2,604
211240837	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	926SA36040V17***	18,600	\$2,604
211240792	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	OVMAAB042112	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240783	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	OVLAAB036098	19,200	\$2,688
211240774	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	OVMAAB036098	19,300	\$2,702
211240763	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	83*SA48060E17***	19,600	\$2,744
211240751	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SA36070E14***	19,400	\$2,716
211240740	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	912SD36040E17***	19,400	\$2,716
211240729	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	912SD30040E14***	19,700	\$2,758
211240718	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	915SB48080E17***	19,700	\$2,758
211240707	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	915SB42060E17***	19,600	\$2,744
211240696	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	912SD48080E17***	19,400	\$2,716
211240685	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	912SD42060E17***	19,400	\$2,716
211240674	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	912SD36060E14***	19,200	\$2,688
211240662	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SA42090E17***	19,500	\$2,730
211240650	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SA36070E17***	19,500	\$2,730
211240638	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SA36045E17***	19,400	\$2,716
211240626	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SA36045E14***	19,600	\$2,744
211240616	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TB42060V17***	19,400	\$2,716
211240605	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	915SB30026E14***	19,800	\$2,772
211240595	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TB36060V14***	19,300	\$2,702
211240585	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TB30040V14***	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240574	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	915SB36060E14***	19,600	\$2,744
211240563	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	915SB36040E17***	19,700	\$2,758
211240552	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	915SB30040E14***	19,700	\$2,758
211240542	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*TA48070V17***	19,300	\$2,702
211240532	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TB48080V17***	19,400	\$2,716
211240522	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926TB36040V17***	19,300	\$2,702
211240520	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*TA48090V17***	19,300	\$2,702
211240518	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*TA36070V14***	19,400	\$2,716
211240508	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*TA36045V14***	19,400	\$2,716
211240497	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	83*SA36040E17***	19,300	\$2,702
211240486	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	935SA48060E17***	19,400	\$2,716
211240477	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*SA48070V17***	19,300	\$2,702
211240468	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*SA48045V17***	19,400	\$2,716
211240439	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SA48070E17***	19,700	\$2,758
211240428	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	935SA36040E17***	19,300	\$2,702
211240419	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926SA48080V17***	19,400	\$2,716
211240410	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926SA36060V14***	19,300	\$2,702
211240401	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926SA36040V17***	19,300	\$2,702
211240392	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926SA30040V14***	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240383	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	926SA42060V17***	19,500	\$2,730
211240365	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	82*SA36045V14***	19,500	\$2,730
211240353	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	8(0,1)*SA36070E14***	19,400	\$2,716
211240342	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	912SD30040E14***	19,700	\$2,758
211240331	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	912SD36060E14***	19,600	\$2,744
211240319	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	8(0,1)*SA36045E14***	19,600	\$2,744
211240308	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	915SB30026E14***	19,800	\$2,772
211240298	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	926TB36060V14***	19,300	\$2,702
211240288	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	926TB30040V14***	19,400	\$2,716
211240277	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	915SB36060E14***	19,600	\$2,744
211240266	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	915SB30040E14***	19,700	\$2,758
211240264	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	82*TA36070V14***	19,400	\$2,716
211240254	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	82*TA36045V14***	19,400	\$2,716
211240245	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	926SA36060V14***	19,300	\$2,702
211240236	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	926SA30040V14***	19,400	\$2,716
211240227	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2414AL*	82*SA36045V14***	19,500	\$2,730
211239221	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	FJ4DN*B24L*		19,200	\$2,688
213353738	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	F54AA*B24L*		12,500	\$1,750
213353728	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	F54AA*A18L*		12,800	\$1,792

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213249247	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	FEVA0024**+NAVA43601CK		12,300	\$1,722
213076384	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	926TC48060V17***	12,400	\$1,736
212989322	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	935SB48060M17***	12,200	\$1,708
212989310	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	935SB48060M17***	12,300	\$1,722
212989298	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	935SB48060M17***	12,200	\$1,708
212989286	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	935SB48060M17***	12,000	\$1,680
212989274	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	935SB48060M17***	12,300	\$1,722
212989262	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	935SB48060M17***	12,100	\$1,694
212988830	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	935SB36040M17***	12,200	\$1,708
212988818	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	935SB36040M17***	12,500	\$1,750
212988806	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	935SB36040M17***	12,200	\$1,708
212988794	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	935SB36040M17***	12,000	\$1,680
212988782	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	935SB36040M17***	12,300	\$1,722
212988770	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	935SB36040M17***	12,100	\$1,694
212987556	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	916SA48080M17***	12,200	\$1,708
212987544	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	916SA48080M17***	12,500	\$1,750
212987532	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	916SA48080M17***	12,100	\$1,694
212987520	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	916SA48080M17***	12,200	\$1,708
212987508	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	916SA48080M17***	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212987496	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	916SA48080M17***	12,300	\$1,722
212987078	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	916SA36060M14***	12,200	\$1,708
212987068	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	916SA36060M14***	12,200	\$1,708
212987058	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	916SA36060M14***	12,300	\$1,722
212987048	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	916SA36060M14***	12,300	\$1,722
212987038	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	916SA36060M14***	12,500	\$1,750
212987028	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	916SA36060M14***	12,200	\$1,708
212987018	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3014AL*	916SA36060M14***	12,200	\$1,708
212987008	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	916SA36060M14***	12,000	\$1,680
212986998	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	916SA36060M14***	12,300	\$1,722
212986988	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	916SA36060M14***	12,300	\$1,722
212986978	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	916SA36060M14***	12,100	\$1,694
212986716	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	916SA36040M17***	12,300	\$1,722
212986704	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	916SA36040M17***	12,500	\$1,750
212986692	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	916SA36040M17***	12,300	\$1,722
212986680	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	916SA36040M17***	12,100	\$1,694
212986668	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	916SA36040M17***	12,300	\$1,722
212986656	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	916SA36040M17***	12,100	\$1,694
212986380	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	916SA30040M14***	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986368	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	916SA30040M14***	12,300	\$1,722
212986356	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	916SA30040M14***	12,400	\$1,736
212986344	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	916SA30040M14***	12,400	\$1,736
212986332	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	916SA30040M14***	12,400	\$1,736
212986320	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	916SA30040M14***	12,300	\$1,722
212986308	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3014AL*	916SA30040M14***	12,300	\$1,722
212986296	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	916SA30040M14***	12,400	\$1,736
212986284	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	916SA30040M14***	12,400	\$1,736
212986272	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	916SA30040M14***	12,200	\$1,708
212985974	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	916SA30026M14***	12,300	\$1,722
212985964	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	916SA30026M14***	12,200	\$1,708
212985954	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	916SA30026M14***	12,300	\$1,722
212985944	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	916SA30026M14***	12,300	\$1,722
212985934	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	916SA30026M14***	12,500	\$1,750
212985924	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	916SA30026M14***	12,200	\$1,708
212985914	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3014AL*	916SA30026M14***	12,200	\$1,708
212985904	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	916SA30026M14***	12,100	\$1,694
212985894	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	916SA30026M14***	12,300	\$1,722
212985884	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	916SA30026M14***	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212985874	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	916SA30026M14***	12,100	\$1,694
212984758	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	912SE48080M17***	12,100	\$1,694
212984746	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	912SE48080M17***	12,500	\$1,750
212984734	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	912SE48080M17***	12,400	\$1,736
212984722	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	912SE48080M17***	12,200	\$1,708
212984710	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	912SE48080M17***	12,500	\$1,750
212984698	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	912SE48080M17***	12,300	\$1,722
212984218	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	912SE42060M17***	12,300	\$1,722
212984206	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	912SE42060M17***	12,400	\$1,736
212984194	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	912SE42060M17***	12,300	\$1,722
212984182	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	912SE42060M17***	12,200	\$1,708
212984170	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	912SE42060M17***	12,400	\$1,736
212984158	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	912SE42060M17***	12,200	\$1,708
212983728	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	912SE36060M14***	12,200	\$1,708
212983718	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3014AL*	912SE36060M14***	12,200	\$1,708
212983707	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	912SE36060M14***	12,400	\$1,736
212983697	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2414AL*	912SE36060M14***	12,400	\$1,736
212983687	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*1814AL*	912SE36060M14***	12,400	\$1,736
212983677	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	912SE36060M14***	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983667	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3014AL*	912SE36060M14***	12,300	\$1,722
212983657	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	912SE36060M14***	12,000	\$1,680
212983647	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	912SE36060M14***	12,400	\$1,736
212983637	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	912SE36060M14***	12,400	\$1,736
212983627	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	912SE36060M14***	12,100	\$1,694
212983306	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	912SE36040M17***	12,300	\$1,722
212983295	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	912SE36040M17***	12,400	\$1,736
212983284	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	912SE36040M17***	12,200	\$1,708
212983273	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	912SE36040M17***	12,100	\$1,694
212983262	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	912SE36040M17***	12,300	\$1,722
212983251	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	912SE36040M17***	12,200	\$1,708
212981881	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	83*SB60100M21***	12,300	\$1,722
212981869	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	83*SB60100M21***	12,600	\$1,764
212981857	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	83*SB60100M21***	12,300	\$1,722
212981845	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	83*SB60100M21***	12,100	\$1,694
212981833	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	83*SB60100M21***	12,300	\$1,722
212981821	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	83*SB60100M21***	12,200	\$1,708
212980002	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	8(0,1)*SB42090M17***	12,300	\$1,722
212979990	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	8(0,1)*SB42090M17***	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979978	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	8(0,1)*SB42090M17***	12,300	\$1,722
212979966	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	8(0,1)*SB42090M17***	12,200	\$1,708
212979954	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	8(0,1)*SB42090M17***	12,400	\$1,736
212979942	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	8(0,1)*SB42090M17***	12,200	\$1,708
212978797	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	8(0,1)*SB36070M17***	12,300	\$1,722
212978786	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	8(0,1)*SB36070M17***	12,300	\$1,722
212978775	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	8(0,1)*SB36070M17***	12,300	\$1,722
212978764	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	8(0,1)*SB36070M17***	12,100	\$1,694
212978753	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	8(0,1)*SB36070M17***	12,300	\$1,722
212978742	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	8(0,1)*SB36070M17***	12,100	\$1,694
212978345	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	8(0,1)*SB36070M14***	12,200	\$1,708
212978333	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	8(0,1)*SB36070M14***	12,200	\$1,708
212978321	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	8(0,1)*SB36070M14***	12,400	\$1,736
212978309	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	8(0,1)*SB36070M14***	12,400	\$1,736
212978297	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	8(0,1)*SB36070M14***	12,400	\$1,736
212978283	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	8(0,1)*SB36070M14***	12,100	\$1,694
212978271	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3014AL*	8(0,1)*SB36070M14***	12,300	\$1,722
212978259	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	8(0,1)*SB36070M14***	12,200	\$1,708
212978247	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	8(0,1)*SB36070M14***	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978235	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2414AL*	8(0,1)*SB36070M14***	12,400	\$1,736
212978223	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	8(0,1)*SB36070M14***	12,200	\$1,708
212977827	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	8(0,1)*SB36045M14***	12,300	\$1,722
212977815	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3014AL*	8(0,1)*SB36045M14***	12,300	\$1,722
212977803	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	8(0,1)*SB36045M14***	12,400	\$1,736
212977791	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2414AL*	8(0,1)*SB36045M14***	12,400	\$1,736
212977779	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*1814AL*	8(0,1)*SB36045M14***	12,400	\$1,736
212977767	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	8(0,1)*SB36045M14***	12,300	\$1,722
212977755	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	8(0,1)*SB36045M14***	12,300	\$1,722
212977743	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	8(0,1)*SB36045M14***	12,100	\$1,694
212977731	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	8(0,1)*SB36045M14***	12,400	\$1,736
212977719	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2414AL*	8(0,1)*SB36045M14***	12,300	\$1,722
212977707	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	8(0,1)*SB36045M14***	12,200	\$1,708
212975838	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926TC48080V17***	12,200	\$1,708
212975825	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926TC48080V17***	12,500	\$1,750
212975812	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926TC48080V17***	12,200	\$1,708
212975799	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	926TC48080V17***	12,000	\$1,680
212975786	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	926TC48080V17***	12,300	\$1,722
212975773	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	926TC48080V17***	12,100	\$1,694

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975486	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926TC36060V14***	12,200	\$1,708
212975475	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3014AL*	926TC36060V14***	12,200	\$1,708
212975464	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926TC36060V14***	12,400	\$1,736
212975453	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2414AL*	926TC36060V14***	12,400	\$1,736
212975442	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*1814AL*	926TC36060V14***	12,400	\$1,736
212975431	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926TC36060V14***	12,200	\$1,708
212975420	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	926TC36060V14***	12,200	\$1,708
212975409	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	926TC36060V14***	12,000	\$1,680
212975398	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	926TC36060V14***	12,300	\$1,722
212975387	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2414AL*	926TC36060V14***	12,200	\$1,708
212975376	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	926TC36060V14***	12,100	\$1,694
212975123	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926TC36040V17***	12,200	\$1,708
212975112	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926TC36040V17***	12,500	\$1,750
212975101	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926TC36040V17***	12,200	\$1,708
212975090	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	926TC36040V17***	12,100	\$1,694
212975079	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	926TC36040V17***	12,300	\$1,722
212975068	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	926TC36040V17***	12,100	\$1,694
212974744	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926TC30040V14***	12,200	\$1,708
212974731	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3014AL*	926TC30040V14***	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974718	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926TC30040V14***	12,400	\$1,736
212974705	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2414AL*	926TC30040V14***	12,400	\$1,736
212974692	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*1814AL*	926TC30040V14***	12,400	\$1,736
212974679	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926TC30040V14***	12,200	\$1,708
212974666	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	926TC30040V14***	12,200	\$1,708
212974653	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	926TC30040V14***	12,100	\$1,694
212974640	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	926TC30040V14***	12,300	\$1,722
212974627	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2414AL*	926TC30040V14***	12,400	\$1,736
212974614	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	926TC30040V14***	12,100	\$1,694
212973703	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926SB48080V17***	12,200	\$1,708
212973693	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926SB48080V17***	12,500	\$1,750
212973683	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926SB48080V17***	12,200	\$1,708
212973673	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	926SB48080V17***	12,000	\$1,680
212973663	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	926SB48080V17***	12,300	\$1,722
212973653	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	926SB48080V17***	12,100	\$1,694
212973393	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926SB36060V14***	12,200	\$1,708
212973383	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3014AL*	926SB36060V14***	12,200	\$1,708
212973373	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926SB36060V14***	12,400	\$1,736
212973363	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2414AL*	926SB36060V14***	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973353	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*1814AL*	926SB36060V14***	12,400	\$1,736
212973343	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926SB36060V14***	12,200	\$1,708
212973333	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	926SB36060V14***	12,200	\$1,708
212973323	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	926SB36060V14***	12,000	\$1,680
212973313	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	926SB36060V14***	12,300	\$1,722
212973303	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2414AL*	926SB36060V14***	12,200	\$1,708
212973293	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	926SB36060V14***	12,100	\$1,694
212973063	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926SB36040V17***	12,200	\$1,708
212973053	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926SB36040V17***	12,500	\$1,750
212973043	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926SB36040V17***	12,200	\$1,708
212973033	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2517AL*	926SB36040V17***	12,100	\$1,694
212973023	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**2417AL*	926SB36040V17***	12,300	\$1,722
212973013	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**1917AL*	926SB36040V17***	12,100	\$1,694
212972763	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926SB30040V14***	12,200	\$1,708
212972753	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3014AL*	926SB30040V14***	12,200	\$1,708
212972743	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926SB30040V14***	12,400	\$1,736
212972733	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2414AL*	926SB30040V14***	12,400	\$1,736
212972723	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*1814AL*	926SB30040V14***	12,400	\$1,736
212972713	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926SB30040V14***	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972703	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3014AL*	926SB30040V14***	12,200	\$1,708
212972693	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926SB30040V14***	12,100	\$1,694
212972683	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926SB30040V14***	12,300	\$1,722
212972673	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	926SB30040V14***	12,300	\$1,722
212972663	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926SB30040V14***	12,100	\$1,694
212971928	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	82*TB48090V17***	12,300	\$1,722
212971924	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	82*TB48090V17***	12,400	\$1,736
212971920	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	82*TB48090V17***	12,300	\$1,722
212971916	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*TB48090V17***	12,100	\$1,694
212971912	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*TB48090V17***	12,400	\$1,736
212971908	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*TB48090V17***	12,200	\$1,708
212971490	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	82*TB48070V17***	12,300	\$1,722
212971479	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	82*TB48070V17***	12,400	\$1,736
212971468	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	82*TB48070V17***	12,300	\$1,722
212971457	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*TB48070V17***	12,100	\$1,694
212971446	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*TB48070V17***	12,400	\$1,736
212971435	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*TB48070V17***	12,200	\$1,708
212971369	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	82*TB36045V14***	12,200	\$1,708
212971367	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	82*TB36045V14***	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971365	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	82*TB36045V14***	12,400	\$1,736
212971363	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	82*TB36045V14***	12,400	\$1,736
212971361	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	82*TB36045V14***	12,400	\$1,736
212971359	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3014AL*	82*TB36045V14***	12,300	\$1,722
212971357	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*TB36045V14***	12,200	\$1,708
212971355	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*TB36045V14***	12,400	\$1,736
212971353	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	82*TB36045V14***	12,400	\$1,736
212971351	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*TB36045V14***	12,200	\$1,708
212969597	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	82*SB36045V14***	12,200	\$1,708
212969587	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	82*SB36045V14***	12,200	\$1,708
212969577	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	82*SB36045V14***	12,500	\$1,750
212969567	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	82*SB36045V14***	12,500	\$1,750
212969557	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	82*SB36045V14***	12,500	\$1,750
212969547	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3014AL*	82*SB36045V14***	12,400	\$1,736
212969537	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*SB36045V14***	12,200	\$1,708
212969527	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*SB36045V14***	12,500	\$1,750
212969517	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	82*SB36045V14***	12,500	\$1,750
212969507	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*SB36045V14***	12,300	\$1,722
211265030	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FV4CNF002L		12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211265008	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FM(C,U)4Z30**AL*		12,400	\$1,736
211264986	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FM(C,U)4Z24**AL*		12,500	\$1,750
211264964	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FM(C,U)4Z18**AL*		12,500	\$1,750
211264942	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FMA4X24**AL*		12,400	\$1,736
211264921	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FMA4X18**AL*		12,400	\$1,736
211264899	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FX4DNF031L		12,400	\$1,736
211264877	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FX4DNF025L		12,400	\$1,736
211264730	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	PF4MN*A18L*		12,700	\$1,778
211264728	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FJ4DN*A18L*		12,700	\$1,778
211264708	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	OVMAAB042112	12,600	\$1,764
211264690	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	OVLAAB036098	12,600	\$1,764
211264672	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	OVMAAB036098	12,600	\$1,764
211264650	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	83*SA48060E17***	12,700	\$1,778
211264625	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	8(0,1)*SA36070E14***	12,300	\$1,722
211264603	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	912SD36040E17***	12,500	\$1,750
211264581	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	912SD30040E14***	12,500	\$1,750
211264559	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	912SD42060E17***	12,300	\$1,722
211264537	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	912SD36060E14***	12,500	\$1,750
211264513	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	8(0,1)*SA36070E17***	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211264489	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	8(0,1)*SA36045E17***	12,400	\$1,736
211264465	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	8(0,1)*SA36045E14***	12,500	\$1,750
211264445	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926TB42060V17***	12,400	\$1,736
211264420	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	915SB30026E14***	12,600	\$1,764
211264398	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926TB36060V14***	12,400	\$1,736
211264355	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926TB30040V14***	12,300	\$1,722
211264297	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	915SB36060E14***	12,400	\$1,736
211264264	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	915SB36040E17***	12,200	\$1,708
211264231	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	915SB30040E14***	12,400	\$1,736
211264191	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	82*TA48070V17***	12,200	\$1,708
211264164	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926TB48080V17***	12,200	\$1,708
211264133	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	926TB36040V17***	12,400	\$1,736
211264127	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	82*TA48090V17***	12,300	\$1,722
211264123	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	82*TA36070V14***	12,300	\$1,722
211264103	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	82*TA36045V14***	12,300	\$1,722
211264081	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	83*SA36040E17***	12,700	\$1,778
211264063	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	82*SA48070V17***	12,200	\$1,708
211264044	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	82*SA48045V17***	12,300	\$1,722
211263998	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*3017AL*	935SA36040E17***	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263980	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	926SA48080V17***	12,200	\$1,708
211263962	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	926SA36060V14***	12,400	\$1,736
211263945	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	926SA36040V17***	12,400	\$1,736
211263926	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	926SA30040V14***	12,300	\$1,722
211263908	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	926SA42060V17***	12,400	\$1,736
211263871	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3017AL*	82*SA36045V14***	12,400	\$1,736
211263846	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	8(0,1)*SA36070E14***	12,300	\$1,722
211263823	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	912SD30040E14***	12,500	\$1,750
211263802	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	912SD36060E14***	12,500	\$1,750
211263777	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	8(0,1)*SA36045E14***	12,500	\$1,750
211263754	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	915SB30026E14***	12,500	\$1,750
211263733	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	926TB36060V14***	12,400	\$1,736
211263713	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	926TB30040V14***	12,200	\$1,708
211263688	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	915SB36060E14***	12,400	\$1,736
211263665	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	915SB30040E14***	12,400	\$1,736
211263661	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	82*TA36070V14***	12,300	\$1,722
211263640	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	82*TA36045V14***	12,300	\$1,722
211263621	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	926SA36060V14***	12,400	\$1,736
211263602	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	926SA30040V14***	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263584	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*3014AL*	82*SA36045V14***	12,400	\$1,736
211263566	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	OVMAAB042112	12,800	\$1,792
211263547	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	OVLAAB036098	12,700	\$1,778
211263528	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	OVMAAB036098	12,800	\$1,792
211263505	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	83*SA48060E17***	12,800	\$1,792
211263480	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	8(0,1)*SA36070E14***	12,400	\$1,736
211263457	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	912SD36040E17***	12,600	\$1,764
211263434	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	912SD30040E14***	12,600	\$1,764
211263411	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	912SD48080E17***	12,900	\$1,806
211263388	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	912SD42060E17***	12,400	\$1,736
211263365	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	912SD36060E14***	12,600	\$1,764
211263340	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	8(0,1)*SA36070E17***	12,600	\$1,764
211263316	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	8(0,1)*SA36045E17***	12,900	\$1,806
211263290	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	8(0,1)*SA36045E14***	12,600	\$1,764
211263270	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	926TB42060V17***	12,500	\$1,750
211263244	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	915SB30026E14***	12,700	\$1,778
211263224	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	926TB36060V14***	12,500	\$1,750
211263203	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	926TB30040V14***	12,300	\$1,722
211263178	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2417AL*	915SB36060E14***	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263156	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	915SB36040E17***	12,300	\$1,722
211263136	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	915SB30040E14***	12,500	\$1,750
211263117	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	82*TA48070V17***	12,300	\$1,722
211263098	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926TB48080V17***	12,300	\$1,722
211263076	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926TB36040V17***	12,500	\$1,750
211263072	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	82*TA48090V17***	12,400	\$1,736
211263068	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	82*TA36070V14***	12,400	\$1,736
211263048	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	82*TA36045V14***	12,400	\$1,736
211263027	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	83*SA36040E17***	12,700	\$1,778
211263005	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	935SA48060E17***	12,900	\$1,806
211262987	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	82*SA48070V17***	12,300	\$1,722
211262969	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	82*SA48045V17***	12,400	\$1,736
211262912	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	935SA36040E17***	12,400	\$1,736
211262895	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926SA48080V17***	12,300	\$1,722
211262877	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926SA36060V14***	12,500	\$1,750
211262860	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926SA36040V17***	12,500	\$1,750
211262842	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926SA30040V14***	12,300	\$1,722
211262824	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	926SA42060V17***	12,400	\$1,736
211262788	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CNPV*2417AL*	82*SA36045V14***	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262764	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	8(0,1)*SA36070E14***	12,400	\$1,736
211262741	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	912SD30040E14***	12,600	\$1,764
211262719	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	912SD36060E14***	12,600	\$1,764
211262695	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	8(0,1)*SA36045E14***	12,600	\$1,764
211262673	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	915SB30026E14***	12,700	\$1,778
211262653	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	926TB36060V14***	12,500	\$1,750
211262632	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	926TB30040V14***	12,300	\$1,722
211262609	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	915SB36060E14***	12,500	\$1,750
211262586	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	915SB30040E14***	12,500	\$1,750
211262582	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	82*TA36070V14***	12,400	\$1,736
211262562	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	82*TA36045V14***	12,400	\$1,736
211262544	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	926SA36060V14***	12,500	\$1,750
211262526	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	926SA30040V14***	12,300	\$1,722
211262508	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*2414AL*	82*SA36045V14***	12,400	\$1,736
211262484	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	8(0,1)*SA36070E14***	12,400	\$1,736
211262462	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	912SD30040E14***	12,600	\$1,764
211262441	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	912SD36060E14***	12,600	\$1,764
211262417	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	8(0,1)*SA36045E14***	12,600	\$1,764
211262394	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	915SB30026E14***	12,700	\$1,778

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262374	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	926TB36060V14***	12,500	\$1,750
211262354	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	926TB30040V14***	12,300	\$1,722
211262330	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	915SB36060E14***	12,500	\$1,750
211262308	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	915SB30040E14***	12,500	\$1,750
211262304	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	82*TA36070V14***	12,400	\$1,736
211262284	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	82*TA36045V14***	12,400	\$1,736
211262267	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	926SA36060V14***	12,500	\$1,750
211262249	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	926SA30040V14***	12,300	\$1,722
211262232	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CNPV*1814AL*	82*SA36045V14***	12,500	\$1,750
211262213	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	OVMAAB042112	12,600	\$1,764
211262196	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	OVLAAB036098	12,600	\$1,764
211262178	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	OVMAAB036098	12,600	\$1,764
211262154	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	8(0,1)*SA36070E14***	12,300	\$1,722
211262133	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	912SD36040E17***	12,500	\$1,750
211262112	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	912SD30040E14***	12,500	\$1,750
211262090	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	912SD42060E17***	12,300	\$1,722
211262068	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	912SD36060E14***	12,500	\$1,750
211262045	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	8(0,1)*SA36070E17***	12,500	\$1,750
211262018	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	8(0,1)*SA36045E17***	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261992	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	8(0,1)*SA36045E14***	12,500	\$1,750
211261971	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	926TB42060V17***	12,400	\$1,736
211261945	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	915SB30026E14***	12,600	\$1,764
211261929	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	926TB36060V14***	12,500	\$1,750
211261913	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	926TB30040V14***	12,200	\$1,708
211261885	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	915SB36060E14***	12,400	\$1,736
211261858	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	915SB36040E17***	12,200	\$1,708
211261839	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	915SB30040E14***	12,400	\$1,736
211261825	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	82*TA48070V17***	12,200	\$1,708
211261806	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	926TB48080V17***	12,200	\$1,708
211261784	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	926TB36040V17***	12,400	\$1,736
211261781	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	82*TA48090V17***	12,300	\$1,722
211261777	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	82*TA36070V14***	12,300	\$1,722
211261758	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	82*TA36045V14***	12,300	\$1,722
211261735	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	83*SA36040E17***	12,700	\$1,778
211261717	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	82*SA48070V17***	12,200	\$1,708
211261699	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	82*SA48045V17***	12,300	\$1,722
211261642	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	935SA36040E17***	12,300	\$1,722
211261624	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**3017AL*	926SA48080V17***	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261606	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926SA36060V14***	12,500	\$1,750
211261588	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926SA36040V17***	12,400	\$1,736
211261570	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926SA30040V14***	12,200	\$1,708
211261552	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	926SA42060V17***	12,400	\$1,736
211261517	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3017AL*	82*SA36045V14***	12,400	\$1,736
211261493	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	8(0,1)*SA36070E14***	12,300	\$1,722
211261471	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	912SD30040E14***	12,500	\$1,750
211261449	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	912SD36060E14***	12,500	\$1,750
211261426	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	8(0,1)*SA36045E14***	12,500	\$1,750
211261404	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	915SB30026E14***	12,500	\$1,750
211261384	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	926TB36060V14***	12,400	\$1,736
211261364	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	926TB30040V14***	12,200	\$1,708
211261342	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	915SB36060E14***	12,400	\$1,736
211261320	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	915SB30040E14***	12,400	\$1,736
211261316	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	82*TA36070V14***	12,300	\$1,722
211261296	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	82*TA36045V14***	12,300	\$1,722
211261277	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	926SA36060V14***	12,400	\$1,736
211261259	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	926SA30040V14***	12,200	\$1,708
211261241	BRYANT HEATING AND COOLING SYSTEMS	38MURQA18AB3*	CAP**3014AL*	82*SA36045V14***	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261222	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	OVMAAB042112	12,500	\$1,750
211261204	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	OVLAAB036098	12,500	\$1,750
211261179	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	OVMAAB036098	12,500	\$1,750
211261143	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	83*SA48060E17***	12,600	\$1,764
211261096	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	8(0,1)*SA36070E14***	12,100	\$1,694
211261057	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	912SD36040E17***	12,400	\$1,736
211261045	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	912SD30040E14***	12,400	\$1,736
211261032	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	912SD42060E17***	12,200	\$1,708
211261019	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	912SD36060E14***	12,400	\$1,736
211261005	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	8(0,1)*SA36070E17***	12,400	\$1,736
211260990	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	8(0,1)*SA36045E17***	12,700	\$1,778
211260976	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	8(0,1)*SA36045E14***	12,400	\$1,736
211260963	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926TB42060V17***	12,200	\$1,708
211260949	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	915SB30026E14***	12,400	\$1,736
211260937	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926TB36060V14***	12,300	\$1,722
211260924	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926TB30040V14***	12,100	\$1,694
211260909	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	915SB36060E14***	12,300	\$1,722
211260896	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	915SB36040E17***	12,100	\$1,694
211260883	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	915SB30040E14***	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260871	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*TA48070V17***	12,000	\$1,680
211260858	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926TB48080V17***	12,100	\$1,694
211260844	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926TB36040V17***	12,300	\$1,722
211260842	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*TA48090V17***	12,200	\$1,708
211260840	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*TA36070V14***	12,200	\$1,708
211260828	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*TA36045V14***	12,200	\$1,708
211260813	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	83*SA36040E17***	12,500	\$1,750
211260802	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*SA48070V17***	12,100	\$1,694
211260791	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*SA48045V17***	12,200	\$1,708
211260757	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	935SA36040E17***	12,200	\$1,708
211260745	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926SA48080V17***	12,100	\$1,694
211260734	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926SA36060V14***	12,300	\$1,722
211260724	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926SA36040V17***	12,300	\$1,722
211260713	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926SA30040V14***	12,100	\$1,694
211260703	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	926SA42060V17***	12,200	\$1,708
211260682	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2517AL*	82*SA36045V14***	12,200	\$1,708
211260671	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	OVMAAB042112	12,700	\$1,778
211260661	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	OVLAAB036098	12,700	\$1,778
211260650	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	OVMAAB036098	12,700	\$1,778

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260637	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	83*SA48060E17***	12,800	\$1,792
211260623	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	8(0,1)*SA36070E14***	12,400	\$1,736
211260612	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	912SD36040E17***	12,600	\$1,764
211260600	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	912SD30040E14***	12,600	\$1,764
211260588	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	912SD42060E17***	12,400	\$1,736
211260574	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	912SD36060E14***	12,600	\$1,764
211260560	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	8(0,1)*SA36070E17***	12,600	\$1,764
211260546	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	8(0,1)*SA36045E17***	12,900	\$1,806
211260531	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	8(0,1)*SA36045E14***	12,600	\$1,764
211260519	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926TB42060V17***	12,400	\$1,736
211260505	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	915SB30026E14***	12,700	\$1,778
211260493	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926TB36060V14***	12,500	\$1,750
211260481	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926TB30040V14***	12,300	\$1,722
211260467	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	915SB36060E14***	12,500	\$1,750
211260454	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	915SB36040E17***	12,300	\$1,722
211260441	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	915SB30040E14***	12,500	\$1,750
211260429	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*TA48070V17***	12,200	\$1,708
211260417	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926TB48080V17***	12,300	\$1,722
211260403	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926TB36040V17***	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260401	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*TA48090V17***	12,400	\$1,736
211260399	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*TA36070V14***	12,400	\$1,736
211260387	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*TA36045V14***	12,400	\$1,736
211260373	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	83*SA36040E17***	12,700	\$1,778
211260362	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*SA48070V17***	12,300	\$1,722
211260352	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*SA48045V17***	12,400	\$1,736
211260317	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	935SA36040E17***	12,400	\$1,736
211260306	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926SA48080V17***	12,300	\$1,722
211260295	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926SA36060V14***	12,500	\$1,750
211260284	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926SA36040V17***	12,500	\$1,750
211260274	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926SA30040V14***	12,300	\$1,722
211260263	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	926SA42060V17***	12,400	\$1,736
211260241	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2417AL*	82*SA36045V14***	12,400	\$1,736
211260227	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	8(0,1)*SA36070E14***	12,300	\$1,722
211260214	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	912SD30040E14***	12,600	\$1,764
211260201	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	912SD36060E14***	12,600	\$1,764
211260184	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	8(0,1)*SA36045E14***	12,600	\$1,764
211260173	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	915SB30026E14***	12,600	\$1,764
211260163	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	926TB36060V14***	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260153	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	926TB30040V14***	12,300	\$1,722
211260136	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	915SB36060E14***	12,500	\$1,750
211260122	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	915SB30040E14***	12,500	\$1,750
211260120	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	82*TA36070V14***	12,400	\$1,736
211260108	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	82*TA36045V14***	12,400	\$1,736
211260095	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	926SA36060V14***	12,500	\$1,750
211260083	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	926SA30040V14***	12,300	\$1,722
211260069	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**2414AL*	82*SA36045V14***	12,400	\$1,736
211260055	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	OVMAAB042112	12,600	\$1,764
211260042	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	OVLAAB036098	12,500	\$1,750
211260028	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	OVMAAB036098	12,600	\$1,764
211260011	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	83*SA48060E17***	12,700	\$1,778
211259996	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	8(0,1)*SA36070E14***	12,200	\$1,708
211259979	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	912SD36040E17***	12,400	\$1,736
211259964	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	912SD30040E14***	12,400	\$1,736
211259947	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	912SD42060E17***	12,200	\$1,708
211259932	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	912SD36060E14***	12,500	\$1,750
211259917	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	8(0,1)*SA36070E17***	12,400	\$1,736
211259902	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	8(0,1)*SA36045E17***	12,700	\$1,778

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211259885	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	8(0,1)*SA36045E14***	12,400	\$1,736
211259871	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926TB42060V17***	12,300	\$1,722
211259855	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	915SB30026E14***	12,500	\$1,750
211259843	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926TB36060V14***	12,400	\$1,736
211259832	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926TB30040V14***	12,100	\$1,694
211259819	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	915SB36060E14***	12,300	\$1,722
211259807	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	915SB36040E17***	12,100	\$1,694
211259795	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	915SB30040E14***	12,400	\$1,736
211259785	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*TA48070V17***	12,000	\$1,680
211259774	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926TB48080V17***	12,100	\$1,694
211259762	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926TB36040V17***	12,300	\$1,722
211259759	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*TA48090V17***	12,200	\$1,708
211259757	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*TA36070V14***	12,200	\$1,708
211259743	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*TA36045V14***	12,200	\$1,708
211259728	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	83*SA36040E17***	12,600	\$1,764
211259716	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*SA48070V17***	12,100	\$1,694
211259703	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*SA48045V17***	12,200	\$1,708
211259664	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	935SA36040E17***	12,200	\$1,708
211259651	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926SA48080V17***	12,100	\$1,694

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211259639	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926SA36060V14***	12,400	\$1,736
211259626	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926SA36040V17***	12,300	\$1,722
211259613	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926SA30040V14***	12,100	\$1,694
211259602	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	926SA42060V17***	12,300	\$1,722
211259577	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	CAP**1917AL*	82*SA36045V14***	12,300	\$1,722
211257333	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	PF4MN*B24L*		12,800	\$1,792
211257332	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FJ4DN*B24L*		12,800	\$1,792
213076444	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CNPV*4217AL*	82*TB36045V14	29,400	\$4,116
213076420	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3717AL*	82*TB36045V14	29,200	\$4,088
213076408	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	CAP**3617AL*	82*TB36045V14	29,400	\$4,116
212600440	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*3017AL*+UI	88*TA48090C17***	31,200	\$4,368
212600390	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3017AL*+UI	88*TA48090C17***	31,000	\$4,340
212600380	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3017AL*+UI	88*TA36070C14***	31,200	\$4,368
212600370	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3017AL*+UI	88*TA48070C17***	31,200	\$4,368
212600360	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3017AL*+UI	83*CA48060C17***	31,200	\$4,368
212600350	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3017AL*+UI	83*CA36040C17***	31,200	\$4,368
210471321	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	987MB60060C21***	31,600	\$4,424
210471299	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	88*TA48090C17***	31,200	\$4,368
210471288	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	88*TA36070C14***	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210471277	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	986TC66100C21***	31,200	\$4,368
210471255	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	987MB66120C24***	31,400	\$4,396
210471244	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	987MB66100C21***	31,200	\$4,368
210471222	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	987MB42080C17***	31,600	\$4,424
210471211	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	986TC66120C24***	31,200	\$4,368
210471200	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	986TC42080C17***	31,600	\$4,424
210471189	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	88*TA66135C24***	31,200	\$4,368
210471178	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	88*TA60090C21***	31,400	\$4,396
210471167	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	88*TA48070C17***	31,400	\$4,396
210471156	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	83*CA60100C21***	31,400	\$4,396
210471145	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	83*CA48060C17***	31,400	\$4,396
210471134	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	83*CA36040C17***	31,400	\$4,396
210471123	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	935CA66100C21***	31,200	\$4,368
210471112	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*6012AL*+UI	935CA60080C21***	31,200	\$4,368
210471053	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	83*CA60100C21***	31,600	\$4,424
210471042	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	83*CA48060C17***	31,600	\$4,424
210471031	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	83*CA36040C17***	31,600	\$4,424
210471019	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CSPH*3612AL*+UI	935CA60080C21***	31,600	\$4,424
210471008	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	987MB60060C21***	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210470986	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	986TC66100C21***	31,200	\$4,368
210470964	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	987MB66120C24***	31,400	\$4,396
210470953	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	987MB66100C21***	31,200	\$4,368
210470931	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	986TC66120C24***	31,200	\$4,368
210470920	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	88*TA66135C24***	31,200	\$4,368
210470909	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	88*TA60090C21***	31,400	\$4,396
210470898	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	83*CA60100C21***	31,400	\$4,396
210470887	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	935CA66100C21***	31,200	\$4,368
210470876	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*6024AL*+UI	935CA60080C21***	31,200	\$4,368
210470855	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	83*CA60100C21***	31,600	\$4,424
210470844	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	935CA66100C21***	31,400	\$4,396
210470833	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4824AL*+UI	935CA60080C21***	31,400	\$4,396
210470810	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	83*CA48060C17***	31,600	\$4,424
210470799	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4821AL*+UI	83*CA36040C17***	31,600	\$4,424
210470777	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*4221AL*+UI	83*CA48060C17***	31,600	\$4,424
210470746	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*3621AL*+UI	986TC66100C21***	31,200	\$4,368
210470724	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CNPV*3621AL*+UI	987MB66100C21***	31,200	\$4,368
210470650	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	987MB60060C21***	31,400	\$4,396
210470628	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	986TC66100C21***	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210470606	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	987MB66120C24***	31,200	\$4,368
210470595	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	987MB66100C21***	31,200	\$4,368
210470573	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	986TC66120C24***	31,200	\$4,368
210470562	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	88*TA66135C24***	31,200	\$4,368
210470551	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	88*TA60090C21***	31,200	\$4,368
210470540	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	83*CA60100C21***	31,200	\$4,368
210470529	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	935CA66100C21***	31,200	\$4,368
210470518	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6124AL*+UI	935CA60080C21***	31,200	\$4,368
210470496	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	88*TA48090C17***	31,200	\$4,368
210470485	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	986TC66100C21***	31,200	\$4,368
210470463	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	987MB66100C21***	31,200	\$4,368
210470441	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	88*TA60090C21***	31,200	\$4,368
210470430	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	88*TA48070C17***	31,400	\$4,396
210470419	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	83*CA60100C21***	31,400	\$4,396
210470408	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	83*CA48060C17***	31,400	\$4,396
210470397	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	83*CA36040C17***	31,400	\$4,396
210470386	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	935CA66100C21***	31,200	\$4,368
210470375	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6121AL*+UI	935CA60080C21***	31,200	\$4,368
210470364	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	987MB60060C21***	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210470342	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	986TC66100C21***	31,000	\$4,340
210470320	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	987MB66120C24***	31,200	\$4,368
210470309	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	987MB66100C21***	31,000	\$4,340
210470287	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	986TC66120C24***	31,000	\$4,340
210470276	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	88*TA66135C24***	31,000	\$4,340
210470265	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	88*TA60090C21***	31,000	\$4,340
210470254	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	83*CA60100C21***	31,200	\$4,368
210470243	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	935CA66100C21***	31,000	\$4,340
210470232	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**6024AL*+UI	935CA60080C21***	31,000	\$4,340
210470158	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	83*CA60100C21***	31,400	\$4,396
210470146	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	83*CA36040C17***	31,400	\$4,396
210470134	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**4221AL*+UI	935CA60080C21***	31,200	\$4,368
210470099	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	83*CA60100C21***	31,200	\$4,368
210470088	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	83*CA48060C17***	31,200	\$4,368
210470077	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	83*CA36040C17***	31,200	\$4,368
210470066	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	935CA66100C21***	31,000	\$4,340
210470055	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3621AL*+UI	935CA60080C21***	31,000	\$4,340
210470041	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**B*	CAP**3617AL*+UI	83*CA48060C17***	31,400	\$4,396
212613994	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*3017AL*+UI	88*TA48090C17***	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212613984	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3017AL*+UI	88*TA48090C17***	31,000	\$4,340
212613974	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3017AL*+UI	88*TA48070C17***	31,200	\$4,368
212613964	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3017AL*+UI	88*TA36070C14***	31,200	\$4,368
212613954	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3017AL*+UI	83*CA48060C17***	31,200	\$4,368
212613944	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3017AL*+UI	83*CA36040C17***	31,200	\$4,368
210596613	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	987MB66120C24***	31,400	\$4,396
210596612	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	987MB66100C21***	31,200	\$4,368
210596610	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	987MB60060C21***	31,600	\$4,424
210596609	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	987MB42080C17***	31,600	\$4,424
210596608	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	986TC66120C24***	31,200	\$4,368
210596607	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	986TC66100C21***	31,200	\$4,368
210596605	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	986TC42080C17***	31,600	\$4,424
210596604	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	935CA66100C21***	31,200	\$4,368
210596603	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	935CA60080C21***	31,200	\$4,368
210596602	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	88*TA66135C24***	31,200	\$4,368
210596600	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	88*TA60090C21***	31,400	\$4,396
210596599	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	88*TA48090C17***	31,200	\$4,368
210596598	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	88*TA48070C17***	31,400	\$4,396
210596597	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	88*TA36070C14***	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210596596	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	83*CA60100C21***	31,400	\$4,396
210596595	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	83*CA48060C17***	31,400	\$4,396
210596594	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*6012AL*+UI	83*CA36040C17***	31,400	\$4,396
210596593	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	935CA60080C21***	31,600	\$4,424
210596592	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	83*CA60100C21***	31,600	\$4,424
210596591	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	83*CA48060C17***	31,600	\$4,424
210596590	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CSPH*3612AL*+UI	83*CA36040C17***	31,600	\$4,424
210596589	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	987MB66120C24***	31,400	\$4,396
210596588	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	987MB66100C21***	31,200	\$4,368
210596587	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	987MB60060C21***	31,600	\$4,424
210596586	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	986TC66120C24***	31,200	\$4,368
210596585	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	986TC66100C21***	31,200	\$4,368
210596583	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	935CA66100C21***	31,200	\$4,368
210596582	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	935CA60080C21***	31,200	\$4,368
210596581	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	88*TA66135C24***	31,200	\$4,368
210596579	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	88*TA60090C21***	31,400	\$4,396
210596578	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*6024AL*+UI	83*CA60100C21***	31,400	\$4,396
210596577	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4824AL*+UI	935CA66100C21***	31,400	\$4,396
210596576	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4824AL*+UI	935CA60080C21***	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210596575	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4824AL*+UI	83*CA60100C21***	31,600	\$4,424
210596574	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4821AL*+UI	83*CA48060C17***	31,600	\$4,424
210596573	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CNPV*4821AL*+UI	83*CA36040C17***	31,600	\$4,424
210596562	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	987MB66120C24***	31,200	\$4,368
210596561	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	987MB66100C21***	31,200	\$4,368
210596559	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	987MB60060C21***	31,400	\$4,396
210596558	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	986TC66120C24***	31,200	\$4,368
210596557	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	986TC66100C21***	31,200	\$4,368
210596555	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	935CA66100C21***	31,200	\$4,368
210596554	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	935CA60080C21***	31,200	\$4,368
210596553	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	88*TA66135C24***	31,200	\$4,368
210596551	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	88*TA60090C21***	31,200	\$4,368
210596550	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6124AL*+UI	83*CA60100C21***	31,200	\$4,368
210596549	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	987MB66100C21***	31,200	\$4,368
210596547	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	986TC66100C21***	31,200	\$4,368
210596545	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	935CA66100C21***	31,200	\$4,368
210596544	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	935CA60080C21***	31,200	\$4,368
210596542	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	88*TA60090C21***	31,200	\$4,368
210596541	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	88*TA48090C17***	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210596540	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	88*TA48070C17***	31,400	\$4,396
210596539	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	83*CA60100C21***	31,400	\$4,396
210596538	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	83*CA48060C17***	31,400	\$4,396
210596537	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6121AL*+UI	83*CA36040C17***	31,400	\$4,396
210596536	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	987MB66120C24***	31,200	\$4,368
210596535	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	987MB66100C21***	31,000	\$4,340
210596533	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	987MB60060C21***	31,400	\$4,396
210596532	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	986TC66120C24***	31,000	\$4,340
210596531	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	986TC66100C21***	31,000	\$4,340
210596529	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	935CA66100C21***	31,000	\$4,340
210596528	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	935CA60080C21***	31,000	\$4,340
210596527	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	88*TA66135C24***	31,000	\$4,340
210596525	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	88*TA60090C21***	31,000	\$4,340
210596524	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**6024AL*+UI	83*CA60100C21***	31,200	\$4,368
210596523	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4221AL*+UI	935CA60080C21***	31,200	\$4,368
210596522	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4221AL*+UI	83*CA60100C21***	31,400	\$4,396
210596521	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**4221AL*+UI	83*CA36040C17***	31,400	\$4,396
210596520	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3621AL*+UI	935CA66100C21***	31,000	\$4,340
210596519	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3621AL*+UI	935CA60080C21***	31,000	\$4,340

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210596518	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3621AL*+UI	83*CA60100C21***	31,200	\$4,368
210596517	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3621AL*+UI	83*CA48060C17***	31,200	\$4,368
210596516	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3621AL*+UI	83*CA36040C17***	31,200	\$4,368
210596515	BRYANT HEATING AND COOLING SYSTEMS	288BNV037*0**A*	CAP**3617AL*+UI	83*CA48060C17***	31,400	\$4,396
210474526	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*4812AL*+UI	88*TA66135C24***	20,600	\$2,884
210474515	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*4812AL*+UI	88*TA48070C17***	20,600	\$2,884
210474504	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*4812AL*+UI	88*TA36045C17***	20,800	\$2,912
210474460	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*4812AL*+UI	935CA66100C21***	20,600	\$2,884
210474449	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*4812AL*+UI	935CA60080C21***	20,600	\$2,884
210474416	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*4212AL*+UI	88*TA48090C17***	20,600	\$2,884
210474240	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*4212AL*+UI	935CA66100C21***	20,600	\$2,884
210474229	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*4212AL*+UI	935CA60080C21***	20,600	\$2,884
210474218	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*4212AL*+UI	935CA48060C17***	20,800	\$2,912
210474092	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4824AL*+UI	88*TA66135C24***	20,600	\$2,884
210474070	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4824AL*+UI	935CA66100C21***	20,600	\$2,884
210474059	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4824AL*+UI	935CA60080C21***	20,600	\$2,884
210473949	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4821AL*+UI	88*TA36045C17***	20,800	\$2,912
210473894	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4821AL*+UI	935CA60080C21***	20,600	\$2,884
210473883	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4821AL*+UI	935CA48060C17***	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210473861	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4221AL*+UI	88*TA48090C17***	20,600	\$2,884
210473729	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4221AL*+UI	935CA66100C21***	20,800	\$2,912
210473718	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4221AL*+UI	935CA60080C21***	20,800	\$2,912
210473696	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*4217AL*+UI	88*TA48090C17***	20,600	\$2,884
210473282	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4821AL*+UI	935CA66100C21***	20,400	\$2,856
210473260	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4821AL*+UI	935CA48060C17***	20,600	\$2,884
210473238	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4321AL*+UI	88*TA48090C17***	20,400	\$2,856
210473161	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4321AL*+UI	88*TA48070C17***	20,600	\$2,884
210473150	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4321AL*+UI	88*TA36045C17***	20,800	\$2,912
210473095	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4321AL*+UI	935CA60080C21***	20,600	\$2,884
210472996	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4224AL*+UI	935CA66100C21***	20,600	\$2,884
210472985	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4224AL*+UI	935CA60080C21***	20,600	\$2,884
210472963	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4221AL*+UI	88*TA48090C17***	20,600	\$2,884
210472875	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4221AL*+UI	88*TA36045C17***	20,800	\$2,912
210472820	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4221AL*+UI	935CA60080C21***	20,600	\$2,884
210472809	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CAP**4221AL*+UI	935CA48060C17***	20,800	\$2,912
206767684	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*3612AL*+UI	935CA48060C17***	20,800	\$2,912
206767657	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*3012AL*+UI	935CA48060C17***	21,000	\$2,940
206767648	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*2412AL*+UI	935CA66100C21***	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206767639	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*2412AL*+UI	935CA60080C21***	21,200	\$2,968
206766898	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*3612AL*+UI	88*TA36045C17***	20,800	\$2,912
206766736	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*3012AL*+UI	88*TA48070C17***	21,000	\$2,940
206766592	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*2412AL*+UI	88*TA66135C24***	21,200	\$2,968
206766565	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CSPH*2412AL*+UI	88*TA48070C17***	21,200	\$2,968
206766068	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**C*	CNPV*2417AL*+UI	88*TA36045C17***	21,200	\$2,968
210596451	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	987MB66120C24***	20,600	\$2,884
210596450	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	987MB66100C21***	20,600	\$2,884
210596449	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	987MB60060C21***	20,600	\$2,884
210596447	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	987MB42060C17***	20,800	\$2,912
210596445	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	986TC66100C21***	20,600	\$2,884
210596444	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	986TC42080C17***	20,600	\$2,884
210596442	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	935CA66100C21***	20,600	\$2,884
210596440	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	935CA48060C17***	20,600	\$2,884
210596439	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	88*TA66135C24***	20,600	\$2,884
210596435	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	88*TA36045C17***	20,800	\$2,912
210596433	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	83*CA48060C17***	20,600	\$2,884
210596432	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4812AL*+UI	83*CA36040C17***	20,600	\$2,884
210596424	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4212AL*+UI	986TC42080C17***	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210596423	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4212AL*+UI	986TC42060C17***	20,800	\$2,912
210596422	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4212AL*+UI	935CA66100C21***	20,600	\$2,884
210596421	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4212AL*+UI	935CA60080C21***	20,600	\$2,884
210596420	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4212AL*+UI	935CA48060C17***	20,800	\$2,912
210596419	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4212AL*+UI	88*TA66135C24***	20,600	\$2,884
210596417	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4212AL*+UI	88*TA48070C17***	20,600	\$2,884
210596415	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*4212AL*+UI	88*TA36045C17***	20,800	\$2,912
210596409	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4824AL*+UI	987MB60060C21***	20,600	\$2,884
210596408	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4824AL*+UI	986TC66120C24***	20,600	\$2,884
210596406	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4824AL*+UI	935CA66100C21***	20,600	\$2,884
210596404	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4824AL*+UI	88*TA66135C24***	20,600	\$2,884
210596403	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4824AL*+UI	83*CA60100C21***	20,600	\$2,884
210596402	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4821AL*+UI	987MB66100C21***	20,600	\$2,884
210596397	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4821AL*+UI	986TC42080C17***	20,600	\$2,884
210596393	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4821AL*+UI	935CA48060C17***	20,600	\$2,884
210596389	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4821AL*+UI	83*CA60100C21***	20,600	\$2,884
210596387	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4821AL*+UI	83*CA36040C17***	20,600	\$2,884
210596376	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4221AL*+UI	88*TA48090C17***	20,600	\$2,884
210596370	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4217AL*+UI	987MB42080C17***	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210596368	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4217AL*+UI	986TC42080C17***	20,800	\$2,912
210596366	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4217AL*+UI	935CA48060C17***	20,800	\$2,912
210596364	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4217AL*+UI	88*TA48070C17***	20,800	\$2,912
210596361	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CNPV*4217AL*+UI	83*CA48060C17***	20,800	\$2,912
210596359	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4824AL*+UI	987MB66120C24***	20,400	\$2,856
210596358	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4824AL*+UI	987MB66100C21***	20,400	\$2,856
210596357	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4824AL*+UI	987MB60060C21***	20,400	\$2,856
210596355	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4824AL*+UI	986TC66100C21***	20,400	\$2,856
210596354	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4824AL*+UI	935CA66100C21***	20,400	\$2,856
210596352	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4824AL*+UI	88*TA66135C24***	20,400	\$2,856
210596349	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	987MB60060C21***	20,600	\$2,884
210596348	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	987MB42080C17***	20,600	\$2,884
210596345	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	986TC42080C17***	20,400	\$2,856
210596344	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	986TC42060C17***	20,600	\$2,884
210596343	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	935CA66100C21***	20,400	\$2,856
210596341	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	935CA48060C17***	20,600	\$2,884
210596340	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	88*TA48090C17***	20,400	\$2,856
210596339	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	88*TA48070C17***	20,400	\$2,856
210596338	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	88*TA36045C17***	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210596337	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	83*CA60100C21***	20,400	\$2,856
210596336	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	83*CA48060C17***	20,400	\$2,856
210596335	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4821AL*+UI	83*CA36040C17***	20,400	\$2,856
210596331	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4321AL*+UI	987MB42060C17***	20,800	\$2,912
210596328	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4321AL*+UI	986TC42060C17***	20,600	\$2,884
210596327	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4321AL*+UI	935CA66100C21***	20,600	\$2,884
210596322	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4321AL*+UI	88*TA36045C17***	20,800	\$2,912
210596321	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4321AL*+UI	83*CA60100C21***	20,600	\$2,884
210596320	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4321AL*+UI	83*CA48060C17***	20,600	\$2,884
210596318	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4224AL*+UI	987MB66120C24***	20,800	\$2,912
210596317	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4224AL*+UI	987MB66100C21***	20,600	\$2,884
210596316	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4224AL*+UI	987MB60060C21***	20,800	\$2,912
210596313	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4224AL*+UI	935CA66100C21***	20,600	\$2,884
210596312	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4224AL*+UI	935CA60080C21***	20,600	\$2,884
210596311	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4224AL*+UI	88*TA66135C24***	20,600	\$2,884
210596310	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4224AL*+UI	83*CA60100C21***	20,800	\$2,912
210596305	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4221AL*+UI	986TC66100C21***	20,600	\$2,884
210596302	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4221AL*+UI	935CA66100C21***	20,600	\$2,884
210596301	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4221AL*+UI	935CA60080C21***	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210596300	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4221AL*+UI	935CA48060C17***	20,800	\$2,912
210596297	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4221AL*+UI	88*TA36045C17***	20,800	\$2,912
210596296	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4221AL*+UI	83*CA60100C21***	20,800	\$2,912
210596294	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CAP**4221AL*+UI	83*CA36040C17***	20,600	\$2,884
206133973	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	935CA48060C17***	20,800	\$2,912
206133963	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3012AL*+UI	935CA66100C21***	21,000	\$2,940
206133717	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	83*CA60100C21***	20,800	\$2,912
206133677	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3012AL*+UI	83*CA60100C21***	21,000	\$2,940
204459430	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	987MB60060C21***	20,800	\$2,912
204459322	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3612AL*+UI	986TC42080C17***	20,800	\$2,912
204459196	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3012AL*+UI	987MB66100C21***	21,000	\$2,940
204459178	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3012AL*+UI	987MB42080C17***	21,000	\$2,940
204459151	BRYANT HEATING AND COOLING SYSTEMS	288BNV025*0**B*	CSPH*3012AL*+UI	986TC42080C17***	21,000	\$2,940
210532923	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CSPH*4812AL*+UI	88*TA66135C24***	43,500	\$6,090
210532921	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CSPH*4812AL*+UI	88*TA60090C21***	43,500	\$6,090
210532917	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CSPH*4812AL*+UI	935CA66100C21***	43,500	\$6,090
210532915	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CSPH*4812AL*+UI	935CA60080C21***	43,500	\$6,090
210532905	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CNPV*4824AL*+UI	88*TA66135C24***	43,500	\$6,090
210532903	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CNPV*4824AL*+UI	88*TA60090C21***	43,500	\$6,090

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210532899	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CNPV*4824AL*+UI	935CA66100C21***	43,500	\$6,090
210532897	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CNPV*4824AL*+UI	935CA60080C21***	43,500	\$6,090
210532893	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CNPV*4821AL*+UI	88*TA60090C21***	43,500	\$6,090
210532889	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CNPV*4821AL*+UI	935CA66100C21***	43,500	\$6,090
210532887	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CNPV*4821AL*+UI	935CA60080C21***	43,500	\$6,090
210532881	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6124AL*+UI	88*TA60090C21***	43,500	\$6,090
210532877	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**6024AL*+UI	88*TA60090C21***	43,000	\$6,020
210532871	BRYANT HEATING AND COOLING SYSTEMS	284ANV048*0**B*	CAP**4824AL*+UI	88*TA60090C21***	43,500	\$6,090
210533111	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*4212AL*+UI	935CA66100C21***	24,600	\$3,444
210533109	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*4212AL*+UI	935CA60080C21***	24,600	\$3,444
210533107	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*4212AL*+UI	935CA48060C17***	24,800	\$3,472
210533103	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3012AL*+UI	88*TA48090C17***	24,800	\$3,472
210533101	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3012AL*+UI	88*TA36070C14***	25,000	\$3,500
210533093	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3012AL*+UI	88*TA48070C17***	25,000	\$3,500
210533087	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3012AL*+UI	935CA66100C21***	25,000	\$3,500
210533085	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3012AL*+UI	935CA60080C21***	25,000	\$3,500
210533083	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CSPH*3012AL*+UI	935CA48060C17***	25,200	\$3,528
210533077	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4221AL*+UI	935CA66100C21***	24,800	\$3,472
210533075	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4221AL*+UI	935CA60080C21***	24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210533073	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4221AL*+UI	935CA48060C17***	25,000	\$3,500
210533067	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*4217AL*+UI	935CA48060C17***	25,000	\$3,500
210533065	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3017AL*+UI	88*TA48090C17***	24,800	\$3,472
210533063	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3017AL*+UI	88*TA36070C14***	25,000	\$3,500
210533055	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3017AL*+UI	88*TA48070C17***	25,000	\$3,500
210533049	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CNPV*3017AL*+UI	935CA48060C17***	25,200	\$3,528
210533045	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4321AL*+UI	88*TA48090C17***	24,600	\$3,444
210533037	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4321AL*+UI	88*TA48070C17***	24,800	\$3,472
210533031	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4321AL*+UI	935CA66100C21***	24,600	\$3,444
210533029	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4321AL*+UI	935CA60080C21***	24,600	\$3,444
210533027	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4321AL*+UI	935CA48060C17***	24,800	\$3,472
210533025	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4224AL*+UI	935CA66100C21***	24,800	\$3,472
210533023	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4224AL*+UI	935CA60080C21***	24,800	\$3,472
210533017	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4221AL*+UI	935CA66100C21***	24,800	\$3,472
210533015	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4221AL*+UI	935CA60080C21***	24,800	\$3,472
210533013	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**4221AL*+UI	935CA48060C17***	25,000	\$3,500
210533009	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3721AL*+UI	88*TA48090C17***	24,600	\$3,444
210533001	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3721AL*+UI	88*TA48070C17***	24,800	\$3,472
210532995	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3721AL*+UI	935CA66100C21***	24,600	\$3,444

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210532993	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3721AL*+UI	935CA60080C21***	24,600	\$3,444
210532991	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3721AL*+UI	935CA48060C17***	24,800	\$3,472
210532989	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3017AL*+UI	88*TA48090C17***	24,800	\$3,472
210532987	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3017AL*+UI	88*TA36070C14***	25,000	\$3,500
210532979	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3017AL*+UI	88*TA48070C17***	25,000	\$3,500
210532977	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3017AL*+UI	88*TA36045C17***	25,200	\$3,528
210532971	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3017AL*+UI	935CA48060C17***	25,200	\$3,528
210532969	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**3014AL*+UI	88*TA36070C14***	25,000	\$3,500
210532967	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**2517AL*+UI	88*TA48090C17***	24,600	\$3,444
210532965	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**2517AL*+UI	88*TA36070C14***	24,800	\$3,472
210532957	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**2517AL*+UI	88*TA48070C17***	24,800	\$3,472
210532951	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**2517AL*+UI	935CA48060C17***	25,000	\$3,500
210532949	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**2417AL*+UI	88*TA48090C17***	25,000	\$3,500
210532947	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**2417AL*+UI	88*TA36070C14***	25,200	\$3,528
210532939	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**2417AL*+UI	88*TA48070C17***	25,200	\$3,528
210532933	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**2417AL*+UI	935CA48060C17***	25,400	\$3,556
210532931	BRYANT HEATING AND COOLING SYSTEMS	284ANV024*0**B*	CAP**2414AL*+UI	88*TA36070C14***	25,200	\$3,528
211201017	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	FX4DN(B,F)037L		23,200	\$3,248
211230815	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FB4CNF042L		29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230826	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FB4CNF048L		29,400	\$4,116
211230837	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FB4CNP042L		29,200	\$4,088
211230849	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FB4CNP048L		29,400	\$4,116
211230872	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FMA4P36**AL*		29,800	\$4,172
211230904	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FX4DN(B,F)037L		29,000	\$4,060
211230937	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ36AB3*	FZ4ANP048L		29,000	\$4,060
211719726	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FMA4P18**AL*		12,700	\$1,778
211264855	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FX4DNF019L		12,300	\$1,722
211264831	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FB4CNP025L		12,100	\$1,694
211264824	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FB4CNP024L		12,300	\$1,722
211264800	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FB4CNP018L		12,300	\$1,722
211264778	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FB4CNF024L		12,300	\$1,722
211264756	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FB4CNF018L		12,300	\$1,722
211264754	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ18AB3*	FZ4ANP024L		12,200	\$1,708
212971159	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	82*TB36045V14	19,100	\$2,674
212971171	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	82*TB36045V14	19,000	\$2,660
212971183	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	82*TB36045V14	18,700	\$2,618
212971195	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	82*TB36045V14	19,500	\$2,730
212971207	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	82*TB36045V14	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971219	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	82*TB36045V14	19,000	\$2,660
212971231	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	82*TB36045V14	19,100	\$2,674
212971243	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	82*TB36045V14	19,100	\$2,674
212978654	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	8(0,1)*SB36070M17***	19,000	\$2,660
212978665	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3621AL*	8(0,1)*SB36070M17***	19,000	\$2,660
212978676	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	8(0,1)*SB36070M17***	18,700	\$2,618
212978687	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3721AL*	8(0,1)*SB36070M17***	18,500	\$2,590
212978698	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	8(0,1)*SB36070M17***	19,400	\$2,716
212978709	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	8(0,1)*SB36070M17***	18,900	\$2,646
212978720	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3617AL*	8(0,1)*SB36070M17***	18,900	\$2,646
212978731	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3621AL*	8(0,1)*SB36070M17***	19,000	\$2,660
212979120	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2417AL*	8(0,1)*SB48070M17***	19,400	\$2,716
212986152	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**2517AL*	916SA30040M14***	18,800	\$2,632
212986164	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3014AL*	916SA30040M14***	19,200	\$2,688
212986176	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3017AL*	916SA30040M14***	19,200	\$2,688
212986188	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3617AL*	916SA30040M14***	19,200	\$2,688
212986200	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CAP**3717AL*	916SA30040M14***	18,800	\$2,632
212986212	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2414AL*	916SA30040M14***	19,500	\$2,730
212986224	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*2417AL*	916SA30040M14***	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986236	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3014AL*	916SA30040M14***	19,200	\$2,688
212986248	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ24AB3*	CNPV*3017AL*	916SA30040M14***	19,200	\$2,688
212971339	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CNPV*4217AL*	82*TB36045V14	23,400	\$3,276
212971291	BRYANT HEATING AND COOLING SYSTEMS	38MURAQ30AB3*	CAP**3717AL*	82*TB36045V14	23,400	\$3,276
213785761	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	986TD66120C24***	31,800	\$4,452
213785759	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	986TD66100C21***	31,800	\$4,452
213785757	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	986TD42080C17***	32,000	\$4,480
213785755	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	986TD42060C17***	32,200	\$4,508
213785753	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	987MC66120C24***	32,000	\$4,480
213785751	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	987MC66100C21***	31,800	\$4,452
213785749	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	987MC42080C17***	32,000	\$4,480
213785747	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	987MC42060C17***	32,200	\$4,508
213785745	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	935CB48060C17***	32,000	\$4,480
213785743	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	88*TB66135C24***	31,800	\$4,452
213785741	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	88*TB60110C21***	31,800	\$4,452
213785739	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	88*TB60090C21***	31,800	\$4,452
213785737	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	88*TB48090C17***	32,000	\$4,480
213785735	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	88*TB48070C17***	32,000	\$4,480
213785733	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	88*TB36070C14***	32,000	\$4,480

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785731	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	88*TB36045C17***	32,200	\$4,508
213785729	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	986TD66120C24***	32,600	\$4,564
213785727	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	986TD66100C21***	32,600	\$4,564
213785725	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	986TD42080C17***	32,800	\$4,592
213785723	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	986TD42060C17***	33,000	\$4,620
213785721	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	987MC66120C24***	32,800	\$4,592
213785719	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	987MC66100C21***	32,600	\$4,564
213785717	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	987MC42080C17***	32,800	\$4,592
213785715	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	987MC42060C17***	33,000	\$4,620
213785713	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	935CB48060C17***	32,800	\$4,592
213785711	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	88*TB66135C24***	32,600	\$4,564
213785709	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	88*TB60110C21***	32,600	\$4,564
213785707	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	88*TB60090C21***	32,600	\$4,564
213785705	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	88*TB48090C17***	32,800	\$4,592
213785703	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	88*TB48070C17***	32,800	\$4,592
213785701	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	88*TB36070C14***	32,800	\$4,592
213785699	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4812AL*+UI	88*TB36045C17***	33,000	\$4,620
213785697	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	986TD66120C24***	32,800	\$4,592
213785695	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	986TD66100C21***	32,800	\$4,592

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785693	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	986TD42080C17***	33,000	\$4,620
213785691	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	986TD42060C17***	33,000	\$4,620
213785689	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	987MC66120C24***	32,800	\$4,592
213785687	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	987MC66100C21***	32,800	\$4,592
213785685	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	987MC42080C17***	33,000	\$4,620
213785683	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	987MC42060C17***	33,200	\$4,648
213785681	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	935CB48060C17***	33,000	\$4,620
213785679	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	88*TB66135C24***	32,800	\$4,592
213785677	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	88*TB60110C21***	32,800	\$4,592
213785675	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	88*TB60090C21***	32,800	\$4,592
213785673	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	88*TB48090C17***	32,800	\$4,592
213785671	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	88*TB48070C17***	33,000	\$4,620
213785669	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	88*TB36070C14***	33,000	\$4,620
213785667	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*4212AL*+UI	88*TB36045C17***	33,200	\$4,648
213785665	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	986TD66120C24***	33,200	\$4,648
213785663	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	986TD66100C21***	33,200	\$4,648
213785661	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	986TD42080C17***	33,400	\$4,676
213785659	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	986TD42060C17***	33,400	\$4,676
213785657	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	987MC66120C24***	33,200	\$4,648

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785655	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	987MC66100C21***	33,200	\$4,648
213785653	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	987MC42080C17***	33,400	\$4,676
213785651	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	987MC42060C17***	33,400	\$4,676
213785649	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	935CB48060C17***	33,400	\$4,676
213785647	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	88*TB66135C24***	33,200	\$4,648
213785645	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	88*TB60110C21***	33,200	\$4,648
213785643	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	88*TB60090C21***	33,200	\$4,648
213785641	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	88*TB48090C17***	33,200	\$4,648
213785639	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	88*TB48070C17***	33,400	\$4,676
213785637	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	88*TB36070C14***	33,400	\$4,676
213785635	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3612AL*+UI	88*TB36045C17***	33,600	\$4,704
213785633	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	986TD66120C24***	34,000	\$4,760
213785631	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	986TD66100C21***	34,000	\$4,760
213785629	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	986TD42080C17***	34,200	\$4,788
213785627	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	986TD42060C17***	34,400	\$4,816
213785625	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	987MC66120C24***	34,200	\$4,788
213785623	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	987MC66100C21***	34,000	\$4,760
213785621	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	987MC42080C17***	34,200	\$4,788
213785619	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	987MC42060C17***	34,400	\$4,816

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785617	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	935CB48060C17***	34,200	\$4,788
213785615	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	88*TB66135C24***	34,000	\$4,760
213785613	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	88*TB60110C21***	34,000	\$4,760
213785611	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	88*TB60090C21***	34,000	\$4,760
213785609	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	88*TB48090C17***	34,200	\$4,788
213785607	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	88*TB48070C17***	34,200	\$4,788
213785605	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	88*TB36070C14***	34,200	\$4,788
213785603	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*3012AL*+UI	88*TB36045C17***	34,400	\$4,816
213785601	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	986TD66120C24***	34,400	\$4,816
213785599	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	986TD66100C21***	34,400	\$4,816
213785597	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	986TD42080C17***	34,600	\$4,844
213785595	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	986TD42060C17***	34,800	\$4,872
213785593	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	987MC66120C24***	34,600	\$4,844
213785591	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	987MC66100C21***	34,400	\$4,816
213785589	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	987MC42080C17***	34,600	\$4,844
213785587	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	987MC42060C17***	34,800	\$4,872
213785585	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	935CB48060C17***	34,600	\$4,844
213785583	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	88*TB66135C24***	34,400	\$4,816
213785581	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	88*TB60110C21***	34,400	\$4,816

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785579	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	88*TB60090C21***	34,400	\$4,816
213785577	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	88*TB48090C17***	34,600	\$4,844
213785575	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	88*TB48070C17***	34,600	\$4,844
213785573	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	88*TB36070C14***	34,600	\$4,844
213785571	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*2412AL*+UI	88*TB36045C17***	34,800	\$4,872
213785569	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	986TD66120C24***	31,600	\$4,424
213785567	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	986TD66100C21***	31,600	\$4,424
213785565	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	987MC66120C24***	31,600	\$4,424
213785563	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	987MC66100C21***	31,600	\$4,424
213785561	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	88*TB66135C24***	31,600	\$4,424
213785559	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	88*TB60110C21***	31,600	\$4,424
213785557	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	88*TB60090C21***	31,600	\$4,424
213785555	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	986TD66100C21***	31,600	\$4,424
213785553	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	986TD42080C17***	31,800	\$4,452
213785551	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	986TD42060C17***	31,800	\$4,452
213785549	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	987MC66100C21***	31,600	\$4,424
213785547	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	987MC42080C17***	31,800	\$4,452
213785545	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	987MC42060C17***	32,000	\$4,480
213785543	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	935CB48060C17***	31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785541	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	88*TB60110C21***	31,600	\$4,424
213785539	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	88*TB60090C21***	31,600	\$4,424
213785537	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	88*TB48090C17***	31,600	\$4,424
213785535	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	88*TB48070C17***	31,800	\$4,452
213785533	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	88*TB36045C17***	32,000	\$4,480
213785531	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	986TD66120C24***	31,600	\$4,424
213785529	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	986TD66100C21***	31,600	\$4,424
213785527	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	987MC66120C24***	31,600	\$4,424
213785525	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	987MC66100C21***	31,600	\$4,424
213785523	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	88*TB66135C24***	31,600	\$4,424
213785521	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	88*TB60110C21***	31,600	\$4,424
213785519	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	88*TB60090C21***	31,600	\$4,424
213785517	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	986TD66120C24***	32,600	\$4,564
213785515	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	986TD66100C21***	32,600	\$4,564
213785513	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	987MC66120C24***	32,600	\$4,564
213785511	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	987MC66100C21***	32,600	\$4,564
213785509	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	88*TB66135C24***	32,600	\$4,564
213785507	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	88*TB60110C21***	32,600	\$4,564
213785505	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4824AL*+UI	88*TB60090C21***	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785503	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	986TD66100C21***	32,600	\$4,564
213785501	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	986TD42080C17***	32,800	\$4,592
213785499	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	986TD42060C17***	32,800	\$4,592
213785497	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	987MC66100C21***	32,600	\$4,564
213785495	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	987MC42080C17***	32,800	\$4,592
213785493	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	987MC42060C17***	32,800	\$4,592
213785491	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	935CB48060C17***	32,800	\$4,592
213785489	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	88*TB60110C21***	32,600	\$4,564
213785487	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	88*TB60090C21***	32,600	\$4,564
213785485	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	88*TB48090C17***	32,600	\$4,564
213785483	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	88*TB48070C17***	32,600	\$4,564
213785481	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4821AL*+UI	88*TB36045C17***	32,800	\$4,592
213785479	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	986TD66100C21***	32,400	\$4,536
213785477	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	986TD42080C17***	32,600	\$4,564
213785475	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	986TD42060C17***	32,600	\$4,564
213785473	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	987MC66100C21***	32,400	\$4,536
213785471	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	987MC42080C17***	32,600	\$4,564
213785469	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	987MC42060C17***	32,600	\$4,564
213785467	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	935CB48060C17***	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785465	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	88*TB60110C21***	32,400	\$4,536
213785463	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	88*TB60090C21***	32,400	\$4,536
213785461	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	88*TB48090C17***	32,400	\$4,536
213785459	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	88*TB48070C17***	32,600	\$4,564
213785457	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4321AL*+UI	88*TB36045C17***	32,800	\$4,592
213785455	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	986TD66120C24***	33,600	\$4,704
213785453	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	986TD66100C21***	33,600	\$4,704
213785451	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	987MC66120C24***	33,800	\$4,732
213785449	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	987MC66100C21***	33,600	\$4,704
213785447	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	88*TB66135C24***	33,600	\$4,704
213785445	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	88*TB60110C21***	33,600	\$4,704
213785443	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4224AL*+UI	88*TB60090C21***	33,600	\$4,704
213785441	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	986TD66100C21***	33,600	\$4,704
213785439	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	986TD42080C17***	33,800	\$4,732
213785437	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	986TD42060C17***	34,000	\$4,760
213785435	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	987MC66100C21***	33,600	\$4,704
213785433	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	987MC42080C17***	33,800	\$4,732
213785431	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	987MC42060C17***	34,000	\$4,760
213785429	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	935CB48060C17***	33,800	\$4,732

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785427	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	88*TB60110C21***	33,600	\$4,704
213785425	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	88*TB60090C21***	33,600	\$4,704
213785423	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	88*TB48090C17***	33,800	\$4,732
213785421	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	88*TB48070C17***	33,800	\$4,732
213785419	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	88*TB36045C17***	34,000	\$4,760
213785417	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	986TD66100C21***	32,400	\$4,536
213785415	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	986TD42080C17***	32,600	\$4,564
213785413	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	986TD42060C17***	32,600	\$4,564
213785411	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	987MC66100C21***	32,400	\$4,536
213785409	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	987MC42080C17***	32,600	\$4,564
213785407	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	987MC42060C17***	32,600	\$4,564
213785405	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	935CB48060C17***	32,600	\$4,564
213785403	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	88*TB60110C21***	32,400	\$4,536
213785401	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	88*TB60090C21***	32,400	\$4,536
213785399	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	88*TB48090C17***	32,400	\$4,536
213785397	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	88*TB48070C17***	32,600	\$4,564
213785395	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3721AL*+UI	88*TB36045C17***	32,800	\$4,592
213785393	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	986TD42080C17***	33,000	\$4,620
213785391	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	986TD42060C17***	33,200	\$4,648

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785389	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	987MC42080C17***	33,000	\$4,620
213785385	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	935CB48060C17***	33,000	\$4,620
213785383	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	88*TB48090C17***	33,000	\$4,620
213785381	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	88*TB48070C17***	33,000	\$4,620
213785379	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	88*TB36070C14***	33,000	\$4,620
213785377	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	88*TB36045C17***	33,200	\$4,648
213785375	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	986TD66100C21***	34,200	\$4,788
213785373	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	986TD42080C17***	34,200	\$4,788
213785371	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	986TD42060C17***	34,400	\$4,816
213785369	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	987MC66100C21***	34,200	\$4,788
213785367	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	987MC42080C17***	34,400	\$4,816
213785365	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	987MC42060C17***	34,400	\$4,816
213785363	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	935CB48060C17***	34,200	\$4,788
213785361	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	88*TB60110C21***	34,200	\$4,788
213785359	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	88*TB60090C21***	34,200	\$4,788
213785357	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	88*TB48090C17***	34,200	\$4,788
213785355	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	88*TB48070C17***	34,200	\$4,788
213785353	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3621AL*+UI	88*TB36045C17***	34,400	\$4,816
213785351	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3617AL*+UI	986TD42080C17***	34,400	\$4,816

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785349	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3617AL*+UI	986TD42060C17***	34,400	\$4,816
213785347	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3617AL*+UI	987MC42080C17***	34,400	\$4,816
213785343	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3617AL*+UI	935CB48060C17***	34,400	\$4,816
213785341	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3617AL*+UI	88*TB48090C17***	34,200	\$4,788
213785339	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3617AL*+UI	88*TB48070C17***	34,400	\$4,816
213785337	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3617AL*+UI	88*TB36070C14***	34,400	\$4,816
213785335	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3617AL*+UI	88*TB36045C17***	34,400	\$4,816
213785333	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3017AL*+UI	986TD42080C17***	34,600	\$4,844
213785331	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3017AL*+UI	986TD42060C17***	34,800	\$4,872
213785329	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3017AL*+UI	987MC42080C17***	34,600	\$4,844
213785327	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3017AL*+UI	987MC42060C17***	34,800	\$4,872
213785325	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3017AL*+UI	935CB48060C17***	34,600	\$4,844
213785323	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3017AL*+UI	88*TB48090C17***	34,400	\$4,816
213785321	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3017AL*+UI	88*TB48070C17***	34,600	\$4,844
213785319	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3017AL*+UI	88*TB36070C14***	34,600	\$4,844
213785317	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3017AL*+UI	88*TB36045C17***	34,800	\$4,872
213785315	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3014AL*+UI	88*TB36070C14***	34,800	\$4,872
213785313	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2517AL*+UI	986TD42080C17***	32,800	\$4,592
213785311	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2517AL*+UI	986TD42060C17***	32,800	\$4,592

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785309	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2517AL*+UI	987MC42080C17***	32,800	\$4,592
213785307	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2517AL*+UI	987MC42060C17***	33,000	\$4,620
213785305	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2517AL*+UI	935CB48060C17***	32,800	\$4,592
213785303	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2517AL*+UI	88*TB48090C17***	32,600	\$4,564
213785301	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2517AL*+UI	88*TB48070C17***	32,800	\$4,592
213785299	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2517AL*+UI	88*TB36070C14***	32,800	\$4,592
213785297	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2517AL*+UI	88*TB36045C17***	33,000	\$4,620
213785295	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2417AL*+UI	986TD42080C17***	35,600	\$4,984
213785293	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2417AL*+UI	986TD42060C17***	35,800	\$5,012
213785291	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2417AL*+UI	987MC42080C17***	35,600	\$4,984
213785289	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2417AL*+UI	987MC42060C17***	35,800	\$5,012
213785287	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2417AL*+UI	935CB48060C17***	35,600	\$4,984
213785285	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2417AL*+UI	88*TB48090C17***	35,600	\$4,984
213785283	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2417AL*+UI	88*TB48070C17***	35,600	\$4,984
213785281	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2417AL*+UI	88*TB36070C14***	35,600	\$4,984
213785279	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2417AL*+UI	88*TB36045C17***	35,800	\$5,012
213785277	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**2414AL*+UI	88*TB36070C14***	35,800	\$5,012
213361588	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	FE4BNBD60L*+UI		29,800	\$4,172
213361586	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	FE4BN(B,X)C48L*+UI		30,400	\$4,256

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213361584	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	FE4BN(B,X)C36L*+UI		31,600	\$4,424
210720694	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	83*CA60100C21***	30,400	\$4,256
210720692	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	83*CA48060C17***	30,400	\$4,256
210720690	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CSPH*6012AL*+UI	83*CA36040C17***	30,400	\$4,256
210720684	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*6024AL*+UI	83*CA60100C21***	30,600	\$4,284
210720678	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4824AL*+UI	83*CA60100C21***	31,400	\$4,396
210720674	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4821AL*+UI	83*CA48060C17***	31,400	\$4,396
210720672	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4821AL*+UI	83*CA36040C17***	31,200	\$4,368
210720668	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4221AL*+UI	83*CA48060C17***	32,200	\$4,508
210720666	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CNPV*4221AL*+UI	83*CA36040C17***	32,000	\$4,480
210720660	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6124AL*+UI	83*CA60100C21***	30,000	\$4,200
210720652	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	83*CA60100C21***	30,200	\$4,228
210720650	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	83*CA48060C17***	30,200	\$4,228
210720648	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6121AL*+UI	83*CA36040C17***	30,000	\$4,200
210720642	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**6024AL*+UI	83*CA60100C21***	30,200	\$4,228
210720638	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**4221AL*+UI	986TC42080C17***	32,200	\$4,508
210720634	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	986TC42080C17***	31,400	\$4,396
210720632	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	986TC42060C17***	31,600	\$4,424
210720630	BRYANT HEATING AND COOLING SYSTEMS	284ANV036*0**B*	CAP**3717AL*+UI	987MB42080C17***	31,600	\$4,424
217155427	C&H	CH-RHP19M-230VO	Heat pump with ducts		17,000	\$2,380

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
217155426	C&H	CH-RHP19M-230VO	Heat pump without ducts		17,600	\$2,464
217155430	C&H	CH-RHP28M-230VO	Heat pump with ducts		23,000	\$3,220
217155429	C&H	CH-RHP28M-230VO	Heat pump without ducts		25,000	\$3,500
217155428	C&H	CH-RHP19M-230VO	Combination heat pumps with or without ducts		17,300	\$2,422
217155432	C&H	CH-RHP36M-230VO	Heat pump without ducts		30,000	\$4,200
217155431	C&H	CH-RHP28M-230VO	Combination heat pumps with or without ducts		24,000	\$3,360
217155433	C&H	CH-RHP36M-230VO	Heat pump with ducts		33,000	\$4,620
217155435	C&H	CH-RHP48M-230VO	Heat pump without ducts		44,000	\$6,160
217155434	C&H	CH-RHP36M-230VO	Combination heat pumps with or without ducts		31,400	\$4,396
217155436	C&H	CH-RHP48M-230VO	Heat pump with ducts		44,500	\$6,230
217155437	C&H	CH-RHP48M-230VO	Combination heat pumps with or without ducts		44,000	\$6,160
217155439	C&H	CH-RHP55M-230VO	Heat pump with ducts		45,000	\$6,300
217155438	C&H	CH-RHP55M-230VO	Heat pump without ducts		44,000	\$6,160
217155440	C&H	CH-RHP55M-230VO	Combination heat pumps with or without ducts		44,500	\$6,230
207740502	C&H	CH-HPR12-230VO	CH-12MASTWM-230VI		10,000	\$1,400
207740503	C&H	CH-HPR18-230VO	CH-18MASTWM-230VI		15,000	\$2,100
207740504	C&H	CH-HPR24-230VO	CH-24MASTWM-230VI		21,200	\$2,968
207742329	C&H	CH-HPR12-230VO	CH-12MSPHCT-230VI		9,900	\$1,386
207742331	C&H	CH-HPR12-230VO	CH-12MSPHMC-230VI		9,600	\$1,344
207742333	C&H	CH-HPR18-230VO	CH-M18DTUI		15,000	\$2,100
207742335	C&H	CH-HPR24-230VO	CH-N24MSPHCT-230VI		21,000	\$2,940
209937052	C&H	CH-HPR12-230VO	CH-12MMC-230VI		10,200	\$1,428
207742377	C&H	CH-HPR28M-230VO	Heat pump with ducts		27,000	\$3,780
208497429	C&H	CH-HPR55M-230VO	Heat pump with ducts		35,200	\$4,928
207742378	C&H	CH-HPR28M-230VO	Combination heat pumps with or without ducts		26,800	\$3,752
208497430	C&H	CH-HPR55M-230VO	Combination heat pumps with or without ducts		34,800	\$4,872
208497428	C&H	CH-HPR55M-230VO	Heat pump without ducts		34,400	\$4,816
207742381	C&H	CH-HPR48M-230VO	Heat pump without ducts		36,000	\$5,040
207742376	C&H	CH-HPR28M-230VO	Heat pump without ducts		26,600	\$3,724
207742373	C&H	CH-HPR19M-230VO	Heat pump without ducts		15,000	\$2,100
207740520	C&H	CH-HPR12-230VO	CH-12MOLVWM-230VI		10,300	\$1,442
210665993	C&H	CH-HPR12-230VO	CH-B12MOLVWM-230VI		10,300	\$1,442

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207740521	C&H	CH-HPR18-230VO	CH-18MOLVWM-230VI		11,100	\$1,554
210665994	C&H	CH-HPR18-230VO	CH-B18MOLVWM-230VI		11,100	\$1,554
207740522	C&H	CH-HPR24-230VO	CH-24MOLVWM-230VI		18,900	\$2,646
210665995	C&H	CH-HPR24-230VO	CH-B24MOLVWM-230VI		18,900	\$2,646
207742336	C&H	CH-HPR24-230VO	CH-M24DTUI		21,000	\$2,940
207742374	C&H	CH-HPR19M-230VO	Heat pump with ducts		16,000	\$2,240
207742379	C&H	CH-HPR36M-230VO	Heat pump without ducts		33,000	\$4,620
207742382	C&H	CH-HPR48M-230VO	Heat pump with ducts		36,000	\$5,040
207742337	C&H	CH-HPR24-230VO	CH-24MSPHFC-230VI		19,000	\$2,660
207742375	C&H	CH-HPR19M-230VO	Combination heat pumps with or without ducts		15,500	\$2,170
207742383	C&H	CH-HPR48M-230VO	Combination heat pumps with or without ducts		36,000	\$5,040
207742384	C&H	CH-HPR36M-230VO	Combination heat pumps with or without ducts		34,000	\$4,760
207742330	C&H	CH-HPR12-230VO	CH-M12DTUI		10,600	\$1,484
207742343	C&H	CH-N48LCU-230VO	CH-48LCFC/I		29,000	\$4,060
207742346	C&H	CH-NHPR36LCU-230VO	CH-N36LCCT-230VI		33,000	\$4,620
207742351	C&H	CH-NHPR48LCU-230VO	CH-48LCFC/I		35,000	\$4,900
207742350	C&H	CH-NHPR48LCU-230VO	CH-48LCDTU/I		39,500	\$5,530
207742349	C&H	CH-NHPR48LCU-230VO	CH-N48LCCT-230VI		35,000	\$4,900
205263902	C&H	CH-HYP28MSPH-230VO	Heat pump without ducts		18,000	\$2,520
205047867	C&H	CH-HYP28MSPH-230VO	Heat pump without ducts		18,000	\$2,520
205282615	C&H	CH-HYP48LCUO	CH-48LCFCI		35,000	\$4,900
205263865	C&H	CH-HYP48LCUO	CH-48LCFC/I		35,000	\$4,900
205263858	C&H	CH-HYP24SPH230VO	CH-M24DTUI		17,200	\$2,408
205263857	C&H	CH-24LCU/O	CH-M24DTUI		17,200	\$2,408
201755335	C&H	CH-24LCU/O	CH-24LCDTU/I		17,200	\$2,408
10443490	C&H	CH-24LCDTU/O	CH-24LCDTU/I		17,200	\$2,408
204098427	C&H	CH-24DKT230VO	CH-24LCDTU/I		17,200	\$2,408
206597270	C&H	CH-24LCU/O	CH-24AHU		17,500	\$2,450
206597269	C&H	CH-HYP24SPH230VO	CH-24AHU		17,500	\$2,450
205263864	C&H	CH-HYP48LCUO	CH-48LCDTU/I		33,000	\$4,620
205263863	C&H	CH-HYP48LCUO	CH-48MSPHCT-230VI		35,000	\$4,900
205263860	C&H	CH-HYP48LCUO	CH-48LCCT-230VI		35,000	\$4,900
205901586	C&H	CH-HYP36LCUO	CH-36LCDTU/I		28,000	\$3,920
207742380	C&H	CH-HPR36M-230VO	Heat pump with ducts		23,000	\$3,220
205313424	C&H	CH-HYP48MSPH-230VO	Heat pump with ducts		28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208816951	C&H	CH-HPR24-230VO	CH-D24MSPHWM-230VI		19,400	\$2,716
205313423	C&H	CH-HYP48MSPH-230VO	Heat pump without ducts		30,000	\$4,200
207742348	C&H	CH-NHPR36LCU-230VO	CH-36LCFC/I		32,000	\$4,480
216720952	CANAIR	4CDH2060C21	CEB-60MX2421		36,000	\$5,040
215449732	CANAIR	4C28MC536H21	Combination heat pumps with or without ducts		31,400	\$4,396
215449730	CANAIR	4C28MC536H21	Heat pump without ducts		30,000	\$4,200
207683257	CanAir	C28SCH12H21	C28SEH12H21		10,000	\$1,400
207683258	CanAir	C28SCH18H21	C28SEH18H21		15,000	\$2,100
207796645	CanAir	C23SCH18H22	C28SEH18H21		15,000	\$2,100
207706569	CANAIR	CDH2024C21	CDH2024F21		19,200	\$2,688
207706568	CANAIR	CDH2018C21	CDH2018F21		13,500	\$1,890
207683259	CanAir	C28SCH24H21	C28SEH24H21		21,200	\$2,968
213479405	CANAIR	C28MC328H21	Heat pump with ducts		27,000	\$3,780
213479406	CANAIR	C28MC328H21	Combination heat pumps with or without ducts		26,800	\$3,752
213479404	CANAIR	C28MC328H21	Heat pump without ducts		26,600	\$3,724
213479410	CANAIR	C28MC218H22	Heat pump without ducts		15,000	\$2,100
207683271	CANAIR	C28MC548H21	Heat pump without ducts		36,000	\$5,040
207706570	CANAIR	CDH2030C21	CDH2030F21		21,000	\$2,940
207706571	CANAIR	CDH2036C21	CDH2036F21		30,400	\$4,256
213479407	CANAIR	C28MC436H22	Heat pump without ducts		33,000	\$4,620
207683273	CANAIR	C28MC548H21	Combination heat pumps with or without ducts		36,000	\$5,040
207683272	CANAIR	C28MC548H21	Heat pump with ducts		36,000	\$5,040
207862104	CANAIR	BZ33-HYP364Z2-G2-P	Heat pump without ducts		33,000	\$4,620
213479409	CANAIR	C28MC436H22	Combination heat pumps with or without ducts		34,000	\$4,760
213479412	CANAIR	C28MC218H22	Combination heat pumps with or without ducts		15,500	\$2,170
213479411	CANAIR	C28MC218H22	Heat pump with ducts		16,000	\$2,240
211644139	CANAIR	CDH2024C21	MAC-24HWDN1-MN0		21,000	\$2,940
216720951	CANAIR	4CDH2060C21	CEB-60MX2121		37,800	\$5,292
215449719	CANAIR	4C28SCH18H21	4C28SEH18H21		16,600	\$2,324
215449704	CANAIR	4CDH2018C21	4CDH2018F21		15,000	\$2,100
215449718	CANAIR	4C28SCH12H21	4C28SEH12H21		9,800	\$1,372
215449705	CANAIR	4CDH2024C21	4CDH2024F21		20,000	\$2,800
215449707	CANAIR	4CDH2036C21	4CDH2036F21		31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216621485	CanAir	4CDH2018C21	CEB-24MX1421		15,200	\$2,128
216621487	CanAir	4CDH2024C21	CEB-24MX1421		19,700	\$2,758
216621486	CanAir	4CDH2018C21	CEB-24MX1721		15,200	\$2,128
216621491	CanAir	4CDH2030C21	CEB-36MX2121		25,000	\$3,500
216621490	CanAir	4CDH2030C21	CEB-36MX1721		25,000	\$3,500
216621489	CanAir	4CDH2030C21	CEB-36MX1421		23,400	\$3,276
216621488	CanAir	4CDH2024C21	CEB-24MX1721		19,700	\$2,758
216621492	CanAir	4CDH2036C21	CEB-36MX1721		29,200	\$4,088
216621493	CanAir	4CDH2036C21	CEB-36MX2121		29,200	\$4,088
215828390	CANAIR	4C25SCH24H21	4C28SEH24H21		18,800	\$2,632
215828389	CANAIR	4C25SCH18H21	4C28SEH18H21		13,600	\$1,904
215828388	CANAIR	4C25SCH12H21	4C28SEH12H21		9,300	\$1,302
216684081	CANAIR	4CDH2048C21	CEB-60MX2121		32,000	\$4,480
211644138	CANAIR	CDH2036C21	MAC-36HWFN1-M		33,000	\$4,620
215449738	CANAIR	4C28MC655H21	Combination heat pumps with or without ducts		44,500	\$6,230
215449737	CANAIR	4C28MC655H21	Heat pump with ducts		45,000	\$6,300
215449736	CANAIR	4C28MC655H21	Heat pump without ducts		44,000	\$6,160
215449735	CANAIR	4C28MC648H21	Combination heat pumps with or without ducts		44,000	\$6,160
215449734	CANAIR	4C28MC648H21	Heat pump with ducts		44,500	\$6,230
215449733	CANAIR	4C28MC648H21	Heat pump without ducts		44,000	\$6,160
215449731	CANAIR	4C28MC536H21	Heat pump with ducts		33,000	\$4,620
215449729	CANAIR	4C28MC428H21	Combination heat pumps with or without ducts		24,000	\$3,360
215449728	CANAIR	4C28MC428H21	Heat pump with ducts		23,000	\$3,220
215449727	CANAIR	4C28MC428H21	Heat pump without ducts		25,000	\$3,500
215449726	CANAIR	4C28MC318H21	Combination heat pumps with or without ducts		17,300	\$2,422
215449725	CANAIR	4C28MC318H21	Heat pump with ducts		17,000	\$2,380
215449724	CANAIR	4C28MC318H21	Heat pump without ducts		17,600	\$2,464
215449723	CANAIR	4C28SCH33H21	4C28SEH33H21		30,000	\$4,200
215449720	CANAIR	4C28SCH24H21	4C28SEH24H21		21,000	\$2,940
215449709	CANAIR	4CDH2060C21	4CDH2060F21		45,000	\$6,300
215449708	CANAIR	4CDH2048C21	4CDH2048F21		37,000	\$5,180
215449706	CANAIR	4CDH2030C21	4CDH2030F21		23,800	\$3,332
205816494	CANAIR	C23SCH24H22	C23SEH24H21		19,400	\$2,716
213160446	CANAIR	CDH2036C21	MVB-36B24T4N1		27,400	\$3,836

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213479416	CANAIR	CDH2036C22	MAC-36HWDN1-MN0		27,000	\$3,780
213479414	CANAIR	CDH2036C22	MVB-36B23T4N1		27,000	\$3,780
213479415	CANAIR	CDH2036C22	CDH2036F21		31,800	\$4,452
213160447	CANAIR	CDH2060C22	MAC-60HWDN1-MN0*		37,000	\$5,180
207690476	CANAIR	CDH2048C21	CDH2048F21		32,000	\$4,480
207690474	CANAIR	CDH2030C21	CDH2030F21		19,400	\$2,716
205816493	CANAIR	C23SCH18H22	C23SEH18H21		10,900	\$1,526
207690472	CANAIR	CDH2018C21	CDH2018F21		13,000	\$1,820
207690473	CANAIR	CDH2024C21	CDH2024F21		16,700	\$2,338
207690475	CANAIR	CDH2036C21	CDH2036F21		24,000	\$3,360
207706572	CANAIR	CDH2048C21	CDH2048F21		36,000	\$5,040
210342131	CANAIR	CDH2060C22	CDH2060F21		42,000	\$5,880
211644140	CANAIR	CDH2030C21	MAC-36HWFN1-M		22,600	\$3,164
212386770	CANAIR	CDH2060C22	MAC-60HWDN1-MN0		37,000	\$5,180
213160452	CANAIR	CDH2060C22	MAC-60HWDN1-MN0**		37,000	\$5,180
216445282	CAPELLA	CPEB-H12A-O	CPEB-H12A-I		10,800	\$1,512
216445283	CAPELLA	CPEB-H18A-O	CPEB-H18A-I		18,000	\$2,520
216445284	CAPELLA	CPEB-H24A-O	CPEB-H24A-I		22,000	\$3,080
216027632	CAPELLA	CPM2B1-H18A-O	Heat pump without ducts		17,600	\$2,464
216027633	CAPELLA	CPM2B1-H18A-O	Heat pump with ducts		17,000	\$2,380
216027634	CAPELLA	CPM2B1-H18A-O	Combination heat pumps with or without ducts		17,300	\$2,422
216027647	CAPELLA	CPM2B1V-H18A-O	Heat pump without ducts		17,600	\$2,464
216027648	CAPELLA	CPM2B1V-H18A-O	Heat pump with ducts		17,000	\$2,380
216027649	CAPELLA	CPM2B1V-H18A-O	Combination heat pumps with or without ducts		17,300	\$2,422
216027636	CAPELLA	CPM3B1-H27A-O	Heat pump with ducts		23,000	\$3,220
216027635	CAPELLA	CPM3B1-H27A-O	Heat pump without ducts		25,000	\$3,500
216027637	CAPELLA	CPM3B1-H27A-O	Combination heat pumps with or without ducts		24,000	\$3,360
216027651	CAPELLA	CPM3B1V-H27A-O	Heat pump with ducts		23,000	\$3,220
216027650	CAPELLA	CPM3B1V-H27A-O	Heat pump without ducts		25,000	\$3,500
216027652	CAPELLA	CPM3B1V-H27A-O	Combination heat pumps with or without ducts		24,000	\$3,360
216027638	CAPELLA	CPM4B1-H36A-O	Heat pump without ducts		30,000	\$4,200
216027639	CAPELLA	CPM4B1-H36A-O	Heat pump with ducts		33,000	\$4,620
216027640	CAPELLA	CPM4B1-H36A-O	Combination heat pumps with or without ducts		31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216027653	CAPELLA	CPM4B1V-H36A-O	Heat pump without ducts		30,000	\$4,200
216027655	CAPELLA	CPM4B1V-H36A-O	Combination heat pumps with or without ducts		31,400	\$4,396
216027654	CAPELLA	CPM4B1V-H36A-O	Heat pump with ducts		33,000	\$4,620
216027641	CAPELLA	CPM5B1-H48A-O	Heat pump without ducts		44,000	\$6,160
216027642	CAPELLA	CPM5B1-H48A-O	Heat pump with ducts		44,500	\$6,230
216027643	CAPELLA	CPM5B1-H48A-O	Combination heat pumps with or without ducts		44,000	\$6,160
216027644	CAPELLA	CPM5B1-H55A-O	Heat pump without ducts		44,000	\$6,160
216027645	CAPELLA	CPM5B1-H55A-O	Heat pump with ducts		45,000	\$6,300
216027646	CAPELLA	CPM5B1-H55A-O	Combination heat pumps with or without ducts		44,500	\$6,230
216027656	CAPELLA	CPM5B1V-H48A-O	Heat pump without ducts		44,000	\$6,160
216027657	CAPELLA	CPM5B1V-H48A-O	Heat pump with ducts		44,500	\$6,230
216027658	CAPELLA	CPM5B1V-H48A-O	Combination heat pumps with or without ducts		44,000	\$6,160
216027659	CAPELLA	CPM5B1V-H55A-O	Heat pump without ducts		44,000	\$6,160
216027661	CAPELLA	CPM5B1V-H55A-O	Combination heat pumps with or without ducts		44,500	\$6,230
216027660	CAPELLA	CPM5B1V-H55A-O	Heat pump with ducts		45,000	\$6,300
216027621	CAPELLA	CPPB-H12A-O	CPPB-H12A-I		9,800	\$1,372
216027625	CAPELLA	CPPB-H12A-O	SICB1-H12A-I		10,000	\$1,400
216027629	CAPELLA	CPPB-H12A-O	SFCB1-H12A-I		10,200	\$1,428
216027622	CAPELLA	CPPB-H18A-O	CPPB-H18A-I		16,600	\$2,324
216027626	CAPELLA	CPPB-H18A-O	SICB1-H18A-I		14,900	\$2,086
216027630	CAPELLA	CPPB-H18A-O	SFCB1-H18A-I		15,000	\$2,100
216027623	CAPELLA	CPPB-H24A-O	CPPB-H24A-I		21,000	\$2,940
216027627	CAPELLA	CPPB-H24A-O	SICB1-H24A-I		20,400	\$2,856
216027631	CAPELLA	CPPB-H24A-O	SFCB1-H24A-I		21,600	\$3,024
216027662	CAPELLA	CCB1-H24A-O	CAHB1-H24A-I		20,000	\$2,800
216623792	CAPELLA	CCB1-H24A-O	CACB1-H24A1418-I		19,700	\$2,758
216623793	CAPELLA	CCB1-H24A-O	CACB1-H24A1718-I		19,700	\$2,758
216027663	CAPELLA	CCB1-H30A-O	CAHB1-H30A-I		23,800	\$3,332
216623794	CAPELLA	CCB1-H30A-O	CACB1-H36A1424-I		23,400	\$3,276
216623795	CAPELLA	CCB1-H30A-O	CACB1-H36A1724-I		25,000	\$3,500
216623796	CAPELLA	CCB1-H30A-O	CACB1-H36A2124-I		25,000	\$3,500
216027664	CAPELLA	CCB1-H36A-O	CAHB1-H36A-I		31,800	\$4,452
216623797	CAPELLA	CCB1-H36A-O	CACB1-H36A1724-I		29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216623798	CAPELLA	CCB1-H36A-O	CACB1-H36A2124-I		29,200	\$4,088
216027665	CAPELLA	CCB1-H48A-O	CAHB1-H48A-I		37,000	\$5,180
216684132	CAPELLA	CCB1-H48A-O	CMCB1-H60A2128-I		32,000	\$4,480
216027666	CAPELLA	CCB1-H60A-O	CAHB1-H60A-I		45,000	\$6,300
216623800	CAPELLA	CCB1-H60A-O	CACB1-H60A2428-I		36,000	\$5,040
216623799	CAPELLA	CCB1-H60A-O	CMCB1-H60A2128-I		38,000	\$5,320
215681673	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	58CU*B040C17**12	42,000	\$5,880
215681663	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59TN6C080C21**20	42,000	\$5,880
215934884	CARRIER	27VNA336A*030*	CVAMA4421XMA*+UI	59CU5B100C21**22	32,600	\$4,564
215934874	CARRIER	27VNA336A*030*	CVAMA4421XMA*+UI	59CU5B080C21**20	32,800	\$4,592
215683083	CARRIER	27VNA060A*030*	CVAVA6024XMA*+UI	59TN7A080C21**20	56,000	\$7,840
215937524	CARRIER	27VNA348A*030*	CVAMA6024XMA*+UI	59MN7C080C21**20	43,500	\$6,090
215937514	CARRIER	27VNA348A*030*	CVAMA6024XMA*+UI	59MN7C060C21**20	44,000	\$6,160
215683063	CARRIER	27VNA060A*030*	CVAVA6024XMA*+UI	58CU*B080C21**20	55,000	\$7,700
215683053	CARRIER	27VNA060A*030*	CVAVA6024XMA*+UI	59TN6C080C21**20	56,000	\$7,840
215937504	CARRIER	27VNA348A*030*	CVAMA6024XMA*+UI	59CU5B100C21**22	43,000	\$6,020
215937494	CARRIER	27VNA348A*030*	CVAMA6024XMA*+UI	59CU5B080C21**20	43,500	\$6,090
215934864	CARRIER	27VNA336A*030*	CVAMA4421XMA*+UI	59CU5B060C17**16	33,200	\$4,648
215934854	CARRIER	27VNA336A*030*	CVAMA4421XMA*+UI	58TN*B110C21**20	32,600	\$4,564
215683033	CARRIER	27VNA060A*030*	CVAVA6021XMA*+UI	59TN7A080C21**20	56,000	\$7,840
215937484	CARRIER	27VNA348A*030*	CVAMA6024XMA*+UI	58TN*B135C24**22	43,000	\$6,020
215937474	CARRIER	27VNA348A*030*	CVAMA6024XMA*+UI	58TN*B110C21**20	43,000	\$6,020
215934844	CARRIER	27VNA336A*030*	CVAMA4421XMA*+UI	58TN*B090C21**20	32,600	\$4,564
215934834	CARRIER	27VNA336A*030*	CVAMA4421XMA*+UI	58TN*B090C17**16	32,800	\$4,592
215681623	CARRIER	27VNA048A*030*	CSAH*4812AM*+UI	59TN7A080C17**16	43,500	\$6,090
215683023	CARRIER	27VNA060A*030*	CVAVA6021XMA*+UI	58CU*B100C21**20	56,000	\$7,840
215937464	CARRIER	27VNA348A*030*	CVAMA6024XMA*+UI	58TN*B090C21**20	43,000	\$6,020
215937454	CARRIER	27VNA348A*030*	CVAMA6024XMA*+UI	58TN*B070C21**20	43,500	\$6,090
215934824	CARRIER	27VNA336A*030*	CVAMA4421XMA*+UI	58TN*B070C21**20	32,800	\$4,592
215934814	CARRIER	27VNA336A*030*	CVAMA4421XMA*+UI	58TN*B070C17**16	33,000	\$4,620
215683003	CARRIER	27VNA060A*030*	CVAVA6021XMA*+UI	58CU*B060C17**16	54,000	\$7,560
215682993	CARRIER	27VNA060A*030*	CVAVA6021XMA*+UI	58CU*B040C17**12	54,000	\$7,560
215937434	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	59TN6C100C21**22	43,500	\$6,090
215937424	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	59TN6C080C17**14	42,500	\$5,950
215934804	CARRIER	27VNA336A*030*	CVAMA4421XMA*+UI	58TN*B045C17**12	33,600	\$4,704
215934764	CARRIER	27VNA336A*030*	CVAMA4321XMA*+UI	59TN6C060C17**14	31,200	\$4,368
215682983	CARRIER	27VNA060A*030*	CVAVA6021XMA*+UI	59TN6C080C21**20	56,000	\$7,840
215681593	CARRIER	27VNA048A*030*	CSAH*4812AM*+UI	58CU*B060C17**16	43,000	\$6,020

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215937414	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	59MN7C100C21**22	43,500	\$6,090
215937404	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	59MN7C080C21**20	43,500	\$6,090
215934754	CARRIER	27VNA336A*030*	CVAMA4321XMA*+UI	59MN7C060C17**14	31,400	\$4,396
215934744	CARRIER	27VNA336A*030*	CVAMA4221XMA*+UI	59TN6C060C17**14	30,400	\$4,256
215682953	CARRIER	27VNA060A*030*	CVAMA6124XMA*+UI	59TN7A080C21**20	56,000	\$7,840
215681563	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59TN7A120C24**22	42,000	\$5,880
215937394	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	59MN7C080C17**14	43,500	\$6,090
215937384	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	59MN7C060C21**20	44,000	\$6,160
215934734	CARRIER	27VNA336A*030*	CVAMA4221XMA*+UI	59MN7C060C17**14	30,600	\$4,284
215934724	CARRIER	27VNA336A*030*	CVAMA3617XMA*+UI	59TN6C060C17**14	30,600	\$4,284
215681553	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59TN7A100C21**22	42,000	\$5,880
215681543	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59TN7A080C21**20	42,000	\$5,880
215937374	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	59CU5B100C21**22	43,000	\$6,020
215937364	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	59CU5B080C21**20	43,500	\$6,090
215682923	CARRIER	27VNA060A*030*	CVAMA6124XMA*+UI	59TN6C080C21**20	56,000	\$7,840
215682913	CARRIER	27VNA060A*030*	CVAMA6024XMA*+UI	59TN7A120C24**22	55,500	\$7,770
215937354	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	59CU5B060C17**16	43,500	\$6,090
215937344	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	58TN*B110C21**20	43,500	\$6,090
215934714	CARRIER	27VNA336A*030*	CVAMA3617XMA*+UI	59MN7C060C17**14	30,600	\$4,284
215934704	CARRIER	27VNA336A*030*	CVAMA3217XMA*+UI	59TN6C060C17**14	32,000	\$4,480
215681533	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	58CU*B100C21**20	42,000	\$5,880
215682903	CARRIER	27VNA060A*030*	CVAMA6024XMA*+UI	59TN7A100C21**22	55,500	\$7,770
215682893	CARRIER	27VNA060A*030*	CVAMA6024XMA*+UI	59TN7A080C21**20	56,000	\$7,840
215937334	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	58TN*B090C21**20	43,000	\$6,020
215937324	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	58TN*B090C17**16	43,000	\$6,020
215934694	CARRIER	27VNA336A*030*	CVAMA3217XMA*+UI	59TN6C040C14**10	29,200	\$4,088
215934684	CARRIER	27VNA336A*030*	CVAMA3217XMA*+UI	59MN7C060C17**14	32,200	\$4,508
215682883	CARRIER	27VNA060A*030*	CVAMA6024XMA*+UI	58CU*B100C21**20	55,500	\$7,770
215682873	CARRIER	27VNA060A*030*	CVAMA6024XMA*+UI	58CU*B080C21**20	55,000	\$7,700
215681513	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59TN6C080C21**20	42,000	\$5,880
215681503	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59TN7A100C21**22	42,000	\$5,880
215934664	CARRIER	27VNA336A*030*	CVAMA3117XMA*+UI	59MN7C060C17**14	31,800	\$4,452
215937314	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	58TN*B070C21**20	43,500	\$6,090
215937304	CARRIER	27VNA348A*030*	CVAMA6021XMA*+UI	58TN*B070C17**16	44,000	\$6,160
215682863	CARRIER	27VNA060A*030*	CVAMA6024XMA*+UI	59TN6C080C21**20	56,000	\$7,840
215682853	CARRIER	27VNA060A*030*	CVAMA6021XMA*+UI	59TN7A100C21**22	56,000	\$7,840
215681493	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59TN7A080C21**20	42,000	\$5,880
215681483	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59TN7A080C17**16	42,500	\$5,950

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215937274	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	59TN6C100C21**22	43,500	\$6,090
215934654	CARRIER	27VNA336A*030*	CVAMA3017XMA*+UI	59TN6C060C17**14	30,600	\$4,284
215934644	CARRIER	27VNA336A*030*	CVAMA3017XMA*+UI	59MN7C060C17**14	30,600	\$4,284
215682843	CARRIER	27VNA060A*030*	CVAMA6021XMA*+UI	59TN7A080C21**20	56,000	\$7,840
215682833	CARRIER	27VNA060A*030*	CVAMA6021XMA*+UI	58CU*B100C21**20	56,000	\$7,840
215937264	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	59TN6C080C17**14	42,500	\$5,950
215937254	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	59MN7C100C21**22	43,500	\$6,090
215681473	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58CU*B100C21**20	42,000	\$5,880
215681463	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58CU*B080C21**20	41,500	\$5,810
215934634	CARRIER	27VNA336A*030*	CVAMA2517XMA*+UI	59TN6C060C17**14	30,600	\$4,284
215934624	CARRIER	27VNA336A*030*	CVAMA2517XMA*+UI	59MN7C060C17**14	30,600	\$4,284
215682813	CARRIER	27VNA060A*030*	CVAMA6021XMA*+UI	58CU*B060C17**16	54,000	\$7,560
215684035	CARRIER	27VNA036A*030*	CSAH*3612AM*+UI	59MN7C060C17**14	31,000	\$4,340
215681453	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58CU*B060C17**16	42,000	\$5,880
215681443	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58CU*B040C17**12	42,000	\$5,880
215937244	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	59MN7C080C21**20	43,500	\$6,090
215937234	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	59MN7C080C17**14	43,500	\$6,090
215933964	CARRIER	27VNA336A*030*	FE5BNBD60L*+UI		29,200	\$4,088
215933954	CARRIER	27VNA336A*030*	FE5BN(B,X)C36L*+UI		30,600	\$4,284
215682803	CARRIER	27VNA060A*030*	CVAMA6021XMA*+UI	58CU*B040C17**12	54,000	\$7,560
215682793	CARRIER	27VNA060A*030*	CVAMA6021XMA*+UI	59TN6C080C21**20	56,000	\$7,840
215681433	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59TN6C080C21**20	42,000	\$5,880
215681423	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59TN7A120C24**22	41,500	\$5,810
215933944	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59TN6C120C24**22	29,800	\$4,172
215933934	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59TN6C100C21**22	29,800	\$4,172
215682773	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	59TN7A100C21**22	51,500	\$7,210
215937224	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	59MN7C060C21**20	44,000	\$6,160
215937214	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	59CU5B100C21**22	43,000	\$6,020
215681413	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59TN7A100C21**22	41,500	\$5,810
215681403	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59TN7A080C21**20	42,000	\$5,880
215933924	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59TN6C080C17**14	30,200	\$4,228
215933914	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59TN6C060C17**14	29,600	\$4,144
215682763	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	59TN7A080C21**20	51,500	\$7,210
215937204	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	59CU5B080C21**20	43,500	\$6,090
215937194	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	59CU5B060C17**16	43,500	\$6,090
215933904	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59TN6C040C14**10	29,400	\$4,116
215933894	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59MN7C100C21**22	29,800	\$4,172
215681393	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	58CU*B100C21**20	41,500	\$5,810

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215681383	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	58CU*B080C21**20	41,500	\$5,810
215682733	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	58CU*B060C17**16	50,500	\$7,070
215937184	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	58TN*B110C21**20	43,500	\$6,090
215937174	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	58TN*B090C21**20	43,000	\$6,020
215681373	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59TN6C080C21**20	42,000	\$5,880
215681363	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59TN7A100C21**22	42,500	\$5,950
215682713	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	59TN6C080C21**20	51,500	\$7,210
215933884	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59MN7C080C21**20	30,000	\$4,200
215933874	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59MN7C080C17**14	30,400	\$4,256
215937164	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	58TN*B090C17**16	43,000	\$6,020
215937154	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	58TN*B070C21**20	43,500	\$6,090
215681353	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59TN7A080C21**20	42,500	\$5,950
215681343	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59TN7A080C17**16	43,000	\$6,020
215682693	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	59TN7A100C21**22	51,500	\$7,210
215682683	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	59TN7A080C21**20	51,500	\$7,210
215684005	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59TN6C100C21**22	30,400	\$4,256
215937144	CARRIER	27VNA348A*030*	CVAMA4921XMA*+UI	58TN*B070C17**16	44,000	\$6,160
215933864	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59MN7C060C21**20	30,400	\$4,256
215933854	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59MN7C060C17**14	29,600	\$4,144
215681333	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	58CU*B100C21**20	42,500	\$5,950
215937114	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	59TN6C100C21**22	43,500	\$6,090
215937104	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	59TN6C080C17**14	42,500	\$5,950
215933844	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59CU5B100C21**22	29,800	\$4,172
215933834	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59CU5B080C21**20	30,000	\$4,200
215684003	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59TN6C080C17**14	30,600	\$4,284
215684001	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59MN7C100C21**22	30,400	\$4,256
215681313	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	58CU*B060C17**16	42,500	\$5,950
215681303	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	58CU*B040C17**12	42,500	\$5,950
215682653	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	59TN6C080C21**20	51,500	\$7,210
215682643	CARRIER	27VNA060A*030*	CAA**6121AM*+UI	58CU*B060C17**16	50,500	\$7,070
215937094	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	59MN7C100C21**22	43,500	\$6,090
215937084	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	59MN7C080C21**20	43,500	\$6,090
215933824	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	59CU5B060C17**16	30,400	\$4,256
215933814	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	58TN*B135C24**22	30,000	\$4,200
215683999	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59MN7C080C21**20	30,400	\$4,256
215683997	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59MN7C080C17**14	30,600	\$4,284
215681293	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59TN6C080C21**20	42,500	\$5,950
215676953	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	59TN6C120C24**22	46,500	\$6,510

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215682633	CARRIER	27VNA060A*030*	CAA**6121AM*+UI	58CU*B040C17**12	50,500	\$7,070
215682623	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	59TN7A120C24**22	51,000	\$7,140
215676943	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	59TN6C100C21**22	46,500	\$6,510
215676933	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	59MN7C120C24**22	46,500	\$6,510
215937074	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	59MN7C080C17**14	43,500	\$6,090
215937064	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	59MN7C060C21**20	44,000	\$6,160
215933804	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	58TN*B110C21**20	30,000	\$4,200
215933794	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	58TN*B090C21**20	29,800	\$4,172
215678423	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59TN7A100C21**22	19,600	\$2,744
215678413	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59TN7A080C17**16	19,700	\$2,758
215683995	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59MN7C060C17**14	30,600	\$4,284
215683993	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59CU5B100C21**22	30,200	\$4,228
215676923	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	59MN7C100C21**22	46,500	\$6,510
215676913	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	59MN7C080C21**20	46,500	\$6,510
215682603	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	59TN7A080C21**20	51,000	\$7,140
215937054	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	59CU5B100C21**22	43,500	\$6,090
215937044	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	59CU5B080C21**20	43,500	\$6,090
215683991	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59CU5B080C21**20	30,400	\$4,256
215683989	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59CU5B060C17**16	30,600	\$4,284
215933784	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	58TN*B090C17**16	30,000	\$4,200
215933774	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	58TN*B070C21**20	30,000	\$4,200
215678403	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59TN7A060C17**16	19,700	\$2,758
215678393	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	58CU*B060C17**16	19,600	\$2,744
215683717	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59TN6C100C21**22	19,600	\$2,744
215682593	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	58CU*B100C21**20	51,000	\$7,140
215682583	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	58CU*B080C21**20	50,500	\$7,070
215676903	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	59MN7C060C21**20	47,000	\$6,580
215676893	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	59CU5B100C21**22	46,500	\$6,510
215937034	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	59CU5B060C17**16	43,500	\$6,090
215937024	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	58TN*B110C21**20	43,500	\$6,090
215683987	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	58TN*B110C21**20	30,200	\$4,228
215683985	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	58TN*B090C21**20	30,200	\$4,228
215678373	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	59TN7A080C17**16	19,900	\$2,786
215933764	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	58TN*B070C17**16	30,200	\$4,228
215933754	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	58TN*B070C14**12	30,400	\$4,256
215683715	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59TN6C080C17**14	19,600	\$2,744
215683713	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59TN6C060C17**14	19,700	\$2,758
215676883	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	58TN*B135C24**22	46,500	\$6,510

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215676873	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	58TN*B090C21**20	46,500	\$6,510
215682573	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	59TN6C080C21**20	51,000	\$7,140
215937014	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	58TN*B090C21**20	43,500	\$6,090
215937004	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	58TN*B090C17**16	43,000	\$6,020
215678363	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	59TN7A060C17**16	19,900	\$2,786
215678353	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	58CU*B060C17**16	19,800	\$2,772
215683711	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59MN7C100C21**22	19,600	\$2,744
215683709	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59MN7C080C17**14	19,700	\$2,758
215683983	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	58TN*B090C17**16	30,400	\$4,256
215683981	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	58TN*B070C21**20	30,400	\$4,256
215933744	CARRIER	27VNA336A*030*	CSAH*6012AM*+UI	58TN*B045C17**12	30,800	\$4,312
215933704	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59TN6C120C24**22	30,400	\$4,256
215676863	CARRIER	27VNA048A*030*	CVAVA6124XMA*+UI	58TN*B070C21**20	46,500	\$6,510
215676833	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	59TN6C100C21**22	46,500	\$6,510
215678163	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	59TN6C100C21**22	51,500	\$7,210
215678153	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	59MN7C120C24**22	51,500	\$7,210
215683707	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59MN7C060C21**20	19,700	\$2,758
215683705	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59MN7C060C17**14	19,700	\$2,758
215936994	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	58TN*B070C21**20	43,500	\$6,090
215936984	CARRIER	27VNA348A*030*	CVAMA4821XMA*+UI	58TN*B070C17**16	44,000	\$6,160
215678343	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	58CU*B040C17**12	19,700	\$2,758
215678333	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	59TN7A080C17**16	20,000	\$2,800
215676823	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	59TN6C080C17**14	46,000	\$6,440
215676813	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	59MN7C100C21**22	46,500	\$6,510
215933694	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59TN6C060C17**14	30,000	\$4,200
215933684	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59TN6C040C14**10	29,800	\$4,172
215678143	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	59MN7C100C21**22	51,500	\$7,210
215678133	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	59MN7C080C21**20	51,500	\$7,210
215683979	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	58TN*B070C17**16	30,400	\$4,256
215683977	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	58TN*B045C17**12	30,800	\$4,312
215934614	CARRIER	27VNA348A*030*	FE5BN(B,X)C48L*+UI		39,000	\$5,460
215683703	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	59CU5B100C21**22	19,600	\$2,744
215683701	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	58TN*B110C21**20	19,600	\$2,744
215678323	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	59TN7A060C17**16	20,000	\$2,800
215678313	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	58CU*B060C17**16	19,900	\$2,786
215676803	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	59MN7C080C17**14	47,500	\$6,650
215676793	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	59MN7C060C21**20	47,000	\$6,580
215933674	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59MN7C120C24**22	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215933664	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59MN7C080C21**20	30,400	\$4,256
215683969	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	59TN6C100C21**22	31,000	\$4,340
215683967	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	59TN6C080C17**14	31,200	\$4,368
215683699	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	58TN*B090C21**20	19,600	\$2,744
215683697	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	58TN*B090C17**16	19,600	\$2,744
215934604	CARRIER	27VNA348A*030*	CSAH*6012AM*+UI	59TN6C080C17**14	37,200	\$5,208
215934594	CARRIER	27VNA348A*030*	CSAH*6012AM*+UI	59MN7C080C17**14	39,000	\$5,460
215678303	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	58CU*B040C17**12	19,900	\$2,786
215678293	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	59TN7A080C17**16	20,200	\$2,828
215933654	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59MN7C080C17**14	31,000	\$4,340
215933644	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59MN7C060C21**20	30,800	\$4,312
215676783	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	59CU5B100C21**22	46,500	\$6,510
215676773	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	59CU5B080C21**20	47,000	\$6,580
215683695	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	58TN*B070C21**20	19,600	\$2,744
215683693	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	58TN*B070C17**16	19,700	\$2,758
215934584	CARRIER	27VNA348A*030*	CSAH*6012AM*+UI	59CU5B100C21**22	39,500	\$5,530
215934574	CARRIER	27VNA348A*030*	CSAH*6012AM*+UI	59CU5B060C17**16	39,000	\$5,460
215683963	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	59MN7C100C21**22	31,000	\$4,340
215678283	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	59TN7A060C17**16	20,200	\$2,828
215678273	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	58CU*B060C17**16	20,000	\$2,800
215678103	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	59CU5B080C21**20	51,500	\$7,210
215933634	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59MN7C060C17**14	30,000	\$4,200
215933624	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59CU5B100C21**22	30,200	\$4,228
215676763	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	59CU5B060C17**16	47,000	\$6,580
215676753	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	58TN*B110C21**20	46,500	\$6,510
215683691	CARRIER	27VNA024A*030*	CAA**3721AM*+UI	58TN*B045C17**12	19,800	\$2,772
215683685	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	59TN6C080C17**14	19,800	\$2,772
215934564	CARRIER	27VNA348A*030*	CSAH*6012AM*+UI	58TN*B090C17**16	38,500	\$5,390
215934554	CARRIER	27VNA348A*030*	CSAH*6012AM*+UI	58TN*B070C14**12	37,200	\$5,208
215678263	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	58CU*B040C17**12	20,000	\$2,800
215678253	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	59TN7A080C17**16	19,800	\$2,772
215683961	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	59MN7C080C21**20	31,000	\$4,340
215933614	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59CU5B080C21**20	30,600	\$4,284
215933604	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	59CU5B060C17**16	30,800	\$4,312
215676743	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	58TN*B090C21**20	46,500	\$6,510
215676733	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	58TN*B090C17**16	47,000	\$6,580
215683683	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	59TN6C060C17**14	19,900	\$2,786
215683681	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	59TN6C040C14**10	20,200	\$2,828

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215934534	CARRIER	27VNA348A*030*	CSAH*4812AM*+UI	59TN6C120C24**22	39,500	\$5,530
215934524	CARRIER	27VNA348A*030*	CSAH*4812AM*+UI	59TN6C100C21**22	39,500	\$5,530
215678243	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	59TN7A060C17**16	19,800	\$2,772
215678233	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	58CU*B060C17**16	19,700	\$2,758
215678053	CARRIER	27VNA060A*030*	CSAH*6012AM*+UI	58TN*B070C17**16	51,000	\$7,140
215676723	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	58TN*B070C21**20	47,000	\$6,580
215676713	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	58TN*B070C17**16	47,000	\$6,580
215683679	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	59MN7C080C17**14	19,900	\$2,786
215683677	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	59MN7C060C17**14	19,900	\$2,786
215933594	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	58TN*B135C24**22	30,400	\$4,256
215933584	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	58TN*B090C21**20	30,400	\$4,256
215934514	CARRIER	27VNA348A*030*	CSAH*4812AM*+UI	59TN6C080C17**14	36,400	\$5,096
215934504	CARRIER	27VNA348A*030*	CSAH*4812AM*+UI	59MN7C120C24**22	39,500	\$5,530
215683953	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	59CU5B100C21**22	30,800	\$4,312
215683951	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	59CU5B080C21**20	31,000	\$4,340
215676703	CARRIER	27VNA048A*030*	CVAVA6121XMA*+UI	58TN*B045C17**12	47,500	\$6,650
215676673	CARRIER	27VNA048A*030*	CVAVA6024XMA*+UI	59TN6C120C24**22	46,000	\$6,440
215678223	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	58CU*B040C17**12	19,600	\$2,744
215678213	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	59TN7A080C17**16	20,400	\$2,856
215683675	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	58TN*B090C17**16	19,800	\$2,772
215683673	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	58TN*B070C17**16	19,800	\$2,772
215678013	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	59TN6C100C21**22	51,500	\$7,210
215678003	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	59MN7C120C24**22	51,500	\$7,210
215934494	CARRIER	27VNA348A*030*	CSAH*4812AM*+UI	59MN7C100C21**22	39,500	\$5,530
215934484	CARRIER	27VNA348A*030*	CSAH*4812AM*+UI	59MN7C080C21**20	39,500	\$5,530
215933574	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	58TN*B090C17**16	30,600	\$4,284
215933564	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	58TN*B070C21**20	30,600	\$4,284
215676663	CARRIER	27VNA048A*030*	CVAVA6024XMA*+UI	59MN7C120C24**22	46,000	\$6,440
215676653	CARRIER	27VNA048A*030*	CVAVA6024XMA*+UI	59MN7C060C21**20	46,500	\$6,510
215683947	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	58TN*B110C21**20	30,800	\$4,312
215678203	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	59TN7A060C17**16	20,400	\$2,856
215678193	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	58CU*B060C17**16	20,200	\$2,828
215683671	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	58TN*B070C14**12	19,800	\$2,772
215683669	CARRIER	27VNA024A*030*	CAA**3717AM*+UI	58TN*B045C17**12	20,000	\$2,800
215934474	CARRIER	27VNA348A*030*	CSAH*4812AM*+UI	58TN*B135C24**22	39,500	\$5,530
215677993	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	59MN7C100C21**22	51,500	\$7,210
215677983	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	59MN7C080C21**20	51,500	\$7,210
215933554	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	58TN*B070C17**16	30,800	\$4,312

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215933544	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	58TN*B070C14**12	30,800	\$4,312
215676643	CARRIER	27VNA048A*030*	CVAVA6024XMA*+UI	59CU5B100C21**22	46,000	\$6,440
215676633	CARRIER	27VNA048A*030*	CVAVA6024XMA*+UI	59CU5B080C21**20	46,500	\$6,510
215683945	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	58TN*B090C21**20	30,800	\$4,312
215683943	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	58TN*B090C17**16	31,000	\$4,340
215683663	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	59TN6C080C17**14	20,000	\$2,800
215683661	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	59TN6C060C17**14	20,000	\$2,800
215678183	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	58CU*B040C17**12	20,200	\$2,828
215677973	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	59MN7C060C21**20	52,000	\$7,280
215933534	CARRIER	27VNA336A*030*	CSAH*4812AM*+UI	58TN*B045C17**12	31,200	\$4,368
215933494	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59TN6C120C24**22	30,400	\$4,256
215676623	CARRIER	27VNA048A*030*	CVAVA6024XMA*+UI	58TN*B110C21**20	46,000	\$6,440
215676613	CARRIER	27VNA048A*030*	CVAVA6024XMA*+UI	58TN*B090C21**20	46,000	\$6,440
215683941	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	58TN*B070C21**20	31,000	\$4,340
215683939	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	58TN*B070C17**16	31,000	\$4,340
215683659	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	59TN6C040C14**10	20,400	\$2,856
215683657	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	59MN7C080C17**14	20,000	\$2,800
215677953	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	59CU5B080C21**20	51,500	\$7,210
215933484	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59TN6C100C21**22	30,400	\$4,256
215933474	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59TN6C080C17**14	30,800	\$4,312
215676603	CARRIER	27VNA048A*030*	CVAVA6024XMA*+UI	58TN*B070C21**20	46,500	\$6,510
215676573	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	59TN6C100C21**22	46,500	\$6,510
215683929	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59TN6C100C21**22	30,400	\$4,256
215683655	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	59MN7C060C17**14	20,000	\$2,800
215683653	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	58TN*B090C17**16	20,000	\$2,800
215933464	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59TN6C060C17**14	30,000	\$4,200
215933454	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59TN6C040C14**10	30,000	\$4,200
215676563	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	59TN6C080C17**14	45,500	\$6,370
215676553	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	59MN7C100C21**22	46,500	\$6,510
215683927	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59TN6C080C17**14	30,600	\$4,284
215683925	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59TN6C060C17**14	30,600	\$4,284
215683651	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	58TN*B070C17**16	20,000	\$2,800
215683649	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	58TN*B070C14**12	20,000	\$2,800
215677913	CARRIER	27VNA060A*030*	CAA**6124AM*+UI	58TN*B070C21**20	51,500	\$7,210
215677883	CARRIER	27VNA060A*030*	CAA**6121AM*+UI	58TN*B070C17**16	50,500	\$7,070
215676543	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	59MN7C080C21**20	46,500	\$6,510
215676533	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	59MN7C080C17**14	47,000	\$6,580
215933444	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59MN7C120C24**22	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215933434	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59MN7C100C21**22	30,400	\$4,256
215683647	CARRIER	27VNA024A*030*	CAA**3617AM*+UI	58TN*B045C17**12	20,200	\$2,828
215683641	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	59TN6C080C17**14	20,200	\$2,828
215683923	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59MN7C100C21**22	30,400	\$4,256
215683921	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59MN7C080C21**20	30,400	\$4,256
215677873	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	59TN6C120C24**22	51,000	\$7,140
215676523	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	59MN7C060C21**20	47,000	\$6,580
215676513	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	59CU5B100C21**22	46,500	\$6,510
215933424	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59MN7C080C21**20	30,600	\$4,284
215933414	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59MN7C080C17**14	31,000	\$4,340
215683639	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	59TN6C060C17**14	20,200	\$2,828
215683637	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	59TN6C040C14**10	20,400	\$2,856
215676503	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	59CU5B080C21**20	46,500	\$6,510
215676493	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	59CU5B060C17**16	47,000	\$6,580
215683919	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59MN7C080C17**14	30,600	\$4,284
215683917	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59MN7C060C21**20	30,600	\$4,284
215933404	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59MN7C060C21**20	31,000	\$4,340
215933394	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59MN7C060C17**14	30,200	\$4,228
215683635	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	59MN7C080C17**14	20,200	\$2,828
215683633	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	59MN7C060C17**14	20,200	\$2,828
215677833	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	59MN7C080C21**20	51,000	\$7,140
215677823	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	59MN7C060C21**20	52,000	\$7,280
215933384	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59CU5B100C21**22	30,400	\$4,256
215933374	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59CU5B080C21**20	30,600	\$4,284
215676483	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	58TN*B110C21**20	46,500	\$6,510
215676473	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	58TN*B090C21**20	46,500	\$6,510
215683631	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	58TN*B090C17**16	20,000	\$2,800
215683629	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	58TN*B070C17**16	20,200	\$2,828
215683915	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59MN7C060C17**14	30,600	\$4,284
215683913	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59CU5B100C21**22	30,400	\$4,256
215677813	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	59CU5B100C21**22	50,500	\$7,070
215677803	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	59CU5B080C21**20	51,000	\$7,140
215933364	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	59CU5B060C17**16	31,000	\$4,340
215933354	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	58TN*B135C24**22	30,400	\$4,256
215676463	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	58TN*B090C17**16	46,500	\$6,510
215676453	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	58TN*B070C21**20	46,500	\$6,510
215683911	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59CU5B080C21**20	30,400	\$4,256
215683909	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59CU5B060C17**16	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215683627	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	58TN*B070C14**12	20,000	\$2,800
215683625	CARRIER	27VNA024A*030*	CAA**3017AM*+UI	58TN*B045C17**12	20,200	\$2,828
215677793	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	58TN*B135C24**22	50,500	\$7,070
215677783	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	58TN*B110C21**20	51,000	\$7,140
215933344	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	58TN*B090C21**20	30,400	\$4,256
215933334	CARRIER	27VNA336A*030*	CSAH*4212AM*+UI	58TN*B090C17**16	30,600	\$4,284
215676443	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	58TN*B070C17**16	47,000	\$6,580
215676433	CARRIER	27VNA048A*030*	CVAVA6021XMA*+UI	58TN*B045C17**12	47,500	\$6,650
215683907	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	58TN*B110C21**20	30,400	\$4,256
215683905	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	58TN*B090C21**20	30,400	\$4,256
215683619	CARRIER	27VNA024A*030*	CAA**3014AM*+UI	59TN6C040C14**10	20,600	\$2,884
215683617	CARRIER	27VNA024A*030*	CAA**3014AM*+UI	58TN*B070C14**12	20,200	\$2,828
215677773	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	58TN*B090C21**20	50,500	\$7,070
215677763	CARRIER	27VNA060A*030*	CAA**6024AM*+UI	58TN*B070C21**20	51,500	\$7,210
215676393	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	59TN6C120C24**22	46,000	\$6,440
215676383	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	59TN6C100C21**22	46,000	\$6,440
215683615	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	59TN6C080C17**14	19,700	\$2,758
215683613	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	59TN6C060C17**14	19,800	\$2,772
215683903	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	58TN*B090C17**16	30,400	\$4,256
215683901	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	58TN*B070C21**20	30,400	\$4,256
215676373	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	59MN7C120C24**22	46,000	\$6,440
215676363	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	59MN7C100C21**22	46,000	\$6,440
215683611	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	59TN6C040C14**10	20,200	\$2,828
215683609	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	59MN7C080C17**14	19,800	\$2,772
215683899	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	58TN*B070C17**16	30,400	\$4,256
215683897	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	58TN*B045C17**12	30,800	\$4,312
215676353	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	59MN7C080C21**20	46,000	\$6,440
215676343	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	59MN7C060C21**20	46,500	\$6,510
215683607	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	59MN7C060C17**14	19,800	\$2,772
215683605	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	58TN*B090C17**16	19,700	\$2,758
215683889	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	59TN6C080C17**14	30,800	\$4,312
215683887	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	59TN6C060C17**14	31,000	\$4,340
215677693	CARRIER	27VNA060A*030*	CVAVA6124XMA*+UI	59MN7C080C21**20	56,500	\$7,910
215677683	CARRIER	27VNA060A*030*	CVAVA6124XMA*+UI	59MN7C060C21**20	57,000	\$7,980
215676333	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	59CU5B100C21**22	46,000	\$6,440
215676323	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	58TN*B135C24**22	46,000	\$6,440
215683603	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	58TN*B070C17**16	19,700	\$2,758
215683601	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	58TN*B070C14**12	19,700	\$2,758

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215683883	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	59MN7C080C17**14	31,000	\$4,340
215676313	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	58TN*B110C21**20	46,000	\$6,440
215676303	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	58TN*B090C21**20	46,000	\$6,440
215677673	CARRIER	27VNA060A*030*	CVAVA6124XMA*+UI	59CU5B080C21**20	56,500	\$7,910
215683599	CARRIER	27VNA024A*030*	CAA**2517AM*+UI	58TN*B045C17**12	19,800	\$2,772
215683595	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	59TN6C060C17**14	20,400	\$2,856
215683881	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	59MN7C060C17**14	31,000	\$4,340
215683879	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	59CU5B060C17**16	31,000	\$4,340
215683593	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	59TN6C040C14**10	20,800	\$2,912
215683591	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	59MN7C080C17**14	20,400	\$2,856
215676293	CARRIER	27VNA048A*030*	CVAVA4924XMA*+UI	58TN*B070C21**20	46,500	\$6,510
215676273	CARRIER	27VNA048A*030*	CVAVA4824XMA*+UI	59TN6C120C24**22	45,500	\$6,370
215683877	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	58TN*B090C17**16	30,800	\$4,312
215683875	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	58TN*B070C17**16	30,800	\$4,312
215683589	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	59MN7C060C17**14	20,400	\$2,856
215683587	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	58TN*B090C17**16	20,400	\$2,856
215676263	CARRIER	27VNA048A*030*	CVAVA4824XMA*+UI	59MN7C120C24**22	45,500	\$6,370
215676253	CARRIER	27VNA048A*030*	CVAVA4824XMA*+UI	59MN7C080C21**20	45,500	\$6,370
215677613	CARRIER	27VNA060A*030*	CVAVA6121XMA*+UI	59MN7C060C21**20	57,500	\$8,050
215683873	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	58TN*B070C14**12	30,800	\$4,312
215683871	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	58TN*B045C17**12	31,200	\$4,368
215683585	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	58TN*B070C17**16	20,400	\$2,856
215683583	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	58TN*B070C14**12	20,400	\$2,856
215677593	CARRIER	27VNA060A*030*	CVAVA6121XMA*+UI	59CU5B080C21**20	56,500	\$7,910
215676243	CARRIER	27VNA048A*030*	CVAVA4824XMA*+UI	59CU5B100C21**22	45,500	\$6,370
215676233	CARRIER	27VNA048A*030*	CVAVA4824XMA*+UI	59CU5B080C21**20	46,000	\$6,440
215676223	CARRIER	27VNA048A*030*	CVAVA4824XMA*+UI	58TN*B135C24**22	45,500	\$6,370
215676213	CARRIER	27VNA048A*030*	CVAVA4824XMA*+UI	58TN*B110C21**20	45,500	\$6,370
215676203	CARRIER	27VNA048A*030*	CVAVA4824XMA*+UI	58TN*B090C21**20	45,500	\$6,370
215676193	CARRIER	27VNA048A*030*	CVAVA4824XMA*+UI	58TN*B070C21**20	46,000	\$6,440
215683581	CARRIER	27VNA024A*030*	CAA**2417AM*+UI	58TN*B045C17**12	20,400	\$2,856
215683575	CARRIER	27VNA024A*030*	CAA**2414AM*+UI	59TN6C040C14**10	20,800	\$2,912
215676163	CARRIER	27VNA048A*030*	CVAVA4821XMA*+UI	59TN6C100C21**22	45,500	\$6,370
215676153	CARRIER	27VNA048A*030*	CVAVA4821XMA*+UI	59TN6C080C17**14	44,500	\$6,230
215676143	CARRIER	27VNA048A*030*	CVAVA4821XMA*+UI	59MN7C100C21**22	45,500	\$6,370
215676133	CARRIER	27VNA048A*030*	CVAVA4821XMA*+UI	59CU5B060C17**16	46,500	\$6,510
215676123	CARRIER	27VNA048A*030*	CVAVA4821XMA*+UI	58TN*B110C21**20	45,500	\$6,370
215676113	CARRIER	27VNA048A*030*	CVAVA4821XMA*+UI	58TN*B070C17**16	46,000	\$6,440

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215676083	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	59TN6C120C24**22	46,500	\$6,510
215676073	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	59TN6C100C21**22	46,500	\$6,510
215676063	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	59MN7C120C24**22	46,500	\$6,510
215676053	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	59MN7C100C21**22	46,500	\$6,510
215676043	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	59MN7C080C21**20	46,500	\$6,510
215676033	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	59MN7C060C21**20	47,000	\$6,580
215676023	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	59CU5B100C21**22	46,500	\$6,510
215676013	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	59CU5B080C21**20	46,500	\$6,510
215676003	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	58TN*B135C24**22	46,500	\$6,510
215675993	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	58TN*B110C21**20	46,500	\$6,510
215675983	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	58TN*B090C21**20	46,500	\$6,510
215675973	CARRIER	27VNA048A*030*	CVAMA6124XMA*+UI	58TN*B070C21**20	46,500	\$6,510
215675943	CARRIER	27VNA048A*030*	CVAMA6024XMA*+UI	59TN6C100C21**22	46,000	\$6,440
215675933	CARRIER	27VNA048A*030*	CVAMA6024XMA*+UI	59MN7C120C24**22	46,000	\$6,440
215675923	CARRIER	27VNA048A*030*	CVAMA6024XMA*+UI	59MN7C100C21**22	46,000	\$6,440
215675913	CARRIER	27VNA048A*030*	CVAMA6024XMA*+UI	59CU5B100C21**22	46,000	\$6,440
215675903	CARRIER	27VNA048A*030*	CVAMA6024XMA*+UI	59CU5B080C21**20	46,500	\$6,510
215675893	CARRIER	27VNA048A*030*	CVAMA6024XMA*+UI	58TN*B135C24**22	46,000	\$6,440
215675883	CARRIER	27VNA048A*030*	CVAMA6024XMA*+UI	58TN*B110C21**20	46,000	\$6,440
215675873	CARRIER	27VNA048A*030*	CVAMA6024XMA*+UI	58TN*B090C21**20	46,000	\$6,440
215675863	CARRIER	27VNA048A*030*	CVAMA6024XMA*+UI	58TN*B070C21**20	46,500	\$6,510
215675833	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	59TN6C100C21**22	46,500	\$6,510
215675823	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	59TN6C080C17**14	45,500	\$6,370
215675813	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	59MN7C100C21**22	46,500	\$6,510
215675803	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	59MN7C080C21**20	46,500	\$6,510
215675793	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	59MN7C080C17**14	47,000	\$6,580
215675783	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	59MN7C060C21**20	47,000	\$6,580
215675773	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	59CU5B100C21**22	46,500	\$6,510
215675763	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	59CU5B080C21**20	46,500	\$6,510
215675753	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	59CU5B060C17**16	47,000	\$6,580
215675743	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	58TN*B110C21**20	46,500	\$6,510
215675733	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	58TN*B090C21**20	46,500	\$6,510
215675723	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	58TN*B090C17**16	46,500	\$6,510
215675713	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	58TN*B070C21**20	46,500	\$6,510
215675703	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	58TN*B070C17**16	47,000	\$6,580
215675693	CARRIER	27VNA048A*030*	CVAMA6021XMA*+UI	58TN*B045C17**12	47,500	\$6,650
215675653	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	59TN6C100C21**22	46,500	\$6,510
215675643	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	59TN6C080C17**14	45,500	\$6,370

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215675633	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	59MN7C100C21**22	46,500	\$6,510
215675623	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	59MN7C080C21**20	46,500	\$6,510
215675613	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	59MN7C080C17**14	47,000	\$6,580
215675603	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	59MN7C060C21**20	47,000	\$6,580
215675593	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	59CU5B100C21**22	46,500	\$6,510
215675583	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	59CU5B060C17**16	47,000	\$6,580
215675573	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	58TN*B110C21**20	46,500	\$6,510
215675563	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	58TN*B090C21**20	46,500	\$6,510
215683573	CARRIER	27VNA024A*030*	CAA**2414AM*+UI	58TN*B070C14**12	20,400	\$2,856
215675553	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	58TN*B090C17**16	46,500	\$6,510
215675543	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	58TN*B070C21**20	46,500	\$6,510
215675533	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	58TN*B070C17**16	47,000	\$6,580
215675523	CARRIER	27VNA048A*030*	CVAMA4921XMA*+UI	58TN*B045C17**12	47,500	\$6,650
215675483	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	59TN6C100C21**22	45,500	\$6,370
215675473	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	59TN6C080C21**20	45,500	\$6,370
215675463	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	59TN6C080C17**14	44,500	\$6,230
215675453	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	59MN7C100C21**22	45,500	\$6,370
215675443	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	59MN7C080C21**20	46,000	\$6,440
215675433	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	59MN7C060C21**20	46,000	\$6,440
215675423	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	59CU5B100C21**22	45,500	\$6,370
215675413	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	59CU5B080C21**20	46,000	\$6,440
215675403	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	59CU5B060C17**16	46,500	\$6,510
215675393	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	58TN*B110C21**20	45,500	\$6,370
215675383	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	58TN*B090C21**20	45,500	\$6,370
215675373	CARRIER	27VNA048A*030*	CVAMA4821XMA*+UI	58TN*B070C17**16	46,000	\$6,440
215675343	CARRIER	27VNA048A*030*	FE5BNBD60L*+UI		41,000	\$5,740
215675333	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59TN6C120C24**22	42,000	\$5,880
215675323	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59TN6C100C21**22	42,000	\$5,880
215675303	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59MN7C120C24**22	42,000	\$5,880
215675293	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59MN7C100C21**22	42,000	\$5,880
215675283	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59MN7C080C21**20	42,000	\$5,880
215675273	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59MN7C080C17**14	42,500	\$5,950
215675263	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59MN7C060C21**20	42,500	\$5,950
215675253	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59CU5B100C21**22	42,000	\$5,880
215675243	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59CU5B080C21**20	42,000	\$5,880
215675233	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	59CU5B060C17**16	42,500	\$5,950
215675223	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	58TN*B135C24**22	42,000	\$5,880
215675213	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	58TN*B110C21**20	42,000	\$5,880

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215675203	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	58TN*B090C21**20	42,000	\$5,880
215675193	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	58TN*B090C17**16	42,500	\$5,950
215675183	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	58TN*B070C21**20	42,500	\$5,950
215675173	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	58TN*B070C17**16	42,500	\$5,950
215675153	CARRIER	27VNA048A*030*	CSAH*6012AM*+UI	58TN*B045C17**12	43,000	\$6,020
215674977	CARRIER	27VNA048A*030*	CSAH*4812AM*+UI	59MN7C080C17**14	43,500	\$6,090
215674954	CARRIER	27VNA048A*030*	CSAH*4812AM*+UI	59MN7C060C21**20	43,500	\$6,090
215674897	CARRIER	27VNA048A*030*	CSAH*4812AM*+UI	59CU5B060C17**16	43,500	\$6,090
215674732	CARRIER	27VNA048A*030*	CSAH*4812AM*+UI	58TN*B045C17**12	44,000	\$6,160
215674658	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59TN6C120C24**22	42,000	\$5,880
215674637	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59TN6C100C21**22	42,000	\$5,880
215674615	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59MN7C120C24**22	42,000	\$5,880
215674594	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59MN7C100C21**22	42,000	\$5,880
215674576	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59MN7C080C21**20	42,000	\$5,880
215674553	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59MN7C060C21**20	42,500	\$5,950
215674531	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59CU5B100C21**22	42,000	\$5,880
215674514	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	59CU5B080C21**20	42,000	\$5,880
215674504	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	58TN*B135C24**22	42,000	\$5,880
215674494	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	58TN*B110C21**20	42,000	\$5,880
215674484	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	58TN*B090C21**20	42,000	\$5,880
215674474	CARRIER	27VNA048A*030*	CAA**6124AM*+UI	58TN*B070C21**20	42,000	\$5,880
215674444	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59TN6C100C21**22	42,000	\$5,880
215674434	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59TN6C080C17**14	41,500	\$5,810
215674424	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59MN7C100C21**22	42,000	\$5,880
215674414	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59MN7C080C21**20	42,000	\$5,880
215674404	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59MN7C060C21**20	42,500	\$5,950
215674394	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59CU5B100C21**22	42,000	\$5,880
215674384	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	59CU5B060C17**16	42,500	\$5,950
215680003	CARRIER	27VNA036A*030*	CSAH*6012AM*+UI	59TN7A120C24**22	30,000	\$4,200
215674374	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58TN*B110C21**20	42,000	\$5,880
215674364	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58TN*B090C21**20	42,000	\$5,880
215674354	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58TN*B090C17**16	42,000	\$5,880
215674344	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58TN*B070C21**20	42,000	\$5,880
215679993	CARRIER	27VNA036A*030*	CSAH*6012AM*+UI	59TN7A100C21**22	30,000	\$4,200
215679983	CARRIER	27VNA036A*030*	CSAH*6012AM*+UI	59TN7A080C21**20	30,000	\$4,200
215674334	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58TN*B070C17**16	42,500	\$5,950
215674324	CARRIER	27VNA048A*030*	CAA**6121AM*+UI	58TN*B045C17**12	43,000	\$6,020
215679963	CARRIER	27VNA036A*030*	CSAH*6012AM*+UI	59TN7A060C17**16	30,200	\$4,228

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215674284	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59TN6C120C24**22	41,500	\$5,810
215674274	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59TN6C100C21**22	41,500	\$5,810
215679953	CARRIER	27VNA036A*030*	CSAH*6012AM*+UI	58CU*B060C17**16	30,000	\$4,200
215679943	CARRIER	27VNA036A*030*	CSAH*6012AM*+UI	58CU*B040C17**12	29,800	\$4,172
215674264	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59MN7C120C24**22	42,000	\$5,880
215674254	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59MN7C100C21**22	41,500	\$5,810
215679933	CARRIER	27VNA036A*030*	CSAH*6012AM*+UI	59TN6C080C21**20	30,000	\$4,200
215679923	CARRIER	27VNA036A*030*	CSAH*4812AM*+UI	59TN7A120C24**22	30,400	\$4,256
215674244	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59MN7C080C21**20	42,000	\$5,880
215674234	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59MN7C060C21**20	42,000	\$5,880
215679913	CARRIER	27VNA036A*030*	CSAH*4812AM*+UI	59TN7A100C21**22	30,400	\$4,256
215679903	CARRIER	27VNA036A*030*	CSAH*4812AM*+UI	59TN7A080C21**20	30,400	\$4,256
215674224	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59CU5B100C21**22	41,500	\$5,810
215674214	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	59CU5B080C21**20	42,000	\$5,880
215679883	CARRIER	27VNA036A*030*	CSAH*4812AM*+UI	58CU*B060C17**16	30,400	\$4,256
215674204	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	58TN*B135C24**22	41,500	\$5,810
215674194	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	58TN*B110C21**20	41,500	\$5,810
215679873	CARRIER	27VNA036A*030*	CSAH*4812AM*+UI	58CU*B040C17**12	30,400	\$4,256
215679863	CARRIER	27VNA036A*030*	CSAH*4812AM*+UI	59TN6C080C21**20	30,400	\$4,256
215674184	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	58TN*B090C21**20	41,500	\$5,810
215674174	CARRIER	27VNA048A*030*	CAA**6024AM*+UI	58TN*B070C21**20	42,000	\$5,880
215674144	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59TN6C100C21**22	42,500	\$5,950
215674124	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59MN7C100C21**22	42,500	\$5,950
215674114	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59MN7C080C21**20	42,500	\$5,950
215674104	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59MN7C080C17**14	43,000	\$6,020
215674094	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59MN7C060C21**20	43,000	\$6,020
215674084	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59CU5B080C21**20	42,500	\$5,950
215674074	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	59CU5B060C17**16	43,000	\$6,020
215674064	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	58TN*B110C21**20	42,500	\$5,950
215674054	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	58TN*B090C21**20	42,500	\$5,950
215674044	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	58TN*B090C17**16	42,500	\$5,950
215674034	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	58TN*B070C21**20	42,500	\$5,950
215674024	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	58TN*B070C17**16	43,000	\$6,020
215674014	CARRIER	27VNA048A*030*	CAA**4821AM*+UI	58TN*B045C17**12	43,500	\$6,090
215679693	CARRIER	27VNA036A*030*	CAA**6124AM*+UI	59TN7A120C24**22	29,800	\$4,172
215679683	CARRIER	27VNA036A*030*	CAA**6124AM*+UI	59TN7A100C21**22	29,800	\$4,172
215662627	CARRIER	27VNA048A*030*	FE5BN(B,X)C48L*+UI		42,000	\$5,880
215679673	CARRIER	27VNA036A*030*	CAA**6124AM*+UI	59TN7A080C21**20	29,800	\$4,172

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215679663	CARRIER	27VNA036A*030*	CAA**6124AM*+UI	59TN6C080C21**20	29,800	\$4,172
215679653	CARRIER	27VNA036A*030*	CAA**6121AM*+UI	59TN7A100C21**22	29,800	\$4,172
215679643	CARRIER	27VNA036A*030*	CAA**6121AM*+UI	59TN7A080C21**20	29,800	\$4,172
215679633	CARRIER	27VNA036A*030*	CAA**6121AM*+UI	59TN7A080C17**16	30,000	\$4,200
215679623	CARRIER	27VNA036A*030*	CAA**6121AM*+UI	59TN7A060C17**16	30,200	\$4,228
215679613	CARRIER	27VNA036A*030*	CAA**6121AM*+UI	58CU*B060C17**16	29,800	\$4,172
215679603	CARRIER	27VNA036A*030*	CAA**6121AM*+UI	58CU*B040C17**12	29,800	\$4,172
215679593	CARRIER	27VNA036A*030*	CAA**6121AM*+UI	59TN6C080C21**20	29,800	\$4,172
215679583	CARRIER	27VNA036A*030*	CAA**6024AM*+UI	59TN7A120C24**22	29,800	\$4,172
215679573	CARRIER	27VNA036A*030*	CAA**6024AM*+UI	59TN7A100C21**22	29,800	\$4,172
215679563	CARRIER	27VNA036A*030*	CAA**6024AM*+UI	59TN7A080C21**20	29,800	\$4,172
215679553	CARRIER	27VNA036A*030*	CAA**6024AM*+UI	59TN6C080C21**20	29,800	\$4,172
215679543	CARRIER	27VNA036A*030*	CAA**4821AM*+UI	59TN7A100C21**22	30,200	\$4,228
215679533	CARRIER	27VNA036A*030*	CAA**4821AM*+UI	59TN7A080C21**20	30,200	\$4,228
215679523	CARRIER	27VNA036A*030*	CAA**4821AM*+UI	59TN7A080C17**16	30,400	\$4,256
215679513	CARRIER	27VNA036A*030*	CAA**4821AM*+UI	59TN7A060C17**16	30,600	\$4,284
215679503	CARRIER	27VNA036A*030*	CAA**4821AM*+UI	58CU*B060C17**16	30,200	\$4,228
215679493	CARRIER	27VNA036A*030*	CAA**4821AM*+UI	58CU*B040C17**12	30,200	\$4,228
215679483	CARRIER	27VNA036A*030*	CAA**4821AM*+UI	59TN6C080C21**20	30,200	\$4,228
215679473	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59TN7A100C21**22	30,400	\$4,256
215679463	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59TN7A080C21**20	30,400	\$4,256
215679453	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59TN7A080C17**16	30,600	\$4,284
215679443	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59TN7A060C17**16	30,600	\$4,284
215679433	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	58CU*B060C17**16	30,200	\$4,228
215679423	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	58CU*B040C17**12	30,200	\$4,228
215679413	CARRIER	27VNA036A*030*	CAA**4321AM*+UI	59TN6C080C21**20	30,400	\$4,256
215679403	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	59TN7A100C21**22	31,000	\$4,340
215679393	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	59TN7A080C21**20	31,000	\$4,340
215679363	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	58CU*B060C17**16	31,000	\$4,340
215679353	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	58CU*B040C17**12	30,800	\$4,312
215679343	CARRIER	27VNA036A*030*	CAA**4221AM*+UI	59TN6C080C21**20	31,000	\$4,340
215679333	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59TN7A100C21**22	30,400	\$4,256
215679323	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59TN7A080C21**20	30,400	\$4,256
215679313	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59TN7A080C17**16	30,600	\$4,284
215679303	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59TN7A060C17**16	30,600	\$4,284
215679293	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	58CU*B060C17**16	30,400	\$4,256
215679283	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	58CU*B040C17**12	30,200	\$4,228
215679273	CARRIER	27VNA036A*030*	CAA**3721AM*+UI	59TN6C080C21**20	30,400	\$4,256

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215679263	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	59TN7A080C17**16	31,000	\$4,340
215679253	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	59TN7A060C17**16	31,000	\$4,340
215679243	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	58CU*B060C17**16	30,600	\$4,284
215679233	CARRIER	27VNA036A*030*	CAA**3717AM*+UI	58CU*B040C17**12	30,600	\$4,284
215587917	CARRIER	27VNA154A*030*	FE5BNBD60L*+UI		50,000	\$7,000
215588191	CARRIER	27VNA154A*030*	FE5BN(B,X)C48L*+UI		50,000	\$7,000
215931484	CARRIER	27VNA360A*030*	FE5BNBD60L*+UI		46,000	\$6,440
215931485	CARRIER	27VNA336A*030*	FE5BN(B,X)C48L*+UI		29,800	\$4,172
215931486	CARRIER	27VNA348A*030*	FE5BNBD60L*+UI		39,000	\$5,460
207683292	Carrier	38MARBQ24AA3	40MBCAQ24XA3		21,000	\$2,940
207614950	Carrier	38MPRBQ12AA3	40MPHBQ12XA3		10,400	\$1,456
207826658	Carrier	38MPRBQ18AA3	40MPHBQ18XA3		20,200	\$2,828
206788846	CARRIER	25VNA436A*031*	CAP**4221AL*+UI	59CU5A060C17**16	32,200	\$4,508
206788850	CARRIER	25VNA436A*031*	CAP**4224AL*+UI	59CU5A100C21**22	32,000	\$4,480
206788854	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	59CU5A060C17**16	31,200	\$4,368
206788855	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	59CU5A080C21**20	31,000	\$4,340
206788858	CARRIER	25VNA436A*031*	CAP**4824AL*+UI	59CU5A100C21**22	30,800	\$4,312
206788866	CARRIER	25VNA436A*031*	CSPH*3612AL*+UI	59CU5A100C21**22	31,600	\$4,424
206788874	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	58TN*A045C17**12	31,200	\$4,368
206788876	CARRIER	25VNA436A*031*	CNPV*4217AL*+UI	58TN*A045C17**12	32,000	\$4,480
206788880	CARRIER	25VNA436A*031*	CSPH*4212AL*+UI	58TN*A045C17**12	31,600	\$4,424
208447885	CARRIER	38MURAQ18AB3	40MUAAQ18XA3		13,500	\$1,890
208447887	CARRIER	38MURAQ24AB3	40MUAAQ24XA3		19,200	\$2,688
208447883	CARRIER	38MURAQ36AB3	40MUAAQ36XA3		30,400	\$4,256
206788417	CARRIER	25VNA424A*031*	CSPH*3612AL*+UI	58TN*A070C14**12	24,800	\$3,472
206788427	CARRIER	25VNA424A*031*	CSPH*4212AL*+UI	58TN*A090C17**16	24,600	\$3,444
206788571	CARRIER	25VNA424A*031*	CSPH*3612AL*+UI	59CU5A060C17**16	25,000	\$3,500
206764878	CARRIER	25VNA837A*031*	CAP**3617AL*+UI	58TN*A070C17**16	31,400	\$4,396
206764883	CARRIER	25VNA837A*031*	CAP**3617AL*+UI	58TN*A070C14**12	31,400	\$4,396
206764884	CARRIER	25VNA837A*031*	CAP**3617AL*+UI	58TN*A090C17**16	31,200	\$4,368
206764886	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	58TN*A070C17**16	31,200	\$4,368
206764890	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	59TN6B080C17**14	31,400	\$4,396
206764892	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	59MN7B080C17**14	31,400	\$4,396
206764894	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	59MN7B100C21**22	31,200	\$4,368
206764896	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	59TN6B100C21**22	31,200	\$4,368
206764899	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	59MN7B060C21**20	31,400	\$4,396
206764911	CARRIER	25VNA837A*031*	CAP**3721AL*+UI	58TN*A090C21**20	31,800	\$4,452
206764917	CARRIER	25VNA837A*031*	CAP**3721AL*+UI	59MN7B100C21**22	31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206764919	CARRIER	25VNA837A*031*	CAP**3721AL*+UI	59TN6B100C21**22	31,800	\$4,452
206764924	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	58TN*A070C17**16	31,400	\$4,396
206764928	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	59TN6B080C17**14	31,600	\$4,424
206764930	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	59MN7B080C17**14	31,600	\$4,424
206764932	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	59MN7B100C21**22	31,200	\$4,368
206764934	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	59TN6B100C21**22	31,200	\$4,368
206764935	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	58TN*A090C17**16	31,200	\$4,368
206764937	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	59MN7B060C21**20	31,600	\$4,424
206764939	CARRIER	25VNA837A*031*	CAP**4224AL*+UI	58TN*A090C21**20	31,400	\$4,396
206764940	CARRIER	25VNA837A*031*	CAP**4224AL*+UI	58TN*A135C24**22	31,200	\$4,368
206764941	CARRIER	25VNA837A*031*	CAP**4224AL*+UI	59TN6B120C24**22	31,200	\$4,368
206764943	CARRIER	25VNA837A*031*	CAP**4224AL*+UI	59MN7B100C21**22	31,200	\$4,368
206764944	CARRIER	25VNA837A*031*	CAP**4224AL*+UI	59MN7B120C24**22	31,400	\$4,396
206764946	CARRIER	25VNA837A*031*	CAP**4224AL*+UI	59TN6B100C21**22	31,200	\$4,368
206764948	CARRIER	25VNA837A*031*	CAP**4224AL*+UI	59MN7B060C21**20	31,600	\$4,424
206764952	CARRIER	25VNA837A*031*	CAP**4321AL*+UI	58TN*A090C21**20	31,800	\$4,452
206764958	CARRIER	25VNA837A*031*	CAP**4321AL*+UI	59MN7B100C21**22	31,800	\$4,452
206764960	CARRIER	25VNA837A*031*	CAP**4321AL*+UI	59TN6B100C21**22	31,800	\$4,452
206764961	CARRIER	25VNA837A*031*	CAP**4321AL*+UI	58TN*A090C17**16	31,800	\$4,452
206764967	CARRIER	25VNA837A*031*	CAP**4821AL*+UI	58TN*A090C21**20	31,400	\$4,396
206764969	CARRIER	25VNA837A*031*	CAP**4821AL*+UI	59TN6B080C17**14	31,800	\$4,452
206764973	CARRIER	25VNA837A*031*	CAP**4821AL*+UI	59MN7B100C21**22	31,400	\$4,396
206764975	CARRIER	25VNA837A*031*	CAP**4821AL*+UI	59TN6B100C21**22	31,400	\$4,396
206764976	CARRIER	25VNA837A*031*	CAP**4821AL*+UI	58TN*A090C17**16	31,400	\$4,396
206764978	CARRIER	25VNA837A*031*	CAP**4821AL*+UI	59MN7B060C21**20	31,800	\$4,452
206764981	CARRIER	25VNA837A*031*	CAP**4824AL*+UI	58TN*A135C24**22	31,400	\$4,396
206764982	CARRIER	25VNA837A*031*	CAP**4824AL*+UI	59TN6B120C24**22	31,400	\$4,396
206764984	CARRIER	25VNA837A*031*	CAP**4824AL*+UI	59MN7B100C21**22	31,400	\$4,396
206764985	CARRIER	25VNA837A*031*	CAP**4824AL*+UI	59MN7B120C24**22	31,400	\$4,396
206764987	CARRIER	25VNA837A*031*	CAP**4824AL*+UI	59TN6B100C21**22	31,400	\$4,396
206764989	CARRIER	25VNA837A*031*	CAP**4824AL*+UI	59MN7B060C21**20	31,600	\$4,424
206765000	CARRIER	25VNA837A*031*	CNPV*4217AL*+UI	58TN*A090C17**16	31,400	\$4,396
206765004	CARRIER	25VNA837A*031*	CNPV*4221AL*+UI	58TN*A090C21**20	31,400	\$4,396
206765010	CARRIER	25VNA837A*031*	CNPV*4221AL*+UI	59MN7B100C21**22	31,400	\$4,396
206765012	CARRIER	25VNA837A*031*	CNPV*4221AL*+UI	59TN6B100C21**22	31,400	\$4,396
206765013	CARRIER	25VNA837A*031*	CNPV*4221AL*+UI	58TN*A090C17**16	31,400	\$4,396
206765017	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	58TN*A070C17**16	31,600	\$4,424
206765019	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	58TN*A090C21**20	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206765021	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	59TN6B080C17**14	31,800	\$4,452
206765023	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	59MN7B080C17**14	31,800	\$4,452
206765025	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	59MN7B100C21**22	31,400	\$4,396
206765027	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	59TN6B100C21**22	31,400	\$4,396
206765030	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	59MN7B060C21**20	31,800	\$4,452
206765032	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	58TN*A090C21**20	31,600	\$4,424
206765033	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	58TN*A135C24**22	31,400	\$4,396
206765034	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	59TN6B120C24**22	31,400	\$4,396
206765036	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	59MN7B100C21**22	31,400	\$4,396
206765037	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	59MN7B120C24**22	31,600	\$4,424
206765039	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	59TN6B100C21**22	31,400	\$4,396
206765041	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	59MN7B060C21**20	31,800	\$4,452
206765043	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	58TN*A070C17**16	31,800	\$4,452
206765045	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	58TN*A090C21**20	31,600	\$4,424
206765046	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	58TN*A135C24**22	31,400	\$4,396
206765049	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	59TN6B120C24**22	31,600	\$4,424
206765053	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	59MN7B100C21**22	31,600	\$4,424
206765054	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	59MN7B120C24**22	31,600	\$4,424
206765056	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	59TN6B100C21**22	31,600	\$4,424
206765057	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	58TN*A070C14**12	31,600	\$4,424
206765062	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	58TN*A070C17**16	31,800	\$4,452
206765064	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	58TN*A090C21**20	31,600	\$4,424
206765065	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	58TN*A135C24**22	31,600	\$4,424
206765068	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	59TN6B120C24**22	31,600	\$4,424
206765072	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	59MN7B100C21**22	31,600	\$4,424
206765073	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	59MN7B120C24**22	31,600	\$4,424
206765075	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	59TN6B100C21**22	31,600	\$4,424
206765076	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	58TN*A070C14**12	31,800	\$4,452
206765077	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	58TN*A090C17**16	31,600	\$4,424
206765079	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	59MN7B060C21**20	31,800	\$4,452
206765081	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	58TN*A070C17**16	31,800	\$4,452
206765083	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	58TN*A090C21**20	31,600	\$4,424
206765087	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	59TN6B120C24**22	31,600	\$4,424
206765091	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	59MN7B100C21**22	31,600	\$4,424
206765092	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	59MN7B120C24**22	31,800	\$4,452
206765094	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	59TN6B100C21**22	31,600	\$4,424
206765096	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	58TN*A090C17**16	31,600	\$4,424
206765098	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	59MN7B060C21**20	32,000	\$4,480

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206765099	CARRIER	25VNA837A*031*	CAP**3617AL*+UI	58CU*A040C17**12	31,200	\$4,368
206765100	CARRIER	25VNA837A*031*	CAP**3721AL*+UI	58CU*A040C17**12	31,800	\$4,452
206765101	CARRIER	25VNA837A*031*	CAP**3721AL*+UI	58CU*A060C17**16	32,000	\$4,480
206765102	CARRIER	25VNA837A*031*	CAP**3721AL*+UI	58CU*A100C21**20	31,800	\$4,452
206765103	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	58CU*A060C17**16	31,400	\$4,396
206765106	CARRIER	25VNA837A*031*	CAP**4224AL*+UI	58CU*A100C21**20	31,400	\$4,396
206765107	CARRIER	25VNA837A*031*	CAP**4321AL*+UI	58CU*A040C17**12	31,800	\$4,452
206765108	CARRIER	25VNA837A*031*	CAP**4321AL*+UI	58CU*A060C17**16	31,800	\$4,452
206765110	CARRIER	25VNA837A*031*	CAP**4321AL*+UI	58CU*A100C21**20	31,800	\$4,452
206765111	CARRIER	25VNA837A*031*	CAP**4821AL*+UI	58CU*A040C17**12	31,400	\$4,396
206765112	CARRIER	25VNA837A*031*	CAP**4821AL*+UI	58CU*A060C17**16	31,600	\$4,424
206765114	CARRIER	25VNA837A*031*	CAP**4821AL*+UI	58CU*A100C21**20	31,600	\$4,424
206765116	CARRIER	25VNA837A*031*	CAP**4824AL*+UI	58CU*A100C21**20	31,400	\$4,396
206765122	CARRIER	25VNA837A*031*	CNPV*4217AL*+UI	58CU*A040C17**12	31,600	\$4,424
206765123	CARRIER	25VNA837A*031*	CNPV*4217AL*+UI	58CU*A060C17**16	31,600	\$4,424
206765125	CARRIER	25VNA837A*031*	CNPV*4221AL*+UI	58CU*A100C21**20	31,400	\$4,396
206765127	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	58CU*A100C21**20	31,600	\$4,424
206765128	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	58CU*A040C17**12	31,600	\$4,424
206765129	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	58CU*A060C17**16	31,800	\$4,452
206765131	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	58CU*A100C21**20	31,600	\$4,424
206765132	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	58CU*A040C17**12	31,600	\$4,424
206765133	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	58CU*A060C17**16	31,800	\$4,452
206765135	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	58CU*A100C21**20	31,800	\$4,452
206765139	CARRIER	25VNA837A*031*	CAP**3721AL*+UI	59CU5A080C21**20	31,800	\$4,452
206765140	CARRIER	25VNA837A*031*	CAP**3721AL*+UI	59CU5A100C21**22	31,800	\$4,452
206765142	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	59CU5A100C21**22	31,200	\$4,368
206765143	CARRIER	25VNA837A*031*	CAP**4224AL*+UI	59CU5A080C21**20	31,200	\$4,368
206765145	CARRIER	25VNA837A*031*	CAP**4321AL*+UI	59CU5A080C21**20	31,800	\$4,452
206765151	CARRIER	25VNA837A*031*	CAP**4824AL*+UI	59CU5A100C21**22	31,400	\$4,396
206765154	CARRIER	25VNA837A*031*	CNPV*3621AL*+UI	59CU5A080C21**20	31,200	\$4,368
206765158	CARRIER	25VNA837A*031*	CNPV*4221AL*+UI	59CU5A100C21**22	31,400	\$4,396
206765159	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	59CU5A080C21**20	31,400	\$4,396
206765162	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	59CU5A100C21**22	31,400	\$4,396
206765164	CARRIER	25VNA837A*031*	CSPH*4212AL*+UI	59CU5A100C21**22	31,600	\$4,424
206765165	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	59CU5A080C21**20	31,600	\$4,424
206765166	CARRIER	25VNA837A*031*	CSPH*4812AL*+UI	59CU5A100C21**22	31,600	\$4,424
206764312	CARRIER	25VNA825A*032*	CAP**2517AL*+UI	58TN*A090C17**16	20,600	\$2,884
206764480	CARRIER	25VNA825A*032*	CAP**3721AL*+UI	58CU*A040C17**12	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206764515	CARRIER	25VNA825A*032*	CAP**3721AL*+UI	59CU5A080C21**20	20,600	\$2,884
206764516	CARRIER	25VNA825A*032*	CAP**3721AL*+UI	59CU5A100C21**22	20,600	\$2,884
206788899	CARRIER	25VNA448A*031*	FE4ANB006L+UI		42,500	\$5,950
206788911	CARRIER	25VNA448A*031*	CSPH*6012AL*+UI	58TN*A135C24**22	43,000	\$6,020
206788914	CARRIER	25VNA448A*031*	CAP**4821AL*+UI	59MN7B100C21**22	43,500	\$6,090
206788918	CARRIER	25VNA448A*031*	CAP**6024AL*+UI	59MN7B120C24**22	43,500	\$6,090
206788931	CARRIER	25VNA448A*031*	CAP**6024AL*+UI	59TN6B120C24**22	43,000	\$6,020
206788941	CARRIER	25VNA448A*031*	CSPH*6012AL*+UI	59TN6B100C21**22	43,000	\$6,020
206788943	CARRIER	25VNA448A*031*	CAP**4821AL*+UI	58CU*A100C21**20	43,500	\$6,090
206788958	CARRIER	25VNA448A*031*	CAP**4824AL*+UI	59CU5A080C21**20	43,500	\$6,090
206788966	CARRIER	25VNA448A*031*	CSPH*6012AL*+UI	59CU5A080C21**20	43,500	\$6,090
206788967	CARRIER	25VNA448A*031*	CSPH*6012AL*+UI	59CU5A100C21**22	43,000	\$6,020
206788969	CARRIER	25VNA448A*031*	CAP**6024AL*+UI	59TN6B100C21**22	43,000	\$6,020
206788900	CARRIER	25VNA448A*031*	FE4AN(B,F)005L+UI		43,000	\$6,020
206788907	CARRIER	25VNA448A*031*	CAP**6124AL*+UI	58TN*A135C24**22	43,000	\$6,020
206788910	CARRIER	25VNA448A*031*	CSPH*6012AL*+UI	58TN*A090C21**20	43,000	\$6,020
206788928	CARRIER	25VNA448A*031*	CAP**4821AL*+UI	59TN6B100C21**22	43,500	\$6,090
206788934	CARRIER	25VNA448A*031*	CAP**6124AL*+UI	59TN6B120C24**22	43,000	\$6,020
206788947	CARRIER	25VNA448A*031*	CAP**6024AL*+UI	58CU*A100C21**20	43,500	\$6,090
206788959	CARRIER	25VNA448A*031*	CAP**4824AL*+UI	59CU5A100C21**22	43,500	\$6,090
209251548	CARRIER	25VNA448A*031*	CNPV*4821AL*+UI	59MN7B100C21**22	43,500	\$6,090
206788961	CARRIER	25VNA448A*031*	CAP**6024AL*+UI	59CU5A100C21**22	43,000	\$6,020
206788963	CARRIER	25VNA448A*031*	CAP**6121AL*+UI	59CU5A100C21**22	43,000	\$6,020
206788916	CARRIER	25VNA448A*031*	CAP**4824AL*+UI	59MN7B120C24**22	43,500	\$6,090
206788927	CARRIER	25VNA448A*031*	CSPH*6012AL*+UI	59MN7B120C24**22	43,500	\$6,090
206788933	CARRIER	25VNA448A*031*	CAP**6121AL*+UI	59TN6B100C21**22	43,500	\$6,090
206788956	CARRIER	25VNA448A*031*	CAP**4821AL*+UI	59CU5A080C21**20	43,500	\$6,090
206788904	CARRIER	25VNA448A*031*	CAP**6024AL*+UI	58TN*A135C24**22	43,000	\$6,020
206788919	CARRIER	25VNA448A*031*	CAP**6121AL*+UI	59MN7B100C21**22	43,500	\$6,090
206788921	CARRIER	25VNA448A*031*	CAP**6124AL*+UI	59MN7B120C24**22	43,500	\$6,090
206788926	CARRIER	25VNA448A*031*	CSPH*6012AL*+UI	59MN7B100C21**22	43,000	\$6,020
206788929	CARRIER	25VNA448A*031*	CAP**4824AL*+UI	59TN6B120C24**22	43,500	\$6,090
206788939	CARRIER	25VNA448A*031*	CSPH*6012AL*+UI	59TN6B120C24**22	43,000	\$6,020
206788945	CARRIER	25VNA448A*031*	CAP**4824AL*+UI	58CU*A100C21**20	43,500	\$6,090
206788951	CARRIER	25VNA448A*031*	CAP**6124AL*+UI	58CU*A100C21**20	43,500	\$6,090
206788955	CARRIER	25VNA448A*031*	CSPH*6012AL*+UI	58CU*A100C21**20	43,500	\$6,090
206788964	CARRIER	25VNA448A*031*	CAP**6124AL*+UI	59CU5A080C21**20	43,500	\$6,090
215323745	CARRIER	37MAHAQ18AA3	45MAHAQ18XA3		16,600	\$2,324

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210025752	CARRIER	38MURAQ60AB3	40MUAAQ60XA3		42,000	\$5,880
213372211	CARRIER	38MURAQ60AB3	40MULAQ60XDX + CI		37,000	\$5,180
215323813	CARRIER	37MAHAQ18AA3	45MBDAQ18XA3		15,000	\$2,100
215323811	CARRIER	37MAHAQ18AA3	45MBFAQ16XA3		14,200	\$1,988
215323810	CARRIER	37MAHAQ18AA3	45MBCAQ18XA3		14,900	\$2,086
215323809	CARRIER	37MAHAQ18AA3	45MCCAQ18XA3		14,500	\$2,030
215323807	CARRIER	37MAHAQ12AA3	45MBDAQ12XA3		9,600	\$1,344
215323806	CARRIER	37MAHAQ12AA3	45MBFAQ12XA3		9,800	\$1,372
215323805	CARRIER	37MAHAQ12AA3	45MBCAQ12XA3		10,000	\$1,400
215323804	CARRIER	37MAHAQ12AA3	45MCCAQ12XA3		9,600	\$1,344
215323744	CARRIER	37MAHAQ12AA3	45MAHAQ12XA3		9,800	\$1,372
215323720	CARRIER	37MUHAQ36AA3	45MUHAQ36XX3		31,000	\$4,340
215323816	CARRIER	37MAHAQ24AA3	45MCFAQ24XA3		20,200	\$2,828
215323815	CARRIER	37MAHAQ24AA3	45MBCAQ24XA3		20,400	\$2,856
215323812	CARRIER	37MAHAQ18AA3	45MCFAQ18XA3		14,400	\$2,016
215323849	CARRIER	37MBHAQ58AA3	45MBDAQ58XH3		45,000	\$6,300
215323847	CARRIER	37MBHAQ48AA3	45MBDAQ48XH3		45,000	\$6,300
215323844	CARRIER	37MBHAQ36AA3	45MBDAQ36XH3		31,600	\$4,424
215323747	CARRIER	37MAHAQ33AA3	45MAHAQ33XA3		30,000	\$4,200
215323817	CARRIER	37MAHAQ24AA3	45MBDAQ24XH3		21,600	\$3,024
215323746	CARRIER	37MAHAQ24AA3	45MAHAQ24XA3		21,000	\$2,940
215413144	CARRIER	37MPRAQ18AA3	45MPHAQ18XA3		19,300	\$2,702
215413143	CARRIER	37MPRAQ12AA3	45MPHAQ12XA3		11,000	\$1,540
215357451	CARRIER	37MGHAQ30EA3	Combination heat pumps with or without ducts		31,400	\$4,396
215357449	CARRIER	37MGHAQ30EA3	Heat pump with ducts		33,000	\$4,620
215357448	CARRIER	37MGHAQ30EA3	Heat pump without ducts		30,000	\$4,200
215357505	CARRIER	37MGRAQ48FA3	Heat pump with ducts		37,000	\$5,180
215357468	CARRIER	37MGHAQ55FA3	Combination heat pumps with or without ducts		44,500	\$6,230
215357466	CARRIER	37MGHAQ55FA3	Heat pump with ducts		45,000	\$6,300
215357464	CARRIER	37MGHAQ55FA3	Heat pump without ducts		44,000	\$6,160
215357462	CARRIER	37MGHAQ48FA3	Combination heat pumps with or without ducts		44,000	\$6,160
215357460	CARRIER	37MGHAQ48FA3	Heat pump with ducts		44,500	\$6,230
215357458	CARRIER	37MGHAQ48FA3	Heat pump without ducts		44,000	\$6,160
215357456	CARRIER	37MGHAQ36EA3	Combination heat pumps with or without ducts		31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357454	CARRIER	37MGHAQ36EA3	Heat pump with ducts		33,000	\$4,620
215357453	CARRIER	37MGHAQ36EA3	Heat pump without ducts		30,000	\$4,200
215357446	CARRIER	37MGHAQ27DA3	Combination heat pumps with or without ducts		24,000	\$3,360
215357444	CARRIER	37MGHAQ27DA3	Heat pump with ducts		23,000	\$3,220
215357443	CARRIER	37MGHAQ27DA3	Heat pump without ducts		25,000	\$3,500
215357437	CARRIER	37MGHAQ18CA3	Combination heat pumps with or without ducts		17,300	\$2,422
215357435	CARRIER	37MGHAQ18CA3	Heat pump with ducts		17,000	\$2,380
215357433	CARRIER	37MGHAQ18CA3	Heat pump without ducts		17,600	\$2,464
215323814	CARRIER	37MAHAQ18AA3	45MBDAQ18XH3		15,000	\$2,100
215323808	CARRIER	37MAHAQ12AA3	45MBDAQ12XH3		10,200	\$1,428
215323848	CARRIER	37MBHAQ58AA3	45MCFAQ58XA3		41,000	\$5,740
215323846	CARRIER	37MBHAQ48AA3	45MCFAQ48XA3		38,500	\$5,390
215323845	CARRIER	37MBHAQ48AA3	45MBCAQ48XA3		44,000	\$6,160
215323843	CARRIER	37MBHAQ36AA3	45MCFAQ36XA3		30,200	\$4,228
215323842	CARRIER	37MBHAQ36AA3	45MBCAQ36XA3		30,600	\$4,284
215318763	CARRIER	37MUHAQ48AA3	45MUHAQ60XX3		34,000	\$4,760
215318762	CARRIER	37MUHAQ30AA3	45MUHAQ36XX3		24,000	\$3,360
215318761	CARRIER	37MUHAQ18AA3	45MUHAQ24XX3		14,700	\$2,058
215318771	CARRIER	37MBHAQ58AA3	45MBAAQ60XA3		41,000	\$5,740
215318769	CARRIER	37MBHAQ36AA3	45MBAAQ36XA3		28,000	\$3,920
215318759	CARRIER	37MURAQ48AA3	45MUAAQ48XX3		32,400	\$4,536
215318756	CARRIER	37MURAQ24AA3	45MUAAQ24XX3		20,000	\$2,800
215318754	CARRIER	37MUHAQ60AA3	45MUHAQ60XX3		35,000	\$4,900
215318753	CARRIER	37MUHAQ60AA3	45MUAAQ60XX3		45,000	\$6,300
215318752	CARRIER	37MUHAQ48AA3	45MUAAQ48XX3		37,000	\$5,180
215318751	CARRIER	37MUHAQ36AA3	45MUAAQ36XX3		31,800	\$4,452
215318750	CARRIER	37MUHAQ30AA3	45MUAAQ30XX3		23,800	\$3,332
215318749	CARRIER	37MUHAQ24AA3	45MUHAQ24XX3		19,000	\$2,660
215318748	CARRIER	37MUHAQ24AA3	45MUAAQ24XX3		20,000	\$2,800
215318747	CARRIER	37MUHAQ18AA3	45MUAAQ18XX3		15,000	\$2,100
215318770	CARRIER	37MBHAQ48AA3	45MBAAQ48XA3		40,000	\$5,600
215318766	CARRIER	37MAHAQ33AA3	45MBAAQ36XB3		27,400	\$3,836
215318765	CARRIER	37MAHAQ24AA3	45MBAAQ24XB3		16,900	\$2,366
215318764	CARRIER	37MAHAQ18AA3	45MBAAQ18XB3		14,000	\$1,960
212981664	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58SU*B040M17**12	23,400	\$3,276
212988059	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC6A100M21**20	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982648	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58SU*B080M21**20	23,400	\$3,276
212982636	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58SU*B080M21**20	23,400	\$3,276
212982360	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SU*B060M17**16	19,100	\$2,674
212982336	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58SU*B060M17**16	19,100	\$2,674
212982288	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SU*B060M17**16	19,100	\$2,674
212982276	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58SU*B060M17**16	19,000	\$2,660
212982168	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SU*B060M17**16	23,200	\$3,248
212981784	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58SU*B040M17**12	19,200	\$2,688
212981712	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58SU*B040M17**12	19,100	\$2,674
212988095	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SC6A100M21**20	23,600	\$3,304
212982696	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SU*B080M21**20	19,000	\$2,660
212981676	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58SU*B040M17**12	23,600	\$3,304
212982144	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SU*B060M17**16	23,200	\$3,248
212981808	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SU*B040M17**12	19,100	\$2,674
212981688	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58SU*B040M17**12	19,500	\$2,730
212981580	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58SU*B040M17**12	23,400	\$3,276
212982936	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SU*B100M21**20	23,200	\$3,248
212982720	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SU*B080M21**20	19,000	\$2,660
212982996	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58SU*B100M21**20	23,600	\$3,304
212981604	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58SU*B040M17**12	23,600	\$3,304
212982348	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58SU*B060M17**16	19,100	\$2,674
212982312	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58SU*B060M17**16	18,700	\$2,618
212981796	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58SU*B040M17**12	19,200	\$2,688
212981736	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SU*B040M17**12	19,100	\$2,674
212981724	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58SU*B040M17**12	19,000	\$2,660
212982264	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58SU*B060M17**16	19,100	\$2,674
212981868	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58SU*B040M17**12	12,600	\$1,764
212988047	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SC6A100M21**20	23,600	\$3,304
212988035	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC6A100M21**20	23,400	\$3,276
212982240	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58SU*B060M17**16	19,400	\$2,716
212982132	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58SU*B060M17**16	23,400	\$3,276
212981772	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58SU*B040M17**12	19,500	\$2,730
206788742	CARRIER	25VNA436A*031*	CSPH*3612AL*+UI	58TN*A090C21**20	33,600	\$4,704
206788741	CARRIER	25VNA436A*031*	CSPH*3612AL*+UI	58TN*A070C21**20	33,800	\$4,732
206788703	CARRIER	25VNA436A*031*	CNPV*4221AL*+UI	58TN*A110C21**20	33,800	\$4,732
206788698	CARRIER	25VNA436A*031*	CNPV*4221AL*+UI	59MN7B080C21**20	34,000	\$4,760
206788694	CARRIER	25VNA436A*031*	CNPV*4221AL*+UI	58TN*A090C21**20	33,800	\$4,732
206788693	CARRIER	25VNA436A*031*	CNPV*4221AL*+UI	58TN*A070C21**20	34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206788609	CARRIER	25VNA436A*031*	CAP**4224AL*+UI	59MN7B100C21**22	33,600	\$4,704
206788608	CARRIER	25VNA436A*031*	CAP**4224AL*+UI	59MN7B080C21**20	33,800	\$4,732
206788604	CARRIER	25VNA436A*031*	CAP**4224AL*+UI	58TN*A070C21**20	33,800	\$4,732
206788600	CARRIER	25VNA436A*031*	CAP**4221AL*+UI	59TN6B100C21**22	33,800	\$4,732
206788594	CARRIER	25VNA436A*031*	CAP**4221AL*+UI	58TN*A090C21**20	33,600	\$4,704
206788754	CARRIER	25VNA436A*031*	CSPH*3612AL*+UI	58TN*A110C21**20	33,600	\$4,704
206788749	CARRIER	25VNA436A*031*	CSPH*3612AL*+UI	59MN7B100C21**22	33,600	\$4,704
206788748	CARRIER	25VNA436A*031*	CSPH*3612AL*+UI	59MN7B080C21**20	33,800	\$4,732
206788701	CARRIER	25VNA436A*031*	CNPV*4221AL*+UI	59TN6B100C21**22	33,800	\$4,732
206788700	CARRIER	25VNA436A*031*	CNPV*4221AL*+UI	59TN6B080C21**20	34,000	\$4,760
206788597	CARRIER	25VNA436A*031*	CAP**4221AL*+UI	59MN7B080C21**20	33,800	\$4,732
206788605	CARRIER	25VNA436A*031*	CAP**4224AL*+UI	58TN*A090C21**20	33,600	\$4,704
206788699	CARRIER	25VNA436A*031*	CNPV*4221AL*+UI	59MN7B100C21**22	33,800	\$4,732
206788613	CARRIER	25VNA436A*031*	CAP**4224AL*+UI	58TN*A110C21**20	33,600	\$4,704
206788752	CARRIER	25VNA436A*031*	CSPH*3612AL*+UI	59TN6B100C21**22	33,600	\$4,704
206788751	CARRIER	25VNA436A*031*	CSPH*3612AL*+UI	59TN6B080C21**20	33,800	\$4,732
206788612	CARRIER	25VNA436A*031*	CAP**4224AL*+UI	59TN6B100C21**22	33,600	\$4,704
206788611	CARRIER	25VNA436A*031*	CAP**4224AL*+UI	59TN6B080C21**20	33,800	\$4,732
206788599	CARRIER	25VNA436A*031*	CAP**4221AL*+UI	59TN6B080C21**20	33,800	\$4,732
206788593	CARRIER	25VNA436A*031*	CAP**4221AL*+UI	58TN*A070C21**20	34,000	\$4,760
213078925	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SU*B040M17**12	29,400	\$4,116
213078817	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58SU*B040M17**12	29,600	\$4,144
213079237	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58SU*B100M21**20	29,400	\$4,116
213079225	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SU*B100M21**20	29,400	\$4,116
213079201	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SU*B100M21**20	29,400	\$4,116
213079321	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58SU*B100M21**20	29,200	\$4,088
213079309	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SU*B100M21**20	29,200	\$4,088
213078913	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58SU*B040M17**12	29,400	\$4,116
213079273	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58SU*B100M21**20	29,000	\$4,060
213079261	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SU*B100M21**20	29,000	\$4,060
212982972	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SU*B100M21**20	23,200	\$3,248
213080429	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC6A100M21**22	29,400	\$4,116
213080375	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC6A100M21**22	29,400	\$4,116
213080351	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC6A100M21**20	29,200	\$4,088
213080267	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC6A100M21**20	29,400	\$4,116
213079177	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SU*B080M21**20	29,200	\$4,088
213079105	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SU*B080M21**20	29,200	\$4,088
213079081	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SU*B080M21**20	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079009	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SU*B060M17**16	29,000	\$4,060
213078985	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SU*B060M17**16	29,000	\$4,060
213078961	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SU*B060M17**16	29,400	\$4,116
213078901	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	58SU*B040M17**12	29,600	\$4,144
213078829	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SU*B040M17**12	29,400	\$4,116
212988224	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC6A100M21**22	29,000	\$4,060
212988011	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC6A100M21**20	29,000	\$4,060
212987999	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC6A100M21**20	29,000	\$4,060
212982432	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58SU*B060M17**16	12,300	\$1,722
212982396	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58SU*B060M17**16	12,200	\$1,708
212982708	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58SU*B080M21**20	18,600	\$2,604
212982372	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58SU*B060M17**16	12,200	\$1,708
212982300	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58SU*B060M17**16	18,800	\$2,632
212981844	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58SU*B040M17**12	12,100	\$1,694
213080402	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC6A100M21**22	29,400	\$4,116
213079213	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SU*B100M21**20	29,000	\$4,060
213079045	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58SU*B060M17**16	29,200	\$4,088
210532906	CARRIER	25VNA448A*031*	CNPV*4824AL*+UI	59TN6B120C24**22	43,500	\$6,090
210532904	CARRIER	25VNA448A*031*	CNPV*4824AL*+UI	58TN*A135C24**22	43,500	\$6,090
210532894	CARRIER	25VNA448A*031*	CNPV*4821AL*+UI	59TN6B100C21**22	43,500	\$6,090
210532882	CARRIER	25VNA448A*031*	CAP**6124AL*+UI	59MN7B100C21**22	43,500	\$6,090
212988215	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC6A100M21**22	29,000	\$4,060
213080438	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC6A100M21**22	29,200	\$4,088
213080393	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC6A100M21**22	29,400	\$4,116
213080363	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC6A100M21**20	29,200	\$4,088
213080339	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC6A100M21**20	29,400	\$4,116
213080303	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC6A100M21**20	29,400	\$4,116
213080291	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC6A100M21**20	29,400	\$4,116
213079165	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SU*B080M21**20	29,400	\$4,116
213079153	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	58SU*B080M21**20	29,600	\$4,144
213079069	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SU*B060M17**16	29,200	\$4,088
212982684	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58SU*B080M21**20	23,400	\$3,276
212982408	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58SU*B060M17**16	12,300	\$1,722
212981592	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SU*B040M17**12	23,200	\$3,248
212982252	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58SU*B060M17**16	18,600	\$2,604
213079249	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SU*B100M21**20	29,000	\$4,060
212969726	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58SP*B045V14**12	19,300	\$2,702
210532912	CARRIER	25VNA448A*031*	CNPV*4824AL*+UI	59TN6B100C21**22	43,500	\$6,090

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210532878	CARRIER	25VNA448A*031*	CAP**6024AL*+UI	59MN7B100C21**22	43,000	\$6,020
210532884	CARRIER	25VNA448A*031*	CAP**6124AL*+UI	59TN6B100C21**22	43,500	\$6,090
210532872	CARRIER	25VNA448A*031*	CAP**4824AL*+UI	59MN7B100C21**22	43,500	\$6,090
212982600	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58SU*B080M21**20	28,800	\$4,032
212982660	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SU*B080M21**20	23,200	\$3,248
213080447	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC6A100M21**22	29,200	\$4,088
213080411	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC6A100M21**22	29,200	\$4,088
213080384	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC6A100M21**22	29,200	\$4,088
213080279	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC6A100M21**20	29,200	\$4,088
213079189	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58SU*B080M21**20	29,200	\$4,088
213079129	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SU*B080M21**20	29,000	\$4,060
213079093	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SU*B080M21**20	29,000	\$4,060
213079057	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SU*B060M17**16	29,400	\$4,116
213079297	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SU*B100M21**20	29,400	\$4,116
212982420	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58SU*B060M17**16	12,400	\$1,736
212982216	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58SU*B060M17**16	23,400	\$3,276
212982156	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58SU*B060M17**16	23,400	\$3,276
212982084	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SU*B060M17**16	28,800	\$4,032
212981700	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58SU*B040M17**12	18,700	\$2,618
210532908	CARRIER	25VNA448A*031*	CNPV*4824AL*+UI	59MN7B100C21**22	43,500	\$6,090
210532900	CARRIER	25VNA448A*031*	CNPV*4824AL*+UI	58CU*A100C21**20	43,500	\$6,090
210532924	CARRIER	25VNA448A*031*	CSPH*4812AL*+UI	59TN6B120C24**22	43,500	\$6,090
210532922	CARRIER	25VNA448A*031*	CSPH*4812AL*+UI	58TN*A135C24**22	43,500	\$6,090
210532918	CARRIER	25VNA448A*031*	CSPH*4812AL*+UI	58CU*A100C21**20	44,000	\$6,160
210532916	CARRIER	25VNA448A*031*	CSPH*4812AL*+UI	59CU5A100C21**22	43,500	\$6,090
210532886	CARRIER	25VNA448A*031*	CNPV*4821AL*+UI	59CU5A080C21**20	43,500	\$6,090
213080315	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC6A100M21**20	29,200	\$4,088
213079141	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SU*B080M21**20	29,000	\$4,060
213079117	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58SU*B080M21**20	29,200	\$4,088
213078997	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SU*B060M17**16	29,400	\$4,116
213078949	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58SU*B060M17**16	29,400	\$4,116
213078937	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SU*B040M17**12	29,200	\$4,088
213078889	CARRIER	38MURAQ36AB3*	CNPV*3617AL*	58SU*B040M17**12	29,600	\$4,144
213078877	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SU*B040M17**12	29,200	\$4,088
213078865	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SU*B040M17**12	29,400	\$4,116
213078853	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SU*B040M17**12	29,200	\$4,088
212988071	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC6A100M21**20	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982384	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58SU*B060M17**16	12,400	\$1,736
212982624	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SU*B080M21**20	23,200	\$3,248
212982324	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58SU*B060M17**16	19,400	\$2,716
212981880	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58SU*B040M17**12	12,300	\$1,722
212981856	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58SU*B040M17**12	12,300	\$1,722
212981820	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58SU*B040M17**12	12,200	\$1,708
212981748	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58SU*B040M17**12	18,800	\$2,632
212981532	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SU*B040M17**12	29,000	\$4,060
212971110	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58TP*B045V14**12	19,300	\$2,702
212981832	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58SU*B040M17**12	12,300	\$1,722
212981616	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SU*B040M17**12	23,200	\$3,248
210533104	CARRIER	25VNA424A*031*	CSPH*3012AL*+UI	59MN7B060C21**20	25,200	\$3,528
210532928	CARRIER	25VNA448A*031*	CSPH*4812AL*+UI	59TN6B100C21**22	43,500	\$6,090
210532926	CARRIER	25VNA448A*031*	CSPH*4812AL*+UI	59MN7B100C21**22	43,500	\$6,090
210532896	CARRIER	25VNA448A*031*	CNPV*4824AL*+UI	59CU5A080C21**20	43,500	\$6,090
210532910	CARRIER	25VNA448A*031*	CNPV*4824AL*+UI	59MN7B120C24**22	44,000	\$6,160
210532890	CARRIER	25VNA448A*031*	CNPV*4821AL*+UI	58CU*A100C21**20	43,500	\$6,090
210532874	CARRIER	25VNA448A*031*	CAP**4824AL*+UI	59TN6B100C21**22	43,500	\$6,090
210473215	CARRIER	25VNA825A*032*	CAP**4321AL*+UI	59MN7B100C21**22	20,600	\$2,884
210473226	CARRIER	25VNA825A*032*	CAP**4321AL*+UI	59TN6B100C21**22	20,600	\$2,884
210473094	CARRIER	25VNA825A*032*	CAP**4321AL*+UI	59CU5A080C21**20	20,600	\$2,884
210473116	CARRIER	25VNA825A*032*	CAP**4321AL*+UI	58CU*A040C17**12	20,600	\$2,884
206348137	CARRIER	38MARBQ18AA3	40MAHBQ18XA3		15,000	\$2,100
211712151	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC5B100E21**20	23,600	\$3,304
211712139	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SU*A100E21**20	23,200	\$3,248
211712127	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SU5A100E21**20	23,400	\$3,276
211712117	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58SP*A070V17**16	23,400	\$3,276
211712105	CARRIER	38MURAQ30AB3*	CAP**3621AL*	58SU*A100E21**20	23,600	\$3,304
211712093	CARRIER	38MURAQ30AB3*	CAP**3621AL*	59SU5A100E21**20	23,600	\$3,304
211709695	CARRIER	38MURAQ30AB3*	PF4MN*B30L*		23,400	\$3,276
213353855	CARRIER	38MURAQ36AB3*	F54AA*C42L*		29,200	\$4,088
213300340	CARRIER	38MURAQ36AB3*	F54AA*B36L*		29,400	\$4,116
213249334	CARRIER	38MURAQ36AB3*	FEVA0036**+NAVA43601CK		29,400	\$4,116
213080872	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SU5B080M21**20	29,200	\$4,088
213080860	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SU5B080M21**20	29,200	\$4,088
213080848	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SU5B080M21**20	29,400	\$4,116
213080836	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59SU5B080M21**20	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080824	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SU5B080M21**20	29,200	\$4,088
213080812	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SU5B080M21**20	29,400	\$4,116
213080800	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SU5B080M21**20	29,400	\$4,116
213080788	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SU5B080M21**20	29,200	\$4,088
213080776	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SU5B080M21**20	29,400	\$4,116
213080764	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SU5B060M17**16	29,200	\$4,088
213080752	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SU5B060M17**16	29,600	\$4,144
213080740	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SU5B060M17**16	29,400	\$4,116
213080704	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SU5B060M17**16	29,200	\$4,088
213080692	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SU5B060M17**16	29,400	\$4,116
213080680	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SU5B060M17**16	29,200	\$4,088
213080668	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SU5B060M17**16	29,400	\$4,116
213080656	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SU5B060M17**16	29,400	\$4,116
213080644	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SU5B060M17**16	29,600	\$4,144
213080632	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SU5B040M17**12	29,400	\$4,116
213080620	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SU5B040M17**12	29,600	\$4,144
213080608	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SU5B040M17**12	29,400	\$4,116
213080572	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SU5B040M17**12	29,200	\$4,088
213080560	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SU5B040M17**12	29,200	\$4,088
213080548	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SU5B040M17**12	29,600	\$4,144
213080536	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SU5B040M17**12	29,200	\$4,088
211274894	CARRIER	38MURAQ30AB3*	FV4CN(B,F)005L		23,000	\$3,220
213080524	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SU5B040M17**12	29,400	\$4,116
213080512	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SU5B040M17**12	29,600	\$4,144
213080500	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SU5B040M17**12	29,600	\$4,144
213080490	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC6A140M24**22	29,200	\$4,088
213080480	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC6A140M24**22	29,400	\$4,116
213080468	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC6A120M24**22	29,200	\$4,088
213080456	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC6A120M24**22	29,400	\$4,116
213080255	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC6A080M21**20	29,200	\$4,088
213080243	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC6A080M21**20	29,200	\$4,088
213080231	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC6A080M21**20	29,400	\$4,116
213080207	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC6A080M21**20	29,000	\$4,060
213080195	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC6A080M21**20	29,000	\$4,060
213080183	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC6A080M21**20	29,200	\$4,088
213080171	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC6A080M21**20	29,400	\$4,116
213080159	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC6A080M21**20	29,400	\$4,116
213080147	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC6A080M21**20	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080135	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC6A080M21**20	29,600	\$4,144
213080123	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC6A080M17**16	29,200	\$4,088
213080111	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC6A080M17**16	29,600	\$4,144
213080099	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SC6A080M17**16	29,400	\$4,116
213080063	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC6A080M17**16	29,000	\$4,060
213080051	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC6A080M17**16	29,200	\$4,088
213080039	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC6A080M17**16	29,400	\$4,116
213080027	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC6A080M17**16	29,200	\$4,088
213080015	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SC6A080M17**16	29,400	\$4,116
213080003	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC6A080M17**16	29,600	\$4,144
213079991	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SC6A080M17**16	29,600	\$4,144
213079981	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SC6A060M14**12	29,600	\$4,144
213079961	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SC6A060M14**12	29,400	\$4,116
213079951	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SC6A060M14**12	29,600	\$4,144
213079940	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC2E120M24**20	29,200	\$4,088
213079929	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC2E120M24**20	29,000	\$4,060
213079918	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC2E120M24**20	29,400	\$4,116
213079909	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC2E100M21**22	29,200	\$4,088
213079900	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2E100M21**22	29,200	\$4,088
213079891	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2E100M21**22	29,400	\$4,116
213079873	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2E100M21**22	29,000	\$4,060
213079864	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC2E100M21**22	29,400	\$4,116
213079855	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2E100M21**22	29,400	\$4,116
213079846	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2E100M21**22	29,000	\$4,060
213079837	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2E100M21**22	29,400	\$4,116
213079825	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC2E100M21**20	29,200	\$4,088
213079813	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2E100M21**20	29,200	\$4,088
213079801	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2E100M21**20	29,400	\$4,116
213079789	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59SC2E100M21**20	29,600	\$4,144
213079777	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2E100M21**20	29,000	\$4,060
213079765	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC2E100M21**20	29,400	\$4,116
213079753	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2E100M21**20	29,400	\$4,116
213079741	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2E100M21**20	29,000	\$4,060
213079729	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2E100M21**20	29,400	\$4,116
213079719	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC2E080M21**20	29,200	\$4,088
213079709	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2E080M21**20	29,200	\$4,088
213079699	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2E080M21**20	29,400	\$4,116
213079689	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59SC2E080M21**20	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079679	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2E080M21**20	29,200	\$4,088
213079669	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC2E080M21**20	29,400	\$4,116
213079659	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2E080M21**20	29,400	\$4,116
213079649	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2E080M21**20	29,200	\$4,088
213079639	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2E080M21**20	29,400	\$4,116
213079627	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2E080M17**16	29,200	\$4,088
213079615	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2E080M17**16	29,400	\$4,116
213079603	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SC2E080M17**16	29,200	\$4,088
9892595	CARRIER	25VNA024A*030*	CSPH*3612AL*+UI	59MN7A060V21**20	25,200	\$3,528
213079567	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2E080M17**16	29,000	\$4,060
213079555	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2E080M17**16	29,400	\$4,116
213079543	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2E080M17**16	29,000	\$4,060
213079531	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SC2E080M17**16	29,400	\$4,116
213079519	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2E080M17**16	29,400	\$4,116
213079507	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SC2E080M17**16	29,400	\$4,116
213079495	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2E060M17**14	29,200	\$4,088
213079483	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2E060M17**14	29,400	\$4,116
213079471	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SC2E060M17**14	29,400	\$4,116
213079435	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2E060M17**14	29,200	\$4,088
213079423	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2E060M17**14	29,400	\$4,116
213079409	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2E060M17**14	29,200	\$4,088
213079397	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SC2E060M17**14	29,400	\$4,116
213079385	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2E060M17**14	29,400	\$4,116
213079373	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SC2E060M17**14	29,400	\$4,116
213079363	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SC2E060M14**12	29,400	\$4,116
213079343	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SC2E060M14**12	29,400	\$4,116
213079333	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SC2E060M14**12	29,600	\$4,144
213078973	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58SU*B060M17**16	29,200	\$4,088
213078841	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58SU*B040M17**12	29,400	\$4,116
213078807	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*B155M24**20	29,200	\$4,088
213078797	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*B155M24**20	29,000	\$4,060
213078787	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*B155M24**20	29,400	\$4,116
213078776	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*B135M24**20	29,200	\$4,088
213078765	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*B135M24**20	29,400	\$4,116
213078755	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*B110M24**20	29,200	\$4,088
213078745	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*B110M24**20	29,000	\$4,060
213078735	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*B110M24**20	29,400	\$4,116
213078723	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*B110M21**20	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078711	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*B110M21**20	29,200	\$4,088
213078699	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*B110M21**20	29,400	\$4,116
213078675	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*B110M21**20	29,000	\$4,060
213078663	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*B110M21**20	29,000	\$4,060
213078651	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*B110M21**20	29,000	\$4,060
213078639	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*B110M21**20	29,400	\$4,116
213078627	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*B110M21**20	29,400	\$4,116
213078615	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*B110M21**20	29,000	\$4,060
213078603	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*B110M21**20	29,400	\$4,116
213078594	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*B090M24**20	29,200	\$4,088
213078585	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*B090M24**20	29,400	\$4,116
213078574	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*B090M21**20	29,200	\$4,088
213078563	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*B090M21**20	29,200	\$4,088
213078552	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*B090M21**20	29,400	\$4,116
213078530	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*B090M21**20	29,200	\$4,088
213078519	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*B090M21**20	29,400	\$4,116
213078508	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*B090M21**20	29,400	\$4,116
213078497	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*B090M21**20	29,200	\$4,088
213078486	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*B090M21**20	29,400	\$4,116
213078475	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*B090M21**16	29,200	\$4,088
211712498	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*A110E21**20	23,600	\$3,304
213078464	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*B090M21**16	29,200	\$4,088
213078453	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*B090M21**16	29,400	\$4,116
213078431	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*B090M21**16	29,000	\$4,060
213078420	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*B090M21**16	29,400	\$4,116
211712485	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*A090E21**20	23,400	\$3,276
213078409	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*B090M21**16	29,400	\$4,116
213078398	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*B090M21**16	29,000	\$4,060
213078387	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*B090M21**16	29,400	\$4,116
211712472	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*A090E21**16	23,600	\$3,304
213078375	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*B090M17**14	29,200	\$4,088
213078363	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*B090M17**14	29,400	\$4,116
213078351	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*B090M17**14	29,200	\$4,088
211712459	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*A090E17**14	23,400	\$3,276
213078315	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*B090M17**14	29,000	\$4,060
213078303	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*B090M17**14	29,400	\$4,116
213078291	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*B090M17**14	29,000	\$4,060
213078279	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*B090M17**14	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078267	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*B090M17**14	29,400	\$4,116
213078255	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*B090M17**14	29,400	\$4,116
213078245	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*B070M21**16	29,200	\$4,088
213078235	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*B070M21**16	29,200	\$4,088
213078225	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*B070M21**16	29,400	\$4,116
213078205	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*B070M21**16	29,000	\$4,060
213078195	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*B070M21**16	29,400	\$4,116
211712422	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58TP*A110V21**22	23,400	\$3,276
213078185	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*B070M21**16	29,400	\$4,116
213078175	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*B070M21**16	29,000	\$4,060
213078165	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*B070M21**16	29,400	\$4,116
213078153	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*B070M17**16	29,200	\$4,088
213078141	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*B070M17**16	29,400	\$4,116
213078129	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*B070M17**16	29,400	\$4,116
213078117	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	58S(B,C)*B070M17**16	29,600	\$4,144
213078105	CARRIER	38MURAQ36AB3*	CNPV*3617AL*	58S(B,C)*B070M17**16	29,600	\$4,144
213078093	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*B070M17**16	29,200	\$4,088
213078081	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*B070M17**16	29,400	\$4,116
213078069	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*B070M17**16	29,200	\$4,088
213078057	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*B070M17**16	29,400	\$4,116
213078045	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*B070M17**16	29,400	\$4,116
213078033	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*B070M17**16	29,600	\$4,144
213078022	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*B070M17**12	29,200	\$4,088
213078011	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*B070M17**12	29,400	\$4,116
213078000	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*B070M17**12	29,400	\$4,116
213077967	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*B070M17**12	29,000	\$4,060
211712377	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58TP*A070V17**16	23,400	\$3,276
213077956	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*B070M17**12	29,400	\$4,116
213077945	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*B070M17**12	29,000	\$4,060
213077934	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*B070M17**12	29,400	\$4,116
213077923	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*B070M17**12	29,400	\$4,116
211712535	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SC2D080E21**20	23,400	\$3,276
213077912	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*B070M17**12	29,400	\$4,116
213077900	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*B070M14**12	29,400	\$4,116
211712365	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SC5B100E21**20	23,600	\$3,304
213077876	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*B070M14**12	29,400	\$4,116
213077864	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*B070M14**12	29,400	\$4,116
213077852	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*B045M14**12	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712353	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SC5B080E21**20	23,400	\$3,276
213077828	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*B045M14**12	29,400	\$4,116
213077815	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*B045M14**12	29,600	\$4,144
213077804	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	GG96VTAB66120D**	29,200	\$4,088
213077803	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59TP6C120V24**22	29,200	\$4,088
213077792	CARRIER	38MURAQ36AB3*	CAP**4224AL*	GG96VTAB66120D**	29,400	\$4,116
213077791	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59TP6C120V24**22	29,400	\$4,116
213077781	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59TP6C100V21**22	29,200	\$4,088
213077771	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6C100V21**22	29,200	\$4,088
213077761	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59TP6C100V21**22	29,400	\$4,116
213077751	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59TP6C100V21**22	29,600	\$4,144
213077741	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59TP6C100V21**22	29,000	\$4,060
213077731	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59TP6C100V21**22	29,400	\$4,116
213077721	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59TP6C100V21**22	29,400	\$4,116
213077711	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59TP6C100V21**22	29,000	\$4,060
213077701	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59TP6C100V21**22	29,400	\$4,116
213077689	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	GG96VTAB60100C**	29,200	\$4,088
213077688	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59TP6C100V21**20	29,200	\$4,088
211712547	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SC2D100E21**20	23,400	\$3,276
213077676	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	GG96VTAB60100C**	29,200	\$4,088
213077675	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6C100V21**20	29,200	\$4,088
213077663	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	GG96VTAB60100C**	29,400	\$4,116
213077662	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59TP6C100V21**20	29,400	\$4,116
213077637	CARRIER	38MURAQ36AB3*	CAP**4321AL*	GG96VTAB60100C**	29,000	\$4,060
213077636	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59TP6C100V21**20	29,000	\$4,060
211712327	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58SU*A040E17**12	23,400	\$3,276
213077624	CARRIER	38MURAQ36AB3*	CAP**4224AL*	GG96VTAB60100C**	29,400	\$4,116
213077623	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59TP6C100V21**20	29,400	\$4,116
213077611	CARRIER	38MURAQ36AB3*	CAP**4221AL*	GG96VTAB60100C**	29,400	\$4,116
213077610	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59TP6C100V21**20	29,400	\$4,116
213077598	CARRIER	38MURAQ36AB3*	CAP**3721AL*	GG96VTAB60100C**	29,000	\$4,060
213077597	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59TP6C100V21**20	29,000	\$4,060
213077585	CARRIER	38MURAQ36AB3*	CAP**3621AL*	GG96VTAB60100C**	29,400	\$4,116
213077584	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59TP6C100V21**20	29,400	\$4,116
213077573	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59TP6C080V21**20	29,200	\$4,088
213077562	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6C080V21**20	29,200	\$4,088
213077551	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59TP6C080V21**20	29,400	\$4,116
213077540	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59TP6C080V21**20	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712315	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58SU*A100E21**20	23,600	\$3,304
213077529	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6C080V21**20	29,000	\$4,060
213077518	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59TP6C080V21**20	29,200	\$4,088
213077507	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59TP6C080V21**20	29,400	\$4,116
213077496	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59TP6C080V21**20	29,400	\$4,116
213077485	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59TP6C080V21**20	29,200	\$4,088
213077474	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59TP6C080V21**20	29,400	\$4,116
213077462	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	GG96VTAB48080B**	29,200	\$4,088
213077461	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6C080V17**16	29,200	\$4,088
213077449	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	GG96VTAB48080B**	29,600	\$4,144
213077448	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59TP6C080V17**16	29,600	\$4,144
213077436	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	GG96VTAB48080B**	29,400	\$4,116
213077435	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59TP6C080V17**16	29,400	\$4,116
211712291	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SU5A100E21**20	23,600	\$3,304
213077397	CARRIER	38MURAQ36AB3*	CAP**4321AL*	GG96VTAB48080B**	29,200	\$4,088
213077396	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59TP6C080V17**16	29,200	\$4,088
213077384	CARRIER	38MURAQ36AB3*	CAP**4221AL*	GG96VTAB48080B**	29,400	\$4,116
213077383	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59TP6C080V17**16	29,400	\$4,116
213077371	CARRIER	38MURAQ36AB3*	CAP**3721AL*	GG96VTAB48080B**	29,200	\$4,088
213077370	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59TP6C080V17**16	29,200	\$4,088
211712559	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SC5B060E17**14	23,600	\$3,304
213077358	CARRIER	38MURAQ36AB3*	CAP**3717AL*	GG96VTAB48080B**	29,400	\$4,116
213077357	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59TP6C080V17**16	29,400	\$4,116
213077345	CARRIER	38MURAQ36AB3*	CAP**3621AL*	GG96VTAB48080B**	29,400	\$4,116
213077344	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59TP6C080V17**16	29,400	\$4,116
213077332	CARRIER	38MURAQ36AB3*	CAP**3617AL*	GG96VTAB48080B**	29,600	\$4,144
213077331	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59TP6C080V17**16	29,600	\$4,144
213077320	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59TP6C060V14**12	29,400	\$4,116
213077298	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59TP6C060V14**12	29,400	\$4,116
213077287	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59TP6C060V14**12	29,600	\$4,144
211712271	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58SP*A070V21**20	23,400	\$3,276
213077276	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6C040V17**12	29,400	\$4,116
213077265	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6C040V17**12	29,200	\$4,088
213077255	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SP6B120V24**22	29,200	\$4,088
213077245	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SP6B120V24**22	29,000	\$4,060
213077235	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SP6B120V24**22	29,400	\$4,116
213077225	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SP6B100V21**20	29,200	\$4,088
213077215	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SP6B100V21**20	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077205	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SP6B100V21**20	29,400	\$4,116
213077185	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SP6B100V21**20	29,000	\$4,060
213077175	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SP6B100V21**20	29,000	\$4,060
213077165	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SP6B100V21**20	29,400	\$4,116
213077155	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SP6B100V21**20	29,400	\$4,116
213077145	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SP6B100V21**20	29,000	\$4,060
213077135	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SP6B100V21**20	29,400	\$4,116
213077125	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SP6B080V21**20	29,200	\$4,088
213077115	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SP6B080V21**20	29,200	\$4,088
213077105	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SP6B080V21**20	29,400	\$4,116
213077095	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59SP6B080V21**20	29,600	\$4,144
213077085	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SP6B080V21**20	29,000	\$4,060
213077075	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SP6B080V21**20	29,200	\$4,088
213077065	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SP6B080V21**20	29,400	\$4,116
213077055	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SP6B080V21**20	29,400	\$4,116
213077045	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SP6B080V21**20	29,200	\$4,088
213077035	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SP6B080V21**20	29,400	\$4,116
213077025	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SP6B080V17**16	29,200	\$4,088
213077015	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SP6B080V17**16	29,600	\$4,144
213077005	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SP6B080V17**16	29,400	\$4,116
211712228	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*A070E17**16	23,600	\$3,304
213076975	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SP6B080V17**16	29,200	\$4,088
213076965	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SP6B080V17**16	29,400	\$4,116
213076955	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SP6B080V17**16	29,200	\$4,088
213076945	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SP6B080V17**16	29,400	\$4,116
213076935	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SP6B080V17**16	29,400	\$4,116
213076925	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SP6B080V17**16	29,600	\$4,144
213076915	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SP6B060V14**12	29,400	\$4,116
213076895	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SP6B060V14**12	29,400	\$4,116
213076885	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SP6B060V14**12	29,600	\$4,144
213076875	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SP6B040V17**12	29,400	\$4,116
211712206	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SP6A080V17**16	23,400	\$3,276
213076865	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SP6B040V17**12	29,200	\$4,088
213076862	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58TP*B135V24**22	29,200	\$4,088
213076859	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58TP*B135V24**22	29,400	\$4,116
213076847	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58TP*B110V21**22	29,200	\$4,088
213076835	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58TP*B110V21**22	29,200	\$4,088
213076823	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58TP*B110V21**22	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076799	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58TP*B110V21**22	29,000	\$4,060
213076787	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58TP*B110V21**22	29,000	\$4,060
211712583	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58SU*A060E17**16	23,400	\$3,276
213076775	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58TP*B110V21**22	29,200	\$4,088
213076763	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58TP*B110V21**22	29,400	\$4,116
213076751	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58TP*B110V21**22	29,400	\$4,116
213076739	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58TP*B110V21**22	29,200	\$4,088
213076727	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58TP*B110V21**22	29,400	\$4,116
213076716	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58TP*B090V21**20	29,200	\$4,088
213076705	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58TP*B090V21**20	29,200	\$4,088
213076694	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58TP*B090V21**20	29,400	\$4,116
213076683	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	58TP*B090V21**20	29,600	\$4,144
213076672	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58TP*B090V21**20	29,200	\$4,088
213076661	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58TP*B090V21**20	29,400	\$4,116
213076650	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58TP*B090V21**20	29,400	\$4,116
213076639	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58TP*B090V21**20	29,200	\$4,088
213076628	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58TP*B090V21**20	29,400	\$4,116
213076624	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58TP*B090V17**16	29,200	\$4,088
213076620	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58TP*B090V17**16	29,400	\$4,116
211712163	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*A045E17**12	23,400	\$3,276
213076616	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58TP*B090V17**16	29,400	\$4,116
213076604	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58TP*B090V17**16	29,000	\$4,060
213076600	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58TP*B090V17**16	29,400	\$4,116
211712656	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58SP*A070V21**20	23,400	\$3,276
213076596	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58TP*B090V17**16	29,000	\$4,060
213076592	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58TP*B090V17**16	29,400	\$4,116
213076588	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58TP*B090V17**16	29,400	\$4,116
213076584	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58TP*B090V17**16	29,400	\$4,116
213076573	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58TP*B070V17**16	29,200	\$4,088
213076562	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58TP*B070V17**16	29,400	\$4,116
213076551	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58TP*B070V17**16	29,400	\$4,116
211712676	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58SP*A090V24**20	23,400	\$3,276
213076518	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58TP*B070V17**16	29,000	\$4,060
213076507	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58TP*B070V17**16	29,400	\$4,116
213076496	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58TP*B070V17**16	29,000	\$4,060
211201111	CARRIER	38MURAQ30AB3*	CAP**3721AL*	GG96VTAA60100C	23,000	\$3,220
211201110	CARRIER	38MURAQ30AB3*	CAP**3721AL*	GG96VTAA42060B	23,200	\$3,248
213076485	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58TP*B070V17**16	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211201109	CARRIER	38MURAQ30AB3*	CAP**3717AL*	GG96VTAA42060B	23,400	\$3,276
213076474	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58TP*B070V17**16	29,400	\$4,116
211712686	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58SP*A110V24**22	23,400	\$3,276
213076463	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58TP*B070V17**16	29,400	\$4,116
213076461	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58TP*B070V14**12	29,400	\$4,116
213076457	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58TP*B070V14**12	29,200	\$4,088
213076455	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58TP*B070V14**12	29,400	\$4,116
213076443	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58TP*B045V14**12	29,400	\$4,116
213076419	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58TP*B045V14**12	29,200	\$4,088
211712696	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SU5A100E21**20	23,600	\$3,304
213076407	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58TP*B045V14**12	29,400	\$4,116
211194296	CARRIER	38MURAQ30AB3*	FV4CNF002L		23,600	\$3,304
213076333	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SU5B100M21**22	29,200	\$4,088
211194294	CARRIER	38MURAQ30AB3*	FMA4X36**AL*		23,800	\$3,332
211194293	CARRIER	38MURAQ30AB3*	FMA4X30**AL*		23,800	\$3,332
213076324	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SU5B100M21**22	29,200	\$4,088
211194292	CARRIER	38MURAQ30AB3*	FM(C,U)4Z36**AL*		23,600	\$3,304
213076315	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SU5B100M21**22	29,400	\$4,116
211194291	CARRIER	38MURAQ30AB3*	FM(C,U)4Z30**AL*		23,600	\$3,304
211194289	CARRIER	38MURAQ30AB3*	CAP**3721AL*	OVMAAB036098	23,200	\$3,248
211194288	CARRIER	38MURAQ30AB3*	CAP**3721AL*	OVLAAB036098	23,200	\$3,248
211194287	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59TP6B100V21**22	23,000	\$3,220
213076297	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SU5B100M21**22	29,000	\$4,060
211194286	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59TP6B100V21**20	23,200	\$3,248
211194285	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59TP6B080V21**20	23,000	\$3,220
213076288	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SU5B100M21**22	29,000	\$4,060
211194284	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59TP6B060V17**14	23,200	\$3,248
213076279	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SU5B100M21**22	29,000	\$4,060
211194283	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SU5A060E17**16	23,400	\$3,276
213076270	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SU5B100M21**22	29,400	\$4,116
211194282	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SU5A040E17**12	23,200	\$3,248
211712708	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58SU*A100E21**20	23,600	\$3,304
211194281	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SP6A100V21**20	23,200	\$3,248
213076261	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SU5B100M21**22	29,400	\$4,116
211194280	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SP6A080V21**20	23,000	\$3,220
211194279	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SP6A080V17**16	23,200	\$3,248
213076252	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SU5B100M21**22	29,000	\$4,060
211194278	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SP6A060V17**14	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211194277	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC5B080E21**20	23,200	\$3,248
213076243	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SU5B100M21**22	29,400	\$4,116
211194276	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC5B060E17**14	23,200	\$3,248
211194275	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC2D100E21**20	23,200	\$3,248
213075994	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SU5B100M21**20	29,200	\$4,088
211194274	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC2D080E21**20	23,200	\$3,248
211194273	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC2D080E17**16	23,400	\$3,276
211194272	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC2D060E17**14	23,400	\$3,276
213075982	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SU5B100M21**20	29,200	\$4,088
211194266	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58TP*A110V21**22	23,200	\$3,248
213075970	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SU5B100M21**20	29,400	\$4,116
211194265	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58TP*A090V21**20	23,200	\$3,248
211194264	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58TP*A090V17**16	23,200	\$3,248
211194263	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58TP*A070V17**16	23,200	\$3,248
211194262	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SU*A080E21**20	23,400	\$3,276
211194261	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SU*A060E17**16	23,200	\$3,248
213075946	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SU5B100M21**20	29,000	\$4,060
211194260	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SU*A040E17**12	23,200	\$3,248
211194259	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SP*A090V21**20	23,200	\$3,248
213075934	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SU5B100M21**20	29,000	\$4,060
211194258	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SP*A070V21**20	23,200	\$3,248
211194257	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SP*A070V17**16	23,200	\$3,248
211194256	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58SP*A045V17**16	23,200	\$3,248
213075922	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SU5B100M21**20	29,000	\$4,060
211194255	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*A110E21**20	23,200	\$3,248
213075910	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SU5B100M21**20	29,400	\$4,116
211194254	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*A090E21**20	23,200	\$3,248
211194253	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*A090E21**16	23,400	\$3,276
213075898	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SU5B100M21**20	29,400	\$4,116
211194252	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*A090E17**14	23,200	\$3,248
211194251	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*A070E21**16	23,200	\$3,248
213075886	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SU5B100M21**20	29,000	\$4,060
211194250	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*A070E17**16	23,400	\$3,276
211194249	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*A070E17**12	23,200	\$3,248
211194244	CARRIER	38MURAQ30AB3*	CAP**3717AL*	OVMAAB036098	23,400	\$3,276
213075874	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SU5B100M21**20	29,400	\$4,116
211194243	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59TP6B060V17**14	23,400	\$3,276
211712734	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC5B080E21**20	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211194242	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SU5A060E17**16	23,400	\$3,276
212989501	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SU5B080M21**20	29,000	\$4,060
211194241	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SU5A040E17**12	23,400	\$3,276
212989489	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SU5B080M21**20	29,000	\$4,060
211194240	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SP6A080V17**16	23,400	\$3,276
211194239	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SC5B060E17**14	23,400	\$3,276
211194238	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SC2D080E17**16	23,400	\$3,276
212988973	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SU5B060M17**16	29,000	\$4,060
211194237	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SC2D060E17**14	23,400	\$3,276
212988401	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC6A140M24**22	29,000	\$4,060
211194236	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SC2D060E14**12	23,400	\$3,276
211194235	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58TP*A090V17**16	23,400	\$3,276
212988317	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC6A120M24**22	29,000	\$4,060
211194234	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58TP*A070V17**16	23,200	\$3,248
211194233	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58TP*A070V14**12	23,400	\$3,276
211194232	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58TP*A045V14**12	23,400	\$3,276
211712746	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC5B100E21**20	23,600	\$3,304
211194231	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58SU*A060E17**16	23,400	\$3,276
211194230	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58SU*A040E17**12	23,400	\$3,276
211194229	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58SP*A045V17**16	23,400	\$3,276
211194225	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58S(B,C)*A045E14**12	23,400	\$3,276
211194228	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58SP*A045V14**12	23,400	\$3,276
211194227	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58S(B,C)*A090E17**14	23,200	\$3,248
212985515	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC2E100M21**22	29,000	\$4,060
212985506	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2E100M21**22	29,000	\$4,060
211194226	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58S(B,C)*A070E17**16	23,400	\$3,276
212985239	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC2E100M21**20	28,800	\$4,032
212985227	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2E100M21**20	28,800	\$4,032
212984949	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC2E080M21**20	28,800	\$4,032
212984939	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2E080M21**20	28,800	\$4,032
212984409	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2E080M17**16	29,000	\$4,060
212983869	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2E060M17**14	29,000	\$4,060
211194211	CARRIER	38MURAQ30AB3*	CAP**3621AL*	59SC2D100E21**20	23,400	\$3,276
211194210	CARRIER	38MURAQ30AB3*	CAP**3621AL*	59SC2D080E21**20	23,400	\$3,276
212981206	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*B135M24**20	29,000	\$4,060
212980688	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*B090M24**20	29,000	\$4,060
212980486	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*B090M21**20	29,000	\$4,060
212980475	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*B090M21**20	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980167	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*B090M21**16	28,800	\$4,032
211194191	CARRIER	38MURAQ30AB3*	CAP**3621AL*	58S(B,C)*A110E21**20	23,600	\$3,304
212980156	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*B090M21**16	28,800	\$4,032
211194189	CARRIER	38MURAQ30AB3*	CAP**3621AL*	58S(B,C)*A090E21**16	23,600	\$3,304
212979653	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*B090M17**14	29,000	\$4,060
212979411	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*B070M21**16	28,800	\$4,032
212979401	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*B070M21**16	28,800	\$4,032
212978963	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*B070M17**16	29,000	\$4,060
212978477	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*B070M17**12	29,000	\$4,060
211712792	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58TP*A110V21**22	23,400	\$3,276
212977251	CARRIER	38MURAQ36AB3*	CAP**4824AL*	GG96VTAB66120D**	29,000	\$4,060
212977250	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59TP6C120V24**22	29,000	\$4,060
212977088	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59TP6C100V21**22	28,800	\$4,032
212977078	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6C100V21**22	28,800	\$4,032
212976806	CARRIER	38MURAQ36AB3*	CAP**4824AL*	GG96VTAB60100C**	29,000	\$4,060
212976805	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59TP6C100V21**20	29,000	\$4,060
212976793	CARRIER	38MURAQ36AB3*	CAP**4821AL*	GG96VTAB60100C**	29,000	\$4,060
212976792	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6C100V21**20	29,000	\$4,060
212976524	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59TP6C080V21**20	28,800	\$4,032
212976296	CARRIER	38MURAQ36AB3*	CAP**4821AL*	GG96VTAB48080B**	29,000	\$4,060
212976295	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6C080V17**16	29,000	\$4,060
212974412	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SP6B100V21**20	29,000	\$4,060
212974192	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SP6B080V21**20	28,800	\$4,032
212974052	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SP6B080V17**16	29,000	\$4,060
212972641	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58TP*B135V24**22	29,000	\$4,060
212972241	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58TP*B090V21**20	29,000	\$4,060
211184348	CARRIER	38MURAQ30AB3*	FJ4DN*B30L*		23,400	\$3,276
211712816	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*A090E21**16	23,600	\$3,304
212972230	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58TP*B090V21**20	29,000	\$4,060
210450236	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	GG96VTAA48080B	23,600	\$3,304
212972067	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58TP*B090V17**16	29,000	\$4,060
212971874	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58TP*B070V17**16	29,000	\$4,060
210450233	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	GG96VTAA48080B	23,400	\$3,276
212970736	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58SP*B090V21**20	29,200	\$4,088
212970726	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SP*B090V21**20	29,200	\$4,088
212970716	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SP*B090V21**20	29,400	\$4,116
212970706	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	58SP*B090V21**20	29,600	\$4,144
212970696	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58SP*B090V21**20	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210450222	CARRIER	38MURAQ30AB3*	CAP**4321AL*	GG96VTAA48080B	23,200	\$3,248
211712829	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*A090E21**20	23,400	\$3,276
212970686	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SP*B090V21**20	29,000	\$4,060
210450220	CARRIER	38MURAQ30AB3*	CAP**4221AL*	GG96VTAA48080B	23,600	\$3,304
212970676	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SP*B090V21**20	29,200	\$4,088
212970666	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58SP*B090V21**20	29,400	\$4,116
210450218	CARRIER	38MURAQ30AB3*	CAP**3721AL*	GG96VTAA48080B	23,200	\$3,248
212970656	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SP*B090V21**20	29,400	\$4,116
212970646	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SP*B090V21**20	29,200	\$4,088
210450215	CARRIER	38MURAQ30AB3*	CAP**3717AL*	GG96VTAA48080B	23,400	\$3,276
212970636	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SP*B090V21**20	29,400	\$4,116
212970476	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SP*B070V17**16	29,200	\$4,088
211712842	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*A090E24**20	23,400	\$3,276
212970466	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SP*B070V17**16	29,400	\$4,116
212970456	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58SP*B070V17**16	29,400	\$4,116
210450188	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59TP6B080V17**16	23,600	\$3,304
210450187	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59TP6B060V14**12	23,600	\$3,304
210450186	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59TP6B080V17**16	23,400	\$3,276
210450179	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59TP6B080V17**16	23,200	\$3,248
210450178	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59TP6B080V17**16	23,600	\$3,304
212970426	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SP*B070V17**16	29,000	\$4,060
212970416	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SP*B070V17**16	29,200	\$4,088
210450177	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59TP6B080V17**16	23,200	\$3,248
212970406	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SP*B070V17**16	29,400	\$4,116
210450176	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59TP6B060V14**12	23,400	\$3,276
212970396	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SP*B070V17**16	29,200	\$4,088
210450175	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59TP6B080V17**16	23,400	\$3,276
211712855	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*A110E21**20	23,600	\$3,304
212970386	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58SP*B070V17**16	29,400	\$4,116
212970376	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SP*B070V17**16	29,600	\$4,144
212970366	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58SP*B070V17**16	29,600	\$4,144
212969956	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58SP*B045V14**12	29,400	\$4,116
212969936	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58SP*B045V14**12	29,200	\$4,088
212969926	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58SP*B045V14**12	29,400	\$4,116
211712868	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*A110E24**20	23,400	\$3,276
212384850	CARRIER	38MURAQ36AB3*	FV4CN(B,F)003L		29,400	\$4,116
212384824	CARRIER	38MURAQ36AB3*	PF4MN*C42L*		29,200	\$4,088
212384823	CARRIER	38MURAQ36AB3*	FJ4DN*C42L*		29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384786	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2D080E17**16	29,200	\$4,088
212384774	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*A070E17**16	29,200	\$4,088
212384764	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	OVLAAB048112	29,600	\$4,144
211712881	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*A135E24**20	23,600	\$3,304
212384754	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	OVMAAB042112	29,400	\$4,116
212384744	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	OVLAAB036098	29,600	\$4,144
212384734	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	OVMAAB036098	29,600	\$4,144
212384722	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SU*A060E17**16	29,400	\$4,116
212384710	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SU*A080E21**20	29,600	\$4,144
212384698	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC5B060E17**14	29,400	\$4,116
212384686	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2D100E21**20	29,400	\$4,116
211712894	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC2D080E21**20	23,400	\$3,276
212384674	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2D080E21**20	29,400	\$4,116
212384662	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2D080E17**16	29,400	\$4,116
212384650	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2D060E17**14	29,400	\$4,116
212384637	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*A110E21**20	29,400	\$4,116
212384624	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*A070E21**16	29,400	\$4,116
211712906	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC2D100E21**20	23,400	\$3,276
212384611	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*A070E17**12	29,600	\$4,144
212384598	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*A045E17**12	29,400	\$4,116
212384587	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58TP*A110V21**22	29,400	\$4,116
212384576	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59TP6B080V21**20	29,600	\$4,144
212384565	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58TP*A070V17**16	29,400	\$4,116
212384553	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC5B080E21**20	29,600	\$4,144
212384542	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58TP*A090V21**20	29,400	\$4,116
212384539	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58TP*A090V17**16	29,400	\$4,116
212384527	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SU*A100E21**20	29,400	\$4,116
211712953	CARRIER	38MURAQ30AB3*	CAP**4224AL*	OVLAAB060154	23,600	\$3,304
211712963	CARRIER	38MURAQ30AB3*	CAP**4224AL*	OVMAAB060154	23,600	\$3,304
211712973	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SP6A060V17**14	23,200	\$3,248
211712983	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SP6A080V21**20	23,000	\$3,220
211712993	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SP6A100V21**20	23,200	\$3,248
211713003	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SP6A080V17**16	23,200	\$3,248
211713013	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SU5A040E17**12	23,200	\$3,248
211713025	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*A070E17**16	23,400	\$3,276
211713037	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59TP6B100V21**22	23,000	\$3,220
211713038	CARRIER	38MURAQ30AB3*	CAP**4321AL*	GG96VTAA60100C	23,000	\$3,220
211713048	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SP*A045V17**16	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713058	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SP*A070V17**16	23,200	\$3,248
211713068	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SP*A070V21**20	23,200	\$3,248
211713078	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SP*A090V21**20	23,200	\$3,248
211713088	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SU5A100E21**20	23,400	\$3,276
211713100	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SU5A060E17**16	23,400	\$3,276
211713112	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SU*A100E21**20	23,400	\$3,276
211713124	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SU*A040E17**12	23,200	\$3,248
213353883	CARRIER	38MURAQ60AB3*	F54AA*D60L*		37,800	\$5,292
213607809	CARRIER	38MURAQ60AB3*	FT4BNBD60L*		37,400	\$5,236
213607810	CARRIER	38MURAQ60AB3*	FG4ANBD60L*		37,400	\$5,236
211713136	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58TP*A090V17**16	23,000	\$3,220
211713139	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58TP*A090V21**20	23,200	\$3,248
211713150	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC5B080E21**20	23,200	\$3,248
211713162	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC5B100E21**20	23,600	\$3,304
211713174	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58TP*A070V17**16	23,200	\$3,248
211713185	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59TP6B060V17**14	23,200	\$3,248
211713186	CARRIER	38MURAQ30AB3*	CAP**4321AL*	GG96VTA42060B	23,200	\$3,248
211713197	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59TP6B080V21**20	23,000	\$3,220
211713208	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59TP6B100V21**20	23,200	\$3,248
211713219	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58TP*A110V21**22	23,200	\$3,248
211713230	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*A045E17**12	23,400	\$3,276
212384515	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SU5A060E17**16	29,400	\$4,116
212384503	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SU5A100E21**20	29,400	\$4,116
212384493	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SP*A090V21**20	29,400	\$4,116
212384483	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SP*A070V21**20	29,400	\$4,116
212384473	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SP*A070V17**16	29,400	\$4,116
211713243	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*A070E17**12	23,200	\$3,248
212384463	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SU5A100E21**22	29,600	\$4,144
212384453	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC5B100E21**22	29,600	\$4,144
212384443	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC2D100E21**22	29,600	\$4,144
212384431	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*A070E17**16	29,400	\$4,116
212384421	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SP6A080V17**16	29,400	\$4,116
212384411	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SP6A100V21**20	29,400	\$4,116
211713256	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*A070E21**16	23,200	\$3,248
212384401	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SP6A080V21**20	29,400	\$4,116
212384391	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SP6A060V17**14	29,400	\$4,116
212384381	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	OVMAAB042112	29,400	\$4,116
212384371	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	OVLAAB036098	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384361	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	OVMAAB036098	29,400	\$4,116
212384349	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58SU*A060E17**16	29,400	\$4,116
211713269	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*A090E17**14	23,200	\$3,248
212384336	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*A070E14**12	29,400	\$4,116
212384324	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SC2D080E17**16	29,200	\$4,088
212384312	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SC2D060E17**14	29,200	\$4,088
212384300	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SC2D060E14**12	29,400	\$4,116
212384287	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*A090E17**14	29,400	\$4,116
211713282	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*A090E21**16	23,400	\$3,276
212384274	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*A070E17**12	29,400	\$4,116
212384261	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*A045E17**12	29,400	\$4,116
212384248	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*A045E14**12	29,600	\$4,144
212384245	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58TP*A090V17**16	29,400	\$4,116
212384234	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58TP*A045V14**12	29,400	\$4,116
211713295	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*A090E21**20	23,200	\$3,248
212384224	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58SP*A070V17**16	29,200	\$4,088
212384214	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58SP*A045V17**16	29,400	\$4,116
212384202	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58S(B,C)*A070E17**16	29,200	\$4,088
211713308	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*A110E21**20	23,400	\$3,276
212384138	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	58SU*A080E21**20	29,800	\$4,172
212384126	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59SC2D100E21**20	29,600	\$4,144
212384114	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59SC2D080E21**20	29,600	\$4,144
211713321	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC2D060E17**14	23,000	\$3,220
211713333	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC2D080E17**16	23,400	\$3,276
211713345	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC2D080E21**20	23,200	\$3,248
211713357	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC2D100E21**20	23,200	\$3,248
212383808	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59SU5A100E21**22	29,800	\$4,172
212383798	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59SC5B100E21**22	29,800	\$4,172
212383788	CARRIER	38MURAQ36AB3*	CNPV*3621AL*	59SC2D100E21**22	29,800	\$4,172
211713369	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC5B060E17**14	23,200	\$3,248
211713381	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SU*A080E21**20	23,400	\$3,276
211713393	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58SU*A060E17**16	23,200	\$3,248
212383480	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*A070E17**16	29,000	\$4,060
212383468	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2D080E17**16	29,000	\$4,060
212383456	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*A070E17**16	29,200	\$4,088
212383446	CARRIER	38MURAQ36AB3*	CAP**4221AL*	OVLAAB048112	29,400	\$4,116
211713405	CARRIER	38MURAQ30AB3*	CAP**4321AL*	OVMAAB036098	23,200	\$3,248
212383434	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2D100E21**20	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383423	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58TP*A090V21**20	29,000	\$4,060
212383411	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SU5A060E17**16	29,200	\$4,088
212383399	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*A070E17**16	29,200	\$4,088
211713415	CARRIER	38MURAQ30AB3*	CAP**4321AL*	OVLAAB036098	23,200	\$3,248
212383387	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58SU*A060E17**16	29,200	\$4,088
212383375	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SU*A060E17**16	29,400	\$4,116
212383363	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SU*A080E21**20	29,600	\$4,144
212383351	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2D100E21**20	29,400	\$4,116
212383339	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2D080E21**20	29,400	\$4,116
212383327	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2D080E17**16	29,400	\$4,116
212383314	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*A090E21**20	29,400	\$4,116
212383301	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*A090E21**16	29,400	\$4,116
212383288	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*A090E17**14	29,600	\$4,144
212383275	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*A070E21**16	29,400	\$4,116
212383264	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58TP*A110V21**22	29,600	\$4,144
212383253	CARRIER	38MURAQ36AB3*	CAP**3621AL*	GG96VTAA42060B	29,600	\$4,144
212383252	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59TP6B060V17**14	29,600	\$4,144
212383241	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58TP*A070V17**16	29,400	\$4,116
212383229	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC5B080E21**20	29,600	\$4,144
212383218	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58TP*A090V21**20	29,400	\$4,116
212383206	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SU5A100E21**20	29,400	\$4,116
212383196	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SP*A090V21**20	29,400	\$4,116
212383186	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SP*A070V21**20	29,400	\$4,116
212383176	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SP*A070V17**16	29,400	\$4,116
212383164	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SU5A080E21**20	29,800	\$4,172
212383154	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SU5A100E21**22	29,600	\$4,144
212383142	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*A070E17**16	29,400	\$4,116
212383132	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SP6A080V17**16	29,400	\$4,116
212383122	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SP6A100V21**20	29,400	\$4,116
212383112	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SP6A080V21**20	29,400	\$4,116
212383102	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SP6A060V17**14	29,600	\$4,144
212383092	CARRIER	38MURAQ36AB3*	CAP**3617AL*	OVLAAB036098	29,600	\$4,144
212383082	CARRIER	38MURAQ36AB3*	CAP**3617AL*	OVMAAB036098	29,600	\$4,144
212383070	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58SU*A060E17**16	29,600	\$4,144
212383057	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*A070E14**12	29,600	\$4,144
212383045	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SC5B060E17**14	29,600	\$4,144
212383033	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SC2D080E17**16	29,400	\$4,116
212383021	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SC2D060E17**14	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383009	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SC2D060E14**12	29,600	\$4,144
212382996	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*A090E17**14	29,600	\$4,144
212382983	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*A070E17**12	29,600	\$4,144
212382970	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*A045E17**12	29,600	\$4,144
212382957	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*A045E14**12	29,800	\$4,172
212382946	CARRIER	38MURAQ36AB3*	CAP**3617AL*	GG96VTAA42060B	29,600	\$4,144
212382945	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59TP6B060V17**14	29,600	\$4,144
212382934	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58TP*A070V17**16	29,400	\$4,116
212382931	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58TP*A090V17**16	29,400	\$4,116
212382928	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58TP*A070V14**12	29,400	\$4,116
212382917	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58TP*A045V14**12	29,600	\$4,144
212382905	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SU5A060E17**16	29,400	\$4,116
212382895	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58SP*A070V17**16	29,400	\$4,116
212382885	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58SP*A045V17**16	29,600	\$4,144
212382873	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58S(B,C)*A070E17**16	29,400	\$4,116
212382863	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SP6A080V17**16	29,400	\$4,116
212382853	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59SP6A060V17**14	29,600	\$4,144
212382843	CARRIER	38MURAQ36AB3*	CAP**3617AL*	58SP*A045V14**12	29,600	\$4,144
211468636	CARRIER	38MURAQ36AB3*	PF4MN*B36L*		29,400	\$4,116
211230959	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	GG96VTAA66120D	29,200	\$4,088
211230958	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	GG96VTAA60100C	29,200	\$4,088
211230957	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	GG96VTAA60100C	29,200	\$4,088
211230956	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	GG96VTAA42060B	29,400	\$4,116
211230955	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	GG96VTAA60100C	29,400	\$4,116
211230954	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	GG96VTAA42060B	29,600	\$4,144
211230953	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	GG96VTAA42060B	29,400	\$4,116
211230952	CARRIER	38MURAQ36AB3*	CAP**4824AL*	GG96VTAA66120D	29,000	\$4,060
211230951	CARRIER	38MURAQ36AB3*	CAP**4824AL*	GG96VTAA60100C	28,800	\$4,032
211230950	CARRIER	38MURAQ36AB3*	CAP**4821AL*	GG96VTAA60100C	28,800	\$4,032
211230949	CARRIER	38MURAQ36AB3*	CAP**4821AL*	GG96VTAA42060B	29,200	\$4,088
211230948	CARRIER	38MURAQ36AB3*	CAP**4321AL*	GG96VTAA60100C	29,000	\$4,060
211230947	CARRIER	38MURAQ36AB3*	CAP**4321AL*	GG96VTAA42060B	29,200	\$4,088
211230946	CARRIER	38MURAQ36AB3*	CAP**4224AL*	GG96VTAA66120D	29,400	\$4,116
211230945	CARRIER	38MURAQ36AB3*	CAP**4224AL*	GG96VTAA60100C	29,200	\$4,088
211230944	CARRIER	38MURAQ36AB3*	CAP**4221AL*	GG96VTAA60100C	29,200	\$4,088
211230943	CARRIER	38MURAQ36AB3*	CAP**4221AL*	GG96VTAA48080B	29,400	\$4,116
211230942	CARRIER	38MURAQ36AB3*	CAP**4221AL*	GG96VTAA42060B	29,600	\$4,144
211230941	CARRIER	38MURAQ36AB3*	CAP**3721AL*	GG96VTAA60100C	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230940	CARRIER	38MURAQ36AB3*	CAP**3721AL*	GG96VTAA42060B	29,200	\$4,088
211230939	CARRIER	38MURAQ36AB3*	CAP**3717AL*	GG96VTAA42060B	29,400	\$4,116
211230938	CARRIER	38MURAQ36AB3*	CAP**3621AL*	GG96VTAA60100C	29,400	\$4,116
211714013	CARRIER	38MURAQ30AB3*	CNPV*3621AL*	58SU*A080E21**20	23,600	\$3,304
211714037	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58SP*A045V14**12	23,400	\$3,276
211714047	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SP6A080V17**16	23,400	\$3,276
211714057	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SU5A040E17**12	23,400	\$3,276
211714069	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*A070E17**16	23,600	\$3,304
211714081	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58SP*A045V17**16	23,400	\$3,276
211714091	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58SP*A070V17**16	23,400	\$3,276
211714101	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SU5A060E17**16	23,600	\$3,304
211714113	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58SU*A040E17**12	23,400	\$3,276
211714125	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58TP*A045V14**12	23,400	\$3,276
211714136	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58TP*A070V14**12	23,200	\$3,248
211714139	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58TP*A090V17**16	23,400	\$3,276
211714142	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58TP*A070V17**16	23,400	\$3,276
211714153	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59TP6B060V17**14	23,400	\$3,276
211714154	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	GG96VTAA42060B	23,400	\$3,276
211714165	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*A045E14**12	23,400	\$3,276
211714178	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*A070E17**12	23,400	\$3,276
211714191	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*A090E17**14	23,400	\$3,276
211714204	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC2D060E14**12	23,400	\$3,276
211714216	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC2D060E17**14	23,200	\$3,248
211714228	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC2D080E17**16	23,200	\$3,248
211714240	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC5B060E17**14	23,400	\$3,276
211714252	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*A070E14**12	23,200	\$3,248
211714265	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58SU*A060E17**16	23,400	\$3,276
211714277	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	OVMAAB036098	23,400	\$3,276
211714287	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	OVLAAB036098	23,400	\$3,276
211714307	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SP6A100V21**20	23,400	\$3,276
211714317	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SP6A080V17**16	23,400	\$3,276
211714339	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58S(B,C)*A070E17**16	23,600	\$3,304
211714351	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59TP6B100V21**22	23,400	\$3,276
211714352	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	GG96VTAA60100C	23,400	\$3,276
211714382	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58SP*A070V21**20	23,400	\$3,276
211714402	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SU5A100E21**20	23,600	\$3,304
211714414	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SU5A060E17**16	23,600	\$3,304
212970756	CARRIER	38MURAQ48AA3*	CAP**4824AL*	58SP*B090V21**20	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212970746	CARRIER	38MURQA48AA3*	CAP**4821AL*	58SP*B090V21**20	32,600	\$4,564
211714426	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58SU*A100E21**20	23,600	\$3,304
211714438	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58SU*A040E17**12	23,400	\$3,276
212970796	CARRIER	38MURQA48AB3*	CAP**4821AL*	58SP*B090V21**20	31,400	\$4,396
212970806	CARRIER	38MURQA48AB3*	CAP**4824AL*	58SP*B090V21**20	31,400	\$4,396
212970816	CARRIER	38MURQA48AB3*	CAP**6024AL*	58SP*B090V21**20	31,000	\$4,340
212970826	CARRIER	38MURQA48AB3*	CAP**6121AL*	58SP*B090V21**20	31,000	\$4,340
212970836	CARRIER	38MURQA48AB3*	CAP**6124AL*	58SP*B090V21**20	31,000	\$4,340
211714464	CARRIER	38MURQA30AB3*	CNPV*4221AL*	59SC5B080E21**20	23,400	\$3,276
211714476	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58TP*A070V17**16	23,400	\$3,276
211714509	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58TP*A110V21**22	23,400	\$3,276
211714533	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58S(B,C)*A070E21**16	23,600	\$3,304
211714546	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58S(B,C)*A090E17**14	23,400	\$3,276
211714559	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58S(B,C)*A090E21**16	23,600	\$3,304
211714572	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58S(B,C)*A090E21**20	23,400	\$3,276
211714585	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58S(B,C)*A110E21**20	23,600	\$3,304
211714622	CARRIER	38MURQA30AB3*	CNPV*4221AL*	59SC2D080E21**20	23,400	\$3,276
211714634	CARRIER	38MURQA30AB3*	CNPV*4221AL*	59SC2D100E21**20	23,400	\$3,276
211714658	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58SU*A060E17**16	23,400	\$3,276
211714680	CARRIER	38MURQA30AB3*	FJ4DN*B36L*		23,400	\$3,276
211714681	CARRIER	38MURQA30AB3*	PF4MN*B36L*		23,400	\$3,276
212969876	CARRIER	38MURQA30AB3*	CAP**3717AL*	58SP*B045V14**12	23,400	\$3,276
212969916	CARRIER	38MURQA30AB3*	CNPV*4217AL*	58SP*B045V14**12	23,400	\$3,276
212970296	CARRIER	38MURQA30AB3*	CAP**4221AL*	58SP*B070V17**16	23,600	\$3,304
212970346	CARRIER	38MURQA30AB3*	CNPV*4217AL*	58SP*B070V17**16	23,400	\$3,276
212970356	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58SP*B070V17**16	23,600	\$3,304
212970586	CARRIER	38MURQA30AB3*	CAP**4221AL*	58SP*B090V21**20	23,600	\$3,304
212970596	CARRIER	38MURQA30AB3*	CAP**4224AL*	58SP*B090V21**20	23,600	\$3,304
212970626	CARRIER	38MURQA30AB3*	CNPV*4221AL*	58SP*B090V21**20	23,600	\$3,304
212971290	CARRIER	38MURQA30AB3*	CAP**3717AL*	58TP*B045V14**12	23,400	\$3,276
212971338	CARRIER	38MURQA30AB3*	CNPV*4217AL*	58TP*B045V14**12	23,400	\$3,276
212971424	CARRIER	38MURQA30AB3*	CAP**3717AL*	58TP*B070V14**12	23,400	\$3,276
212971432	CARRIER	38MURQA30AB3*	CNPV*4217AL*	58TP*B070V14**12	23,400	\$3,276
212971775	CARRIER	38MURQA30AB3*	CAP**3717AL*	58TP*B070V17**16	23,400	\$3,276
212971786	CARRIER	38MURQA30AB3*	CAP**3721AL*	58TP*B070V17**16	23,200	\$3,248
212971797	CARRIER	38MURQA30AB3*	CAP**4221AL*	58TP*B070V17**16	23,600	\$3,304
212971808	CARRIER	38MURQA30AB3*	CAP**4321AL*	58TP*B070V17**16	23,200	\$3,248
212971852	CARRIER	38MURQA30AB3*	CNPV*4217AL*	58TP*B070V17**16	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971863	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58TP*B070V17**16	23,600	\$3,304
212972031	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58TP*B090V17**16	23,400	\$3,276
212972035	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58TP*B090V17**16	23,200	\$3,248
212972043	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58TP*B090V17**16	23,200	\$3,248
212972059	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58TP*B090V17**16	23,400	\$3,276
212972063	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58TP*B090V17**16	23,600	\$3,304
212972164	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58TP*B090V21**20	23,200	\$3,248
212972175	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58TP*B090V21**20	23,600	\$3,304
212972186	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58TP*B090V21**20	23,600	\$3,304
212972197	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58TP*B090V21**20	23,200	\$3,248
212972219	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58TP*B090V21**20	23,600	\$3,304
212972446	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58TP*B110V21**22	23,400	\$3,276
212972458	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58TP*B110V21**22	23,400	\$3,276
212972470	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58TP*B110V21**22	23,400	\$3,276
212972482	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58TP*B110V21**22	23,200	\$3,248
212973642	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SP6B060V14**12	23,600	\$3,304
212973962	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SP6B080V17**16	23,400	\$3,276
212973972	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SP6B080V17**16	23,400	\$3,276
212973992	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SP6B080V17**16	23,200	\$3,248
212974032	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SP6B080V17**16	23,400	\$3,276
212974132	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SP6B080V21**20	23,200	\$3,248
212974142	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SP6B080V21**20	23,400	\$3,276
212974152	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SP6B080V21**20	23,400	\$3,276
212974162	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SP6B080V21**20	23,200	\$3,248
212974182	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SP6B080V21**20	23,600	\$3,304
212974352	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SP6B100V21**20	23,200	\$3,248
212974362	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SP6B100V21**20	23,600	\$3,304
212974372	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SP6B100V21**20	23,600	\$3,304
212974382	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SP6B100V21**20	23,200	\$3,248
212974402	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SP6B100V21**20	23,600	\$3,304
212974522	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SP6B120V24**22	23,600	\$3,304
212975760	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59TP6C060V14**12	23,600	\$3,304
212976174	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59TP6C080V17**16	23,400	\$3,276
212976175	CARRIER	38MURAQ30AB3*	CAP**3717AL*	GG96VTAB48080B**	23,400	\$3,276
212976187	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59TP6C080V17**16	23,400	\$3,276
212976188	CARRIER	38MURAQ30AB3*	CAP**3721AL*	GG96VTAB48080B**	23,400	\$3,276
212976213	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59TP6C080V17**16	23,200	\$3,248
212976214	CARRIER	38MURAQ30AB3*	CAP**4321AL*	GG96VTAB48080B**	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976265	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59TP6C080V17**16	23,400	\$3,276
212976266	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	GG96VTAB48080B**	23,400	\$3,276
212976441	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59TP6C080V21**20	23,200	\$3,248
212976456	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59TP6C080V21**20	23,400	\$3,276
212976469	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59TP6C080V21**20	23,400	\$3,276
212976483	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59TP6C080V21**20	23,200	\$3,248
212976511	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59TP6C080V21**20	23,600	\$3,304
212976714	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59TP6C100V21**20	23,200	\$3,248
212976715	CARRIER	38MURAQ30AB3*	CAP**3721AL*	GG96VTAB60100C**	23,200	\$3,248
212976727	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59TP6C100V21**20	23,600	\$3,304
212976728	CARRIER	38MURAQ30AB3*	CAP**4221AL*	GG96VTAB60100C**	23,600	\$3,304
212976740	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59TP6C100V21**20	23,600	\$3,304
212976741	CARRIER	38MURAQ30AB3*	CAP**4224AL*	GG96VTAB60100C**	23,600	\$3,304
212976753	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59TP6C100V21**20	23,200	\$3,248
212976754	CARRIER	38MURAQ30AB3*	CAP**4321AL*	GG96VTAB60100C**	23,200	\$3,248
212976779	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59TP6C100V21**20	23,600	\$3,304
212976780	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	GG96VTAB60100C**	23,600	\$3,304
212977018	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59TP6C100V21**22	23,200	\$3,248
212977028	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59TP6C100V21**22	23,400	\$3,276
212977038	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59TP6C100V21**22	23,400	\$3,276
212977048	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59TP6C100V21**22	23,200	\$3,248
212977068	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59TP6C100V21**22	23,400	\$3,276
212977238	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59TP6C120V24**22	23,600	\$3,304
212977239	CARRIER	38MURAQ30AB3*	CAP**4224AL*	GG96VTAB66120D**	23,600	\$3,304
212977514	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58S(B,C)*B045M14**12	23,400	\$3,276
212977550	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*B045M14**12	23,400	\$3,276
212978018	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58S(B,C)*B070M14**12	23,400	\$3,276
212978066	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*B070M14**12	23,400	\$3,276
212978521	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58S(B,C)*B070M17**12	23,400	\$3,276
212978532	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*B070M17**12	23,200	\$3,248
212978543	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*B070M17**12	23,400	\$3,276
212978554	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*B070M17**12	23,200	\$3,248
212978598	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*B070M17**12	23,400	\$3,276
212978609	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58S(B,C)*B070M17**12	23,400	\$3,276
212979011	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58S(B,C)*B070M17**16	23,400	\$3,276
212979023	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*B070M17**16	23,200	\$3,248
212979035	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*B070M17**16	23,600	\$3,304
212979047	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*B070M17**16	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979095	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*B070M17**16	23,400	\$3,276
212979107	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58S(B,C)*B070M17**16	23,600	\$3,304
212979431	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*B070M21**16	23,200	\$3,248
212979441	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*B070M21**16	23,400	\$3,276
212979451	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*B070M21**16	23,400	\$3,276
212979461	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*B070M21**16	23,200	\$3,248
212979701	CARRIER	38MURAQ30AB3*	CAP**3717AL*	58S(B,C)*B090M17**14	23,400	\$3,276
212979713	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*B090M17**14	23,200	\$3,248
212979725	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*B090M17**14	23,400	\$3,276
212979737	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*B090M17**14	23,200	\$3,248
212979785	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	58S(B,C)*B090M17**14	23,400	\$3,276
212980189	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*B090M21**16	23,200	\$3,248
212980222	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*B090M21**16	23,200	\$3,248
212980244	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58S(B,C)*B090M21**16	23,600	\$3,304
212980508	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*B090M21**20	23,200	\$3,248
212980519	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*B090M21**20	23,600	\$3,304
212980541	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*B090M21**20	23,200	\$3,248
212980563	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58S(B,C)*B090M21**20	23,600	\$3,304
212980697	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*B090M24**20	23,600	\$3,304
212980898	CARRIER	38MURAQ30AB3*	CAP**3621AL*	58S(B,C)*B110M21**20	23,600	\$3,304
212980910	CARRIER	38MURAQ30AB3*	CAP**3721AL*	58S(B,C)*B110M21**20	23,200	\$3,248
212980922	CARRIER	38MURAQ30AB3*	CAP**4221AL*	58S(B,C)*B110M21**20	23,600	\$3,304
212980934	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*B110M21**20	23,600	\$3,304
212980946	CARRIER	38MURAQ30AB3*	CAP**4321AL*	58S(B,C)*B110M21**20	23,200	\$3,248
212980970	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	58S(B,C)*B110M21**20	23,600	\$3,304
212981108	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*B110M24**20	23,400	\$3,276
212981217	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*B135M24**20	23,600	\$3,304
212981318	CARRIER	38MURAQ30AB3*	CAP**4224AL*	58S(B,C)*B155M24**20	23,400	\$3,276
212983466	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SC2E060M14**12	23,400	\$3,276
212983496	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC2E060M14**12	23,600	\$3,304
212983917	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SC2E060M17**14	23,400	\$3,276
212983929	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC2E060M17**14	23,200	\$3,248
212983953	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC2E060M17**14	23,200	\$3,248
212984001	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC2E060M17**14	23,400	\$3,276
212984457	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SC2E080M17**16	23,400	\$3,276
212984469	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC2E080M17**16	23,200	\$3,248
212984481	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SC2E080M17**16	23,400	\$3,276
212984493	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC2E080M17**16	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984541	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC2E080M17**16	23,400	\$3,276
212984969	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC2E080M21**20	23,200	\$3,248
212984979	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SC2E080M21**20	23,400	\$3,276
212984989	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC2E080M21**20	23,400	\$3,276
212984999	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC2E080M21**20	23,200	\$3,248
212985019	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SC2E080M21**20	23,600	\$3,304
212985263	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC2E100M21**20	23,200	\$3,248
212985275	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SC2E100M21**20	23,400	\$3,276
212985287	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC2E100M21**20	23,400	\$3,276
212985299	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC2E100M21**20	23,600	\$3,304
212985323	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SC2E100M21**20	23,600	\$3,304
212985612	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC2E120M24**20	23,400	\$3,276
212985743	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC6A026M14**10	23,600	\$3,304
212986847	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC6A060M14**12	23,600	\$3,304
212987255	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SC6A080M17**16	23,400	\$3,276
212987267	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC6A080M17**16	23,200	\$3,248
212987291	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC6A080M17**16	23,400	\$3,276
212987339	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SC6A080M17**16	23,600	\$3,304
212987351	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SC6A080M17**16	23,600	\$3,304
212987723	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SC6A080M21**20	23,200	\$3,248
212987747	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC6A080M21**20	23,400	\$3,276
212987759	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SC6A080M21**20	23,200	\$3,248
212988329	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC6A120M24**22	23,400	\$3,276
212988411	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SC6A140M24**22	23,600	\$3,304
212988577	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SU5B040M17**12	23,600	\$3,304
212988589	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SU5B040M17**12	23,200	\$3,248
212988613	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SU5B040M17**12	23,200	\$3,248
212988625	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SU5B040M17**12	23,600	\$3,304
212989021	CARRIER	38MURAQ30AB3*	CAP**3717AL*	59SU5B060M17**16	23,400	\$3,276
212989033	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SU5B060M17**16	23,200	\$3,248
212989045	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SU5B060M17**16	23,600	\$3,304
212989057	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SU5B060M17**16	23,200	\$3,248
212989105	CARRIER	38MURAQ30AB3*	CNPV*4217AL*	59SU5B060M17**16	23,400	\$3,276
212989117	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SU5B060M17**16	23,600	\$3,304
212989525	CARRIER	38MURAQ30AB3*	CAP**3721AL*	59SU5B080M21**20	23,200	\$3,248
212989537	CARRIER	38MURAQ30AB3*	CAP**4221AL*	59SU5B080M21**20	23,600	\$3,304
212989549	CARRIER	38MURAQ30AB3*	CAP**4224AL*	59SU5B080M21**20	23,600	\$3,304
212989561	CARRIER	38MURAQ30AB3*	CAP**4321AL*	59SU5B080M21**20	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989585	CARRIER	38MURAQ30AB3*	CNPV*4221AL*	59SU5B080M21**20	23,600	\$3,304
213249290	CARRIER	38MURAQ30AB3*	FEVA0036**+NAVA43601CK		23,600	\$3,304
213353807	CARRIER	38MURAQ30AB3*	F54AA*B30L*		23,400	\$3,276
213353817	CARRIER	38MURAQ30AB3*	F54AA*B36L*		23,600	\$3,304
210450189	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59TP6B080V17**16	29,600	\$4,144
210450190	CARRIER	38MURAQ36AB3*	CAP**3617AL*	59TP6B060V14**12	29,800	\$4,172
210450191	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59TP6B080V17**16	29,600	\$4,144
210450192	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59TP6B080V17**16	29,400	\$4,116
210450193	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59TP6B060V14**12	29,600	\$4,144
210450194	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59TP6B080V17**16	29,200	\$4,088
210450195	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59TP6B080V17**16	29,200	\$4,088
210450196	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6B080V17**16	29,000	\$4,060
210450200	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59TP6B080V17**16	29,400	\$4,116
210450201	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59TP6B060V14**12	29,600	\$4,144
210450202	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59TP6B080V17**16	29,400	\$4,116
210450203	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6B080V17**16	29,200	\$4,088
210450238	CARRIER	38MURAQ36AB3*	CAP**3617AL*	GG96VTAA48080B	29,600	\$4,144
210450241	CARRIER	38MURAQ36AB3*	CAP**3621AL*	GG96VTAA48080B	29,600	\$4,144
210450243	CARRIER	38MURAQ36AB3*	CAP**3717AL*	GG96VTAA48080B	29,400	\$4,116
210450246	CARRIER	38MURAQ36AB3*	CAP**3721AL*	GG96VTAA48080B	29,200	\$4,088
210450248	CARRIER	38MURAQ36AB3*	CAP**4321AL*	GG96VTAA48080B	29,200	\$4,088
210450250	CARRIER	38MURAQ36AB3*	CAP**4821AL*	GG96VTAA48080B	29,000	\$4,060
210450257	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	GG96VTAA48080B	29,400	\$4,116
210450260	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	GG96VTAA48080B	29,400	\$4,116
210450262	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	GG96VTAA48080B	29,200	\$4,088
211225659	CARRIER	38MURAQ36AB3*	FJ4DN*B36L*		29,400	\$4,116
211225673	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*A045E17**12	29,600	\$4,144
211225674	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*A070E17**12	29,600	\$4,144
211225675	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58S(B,C)*A110E21**20	29,400	\$4,116
211225676	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SP*A045V17**16	29,600	\$4,144
211225677	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58SU*A100E21**20	29,400	\$4,116
211225678	CARRIER	38MURAQ36AB3*	CAP**3621AL*	58TP*A090V17**16	29,400	\$4,116
211225680	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2D060E17**14	29,400	\$4,116
211225681	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC2D100E21**22	29,600	\$4,144
211225682	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC5B060E17**14	29,400	\$4,116
211225683	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC5B080E17**16	29,400	\$4,116
211225684	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC5B100E21**20	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211225685	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SC5B100E21**22	29,600	\$4,144
211225686	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59SU5A060E17**16	29,400	\$4,116
211225687	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59TP6B080V21**20	29,400	\$4,116
211225688	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59TP6B100V21**20	29,600	\$4,144
211225689	CARRIER	38MURAQ36AB3*	CAP**3621AL*	59TP6B100V21**22	29,400	\$4,116
211225690	CARRIER	38MURAQ36AB3*	CAP**3621AL*	OVLAAB036098	29,600	\$4,144
211225691	CARRIER	38MURAQ36AB3*	CAP**3621AL*	OVLAAB048112	29,600	\$4,144
211225692	CARRIER	38MURAQ36AB3*	CAP**3621AL*	OVMAAB036098	29,600	\$4,144
211225693	CARRIER	38MURAQ36AB3*	CAP**3621AL*	OVMAAB042112	29,600	\$4,144
211225696	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*A045E14**12	29,400	\$4,116
211225697	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*A070E14**12	29,200	\$4,088
211225698	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*A070E17**12	29,400	\$4,116
211225699	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*A070E17**16	29,400	\$4,116
211225700	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58S(B,C)*A090E17**14	29,200	\$4,088
211225701	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58SP*A045V14**12	29,400	\$4,116
211225702	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58SP*A045V17**16	29,400	\$4,116
211225703	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58SP*A070V17**16	29,400	\$4,116
211225705	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58TP*A045V14**12	29,400	\$4,116
211225706	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58TP*A070V14**12	29,200	\$4,088
211225707	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58TP*A070V17**16	29,400	\$4,116
211225708	CARRIER	38MURAQ36AB3*	CAP**3717AL*	58TP*A090V17**16	29,200	\$4,088
211225710	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SC2D060E14**12	29,400	\$4,116
211225711	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SC2D060E17**14	29,200	\$4,088
211225712	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SC2D080E17**16	29,400	\$4,116
211225714	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SC5B060E17**14	29,400	\$4,116
211225715	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SP6A060V14**12	29,400	\$4,116
211225716	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SP6A060V17**14	29,400	\$4,116
211225717	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SP6A080V17**16	29,400	\$4,116
211225718	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59SU5A060E17**16	29,400	\$4,116
211225719	CARRIER	38MURAQ36AB3*	CAP**3717AL*	59TP6B060V17**14	29,400	\$4,116
211225720	CARRIER	38MURAQ36AB3*	CAP**3717AL*	OVLAAB036098	29,400	\$4,116
211225721	CARRIER	38MURAQ36AB3*	CAP**3717AL*	OVMAAB036098	29,400	\$4,116
211225722	CARRIER	38MURAQ36AB3*	CAP**3717AL*	OVMAAB042112	29,400	\$4,116
211225728	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*A070E17**12	29,200	\$4,088
211225729	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*A070E21**16	29,200	\$4,088
211225730	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*A090E17**14	29,200	\$4,088
211225731	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*A090E21**16	29,000	\$4,060
211225732	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*A090E21**20	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211225733	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58S(B,C)*A110E21**20	29,200	\$4,088
211225734	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SP*A045V17**16	29,200	\$4,088
211225735	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SP*A070V17**16	29,200	\$4,088
211225736	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SP*A070V21**20	29,000	\$4,060
211225737	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SP*A090V21**20	29,000	\$4,060
211225738	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SU*A040E17**12	29,400	\$4,116
211225739	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SU*A060E17**16	29,200	\$4,088
211225740	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SU*A100E21**20	29,000	\$4,060
211225741	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58TP*A070V17**16	29,000	\$4,060
211225742	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58TP*A090V17**16	29,000	\$4,060
211225743	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58TP*A110V21**22	29,200	\$4,088
211225747	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2D060E17**14	29,000	\$4,060
211225748	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2D080E17**16	29,000	\$4,060
211225749	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2D080E21**20	29,200	\$4,088
211225750	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC5B060E17**14	29,400	\$4,116
211225752	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC5B080E21**20	29,200	\$4,088
211225753	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC5B100E21**20	29,200	\$4,088
211225755	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SP6A060V17**14	29,200	\$4,088
211225756	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SP6A080V17**16	29,200	\$4,088
211225757	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SP6A080V21**20	29,000	\$4,060
211225758	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SP6A100V21**20	29,000	\$4,060
211225759	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SU5A100E21**20	29,000	\$4,060
211225760	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SU5A100E21**22	29,200	\$4,088
211225762	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59TP6B060V17**14	29,200	\$4,088
211225763	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59TP6B080V21**20	29,200	\$4,088
211225764	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59TP6B100V21**20	29,200	\$4,088
211225765	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59TP6B100V21**22	29,000	\$4,060
211225766	CARRIER	38MURAQ36AB3*	CAP**3721AL*	OVLAAB036098	29,200	\$4,088
211225767	CARRIER	38MURAQ36AB3*	CAP**3721AL*	OVLAAB048112	29,200	\$4,088
211225768	CARRIER	38MURAQ36AB3*	CAP**3721AL*	OVMAAB036098	29,200	\$4,088
211225769	CARRIER	38MURAQ36AB3*	CAP**3721AL*	OVMAAB042112	29,200	\$4,088
211225774	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*A045E17**12	29,400	\$4,116
211225775	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*A070E17**12	29,400	\$4,116
211225776	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*A070E17**16	29,400	\$4,116
211225777	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*A070E21**16	29,400	\$4,116
211225778	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*A090E17**14	29,400	\$4,116
211225779	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*A090E21**16	29,400	\$4,116
211225780	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*A090E21**20	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211225781	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58S(B,C)*A110E21**20	29,400	\$4,116
211225782	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SP*A045V17**16	29,400	\$4,116
211225783	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SP*A070V17**16	29,400	\$4,116
211225784	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SP*A070V21**20	29,400	\$4,116
211225785	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SP*A090V21**20	29,400	\$4,116
211225787	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SU*A060E17**16	29,200	\$4,088
211225788	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SU*A080E21**20	29,600	\$4,144
211225789	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58SU*A100E21**20	29,400	\$4,116
211225790	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58TP*A070V17**16	29,400	\$4,116
211225791	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58TP*A090V17**16	29,400	\$4,116
211225792	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58TP*A090V21**20	29,400	\$4,116
211225793	CARRIER	38MURAQ36AB3*	CAP**4221AL*	58TP*A110V21**22	29,400	\$4,116
211225796	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2D060E17**14	29,400	\$4,116
211225797	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2D080E17**16	29,400	\$4,116
211225798	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2D080E21**20	29,200	\$4,088
211225799	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2D100E21**20	29,200	\$4,088
211225800	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC2D100E21**22	29,600	\$4,144
211225801	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC5B060E17**14	29,400	\$4,116
211225802	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC5B080E21**20	29,400	\$4,116
211225803	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SC5B100E21**22	29,600	\$4,144
211225804	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SP6A060V17**14	29,400	\$4,116
211225805	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SP6A080V17**16	29,400	\$4,116
211225806	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SP6A080V21**20	29,400	\$4,116
211225807	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SP6A100V21**20	29,400	\$4,116
211225808	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SU5A060E17**16	29,400	\$4,116
211225809	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SU5A080E21**20	29,600	\$4,144
211225810	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SU5A100E21**20	29,400	\$4,116
211225811	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59SU5A100E21**22	29,600	\$4,144
211225812	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59TP6B060V17**14	29,600	\$4,144
211225813	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59TP6B080V17**16	29,400	\$4,116
211225814	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59TP6B080V21**20	29,400	\$4,116
211225815	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59TP6B100V21**20	29,400	\$4,116
211225816	CARRIER	38MURAQ36AB3*	CAP**4221AL*	59TP6B100V21**22	29,200	\$4,088
211225817	CARRIER	38MURAQ36AB3*	CAP**4221AL*	OVLAAB036098	29,400	\$4,116
211225818	CARRIER	38MURAQ36AB3*	CAP**4221AL*	OVMAAB036098	29,400	\$4,116
211225819	CARRIER	38MURAQ36AB3*	CAP**4221AL*	OVMAAB042112	29,400	\$4,116
211225822	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*A070E21**16	29,400	\$4,116
211225823	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*A090E21**16	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211225824	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*A090E21**20	29,400	\$4,116
211225825	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*A090E24**20	29,400	\$4,116
211225826	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*A110E21**20	29,400	\$4,116
211225827	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*A110E24**20	29,200	\$4,088
211225828	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*A135E24**20	29,400	\$4,116
211225829	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58S(B,C)*A155E24**20	29,400	\$4,116
211225830	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58SP*A070V21**20	29,400	\$4,116
211225831	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58SP*A090V21**20	29,400	\$4,116
211225832	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58SP*A090V24**20	29,400	\$4,116
211225833	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58SP*A110V24**22	29,200	\$4,088
211225834	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58SU*A080E21**20	29,600	\$4,144
211225835	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58SU*A100E21**20	29,400	\$4,116
211225836	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58TP*A090V21**20	29,400	\$4,116
211225837	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58TP*A110V21**22	29,400	\$4,116
211225838	CARRIER	38MURAQ36AB3*	CAP**4224AL*	58TP*A135V24**22	29,400	\$4,116
211225841	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC2D080E21**20	29,200	\$4,088
211225842	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC2D100E21**20	29,200	\$4,088
211225843	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC2D100E21**22	29,600	\$4,144
211225844	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC2D120E24**20	29,400	\$4,116
211225845	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC5B080E21**20	29,400	\$4,116
211225846	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC5B100E21**20	29,400	\$4,116
211225847	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC5B100E21**22	29,600	\$4,144
211225848	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC5B120E24**22	29,600	\$4,144
211225849	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SC5B140E24**22	29,600	\$4,144
211225850	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SP6A080V21**20	29,400	\$4,116
211225851	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SP6A100V21**20	29,400	\$4,116
211225852	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SP6A120V24**22	29,400	\$4,116
211225853	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SU5A080E21**20	29,600	\$4,144
211225854	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SU5A100E21**20	29,400	\$4,116
211225855	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59SU5A100E21**22	29,600	\$4,144
211225856	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59TP6B080V21**20	29,400	\$4,116
211225857	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59TP6B100V21**20	29,400	\$4,116
211225858	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59TP6B100V21**22	29,200	\$4,088
211225859	CARRIER	38MURAQ36AB3*	CAP**4224AL*	59TP6B120V24**22	29,400	\$4,116
211225860	CARRIER	38MURAQ36AB3*	CAP**4224AL*	OVLAAB048112	29,400	\$4,116
211225861	CARRIER	38MURAQ36AB3*	CAP**4224AL*	OVLAAB060154	29,600	\$4,144
211225862	CARRIER	38MURAQ36AB3*	CAP**4224AL*	OVMAAB060154	29,400	\$4,116
211225867	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*A045E17**12	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211225868	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*A070E17**12	29,200	\$4,088
211225869	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*A070E21**16	29,200	\$4,088
211225870	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*A090E17**14	29,200	\$4,088
211225871	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*A090E21**16	29,000	\$4,060
211225872	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*A090E21**20	29,200	\$4,088
211225873	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58S(B,C)*A110E21**20	29,200	\$4,088
211225874	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SP*A045V17**16	29,200	\$4,088
211225875	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SP*A070V17**16	29,200	\$4,088
211225876	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SP*A070V21**20	29,000	\$4,060
211225877	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SP*A090V21**20	29,000	\$4,060
211225878	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SU*A040E17**12	29,400	\$4,116
211225879	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SU*A060E17**16	29,200	\$4,088
211225880	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SU*A080E21**20	29,200	\$4,088
211225881	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58SU*A100E21**20	29,000	\$4,060
211225882	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58TP*A070V17**16	29,000	\$4,060
211225883	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58TP*A090V17**16	29,000	\$4,060
211225884	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58TP*A090V21**20	29,000	\$4,060
211225885	CARRIER	38MURAQ36AB3*	CAP**4321AL*	58TP*A110V21**22	29,200	\$4,088
211225889	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2D060E17**14	29,000	\$4,060
211225890	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2D080E21**20	29,200	\$4,088
211225891	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2D100E21**20	29,200	\$4,088
211225892	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC5B060E17**14	29,400	\$4,116
211225894	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC5B080E21**20	29,200	\$4,088
211225895	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC5B100E21**20	29,200	\$4,088
211225897	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SP6A060V17**14	29,200	\$4,088
211225898	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SP6A080V17**16	29,200	\$4,088
211225899	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SP6A080V21**20	29,000	\$4,060
211225900	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SP6A100V21**20	29,000	\$4,060
211225901	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SU5A060E17**16	29,200	\$4,088
211225902	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SU5A100E21**20	29,000	\$4,060
211225904	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59TP6B060V17**14	29,200	\$4,088
211225905	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59TP6B080V21**20	29,200	\$4,088
211225906	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59TP6B100V21**20	29,200	\$4,088
211225907	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59TP6B100V21**22	29,000	\$4,060
211225908	CARRIER	38MURAQ36AB3*	CAP**4321AL*	OVLAAB036098	29,200	\$4,088
211225909	CARRIER	38MURAQ36AB3*	CAP**4321AL*	OVLAAB048112	29,200	\$4,088
211225910	CARRIER	38MURAQ36AB3*	CAP**4321AL*	OVMAAB036098	29,200	\$4,088
211225911	CARRIER	38MURAQ36AB3*	CAP**4321AL*	OVMAAB042112	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211225916	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*A045E17**12	29,000	\$4,060
211225917	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*A070E17**12	29,000	\$4,060
211225918	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*A070E21**16	28,800	\$4,032
211225919	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*A090E17**14	29,000	\$4,060
211225920	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*A090E21**16	29,000	\$4,060
211225921	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*A090E21**20	29,000	\$4,060
211225922	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58S(B,C)*A110E21**20	29,000	\$4,060
211225923	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SP*A045V17**16	29,000	\$4,060
211225924	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SP*A070V17**16	29,000	\$4,060
211225925	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SP*A070V21**20	29,000	\$4,060
211225926	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SP*A090V21**20	28,800	\$4,032
211225927	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SU*A040E17**12	29,400	\$4,116
211225928	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SU*A060E17**16	29,000	\$4,060
211225929	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SU*A080E21**20	29,200	\$4,088
211225930	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58SU*A100E21**20	29,000	\$4,060
211225931	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58TP*A070V17**16	29,000	\$4,060
211225932	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58TP*A090V17**16	29,000	\$4,060
211225933	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58TP*A090V21**20	28,800	\$4,032
211225934	CARRIER	38MURAQ36AB3*	CAP**4821AL*	58TP*A110V21**22	29,000	\$4,060
211225938	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2D060E17**14	29,000	\$4,060
211225939	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2D080E17**16	29,000	\$4,060
211225940	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2D080E21**20	28,800	\$4,032
211225941	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2D100E21**20	28,800	\$4,032
211225942	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC2D100E21**22	29,200	\$4,088
211225943	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC5B060E17**14	29,000	\$4,060
211225944	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC5B080E17**16	29,000	\$4,060
211225945	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC5B080E21**20	29,200	\$4,088
211225946	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC5B100E21**20	29,000	\$4,060
211225947	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SC5B100E21**22	29,200	\$4,088
211225949	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SP6A060V17**14	29,000	\$4,060
211225950	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SP6A080V17**16	29,000	\$4,060
211225951	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SP6A080V21**20	29,000	\$4,060
211225952	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SP6A100V21**20	29,000	\$4,060
211225953	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SU5A060E17**16	29,000	\$4,060
211225954	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SU5A080E21**20	29,400	\$4,116
211225955	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SU5A100E21**20	29,000	\$4,060
211225956	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59SU5A100E21**22	29,200	\$4,088
211225957	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6B060V17**14	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211225958	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6B080V21**20	29,000	\$4,060
211225959	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6B100V21**20	29,000	\$4,060
211225960	CARRIER	38MURAQ36AB3*	CAP**4821AL*	59TP6B100V21**22	28,800	\$4,032
211225961	CARRIER	38MURAQ36AB3*	CAP**4821AL*	OVLAAB036098	29,000	\$4,060
211225962	CARRIER	38MURAQ36AB3*	CAP**4821AL*	OVLAAB048112	29,000	\$4,060
211225963	CARRIER	38MURAQ36AB3*	CAP**4821AL*	OVMAAB036098	29,000	\$4,060
211225964	CARRIER	38MURAQ36AB3*	CAP**4821AL*	OVMAAB042112	29,000	\$4,060
211225967	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*A070E21**16	28,800	\$4,032
211225968	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*A090E21**16	29,000	\$4,060
211225969	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*A090E21**20	29,000	\$4,060
211225970	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*A090E24**20	29,000	\$4,060
211225971	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*A110E21**20	29,000	\$4,060
211225972	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*A110E24**20	28,800	\$4,032
211225973	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*A135E24**20	29,000	\$4,060
211225974	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58S(B,C)*A155E24**20	29,200	\$4,088
211225975	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58SP*A070V21**20	29,000	\$4,060
211225976	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58SP*A090V21**20	28,800	\$4,032
211225977	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58SP*A090V24**20	28,800	\$4,032
211225978	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58SP*A110V24**22	28,800	\$4,032
211225979	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58SU*A080E21**20	29,200	\$4,088
211225980	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58SU*A100E21**20	29,000	\$4,060
211225981	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58TP*A090V21**20	28,800	\$4,032
211225982	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58TP*A110V21**22	29,000	\$4,060
211225983	CARRIER	38MURAQ36AB3*	CAP**4824AL*	58TP*A135V24**22	29,000	\$4,060
211225986	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC2D080E21**20	28,800	\$4,032
211225987	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC2D100E21**20	28,800	\$4,032
211225988	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC2D100E21**22	29,200	\$4,088
211225989	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC2D120E24**20	29,000	\$4,060
211225990	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC5B080E21**20	29,200	\$4,088
211225991	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC5B100E21**20	29,000	\$4,060
211225992	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC5B100E21**22	29,200	\$4,088
211225993	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC5B120E24**22	29,200	\$4,088
211225994	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SC5B140E24**22	29,200	\$4,088
211225995	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SP6A080V21**20	29,000	\$4,060
211225996	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SP6A100V21**20	29,000	\$4,060
211225997	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SP6A120V24**22	29,000	\$4,060
211225998	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SU5A080E21**20	29,400	\$4,116
211225999	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SU5A100E21**20	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226000	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59SU5A100E21**22	29,200	\$4,088
211226001	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59TP6B080V21**20	28,800	\$4,032
211226002	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59TP6B100V21**20	29,000	\$4,060
211226003	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59TP6B100V21**22	28,800	\$4,032
211226004	CARRIER	38MURAQ36AB3*	CAP**4824AL*	59TP6B120V24**22	29,000	\$4,060
211226005	CARRIER	38MURAQ36AB3*	CAP**4824AL*	OVLAAB048112	29,000	\$4,060
211226006	CARRIER	38MURAQ36AB3*	CAP**4824AL*	OVMAAB060154	29,000	\$4,060
211226007	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58SP*A045V14**12	29,400	\$4,116
211226008	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58TP*A070V14**12	29,400	\$4,116
211226009	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	58TP*A070V17**16	29,200	\$4,088
211226011	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SC5B060E17**14	29,400	\$4,116
211226014	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SP6A060V17**14	29,400	\$4,116
211226015	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SP6A080V17**16	29,400	\$4,116
211226016	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59SU5A060E17**16	29,200	\$4,088
211226017	CARRIER	38MURAQ36AB3*	CNPV*4217AL*	59TP6B060V17**14	29,400	\$4,116
211226019	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*A090E17**14	29,400	\$4,116
211226020	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*A090E21**16	29,400	\$4,116
211226021	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58S(B,C)*A090E21**20	29,400	\$4,116
211226022	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	58SP*A045V17**16	29,400	\$4,116
211226024	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59SC5B100E21**20	29,400	\$4,116
211226025	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59TP6B060V17**14	29,600	\$4,144
211226026	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59TP6B100V21**20	29,400	\$4,116
211226027	CARRIER	38MURAQ36AB3*	CNPV*4221AL*	59TP6B100V21**22	29,400	\$4,116
211226032	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*A045E17**12	29,200	\$4,088
211226033	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*A070E17**12	29,400	\$4,116
211226034	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*A070E21**16	29,200	\$4,088
211226035	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*A090E17**14	29,200	\$4,088
211226036	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*A090E21**16	29,200	\$4,088
211226037	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*A090E21**20	29,200	\$4,088
211226038	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58S(B,C)*A110E21**20	29,200	\$4,088
211226039	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SP*A045V17**16	29,200	\$4,088
211226040	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SP*A070V17**16	29,200	\$4,088
211226041	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SP*A070V21**20	29,200	\$4,088
211226042	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SP*A090V21**20	29,200	\$4,088
211226043	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SU*A040E17**12	29,600	\$4,144
211226044	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SU*A060E17**16	29,000	\$4,060
211226045	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SU*A100E21**20	29,200	\$4,088
211226046	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58TP*A070V17**16	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226047	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58TP*A090V17**16	29,200	\$4,088
211226048	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58TP*A090V21**20	29,200	\$4,088
211226049	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58TP*A110V21**22	29,200	\$4,088
211226053	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2D060E17**14	29,200	\$4,088
211226054	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2D080E21**20	29,000	\$4,060
211226055	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2D100E21**20	29,200	\$4,088
211226056	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC2D100E21**22	29,400	\$4,116
211226057	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC5B060E17**14	29,200	\$4,088
211226058	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC5B080E17**16	29,200	\$4,088
211226059	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC5B080E21**20	29,400	\$4,116
211226060	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC5B100E21**20	29,200	\$4,088
211226061	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SC5B100E21**22	29,400	\$4,116
211226063	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SP6A060V17**14	29,200	\$4,088
211226064	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SP6A080V17**16	29,200	\$4,088
211226065	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SP6A080V21**20	29,200	\$4,088
211226066	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SP6A100V21**20	29,200	\$4,088
211226067	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SU5A060E17**16	29,200	\$4,088
211226068	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SU5A080E21**20	29,600	\$4,144
211226069	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SU5A100E21**20	29,200	\$4,088
211226070	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59SU5A100E21**22	29,400	\$4,116
211226072	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6B060V17**14	29,400	\$4,116
211226073	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6B080V21**20	29,200	\$4,088
211226074	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6B100V21**20	29,200	\$4,088
211226075	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	59TP6B100V21**22	29,200	\$4,088
211226076	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	OVLAAB036098	29,200	\$4,088
211226077	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	OVLAAB048112	29,200	\$4,088
211226078	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	OVMAAB036098	29,200	\$4,088
211226079	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	OVMAAB042112	29,200	\$4,088
211226082	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*A070E21**16	29,200	\$4,088
211226083	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*A090E21**16	29,200	\$4,088
211226084	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*A090E21**20	29,200	\$4,088
211226085	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*A090E24**20	29,200	\$4,088
211226086	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*A110E21**20	29,200	\$4,088
211226087	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*A110E24**20	29,200	\$4,088
211226088	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*A135E24**20	29,200	\$4,088
211226089	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58S(B,C)*A155E24**20	29,200	\$4,088
211226090	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58SP*A070V21**20	29,200	\$4,088
211226091	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58SP*A090V21**20	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226092	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58SP*A090V24**20	29,200	\$4,088
211226093	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58SP*A110V24**22	29,200	\$4,088
211226094	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58SU*A100E21**20	29,200	\$4,088
211226095	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58TP*A090V21**20	29,200	\$4,088
211226096	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58TP*A110V21**22	29,200	\$4,088
211226097	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58TP*A135V24**22	29,200	\$4,088
211226100	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC2D080E21**20	29,000	\$4,060
211226101	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC2D100E21**20	29,200	\$4,088
211226102	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC2D100E21**22	29,400	\$4,116
211226103	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC2D120E24**20	29,200	\$4,088
211226104	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC5B080E21**20	29,400	\$4,116
211226105	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC5B100E21**20	29,200	\$4,088
211226106	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC5B100E21**22	29,400	\$4,116
211226107	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC5B120E24**22	29,400	\$4,116
211226108	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SC5B140E24**22	29,400	\$4,116
211226109	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SP6A080V21**20	29,200	\$4,088
211226110	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SP6A100V21**20	29,200	\$4,088
211226111	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SP6A120V24**22	29,200	\$4,088
211226112	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SU5A080E21**20	29,600	\$4,144
211226113	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SU5A100E21**20	29,200	\$4,088
211226114	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59SU5A100E21**22	29,400	\$4,116
211226115	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59TP6B080V21**20	29,200	\$4,088
211226116	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59TP6B100V21**20	29,200	\$4,088
211226117	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59TP6B100V21**22	29,200	\$4,088
211226118	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	59TP6B120V24**22	29,200	\$4,088
211226119	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	OVLAAB048112	29,200	\$4,088
211226120	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	OVMAAB060154	29,200	\$4,088
211226125	CARRIER	38MURAQ36AB3*	FM(C,U)4Z36**AL*		29,600	\$4,144
211226127	CARRIER	38MURAQ36AB3*	FMA4X36**AL*		29,600	\$4,144
211226129	CARRIER	38MURAQ36AB3*	FX4DN(B,F)043L		29,000	\$4,060
211226130	CARRIER	38MURAQ36AB3*	FX4DN(B,F)049L		29,000	\$4,060
211226132	CARRIER	38MURAQ36AB3*	FV4CN(B,F)005L		28,600	\$4,004
211226133	CARRIER	38MURAQ36AB3*	CAP**3721AL*	58SU*A080E21**20	29,400	\$4,116
211226134	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC2D100E21**22	29,400	\$4,116
211226135	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SC5B100E21**22	29,200	\$4,088
211226136	CARRIER	38MURAQ36AB3*	CAP**3721AL*	59SU5A080E21**20	29,400	\$4,116
211226137	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC2D100E21**22	29,400	\$4,116
211226138	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SC5B100E21**22	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226139	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SU5A080E21**20	29,400	\$4,116
211226140	CARRIER	38MURAQ36AB3*	CAP**4321AL*	59SU5A100E21**22	29,200	\$4,088
211226141	CARRIER	38MURAQ36AB3*	CAP**4824AL*	OVLAAB060154	29,200	\$4,088
211226142	CARRIER	38MURAQ36AB3*	CNPV*4821AL*	58SU*A080E21**20	29,400	\$4,116
211226143	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	58SU*A080E21**20	29,400	\$4,116
211226144	CARRIER	38MURAQ36AB3*	CNPV*4824AL*	OVLAAB060154	29,400	\$4,116
213353777	CARRIER	38MURAQ24AB3*	F54AA*B30L*		19,100	\$2,674
213353767	CARRIER	38MURAQ24AB3*	F54AA*B24L*		19,300	\$2,702
213249268	CARRIER	38MURAQ24AB3*	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076396	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	GG96VTAB48060B**	19,400	\$2,716
213076395	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6C060V17**16	19,400	\$2,716
213076370	CARRIER	38MURAQ24AB3*	CAP**2417AL*	GG96VTAB48060B**	19,400	\$2,716
213076369	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6C060V17**16	19,400	\$2,716
213076360	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SU5B100M21**22	19,100	\$2,674
213076342	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SU5B100M21**22	19,000	\$2,660
213076114	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SU5B100M21**20	19,200	\$2,688
212989621	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SU5B080M21**20	19,100	\$2,674
212989609	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SU5B080M21**20	18,600	\$2,604
212989597	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SU5B080M21**20	19,100	\$2,674
212989249	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SU5B060M17**16	19,100	\$2,674
212989237	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SU5B060M17**16	19,100	\$2,674
212989225	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SU5B060M17**16	19,100	\$2,674
212989213	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SU5B060M17**16	19,400	\$2,716
212989201	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SU5B060M17**16	18,700	\$2,618
212989189	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SU5B060M17**16	18,900	\$2,646
212989177	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SU5B060M17**16	19,100	\$2,674
212989165	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SU5B060M17**16	19,100	\$2,674
212989153	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SU5B060M17**16	19,100	\$2,674
212989141	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SU5B060M17**16	18,600	\$2,604
212989129	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SU5B060M17**16	19,400	\$2,716
212988757	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SU5B040M17**12	19,200	\$2,688
212988745	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SU5B040M17**12	19,200	\$2,688
212988733	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SU5B040M17**12	19,200	\$2,688
212988721	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SU5B040M17**12	19,500	\$2,730
212988709	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SU5B040M17**12	18,600	\$2,604
212988697	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SU5B040M17**12	18,800	\$2,632
212988685	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SU5B040M17**12	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988673	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SU5B040M17**12	19,100	\$2,674
212988661	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SU5B040M17**12	19,200	\$2,688
212988649	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SU5B040M17**12	18,700	\$2,618
212988637	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SU5B040M17**12	19,500	\$2,730
212987819	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC6A080M21**20	19,100	\$2,674
212987807	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SC6A080M21**20	18,700	\$2,618
212987795	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC6A080M21**20	19,100	\$2,674
212987483	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC6A080M17**16	19,200	\$2,688
212987471	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC6A080M17**16	19,200	\$2,688
212987459	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC6A080M17**16	19,200	\$2,688
212987447	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC6A080M17**16	19,500	\$2,730
212987435	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SC6A080M17**16	19,800	\$2,772
212987423	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC6A080M17**16	18,800	\$2,632
212987411	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC6A080M17**16	19,000	\$2,660
212987399	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC6A080M17**16	19,100	\$2,674
212987387	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC6A080M17**16	19,200	\$2,688
212987375	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC6A080M17**16	18,700	\$2,618
212987363	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC6A080M17**16	19,400	\$2,716
212986967	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC6A060M14**12	19,200	\$2,688
212986957	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC6A060M14**12	19,200	\$2,688
212986947	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SC6A060M14**12	19,200	\$2,688
212986937	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC6A060M14**12	19,500	\$2,730
212986927	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SC6A060M14**12	19,500	\$2,730
212986917	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC6A060M14**12	18,800	\$2,632
212986907	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC6A060M14**12	19,100	\$2,674
212986897	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC6A060M14**12	19,100	\$2,674
212986887	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SC6A060M14**12	19,200	\$2,688
212986877	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC6A060M14**12	18,700	\$2,618
212986867	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC6A060M14**12	19,400	\$2,716
212986857	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SC6A060M14**12	19,400	\$2,716
212986643	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC6A040M17**12	19,100	\$2,674
212986631	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC6A040M17**12	19,100	\$2,674
212986619	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC6A040M17**12	19,100	\$2,674
212986607	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC6A040M17**12	19,700	\$2,758
211289627	CARRIER	38MURAQ60AB3*	FV4CNB006L		37,800	\$5,292
213607735	CARRIER	38MURAQ36AB3*	FG4ANXC48L*		28,800	\$4,032
213607734	CARRIER	38MURAQ36AB3*	FT4BN(B,X)C48L*		28,800	\$4,032
213607720	CARRIER	38MURAQ36AB3*	FG4ANXC36L*		29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213607719	CARRIER	38MURAQ36AB3*	FT4BN(B,X)C36L*		29,400	\$4,116
213607675	CARRIER	38MURAQ30AB3*	FG4ANXC36L*		23,600	\$3,304
213607674	CARRIER	38MURAQ30AB3*	FT4BN(B,X)C36L*		23,600	\$3,304
213607645	CARRIER	38MURAQ24AB3*	FG4ANXB24L*		19,300	\$2,702
213607644	CARRIER	38MURAQ24AB3*	FT4BNXB24L*		19,300	\$2,702
213607630	CARRIER	38MURAQ24AB3*	FG4ANXC36L*		19,100	\$2,674
213607629	CARRIER	38MURAQ24AB3*	FT4BN(B,X)C36L*		19,100	\$2,674
213607585	CARRIER	38MURAQ18AB3*	FG4ANXB24L*		12,400	\$1,736
213607584	CARRIER	38MURAQ18AB3*	FT4BNXB24L*		12,400	\$1,736
212986595	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SC6A040M17**12	18,800	\$2,632
212986583	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC6A040M17**12	19,000	\$2,660
212986571	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC6A040M17**12	19,200	\$2,688
212986559	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC6A040M17**12	19,200	\$2,688
212986547	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC6A040M17**12	19,200	\$2,688
212986535	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC6A040M17**12	18,900	\$2,646
212986523	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC6A040M17**12	19,500	\$2,730
212986259	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC6A040M14**10	19,200	\$2,688
212986151	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC6A040M14**10	18,800	\$2,632
212986139	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC6A040M14**10	19,500	\$2,730
212986127	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SC6A040M14**10	19,500	\$2,730
212985863	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC6A026M14**10	19,000	\$2,660
212985853	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC6A026M14**10	19,000	\$2,660
212985843	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SC6A026M14**10	19,100	\$2,674
212985833	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC6A026M14**10	19,500	\$2,730
212985823	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SC6A026M14**10	19,500	\$2,730
212985813	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC6A026M14**10	18,800	\$2,632
212985803	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC6A026M14**10	19,100	\$2,674
212985793	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC6A026M14**10	19,100	\$2,674
212985783	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SC6A026M14**10	19,200	\$2,688
212985773	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC6A026M14**10	18,700	\$2,618
212985763	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC6A026M14**10	19,500	\$2,730
212985753	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SC6A026M14**10	19,500	\$2,730
212985359	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2E100M21**20	19,100	\$2,674
212985347	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SC2E100M21**20	18,700	\$2,618
212985335	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2E100M21**20	19,100	\$2,674
212985049	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2E080M21**20	19,000	\$2,660
212985039	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SC2E080M21**20	18,900	\$2,646
212985029	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2E080M21**20	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984685	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2E080M17**16	19,100	\$2,674
212984673	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC2E080M17**16	19,100	\$2,674
212984661	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC2E080M17**16	19,100	\$2,674
212984649	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC2E080M17**16	19,500	\$2,730
212984637	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SC2E080M17**16	18,400	\$2,576
212984625	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC2E080M17**16	18,900	\$2,646
212984613	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2E080M17**16	19,000	\$2,660
212984601	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC2E080M17**16	19,000	\$2,660
212984589	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC2E080M17**16	19,100	\$2,674
212984577	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC2E080M17**16	18,500	\$2,590
212984565	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC2E080M17**16	19,300	\$2,702
212984145	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2E060M17**14	19,100	\$2,674
212984133	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC2E060M17**14	19,100	\$2,674
212984121	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC2E060M17**14	19,100	\$2,674
212984109	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC2E060M17**14	19,400	\$2,716
212984097	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SC2E060M17**14	18,700	\$2,618
212984085	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC2E060M17**14	18,900	\$2,646
212984073	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2E060M17**14	19,100	\$2,674
212984061	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC2E060M17**14	19,100	\$2,674
212984049	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC2E060M17**14	19,100	\$2,674
212984037	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC2E060M17**14	18,700	\$2,618
212984025	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC2E060M17**14	19,400	\$2,716
212983616	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC2E060M14**12	19,200	\$2,688
212983606	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC2E060M14**12	19,200	\$2,688
212983596	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SC2E060M14**12	19,200	\$2,688
212983586	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC2E060M14**12	19,500	\$2,730
212983576	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SC2E060M14**12	19,500	\$2,730
212983566	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC2E060M14**12	19,000	\$2,660
212983556	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC2E060M14**12	19,200	\$2,688
212983546	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC2E060M14**12	19,200	\$2,688
212983536	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SC2E060M14**12	19,200	\$2,688
212983526	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC2E060M14**12	18,800	\$2,632
212983516	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC2E060M14**12	19,500	\$2,730
212983506	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SC2E060M14**12	19,500	\$2,730
212983239	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2E040M17**12	19,200	\$2,688
212983228	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC2E040M17**12	19,200	\$2,688
212983217	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC2E040M17**12	19,200	\$2,688
212983206	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC2E040M17**12	19,600	\$2,744

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983195	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SC2E040M17**12	18,800	\$2,632
212983184	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC2E040M17**12	19,000	\$2,660
212983173	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2E040M17**12	19,200	\$2,688
212983162	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC2E040M17**12	19,200	\$2,688
212983151	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC2E040M17**12	19,300	\$2,702
212983140	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC2E040M17**12	18,800	\$2,632
212983129	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC2E040M17**12	19,500	\$2,730
212981006	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*B110M21**20	19,100	\$2,674
212980994	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58S(B,C)*B110M21**20	18,800	\$2,632
212980982	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*B110M21**20	19,000	\$2,660
212980596	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*B090M21**20	19,100	\$2,674
212980585	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58S(B,C)*B090M21**20	18,600	\$2,604
212980574	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*B090M21**20	19,100	\$2,674
212980277	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*B090M21**16	19,100	\$2,674
212980266	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58S(B,C)*B090M21**16	18,600	\$2,604
212980255	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*B090M21**16	19,000	\$2,660
212979929	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*B090M17**14	19,100	\$2,674
212979917	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*B090M17**14	19,100	\$2,674
212979905	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*B090M17**14	19,100	\$2,674
212979893	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*B090M17**14	19,500	\$2,730
212979881	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58S(B,C)*B090M17**14	18,700	\$2,618
212979869	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58S(B,C)*B090M17**14	18,700	\$2,618
212979857	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*B090M17**14	19,100	\$2,674
212979845	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*B090M17**14	19,100	\$2,674
212979833	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*B090M17**14	19,100	\$2,674
212979821	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58S(B,C)*B090M17**14	18,600	\$2,604
212979809	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*B090M17**14	19,400	\$2,716
212979511	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*B070M21**16	19,200	\$2,688
212979501	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58S(B,C)*B070M21**16	18,600	\$2,604
212979491	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*B070M21**16	19,100	\$2,674
212979239	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*B070M17**16	19,100	\$2,674
212979227	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*B070M17**16	19,100	\$2,674
212979215	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*B070M17**16	19,100	\$2,674
212979203	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*B070M17**16	19,400	\$2,716
212979191	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58S(B,C)*B070M17**16	18,700	\$2,618
212979179	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58S(B,C)*B070M17**16	18,700	\$2,618
212979167	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*B070M17**16	19,100	\$2,674
212979155	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*B070M17**16	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979143	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*B070M17**16	19,100	\$2,674
212979131	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58S(B,C)*B070M17**16	18,700	\$2,618
212978642	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*B070M17**12	19,000	\$2,660
212978631	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58S(B,C)*B070M17**12	18,600	\$2,604
212978620	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*B070M17**12	19,400	\$2,716
212978210	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*B070M14**12	19,000	\$2,660
212978198	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*B070M14**12	19,000	\$2,660
212978186	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58S(B,C)*B070M14**12	19,100	\$2,674
212978174	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*B070M14**12	19,400	\$2,716
212978162	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58S(B,C)*B070M14**12	19,400	\$2,716
212978150	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58S(B,C)*B070M14**12	18,700	\$2,618
212978138	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*B070M14**12	19,000	\$2,660
212978126	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*B070M14**12	19,100	\$2,674
212978114	CARRIER	38MURAQ24AB3*	CAP**3014AL*	58S(B,C)*B070M14**12	19,100	\$2,674
212978102	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58S(B,C)*B070M14**12	18,600	\$2,604
212978090	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*B070M14**12	19,400	\$2,716
212978078	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58S(B,C)*B070M14**12	19,300	\$2,702
212977694	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*B045M14**12	19,100	\$2,674
212977682	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*B045M14**12	19,100	\$2,674
212977670	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58S(B,C)*B045M14**12	19,000	\$2,660
212977658	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*B045M14**12	19,500	\$2,730
212977646	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58S(B,C)*B045M14**12	19,500	\$2,730
212977634	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58S(B,C)*B045M14**12	18,700	\$2,618
212977622	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*B045M14**12	19,100	\$2,674
212977610	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*B045M14**12	19,100	\$2,674
212977598	CARRIER	38MURAQ24AB3*	CAP**3014AL*	58S(B,C)*B045M14**12	19,100	\$2,674
212977586	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58S(B,C)*B045M14**12	18,700	\$2,618
212977574	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*B045M14**12	19,400	\$2,716
212977562	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58S(B,C)*B045M14**12	19,400	\$2,716
212976998	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6C100V21**22	19,200	\$2,688
212976978	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6C100V21**22	19,100	\$2,674
212976689	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	GG96VTAB60100C**	19,100	\$2,674
212976688	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6C100V21**20	19,100	\$2,674
212976676	CARRIER	38MURAQ24AB3*	CAP**3721AL*	GG96VTAB60100C**	18,600	\$2,604
212976675	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59TP6C100V21**20	18,600	\$2,604
212976663	CARRIER	38MURAQ24AB3*	CAP**3621AL*	GG96VTAB60100C**	19,000	\$2,660
212976662	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6C100V21**20	19,000	\$2,660
212976413	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6C080V21**20	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976399	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59TP6C080V21**20	18,600	\$2,604
212976386	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6C080V21**20	19,100	\$2,674
212976123	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	GG96VTAB48080B**	18,900	\$2,646
212976122	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6C080V17**16	18,900	\$2,646
212976110	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	GG96VTAB48080B**	18,900	\$2,646
212976109	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59TP6C080V17**16	18,900	\$2,646
212976097	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	GG96VTAB48080B**	18,900	\$2,646
212976096	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59TP6C080V17**16	18,900	\$2,646
212976084	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	GG96VTAB48080B**	19,500	\$2,730
212976083	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6C080V17**16	19,500	\$2,730
212976058	CARRIER	38MURAQ24AB3*	CAP**3717AL*	GG96VTAB48080B**	19,000	\$2,660
212976057	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59TP6C080V17**16	19,000	\$2,660
212976045	CARRIER	38MURAQ24AB3*	CAP**3621AL*	GG96VTAB48080B**	19,000	\$2,660
212976044	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6C080V17**16	19,000	\$2,660
212976032	CARRIER	38MURAQ24AB3*	CAP**3617AL*	GG96VTAB48080B**	19,000	\$2,660
212976031	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59TP6C080V17**16	19,000	\$2,660
212976019	CARRIER	38MURAQ24AB3*	CAP**3017AL*	GG96VTAB48080B**	19,100	\$2,674
212976018	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59TP6C080V17**16	19,100	\$2,674
212976006	CARRIER	38MURAQ24AB3*	CAP**2517AL*	GG96VTAB48080B**	18,800	\$2,632
212976005	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59TP6C080V17**16	18,800	\$2,632
212975993	CARRIER	38MURAQ24AB3*	CAP**2417AL*	GG96VTAB48080B**	19,500	\$2,730
212975992	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6C080V17**16	19,500	\$2,730
212975749	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59TP6C060V14**12	19,100	\$2,674
212975738	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59TP6C060V14**12	19,100	\$2,674
212975727	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59TP6C060V14**12	19,000	\$2,660
212975716	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6C060V14**12	19,500	\$2,730
212975705	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59TP6C060V14**12	19,500	\$2,730
212975694	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59TP6C060V14**12	18,800	\$2,632
212975683	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59TP6C060V14**12	19,100	\$2,674
212975672	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59TP6C060V14**12	19,100	\$2,674
212975661	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59TP6C060V14**12	19,100	\$2,674
212975650	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59TP6C060V14**12	18,600	\$2,604
212975639	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6C060V14**12	19,400	\$2,716
212975628	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59TP6C060V14**12	19,400	\$2,716
212975364	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6C040V17**12	19,200	\$2,688
212975353	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59TP6C040V17**12	19,200	\$2,688
212975342	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59TP6C040V17**12	19,200	\$2,688
212975331	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6C040V17**12	19,600	\$2,744

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975320	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59TP6C040V17**12	18,900	\$2,646
212975309	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59TP6C040V17**12	18,900	\$2,646
212975298	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6C040V17**12	19,100	\$2,674
212975287	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59TP6C040V17**12	19,100	\$2,674
212975276	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59TP6C040V17**12	19,200	\$2,688
212975265	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59TP6C040V17**12	18,800	\$2,632
212975254	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6C040V17**12	19,500	\$2,730
212975055	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	GG96VTAB30040A**	19,200	\$2,688
212975054	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59TP6C040V14**10	19,200	\$2,688
212975042	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	GG96VTAB30040A**	19,200	\$2,688
212975041	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59TP6C040V14**10	19,200	\$2,688
212975029	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	GG96VTAB30040A**	19,100	\$2,674
212975028	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59TP6C040V14**10	19,100	\$2,674
212975016	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	GG96VTAB30040A**	19,600	\$2,744
212975015	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6C040V14**10	19,600	\$2,744
212975003	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	GG96VTAB30040A**	19,600	\$2,744
212975002	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59TP6C040V14**10	19,600	\$2,744
212974990	CARRIER	38MURAQ24AB3*	CAP**3717AL*	GG96VTAB30040A**	18,800	\$2,632
212974989	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59TP6C040V14**10	18,800	\$2,632
212974977	CARRIER	38MURAQ24AB3*	CAP**3617AL*	GG96VTAB30040A**	19,200	\$2,688
212974976	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59TP6C040V14**10	19,200	\$2,688
212974964	CARRIER	38MURAQ24AB3*	CAP**3017AL*	GG96VTAB30040A**	19,200	\$2,688
212974963	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59TP6C040V14**10	19,200	\$2,688
212974951	CARRIER	38MURAQ24AB3*	CAP**3014AL*	GG96VTAB30040A**	19,200	\$2,688
212974950	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59TP6C040V14**10	19,200	\$2,688
212974938	CARRIER	38MURAQ24AB3*	CAP**2517AL*	GG96VTAB30040A**	18,700	\$2,618
212974937	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59TP6C040V14**10	18,700	\$2,618
212974925	CARRIER	38MURAQ24AB3*	CAP**2417AL*	GG96VTAB30040A**	19,500	\$2,730
212974924	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6C040V14**10	19,500	\$2,730
212974912	CARRIER	38MURAQ24AB3*	CAP**2414AL*	GG96VTAB30040A**	19,500	\$2,730
212974911	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59TP6C040V14**10	19,500	\$2,730
212974322	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SP6B100V21**20	18,900	\$2,646
212974312	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SP6B100V21**20	19,000	\$2,660
212974112	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SP6B080V21**20	19,200	\$2,688
212974102	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SP6B080V21**20	18,600	\$2,604
212974092	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SP6B080V21**20	19,100	\$2,674
212973922	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SP6B080V17**16	18,900	\$2,646
212973912	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SP6B080V17**16	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973902	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SP6B080V17**16	18,900	\$2,646
212973892	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SP6B080V17**16	19,500	\$2,730
212973872	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SP6B080V17**16	19,000	\$2,660
212973862	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SP6B080V17**16	19,000	\$2,660
212973852	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SP6B080V17**16	19,000	\$2,660
212973842	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SP6B080V17**16	19,100	\$2,674
212973832	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SP6B080V17**16	18,800	\$2,632
212973822	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SP6B080V17**16	19,500	\$2,730
212973632	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SP6B060V14**12	19,100	\$2,674
212973622	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SP6B060V14**12	19,100	\$2,674
212973612	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SP6B060V14**12	19,000	\$2,660
212973602	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SP6B060V14**12	19,500	\$2,730
212973592	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SP6B060V14**12	19,500	\$2,730
212973582	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SP6B060V14**12	18,800	\$2,632
212973572	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SP6B060V14**12	19,100	\$2,674
212973562	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SP6B060V14**12	19,100	\$2,674
212973552	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SP6B060V14**12	19,100	\$2,674
212973542	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SP6B060V14**12	18,600	\$2,604
212973532	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SP6B060V14**12	19,400	\$2,716
212973522	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SP6B060V14**12	19,400	\$2,716
212973282	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SP6B040V17**12	19,200	\$2,688
212973272	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SP6B040V17**12	19,200	\$2,688
212973262	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SP6B040V17**12	19,200	\$2,688
212973252	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SP6B040V17**12	19,600	\$2,744
212973242	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SP6B040V17**12	18,900	\$2,646
212973232	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SP6B040V17**12	18,900	\$2,646
212973222	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SP6B040V17**12	19,100	\$2,674
212973212	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SP6B040V17**12	19,100	\$2,674
212973202	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SP6B040V17**12	19,200	\$2,688
212973192	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SP6B040V17**12	18,800	\$2,632
212973182	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SP6B040V17**12	19,500	\$2,730
212973002	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SP6B040V14**10	19,200	\$2,688
212972992	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SP6B040V14**10	19,200	\$2,688
212972982	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SP6B040V14**10	19,200	\$2,688
212972972	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SP6B040V14**10	19,500	\$2,730
212972962	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SP6B040V14**10	19,500	\$2,730
212972952	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SP6B040V14**10	19,000	\$2,660
212972942	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SP6B040V14**10	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972932	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SP6B040V14**10	19,200	\$2,688
212972922	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SP6B040V14**10	19,200	\$2,688
212972912	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SP6B040V14**10	18,800	\$2,632
212972902	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SP6B040V14**10	19,500	\$2,730
212972892	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SP6B040V14**10	19,500	\$2,730
212972422	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58TP*B110V21**22	19,200	\$2,688
212972410	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58TP*B110V21**22	18,800	\$2,632
212972398	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58TP*B110V21**22	19,100	\$2,674
212972142	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58TP*B090V21**20	19,100	\$2,674
212972131	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58TP*B090V21**20	18,900	\$2,646
212972120	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58TP*B090V21**20	19,100	\$2,674
212972015	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58TP*B090V17**16	19,100	\$2,674
212972011	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58TP*B090V17**16	19,100	\$2,674
212972007	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58TP*B090V17**16	19,100	\$2,674
212972003	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58TP*B090V17**16	19,500	\$2,730
212971999	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58TP*B090V17**16	18,600	\$2,604
212971995	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58TP*B090V17**16	18,800	\$2,632
212971991	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58TP*B090V17**16	19,000	\$2,660
212971987	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58TP*B090V17**16	19,000	\$2,660
212971983	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58TP*B090V17**16	19,100	\$2,674
212971979	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58TP*B090V17**16	18,700	\$2,618
212971975	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58TP*B090V17**16	19,400	\$2,716
212971731	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58TP*B070V17**16	19,100	\$2,674
212971720	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58TP*B070V17**16	19,100	\$2,674
212971709	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58TP*B070V17**16	19,100	\$2,674
212971698	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58TP*B070V17**16	19,500	\$2,730
212971687	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58TP*B070V17**16	18,700	\$2,618
212971676	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58TP*B070V17**16	18,700	\$2,618
212971665	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58TP*B070V17**16	19,100	\$2,674
212971654	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58TP*B070V17**16	19,100	\$2,674
212971643	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58TP*B070V17**16	19,100	\$2,674
212971632	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58TP*B070V17**16	18,600	\$2,604
212971621	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58TP*B070V17**16	19,400	\$2,716
212971416	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58TP*B070V14**12	19,100	\$2,674
212971414	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58TP*B070V14**12	19,100	\$2,674
212971412	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58TP*B070V14**12	19,100	\$2,674
212971410	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58TP*B070V14**12	19,400	\$2,716
212971408	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58TP*B070V14**12	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971406	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58TP*B070V14**12	18,700	\$2,618
212971404	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58TP*B070V14**12	19,100	\$2,674
212971402	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58TP*B070V14**12	19,100	\$2,674
212971400	CARRIER	38MURAQ24AB3*	CAP**3014AL*	58TP*B070V14**12	19,000	\$2,660
212971398	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58TP*B070V14**12	18,600	\$2,604
212971396	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58TP*B070V14**12	19,400	\$2,716
212971394	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58TP*B070V14**12	19,400	\$2,716
212971242	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58TP*B045V14**12	19,100	\$2,674
212971230	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58TP*B045V14**12	19,100	\$2,674
212971218	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58TP*B045V14**12	19,000	\$2,660
212971206	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58TP*B045V14**12	19,500	\$2,730
212971194	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58TP*B045V14**12	19,500	\$2,730
212971182	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58TP*B045V14**12	18,700	\$2,618
212971170	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58TP*B045V14**12	19,000	\$2,660
212971158	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58TP*B045V14**12	19,100	\$2,674
212969836	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58SP*B045V14**12	19,100	\$2,674
212969826	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58SP*B045V14**12	19,100	\$2,674
212969816	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58SP*B045V14**12	19,000	\$2,660
212969806	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58SP*B045V14**12	19,500	\$2,730
212969796	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58SP*B045V14**12	19,500	\$2,730
212969786	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58SP*B045V14**12	18,700	\$2,618
212969776	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58SP*B045V14**12	19,000	\$2,660
212969766	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58SP*B045V14**12	19,100	\$2,674
212969756	CARRIER	38MURAQ24AB3*	CAP**3014AL*	58SP*B045V14**12	19,100	\$2,674
212969746	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58SP*B045V14**12	18,500	\$2,590
212969736	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58SP*B045V14**12	19,300	\$2,702
211727050	CARRIER	38MURAQ24AB3*	PF4MN*B24L*		19,200	\$2,688
211246026	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	GG96VTAA42060B	19,100	\$2,674
211246025	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	GG96VTAA48080B	19,100	\$2,674
211246024	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	GG96VTAA60100C	18,900	\$2,646
211246023	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	GG96VTAA42060B	19,100	\$2,674
211246022	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	GG96VTAA30040A	19,000	\$2,660
211246021	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	GG96VTAA48080B	19,100	\$2,674
211246020	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	GG96VTAA42060B	19,100	\$2,674
211246019	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	GG96VTAA30040A	19,000	\$2,660
211246018	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	GG96VTAA48080B	19,100	\$2,674
211246017	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	GG96VTAA30040A	19,100	\$2,674
211246016	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	GG96VTAA42060B	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211246015	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	GG96VTAA30040A	19,500	\$2,730
211246014	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	GG96VTAA48080B	19,500	\$2,730
211246013	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	GG96VTAA30040A	19,500	\$2,730
211246010	CARRIER	38MURAQ24AB3*	CAP**3721AL*	GG96VTAA60100C	18,400	\$2,576
211246009	CARRIER	38MURAQ24AB3*	CAP**3717AL*	GG96VTAA42060B	18,900	\$2,646
211246008	CARRIER	38MURAQ24AB3*	CAP**3717AL*	GG96VTAA30040A	18,900	\$2,646
211246007	CARRIER	38MURAQ24AB3*	CAP**3717AL*	GG96VTAA48080B	18,900	\$2,646
211246006	CARRIER	38MURAQ24AB3*	CAP**3621AL*	GG96VTAA42060B	19,100	\$2,674
211246005	CARRIER	38MURAQ24AB3*	CAP**3621AL*	GG96VTAA48080B	19,100	\$2,674
211246004	CARRIER	38MURAQ24AB3*	CAP**3621AL*	GG96VTAA60100C	18,900	\$2,646
211246003	CARRIER	38MURAQ24AB3*	CAP**3617AL*	GG96VTAA42060B	19,100	\$2,674
211246002	CARRIER	38MURAQ24AB3*	CAP**3617AL*	GG96VTAA30040A	18,900	\$2,646
211246001	CARRIER	38MURAQ24AB3*	CAP**3617AL*	GG96VTAA48080B	19,100	\$2,674
211246000	CARRIER	38MURAQ24AB3*	CAP**3017AL*	GG96VTAA42060B	19,100	\$2,674
211245999	CARRIER	38MURAQ24AB3*	CAP**3017AL*	GG96VTAA30040A	19,000	\$2,660
211245998	CARRIER	38MURAQ24AB3*	CAP**3017AL*	GG96VTAA48080B	19,200	\$2,688
211245997	CARRIER	38MURAQ24AB3*	CAP**3014AL*	GG96VTAA30040A	19,100	\$2,674
211245993	CARRIER	38MURAQ24AB3*	CAP**2417AL*	GG96VTAA42060B	19,400	\$2,716
211245992	CARRIER	38MURAQ24AB3*	CAP**2417AL*	GG96VTAA30040A	19,400	\$2,716
211245991	CARRIER	38MURAQ24AB3*	CAP**2417AL*	GG96VTAA48080B	19,400	\$2,716
211245990	CARRIER	38MURAQ24AB3*	CAP**2414AL*	GG96VTAA30040A	19,400	\$2,716
213372207	CARRIER	38MURAQ30AB3	40MULAQ36XCX + CI		22,600	\$3,164
211240226	CARRIER	38MURAQ24AB3*	FV4CN(B,F)003L		19,000	\$2,660
211240225	CARRIER	38MURAQ24AB3*	FV4CNF002L		19,000	\$2,660
211240224	CARRIER	38MURAQ24AB3*	FM(C,U)4Z36**AL*		19,300	\$2,702
211240223	CARRIER	38MURAQ24AB3*	FM(C,U)4Z30**AL*		19,300	\$2,702
211240222	CARRIER	38MURAQ24AB3*	FM(C,U)4Z24**AL*		19,500	\$2,730
211240221	CARRIER	38MURAQ24AB3*	FM(C,U)4X36**AL*		19,900	\$2,786
211240220	CARRIER	38MURAQ24AB3*	FM(C,U)4X30**AL*		19,900	\$2,786
211240219	CARRIER	38MURAQ24AB3*	FMA4X36**AL*		19,600	\$2,744
211240218	CARRIER	38MURAQ24AB3*	FMA4X30**AL*		19,600	\$2,744
211240217	CARRIER	38MURAQ24AB3*	FMA4X24**AL*		19,600	\$2,744
211240215	CARRIER	38MURAQ24AB3*	FMA4P24**AL*		19,900	\$2,786
211240214	CARRIER	38MURAQ24AB3*	FX4DN(B,F)037L		18,500	\$2,590
211240213	CARRIER	38MURAQ24AB3*	FX4DNF031L		19,100	\$2,674
211240212	CARRIER	38MURAQ24AB3*	FX4DNF025L		19,100	\$2,674
211240211	CARRIER	38MURAQ24AB3*	FB4CNP030L		19,100	\$2,674
211240210	CARRIER	38MURAQ24AB3*	FB4CNP025L		19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240209	CARRIER	38MURAQ24AB3*	FB4CNF030L		19,100	\$2,674
211240208	CARRIER	38MURAQ24AB3*	FZ4ANP036L		19,000	\$2,660
211240207	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	OVLAAB048112	19,300	\$2,702
211240206	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	OVMAAB042112	19,200	\$2,688
211240205	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	OVLAAB036098	18,900	\$2,646
211240204	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	OVMAAB036098	19,000	\$2,660
211240203	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SU*A060E17**16	19,300	\$2,702
211240202	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SU*A080E21**20	19,100	\$2,674
211240201	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2D040E17**12	19,100	\$2,674
211240200	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC5B080E17**16	19,500	\$2,730
211240199	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC5B060E17**14	19,400	\$2,716
211240198	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2D100E21**20	19,300	\$2,702
211240197	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2D080E21**20	19,300	\$2,702
211240196	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2D080E17**16	19,100	\$2,674
211240195	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC2D060E17**14	19,100	\$2,674
211240194	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*A110E21**20	19,400	\$2,716
211240193	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*A090E21**20	19,300	\$2,702
211240192	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*A090E17**14	19,200	\$2,688
211240191	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*A070E21**16	19,100	\$2,674
211240190	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*A070E17**12	19,200	\$2,688
211240189	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*A045E17**12	19,100	\$2,674
211240188	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58TP*A110V21**22	19,000	\$2,660
211240187	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6B100V21**20	19,000	\$2,660
211240186	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6B080V21**20	18,900	\$2,646
211240185	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6B060V17**14	19,100	\$2,674
211240184	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC5B040E17**12	19,400	\$2,716
211240183	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58TP*A070V17**16	19,100	\$2,674
211240182	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6B080V17**16	19,100	\$2,674
211240181	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SC5B080E21**20	19,300	\$2,702
211240180	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6B040V17**12	19,000	\$2,660
211240179	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58TP*A090V21**20	19,000	\$2,660
211240178	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58TP*A090V17**16	19,000	\$2,660
211240177	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SU*A040E17**12	19,000	\$2,660
211240176	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SU5A060E17**16	19,100	\$2,674
211240175	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SP*A090V21**20	19,000	\$2,660
211240174	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SP*A070V21**20	19,300	\$2,702
211240173	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SP*A070V17**16	19,000	\$2,660
211240172	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58SP*A045V17**16	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240167	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59TP6B100V21**22	18,900	\$2,646
211240166	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*A070E17**16	19,400	\$2,716
211240165	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SU5A040E17**12	19,000	\$2,660
211240164	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SP6A080V17**16	19,100	\$2,674
211240163	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SP6A040V17**12	19,000	\$2,660
211240162	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SP6A100V21**20	19,000	\$2,660
211240161	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SP6A080V21**20	19,000	\$2,660
211240160	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	59SP6A060V17**14	18,900	\$2,646
211240156	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	OVMAAB042112	19,200	\$2,688
211240155	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	OVLAAB036098	18,900	\$2,646
211240154	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	OVMAAB036098	19,000	\$2,660
211240153	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58SU*A060E17**16	19,300	\$2,702
211240152	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*A070E14**12	19,100	\$2,674
211240151	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC2D040E17**12	19,100	\$2,674
211240150	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC2D040E14**10	19,400	\$2,716
211240149	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC5B080E17**16	19,500	\$2,730
211240148	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC5B060E17**14	19,400	\$2,716
211240147	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC2D080E17**16	19,100	\$2,674
211240146	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC2D060E17**14	19,100	\$2,674
211240145	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC2D060E14**12	18,900	\$2,646
211240144	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*A090E17**14	19,200	\$2,688
211240143	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*A070E17**12	19,200	\$2,688
211240142	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*A045E17**12	19,100	\$2,674
211240141	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*A045E14**12	19,300	\$2,702
211240140	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59TP6B060V17**14	19,100	\$2,674
211240139	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC5B026E14**10	18,900	\$2,646
211240138	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59TP6B060V14**12	19,000	\$2,660
211240137	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59TP6B040V14**10	19,000	\$2,660
211240136	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC5B060E14**12	19,400	\$2,716
211240135	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC5B040E17**12	19,400	\$2,716
211240134	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SC5B040E14**10	19,500	\$2,730
211240133	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58TP*A070V17**16	19,100	\$2,674
211240132	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59TP6B080V17**16	19,100	\$2,674
211240131	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59TP6B040V17**12	19,000	\$2,660
211240130	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58TP*A090V17**16	19,000	\$2,660
211240129	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58TP*A070V14**12	19,100	\$2,674
211240128	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58TP*A045V14**12	19,100	\$2,674
211240127	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58SU*A040E17**12	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240126	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SU5A060E17**16	19,100	\$2,674
211240125	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58SP*A070V17**16	19,000	\$2,660
211240124	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58SP*A045V17**16	19,200	\$2,688
211240121	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*A070E17**16	19,400	\$2,716
211240120	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SU5A040E17**12	19,000	\$2,660
211240119	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SP6A080V17**16	19,100	\$2,674
211240118	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SP6A060V14**12	19,000	\$2,660
211240117	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SP6A040V17**12	19,000	\$2,660
211240116	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SP6A040V14**10	19,000	\$2,660
211240115	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	59SP6A060V17**14	18,900	\$2,646
211240113	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58SP*A045V14**12	18,900	\$2,646
211240112	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	OVMAAB042112	19,200	\$2,688
211240111	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	OVLAAB036098	18,900	\$2,646
211240110	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	OVMAAB036098	19,000	\$2,660
211240109	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58SU*A060E17**16	19,300	\$2,702
211240108	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*A070E14**12	19,100	\$2,674
211240107	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC2D040E17**12	19,100	\$2,674
211240106	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC2D040E14**10	19,400	\$2,716
211240105	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC5B080E17**16	19,500	\$2,730
211240104	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC5B060E17**14	19,400	\$2,716
211240103	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC2D080E17**16	19,100	\$2,674
211240102	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC2D060E17**14	19,100	\$2,674
211240101	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC2D060E14**12	18,900	\$2,646
211240100	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*A090E17**14	19,200	\$2,688
211240099	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*A070E17**12	19,200	\$2,688
211240098	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*A045E17**12	19,100	\$2,674
211240097	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*A045E14**12	19,300	\$2,702
211240096	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59TP6B060V17**14	19,100	\$2,674
211240095	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC5B026E14**10	18,900	\$2,646
211240094	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59TP6B060V14**12	19,000	\$2,660
211240093	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59TP6B040V14**10	19,000	\$2,660
211240092	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC5B060E14**12	19,400	\$2,716
211240091	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC5B040E17**12	19,400	\$2,716
211240090	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC5B040E14**10	19,500	\$2,730
211240089	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58TP*A070V17**16	19,100	\$2,674
211240088	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59TP6B080V17**16	19,100	\$2,674
211240087	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59TP6B040V17**12	19,000	\$2,660
211240086	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58TP*A090V17**16	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240085	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58TP*A070V14**12	19,100	\$2,674
211240084	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58TP*A045V14**12	19,100	\$2,674
211240083	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58SU*A040E17**12	19,000	\$2,660
211240082	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SU5A060E17**16	19,100	\$2,674
211240081	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58SP*A070V17**16	19,000	\$2,660
211240080	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58SP*A045V17**16	19,200	\$2,688
211240077	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*A070E17**16	19,400	\$2,716
211240076	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SU5A040E17**12	19,000	\$2,660
211240075	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SP6A080V17**16	19,100	\$2,674
211240074	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SP6A060V14**12	19,000	\$2,660
211240073	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SP6A040V17**12	19,000	\$2,660
211240072	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SP6A040V14**10	19,000	\$2,660
211240071	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SP6A060V17**14	18,900	\$2,646
211240069	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58SP*A045V14**12	18,900	\$2,646
211240068	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58S(B,C)*A070E14**12	19,100	\$2,674
211240067	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SC2D040E14**10	19,400	\$2,716
211240066	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SC2D060E14**12	18,900	\$2,646
211240065	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58S(B,C)*A045E14**12	19,300	\$2,702
211240064	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SC5B026E14**10	19,500	\$2,730
211240063	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59TP6B060V14**12	19,000	\$2,660
211240062	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59TP6B040V14**10	19,100	\$2,674
211240061	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SC5B060E14**12	19,400	\$2,716
211240060	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SC5B040E14**10	19,500	\$2,730
211240059	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58TP*A070V14**12	19,100	\$2,674
211240058	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58TP*A045V14**12	19,100	\$2,674
211240057	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SP6A060V14**12	19,000	\$2,660
211240056	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SP6A040V14**10	19,100	\$2,674
211240055	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	58SP*A045V14**12	19,200	\$2,688
211240054	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	OVMAAB042112	19,700	\$2,758
211240053	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	OVLAAB036098	19,300	\$2,702
211240052	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	OVMAAB036098	19,400	\$2,716
211240051	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58SU*A060E17**16	19,600	\$2,744
211240050	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*A070E14**12	19,500	\$2,730
211240049	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC2D040E17**12	19,500	\$2,730
211240048	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC2D040E14**10	19,700	\$2,758
211240047	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC5B080E17**16	19,800	\$2,772
211240046	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC5B060E17**14	19,700	\$2,758
211240045	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC2D080E17**16	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240044	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC2D060E17**14	19,500	\$2,730
211240043	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC2D060E14**12	19,600	\$2,744
211240042	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*A090E17**14	19,500	\$2,730
211240041	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*A070E17**12	19,500	\$2,730
211240040	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*A045E17**12	19,400	\$2,716
211240039	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*A045E14**12	19,600	\$2,744
211240038	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6B060V17**14	19,400	\$2,716
211240037	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC5B026E14**10	19,900	\$2,786
211240036	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6B060V14**12	19,300	\$2,702
211240035	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6B040V14**10	19,500	\$2,730
211240034	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC5B060E14**12	19,700	\$2,758
211240033	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC5B040E17**12	19,700	\$2,758
211240032	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC5B040E14**10	19,800	\$2,772
211240031	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58TP*A070V17**16	19,400	\$2,716
211240030	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6B080V17**16	19,500	\$2,730
211240029	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59TP6B040V17**12	19,700	\$2,758
211240028	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58TP*A090V17**16	19,300	\$2,702
211240027	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58TP*A070V14**12	19,500	\$2,730
211240026	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58TP*A045V14**12	19,500	\$2,730
211240025	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58SU*A040E17**12	19,300	\$2,702
211240024	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SU5A060E17**16	19,400	\$2,716
211240023	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58SP*A070V17**16	19,400	\$2,716
211240022	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58SP*A045V17**16	19,500	\$2,730
211240019	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*A070E17**16	19,700	\$2,758
211240018	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SU5A040E17**12	19,300	\$2,702
211240017	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SP6A080V17**16	19,500	\$2,730
211240016	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SP6A060V14**12	19,300	\$2,702
211240015	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SP6A040V17**12	19,700	\$2,758
211240014	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SP6A040V14**10	19,500	\$2,730
211240013	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SP6A060V17**14	19,500	\$2,730
211240011	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58SP*A045V14**12	19,500	\$2,730
211240010	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58S(B,C)*A070E14**12	19,500	\$2,730
211240009	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SC2D040E14**10	19,700	\$2,758
211240008	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SC2D060E14**12	19,600	\$2,744
211240007	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58S(B,C)*A045E14**12	19,600	\$2,744
211240006	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SC5B026E14**10	19,900	\$2,786
211240005	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59TP6B060V14**12	19,300	\$2,702
211240004	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59TP6B040V14**10	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240003	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SC5B060E14**12	19,700	\$2,758
211240002	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SC5B040E14**10	19,800	\$2,772
211240001	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58TP*A070V14**12	19,500	\$2,730
211240000	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58TP*A045V14**12	19,500	\$2,730
211239999	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SP6A060V14**12	19,300	\$2,702
211239998	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SP6A040V14**10	19,500	\$2,730
211239997	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	58SP*A045V14**12	19,500	\$2,730
211239994	CARRIER	38MURAQ24AB3*	CAP**3721AL*	OVLAAB036098	18,400	\$2,576
211239977	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58TP*A110V21**22	18,500	\$2,590
211239975	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59TP6B080V21**20	18,400	\$2,576
211239969	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59TP6B040V17**12	18,500	\$2,590
211239956	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59TP6B100V21**22	18,400	\$2,576
211239952	CARRIER	38MURAQ24AB3*	CAP**3721AL*	59SP6A040V17**12	18,500	\$2,590
211239944	CARRIER	38MURAQ24AB3*	CAP**3717AL*	OVLAAB036098	18,700	\$2,618
211239943	CARRIER	38MURAQ24AB3*	CAP**3717AL*	OVMAAB036098	18,800	\$2,632
211239941	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58S(B,C)*A070E14**12	18,900	\$2,646
211239940	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC2D040E17**12	18,900	\$2,646
211239936	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC2D080E17**16	18,900	\$2,646
211239935	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC2D060E17**14	18,900	\$2,646
211239931	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58S(B,C)*A045E17**12	18,900	\$2,646
211239929	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59TP6B060V17**14	18,900	\$2,646
211239927	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59TP6B060V14**12	18,700	\$2,618
211239926	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59TP6B040V14**10	18,900	\$2,646
211239922	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58TP*A070V17**16	18,800	\$2,632
211239921	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59TP6B080V17**16	18,900	\$2,646
211239919	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58TP*A090V17**16	18,700	\$2,618
211239917	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58TP*A045V14**12	18,900	\$2,646
211239916	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58SU*A040E17**12	18,700	\$2,618
211239915	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SU5A060E17**16	18,900	\$2,646
211239914	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58SP*A070V17**16	18,800	\$2,632
211239913	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58SP*A045V17**16	19,000	\$2,660
211239909	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SU5A040E17**12	18,700	\$2,618
211239908	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SP6A080V17**16	18,900	\$2,646
211239907	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SP6A060V14**12	18,700	\$2,618
211239905	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SP6A040V14**10	18,900	\$2,646
211239904	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SP6A060V17**14	19,000	\$2,660
211239901	CARRIER	38MURAQ24AB3*	CAP**3621AL*	OVLAAB048112	19,200	\$2,688
211239900	CARRIER	38MURAQ24AB3*	CAP**3621AL*	OVMAAB042112	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211239899	CARRIER	38MURAQ24AB3*	CAP**3621AL*	OVLAAB036098	18,900	\$2,646
211239898	CARRIER	38MURAQ24AB3*	CAP**3621AL*	OVMAAB036098	18,900	\$2,646
211239897	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SU*A060E17**16	19,300	\$2,702
211239896	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SU*A080E21**20	19,100	\$2,674
211239895	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2D040E17**12	19,100	\$2,674
211239894	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC5B080E17**16	19,400	\$2,716
211239893	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC5B060E17**14	19,300	\$2,702
211239892	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2D100E21**20	19,300	\$2,702
211239891	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2D080E21**20	19,300	\$2,702
211239890	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2D080E17**16	19,100	\$2,674
211239889	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC2D060E17**14	19,100	\$2,674
211239888	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*A110E21**20	19,400	\$2,716
211239887	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*A090E21**20	19,200	\$2,688
211239886	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*A090E17**14	19,200	\$2,688
211239885	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*A070E21**16	19,100	\$2,674
211239884	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*A070E17**12	18,800	\$2,632
211239883	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*A045E17**12	19,100	\$2,674
211239882	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58TP*A110V21**22	18,900	\$2,646
211239881	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6B100V21**20	19,000	\$2,660
211239880	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6B080V21**20	18,900	\$2,646
211239879	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6B060V17**14	19,100	\$2,674
211239878	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC5B040E17**12	19,300	\$2,702
211239877	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58TP*A070V17**16	19,000	\$2,660
211239876	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6B080V17**16	19,100	\$2,674
211239875	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SC5B080E21**20	19,300	\$2,702
211239874	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6B040V17**12	19,000	\$2,660
211239873	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58TP*A090V21**20	19,000	\$2,660
211239872	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58TP*A090V17**16	19,000	\$2,660
211239871	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SU*A040E17**12	18,900	\$2,646
211239870	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SU5A060E17**16	19,100	\$2,674
211239869	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SP*A090V21**20	19,000	\$2,660
211239868	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SP*A070V21**20	19,300	\$2,702
211239867	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SP*A070V17**16	19,000	\$2,660
211239866	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58SP*A045V17**16	18,800	\$2,632
211239861	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59TP6B100V21**22	18,900	\$2,646
211239860	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*A070E17**16	19,400	\$2,716
211239859	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SU5A040E17**12	18,900	\$2,646
211239858	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SP6A080V17**16	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211239857	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SP6A040V17**12	19,000	\$2,660
211239856	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SP6A100V21**20	18,900	\$2,646
211239855	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SP6A080V21**20	19,000	\$2,660
211239854	CARRIER	38MURAQ24AB3*	CAP**3621AL*	59SP6A060V17**14	18,900	\$2,646
211239850	CARRIER	38MURAQ24AB3*	CAP**3617AL*	OVMAAB042112	19,200	\$2,688
211239849	CARRIER	38MURAQ24AB3*	CAP**3617AL*	OVLAAB036098	18,900	\$2,646
211239848	CARRIER	38MURAQ24AB3*	CAP**3617AL*	OVMAAB036098	18,900	\$2,646
211239847	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58SU*A060E17**16	19,300	\$2,702
211239846	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*A070E14**12	19,100	\$2,674
211239845	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC2D040E17**12	19,100	\$2,674
211239844	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC2D040E14**10	19,400	\$2,716
211239843	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC5B080E17**16	19,400	\$2,716
211239842	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC5B060E17**14	19,300	\$2,702
211239841	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC2D080E17**16	19,100	\$2,674
211239840	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC2D060E17**14	19,100	\$2,674
211239839	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC2D060E14**12	18,800	\$2,632
211239838	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*A090E17**14	19,200	\$2,688
211239837	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*A070E17**12	19,200	\$2,688
211239836	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*A045E17**12	19,100	\$2,674
211239835	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*A045E14**12	19,300	\$2,702
211239834	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59TP6B060V17**14	19,100	\$2,674
211239833	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC5B026E14**10	18,900	\$2,646
211239832	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59TP6B060V14**12	18,900	\$2,646
211239831	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59TP6B040V14**10	18,900	\$2,646
211239830	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC5B060E14**12	19,300	\$2,702
211239829	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC5B040E17**12	19,300	\$2,702
211239828	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC5B040E14**10	19,400	\$2,716
211239827	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58TP*A070V17**16	19,000	\$2,660
211239826	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59TP6B080V17**16	19,100	\$2,674
211239825	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59TP6B040V17**12	18,900	\$2,646
211239824	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58TP*A090V17**16	18,900	\$2,646
211239823	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58TP*A070V14**12	19,100	\$2,674
211239822	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58TP*A045V14**12	19,100	\$2,674
211239821	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58SU*A040E17**12	18,900	\$2,646
211239820	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SU5A060E17**16	19,100	\$2,674
211239819	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58SP*A070V17**16	19,000	\$2,660
211239818	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58SP*A045V17**16	19,100	\$2,674
211239815	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*A070E17**16	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211239814	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SU5A040E17**12	18,900	\$2,646
211239813	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SP6A080V17**16	19,100	\$2,674
211239812	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SP6A060V14**12	18,900	\$2,646
211239811	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SP6A040V17**12	18,900	\$2,646
211239810	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SP6A040V14**10	18,900	\$2,646
211239809	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SP6A060V17**14	18,900	\$2,646
211239807	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58SP*A045V14**12	18,800	\$2,632
211239806	CARRIER	38MURAQ24AB3*	CAP**3017AL*	OVMAAB042112	19,200	\$2,688
211239805	CARRIER	38MURAQ24AB3*	CAP**3017AL*	OVLAAB036098	18,900	\$2,646
211239804	CARRIER	38MURAQ24AB3*	CAP**3017AL*	OVMAAB036098	19,000	\$2,660
211239803	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58SU*A060E17**16	19,300	\$2,702
211239802	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*A070E14**12	19,200	\$2,688
211239801	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC2D040E17**12	19,100	\$2,674
211239800	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC2D040E14**10	19,400	\$2,716
211239799	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC5B080E17**16	19,500	\$2,730
211239798	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC5B060E17**14	19,400	\$2,716
211239797	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC2D080E17**16	19,100	\$2,674
211239796	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC2D060E17**14	19,200	\$2,688
211239795	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC2D060E14**12	18,900	\$2,646
211239794	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*A090E17**14	19,200	\$2,688
211239793	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*A070E17**12	19,200	\$2,688
211239792	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*A045E17**12	19,100	\$2,674
211239791	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*A045E14**12	19,400	\$2,716
211239790	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59TP6B060V17**14	19,100	\$2,674
211239789	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC5B026E14**10	18,900	\$2,646
211239788	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59TP6B060V14**12	19,000	\$2,660
211239787	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59TP6B040V14**10	19,000	\$2,660
211239786	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC5B060E14**12	19,400	\$2,716
211239785	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC5B040E17**12	19,400	\$2,716
211239784	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC5B040E14**10	19,500	\$2,730
211239783	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58TP*A070V17**16	19,100	\$2,674
211239782	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59TP6B080V17**16	19,200	\$2,688
211239781	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59TP6B040V17**12	19,000	\$2,660
211239780	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58TP*A090V17**16	19,000	\$2,660
211239779	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58TP*A070V14**12	19,200	\$2,688
211239778	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58TP*A045V14**12	19,200	\$2,688
211239777	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58SU*A040E17**12	19,000	\$2,660
211239776	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SU5A060E17**16	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211239775	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58SP*A070V17**16	19,100	\$2,674
211239774	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58SP*A045V17**16	19,200	\$2,688
211239771	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*A070E17**16	19,400	\$2,716
211239770	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SU5A040E17**12	19,000	\$2,660
211239769	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SP6A080V17**16	19,200	\$2,688
211239768	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SP6A060V14**12	19,000	\$2,660
211239767	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SP6A040V17**12	19,000	\$2,660
211239766	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SP6A040V14**10	19,000	\$2,660
211239765	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SP6A060V17**14	18,900	\$2,646
211239763	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58SP*A045V14**12	18,900	\$2,646
211239762	CARRIER	38MURAQ24AB3*	CAP**3014AL*	58S(B,C)*A070E14**12	19,200	\$2,688
211239761	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SC2D040E14**10	19,400	\$2,716
211239760	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SC2D060E14**12	18,900	\$2,646
211239759	CARRIER	38MURAQ24AB3*	CAP**3014AL*	58S(B,C)*A045E14**12	19,300	\$2,702
211239758	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SC5B026E14**10	19,600	\$2,744
211239757	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59TP6B060V14**12	19,000	\$2,660
211239756	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59TP6B040V14**10	19,100	\$2,674
211239755	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SC5B060E14**12	19,400	\$2,716
211239754	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SC5B040E14**10	19,500	\$2,730
211239753	CARRIER	38MURAQ24AB3*	CAP**3014AL*	58TP*A070V14**12	19,200	\$2,688
211239752	CARRIER	38MURAQ24AB3*	CAP**3014AL*	58TP*A045V14**12	19,100	\$2,674
211239751	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SP6A060V14**12	19,000	\$2,660
211239750	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SP6A040V14**10	19,100	\$2,674
211239749	CARRIER	38MURAQ24AB3*	CAP**3014AL*	58SP*A045V14**12	19,200	\$2,688
211239747	CARRIER	38MURAQ24AB3*	CAP**2517AL*	OVLAAB036098	18,600	\$2,604
211239746	CARRIER	38MURAQ24AB3*	CAP**2517AL*	OVMAAB036098	18,600	\$2,604
211239737	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SC2D060E14**12	18,500	\$2,590
211239730	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59TP6B060V14**12	18,600	\$2,604
211239723	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59TP6B040V17**12	18,600	\$2,604
211239722	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58TP*A090V17**16	18,600	\$2,604
211239719	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58SU*A040E17**12	18,600	\$2,604
211239717	CARRIER	38MURAQ24AB3*	CAP**2517AL*	58SP*A070V17**16	18,700	\$2,618
211239712	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SU5A040E17**12	18,600	\$2,604
211239710	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SP6A060V14**12	18,600	\$2,604
211239709	CARRIER	38MURAQ24AB3*	CAP**2517AL*	59SP6A040V17**12	18,600	\$2,604
211239704	CARRIER	38MURAQ24AB3*	CAP**2417AL*	OVMAAB042112	19,500	\$2,730
211239703	CARRIER	38MURAQ24AB3*	CAP**2417AL*	OVLAAB036098	19,200	\$2,688
211239702	CARRIER	38MURAQ24AB3*	CAP**2417AL*	OVMAAB036098	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211239701	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58SU*A060E17**16	19,600	\$2,744
211239700	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*A070E14**12	19,400	\$2,716
211239699	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC2D040E17**12	19,400	\$2,716
211239698	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC2D040E14**10	19,700	\$2,758
211239697	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC5B080E17**16	19,700	\$2,758
211239696	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC5B060E17**14	19,600	\$2,744
211239695	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC2D080E17**16	19,400	\$2,716
211239694	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC2D060E17**14	19,400	\$2,716
211239693	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC2D060E14**12	19,200	\$2,688
211239692	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*A090E17**14	19,500	\$2,730
211239691	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*A070E17**12	19,500	\$2,730
211239690	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*A045E17**12	19,400	\$2,716
211239689	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*A045E14**12	19,600	\$2,744
211239688	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6B060V17**14	19,400	\$2,716
211239687	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC5B026E14**10	19,800	\$2,772
211239686	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6B060V14**12	19,300	\$2,702
211239685	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6B040V14**10	19,400	\$2,716
211239684	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC5B060E14**12	19,600	\$2,744
211239683	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC5B040E17**12	19,700	\$2,758
211239682	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SC5B040E14**10	19,700	\$2,758
211239681	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58TP*A070V17**16	19,300	\$2,702
211239680	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6B080V17**16	19,400	\$2,716
211239679	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59TP6B040V17**12	19,300	\$2,702
211239678	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58TP*A090V17**16	19,300	\$2,702
211239677	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58TP*A070V14**12	19,400	\$2,716
211239676	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58TP*A045V14**12	19,400	\$2,716
211239675	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58SU*A040E17**12	19,300	\$2,702
211239674	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SU5A060E17**16	19,400	\$2,716
211239673	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58SP*A070V17**16	19,300	\$2,702
211239672	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58SP*A045V17**16	19,400	\$2,716
211239669	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*A070E17**16	19,700	\$2,758
211239668	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SU5A040E17**12	19,300	\$2,702
211239667	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SP6A080V17**16	19,400	\$2,716
211239666	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SP6A060V14**12	19,300	\$2,702
211239665	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SP6A040V17**12	19,300	\$2,702
211239664	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SP6A040V14**10	19,400	\$2,716
211239663	CARRIER	38MURAQ24AB3*	CAP**2417AL*	59SP6A060V17**14	19,500	\$2,730
211239661	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58SP*A045V14**12	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211239660	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58S(B,C)*A070E14**12	19,400	\$2,716
211239659	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SC2D040E14**10	19,700	\$2,758
211239658	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SC2D060E14**12	19,600	\$2,744
211239657	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58S(B,C)*A045E14**12	19,600	\$2,744
211239656	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SC5B026E14**10	19,800	\$2,772
211239655	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59TP6B060V14**12	19,300	\$2,702
211239654	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59TP6B040V14**10	19,400	\$2,716
211239653	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SC5B060E14**12	19,600	\$2,744
211239652	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SC5B040E14**10	19,700	\$2,758
211239651	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58TP*A070V14**12	19,400	\$2,716
211239650	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58TP*A045V14**12	19,400	\$2,716
211239649	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SP6A060V14**12	19,300	\$2,702
211239648	CARRIER	38MURAQ24AB3*	CAP**2414AL*	59SP6A040V14**10	19,400	\$2,716
211239647	CARRIER	38MURAQ24AB3*	CAP**2414AL*	58SP*A045V14**12	19,500	\$2,730
211239220	CARRIER	38MURAQ24AB3*	FJ4DN*B24L*		19,200	\$2,688
213353737	CARRIER	38MURAQ18AB3*	F54AA*B24L*		12,500	\$1,750
213353727	CARRIER	38MURAQ18AB3*	F54AA*A18L*		12,800	\$1,792
213249246	CARRIER	38MURAQ18AB3*	FEVA0024**+NAVA43601CK		12,300	\$1,722
213076383	CARRIER	38MURAQ18AB3*	CAP**2417AL*	GG96VTAB48060B**	12,400	\$1,736
213076382	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6C060V17**16	12,400	\$1,736
212989321	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SU5B060M17**16	12,200	\$1,708
212989309	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SU5B060M17**16	12,300	\$1,722
212989297	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SU5B060M17**16	12,200	\$1,708
212989285	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SU5B060M17**16	12,000	\$1,680
212989273	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SU5B060M17**16	12,300	\$1,722
212989261	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SU5B060M17**16	12,100	\$1,694
212988829	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SU5B040M17**12	12,200	\$1,708
212988817	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SU5B040M17**12	12,500	\$1,750
212988805	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SU5B040M17**12	12,200	\$1,708
212988793	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SU5B040M17**12	12,000	\$1,680
212988781	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SU5B040M17**12	12,300	\$1,722
212988769	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SU5B040M17**12	12,100	\$1,694
212987555	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC6A080M17**16	12,200	\$1,708
212987543	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC6A080M17**16	12,500	\$1,750
212987531	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC6A080M17**16	12,100	\$1,694
212987519	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC6A080M17**16	12,200	\$1,708
212987507	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC6A080M17**16	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212987495	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC6A080M17**16	12,300	\$1,722
212987077	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC6A060M14**12	12,200	\$1,708
212987067	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SC6A060M14**12	12,200	\$1,708
212987057	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC6A060M14**12	12,300	\$1,722
212987047	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SC6A060M14**12	12,300	\$1,722
212987037	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SC6A060M14**12	12,500	\$1,750
212987027	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC6A060M14**12	12,200	\$1,708
212987017	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SC6A060M14**12	12,200	\$1,708
212987007	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC6A060M14**12	12,000	\$1,680
212986997	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC6A060M14**12	12,300	\$1,722
212986987	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SC6A060M14**12	12,300	\$1,722
212986977	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC6A060M14**12	12,100	\$1,694
212986715	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC6A040M17**12	12,300	\$1,722
212986703	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC6A040M17**12	12,500	\$1,750
212986691	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC6A040M17**12	12,300	\$1,722
212986679	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC6A040M17**12	12,100	\$1,694
212986667	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC6A040M17**12	12,300	\$1,722
212986655	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC6A040M17**12	12,100	\$1,694
212986379	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC6A040M14**10	12,300	\$1,722
212986367	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SC6A040M14**10	12,300	\$1,722
212986355	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC6A040M14**10	12,400	\$1,736
212986343	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SC6A040M14**10	12,400	\$1,736
212986331	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SC6A040M14**10	12,400	\$1,736
212986319	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC6A040M14**10	12,300	\$1,722
212986307	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SC6A040M14**10	12,300	\$1,722
212986295	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC6A040M14**10	12,400	\$1,736
212986283	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SC6A040M14**10	12,400	\$1,736
212986271	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC6A040M14**10	12,200	\$1,708
212985973	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC6A026M14**10	12,300	\$1,722
212985963	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SC6A026M14**10	12,200	\$1,708
212985953	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC6A026M14**10	12,300	\$1,722
212985943	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SC6A026M14**10	12,300	\$1,722
212985933	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SC6A026M14**10	12,500	\$1,750
212985923	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC6A026M14**10	12,200	\$1,708
212985913	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SC6A026M14**10	12,200	\$1,708
212985903	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC6A026M14**10	12,100	\$1,694
212985893	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC6A026M14**10	12,300	\$1,722
212985883	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SC6A026M14**10	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212985873	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC6A026M14**10	12,100	\$1,694
212984757	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC2E080M17**16	12,100	\$1,694
212984745	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC2E080M17**16	12,500	\$1,750
212984733	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC2E080M17**16	12,400	\$1,736
212984721	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC2E080M17**16	12,200	\$1,708
212984709	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC2E080M17**16	12,500	\$1,750
212984697	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC2E080M17**16	12,300	\$1,722
212984217	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC2E060M17**14	12,300	\$1,722
212984205	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC2E060M17**14	12,400	\$1,736
212984193	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC2E060M17**14	12,300	\$1,722
212984181	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC2E060M17**14	12,200	\$1,708
212984169	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC2E060M17**14	12,400	\$1,736
212984157	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC2E060M17**14	12,200	\$1,708
212983727	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC2E060M14**12	12,200	\$1,708
212983717	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SC2E060M14**12	12,200	\$1,708
212983706	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC2E060M14**12	12,400	\$1,736
212983696	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SC2E060M14**12	12,400	\$1,736
212983686	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SC2E060M14**12	12,400	\$1,736
212983676	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC2E060M14**12	12,200	\$1,708
212983666	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SC2E060M14**12	12,300	\$1,722
212983656	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC2E060M14**12	12,000	\$1,680
212983646	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC2E060M14**12	12,400	\$1,736
212983636	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SC2E060M14**12	12,400	\$1,736
212983626	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC2E060M14**12	12,100	\$1,694
212983305	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC2E040M17**12	12,300	\$1,722
212983294	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC2E040M17**12	12,400	\$1,736
212983283	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC2E040M17**12	12,200	\$1,708
212983272	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC2E040M17**12	12,100	\$1,694
212983261	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC2E040M17**12	12,300	\$1,722
212983250	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC2E040M17**12	12,200	\$1,708
212980001	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58S(B,C)*B090M17**14	12,300	\$1,722
212979989	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58S(B,C)*B090M17**14	12,400	\$1,736
212979977	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58S(B,C)*B090M17**14	12,300	\$1,722
212979965	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58S(B,C)*B090M17**14	12,200	\$1,708
212979953	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58S(B,C)*B090M17**14	12,400	\$1,736
212979941	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58S(B,C)*B090M17**14	12,200	\$1,708
212978796	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58S(B,C)*B070M17**12	12,300	\$1,722
212978785	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58S(B,C)*B070M17**12	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978774	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58S(B,C)*B070M17**12	12,300	\$1,722
212978763	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58S(B,C)*B070M17**12	12,100	\$1,694
212978752	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58S(B,C)*B070M17**12	12,300	\$1,722
212978741	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58S(B,C)*B070M17**12	12,100	\$1,694
212978344	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58S(B,C)*B070M14**12	12,200	\$1,708
212978332	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	58S(B,C)*B070M14**12	12,200	\$1,708
212978320	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58S(B,C)*B070M14**12	12,400	\$1,736
212978308	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	58S(B,C)*B070M14**12	12,400	\$1,736
212978296	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	58S(B,C)*B070M14**12	12,400	\$1,736
212978282	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58S(B,C)*B070M14**12	12,100	\$1,694
212978270	CARRIER	38MURAQ18AB3*	CAP**3014AL*	58S(B,C)*B070M14**12	12,300	\$1,722
212978258	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58S(B,C)*B070M14**12	12,200	\$1,708
212978246	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58S(B,C)*B070M14**12	12,400	\$1,736
212978234	CARRIER	38MURAQ18AB3*	CAP**2414AL*	58S(B,C)*B070M14**12	12,400	\$1,736
212978222	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58S(B,C)*B070M14**12	12,200	\$1,708
212977826	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58S(B,C)*B045M14**12	12,300	\$1,722
212977814	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	58S(B,C)*B045M14**12	12,300	\$1,722
212977802	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58S(B,C)*B045M14**12	12,400	\$1,736
212977790	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	58S(B,C)*B045M14**12	12,400	\$1,736
212977778	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	58S(B,C)*B045M14**12	12,400	\$1,736
212977766	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58S(B,C)*B045M14**12	12,300	\$1,722
212977754	CARRIER	38MURAQ18AB3*	CAP**3014AL*	58S(B,C)*B045M14**12	12,300	\$1,722
212977742	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58S(B,C)*B045M14**12	12,100	\$1,694
212977730	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58S(B,C)*B045M14**12	12,400	\$1,736
212977718	CARRIER	38MURAQ18AB3*	CAP**2414AL*	58S(B,C)*B045M14**12	12,300	\$1,722
212977706	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58S(B,C)*B045M14**12	12,200	\$1,708
212975837	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	GG96VTAB48080B**	12,200	\$1,708
212975836	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59TP6C080V17**16	12,200	\$1,708
212975824	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	GG96VTAB48080B**	12,500	\$1,750
212975823	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59TP6C080V17**16	12,500	\$1,750
212975811	CARRIER	38MURAQ18AB3*	CAP**3017AL*	GG96VTAB48080B**	12,200	\$1,708
212975810	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59TP6C080V17**16	12,200	\$1,708
212975798	CARRIER	38MURAQ18AB3*	CAP**2517AL*	GG96VTAB48080B**	12,000	\$1,680
212975797	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59TP6C080V17**16	12,000	\$1,680
212975785	CARRIER	38MURAQ18AB3*	CAP**2417AL*	GG96VTAB48080B**	12,300	\$1,722
212975784	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6C080V17**16	12,300	\$1,722
212975772	CARRIER	38MURAQ18AB3*	CAP**1917AL*	GG96VTAB48080B**	12,100	\$1,694
212975771	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59TP6C080V17**16	12,100	\$1,694

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975485	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59TP6C060V14**12	12,200	\$1,708
212975474	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59TP6C060V14**12	12,200	\$1,708
212975463	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59TP6C060V14**12	12,400	\$1,736
212975452	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59TP6C060V14**12	12,400	\$1,736
212975441	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59TP6C060V14**12	12,400	\$1,736
212975430	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59TP6C060V14**12	12,200	\$1,708
212975419	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59TP6C060V14**12	12,200	\$1,708
212975408	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59TP6C060V14**12	12,000	\$1,680
212975397	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6C060V14**12	12,300	\$1,722
212975386	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59TP6C060V14**12	12,200	\$1,708
212975375	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59TP6C060V14**12	12,100	\$1,694
212975122	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59TP6C040V17**12	12,200	\$1,708
212975111	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59TP6C040V17**12	12,500	\$1,750
212975100	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59TP6C040V17**12	12,200	\$1,708
212975089	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59TP6C040V17**12	12,100	\$1,694
212975078	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6C040V17**12	12,300	\$1,722
212975067	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59TP6C040V17**12	12,100	\$1,694
212974743	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	GG96VTAB30040A**	12,200	\$1,708
212974742	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59TP6C040V14**10	12,200	\$1,708
212974730	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	GG96VTAB30040A**	12,200	\$1,708
212974729	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59TP6C040V14**10	12,200	\$1,708
212974717	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	GG96VTAB30040A**	12,400	\$1,736
212974716	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59TP6C040V14**10	12,400	\$1,736
212974704	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	GG96VTAB30040A**	12,400	\$1,736
212974703	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59TP6C040V14**10	12,400	\$1,736
212974691	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	GG96VTAB30040A**	12,400	\$1,736
212974690	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59TP6C040V14**10	12,400	\$1,736
212974678	CARRIER	38MURAQ18AB3*	CAP**3017AL*	GG96VTAB30040A**	12,200	\$1,708
212974677	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59TP6C040V14**10	12,200	\$1,708
212974665	CARRIER	38MURAQ18AB3*	CAP**3014AL*	GG96VTAB30040A**	12,200	\$1,708
212974664	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59TP6C040V14**10	12,200	\$1,708
212974652	CARRIER	38MURAQ18AB3*	CAP**2517AL*	GG96VTAB30040A**	12,100	\$1,694
212974651	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59TP6C040V14**10	12,100	\$1,694
212974639	CARRIER	38MURAQ18AB3*	CAP**2417AL*	GG96VTAB30040A**	12,300	\$1,722
212974638	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6C040V14**10	12,300	\$1,722
212974626	CARRIER	38MURAQ18AB3*	CAP**2414AL*	GG96VTAB30040A**	12,400	\$1,736
212974625	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59TP6C040V14**10	12,400	\$1,736
212974613	CARRIER	38MURAQ18AB3*	CAP**1917AL*	GG96VTAB30040A**	12,100	\$1,694

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974612	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59TP6C040V14**10	12,100	\$1,694
212973702	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SP6B080V17**16	12,200	\$1,708
212973692	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SP6B080V17**16	12,500	\$1,750
212973682	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SP6B080V17**16	12,200	\$1,708
212973672	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SP6B080V17**16	12,000	\$1,680
212973662	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SP6B080V17**16	12,300	\$1,722
212973652	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SP6B080V17**16	12,100	\$1,694
212973392	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SP6B060V14**12	12,200	\$1,708
212973382	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SP6B060V14**12	12,200	\$1,708
212973372	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SP6B060V14**12	12,400	\$1,736
212973362	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SP6B060V14**12	12,400	\$1,736
212973352	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SP6B060V14**12	12,400	\$1,736
212973342	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SP6B060V14**12	12,200	\$1,708
212973332	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SP6B060V14**12	12,200	\$1,708
212973322	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SP6B060V14**12	12,000	\$1,680
212973312	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SP6B060V14**12	12,300	\$1,722
212973302	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SP6B060V14**12	12,200	\$1,708
212973292	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SP6B060V14**12	12,100	\$1,694
212973062	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SP6B040V17**12	12,200	\$1,708
212973052	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SP6B040V17**12	12,500	\$1,750
212973042	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SP6B040V17**12	12,200	\$1,708
212973032	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SP6B040V17**12	12,100	\$1,694
212973022	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SP6B040V17**12	12,300	\$1,722
212973012	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SP6B040V17**12	12,100	\$1,694
212972762	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SP6B040V14**10	12,200	\$1,708
212972752	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SP6B040V14**10	12,200	\$1,708
212972742	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SP6B040V14**10	12,400	\$1,736
212972732	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SP6B040V14**10	12,400	\$1,736
212972722	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SP6B040V14**10	12,400	\$1,736
212972712	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SP6B040V14**10	12,200	\$1,708
212972702	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SP6B040V14**10	12,200	\$1,708
212972692	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SP6B040V14**10	12,100	\$1,694
212972682	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SP6B040V14**10	12,300	\$1,722
212972672	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SP6B040V14**10	12,300	\$1,722
212972662	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SP6B040V14**10	12,100	\$1,694
212971927	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58TP*B090V17**16	12,300	\$1,722
212971923	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58TP*B090V17**16	12,400	\$1,736
212971919	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58TP*B090V17**16	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971915	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58TP*B090V17**16	12,100	\$1,694
212971911	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58TP*B090V17**16	12,400	\$1,736
212971907	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58TP*B090V17**16	12,200	\$1,708
212971489	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58TP*B070V17**16	12,300	\$1,722
212971478	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58TP*B070V17**16	12,400	\$1,736
212971467	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58TP*B070V17**16	12,300	\$1,722
212971456	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58TP*B070V17**16	12,100	\$1,694
212971445	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58TP*B070V17**16	12,400	\$1,736
212971434	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58TP*B070V17**16	12,200	\$1,708
212971368	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58TP*B070V14**12	12,200	\$1,708
212971366	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	58TP*B070V14**12	12,200	\$1,708
212971364	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58TP*B070V14**12	12,400	\$1,736
212971362	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	58TP*B070V14**12	12,400	\$1,736
212971360	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	58TP*B070V14**12	12,400	\$1,736
212971358	CARRIER	38MURAQ18AB3*	CAP**3014AL*	58TP*B070V14**12	12,300	\$1,722
212971356	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58TP*B070V14**12	12,200	\$1,708
212971354	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58TP*B070V14**12	12,400	\$1,736
212971352	CARRIER	38MURAQ18AB3*	CAP**2414AL*	58TP*B070V14**12	12,400	\$1,736
212971350	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58TP*B070V14**12	12,200	\$1,708
212969596	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58SP*B045V14**12	12,200	\$1,708
212969586	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	58SP*B045V14**12	12,200	\$1,708
212969576	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58SP*B045V14**12	12,500	\$1,750
212969566	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	58SP*B045V14**12	12,500	\$1,750
212969556	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	58SP*B045V14**12	12,500	\$1,750
212969546	CARRIER	38MURAQ18AB3*	CAP**3014AL*	58SP*B045V14**12	12,400	\$1,736
212969536	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58SP*B045V14**12	12,200	\$1,708
212969526	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58SP*B045V14**12	12,500	\$1,750
212969516	CARRIER	38MURAQ18AB3*	CAP**2414AL*	58SP*B045V14**12	12,500	\$1,750
212969506	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58SP*B045V14**12	12,300	\$1,722
211264726	CARRIER	38MURAQ18AB3*	PF4MN*A18L*		12,700	\$1,778
211264443	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	GG96VTAA42060B	12,400	\$1,736
211264344	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	GG96VTAA30040A	12,300	\$1,722
211264158	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	GG96VTAA48080B	12,200	\$1,708
211263711	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	GG96VTAA30040A	12,200	\$1,708
211263268	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	GG96VTAA42060B	12,500	\$1,750
211263201	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	GG96VTAA30040A	12,300	\$1,722
211263096	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	GG96VTAA48080B	12,300	\$1,722
211262631	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	GG96VTAA30040A	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262352	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	GG96VTAA30040A	12,300	\$1,722
211261968	CARRIER	38MURAQ18AB3*	CAP**3017AL*	GG96VTAA42060B	12,400	\$1,736
211261910	CARRIER	38MURAQ18AB3*	CAP**3017AL*	GG96VTAA30040A	12,200	\$1,708
211261804	CARRIER	38MURAQ18AB3*	CAP**3017AL*	GG96VTAA48080B	12,200	\$1,708
211261362	CARRIER	38MURAQ18AB3*	CAP**3014AL*	GG96VTAA30040A	12,200	\$1,708
211260962	CARRIER	38MURAQ18AB3*	CAP**2517AL*	GG96VTAA42060B	12,200	\$1,708
211260923	CARRIER	38MURAQ18AB3*	CAP**2517AL*	GG96VTAA30040A	12,100	\$1,694
211260857	CARRIER	38MURAQ18AB3*	CAP**2517AL*	GG96VTAA48080B	12,100	\$1,694
211260518	CARRIER	38MURAQ18AB3*	CAP**2417AL*	GG96VTAA42060B	12,400	\$1,736
211260480	CARRIER	38MURAQ18AB3*	CAP**2417AL*	GG96VTAA30040A	12,300	\$1,722
211260415	CARRIER	38MURAQ18AB3*	CAP**2417AL*	GG96VTAA48080B	12,300	\$1,722
211260152	CARRIER	38MURAQ18AB3*	CAP**2414AL*	GG96VTAA30040A	12,300	\$1,722
211259870	CARRIER	38MURAQ18AB3*	CAP**1917AL*	GG96VTAA42060B	12,300	\$1,722
211259831	CARRIER	38MURAQ18AB3*	CAP**1917AL*	GG96VTAA30040A	12,100	\$1,694
211259773	CARRIER	38MURAQ18AB3*	CAP**1917AL*	GG96VTAA48080B	12,100	\$1,694
211258125	CARRIER	38MURAQ18AB3*	FV4CNF002L		12,400	\$1,736
211258124	CARRIER	38MURAQ18AB3*	FM(C,U)4Z30**AL*		12,400	\$1,736
211258123	CARRIER	38MURAQ18AB3*	FM(C,U)4Z24**AL*		12,500	\$1,750
211258122	CARRIER	38MURAQ18AB3*	FM(C,U)4Z18**AL*		12,500	\$1,750
211258121	CARRIER	38MURAQ18AB3*	FMA4X24**AL*		12,400	\$1,736
211258120	CARRIER	38MURAQ18AB3*	FMA4X18**AL*		12,400	\$1,736
211258119	CARRIER	38MURAQ18AB3*	FX4DNF031L		12,400	\$1,736
211258116	CARRIER	38MURAQ18AB3*	FX4DNF025L		12,400	\$1,736
211258106	CARRIER	38MURAQ18AB3*	FJ4DN*A18L*		12,700	\$1,778
211258105	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	OVMAAB042112	12,600	\$1,764
211258104	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	OVLAAB036098	12,600	\$1,764
211258102	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	OVMAAB036098	12,600	\$1,764
211258101	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58SU*A060E17**16	12,700	\$1,778
211258100	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58S(B,C)*A070E14**12	12,300	\$1,722
211258098	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC2D040E17**12	12,500	\$1,750
211258097	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC2D040E14**10	12,500	\$1,750
211258096	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC2D060E17**14	12,300	\$1,722
211258095	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC2D060E14**12	12,500	\$1,750
211258093	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58S(B,C)*A070E17**12	12,500	\$1,750
211258092	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58S(B,C)*A045E17**12	12,400	\$1,736
211258091	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58S(B,C)*A045E14**12	12,500	\$1,750
211258090	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59TP6B060V17**14	12,400	\$1,736
211258088	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC5B026E14**10	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211258087	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59TP6B060V14**12	12,400	\$1,736
211258086	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59TP6B040V14**10	12,300	\$1,722
211258084	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC5B060E14**12	12,400	\$1,736
211258083	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC5B040E17**12	12,200	\$1,708
211258082	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SC5B040E14**10	12,400	\$1,736
211258081	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58TP*A070V17**16	12,200	\$1,708
211258079	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59TP6B080V17**16	12,200	\$1,708
211258078	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59TP6B040V17**12	12,400	\$1,736
211258077	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58TP*A090V17**16	12,300	\$1,722
211258075	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58TP*A070V14**12	12,300	\$1,722
211258074	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58TP*A045V14**12	12,300	\$1,722
211258073	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58SU*A040E17**12	12,700	\$1,778
211258071	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58SP*A070V17**16	12,200	\$1,708
211258070	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58SP*A045V17**16	12,300	\$1,722
211258066	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SU5A040E17**12	12,400	\$1,736
211258065	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SP6A080V17**16	12,200	\$1,708
211258064	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SP6A060V14**12	12,400	\$1,736
211258062	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SP6A040V17**12	12,400	\$1,736
211258061	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SP6A040V14**10	12,300	\$1,722
211258060	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	59SP6A060V17**14	12,400	\$1,736
211258057	CARRIER	38MURAQ18AB3*	CNPV*3017AL*	58SP*A045V14**12	12,400	\$1,736
211258056	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	58S(B,C)*A070E14**12	12,300	\$1,722
211258055	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SC2D040E14**10	12,500	\$1,750
211258053	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SC2D060E14**12	12,500	\$1,750
211258052	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	58S(B,C)*A045E14**12	12,500	\$1,750
211258050	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SC5B026E14**10	12,500	\$1,750
211258049	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59TP6B060V14**12	12,400	\$1,736
211258048	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59TP6B040V14**10	12,200	\$1,708
211258047	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SC5B060E14**12	12,400	\$1,736
211258046	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SC5B040E14**10	12,400	\$1,736
211258044	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	58TP*A070V14**12	12,300	\$1,722
211258043	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	58TP*A045V14**12	12,300	\$1,722
211258041	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SP6A060V14**12	12,400	\$1,736
211258040	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	59SP6A040V14**10	12,200	\$1,708
211258039	CARRIER	38MURAQ18AB3*	CNPV*3014AL*	58SP*A045V14**12	12,400	\$1,736
211258038	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	OVMAAB042112	12,800	\$1,792
211258037	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	OVLAAB036098	12,700	\$1,778
211258036	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	OVMAAB036098	12,800	\$1,792

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211258034	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58SU*A060E17**16	12,800	\$1,792
211258032	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58S(B,C)*A070E14**12	12,400	\$1,736
211258031	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC2D040E17**12	12,600	\$1,764
211258030	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC2D040E14**10	12,600	\$1,764
211258029	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC2D080E17**16	12,900	\$1,806
211258028	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC2D060E17**14	12,400	\$1,736
211258027	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC2D060E14**12	12,600	\$1,764
211258026	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58S(B,C)*A070E17**12	12,600	\$1,764
211258023	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58S(B,C)*A045E17**12	12,900	\$1,806
211258022	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58S(B,C)*A045E14**12	12,600	\$1,764
211258021	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59TP6B060V17**14	12,500	\$1,750
211258020	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC5B026E14**10	12,700	\$1,778
211258019	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59TP6B060V14**12	12,500	\$1,750
211258018	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59TP6B040V14**10	12,300	\$1,722
211258015	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC5B060E14**12	12,500	\$1,750
211258014	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC5B040E17**12	12,300	\$1,722
211258013	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SC5B040E14**10	12,500	\$1,750
211258012	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58TP*A070V17**16	12,300	\$1,722
211258011	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59TP6B080V17**16	12,300	\$1,722
211258010	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59TP6B040V17**12	12,500	\$1,750
211258009	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58TP*A090V17**16	12,400	\$1,736
211258008	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58TP*A070V14**12	12,400	\$1,736
211258005	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58TP*A045V14**12	12,400	\$1,736
211258004	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58SU*A040E17**12	12,700	\$1,778
211258003	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SU5A060E17**16	12,900	\$1,806
211258002	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58SP*A070V17**16	12,300	\$1,722
211258001	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58SP*A045V17**16	12,400	\$1,736
211257997	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SU5A040E17**12	12,400	\$1,736
211257996	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SP6A080V17**16	12,300	\$1,722
211257994	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SP6A060V14**12	12,500	\$1,750
211257993	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SP6A040V17**12	12,500	\$1,750
211257992	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SP6A040V14**10	12,300	\$1,722
211257991	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	59SP6A060V17**14	12,400	\$1,736
211257988	CARRIER	38MURAQ18AB3*	CNPV*2417AL*	58SP*A045V14**12	12,400	\$1,736
211257987	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	58S(B,C)*A070E14**12	12,400	\$1,736
211257985	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SC2D040E14**10	12,600	\$1,764
211257984	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SC2D060E14**12	12,600	\$1,764
211257983	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	58S(B,C)*A045E14**12	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211257982	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SC5B026E14**10	12,700	\$1,778
211257980	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59TP6B060V14**12	12,500	\$1,750
211257979	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59TP6B040V14**10	12,300	\$1,722
211257978	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SC5B060E14**12	12,500	\$1,750
211257976	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SC5B040E14**10	12,500	\$1,750
211257975	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	58TP*A070V14**12	12,400	\$1,736
211257974	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	58TP*A045V14**12	12,400	\$1,736
211257972	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SP6A060V14**12	12,500	\$1,750
211257971	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	59SP6A040V14**10	12,300	\$1,722
211257969	CARRIER	38MURAQ18AB3*	CNPV*2414AL*	58SP*A045V14**12	12,400	\$1,736
211257968	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	58S(B,C)*A070E14**12	12,400	\$1,736
211257967	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SC2D040E14**10	12,600	\$1,764
211257965	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SC2D060E14**12	12,600	\$1,764
211257964	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	58S(B,C)*A045E14**12	12,600	\$1,764
211257962	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SC5B026E14**10	12,700	\$1,778
211257961	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59TP6B060V14**12	12,500	\$1,750
211257959	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59TP6B040V14**10	12,300	\$1,722
211257958	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SC5B060E14**12	12,500	\$1,750
211257956	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SC5B040E14**10	12,500	\$1,750
211257955	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	58TP*A070V14**12	12,400	\$1,736
211257954	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	58TP*A045V14**12	12,400	\$1,736
211257952	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SP6A060V14**12	12,500	\$1,750
211257951	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	59SP6A040V14**10	12,300	\$1,722
211257949	CARRIER	38MURAQ18AB3*	CNPV*1814AL*	58SP*A045V14**12	12,500	\$1,750
211257948	CARRIER	38MURAQ18AB3*	CAP**3017AL*	OVMAAB042112	12,600	\$1,764
211257946	CARRIER	38MURAQ18AB3*	CAP**3017AL*	OVLAAB036098	12,600	\$1,764
211257945	CARRIER	38MURAQ18AB3*	CAP**3017AL*	OVMAAB036098	12,600	\$1,764
211257943	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58S(B,C)*A070E14**12	12,300	\$1,722
211257942	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC2D040E17**12	12,500	\$1,750
211257941	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC2D040E14**10	12,500	\$1,750
211257940	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC2D060E17**14	12,300	\$1,722
211257939	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC2D060E14**12	12,500	\$1,750
211257937	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58S(B,C)*A070E17**12	12,500	\$1,750
211257936	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58S(B,C)*A045E17**12	12,400	\$1,736
211257934	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58S(B,C)*A045E14**12	12,500	\$1,750
211257933	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59TP6B060V17**14	12,400	\$1,736
211257931	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC5B026E14**10	12,600	\$1,764
211257930	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59TP6B060V14**12	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211257929	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59TP6B040V14**10	12,200	\$1,708
211257927	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC5B060E14**12	12,400	\$1,736
211257926	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC5B040E17**12	12,200	\$1,708
211257925	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SC5B040E14**10	12,400	\$1,736
211257924	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58TP*A070V17**16	12,200	\$1,708
211257923	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59TP6B080V17**16	12,200	\$1,708
211257921	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59TP6B040V17**12	12,400	\$1,736
211257920	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58TP*A090V17**16	12,300	\$1,722
211257918	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58TP*A070V14**12	12,300	\$1,722
211257917	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58TP*A045V14**12	12,300	\$1,722
211257915	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58SU*A040E17**12	12,700	\$1,778
211257914	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58SP*A070V17**16	12,200	\$1,708
211257912	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58SP*A045V17**16	12,300	\$1,722
211257908	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SU5A040E17**12	12,300	\$1,722
211257907	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SP6A080V17**16	12,200	\$1,708
211257906	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SP6A060V14**12	12,500	\$1,750
211257905	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SP6A040V17**12	12,400	\$1,736
211257904	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SP6A040V14**10	12,200	\$1,708
211257902	CARRIER	38MURAQ18AB3*	CAP**3017AL*	59SP6A060V17**14	12,400	\$1,736
211257899	CARRIER	38MURAQ18AB3*	CAP**3017AL*	58SP*A045V14**12	12,400	\$1,736
211257898	CARRIER	38MURAQ18AB3*	CAP**3014AL*	58S(B,C)*A070E14**12	12,300	\$1,722
211257896	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SC2D040E14**10	12,500	\$1,750
211257895	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SC2D060E14**12	12,500	\$1,750
211257894	CARRIER	38MURAQ18AB3*	CAP**3014AL*	58S(B,C)*A045E14**12	12,500	\$1,750
211257892	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SC5B026E14**10	12,500	\$1,750
211257891	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59TP6B060V14**12	12,400	\$1,736
211257890	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59TP6B040V14**10	12,200	\$1,708
211257888	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SC5B060E14**12	12,400	\$1,736
211257887	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SC5B040E14**10	12,400	\$1,736
211257885	CARRIER	38MURAQ18AB3*	CAP**3014AL*	58TP*A070V14**12	12,300	\$1,722
211257884	CARRIER	38MURAQ18AB3*	CAP**3014AL*	58TP*A045V14**12	12,300	\$1,722
211257883	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SP6A060V14**12	12,400	\$1,736
211257881	CARRIER	38MURAQ18AB3*	CAP**3014AL*	59SP6A040V14**10	12,200	\$1,708
211257880	CARRIER	38MURAQ18AB3*	CAP**3014AL*	58SP*A045V14**12	12,400	\$1,736
211257878	CARRIER	38MURAQ18AB3*	CAP**2517AL*	OVMAAB042112	12,500	\$1,750
211257877	CARRIER	38MURAQ18AB3*	CAP**2517AL*	OVLAAB036098	12,500	\$1,750
211257876	CARRIER	38MURAQ18AB3*	CAP**2517AL*	OVMAAB036098	12,500	\$1,750
211257875	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58SU*A060E17**16	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211257874	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58S(B,C)*A070E14**12	12,100	\$1,694
211257872	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC2D040E17**12	12,400	\$1,736
211257871	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC2D040E14**10	12,400	\$1,736
211257870	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC2D060E17**14	12,200	\$1,708
211257868	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC2D060E14**12	12,400	\$1,736
211257867	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58S(B,C)*A070E17**12	12,400	\$1,736
211257866	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58S(B,C)*A045E17**12	12,700	\$1,778
211257865	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58S(B,C)*A045E14**12	12,400	\$1,736
211257864	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59TP6B060V17**14	12,200	\$1,708
211257862	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC5B026E14**10	12,400	\$1,736
211257861	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59TP6B060V14**12	12,300	\$1,722
211257859	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59TP6B040V14**10	12,100	\$1,694
211257858	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC5B060E14**12	12,300	\$1,722
211257857	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC5B040E17**12	12,100	\$1,694
211257856	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SC5B040E14**10	12,300	\$1,722
211257855	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58TP*A070V17**16	12,000	\$1,680
211257854	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59TP6B080V17**16	12,100	\$1,694
211257853	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59TP6B040V17**12	12,300	\$1,722
211257851	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58TP*A090V17**16	12,200	\$1,708
211257849	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58TP*A070V14**12	12,200	\$1,708
211257848	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58TP*A045V14**12	12,200	\$1,708
211257847	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58SU*A040E17**12	12,500	\$1,750
211257846	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58SP*A070V17**16	12,100	\$1,694
211257845	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58SP*A045V17**16	12,200	\$1,708
211257840	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SU5A040E17**12	12,200	\$1,708
211257839	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SP6A080V17**16	12,100	\$1,694
211257838	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SP6A060V14**12	12,300	\$1,722
211257837	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SP6A040V17**12	12,300	\$1,722
211257835	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SP6A040V14**10	12,100	\$1,694
211257833	CARRIER	38MURAQ18AB3*	CAP**2517AL*	59SP6A060V17**14	12,200	\$1,708
211257831	CARRIER	38MURAQ18AB3*	CAP**2517AL*	58SP*A045V14**12	12,200	\$1,708
211257830	CARRIER	38MURAQ18AB3*	CAP**2417AL*	OVMAAB042112	12,700	\$1,778
211257829	CARRIER	38MURAQ18AB3*	CAP**2417AL*	OVLAAB036098	12,700	\$1,778
211257826	CARRIER	38MURAQ18AB3*	CAP**2417AL*	OVMAAB036098	12,700	\$1,778
211257825	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58SU*A060E17**16	12,800	\$1,792
211257824	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58S(B,C)*A070E14**12	12,400	\$1,736
211257823	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC2D040E17**12	12,600	\$1,764
211257822	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC2D040E14**10	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211257820	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC2D060E17**14	12,400	\$1,736
211257818	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC2D060E14**12	12,600	\$1,764
211257817	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58S(B,C)*A070E17**12	12,600	\$1,764
211257816	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58S(B,C)*A045E17**12	12,900	\$1,806
211257815	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58S(B,C)*A045E14**12	12,600	\$1,764
211257814	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6B060V17**14	12,400	\$1,736
211257812	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC5B026E14**10	12,700	\$1,778
211257810	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6B060V14**12	12,500	\$1,750
211257809	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6B040V14**10	12,300	\$1,722
211257808	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC5B060E14**12	12,500	\$1,750
211257807	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC5B040E17**12	12,300	\$1,722
211257805	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SC5B040E14**10	12,500	\$1,750
211257804	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58TP*A070V17**16	12,200	\$1,708
211257802	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6B080V17**16	12,300	\$1,722
211257801	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59TP6B040V17**12	12,500	\$1,750
211257800	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58TP*A090V17**16	12,400	\$1,736
211257799	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58TP*A070V14**12	12,400	\$1,736
211257797	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58TP*A045V14**12	12,400	\$1,736
211257796	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58SU*A040E17**12	12,700	\$1,778
211257794	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58SP*A070V17**16	12,300	\$1,722
211257793	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58SP*A045V17**16	12,400	\$1,736
211257789	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SU5A040E17**12	12,400	\$1,736
211257788	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SP6A080V17**16	12,300	\$1,722
211257786	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SP6A060V14**12	12,500	\$1,750
211257785	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SP6A040V17**12	12,500	\$1,750
211257783	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SP6A040V14**10	12,300	\$1,722
211257782	CARRIER	38MURAQ18AB3*	CAP**2417AL*	59SP6A060V17**14	12,400	\$1,736
211257780	CARRIER	38MURAQ18AB3*	CAP**2417AL*	58SP*A045V14**12	12,400	\$1,736
211257778	CARRIER	38MURAQ18AB3*	CAP**2414AL*	58S(B,C)*A070E14**12	12,300	\$1,722
211257777	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SC2D040E14**10	12,600	\$1,764
211257776	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SC2D060E14**12	12,600	\$1,764
211257775	CARRIER	38MURAQ18AB3*	CAP**2414AL*	58S(B,C)*A045E14**12	12,600	\$1,764
211257773	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SC5B026E14**10	12,600	\$1,764
211257772	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59TP6B060V14**12	12,500	\$1,750
211257771	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59TP6B040V14**10	12,300	\$1,722
211257770	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SC5B060E14**12	12,500	\$1,750
211257769	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SC5B040E14**10	12,500	\$1,750
211257767	CARRIER	38MURAQ18AB3*	CAP**2414AL*	58TP*A070V14**12	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211257766	CARRIER	38MURAQ18AB3*	CAP**2414AL*	58TP*A045V14**12	12,400	\$1,736
211257765	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SP6A060V14**12	12,500	\$1,750
211257764	CARRIER	38MURAQ18AB3*	CAP**2414AL*	59SP6A040V14**10	12,300	\$1,722
211257762	CARRIER	38MURAQ18AB3*	CAP**2414AL*	58SP*A045V14**12	12,400	\$1,736
211257761	CARRIER	38MURAQ18AB3*	CAP**1917AL*	OVMAAB042112	12,600	\$1,764
211257760	CARRIER	38MURAQ18AB3*	CAP**1917AL*	OVLAAB036098	12,500	\$1,750
211257759	CARRIER	38MURAQ18AB3*	CAP**1917AL*	OVMAAB036098	12,600	\$1,764
211257758	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58SU*A060E17**16	12,700	\$1,778
211257757	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58S(B,C)*A070E14**12	12,200	\$1,708
211257756	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC2D040E17**12	12,400	\$1,736
211257754	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC2D040E14**10	12,400	\$1,736
211257752	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC2D060E17**14	12,200	\$1,708
211257751	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC2D060E14**12	12,500	\$1,750
211257750	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58S(B,C)*A070E17**12	12,400	\$1,736
211257749	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58S(B,C)*A045E17**12	12,700	\$1,778
211257747	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58S(B,C)*A045E14**12	12,400	\$1,736
211257746	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59TP6B060V17**14	12,300	\$1,722
211257744	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC5B026E14**10	12,500	\$1,750
211257743	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59TP6B060V14**12	12,400	\$1,736
211257742	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59TP6B040V14**10	12,100	\$1,694
211257741	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC5B060E14**12	12,300	\$1,722
211257739	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC5B040E17**12	12,100	\$1,694
211257738	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SC5B040E14**10	12,400	\$1,736
211257736	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58TP*A070V17**16	12,000	\$1,680
211257735	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59TP6B080V17**16	12,100	\$1,694
211257734	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59TP6B040V17**12	12,300	\$1,722
211257733	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58TP*A090V17**16	12,200	\$1,708
211257732	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58TP*A070V14**12	12,200	\$1,708
211257730	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58TP*A045V14**12	12,200	\$1,708
211257729	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58SU*A040E17**12	12,600	\$1,764
211257727	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58SP*A070V17**16	12,100	\$1,694
211257726	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58SP*A045V17**16	12,200	\$1,708
211257722	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SU5A040E17**12	12,200	\$1,708
211257720	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SP6A080V17**16	12,100	\$1,694
211257719	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SP6A060V14**12	12,400	\$1,736
211257718	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SP6A040V17**12	12,300	\$1,722
211257717	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SP6A040V14**10	12,100	\$1,694
211257716	CARRIER	38MURAQ18AB3*	CAP**1917AL*	59SP6A060V17**14	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211257712	CARRIER	38MURAQ18AB3*	CAP**1917AL*	58SP*A045V14**12	12,300	\$1,722
211257345	CARRIER	38MURAQ18AB3*	PF4MN*B24L*		12,800	\$1,792
211257311	CARRIER	38MURAQ18AB3*	FJ4DN*B24L*		12,800	\$1,792
212600439	CARRIER	25VNA837A*031*	CNPV*3017AL*+UI	58TN*A090C17**16	31,200	\$4,368
212600389	CARRIER	25VNA837A*031*	CAP**3017AL*+UI	58TN*A090C17**16	31,000	\$4,340
212600379	CARRIER	25VNA837A*031*	CAP**3017AL*+UI	58TN*A070C14**12	31,200	\$4,368
212600369	CARRIER	25VNA837A*031*	CAP**3017AL*+UI	58TN*A070C17**16	31,200	\$4,368
212600359	CARRIER	25VNA837A*031*	CAP**3017AL*+UI	58CU*A060C17**16	31,200	\$4,368
212600349	CARRIER	25VNA837A*031*	CAP**3017AL*+UI	58CU*A040C17**12	31,200	\$4,368
210471320	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	59MN7B060C21**20	31,600	\$4,424
210471298	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	58TN*A090C17**16	31,200	\$4,368
210471276	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	59TN6B100C21**22	31,200	\$4,368
210471254	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	59MN7B120C24**22	31,400	\$4,396
210471243	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	59MN7B100C21**22	31,200	\$4,368
210471221	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	59MN7B080C17**14	31,600	\$4,424
210471210	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	59TN6B120C24**22	31,200	\$4,368
210471199	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	59TN6B080C17**14	31,600	\$4,424
210471177	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	58TN*A090C21**20	31,400	\$4,396
210471166	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	58TN*A070C17**16	31,400	\$4,396
210471155	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	58CU*A100C21**20	31,400	\$4,396
210471144	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	58CU*A060C17**16	31,400	\$4,396
210471133	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	58CU*A040C17**12	31,400	\$4,396
210471122	CARRIER	25VNA837A*031*	CSPH*6012AL*+UI	59CU5A100C21**22	31,200	\$4,368
210471052	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	58CU*A100C21**20	31,600	\$4,424
210471041	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	58CU*A060C17**16	31,600	\$4,424
210471030	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	58CU*A040C17**12	31,600	\$4,424
210471018	CARRIER	25VNA837A*031*	CSPH*3612AL*+UI	59CU5A080C21**20	31,600	\$4,424
210471007	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	59MN7B060C21**20	31,600	\$4,424
210470985	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	59TN6B100C21**22	31,200	\$4,368
210470963	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	59MN7B120C24**22	31,400	\$4,396
210470952	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	59MN7B100C21**22	31,200	\$4,368
210470930	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	59TN6B120C24**22	31,200	\$4,368
210470919	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	58TN*A135C24**22	31,200	\$4,368
210470908	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	58TN*A090C21**20	31,400	\$4,396
210470897	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	58CU*A100C21**20	31,400	\$4,396
210470886	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	59CU5A100C21**22	31,200	\$4,368
210470875	CARRIER	25VNA837A*031*	CNPV*6024AL*+UI	59CU5A080C21**20	31,200	\$4,368
210470854	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	58CU*A100C21**20	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210470843	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	59CU5A100C21**22	31,400	\$4,396
210470832	CARRIER	25VNA837A*031*	CNPV*4824AL*+UI	59CU5A080C21**20	31,400	\$4,396
210470809	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	58CU*A060C17**16	31,600	\$4,424
210470798	CARRIER	25VNA837A*031*	CNPV*4821AL*+UI	58CU*A040C17**12	31,600	\$4,424
210470776	CARRIER	25VNA837A*031*	CNPV*4221AL*+UI	58CU*A060C17**16	31,600	\$4,424
210470745	CARRIER	25VNA837A*031*	CNPV*3621AL*+UI	59TN6B100C21**22	31,200	\$4,368
210470723	CARRIER	25VNA837A*031*	CNPV*3621AL*+UI	59MN7B100C21**22	31,200	\$4,368
210470649	CARRIER	25VNA837A*031*	CAP**6124AL*+UI	59MN7B060C21**20	31,400	\$4,396
210470627	CARRIER	25VNA837A*031*	CAP**6124AL*+UI	59TN6B100C21**22	31,200	\$4,368
210470605	CARRIER	25VNA837A*031*	CAP**6124AL*+UI	59MN7B120C24**22	31,200	\$4,368
210470594	CARRIER	25VNA837A*031*	CAP**6124AL*+UI	59MN7B100C21**22	31,200	\$4,368
210470572	CARRIER	25VNA837A*031*	CAP**6124AL*+UI	59TN6B120C24**22	31,200	\$4,368
210470561	CARRIER	25VNA837A*031*	CAP**6124AL*+UI	58TN*A135C24**22	31,200	\$4,368
210470539	CARRIER	25VNA837A*031*	CAP**6124AL*+UI	58CU*A100C21**20	31,200	\$4,368
210470517	CARRIER	25VNA837A*031*	CAP**6124AL*+UI	59CU5A080C21**20	31,200	\$4,368
210470495	CARRIER	25VNA837A*031*	CAP**6121AL*+UI	58TN*A090C17**16	31,200	\$4,368
210470484	CARRIER	25VNA837A*031*	CAP**6121AL*+UI	59TN6B100C21**22	31,200	\$4,368
210470462	CARRIER	25VNA837A*031*	CAP**6121AL*+UI	59MN7B100C21**22	31,200	\$4,368
210470440	CARRIER	25VNA837A*031*	CAP**6121AL*+UI	58TN*A090C21**20	31,200	\$4,368
210470418	CARRIER	25VNA837A*031*	CAP**6121AL*+UI	58CU*A100C21**20	31,400	\$4,396
210470407	CARRIER	25VNA837A*031*	CAP**6121AL*+UI	58CU*A060C17**16	31,400	\$4,396
210470396	CARRIER	25VNA837A*031*	CAP**6121AL*+UI	58CU*A040C17**12	31,400	\$4,396
210470363	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	59MN7B060C21**20	31,400	\$4,396
210470341	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	59TN6B100C21**22	31,000	\$4,340
210470319	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	59MN7B120C24**22	31,200	\$4,368
210470308	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	59MN7B100C21**22	31,000	\$4,340
210470286	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	59TN6B120C24**22	31,000	\$4,340
210470275	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	58TN*A135C24**22	31,000	\$4,340
210470264	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	58TN*A090C21**20	31,000	\$4,340
210470253	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	58CU*A100C21**20	31,200	\$4,368
210470242	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	59CU5A100C21**22	31,000	\$4,340
210470231	CARRIER	25VNA837A*031*	CAP**6024AL*+UI	59CU5A080C21**20	31,000	\$4,340
210470157	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	58CU*A100C21**20	31,400	\$4,396
210470145	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	58CU*A040C17**12	31,400	\$4,396
210470133	CARRIER	25VNA837A*031*	CAP**4221AL*+UI	59CU5A080C21**20	31,200	\$4,368
210470098	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	58CU*A100C21**20	31,200	\$4,368
210470087	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	58CU*A060C17**16	31,200	\$4,368
210470076	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	58CU*A040C17**12	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210470054	CARRIER	25VNA837A*031*	CAP**3621AL*+UI	59CU5A080C21**20	31,000	\$4,340
210470040	CARRIER	25VNA837A*031*	CAP**3617AL*+UI	58CU*A060C17**16	31,400	\$4,396
212614002	CARRIER	25VNA837A*030*	CNPV*3017AL*+UI	58TN*A090C17**16	31,200	\$4,368
212613992	CARRIER	25VNA837A*030*	CAP**3017AL*+UI	58TN*A090C17**16	31,000	\$4,340
212613983	CARRIER	25VNA837A*030*	CAP**3017AL*+UI	58TN*A070C17**16	31,200	\$4,368
212613972	CARRIER	25VNA837A*030*	CAP**3017AL*+UI	58TN*A070C14**12	31,200	\$4,368
212613962	CARRIER	25VNA837A*030*	CAP**3017AL*+UI	58CU*A060C17**16	31,200	\$4,368
212613953	CARRIER	25VNA837A*030*	CAP**3017AL*+UI	58CU*A040C17**12	31,200	\$4,368
210596257	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	59TN6B120C24**22	31,200	\$4,368
210596256	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	59TN6B100C21**22	31,200	\$4,368
210596254	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	59TN6B080C17**14	31,600	\$4,424
210596253	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	59MN7B120C24**22	31,400	\$4,396
210596252	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	59MN7B100C21**22	31,200	\$4,368
210596250	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	59MN7B080C17**14	31,600	\$4,424
210596249	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	59MN7B060C21**20	31,600	\$4,424
210596248	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	59CU5A100C21**22	31,200	\$4,368
210596247	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	59CU5A080C21**20	31,200	\$4,368
210596246	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	58TN*A135C24**22	31,200	\$4,368
210596244	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	58TN*A090C21**20	31,400	\$4,396
210596243	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	58TN*A090C17**16	31,200	\$4,368
210596241	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	58TN*A070C14**12	31,400	\$4,396
210596240	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	58CU*A100C21**20	31,400	\$4,396
210596239	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	58CU*A060C17**16	31,400	\$4,396
210596238	CARRIER	25VNA837A*030*	CSPH*6012AL*+UI	58CU*A040C17**12	31,400	\$4,396
210596237	CARRIER	25VNA837A*030*	CSPH*3612AL*+UI	59CU5A080C21**20	31,600	\$4,424
210596236	CARRIER	25VNA837A*030*	CSPH*3612AL*+UI	58CU*A100C21**20	31,600	\$4,424
210596235	CARRIER	25VNA837A*030*	CSPH*3612AL*+UI	58CU*A060C17**16	31,600	\$4,424
210596234	CARRIER	25VNA837A*030*	CSPH*3612AL*+UI	58CU*A040C17**12	31,600	\$4,424
210596233	CARRIER	25VNA837A*030*	CNPV*6024AL*+UI	59TN6B120C24**22	31,200	\$4,368
212596825	CARRIER	25VNA424A*031*	CNPV*3017AL*+UI	59MN7B060C17**14	25,200	\$3,528
210533114	CARRIER	25VNA424A*031*	CSPH*4212AL*+UI	58CU*A060C17**16	24,600	\$3,444
210533112	CARRIER	25VNA424A*031*	CSPH*4212AL*+UI	58CU*A040C17**12	24,600	\$3,444
210533106	CARRIER	25VNA424A*031*	CSPH*4212AL*+UI	59CU5A060C17**16	24,800	\$3,472
210533102	CARRIER	25VNA424A*031*	CSPH*3012AL*+UI	58TN*A090C17**16	24,800	\$3,472
210533100	CARRIER	25VNA424A*031*	CSPH*3012AL*+UI	58TN*A070C14**12	25,000	\$3,500
210533098	CARRIER	25VNA424A*031*	CSPH*3012AL*+UI	59MN7B080C17**14	25,200	\$3,528
210533096	CARRIER	25VNA424A*031*	CSPH*3012AL*+UI	59TN6B080C17**14	25,000	\$3,500
210533094	CARRIER	25VNA424A*031*	CSPH*3012AL*+UI	59TN6B060C17**14	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210533090	CARRIER	25VNA424A*031*	CSPH*3012AL*+UI	58CU*A060C17**16	25,000	\$3,500
210533088	CARRIER	25VNA424A*031*	CSPH*3012AL*+UI	58CU*A040C17**12	25,000	\$3,500
210533082	CARRIER	25VNA424A*031*	CSPH*3012AL*+UI	59CU5A060C17**16	25,200	\$3,528
210533080	CARRIER	25VNA424A*031*	CNPV*4221AL*+UI	58CU*A060C17**16	24,800	\$3,472
210533078	CARRIER	25VNA424A*031*	CNPV*4221AL*+UI	58CU*A040C17**12	24,800	\$3,472
210533076	CARRIER	25VNA424A*031*	CNPV*4221AL*+UI	59CU5A100C21**22	24,800	\$3,472
210533072	CARRIER	25VNA424A*031*	CNPV*4221AL*+UI	59CU5A060C17**16	25,000	\$3,500
210533070	CARRIER	25VNA424A*031*	CNPV*4217AL*+UI	58CU*A060C17**16	24,800	\$3,472
210533068	CARRIER	25VNA424A*031*	CNPV*4217AL*+UI	58CU*A040C17**12	24,800	\$3,472
210533066	CARRIER	25VNA424A*031*	CNPV*4217AL*+UI	59CU5A060C17**16	25,000	\$3,500
210533064	CARRIER	25VNA424A*031*	CNPV*3017AL*+UI	58TN*A090C17**16	24,800	\$3,472
210533062	CARRIER	25VNA424A*031*	CNPV*3017AL*+UI	58TN*A070C14**12	25,000	\$3,500
210533060	CARRIER	25VNA424A*031*	CNPV*3017AL*+UI	59MN7B080C17**14	25,200	\$3,528
210533058	CARRIER	25VNA424A*031*	CNPV*3017AL*+UI	59TN6B080C17**14	25,000	\$3,500
210533056	CARRIER	25VNA424A*031*	CNPV*3017AL*+UI	59TN6B060C17**14	25,200	\$3,528
210533052	CARRIER	25VNA424A*031*	CNPV*3017AL*+UI	58CU*A060C17**16	25,000	\$3,500
210533050	CARRIER	25VNA424A*031*	CNPV*3017AL*+UI	58CU*A040C17**12	25,000	\$3,500
210533046	CARRIER	25VNA424A*031*	CAP**4321AL*+UI	59MN7B060C21**20	24,800	\$3,472
210533044	CARRIER	25VNA424A*031*	CAP**4321AL*+UI	58TN*A090C17**16	24,600	\$3,444
210533042	CARRIER	25VNA424A*031*	CAP**4321AL*+UI	59MN7B080C17**14	24,800	\$3,472
210533040	CARRIER	25VNA424A*031*	CAP**4321AL*+UI	59TN6B080C17**14	24,800	\$3,472
210533038	CARRIER	25VNA424A*031*	CAP**4321AL*+UI	59TN6B060C17**14	24,800	\$3,472
210533034	CARRIER	25VNA424A*031*	CAP**4321AL*+UI	58CU*A060C17**16	24,600	\$3,444
210533032	CARRIER	25VNA424A*031*	CAP**4321AL*+UI	58CU*A040C17**12	24,600	\$3,444
210533026	CARRIER	25VNA424A*031*	CAP**4321AL*+UI	59CU5A060C17**16	24,800	\$3,472
210533024	CARRIER	25VNA424A*031*	CAP**4224AL*+UI	59CU5A100C21**22	24,800	\$3,472
210533020	CARRIER	25VNA424A*031*	CAP**4221AL*+UI	58CU*A060C17**16	24,800	\$3,472
210533018	CARRIER	25VNA424A*031*	CAP**4221AL*+UI	58CU*A040C17**12	24,800	\$3,472
210533010	CARRIER	25VNA424A*031*	CAP**3721AL*+UI	59MN7B060C21**20	24,800	\$3,472
210533008	CARRIER	25VNA424A*031*	CAP**3721AL*+UI	58TN*A090C17**16	24,600	\$3,444
210533006	CARRIER	25VNA424A*031*	CAP**3721AL*+UI	59MN7B080C17**14	24,800	\$3,472
210533004	CARRIER	25VNA424A*031*	CAP**3721AL*+UI	59TN6B080C17**14	24,800	\$3,472
210533002	CARRIER	25VNA424A*031*	CAP**3721AL*+UI	59TN6B060C17**14	24,800	\$3,472
210532998	CARRIER	25VNA424A*031*	CAP**3721AL*+UI	58CU*A060C17**16	24,600	\$3,444
210532996	CARRIER	25VNA424A*031*	CAP**3721AL*+UI	58CU*A040C17**12	24,600	\$3,444
210532990	CARRIER	25VNA424A*031*	CAP**3721AL*+UI	59CU5A060C17**16	24,800	\$3,472
210532988	CARRIER	25VNA424A*031*	CAP**3017AL*+UI	58TN*A090C17**16	24,800	\$3,472
210532986	CARRIER	25VNA424A*031*	CAP**3017AL*+UI	58TN*A070C14**12	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210532984	CARRIER	25VNA424A*031*	CAP**3017AL*+UI	59MN7B080C17**14	25,200	\$3,528
210532982	CARRIER	25VNA424A*031*	CAP**3017AL*+UI	59TN6B080C17**14	25,000	\$3,500
210532980	CARRIER	25VNA424A*031*	CAP**3017AL*+UI	59TN6B060C17**14	25,200	\$3,528
210532974	CARRIER	25VNA424A*031*	CAP**3017AL*+UI	58CU*A060C17**16	25,000	\$3,500
210532972	CARRIER	25VNA424A*031*	CAP**3017AL*+UI	58CU*A040C17**12	25,000	\$3,500
210532970	CARRIER	25VNA424A*031*	CAP**3017AL*+UI	59CU5A060C17**16	25,200	\$3,528
210532968	CARRIER	25VNA424A*031*	CAP**3014AL*+UI	58TN*A070C14**12	25,000	\$3,500
210532964	CARRIER	25VNA424A*031*	CAP**2517AL*+UI	58TN*A070C14**12	24,800	\$3,472
210532962	CARRIER	25VNA424A*031*	CAP**2517AL*+UI	59MN7B080C17**14	25,000	\$3,500
210532960	CARRIER	25VNA424A*031*	CAP**2517AL*+UI	59TN6B080C17**14	24,800	\$3,472
210532958	CARRIER	25VNA424A*031*	CAP**2517AL*+UI	59TN6B060C17**14	25,000	\$3,500
210532956	CARRIER	25VNA424A*031*	CAP**2517AL*+UI	58TN*A070C17**16	24,800	\$3,472
210532954	CARRIER	25VNA424A*031*	CAP**2517AL*+UI	58CU*A060C17**16	24,800	\$3,472
210532952	CARRIER	25VNA424A*031*	CAP**2517AL*+UI	58CU*A040C17**12	24,800	\$3,472
210532944	CARRIER	25VNA424A*031*	CAP**2417AL*+UI	59MN7B080C17**14	25,400	\$3,556
210532942	CARRIER	25VNA424A*031*	CAP**2417AL*+UI	59TN6B080C17**14	25,200	\$3,528
210532940	CARRIER	25VNA424A*031*	CAP**2417AL*+UI	59TN6B060C17**14	25,400	\$3,556
210532938	CARRIER	25VNA424A*031*	CAP**2417AL*+UI	58TN*A070C17**16	25,200	\$3,528
210532936	CARRIER	25VNA424A*031*	CAP**2417AL*+UI	58CU*A060C17**16	25,200	\$3,528
201863358	CARRIER	38VMA036HDS3-1	Heat pump with ducts		25,000	\$3,500
205282596	CARRIER	38VMB036HDS3-1	Heat pump with ducts		25,000	\$3,500
201863360	CARRIER	38VMA048HDS3-1	Heat pump with ducts		34,000	\$4,760
205282599	CARRIER	38VMB048HDS3-1	Heat pump with ducts		34,000	\$4,760
204722797	CARRIER	38MGRQ30D--3	Combination heat pumps with or without ducts		20,200	\$2,828
204722798	CARRIER	38MGRQ36D--3	Combination heat pumps with or without ducts		23,800	\$3,332
204711112	CARRIER	38MGRQ30D--3	Heat pump with ducts		23,000	\$3,220
202345968	CARRIER	38MGRQ36D--3	Heat pump with ducts		24,600	\$3,444
200059145	CARRIER	38MAQB24R--3	40MBDQ24---3		17,300	\$2,422
200059155	CARRIER	38MAQB12R--3	40MBCQ12---3		8,700	\$1,218
201847015	CARRIER	38MAQB24R--3	40MBFQ24---3		17,200	\$2,408
201847017	CARRIER	38MBRQ48A--3	40MBFQ48---3		35,000	\$4,900
201753411	CARRIER	38MPRAQ12AA3	40MPHAQ12XA3		6,800	\$952
202463635	CARRIER	38MPRAQ24AA3	40MPHAQ24XA3		15,450	\$2,163
205282600	CARRIER	38VMB048HDS3-1	Combination heat pumps with or without ducts		34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205282597	CARRIER	38VMB036HDS3-1	Combination heat pumps with or without ducts		25,000	\$3,500
8738636	CARRIER	38MAQB12R--3	40MAQB12B--3		7,800	\$1,092
206350331	CARRIER	38MARBQ12AA3	40MBFQ12--3		8,400	\$1,176
206350329	CARRIER	38MARBQ12AA3	40MBCQ12--3		7,900	\$1,106
206396031	CARRIER	38MAQB12R--3	40MAHBQ12XA3		7,500	\$1,050
206350330	CARRIER	38MARBQ12AA3	40MBDQ12--3		8,300	\$1,162
206350336	CARRIER	38MARBQ24AA3	40MBDQ24--3		14,500	\$2,030
205921384	CARRIER	38MAQB24R--3	40MBAAQ24XA3		17,500	\$2,450
206350334	CARRIER	38MARBQ18AA3	40MBFQ18--3		12,000	\$1,680
206350335	CARRIER	38MARBQ24AA3	40MBCQ24--3		14,500	\$2,030
206350337	CARRIER	38MARBQ24AA3	40MBFQ24--3		14,500	\$2,030
206348136	CARRIER	38MARBQ12AA3	40MAHBQ12XA3		7,500	\$1,050
206348138	CARRIER	38MARBQ24AA3	40MAHBQ24XA3		19,800	\$2,772
206188253	CARRIER	38MARBQ24AA3	40MBAAQ24XA3		16,500	\$2,310
206350333	CARRIER	38MARBQ18AA3	40MBDQ18--3		12,700	\$1,778
206788602	CARRIER	25VNA436A*031*	CAP**4221AL*+UI	58TN*A110C21**20	33,800	\$4,732
206788598	CARRIER	25VNA436A*031*	CAP**4221AL*+UI	59MN7B100C21**22	33,800	\$4,732
206788725	CARRIER	25VNA436A*031*	CNPV*4824AL*+UI	59TN6B080C21**20	33,600	\$4,704
206788722	CARRIER	25VNA436A*031*	CNPV*4824AL*+UI	59MN7B080C21**20	33,600	\$4,704
206788718	CARRIER	25VNA436A*031*	CNPV*4824AL*+UI	58TN*A070C21**20	33,600	\$4,704
206788713	CARRIER	25VNA436A*031*	CNPV*4821AL*+UI	59TN6B080C21**20	33,600	\$4,704
206788711	CARRIER	25VNA436A*031*	CNPV*4821AL*+UI	59MN7B080C21**20	33,600	\$4,704
206788773	CARRIER	25VNA436A*031*	CSPH*4812AL*+UI	58TN*A070C21**20	33,600	\$4,704
206788706	CARRIER	25VNA436A*031*	CNPV*4821AL*+UI	58TN*A070C21**20	33,600	\$4,704
206788767	CARRIER	25VNA436A*031*	CSPH*4212AL*+UI	59TN6B080C21**20	33,600	\$4,704
206788764	CARRIER	25VNA436A*031*	CSPH*4212AL*+UI	59MN7B080C21**20	33,600	\$4,704
206788757	CARRIER	25VNA436A*031*	CSPH*4212AL*+UI	58TN*A070C21**20	33,600	\$4,704
206788580	CARRIER	25VNA436A*031*	CAP**3721AL*+UI	58TN*A070C21**20	33,800	\$4,732
206788727	CARRIER	25VNA436A*031*	CNPV*4824AL*+UI	58TN*A110C21**20	33,400	\$4,676
206788723	CARRIER	25VNA436A*031*	CNPV*4824AL*+UI	59MN7B100C21**22	33,400	\$4,676
206788726	CARRIER	25VNA436A*031*	CNPV*4824AL*+UI	59TN6B100C21**22	33,400	\$4,676
206788719	CARRIER	25VNA436A*031*	CNPV*4824AL*+UI	58TN*A090C21**20	33,400	\$4,676
206788716	CARRIER	25VNA436A*031*	CNPV*4821AL*+UI	58TN*A110C21**20	33,400	\$4,676
206788714	CARRIER	25VNA436A*031*	CNPV*4821AL*+UI	59TN6B100C21**22	33,400	\$4,676
206788712	CARRIER	25VNA436A*031*	CNPV*4821AL*+UI	59MN7B100C21**22	33,400	\$4,676
206788590	CARRIER	25VNA436A*031*	CAP**3721AL*+UI	58TN*A110C21**20	33,600	\$4,704
206788707	CARRIER	25VNA436A*031*	CNPV*4821AL*+UI	58TN*A090C21**20	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206788588	CARRIER	25VNA436A*031*	CAP**3721AL*+UI	59TN6B100C21**22	33,600	\$4,704
206788586	CARRIER	25VNA436A*031*	CAP**3721AL*+UI	59MN7B100C21**22	33,600	\$4,704
206788786	CARRIER	25VNA436A*031*	CSPH*4812AL*+UI	58TN*A110C21**20	33,400	\$4,676
206788784	CARRIER	25VNA436A*031*	CSPH*4812AL*+UI	59TN6B100C21**22	33,400	\$4,676
206788783	CARRIER	25VNA436A*031*	CSPH*4812AL*+UI	59TN6B080C21**20	33,600	\$4,704
206788781	CARRIER	25VNA436A*031*	CSPH*4812AL*+UI	59MN7B100C21**22	33,400	\$4,676
206788780	CARRIER	25VNA436A*031*	CSPH*4812AL*+UI	59MN7B080C21**20	33,600	\$4,704
206788770	CARRIER	25VNA436A*031*	CSPH*4212AL*+UI	58TN*A110C21**20	33,400	\$4,676
206788768	CARRIER	25VNA436A*031*	CSPH*4212AL*+UI	59TN6B100C21**22	33,400	\$4,676
206788765	CARRIER	25VNA436A*031*	CSPH*4212AL*+UI	59MN7B100C21**22	33,400	\$4,676
206788758	CARRIER	25VNA436A*031*	CSPH*4212AL*+UI	58TN*A090C21**20	33,400	\$4,676
206788641	CARRIER	25VNA436A*031*	CAP**4824AL*+UI	58TN*A070C21**20	33,400	\$4,676
206788636	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	59TN6B080C21**20	33,400	\$4,676
206788623	CARRIER	25VNA436A*031*	CAP**4321AL*+UI	59TN6B080C21**20	33,600	\$4,704
206788621	CARRIER	25VNA436A*031*	CAP**4321AL*+UI	59MN7B080C21**20	33,600	\$4,704
206788616	CARRIER	25VNA436A*031*	CAP**4321AL*+UI	58TN*A070C21**20	33,600	\$4,704
206788587	CARRIER	25VNA436A*031*	CAP**3721AL*+UI	59TN6B080C21**20	33,600	\$4,704
206788581	CARRIER	25VNA436A*031*	CAP**3721AL*+UI	58TN*A090C21**20	33,400	\$4,676
206788585	CARRIER	25VNA436A*031*	CAP**3721AL*+UI	59MN7B080C21**20	33,600	\$4,704
206788634	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	59MN7B080C21**20	33,400	\$4,676
206788729	CARRIER	25VNA436A*031*	CNPV*6024AL*+UI	58TN*A070C21**20	33,200	\$4,648
206788629	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	58TN*A070C21**20	33,600	\$4,704
206788664	CARRIER	25VNA436A*031*	CAP**6121AL*+UI	58TN*A070C21**20	33,200	\$4,648
206788650	CARRIER	25VNA436A*031*	CAP**4824AL*+UI	58TN*A110C21**20	33,200	\$4,648
206788626	CARRIER	25VNA436A*031*	CAP**4321AL*+UI	58TN*A110C21**20	33,400	\$4,676
206788642	CARRIER	25VNA436A*031*	CAP**4824AL*+UI	58TN*A090C21**20	33,200	\$4,648
206788624	CARRIER	25VNA436A*031*	CAP**4321AL*+UI	59TN6B100C21**22	33,400	\$4,676
206788622	CARRIER	25VNA436A*031*	CAP**4321AL*+UI	59MN7B100C21**22	33,400	\$4,676
206788617	CARRIER	25VNA436A*031*	CAP**4321AL*+UI	58TN*A090C21**20	33,400	\$4,676
206788774	CARRIER	25VNA436A*031*	CSPH*4812AL*+UI	58TN*A090C21**20	33,400	\$4,676
206788649	CARRIER	25VNA436A*031*	CAP**4824AL*+UI	59TN6B100C21**22	33,200	\$4,648
206788646	CARRIER	25VNA436A*031*	CAP**4824AL*+UI	59MN7B100C21**22	33,200	\$4,648
206788637	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	59TN6B100C21**22	33,400	\$4,676
206788635	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	59MN7B100C21**22	33,400	\$4,676
206788639	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	58TN*A110C21**20	33,400	\$4,676
206788648	CARRIER	25VNA436A*031*	CAP**4824AL*+UI	59TN6B080C21**20	33,400	\$4,676
206788645	CARRIER	25VNA436A*031*	CAP**4824AL*+UI	59MN7B080C21**20	33,400	\$4,676
206788738	CARRIER	25VNA436A*031*	CNPV*6024AL*+UI	58TN*A110C21**20	33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206788737	CARRIER	25VNA436A*031*	CNPV*6024AL*+UI	59TN6B100C21**22	33,000	\$4,620
206788630	CARRIER	25VNA436A*031*	CAP**4821AL*+UI	58TN*A090C21**20	33,200	\$4,648
206788736	CARRIER	25VNA436A*031*	CNPV*6024AL*+UI	59TN6B080C21**20	33,200	\$4,648
206788733	CARRIER	25VNA436A*031*	CNPV*6024AL*+UI	59MN7B080C21**20	33,200	\$4,648
206788734	CARRIER	25VNA436A*031*	CNPV*6024AL*+UI	59MN7B100C21**22	33,000	\$4,620
206788730	CARRIER	25VNA436A*031*	CNPV*6024AL*+UI	58TN*A090C21**20	33,000	\$4,620
206788676	CARRIER	25VNA436A*031*	CAP**6124AL*+UI	58TN*A070C21**20	33,200	\$4,648
206788683	CARRIER	25VNA436A*031*	CAP**6124AL*+UI	59TN6B080C21**20	33,200	\$4,648
206788674	CARRIER	25VNA436A*031*	CAP**6121AL*+UI	58TN*A110C21**20	33,000	\$4,620
206788671	CARRIER	25VNA436A*031*	CAP**6121AL*+UI	59TN6B080C21**20	33,200	\$4,648
206788680	CARRIER	25VNA436A*031*	CAP**6124AL*+UI	59MN7B080C21**20	33,200	\$4,648
206788669	CARRIER	25VNA436A*031*	CAP**6121AL*+UI	59MN7B080C21**20	33,200	\$4,648
206788670	CARRIER	25VNA436A*031*	CAP**6121AL*+UI	59MN7B100C21**22	33,000	\$4,620
206788789	CARRIER	25VNA436A*031*	CSPH*6012AL*+UI	58TN*A070C21**20	33,200	\$4,648
206788672	CARRIER	25VNA436A*031*	CAP**6121AL*+UI	59TN6B100C21**22	33,000	\$4,620
206788802	CARRIER	25VNA436A*031*	CSPH*6012AL*+UI	58TN*A110C21**20	33,000	\$4,620
206788797	CARRIER	25VNA436A*031*	CSPH*6012AL*+UI	59MN7B100C21**22	33,000	\$4,620
206788800	CARRIER	25VNA436A*031*	CSPH*6012AL*+UI	59TN6B100C21**22	33,000	\$4,620
206788685	CARRIER	25VNA436A*031*	CAP**6124AL*+UI	58TN*A110C21**20	33,000	\$4,620
206788684	CARRIER	25VNA436A*031*	CAP**6124AL*+UI	59TN6B100C21**22	33,000	\$4,620
206788681	CARRIER	25VNA436A*031*	CAP**6124AL*+UI	59MN7B100C21**22	33,000	\$4,620
206788665	CARRIER	25VNA436A*031*	CAP**6121AL*+UI	58TN*A090C21**20	33,000	\$4,620
206788677	CARRIER	25VNA436A*031*	CAP**6124AL*+UI	58TN*A090C21**20	33,000	\$4,620
206788799	CARRIER	25VNA436A*031*	CSPH*6012AL*+UI	59TN6B080C21**20	33,000	\$4,620
206788796	CARRIER	25VNA436A*031*	CSPH*6012AL*+UI	59MN7B080C21**20	33,000	\$4,620
206788652	CARRIER	25VNA436A*031*	CAP**6024AL*+UI	58TN*A070C21**20	33,000	\$4,620
206788790	CARRIER	25VNA436A*031*	CSPH*6012AL*+UI	58TN*A090C21**20	32,800	\$4,592
206788659	CARRIER	25VNA436A*031*	CAP**6024AL*+UI	59TN6B080C21**20	33,000	\$4,620
206788657	CARRIER	25VNA436A*031*	CAP**6024AL*+UI	59MN7B100C21**22	32,800	\$4,592
206788660	CARRIER	25VNA436A*031*	CAP**6024AL*+UI	59TN6B100C21**22	32,800	\$4,592
206788656	CARRIER	25VNA436A*031*	CAP**6024AL*+UI	59MN7B080C21**20	33,000	\$4,620
206788661	CARRIER	25VNA436A*031*	CAP**6024AL*+UI	58TN*A110C21**20	32,800	\$4,592
206788653	CARRIER	25VNA436A*031*	CAP**6024AL*+UI	58TN*A090C21**20	32,800	\$4,592
206788546	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	59TN6B120C24**22	23,800	\$3,332
206788543	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	58TN*A135C24**22	23,800	\$3,332
206788545	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	59TN6B080C17**14	24,000	\$3,360
206788544	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	59TN6B060C17**14	24,000	\$3,360
206788539	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	58TN*A045C17**12	24,000	\$3,360

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206788542	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	58TN*A090C21**20	23,800	\$3,332
206788535	CARRIER	25VNA424A*031*	CSPH*4812AL*+UI	58TN*A135C24**22	24,000	\$3,360
206788533	CARRIER	25VNA424A*031*	CSPH*4812AL*+UI	58TN*A070C21**20	24,200	\$3,388
206788530	CARRIER	25VNA424A*031*	CSPH*4212AL*+UI	59TN6B120C24**22	24,200	\$3,388
206788532	CARRIER	25VNA424A*031*	CSPH*4812AL*+UI	58TN*A070C17**16	24,200	\$3,388
206788525	CARRIER	25VNA424A*031*	CSPH*4212AL*+UI	58TN*A070C21**20	24,200	\$3,388
206788522	CARRIER	25VNA424A*031*	CSPH*3612AL*+UI	59TN6B120C24**22	24,200	\$3,388
206788518	CARRIER	25VNA424A*031*	CSPH*3612AL*+UI	58TN*A090C21**20	24,200	\$3,388
206788512	CARRIER	25VNA424A*031*	CNPV*6024AL*+UI	58TN*A090C21**20	23,800	\$3,332
206788513	CARRIER	25VNA424A*031*	CNPV*6024AL*+UI	58TN*A135C24**22	23,800	\$3,332
206788519	CARRIER	25VNA424A*031*	CSPH*3612AL*+UI	58TN*A135C24**22	24,200	\$3,388
206788508	CARRIER	25VNA424A*031*	CNPV*4824AL*+UI	58TN*A090C21**20	24,000	\$3,360
206788504	CARRIER	25VNA424A*031*	CNPV*4821AL*+UI	58TN*A090C21**20	24,000	\$3,360
206788509	CARRIER	25VNA424A*031*	CNPV*4824AL*+UI	58TN*A135C24**22	24,000	\$3,360
206788503	CARRIER	25VNA424A*031*	CNPV*4821AL*+UI	58TN*A070C21**20	24,200	\$3,388
206788502	CARRIER	25VNA424A*031*	CNPV*4821AL*+UI	58TN*A070C17**16	24,200	\$3,388
206788507	CARRIER	25VNA424A*031*	CNPV*4824AL*+UI	58TN*A070C21**20	24,200	\$3,388
206788498	CARRIER	25VNA424A*031*	CNPV*4221AL*+UI	58TN*A090C21**20	24,200	\$3,388
206788487	CARRIER	25VNA424A*031*	CNPV*3621AL*+UI	58TN*A070C21**20	24,400	\$3,416
206788481	CARRIER	25VNA424A*031*	CNPV*3617AL*+UI	58TN*A045C17**12	24,600	\$3,444
206788479	CARRIER	25VNA424A*031*	CAP**6024AL*+UI	58TN*A135C24**22	23,600	\$3,304
206788480	CARRIER	25VNA424A*031*	CAP**6024AL*+UI	59TN6B120C24**22	23,600	\$3,304
206788476	CARRIER	25VNA424A*031*	CAP**4824AL*+UI	59TN6B120C24**22	24,000	\$3,360
206788473	CARRIER	25VNA424A*031*	CAP**4824AL*+UI	58TN*A070C21**20	24,000	\$3,360
206788471	CARRIER	25VNA424A*031*	CAP**4821AL*+UI	59TN6B060C17**14	24,200	\$3,388
206788469	CARRIER	25VNA424A*031*	CAP**4821AL*+UI	58TN*A070C21**20	24,000	\$3,360
206788468	CARRIER	25VNA424A*031*	CAP**4821AL*+UI	58TN*A070C17**16	24,000	\$3,360
206788467	CARRIER	25VNA424A*031*	CAP**4821AL*+UI	58TN*A045C17**12	24,200	\$3,388
206788478	CARRIER	25VNA424A*031*	CAP**6024AL*+UI	58TN*A090C21**20	23,600	\$3,304
206788466	CARRIER	25VNA424A*031*	CAP**4224AL*+UI	59TN6B120C24**22	24,200	\$3,388
206788464	CARRIER	25VNA424A*031*	CAP**4224AL*+UI	58TN*A090C21**20	24,200	\$3,388
206788463	CARRIER	25VNA424A*031*	CAP**4224AL*+UI	58TN*A070C21**20	24,200	\$3,388
206788460	CARRIER	25VNA424A*031*	CAP**4221AL*+UI	58TN*A090C21**20	24,200	\$3,388
206788459	CARRIER	25VNA424A*031*	CAP**4221AL*+UI	58TN*A070C21**20	24,200	\$3,388
206788446	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	58TN*A110C21**20	23,800	\$3,332
206788454	CARRIER	25VNA424A*031*	CAP**3621AL*+UI	58TN*A090C21**20	24,200	\$3,388
206788443	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	59MN7B120C24**22	23,800	\$3,332
206788442	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	59MN7B100C21**22	23,800	\$3,332

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206788445	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	58TN*A090C17**16	23,800	\$3,332
206788435	CARRIER	25VNA424A*031*	CSPH*4812AL*+UI	58TN*A070C14**12	24,200	\$3,388
206788441	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	59MN7B080C21**20	23,800	\$3,332
206788439	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	59MN7B080C17**14	24,000	\$3,360
206788419	CARRIER	25VNA424A*031*	CSPH*3612AL*+UI	58TN*A110C21**20	24,200	\$3,388
206788423	CARRIER	25VNA424A*031*	CSPH*4212AL*+UI	59MN7B080C21**20	24,200	\$3,388
206788416	CARRIER	25VNA424A*031*	CSPH*3612AL*+UI	59MN7B120C24**22	24,200	\$3,388
206788415	CARRIER	25VNA424A*031*	CSPH*3612AL*+UI	59MN7B100C21**22	24,200	\$3,388
206788408	CARRIER	25VNA424A*031*	CNPV*6024AL*+UI	59MN7B100C21**22	23,800	\$3,332
206788425	CARRIER	25VNA424A*031*	CSPH*4212AL*+UI	59MN7B120C24**22	24,200	\$3,388
206788410	CARRIER	25VNA424A*031*	CNPV*6024AL*+UI	58TN*A110C21**20	23,800	\$3,332
206788406	CARRIER	25VNA424A*031*	CNPV*6024AL*+UI	59MN7B060C21**20	24,000	\$3,360
206788405	CARRIER	25VNA424A*031*	CNPV*4824AL*+UI	58TN*A110C21**20	24,000	\$3,360
206788401	CARRIER	25VNA424A*031*	CNPV*4824AL*+UI	59MN7B060C21**20	24,200	\$3,388
206788400	CARRIER	25VNA424A*031*	CNPV*4821AL*+UI	58TN*A110C21**20	24,000	\$3,360
206788395	CARRIER	25VNA424A*031*	CNPV*4821AL*+UI	59MN7B080C17**14	24,200	\$3,388
206788393	CARRIER	25VNA424A*031*	CNPV*4221AL*+UI	58TN*A110C21**20	24,200	\$3,388
206788396	CARRIER	25VNA424A*031*	CNPV*4821AL*+UI	59MN7B060C21**20	24,200	\$3,388
206788380	CARRIER	25VNA424A*031*	CNPV*3621AL*+UI	59MN7B100C21**22	24,400	\$3,416
206788371	CARRIER	25VNA424A*031*	CAP**6024AL*+UI	58TN*A110C21**20	23,600	\$3,304
206788370	CARRIER	25VNA424A*031*	CAP**6024AL*+UI	59MN7B120C24**22	23,600	\$3,304
206788369	CARRIER	25VNA424A*031*	CAP**6024AL*+UI	59MN7B100C21**22	23,600	\$3,304
206788368	CARRIER	25VNA424A*031*	CAP**6024AL*+UI	59MN7B080C21**20	23,600	\$3,304
206788367	CARRIER	25VNA424A*031*	CAP**6024AL*+UI	59MN7B060C21**20	23,800	\$3,332
206788379	CARRIER	25VNA424A*031*	CNPV*3621AL*+UI	59MN7B080C21**20	24,400	\$3,416
206788359	CARRIER	25VNA424A*031*	CAP**4821AL*+UI	59MN7B100C21**22	24,000	\$3,360
206788363	CARRIER	25VNA424A*031*	CAP**4824AL*+UI	59MN7B080C21**20	24,000	\$3,360
206788358	CARRIER	25VNA424A*031*	CAP**4821AL*+UI	59MN7B080C21**20	24,000	\$3,360
206788354	CARRIER	25VNA424A*031*	CAP**4224AL*+UI	58TN*A110C21**20	24,200	\$3,388
206788353	CARRIER	25VNA424A*031*	CAP**4224AL*+UI	59MN7B120C24**22	24,200	\$3,388
206788351	CARRIER	25VNA424A*031*	CAP**4224AL*+UI	59MN7B080C21**20	24,200	\$3,388
206788365	CARRIER	25VNA424A*031*	CAP**4824AL*+UI	59MN7B120C24**22	24,000	\$3,360
206788352	CARRIER	25VNA424A*031*	CAP**4224AL*+UI	59MN7B100C21**22	24,200	\$3,388
206788349	CARRIER	25VNA424A*031*	CAP**4221AL*+UI	58TN*A110C21**20	24,200	\$3,388
206788347	CARRIER	25VNA424A*031*	CAP**4221AL*+UI	59MN7B100C21**22	24,200	\$3,388
206788342	CARRIER	25VNA424A*031*	CAP**3621AL*+UI	58TN*A110C21**20	24,200	\$3,388
206788346	CARRIER	25VNA424A*031*	CAP**4221AL*+UI	59MN7B080C21**20	24,200	\$3,388
206788340	CARRIER	25VNA424A*031*	CAP**3621AL*+UI	59MN7B100C21**22	24,200	\$3,388

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206788431	CARRIER	25VNA424A*031*	CSPH*4812AL*+UI	59MN7B060C21**20	24,200	\$3,388
206788438	CARRIER	25VNA424A*031*	CSPH*6012AL*+UI	59MN7B060C17**14	24,000	\$3,360
206788430	CARRIER	25VNA424A*031*	CSPH*4812AL*+UI	59MN7B080C17**14	24,200	\$3,388
206788429	CARRIER	25VNA424A*031*	CSPH*4812AL*+UI	59MN7B060C17**14	24,400	\$3,416
206788414	CARRIER	25VNA424A*031*	CSPH*3612AL*+UI	59MN7B080C21**20	24,200	\$3,388
206788420	CARRIER	25VNA424A*031*	CSPH*4212AL*+UI	59MN7B060C17**14	24,400	\$3,416
206788394	CARRIER	25VNA424A*031*	CNPV*4821AL*+UI	59MN7B060C17**14	24,400	\$3,416
206788376	CARRIER	25VNA424A*031*	CNPV*3621AL*+UI	59MN7B060C17**14	24,600	\$3,444
206788372	CARRIER	25VNA424A*031*	CNPV*3617AL*+UI	59MN7B060C17**14	24,600	\$3,444
206788355	CARRIER	25VNA424A*031*	CAP**4821AL*+UI	59MN7B060C17**14	24,200	\$3,388
206788332	CARRIER	25VNA424A*031*	CAP**3617AL*+UI	59MN7B060C17**14	24,600	\$3,444
201846961	CARRIER	38MAQB12R--3	40MBDQ12---3		8,500	\$1,190
207642893	CARRIER	38MGHBQ36DA3	Combination heat pumps with or without ducts		23,000	\$3,220
207642890	CARRIER	38MGHBQ48EA3	Combination heat pumps with or without ducts		29,000	\$4,060
207642884	CARRIER	38MGHBQ30DA3	Combination heat pumps with or without ducts		18,200	\$2,548
207642892	CARRIER	38MGHBQ36DA3	Heat pump with ducts		23,000	\$3,220
207642883	CARRIER	38MGHBQ30DA3	Heat pump with ducts		19,000	\$2,660
207642889	CARRIER	38MGHBQ48EA3	Heat pump with ducts		28,000	\$3,920
205272699	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59TN6B100C21**22	33,600	\$4,704
205272698	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59TN6B080C21**20	33,800	\$4,732
205272697	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59MN7B120C24**22	33,800	\$4,732
205272696	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59MN7B100C21**22	33,600	\$4,704
205272695	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59MN7B080C21**20	33,800	\$4,732
204430057	CARRIER	25VNA024A*030*	CNPV*3621AL*+UI	59TN6B080C21**20	25,000	\$3,500
203380995	CARRIER	38MAQB24R--3	FM(C,U)4Z24**AL*		15,000	\$2,100
203380994	CARRIER	38MAQB18R--3	FM(C,U)4Z18**AL*		12,200	\$1,708
203380979	CARRIER	38MAQB18R--3	FMA4X18**AL*		10,800	\$1,512
204344190	CARRIER	38MAQB18R--3	FV4CNF002		11,000	\$1,540
204344191	CARRIER	38MAQB24R--3	FV4CNF002		14,000	\$1,960
204344192	CARRIER	38MAQB30R--3	FV4CN(B,F)003		20,200	\$2,828
205272415	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	58TN*A045C17**12	24,400	\$3,416
205272416	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	58TN*A070C17**16	24,200	\$3,388
205272418	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	58TN*A090C21**20	24,200	\$3,388
205272417	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	58TN*A070C21**20	24,200	\$3,388
205272419	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	59TN6B060C17**14	24,400	\$3,416

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272420	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	59TN6B080C17**14	24,400	\$3,416
205272421	CARRIER	25VNA424A*030*	CAP**4224AL*+UI	58TN*A070C21**20	24,200	\$3,388
205272423	CARRIER	25VNA424A*030*	CAP**4224AL*+UI	58TN*A135C24**22	24,000	\$3,360
205272422	CARRIER	25VNA424A*030*	CAP**4224AL*+UI	58TN*A090C21**20	24,200	\$3,388
205272424	CARRIER	25VNA424A*030*	CAP**4224AL*+UI	59TN6B120C24**22	24,200	\$3,388
205272425	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	58TN*A045C17**12	24,200	\$3,388
205272426	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	58TN*A070C17**16	24,000	\$3,360
205272428	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	58TN*A090C21**20	23,800	\$3,332
205272427	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	58TN*A070C21**20	24,000	\$3,360
205272430	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	59TN6B080C17**14	24,000	\$3,360
205272429	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	59TN6B060C17**14	24,200	\$3,388
205272431	CARRIER	25VNA424A*030*	CAP**4824AL*+UI	58TN*A070C21**20	24,000	\$3,360
205272432	CARRIER	25VNA424A*030*	CAP**4824AL*+UI	58TN*A090C21**20	23,800	\$3,332
205272433	CARRIER	25VNA424A*030*	CAP**4824AL*+UI	58TN*A135C24**22	23,800	\$3,332
205272436	CARRIER	25VNA424A*030*	CAP**6024AL*+UI	58TN*A090C21**20	23,600	\$3,304
205272434	CARRIER	25VNA424A*030*	CAP**4824AL*+UI	59TN6B120C24**22	24,000	\$3,360
205272437	CARRIER	25VNA424A*030*	CAP**6024AL*+UI	58TN*A135C24**22	23,600	\$3,304
205272440	CARRIER	25VNA424A*030*	CNPV*3617AL*+UI	58TN*A070C17**16	24,400	\$3,416
205272435	CARRIER	25VNA424A*030*	CAP**6024AL*+UI	58TN*A070C21**20	23,600	\$3,304
205272439	CARRIER	25VNA424A*030*	CNPV*3617AL*+UI	58TN*A045C17**12	24,600	\$3,444
205272438	CARRIER	25VNA424A*030*	CAP**6024AL*+UI	59TN6B120C24**22	23,600	\$3,304
205272441	CARRIER	25VNA424A*030*	CNPV*3617AL*+UI	59TN6B060C17**14	24,600	\$3,444
205272442	CARRIER	25VNA424A*030*	CNPV*3617AL*+UI	59TN6B080C17**14	24,400	\$3,416
205272447	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	59TN6B060C17**14	24,600	\$3,444
205272443	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	58TN*A045C17**12	24,600	\$3,444
205272448	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	59TN6B080C17**14	24,400	\$3,416
205272444	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	58TN*A070C17**16	24,400	\$3,416
205272445	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	58TN*A070C21**20	24,400	\$3,416
205272446	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	58TN*A090C21**20	24,200	\$3,388
205272449	CARRIER	25VNA424A*030*	CNPV*4217AL*+UI	58TN*A045C17**12	24,400	\$3,416
205272451	CARRIER	25VNA424A*030*	CNPV*4217AL*+UI	59TN6B060C17**14	24,400	\$3,416
205272450	CARRIER	25VNA424A*030*	CNPV*4217AL*+UI	58TN*A070C17**16	24,200	\$3,388
205272452	CARRIER	25VNA424A*030*	CNPV*4217AL*+UI	59TN6B080C17**14	24,400	\$3,416
205272457	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	59TN6B060C17**14	24,400	\$3,416
205272453	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	58TN*A045C17**12	24,400	\$3,416
205272454	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	58TN*A070C17**16	24,400	\$3,416
205272455	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	58TN*A070C21**20	24,200	\$3,388
205272456	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	58TN*A090C21**20	24,200	\$3,388

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272459	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	58TN*A045C17**12	24,200	\$3,388
205272458	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	59TN6B080C17**14	24,400	\$3,416
205272460	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	58TN*A070C17**16	24,200	\$3,388
205272462	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	58TN*A090C21**20	24,000	\$3,360
205272465	CARRIER	25VNA424A*030*	CNPV*4824AL*+UI	58TN*A070C21**20	24,200	\$3,388
205272461	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	58TN*A070C21**20	24,200	\$3,388
205272464	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	59TN6B080C17**14	24,200	\$3,388
205272463	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	59TN6B060C17**14	24,200	\$3,388
205272466	CARRIER	25VNA424A*030*	CNPV*4824AL*+UI	58TN*A090C21**20	24,000	\$3,360
205272467	CARRIER	25VNA424A*030*	CNPV*4824AL*+UI	58TN*A135C24**22	24,000	\$3,360
205272468	CARRIER	25VNA424A*030*	CNPV*4824AL*+UI	59TN6B120C24**22	24,000	\$3,360
205272470	CARRIER	25VNA424A*030*	CNPV*6024AL*+UI	58TN*A090C21**20	23,800	\$3,332
205272469	CARRIER	25VNA424A*030*	CNPV*6024AL*+UI	58TN*A070C21**20	23,800	\$3,332
205272471	CARRIER	25VNA424A*030*	CNPV*6024AL*+UI	58TN*A135C24**22	23,800	\$3,332
205272472	CARRIER	25VNA424A*030*	CNPV*6024AL*+UI	59TN6B120C24**22	23,800	\$3,332
205272474	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	58TN*A070C17**16	24,200	\$3,388
205272473	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	58TN*A045C17**12	24,400	\$3,416
205272475	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	58TN*A070C21**20	24,200	\$3,388
205272476	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	58TN*A090C21**20	24,200	\$3,388
205272478	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	59TN6B060C17**14	24,400	\$3,416
205272477	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	58TN*A135C24**22	24,200	\$3,388
205272479	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	59TN6B080C17**14	24,400	\$3,416
205272480	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	59TN6B120C24**22	24,200	\$3,388
205272481	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	58TN*A045C17**12	24,400	\$3,416
205272483	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	58TN*A070C21**20	24,200	\$3,388
205272482	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	58TN*A070C17**16	24,200	\$3,388
205272485	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	58TN*A135C24**22	24,000	\$3,360
205272484	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	58TN*A090C21**20	24,000	\$3,360
205272486	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	59TN6B060C17**14	24,400	\$3,416
205272491	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	58TN*A070C21**20	24,200	\$3,388
205272488	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	59TN6B120C24**22	24,200	\$3,388
205272487	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	59TN6B080C17**14	24,200	\$3,388
205272489	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	58TN*A045C17**12	24,200	\$3,388
205272490	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	58TN*A070C17**16	24,200	\$3,388
205272492	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	58TN*A090C21**20	24,000	\$3,360
205272493	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	58TN*A135C24**22	24,000	\$3,360
205272494	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	59TN6B060C17**14	24,200	\$3,388
205272495	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	59TN6B080C17**14	24,200	\$3,388

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272496	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	59TN6B120C24**22	24,000	\$3,360
205272497	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	58TN*A045C17**12	24,000	\$3,360
205272499	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	58TN*A070C21**20	23,800	\$3,332
205272498	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	58TN*A070C17**16	23,800	\$3,332
205272500	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	58TN*A090C21**20	23,800	\$3,332
205272501	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	58TN*A135C24**22	23,800	\$3,332
205272502	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	59TN6B060C17**14	24,000	\$3,360
205272503	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	59TN6B080C17**14	24,000	\$3,360
205272504	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	59TN6B120C24**22	23,800	\$3,332
205272288	CARRIER	25VNA424A*030*	FE4AN(B,F)003L+UI		24,200	\$3,388
205272289	CARRIER	25VNA424A*030*	FE4AN(B,F)005L+UI		23,600	\$3,304
205272287	CARRIER	25VNA424A*030*	FE4ANF002L+UI		24,400	\$3,416
205272292	CARRIER	25VNA424A*030*	CAP**3617AL*+UI	58TN*A070C14**12	24,400	\$3,416
205272293	CARRIER	25VNA424A*030*	CAP**3617AL*+UI	58TN*A090C17**16	24,200	\$3,388
205272297	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	59MN7B080C21**20	24,200	\$3,388
205272298	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	59MN7B100C21**22	24,200	\$3,388
205272299	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	58TN*A090C17**16	24,200	\$3,388
205272300	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	58TN*A110C21**20	24,200	\$3,388
205272304	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	59MN7B080C21**20	24,200	\$3,388
205272305	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	59MN7B100C21**22	24,200	\$3,388
205272306	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	58TN*A090C17**16	24,200	\$3,388
205272307	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	58TN*A110C21**20	24,200	\$3,388
205272309	CARRIER	25VNA424A*030*	CAP**4224AL*+UI	59MN7B080C21**20	24,200	\$3,388
205272310	CARRIER	25VNA424A*030*	CAP**4224AL*+UI	59MN7B100C21**22	24,200	\$3,388
205272311	CARRIER	25VNA424A*030*	CAP**4224AL*+UI	59MN7B120C24**22	24,200	\$3,388
205272314	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	59MN7B080C17**14	24,000	\$3,360
205272312	CARRIER	25VNA424A*030*	CAP**4224AL*+UI	58TN*A110C21**20	24,200	\$3,388
205272315	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	59MN7B060C21**20	24,000	\$3,360
205272316	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	59MN7B080C21**20	24,000	\$3,360
205272317	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	59MN7B100C21**22	24,000	\$3,360
205272318	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	58TN*A090C17**16	23,800	\$3,332
205272319	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	58TN*A110C21**20	23,800	\$3,332
205272320	CARRIER	25VNA424A*030*	CAP**4824AL*+UI	59MN7B060C21**20	24,000	\$3,360
205272321	CARRIER	25VNA424A*030*	CAP**4824AL*+UI	59MN7B080C21**20	24,000	\$3,360
205272322	CARRIER	25VNA424A*030*	CAP**4824AL*+UI	59MN7B100C21**22	23,800	\$3,332
205272324	CARRIER	25VNA424A*030*	CAP**4824AL*+UI	58TN*A110C21**20	23,800	\$3,332
205272323	CARRIER	25VNA424A*030*	CAP**4824AL*+UI	59MN7B120C24**22	24,000	\$3,360
205272325	CARRIER	25VNA424A*030*	CAP**6024AL*+UI	59MN7B060C21**20	23,800	\$3,332

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272326	CARRIER	25VNA424A*030*	CAP**6024AL*+UI	59MN7B080C21**20	23,600	\$3,304
205272327	CARRIER	25VNA424A*030*	CAP**6024AL*+UI	59MN7B100C21**22	23,600	\$3,304
205272328	CARRIER	25VNA424A*030*	CAP**6024AL*+UI	59MN7B120C24**22	23,600	\$3,304
205272329	CARRIER	25VNA424A*030*	CAP**6024AL*+UI	58TN*A110C21**20	23,600	\$3,304
205272337	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	59MN7B080C21**20	24,400	\$3,416
205272333	CARRIER	25VNA424A*030*	CNPV*3617AL*+UI	58TN*A090C17**16	24,200	\$3,388
205272332	CARRIER	25VNA424A*030*	CNPV*3617AL*+UI	58TN*A070C14**12	24,400	\$3,416
205272338	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	59MN7B100C21**22	24,400	\$3,416
205272339	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	58TN*A090C17**16	24,200	\$3,388
205272340	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	58TN*A110C21**20	24,200	\$3,388
205272343	CARRIER	25VNA424A*030*	CNPV*4217AL*+UI	58TN*A070C14**12	24,200	\$3,388
205272344	CARRIER	25VNA424A*030*	CNPV*4217AL*+UI	58TN*A090C17**16	24,200	\$3,388
205272349	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	59MN7B100C21**22	24,200	\$3,388
205272348	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	59MN7B080C21**20	24,200	\$3,388
205272350	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	58TN*A090C17**16	24,200	\$3,388
205272351	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	58TN*A110C21**20	24,200	\$3,388
205272353	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	59MN7B080C17**14	24,200	\$3,388
205272354	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	59MN7B060C21**20	24,200	\$3,388
205272358	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	58TN*A110C21**20	24,000	\$3,360
205272355	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	59MN7B080C21**20	24,000	\$3,360
205272356	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	59MN7B100C21**22	24,000	\$3,360
205272357	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	58TN*A090C17**16	24,000	\$3,360
205272359	CARRIER	25VNA424A*030*	CNPV*4824AL*+UI	59MN7B060C21**20	24,200	\$3,388
205272360	CARRIER	25VNA424A*030*	CNPV*4824AL*+UI	59MN7B080C21**20	24,000	\$3,360
205272361	CARRIER	25VNA424A*030*	CNPV*4824AL*+UI	59MN7B100C21**22	24,000	\$3,360
205272362	CARRIER	25VNA424A*030*	CNPV*4824AL*+UI	59MN7B120C24**22	24,000	\$3,360
205272363	CARRIER	25VNA424A*030*	CNPV*4824AL*+UI	58TN*A110C21**20	24,000	\$3,360
205272364	CARRIER	25VNA424A*030*	CNPV*6024AL*+UI	59MN7B060C21**20	24,000	\$3,360
205272365	CARRIER	25VNA424A*030*	CNPV*6024AL*+UI	59MN7B080C21**20	23,800	\$3,332
205272373	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	59MN7B100C21**22	24,200	\$3,388
205272366	CARRIER	25VNA424A*030*	CNPV*6024AL*+UI	59MN7B100C21**22	23,800	\$3,332
205272367	CARRIER	25VNA424A*030*	CNPV*6024AL*+UI	59MN7B120C24**22	23,800	\$3,332
205272368	CARRIER	25VNA424A*030*	CNPV*6024AL*+UI	58TN*A110C21**20	23,800	\$3,332
205272377	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	58TN*A110C21**20	24,200	\$3,388
205272374	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	59MN7B120C24**22	24,200	\$3,388
205272375	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	58TN*A070C14**12	24,200	\$3,388
205272376	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	58TN*A090C17**16	24,200	\$3,388
205272381	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	59MN7B080C21**20	24,200	\$3,388

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272382	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	59MN7B100C21**22	24,000	\$3,360
205272385	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	58TN*A090C17**16	24,000	\$3,360
205272383	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	59MN7B120C24**22	24,200	\$3,388
205272384	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	58TN*A070C14**12	24,200	\$3,388
205272386	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	58TN*A110C21**20	24,000	\$3,360
205272390	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	59MN7B080C21**20	24,000	\$3,360
205272391	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	59MN7B100C21**22	24,000	\$3,360
205272392	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	59MN7B120C24**22	24,000	\$3,360
205272394	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	58TN*A090C17**16	24,000	\$3,360
205272393	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	58TN*A070C14**12	24,200	\$3,388
205272395	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	58TN*A110C21**20	24,000	\$3,360
205272397	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	59MN7B080C17**14	24,000	\$3,360
205272398	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	59MN7B060C21**20	23,800	\$3,332
205272399	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	59MN7B080C21**20	23,800	\$3,332
205272400	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	59MN7B100C21**22	23,800	\$3,332
205272401	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	59MN7B120C24**22	23,800	\$3,332
205272405	CARRIER	25VNA424A*030*	CAP**3617AL*+UI	58TN*A045C17**12	24,400	\$3,416
205272403	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	58TN*A090C17**16	23,800	\$3,332
205272402	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	58TN*A070C14**12	23,800	\$3,332
205272404	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	58TN*A110C21**20	23,800	\$3,332
205272406	CARRIER	25VNA424A*030*	CAP**3617AL*+UI	58TN*A070C17**16	24,400	\$3,416
205272407	CARRIER	25VNA424A*030*	CAP**3617AL*+UI	59TN6B060C17**14	24,400	\$3,416
205272408	CARRIER	25VNA424A*030*	CAP**3617AL*+UI	59TN6B080C17**14	24,400	\$3,416
205272410	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	58TN*A070C17**16	24,200	\$3,388
205272409	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	58TN*A045C17**12	24,400	\$3,416
205272411	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	58TN*A070C21**20	24,200	\$3,388
205272412	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	58TN*A090C21**20	24,200	\$3,388
205272413	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	59TN6B060C17**14	24,400	\$3,416
205272414	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	59TN6B080C17**14	24,400	\$3,416
205272680	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	59MN7B120C24**22	33,200	\$4,648
205272682	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	59TN6B100C21**22	33,000	\$4,620
205272681	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	59TN6B080C21**20	33,200	\$4,648
205272683	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	58TN*A110C21**20	33,000	\$4,620
205272745	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	58TN*A090C21**20	32,800	\$4,592
205272684	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	59MN7B060C21**20	33,600	\$4,704
205272746	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	58TN*A135C24**22	32,800	\$4,592
205272758	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	58TN*A090C17**16	33,000	\$4,620
205272749	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59TN6B120C24**22	33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272756	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59TN6B100C21**22	33,000	\$4,620
205272753	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59MN7B100C21**22	33,000	\$4,620
205272759	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	58TN*A110C21**20	33,000	\$4,620
205272505	CARRIER	25VNA436A*030*	FE4AN(B,F)005L+UI		32,800	\$4,592
205272507	CARRIER	25VNA436A*030*	FE4ANB006L+UI		32,400	\$4,536
205272290	CARRIER	25VNA424A*030*	CAP**3617AL*+UI	59MN7B060C17**14	24,600	\$3,444
205272291	CARRIER	25VNA424A*030*	CAP**3617AL*+UI	59MN7B080C17**14	24,400	\$3,416
205272294	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	59MN7B060C17**14	24,400	\$3,416
205272295	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	59MN7B080C17**14	24,400	\$3,416
205272296	CARRIER	25VNA424A*030*	CAP**3621AL*+UI	59MN7B060C21**20	24,400	\$3,416
205272301	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	59MN7B060C17**14	24,400	\$3,416
205272302	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	59MN7B080C17**14	24,400	\$3,416
205272303	CARRIER	25VNA424A*030*	CAP**4221AL*+UI	59MN7B060C21**20	24,200	\$3,388
205272313	CARRIER	25VNA424A*030*	CAP**4821AL*+UI	59MN7B060C17**14	24,200	\$3,388
205272308	CARRIER	25VNA424A*030*	CAP**4224AL*+UI	59MN7B060C21**20	24,200	\$3,388
205272330	CARRIER	25VNA424A*030*	CNPV*3617AL*+UI	59MN7B060C17**14	24,600	\$3,444
205272335	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	59MN7B080C17**14	24,400	\$3,416
205272331	CARRIER	25VNA424A*030*	CNPV*3617AL*+UI	59MN7B080C17**14	24,400	\$3,416
205272334	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	59MN7B060C17**14	24,600	\$3,444
205272336	CARRIER	25VNA424A*030*	CNPV*3621AL*+UI	59MN7B060C21**20	24,400	\$3,416
205272341	CARRIER	25VNA424A*030*	CNPV*4217AL*+UI	59MN7B060C17**14	24,400	\$3,416
205272342	CARRIER	25VNA424A*030*	CNPV*4217AL*+UI	59MN7B080C17**14	24,400	\$3,416
205272345	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	59MN7B060C17**14	24,400	\$3,416
205272347	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	59MN7B060C21**20	24,400	\$3,416
205272346	CARRIER	25VNA424A*030*	CNPV*4221AL*+UI	59MN7B080C17**14	24,400	\$3,416
205272352	CARRIER	25VNA424A*030*	CNPV*4821AL*+UI	59MN7B060C17**14	24,400	\$3,416
205272369	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	59MN7B060C17**14	24,400	\$3,416
205272370	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	59MN7B080C17**14	24,400	\$3,416
205272379	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	59MN7B080C17**14	24,200	\$3,388
205272371	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	59MN7B060C21**20	24,400	\$3,416
205272380	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	59MN7B060C21**20	24,200	\$3,388
205272387	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	59MN7B060C17**14	24,400	\$3,416
205272372	CARRIER	25VNA424A*030*	CSPH*3612AL*+UI	59MN7B080C21**20	24,200	\$3,388
205272378	CARRIER	25VNA424A*030*	CSPH*4212AL*+UI	59MN7B060C17**14	24,400	\$3,416
205272388	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	59MN7B080C17**14	24,200	\$3,388
205272389	CARRIER	25VNA424A*030*	CSPH*4812AL*+UI	59MN7B060C21**20	24,200	\$3,388
205272396	CARRIER	25VNA424A*030*	CSPH*6012AL*+UI	59MN7B060C17**14	24,000	\$3,360
205272506	CARRIER	25VNA436A*030*	FE4AN(B,F)003L+UI		33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272518	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	59MN7B100C21**22	33,600	\$4,704
205272520	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	59TN6B100C21**22	33,600	\$4,704
205272551	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	58TN*A090C21**20	33,400	\$4,676
205272521	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	58TN*A090C17**16	33,600	\$4,704
205272522	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	58TN*A110C21**20	33,600	\$4,704
205272556	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	59MN7B100C21**22	33,400	\$4,676
205272560	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	58TN*A110C21**20	33,400	\$4,676
205272578	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	58TN*A090C21**20	33,200	\$4,648
205272559	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	58TN*A090C17**16	33,600	\$4,704
205272558	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	59TN6B100C21**22	33,400	\$4,676
205272579	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	58TN*A135C24**22	33,000	\$4,620
205272586	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	58TN*A110C21**20	33,200	\$4,648
205272589	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	58TN*A090C21**20	32,800	\$4,592
205272590	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	58TN*A135C24**22	32,600	\$4,564
205272593	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	59MN7B100C21**22	32,800	\$4,592
205272592	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	59MN7B080C21**20	33,000	\$4,620
205272591	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	59TN6B120C24**22	32,800	\$4,592
205272594	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	59MN7B120C24**22	33,000	\$4,620
205272596	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	59TN6B100C21**22	32,800	\$4,592
205272595	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	59TN6B080C21**20	33,000	\$4,620
205272602	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	58TN*A090C21**20	33,000	\$4,620
205272597	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	58TN*A110C21**20	32,800	\$4,592
205272600	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	58TN*A070C17**16	33,400	\$4,676
205272601	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	58TN*A070C21**20	33,200	\$4,648
205272608	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	59MN7B100C21**22	33,000	\$4,620
205272607	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	59MN7B080C21**20	33,200	\$4,648
205272609	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	59TN6B080C21**20	33,200	\$4,648
205272610	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	59TN6B100C21**22	33,000	\$4,620
205272611	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	58TN*A090C17**16	33,200	\$4,648
205272612	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	58TN*A110C21**20	33,000	\$4,620
205272614	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	58TN*A070C21**20	33,200	\$4,648
205272615	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	58TN*A090C21**20	33,000	\$4,620
205272616	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	58TN*A135C24**22	32,800	\$4,592
205272619	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	59MN7B100C21**22	33,000	\$4,620
205272620	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	59MN7B120C24**22	33,000	\$4,620
205272617	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	59TN6B120C24**22	33,000	\$4,620
205272618	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	59MN7B080C21**20	33,200	\$4,648
205272621	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	59TN6B080C21**20	33,200	\$4,648

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272622	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	59TN6B100C21**22	33,000	\$4,620
205272623	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	58TN*A110C21**20	33,000	\$4,620
205272657	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	59MN7B100C21**22	33,400	\$4,676
205272650	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	58TN*A070C21**20	33,600	\$4,704
205272642	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	59MN7B100C21**22	33,800	\$4,732
205272651	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	58TN*A090C21**20	33,400	\$4,676
205272656	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	59MN7B080C21**20	33,600	\$4,704
205272660	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	58TN*A090C17**16	33,400	\$4,676
205272659	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	59TN6B100C21**22	33,400	\$4,676
205272658	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	59TN6B080C21**20	33,600	\$4,704
205272661	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	58TN*A110C21**20	33,400	\$4,676
205272663	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	58TN*A070C21**20	33,600	\$4,704
205272665	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	58TN*A135C24**22	33,200	\$4,648
205272664	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	58TN*A090C21**20	33,400	\$4,676
205272668	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	59MN7B100C21**22	33,400	\$4,676
205272666	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	59TN6B120C24**22	33,400	\$4,676
205272667	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	59MN7B080C21**20	33,600	\$4,704
205272671	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	59TN6B100C21**22	33,400	\$4,676
205272669	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	59MN7B120C24**22	33,400	\$4,676
205272670	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	59TN6B080C21**20	33,600	\$4,704
205272672	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	58TN*A110C21**20	33,400	\$4,676
205272674	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	58TN*A070C21**20	33,200	\$4,648
205272675	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	58TN*A090C21**20	33,000	\$4,620
205272676	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	58TN*A135C24**22	32,800	\$4,592
205272677	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	59TN6B120C24**22	33,000	\$4,620
205272678	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	59MN7B080C21**20	33,200	\$4,648
205272679	CARRIER	25VNA436A*030*	CNPV*6024AL*+UI	59MN7B100C21**22	33,000	\$4,620
205272636	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	58TN*A090C21**20	33,800	\$4,732
205272641	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	59MN7B080C21**20	34,000	\$4,760
205272646	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	58TN*A110C21**20	33,800	\$4,732
205272644	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	59TN6B100C21**22	33,800	\$4,732
205272643	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	59TN6B080C21**20	34,000	\$4,760
205272645	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	58TN*A090C17**16	33,800	\$4,732
205272649	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	58TN*A070C17**16	33,800	\$4,732
205272653	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	59TN6B080C17**14	34,000	\$4,760
205272655	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	59MN7B080C17**14	34,000	\$4,760
205272662	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	59MN7B060C21**20	34,000	\$4,760
205272673	CARRIER	25VNA436A*030*	CNPV*4824AL*+UI	59MN7B060C21**20	34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272689	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	58TN*A135C24**22	33,400	\$4,676
205272688	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	58TN*A090C21**20	33,600	\$4,704
205272692	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59TN6B120C24**22	33,600	\$4,704
205272706	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	58TN*A070C21**20	33,600	\$4,704
205272701	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	58TN*A090C17**16	33,800	\$4,732
205272707	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	58TN*A090C21**20	33,400	\$4,676
205272702	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	58TN*A110C21**20	33,600	\$4,704
205272708	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	58TN*A135C24**22	33,400	\$4,676
205272711	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59TN6B120C24**22	33,400	\$4,676
205272714	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59MN7B080C21**20	33,600	\$4,704
205272715	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59MN7B100C21**22	33,400	\$4,676
205272716	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59MN7B120C24**22	33,600	\$4,704
205272717	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59TN6B080C21**20	33,600	\$4,704
205272720	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	58TN*A090C17**16	33,600	\$4,704
205272718	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59TN6B100C21**22	33,400	\$4,676
205272721	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	58TN*A110C21**20	33,400	\$4,676
205272725	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	58TN*A070C21**20	33,600	\$4,704
205272724	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	58TN*A070C17**16	33,800	\$4,732
205272726	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	58TN*A090C21**20	33,400	\$4,676
205272727	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	58TN*A135C24**22	33,200	\$4,648
205272730	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59TN6B120C24**22	33,400	\$4,676
205272735	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59MN7B120C24**22	33,600	\$4,704
205272733	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59MN7B080C21**20	33,600	\$4,704
205272734	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59MN7B100C21**22	33,400	\$4,676
205272737	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59TN6B100C21**22	33,400	\$4,676
205272739	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	58TN*A090C17**16	33,400	\$4,676
205272736	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59TN6B080C21**20	33,600	\$4,704
205272740	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	58TN*A110C21**20	33,400	\$4,676
205272743	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	58TN*A070C17**16	33,400	\$4,676
205272744	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	58TN*A070C21**20	33,200	\$4,648
205272755	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59TN6B080C21**20	33,000	\$4,620
205272748	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59TN6B080C17**14	33,600	\$4,704
205272752	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59MN7B080C21**20	33,000	\$4,620
205272751	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59MN7B080C17**14	33,600	\$4,704
205272754	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59MN7B120C24**22	33,000	\$4,620
205272760	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59MN7B060C21**20	33,400	\$4,676
205272757	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	58TN*A070C14**12	33,600	\$4,704
205272511	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	58TN*A070C17**16	34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272510	CARRIER	25VNA436A*030*	CAP**3717AL*+UI	58TN*A090C17**16	33,800	\$4,732
205272512	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	58TN*A070C21**20	33,800	\$4,732
205272517	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	59MN7B080C21**20	33,600	\$4,704
205272513	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	58TN*A090C21**20	33,400	\$4,676
205272523	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	59MN7B060C21**20	34,000	\$4,760
205272527	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	58TN*A090C21**20	33,600	\$4,704
205272519	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	59TN6B080C21**20	33,600	\$4,704
205272536	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	58TN*A110C21**20	33,800	\$4,732
205272539	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	58TN*A090C21**20	33,600	\$4,704
205272549	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	58TN*A070C17**16	33,800	\$4,732
205272540	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	58TN*A135C24**22	33,600	\$4,704
205272547	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	58TN*A110C21**20	33,600	\$4,704
205272550	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	58TN*A070C21**20	33,600	\$4,704
205272554	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	59MN7B080C17**14	34,000	\$4,760
205272555	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	59MN7B080C21**20	33,600	\$4,704
205272557	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	59TN6B080C21**20	33,600	\$4,704
205272561	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	59MN7B060C21**20	34,000	\$4,760
205272565	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	58TN*A090C21**20	33,200	\$4,648
205272563	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	58TN*A070C17**16	33,800	\$4,732
205272572	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	59TN6B080C21**20	33,400	\$4,676
205272571	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	59MN7B100C21**22	33,400	\$4,676
205272573	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	59TN6B100C21**22	33,400	\$4,676
205272574	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	58TN*A090C17**16	33,400	\$4,676
205272575	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	58TN*A110C21**20	33,400	\$4,676
205272577	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	58TN*A070C21**20	33,400	\$4,676
205272580	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	59TN6B120C24**22	33,200	\$4,648
205272585	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	59TN6B100C21**22	33,200	\$4,648
205272582	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	59MN7B100C21**22	33,200	\$4,648
205272599	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	58TN*A045C17**12	33,800	\$4,732
205272587	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	59MN7B060C21**20	33,800	\$4,732
205272588	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	58TN*A070C21**20	33,000	\$4,620
205272598	CARRIER	25VNA436A*030*	CAP**6024AL*+UI	59MN7B060C21**20	33,400	\$4,676
205272603	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	59TN6B060C17**14	34,000	\$4,760
205272604	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	59TN6B080C17**14	33,800	\$4,732
205272606	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	59MN7B080C17**14	33,800	\$4,732
205272613	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	59MN7B060C21**20	33,600	\$4,704
205272624	CARRIER	25VNA436A*030*	CAP**6124AL*+UI	59MN7B060C21**20	33,600	\$4,704
205272632	CARRIER	25VNA436A*030*	CNPV*4217AL*+UI	58TN*A090C17**16	33,800	\$4,732

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272626	CARRIER	25VNA436A*030*	CNPV*4217AL*+UI	58TN*A070C17**16	34,200	\$4,788
205272747	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59TN6B060C17**14	33,800	\$4,732
205272750	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	59MN7B060C17**14	33,800	\$4,732
205272508	CARRIER	25VNA436A*030*	CAP**3717AL*+UI	58TN*A070C17**16	34,200	\$4,788
205272509	CARRIER	25VNA436A*030*	CAP**3717AL*+UI	58TN*A070C14**12	34,000	\$4,760
205272515	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	59TN6B080C17**14	34,200	\$4,788
205272514	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	59TN6B060C17**14	34,400	\$4,816
205272526	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	58TN*A070C21**20	34,000	\$4,760
205272516	CARRIER	25VNA436A*030*	CAP**3721AL*+UI	59MN7B080C17**14	34,000	\$4,760
205272525	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	58TN*A070C17**16	34,200	\$4,788
205272528	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	59TN6B060C17**14	34,600	\$4,844
205272530	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	59MN7B080C17**14	34,400	\$4,816
205272531	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	59MN7B080C21**20	33,800	\$4,732
205272533	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	59TN6B080C21**20	33,800	\$4,732
205272532	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	59MN7B100C21**22	33,800	\$4,732
205272534	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	59TN6B100C21**22	33,800	\$4,732
205272541	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	59TN6B120C24**22	33,600	\$4,704
205272535	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	58TN*A090C17**16	33,800	\$4,732
205272537	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	59MN7B060C21**20	34,200	\$4,788
205272545	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	59TN6B080C21**20	33,800	\$4,732
205272543	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	59MN7B100C21**22	33,600	\$4,704
205272542	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	59MN7B080C21**20	33,800	\$4,732
205272544	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	59MN7B120C24**22	33,800	\$4,732
205272548	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	59MN7B060C21**20	34,200	\$4,788
205272546	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	59TN6B100C21**22	33,600	\$4,704
205272552	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	59TN6B060C17**14	34,400	\$4,816
205272553	CARRIER	25VNA436A*030*	CAP**4321AL*+UI	59TN6B080C17**14	34,200	\$4,788
205272562	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	58TN*A045C17**12	34,200	\$4,788
205272567	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	59TN6B080C17**14	34,000	\$4,760
205272568	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	59MN7B060C17**14	34,000	\$4,760
205272564	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	58TN*A070C21**20	33,600	\$4,704
205272566	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	59TN6B060C17**14	34,200	\$4,788
205272569	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	59MN7B080C17**14	33,800	\$4,732
205272581	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	59MN7B080C21**20	33,400	\$4,676
205272570	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	59MN7B080C21**20	33,400	\$4,676
205272576	CARRIER	25VNA436A*030*	CAP**4821AL*+UI	59MN7B060C21**20	33,800	\$4,732
205272583	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	59MN7B120C24**22	33,400	\$4,676
205272584	CARRIER	25VNA436A*030*	CAP**4824AL*+UI	59TN6B080C21**20	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272605	CARRIER	25VNA436A*030*	CAP**6121AL*+UI	59MN7B060C17**14	33,600	\$4,704
205272625	CARRIER	25VNA436A*030*	CNPV*4217AL*+UI	58TN*A045C17**12	34,600	\$4,844
205272628	CARRIER	25VNA436A*030*	CNPV*4217AL*+UI	59TN6B080C17**14	34,400	\$4,816
205272627	CARRIER	25VNA436A*030*	CNPV*4217AL*+UI	59TN6B060C17**14	34,600	\$4,844
205272629	CARRIER	25VNA436A*030*	CNPV*4217AL*+UI	59MN7B060C17**14	34,400	\$4,816
205272630	CARRIER	25VNA436A*030*	CNPV*4217AL*+UI	59MN7B080C17**14	34,200	\$4,788
205272631	CARRIER	25VNA436A*030*	CNPV*4217AL*+UI	58TN*A070C14**12	34,200	\$4,788
205272633	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	58TN*A045C17**12	34,800	\$4,872
205272634	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	58TN*A070C17**16	34,200	\$4,788
205272637	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	59TN6B060C17**14	34,600	\$4,844
205272635	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	58TN*A070C21**20	34,000	\$4,760
205272638	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	59TN6B080C17**14	34,600	\$4,844
205272639	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	59MN7B060C17**14	34,600	\$4,844
205272640	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	59MN7B080C17**14	34,400	\$4,816
205272647	CARRIER	25VNA436A*030*	CNPV*4221AL*+UI	59MN7B060C21**20	34,400	\$4,816
205272648	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	58TN*A045C17**12	34,200	\$4,788
205272652	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	59TN6B060C17**14	34,400	\$4,816
205272654	CARRIER	25VNA436A*030*	CNPV*4821AL*+UI	59MN7B060C17**14	34,200	\$4,788
205272686	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	58TN*A070C17**16	34,000	\$4,760
205272687	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	58TN*A070C21**20	33,800	\$4,732
205272691	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59TN6B080C17**14	34,400	\$4,816
205272690	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59TN6B060C17**14	34,600	\$4,844
205272700	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	58TN*A070C14**12	34,200	\$4,788
205272694	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59MN7B080C17**14	34,200	\$4,788
205272703	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59MN7B060C21**20	34,200	\$4,788
205272704	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	58TN*A045C17**12	34,400	\$4,816
205272709	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59TN6B060C17**14	34,400	\$4,816
205272705	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	58TN*A070C17**16	34,000	\$4,760
205272710	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59TN6B080C17**14	34,200	\$4,788
205272712	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59MN7B060C17**14	34,200	\$4,788
205272713	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59MN7B080C17**14	34,200	\$4,788
205272722	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	59MN7B060C21**20	34,000	\$4,760
205272719	CARRIER	25VNA436A*030*	CSPH*4212AL*+UI	58TN*A070C14**12	34,000	\$4,760
205272723	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	58TN*A045C17**12	34,400	\$4,816
205272728	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59TN6B060C17**14	34,200	\$4,788
205272729	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59TN6B080C17**14	34,200	\$4,788
205272731	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59MN7B060C17**14	34,200	\$4,788
205272732	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59MN7B080C17**14	34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205272738	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	58TN*A070C14**12	34,000	\$4,760
205272742	CARRIER	25VNA436A*030*	CSPH*6012AL*+UI	58TN*A045C17**12	33,800	\$4,732
205272741	CARRIER	25VNA436A*030*	CSPH*4812AL*+UI	59MN7B060C21**20	34,000	\$4,760
205272524	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	58TN*A045C17**12	34,600	\$4,844
205272529	CARRIER	25VNA436A*030*	CAP**4221AL*+UI	59MN7B060C17**14	34,600	\$4,844
205272538	CARRIER	25VNA436A*030*	CAP**4224AL*+UI	58TN*A070C21**20	33,800	\$4,732
205272685	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	58TN*A045C17**12	34,600	\$4,844
205272693	CARRIER	25VNA436A*030*	CSPH*3612AL*+UI	59MN7B060C17**14	34,400	\$4,816
9892813	CARRIER	25VNA060A*030*	FE4ANB006L+UI		52,500	\$7,350
9892806	CARRIER	25VNA048A*030*	CNPV*6024AL*+UI & 59*N*A100V21**22		48,500	\$6,790
9892805	CARRIER	25VNA048A*030*	CNPV*6024AL*+UI & 59*N*A080V21**20		49,000	\$6,860
9892800	CARRIER	25VNA048A*030*	CNPV*4821AL*+UI & 59*N*A100V21**22		48,000	\$6,720
9892794	CARRIER	25VNA048A*030*	CAP**6021AL*+UI & 59*N*A100V21**22		48,000	\$6,720
9892783	CARRIER	25VNA048A*030*	CNPV*6024AL*+UI & 59*N*A120V24**22		49,000	\$6,860
9892797	CARRIER	25VNA048A*030*	CAP**6024AL*+UI & 59*N*A100V21**22		48,000	\$6,720
9892779	CARRIER	25VNA048A*030*	FE4AN(B,F)005L+UI		48,500	\$6,790
9892751	CARRIER	25VNA048A*030*	FE4ANB006L+UI		47,500	\$6,650
9892749	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI & 59*N*A100V21**22		32,000	\$4,480
9892748	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI & 59*N*A080V21**20		32,000	\$4,480
9892746	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI & 59*N*A100V21**22		30,000	\$4,200
9892747	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI & 59MN7A060V21**20		32,200	\$4,508
9892745	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI & 59*N*A080V21**20		30,000	\$4,200
9892744	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI & 59MN7A060V21**20		30,400	\$4,256
9892743	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI & 59*N*A100V21**22		30,000	\$4,200
9892742	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI & 59*N*A080V21**20		30,200	\$4,228

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9892741	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI & 59MN7A060V21**20		30,400	\$4,256
9892740	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI & 59*N*A100V21**22		30,200	\$4,228
9892739	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI & 59*N*A080V21**20		30,200	\$4,228
9892737	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI & 59*N*A100V21**22		32,000	\$4,480
9892736	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI & 59*N*A080V21**20		32,200	\$4,508
9892734	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI & 59*N*A100V21**22		30,000	\$4,200
9892735	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI & 59MN7A060V21**20		32,400	\$4,536
9892733	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI & 59*N*A080V21**20		30,000	\$4,200
9892732	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI & 59MN7A060V21**20		30,400	\$4,256
9892731	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI & 59*N*A100V21**22		30,000	\$4,200
9892730	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI & 59*N*A080V21**20		30,000	\$4,200
9892729	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI & 59MN7A060V21**20		30,400	\$4,256
9892728	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI & 59*N*A100V21**22		30,200	\$4,228
9892725	CARRIER	25VNA036A*030*	CAP**6024AL*+UI & 59*N*A100V21**22		31,800	\$4,452
9892727	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI & 59*N*A080V21**20		30,400	\$4,256
9892724	CARRIER	25VNA036A*030*	CAP**6024AL*+UI & 59*N*A080V21**20		31,800	\$4,452
9892723	CARRIER	25VNA036A*030*	CAP**6024AL*+UI & 59MN7A060V21**20		32,200	\$4,508
9892722	CARRIER	25VNA036A*030*	CAP**6021AL*+UI & 59*N*A100V21**22		31,800	\$4,452
9892718	CARRIER	25VNA036A*030*	CAP**4824AL*+UI & 59*N*A080V21**20		29,800	\$4,172

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9892721	CARRIER	25VNA036A*030*	CAP**6021AL*+UI & 59*N*A080V21**20		31,800	\$4,452
9892720	CARRIER	25VNA036A*030*	CAP**6021AL*+UI & 59MN7A060V21**20		32,200	\$4,508
9892719	CARRIER	25VNA036A*030*	CAP**4824AL*+UI & 59*N*A100V21**22		29,800	\$4,172
9892717	CARRIER	25VNA036A*030*	CAP**4824AL*+UI & 59MN7A060V21**20		30,200	\$4,228
9892716	CARRIER	25VNA036A*030*	CAP**4821AL*+UI & 59*N*A100V21**22		29,800	\$4,172
9892715	CARRIER	25VNA036A*030*	CAP**4821AL*+UI & 59*N*A080V21**20		30,000	\$4,200
9892711	CARRIER	25VNA036A*030*	CAP**4224AL*+UI & 59MN7A060V21**20		30,400	\$4,256
9892713	CARRIER	25VNA036A*030*	CAP**4224AL*+UI & 59*N*A100V21**22		30,200	\$4,228
9892714	CARRIER	25VNA036A*030*	CAP**4821AL*+UI & 59MN7A060V21**20		30,200	\$4,228
9892712	CARRIER	25VNA036A*030*	CAP**4224AL*+UI & 59*N*A080V21**20		30,200	\$4,228
9892710	CARRIER	25VNA036A*030*	CAP**4221AL*+UI & 59*N*A100V21**22		30,200	\$4,228
9892709	CARRIER	25VNA036A*030*	CAP**4221AL*+UI & 59*N*A080V21**20		30,200	\$4,228
9892706	CARRIER	25VNA036A*030*	CAP**3621AL*+UI & 59*N*A080V21**20		30,400	\$4,256
9892705	CARRIER	25VNA036A*030*	CAP**3621AL*+UI & 59MN7A060V21**20		30,600	\$4,284
9892708	CARRIER	25VNA036A*030*	CAP**4221AL*+UI & 59MN7A060V21**20		30,600	\$4,284
9892707	CARRIER	25VNA036A*030*	CAP**3621AL*+UI & 59*N*A100V21**22		30,200	\$4,228
9892704	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI & 59*N*A120V24**22		32,000	\$4,480
9892703	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI & 59*N*A080V17**14		32,400	\$4,536
9892701	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI & 59*N*A120V24**22		32,200	\$4,508

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9892702	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI & 59*N*A060V17**14		32,600	\$4,564
9892700	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI & 59*N*A080V17**14		32,800	\$4,592
9892698	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI & 59*N*A120V24**22		30,200	\$4,228
9892697	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI & 59*N*A080V17**14		30,600	\$4,284
9892695	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI & 59*N*A120V24**22		30,400	\$4,256
9892692	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI & 59*N*A120V24**22		32,200	\$4,508
9892690	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI & 59*N*A080V17**14		32,600	\$4,564
9892691	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI & 59*N*A120V24**22		32,200	\$4,508
9892680	CARRIER	25VNA036A*030*	CAP**6024AL*+UI & 59*N*A120V24**22		31,600	\$4,424
9892679	CARRIER	25VNA036A*030*	CAP**6021AL*+UI & 59*N*A080V17**14		32,000	\$4,480
9892677	CARRIER	25VNA036A*030*	CAP**4824AL*+UI & 59*N*A120V24**22		32,000	\$4,480
9892676	CARRIER	25VNA036A*030*	CAP**4821AL*+UI & 59*N*A080V17**14		32,600	\$4,564
9892672	CARRIER	25VNA036A*030*	CAP**4224AL*+UI & 59*N*A120V24**22		30,200	\$4,228
9892665	CARRIER	25VNA036A*030*	FE4AN(B,F)005L+UI		31,600	\$4,424
9892607	CARRIER	25VNA036A*030*	FE4ANB006L+UI		31,600	\$4,424
9892606	CARRIER	25VNA024A*030*	CSPH*6012AL*+UI & 59*N*A100V21**22		25,000	\$3,500
9892605	CARRIER	25VNA024A*030*	CSPH*6012AL*+UI & 59*N*A080V21**20		25,000	\$3,500
9892604	CARRIER	25VNA024A*030*	CSPH*6012AL*+UI & 59MN7A060V21**20		25,000	\$3,500
9892602	CARRIER	25VNA024A*030*	CSPH*4812AL*+UI & 59*N*A080V21**20		25,000	\$3,500
9892603	CARRIER	25VNA024A*030*	CSPH*4812AL*+UI & 59*N*A100V21**22		24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9892601	CARRIER	25VNA024A*030*	CSPH*4812AL*+UI & 59MN7A060V21**20		25,000	\$3,500
9892600	CARRIER	25VNA024A*030*	CSPH*4212AL*+UI & 59*N*A100V21**22		25,000	\$3,500
9892599	CARRIER	25VNA024A*030*	CSPH*4212AL*+UI & 59*N*A080V21**20		25,000	\$3,500
9892598	CARRIER	25VNA024A*030*	CSPH*4212AL*+UI & 59MN7A060V21**20		25,000	\$3,500
9892597	CARRIER	25VNA024A*030*	CSPH*3612AL*+UI & 59*N*A100V21**22		25,000	\$3,500
9892596	CARRIER	25VNA024A*030*	CSPH*3612AL*+UI & 59*N*A080V21**20		25,000	\$3,500
9892594	CARRIER	25VNA024A*030*	CNPV*6024AL*+UI & 59*N*A100V21**22		25,000	\$3,500
9892593	CARRIER	25VNA024A*030*	CNPV*6024AL*+UI & 59*N*A080V21**20		25,000	\$3,500
9892592	CARRIER	25VNA024A*030*	CNPV*6024AL*+UI & 59MN7A060V21**20		25,000	\$3,500
9892591	CARRIER	25VNA024A*030*	CNPV*4824AL*+UI & 59*N*A100V21**22		25,000	\$3,500
9892590	CARRIER	25VNA024A*030*	CNPV*4824AL*+UI & 59*N*A080V21**20		25,000	\$3,500
9892589	CARRIER	25VNA024A*030*	CNPV*4824AL*+UI & 59MN7A060V21**20		25,000	\$3,500
9892588	CARRIER	25VNA024A*030*	CNPV*4221AL*+UI & 59*N*A100V21**22		25,000	\$3,500
9892587	CARRIER	25VNA024A*030*	CNPV*4221AL*+UI & 59*N*A080V21**20		25,200	\$3,528
9892586	CARRIER	25VNA024A*030*	CNPV*4221AL*+UI & 59MN7A060V21**20		25,200	\$3,528
9892585	CARRIER	25VNA024A*030*	CNPV*3621AL*+UI & 59*N*A100V21**22		25,200	\$3,528
9892583	CARRIER	25VNA024A*030*	CNPV*3621AL*+UI & 59MN7A060V21**20		25,200	\$3,528
9892584	CARRIER	25VNA024A*030*	CNPV*3621AL*+UI & 59*N*A080V21**20		25,200	\$3,528
9892582	CARRIER	25VNA024A*030*	CAP**6024AL*+UI & 59*N*A100V21**22		24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9892581	CARRIER	25VNA024A*030*	CAP**6024AL*+UI & 59*N*A080V21**20		24,800	\$3,472
9892580	CARRIER	25VNA024A*030*	CAP**6024AL*+UI & 59MN7A060V21**20		24,800	\$3,472
9892579	CARRIER	25VNA024A*030*	CAP**6021AL*+UI & 59*N*A100V21**22		24,800	\$3,472
9892577	CARRIER	25VNA024A*030*	CAP**6021AL*+UI & 59MN7A060V21**20		24,800	\$3,472
9892578	CARRIER	25VNA024A*030*	CAP**6021AL*+UI & 59*N*A080V21**20		24,800	\$3,472
9892576	CARRIER	25VNA024A*030*	CAP**4824AL*+UI & 59*N*A100V21**22		24,800	\$3,472
9892575	CARRIER	25VNA024A*030*	CAP**4824AL*+UI & 59*N*A080V21**20		24,800	\$3,472
9892574	CARRIER	25VNA024A*030*	CAP**4824AL*+UI & 59MN7A060V21**20		24,800	\$3,472
9892573	CARRIER	25VNA024A*030*	CAP**4821AL*+UI & 59*N*A100V21**22		24,800	\$3,472
9892571	CARRIER	25VNA024A*030*	CAP**4821AL*+UI & 59MN7A060V21**20		24,800	\$3,472
9892572	CARRIER	25VNA024A*030*	CAP**4821AL*+UI & 59*N*A080V21**20		24,800	\$3,472
9892570	CARRIER	25VNA024A*030*	CAP**4224AL*+UI & 59*N*A100V21**22		25,000	\$3,500
9892569	CARRIER	25VNA024A*030*	CAP**4224AL*+UI & 59*N*A080V21**20		25,000	\$3,500
9892567	CARRIER	25VNA024A*030*	CAP**4221AL*+UI & 59*N*A100V21**22		25,000	\$3,500
9892566	CARRIER	25VNA024A*030*	CAP**4221AL*+UI & 59*N*A080V21**20		25,000	\$3,500
9892564	CARRIER	25VNA024A*030*	CAP**3621AL*+UI & 59*N*A100V21**22		25,000	\$3,500
9892563	CARRIER	25VNA024A*030*	CAP**3621AL*+UI & 59*N*A080V21**20		25,000	\$3,500
9892562	CARRIER	25VNA024A*030*	CAP**3621AL*+UI & 59MN7A060V21**20		25,200	\$3,528
9892561	CARRIER	25VNA024A*030*	CSPH*6012AL*+UI & 59*N*A120V24**22		25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9892560	CARRIER	25VNA024A*030*	CSPH*6012AL*+UI & 59*N*A080V17**14		25,000	\$3,500
9892559	CARRIER	25VNA024A*030*	CSPH*6012AL*+UI & 59*N*A060V17**14		25,000	\$3,500
9892558	CARRIER	25VNA024A*030*	CSPH*4812AL*+UI & 59*N*A120V24**22		25,000	\$3,500
9892557	CARRIER	25VNA024A*030*	CSPH*4812AL*+UI & 59*N*A080V17**14		25,000	\$3,500
9892556	CARRIER	25VNA024A*030*	CSPH*4812AL*+UI & 59*N*A060V17**14		25,000	\$3,500
9892555	CARRIER	25VNA024A*030*	CSPH*4212AL*+UI & 59*N*A120V24**22		25,000	\$3,500
9892554	CARRIER	25VNA024A*030*	CSPH*4212AL*+UI & 59*N*A080V17**14		25,000	\$3,500
9892551	CARRIER	25VNA024A*030*	CSPH*3612AL*+UI & 59*N*A080V17**14		25,200	\$3,528
9892553	CARRIER	25VNA024A*030*	CSPH*4212AL*+UI & 59*N*A060V17**14		25,200	\$3,528
9892552	CARRIER	25VNA024A*030*	CSPH*3612AL*+UI & 59*N*A120V24**22		25,000	\$3,500
9892550	CARRIER	25VNA024A*030*	CSPH*3612AL*+UI & 59*N*A060V17**14		25,200	\$3,528
9892549	CARRIER	25VNA024A*030*	CNPV*6024AL*+UI & 59*N*A120V24**22		25,000	\$3,500
9892548	CARRIER	25VNA024A*030*	CNPV*4824AL*+UI & 59*N*A120V24**22		25,000	\$3,500
9892547	CARRIER	25VNA024A*030*	CNPV*4821AL*+UI & 59*N*A080V17**14		25,000	\$3,500
9892546	CARRIER	25VNA024A*030*	CNPV*4821AL*+UI & 59*N*A060V17**14		25,000	\$3,500
9892545	CARRIER	25VNA024A*030*	CNPV*4221AL*+UI & 59*N*A080V17**14		25,200	\$3,528
9892544	CARRIER	25VNA024A*030*	CNPV*4221AL*+UI & 59*N*A060V17**14		25,200	\$3,528
9892543	CARRIER	25VNA024A*030*	CNPV*4217AL*+UI & 59*N*A080V17**14		25,200	\$3,528
9892542	CARRIER	25VNA024A*030*	CNPV*4217AL*+UI & 59*N*A060V17**14		25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
9892541	CARRIER	25VNA024A*030*	CNPV*3621AL*+UI & 59*N*A080V17**14		25,200	\$3,528
9892540	CARRIER	25VNA024A*030*	CNPV*3621AL*+UI & 59*N*A060V17**14		25,400	\$3,556
9892539	CARRIER	25VNA024A*030*	CNPV*3617AL*+UI & 59*N*A080V17**14		25,200	\$3,528
9892538	CARRIER	25VNA024A*030*	CNPV*3617AL*+UI & 59*N*A060V17**14		25,400	\$3,556
9892537	CARRIER	25VNA024A*030*	CAP**6024AL*+UI & 59*N*A120V24**22		24,400	\$3,416
9892536	CARRIER	25VNA024A*030*	CAP**6021AL*+UI & 59*N*A080V17**14		24,600	\$3,444
9892534	CARRIER	25VNA024A*030*	CAP**4824AL*+UI & 59*N*A120V24**22		24,800	\$3,472
9892535	CARRIER	25VNA024A*030*	CAP**6021AL*+UI & 59*N*A060V17**14		24,600	\$3,444
9892533	CARRIER	25VNA024A*030*	CAP**4821AL*+UI & 59*N*A080V17**14		24,800	\$3,472
9892532	CARRIER	25VNA024A*030*	CAP**4821AL*+UI & 59*N*A060V17**14		25,000	\$3,500
9892529	CARRIER	25VNA024A*030*	CAP**4224AL*+UI & 59*N*A120V24**22		25,000	\$3,500
9892527	CARRIER	25VNA024A*030*	CAP**4221AL*+UI & 59*N*A060V17**14		25,200	\$3,528
9892528	CARRIER	25VNA024A*030*	CAP**4221AL*+UI & 59*N*A080V17**14		25,200	\$3,528
9892526	CARRIER	25VNA024A*030*	CAP**3621AL*+UI & 59*N*A080V17**14		25,200	\$3,528
9892525	CARRIER	25VNA024A*030*	CAP**3621AL*+UI & 59*N*A060V17**14		25,200	\$3,528
9892524	CARRIER	25VNA024A*030*	CAP**3617AL*+UI & 59*N*A080V17**14		25,200	\$3,528
9892523	CARRIER	25VNA024A*030*	CAP**3617AL*+UI & 59*N*A060V17**14		25,200	\$3,528
9892513	CARRIER	25VNA024A*030*	FE4AN(B,F)003L+UI		25,000	\$3,500
9892512	CARRIER	25VNA024A*030*	FE4ANF002L + UI		25,200	\$3,528
9892461	CARRIER	25VNA024A*030*	FE4ANB006L+UI		24,800	\$3,472
9892658	CARRIER	25VNA036A*030*	FE4ANF002L+UI		30,600	\$4,284
9892659	CARRIER	25VNA036A*030*	FE4AN(B,F)003L+UI		30,200	\$4,228

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430011	CARRIER	25VNA024A*030*	CAP**4224AL*+UI	58TN*A135C24**22	25,000	\$3,500
204430006	CARRIER	25VNA024A*030*	CAP**4224AL*+UI	58TN*A090C21**20	22,000	\$3,080
204429898	CARRIER	25VNA024A*030*	CAP**3617AL*+UI	58TN*A090C17**16	21,600	\$3,024
204430066	CARRIER	25VNA024A*030*	CNPV*4221AL*+UI	59MN7B100C21**22	25,200	\$3,528
204430064	CARRIER	25VNA024A*030*	CNPV*4221AL*+UI	59TN6B080C17**14	22,400	\$3,136
204429998	CARRIER	25VNA024A*030*	CAP**4221AL*+UI	58TN*A110C21**20	22,000	\$3,080
204430074	CARRIER	25VNA024A*030*	CNPV*4221AL*+UI	59MN7B060C21**20	22,400	\$3,136
204430019	CARRIER	25VNA024A*030*	CAP**4224AL*+UI	59TN6B080C21**20	22,200	\$3,108
204430096	CARRIER	25VNA024A*030*	CSPH*3012AL*+UI	58TN*A090C21**20	23,000	\$3,220
204430052	CARRIER	25VNA024A*030*	CNPV*3621AL*+UI	59MN7B080C21**20	25,000	\$3,500
204633415	CARRIER	25VNA024A*030*	CNPV*3621AL*+UI	59MN7B060C21**20	21,400	\$2,996
204429928	CARRIER	25VNA024A*030*	CAP**3621AL*+UI	59TN6B080C17**14	25,200	\$3,528
204430122	CARRIER	25VNA024A*030*	CSPH*3012AL*+UI	58TN*A070C14**12	25,200	\$3,528
204429880	CARRIER	25VNA024A*030*	CAP**3617AL*+UI	59TN6B080C17**14	25,200	\$3,528
204430099	CARRIER	25VNA024A*030*	CSPH*3012AL*+UI	58TN*A135C24**22	25,200	\$3,528
204429923	CARRIER	25VNA024A*030*	CAP**3621AL*+UI	59TN6B060C17**14	21,600	\$3,024
204430114	CARRIER	25VNA024A*030*	CSPH*3012AL*+UI	59MN7B120C24**22	25,200	\$3,528
204430027	CARRIER	25VNA024A*030*	CNPV*3017AL*+UI	59TN6B080C17**14	25,200	\$3,528
204429965	CARRIER	25VNA024A*030*	CAP**4221AL*+UI	58TN*A070C21**20	22,200	\$3,108
204431332	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59MN7B100C21**22	32,200	\$4,508
204430428	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	59TN6B120C24**22	32,200	\$4,508
204430426	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	58TN*A135C24**22	32,000	\$4,480
204430864	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	59TN6B120C24**22	32,400	\$4,536
204430879	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	59MN7B080C21**20	32,400	\$4,536
204431321	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59TN6B120C24**22	32,200	\$4,508
204430779	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	59TN6B120C24**22	32,600	\$4,564
204431313	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	58TN*A135C24**22	32,200	\$4,508
204431232	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	58TN*A135C24**22	32,600	\$4,564
204429866	CARRIER	25VNA024A*030*	CAP**3617AL*+UI	58TN*A045C17**12	25,200	\$3,528
204430395	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	58TN*A135C24**22	32,400	\$4,536
204430081	CARRIER	25VNA024A*030*	CSPH*2412AL*+UI	59MN7B100C21**22	25,200	\$3,528
204430076	CARRIER	25VNA024A*030*	CSPH*2412AL*+UI	58TN*A090C21**20	25,200	\$3,528
204430508	CARRIER	25VNA036A*030*	CAP**6124AL*+UI	59TN6B100C21**22	32,200	\$4,508
204430500	CARRIER	25VNA036A*030*	CAP**6124AL*+UI	59MN7B100C21**22	32,200	\$4,508
204430489	CARRIER	25VNA036A*030*	CAP**6124AL*+UI	59TN6B120C24**22	32,200	\$4,508
204430851	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	58TN*A135C24**22	32,200	\$4,508
204430459	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	58TN*A090C21**20	32,200	\$4,508
204430775	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	58TN*A135C24**22	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430918	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	58TN*A110C21**20	32,400	\$4,536
204430900	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	59TN6B080C21**20	32,400	\$4,536
204430909	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	59TN6B100C21**22	32,400	\$4,536
204430888	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	59MN7B100C21**22	32,400	\$4,536
204430772	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	58TN*A090C21**20	32,600	\$4,564
204430838	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	58TN*A090C21**20	32,400	\$4,536
204430753	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	58TN*A110C21**20	32,600	\$4,564
204430895	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	59MN7B120C24**22	32,400	\$4,536
204430423	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	58TN*A090C21**20	32,000	\$4,480
204429905	CARRIER	25VNA024A*030*	CAP**3621AL*+UI	58TN*A045C17**12	25,200	\$3,528
204430342	CARRIER	25VNA036A*030*	CAP**4321AL*+UI	59MN7B080C21**20	32,800	\$4,592
204430813	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	58TN*A110C21**20	32,600	\$4,564
204430244	CARRIER	25VNA036A*030*	CAP**3721AL*+UI	58TN*A090C21**20	32,600	\$4,564
204430711	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	58TN*A090C21**20	32,600	\$4,564
204430607	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	58TN*A090C21**20	32,600	\$4,564
204431309	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	58TN*A090C21**20	32,200	\$4,508
204431306	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	58TN*A070C21**20	32,400	\$4,536
204430689	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	58TN*A110C21**20	32,600	\$4,564
204431753	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	59TN6B120C24**22	55,000	\$7,700
204431329	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59MN7B080C21**20	32,400	\$4,536
204430434	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	59MN7B100C21**22	32,200	\$4,508
204430403	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	59MN7B100C21**22	32,400	\$4,536
204430431	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	59MN7B080C21**20	32,200	\$4,508
204430400	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	59MN7B080C21**20	32,600	\$4,564
204430398	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	59TN6B120C24**22	32,400	\$4,536
204430420	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	58TN*A070C21**20	32,200	\$4,508
204430372	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	59MN7B100C21**22	32,600	\$4,564
204431266	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59MN7B080C21**20	32,800	\$4,592
204430369	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	59MN7B080C21**20	32,600	\$4,564
204431359	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59MN7B060C21**20	32,600	\$4,564
204431349	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	58TN*A070C14**12	32,600	\$4,564
204431116	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	58TN*A135C24**22	32,600	\$4,564
204431270	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59MN7B100C21**22	32,600	\$4,564
204430448	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	59MN7B060C21**20	32,600	\$4,564
204431148	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59MN7B080C21**20	32,800	\$4,592
204431253	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59TN6B120C24**22	32,600	\$4,564
204430784	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	59MN7B080C21**20	32,800	\$4,592
204431218	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	58TN*A070C21**20	32,800	\$4,592

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431132	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59TN6B120C24**22	32,600	\$4,564
204431154	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59MN7B100C21**22	32,800	\$4,592
204430737	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	59MN7B100C21**22	32,600	\$4,564
204430706	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	58TN*A070C21**20	32,800	\$4,592
204430763	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	58TN*A070C21**20	32,800	\$4,592
204430789	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	59MN7B100C21**22	32,600	\$4,564
204430306	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	58TN*A135C24**22	32,400	\$4,536
204431101	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	58TN*A070C21**20	32,800	\$4,592
204430733	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	59MN7B080C21**20	32,800	\$4,592
204430823	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	59MN7B060C21**20	33,000	\$4,620
204430314	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	59MN7B100C21**22	32,400	\$4,536
204430280	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	59MN7B080C21**20	32,600	\$4,564
204430757	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	59MN7B060C21**20	33,000	\$4,620
204430311	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	59MN7B080C21**20	32,600	\$4,564
204430309	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	59TN6B120C24**22	32,400	\$4,536
204430283	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	59MN7B100C21**22	32,600	\$4,564
204430973	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	58TN*A135C24**22	32,800	\$4,592
204430654	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	59MN7B100C21**22	32,600	\$4,564
204430994	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59TN6B120C24**22	32,800	\$4,592
204430104	CARRIER	25VNA024A*030*	CSPH*3012AL*+UI	59MN7B060C17**14	25,400	\$3,556
204430215	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	59MN7B100C21**22	32,200	\$4,508
204430927	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	59MN7B060C21**20	32,800	\$4,592
204430644	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	59MN7B080C21**20	32,600	\$4,564
204431005	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59MN7B100C21**22	32,800	\$4,592
204431343	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59TN6B100C21**22	32,200	\$4,508
204431336	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59MN7B120C24**22	32,400	\$4,536
204431352	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	58TN*A110C21**20	32,200	\$4,508
204430503	CARRIER	25VNA036A*030*	CAP**6124AL*+UI	59MN7B120C24**22	32,200	\$4,508
204430481	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	59TN6B100C21**22	32,200	\$4,508
204430478	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	59TN6B080C21**20	32,400	\$4,536
204430475	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	59MN7B100C21**22	32,200	\$4,508
204431340	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59TN6B080C21**20	32,400	\$4,536
204430506	CARRIER	25VNA036A*030*	CAP**6124AL*+UI	59TN6B080C21**20	32,200	\$4,508
204430472	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	59MN7B080C21**20	32,400	\$4,536
204430492	CARRIER	25VNA036A*030*	CAP**6124AL*+UI	59MN7B080C21**20	32,200	\$4,508
204430487	CARRIER	25VNA036A*030*	CAP**6124AL*+UI	58TN*A070C21**20	32,400	\$4,536
204430445	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	58TN*A110C21**20	32,000	\$4,480
204430442	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	59TN6B100C21**22	32,200	\$4,508

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430456	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	58TN*A070C21**20	32,400	\$4,536
204430439	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	59TN6B080C21**20	32,200	\$4,508
204430391	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	58TN*A090C21**20	32,400	\$4,536
204430412	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	59TN6B100C21**22	32,400	\$4,536
204430437	CARRIER	25VNA036A*030*	CAP**6024AL*+UI	59MN7B120C24**22	32,200	\$4,508
204430414	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	58TN*A110C21**20	32,400	\$4,536
204431224	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	58TN*A090C21**20	32,600	\$4,564
204431283	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59TN6B100C21**22	32,600	\$4,564
204430453	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	58TN*A070C17**16	32,600	\$4,564
204430409	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	59TN6B080C21**20	32,600	\$4,564
204430380	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	58TN*A090C17**16	32,600	\$4,564
204430406	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	59MN7B120C24**22	32,600	\$4,564
204431294	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	58TN*A110C21**20	32,600	\$4,564
204430383	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	58TN*A110C21**20	32,400	\$4,536
204430378	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	59TN6B100C21**22	32,600	\$4,564
204430794	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	59MN7B120C24**22	32,800	\$4,592
204430355	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	58TN*A090C21**20	32,400	\$4,536
204430831	CARRIER	25VNA036A*030*	CNPV*6024AL*+UI	58TN*A070C21**20	32,600	\$4,564
204431195	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	58TN*A110C21**20	32,600	\$4,564
204430801	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	59TN6B080C21**20	32,800	\$4,592
204430741	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	59TN6B080C21**20	32,800	\$4,592
204430807	CARRIER	25VNA036A*030*	CNPV*4824AL*+UI	59TN6B100C21**22	32,600	\$4,564
204430749	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	58TN*A090C17**16	32,600	\$4,564
204430593	CARRIER	25VNA036A*030*	CNPV*4217AL*+UI	58TN*A090C17**16	33,000	\$4,620
204430320	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	59TN6B080C21**20	32,600	\$4,564
204430745	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	59TN6B100C21**22	32,600	\$4,564
204431109	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	58TN*A090C21**20	32,600	\$4,564
204430289	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	59TN6B100C21**22	32,600	\$4,564
204430317	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	59MN7B120C24**22	32,600	\$4,564
204430702	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	58TN*A070C17**16	33,000	\$4,620
204430681	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	58TN*A090C17**16	32,600	\$4,564
204430672	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	59TN6B100C21**22	32,600	\$4,564
204430662	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	59TN6B080C21**20	32,600	\$4,564
204430201	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	58TN*A090C21**20	32,000	\$4,480
204430226	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	58TN*A110C21**20	32,200	\$4,508
204430600	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	58TN*A070C17**16	32,800	\$4,592
204430286	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	59TN6B080C21**20	32,600	\$4,564
204431508	CARRIER	25VNA048A*030*	CAP**6124AL*+UI	58TN*A135C24**22	48,500	\$6,790

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430218	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	59TN6B080C21**20	32,200	\$4,508
204430220	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	59TN6B100C21**22	32,200	\$4,508
204430223	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	58TN*A090C17**16	32,200	\$4,508
204430388	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	58TN*A070C21**20	32,600	\$4,564
204430353	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	58TN*A070C21**20	32,600	\$4,564
204430417	CARRIER	25VNA036A*030*	CAP**4824AL*+UI	59MN7B060C21**20	32,800	\$4,592
204431504	CARRIER	25VNA048A*030*	CAP**6124AL*+UI	58TN*A090C21**20	48,500	\$6,790
204431300	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	58TN*A045C17**12	33,000	\$4,620
204430361	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	59TN6B080C17**14	33,000	\$4,620
204430557	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	58TN*A090C17**16	32,200	\$4,508
204430559	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	58TN*A110C21**20	32,200	\$4,508
204430552	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	59TN6B100C21**22	32,200	\$4,508
204430526	CARRIER	25VNA036A*030*	CNPV*3617AL*+UI	58TN*A090C17**16	32,200	\$4,508
204430331	CARRIER	25VNA036A*030*	CAP**4321AL*+UI	58TN*A070C17**16	33,000	\$4,620
204431319	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59TN6B080C17**14	32,800	\$4,592
204431286	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	58TN*A070C14**12	33,000	\$4,620
204430548	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	59TN6B080C21**20	32,200	\$4,508
204431316	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59TN6B060C17**14	33,000	\$4,620
204431248	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59TN6B080C17**14	33,200	\$4,648
204430386	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	59MN7B060C21**20	33,000	\$4,620
204430268	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	58TN*A070C21**20	32,800	\$4,592
204430165	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	59MN7B080C17**14	32,600	\$4,564
204430726	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	59TN6B080C17**14	33,200	\$4,648
204430300	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	58TN*A070C21**20	32,600	\$4,564
204431440	CARRIER	25VNA048A*030*	CAP**6024AL*+UI	58TN*A135C24**22	48,500	\$6,790
204431201	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59MN7B060C21**20	33,200	\$4,648
204431001	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59MN7B080C21**20	33,000	\$4,620
204431297	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59MN7B060C21**20	33,000	\$4,620
204431185	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	58TN*A070C14**12	33,200	\$4,648
204431128	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59TN6B080C17**14	33,200	\$4,648
204431041	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	58TN*A070C14**12	33,200	\$4,648
204430960	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	58TN*A070C21**20	33,000	\$4,620
204430212	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	59MN7B080C21**20	32,200	\$4,508
204430603	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	58TN*A070C21**20	32,800	\$4,592
204430229	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	59MN7B060C21**20	32,600	\$4,564
204430297	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	59MN7B060C21**20	33,000	\$4,620
204430328	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	59MN7B060C21**20	32,800	\$4,592
204431600	CARRIER	25VNA048A*030*	CSPH*6012AL*+UI	58TN*A135C24**22	48,500	\$6,790

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430545	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	59MN7B100C21**22	32,200	\$4,508
204430333	CARRIER	25VNA036A*030*	CAP**4321AL*+UI	58TN*A070C21**20	32,800	\$4,592
204430258	CARRIER	25VNA036A*030*	CAP**3721AL*+UI	59TN6B080C21**20	32,800	\$4,592
204431304	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	58TN*A070C17**16	32,600	\$4,564
204430242	CARRIER	25VNA036A*030*	CAP**3721AL*+UI	58TN*A070C21**20	32,800	\$4,592
204430345	CARRIER	25VNA036A*030*	CAP**4321AL*+UI	59MN7B060C21**20	33,000	\$4,620
204430255	CARRIER	25VNA036A*030*	CAP**3721AL*+UI	59MN7B080C21**20	32,800	\$4,592
204430239	CARRIER	25VNA036A*030*	CAP**3721AL*+UI	58TN*A070C17**16	33,000	\$4,620
204430511	CARRIER	25VNA036A*030*	CAP**6124AL*+UI	59MN7B060C21**20	32,600	\$4,564
204431290	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	58TN*A090C17**16	32,600	\$4,564
204430375	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	59TN6B080C21**20	32,600	\$4,564
204430260	CARRIER	25VNA036A*030*	CAP**3721AL*+UI	59MN7B060C21**20	33,000	\$4,620
204431277	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59TN6B080C21**20	32,800	\$4,592
204431327	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59MN7B080C17**14	32,800	\$4,592
204430484	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	59MN7B060C21**20	32,600	\$4,564
204431274	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59MN7B120C24**22	32,800	\$4,592
204430464	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	59TN6B080C17**14	32,800	\$4,592
204431172	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59TN6B080C21**20	32,800	\$4,592
204430470	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	59MN7B080C17**14	32,800	\$4,592
204431178	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59TN6B100C21**22	32,800	\$4,592
204431191	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	58TN*A090C17**16	32,800	\$4,592
204431213	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	58TN*A070C17**16	33,000	\$4,620
204431164	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59MN7B120C24**22	32,800	\$4,592
204430461	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	59TN6B060C17**14	33,000	\$4,620
204430350	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	58TN*A070C17**16	32,800	\$4,592
204430237	CARRIER	25VNA036A*030*	CAP**3717AL*+UI	58TN*A090C17**16	33,000	\$4,620
204431094	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	58TN*A070C17**16	33,000	\$4,620
204431065	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	58TN*A110C21**20	32,800	\$4,592
204430968	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	58TN*A090C21**20	32,800	\$4,592
204431048	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	58TN*A090C17**16	32,800	\$4,592
204431032	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59TN6B100C21**22	32,800	\$4,592
204431010	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59MN7B120C24**22	33,000	\$4,620
204431020	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59TN6B080C21**20	33,000	\$4,620
204430325	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	58TN*A110C21**20	32,400	\$4,536
204430323	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	59TN6B100C21**22	32,400	\$4,536
204430295	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	58TN*A110C21**20	32,600	\$4,564
204430292	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	58TN*A090C17**16	32,600	\$4,564
204430531	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	58TN*A070C21**20	32,400	\$4,536

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204430270	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	58TN*A090C21**20	32,400	\$4,536
204430303	CARRIER	25VNA036A*030*	CAP**4224AL*+UI	58TN*A090C21**20	32,400	\$4,536
204430571	CARRIER	25VNA036A*030*	CNPV*4217AL*+UI	58TN*A070C17**16	33,200	\$4,648
204430265	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	58TN*A070C17**16	32,800	\$4,592
204431527	CARRIER	25VNA048A*030*	CAP**6124AL*+UI	58TN*A110C21**20	48,500	\$6,790
204430635	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	59MN7B080C17**14	33,200	\$4,648
204430195	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	58TN*A070C17**16	32,400	\$4,536
204431521	CARRIER	25VNA048A*030*	CAP**6124AL*+UI	59TN6B080C21**20	49,000	\$6,860
204430541	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	59MN7B080C21**20	32,200	\$4,508
204430347	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	58TN*A045C17**12	33,200	\$4,648
204431512	CARRIER	25VNA048A*030*	CAP**6124AL*+UI	59TN6B120C24**22	48,500	\$6,790
204431518	CARRIER	25VNA048A*030*	CAP**6124AL*+UI	59MN7B100C21**22	48,500	\$6,790
204431621	CARRIER	25VNA048A*030*	CSPH*6012AL*+UI	59TN6B100C21**22	49,000	\$6,860
204431497	CARRIER	25VNA048A*030*	CAP**6121AL*+UI	58TN*A110C21**20	48,500	\$6,790
204431500	CARRIER	25VNA048A*030*	CAP**6124AL*+UI	58TN*A070C21**20	49,000	\$6,860
204431478	CARRIER	25VNA048A*030*	CAP**6121AL*+UI	58TN*A090C21**20	48,500	\$6,790
204431490	CARRIER	25VNA048A*030*	CAP**6121AL*+UI	59TN6B100C21**22	48,500	\$6,790
204431515	CARRIER	25VNA048A*030*	CAP**6124AL*+UI	59MN7B080C21**20	49,000	\$6,860
204430175	CARRIER	25VNA036A*030*	CAP**3617AL*+UI	58TN*A070C17**16	32,600	\$4,564
204431476	CARRIER	25VNA048A*030*	CAP**6121AL*+UI	58TN*A070C21**20	49,000	\$6,860
204431437	CARRIER	25VNA048A*030*	CAP**6024AL*+UI	58TN*A090C21**20	48,500	\$6,790
204431493	CARRIER	25VNA048A*030*	CAP**6121AL*+UI	58TN*A090C17**16	49,000	\$6,860
204431625	CARRIER	25VNA048A*030*	CSPH*6012AL*+UI	58TN*A090C17**16	49,000	\$6,860
204431617	CARRIER	25VNA048A*030*	CSPH*6012AL*+UI	59TN6B080C21**20	49,000	\$6,860
204431614	CARRIER	25VNA048A*030*	CSPH*6012AL*+UI	59MN7B120C24**22	49,000	\$6,860
204431484	CARRIER	25VNA048A*030*	CAP**6121AL*+UI	59MN7B100C21**22	48,500	\$6,790
204430514	CARRIER	25VNA036A*030*	CNPV*3617AL*+UI	58TN*A070C17**16	32,600	\$4,564
204430563	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	59MN7B060C21**20	32,600	\$4,564
204430528	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	58TN*A070C17**16	32,400	\$4,536
204431454	CARRIER	25VNA048A*030*	CAP**6024AL*+UI	59MN7B120C24**22	49,000	\$6,860
204430538	CARRIER	25VNA036A*030*	CNPV*3621AL*+UI	59MN7B080C17**14	32,600	\$4,564
204430209	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	59MN7B080C17**14	32,600	\$4,564
204430450	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	58TN*A045C17**12	33,000	\$4,620
204431207	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	58TN*A045C17**12	33,400	\$4,676
204430358	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	59TN6B060C17**14	33,200	\$4,648
204431604	CARRIER	25VNA048A*030*	CSPH*6012AL*+UI	59TN6B120C24**22	48,500	\$6,790
204431427	CARRIER	25VNA048A*030*	CAP**6024AL*+UI	58TN*A070C21**20	50,000	\$7,000
204430699	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	58TN*A045C17**12	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431443	CARRIER	25VNA048A*030*	CAP**6024AL*+UI	59TN6B120C24**22	48,500	\$6,790
204431751	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	58TN*A135C24**22	55,000	\$7,700
204431244	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59TN6B060C17**14	33,200	\$4,648
204431447	CARRIER	25VNA048A*030*	CAP**6024AL*+UI	59MN7B080C21**20	49,000	\$6,860
204430147	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	59MN7B080C17**14	30,600	\$4,284
204430162	CARRIER	25VNA036A*030*	CNPV*4217AL*+UI	59MN7B060C17**14	31,000	\$4,340
204430719	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	59TN6B060C17**14	33,200	\$4,648
204431720	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	58TN*A135C24**22	55,500	\$7,770
204431072	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59MN7B060C21**20	33,200	\$4,648
204431122	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59TN6B060C17**14	33,400	\$4,676
204430991	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59TN6B080C17**14	33,400	\$4,676
204430579	CARRIER	25VNA036A*030*	CNPV*4217AL*+UI	59TN6B080C17**14	33,400	\$4,676
204430198	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	58TN*A070C21**20	32,400	\$4,536
204430589	CARRIER	25VNA036A*030*	CNPV*4217AL*+UI	58TN*A070C14**12	33,200	\$4,648
204430575	CARRIER	25VNA036A*030*	CNPV*4217AL*+UI	59TN6B060C17**14	33,600	\$4,704
204430565	CARRIER	25VNA036A*030*	CNPV*4217AL*+UI	58TN*A045C17**12	33,600	\$4,704
204431607	CARRIER	25VNA048A*030*	CSPH*6012AL*+UI	59MN7B080C21**20	49,000	\$6,860
204431611	CARRIER	25VNA048A*030*	CSPH*6012AL*+UI	59MN7B100C21**22	49,000	\$6,860
204431597	CARRIER	25VNA048A*030*	CSPH*6012AL*+UI	58TN*A070C21**20	49,000	\$6,860
204430983	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59TN6B060C17**14	33,600	\$4,704
204430207	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	59TN6B080C17**14	32,600	\$4,564
204431487	CARRIER	25VNA048A*030*	CAP**6121AL*+UI	59TN6B080C21**20	49,000	\$6,860
204430273	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	59TN6B060C17**14	33,200	\$4,648
204431730	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	59MN7B100C21**22	56,000	\$7,840
204430596	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	58TN*A045C17**12	33,400	\$4,676
204430339	CARRIER	25VNA036A*030*	CAP**4321AL*+UI	59MN7B080C17**14	33,200	\$4,648
204430336	CARRIER	25VNA036A*030*	CAP**4321AL*+UI	59TN6B080C17**14	33,200	\$4,648
204430250	CARRIER	25VNA036A*030*	CAP**3721AL*+UI	59TN6B080C17**14	33,200	\$4,648
204430467	CARRIER	25VNA036A*030*	CAP**6121AL*+UI	59MN7B060C17**14	33,000	\$4,620
204430252	CARRIER	25VNA036A*030*	CAP**3721AL*+UI	59MN7B080C17**14	33,200	\$4,648
204430247	CARRIER	25VNA036A*030*	CAP**3721AL*+UI	59TN6B060C17**14	33,400	\$4,676
204431324	CARRIER	25VNA036A*030*	CSPH*6012AL*+UI	59MN7B060C17**14	33,000	\$4,620
204430232	CARRIER	25VNA036A*030*	CAP**3717AL*+UI	58TN*A070C17**16	33,200	\$4,648
204431262	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59MN7B080C17**14	33,200	\$4,648
204430234	CARRIER	25VNA036A*030*	CAP**3717AL*+UI	58TN*A070C14**12	33,400	\$4,676
204430366	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	59MN7B080C17**14	33,000	\$4,620
204430364	CARRIER	25VNA036A*030*	CAP**4821AL*+UI	59MN7B060C17**14	33,200	\$4,648
204430999	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59MN7B080C17**14	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431138	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59MN7B080C17**14	33,200	\$4,648
204430585	CARRIER	25VNA036A*030*	CNPV*4217AL*+UI	59MN7B080C17**14	33,400	\$4,676
204430948	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	58TN*A070C17**16	33,200	\$4,648
204430729	CARRIER	25VNA036A*030*	CNPV*4821AL*+UI	59MN7B060C17**14	33,400	\$4,676
204430621	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	59TN6B080C17**14	33,200	\$4,648
204431525	CARRIER	25VNA048A*030*	CAP**6124AL*+UI	59TN6B100C21**22	48,500	\$6,790
204430613	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	59TN6B060C17**14	33,400	\$4,676
204430694	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	59MN7B060C21**20	33,000	\$4,620
204430181	CARRIER	25VNA036A*030*	CAP**3617AL*+UI	59TN6B080C17**14	32,800	\$4,592
204431635	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	58TN*A135C24**22	53,500	\$7,490
204431576	CARRIER	25VNA048A*030*	CSPH*4812AL*+UI	59MN7B080C21**20	35,600	\$4,984
204430156	CARRIER	25VNA036A*030*	CNPV*3617AL*+UI	59MN7B080C17**14	31,000	\$4,340
204431471	CARRIER	25VNA048A*030*	CAP**6024AL*+UI	58TN*A110C21**20	48,500	\$6,790
204430519	CARRIER	25VNA036A*030*	CNPV*3617AL*+UI	58TN*A070C14**12	32,600	\$4,564
204431463	CARRIER	25VNA048A*030*	CAP**6024AL*+UI	59TN6B080C21**20	49,000	\$6,860
204430204	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	59TN6B060C17**14	32,800	\$4,592
204430631	CARRIER	25VNA036A*030*	CNPV*4221AL*+UI	59MN7B060C17**14	33,400	\$4,676
204431683	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	58TN*A070C21**20	54,000	\$7,560
204431748	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	58TN*A090C21**20	55,000	\$7,700
204430186	CARRIER	25VNA036A*030*	CAP**3617AL*+UI	59MN7B080C17**14	32,800	\$4,592
204431703	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	59MN7B120C24**22	55,000	\$7,700
204430276	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	59MN7B060C17**14	33,200	\$4,648
204431696	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	59MN7B080C21**20	54,000	\$7,560
204431769	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	59TN6B100C21**22	55,000	\$7,700
204431772	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	58TN*A110C21**20	55,000	\$7,700
204431705	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	59TN6B080C21**20	54,000	\$7,560
204431663	CARRIER	25VNA060A*030*	CAP**6121AL*+UI	58TN*A090C21**20	55,000	\$7,700
204431679	CARRIER	25VNA060A*030*	CAP**6121AL*+UI	58TN*A110C21**20	55,000	\$7,700
204431711	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	58TN*A110C21**20	55,000	\$7,700
204431709	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	59TN6B100C21**22	55,000	\$7,700
204431676	CARRIER	25VNA060A*030*	CAP**6121AL*+UI	59TN6B100C21**22	55,000	\$7,700
204431670	CARRIER	25VNA060A*030*	CAP**6121AL*+UI	59MN7B100C21**22	55,000	\$7,700
204431689	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	58TN*A135C24**22	55,000	\$7,700
204431700	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	59MN7B100C21**22	55,000	\$7,700
204431686	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	58TN*A090C21**20	55,000	\$7,700
204431692	CARRIER	25VNA060A*030*	CAP**6124AL*+UI	59TN6B120C24**22	55,000	\$7,700
204431741	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	58TN*A110C21**20	56,000	\$7,840
204431717	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	58TN*A090C21**20	56,000	\$7,840

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204431739	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	59TN6B100C21**22	56,000	\$7,840
204430262	CARRIER	25VNA036A*030*	CAP**4221AL*+UI	58TN*A045C17**12	33,200	\$4,648
204431654	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	59TN6B100C21**22	53,500	\$7,490
204431632	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	58TN*A090C21**20	53,500	\$7,490
204431733	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	59MN7B120C24**22	54,500	\$7,630
204431714	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	58TN*A070C21**20	56,000	\$7,840
204431735	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	59TN6B080C21**20	54,500	\$7,630
204431083	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	58TN*A045C17**12	33,400	\$4,676
204431658	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	58TN*A110C21**20	53,500	\$7,490
204430937	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	58TN*A045C17**12	33,600	\$4,704
204431760	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	59MN7B100C21**22	55,000	\$7,700
204431136	CARRIER	25VNA036A*030*	CSPH*4212AL*+UI	59MN7B060C17**14	33,400	\$4,676
204430192	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	58TN*A045C17**12	32,800	\$4,592
204431641	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	59MN7B080C21**20	54,000	\$7,560
204431258	CARRIER	25VNA036A*030*	CSPH*4812AL*+UI	59MN7B060C17**14	33,400	\$4,676
204430997	CARRIER	25VNA036A*030*	CSPH*3612AL*+UI	59MN7B060C17**14	33,600	\$4,704
204431744	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	58TN*A070C21**20	55,500	\$7,770
204431644	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	59MN7B100C21**22	53,500	\$7,490
204431723	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	59TN6B120C24**22	56,000	\$7,840
204431638	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	59TN6B120C24**22	53,500	\$7,490
204431766	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	59TN6B080C21**20	55,500	\$7,770
204431647	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	59MN7B120C24**22	53,500	\$7,490
204431673	CARRIER	25VNA060A*030*	CAP**6121AL*+UI	59TN6B080C21**20	55,500	\$7,770
204431667	CARRIER	25VNA060A*030*	CAP**6121AL*+UI	59MN7B080C21**20	55,500	\$7,770
204431651	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	59TN6B080C21**20	54,000	\$7,560
204431763	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	59MN7B120C24**22	55,500	\$7,770
204431629	CARRIER	25VNA060A*030*	CAP**6024AL*+UI	58TN*A070C21**20	54,000	\$7,560
204431660	CARRIER	25VNA060A*030*	CAP**6121AL*+UI	58TN*A070C21**20	54,000	\$7,560
204431757	CARRIER	25VNA060A*030*	CSPH*6012AL*+UI	59MN7B080C21**20	55,500	\$7,770
204431726	CARRIER	25VNA060A*030*	CNPV*6024AL*+UI	59MN7B080C21**20	54,500	\$7,630
204430145	CARRIER	25VNA036A*030*	CAP**3621AL*+UI	59MN7B060C17**14	31,000	\$4,340
204430189	CARRIER	25VNA036A*030*	CAP**3617AL*+UI	58TN*A090C17**16	32,400	\$4,536
207642891	CARRIER	38MGHBQ36DA3	Heat pump without ducts		23,200	\$3,248
207642888	CARRIER	38MGHBQ48EA3	Heat pump without ducts		30,000	\$4,200
207642882	CARRIER	38MGHBQ30DA3	Heat pump without ducts		17,500	\$2,450
206788331	CARRIER	25VNA424A*031*	FE4AN(B,F)005L+UI		23,800	\$3,332
9118473	CARRIER	38MGRQ36D--3	Heat pump without ducts		23,200	\$3,248
9854626	CARRIER	38MGRQ30D--3	Heat pump without ducts		17,400	\$2,436

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211194297	CARRIER	38MURAQ30AB3*	FX4DN(B,F)037L		23,200	\$3,248
208447882	CARRIER	38MURAQ48AB3	40MUAAQ48XA3		36,000	\$5,040
211226121	CARRIER	38MURAQ36AB3*	FB4CNF042L		29,200	\$4,088
211226122	CARRIER	38MURAQ36AB3*	FB4CNF048L		29,400	\$4,116
211226123	CARRIER	38MURAQ36AB3*	FB4CNP042L		29,200	\$4,088
211226124	CARRIER	38MURAQ36AB3*	FB4CNP048L		29,400	\$4,116
211226126	CARRIER	38MURAQ36AB3*	FMA4P36**AL*		29,800	\$4,172
211226128	CARRIER	38MURAQ36AB3*	FX4DN(B,F)037L		29,000	\$4,060
211226131	CARRIER	38MURAQ36AB3*	FZ4ANP048L		29,000	\$4,060
211719725	CARRIER	38MURAQ18AB3*	FMA4P18**AL*		12,700	\$1,778
211258115	CARRIER	38MURAQ18AB3*	FX4DNF019L		12,300	\$1,722
211258114	CARRIER	38MURAQ18AB3*	FB4CNP025L		12,100	\$1,694
211258113	CARRIER	38MURAQ18AB3*	FB4CNP024L		12,300	\$1,722
211258112	CARRIER	38MURAQ18AB3*	FB4CNP018L		12,300	\$1,722
211258111	CARRIER	38MURAQ18AB3*	FB4CNF024L		12,300	\$1,722
211258109	CARRIER	38MURAQ18AB3*	FB4CNF018L		12,300	\$1,722
211258107	CARRIER	38MURAQ18AB3*	FZ4ANP024L		12,200	\$1,708
212409578	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*A045E17**14	19,100	\$2,674
212409577	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*A045E17**14	19,100	\$2,674
212409576	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*A045E17**14	19,100	\$2,674
212409575	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*A045E17**14	19,400	\$2,716
212409573	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58S(B,C)*A045E17**14	18,900	\$2,646
212409572	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*A045E17**14	19,100	\$2,674
212409571	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*A045E17**14	19,100	\$2,674
212409570	CARRIER	38MURAQ24AB3*	CAP**3017AL*	58S(B,C)*A045E17**14	19,100	\$2,674
212409568	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*A045E17**14	19,400	\$2,716
213785314	CARRIER	25VNA436A*031*	CAP**3014AL*+UI	58TN*B070C14**12	34,800	\$4,872
213785312	CARRIER	25VNA436A*031*	CAP**2517AL*+UI	59TN6C080C17**14	32,800	\$4,592
213785310	CARRIER	25VNA436A*031*	CAP**2517AL*+UI	59TN6C060C17**14	32,800	\$4,592
213785308	CARRIER	25VNA436A*031*	CAP**2517AL*+UI	59MN7C080C17**14	32,800	\$4,592
213785306	CARRIER	25VNA436A*031*	CAP**2517AL*+UI	59MN7C060C17**14	33,000	\$4,620
213785304	CARRIER	25VNA436A*031*	CAP**2517AL*+UI	59CU5B060C17**16	32,800	\$4,592
213785302	CARRIER	25VNA436A*031*	CAP**2517AL*+UI	58TN*B090C17**16	32,600	\$4,564
213785300	CARRIER	25VNA436A*031*	CAP**2517AL*+UI	58TN*B070C17**16	32,800	\$4,592
213785298	CARRIER	25VNA436A*031*	CAP**2517AL*+UI	58TN*B070C14**12	32,800	\$4,592
213785296	CARRIER	25VNA436A*031*	CAP**2517AL*+UI	58TN*B045C17**12	33,000	\$4,620
213785294	CARRIER	25VNA436A*031*	CAP**2417AL*+UI	59TN6C080C17**14	35,600	\$4,984
213785292	CARRIER	25VNA436A*031*	CAP**2417AL*+UI	59TN6C060C17**14	35,800	\$5,012

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785290	CARRIER	25VNA436A*031*	CAP**2417AL*+UI	59MN7C080C17**14	35,600	\$4,984
213785288	CARRIER	25VNA436A*031*	CAP**2417AL*+UI	59MN7C060C17**14	35,800	\$5,012
213785286	CARRIER	25VNA436A*031*	CAP**2417AL*+UI	59CU5B060C17**16	35,600	\$4,984
213785284	CARRIER	25VNA436A*031*	CAP**2417AL*+UI	58TN*B090C17**16	35,600	\$4,984
213785282	CARRIER	25VNA436A*031*	CAP**2417AL*+UI	58TN*B070C17**16	35,600	\$4,984
213785280	CARRIER	25VNA436A*031*	CAP**2417AL*+UI	58TN*B070C14**12	35,600	\$4,984
213785278	CARRIER	25VNA436A*031*	CAP**2417AL*+UI	58TN*B045C17**12	35,800	\$5,012
213785276	CARRIER	25VNA436A*031*	CAP**2414AL*+UI	58TN*B070C14**12	35,800	\$5,012
210720685	CARRIER	25VNA436A*031*	CNPV*6024AL*+UI	59CU5A080C21**20	30,600	\$4,284
210720679	CARRIER	25VNA436A*031*	CNPV*4824AL*+UI	59CU5A080C21**20	31,200	\$4,368
210720655	CARRIER	25VNA436A*031*	CAP**6121AL*+UI	59CU5A080C21**20	30,000	\$4,200
212978653	CARRIER	38MURAQ24AB3*	CAP**3617AL*	58S(B,C)*B070M17**12	19,000	\$2,660
212978664	CARRIER	38MURAQ24AB3*	CAP**3621AL*	58S(B,C)*B070M17**12	19,000	\$2,660
212978675	CARRIER	38MURAQ24AB3*	CAP**3717AL*	58S(B,C)*B070M17**12	18,700	\$2,618
212978686	CARRIER	38MURAQ24AB3*	CAP**3721AL*	58S(B,C)*B070M17**12	18,500	\$2,590
212978697	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	58S(B,C)*B070M17**12	19,400	\$2,716
212978708	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	58S(B,C)*B070M17**12	18,900	\$2,646
212978719	CARRIER	38MURAQ24AB3*	CNPV*3617AL*	58S(B,C)*B070M17**12	18,900	\$2,646
212978730	CARRIER	38MURAQ24AB3*	CNPV*3621AL*	58S(B,C)*B070M17**12	19,000	\$2,660
212979119	CARRIER	38MURAQ24AB3*	CAP**2417AL*	58S(B,C)*B070M17**16	19,400	\$2,716
212986163	CARRIER	38MURAQ24AB3*	CAP**3014AL*	59SC6A040M14**10	19,200	\$2,688
212986175	CARRIER	38MURAQ24AB3*	CAP**3017AL*	59SC6A040M14**10	19,200	\$2,688
212986187	CARRIER	38MURAQ24AB3*	CAP**3617AL*	59SC6A040M14**10	19,200	\$2,688
212986199	CARRIER	38MURAQ24AB3*	CAP**3717AL*	59SC6A040M14**10	18,800	\$2,632
212986211	CARRIER	38MURAQ24AB3*	CNPV*2414AL*	59SC6A040M14**10	19,500	\$2,730
212986223	CARRIER	38MURAQ24AB3*	CNPV*2417AL*	59SC6A040M14**10	19,500	\$2,730
212986235	CARRIER	38MURAQ24AB3*	CNPV*3014AL*	59SC6A040M14**10	19,200	\$2,688
212986247	CARRIER	38MURAQ24AB3*	CNPV*3017AL*	59SC6A040M14**10	19,200	\$2,688
207801578	CARRIER	38MARBQ18AA3	40MBDQ24---3		12,600	\$1,764
207826659	CARRIER	38MARBQ18AA3	40MBABQ18XB3		12,000	\$1,680
213785600	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	59TN6C120C24**22	34,400	\$4,816
213785598	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	59TN6C100C21**22	34,400	\$4,816
213785596	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	59TN6C080C17**14	34,600	\$4,844
213785594	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	59TN6C060C17**14	34,800	\$4,872
213785592	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	59MN7C120C24**22	34,600	\$4,844
213785590	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	59MN7C100C21**22	34,400	\$4,816
213785588	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	59MN7C080C17**14	34,600	\$4,844
213785586	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	59MN7C060C17**14	34,800	\$4,872

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213785584	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	59CU5B060C17**16	34,600	\$4,844
213785582	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	58TN*B135C24**22	34,400	\$4,816
213785580	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	58TN*B110C21**20	34,400	\$4,816
213785578	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	58TN*B090C21**20	34,400	\$4,816
213785576	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	58TN*B090C17**16	34,600	\$4,844
213785574	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	58TN*B070C17**16	34,600	\$4,844
213785572	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	58TN*B070C14**12	34,600	\$4,844
213785570	CARRIER	25VNA436A*031*	CSPH*2412AL*+UI	58TN*B045C17**12	34,800	\$4,872
213785632	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	59TN6C120C24**22	34,000	\$4,760
213785630	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	59TN6C100C21**22	34,000	\$4,760
213785628	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	59TN6C080C17**14	34,200	\$4,788
213785626	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	59TN6C060C17**14	34,400	\$4,816
213785624	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	59MN7C120C24**22	34,200	\$4,788
213785622	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	59MN7C100C21**22	34,000	\$4,760
213785620	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	59MN7C080C17**14	34,200	\$4,788
213785618	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	59MN7C060C17**14	34,400	\$4,816
213785616	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	59CU5B060C17**16	34,200	\$4,788
213785614	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	58TN*B135C24**22	34,000	\$4,760
213785612	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	58TN*B110C21**20	34,000	\$4,760
213785610	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	58TN*B090C21**20	34,000	\$4,760
213785608	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	58TN*B090C17**16	34,200	\$4,788
213785606	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	58TN*B070C17**16	34,200	\$4,788
213785604	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	58TN*B070C14**12	34,200	\$4,788
213785602	CARRIER	25VNA436A*031*	CSPH*3012AL*+UI	58TN*B045C17**12	34,400	\$4,816
213785332	CARRIER	25VNA436A*031*	CAP**3017AL*+UI	59TN6C080C17**14	34,600	\$4,844
213785330	CARRIER	25VNA436A*031*	CAP**3017AL*+UI	59TN6C060C17**14	34,800	\$4,872
213785328	CARRIER	25VNA436A*031*	CAP**3017AL*+UI	59MN7C080C17**14	34,600	\$4,844
213785326	CARRIER	25VNA436A*031*	CAP**3017AL*+UI	59MN7C060C17**14	34,800	\$4,872
213785324	CARRIER	25VNA436A*031*	CAP**3017AL*+UI	59CU5B060C17**16	34,600	\$4,844
213785322	CARRIER	25VNA436A*031*	CAP**3017AL*+UI	58TN*B090C17**16	34,400	\$4,816
213785320	CARRIER	25VNA436A*031*	CAP**3017AL*+UI	58TN*B070C17**16	34,600	\$4,844
213785318	CARRIER	25VNA436A*031*	CAP**3017AL*+UI	58TN*B070C14**12	34,600	\$4,844
213785316	CARRIER	25VNA436A*031*	CAP**3017AL*+UI	58TN*B045C17**12	34,800	\$4,872
214442637	CENTURY	A-VMH48PV-1	Heat pump without ducts		36,000	\$5,040
214442638	CENTURY	A-VMH48PV-1	Heat pump with ducts		36,000	\$5,040
214442639	CENTURY	A-VMH48PV-1	Combination heat pumps with or without ducts		36,000	\$5,040
214442634	CENTURY	A-VMH55PV-1	Heat pump without ducts		34,400	\$4,816

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214442635	CENTURY	A-VMH55PV-1	Heat pump with ducts		35,200	\$4,928
214442636	CENTURY	A-VMH55PV-1	Combination heat pumps with or without ducts		34,800	\$4,872
212940802	CENTURY	A-VCD24SA-1	B-VCD24SA-1		19,200	\$2,688
212940800	CENTURY	A-VCD18SA-1	B-VCD18SA-1		13,500	\$1,890
212940827	CENTURY	A-VMH28TV-1	Combination heat pumps with or without ducts		26,800	\$3,752
212940824	CENTURY	A-VMH28TV-1	Heat pump with ducts		27,000	\$3,780
212940817	CENTURY	A-VMH24SV-1	B-VMH24SV-1		21,200	\$2,968
212940816	CENTURY	A-VMH18SV-1	B-VMH18SV-1		15,000	\$2,100
212940815	CENTURY	A-VMH12SV-1	B-VMH12SV-1		10,000	\$1,400
212940823	CENTURY	A-VMH28TV-1	Heat pump without ducts		26,600	\$3,724
212940821	CENTURY	A-VMH18DV-1	Heat pump without ducts		15,000	\$2,100
212940795	CENTURY	A-VCD30SA-1	B-VCD30SA-1		21,000	\$2,940
212940796	CENTURY	A-VCD36SA-1	B-VCD36SA-1		30,400	\$4,256
212940828	CENTURY	A-VMH36QV-1	Combination heat pumps with or without ducts		34,000	\$4,760
212940820	CENTURY	A-VMH18DV-1	Heat pump with ducts		16,000	\$2,240
212940822	CENTURY	A-VMH18DV-1	Combination heat pumps with or without ducts		15,500	\$2,170
212940825	CENTURY	A-VMH36QV-1	Heat pump without ducts		33,000	\$4,620
212940798	CENTURY	A-VCD24SA-1	MCD18/24B1A		21,000	\$2,940
212940805	CENTURY	A-VCD36SA-1	MCD30/36C1A		33,000	\$4,620
214810655	CENTURY	A-VCD30SA-1	MCD30/36B1A		19,600	\$2,744
200059040	CENTURY	B-VMH12SU-1	A-VMH12SU-1		7,800	\$1,092
214810656	CENTURY	A-VCD36SA-1	MCD30/36B1A		27,400	\$3,836
201862959	CENTURY	A-VMH36QU-1	Heat pump without ducts		23,200	\$3,248
214415105	CENTURY	A-VMH33SV-1	B-VMH33SV-1		28,800	\$4,032
214415107	CENTURY	A-VMH36QV-1A	Heat pump without ducts		27,400	\$3,836
214415109	CENTURY	A-VMH36QV-1A	Heat pump with ducts		30,000	\$4,200
214415110	CENTURY	A-VMH36QV-1A	Combination heat pumps with or without ducts		28,600	\$4,004
200059036	CENTURY	A-VMH24SU-1	B-VMH24SU-1		15,400	\$2,156
212940801	CENTURY	A-VCD48SA-1	B-VCD48SA-1		36,000	\$5,040
212940803	CENTURY	A-VCD30SA-1	MCD30/36C1A		22,600	\$3,164
212940797	CENTURY	A-VCD60SA-1	B-VCD60SA-1		42,000	\$5,880
212940806	CENTURY	A-VCD60SA-1	MCD60D1A		37,000	\$5,180
214397304	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM9E080C20MP12	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396904	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM9E080C20MP12	29,000	\$4,060
214398184	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM9Y100C20MP11	30,000	\$4,200
214398521	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM9E100C20MP12	29,000	\$4,060
214396431	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM9E100C20MP12	29,000	\$4,060
214397677	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM9Y100C20MP11	28,600	\$4,004
214595047	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z8ES100C20SMPS1	28,600	\$4,004
214595062	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z8ES080C20SMPS1	29,400	\$4,116
214595067	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z8ES100C20SMPS1	28,600	\$4,004
214398568	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TL9E100C20UH11	28,400	\$3,976
214584674	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z8ES120C16SMPS1	28,000	\$3,920
214594987	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z8ES120C20SMPS1	28,600	\$4,004
215853454	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z9ES080C20SMPS1	28,600	\$4,004
214595017	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z8ES120C20SMPS1	28,600	\$4,004
214398526	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TL9E100C20UH11	28,600	\$4,004
214584709	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z8ES080C16SMPS1	27,600	\$3,864
214584679	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z8ES080C16SMPS1	27,600	\$3,864
214584744	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z8ES120C16SMPS1	28,000	\$3,920
214595052	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z8ES080C20SMPS1	28,400	\$3,976
214584714	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z8ES100C16SMPS1	28,200	\$3,948

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216374751	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z9ET100C20SMPS1	27,600	\$3,864
214584559	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z8ES100C16SMPS1	28,200	\$3,948
214397284	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TL8E100C20UH11	27,400	\$3,836
214398504	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TL8E100C20UH11	27,600	\$3,864
214398189	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TL8E080C16UH11	28,600	\$4,004
214396818	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TL8E080C16UH11	28,600	\$4,004
214606489	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1		28,000	\$3,920
216374552	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z9ET080C16SMPS1	27,600	\$3,864
214398548	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TL9E080C16UH11	29,000	\$4,060
214606501	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1		27,800	\$3,892
214396889	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TL9E080C16UH11	28,200	\$3,948
214606507	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1		27,600	\$3,864
216374674	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z9ET080C16SMPS1	27,600	\$3,864
214396880	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TPLC100C16MP13	28,600	\$4,004
214396875	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TPLC080C16MP13	28,600	\$4,004
214396870	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TMLV100C16MP12	28,600	\$4,004
214396865	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM8V080C16MP12	28,600	\$4,004
214396860	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM8V100C16MP12	28,600	\$4,004
214396409	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TP9C100C20MP13	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396404	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM9V100C20MP12	29,600	\$4,144
215853429	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1+JMET16CS2N1		27,800	\$3,892
214807834	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+JMET18DS2N1+TXV		36,600	\$5,124
214397590	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1+JMET18DS2N1		36,600	\$5,124
214398469	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1	TM9Y120D20MP11	38,500	\$5,390
214833525	CHAMPION HEATING AND COOLING	HH860E2S11	JSE60D5CJ2SS1		37,200	\$5,208
214606524	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1		38,000	\$5,320
214833520	CHAMPION HEATING AND COOLING	HH860E2S11	JSC60D5CJ2SS1		37,200	\$5,208
214396352	CHAMPION HEATING AND COOLING	HH860E2S11	JHC60D5CJ2SS1		37,200	\$5,208
214421539	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1+JMET16CS2N1		36,800	\$5,152
214396721	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TP9C060B12MP13	18,100	\$2,534
214396716	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TM9V060B12MP12	18,100	\$2,534
214396292	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TL9E060B12UH11	18,100	\$2,534
214807824	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+JME12B2SN1+TXV		17,500	\$2,450
214397973	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1+JME12B2SN1		17,500	\$2,450
215853312	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1+JMET08BS2N1		17,900	\$2,506
214584574	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	Z8ES100B12SMPS1	17,700	\$2,478
214606546	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1		34,800	\$4,872
216374710	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	Z9ET060B12SMPS1	28,200	\$3,948

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214807769	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+JME12B2SN 1+TXV		26,800	\$3,752
214397294	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1+JME12B2SN 1		26,800	\$3,752
214396426	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	TM9E060B12MP12	27,400	\$3,836
214398531	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM9E080C16MP12	28,000	\$3,920
214397277	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TP9C080C16MP13	28,200	\$3,948
214397272	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM9V080C16MP12	28,200	\$3,948
214398125	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	TM9Y080B12MP11	27,800	\$3,892
214398155	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TP9C080C16MP13	28,200	\$3,948
214398150	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM9V080C16MP12	28,200	\$3,948
215853434	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1+JMV17CC 2N1		28,200	\$3,948
214398108	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1+JMC16C2SN 1		28,000	\$3,920
214595002	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	Z8ES100B12SMPS1	27,000	\$3,780
214397237	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1+JMET16CS2 N1		27,800	\$3,892
215853428	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1+JMC17C2S N1		28,200	\$3,948
214719876	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM9E100C20MP12	26,400	\$3,696
214397390	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM9E100C20MP12	26,400	\$3,696
214720097	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TL8E080C16UH11	26,000	\$3,640
214398229	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TL8E080C16UH11	26,000	\$3,640
214720051	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM9Y080C16MP11	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398214	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM9Y080C16MP11	25,800	\$3,612
214609119	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	Z9ES080C16SMPS1	26,400	\$3,696
214396496	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1+JME16C2S N1		25,800	\$3,612
214396944	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1+JMT16CC2 N1		25,800	\$3,612
214397795	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1+JME12C2S N1		25,800	\$3,612
214720046	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+JMET12CS2 N1+TXV		25,800	\$3,612
214397645	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1+JMET12CS2 N1		25,800	\$3,612
214606517	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1		27,000	\$3,780
216374659	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	Z9ET100C20SMPS1	37,400	\$5,236
214650728	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+TXV	TM9E120D20MP12	37,800	\$5,292
214397197	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1	TM9E120D20MP12	37,800	\$5,292
214398000	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1+JMC17C2SN 1		36,400	\$5,096
214397175	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CHS1+JME18D2S N1		36,600	\$5,124
214584649	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z8ES100C20SMPS1	32,800	\$4,592
214584684	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z8ES120C16SMPS1	32,200	\$4,508
214720029	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TL9E080C16UH11	33,000	\$4,620
214396617	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TL9E080C16UH11	33,000	\$4,620
214398429	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1+JMT17CC 2N1		36,400	\$5,096
215853494	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1	TP9C120D20MP13	38,000	\$5,320

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853493	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1	TM9V120D20MP12	38,000	\$5,320
214397207	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1+JMET18DS2 N1		37,200	\$5,208
214606570	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CHS1		34,800	\$4,872
214807844	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+JMC20D2S N1+TXV		36,600	\$5,124
214397170	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1+JMC20D2SN 1		36,600	\$5,124
214396275	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TP9C080B12MP13	18,000	\$2,520
214396270	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TM9V080B12MP12	18,000	\$2,520
214651807	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	TM9E080B12MP12	17,800	\$2,492
214396711	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TM9E080B12MP12	17,800	\$2,492
214650811	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	TP9C060B12MP13	18,000	\$2,520
214650796	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	TM9V060B12MP12	18,000	\$2,520
214397573	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TP9C060B12MP13	18,000	\$2,520
214397568	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TM9V060B12MP12	18,000	\$2,520
214397561	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TPLC080B12MP13	18,100	\$2,534
214397556	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TM8V080B12MP12	18,100	\$2,534
214396255	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TM9Y080B12MP11	18,000	\$2,520
214396706	CHAMPION HEATING AND COOLING	HH824E2S11	JHE24B5AC2SS1		18,600	\$2,604
214606560	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1		34,800	\$4,872
214807754	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	Z8ET080B12LMPS1	26,800	\$3,752

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214584589	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	Z8ET080B12LMPS1	26,800	\$3,752
214807764	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	Z8ES080B12SMPS1	26,800	\$3,752
214584594	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	Z8ES080B12SMPS1	26,800	\$3,752
214807774	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	Z8ES100B12SMPS1	27,200	\$3,808
214584624	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	Z8ES100B12SMPS1	27,200	\$3,808
214396399	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1+JMC17C2SN1		27,600	\$3,864
214728379	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	TPLC080B12MP13	27,200	\$3,808
214728374	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	TM8V080B12MP12	27,200	\$3,808
214397314	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	TPLC080B12MP13	27,200	\$3,808
214397309	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	TM8V080B12MP12	27,200	\$3,808
214398167	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TP9C100C16MP13	28,000	\$3,920
214398162	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM9V100C16MP12	28,000	\$3,920
214397252	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1+JME16C2SN1		28,200	\$3,948
214398103	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1+JMET12CS2N1		27,800	\$3,892
214720224	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM9E080C20MP12	26,200	\$3,668
214397820	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM9E080C20MP12	26,200	\$3,668
214720152	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TL9E100C20UH11	26,200	\$3,668
214398610	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TL9E100C20UH11	26,200	\$3,668
214719871	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TL9E080C16UH11	26,000	\$3,640

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398605	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TL9E080C16UH11	26,000	\$3,640
214719989	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM9E080C16MP12	26,000	\$3,640
214397385	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM9E080C16MP12	26,000	\$3,640
214397366	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TP9C080C16MP13	25,800	\$3,612
214397361	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM9V080C16MP12	25,800	\$3,612
214398234	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1+JMC16C2S N1		25,800	\$3,612
214719908	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM9Y100C20MP11	26,600	\$3,724
214396486	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM9Y100C20MP11	26,600	\$3,724
214720137	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM9E100C16MP12	26,000	\$3,640
214397326	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM9E100C16MP12	26,000	\$3,640
214397222	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TL9E080C16UH11	26,000	\$3,640
214606490	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1		26,000	\$3,640
214397662	CHAMPION HEATING AND COOLING	HH836E2S11	JHC36B5CD2SS1		26,600	\$3,724
214650953	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+TXV	Z8ES130D20SMPS1	37,000	\$5,180
214584584	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1	Z8ES130D20SMPS1	37,000	\$5,180
214398454	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	TL8E100C20UH11	36,800	\$5,152
214396325	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1+JMC17C2S N1		36,400	\$5,096
214397916	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1	TM9Y120D20MP11	32,400	\$4,536
214809219	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z8ES120C16SMPS1	32,000	\$4,480

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214584759	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z8ES120C16SMPS1	32,000	\$4,480
214809016	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TP9C100C16MP13	32,200	\$4,508
214809199	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM9V100C16MP12	32,200	\$4,508
214396575	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TP9C100C16MP13	32,200	\$4,508
214396570	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM9V100C16MP12	32,200	\$4,508
215853496	CHAMPION HEATING AND COOLING	HH860E2S11	JHE60C5CH2SS1		37,000	\$5,180
215853495	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1	TM9Y120D20MP11	38,500	\$5,390
214606525	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1		38,000	\$5,320
214398459	CHAMPION HEATING AND COOLING	HH860E2S11	JHE60D5CJ2SS1		37,400	\$5,236
214651703	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	TM9Y080B12MP11	17,900	\$2,506
214396701	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TM9Y080B12MP11	17,900	\$2,506
214652049	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	TP9C080B12MP13	17,900	\$2,506
214652035	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	TM9V080B12MP12	17,900	\$2,506
214397983	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TP9C080B12MP13	17,900	\$2,506
214397978	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TM9V080B12MP12	17,900	\$2,506
214584739	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	Z8ES080B12SMPS1	17,700	\$2,478
214651325	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	TM9E060B12MP12	17,900	\$2,506
214397128	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TM9E060B12MP12	17,900	\$2,506
214651641	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	Z8ES080B12SMPS1	17,700	\$2,478

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214584694	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	Z8ES080B12SMPS1	17,700	\$2,478
215853313	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1+JMET12BS2 N1		17,800	\$2,492
214606544	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1		34,800	\$4,872
216374669	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	Z9ET060B12SMPS1	28,200	\$3,948
216374629	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	Z9ET060B12SMPS1	28,200	\$3,948
214398514	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	TP9C080B12MP13	27,000	\$3,780
214398509	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	TM9V080B12MP12	27,000	\$3,780
214728396	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	TP9C060B12MP13	27,200	\$3,808
214728391	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	TM9V060B12MP12	27,200	\$3,808
214396848	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	TP9C060B12MP13	27,200	\$3,808
214396843	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	TM9V060B12MP12	27,200	\$3,808
214397722	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TP9C100C16MP13	27,800	\$3,892
214397717	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM9V100C16MP12	27,800	\$3,892
214398145	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM9Y080C16MP11	27,200	\$3,808
214396436	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM9E080C16MP12	29,400	\$4,116
215853440	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	TL9E060B12UH11	27,200	\$3,808
215853441	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	TL9E060B12UH11	27,200	\$3,808
215853427	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1+JMVT16CC 2N1		28,200	\$3,948
214396813	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1+JMVT17CC2 N1		28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853450	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	Z9ES080B12SMPS1	27,600	\$3,864
214595072	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	Z8ES120C20SMPS1	26,200	\$3,668
214398583	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TP9C100C20MP13	26,400	\$3,696
214398578	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM9V100C20MP12	26,400	\$3,696
214720214	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM9Y100C16MP11	26,000	\$3,640
214396783	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM9Y100C16MP11	26,000	\$3,640
214595082	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	Z8ES080C16SMPS1	26,200	\$3,668
214807799	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+JME16C2SN1+TXV		25,800	\$3,612
214396374	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1+JME16C2SN1		25,800	\$3,612
214397346	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1+JMC17C2SN1		25,600	\$3,584
214720142	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	Z8ES100C20SMPS1	26,000	\$3,640
214595007	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	Z8ES100C20SMPS1	26,000	\$3,640
215853439	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+JMET16CS2N1+TXV		25,800	\$3,612
214396481	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1+JMET16CS2N1		25,800	\$3,612
214396446	CHAMPION HEATING AND COOLING	HH836E2S11	JHE36C5CD2SS1		27,200	\$3,808
216374776	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CHS1	Z9ET120D20SMPS1	38,000	\$5,320
214396320	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1+JME16C2SN1		36,600	\$5,124
214807849	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+JME18D2SN1+TXV		36,600	\$5,124
214396743	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1+JME18D2SN1		36,600	\$5,124

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398424	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1+JME16C2SN1		36,600	\$5,124
214809165	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+JME18D2SN1+TXV		34,400	\$4,816
214397033	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1+JME18D2SN1		34,400	\$4,816
214808991	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TL8E100C20UH11	32,600	\$4,564
214396565	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TL8E100C20UH11	32,600	\$4,564
215853489	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1	Z8ES130D20SMPS1	38,000	\$5,320
214397212	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1+JME18D2SN1		37,200	\$5,208
214606569	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1		34,600	\$4,844
214397202	CHAMPION HEATING AND COOLING	HH860E2S11	JHE60D5CH2SS1		36,800	\$5,152
214396265	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1+JMC12B2SN1		17,600	\$2,464
214397990	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TM9E080B12MP12	17,900	\$2,506
214650001	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	TL9E060B12UH11	18,000	\$2,520
214397995	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TL9E060B12UH11	18,000	\$2,520
215853311	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1+JMVT12BC2N1		17,600	\$2,464
214807819	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+JMC12B2SN1+TXV		17,600	\$2,464
214396696	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1+JMC12B2SN1		17,600	\$2,464
214807804	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+JME08B2SN1+TXV		17,600	\$2,464
214397963	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1+JME08B2SN1		17,600	\$2,464
216374588	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	Z9ET080B12SMPS1	28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214397378	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TP9C100C20MP13	26,600	\$3,724
214397373	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM9V100C20MP12	26,600	\$3,724
214398590	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM9Y080C16MP11	25,800	\$3,612
214720219	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	Z8ES080C16SMPS1	26,200	\$3,668
214595037	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	Z8ES080C16SMPS1	26,200	\$3,668
214807784	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+JMT17CC2 N1+TXV		25,800	\$3,612
214398573	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1+JMT17CC2 N1		25,800	\$3,612
214397331	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1+JMT17CC2 N1		25,600	\$3,584
214807789	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+JMC17C2SN 1+TXV		25,800	\$3,612
214396491	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1+JMC17C2SN 1		25,800	\$3,612
214421529	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1+JMT16CS2 N1		25,800	\$3,612
216374735	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	Z9ET100C20SMPS1	37,400	\$5,236
214398064	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	TM9E080C20MP12	38,000	\$5,320
214584579	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	Z8ES120C20SMPS1	36,600	\$5,124
214397595	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CHS1+JMT20DC 2N1		36,600	\$5,124
214609056	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z9ES100C16SMPS1	33,600	\$4,704
214651822	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+TXV	TM9Y120D20MP11	32,400	\$4,536
214398721	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1	TM9Y120D20MP11	32,400	\$4,536
214807839	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+JMT20DC2 N1+TXV		37,000	\$5,180

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396738	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1+JMVT20DC2 N1		37,000	\$5,180
214595012	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1	Z8ES130D20SMPS1	37,600	\$5,264
214398069	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1+JMC20D2SN 1		37,000	\$5,180
214606547	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1		34,600	\$4,844
214421514	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1+JMET16CS2 N1		36,800	\$5,152
214651972	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	Z8ET080B12LMPS1	17,800	\$2,492
214584699	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	Z8ET080B12LMPS1	17,800	\$2,492
214807814	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+JMVT12BC2 N1+TXV		17,600	\$2,464
214396260	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1+JMVT12BC2 N1		17,600	\$2,464
214651759	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	TM9Y060B12MP11	18,000	\$2,520
214397133	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TM9Y060B12MP11	18,000	\$2,520
214397968	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1+JME12B2SN 1		17,600	\$2,464
214807809	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+JMET08BS2 N1+TXV		17,800	\$2,492
214397123	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1+JMET08BS2 N1		17,800	\$2,492
214606480	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1		18,800	\$2,632
214809150	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+JMVT20DC2 N1+TXV		33,800	\$4,732
214397432	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1+JMVT20DC2 N1		33,800	\$4,732
216374634	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	Z9ET080B12SMPS1	28,000	\$3,920
216374593	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	Z9ET080B12SMPS1	28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216374547	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z9ET100C16SMPS1	26,800	\$3,752
215853451	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z9ES080C16SMPS1	27,000	\$3,780
214396441	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	TM9E080B12MP12	28,200	\$3,948
214728369	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	TM9Y060B12MP11	27,800	\$3,892
214396909	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	TM9Y060B12MP11	27,800	\$3,892
214397729	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM9E100C16MP12	28,000	\$3,920
214719695	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	TM9Y080B12MP11	27,800	\$3,892
214397257	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	TM9Y080B12MP11	27,800	\$3,892
214807749	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+JMV12BC2 N1+TXV		27,800	\$3,892
214396394	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1+JMV12BC2 N1		27,800	\$3,892
214779457	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+JMET12BS2 N1+TXV		28,200	\$3,948
214421509	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1+JMET12BS2 N1		28,200	\$3,948
214398499	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1+JMV16CC2 N1		28,000	\$3,920
214398140	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	TM9Y060B12MP11	27,600	\$3,864
214397299	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1+JME12C2SN 1		27,000	\$3,780
214584749	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	Z8ES120C16SMPS1	25,800	\$3,612
214421524	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1+JMET12CS2 N1		25,800	\$3,612
214397805	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM9Y100C16MP11	25,800	\$3,612
214398084	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TP9C100C16MP13	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398079	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM9V100C16MP12	25,800	\$3,612
214398372	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1+JME08B2SN1		17,700	\$2,478
214584659	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	Z8ET080B12LMPS1	17,800	\$2,492
214606481	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1		18,800	\$2,632
214606542	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1		34,800	\$4,872
216374746	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z9ET100C16SMPS1	28,000	\$3,920
214728386	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	TM9E060B12MP12	27,400	\$3,836
214396808	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	TM9E060B12MP12	27,400	\$3,836
215853432	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1+JME12C2SN1		26,800	\$3,752
214397764	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TPLC100C16MP13	28,200	\$3,948
214397759	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TPLC080C16MP13	28,200	\$3,948
214397754	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TMLV100C16MP12	28,200	\$3,948
214397749	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM8V080C16MP12	28,200	\$3,948
214397744	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM8V100C16MP12	28,200	\$3,948
214728364	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	TM9E080B12MP12	28,200	\$3,948
214397289	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	TM9E080B12MP12	28,200	\$3,948
215853433	CHAMPION HEATING AND COOLING	HH836E2S11	JHE36B5CD2SS1		28,400	\$3,976
214807759	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+JMC12B2SN1+TXV		27,800	\$3,892
214396855	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1+JMC12B2SN1		27,800	\$3,892

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853431	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1+JMET12CS2N1		27,800	\$3,892
215853436	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1+JMC16C2SN1		28,200	\$3,948
214719881	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TL8E100C20UH11	25,800	\$3,612
214397395	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TL8E100C20UH11	25,800	\$3,612
214396998	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TL9E100C20UH11	26,200	\$3,668
214396541	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TPLC100C16MP13	25,800	\$3,612
214396536	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TPLC080C16MP13	25,800	\$3,612
214396531	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TMLV100C16MP12	25,800	\$3,612
214396526	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM8V080C16MP12	25,800	\$3,612
214396521	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM8V100C16MP12	25,800	\$3,612
214397800	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM9Y100C20MP11	26,600	\$3,724
214398074	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM9E100C16MP12	26,000	\$3,640
215853437	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+JMC16C2SN1+TXV		25,800	\$3,612
214398209	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1+JMC16C2SN1		25,800	\$3,612
214807779	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	Z8ES120C16SMPS1	25,800	\$3,612
214584629	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	Z8ES120C16SMPS1	25,800	\$3,612
214719901	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TP9C080C16MP13	26,000	\$3,640
214719896	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM9V080C16MP12	26,000	\$3,640
214397788	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TP9C080C16MP13	26,000	\$3,640

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214397783	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM9V080C16MP12	26,000	\$3,640
214397321	CHAMPION HEATING AND COOLING	HH836E2S11	JHC42C5CF2SS1		25,800	\$3,612
214606492	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1		26,000	\$3,640
214584639	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CHS1	Z8ES130D20SMPS1	37,000	\$5,180
214584554	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	Z8ES100C20SMPS1	36,600	\$5,124
214396308	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	TP9C100C20MP13	37,000	\$5,180
214396302	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	TM9V100C20MP12	37,000	\$5,180
214650833	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+TXV	Z8ES130D20SMPS1	32,400	\$4,536
214584729	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1	Z8ES130D20SMPS1	32,400	\$4,536
214809263	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z9ES100C20SMPS1	33,800	\$4,732
214609061	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z9ES100C20SMPS1	33,800	\$4,732
214396587	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1+JME18D2S N1		32,000	\$4,480
215853497	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1	Z9ES120D20SMPS1	37,600	\$5,264
214609095	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	Z9ES060B12SMPS1	17,900	\$2,506
214609139	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z9ES080C20SMPS1	32,600	\$4,564
215853443	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	Z9ES060B12SMPS1	27,400	\$3,836
215853445	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z9ES100C20SMPS1	29,600	\$4,144
214609193	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	Z9ES080C20SMPS1	37,400	\$5,236
214609218	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	Z9ES060B12SMPS1	18,300	\$2,562

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853447	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z9ES100C16SMPS1	29,200	\$4,088
214609178	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	Z9ES080C20SMPS1	26,200	\$3,668
214651038	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+TXV	Z9ES120D20SMPS1	37,000	\$5,180
214609080	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1	Z9ES120D20SMPS1	37,000	\$5,180
215853498	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1	Z9ES120D20SMPS1	38,000	\$5,320
214609168	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z9ES100C20SMPS1	34,600	\$4,844
215853446	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z9ES100C16SMPS1	29,200	\$4,088
214719923	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	Z9ES080C20SMPS1	26,200	\$3,668
214609208	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	Z9ES080C20SMPS1	26,200	\$3,668
214609134	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	Z9ES080C20SMPS1	37,200	\$5,208
214651886	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	Z9ES060B12SMPS1	18,400	\$2,576
214609100	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	Z9ES060B12SMPS1	18,400	\$2,576
214650016	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+TXV	Z9ES120D20SMPS1	34,400	\$4,816
214609114	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1	Z9ES120D20SMPS1	34,400	\$4,816
215853453	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	Z9ES080C20SMPS1	28,600	\$4,004
214609109	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CHS1	Z9ES120D20SMPS1	37,000	\$5,180
214650642	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	Z9ES060B12SMPS1	17,900	\$2,506
214609183	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	Z9ES060B12SMPS1	17,900	\$2,506
214809273	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z9ES080C16SMPS1	33,200	\$4,648

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214609203	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z9ES080C16SMPS1	33,200	\$4,648
215853442	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	Z9ES060B12SMPS1	27,600	\$3,864
215853444	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	Z9ES060B12SMPS1	27,600	\$3,864
215853449	CHAMPION HEATING AND COOLING	HH836E2S11	CTU36B5XDS1+TXV	Z9ES080B12SMPS1	27,800	\$3,892
215853448	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36B5CDS1	Z9ES080B12SMPS1	27,800	\$3,892
214609051	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	Z9ES100C20SMPS1	37,200	\$5,208
214650098	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	Z9ES080B12SMPS1	17,900	\$2,506
214609154	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	Z9ES080B12SMPS1	17,900	\$2,506
214609085	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1	Z9ES120D20SMPS1	34,400	\$4,816
215853452	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	Z9ES080C16SMPS1	27,600	\$3,864
214609163	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	Z9ES100C20SMPS1	37,200	\$5,208
214395402	CHAMPION HEATING AND COOLING	HH836E2S11	JHC36C5CD2SS1		26,600	\$3,724
214395394	CHAMPION HEATING AND COOLING	HH824E2S11	JHC24B5AC2SS1		18,400	\$2,576
214398194	CHAMPION HEATING AND COOLING	HH836E2S11	JHE42C5CF2SS1		25,800	\$3,612
216013295	CHAMPION HEATING AND COOLING	HH824E2S11	JHE36B5AD2SS1		18,200	\$2,548
214396661	CHAMPION HEATING AND COOLING	HH824E2S11	JHC36B5AD2SS1		18,400	\$2,576
214396218	CHAMPION HEATING AND COOLING	HH824E2S11	JHE30B5AD2SS1		17,700	\$2,478
216411167	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	Z9ET040A10SMPS1	17,200	\$2,408
216374740	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1	Z9ET120D20SMPS1	38,500	\$5,390

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216374699	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1	Z9ET120D20SMPS1	39,000	\$5,460
216374618	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+TXV	Z9ET120D20SMPS1	38,000	\$5,320
216374577	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1	Z9ET120D20SMPS1	38,000	\$5,320
216374694	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z9ET100C20SMPS1	35,400	\$4,956
216374654	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z9ET100C16SMPS1	34,000	\$4,760
216374613	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z9ET100C16SMPS1	34,000	\$4,760
216374572	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z9ET100C16SMPS1	34,000	\$4,760
216374771	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1	Z9ET120D20SMPS1	33,400	\$4,676
216374730	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+TXV	Z9ET120D20SMPS1	33,200	\$4,648
216374689	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1	Z9ET120D20SMPS1	33,200	\$4,648
216374649	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z9ET080C16SMPS1	33,200	\$4,648
216374608	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z9ET080C16SMPS1	33,200	\$4,648
216374567	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z9ET080C16SMPS1	33,200	\$4,648
216374766	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z9ET100C20SMPS1	33,800	\$4,732
216374725	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z9ET100C20SMPS1	33,800	\$4,732
216374684	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	Z9ET060B12SMPS1	18,600	\$2,604
216374644	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	Z9ET080B12SMPS1	17,600	\$2,464
216374603	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	Z9ET080B12SMPS1	17,600	\$2,464
216374562	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	Z9ET060B12SMPS1	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216374761	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	Z9ET060B12SMPS1	18,600	\$2,604
216374720	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	Z9ET080B12SMPS1	17,500	\$2,450
216374679	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	Z9ET100C16SMPS1	26,000	\$3,640
216374639	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	Z9ET080C16SMPS1	29,000	\$4,060
216374598	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	Z9ET080C16SMPS1	29,000	\$4,060
216374557	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	Z9ET080C16SMPS1	29,000	\$4,060
216374756	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	Z9ET100C16SMPS1	27,600	\$3,864
216374715	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	Z9ET100C16SMPS1	27,600	\$3,864
216374705	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	Z9ET060B12SMPS1	18,000	\$2,520
216374664	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	Z9ET080B12SMPS1	17,900	\$2,506
216374624	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	Z9ET080B12SMPS1	17,900	\$2,506
216374583	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	Z9ET080B12SMPS1	17,900	\$2,506
216374542	CHAMPION HEATING AND COOLING	HH824E2S11	CTU30B5XCS1+TXV	Z9ET060B12SMPS1	17,900	\$2,506
216374741	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	Z9ET060B12SMPS1	17,900	\$2,506
213297446	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z9ET060B12SMPS1	26,000	\$3,640
213297686	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z9ET100C16SMPS1	26,600	\$3,724
213296791	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z9ET100C16SMPS1	25,800	\$3,612
213297021	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z9ET080B12SMPS1	25,800	\$3,612
213297251	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z9ET040A10SMPS1	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297241	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z9ET080B12SMPS1	25,800	\$3,612
213297696	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z9ET060B12SMPS1	26,000	\$3,640
215912261	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM9E080B12MP12	18,500	\$2,590
216010748	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TL9E060B12UH11	18,600	\$2,604
216010733	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1+JMC12B2SN1		18,300	\$2,562
216010743	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1+JME08B2SN1		17,600	\$2,464
216010753	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	Z8ET080B12LMPS1	18,300	\$2,562
216010738	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1+JME12B2SN1		18,100	\$2,534
215912255	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM8Y080B12MP11	18,000	\$2,520
215912234	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM9Y080B12MP11	18,200	\$2,548
215912239	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM9E060B12MP12	18,000	\$2,520
215912232	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM9Y060B12MP11	17,600	\$2,464
215912248	CHAMPION HEATING AND COOLING	HH860E2S11	JSE48D5CG2SS1		33,600	\$4,704
215912241	CHAMPION HEATING AND COOLING	HH860E2S11	JSC48D5CG2SS1		33,600	\$4,704
214396676	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TM8E060A12MP11	18,300	\$2,562
214807730	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TP9C060B12MP13	17,100	\$2,394
214810245	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM9V060B12MP12	17,100	\$2,394
214650230	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	Z9ES080B12SMPS1	18,300	\$2,562
214609129	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	Z9ES080B12SMPS1	18,300	\$2,562

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214651509	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	Z8ES100B12SMPS1	18,600	\$2,604
214584664	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	Z8ES100B12SMPS1	18,600	\$2,604
214584724	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	Z8ES040A12SMPS1	18,600	\$2,604
214651271	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TP9C060B12MP13	18,500	\$2,590
214651257	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM9V060B12MP12	18,500	\$2,590
215223953	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	Z8ES100B12SMPS1	18,500	\$2,590
214397936	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TM9E060A10MP12	17,700	\$2,478
214807742	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TP9C080B12MP13	18,100	\$2,534
214810239	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM9V080B12MP12	18,100	\$2,534
214397521	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TM9E040A10MP12	17,600	\$2,464
214650938	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TMLE080B12MP11	18,400	\$2,576
214650923	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM8E080B12MP11	18,400	\$2,576
214397541	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TMLE080B12MP11	18,400	\$2,576
214397536	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM8E080B12MP11	18,400	\$2,576
214651018	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TP9C080B12MP13	18,100	\$2,534
214651004	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM9V080B12MP12	18,100	\$2,534
214398365	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TP9C080B12MP13	18,100	\$2,534
214398360	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM9V080B12MP12	18,100	\$2,534
214650712	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM9E080B12MP12	18,500	\$2,590

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214397113	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM9E080B12MP12	18,500	\$2,590
214651393	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM9Y080B12MP11	18,300	\$2,562
214396250	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM9Y080B12MP11	18,300	\$2,562
214396681	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TMLE060A12MP11	18,300	\$2,562
214397956	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TP9C060B12MP13	18,500	\$2,590
214397951	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM9V060B12MP12	18,500	\$2,590
214651069	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	Z8ES080B12SMPS1	18,300	\$2,562
214584619	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	Z8ES080B12SMPS1	18,300	\$2,562
214397531	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TM9V040A10MP12	17,300	\$2,422
214807723	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TPLC080B12MP13	17,200	\$2,408
214810225	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM8V080B12MP12	17,200	\$2,408
214398355	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TL8E060A12UH11	18,400	\$2,576
214609071	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	Z9ES026A08SMPS1	17,700	\$2,478
214396235	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TM9Y040A10MP11	17,600	\$2,464
214650483	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM8Y080B12MP11	18,000	\$2,520
214397108	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM8Y080B12MP11	18,000	\$2,520
214650371	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM9Y060B12MP11	18,100	\$2,534
214396671	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM9Y060B12MP11	18,100	\$2,534
214650622	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	Z8ET080B12LMPS1	18,300	\$2,562

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214584734	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	Z8ET080B12LMPS1	18,300	\$2,562
214807718	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+JME12B2SN1+TXV		18,200	\$2,548
214397931	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1+JME12B2SN1		18,200	\$2,548
214650078	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TL9E060B12UH11	18,600	\$2,604
214396666	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TL9E060B12UH11	18,600	\$2,604
214807703	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+JMC12B2SN1+TXV		18,200	\$2,548
214398350	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1+JMC12B2SN1		18,200	\$2,548
214807698	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+JMVT12BC2N1+TXV		18,200	\$2,548
214397926	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1+JMVT12BC2N1		18,200	\$2,548
214807693	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+JMET08BS2N1+TXV		17,400	\$2,436
214397098	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1+JMET08BS2N1		17,400	\$2,436
214807688	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TMLE080B12MP11	18,300	\$2,562
214810248	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM8E080B12MP11	18,300	\$2,562
214397946	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TMLE040A12MP11	18,100	\$2,534
214397941	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TM8E040A12MP11	18,100	\$2,534
214807713	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+JMET12BS2N1+TXV		17,700	\$2,478
214397526	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1+JMET12BS2N1		17,700	\$2,478
214807708	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+JME08B2SN1+TXV		17,600	\$2,464
214397103	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1+JME08B2SN1		17,600	\$2,464

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214609213	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	Z9ES040A10SMPS1	17,200	\$2,408
214650201	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TPLC080B12MP13	18,200	\$2,548
214650181	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM8V080B12MP12	18,200	\$2,548
214396228	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TPLC080B12MP13	18,200	\$2,548
214396223	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM8V080B12MP12	18,200	\$2,548
214397118	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TM9E026A08MP12	17,900	\$2,506
214396691	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	TM8Y060A12MP11	17,800	\$2,492
214609188	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	Z9ES060A10SMPS1	18,200	\$2,548
214584569	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	Z8ET060A12LMPS1	18,200	\$2,548
214584689	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30A5ADS1	Z8ES060A12SMPS1	17,600	\$2,464
214807737	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TMLE100B12MP11	18,600	\$2,604
214810242	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	TM8E100B12MP11	18,600	\$2,604
215223948	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	Z8ES080B12SMPS1	18,300	\$2,562
214609159	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1	Z9ES080B12SMPS1	18,300	\$2,562
214651175	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM9E060B12MP12	18,900	\$2,646
214396686	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM9E060B12MP12	18,900	\$2,646
214651448	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TMLE100B12MP11	18,600	\$2,604
214651436	CHAMPION HEATING AND COOLING	HH824E2S11	CTU36B5XDS1+TXV	TM8E100B12MP11	18,600	\$2,604
214396245	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TMLE100B12MP11	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396240	CHAMPION HEATING AND COOLING	HH824E2S11	CTF36B5ADS1	TM8E100B12MP11	18,600	\$2,604
214397867	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TMLE120C16MP11	34,000	\$4,760
214397862	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8E120C16MP11	34,000	\$4,760
214720182	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TMLE120C16MP11	34,000	\$4,760
214720177	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM8E120C16MP11	34,000	\$4,760
214397852	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TMLE120C16MP11	34,000	\$4,760
214397847	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8E120C16MP11	34,000	\$4,760
214398630	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9Y080C16MP11	33,000	\$4,620
214809209	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TL8E080C16UH11	32,800	\$4,592
214397489	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TL8E080C16UH11	32,800	\$4,592
214720157	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM9Y100C16MP11	33,000	\$4,620
214397400	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM9Y100C16MP11	33,000	\$4,620
214397018	CHAMPION HEATING AND COOLING	HH860E2S11	JHC48D5CG2SS1		33,600	\$4,704
214808996	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+JMET16CS2 N1+TXV		34,400	\$4,816
214397023	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1+JMET16CS2 N1		34,400	\$4,816
214398674	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1+JME16C2S N1		32,200	\$4,508
214396597	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TL8E100C20UH11	32,600	\$4,564
214809214	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z8ES100C20SMPS1	32,800	\$4,592
214584719	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z8ES100C20SMPS1	32,800	\$4,592

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214397877	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TL8E080C16UH11	32,800	\$4,592
214809258	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TL9E100C20UH11	32,600	\$4,564
214397093	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TL9E100C20UH11	32,600	\$4,564
214809268	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z9ES080C20SMPS1	32,600	\$4,564
214609198	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z9ES080C20SMPS1	32,600	\$4,564
214720132	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM9E080C16MP12	34,200	\$4,788
214398335	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM9E080C16MP12	34,200	\$4,788
214398298	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9Y100C20MP11	35,000	\$4,900
214397068	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9E080C16MP12	34,200	\$4,788
214808986	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z8ES120C20SMPS1	32,800	\$4,592
214584604	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z8ES120C20SMPS1	32,800	\$4,592
214397902	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TPLC120C20MP13	33,000	\$4,620
214397897	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TPLC100C20MP13	33,000	\$4,620
214397892	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TMLV120C20MP12	33,000	\$4,620
214397887	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8V100C20MP12	33,000	\$4,620
214397882	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8V120C20MP12	33,000	\$4,620
214397442	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TMLE080C16MP11	34,200	\$4,788
214397437	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8E080C16MP11	34,200	\$4,788
214809028	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+JMC16C2S N1+TXV		33,600	\$4,704

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396582	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1+JMC16C2S N1		33,600	\$4,704
214398679	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9E100C20MP12	33,200	\$4,648
214720167	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TMLE100C16MP11	34,200	\$4,788
214720162	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM8E100C16MP11	34,200	\$4,788
214397427	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TMLE100C16MP11	34,200	\$4,788
214397422	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8E100C16MP11	34,200	\$4,788
214809224	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z8ES100C16SMPS1	32,200	\$4,508
214584609	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z8ES100C16SMPS1	32,200	\$4,508
214720192	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TMLE080C16MP11	34,200	\$4,788
214720187	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM8E080C16MP11	34,200	\$4,788
214397452	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TMLE080C16MP11	34,200	\$4,788
214397447	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8E080C16MP11	34,200	\$4,788
214584564	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z8ES100C16SMPS1	32,400	\$4,536
214584704	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1	Z8ES130D20SMPS1	33,400	\$4,676
214809160	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+JME16C2S N1+TXV		32,200	\$4,508
214398293	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1+JME16C2S N1		32,200	\$4,508
214398325	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1+JMVT20DC 2N1		33,200	\$4,648
214809155	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+JMC20D2S N1+TXV		34,600	\$4,844
214397857	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1+JMC20D2S N1		34,600	\$4,844

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214584644	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z8ES120C20SMPS1	32,800	\$4,592
214584599	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z8ES080C20SMPS1	32,600	\$4,564
214397830	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TP9C080C16MP13	33,800	\$4,732
214397825	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9V080C16MP12	33,800	\$4,732
214396560	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9Y100C16MP11	33,000	\$4,620
214719943	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM9Y080C16MP11	33,000	\$4,620
214397013	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM9Y080C16MP11	33,000	\$4,620
214397043	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8Y080C16MP11	32,600	\$4,564
214397038	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8Y100C16MP11	32,600	\$4,564
214396592	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TL9E080C16UH11	34,400	\$4,816
214719979	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM9E100C16MP12	34,400	\$4,816
214398704	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM9E100C16MP12	34,400	\$4,816
214720204	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TP9C100C20MP13	33,400	\$4,676
214720197	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM9V100C20MP12	33,400	\$4,676
214398714	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TP9C100C20MP13	33,400	\$4,676
214398709	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM9V100C20MP12	33,400	\$4,676
214397482	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TP9C100C20MP13	32,800	\$4,592
214397477	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9V100C20MP12	32,800	\$4,592
214719886	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TMLE080C20MP11	33,600	\$4,704

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214719891	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM8E080C20MP11	33,600	\$4,704
214398308	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TMLE080C20MP11	33,600	\$4,704
214398303	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8E080C20MP11	33,600	\$4,704
214397063	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9E100C16MP12	34,400	\$4,816
214720127	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TMLE120C20MP11	33,200	\$4,648
214720122	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM8E120C20MP11	33,200	\$4,648
214397472	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TMLE120C20MP11	33,200	\$4,648
214397467	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8E120C20MP11	33,200	\$4,648
214396607	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TMLE120C20MP11	33,400	\$4,676
214396602	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8E120C20MP11	33,400	\$4,676
214397516	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TL9E100C20UH11	32,600	\$4,564
214397405	CHAMPION HEATING AND COOLING	HH860E2S11	JHE48C5CG2SS1		32,200	\$4,508
214720209	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z9ES100C16SMPS1	34,200	\$4,788
214609173	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z9ES100C16SMPS1	34,200	\$4,788
214398699	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TMLE100C20MP11	33,400	\$4,676
214398694	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8E100C20MP11	33,400	\$4,676
214720041	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TP9C080C16MP13	32,600	\$4,564
214720034	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM9V080C16MP12	32,600	\$4,564
214397504	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TP9C080C16MP13	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214397499	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM9V080C16MP12	32,600	\$4,564
214720117	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TMLE100C20MP11	33,400	\$4,676
214720112	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM8E100C20MP11	33,400	\$4,676
214398689	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TMLE100C20MP11	33,400	\$4,676
214398684	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8E100C20MP11	33,400	\$4,676
214396652	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TPLC100C16MP13	32,800	\$4,592
214396647	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TPLC080C16MP13	32,800	\$4,592
214396642	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TMLV100C16MP12	32,800	\$4,592
214396637	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8V080C16MP12	32,800	\$4,592
214396632	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8V100C16MP12	32,800	\$4,592
214398635	CHAMPION HEATING AND COOLING	HH860E2S11	JHE48D5CG2SS1		33,200	\$4,648
214809190	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TPLC100C16MP13	32,200	\$4,508
214809185	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TPLC080C16MP13	32,200	\$4,508
214809180	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TMLV100C16MP12	32,200	\$4,508
214809175	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM8V080C16MP12	32,200	\$4,508
214809011	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM8V100C16MP12	32,200	\$4,508
214398660	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TPLC100C16MP13	32,200	\$4,508
214398655	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TPLC080C16MP13	32,200	\$4,508
214398650	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TMLV100C16MP12	32,200	\$4,508

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398645	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8V080C16MP12	32,200	\$4,508
214398640	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8V100C16MP12	32,200	\$4,508
214649827	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+TXV	TMLE130D20MP11	36,200	\$5,068
214649821	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+TXV	TM8E130D20MP11	36,200	\$5,068
214396627	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1	TMLE130D20MP11	36,200	\$5,068
214396622	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1	TM8E130D20MP11	36,200	\$5,068
214398249	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8Y100C20MP11	33,600	\$4,704
214398264	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8V100C20MP12	33,600	\$4,704
214398259	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM8V120C20MP12	33,600	\$4,704
214396612	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1+JMC20D2S N1		34,000	\$4,760
214397911	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1+JMT17CC 2N1		33,600	\$4,704
214809023	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+JMET18DS2 N1+TXV		34,200	\$4,788
214397842	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1+JMET18DS2 N1		34,200	\$4,788
214421544	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1+JMET18DS 2N1		34,000	\$4,760
214720172	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	TM9Y100C20MP11	33,600	\$4,704
214398239	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	TM9Y100C20MP11	33,600	\$4,704
214421534	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1+JMET16CS 2N1		34,400	\$4,816
214809001	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+JMT17CC2 N1+TXV		31,800	\$4,452
214397837	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1+JMT17CC2 N1		31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214809006	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+JMC17C2S N1+TXV		31,800	\$4,452
214398254	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1+JMC17C2S N1		31,800	\$4,452
214397058	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TMLE080C20MP11	33,600	\$4,704
214397053	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8E080C20MP11	33,600	\$4,704
214584654	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	Z8ES080C16SMPS1	33,000	\$4,620
214809253	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z8ES080C16SMPS1	33,000	\$4,620
214584614	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z8ES080C16SMPS1	33,000	\$4,620
214649911	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XGS1+TXV	TM9E120D20MP12	35,600	\$4,984
214397921	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CGS1	TM9E120D20MP12	35,600	\$4,984
214398318	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TP9C100C16MP13	32,200	\$4,508
214398313	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9V100C16MP12	32,200	\$4,508
214398330	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1+JMC17C2S N1		33,000	\$4,620
214397088	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TMLE100C16MP11	34,200	\$4,788
214397083	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM8E100C16MP11	34,200	\$4,788
214809145	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+JMV16CC2 N1+TXV		33,600	\$4,704
214397028	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1+JMV16CC2 N1		33,600	\$4,704
214809140	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60C5XGS1+TXV	Z8ES080C20SMPS1	32,600	\$4,564
214584754	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CGS1	Z8ES080C20SMPS1	32,600	\$4,564
214398669	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1+JMC16C2S N1		33,600	\$4,704

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398288	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1+JMV16CC2N1		32,400	\$4,536
216013310	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1+JMV12BC2N1		18,300	\$2,562
216013305	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1+JMET12BS2N1		17,600	\$2,464
216013300	CHAMPION HEATING AND COOLING	HH824E2S11	CTM36B5ADS1+JMET08BS2N1		17,400	\$2,436
211387895	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TP9C080B12MP13	25,800	\$3,612
211387956	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TP9C080B12MP13	25,800	\$3,612
211387927	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM9V080B12MP12	25,800	\$3,612
211387880	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM9V080B12MP12	25,800	\$3,612
211396599	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM8Y100C20MP11	25,600	\$3,584
211390163	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8V100C16MP12	25,400	\$3,556
211389380	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8Y100C20MP11	25,800	\$3,612
211388355	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211387038	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211396799	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8Y080C16MP11	25,400	\$3,556
211390219	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TPLC100C16MP13	25,400	\$3,556
211390177	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8V080C16MP12	25,400	\$3,556
211388378	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211388309	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211387228	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM9Y060B12MP11	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211387200	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM9Y060B12MP11	25,600	\$3,584
211387009	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211390191	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TMLV100C16MP12	25,400	\$3,556
211388323	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211396586	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM8Y120C20MP11	25,600	\$3,584
211390205	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TPLC080C16MP13	25,400	\$3,556
211387942	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TP9C080B12MP13	25,000	\$3,500
211387916	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM9V080B12MP12	25,000	\$3,500
211398868	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TMLE080C16MP11	25,200	\$3,528
211398841	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TMLE080C16MP11	24,800	\$3,472
211398798	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8E080C16MP11	24,800	\$3,472
211398734	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TMLE100B12MP11	25,400	\$3,556
211398704	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8E100B12MP11	25,400	\$3,556
211398674	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TMLE100B12MP11	25,400	\$3,556
211398644	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TMLE100B12MP11	25,000	\$3,500
211398577	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TMLE100C16MP11	25,400	\$3,556
211398562	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8E100C16MP11	25,400	\$3,556
211398547	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8E100C16MP11	25,400	\$3,556
211398394	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TMLE100C16MP11	24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211398380	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM8E100C16MP11	24,800	\$3,472
211398315	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8E120C16MP11	25,400	\$3,556
211398258	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TMLE120C16MP11	25,200	\$3,528
211398243	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM8E120C16MP11	25,200	\$3,528
211398228	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TMLE120C16MP11	25,200	\$3,528
211398213	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM8E120C16MP11	25,200	\$3,528
211398182	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8E120C16MP11	24,800	\$3,472
211398157	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8E120C16MP11	24,800	\$3,472
211397978	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8V080B12MP12	25,200	\$3,528
211397960	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TPLC080B12MP13	25,200	\$3,528
211397798	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8V100C16MP12	25,800	\$3,612
211397726	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TMLV100C16MP12	25,800	\$3,612
211397713	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8V080C16MP12	25,800	\$3,612
211397675	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TPLC100C16MP13	25,800	\$3,612
211397660	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TPLC080C16MP13	25,800	\$3,612
211397630	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM8V080C16MP12	25,800	\$3,612
211397543	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM8V080C16MP12	25,800	\$3,612
211397448	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8V100C16MP12	25,400	\$3,556
211397305	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM8V080C16MP12	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211397267	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TPLC100C16MP13	25,200	\$3,528
211397237	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TMLV100C16MP12	25,200	\$3,528
211397222	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM8V080C16MP12	25,400	\$3,556
211397182	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TPLC120C20MP13	25,200	\$3,528
211397168	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TPLC100C20MP13	25,200	\$3,528
211397035	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8Y080B12MP11	25,400	\$3,556
211396990	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8Y080B12MP11	24,800	\$3,472
211396936	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8Y100C16MP11	25,800	\$3,612
211396852	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM8Y080C16MP11	25,800	\$3,612
211396784	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8Y100C16MP11	25,400	\$3,556
211396653	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8Y100C20MP11	25,600	\$3,584
211396556	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8Y120C20MP11	25,200	\$3,528
211396523	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8Y120C20MP11	25,200	\$3,528
211396317	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9E060B12MP12	25,200	\$3,528
211396275	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9E080B12MP12	25,600	\$3,584
211396210	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9E080B12MP12	25,000	\$3,500
211396059	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM9E080C16MP12	25,600	\$3,584
211395933	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM9E100C16MP12	24,800	\$3,472
211395771	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9V060B12MP12	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211395562	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9V080B12MP12	25,600	\$3,584
211395530	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TP9C080B12MP13	25,200	\$3,528
211395326	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211395301	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211395241	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM9V080C16MP12	25,400	\$3,556
211395037	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM9V080C16MP12	25,000	\$3,500
211395019	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TP9C080C16MP13	25,000	\$3,500
211394964	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TP9C100C16MP13	25,400	\$3,556
211394871	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM9V100C16MP12	25,400	\$3,556
211394698	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM9V100C16MP12	24,800	\$3,472
211394671	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TP9C100C20MP13	25,800	\$3,612
211394656	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TP9C100C20MP13	25,800	\$3,612
211394644	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9V100C20MP12	25,800	\$3,612
211394612	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TP9C100C20MP13	25,800	\$3,612
211394561	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM9V100C20MP12	25,600	\$3,584
211394542	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TP9C100C20MP13	25,600	\$3,584
211394529	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM9V100C20MP12	25,600	\$3,584
211394446	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TP9C100C20MP13	25,200	\$3,528
211394431	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM9V100C20MP12	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211394400	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM9V100C20MP12	25,200	\$3,528
211394379	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TP9C120D20MP13	25,400	\$3,556
211394347	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TP9C120D20MP13	25,400	\$3,556
211394113	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9Y080C16MP11	25,800	\$3,612
211394040	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9Y080C16MP11	25,200	\$3,528
211394025	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9Y080C16MP11	25,200	\$3,528
211394010	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM9Y080C16MP11	25,000	\$3,500
211393890	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9Y100C16MP11	25,200	\$3,528
211393770	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	TMLE040A12MP11	25,200	\$3,528
211393726	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	TM8E060A12MP11	25,400	\$3,556
211393680	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	TM8V060A12MP12	25,800	\$3,612
211393666	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	TM8Y060A12MP11	25,200	\$3,528
211393638	CHAMPION HEATING AND COOLING	HMH72B341	JHETB36DBCS2N1		25,400	\$3,556
211393568	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TL8E060A12UH11	25,400	\$3,556
211393420	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TL8E080C16UH11	25,800	\$3,612
211393201	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TL9E060B12UH11	25,600	\$3,584
211392991	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TL9E100C20UH11	25,600	\$3,584
211392902	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TMLE040A12MP11	25,200	\$3,528
211392881	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM8E040A12MP11	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211392791	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TMLE040A12MP11	24,800	\$3,472
211392746	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM8E040A12MP11	24,800	\$3,472
211392483	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	TMLE080B12MP11	26,800	\$3,752
211392453	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TMLE080B12MP11	25,800	\$3,612
211392442	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TMLE080B12MP11	25,800	\$3,612
211392414	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM8E080B12MP11	25,800	\$3,612
211392373	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	TMLE080B12MP11	26,800	\$3,752
211392301	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8E080B12MP11	25,800	\$3,612
211392253	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM8E080B12MP11	25,000	\$3,500
211392238	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TMLE080B12MP11	25,000	\$3,500
211392066	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TMLE080C16MP11	25,200	\$3,528
211392058	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8E080C16MP11	25,200	\$3,528
211392017	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TMLE080C16MP11	24,600	\$3,444
211391987	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TMLE080C16MP11	24,600	\$3,444
211391972	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8E080C16MP11	24,600	\$3,444
211391882	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TMLE100B12MP11	25,400	\$3,556
211391742	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8E100B12MP11	25,400	\$3,556
211391539	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TMLE100C16MP11	25,200	\$3,528
211391524	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8E100C16MP11	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211391509	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TMLE100C16MP11	25,200	\$3,528
211391359	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TMLE120C16MP11	25,200	\$3,528
211391344	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8E120C16MP11	25,200	\$3,528
211391255	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8E120C16MP11	24,800	\$3,472
211391122	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TPLC060A12MP13	25,600	\$3,584
211391092	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TMLV060A12MP12	25,600	\$3,584
211391032	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TPLC060A12MP13	25,600	\$3,584
211390768	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TPLC080B12MP13	25,400	\$3,556
211390753	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM8V080B12MP12	25,400	\$3,556
211390556	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TPLC080B12MP13	25,000	\$3,500
211390508	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM8V080B12MP12	25,000	\$3,500
211390458	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TPLC080B12MP13	24,800	\$3,472
211390042	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TPLC080C16MP13	25,600	\$3,584
211389881	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM8Y060A12MP11	25,200	\$3,528
211389854	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM8Y060A12MP11	25,200	\$3,528
211389810	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM8Y060A12MP11	24,600	\$3,444
211389735	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM8Y080B12MP11	25,200	\$3,528
211389654	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM8Y080B12MP11	24,800	\$3,472
211389324	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8Y100C20MP11	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211389165	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM9E060A10MP12	24,600	\$3,444
211389106	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211389032	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211388947	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9E060B12MP12	25,200	\$3,528
211388890	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM9E080B12MP12	25,400	\$3,556
211388796	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM9E080B12MP12	25,000	\$3,500
211388768	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9E080B12MP12	25,000	\$3,500
211388723	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9E080C16MP12	25,200	\$3,528
211388619	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9E100C16MP12	25,200	\$3,528
211388575	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9E100C16MP12	24,800	\$3,472
211388476	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM9V040A10MP12	24,800	\$3,472
211388126	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM9V060B12MP12	25,000	\$3,500
211388030	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9V060B12MP12	25,200	\$3,528
211387835	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TP9C080B12MP13	25,800	\$3,612
211387745	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM9V080B12MP12	25,200	\$3,528
211387685	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9V080B12MP12	25,000	\$3,500
211387646	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9V080C16MP12	25,400	\$3,556
211387575	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TP9C080C16MP13	25,000	\$3,500
211387541	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TP9C100C16MP13	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211387517	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211387408	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9V100C16MP12	25,000	\$3,500
211387356	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TP9C100C20MP13	26,000	\$3,640
211387078	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9Y060B12MP11	25,200	\$3,528
211387065	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	TM9Y080B12MP11	26,800	\$3,752
211386981	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9Y080B12MP11	25,800	\$3,612
211386896	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9Y080B12MP11	25,400	\$3,556
211386856	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9Y080C16MP11	25,800	\$3,612
211386768	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9Y100C16MP11	25,800	\$3,612
211386674	CHAMPION HEATING AND COOLING	HMH72B341	JHETC42FBCS2N1		25,200	\$3,528
211386595	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+JMET12CS2N1+TXV		24,800	\$3,472
211386559	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TL8E080C16UH11	26,000	\$3,640
211386387	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TL8E100C20UH11	24,800	\$3,472
211386375	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TL8E100C20UH11	24,800	\$3,472
211386352	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TL9E060B12UH11	25,800	\$3,612
211386339	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TL9E060B12UH11	25,800	\$3,612
211386191	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TL9E080C16UH11	25,200	\$3,528
211386100	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TL9E100C20UH11	25,000	\$3,500
211386086	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TL9E100C20UH11	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211385973	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8E080B12MP11	25,600	\$3,584
211385906	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TMLE080C16MP11	25,200	\$3,528
211385858	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8E080C16MP11	25,200	\$3,528
211212527	CHAMPION HEATING AND COOLING	HL20B6021	JHVVC60HE4C2N1+CC		48,000	\$6,720
211206981	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TM8V100C16MP12	41,500	\$5,810
211206968	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TPLC100C20MP13	41,500	\$5,810
211206958	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TM8V100C20MP12	41,500	\$5,810
211206922	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TP9C100C20MP13	41,500	\$5,810
211206894	CHAMPION HEATING AND COOLING	HL20B3621	XAMB36DE2N1+CC	TM8V080B12MP12	34,600	\$4,844
211206887	CHAMPION HEATING AND COOLING	HL20B3621	XAMB36DE2N1+CC	TP9C080B12MP13	34,600	\$4,844
211206875	CHAMPION HEATING AND COOLING	HL20B3621	XAMC36DE2N1+CC	TP9C080C16MP13	34,400	\$4,816
211206852	CHAMPION HEATING AND COOLING	HL20B2421	XAMB24DE1N1+CC	TPLC080B12MP13	23,000	\$3,220
211010188	CHAMPION HEATING AND COOLING	HL20B4821	JHVVC48HE3C2N1+CC		43,500	\$6,090
211010184	CHAMPION HEATING AND COOLING	HL20B6021	JHVVD60HE4C2N1+CC		46,500	\$6,510
211387214	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM9Y060B12MP11	25,200	\$3,528
211387023	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM9Y080B12MP11	25,200	\$3,528
211398896	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TMLE080C16MP11	25,200	\$3,528
211398790	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TMLE080C16MP11	24,800	\$3,472
211398748	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM8E080C16MP11	24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211398622	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TMLE100B12MP11	25,000	\$3,500
211398607	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8E100B12MP11	25,000	\$3,500
211398532	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TMLE100C16MP11	25,400	\$3,556
211398517	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8E100C16MP11	25,400	\$3,556
211398502	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TMLE100C16MP11	25,400	\$3,556
211398477	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TMLE100C16MP11	25,400	\$3,556
211398469	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM8E100C16MP11	25,400	\$3,556
211398409	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8E100C16MP11	24,800	\$3,472
211398353	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM8E100C16MP11	24,800	\$3,472
211398338	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TMLE120C16MP11	25,400	\$3,556
211398326	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TMLE120C16MP11	25,400	\$3,556
211398300	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8E120C16MP11	25,400	\$3,556
211398197	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TMLE120C16MP11	24,800	\$3,472
211398086	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TPLC080B12MP13	25,800	\$3,612
211398011	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8V080B12MP12	25,800	\$3,612
211397945	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8V080B12MP12	25,200	\$3,528
211397906	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TPLC100C16MP13	25,800	\$3,612
211397891	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TPLC100C16MP13	25,800	\$3,612
211397877	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TPLC080C16MP13	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211397850	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TMLV100C16MP12	25,800	\$3,612
211397702	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8V100C16MP12	25,800	\$3,612
211397558	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TMLV100C16MP12	25,800	\$3,612
211397486	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TPLC080C16MP13	25,400	\$3,556
211397331	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TPLC080C16MP13	25,200	\$3,528
211397252	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TPLC080C16MP13	25,200	\$3,528
211397131	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8V120C20MP12	25,200	\$3,528
211396980	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8Y080B12MP11	24,800	\$3,472
211396912	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8Y080C16MP11	25,800	\$3,612
211396754	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM8Y100C16MP11	25,400	\$3,556
211396739	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM8Y080C16MP11	25,400	\$3,556
211396725	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM8Y100C16MP11	25,400	\$3,556
211396710	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8Y100C20MP11	25,600	\$3,584
211396625	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM8Y100C20MP11	25,600	\$3,584
211396571	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8Y100C20MP11	25,200	\$3,528
211396454	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM8Y100C20MP11	25,200	\$3,528
211396410	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211396385	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9E060B12MP12	25,800	\$3,612
211396295	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9E080B12MP12	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211396152	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9E080C16MP12	26,000	\$3,640
211396089	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9E080C16MP12	25,600	\$3,584
211396017	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9E100C16MP12	25,400	\$3,556
211395987	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM9E100C16MP12	25,400	\$3,556
211395973	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9E100C16MP12	24,800	\$3,472
211395946	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM9E100C16MP12	24,800	\$3,472
211395909	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211395868	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9V060B12MP12	25,600	\$3,584
211395839	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211395793	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TP9C060B12MP13	25,200	\$3,528
211395722	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9V060B12MP12	25,200	\$3,528
211395636	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9V080B12MP12	25,600	\$3,584
211395617	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9V080B12MP12	25,600	\$3,584
211395414	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211395395	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TP9C080C16MP13	25,400	\$3,556
211395371	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211395265	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TP9C080C16MP13	25,400	\$3,556
211395096	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TP9C080C16MP13	24,800	\$3,472
211395079	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9V080C16MP12	24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211395005	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM9V080C16MP12	25,000	\$3,500
211394979	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211394850	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211394836	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211394800	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9V100C16MP12	24,800	\$3,472
211394779	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TP9C100C16MP13	24,800	\$3,472
211394629	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9V100C20MP12	25,800	\$3,612
211394597	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9V100C20MP12	25,800	\$3,612
211394413	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TP9C100C20MP13	25,200	\$3,528
211394282	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TP9C120D20MP13	24,800	\$3,472
211394252	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9Y060B12MP11	25,800	\$3,612
211394237	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9Y060B12MP11	25,800	\$3,612
211394098	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9Y080C16MP11	25,800	\$3,612
211393995	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM9Y080C16MP11	25,000	\$3,500
211393950	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9Y100C16MP11	25,800	\$3,612
211393845	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM9Y120D20MP11	25,400	\$3,556
211393815	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM9Y120D20MP11	25,000	\$3,500
211393785	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	TL8E060A12UH11	25,400	\$3,556
211393756	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	TM8E040A12MP11	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211393610	CHAMPION HEATING AND COOLING	HMH72B341	JHVTC36DBCC2N1		25,400	\$3,556
211393538	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TL8E060A12UH11	25,400	\$3,556
211393405	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TL8E080C16UH11	25,800	\$3,612
211393375	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TL8E100C20UH11	25,400	\$3,556
211393360	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TL8E100C20UH11	25,400	\$3,556
211393328	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TL8E100C20UH11	25,600	\$3,584
211393269	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TL9E060B12UH11	25,000	\$3,500
211393246	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TL9E060B12UH11	25,000	\$3,500
211392836	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM8E040A12MP11	25,200	\$3,528
211392655	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM8E060A12MP11	25,400	\$3,556
211392554	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM8E060A12MP11	25,000	\$3,500
211392498	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	TM8E080B12MP11	26,800	\$3,752
211392388	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM8E080B12MP11	25,800	\$3,612
211392343	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TMLE080B12MP11	25,800	\$3,612
211392268	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TMLE080B12MP11	25,000	\$3,500
211392141	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8E080B12MP11	25,000	\$3,500
211392002	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8E080C16MP11	24,600	\$3,444
211391783	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TMLE100B12MP11	25,400	\$3,556
211391768	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8E100B12MP11	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211391584	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8E100B12MP11	24,800	\$3,472
211391494	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8E100C16MP11	25,200	\$3,528
211391449	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TMLE100C16MP11	24,800	\$3,472
211391419	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TMLE100C16MP11	24,800	\$3,472
211391107	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TPLC060A12MP13	25,600	\$3,584
211391077	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TMLV060A12MP12	25,600	\$3,584
211391062	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM8V060A12MP12	25,600	\$3,584
211390928	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TMLV060A12MP12	25,200	\$3,528
211390883	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TMLV060A12MP12	25,200	\$3,528
211390869	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM8V060A12MP12	25,200	\$3,528
211390720	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TPLC080B12MP13	25,400	\$3,556
211390654	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TPLC080B12MP13	25,600	\$3,584
211390640	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8V080B12MP12	25,600	\$3,584
211390622	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TPLC080B12MP13	25,600	\$3,584
211390607	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8V080B12MP12	25,600	\$3,584
211390541	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM8V080B12MP12	25,000	\$3,500
211390274	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TMLV100C16MP12	25,400	\$3,556
211390055	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TPLC100C16MP13	25,600	\$3,584
211390028	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TMLV100C16MP12	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211389713	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8Y080B12MP11	25,200	\$3,528
211389625	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8Y080B12MP11	24,800	\$3,472
211389446	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8Y100C16MP11	25,600	\$3,584
211389369	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8Y120C20MP11	25,200	\$3,528
211389199	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM9E060A10MP12	25,400	\$3,556
211389047	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9E060B12MP12	25,800	\$3,612
211389003	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM9E060B12MP12	25,200	\$3,528
211388988	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM9E060B12MP12	25,200	\$3,528
211388961	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9E060B12MP12	25,200	\$3,528
211388880	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM9E080B12MP12	25,400	\$3,556
211388679	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9E080C16MP12	25,600	\$3,584
211388634	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9E100C16MP12	25,200	\$3,528
211388590	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9E100C16MP12	24,800	\$3,472
211388552	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9E100C20MP12	25,000	\$3,500
211388504	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM9V040A10MP12	25,200	\$3,528
211388369	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TP9C060B12MP13	25,400	\$3,556
211388160	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM9V060B12MP12	25,000	\$3,500
211387826	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9V080B12MP12	25,800	\$3,612
211387773	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TP9C080B12MP13	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211387567	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9V080C16MP12	25,000	\$3,500
211387504	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211387454	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TP9C100C16MP13	25,000	\$3,500
211387318	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TP9C100C20MP13	26,000	\$3,640
211387304	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9V100C20MP12	26,000	\$3,640
211387243	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	TM9Y060B12MP11	26,600	\$3,724
211387185	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	TM9Y060B12MP11	26,600	\$3,724
211387172	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9Y060B12MP11	25,600	\$3,584
211387116	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM9Y060B12MP11	25,000	\$3,500
211387091	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9Y060B12MP11	25,200	\$3,528
211386996	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	TM9Y080B12MP11	26,800	\$3,752
211386939	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM9Y080B12MP11	24,800	\$3,472
211386841	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9Y080C16MP11	25,800	\$3,612
211386728	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9Y100C16MP11	25,400	\$3,556
211386716	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9Y100C16MP11	25,400	\$3,556
211386689	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9Y100C20MP11	25,600	\$3,584
211386635	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1+JMET12CS2 N1		25,400	\$3,556
211386623	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+JMET12CS2 N1+TXV		25,400	\$3,556
211386582	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TL8E080C16UH11	26,000	\$3,640

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211386572	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TL8E080C16UH11	26,000	\$3,640
211386547	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TL8E080C16UH11	25,600	\$3,584
211386522	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TL8E080C16UH11	25,600	\$3,584
211386492	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TL8E080C16UH11	25,400	\$3,556
211386466	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TL8E100C20UH11	25,400	\$3,556
211386438	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TL8E100C20UH11	25,400	\$3,556
211386316	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TL9E060B12UH11	25,200	\$3,528
211386302	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TL9E060B12UH11	25,200	\$3,528
211386222	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TL9E080C16UH11	25,200	\$3,528
211386209	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TL9E080C16UH11	25,200	\$3,528
211386071	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TL9E100C20UH11	25,000	\$3,500
211386029	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TMLE080B12MP11	25,600	\$3,584
211386014	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8E080B12MP11	25,600	\$3,584
211385999	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8E080B12MP11	25,600	\$3,584
211385985	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TMLE080B12MP11	25,600	\$3,584
211385959	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TMLE080B12MP11	25,400	\$3,556
211385890	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TMLE080C16MP11	25,200	\$3,528
211385833	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8E080C16MP11	25,200	\$3,528
211206963	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TMLV120C20MP12	41,500	\$5,810

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211206953	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TM8V120C20MP12	41,500	\$5,810
211206946	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TP9C080C16MP13	41,500	\$5,810
211206934	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TP9C100C16MP13	41,500	\$5,810
211206929	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TM9V100C16MP12	41,500	\$5,810
211206910	CHAMPION HEATING AND COOLING	HL20B6021	XAMC60HE4N1+CC	TP9C100C20MP13	47,000	\$6,580
211206899	CHAMPION HEATING AND COOLING	HL20B3621	XAMB36DE2N1+CC	TPLC080B12MP13	34,600	\$4,844
211010193	CHAMPION HEATING AND COOLING	HL20B2421	JHVVB24DE1C2N1+CC		22,800	\$3,192
211010180	CHAMPION HEATING AND COOLING	HL20B3621	JHVVB36DE2C2N1+CC		35,800	\$5,012
211398026	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TPLC080B12MP13	25,800	\$3,612
211397005	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8Y080B12MP11	25,400	\$3,556
211396922	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8Y100C16MP11	25,800	\$3,612
211396074	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM9E080C16MP12	25,600	\$3,584
211394936	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9V100C16MP12	25,400	\$3,556
211394070	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM9Y080C16MP11	25,400	\$3,556
211393494	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TL8E060A12UH11	25,000	\$3,500
211391897	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TMLE100B12MP11	25,400	\$3,556
211389561	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8Y100C16MP11	25,400	\$3,556
211386247	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TL9E080C16UH11	25,600	\$3,584
211206986	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TM8V080C16MP12	41,500	\$5,810

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211398882	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM8E080C16MP11	25,200	\$3,528
211398856	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM8E080C16MP11	25,200	\$3,528
211398826	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8E080C16MP11	24,800	\$3,472
211398811	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TMLE080C16MP11	24,800	\$3,472
211398776	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM8E080C16MP11	24,800	\$3,472
211398763	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TMLE080C16MP11	24,800	\$3,472
211398719	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TMLE100B12MP11	25,400	\$3,556
211398689	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8E100B12MP11	25,400	\$3,556
211398592	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TMLE100C16MP11	25,400	\$3,556
211398488	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM8E100C16MP11	25,400	\$3,556
211398439	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8E100C16MP11	24,800	\$3,472
211398365	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TMLE100C16MP11	24,800	\$3,472
211398288	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TMLE120C16MP11	25,400	\$3,556
211398273	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8E120C16MP11	25,400	\$3,556
211398167	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TMLE120C16MP11	24,800	\$3,472
211398144	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TMLE120C16MP11	24,800	\$3,472
211398114	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TMLE120C16MP11	24,800	\$3,472
211398074	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TPLC080B12MP13	25,800	\$3,612
211397835	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TMLV100C16MP12	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211397615	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM8V100C16MP12	25,800	\$3,612
211397347	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TPLC100C16MP13	25,200	\$3,528
211397290	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM8V100C16MP12	25,200	\$3,528
211397206	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM8V100C16MP12	25,200	\$3,528
211397096	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TPLC100C20MP13	25,200	\$3,528
211397080	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TMLV120C20MP12	25,200	\$3,528
211397065	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8V100C20MP12	25,200	\$3,528
211396882	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM8Y080C16MP11	25,800	\$3,612
211396822	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8Y080C16MP11	25,400	\$3,556
211396694	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8Y100C20MP11	25,600	\$3,584
211396614	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM8Y120C20MP11	25,600	\$3,584
211396540	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8Y100C20MP11	25,200	\$3,528
211396479	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM8Y120C20MP11	25,200	\$3,528
211396362	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211396342	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9E060B12MP12	25,200	\$3,528
211396190	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9E080C16MP12	26,000	\$3,640
211396134	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM9E080C16MP12	26,000	\$3,640
211396119	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM9E080C16MP12	26,000	\$3,640
211396105	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9E080C16MP12	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211396031	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9E100C16MP12	25,400	\$3,556
211396003	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM9E100C16MP12	25,400	\$3,556
211395960	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9E100C16MP12	24,800	\$3,472
211395897	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TP9C060B12MP13	25,600	\$3,584
211395885	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211395815	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211395743	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TP9C060B12MP13	25,200	\$3,528
211395683	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TP9C080B12MP13	25,600	\$3,584
211395505	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9V080B12MP12	25,200	\$3,528
211395185	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211395151	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TP9C080C16MP13	24,800	\$3,472
211395128	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9V080C16MP12	24,800	\$3,472
211395048	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TP9C080C16MP13	25,000	\$3,500
211394903	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211394884	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TP9C100C16MP13	25,400	\$3,556
211394815	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TP9C100C16MP13	24,800	\$3,472
211394744	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TP9C100C16MP13	24,800	\$3,472
211394500	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9V100C20MP12	25,000	\$3,500
211394467	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9V100C20MP12	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211394364	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM9V120D20MP12	25,400	\$3,556
211394334	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM9V120D20MP12	25,400	\$3,556
211394315	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TP9C120D20MP13	24,800	\$3,472
211394302	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM9V120D20MP12	24,800	\$3,472
211394267	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM9V120D20MP12	24,800	\$3,472
211394197	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9Y060B12MP11	25,400	\$3,556
211394156	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211394126	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9Y080B12MP11	25,400	\$3,556
211394085	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9Y080C16MP11	25,800	\$3,612
211393980	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9Y100C16MP11	25,800	\$3,612
211393965	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9Y100C16MP11	25,800	\$3,612
211393935	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM9Y100C16MP11	25,400	\$3,556
211393875	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM9Y100C16MP11	25,200	\$3,528
211393830	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM9Y120D20MP11	25,400	\$3,556
211393741	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	TMLE060A12MP11	25,400	\$3,556
211393696	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	TMLV060A12MP12	25,800	\$3,612
211393624	CHAMPION HEATING AND COOLING	HMH72B341	JHVTB36DBCC2N1		25,200	\$3,528
211393254	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TL9E060B12UH11	25,000	\$3,500
211393160	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TL9E060B12UH11	24,400	\$3,416

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211393115	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TL9E080C16UH11	25,800	\$3,612
211393066	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TL9E080C16UH11	25,400	\$3,556
211393037	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TL9E100C20UH11	26,200	\$3,668
211393022	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TL9E100C20UH11	26,200	\$3,668
211392761	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TMLE040A12MP11	24,800	\$3,472
211392625	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TMLE060A12MP11	25,400	\$3,556
211392565	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TMLE060A12MP11	25,000	\$3,500
211392524	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM8E060A12MP11	25,000	\$3,500
211392427	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM8E080B12MP11	25,800	\$3,612
211392328	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8E080B12MP11	25,800	\$3,612
211392313	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TMLE080B12MP11	25,800	\$3,612
211392187	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TMLE080B12MP11	25,000	\$3,500
211392171	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8E080B12MP11	25,000	\$3,500
211392156	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TMLE080B12MP11	25,000	\$3,500
211392081	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8E080C16MP11	25,200	\$3,528
211391867	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM8E100B12MP11	25,400	\$3,556
211391838	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TMLE100B12MP11	25,400	\$3,556
211391753	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TMLE100B12MP11	25,400	\$3,556
211391681	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TMLE100B12MP11	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211391666	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM8E100B12MP11	25,000	\$3,500
211391627	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TMLE100B12MP11	24,800	\$3,472
211391434	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8E100C16MP11	24,800	\$3,472
211391329	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TMLE120C16MP11	25,200	\$3,528
211391314	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8E120C16MP11	25,200	\$3,528
211391270	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TMLE120C16MP11	24,800	\$3,472
211391241	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TMLE120C16MP11	24,800	\$3,472
211391017	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TMLV060A12MP12	25,600	\$3,584
211390523	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TPLC080B12MP13	25,000	\$3,500
211390443	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8V080B12MP12	24,800	\$3,472
211390410	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8V080B12MP12	24,800	\$3,472
211390287	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TPLC080C16MP13	25,400	\$3,556
211390260	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8V080C16MP12	25,400	\$3,556
211390245	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8V100C16MP12	25,400	\$3,556
211390013	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8V080C16MP12	25,600	\$3,584
211389917	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8V100C16MP12	25,600	\$3,584
211389765	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM8Y080B12MP11	25,200	\$3,528
211389750	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM8Y080B12MP11	25,200	\$3,528
211389669	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM8Y080B12MP11	24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211389547	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8Y080C16MP11	25,400	\$3,556
211389488	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8Y080C16MP11	25,600	\$3,584
211389473	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8Y100C16MP11	25,600	\$3,584
211389458	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8Y080C16MP11	25,600	\$3,584
211389280	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8Y120C20MP11	25,400	\$3,556
211389214	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM9E060A10MP12	25,400	\$3,556
211389184	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM9E060A10MP12	25,400	\$3,556
211388850	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9E080B12MP12	25,800	\$3,612
211388805	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM9E080B12MP12	25,000	\$3,500
211388753	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9E080B12MP12	25,000	\$3,500
211388664	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9E080C16MP12	25,600	\$3,584
211388562	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9E100C20MP12	25,000	\$3,500
211388522	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM9V040A10MP12	25,200	\$3,528
211388463	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM9V040A10MP12	24,800	\$3,472
211388340	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM9V060B12MP12	25,400	\$3,556
211388255	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TP9C060B12MP13	25,600	\$3,584
211388241	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9V060B12MP12	25,600	\$3,584
211388174	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TP9C060B12MP13	25,000	\$3,500
211388140	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TP9C060B12MP13	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211388074	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TP9C060B12MP13	25,200	\$3,528
211388060	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9V060B12MP12	25,200	\$3,528
211388042	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TP9C060B12MP13	25,200	\$3,528
211387753	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TP9C080B12MP13	25,200	\$3,528
211387705	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9V080B12MP12	25,000	\$3,500
211387653	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TP9C080C16MP13	25,400	\$3,556
211387596	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TP9C080C16MP13	25,000	\$3,500
211387588	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9V080C16MP12	25,000	\$3,500
211387532	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9V100C16MP12	25,400	\$3,556
211387340	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM9V100C20MP12	26,000	\$3,640
211387257	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	TM9Y060B12MP11	26,600	\$3,724
211387158	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9Y060B12MP11	25,600	\$3,584
211387130	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM9Y060B12MP11	25,000	\$3,500
211386925	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM9Y080B12MP11	24,800	\$3,472
211386755	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9Y100C16MP11	25,800	\$3,612
211386703	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9Y100C20MP11	25,600	\$3,584
211386648	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+JMET12CS2 N1+TXV		25,400	\$3,556
211386535	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TL8E080C16UH11	25,600	\$3,584
211386452	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TL8E100C20UH11	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211386424	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TL8E100C20UH11	25,400	\$3,556
211386400	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TL8E100C20UH11	24,800	\$3,472
211386363	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TL8E100C20UH11	24,800	\$3,472
211386328	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TL9E060B12UH11	25,800	\$3,612
211386274	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TL9E080C16UH11	25,800	\$3,612
211386259	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TL9E080C16UH11	25,800	\$3,612
211386235	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TL9E080C16UH11	25,600	\$3,584
211386202	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TL9E080C16UH11	25,200	\$3,528
211386056	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TL9E100C20UH11	25,000	\$3,500
211386044	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TMLE080B12MP11	25,600	\$3,584
211385946	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8E080B12MP11	25,400	\$3,556
211385873	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8E080C16MP11	25,200	\$3,528
211385845	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TMLE080C16MP11	25,200	\$3,528
211206996	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TPLC080C16MP13	41,500	\$5,810
211206991	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TMLV100C16MP12	41,500	\$5,810
211206973	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TPLC120C20MP13	41,500	\$5,810
211206917	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TM9V100C20MP12	41,500	\$5,810
211206882	CHAMPION HEATING AND COOLING	HL20B3621	XAMB36DE2N1+CC	TM9V080B12MP12	34,600	\$4,844
211206863	CHAMPION HEATING AND COOLING	HL20B3621	XAMC36DE2N1+CC	TP9C100C16MP13	34,400	\$4,816

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211398659	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8E100B12MP11	25,400	\$3,556
211398634	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8E100B12MP11	25,000	\$3,500
211398454	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TMLE100C16MP11	24,800	\$3,472
211398424	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TMLE100C16MP11	24,800	\$3,472
211398129	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM8E120C16MP11	24,800	\$3,472
211398099	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM8E120C16MP11	24,800	\$3,472
211398059	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8V080B12MP12	25,800	\$3,612
211398044	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8V080B12MP12	25,800	\$3,612
211397993	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TPLC080B12MP13	25,200	\$3,528
211397865	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TPLC080C16MP13	25,800	\$3,612
211397820	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8V080C16MP12	25,800	\$3,612
211397806	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8V080C16MP12	25,800	\$3,612
211397783	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8V100C16MP12	25,800	\$3,612
211397756	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TPLC100C16MP13	25,800	\$3,612
211397741	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TPLC080C16MP13	25,800	\$3,612
211397645	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TMLV100C16MP12	25,800	\$3,612
211397588	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TPLC100C16MP13	25,800	\$3,612
211397573	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TPLC080C16MP13	25,800	\$3,612
211397528	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM8V100C16MP12	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211397501	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TPLC100C16MP13	25,400	\$3,556
211397471	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TMLV100C16MP12	25,400	\$3,556
211397317	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TMLV100C16MP12	25,200	\$3,528
211397161	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TMLV120C20MP12	25,200	\$3,528
211397146	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8V100C20MP12	25,200	\$3,528
211397110	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TPLC120C20MP13	25,200	\$3,528
211397050	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8V120C20MP12	25,200	\$3,528
211397020	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8Y080B12MP11	25,400	\$3,556
211396966	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM8Y080C16MP11	25,800	\$3,612
211396951	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8Y080C16MP11	25,800	\$3,612
211396897	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM8Y100C16MP11	25,800	\$3,612
211396867	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TM8Y100C16MP11	25,800	\$3,612
211396837	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM8Y100C16MP11	25,800	\$3,612
211396807	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8Y100C16MP11	25,400	\$3,556
211396769	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM8Y080C16MP11	25,400	\$3,556
211396668	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM8Y120C20MP11	25,600	\$3,584
211396500	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM8Y100C20MP11	25,200	\$3,528
211396432	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM8Y120C20MP11	25,200	\$3,528
211396253	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9E080B12MP12	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211396230	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9E080B12MP12	25,000	\$3,500
211396171	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9E080C16MP12	26,000	\$3,640
211396044	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9E100C16MP12	25,400	\$3,556
211395662	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TP9C080B12MP13	25,600	\$3,584
211395586	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TP9C080B12MP13	25,600	\$3,584
211395479	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TP9C080B12MP13	25,200	\$3,528
211395460	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9V080B12MP12	25,200	\$3,528
211395354	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9V080C16MP12	25,400	\$3,556
211395211	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211394949	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211394917	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211394765	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM9V100C16MP12	24,800	\$3,472
211394729	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FBCN1	TM9V100C16MP12	24,800	\$3,472
211394712	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TP9C100C16MP13	24,800	\$3,472
211394576	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TP9C100C20MP13	25,600	\$3,584
211394512	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TP9C100C20MP13	25,000	\$3,500
211394480	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TP9C100C20MP13	25,000	\$3,500
211394225	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TM9Y060B12MP11	25,800	\$3,612
211394210	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9Y060B12MP11	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211394182	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211394167	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TM9Y080B12MP11	25,800	\$3,612
211394141	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9Y080B12MP11	25,400	\$3,556
211394055	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM9Y080C16MP11	25,400	\$3,556
211393920	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TM9Y100C16MP11	25,400	\$3,556
211393905	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM9Y100C16MP11	25,200	\$3,528
211393860	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM9Y100C16MP11	25,200	\$3,528
211393800	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TM9Y120D20MP11	25,000	\$3,500
211393711	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	TPLC060A12MP13	25,800	\$3,612
211393553	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TL8E060A12UH11	25,400	\$3,556
211393509	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TL8E060A12UH11	25,000	\$3,500
211393464	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TL8E080C16UH11	25,600	\$3,584
211393449	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TL8E080C16UH11	25,600	\$3,584
211393313	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TL8E100C20UH11	25,600	\$3,584
211393216	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TL9E060B12UH11	25,600	\$3,584
211393145	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TL9E060B12UH11	24,400	\$3,416
211393100	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TL9E080C16UH11	25,800	\$3,612
211393074	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TL9E080C16UH11	25,400	\$3,556
211392976	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TL9E100C20UH11	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211392888	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TMLE040A12MP11	25,200	\$3,528
211392866	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM8E040A12MP11	25,200	\$3,528
211392851	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TMLE040A12MP11	25,200	\$3,528
211392776	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM8E040A12MP11	24,800	\$3,472
211392684	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TMLE060A12MP11	25,400	\$3,556
211392669	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TMLE060A12MP11	25,400	\$3,556
211392640	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM8E060A12MP11	25,400	\$3,556
211392610	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM8E060A12MP11	25,400	\$3,556
211392539	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TMLE060A12MP11	25,000	\$3,500
211392513	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	TMLE080B12MP11	26,800	\$3,752
211392468	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	TM8E080B12MP11	26,800	\$3,752
211392403	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TMLE080B12MP11	25,800	\$3,612
211392358	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	TM8E080B12MP11	26,800	\$3,752
211392223	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM8E080B12MP11	25,000	\$3,500
211392096	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TMLE080C16MP11	25,200	\$3,528
211391852	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM8E100B12MP11	25,400	\$3,556
211391824	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM8E100B12MP11	25,400	\$3,556
211391701	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TMLE100B12MP11	25,000	\$3,500
211391696	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM8E100B12MP11	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211391614	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8E100B12MP11	24,800	\$3,472
211391599	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TMLE100B12MP11	24,800	\$3,472
211391404	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8E100C16MP11	24,800	\$3,472
211391226	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8E120C16MP11	24,800	\$3,472
211391047	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM8V060A12MP12	25,600	\$3,584
211391002	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM8V060A12MP12	25,600	\$3,584
211390943	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TPLC060A12MP13	25,200	\$3,528
211390913	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM8V060A12MP12	25,200	\$3,528
211390898	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TPLC060A12MP13	25,200	\$3,528
211390783	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TPLC080B12MP13	25,400	\$3,556
211390738	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM8V080B12MP12	25,400	\$3,556
211390705	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM8V080B12MP12	25,400	\$3,556
211390425	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TPLC080B12MP13	24,800	\$3,472
211390301	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TPLC100C16MP13	25,400	\$3,556
211390000	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8V100C16MP12	25,600	\$3,584
211389975	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TPLC100C16MP13	25,600	\$3,584
211389961	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TPLC080C16MP13	25,600	\$3,584
211389946	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TMLV100C16MP12	25,600	\$3,584
211389932	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8V080C16MP12	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211389867	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM8Y060A12MP11	25,200	\$3,528
211389824	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM8Y060A12MP11	24,600	\$3,444
211389699	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8Y080B12MP11	25,200	\$3,528
211389610	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8Y080B12MP11	24,800	\$3,472
211389568	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8Y080C16MP11	25,400	\$3,556
211389532	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM8Y100C16MP11	25,400	\$3,556
211389409	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8Y100C20MP11	25,200	\$3,528
211389394	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	TM8Y120C20MP11	25,200	\$3,528
211389310	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM8Y120C20MP11	25,400	\$3,556
211389295	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM8Y100C20MP11	25,400	\$3,556
211389151	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	TM9E060A10MP12	24,600	\$3,444
211389091	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM9E060B12MP12	25,800	\$3,612
211389076	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211388902	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	TM9E080B12MP12	25,400	\$3,556
211388835	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9E080B12MP12	25,800	\$3,612
211388709	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9E080C16MP12	25,200	\$3,528
211388512	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	TM9V040A10MP12	25,200	\$3,528
211388227	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211388222	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9V060B12MP12	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211387814	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TP9C080B12MP13	25,800	\$3,612
211387805	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9V080B12MP12	25,800	\$3,612
211387764	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	TM9V080B12MP12	25,200	\$3,528
211387713	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TP9C080B12MP13	25,000	\$3,500
211387693	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TP9C080B12MP13	25,000	\$3,500
211387636	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211387627	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211387440	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9V100C16MP12	25,000	\$3,500
211387423	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TP9C100C16MP13	25,000	\$3,500
211387052	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	TM9Y080B12MP11	26,800	\$3,752
211386967	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211386882	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9Y080B12MP11	25,400	\$3,556
211386814	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	TM9Y080C16MP11	25,400	\$3,556
211386799	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	TM9Y080C16MP11	25,400	\$3,556
211386660	CHAMPION HEATING AND COOLING	HMH72B341	JHVTC42FBCC2N1		25,000	\$3,500
211386610	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1+JMET12CS2N1		24,800	\$3,472
211386507	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TL8E080C16UH11	25,600	\$3,584
211386478	CHAMPION HEATING AND COOLING	HMH72B341	XAHD48FXXN1+TXV	TL8E080C16UH11	25,400	\$3,556
211386411	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TL8E100C20UH11	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211386288	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TL9E080C16UH11	25,800	\$3,612
211386174	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	TL9E100C20UH11	25,400	\$3,556
211386159	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	TL9E100C20UH11	25,400	\$3,556
211386145	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	TL9E100C20UH11	25,400	\$3,556
211386128	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	TL9E100C20UH11	25,400	\$3,556
211386114	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	TL9E100C20UH11	25,400	\$3,556
211385932	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TMLE080B12MP11	25,400	\$3,556
211385920	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8E080B12MP11	25,400	\$3,556
211397463	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FBCN1	TM8V080C16MP12	25,400	\$3,556
211397382	CHAMPION HEATING AND COOLING	HMH72B341	XAHC48FXXN1+TXV	TM8V080C16MP12	25,400	\$3,556
211207001	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TPLC100C16MP13	41,500	\$5,810
211206941	CHAMPION HEATING AND COOLING	HL20B4821	XAMC48HE3N1+CC	TM9V080C16MP12	41,500	\$5,810
211206905	CHAMPION HEATING AND COOLING	HL20B6021	XAMC60HE4N1+CC	TM9V100C20MP12	47,000	\$6,580
211206870	CHAMPION HEATING AND COOLING	HL20B3621	XAMC36DE2N1+CC	TM9V080C16MP12	34,400	\$4,816
211206858	CHAMPION HEATING AND COOLING	HL20B3621	XAMC36DE2N1+CC	TM9V100C16MP12	34,400	\$4,816
211206847	CHAMPION HEATING AND COOLING	HL20B2421	XAMB24DE1N1+CC	TM8V080B12MP12	23,000	\$3,220
211206840	CHAMPION HEATING AND COOLING	HL20B2421	XAMB24DE1N1+CC	TP9C060B12MP13	23,200	\$3,248
211206835	CHAMPION HEATING AND COOLING	HL20B2421	XAMB24DE1N1+CC	TM9V060B12MP12	23,200	\$3,248
214609124	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	Z9ES080B12SMPS1	18,400	\$2,576

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214720061	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM8V080C16MP12	26,000	\$3,640
214396989	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TPLC100C16MP13	26,000	\$3,640
214396984	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TPLC080C16MP13	26,000	\$3,640
214396979	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TMLV100C16MP12	26,000	\$3,640
214396974	CHAMPION HEATING AND COOLING	HH836E2S11	CTF48C5CFS1	TM8V080C16MP12	26,000	\$3,640
214720056	CHAMPION HEATING AND COOLING	HH836E2S11	CTU48C5XFS1+TXV	TM8V100C16MP12	26,000	\$3,640
214396367	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1	TP9C120D20MP13	38,000	\$5,320
214396362	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1	TM9V120D20MP12	38,000	\$5,320
214396357	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1+JMC20D2SN1		37,000	\$5,180
214396345	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	TP9C100C20MP13	37,000	\$5,180
214396340	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	TM9V100C20MP12	37,000	\$5,180
214396335	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	TM8Y100C20MP11	38,000	\$5,320
214396330	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	TM8Y120C20MP11	38,000	\$5,320
214398020	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	TMLE080C20MP11	38,000	\$5,320
214398015	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	TM8E080C20MP11	38,000	\$5,320
214397267	CHAMPION HEATING AND COOLING	HH836E2S11	CTF36C5CDS1	TM9Y100C16MP11	27,400	\$3,836
214398118	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	TPLC080B12MP13	26,800	\$3,752
214398113	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36B5CDS1	TM8V080B12MP12	26,800	\$3,752
214396964	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TMLE120C16MP11	26,000	\$3,640

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396959	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM8E120C16MP11	26,000	\$3,640
214396929	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TMLE080C16MP11	26,000	\$3,640
214396924	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM8E080C16MP11	26,000	\$3,640
214397640	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1	TM9E120D20MP12	37,400	\$5,236
214421519	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1+JMV20DC2 N1		37,000	\$5,180
214594997	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	Z8ES080C20SMPS1	37,200	\$5,208
214397630	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	TMLE120C20MP11	37,400	\$5,236
214397625	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CHS1	TM8E120C20MP11	37,400	\$5,236
214397620	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	TM8Y100C20MP11	38,000	\$5,320
214397615	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	TM8Y120C20MP11	38,000	\$5,320
214651100	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+TXV	TMLE130D20MP11	38,000	\$5,320
214396753	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CHS1	TMLE130D20MP11	38,000	\$5,320
214651085	CHAMPION HEATING AND COOLING	HH860E2S11	CTU60D5XHS1+TXV	TM8E130D20MP11	38,000	\$5,320
214397494	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60C5CGS1	TM9E080C20MP12	35,800	\$5,012
213298106	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1+JMET12BS2 N1		25,200	\$3,528
213297421	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1+JMV212BC2 N1		25,000	\$3,500
213297221	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1+JMET12CS 2N1		24,600	\$3,444
213296946	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES080C20SMPS1	25,800	\$3,612
213296906	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES100C16SMPS1	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297971	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES100C16SMPS1	25,200	\$3,528
213297951	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	Z8ES120C16SMPS1	25,200	\$3,528
213297501	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	Z8ET080C16LMPS1	25,000	\$3,500
213297496	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	Z8ET080C16LMPS1	25,000	\$3,500
213296986	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z8ES080B12SMPS1	25,400	\$3,556
213297641	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	Z8ES080B12SMPS1	24,600	\$3,444
213298011	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES080C20SMPS1	25,000	\$3,500
213297346	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES100C20SMPS1	25,400	\$3,556
213297121	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	Z8ES120C16SMPS1	25,200	\$3,528
213297111	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	Z8ES120C16SMPS1	25,200	\$3,528
213296866	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES120C20SMPS1	25,800	\$3,612
213297316	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ET080C16LMPS1	25,400	\$3,556
213297846	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1+JMV12BC2N1		24,400	\$3,416
213298031	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES080C16SMPS1	25,400	\$3,556
213296886	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES120C16SMPS1	25,600	\$3,584
213297931	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z8ET080B12LMPS1	25,400	\$3,556
213297856	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1+JMET12CS2N1		25,400	\$3,556
213297661	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	Z8ES040A12SMPS1	24,600	\$3,444
213298051	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES080B12SMPS1	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213296926	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES100B12SMPS1	25,800	\$3,612
213297551	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES100C20SMPS1	25,000	\$3,500
214398731	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1	TP9C120D20MP13	32,400	\$4,536
214398726	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CGS1	TM9V120D20MP12	32,400	\$4,536
214594982	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	Z8ES080C20SMPS1	26,000	\$3,640
214396550	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM9E100C20MP12	26,400	\$3,696
214396389	CHAMPION HEATING AND COOLING	HH836E2S11	CTM36C5CDS1	TM9Y100C16MP11	27,400	\$3,836
214396384	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM8Y080C16MP11	26,200	\$3,668
214396379	CHAMPION HEATING AND COOLING	HH836E2S11	CTM48C5CFS1	TM8Y100C16MP11	26,200	\$3,668
214396778	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1	TMLE130D20MP11	37,200	\$5,208
214396773	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1	TM8E130D20MP11	37,200	\$5,208
214396768	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60D5CJS1+JME18D2SN1		37,200	\$5,208
214421554	CHAMPION HEATING AND COOLING	HH860E2S11	CTM60D5CJS1+JMET18DS2N1		37,200	\$5,208
214396763	CHAMPION HEATING AND COOLING	HH860E2S11	JHC60D5CH2SS1		36,200	\$5,068
214584634	CHAMPION HEATING AND COOLING	HH860E2S11	CTF60C5CHS1	Z8ES120C20SMPS1	36,600	\$5,124
214397158	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TPLC080B12MP13	18,200	\$2,548
214397153	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TM8V080B12MP12	18,200	\$2,548
214397148	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TMLE080B12MP11	18,400	\$2,576
214397143	CHAMPION HEATING AND COOLING	HH824E2S11	CTF30B5ACS1	TM8E080B12MP11	18,400	\$2,576

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214397138	CHAMPION HEATING AND COOLING	HH824E2S11	CTM30B5ACS1	TM9Y060B12MP11	18,700	\$2,618
213297656	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	Z8ES040A12LMPS1	24,600	\$3,444
213297651	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	Z8ES040A12SMPS1	24,600	\$3,444
213297976	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES100C16LMPS1	25,200	\$3,528
213297966	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES100C16LMPS1	25,200	\$3,528
213297961	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES100C16SMPS1	25,200	\$3,528
213296841	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ET100C20LMPS1	26,400	\$3,696
213297001	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	Z8ES080B12LMPS1	25,400	\$3,556
213296996	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z8ES080B12LMPS1	25,400	\$3,556
213296991	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	Z8ES080B12SMPS1	25,400	\$3,556
213296981	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	Z8ES080B12LMPS1	25,400	\$3,556
213296976	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	Z8ES080B12SMPS1	25,400	\$3,556
213297556	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES100C20LMPS1	25,000	\$3,500
213297546	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES100C20LMPS1	25,000	\$3,500
213296901	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES100C16LMPS1	25,800	\$3,612
213297541	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES100C20SMPS1	25,000	\$3,500
213297911	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ET100C20LMPS1	26,000	\$3,640
213296896	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES100C16SMPS1	25,800	\$3,612
213297186	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES080B12LMPS1	26,400	\$3,696

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297491	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ET100C16LMPS1	25,600	\$3,584
213297181	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES080B12SMPS1	26,400	\$3,696
213297206	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	Z8ES040A12LMPS1	26,600	\$3,724
213297776	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES120C16LMPS1	26,800	\$3,752
213297201	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	Z8ES040A12SMPS1	26,600	\$3,724
213297771	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES120C16SMPS1	26,800	\$3,752
213297196	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	Z8ES040A12LMPS1	26,600	\$3,724
213297296	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ET100C20LMPS1	25,000	\$3,500
213297291	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ET100C20LMPS1	25,000	\$3,500
213297191	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	Z8ES040A12SMPS1	26,600	\$3,724
213298056	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES080B12LMPS1	25,400	\$3,556
213297786	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES100C16LMPS1	26,800	\$3,752
213298046	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES080B12LMPS1	25,400	\$3,556
213297781	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES100C16SMPS1	26,800	\$3,752
213298041	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES080B12SMPS1	25,400	\$3,556
213297306	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ET100C16LMPS1	25,600	\$3,584
213296891	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES120C16LMPS1	25,600	\$3,584
213297301	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ET100C16LMPS1	25,600	\$3,584
213297836	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	Z8ES080B12LMPS1	26,400	\$3,696

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297831	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	Z8ES080B12SMPS1	26,400	\$3,696
213296881	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES120C16LMPS1	25,600	\$3,584
213297826	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	Z8ES080B12LMPS1	26,400	\$3,696
213297821	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	Z8ES080B12SMPS1	26,400	\$3,696
213296876	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES120C16SMPS1	25,600	\$3,584
213297486	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ET120C20LMPS1	26,600	\$3,724
213297351	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES100C20LMPS1	25,400	\$3,556
213297341	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES100C20LMPS1	25,400	\$3,556
213297336	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES100C20SMPS1	25,400	\$3,556
213297076	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ET100C20LMPS1	25,400	\$3,556
213297071	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ET100C20LMPS1	25,400	\$3,556
213297401	CHAMPION HEATING AND COOLING	HMH72B341	XAHB30CXXN1+TXV	Z8ES080B12LMPS1	24,800	\$3,472
213297606	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	Z8ES100B12LMPS1	25,800	\$3,612
213297396	CHAMPION HEATING AND COOLING	HMH72B341	XAHB30CXXN1+TXV	Z8ES080B12SMPS1	24,800	\$3,472
213297601	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z8ES100B12LMPS1	25,800	\$3,612
213297136	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	Z8ES120C16LMPS1	25,200	\$3,528
213297596	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	Z8ES100B12SMPS1	25,800	\$3,612
213297131	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FBCN1	Z8ES120C16LMPS1	25,200	\$3,528
213297591	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z8ES100B12SMPS1	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297126	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	Z8ES120C16SMPS1	25,200	\$3,528
213297586	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	Z8ES100B12LMPS1	25,800	\$3,612
213297581	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	Z8ES100B12SMPS1	25,800	\$3,612
213297116	CHAMPION HEATING AND COOLING	HMH72B341	XAFC48FXXN1+TXV	Z8ES120C16LMPS1	25,200	\$3,528
213297921	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ET080C16LMPS1	26,600	\$3,724
213297731	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ET120C20LMPS1	25,600	\$3,584
213297841	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+JMVT12BC2N1+TXV		24,400	\$3,416
213297726	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ET120C20LMPS1	25,600	\$3,584
213297361	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES100B12LMPS1	25,000	\$3,500
213297666	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	Z8ES040A12LMPS1	24,600	\$3,444
213297356	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES100B12SMPS1	25,000	\$3,500
213297086	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ET080C16LMPS1	25,200	\$3,528
213297081	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ET080C16LMPS1	25,200	\$3,528
213297671	CHAMPION HEATING AND COOLING	HMH72B341	XAHB30CXXN1+JMVT12BC2N1+TXV		25,800	\$3,612
213297996	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	Z8ES100B12LMPS1	24,800	\$3,472
213297991	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	Z8ES100B12SMPS1	24,800	\$3,472
213297986	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	Z8ES100B12LMPS1	24,800	\$3,472
213297981	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	Z8ES100B12SMPS1	24,800	\$3,472
213296846	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ET080C16LMPS1	26,000	\$3,640

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297011	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	Z8ES040A12LMPS1	25,000	\$3,500
213297006	CHAMPION HEATING AND COOLING	HMH72B341	XAFA30DXXN1+TXV	Z8ES040A12SMPS1	25,000	\$3,500
213297576	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES100B12LMPS1	24,800	\$3,472
213297571	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES100B12SMPS1	24,800	\$3,472
213297566	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES100B12LMPS1	24,800	\$3,472
213297561	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES100B12SMPS1	24,800	\$3,472
213298111	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+JMET12BS2 N1+TXV		25,200	\$3,528
213298101	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+JMET12BS2 N1+TXV		25,200	\$3,528
213297916	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ET100C16LMPS1	26,600	\$3,724
213298086	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	Z8ES040A12LMPS1	25,600	\$3,584
213296951	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES080C20LMPS1	25,800	\$3,612
213298081	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z8ES040A12LMPS1	25,600	\$3,584
213298076	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	Z8ES040A12SMPS1	25,600	\$3,584
213296941	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES080C20LMPS1	25,800	\$3,612
213298071	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DBCN1	Z8ES040A12SMPS1	25,600	\$3,584
213296936	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES080C20SMPS1	25,800	\$3,612
213298066	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	Z8ES040A12LMPS1	25,600	\$3,584
213297516	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ET080B12LMPS1	25,400	\$3,556
213298061	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	Z8ES040A12SMPS1	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297511	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ET080B12LMPS1	25,400	\$3,556
213296911	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES100C16LMPS1	25,800	\$3,612
213297431	CHAMPION HEATING AND COOLING	HMH72B341	XAHB30CXXN1+JMET12BS2N1+TXV		25,600	\$3,584
213297166	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES080C20LMPS1	25,800	\$3,612
213297161	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES080C20SMPS1	25,800	\$3,612
213297756	CHAMPION HEATING AND COOLING	HMH72B341	XAHB30CXXN1+TXV	Z8ET080B12LMPS1	24,800	\$3,472
213297676	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+JMET12CS2N1+TXV		26,400	\$3,696
213298016	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES080C20LMPS1	25,000	\$3,500
213298006	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES080C20LMPS1	25,000	\$3,500
213298001	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES080C20SMPS1	25,000	\$3,500
213296851	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ET080B12LMPS1	24,800	\$3,472
213297216	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+JMET12CS2N1+TXV		24,600	\$3,444
213297796	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES100B12LMPS1	26,000	\$3,640
213297791	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES100B12SMPS1	26,000	\$3,640
213297311	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ET080C16LMPS1	25,400	\$3,556
213297151	CHAMPION HEATING AND COOLING	HMH72B341	XAHB30CXXN1+TXV	Z8ES100B12SMPS1	25,000	\$3,500
213297751	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	Z8ET080C16LMPS1	25,000	\$3,500
213297851	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+JMET12CS2N1+TXV		25,400	\$3,556
213297746	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	Z8ET080C16LMPS1	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297381	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	Z8ES100B12LMPS1	26,000	\$3,640
213296971	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES080B12LMPS1	24,600	\$3,444
213297376	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	Z8ES100B12SMPS1	26,000	\$3,640
213297371	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	Z8ES100B12LMPS1	26,000	\$3,640
213296966	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES080B12SMPS1	24,600	\$3,444
213297366	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	Z8ES100B12SMPS1	26,000	\$3,640
213296961	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES080B12LMPS1	24,600	\$3,444
213296956	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES080B12SMPS1	24,600	\$3,444
213297096	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ET080B12LMPS1	24,200	\$3,388
213297091	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ET080B12LMPS1	24,200	\$3,388
213297536	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES120C16LMPS1	25,200	\$3,528
213297531	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES120C16SMPS1	25,200	\$3,528
213297211	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+JMET12CS2 N1+TXV		26,000	\$3,640
213297526	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES120C16LMPS1	25,200	\$3,528
213297521	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES120C16SMPS1	25,200	\$3,528
213297231	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+JMET12BS2 N1+TXV		26,000	\$3,640
213297226	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+JMET12BS2 N1+TXV		26,000	\$3,640
213297806	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES080C20LMPS1	26,400	\$3,696
213297801	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES080C20SMPS1	26,400	\$3,696

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297321	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ET080B12LMPS1	26,400	\$3,696
213297176	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES080C16LMPS1	26,600	\$3,724
213297171	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES080C16SMPS1	26,600	\$3,724
213297766	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES120C20LMPS1	26,200	\$3,668
213297761	CHAMPION HEATING AND COOLING	HMH72B341	XAFC30CXXN1+TXV	Z8ES120C20SMPS1	26,200	\$3,668
213343200	CHAMPION HEATING AND COOLING	HMH72B341	JHVTB24CXXC2N1+TXV		25,800	\$3,612
213297626	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES080C16LMPS1	25,000	\$3,500
213297621	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ES080C16SMPS1	25,000	\$3,500
213343219	CHAMPION HEATING AND COOLING	HMH72B341	JHETB30DXXS2N1+TXV		24,800	\$3,472
213297616	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES080C16LMPS1	25,000	\$3,500
213297611	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ES080C16SMPS1	25,000	\$3,500
213297391	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES080C16LMPS1	26,000	\$3,640
213297936	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+TXV	Z8ET080B12LMPS1	25,400	\$3,556
213297386	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES080C16SMPS1	26,000	\$3,640
213297106	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+TXV	Z8ET080B12LMPS1	26,400	\$3,696
213297101	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+TXV	Z8ET080B12LMPS1	26,400	\$3,696
213343204	CHAMPION HEATING AND COOLING	HMH72B341	JHETB24CXXS2N1+TXV		25,200	\$3,528
213297926	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+TXV	Z8ET080B12LMPS1	25,400	\$3,556
213298036	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES080C16LMPS1	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213298026	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES080C16LMPS1	25,400	\$3,556
213298021	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES080C16SMPS1	25,400	\$3,556
213296871	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBCN1	Z8ES120C20LMPS1	25,800	\$3,612
213296861	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES120C20LMPS1	25,800	\$3,612
213296856	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES120C20SMPS1	25,800	\$3,612
213297646	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DBCN1	Z8ES080B12LMPS1	24,600	\$3,444
213297636	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	Z8ES080B12LMPS1	24,600	\$3,444
213297631	CHAMPION HEATING AND COOLING	HMH72B341	XAHB36DXXN1+TXV	Z8ES080B12SMPS1	24,600	\$3,444
213297956	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FBCN1	Z8ES120C16LMPS1	25,200	\$3,528
213297946	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	Z8ES120C16LMPS1	25,200	\$3,528
213297941	CHAMPION HEATING AND COOLING	HMH72B341	XAFD48FXXN1+TXV	Z8ES120C16SMPS1	25,200	\$3,528
213296836	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBCN1	Z8ET120C20LMPS1	25,000	\$3,500
213296831	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ET120C20LMPS1	25,000	\$3,500
213297816	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES080B12LMPS1	24,800	\$3,472
213297811	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES080B12SMPS1	24,800	\$3,472
213297331	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES120C16LMPS1	25,600	\$3,584
213297326	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES120C16SMPS1	25,600	\$3,584
213297426	CHAMPION HEATING AND COOLING	HMH72B341	XAUB36DXXN1+JMVT12BC2 N1+TXV		25,000	\$3,500
213297416	CHAMPION HEATING AND COOLING	HMH72B341	XAFB36DXXN1+JMVT12BC2 N1+TXV		25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297156	CHAMPION HEATING AND COOLING	HMH72B341	XAHB30CXXN1+TXV	Z8ES100B12LMPS1	25,000	\$3,500
213298096	CHAMPION HEATING AND COOLING	HMH72B341	XAUB30CXXN1+JMV12BC2N1+TXV		26,600	\$3,724
213298091	CHAMPION HEATING AND COOLING	HMH72B341	XAFB30CXXN1+JMV12BC2N1+TXV		26,600	\$3,724
213296931	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DBC1	Z8ES100B12LMPS1	25,800	\$3,612
213296921	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES100B12LMPS1	25,800	\$3,612
213296916	CHAMPION HEATING AND COOLING	HMH72B341	XAFC36DXXN1+TXV	Z8ES100B12SMPS1	25,800	\$3,612
213297506	CHAMPION HEATING AND COOLING	HMH72B341	XAUC48FXXN1+TXV	Z8ET080C16LMPS1	25,000	\$3,500
213297411	CHAMPION HEATING AND COOLING	HMH72B341	XAHB30CXXN1+TXV	Z8ES040A12LMPS1	25,000	\$3,500
213297406	CHAMPION HEATING AND COOLING	HMH72B341	XAHB30CXXN1+TXV	Z8ES040A12SMPS1	25,000	\$3,500
213297146	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES100C16LMPS1	25,600	\$3,584
213297141	CHAMPION HEATING AND COOLING	HMH72B341	XAHC30CXXN1+TXV	Z8ES100C16SMPS1	25,600	\$3,584
213297741	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DBC1	Z8ET100C16LMPS1	25,200	\$3,528
213297736	CHAMPION HEATING AND COOLING	HMH72B341	XAHC36DXXN1+TXV	Z8ET100C16LMPS1	25,200	\$3,528
211393652	CHAMPION HEATING AND COOLING	HMH72B341	JHETB30DBAS2N1		24,800	\$3,472
10525524	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TP9C080C16MP13	31,800	\$4,452
10525523	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TMLV100C16MP12	33,400	\$4,676
10525522	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TMLV080C16MP12	33,400	\$4,676
10525520	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TM9V080C16MP12	31,800	\$4,452
10525518	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TM8V080C16MP12	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
10525519	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TM8V100C16MP12	33,400	\$4,676
10309049	CHAMPION HEATING AND COOLING	HL20B2421	CM25BE1A1+MVC12BN21		22,400	\$3,136
201982916	CHAMPION HEATING AND COOLING	HL20B3621	AVV38CE221		33,400	\$4,676
10525548	CHAMPION HEATING AND COOLING	HL20B4821	CM50DE3A1	TP9C120D20MP13	44,000	\$6,160
10525544	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TPLC100C16MP13	44,000	\$6,160
10525547	CHAMPION HEATING AND COOLING	HL20B4821	CM50DE3A1	TM9V120D20MP12	44,000	\$6,160
10525545	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TPLC100C20MP13	44,000	\$6,160
10525546	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TPLC120C20MP13	44,000	\$6,160
10525543	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TPLC080C16MP13	44,000	\$6,160
10525542	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TP9C100C20MP13	44,000	\$6,160
10525539	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TMLV120C20MP12	44,000	\$6,160
10525537	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TMLV100C16MP12	44,000	\$6,160
10525538	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TMLV100C20MP12	44,000	\$6,160
10525536	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TMLV080C16MP12	44,000	\$6,160
10525535	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TM9V100C20MP12	44,000	\$6,160
10525532	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TM8V120C20MP12	44,000	\$6,160
10525531	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TM8V100C20MP12	44,000	\$6,160
10525526	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TPLC080C16MP13	33,400	\$4,676
10525528	CHAMPION HEATING AND COOLING	HL20B4821	AVV50CE321		43,500	\$6,090

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
10525530	CHAMPION HEATING AND COOLING	HL20B4821S	CM50CE3A1	TM8V100C16MP12	44,000	\$6,160
10525529	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1	TM8V080C16MP12	44,000	\$6,160
10525527	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TPLC100C16MP13	33,400	\$4,676
10525521	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TM9V100C16MP12	31,600	\$4,424
10525525	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1	TP9C100C16MP13	31,600	\$4,424
10309109	CHAMPION HEATING AND COOLING	HL20B4821	CM50DE3A1+MVC20DN21		42,500	\$5,950
10309113	CHAMPION HEATING AND COOLING	HL20B4821	CM50CE3A1+MVC16CN21		43,500	\$6,090
10309097	CHAMPION HEATING AND COOLING	HL20B3621	CM38CE2A1+MVC16CN21		33,400	\$4,676
10309105	CHAMPION HEATING AND COOLING	HL20B4821	AVV50DE321		44,000	\$6,160
209843010	CLASSIC	MRSVHC48AS	MUVHC48S		29,000	\$4,060
214397301	COLEMAN	HH836E2S11	CTF36C5CDS1	TM9E080C20MP12	29,000	\$4,060
214396901	COLEMAN	HH836E2S11	CTM36C5CDS1	TM9E080C20MP12	29,000	\$4,060
214398181	COLEMAN	HH836E2S11	CTM36C5CDS1	TM9Y100C20MP11	30,000	\$4,200
214398518	COLEMAN	HH836E2S11	CTF36C5CDS1	TM9E100C20MP12	29,000	\$4,060
214396428	COLEMAN	HH836E2S11	CTM36C5CDS1	TM9E100C20MP12	29,000	\$4,060
214397674	COLEMAN	HH836E2S11	CTF36C5CDS1	TM9Y100C20MP11	28,600	\$4,004
214595044	COLEMAN	HH836E2S11	CTF36C5CDS1	Z8ES100C20SMPS1	28,600	\$4,004
214595059	COLEMAN	HH836E2S11	CTF36C5CDS1	Z8ES080C20SMPS1	29,400	\$4,116
214595064	COLEMAN	HH836E2S11	CTM36C5CDS1	Z8ES100C20SMPS1	28,600	\$4,004
214398565	COLEMAN	HH836E2S11	CTM36C5CDS1	TL9E100C20UH11	28,400	\$3,976
214584671	COLEMAN	HH836E2S11	CTF36C5CDS1	Z8ES120C16SMPS1	28,000	\$3,920
214594984	COLEMAN	HH836E2S11	CTF36C5CDS1	Z8ES120C20SMPS1	28,600	\$4,004
215853366	COLEMAN	HH836E2S11	CTM36C5CDS1	Z9ES080C20SMPS1	28,600	\$4,004
214595014	COLEMAN	HH836E2S11	CTM36C5CDS1	Z8ES120C20SMPS1	28,600	\$4,004
214398523	COLEMAN	HH836E2S11	CTF36C5CDS1	TL9E100C20UH11	28,600	\$4,004
214584706	COLEMAN	HH836E2S11	CTM36C5CDS1	Z8ES080C16SMPS1	27,600	\$3,864
214584676	COLEMAN	HH836E2S11	CTF36C5CDS1	Z8ES080C16SMPS1	27,600	\$3,864
214584741	COLEMAN	HH836E2S11	CTM36C5CDS1	Z8ES120C16SMPS1	28,000	\$3,920
214595049	COLEMAN	HH836E2S11	CTM36C5CDS1	Z8ES080C20SMPS1	28,400	\$3,976
214584711	COLEMAN	HH836E2S11	CTM36C5CDS1	Z8ES100C16SMPS1	28,200	\$3,948

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216374631	COLEMAN	HH836E2S11	CTF36C5CDS1	Z9ET100C20SMPS1	27,600	\$3,864
214584556	COLEMAN	HH836E2S11	CTF36C5CDS1	Z8ES100C16SMPS1	28,200	\$3,948
214397281	COLEMAN	HH836E2S11	CTM36C5CDS1	TL8E100C20UH11	27,400	\$3,836
214398501	COLEMAN	HH836E2S11	CTF36C5CDS1	TL8E100C20UH11	27,600	\$3,864
214398186	COLEMAN	HH836E2S11	CTM36C5CDS1	TL8E080C16UH11	28,600	\$4,004
214396815	COLEMAN	HH836E2S11	CTF36C5CDS1	TL8E080C16UH11	28,600	\$4,004
214606502	COLEMAN	HH836E2S11	CTF36C5CDS1		28,000	\$3,920
216374671	COLEMAN	HH836E2S11	CTF36C5CDS1	Z9ET080C16SMPS1	27,600	\$3,864
214398545	COLEMAN	HH836E2S11	CTM36C5CDS1	TL9E080C16UH11	29,000	\$4,060
214606488	COLEMAN	HH836E2S11	CTF36B5CDS1		27,800	\$3,892
214396886	COLEMAN	HH836E2S11	CTF36C5CDS1	TL9E080C16UH11	28,200	\$3,948
214606495	COLEMAN	HH836E2S11	CTM36C5CDS1		27,600	\$3,864
216374554	COLEMAN	HH836E2S11	CTM36C5CDS1	Z9ET080C16SMPS1	27,600	\$3,864
214396884	COLEMAN	HH836E2S11	CTM36C5CDS1	CPLC100C16MP13	28,600	\$4,004
214396882	COLEMAN	HH836E2S11	CTM36C5CDS1	CPLC080C16MP13	28,600	\$4,004
214396877	COLEMAN	HH836E2S11	CTM36C5CDS1	TPLC100C16MP13	28,600	\$4,004
214396872	COLEMAN	HH836E2S11	CTM36C5CDS1	TPLC080C16MP13	28,600	\$4,004
214396867	COLEMAN	HH836E2S11	CTM36C5CDS1	TMLV100C16MP12	28,600	\$4,004
214396862	COLEMAN	HH836E2S11	CTM36C5CDS1	TM8V080C16MP12	28,600	\$4,004
214396857	COLEMAN	HH836E2S11	CTM36C5CDS1	TM8V100C16MP12	28,600	\$4,004
214396411	COLEMAN	HH836E2S11	CTF36C5CDS1	CP9C100C20MP13	29,600	\$4,144
214396406	COLEMAN	HH836E2S11	CTF36C5CDS1	TP9C100C20MP13	29,600	\$4,144
214396401	COLEMAN	HH836E2S11	CTF36C5CDS1	TM9V100C20MP12	29,600	\$4,144
215853355	COLEMAN	HH836E2S11	CTM36C5CDS1+JMET16CS2N1		27,800	\$3,892
216566094	COLEMAN	UMC48CN23STG1	Combination heat pumps with or without ducts		27,800	\$3,892
216566093	COLEMAN	UMC48CN23STG1	Heat pump without ducts		28,200	\$3,948
216566096	COLEMAN	UMC36CN23STG1	Heat pump without ducts		22,600	\$3,164
216566116	COLEMAN	UMC18CN23STG1	Heat pump without ducts		11,500	\$1,610
216572459	COLEMAN	UPC36CN23STG1	UNI36HW23STG1		26,000	\$3,640
216572160	COLEMAN	UPC24CN23STG1	UNI24HW23STG1		17,000	\$2,380
216572159	COLEMAN	UPC18CN23STG1	UNI18HW23STG1		13,400	\$1,876
216572158	COLEMAN	UPC12CN23STG1	UNI12HW23STG1		8,900	\$1,246
216566113	COLEMAN	UPC24CN23STG1	UNI24DT23STG1		18,200	\$2,548
216566112	COLEMAN	UPC18CN23STG1	UNI18DT23STG1		13,200	\$1,848
216566109	COLEMAN	UPC24CN23STG1	UNI24CS23STG1		19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214807831	COLEMAN	HH860E2S11	CTU60D5XHS1+JMET18DS2 N1+TXV		36,600	\$5,124
214397587	COLEMAN	HH860E2S11	CTF60D5CHS1+JMET18DS2 N1		36,600	\$5,124
214398466	COLEMAN	HH860E2S11	CTF60D5CJS1	TM9Y120D20MP11	38,500	\$5,390
214833522	COLEMAN	HH860E2S11	JSE60D5CJ2SS1		37,200	\$5,208
214606520	COLEMAN	HH860E2S11	CTF60D5CJS1		38,000	\$5,320
214833517	COLEMAN	HH860E2S11	JSC60D5CJ2SS1		37,200	\$5,208
214396349	COLEMAN	HH860E2S11	JHC60D5CJ2SS1		37,200	\$5,208
214421536	COLEMAN	HH860E2S11	CTM60C5CHS1+JMET16CS 2N1		36,800	\$5,152
214396723	COLEMAN	HH824E2S11	CTM30B5ACS1	CP9C060B12MP13	18,100	\$2,534
214396718	COLEMAN	HH824E2S11	CTM30B5ACS1	TP9C060B12MP13	18,100	\$2,534
214396713	COLEMAN	HH824E2S11	CTM30B5ACS1	TM9V060B12MP12	18,100	\$2,534
214396289	COLEMAN	HH824E2S11	CTM30B5ACS1	TL9E060B12UH11	18,100	\$2,534
214807821	COLEMAN	HH824E2S11	CTU30B5XCS1+JME12B2SN 1+TXV		17,500	\$2,450
214397970	COLEMAN	HH824E2S11	CTF30B5ACS1+JME12B2SN 1		17,500	\$2,450
215853303	COLEMAN	HH824E2S11	CTM30B5ACS1+JMET08BS2 N1		17,900	\$2,506
214606566	COLEMAN	HH860E2S11	CTM60C5CGS1		34,800	\$4,872
216374590	COLEMAN	HH836E2S11	CTM36B5CDS1	Z9ET060B12SMPS1	28,200	\$3,948
214807766	COLEMAN	HH836E2S11	CTU36B5XDS1+JME12B2SN 1+TXV		26,800	\$3,752
214397291	COLEMAN	HH836E2S11	CTF36B5CDS1+JME12B2SN 1		26,800	\$3,752
214396423	COLEMAN	HH836E2S11	CTM36B5CDS1	TM9E060B12MP12	27,400	\$3,836
214398528	COLEMAN	HH836E2S11	CTF36C5CDS1	TM9E080C16MP12	28,000	\$3,920
214397279	COLEMAN	HH836E2S11	CTF36C5CDS1	CP9C080C16MP13	28,200	\$3,948
214397274	COLEMAN	HH836E2S11	CTF36C5CDS1	TP9C080C16MP13	28,200	\$3,948
214397269	COLEMAN	HH836E2S11	CTF36C5CDS1	TM9V080C16MP12	28,200	\$3,948
214398122	COLEMAN	HH836E2S11	CTM36B5CDS1	TM9Y080B12MP11	27,800	\$3,892
214398157	COLEMAN	HH836E2S11	CTM36C5CDS1	CP9C080C16MP13	28,200	\$3,948
214398152	COLEMAN	HH836E2S11	CTM36C5CDS1	TP9C080C16MP13	28,200	\$3,948
214398147	COLEMAN	HH836E2S11	CTM36C5CDS1	TM9V080C16MP12	28,200	\$3,948
215853349	COLEMAN	HH836E2S11	CTM36C5CDS1+JMVT17CC 2N1		28,200	\$3,948

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398105	COLEMAN	HH836E2S11	CTF36C5CDS1+JMC16C2SN1		28,000	\$3,920
214397234	COLEMAN	HH836E2S11	CTF36C5CDS1+JMET16CS2N1		27,800	\$3,892
215853356	COLEMAN	HH836E2S11	CTM36C5CDS1+JMC17C2SN1		28,200	\$3,948
214719873	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TM9E100C20MP12	26,400	\$3,696
214397387	COLEMAN	HH836E2S11	CTF48C5CFS1	TM9E100C20MP12	26,400	\$3,696
214720048	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TM9Y080C16MP11	25,800	\$3,612
214398211	COLEMAN	HH836E2S11	CTF48C5CFS1	TM9Y080C16MP11	25,800	\$3,612
214609205	COLEMAN	HH836E2S11	CTM48C5CFS1	Z9ES080C16SMPS1	26,400	\$3,696
214396493	COLEMAN	HH836E2S11	CTM48C5CFS1+JME16C2SN1		25,800	\$3,612
214396941	COLEMAN	HH836E2S11	CTM48C5CFS1+JMT16CC2N1		25,800	\$3,612
214397792	COLEMAN	HH836E2S11	CTM48C5CFS1+JME12C2SN1		25,800	\$3,612
214720043	COLEMAN	HH836E2S11	CTU48C5XFS1+JMET12CS2N1+TXV		25,800	\$3,612
214397642	COLEMAN	HH836E2S11	CTF48C5CFS1+JMET12CS2N1		25,800	\$3,612
214606515	COLEMAN	HH836E2S11	CTM36B5CDS1		27,000	\$3,780
216374778	COLEMAN	HH860E2S11	CTM60C5CHS1	Z9ET100C20SMPS1	37,400	\$5,236
214650719	COLEMAN	HH860E2S11	CTU60D5XHS1+TXV	TM9E120D20MP12	37,800	\$5,292
214397194	COLEMAN	HH860E2S11	CTF60D5CHS1	TM9E120D20MP12	37,800	\$5,292
214397997	COLEMAN	HH860E2S11	CTF60C5CHS1+JMC17C2SN1		36,400	\$5,096
214397172	COLEMAN	HH860E2S11	CTM60D5CHS1+JME18D2SN1		36,600	\$5,124
214720026	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TL9E080C16UH11	33,000	\$4,620
214396614	COLEMAN	HH860E2S11	CTF60C5CGS1	TL9E080C16UH11	33,000	\$4,620
214398426	COLEMAN	HH860E2S11	CTM60C5CHS1+JMT17CC2N1		36,400	\$5,096
215853459	COLEMAN	HH860E2S11	CTM60D5CJS1	CP9C120D20MP13	38,000	\$5,320
215853460	COLEMAN	HH860E2S11	CTM60D5CJS1	TP9C120D20MP13	38,000	\$5,320
215853461	COLEMAN	HH860E2S11	CTM60D5CJS1	TM9V120D20MP12	38,000	\$5,320
214397204	COLEMAN	HH860E2S11	CTF60D5CJS1+JMET18DS2N1		37,200	\$5,208
214606550	COLEMAN	HH860E2S11	CTM60D5CHS1		34,800	\$4,872

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214807841	COLEMAN	HH860E2S11	CTU60D5XHS1+JMC20D2S N1+TXV		36,600	\$5,124
214397167	COLEMAN	HH860E2S11	CTF60D5CHS1+JMC20D2SN 1		36,600	\$5,124
214396277	COLEMAN	HH824E2S11	CTM30B5ACS1	CP9C080B12MP13	18,000	\$2,520
214396272	COLEMAN	HH824E2S11	CTM30B5ACS1	TP9C080B12MP13	18,000	\$2,520
214396267	COLEMAN	HH824E2S11	CTM30B5ACS1	TM9V080B12MP12	18,000	\$2,520
214651799	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	TM9E080B12MP12	17,800	\$2,492
214396708	COLEMAN	HH824E2S11	CTF30B5ACS1	TM9E080B12MP12	17,800	\$2,492
214650818	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	CP9C060B12MP13	18,000	\$2,520
214650802	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	TP9C060B12MP13	18,000	\$2,520
214650787	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	TM9V060B12MP12	18,000	\$2,520
214397575	COLEMAN	HH824E2S11	CTF30B5ACS1	CP9C060B12MP13	18,000	\$2,520
214397570	COLEMAN	HH824E2S11	CTF30B5ACS1	TP9C060B12MP13	18,000	\$2,520
214397565	COLEMAN	HH824E2S11	CTF30B5ACS1	TM9V060B12MP12	18,000	\$2,520
214397563	COLEMAN	HH824E2S11	CTM30B5ACS1	CPLC080B12MP13	18,100	\$2,534
214397558	COLEMAN	HH824E2S11	CTM30B5ACS1	TPLC080B12MP13	18,100	\$2,534
214396252	COLEMAN	HH824E2S11	CTM30B5ACS1	TM9Y080B12MP11	18,000	\$2,520
214396703	COLEMAN	HH824E2S11	JHE24B5AC2SS1		18,600	\$2,604
214606540	COLEMAN	HH860E2S11	CTF60D5CGS1		34,800	\$4,872
214396396	COLEMAN	HH836E2S11	CTF36C5CDS1+JMC17C2SN 1		27,600	\$3,864
214728381	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	CPLC080B12MP13	27,200	\$3,808
214728376	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	TPLC080B12MP13	27,200	\$3,808
214397316	COLEMAN	HH836E2S11	CTF36B5CDS1	CPLC080B12MP13	27,200	\$3,808
214397311	COLEMAN	HH836E2S11	CTF36B5CDS1	TPLC080B12MP13	27,200	\$3,808
214398169	COLEMAN	HH836E2S11	CTM36C5CDS1	CP9C100C16MP13	28,000	\$3,920
214398164	COLEMAN	HH836E2S11	CTM36C5CDS1	TP9C100C16MP13	28,000	\$3,920
214398159	COLEMAN	HH836E2S11	CTM36C5CDS1	TM9V100C16MP12	28,000	\$3,920
214397249	COLEMAN	HH836E2S11	CTF36C5CDS1+JME16C2SN 1		28,200	\$3,948
214398100	COLEMAN	HH836E2S11	CTF36C5CDS1+JMET12CS2 N1		27,800	\$3,892
214720221	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TM9E080C20MP12	26,200	\$3,668
214397817	COLEMAN	HH836E2S11	CTF48C5CFS1	TM9E080C20MP12	26,200	\$3,668
214720149	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TL9E100C20UH11	26,200	\$3,668
214398607	COLEMAN	HH836E2S11	CTF48C5CFS1	TL9E100C20UH11	26,200	\$3,668
214719868	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TL9E080C16UH11	26,000	\$3,640

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398602	COLEMAN	HH836E2S11	CTF48C5CFS1	TL9E080C16UH11	26,000	\$3,640
214719986	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TM9E080C16MP12	26,000	\$3,640
214397382	COLEMAN	HH836E2S11	CTF48C5CFS1	TM9E080C16MP12	26,000	\$3,640
214397368	COLEMAN	HH836E2S11	CTM48C5CFS1	CP9C080C16MP13	25,800	\$3,612
214397363	COLEMAN	HH836E2S11	CTM48C5CFS1	TP9C080C16MP13	25,800	\$3,612
214397358	COLEMAN	HH836E2S11	CTM48C5CFS1	TM9V080C16MP12	25,800	\$3,612
214398231	COLEMAN	HH836E2S11	CTM48C5CFS1+JMC16C2S N1		25,800	\$3,612
214719905	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TM9Y100C20MP11	26,600	\$3,724
214396483	COLEMAN	HH836E2S11	CTF48C5CFS1	TM9Y100C20MP11	26,600	\$3,724
214720134	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TM9E100C16MP12	26,000	\$3,640
214397323	COLEMAN	HH836E2S11	CTF48C5CFS1	TM9E100C16MP12	26,000	\$3,640
214397219	COLEMAN	HH836E2S11	CTM48C5CFS1	TL9E080C16UH11	26,000	\$3,640
214606503	COLEMAN	HH836E2S11	CTM48C5CFS1		26,000	\$3,640
214397659	COLEMAN	HH836E2S11	JHC36B5CD2SS1		26,600	\$3,724
214396322	COLEMAN	HH860E2S11	CTM60C5CHS1+JMC17C2S N1		36,400	\$5,096
214397913	COLEMAN	HH860E2S11	CTM60D5CGS1	TM9Y120D20MP11	32,400	\$4,536
214809018	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	CP9C100C16MP13	32,200	\$4,508
214809013	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TP9C100C16MP13	32,200	\$4,508
214809196	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TM9V100C16MP12	32,200	\$4,508
214396577	COLEMAN	HH860E2S11	CTF60C5CGS1	CP9C100C16MP13	32,200	\$4,508
214396572	COLEMAN	HH860E2S11	CTF60C5CGS1	TP9C100C16MP13	32,200	\$4,508
214396567	COLEMAN	HH860E2S11	CTF60C5CGS1	TM9V100C16MP12	32,200	\$4,508
215853457	COLEMAN	HH860E2S11	JHE60C5CH2SS1		37,000	\$5,180
215853458	COLEMAN	HH860E2S11	CTM60D5CJS1	TM9Y120D20MP11	38,500	\$5,390
214606521	COLEMAN	HH860E2S11	CTM60D5CJS1		38,000	\$5,320
214398456	COLEMAN	HH860E2S11	JHE60D5CJ2SS1		37,400	\$5,236
214651694	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	TM9Y080B12MP11	17,900	\$2,506
214396698	COLEMAN	HH824E2S11	CTF30B5ACS1	TM9Y080B12MP11	17,900	\$2,506
214652055	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	CP9C080B12MP13	17,900	\$2,506
214652041	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	TP9C080B12MP13	17,900	\$2,506
214652027	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	TM9V080B12MP12	17,900	\$2,506
214397985	COLEMAN	HH824E2S11	CTF30B5ACS1	CP9C080B12MP13	17,900	\$2,506
214397980	COLEMAN	HH824E2S11	CTF30B5ACS1	TP9C080B12MP13	17,900	\$2,506
214397975	COLEMAN	HH824E2S11	CTF30B5ACS1	TM9V080B12MP12	17,900	\$2,506
214651317	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	TM9E060B12MP12	17,900	\$2,506
214397125	COLEMAN	HH824E2S11	CTF30B5ACS1	TM9E060B12MP12	17,900	\$2,506

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853302	COLEMAN	HH824E2S11	CTM30B5ACS1+JMET12BS2 N1		17,800	\$2,492
214606564	COLEMAN	HH860E2S11	CTM60D5CGS1		34,800	\$4,872
216374549	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	Z9ET060B12SMPS1	28,200	\$3,948
216374748	COLEMAN	HH836E2S11	CTF36B5CDS1	Z9ET060B12SMPS1	28,200	\$3,948
214398516	COLEMAN	HH836E2S11	CTM36B5CDS1	CP9C080B12MP13	27,000	\$3,780
214398511	COLEMAN	HH836E2S11	CTM36B5CDS1	TP9C080B12MP13	27,000	\$3,780
214398506	COLEMAN	HH836E2S11	CTM36B5CDS1	TM9V080B12MP12	27,000	\$3,780
214728398	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	CP9C060B12MP13	27,200	\$3,808
214728393	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	TP9C060B12MP13	27,200	\$3,808
214728388	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	TM9V060B12MP12	27,200	\$3,808
214396850	COLEMAN	HH836E2S11	CTF36B5CDS1	CP9C060B12MP13	27,200	\$3,808
214396845	COLEMAN	HH836E2S11	CTF36B5CDS1	TP9C060B12MP13	27,200	\$3,808
214396840	COLEMAN	HH836E2S11	CTF36B5CDS1	TM9V060B12MP12	27,200	\$3,808
214397724	COLEMAN	HH836E2S11	CTF36C5CDS1	CP9C100C16MP13	27,800	\$3,892
214397719	COLEMAN	HH836E2S11	CTF36C5CDS1	TP9C100C16MP13	27,800	\$3,892
214397714	COLEMAN	HH836E2S11	CTF36C5CDS1	TM9V100C16MP12	27,800	\$3,892
214398142	COLEMAN	HH836E2S11	CTM36C5CDS1	TM9Y080C16MP11	27,200	\$3,808
214396433	COLEMAN	HH836E2S11	CTM36C5CDS1	TM9E080C16MP12	29,400	\$4,116
215853343	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	TL9E060B12UH11	27,200	\$3,808
215853344	COLEMAN	HH836E2S11	CTF36B5CDS1	TL9E060B12UH11	27,200	\$3,808
215853357	COLEMAN	HH836E2S11	CTM36C5CDS1+JMVT16CC 2N1		28,200	\$3,948
214396810	COLEMAN	HH836E2S11	CTF36C5CDS1+JMVT17CC2 N1		28,000	\$3,920
215853358	COLEMAN	HH836E2S11	CTM36B5CDS1	Z9ES080B12SMPS1	27,600	\$3,864
214398585	COLEMAN	HH836E2S11	CTM48C5CFS1	CP9C100C20MP13	26,400	\$3,696
214398580	COLEMAN	HH836E2S11	CTM48C5CFS1	TP9C100C20MP13	26,400	\$3,696
214398575	COLEMAN	HH836E2S11	CTM48C5CFS1	TM9V100C20MP12	26,400	\$3,696
214720211	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TM9Y100C16MP11	26,000	\$3,640
214396780	COLEMAN	HH836E2S11	CTF48C5CFS1	TM9Y100C16MP11	26,000	\$3,640
214807796	COLEMAN	HH836E2S11	CTU48C5XFS1+JME16C2SN 1+TXV		25,800	\$3,612
214396371	COLEMAN	HH836E2S11	CTF48C5CFS1+JME16C2SN 1		25,800	\$3,612
214397343	COLEMAN	HH836E2S11	CTM48C5CFS1+JMC17C2S N1		25,600	\$3,584
215853345	COLEMAN	HH836E2S11	CTU48C5XFS1+JMET16CS2 N1+TXV		25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396478	COLEMAN	HH836E2S11	CTF48C5CFS1+JMET16CS2 N1		25,800	\$3,612
214396443	COLEMAN	HH836E2S11	JHE36C5CD2SS1		27,200	\$3,808
216374656	COLEMAN	HH860E2S11	CTM60D5CHS1	Z9ET120D20SMPS1	38,000	\$5,320
214396317	COLEMAN	HH860E2S11	CTM60C5CHS1+JME16C2S N1		36,600	\$5,124
214807846	COLEMAN	HH860E2S11	CTU60D5XHS1+JME18D2SN 1+TXV		36,600	\$5,124
214396740	COLEMAN	HH860E2S11	CTF60D5CHS1+JME18D2SN 1		36,600	\$5,124
214398421	COLEMAN	HH860E2S11	CTF60C5CHS1+JME16C2SN 1		36,600	\$5,124
214809162	COLEMAN	HH860E2S11	CTU60D5XGS1+JME18D2S N1+TXV		34,400	\$4,816
214397030	COLEMAN	HH860E2S11	CTF60D5CGS1+JME18D2SN 1		34,400	\$4,816
214397209	COLEMAN	HH860E2S11	CTM60D5CJS1+JME18D2SN 1		37,200	\$5,208
214606548	COLEMAN	HH860E2S11	CTF60D5CHS1		34,600	\$4,844
214397199	COLEMAN	HH860E2S11	JHE60D5CH2SS1		36,800	\$5,152
214396262	COLEMAN	HH824E2S11	CTM30B5ACS1+JMC12B2S N1		17,600	\$2,464
214397987	COLEMAN	HH824E2S11	CTM30B5ACS1	TM9E080B12MP12	17,900	\$2,506
214649991	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	TL9E060B12UH11	18,000	\$2,520
214397992	COLEMAN	HH824E2S11	CTF30B5ACS1	TL9E060B12UH11	18,000	\$2,520
215853304	COLEMAN	HH824E2S11	CTM30B5ACS1+JMV12BC2 N1		17,600	\$2,464
214807816	COLEMAN	HH824E2S11	CTU30B5XCS1+JMC12B2SN 1+TXV		17,600	\$2,464
214396693	COLEMAN	HH824E2S11	CTF30B5ACS1+JMC12B2SN 1		17,600	\$2,464
214807801	COLEMAN	HH824E2S11	CTU30B5XCS1+JME08B2SN 1+TXV		17,600	\$2,464
214397960	COLEMAN	HH824E2S11	CTF30B5ACS1+JME08B2SN 1		17,600	\$2,464
216374707	COLEMAN	HH836E2S11	CTM36B5CDS1	Z9ET080B12SMPS1	28,000	\$3,920
214397380	COLEMAN	HH836E2S11	CTF48C5CFS1	CP9C100C20MP13	26,600	\$3,724
214397375	COLEMAN	HH836E2S11	CTF48C5CFS1	TP9C100C20MP13	26,600	\$3,724
214397370	COLEMAN	HH836E2S11	CTF48C5CFS1	TM9V100C20MP12	26,600	\$3,724

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398587	COLEMAN	HH836E2S11	CTM48C5CFS1	TM9Y080C16MP11	25,800	\$3,612
214807781	COLEMAN	HH836E2S11	CTU48C5XFS1+JMVT17CC2 N1+TXV		25,800	\$3,612
214398570	COLEMAN	HH836E2S11	CTF48C5CFS1+JMVT17CC2 N1		25,800	\$3,612
214397328	COLEMAN	HH836E2S11	CTM48C5CFS1+JMVT17CC2 N1		25,600	\$3,584
214807786	COLEMAN	HH836E2S11	CTU48C5XFS1+JMC17C2SN 1+TXV		25,800	\$3,612
214396488	COLEMAN	HH836E2S11	CTF48C5CFS1+JMC17C2SN 1		25,800	\$3,612
214421526	COLEMAN	HH836E2S11	CTM48C5CFS1+JMET16CS2 N1		25,800	\$3,612
216374615	COLEMAN	HH860E2S11	CTF60C5CHS1	Z9ET100C20SMPS1	37,400	\$5,236
214398061	COLEMAN	HH860E2S11	CTM60C5CHS1	TM9E080C20MP12	38,000	\$5,320
214397592	COLEMAN	HH860E2S11	CTM60D5CHS1+JMVT20DC 2N1		36,600	\$5,124
214609141	COLEMAN	HH860E2S11	CTM60C5CGS1	Z9ES100C16SMPS1	33,600	\$4,704
214651813	COLEMAN	HH860E2S11	CTU60D5XGS1+TXV	TM9Y120D20MP11	32,400	\$4,536
214398718	COLEMAN	HH860E2S11	CTF60D5CGS1	TM9Y120D20MP11	32,400	\$4,536
214807836	COLEMAN	HH860E2S11	CTU60D5XHS1+JMVT20DC2 N1+TXV		37,000	\$5,180
214396735	COLEMAN	HH860E2S11	CTF60D5CHS1+JMVT20DC2 N1		37,000	\$5,180
214398066	COLEMAN	HH860E2S11	CTF60D5CJS1+JMC20D2SN 1		37,000	\$5,180
214606567	COLEMAN	HH860E2S11	CTM60C5CHS1		34,600	\$4,844
214421511	COLEMAN	HH860E2S11	CTF60C5CHS1+JMET16CS2 N1		36,800	\$5,152
214807811	COLEMAN	HH824E2S11	CTU30B5XCS1+JMVT12BC2 N1+TXV		17,600	\$2,464
214396257	COLEMAN	HH824E2S11	CTF30B5ACS1+JMVT12BC2 N1		17,600	\$2,464
214651750	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	TM9Y060B12MP11	18,000	\$2,520
214397130	COLEMAN	HH824E2S11	CTF30B5ACS1	TM9Y060B12MP11	18,000	\$2,520
214397965	COLEMAN	HH824E2S11	CTM30B5ACS1+JME12B2SN 1		17,600	\$2,464
214807806	COLEMAN	HH824E2S11	CTU30B5XCS1+JMET08BS2 N1+TXV		17,800	\$2,492

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214397120	COLEMAN	HH824E2S11	CTF30B5ACS1+JMET08BS2 N1		17,800	\$2,492
214606486	COLEMAN	HH824E2S11	CTM30B5ACS1		18,800	\$2,632
214809147	COLEMAN	HH860E2S11	CTU60D5XGS1+JMVT20DC2 N1+TXV		33,800	\$4,732
214397429	COLEMAN	HH860E2S11	CTF60D5CGS1+JMVT20DC2 N1		33,800	\$4,732
216374753	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	Z9ET080B12SMPS1	28,000	\$3,920
216374712	COLEMAN	HH836E2S11	CTF36B5CDS1	Z9ET080B12SMPS1	28,000	\$3,920
216374666	COLEMAN	HH836E2S11	CTF36C5CDS1	Z9ET100C16SMPS1	26,800	\$3,752
215853362	COLEMAN	HH836E2S11	CTF36C5CDS1	Z9ES080C16SMPS1	27,000	\$3,780
214396438	COLEMAN	HH836E2S11	CTM36B5CDS1	TM9E080B12MP12	28,200	\$3,948
214728366	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	TM9Y060B12MP11	27,800	\$3,892
214396906	COLEMAN	HH836E2S11	CTF36B5CDS1	TM9Y060B12MP11	27,800	\$3,892
214397726	COLEMAN	HH836E2S11	CTM36C5CDS1	TM9E100C16MP12	28,000	\$3,920
214719692	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	TM9Y080B12MP11	27,800	\$3,892
214397254	COLEMAN	HH836E2S11	CTF36B5CDS1	TM9Y080B12MP11	27,800	\$3,892
214807746	COLEMAN	HH836E2S11	CTU36B5XDS1+JMVT12BC2 N1+TXV		27,800	\$3,892
214396391	COLEMAN	HH836E2S11	CTF36B5CDS1+JMVT12BC2 N1		27,800	\$3,892
214779454	COLEMAN	HH836E2S11	CTU36B5XDS1+JMET12BS2 N1+TXV		28,200	\$3,948
214421506	COLEMAN	HH836E2S11	CTF36B5CDS1+JMET12BS2 N1		28,200	\$3,948
214398496	COLEMAN	HH836E2S11	CTF36C5CDS1+JMVT16CC2 N1		28,000	\$3,920
214398137	COLEMAN	HH836E2S11	CTM36B5CDS1	TM9Y060B12MP11	27,600	\$3,864
214397296	COLEMAN	HH836E2S11	CTF36C5CDS1+JME12C2SN 1		27,000	\$3,780
214421521	COLEMAN	HH836E2S11	CTM48C5CFS1+JMET12CS2 N1		25,800	\$3,612
214397802	COLEMAN	HH836E2S11	CTM48C5CFS1	TM9Y100C16MP11	25,800	\$3,612
214398086	COLEMAN	HH836E2S11	CTM48C5CFS1	CP9C100C16MP13	25,800	\$3,612
214398081	COLEMAN	HH836E2S11	CTM48C5CFS1	TP9C100C16MP13	25,800	\$3,612
214398369	COLEMAN	HH824E2S11	CTM30B5ACS1+JME08B2SN 1		17,700	\$2,478
214606487	COLEMAN	HH824E2S11	CTF30B5ACS1		18,800	\$2,632
214606562	COLEMAN	HH860E2S11	CTF60C5CGS1		34,800	\$4,872

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216374626	COLEMAN	HH836E2S11	CTM36C5CDS1	Z9ET100C16SMPS1	28,000	\$3,920
214728383	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	TM9E060B12MP12	27,400	\$3,836
214396805	COLEMAN	HH836E2S11	CTF36B5CDS1	TM9E060B12MP12	27,400	\$3,836
215853351	COLEMAN	HH836E2S11	CTM36C5CDS1+JME12C2S N1		26,800	\$3,752
214397768	COLEMAN	HH836E2S11	CTF36C5CDS1	CPLC100C16MP13	28,200	\$3,948
214397766	COLEMAN	HH836E2S11	CTF36C5CDS1	CPLC080C16MP13	28,200	\$3,948
214397761	COLEMAN	HH836E2S11	CTF36C5CDS1	TPLC100C16MP13	28,200	\$3,948
214397756	COLEMAN	HH836E2S11	CTF36C5CDS1	TPLC080C16MP13	28,200	\$3,948
214397751	COLEMAN	HH836E2S11	CTF36C5CDS1	TMLV100C16MP12	28,200	\$3,948
214728361	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	TM9E080B12MP12	28,200	\$3,948
214397286	COLEMAN	HH836E2S11	CTF36B5CDS1	TM9E080B12MP12	28,200	\$3,948
215853350	COLEMAN	HH836E2S11	JHE36B5CD2SS1		28,400	\$3,976
214807756	COLEMAN	HH836E2S11	CTU36B5XDS1+JMC12B2SN 1+TXV		27,800	\$3,892
214396852	COLEMAN	HH836E2S11	CTF36B5CDS1+JMC12B2SN 1		27,800	\$3,892
215853353	COLEMAN	HH836E2S11	CTM36C5CDS1+JMET12CS 2N1		27,800	\$3,892
215853352	COLEMAN	HH836E2S11	CTM36C5CDS1+JMC16C2S N1		28,200	\$3,948
214396995	COLEMAN	HH836E2S11	CTM48C5CFS1	TL9E100C20UH11	26,200	\$3,668
214396545	COLEMAN	HH836E2S11	CTM48C5CFS1	CPLC100C16MP13	25,800	\$3,612
214396543	COLEMAN	HH836E2S11	CTM48C5CFS1	CPLC080C16MP13	25,800	\$3,612
214396538	COLEMAN	HH836E2S11	CTM48C5CFS1	TPLC100C16MP13	25,800	\$3,612
214396533	COLEMAN	HH836E2S11	CTM48C5CFS1	TPLC080C16MP13	25,800	\$3,612
214396528	COLEMAN	HH836E2S11	CTM48C5CFS1	TMLV100C16MP12	25,800	\$3,612
214397797	COLEMAN	HH836E2S11	CTM48C5CFS1	TM9Y100C20MP11	26,600	\$3,724
214398071	COLEMAN	HH836E2S11	CTM48C5CFS1	TM9E100C16MP12	26,000	\$3,640
215853347	COLEMAN	HH836E2S11	CTU48C5XFS1+JMC16C2SN 1+TXV		25,800	\$3,612
214398206	COLEMAN	HH836E2S11	CTF48C5CFS1+JMC16C2SN 1		25,800	\$3,612
214719903	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	CP9C080C16MP13	26,000	\$3,640
214719898	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TP9C080C16MP13	26,000	\$3,640
214719893	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	TM9V080C16MP12	26,000	\$3,640
214397790	COLEMAN	HH836E2S11	CTF48C5CFS1	CP9C080C16MP13	26,000	\$3,640
214397785	COLEMAN	HH836E2S11	CTF48C5CFS1	TP9C080C16MP13	26,000	\$3,640
214397780	COLEMAN	HH836E2S11	CTF48C5CFS1	TM9V080C16MP12	26,000	\$3,640

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214397318	COLEMAN	HH836E2S11	JHC42C5CF2SS1		25,800	\$3,612
214606505	COLEMAN	HH836E2S11	CTF48C5CFS1		26,000	\$3,640
214396310	COLEMAN	HH860E2S11	CTF60C5CHS1	CP9C100C20MP13	37,000	\$5,180
214396305	COLEMAN	HH860E2S11	CTF60C5CHS1	TP9C100C20MP13	37,000	\$5,180
214396299	COLEMAN	HH860E2S11	CTF60C5CHS1	TM9V100C20MP12	37,000	\$5,180
214809260	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	Z9ES100C20SMPS1	33,800	\$4,732
214609146	COLEMAN	HH860E2S11	CTF60C5CGS1	Z9ES100C20SMPS1	33,800	\$4,732
214396584	COLEMAN	HH860E2S11	CTM60D5CGS1+JME18D2S N1		32,000	\$4,480
215853466	COLEMAN	HH860E2S11	CTF60D5CJS1	Z9ES120D20SMPS1	37,600	\$5,264
214609180	COLEMAN	HH824E2S11	CTM30B5ACS1	Z9ES060B12SMPS1	17,900	\$2,506
214609053	COLEMAN	HH860E2S11	CTM60C5CGS1	Z9ES080C20SMPS1	32,600	\$4,564
215853365	COLEMAN	HH836E2S11	CTM36B5CDS1	Z9ES060B12SMPS1	27,400	\$3,836
215853370	COLEMAN	HH836E2S11	CTF36C5CDS1	Z9ES100C20SMPS1	29,600	\$4,144
214609106	COLEMAN	HH860E2S11	CTM60C5CHS1	Z9ES080C20SMPS1	37,400	\$5,236
214609131	COLEMAN	HH824E2S11	CTM36B5ADS1	Z9ES060B12SMPS1	18,300	\$2,562
215853369	COLEMAN	HH836E2S11	CTF36C5CDS1	Z9ES100C16SMPS1	29,200	\$4,088
214609092	COLEMAN	HH836E2S11	CTM48C5CFS1	Z9ES080C20SMPS1	26,200	\$3,668
214651029	COLEMAN	HH860E2S11	CTU60D5XHS1+TXV	Z9ES120D20SMPS1	37,000	\$5,180
214609165	COLEMAN	HH860E2S11	CTF60D5CHS1	Z9ES120D20SMPS1	37,000	\$5,180
215853467	COLEMAN	HH860E2S11	CTM60D5CJS1	Z9ES120D20SMPS1	38,000	\$5,320
214609082	COLEMAN	HH860E2S11	CTM60C5CGS1	Z9ES100C20SMPS1	34,600	\$4,844
215853368	COLEMAN	HH836E2S11	CTM36C5CDS1	Z9ES100C16SMPS1	29,200	\$4,088
214719920	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	Z9ES080C20SMPS1	26,200	\$3,668
214609121	COLEMAN	HH836E2S11	CTF48C5CFS1	Z9ES080C20SMPS1	26,200	\$3,668
214609048	COLEMAN	HH860E2S11	CTF60C5CHS1	Z9ES080C20SMPS1	37,200	\$5,208
214651877	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	Z9ES060B12SMPS1	18,400	\$2,576
214609185	COLEMAN	HH824E2S11	CTF36B5ADS1	Z9ES060B12SMPS1	18,400	\$2,576
214650007	COLEMAN	HH860E2S11	CTU60D5XGS1+TXV	Z9ES120D20SMPS1	34,400	\$4,816
214609200	COLEMAN	HH860E2S11	CTF60D5CGS1	Z9ES120D20SMPS1	34,400	\$4,816
215853367	COLEMAN	HH836E2S11	CTF36C5CDS1	Z9ES080C20SMPS1	28,600	\$4,004
214609195	COLEMAN	HH860E2S11	CTM60D5CHS1	Z9ES120D20SMPS1	37,000	\$5,180
214650630	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	Z9ES060B12SMPS1	17,900	\$2,506
214609097	COLEMAN	HH824E2S11	CTF30B5ACS1	Z9ES060B12SMPS1	17,900	\$2,506
214809270	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	Z9ES080C16SMPS1	33,200	\$4,648
214609116	COLEMAN	HH860E2S11	CTF60C5CGS1	Z9ES080C16SMPS1	33,200	\$4,648
215853363	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	Z9ES060B12SMPS1	27,600	\$3,864
215853364	COLEMAN	HH836E2S11	CTF36B5CDS1	Z9ES060B12SMPS1	27,600	\$3,864

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853359	COLEMAN	HH836E2S11	CTU36B5XDS1+TXV	Z9ES080B12SMPS1	27,800	\$3,892
215853360	COLEMAN	HH836E2S11	CTF36B5CDS1	Z9ES080B12SMPS1	27,800	\$3,892
214609136	COLEMAN	HH860E2S11	CTF60C5CHS1	Z9ES100C20SMPS1	37,200	\$5,208
214650086	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	Z9ES080B12SMPS1	17,900	\$2,506
214609068	COLEMAN	HH824E2S11	CTF30B5ACS1	Z9ES080B12SMPS1	17,900	\$2,506
214609170	COLEMAN	HH860E2S11	CTM60D5CGS1	Z9ES120D20SMPS1	34,400	\$4,816
215853361	COLEMAN	HH836E2S11	CTM36C5CDS1	Z9ES080C16SMPS1	27,600	\$3,864
214609077	COLEMAN	HH860E2S11	CTM60C5CHS1	Z9ES100C20SMPS1	37,200	\$5,208
214395392	COLEMAN	HH836E2S11	JHC36C5CD2SS1		26,600	\$3,724
214395404	COLEMAN	HH824E2S11	JHC24B5AC2SS1		18,400	\$2,576
214398191	COLEMAN	HH836E2S11	JHE42C5CF2SS1		25,800	\$3,612
216013292	COLEMAN	HH824E2S11	JHE36B5AD2SS1		18,200	\$2,548
214396658	COLEMAN	HH824E2S11	JHC36B5AD2SS1		18,400	\$2,576
214396215	COLEMAN	HH824E2S11	JHE30B5AD2SS1		17,700	\$2,478
216572156	COLEMAN	URC12CN15STG1	URD12HW15STG1		9,300	\$1,302
216572153	COLEMAN	URC24CN23STG1	UNI24HW23STG1		22,000	\$3,080
216572151	COLEMAN	URC18CN23STG1	UNI18HW23STG1		18,000	\$2,520
216572150	COLEMAN	URC12CN23STG1	UNI12HW23STG1		10,800	\$1,512
216411170	COLEMAN	HH824E2S11	CTF30A5ADS1	Z9ET040A10SMPS1	17,200	\$2,408
216374620	COLEMAN	HH860E2S11	CTM60D5CJS1	Z9ET120D20SMPS1	38,500	\$5,390
216374579	COLEMAN	HH860E2S11	CTF60D5CJS1	Z9ET120D20SMPS1	39,000	\$5,460
216374737	COLEMAN	HH860E2S11	CTU60D5XHS1+TXV	Z9ET120D20SMPS1	38,000	\$5,320
216374696	COLEMAN	HH860E2S11	CTF60D5CHS1	Z9ET120D20SMPS1	38,000	\$5,320
216374574	COLEMAN	HH860E2S11	CTM60C5CGS1	Z9ET100C20SMPS1	35,400	\$4,956
216374773	COLEMAN	HH860E2S11	CTM60C5CGS1	Z9ET100C16SMPS1	34,000	\$4,760
216374732	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	Z9ET100C16SMPS1	34,000	\$4,760
216374691	COLEMAN	HH860E2S11	CTF60C5CGS1	Z9ET100C16SMPS1	34,000	\$4,760
216374651	COLEMAN	HH860E2S11	CTM60D5CGS1	Z9ET120D20SMPS1	33,400	\$4,676
216374610	COLEMAN	HH860E2S11	CTU60D5XGS1+TXV	Z9ET120D20SMPS1	33,200	\$4,648
216374569	COLEMAN	HH860E2S11	CTF60D5CGS1	Z9ET120D20SMPS1	33,200	\$4,648
216374768	COLEMAN	HH860E2S11	CTM60C5CGS1	Z9ET080C16SMPS1	33,200	\$4,648
216374727	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	Z9ET080C16SMPS1	33,200	\$4,648
216374686	COLEMAN	HH860E2S11	CTF60C5CGS1	Z9ET080C16SMPS1	33,200	\$4,648
216374646	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	Z9ET100C20SMPS1	33,800	\$4,732
216374605	COLEMAN	HH860E2S11	CTF60C5CGS1	Z9ET100C20SMPS1	33,800	\$4,732
216374564	COLEMAN	HH824E2S11	CTM36B5ADS1	Z9ET060B12SMPS1	18,600	\$2,604
216374763	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	Z9ET080B12SMPS1	17,600	\$2,464
216374722	COLEMAN	HH824E2S11	CTF36B5ADS1	Z9ET080B12SMPS1	17,600	\$2,464

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216374681	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	Z9ET060B12SMPS1	18,600	\$2,604
216374641	COLEMAN	HH824E2S11	CTF36B5ADS1	Z9ET060B12SMPS1	18,600	\$2,604
216374600	COLEMAN	HH824E2S11	CTM36B5ADS1	Z9ET080B12SMPS1	17,500	\$2,450
216374559	COLEMAN	HH836E2S11	CTM48C5CFS1	Z9ET100C16SMPS1	26,000	\$3,640
216374758	COLEMAN	HH836E2S11	CTM48C5CFS1	Z9ET080C16SMPS1	29,000	\$4,060
216374717	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	Z9ET080C16SMPS1	29,000	\$4,060
216374676	COLEMAN	HH836E2S11	CTF48C5CFS1	Z9ET080C16SMPS1	29,000	\$4,060
216374636	COLEMAN	HH836E2S11	CTU48C5XFS1+TXV	Z9ET100C16SMPS1	27,600	\$3,864
216374595	COLEMAN	HH836E2S11	CTF48C5CFS1	Z9ET100C16SMPS1	27,600	\$3,864
216374585	COLEMAN	HH824E2S11	CTM30B5ACS1	Z9ET060B12SMPS1	18,000	\$2,520
216374544	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	Z9ET080B12SMPS1	17,900	\$2,506
216374743	COLEMAN	HH824E2S11	CTF30B5ACS1	Z9ET080B12SMPS1	17,900	\$2,506
216374702	COLEMAN	HH824E2S11	CTM30B5ACS1	Z9ET080B12SMPS1	17,900	\$2,506
216374661	COLEMAN	HH824E2S11	CTU30B5XCS1+TXV	Z9ET060B12SMPS1	17,900	\$2,506
216374621	COLEMAN	HH824E2S11	CTF30B5ACS1	Z9ET060B12SMPS1	17,900	\$2,506
213297443	COLEMAN	HMH72B341	XAFB36DBCN1	Z9ET060B12SMPS1	26,000	\$3,640
213297683	COLEMAN	HMH72B341	XAFC36DBCN1	Z9ET100C16SMPS1	26,600	\$3,724
213296788	COLEMAN	HMH72B341	XAHC36DBCN1	Z9ET100C16SMPS1	25,800	\$3,612
213297018	COLEMAN	HMH72B341	XAFB36DBCN1	Z9ET080B12SMPS1	25,800	\$3,612
213297248	COLEMAN	HMH72B341	XAFB36DBCN1	Z9ET040A10SMPS1	25,800	\$3,612
213297238	COLEMAN	HMH72B341	XAFC36DBCN1	Z9ET080B12SMPS1	25,800	\$3,612
213297693	COLEMAN	HMH72B341	XAFC36DBCN1	Z9ET060B12SMPS1	26,000	\$3,640
215912243	COLEMAN	HH824E2S11	CTM36B5ADS1	TM9E080B12MP12	18,500	\$2,590
216010735	COLEMAN	HH824E2S11	CTM36B5ADS1	TL9E060B12UH11	18,600	\$2,604
216010745	COLEMAN	HH824E2S11	CTM36B5ADS1+JMC12B2SN1		18,300	\$2,562
216010730	COLEMAN	HH824E2S11	CTM36B5ADS1+JME08B2SN1		17,600	\$2,464
216010750	COLEMAN	HH824E2S11	CTM36B5ADS1+JME12B2SN1		18,100	\$2,534
215912252	COLEMAN	HH824E2S11	CTM36B5ADS1	TM9Y080B12MP11	18,200	\$2,548
215912257	COLEMAN	HH824E2S11	CTM36B5ADS1	TM9E060B12MP12	18,000	\$2,520
215912250	COLEMAN	HH824E2S11	CTM36B5ADS1	TM9Y060B12MP11	17,600	\$2,464
215912229	COLEMAN	HH860E2S11	JSE48D5CG2SS1		33,600	\$4,704
215912258	COLEMAN	HH860E2S11	JSC48D5CG2SS1		33,600	\$4,704
214807732	COLEMAN	HH824E2S11	CTM36B5ADS1	CP9C060B12MP13	17,100	\$2,394
214807727	COLEMAN	HH824E2S11	CTM36B5ADS1	TP9C060B12MP13	17,100	\$2,394
214810232	COLEMAN	HH824E2S11	CTM36B5ADS1	TM9V060B12MP12	17,100	\$2,394

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214650218	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	Z9ES080B12SMPS1	18,300	\$2,562
214609215	COLEMAN	HH824E2S11	CTF36B5ADS1	Z9ES080B12SMPS1	18,300	\$2,562
214651277	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	CP9C060B12MP13	18,500	\$2,590
214651263	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TP9C060B12MP13	18,500	\$2,590
214397933	COLEMAN	HH824E2S11	CTF30A5ADS1	TM9E060A10MP12	17,700	\$2,478
214807744	COLEMAN	HH824E2S11	CTM36B5ADS1	CP9C080B12MP13	18,100	\$2,534
214807739	COLEMAN	HH824E2S11	CTM36B5ADS1	TP9C080B12MP13	18,100	\$2,534
214810226	COLEMAN	HH824E2S11	CTM36B5ADS1	TM9V080B12MP12	18,100	\$2,534
214397518	COLEMAN	HH824E2S11	CTF30A5ADS1	TM9E040A10MP12	17,600	\$2,464
214650930	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TMLE080B12MP11	18,400	\$2,576
214397538	COLEMAN	HH824E2S11	CTF36B5ADS1	TMLE080B12MP11	18,400	\$2,576
214651023	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	CP9C080B12MP13	18,100	\$2,534
214651009	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TP9C080B12MP13	18,100	\$2,534
214650996	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TM9V080B12MP12	18,100	\$2,534
214398367	COLEMAN	HH824E2S11	CTF36B5ADS1	CP9C080B12MP13	18,100	\$2,534
214398362	COLEMAN	HH824E2S11	CTF36B5ADS1	TP9C080B12MP13	18,100	\$2,534
214398357	COLEMAN	HH824E2S11	CTF36B5ADS1	TM9V080B12MP12	18,100	\$2,534
214650703	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TM9E080B12MP12	18,500	\$2,590
214397110	COLEMAN	HH824E2S11	CTF36B5ADS1	TM9E080B12MP12	18,500	\$2,590
214651385	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TM9Y080B12MP11	18,300	\$2,562
214396247	COLEMAN	HH824E2S11	CTF36B5ADS1	TM9Y080B12MP11	18,300	\$2,562
214396678	COLEMAN	HH824E2S11	CTF30A5ADS1	TMLE060A12MP11	18,300	\$2,562
214651248	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TM9V060B12MP12	18,500	\$2,590
214397958	COLEMAN	HH824E2S11	CTF36B5ADS1	CP9C060B12MP13	18,500	\$2,590
214397953	COLEMAN	HH824E2S11	CTF36B5ADS1	TP9C060B12MP13	18,500	\$2,590
214397948	COLEMAN	HH824E2S11	CTF36B5ADS1	TM9V060B12MP12	18,500	\$2,590
214397528	COLEMAN	HH824E2S11	CTF30A5ADS1	TM9V040A10MP12	17,300	\$2,422
214807725	COLEMAN	HH824E2S11	CTM36B5ADS1	CPLC080B12MP13	17,200	\$2,408
214807720	COLEMAN	HH824E2S11	CTM36B5ADS1	TPLC080B12MP13	17,200	\$2,408
214609156	COLEMAN	HH824E2S11	CTF30A5ADS1	Z9ES026A08SMPS1	17,700	\$2,478
214396232	COLEMAN	HH824E2S11	CTF30A5ADS1	TM9Y040A10MP11	17,600	\$2,464
214650359	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TM9Y060B12MP11	18,100	\$2,534
214396668	COLEMAN	HH824E2S11	CTF36B5ADS1	TM9Y060B12MP11	18,100	\$2,534
214807715	COLEMAN	HH824E2S11	CTU36B5XDS1+JME12B2SN 1+TXV		18,200	\$2,548
214397928	COLEMAN	HH824E2S11	CTF36B5ADS1+JME12B2SN 1		18,200	\$2,548
214650065	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TL9E060B12UH11	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396663	COLEMAN	HH824E2S11	CTF36B5ADS1	TL9E060B12UH11	18,600	\$2,604
214807700	COLEMAN	HH824E2S11	CTU36B5XDS1+JMC12B2SN1+TXV		18,200	\$2,548
214398347	COLEMAN	HH824E2S11	CTF36B5ADS1+JMC12B2SN1		18,200	\$2,548
214807695	COLEMAN	HH824E2S11	CTU36B5XDS1+JMV12BC2N1+TXV		18,200	\$2,548
214397923	COLEMAN	HH824E2S11	CTF36B5ADS1+JMV12BC2N1		18,200	\$2,548
214807690	COLEMAN	HH824E2S11	CTU36B5XDS1+JMET08BS2N1+TXV		17,400	\$2,436
214397095	COLEMAN	HH824E2S11	CTF36B5ADS1+JMET08BS2N1		17,400	\$2,436
214807685	COLEMAN	HH824E2S11	CTM36B5ADS1	TMLE080B12MP11	18,300	\$2,562
214397943	COLEMAN	HH824E2S11	CTF30A5ADS1	TMLE040A12MP11	18,100	\$2,534
214807710	COLEMAN	HH824E2S11	CTU36B5XDS1+JMET12BS2N1+TXV		17,700	\$2,478
214397523	COLEMAN	HH824E2S11	CTF36B5ADS1+JMET12BS2N1		17,700	\$2,478
214807705	COLEMAN	HH824E2S11	CTU36B5XDS1+JME08B2SN1+TXV		17,600	\$2,464
214397100	COLEMAN	HH824E2S11	CTF36B5ADS1+JME08B2SN1		17,600	\$2,464
214609126	COLEMAN	HH824E2S11	CTF30A5ADS1	Z9ES040A10SMPS1	17,200	\$2,408
214650210	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	CPLC080B12MP13	18,200	\$2,548
214650189	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TPLC080B12MP13	18,200	\$2,548
214396230	COLEMAN	HH824E2S11	CTF36B5ADS1	CPLC080B12MP13	18,200	\$2,548
214396225	COLEMAN	HH824E2S11	CTF36B5ADS1	TPLC080B12MP13	18,200	\$2,548
214397115	COLEMAN	HH824E2S11	CTF30A5ADS1	TM9E026A08MP12	17,900	\$2,506
214609102	COLEMAN	HH824E2S11	CTF30A5ADS1	Z9ES060A10SMPS1	18,200	\$2,548
214807734	COLEMAN	HH824E2S11	CTM36B5ADS1	TMLE100B12MP11	18,600	\$2,604
214609073	COLEMAN	HH824E2S11	CTM36B5ADS1	Z9ES080B12SMPS1	18,300	\$2,562
214651166	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TM9E060B12MP12	18,900	\$2,646
214396683	COLEMAN	HH824E2S11	CTF36B5ADS1	TM9E060B12MP12	18,900	\$2,646
214651442	COLEMAN	HH824E2S11	CTU36B5XDS1+TXV	TMLE100B12MP11	18,600	\$2,604
214396242	COLEMAN	HH824E2S11	CTF36B5ADS1	TMLE100B12MP11	18,600	\$2,604
214397864	COLEMAN	HH860E2S11	CTM60C5CGS1	TMLE120C16MP11	34,000	\$4,760
214720179	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TMLE120C16MP11	34,000	\$4,760
214397849	COLEMAN	HH860E2S11	CTF60C5CGS1	TMLE120C16MP11	34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214398627	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9Y080C16MP11	33,000	\$4,620
214720154	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TM9Y100C16MP11	33,000	\$4,620
214397397	COLEMAN	HH860E2S11	CTF60C5CGS1	TM9Y100C16MP11	33,000	\$4,620
214397015	COLEMAN	HH860E2S11	JHC48D5CG2SS1		33,600	\$4,704
214808993	COLEMAN	HH860E2S11	CTU60C5XGS1+JMET16CS2 N1+TXV		34,400	\$4,816
214397020	COLEMAN	HH860E2S11	CTF60C5CGS1+JMET16CS2 N1		34,400	\$4,816
214398671	COLEMAN	HH860E2S11	CTM60C5CGS1+JME16C2S N1		32,200	\$4,508
214809255	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TL9E100C20UH11	32,600	\$4,564
214397090	COLEMAN	HH860E2S11	CTF60C5CGS1	TL9E100C20UH11	32,600	\$4,564
214809265	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	Z9ES080C20SMPS1	32,600	\$4,564
214609111	COLEMAN	HH860E2S11	CTF60C5CGS1	Z9ES080C20SMPS1	32,600	\$4,564
214720129	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TM9E080C16MP12	34,200	\$4,788
214398332	COLEMAN	HH860E2S11	CTF60C5CGS1	TM9E080C16MP12	34,200	\$4,788
214398295	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9Y100C20MP11	35,000	\$4,900
214397065	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9E080C16MP12	34,200	\$4,788
214397906	COLEMAN	HH860E2S11	CTM60C5CGS1	CPLC120C20MP13	33,000	\$4,620
214397904	COLEMAN	HH860E2S11	CTM60C5CGS1	CPLC100C20MP13	33,000	\$4,620
214397899	COLEMAN	HH860E2S11	CTM60C5CGS1	TPLC120C20MP13	33,000	\$4,620
214397894	COLEMAN	HH860E2S11	CTM60C5CGS1	TPLC100C20MP13	33,000	\$4,620
214397889	COLEMAN	HH860E2S11	CTM60C5CGS1	TMLV120C20MP12	33,000	\$4,620
214397439	COLEMAN	HH860E2S11	CTM60C5CGS1	TMLE080C16MP11	34,200	\$4,788
214809025	COLEMAN	HH860E2S11	CTU60C5XGS1+JMC16C2S N1+TXV		33,600	\$4,704
214396579	COLEMAN	HH860E2S11	CTF60C5CGS1+JMC16C2S N1		33,600	\$4,704
214398676	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9E100C20MP12	33,200	\$4,648
214720164	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TMLE100C16MP11	34,200	\$4,788
214397424	COLEMAN	HH860E2S11	CTF60C5CGS1	TMLE100C16MP11	34,200	\$4,788
214720189	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TMLE080C16MP11	34,200	\$4,788
214397449	COLEMAN	HH860E2S11	CTF60C5CGS1	TMLE080C16MP11	34,200	\$4,788
214809157	COLEMAN	HH860E2S11	CTU60C5XGS1+JME16C2S N1+TXV		32,200	\$4,508
214398290	COLEMAN	HH860E2S11	CTF60C5CGS1+JME16C2SN 1		32,200	\$4,508
214398322	COLEMAN	HH860E2S11	CTM60D5CGS1+JMVT20DC 2N1		33,200	\$4,648

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214809152	COLEMAN	HH860E2S11	CTU60D5XGS1+JMC20D2S N1+TXV		34,600	\$4,844
214397854	COLEMAN	HH860E2S11	CTF60D5CGS1+JMC20D2S N1		34,600	\$4,844
214397832	COLEMAN	HH860E2S11	CTM60C5CGS1	CP9C080C16MP13	33,800	\$4,732
214397827	COLEMAN	HH860E2S11	CTM60C5CGS1	TP9C080C16MP13	33,800	\$4,732
214397822	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9V080C16MP12	33,800	\$4,732
214396557	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9Y100C16MP11	33,000	\$4,620
214719940	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TM9Y080C16MP11	33,000	\$4,620
214397010	COLEMAN	HH860E2S11	CTF60C5CGS1	TM9Y080C16MP11	33,000	\$4,620
214396589	COLEMAN	HH860E2S11	CTM60C5CGS1	TL9E080C16UH11	34,400	\$4,816
214719976	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TM9E100C16MP12	34,400	\$4,816
214398701	COLEMAN	HH860E2S11	CTF60C5CGS1	TM9E100C16MP12	34,400	\$4,816
214720199	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	CP9C100C20MP13	33,400	\$4,676
214720201	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TP9C100C20MP13	33,400	\$4,676
214720194	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TM9V100C20MP12	33,400	\$4,676
214398716	COLEMAN	HH860E2S11	CTF60C5CGS1	CP9C100C20MP13	33,400	\$4,676
214398711	COLEMAN	HH860E2S11	CTF60C5CGS1	TP9C100C20MP13	33,400	\$4,676
214398706	COLEMAN	HH860E2S11	CTF60C5CGS1	TM9V100C20MP12	33,400	\$4,676
214397484	COLEMAN	HH860E2S11	CTM60C5CGS1	CP9C100C20MP13	32,800	\$4,592
214397479	COLEMAN	HH860E2S11	CTM60C5CGS1	TP9C100C20MP13	32,800	\$4,592
214397474	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9V100C20MP12	32,800	\$4,592
214719883	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TMLE080C20MP11	33,600	\$4,704
214398305	COLEMAN	HH860E2S11	CTF60C5CGS1	TMLE080C20MP11	33,600	\$4,704
214397060	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9E100C16MP12	34,400	\$4,816
214720124	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TMLE120C20MP11	33,200	\$4,648
214397469	COLEMAN	HH860E2S11	CTF60C5CGS1	TMLE120C20MP11	33,200	\$4,648
214396604	COLEMAN	HH860E2S11	CTM60C5CGS1	TMLE120C20MP11	33,400	\$4,676
214397513	COLEMAN	HH860E2S11	CTM60C5CGS1	TL9E100C20UH11	32,600	\$4,564
214397402	COLEMAN	HH860E2S11	JHE48C5CG2SS1		32,200	\$4,508
214720206	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	Z9ES100C16SMPS1	34,200	\$4,788
214609087	COLEMAN	HH860E2S11	CTF60C5CGS1	Z9ES100C16SMPS1	34,200	\$4,788
214398696	COLEMAN	HH860E2S11	CTM60C5CGS1	TMLE100C20MP11	33,400	\$4,676
214720036	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	CP9C080C16MP13	32,600	\$4,564
214720038	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TP9C080C16MP13	32,600	\$4,564
214720031	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TM9V080C16MP12	32,600	\$4,564
214397506	COLEMAN	HH860E2S11	CTF60C5CGS1	CP9C080C16MP13	32,600	\$4,564
214397501	COLEMAN	HH860E2S11	CTF60C5CGS1	TP9C080C16MP13	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214397496	COLEMAN	HH860E2S11	CTF60C5CGS1	TM9V080C16MP12	32,600	\$4,564
214720114	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TMLE100C20MP11	33,400	\$4,676
214398686	COLEMAN	HH860E2S11	CTF60C5CGS1	TMLE100C20MP11	33,400	\$4,676
214396656	COLEMAN	HH860E2S11	CTM60C5CGS1	CPLC100C16MP13	32,800	\$4,592
214396654	COLEMAN	HH860E2S11	CTM60C5CGS1	CPLC080C16MP13	32,800	\$4,592
214396649	COLEMAN	HH860E2S11	CTM60C5CGS1	TPLC100C16MP13	32,800	\$4,592
214396644	COLEMAN	HH860E2S11	CTM60C5CGS1	TPLC080C16MP13	32,800	\$4,592
214396639	COLEMAN	HH860E2S11	CTM60C5CGS1	TMLV100C16MP12	32,800	\$4,592
214398632	COLEMAN	HH860E2S11	JHE48D5CG2SS1		33,200	\$4,648
214809194	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	CPLC100C16MP13	32,200	\$4,508
214809192	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	CPLC080C16MP13	32,200	\$4,508
214809187	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TPLC100C16MP13	32,200	\$4,508
214809182	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TPLC080C16MP13	32,200	\$4,508
214809177	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TMLV100C16MP12	32,200	\$4,508
214398664	COLEMAN	HH860E2S11	CTF60C5CGS1	CPLC100C16MP13	32,200	\$4,508
214398662	COLEMAN	HH860E2S11	CTF60C5CGS1	CPLC080C16MP13	32,200	\$4,508
214398657	COLEMAN	HH860E2S11	CTF60C5CGS1	TPLC100C16MP13	32,200	\$4,508
214398652	COLEMAN	HH860E2S11	CTF60C5CGS1	TPLC080C16MP13	32,200	\$4,508
214398647	COLEMAN	HH860E2S11	CTF60C5CGS1	TMLV100C16MP12	32,200	\$4,508
214649823	COLEMAN	HH860E2S11	CTU60D5XGS1+TXV	TMLE130D20MP11	36,200	\$5,068
214396624	COLEMAN	HH860E2S11	CTF60D5CGS1	TMLE130D20MP11	36,200	\$5,068
214396609	COLEMAN	HH860E2S11	CTM60D5CGS1+JMC20D2S N1		34,000	\$4,760
214397908	COLEMAN	HH860E2S11	CTM60C5CGS1+JMVT17CC 2N1		33,600	\$4,704
214809020	COLEMAN	HH860E2S11	CTU60D5XGS1+JMET18DS2 N1+TXV		34,200	\$4,788
214397839	COLEMAN	HH860E2S11	CTF60D5CGS1+JMET18DS2 N1		34,200	\$4,788
214421541	COLEMAN	HH860E2S11	CTM60D5CGS1+JMET18DS 2N1		34,000	\$4,760
214720169	COLEMAN	HH860E2S11	CTU60C5XGS1+TXV	TM9Y100C20MP11	33,600	\$4,704
214398236	COLEMAN	HH860E2S11	CTF60C5CGS1	TM9Y100C20MP11	33,600	\$4,704
214421531	COLEMAN	HH860E2S11	CTM60C5CGS1+JMET16CS 2N1		34,400	\$4,816
214808998	COLEMAN	HH860E2S11	CTU60C5XGS1+JMVT17CC2 N1+TXV		31,800	\$4,452
214397834	COLEMAN	HH860E2S11	CTF60C5CGS1+JMVT17CC2 N1		31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214809003	COLEMAN	HH860E2S11	CTU60C5XGS1+JMC17C2S N1+TXV		31,800	\$4,452
214398251	COLEMAN	HH860E2S11	CTF60C5CGS1+JMC17C2S N1		31,800	\$4,452
214397055	COLEMAN	HH860E2S11	CTM60C5CGS1	TMLE080C20MP11	33,600	\$4,704
214649901	COLEMAN	HH860E2S11	CTU60D5XGS1+TXV	TM9E120D20MP12	35,600	\$4,984
214397918	COLEMAN	HH860E2S11	CTF60D5CGS1	TM9E120D20MP12	35,600	\$4,984
214398320	COLEMAN	HH860E2S11	CTM60C5CGS1	CP9C100C16MP13	32,200	\$4,508
214398315	COLEMAN	HH860E2S11	CTM60C5CGS1	TP9C100C16MP13	32,200	\$4,508
214398310	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9V100C16MP12	32,200	\$4,508
214398327	COLEMAN	HH860E2S11	CTM60C5CGS1+JMC17C2S N1		33,000	\$4,620
214397085	COLEMAN	HH860E2S11	CTM60C5CGS1	TMLE100C16MP11	34,200	\$4,788
214809142	COLEMAN	HH860E2S11	CTU60C5XGS1+JMVT16CC2 N1+TXV		33,600	\$4,704
214397025	COLEMAN	HH860E2S11	CTF60C5CGS1+JMVT16CC2 N1		33,600	\$4,704
214398666	COLEMAN	HH860E2S11	CTM60C5CGS1+JMC16C2S N1		33,600	\$4,704
214398285	COLEMAN	HH860E2S11	CTM60C5CGS1+JMVT16CC 2N1		32,400	\$4,536
216013307	COLEMAN	HH824E2S11	CTM36B5ADS1+JMVT12BC2 N1		18,300	\$2,562
216013302	COLEMAN	HH824E2S11	CTM36B5ADS1+JMET12BS2 N1		17,600	\$2,464
216013297	COLEMAN	HH824E2S11	CTM36B5ADS1+JMET08BS2 N1		17,400	\$2,436
211387947	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TP9C080B12MP13	25,800	\$3,612
211387871	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TM9V080B12MP12	25,800	\$3,612
211387963	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	CP9C080B12MP13	25,800	\$3,612
211387921	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TM9V080B12MP12	25,800	\$3,612
211387901	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	CP9C080B12MP13	25,800	\$3,612
211387886	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TP9C080B12MP13	25,800	\$3,612
211388344	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211387001	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TM9V080B12MP11	25,800	\$3,612
211388375	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211388300	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211388390	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	CP9C060B12MP13	25,600	\$3,584
211388328	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	CP9C060B12MP13	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211387219	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TM9Y060B12MP11	25,600	\$3,584
211388315	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211387191	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TM9Y060B12MP11	25,600	\$3,584
211387029	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211387961	COLEMAN	HMH72B341	XAFB36DBCN1	CP9C080B12MP13	25,000	\$3,500
211387906	COLEMAN	HMH72B341	XAFB36DBCN1	TM9V080B12MP12	25,000	\$3,500
211387932	COLEMAN	HMH72B341	XAFB36DBCN1	TP9C080B12MP13	25,000	\$3,500
211719744	COLEMAN	HC20B2421	XAMB24DE1N1+CC	CPLC080B12MP13	23,000	\$3,220
211396395	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211396282	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9E080B12MP12	25,600	\$3,584
211396261	COLEMAN	HMH72B341	XAFC48FBCN1	TM9E080B12MP12	25,600	\$3,584
211396177	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9E080C16MP12	26,000	\$3,640
211396139	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9E080C16MP12	26,000	\$3,640
211396065	COLEMAN	HMH72B341	XAHD48FBCN1	TM9E080C16MP12	25,600	\$3,584
211396051	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TM9E080C16MP12	25,600	\$3,584
211395993	COLEMAN	HMH72B341	XAFD48FBCN1	TM9E100C16MP12	25,400	\$3,556
211395902	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211395849	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	CP9C060B12MP13	25,600	\$3,584
211395825	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211395626	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9V080B12MP12	25,600	\$3,584
211395571	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TP9C080B12MP13	25,600	\$3,584
211395549	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9V080B12MP12	25,600	\$3,584
211395424	COLEMAN	HMH72B341	XAFC48FBCN1	CP9C080C16MP13	25,400	\$3,556
211395311	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211395170	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211394991	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	CP9C100C16MP13	25,400	\$3,556
211394985	COLEMAN	HMH72B341	XAFC48FBCN1	CP9C100C16MP13	25,400	\$3,556
211394909	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211394890	COLEMAN	HMH72B341	XAFD48FBCN1	CP9C100C16MP13	25,400	\$3,556
211394806	COLEMAN	HMH72B341	XAHC48FBCN1	TP9C100C16MP13	24,800	\$3,472
211394791	COLEMAN	HMH72B341	XAHC48FBCN1	TM9V100C16MP12	24,800	\$3,472
211394683	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	CP9C100C20MP13	25,800	\$3,612
211394635	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9V100C20MP12	25,800	\$3,612
211394603	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TP9C100C20MP13	25,800	\$3,612
211394504	COLEMAN	HMH72B341	XAHC48FBCN1	TP9C100C20MP13	25,000	\$3,500
211394486	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	CP9C100C20MP13	25,000	\$3,500
211394391	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TM9V100C20MP12	25,200	\$3,528
211394339	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TP9C120D20MP13	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211394243	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9Y060B12MP11	25,800	\$3,612
211394216	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9Y060B12MP11	25,800	\$3,612
211394173	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211394147	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211394119	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9Y080B12MP11	25,400	\$3,556
211393866	COLEMAN	HMH72B341	XAHD48FBCN1	TM9Y100C16MP11	25,200	\$3,528
211393821	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9Y120D20MP11	25,400	\$3,556
211393629	COLEMAN	HMH72B341	JHETB36DBCS2N1		25,400	\$3,556
211393260	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TL9E060B12UH11	25,000	\$3,500
211393192	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TL9E060B12UH11	25,600	\$3,584
211393151	COLEMAN	HMH72B341	XAHC36DBCN1	TL9E060B12UH11	24,400	\$3,416
211393071	COLEMAN	HMH72B341	XAHC36DBCN1	TL9E080C16UH11	25,400	\$3,556
211393057	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TL9E080C16UH11	25,400	\$3,556
211389176	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TM9E060A10MP12	25,400	\$3,556
211389157	COLEMAN	HMH72B341	XAHB36DBCN1	TM9E060A10MP12	24,600	\$3,444
211389082	COLEMAN	HMH72B341	XAFB36DBCN1	TM9E060B12MP12	25,800	\$3,612
211388979	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TM9E060B12MP12	25,200	\$3,528
211388893	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TM9E080B12MP12	25,400	\$3,556
211388871	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TM9E080B12MP12	25,400	\$3,556
211388788	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TM9E080B12MP12	25,000	\$3,500
211388759	COLEMAN	HMH72B341	XAHC36DBCN1	TM9E080B12MP12	25,000	\$3,500
211388744	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9E080B12MP12	25,000	\$3,500
211388700	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9E080C16MP12	25,200	\$3,528
211388670	COLEMAN	HMH72B341	XAHC36DBCN1	TM9E080C16MP12	25,600	\$3,584
211388655	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9E080C16MP12	25,600	\$3,584
211388625	COLEMAN	HMH72B341	XAFC36DBCN1	TM9E100C16MP12	25,200	\$3,528
211388566	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9E100C16MP12	24,800	\$3,472
211388509	COLEMAN	HMH72B341	XAFB36DBCN1	TM9V040A10MP12	25,200	\$3,528
211388457	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TM9V040A10MP12	24,800	\$3,472
211388215	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211388180	COLEMAN	HMH72B341	XAHB36DBCN1	CP9C060B12MP13	25,000	\$3,500
211388166	COLEMAN	HMH72B341	XAHB36DBCN1	TP9C060B12MP13	25,000	\$3,500
211388117	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TM9V060B12MP12	25,000	\$3,500
211388066	COLEMAN	HMH72B341	XAHC36DBCN1	TP9C060B12MP13	25,200	\$3,528
211388027	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9V060B12MP12	25,200	\$3,528
211387768	COLEMAN	HMH72B341	XAHB36DBCN1	TP9C080B12MP13	25,200	\$3,528
211387700	COLEMAN	HMH72B341	XAHC36DBCN1	TM9V080B12MP12	25,000	\$3,500
211387656	COLEMAN	HMH72B341	XAFC36DBCN1	CP9C080C16MP13	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211387648	COLEMAN	HMH72B341	XAFC36DBCN1	TP9C080C16MP13	25,400	\$3,556
211387642	COLEMAN	HMH72B341	XAFC36DBCN1	TM9V080C16MP12	25,400	\$3,556
211387631	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211387622	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211387570	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TP9C080C16MP13	25,000	\$3,500
211387562	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9V080C16MP12	25,000	\$3,500
211387522	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	CP9C100C16MP13	25,400	\$3,556
211387509	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211387446	COLEMAN	HMH72B341	XAHC36DBCN1	TP9C100C16MP13	25,000	\$3,500
211387434	COLEMAN	HMH72B341	XAHC36DBCN1	TM9V100C16MP12	25,000	\$3,500
211387296	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9V100C20MP12	26,000	\$3,640
211387234	COLEMAN	HMH72B341	XAFB30CXXN1+TXV	TM9Y060B12MP11	26,600	\$3,724
211387178	COLEMAN	HMH72B341	XAFC30CXXN1+TXV	TM9Y060B12MP11	26,600	\$3,724
211387165	COLEMAN	HMH72B341	XAFC36DBCN1	TM9Y060B12MP11	25,600	\$3,584
211387070	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9Y060B12MP11	25,200	\$3,528
211386932	COLEMAN	HMH72B341	XAHB36DBCN1	TM9Y080B12MP11	24,800	\$3,472
211386916	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TM9Y080B12MP11	24,800	\$3,472
211386887	COLEMAN	HMH72B341	XAHC36DBCN1	TM9Y080B12MP11	25,400	\$3,556
211386874	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9Y080B12MP11	25,400	\$3,556
211386746	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9Y100C16MP11	25,800	\$3,612
211386666	COLEMAN	HMH72B341	JHETC42FBCS2N1		25,200	\$3,528
211386641	COLEMAN	HMH72B341	XAUC48FXXN1+JMET12CS2N1+TXV		25,400	\$3,556
211386615	COLEMAN	HMH72B341	XAFC48FXXN1+JMET12CS2N1+TXV		25,400	\$3,556
211386280	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TL9E080C16UH11	25,800	\$3,612
211386204	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TL9E080C16UH11	25,200	\$3,528
211386179	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TL9E080C16UH11	25,200	\$3,528
211386151	COLEMAN	HMH72B341	XAFC48FBCN1	TL9E100C20UH11	25,400	\$3,556
211386134	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TL9E100C20UH11	25,400	\$3,556
211386105	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TL9E100C20UH11	25,400	\$3,556
211386077	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TL9E100C20UH11	25,000	\$3,500
211386063	COLEMAN	HMH72B341	XAHD48FBCN1	TL9E100C20UH11	25,000	\$3,500
211212531	COLEMAN	HC20B6021	JHVVC60HE4C2N1+CC		48,000	\$6,720
211206970	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TPLC120C20MP13	41,500	\$5,810
211206965	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TPLC100C20MP13	41,500	\$5,810
211206926	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TM9V100C16MP12	41,500	\$5,810
211206919	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TP9C100C20MP13	41,500	\$5,810

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211206907	COLEMAN	HC20B6021	XAMC60HE4N1+CC	TP9C100C20MP13	47,000	\$6,580
211206902	COLEMAN	HC20B6021	XAMC60HE4N1+CC	TM9V100C20MP12	47,000	\$6,580
211206889	COLEMAN	HC20B3621	XAMB36DE2N1+CC	CP9C080B12MP13	34,600	\$4,844
211206877	COLEMAN	HC20B3621	XAMC36DE2N1+CC	CP9C080C16MP13	34,400	\$4,816
211206849	COLEMAN	HC20B2421	XAMB24DE1N1+CC	TPLC080B12MP13	23,000	\$3,220
211206842	COLEMAN	HC20B2421	XAMB24DE1N1+CC	CP9C060B12MP13	23,200	\$3,248
211396372	COLEMAN	HMH72B341	XAFC48FBCN1	TM9E060B12MP12	25,800	\$3,612
211396350	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211396304	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9E060B12MP12	25,200	\$3,528
211396217	COLEMAN	HMH72B341	XAHC48FBCN1	TM9E080B12MP12	25,000	\$3,500
211396162	COLEMAN	HMH72B341	XAFC48FBCN1	TM9E080C16MP12	26,000	\$3,640
211396126	COLEMAN	HMH72B341	XAFC48FBCN1	TM9E080C16MP12	26,000	\$3,640
211396080	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9E080C16MP12	25,600	\$3,584
211396009	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9E100C16MP12	25,400	\$3,556
211395951	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9E100C16MP12	24,800	\$3,472
211395918	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	CP9C060B12MP13	25,600	\$3,584
211395876	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211395858	COLEMAN	HMH72B341	XAFC48FBCN1	TM9V060B12MP12	25,600	\$3,584
211395752	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	CP9C060B12MP13	25,200	\$3,528
211395690	COLEMAN	HMH72B341	XAFC48FBCN1	CP9C080B12MP13	25,600	\$3,584
211395646	COLEMAN	HMH72B341	XAFC48FBCN1	TP9C080B12MP13	25,600	\$3,584
211395488	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	CP9C080B12MP13	25,200	\$3,528
211395468	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TP9C080B12MP13	25,200	\$3,528
211395445	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9V080B12MP12	25,200	\$3,528
211395343	COLEMAN	HMH72B341	XAFC48FBCN1	TM9V080C16MP12	25,400	\$3,556
211395334	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	CP9C080C16MP13	25,400	\$3,556
211395250	COLEMAN	HMH72B341	XAFC48FBCN1	TP9C080C16MP13	25,400	\$3,556
211395229	COLEMAN	HMH72B341	XAFC48FBCN1	TM9V080C16MP12	25,400	\$3,556
211395085	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TP9C080C16MP13	24,800	\$3,472
211394970	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211394923	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	CP9C100C16MP13	25,400	\$3,556
211394876	COLEMAN	HMH72B341	XAFC48FBCN1	TP9C100C16MP13	25,400	\$3,556
211394862	COLEMAN	HMH72B341	XAFC48FBCN1	TM9V100C16MP12	25,400	\$3,556
211394750	COLEMAN	HMH72B341	XAHD48FBCN1	CP9C100C16MP13	24,800	\$3,472
211394703	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TP9C100C16MP13	24,800	\$3,472
211394689	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TM9V100C16MP12	24,800	\$3,472
211394677	COLEMAN	HMH72B341	XAFC48FBCN1	CP9C100C20MP13	25,800	\$3,612
211394618	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	CP9C100C20MP13	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211394582	COLEMAN	HMH72B341	XAFD48FBCN1	CP9C100C20MP13	25,600	\$3,584
211394534	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TP9C100C20MP13	25,600	\$3,584
211394523	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TM9V100C20MP12	25,600	\$3,584
211394473	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TP9C100C20MP13	25,000	\$3,500
211394452	COLEMAN	HMH72B341	XAHD48FBCN1	CP9C100C20MP13	25,200	\$3,528
211394422	COLEMAN	HMH72B341	XAHD48FBCN1	TM9V100C20MP12	25,200	\$3,528
211394404	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TP9C100C20MP13	25,200	\$3,528
211394385	COLEMAN	HMH72B341	XAFD48FBCN1	CP9C120D20MP13	25,400	\$3,556
211394325	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TM9V120D20MP12	25,400	\$3,556
211394288	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	CP9C120D20MP13	24,800	\$3,472
211394258	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TM9V120D20MP12	24,800	\$3,472
211394188	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9Y060B12MP11	25,400	\$3,556
211394104	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9Y080C16MP11	25,800	\$3,612
211394061	COLEMAN	HMH72B341	XAFD48FBCN1	TM9Y080C16MP11	25,400	\$3,556
211394046	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TM9Y080C16MP11	25,400	\$3,556
211394031	COLEMAN	HMH72B341	XAHC48FBCN1	TM9Y080C16MP11	25,200	\$3,528
211394016	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9Y080C16MP11	25,200	\$3,528
211393971	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9Y100C16MP11	25,800	\$3,612
211393896	COLEMAN	HMH72B341	XAHC48FBCN1	TM9Y100C16MP11	25,200	\$3,528
211393851	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TM9Y100C16MP11	25,200	\$3,528
211393616	COLEMAN	HMH72B341	JHVTB36DBCC2N1		25,200	\$3,528
211389038	COLEMAN	HMH72B341	XAFC36DBCN1	TM9E060B12MP12	25,800	\$3,612
211388714	COLEMAN	HMH72B341	XAFC36DBCN1	TM9E080C16MP12	25,200	\$3,528
211388581	COLEMAN	HMH72B341	XAHC36DBCN1	TM9E100C16MP12	24,800	\$3,472
211388514	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TM9V040A10MP12	25,200	\$3,528
211388384	COLEMAN	HMH72B341	XAFB36DBCN1	CP9C060B12MP13	25,400	\$3,556
211388247	COLEMAN	HMH72B341	XAFC36DBCN1	TP9C060B12MP13	25,600	\$3,584
211388233	COLEMAN	HMH72B341	XAFC36DBCN1	TM9V060B12MP12	25,600	\$3,584
211388229	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	CP9C060B12MP13	25,600	\$3,584
211388151	COLEMAN	HMH72B341	XAHB36DBCN1	TM9V060B12MP12	25,000	\$3,500
211388132	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TP9C060B12MP13	25,000	\$3,500
211388052	COLEMAN	HMH72B341	XAHC36DBCN1	TM9V060B12MP12	25,200	\$3,528
211387831	COLEMAN	HMH72B341	XAFC36DBCN1	TP9C080B12MP13	25,800	\$3,612
211387817	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	CP9C080B12MP13	25,800	\$3,612
211387760	COLEMAN	HMH72B341	XAHB36DBCN1	TM9V080B12MP12	25,200	\$3,528
211387756	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	CP9C080B12MP13	25,200	\$3,528
211387740	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TM9V080B12MP12	25,200	\$3,528
211387688	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TP9C080B12MP13	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211387600	COLEMAN	HMH72B341	XAHC36DBCN1	CP9C080C16MP13	25,000	\$3,500
211387591	COLEMAN	HMH72B341	XAHC36DBCN1	TP9C080C16MP13	25,000	\$3,500
211387429	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	CP9C100C16MP13	25,000	\$3,500
211387413	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TP9C100C16MP13	25,000	\$3,500
211387361	COLEMAN	HMH72B341	XAFC36DBCN1	CP9C100C20MP13	26,000	\$3,640
211387330	COLEMAN	HMH72B341	XAFC36DBCN1	TM9V100C20MP12	26,000	\$3,640
211387323	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	CP9C100C20MP13	26,000	\$3,640
211387121	COLEMAN	HMH72B341	XAHC36DBCN1	TM9Y060B12MP11	25,000	\$3,500
211387083	COLEMAN	HMH72B341	XAHC36DBCN1	TM9Y060B12MP11	25,200	\$3,528
211386987	COLEMAN	HMH72B341	XAFC30CXXN1+TXV	TM9Y080B12MP11	26,800	\$3,752
211386805	COLEMAN	HMH72B341	XAHC36DBCN1	TM9Y080C16MP11	25,400	\$3,556
211386708	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9Y100C16MP11	25,400	\$3,556
211386627	COLEMAN	HMH72B341	XAFC48FBCN1+JMET12CS2 N1		25,400	\$3,556
211386601	COLEMAN	HMH72B341	XAHC48FBCN1+JMET12CS2 N1		24,800	\$3,472
211386332	COLEMAN	HMH72B341	XAFC48FBCN1	TL9E060B12UH11	25,800	\$3,612
211386321	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TL9E060B12UH11	25,800	\$3,612
211386308	COLEMAN	HMH72B341	XAHC48FBCN1	TL9E060B12UH11	25,200	\$3,528
211386252	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TL9E080C16UH11	25,800	\$3,612
211386240	COLEMAN	HMH72B341	XAFC48FBCN1	TL9E080C16UH11	25,600	\$3,584
211386227	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TL9E080C16UH11	25,600	\$3,584
211386119	COLEMAN	HMH72B341	XAFC48FBCN1	TL9E100C20UH11	25,400	\$3,556
211207005	COLEMAN	HC20B4821	XAMC48HE3N1+CC	CPLC100C16MP13	41,500	\$5,810
211206993	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TPLC080C16MP13	41,500	\$5,810
211206938	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TM9V080C16MP12	41,500	\$5,810
211206936	COLEMAN	HC20B4821	XAMC48HE3N1+CC	CP9C100C16MP13	41,500	\$5,810
211206924	COLEMAN	HC20B4821	XAMC48HE3N1+CC	CP9C100C20MP13	41,500	\$5,810
211010194	COLEMAN	HC20B6021	JHVVD60HE4C2N1+CC		46,500	\$6,510
211396328	COLEMAN	HMH72B341	XAHC48FBCN1	TM9E060B12MP12	25,200	\$3,528
211396197	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9E080B12MP12	25,000	\$3,500
211395731	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TP9C060B12MP13	25,200	\$3,528
211395161	COLEMAN	HMH72B341	XAHC48FBCN1	CP9C080C16MP13	24,800	\$3,472
211395042	COLEMAN	HMH72B341	XAHD48FBCN1	TP9C080C16MP13	25,000	\$3,500
211394437	COLEMAN	HMH72B341	XAHD48FBCN1	TP9C100C20MP13	25,200	\$3,528
211393956	COLEMAN	HMH72B341	XAFC48FBCN1	TM9Y100C16MP11	25,800	\$3,612
211392982	COLEMAN	HMH72B341	XAHC36DBCN1	TL9E100C20UH11	25,600	\$3,584
211386957	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211387015	COLEMAN	HMH72B341	XAFB36DBCN1	TM9Y080B12MP11	25,200	\$3,528
211719745	COLEMAN	HC20B4821	XAMC48HE3N1+CC	CPLC100C20MP13	41,500	\$5,810
211719706	COLEMAN	HC20B3621	XAMB36DE2N1+CC	CPLC080B12MP13	34,600	\$4,844
211397468	COLEMAN	HMH72B341	XAHC48FBCN1	TMLV100C16MP12	25,400	\$3,556
211396095	COLEMAN	HMH72B341	XAHC48FBCN1	TM9E080C16MP12	25,600	\$3,584
211396036	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9E100C16MP12	25,400	\$3,556
211396024	COLEMAN	HMH72B341	XAFC48FBCN1	TM9E100C16MP12	25,400	\$3,556
211395965	COLEMAN	HMH72B341	XAHC48FBCN1	TM9E100C16MP12	24,800	\$3,472
211395914	COLEMAN	HMH72B341	XAFC48FBCN1	CP9C060B12MP13	25,600	\$3,584
211395798	COLEMAN	HMH72B341	XAHC48FBCN1	CP9C060B12MP13	25,200	\$3,528
211395781	COLEMAN	HMH72B341	XAHC48FBCN1	TP9C060B12MP13	25,200	\$3,528
211395711	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9V060B12MP12	25,200	\$3,528
211395701	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	CP9C080B12MP13	25,600	\$3,584
211395602	COLEMAN	HMH72B341	XAFC48FBCN1	TM9V080B12MP12	25,600	\$3,584
211395595	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	CP9C080B12MP13	25,600	\$3,584
211395435	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	CP9C080C16MP13	25,400	\$3,556
211395402	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211395381	COLEMAN	HMH72B341	XAFC48FBCN1	TP9C080C16MP13	25,400	\$3,556
211395285	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211395275	COLEMAN	HMH72B341	XAFD48FBCN1	CP9C080C16MP13	25,400	\$3,556
211395219	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	CP9C080C16MP13	25,400	\$3,556
211395138	COLEMAN	HMH72B341	XAHC48FBCN1	TP9C080C16MP13	24,800	\$3,472
211395113	COLEMAN	HMH72B341	XAHC48FBCN1	TM9V080C16MP12	24,800	\$3,472
211395065	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9V080C16MP12	24,800	\$3,472
211394996	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TM9V080C16MP12	25,000	\$3,500
211394955	COLEMAN	HMH72B341	XAFC48FBCN1	TP9C100C16MP13	25,400	\$3,556
211394941	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211394929	COLEMAN	HMH72B341	XAFC48FBCN1	TM9V100C16MP12	25,400	\$3,556
211394841	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211394756	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9V100C16MP12	24,800	\$3,472
211394735	COLEMAN	HMH72B341	XAHD48FBCN1	TP9C100C16MP13	24,800	\$3,472
211394721	COLEMAN	HMH72B341	XAHD48FBCN1	TM9V100C16MP12	24,800	\$3,472
211394716	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	CP9C100C16MP13	24,800	\$3,472
211394662	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TP9C100C20MP13	25,800	\$3,612
211394624	COLEMAN	HMH72B341	XAFC48FBCN1	TM9V100C20MP12	25,800	\$3,612
211394588	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9V100C20MP12	25,800	\$3,612
211394567	COLEMAN	HMH72B341	XAFD48FBCN1	TP9C100C20MP13	25,600	\$3,584
211394554	COLEMAN	HMH72B341	XAFD48FBCN1	TM9V100C20MP12	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211394492	COLEMAN	HMH72B341	XAHC48FBCN1	TM9V100C20MP12	25,000	\$3,500
211394458	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9V100C20MP12	25,000	\$3,500
211394360	COLEMAN	HMH72B341	XAFD48FBCN1	TM9V120D20MP12	25,400	\$3,556
211394353	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	CP9C120D20MP13	25,400	\$3,556
211394320	COLEMAN	HMH72B341	XAHD48FBCN1	CP9C120D20MP13	24,800	\$3,472
211394308	COLEMAN	HMH72B341	XAHD48FBCN1	TP9C120D20MP13	24,800	\$3,472
211394231	COLEMAN	HMH72B341	XAFC48FBCN1	TM9Y060B12MP11	25,800	\$3,612
211394203	COLEMAN	HMH72B341	XAHC48FBCN1	TM9Y060B12MP11	25,400	\$3,556
211394076	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9Y080C16MP11	25,800	\$3,612
211394001	COLEMAN	HMH72B341	XAHD48FBCN1	TM9Y080C16MP11	25,000	\$3,500
211393986	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TM9Y080C16MP11	25,000	\$3,500
211393941	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9Y100C16MP11	25,800	\$3,612
211393926	COLEMAN	HMH72B341	XAFD48FBCN1	TM9Y100C16MP11	25,400	\$3,556
211393836	COLEMAN	HMH72B341	XAFD48FBCN1	TM9Y120D20MP11	25,400	\$3,556
211393806	COLEMAN	HMH72B341	XAHD48FBCN1	TM9Y120D20MP11	25,000	\$3,500
211393791	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TM9Y120D20MP11	25,000	\$3,500
211393602	COLEMAN	HMH72B341	JHVTC36DBCC2N1		25,400	\$3,556
211393237	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TL9E060B12UH11	25,000	\$3,500
211393136	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TL9E060B12UH11	24,400	\$3,416
211393028	COLEMAN	HMH72B341	XAFC36DBCN1	TL9E100C20UH11	26,200	\$3,668
211393012	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TL9E100C20UH11	26,200	\$3,668
211392967	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TL9E100C20UH11	25,600	\$3,584
211389205	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TM9E060A10MP12	25,400	\$3,556
211389142	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TM9E060A10MP12	24,600	\$3,444
211389023	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211388953	COLEMAN	HMH72B341	XAHC36DBCN1	TM9E060B12MP12	25,200	\$3,528
211388886	COLEMAN	HMH72B341	XAFB36DBCN1	TM9E080B12MP12	25,400	\$3,556
211388841	COLEMAN	HMH72B341	XAFC36DBCN1	TM9E080B12MP12	25,800	\$3,612
211388826	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9E080B12MP12	25,800	\$3,612
211388798	COLEMAN	HMH72B341	XAHB36DBCN1	TM9E080B12MP12	25,000	\$3,500
211388495	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TM9V040A10MP12	25,200	\$3,528
211388360	COLEMAN	HMH72B341	XAFB36DBCN1	TP9C060B12MP13	25,400	\$3,556
211388146	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	CP9C060B12MP13	25,000	\$3,500
211387821	COLEMAN	HMH72B341	XAFC36DBCN1	TM9V080B12MP12	25,800	\$3,612
211387777	COLEMAN	HMH72B341	XAHB36DBCN1	CP9C080B12MP13	25,200	\$3,528
211387716	COLEMAN	HMH72B341	XAHC36DBCN1	CP9C080B12MP13	25,000	\$3,500
211387708	COLEMAN	HMH72B341	XAHC36DBCN1	TP9C080B12MP13	25,000	\$3,500
211387680	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9V080B12MP12	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211387583	COLEMAN	HMH72B341	XAHC36DBCN1	TM9V080C16MP12	25,000	\$3,500
211387536	COLEMAN	HMH72B341	XAFC36DBCN1	TP9C100C16MP13	25,400	\$3,556
211387528	COLEMAN	HMH72B341	XAFC36DBCN1	TM9V100C16MP12	25,400	\$3,556
211387401	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9V100C16MP12	25,000	\$3,500
211387346	COLEMAN	HMH72B341	XAFC36DBCN1	TP9C100C20MP13	26,000	\$3,640
211387310	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TP9C100C20MP13	26,000	\$3,640
211387248	COLEMAN	HMH72B341	XAUB30CXXN1+TXV	TM9Y060B12MP11	26,600	\$3,724
211387108	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TM9Y060B12MP11	25,000	\$3,500
211387057	COLEMAN	HMH72B341	XAUB30CXXN1+TXV	TM9Y080B12MP11	26,800	\$3,752
211387044	COLEMAN	HMH72B341	XAFB30CXXN1+TXV	TM9Y080B12MP11	26,800	\$3,752
211386833	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9Y080C16MP11	25,800	\$3,612
211386789	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9Y080C16MP11	25,400	\$3,556
211386759	COLEMAN	HMH72B341	XAFC36DBCN1	TM9Y100C16MP11	25,800	\$3,612
211386694	COLEMAN	HMH72B341	XAHC36DBCN1	TM9Y100C20MP11	25,600	\$3,584
211386680	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9Y100C20MP11	25,600	\$3,584
211386653	COLEMAN	HMH72B341	JHVTC42FBCC2N1		25,000	\$3,500
211386293	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TL9E060B12UH11	25,200	\$3,528
211386214	COLEMAN	HMH72B341	XAHC48FBCN1	TL9E080C16UH11	25,200	\$3,528
211386196	COLEMAN	HMH72B341	XAHD48FBCN1	TL9E080C16UH11	25,200	\$3,528
211386091	COLEMAN	HMH72B341	XAHC48FBCN1	TL9E100C20UH11	25,000	\$3,500
211207003	COLEMAN	HC20B4821	XAMC48HE3N1+CC	CPLC080C16MP13	41,500	\$5,810
211206988	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TMLV100C16MP12	41,500	\$5,810
211206960	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TMLV120C20MP12	41,500	\$5,810
211206943	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TP9C080C16MP13	41,500	\$5,810
211206912	COLEMAN	HC20B6021	XAMC60HE4N1+CC	CP9C100C20MP13	47,000	\$6,580
211206896	COLEMAN	HC20B3621	XAMB36DE2N1+CC	TPLC080B12MP13	34,600	\$4,844
211206884	COLEMAN	HC20B3621	XAMB36DE2N1+CC	TP9C080B12MP13	34,600	\$4,844
211206872	COLEMAN	HC20B3621	XAMC36DE2N1+CC	TP9C080C16MP13	34,400	\$4,816
211206865	COLEMAN	HC20B3621	XAMC36DE2N1+CC	CP9C100C16MP13	34,400	\$4,816
211206855	COLEMAN	HC20B3621	XAMC36DE2N1+CC	TM9V100C16MP12	34,400	\$4,816
211206837	COLEMAN	HC20B2421	XAMB24DE1N1+CC	TP9C060B12MP13	23,200	\$3,248
211010182	COLEMAN	HC20B2421	JHVVB24DE1C2N1+CC		22,800	\$3,192
211010178	COLEMAN	HC20B4821	JHVVC48HE3C2N1+CC		43,500	\$6,090
211398568	COLEMAN	HMH72B341	XAFC48FBCN1	TMLE100C16MP11	25,400	\$3,556
211396238	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9E080B12MP12	25,600	\$3,584
211396111	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TM9E080C16MP12	26,000	\$3,640
211395979	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TM9E100C16MP12	25,400	\$3,556
211395939	COLEMAN	HMH72B341	XAHD48FBCN1	TM9E100C16MP12	24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211395924	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TM9E100C16MP12	24,800	\$3,472
211395891	COLEMAN	HMH72B341	XAFC48FBCN1	TP9C060B12MP13	25,600	\$3,584
211395804	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211395761	COLEMAN	HMH72B341	XAHC48FBCN1	TM9V060B12MP12	25,200	\$3,528
211395670	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TP9C080B12MP13	25,600	\$3,584
211395539	COLEMAN	HMH72B341	XAHC48FBCN1	CP9C080B12MP13	25,200	\$3,528
211395514	COLEMAN	HMH72B341	XAHC48FBCN1	TP9C080B12MP13	25,200	\$3,528
211395496	COLEMAN	HMH72B341	XAHC48FBCN1	TM9V080B12MP12	25,200	\$3,528
211395362	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211395195	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211395106	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	CP9C080C16MP13	24,800	\$3,472
211395055	COLEMAN	HMH72B341	XAHD48FBCN1	CP9C080C16MP13	25,000	\$3,500
211395030	COLEMAN	HMH72B341	XAHD48FBCN1	TM9V080C16MP12	25,000	\$3,500
211395024	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	CP9C080C16MP13	25,000	\$3,500
211395010	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TP9C080C16MP13	25,000	\$3,500
211394895	COLEMAN	HMH72B341	XAFC48FXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211394856	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	CP9C100C16MP13	25,400	\$3,556
211394827	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211394821	COLEMAN	HMH72B341	XAHC48FBCN1	CP9C100C16MP13	24,800	\$3,472
211394785	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	CP9C100C16MP13	24,800	\$3,472
211394770	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TP9C100C16MP13	24,800	\$3,472
211394650	COLEMAN	HMH72B341	XAFC48FBCN1	TP9C100C20MP13	25,800	\$3,612
211394548	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	CP9C100C20MP13	25,600	\$3,584
211394517	COLEMAN	HMH72B341	XAHC48FBCN1	CP9C100C20MP13	25,000	\$3,500
211394416	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	CP9C100C20MP13	25,200	\$3,528
211394370	COLEMAN	HMH72B341	XAFD48FBCN1	TP9C120D20MP13	25,400	\$3,556
211394294	COLEMAN	HMH72B341	XAHD48FBCN1	TM9V120D20MP12	24,800	\$3,472
211394273	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TP9C120D20MP13	24,800	\$3,472
211394160	COLEMAN	HMH72B341	XAFC48FBCN1	TM9Y080B12MP11	25,800	\$3,612
211394132	COLEMAN	HMH72B341	XAHC48FBCN1	TM9Y080B12MP11	25,400	\$3,556
211394091	COLEMAN	HMH72B341	XAFC48FBCN1	TM9Y080C16MP11	25,800	\$3,612
211393911	COLEMAN	HMH72B341	XAFD48FXXN1+TXV	TM9Y100C16MP11	25,400	\$3,556
211393881	COLEMAN	HMH72B341	XAHC48FXXN1+TXV	TM9Y100C16MP11	25,200	\$3,528
211393249	COLEMAN	HMH72B341	XAFB36DBCN1	TL9E060B12UH11	25,000	\$3,500
211393207	COLEMAN	HMH72B341	XAFC36DBCN1	TL9E060B12UH11	25,600	\$3,584
211393106	COLEMAN	HMH72B341	XAFC36DBCN1	TL9E080C16UH11	25,800	\$3,612
211393091	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TL9E080C16UH11	25,800	\$3,612
211391350	COLEMAN	HMH72B341	XAFC36DBCN1	TMLE120C16MP11	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211389190	COLEMAN	HMH72B341	XAFB36DBCN1	TM9E060A10MP12	25,400	\$3,556
211389097	COLEMAN	HMH72B341	XAUB36DXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211389068	COLEMAN	HMH72B341	XAFB36DXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211388994	COLEMAN	HMH72B341	XAHB36DBCN1	TM9E060B12MP12	25,200	\$3,528
211388938	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9E060B12MP12	25,200	\$3,528
211388611	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9E100C16MP12	25,200	\$3,528
211388556	COLEMAN	HMH72B341	XAHC36DBCN1	TM9E100C20MP12	25,000	\$3,500
211388548	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TM9E100C20MP12	25,000	\$3,500
211388468	COLEMAN	HMH72B341	XAHB36DBCN1	TM9V040A10MP12	24,800	\$3,472
211388335	COLEMAN	HMH72B341	XAFB36DBCN1	TM9V060B12MP12	25,400	\$3,556
211388261	COLEMAN	HMH72B341	XAFC36DBCN1	CP9C060B12MP13	25,600	\$3,584
211388224	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211388080	COLEMAN	HMH72B341	XAHC36DBCN1	CP9C060B12MP13	25,200	\$3,528
211388047	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	CP9C060B12MP13	25,200	\$3,528
211388032	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	TP9C060B12MP13	25,200	\$3,528
211387837	COLEMAN	HMH72B341	XAFC36DBCN1	CP9C080B12MP13	25,800	\$3,612
211387809	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TP9C080B12MP13	25,800	\$3,612
211387800	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9V080B12MP12	25,800	\$3,612
211387748	COLEMAN	HMH72B341	XAHB36DXXN1+TXV	TP9C080B12MP13	25,200	\$3,528
211387696	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	CP9C080B12MP13	25,000	\$3,500
211387639	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	CP9C080C16MP13	25,400	\$3,556
211387579	COLEMAN	HMH72B341	XAHC36DXXN1+TXV	CP9C080C16MP13	25,000	\$3,500
211387543	COLEMAN	HMH72B341	XAFC36DBCN1	CP9C100C16MP13	25,400	\$3,556
211387496	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211387459	COLEMAN	HMH72B341	XAHC36DBCN1	CP9C100C16MP13	25,000	\$3,500
211387148	COLEMAN	HMH72B341	XAFC36DXXN1+TXV	TM9Y060B12MP11	25,600	\$3,584
211386972	COLEMAN	HMH72B341	XAFC36DBCN1	TM9Y080B12MP11	25,800	\$3,612
211386849	COLEMAN	HMH72B341	XAFC36DBCN1	TM9Y080C16MP11	25,800	\$3,612
211386721	COLEMAN	HMH72B341	XAHC36DBCN1	TM9Y100C16MP11	25,400	\$3,556
211386587	COLEMAN	HMH72B341	XAHC48FXXN1+JMET12CS2 N1+TXV		24,800	\$3,472
211386344	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TL9E060B12UH11	25,800	\$3,612
211386265	COLEMAN	HMH72B341	XAFC48FBCN1	TL9E080C16UH11	25,800	\$3,612
211386165	COLEMAN	HMH72B341	XAUC48FXXN1+TXV	TL9E100C20UH11	25,400	\$3,556
211386048	COLEMAN	HMH72B341	XAHD48FXXN1+TXV	TL9E100C20UH11	25,000	\$3,500
211206998	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TPLC100C16MP13	41,500	\$5,810
211206976	COLEMAN	HC20B4821	XAMC48HE3N1+CC	CPLC120C20MP13	41,500	\$5,810
211206948	COLEMAN	HC20B4821	XAMC48HE3N1+CC	CP9C080C16MP13	41,500	\$5,810

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211206931	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TP9C100C16MP13	41,500	\$5,810
211206914	COLEMAN	HC20B4821	XAMC48HE3N1+CC	TM9V100C20MP12	41,500	\$5,810
211206879	COLEMAN	HC20B3621	XAMB36DE2N1+CC	TM9V080B12MP12	34,600	\$4,844
211206867	COLEMAN	HC20B3621	XAMC36DE2N1+CC	TM9V080C16MP12	34,400	\$4,816
211206860	COLEMAN	HC20B3621	XAMC36DE2N1+CC	TP9C100C16MP13	34,400	\$4,816
211206832	COLEMAN	HC20B2421	XAMB24DE1N1+CC	TM9V060B12MP12	23,200	\$3,248
211387205	COLEMAN	HMH72B341	XAFB36DBCN1	TM9Y060B12MP11	25,200	\$3,528
211010190	COLEMAN	HC20B3621	JHVVB36DE2C2N1+CC		35,800	\$5,012
214609210	COLEMAN	HH824E2S11	CTM30B5ACS1	Z9ES080B12SMPS1	18,400	\$2,576
214396993	COLEMAN	HH836E2S11	CTF48C5CFS1	CPLC100C16MP13	26,000	\$3,640
214396991	COLEMAN	HH836E2S11	CTF48C5CFS1	CPLC080C16MP13	26,000	\$3,640
214396986	COLEMAN	HH836E2S11	CTF48C5CFS1	TPLC100C16MP13	26,000	\$3,640
214396981	COLEMAN	HH836E2S11	CTF48C5CFS1	TPLC080C16MP13	26,000	\$3,640
214396976	COLEMAN	HH836E2S11	CTF48C5CFS1	TMLV100C16MP12	26,000	\$3,640
214396369	COLEMAN	HH860E2S11	CTF60D5CJS1	CP9C120D20MP13	38,000	\$5,320
214396364	COLEMAN	HH860E2S11	CTF60D5CJS1	TP9C120D20MP13	38,000	\$5,320
214396359	COLEMAN	HH860E2S11	CTF60D5CJS1	TM9V120D20MP12	38,000	\$5,320
214396354	COLEMAN	HH860E2S11	CTM60D5CJS1+JMC20D2SN1		37,000	\$5,180
214396347	COLEMAN	HH860E2S11	CTM60C5CHS1	CP9C100C20MP13	37,000	\$5,180
214396342	COLEMAN	HH860E2S11	CTM60C5CHS1	TP9C100C20MP13	37,000	\$5,180
214396337	COLEMAN	HH860E2S11	CTM60C5CHS1	TM9V100C20MP12	37,000	\$5,180
214398017	COLEMAN	HH860E2S11	CTF60C5CHS1	TMLE080C20MP11	38,000	\$5,320
214397264	COLEMAN	HH836E2S11	CTF36C5CDS1	TM9Y100C16MP11	27,400	\$3,836
214398120	COLEMAN	HH836E2S11	CTM36B5CDS1	CPLC080B12MP13	26,800	\$3,752
214398115	COLEMAN	HH836E2S11	CTM36B5CDS1	TPLC080B12MP13	26,800	\$3,752
214396961	COLEMAN	HH836E2S11	CTM48C5CFS1	TMLE120C16MP11	26,000	\$3,640
214396926	COLEMAN	HH836E2S11	CTM48C5CFS1	TMLE080C16MP11	26,000	\$3,640
214397637	COLEMAN	HH860E2S11	CTF60D5CJS1	TM9E120D20MP12	37,400	\$5,236
214421516	COLEMAN	HH860E2S11	CTF60D5CJS1+JMV20DC2N1		37,000	\$5,180
214397627	COLEMAN	HH860E2S11	CTM60C5CHS1	TMLE120C20MP11	37,400	\$5,236
214651091	COLEMAN	HH860E2S11	CTU60D5XHS1+TXV	TMLE130D20MP11	38,000	\$5,320
214397491	COLEMAN	HH860E2S11	CTM60C5CGS1	TM9E080C20MP12	35,800	\$5,012
213298103	COLEMAN	HMH72B341	XAFB36DBCN1+JMET12BS2N1		25,200	\$3,528
213297418	COLEMAN	HMH72B341	XAFB36DBCN1+JMV212BC2N1		25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213297218	COLEMAN	HMH72B341	XAHC36DBCN1+JMET12CS2N1		24,600	\$3,444
213297843	COLEMAN	HMH72B341	XAHB36DBCN1+JMTV12BC2N1		24,400	\$3,416
213297853	COLEMAN	HMH72B341	XAFC36DBCN1+JMET12CS2N1		25,400	\$3,556
214398733	COLEMAN	HH860E2S11	CTM60D5CGS1	CP9C120D20MP13	32,400	\$4,536
214398728	COLEMAN	HH860E2S11	CTM60D5CGS1	TP9C120D20MP13	32,400	\$4,536
214398723	COLEMAN	HH860E2S11	CTM60D5CGS1	TM9V120D20MP12	32,400	\$4,536
214396547	COLEMAN	HH836E2S11	CTM48C5CFS1	TM9E100C20MP12	26,400	\$3,696
214396386	COLEMAN	HH836E2S11	CTM36C5CDS1	TM9Y100C16MP11	27,400	\$3,836
214396775	COLEMAN	HH860E2S11	CTF60D5CJS1	TMLE130D20MP11	37,200	\$5,208
214396765	COLEMAN	HH860E2S11	CTF60D5CJS1+JME18D2SN1		37,200	\$5,208
214396760	COLEMAN	HH860E2S11	JHC60D5CH2SS1		36,200	\$5,068
214397160	COLEMAN	HH824E2S11	CTF30B5ACS1	CPLC080B12MP13	18,200	\$2,548
214397155	COLEMAN	HH824E2S11	CTF30B5ACS1	TPLC080B12MP13	18,200	\$2,548
214397145	COLEMAN	HH824E2S11	CTF30B5ACS1	TMLE080B12MP11	18,400	\$2,576
214397135	COLEMAN	HH824E2S11	CTM30B5ACS1	TM9Y060B12MP11	18,700	\$2,618
213297838	COLEMAN	HMH72B341	XAHB36DXXN1+JMTV12BC2N1+TXV		24,400	\$3,416
213297668	COLEMAN	HMH72B341	XAHB30CXXN1+JMTV12BC2N1+TXV		25,800	\$3,612
213298098	COLEMAN	HMH72B341	XAFB36DXXN1+JMET12BS2N1+TXV		25,200	\$3,528
213297428	COLEMAN	HMH72B341	XAHB30CXXN1+JMET12BS2N1+TXV		25,600	\$3,584
213297673	COLEMAN	HMH72B341	XAFC30CXXN1+JMET12CS2N1+TXV		26,400	\$3,696
213297213	COLEMAN	HMH72B341	XAHC36DXXN1+JMET12CS2N1+TXV		24,600	\$3,444
213297848	COLEMAN	HMH72B341	XAFC36DXXN1+JMET12CS2N1+TXV		25,400	\$3,556
213297208	COLEMAN	HMH72B341	XAHC30CXXN1+JMET12CS2N1+TXV		26,000	\$3,640
213297228	COLEMAN	HMH72B341	XAUB30CXXN1+JMET12BS2N1+TXV		26,000	\$3,640
213297223	COLEMAN	HMH72B341	XAFB30CXXN1+JMET12BS2N1+TXV		26,000	\$3,640

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213343193	COLEMAN	HMH72B341	JHVTB24CXXC2N1+TXV		25,800	\$3,612
213343211	COLEMAN	HMH72B341	JHETB30DXXS2N1+TXV		24,800	\$3,472
213343222	COLEMAN	HMH72B341	JHETB24CXXS2N1+TXV		25,200	\$3,528
213298108	COLEMAN	HMH72B341	XAUB36DXXN1+JMET12BS2N1+TXV		25,200	\$3,528
213297423	COLEMAN	HMH72B341	XAUB36DXXN1+JMVT12BC2N1+TXV		25,000	\$3,500
213297413	COLEMAN	HMH72B341	XAFB36DXXN1+JMVT12BC2N1+TXV		25,000	\$3,500
213298093	COLEMAN	HMH72B341	XAUB30CXXN1+JMVT12BC2N1+TXV		26,600	\$3,724
213298088	COLEMAN	HMH72B341	XAFB30CXXN1+JMVT12BC2N1+TXV		26,600	\$3,724
211393643	COLEMAN	HMH72B341	JHETB30DBAS2N1		24,800	\$3,472
10525581	COLEMAN	HC20B3621	CM38CE2A1	TP9C100C16MP13	31,600	\$4,424
10525580	COLEMAN	HC20B3621	CM38CE2A1	TP9C080C16MP13	31,800	\$4,452
10525610	COLEMAN	HC20B4821	CM50DE3A1	CP9C120D20MP13	44,000	\$6,160
201982919	COLEMAN	HC20B3621	AVV38CE221		33,400	\$4,676
10525611	COLEMAN	HC20B4821	CM50DE3A1	TM9V120D20MP12	44,000	\$6,160
10525612	COLEMAN	HC20B4821	CM50DE3A1	TP9C120D20MP13	44,000	\$6,160
10525605	COLEMAN	HC20B4821	CM50CE3A1	TP9C100C20MP13	44,000	\$6,160
10525598	COLEMAN	HC20B4821	CM50CE3A1	TM9V100C20MP12	44,000	\$6,160
10525587	COLEMAN	HC20B4821	CM50CE3A1	CP9C100C20MP13	44,000	\$6,160
10525584	COLEMAN	HC20B4821	AVV50CE321		43,500	\$6,090
10525577	COLEMAN	HC20B3621	CM38CE2A1	TM9V100C16MP12	31,600	\$4,424
10525576	COLEMAN	HC20B3621	CM38CE2A1	TM9V080C16MP12	31,800	\$4,452
10525569	COLEMAN	HC20B3621	CM38CE2A1	CP9C080C16MP13	31,800	\$4,452
10525570	COLEMAN	HC20B3621	CM38CE2A1	CP9C100C16MP13	31,600	\$4,424
10309106	COLEMAN	HC20B4821	CM50DE3A1+MVC20DN21		42,500	\$5,950
10309094	COLEMAN	HC20B3621	CM38CE2A1+MVC16CN21		33,400	\$4,676
10309110	COLEMAN	HC20B4821	CM50CE3A1+MVC16CN21		43,500	\$6,090
10309102	COLEMAN	HC20B4821	AVV50DE321		44,000	\$6,160
10309046	COLEMAN	HC20B2421	CM25BE1A1+MVC12BN21		22,400	\$3,136
215427968	COMFIAIRE	CA-12UXEO	CA-12UWXI		6,800	\$952
215427969	COMFIAIRE	CA-18UXEO	CA-18UWXI		10,500	\$1,470
215438063	COMFIAIRE	CA3-24UMTO	Heat pump without ducts		15,000	\$2,100
215438064	COMFIAIRE	CA4-36UMTO	Heat pump without ducts		22,400	\$3,136
216765686	COMFIAIRE	CA-24UHDO	CA-24UHDI		16,000	\$2,240

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216765687	COMFIAIRE	CA-36UHDO	CA-36UHDI		24,000	\$3,360
217101874	COMFORT AIRE	A-KMH18SU-1	B-KMH18SV-1		15,000	\$2,100
217101875	COMFORT AIRE	A-KMH24SU-1	B-KMH24SV-1		21,200	\$2,968
217101903	COMFORT AIRE	A-VHP12SA-1	B-VHP12SA-1		9,800	\$1,372
217101911	COMFORT AIRE	A-VHP183A-1	Heat pump without ducts		17,600	\$2,464
217101912	COMFORT AIRE	A-VHP183A-1	Heat pump with ducts		17,000	\$2,380
217101913	COMFORT AIRE	A-VHP183A-1	Combination heat pumps with or without ducts		17,300	\$2,422
217101904	COMFORT AIRE	A-VHP18SA-1	B-VHP18SA-1		15,000	\$2,100
217101905	COMFORT AIRE	A-VHP24SA-1	B-VHP24SA-1		21,000	\$2,940
217101914	COMFORT AIRE	A-VHP284A-1	Heat pump without ducts		25,000	\$3,500
217101915	COMFORT AIRE	A-VHP284A-1	Heat pump with ducts		23,000	\$3,220
217101916	COMFORT AIRE	A-VHP284A-1	Combination heat pumps with or without ducts		24,000	\$3,360
217101906	COMFORT AIRE	A-VHP33SA-1	B-VHP33SA-1		30,000	\$4,200
217101917	COMFORT AIRE	A-VHP365A-1	Heat pump without ducts		30,000	\$4,200
217101918	COMFORT AIRE	A-VHP365A-1	Heat pump with ducts		33,000	\$4,620
217101919	COMFORT AIRE	A-VHP365A-1	Combination heat pumps with or without ducts		31,400	\$4,396
217101920	COMFORT AIRE	A-VHP486A-1	Heat pump without ducts		44,000	\$6,160
217101921	COMFORT AIRE	A-VHP486A-1	Heat pump with ducts		44,500	\$6,230
217101922	COMFORT AIRE	A-VHP486A-1	Combination heat pumps with or without ducts		44,000	\$6,160
217101925	COMFORT AIRE	A-VHP556A-1	Combination heat pumps with or without ducts		44,500	\$6,230
217101923	COMFORT AIRE	A-VHP556A-1	Heat pump without ducts		44,000	\$6,160
217101924	COMFORT AIRE	A-VHP556A-1	Heat pump with ducts		45,000	\$6,300
217101834	COMFORT AIRE	A-VMH12SV-1	B-VMH12SV-1		10,000	\$1,400
217101880	COMFORT AIRE	A-VMH12SV-1	B-VMH12CU-1		9,900	\$1,386
217101882	COMFORT AIRE	A-VMH12SV-1	B-VMH12FU-1		9,600	\$1,344
217101886	COMFORT AIRE	A-VMH12SV-1	B-VMH12DU-1		10,600	\$1,484
217101887	COMFORT AIRE	A-VMH12SV-1	B-VMH12FV-1		10,200	\$1,428
217101840	COMFORT AIRE	A-VMH18DV-1	Heat pump with ducts		16,000	\$2,240
217101841	COMFORT AIRE	A-VMH18DV-1	Heat pump without ducts		15,000	\$2,100
217101842	COMFORT AIRE	A-VMH18DV-1	Combination heat pumps with or without ducts		15,500	\$2,170
217101864	COMFORT AIRE	A-VMH18SU-1A	B-VMH18SV-1		15,000	\$2,100
217101835	COMFORT AIRE	A-VMH18SV-1	B-VMH18SV-1		15,000	\$2,100
217101877	COMFORT AIRE	A-VMH18SV-1	B-VMH18UU-1		12,000	\$1,680

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
217101879	COMFORT AIRE	A-VMH18SV-1	B-VMH18DU-1		15,000	\$2,100
217101865	COMFORT AIRE	A-VMH24SU-1	B-VMH24SV-1		21,200	\$2,968
217101836	COMFORT AIRE	A-VMH24SV-1	B-VMH24SV-1		21,200	\$2,968
217101839	COMFORT AIRE	A-VMH24SV-1	B-VMH24CV-1		21,000	\$2,940
217101883	COMFORT AIRE	A-VMH24SV-1	B-VMH24DU-1		21,000	\$2,940
217101884	COMFORT AIRE	A-VMH24SV-1	B-VMH24UU-1		19,000	\$2,660
217101891	COMFORT AIRE	A-VMH33SV-1	B-VMH33SV-1		28,800	\$4,032
217101845	COMFORT AIRE	A-VMH36QV-1	Heat pump without ducts		33,000	\$4,620
217101963	COMFORT AIRE	A-VMH36QV-1	Combination heat pumps with or without ducts		34,000	\$4,760
217101892	COMFORT AIRE	A-VMH36QV-1A	Heat pump without ducts		27,400	\$3,836
217101894	COMFORT AIRE	A-VMH36QV-1A	Combination heat pumps with or without ducts		28,600	\$4,004
217101893	COMFORT AIRE	A-VMH36QV-1A	Heat pump with ducts		30,000	\$4,200
217101847	COMFORT AIRE	A-VMH48PV-1	Heat pump without ducts		36,000	\$5,040
217101848	COMFORT AIRE	A-VMH48PV-1	Heat pump with ducts		36,000	\$5,040
217101962	COMFORT AIRE	A-VMH48PV-1	Combination heat pumps with or without ducts		36,000	\$5,040
217101888	COMFORT AIRE	A-VMH55PV-1	Heat pump without ducts		34,400	\$4,816
217101889	COMFORT AIRE	A-VMH55PV-1	Heat pump with ducts		35,200	\$4,928
217101890	COMFORT AIRE	A-VMH55PV-1	Combination heat pumps with or without ducts		34,800	\$4,872
217101909	COMFORT AIRE	A-ZHP12SA-1	B-ZHP12SA-1		11,000	\$1,540
217101910	COMFORT AIRE	A-ZHP18SA-1	B-ZHP18SA-1		19,300	\$2,702
217123452	COMFORT AIRE	A-VCD18SA-1	B-VCD18SA-1		13,500	\$1,890
217123459	COMFORT AIRE	A-VCD18SA-1	B-KCD18SA-1		13,500	\$1,890
217123450	COMFORT AIRE	A-VCD24SA-1	MCD18/24B1A		21,000	\$2,940
217123454	COMFORT AIRE	A-VCD24SA-1	B-VCD24SA-1		19,200	\$2,688
217123460	COMFORT AIRE	A-VCD24SA-1	B-KCD24SA-1		19,200	\$2,688
217123447	COMFORT AIRE	A-VCD30SA-1	B-VCD30SA-1		21,000	\$2,940
217123455	COMFORT AIRE	A-VCD30SA-1	MCD30/36C1A		22,600	\$3,164
217123461	COMFORT AIRE	A-VCD30SA-1	B-KCD30SA-1		21,000	\$2,940
217123448	COMFORT AIRE	A-VCD36SA-1	B-VCD36SA-1		30,400	\$4,256
217123457	COMFORT AIRE	A-VCD36SA-1	MCD30/36C1A		33,000	\$4,620
217123466	COMFORT AIRE	A-VCD36SA-1	MCD30/36B1A		27,400	\$3,836
217123462	COMFORT AIRE	A-VCD36SA-1	B-KCD36SA-1		30,400	\$4,256
217123453	COMFORT AIRE	A-VCD48SA-1	B-VCD48SA-1		36,000	\$5,040
217123463	COMFORT AIRE	A-VCD48SA-1	B-KCD48SA-1		36,000	\$5,040

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
217123449	COMFORT AIRE	A-VCD60SA-1	B-VCD60SA-1		42,000	\$5,880
217123464	COMFORT AIRE	A-VCD60SA-1	B-KCD60SA-1		42,000	\$5,880
217123473	COMFORT AIRE	A-VHP18SA-1	B-VHP18AA-1		14,000	\$1,960
217123474	COMFORT AIRE	A-VHP24SA-1	B-VHP24AA-1		16,900	\$2,366
217123475	COMFORT AIRE	A-VHP33SA-1	B-VHP30AA-1		27,400	\$3,836
217123445	COMFORT AIRE	A-VMH18SV-1	B-VMH18AV-1		15,400	\$2,156
217123446	COMFORT AIRE	A-VMH24SV-1	B-VMH24AV-1		16,900	\$2,366
217123467	COMFORT AIRE	A-VXP18TA-1	B-VXP18TA-1		15,000	\$2,100
217123476	COMFORT AIRE	A-VXP18TA-1	MXP18/24A1A		15,200	\$2,128
217123477	COMFORT AIRE	A-VXP18TA-1	MXP18/24B1A		15,200	\$2,128
217123468	COMFORT AIRE	A-VXP24TA-1	B-VXP24TA-1		20,000	\$2,800
217123478	COMFORT AIRE	A-VXP24TA-1	MXP18/24A1A		19,700	\$2,758
217123479	COMFORT AIRE	A-VXP24TA-1	MXP18/24B1A		19,700	\$2,758
217123481	COMFORT AIRE	A-VXP30TA-1	MXP30/36B1A		25,000	\$3,500
217123482	COMFORT AIRE	A-VXP30TA-1	MXP30/36C1A		25,000	\$3,500
217123469	COMFORT AIRE	A-VXP30TA-1	B-VXP30TA-1		23,800	\$3,332
217123470	COMFORT AIRE	A-VXP36TA-1	B-VXP36TA-1		31,800	\$4,452
217123483	COMFORT AIRE	A-VXP36TA-1	MXP30/36B1A		29,200	\$4,088
217123484	COMFORT AIRE	A-VXP36TA-1	MXP30/36C1A		29,200	\$4,088
217123471	COMFORT AIRE	A-VXP48TA-1	B-VXP48TA-1		37,000	\$5,180
217123485	COMFORT AIRE	A-VXP48TA-1	MXP48/60C1A		34,400	\$4,816
217123472	COMFORT AIRE	A-VXP60TA-1	B-VXP60TA-1		45,000	\$6,300
216472850	COMFORT TEMPS	CTP-BH121A-O	CTP-BH121A-I		7,800	\$1,092
216472852	COMFORT TEMPS	CTP-BH122A-O	CTP-BH122A-I		8,100	\$1,134
216472853	COMFORT TEMPS	CTP-BH182A-O	CTP-BH182A-I		11,000	\$1,540
216472854	COMFORT TEMPS	CTP-BH242A-O	CTP-BH242A-I		14,000	\$1,960
216097132	COMFORT-AIRE	A-VHP365A-1	Combination heat pumps with or without ducts		31,400	\$4,396
216097130	COMFORT-AIRE	A-VHP365A-1	Heat pump without ducts		30,000	\$4,200
207657387	COMFORT-AIRE	A-VMH12SV-1	B-VMH12SV-1		10,000	\$1,400
208141177	COMFORT-AIRE	A-VMH18SU-1A	B-VMH18SV-1		15,000	\$2,100
207657388	COMFORT-AIRE	A-VMH18SV-1	B-VMH18SV-1		15,000	\$2,100
208141188	COMFORT-AIRE	A-KMH18SU-1	B-KMH18SV-1		15,000	\$2,100
208141189	COMFORT-AIRE	A-KMH24SU-1	B-KMH24SV-1		21,200	\$2,968
207657389	COMFORT-AIRE	A-VMH24SV-1	B-VMH24SV-1		21,200	\$2,968
208141178	COMFORT-AIRE	A-VMH24SU-1	B-VMH24SV-1		21,200	\$2,968
210568240	COMFORT-AIRE	A-VMH12SV-1	B-VMH12CU-1		9,900	\$1,386
210568242	COMFORT-AIRE	A-VMH12SV-1	B-VMH12FU-1		9,600	\$1,344

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210568239	COMFORT-AIRE	A-VMH18SV-1	B-VMH18DU-1		15,000	\$2,100
207657392	COMFORT-AIRE	A-VMH24SV-1	B-VMH24CV-1		21,000	\$2,940
207657613	COMFORT-AIRE	A-VMH28TV-1	Heat pump with ducts		27,000	\$3,780
214232457	COMFORT-AIRE	A-VMH55PV-1	Combination heat pumps with or without ducts		34,800	\$4,872
214232456	COMFORT-AIRE	A-VMH55PV-1	Heat pump with ducts		35,200	\$4,928
214232455	COMFORT-AIRE	A-VMH55PV-1	Heat pump without ducts		34,400	\$4,816
210568231	COMFORT-AIRE	A-VCD18SA-1	B-VCD18SA-1		13,500	\$1,890
208136322	COMFORT-AIRE	A-VMH18SV-1	B-VMH18AV-1		15,400	\$2,156
208136323	COMFORT-AIRE	A-VMH24SV-1	B-VMH24AV-1		16,900	\$2,366
210568233	COMFORT-AIRE	A-VCD24SA-1	B-VCD24SA-1		19,200	\$2,688
207657614	COMFORT-AIRE	A-VMH28TV-1	Combination heat pumps with or without ducts		26,800	\$3,752
213348292	COMFORT-AIRE	A-VCD18SA-1	B-KCD18SA-1		13,500	\$1,890
213348293	COMFORT-AIRE	A-VCD24SA-1	B-KCD24SA-1		19,200	\$2,688
213916260	COMFORT-AIRE	A-VMH12SV-1	B-VMH12FV-1		10,200	\$1,428
207657617	COMFORT-AIRE	A-VMH48PV-1	Heat pump without ducts		36,000	\$5,040
207657612	COMFORT-AIRE	A-VMH28TV-1	Heat pump without ducts		26,600	\$3,724
207657610	COMFORT-AIRE	A-VMH18DV-1	Heat pump without ducts		15,000	\$2,100
210568226	COMFORT-AIRE	A-VCD30SA-1	B-VCD30SA-1		21,000	\$2,940
213348294	COMFORT-AIRE	A-VCD30SA-1	B-KCD30SA-1		21,000	\$2,940
213348295	COMFORT-AIRE	A-VCD36SA-1	B-KCD36SA-1		30,400	\$4,256
210568227	COMFORT-AIRE	A-VCD36SA-1	B-VCD36SA-1		30,400	\$4,256
207657615	COMFORT-AIRE	A-VMH36QV-1	Heat pump without ducts		33,000	\$4,620
207657619	COMFORT-AIRE	A-VMH48PV-1	Combination heat pumps with or without ducts		36,000	\$5,040
207657620	COMFORT-AIRE	A-VMH36QV-1	Combination heat pumps with or without ducts		34,000	\$4,760
210568246	COMFORT-AIRE	A-VMH12SV-1	B-VMH12DU-1		10,600	\$1,484
207657609	COMFORT-AIRE	A-VMH18DV-1	Heat pump with ducts		16,000	\$2,240
210568244	COMFORT-AIRE	A-VMH24SV-1	B-VMH24UU-1		19,000	\$2,660
207657611	COMFORT-AIRE	A-VMH18DV-1	Combination heat pumps with or without ducts		15,500	\$2,170
207657618	COMFORT-AIRE	A-VMH48PV-1	Heat pump with ducts		36,000	\$5,040
210568243	COMFORT-AIRE	A-VMH24SV-1	B-VMH24DU-1		21,000	\$2,940
210568229	COMFORT-AIRE	A-VCD24SA-1	MCD18/24B1A		21,000	\$2,940
216097107	COMFORT-AIRE	A-VHP18SA-1	B-VHP18SA-1		16,600	\$2,324
216097074	COMFORT-AIRE	A-VXP18TA-1	B-VXP18TA-1		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216097106	COMFORT-AIRE	A-VHP12SA-1	B-VHP12SA-1		9,800	\$1,372
216097075	COMFORT-AIRE	A-VXP24TA-1	B-VXP24TA-1		20,000	\$2,800
216097077	COMFORT-AIRE	A-VXP36TA-1	B-VXP36TA-1		31,800	\$4,452
216623765	COMFORT-AIRE	A-VXP24TA-1	MXP18/24A1A		19,700	\$2,758
216623764	COMFORT-AIRE	A-VXP18TA-1	MXP18/24B1A		15,200	\$2,128
216623763	COMFORT-AIRE	A-VXP18TA-1	MXP18/24A1A		15,200	\$2,128
216623768	COMFORT-AIRE	A-VXP30TA-1	MXP30/36B1A		25,000	\$3,500
216623769	COMFORT-AIRE	A-VXP30TA-1	MXP30/36C1A		25,000	\$3,500
216623767	COMFORT-AIRE	A-VXP30TA-1	MXP30/36A1A		23,400	\$3,276
216623766	COMFORT-AIRE	A-VXP24TA-1	MXP18/24B1A		19,700	\$2,758
216623771	COMFORT-AIRE	A-VXP36TA-1	MXP30/36C1A		29,200	\$4,088
216623770	COMFORT-AIRE	A-VXP36TA-1	MXP30/36B1A		29,200	\$4,088
216684130	COMFORT-AIRE	A-VXP48TA-1	MXP48/60C1A		32,000	\$4,480
216097108	COMFORT-AIRE	A-VHP24SA-1	B-VHP24SA-1		21,000	\$2,940
216097109	COMFORT-AIRE	A-VHP33SA-1	B-VHP33SA-1		30,000	\$4,200
216097118	COMFORT-AIRE	A-ZHP12SA-1	B-ZHP12SA-1		11,000	\$1,540
216097119	COMFORT-AIRE	A-ZHP18SA-1	B-ZHP18SA-1		19,300	\$2,702
216097124	COMFORT-AIRE	A-VHP183A-1	Heat pump without ducts		17,600	\$2,464
216097125	COMFORT-AIRE	A-VHP183A-1	Heat pump with ducts		17,000	\$2,380
216097126	COMFORT-AIRE	A-VHP183A-1	Combination heat pumps with or without ducts		17,300	\$2,422
216097127	COMFORT-AIRE	A-VHP284A-1	Heat pump without ducts		25,000	\$3,500
216097128	COMFORT-AIRE	A-VHP284A-1	Heat pump with ducts		23,000	\$3,220
216097129	COMFORT-AIRE	A-VHP284A-1	Combination heat pumps with or without ducts		24,000	\$3,360
216097131	COMFORT-AIRE	A-VHP365A-1	Heat pump with ducts		33,000	\$4,620
216097133	COMFORT-AIRE	A-VHP486A-1	Heat pump without ducts		44,000	\$6,160
216097134	COMFORT-AIRE	A-VHP486A-1	Heat pump with ducts		44,500	\$6,230
216097135	COMFORT-AIRE	A-VHP486A-1	Combination heat pumps with or without ducts		44,000	\$6,160
216097136	COMFORT-AIRE	A-VHP556A-1	Heat pump without ducts		44,000	\$6,160
216097137	COMFORT-AIRE	A-VHP556A-1	Heat pump with ducts		45,000	\$6,300
216097138	COMFORT-AIRE	A-VHP556A-1	Combination heat pumps with or without ducts		44,500	\$6,230
216097079	COMFORT-AIRE	A-VXP60TA-1	B-VXP60TA-1		45,000	\$6,300
216097078	COMFORT-AIRE	A-VXP48TA-1	B-VXP48TA-1		37,000	\$5,180
216097076	COMFORT-AIRE	A-VXP30TA-1	B-VXP30TA-1		23,800	\$3,332
216097080	COMFORT-AIRE	A-VHP18SA-1	B-VHP18AA-1		14,000	\$1,960

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216097082	COMFORT-AIRE	A-VHP33SA-1	B-VHP30AA-1		27,400	\$3,836
216097081	COMFORT-AIRE	A-VHP24SA-1	B-VHP24AA-1		16,900	\$2,366
210568236	COMFORT-AIRE	A-VCD36SA-1	MCD30/36C1A		33,000	\$4,620
213614244	COMFORT-AIRE	A-VCD30SA-1	MCD30/36B1A		19,600	\$2,744
200059039	COMFORT-AIRE	B-VMH12SU-1	A-VMH12SU-1		7,800	\$1,092
206913036	COMFORT-AIRE	A-VMH24SU-1A	B-VMH24SU-1		19,400	\$2,716
206221394	COMFORT-AIRE	A-VMH24SU-1A	B-VMH24SU-1A		19,400	\$2,716
208141184	COMFORT-AIRE	A-KMH24SV-1	B-KMH24SU-1		19,400	\$2,716
206913571	COMFORT-AIRE	A-VMH24SU-1	B-VMH24SU-1A		19,400	\$2,716
208141170	COMFORT-AIRE	A-VMH24SV-1	B-VMH24SU-1		19,400	\$2,716
214810657	COMFORT-AIRE	A-VCD36SA-1	MCD30/36B1A		27,400	\$3,836
201810036	COMFORT-AIRE	A-VMH36QU-1	Heat pump without ducts		23,200	\$3,248
214377755	COMFORT-AIRE	A-VMH33SV-1	B-VMH33SV-1		28,800	\$4,032
214377756	COMFORT-AIRE	A-VMH36QV-1A	Heat pump without ducts		27,400	\$3,836
214377757	COMFORT-AIRE	A-VMH36QV-1A	Heat pump with ducts		30,000	\$4,200
214377758	COMFORT-AIRE	A-VMH36QV-1A	Combination heat pumps with or without ducts		28,600	\$4,004
213348297	COMFORT-AIRE	A-VCD60SA-1	B-KCD60SA-1		42,000	\$5,880
213348296	COMFORT-AIRE	A-VCD48SA-1	B-KCD48SA-1		36,000	\$5,040
200059035	COMFORT-AIRE	A-VMH24SU-1	B-VMH24SU-1		15,400	\$2,156
205747696	COMFORT-AIRE	A-VMH18SU-1B	B-VMH18SU-1B		10,900	\$1,526
207657616	COMFORT-AIRE	A-VMH36QV-1	Heat pump with ducts		23,000	\$3,220
210568232	COMFORT-AIRE	A-VCD48SA-1	B-VCD48SA-1		36,000	\$5,040
210568228	COMFORT-AIRE	A-VCD60SA-1	B-VCD60SA-1		42,000	\$5,880
210568234	COMFORT-AIRE	A-VCD30SA-1	MCD30/36C1A		22,600	\$3,164
212386767	COMFORT-AIRE	A-VCD60SA-1	MCD60D1A		37,000	\$5,180
207614962	COMFORTMAKER	DLCPRBH12AAK	DLFPHBH12XAK		10,400	\$1,456
207826645	COMFORTMAKER	DLCPRBH18AAK	DLFPHBH18XAK		20,200	\$2,828
206361875	COMFORTMAKER	DLCSR BH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361877	COMFORTMAKER	DLCSR BH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361876	COMFORTMAKER	DLCSR BH18AAK	DLFSHBH18XAK		11,100	\$1,554
210857431	COMFORTMAKER	DLCSR BH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857432	COMFORTMAKER	DLCSR BH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132684	COMFORTMAKER	DLCSR BH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948192	COMFORTMAKER	DLCSR BH12AAK	DLFSFBH12XAK		10,200	\$1,428
207683334	COMFORTMAKER	DLCSR BH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447623	COMFORTMAKER	DLCSR BH24AAK	DLFSHCH24XAK		21,200	\$2,968
208447627	COMFORTMAKER	DLCSR BH18AAK	DLFSHCH18XAK		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208447622	COMFORTMAKER	DLCSRBH12AAK	DLFSHCH12XAK		10,000	\$1,400
211132716	COMFORTMAKER	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
206771905	COMFORTMAKER	CVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	31,400	\$4,396
211132682	COMFORTMAKER	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
206771725	COMFORTMAKER	CVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206771356	COMFORTMAKER	CVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206771626	COMFORTMAKER	CVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206771275	COMFORTMAKER	CVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206771779	COMFORTMAKER	CVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206771644	COMFORTMAKER	CVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206771860	COMFORTMAKER	CVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	31,400	\$4,396
206771896	COMFORTMAKER	CVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
215324190	COMFORTMAKER	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215323726	COMFORTMAKER	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215324201	COMFORTMAKER	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324200	COMFORTMAKER	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324197	COMFORTMAKER	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324195	COMFORTMAKER	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324193	COMFORTMAKER	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324192	COMFORTMAKER	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324191	COMFORTMAKER	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324188	COMFORTMAKER	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324187	COMFORTMAKER	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324186	COMFORTMAKER	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324185	COMFORTMAKER	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215413228	COMFORTMAKER	D5CPRAH18AA	D5FPAH18XAK		19,300	\$2,702
215413227	COMFORTMAKER	D5CPRAH12AAK	D5FPAH12XAK		11,000	\$1,540
215357201	COMFORTMAKER	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357200	COMFORTMAKER	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357199	COMFORTMAKER	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215324196	COMFORTMAKER	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324189	COMFORTMAKER	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215357227	COMFORTMAKER	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357210	COMFORTMAKER	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357209	COMFORTMAKER	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357208	COMFORTMAKER	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357207	COMFORTMAKER	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357206	COMFORTMAKER	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357205	COMFORTMAKER	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357204	COMFORTMAKER	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357203	COMFORTMAKER	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357202	COMFORTMAKER	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357198	COMFORTMAKER	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357197	COMFORTMAKER	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357196	COMFORTMAKER	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357192	COMFORTMAKER	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357191	COMFORTMAKER	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357190	COMFORTMAKER	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324238	COMFORTMAKER	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324236	COMFORTMAKER	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324235	COMFORTMAKER	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324233	COMFORTMAKER	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324232	COMFORTMAKER	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324199	COMFORTMAKER	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324194	COMFORTMAKER	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324239	COMFORTMAKER	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324237	COMFORTMAKER	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324234	COMFORTMAKER	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324184	COMFORTMAKER	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215318931	COMFORTMAKER	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215318930	COMFORTMAKER	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215318929	COMFORTMAKER	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215318939	COMFORTMAKER	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215318937	COMFORTMAKER	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215318927	COMFORTMAKER	D5CURAH48AAK	D5FUAAH48XAK		32,400	\$4,536
215318924	COMFORTMAKER	D5CURAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215318922	COMFORTMAKER	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215318921	COMFORTMAKER	D5CUHAH60AAK	D5FUAAH60XAK		45,000	\$6,300
215318920	COMFORTMAKER	D5CUHAH48AAK	D5FUAAH48XAK		37,000	\$5,180
215318919	COMFORTMAKER	D5CUHAH36AAK	D5FUAAH36XAK		31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215318918	COMFORTMAKER	D5CUHAH30AAK	D5FUAAH30XAK		23,800	\$3,332
215318917	COMFORTMAKER	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215318916	COMFORTMAKER	D5CUHAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215318915	COMFORTMAKER	D5CUHAH18AAK	D5FUAAH18XAK		15,000	\$2,100
215318938	COMFORTMAKER	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215318934	COMFORTMAKER	D5CSHAH33AAK	D5FSAAH36XBK		27,400	\$3,836
215318933	COMFORTMAKER	D5CSHAH24AAK	D5FSAAH24XBK		16,900	\$2,366
215318932	COMFORTMAKER	D5CSHAH18AAK	D5FSAAH18XBK		14,000	\$1,960
209852054	COMFORTMAKER	DLCURAH36ABK	DLFUAAH36XAK		30,400	\$4,256
210470270	COMFORTMAKER	CVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	31,000	\$4,340
210470567	COMFORTMAKER	CVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL1352422A*	31,200	\$4,368
210473243	COMFORTMAKER	CVH825GKA3*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210470501	COMFORTMAKER	CVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0901716A*	31,200	\$4,368
210470435	COMFORTMAKER	CVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0701716A*	31,400	\$4,396
210470556	COMFORTMAKER	CVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470446	COMFORTMAKER	CVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470281	COMFORTMAKER	CVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL1352422A*	31,000	\$4,340
211709688	COMFORTMAKER	DLCURAH30ABK	FJMA4*30L*B*		23,400	\$3,276
213353859	COMFORTMAKER	DLCURAH36ABK	F5MA4*42L*C*		29,200	\$4,088
213353849	COMFORTMAKER	DLCURAH36ABK	F5MA4*36L*B*		29,400	\$4,116
213249339	COMFORTMAKER	DLCURAH36ABK	FEVA0036***+NAVA43601CK		29,400	\$4,116
211274899	COMFORTMAKER	DLCURAH30ABK	FVM4X48***L		23,000	\$3,220
211222781	COMFORTMAKER	DLCURAH30ABK	FVM4X24***L		23,600	\$3,304
211222765	COMFORTMAKER	DLCURAH30ABK	FMA4X36**AL*		23,800	\$3,332
211222757	COMFORTMAKER	DLCURAH30ABK	FMA4X30**AL*		23,800	\$3,332
211222749	COMFORTMAKER	DLCURAH30ABK	FM(C,U)4Z36**AL*		23,600	\$3,304
211222741	COMFORTMAKER	DLCURAH30ABK	FM(C,U)4Z30**AL*		23,600	\$3,304
213353887	COMFORTMAKER	DLCURAH60ABK	F5MA4*60L*D*		37,800	\$5,292
213607817	COMFORTMAKER	DLCURAH60ABK	FTMA4B60L0D*		37,400	\$5,236
210025742	COMFORTMAKER	DLCURAH60ABK	DLFUAAH60XAK		42,000	\$5,880
211230930	COMFORTMAKER	DLCURAH36ABK	FXM4X48**AL		29,000	\$4,060
211230919	COMFORTMAKER	DLCURAH36ABK	FXM4X42**AL		29,000	\$4,060
211230898	COMFORTMAKER	DLCURAH36ABK	FVM4X48***L		28,600	\$4,004
211230887	COMFORTMAKER	DLCURAH36ABK	FMA4X36**AL*		29,600	\$4,144
211230865	COMFORTMAKER	DLCURAH36ABK	FM(C,U)4Z36**AL*		29,600	\$4,144
211714688	COMFORTMAKER	DLCURAH30ABK	FJMA4*36L*B*		23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213249295	COMFORTMAKER	DLCURAH30ABK	FEVA0036**+NAVA43601CK		23,600	\$3,304
213353811	COMFORTMAKER	DLCURAH30ABK	F5MA4*30L*B*		23,400	\$3,276
213353821	COMFORTMAKER	DLCURAH30ABK	F5MA4*36L*B*		23,600	\$3,304
213353781	COMFORTMAKER	DLCURAH24ABK	F5MA4*30L*B*		19,100	\$2,674
213353771	COMFORTMAKER	DLCURAH24ABK	F5MA4*24L*B*		19,300	\$2,702
213249273	COMFORTMAKER	DLCURAH24ABK	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076401	COMFORTMAKER	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601716B*	19,400	\$2,716
213076375	COMFORTMAKER	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601716B*	19,400	\$2,716
213076364	COMFORTMAKER	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002122A*	19,100	\$2,674
213076346	COMFORTMAKER	DLCURAH24ABK	EA*4X36L21A*	*95MSU1002122A*	19,000	\$2,660
211289632	COMFORTMAKER	DLCURAH60ABK	FVM4X60***L		37,800	\$5,292
213607742	COMFORTMAKER	DLCURAH36ABK	FTMA4B48L0C*		28,800	\$4,032
213607727	COMFORTMAKER	DLCURAH36ABK	FTMA4B36L0C*		29,400	\$4,116
213607682	COMFORTMAKER	DLCURAH30ABK	FTMA4B36L0C*		23,600	\$3,304
213607652	COMFORTMAKER	DLCURAH24ABK	FTMA4X24L0B*		19,300	\$2,702
213607637	COMFORTMAKER	DLCURAH24ABK	FTMA4B36L0C*		19,100	\$2,674
213607592	COMFORTMAKER	DLCURAH18ABK	FTMA4X24L0B*		12,400	\$1,736
212975270	COMFORTMAKER	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712B*	18,800	\$2,632
212975259	COMFORTMAKER	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712B*	19,500	\$2,730
212975060	COMFORTMAKER	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410B*	19,200	\$2,688
212975047	COMFORTMAKER	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410B*	19,200	\$2,688
212975034	COMFORTMAKER	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410B*	19,100	\$2,674
212975021	COMFORTMAKER	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410B*	19,600	\$2,744
212975008	COMFORTMAKER	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410B*	19,600	\$2,744
212974995	COMFORTMAKER	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410B*	18,800	\$2,632
212974982	COMFORTMAKER	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410B*	19,200	\$2,688
212974969	COMFORTMAKER	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410B*	19,200	\$2,688
212974956	COMFORTMAKER	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410B*	19,200	\$2,688
212974943	COMFORTMAKER	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401410B*	18,700	\$2,618
211245984	COMFORTMAKER	DLCURAH24ABK	FVM4X36***L		19,000	\$2,660
211245974	COMFORTMAKER	DLCURAH24ABK	FVM4X24***L		19,000	\$2,660
211245963	COMFORTMAKER	DLCURAH24ABK	FM(C,U)4Z36**AL*		19,300	\$2,702
211245952	COMFORTMAKER	DLCURAH24ABK	FM(C,U)4Z30**AL*		19,300	\$2,702
211245941	COMFORTMAKER	DLCURAH24ABK	FM(C,U)4Z24**AL*		19,500	\$2,730
211245930	COMFORTMAKER	DLCURAH24ABK	FM(C,U)4X36**AL*		19,900	\$2,786
211245919	COMFORTMAKER	DLCURAH24ABK	FM(C,U)4X30**AL*		19,900	\$2,786

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245908	COMFORTMAKER	DLCURAH24ABK	FMA4X36**AL*		19,600	\$2,744
211245897	COMFORTMAKER	DLCURAH24ABK	FMA4X30**AL*		19,600	\$2,744
211245886	COMFORTMAKER	DLCURAH24ABK	FMA4X24**AL*		19,600	\$2,744
211245864	COMFORTMAKER	DLCURAH24ABK	FMA4P24**AL*		19,900	\$2,786
211245853	COMFORTMAKER	DLCURAH24ABK	FXM4X36**AL		18,500	\$2,590
211245842	COMFORTMAKER	DLCURAH24ABK	FXM4X30**AL		19,100	\$2,674
211245831	COMFORTMAKER	DLCURAH24ABK	FXM4X24**AL		19,100	\$2,674
211245820	COMFORTMAKER	DLCURAH24ABK	FEM4X30**BL		19,100	\$2,674
211245808	COMFORTMAKER	DLCURAH24ABK	FEM4X24**CL		19,000	\$2,660
211245796	COMFORTMAKER	DLCURAH24ABK	FEM4P30**AL		19,100	\$2,674
213372131	COMFORTMAKER	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372127	COMFORTMAKER	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
211239225	COMFORTMAKER	DLCURAH24ABK	FJMA4*24L*B*		19,200	\$2,688
213353741	COMFORTMAKER	DLCURAH18ABK	F5MA4*24L*B*		12,500	\$1,750
213353731	COMFORTMAKER	DLCURAH18ABK	F5MA4*18L*A*		12,800	\$1,792
213249251	COMFORTMAKER	DLCURAH18ABK	FEVA0024**+NAVA43601CK		12,300	\$1,722
211265037	COMFORTMAKER	DLCURAH18ABK	FVM4X24***L		12,400	\$1,736
211265016	COMFORTMAKER	DLCURAH18ABK	FM(C,U)4Z30**AL*		12,400	\$1,736
211264994	COMFORTMAKER	DLCURAH18ABK	FM(C,U)4Z24**AL*		12,500	\$1,750
211264973	COMFORTMAKER	DLCURAH18ABK	FM(C,U)4Z18**AL*		12,500	\$1,750
211264950	COMFORTMAKER	DLCURAH18ABK	FMA4X24**AL*		12,400	\$1,736
211264928	COMFORTMAKER	DLCURAH18ABK	FMA4X18**AL*		12,400	\$1,736
211264907	COMFORTMAKER	DLCURAH18ABK	FXM4X30**AL		12,400	\$1,736
211264885	COMFORTMAKER	DLCURAH18ABK	FXM4X24**AL		12,400	\$1,736
211264764	COMFORTMAKER	DLCURAH18ABK	FEM4P18**AL		12,300	\$1,722
211264741	COMFORTMAKER	DLCURAH18ABK	FJMA4*18L*A*		12,700	\$1,778
211257338	COMFORTMAKER	DLCURAH18ABK	FJMA4*24L*B*		12,800	\$1,792
201835582	COMFORTMAKER	DLCSRAH12AAK	DLFSCAH12XAK		8,200	\$1,148
201835586	COMFORTMAKER	DLCSRAH18AAK	DLFSCAH18XAK		12,000	\$1,680
201835584	COMFORTMAKER	DLCSRAH12AAK	DLFSDAH12XAK		8,100	\$1,134
201835588	COMFORTMAKER	DLCSRAH24AAK	DLFSFAH24XAK		17,200	\$2,408
201835593	COMFORTMAKER	DLCLRAH48AAK	DLFLFAH48XAK		35,000	\$4,900
201835565	COMFORTMAKER	DLCSRAH18AAK	DLFSHAH18XAK		11,900	\$1,666
201835566	COMFORTMAKER	DLCSRAH24AAK	DLFSHAH24XAK		15,000	\$2,100
201835587	COMFORTMAKER	DLCSRAH24AAK	DLFSDAH24XAK		17,400	\$2,436
202463645	COMFORTMAKER	DLCPRAH24AAK	DLFPHAH24XAK		15,450	\$2,163
201835589	COMFORTMAKER	DLCSRAH24AAK	DLFSCAH24XAK		16,200	\$2,268

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205921373	COMFORTMAKER	DLCSRAH24AAK	DLFSAAH24XAK		17,500	\$2,450
206350402	COMFORTMAKER	DLCSRBH24AAK	DLFSDAH24XAK		14,500	\$2,030
206350397	COMFORTMAKER	DLCSRBH12AAK	DLFSFAH12XAK		8,400	\$1,176
206350396	COMFORTMAKER	DLCSRBH12AAK	DLFSDAH12XAK		8,300	\$1,162
206350395	COMFORTMAKER	DLCSRBH12AAK	DLFSCAH12XAK		7,900	\$1,106
206396079	COMFORTMAKER	DLCSRAH12AAK	DLFSHBH12XAK		7,500	\$1,050
206350399	COMFORTMAKER	DLCSRBH18AAK	DLFSDAH18XAK		12,700	\$1,778
206188295	COMFORTMAKER	DLCSRBH24AAK	DLFSAAH24XAK		16,500	\$2,310
206350401	COMFORTMAKER	DLCSRBH24AAK	DLFSCAH24XAK		14,500	\$2,030
206350403	COMFORTMAKER	DLCSRBH24AAK	DLFSFAH24XAK		14,500	\$2,030
206350400	COMFORTMAKER	DLCSRBH18AAK	DLFSFAH18XAK		12,000	\$1,680
207643022	COMFORTMAKER	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340
207643025	COMFORTMAKER	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643016	COMFORTMAKER	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207643021	COMFORTMAKER	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207643024	COMFORTMAKER	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220
207643015	COMFORTMAKER	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643023	COMFORTMAKER	DLCMHBH36DAK	Heat pump without ducts		22,000	\$3,080
207643020	COMFORTMAKER	DLCMHBH48EAK	Heat pump without ducts		34,000	\$4,760
207643014	COMFORTMAKER	DLCMHBH30DAK	Heat pump without ducts		18,500	\$2,590
211222789	COMFORTMAKER	DLCURAH30ABK	FXM4X36**AL		23,200	\$3,248
211230819	COMFORTMAKER	DLCURAH36ABK	FEM4P42**AL		29,200	\$4,088
211230830	COMFORTMAKER	DLCURAH36ABK	FEM4P48**AL		29,400	\$4,116
211230842	COMFORTMAKER	DLCURAH36ABK	FEM4X42**BL		29,200	\$4,088
211230854	COMFORTMAKER	DLCURAH36ABK	FEM4X48**BL		29,400	\$4,116
211230876	COMFORTMAKER	DLCURAH36ABK	FMA4P36**AL*		29,800	\$4,172
211230908	COMFORTMAKER	DLCURAH36ABK	FXM4X36**AL		29,000	\$4,060
211719730	COMFORTMAKER	DLCURAH18ABK	FMA4P18**AL*		12,700	\$1,778
211264862	COMFORTMAKER	DLCURAH18ABK	FXM4X18**AL		12,300	\$1,722
211264841	COMFORTMAKER	DLCURAH18ABK	FEM4X24**CL		12,100	\$1,694
211264810	COMFORTMAKER	DLCURAH18ABK	FEM4X18**BL		12,300	\$1,722
211264786	COMFORTMAKER	DLCURAH18ABK	FEM4P24**AL		12,300	\$1,722
209852047	COMFORTMAKER	DLCURAH18ABK	DLFUAH18XAK		13,500	\$1,890
209852048	COMFORTMAKER	DLCURAH24ABK	DLFUAH24XAK		19,200	\$2,688
209852050	COMFORTMAKER	DLCURAH48ABK	DLFUAH48XAK		36,000	\$5,040

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207801569	COMFORTMAKER	DLCSRBH18AAK	DLFSDAH24XAK		12,600	\$1,764
207826597	COMFORTMAKER	DLCSRBH18AAK	DLFSABH18XBK		12,000	\$1,680
217138354	COMFORTSTAR	CPP3-24CD(O)	AHU3-24M		16,900	\$2,366
217138353	COMFORTSTAR	CPP3-18CD(O)	AHU3-18M		14,000	\$1,960
217138360	COMFORTSTAR	CHF3-18CD(O)	AHU3-18M		14,000	\$1,960
217138364	COMFORTSTAR	CHF3-48DU(O)	AHU3-48DU(I)		40,000	\$5,600
217138363	COMFORTSTAR	CHF3-36DU(O)	AHU3-36DU(I)		28,000	\$3,920
217138362	COMFORTSTAR	CHF3-36CD(O)	AHU3-36M		27,400	\$3,836
217138361	COMFORTSTAR	CHF3-24CD(O)	AHU3-24M		16,900	\$2,366
217138365	COMFORTSTAR	CHF3-60DU(O)	AHU3-60DU(I)		41,000	\$5,740
217138389	COMFORTSTAR	CHF3-60DU(O)	CPA3H-60DU(I)		45,000	\$6,300
217138388	COMFORTSTAR	CHF3-48DU(O)	CPA3H-48DU(I)		45,000	\$6,300
217138387	COMFORTSTAR	CHF3-36DU(O)	CPA3H-36DU(I)		31,600	\$4,424
217138378	COMFORTSTAR	CHF3-18CD(O)	CPA3-18CD(I)		15,000	\$2,100
217138377	COMFORTSTAR	CHF3-12CD(O)	CPA3-12CD(I)		9,600	\$1,344
217138373	COMFORTSTAR	CHF3-36CD(O)	CPP3H-36CD(I)		29,600	\$4,144
217138374	COMFORTSTAR	CHF3-24CD(O)	TIP3-24CD(I)		20,400	\$2,856
217138386	COMFORTSTAR	CHF3-60DU(O)	FPA3-60DU(I)		41,000	\$5,740
217138385	COMFORTSTAR	CHF3-48DU(O)	FPA3-48DU(I)		38,500	\$5,390
217138391	COMFORTSTAR	CHF3-48DU(O)	TIP3-48DU(I)		44,000	\$6,160
217138384	COMFORTSTAR	CHF3-36DU(O)	FPA3-36DU(I)		30,200	\$4,228
217138390	COMFORTSTAR	CHF3-36DU(O)	TIP3-36DU(I)		30,600	\$4,284
217138372	COMFORTSTAR	CHF3-24CD(O)	CPP3-24CD(I)		21,600	\$3,024
217138371	COMFORTSTAR	CHF3-18CD(O)	CPP3-18CD(I)		14,400	\$2,016
217138370	COMFORTSTAR	CHF3-12CD(O)	CPP3-12CD(I)		10,000	\$1,400
212940790	COMFORTSTAR	CPH24CD(O)	AHU24-SG2		19,200	\$2,688
212940789	COMFORTSTAR	CPH18CD(O)	AHU18-SG2		13,500	\$1,890
207658927	COMFORTSTAR	CHF12CD(O)	CHF12CD(I)		10,000	\$1,400
207658928	COMFORTSTAR	CHF18CD(O)	CHF18CD(I)		15,000	\$2,100
207658929	COMFORTSTAR	CHF24CD(O)	CHF24CD(I)		21,200	\$2,968
207658950	COMFORTSTAR	CHF12CD(O)	TPA-12		9,900	\$1,386
207658939	COMFORTSTAR	CHF18CD(O)	CPA-18C		15,000	\$2,100
207765971	COMFORTSTAR	CHF18CD(O)	CPA-18B		15,000	\$2,100
207658952	COMFORTSTAR	CHF24CD(O)	TIP-24		21,000	\$2,940
207658980	COMFORTSTAR	CVH-27-3SH	Heat pump with ducts		27,000	\$3,780
207658981	COMFORTSTAR	CVH-27-3SH	Combination heat pumps with or without ducts		26,800	\$3,752
207658976	COMFORTSTAR	CVH-18-2SH	Heat pump without ducts		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207658979	COMFORTSTAR	CVH-27-3SH	Heat pump without ducts		26,600	\$3,724
207658984	COMFORTSTAR	CVH-48-5SH	Heat pump without ducts		36,000	\$5,040
212940791	COMFORTSTAR	CPH30CD(O)	AHU30-SG2		21,000	\$2,940
212940792	COMFORTSTAR	CPH36CD(O)	AHU36-SG2		30,400	\$4,256
207658940	COMFORTSTAR	CHF24CD(O)	CPA-24C		21,000	\$2,940
207658977	COMFORTSTAR	CVH-18-2SH	Heat pump with ducts		16,000	\$2,240
207658978	COMFORTSTAR	CVH-18-2SH	Combination heat pumps with or without ducts		15,500	\$2,170
207658985	COMFORTSTAR	CVH-48-5SH	Heat pump with ducts		36,000	\$5,040
207658986	COMFORTSTAR	CVH-48-5SH	Combination heat pumps with or without ducts		36,000	\$5,040
207658938	COMFORTSTAR	CHF12CD(O)	CPA-12C		10,600	\$1,484
207658961	COMFORTSTAR	CHF24CD(O)	FPA-24		19,000	\$2,660
207658987	COMFORTSTAR	CVH-36-4SH	Combination heat pumps with or without ducts		34,000	\$4,760
207658982	COMFORTSTAR	CVH-36-4SH	Heat pump without ducts		33,000	\$4,620
207765970	COMFORTSTAR	CHF12CD(O)	CPA-12B		10,600	\$1,484
207765972	COMFORTSTAR	CHF24CD(O)	CPA-24B		21,000	\$2,940
213386530	COMFORTSTAR	CPH24CD(O)	UACP-24B		21,000	\$2,940
213386518	COMFORTSTAR	CPH24CD(O)	ACP-24B		21,000	\$2,940
214594912	COMFORTSTAR	CHF18CD(O)	T1W18P		14,500	\$2,030
214594911	COMFORTSTAR	CHF12CD(O)	T1W12P		9,500	\$1,330
216720934	COMFORTSTAR	CMZ3-55-6Z	Heat pump with ducts		37,000	\$5,180
216720923	COMFORTSTAR	CVH3-60-6SH	Combination heat pumps with or without ducts		45,000	\$6,300
216720922	COMFORTSTAR	CVH3-60-6SH	Heat pump with ducts		45,000	\$6,300
216720921	COMFORTSTAR	CVH3-60-6SH	Heat pump without ducts		45,000	\$6,300
216720920	COMFORTSTAR	CVH3-48-6SH	Combination heat pumps with or without ducts		42,500	\$5,950
216720919	COMFORTSTAR	CVH3-48-6SH	Heat pump with ducts		44,500	\$6,230
216720918	COMFORTSTAR	CVH3-48-6SH	Heat pump without ducts		40,500	\$5,670
216720917	COMFORTSTAR	CVH3-36-5SH	Combination heat pumps with or without ducts		34,800	\$4,872
216720916	COMFORTSTAR	CVH3-36-5SH	Heat pump with ducts		33,000	\$4,620
216720915	COMFORTSTAR	CVH3-36-5SH	Heat pump without ducts		36,600	\$5,124
216720914	COMFORTSTAR	CVH3-27-4SH	Combination heat pumps with or without ducts		23,200	\$3,248
216720913	COMFORTSTAR	CVH3-27-4SH	Heat pump with ducts		23,000	\$3,220
216720912	COMFORTSTAR	CVH3-27-4SH	Heat pump without ducts		23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216720911	COMFORTSTAR	CVH3-18-3SH	Combination heat pumps with or without ducts		16,700	\$2,338
216720910	COMFORTSTAR	CVH3-18-3SH	Heat pump with ducts		17,000	\$2,380
216720909	COMFORTSTAR	CVH3-18-3SH	Heat pump without ducts		16,400	\$2,296
216720948	COMFORTSTAR	CPH3-36CD(O)	AHU3-36-SG3		23,200	\$3,248
216720943	COMFORTSTAR	CPR3-48CD(O)	AHU3-48-SG3		32,400	\$4,536
216720940	COMFORTSTAR	CPR3-24CD(O)	AHU3-24-SG3		20,000	\$2,800
216720950	COMFORTSTAR	CPH3-60CD(O)	AHU3-60-SG3		45,000	\$6,300
216720949	COMFORTSTAR	CPH3-48CD(O)	AHU3-48-SG3		37,000	\$5,180
216720947	COMFORTSTAR	CPH3-30CD(O)	AHU3-30-SG3		23,800	\$3,332
216720946	COMFORTSTAR	CPH3-24CD(O)	AHU3-24-SG3		20,000	\$2,800
216720945	COMFORTSTAR	CPH3-18CD(O)	AHU3-18-SG3		15,000	\$2,100
207658958	COMFORTSTAR	CZP48CD(O)	FPA-48DU		29,000	\$4,060
213386520	COMFORTSTAR	CPH36CD(O)	ACP-36C		33,000	\$4,620
213386532	COMFORTSTAR	CPH36CD(O)	UACP-36C		33,000	\$4,620
207658942	COMFORTSTAR	CHF48CD(O)	CPA-48C		39,500	\$5,530
207658954	COMFORTSTAR	CHF48CD(O)	TIP-48		35,000	\$4,900
207765966	COMFORTSTAR	CHF48CD(O)	CPA-48DUB		39,500	\$5,530
207658963	COMFORTSTAR	CHF48CD(O)	FPA-48DU		35,000	\$4,900
207658953	COMFORTSTAR	CHF36CD(O)	TIP-36		33,000	\$4,620
202575872	COMFORTSTAR	CM3-27-3ZX	Heat pump without ducts		18,000	\$2,520
213427546	COMFORTSTAR	CPH36CD(O)-B	UACP-36C		27,000	\$3,780
213427551	COMFORTSTAR	CPH36CD(O)-B	ACP-36C		27,000	\$3,780
213427550	COMFORTSTAR	CPH36CD(O)-B	ACP-36B		27,000	\$3,780
213427548	COMFORTSTAR	CPH36CD(O)-B	UACP-36B		27,000	\$3,780
213386534	COMFORTSTAR	CPH60CD(O)	UACP-60D		37,000	\$5,180
213386522	COMFORTSTAR	CPH60CD(O)	ACP-60D		37,000	\$5,180
213386519	COMFORTSTAR	CPH30CD(O)	ACP-36C		22,600	\$3,164
213386531	COMFORTSTAR	CPH30CD(O)	UACP-36C		22,600	\$3,164
213479752	COMFORTSTAR	CPH36CD(O)-B	AHU36-SG2		31,800	\$4,452
202575869	COMFORTSTAR	CXH024CD(O)	CPA-24B		17,200	\$2,408
207658983	COMFORTSTAR	CVH-36-4SH	Heat pump with ducts		23,000	\$3,220
207658962	COMFORTSTAR	CHF36CD(O)	FPA-36DU		32,000	\$4,480
212940793	COMFORTSTAR	CPH48CD(O)	AHU48-SG2		36,000	\$5,040
212940794	COMFORTSTAR	CPH60CD(O)	AHU60-SG2		42,000	\$5,880
9008899	CONCERTO	MOB30-12HFN1-MV0W	MSVPC-12HFRN1-MU0W		8,400	\$1,176
208106839	CONCORD	4DHP2S48M-1P	Heat pump without ducts		36,000	\$5,040
216769824	CONCORD	7SCP18V60P-**A	7EH60DX-***TDR	97G2UH135DV20*	44,000	\$6,160

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216769820	CONCORD	7SCP18V60P-**-A	7ED60DX-**-TDR	97G2DF110CV20*	44,000	\$6,160
216769818	CONCORD	7SCP18V60P-**-A	7ED60DX-**-TDR	97G2DF090CV20*	44,000	\$6,160
216769816	CONCORD	7SCP18V60P-**-A	7E[C,U]60DX-**-TDR	97G2UH135DV20*	44,000	\$6,160
216769814	CONCORD	7SCP18V60P-**-A	7EH50/60CX-**-TDR	97G2UH090CV20*	44,500	\$6,230
216769812	CONCORD	7SCP18V60P-**-A	7EH50/60CX-**-TDR	97G2UH110CV20*	44,000	\$6,160
216769810	CONCORD	7SCP18V60P-**-A	7E[C,U]60CX-**-TDR	97G2UH090CV20*	44,000	\$6,160
216769808	CONCORD	7SCP18V60P-**-A	7E[C,U]60CX-**-TDR	97G2UH110CV20*	43,500	\$6,090
216769788	CONCORD	7SCP18V60P-**-A	7ED48CX-**-TDR	97G2DF110CV20*	39,500	\$5,530
216769786	CONCORD	7SCP18V60P-**-A	7ED48CX-**-TDR	97G2DF090CV20*	39,500	\$5,530
216769782	CONCORD	7SCP18V60P-**-A	7EH48CX-**-TDR	97G2UH110CV20*	39,500	\$5,530
216769780	CONCORD	7SCP18V60P-**-A	7EH42CX-**-TDR	97G2UH090CV20*	39,500	\$5,530
216769778	CONCORD	7SCP18V60P-**-A	7EH42CX-**-TDR	97G2UH110CV20*	39,500	\$5,530
216769776	CONCORD	7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	97G2UH090CV20*	39,500	\$5,530
216769774	CONCORD	7SCP18V60P-**-A	7E[C,U]49CX-**-TDR	97G2UH110CV20*	39,000	\$5,460
216769772	CONCORD	7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	97G2UH090CV20*	39,500	\$5,530
216769770	CONCORD	7SCP18V60P-**-A	7E[C,U]48CX-**-TDR	97G2UH110CV20*	39,500	\$5,530
216769784	CONCORD	7SCP18V60P-**-A	7ED42BX-**-TDR	97G2DF070BV16*	40,000	\$5,600
216769734	CONCORD	7SCP18V36P-**-A	7ED42BX-**-TDR	97G2DF070BV16*	29,000	\$4,060
216769732	CONCORD	7SCP18V36P-**-A	7ED30/36BX-**-TDR	97G2DF070BV16*	29,000	\$4,060
216769730	CONCORD	7SCP18V36P-**-A	7EH36CX-**-TDR	97G2UH090CV12*	28,600	\$4,004
216769728	CONCORD	7SCP18V36P-**-A	7EH36BX-**-TDR	97G2UH070BV12*	28,800	\$4,032
216769726	CONCORD	7SCP18V36P-**-A	7EH36BX-**-TDR	97G2UH045BV12*	28,800	\$4,032
216769724	CONCORD	7SCP18V36P-**-A	7EH30BX-**-TDR	97G2UH070BV12*	28,800	\$4,032
216769673	CONCORD	7SCP18V24P-**-A	7EH30BX-**-TDR	97G2UH070BV12*	19,800	\$2,772
216769722	CONCORD	7SCP18V36P-**-A	7EH30BX-**-TDR	97G2UH045BV12*	28,800	\$4,032
216769671	CONCORD	7SCP18V24P-**-A	7EH30BX-**-TDR	97G2UH045BV12*	19,800	\$2,772
216769669	CONCORD	7SCP18V24P-**-A	7EH24BX-**-TDR	97G2UH070BV12*	19,800	\$2,772
216769667	CONCORD	7SCP18V24P-**-A	7EH24BX-**-TDR	97G2UH045BV12*	19,800	\$2,772
216769720	CONCORD	7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	97G2UH070BV12*	28,800	\$4,032
216769665	CONCORD	7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	97G2UH070BV12*	19,800	\$2,772
216769718	CONCORD	7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	97G2UH045BV12*	28,800	\$4,032
216769663	CONCORD	7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	97G2UH045BV12*	19,800	\$2,772
216769716	CONCORD	7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	97G2UH070BV12*	28,800	\$4,032
216769661	CONCORD	7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	97G2UH070BV12*	19,800	\$2,772
216769659	CONCORD	7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	97G2UH045BV12*	19,800	\$2,772
210605803	Conforto	MHSZ112DA	MHWAL12DA		10,000	\$1,400
210605804	Conforto	MHSZ118DA	MHWAL18DA		15,000	\$2,100
210605805	Conforto	MHSZ124DA	MHWAL24DA		21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210605807	Conforto	MHSZ112DA	MHCAS12DA		9,900	\$1,386
210605809	Conforto	MHSZ124DA	MHCAS24DA		21,000	\$2,940
210605814	CONFORTO	MHMZ327DA	Heat pump with ducts		27,000	\$3,780
210605815	CONFORTO	MHMZ327DA	Combination heat pumps with or without ducts		26,800	\$3,752
210605813	CONFORTO	MHMZ327DA	Heat pump without ducts		26,600	\$3,724
210605810	CONFORTO	MHMZ218DA	Heat pump without ducts		15,000	\$2,100
210605819	CONFORTO	MHMZ548DA	Heat pump without ducts		36,000	\$5,040
210605818	CONFORTO	MHMZ436DA	Combination heat pumps with or without ducts		34,000	\$4,760
210605821	CONFORTO	MHMZ548DA	Combination heat pumps with or without ducts		36,000	\$5,040
210605812	CONFORTO	MHMZ218DA	Combination heat pumps with or without ducts		15,500	\$2,170
210605820	CONFORTO	MHMZ548DA	Heat pump with ducts		36,000	\$5,040
210605811	CONFORTO	MHMZ218DA	Heat pump with ducts		16,000	\$2,240
210605816	CONFORTO	MHMZ436DA	Heat pump without ducts		33,000	\$4,620
216683748	CONFORTO	MHSD118DACFC	MHAH118DACFC		13,500	\$1,890
216683749	CONFORTO	MHSD124DACFC	MHAH124DACFC		19,200	\$2,688
216683751	CONFORTO	MHSD136DACFC	MHAH136DACFC		30,400	\$4,256
216683750	CONFORTO	MHSD130DACFC	MHAH130DACFC		21,000	\$2,940
216683752	CONFORTO	MHSD148DACFC	MHAH148DACFC		36,000	\$5,040
216683753	CONFORTO	MHSD160DACFC	MHAH160DACFC		42,000	\$5,880
215748022	CONNECT M	CNTM16DHP18AA	CNTM16DAH18AA		13,500	\$1,890
215748023	CONNECT M	CNTM16DHP24AA	CNTM16DAH24AA		19,200	\$2,688
215748024	CONNECT M	CNTM16DHP36AA	CNTM16DAH36AA		30,400	\$4,256
215748028	CONNECT M	CNTM16DHP36AA	CNTMDCC36AA		33,000	\$4,620
215748025	CONNECT M	CNTM16DHP48AA	CNTM16DAH48AA		36,000	\$5,040
215748026	CONNECT M	CNTM16DHP60AA	CNTM16DAH60AA		42,000	\$5,880
215213730	CONTINENTAL	NDHAMB-36-O	Combination heat pumps with or without ducts		31,400	\$4,396
215931372	CONTINENTAL	CDHAMBB-36-O	Heat pump without ducts		30,000	\$4,200
215213728	CONTINENTAL	CDHAMB-36-O	Heat pump without ducts		30,000	\$4,200
213386537	CONTINENTAL	CDHAS26-24-O	CDHAS26-24-I		21,200	\$2,968
213386542	CONTINENTAL	CDHAM-28-O	Heat pump with ducts		27,000	\$3,780
213386546	CONTINENTAL	CDHAM-36-O	Combination heat pumps with or without ducts		35,000	\$4,900
213386543	CONTINENTAL	CDHAM-28-O	Combination heat pumps with or without ducts		26,200	\$3,668

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213386541	CONTINENTAL	CDHAM-28-O	Heat pump without ducts		25,600	\$3,584
213386539	CONTINENTAL	CDHAS26-12-O	CDHAS26-12-I		10,000	\$1,400
213386536	CONTINENTAL	CDHAS26-18-O	CDHAS26-18-I		15,000	\$2,100
207335556	CONTINENTAL	CS18HV24A36	CPFX24A		16,000	\$2,240
207335557	CONTINENTAL	CS18HV24A36	CPFX24A36A		24,000	\$3,360
207335558	CONTINENTAL	CS18HV48A60	CPFX48A		31,400	\$4,396
213386544	CONTINENTAL	CDHAM-36-O	Heat pump without ducts		35,000	\$4,900
211624980	CONTINENTAL	WSEHV4860RA1-C	CPFX48A60A		44,000	\$6,160
211624979	CONTINENTAL	WSEHV4860RA1-C	CPFX48A		39,500	\$5,530
211624977	CONTINENTAL	WSEHV2436RA1-C	CPFX24A		20,000	\$2,800
211624978	CONTINENTAL	WSEHV2436RA1-C	CPFX24A36A		29,000	\$4,060
216706206	CONTINENTAL	CDHAS26B-33-O	CDHAS26B-33-I		30,000	\$4,200
213060799	CONTINENTAL	WSEHV2436RA1-C	WPCCA24		19,600	\$2,744
213060801	CONTINENTAL	WSEHV4860RA1-C	WPCCB48		39,000	\$5,460
213060802	CONTINENTAL	WSEHV4860RA1-C	WPCCB60		44,500	\$6,230
215213716	CONTINENTAL	CDHAS26B-18-O	CDHAS26B-18-I		16,600	\$2,324
215931367	CONTINENTAL	CDHAS26BA-18-O	CDHAS26BA-18-I		16,600	\$2,324
215931366	CONTINENTAL	CDHAS26BA-12-O	CDHAS26BA-12-I		9,800	\$1,372
215213715	CONTINENTAL	CDHAS26B-12-O	CDHAS26B-12-I		9,800	\$1,372
215931359	CONTINENTAL	CDHAS22BA-24-O	CDHAS22BB-24-I		19,500	\$2,730
215931358	CONTINENTAL	CDHAS22BA-18-O	CDHAS22BB-18-I		13,000	\$1,820
215931357	CONTINENTAL	CDHAS22BA-12-O	CDHAS22BB-12-I		9,600	\$1,344
215213713	CONTINENTAL	CDHAS22B-24-O	CDHAS22B-24-I		19,500	\$2,730
215213712	CONTINENTAL	CDHAS22B-18-O	CDHAS22B-18-I		13,000	\$1,820
215213711	CONTINENTAL	CDHAS22B-12-O	CDHAS22B-12-I		9,600	\$1,344
215931371	CONTINENTAL	CDHAMBB-27-O	Heat pump without ducts		25,000	\$3,500
215931370	CONTINENTAL	CDHAMBB-18-O	Heat pump without ducts		17,600	\$2,464
215931369	CONTINENTAL	CDHAS26BA-33-O	CDHAS26BA-33-I		30,000	\$4,200
215931368	CONTINENTAL	CDHAS26BA-24-O	CDHAS26BA-24-I		21,000	\$2,940
215463871	CONTINENTAL	NDHAS26B-33-O	NDHAS26B-33-I		30,000	\$4,200
207335559	CONTINENTAL	CS18HV48A60	CPFX48A60A		36,000	\$5,040
215213717	CONTINENTAL	CDHAS26B-24-O	CDHAS26B-24-I		19,300	\$2,702
215213729	CONTINENTAL	NDHAMB-36-O	Heat pump with ducts		33,000	\$4,620
215213724	CONTINENTAL	CDHAMB-27-O	Combination heat pumps with or without ducts		24,000	\$3,360
215213723	CONTINENTAL	CDHAMB-27-O	Heat pump with ducts		23,000	\$3,220
215213722	CONTINENTAL	CDHAMB-27-O	Heat pump without ducts		25,000	\$3,500
212404681	CONTINENTAL	WSEHV4860RA1-C	H,DE50960	WPV090T5BA	38,000	\$5,320

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212404697	CONTINENTAL	WSEHV2436RA1-C	H,DE33(6,9)36	WPV050T3AA	15,000	\$2,100
209048792	CONTINENTAL	CS18HV24A36	H,DE33(6,9)36	WPV050T3AA	19,400	\$2,716
209048793	CONTINENTAL	CS18HV24A36	H,DE33(6,9)36	WPV070T3AA	19,400	\$2,716
209048794	CONTINENTAL	CS18HV24A36	H,DE33(6,9)36	WUV050T3AA	19,400	\$2,716
209048801	CONTINENTAL	CS18HV24A36	H,DE33(6,9)36	WUV070T3AA	19,400	\$2,716
209664494	CONTINENTAL	CS18HV24A36	H,DE32(6,9)36	WUV035T2AA	15,100	\$2,114
209664495	CONTINENTAL	CS18HV24A36	H,DE32(6,9)36	WPV035T2AA	15,100	\$2,114
212427856	CONTINENTAL	WSEHV2436RA1-C	H,DE33(6,9)36	WUV070T3AA	15,000	\$2,100
212427855	CONTINENTAL	WSEHV2436RA1-C	H,DE33(6,9)36	WPV070T3AA	15,000	\$2,100
212404700	CONTINENTAL	WSEHV2436RA1-C	H,DE33(6,9)36	WUV060T3AA	15,000	\$2,100
212404699	CONTINENTAL	WSEHV2436RA1-C	H,DE33(6,9)36	WUV050T3AA	15,000	\$2,100
212404698	CONTINENTAL	WSEHV2436RA1-C	H,DE33(6,9)36	WPV060T3AA	15,000	\$2,100
212404691	CONTINENTAL	CS18HV48A60	H,DE50960	WUV100T5BA	38,000	\$5,320
212404690	CONTINENTAL	CS18HV48A60	H,DE50960	WUV090T5BA	38,000	\$5,320
212404692	CONTINENTAL	CS18HV48A60	H,DE50960	WPV100T5BA	38,000	\$5,320
212404689	CONTINENTAL	CS18HV48A60	H,DE50960	WPV090T5BA	38,000	\$5,320
212404683	CONTINENTAL	WSEHV4860RA1-C	H,DE50960	WUV100T5BA	38,000	\$5,320
212404682	CONTINENTAL	WSEHV4860RA1-C	H,DE50960	WUV090T5BA	38,000	\$5,320
212404684	CONTINENTAL	WSEHV4860RA1-C	H,DE50960	WPV100T5BA	38,000	\$5,320
212603043	CONTINENTAL	WSEHV2436RA1-C	H,DE37936	WPV070T3AA	25,600	\$3,584
212603044	CONTINENTAL	WSEHV2436RA1-C	H,DE37936	WPV080T3AA	25,600	\$3,584
212603047	CONTINENTAL	CS18HV24A36	H,DE37936	WPV070T3AA	25,600	\$3,584
212603048	CONTINENTAL	CS18HV24A36	H,DE37936	WPV080T3AA	25,600	\$3,584
212920612	CONTINENTAL	WSEHV2436RA1-C	H,DE37936	WUV070T3AA	25,600	\$3,584
212920613	CONTINENTAL	WSEHV2436RA1-C	H,DE37936	WUV080T3AA	25,600	\$3,584
212920616	CONTINENTAL	CS18HV24A36	H,DE37936	WUV070T3AA	25,600	\$3,584
212920617	CONTINENTAL	CS18HV24A36	H,DE37936	WUV080T3AA	25,600	\$3,584
207709205	Convectair	8028-C12-O	8028-C12-I		10,000	\$1,400
207709206	Convectair	8028-C18-O	8028-C18-I		15,000	\$2,100
207709207	Convectair	8028-C24-O	8028-C24-I		21,200	\$2,968
207590850	CONVECTAIR	8322-C27-O	Heat pump with ducts		27,000	\$3,780
207590851	CONVECTAIR	8322-C27-O	Combination heat pumps with or without ducts		26,800	\$3,752
207590849	CONVECTAIR	8322-C27-O	Heat pump without ducts		26,600	\$3,724
207590852	CONVECTAIR	8522-C48-O	Heat pump without ducts		36,000	\$5,040
207590846	CONVECTAIR	8222-C18-O	Heat pump without ducts		15,000	\$2,100
207590848	CONVECTAIR	8222-C18-O	Combination heat pumps with or without ducts		15,500	\$2,170

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207657624	CONVECTAIR	8422-C36-O	Combination heat pumps with or without ducts		34,000	\$4,760
207590854	CONVECTAIR	8522-C48-O	Combination heat pumps with or without ducts		36,000	\$5,040
207657622	CONVECTAIR	8422-C36-O	Heat pump without ducts		33,000	\$4,620
207590847	CONVECTAIR	8222-C18-O	Heat pump with ducts		16,000	\$2,240
207590853	CONVECTAIR	8522-C48-O	Heat pump with ducts		36,000	\$5,040
206422439	CONVECTAIR	8240-O	8240-I		19,400	\$2,716
206422438	CONVECTAIR	8180-O	8180-I		10,900	\$1,526
207657623	CONVECTAIR	8422-C36-O	Heat pump with ducts		23,000	\$3,220
215864166	COOPER&HUNTER	CH-RHP18-230VO	CH-RB18MOLVWM-230VI		14,400	\$2,016
215864154	COOPER&HUNTER	CH-RHP18-230VO	CH-R18MOLVWM-230VI		14,400	\$2,016
215864153	COOPER&HUNTER	CH-RHP12-230VO	CH-R12MOLVWM-230VI		10,000	\$1,400
215864165	COOPER&HUNTER	CH-RHP12-230VO	CH-RB12MOLVWM-230VI		10,000	\$1,400
215864277	COOPER&HUNTER	CH-RVHP36M-230VO	Combination heat pumps with or without ducts		31,400	\$4,396
215864275	COOPER&HUNTER	CH-RVHP36M-230VO	Heat pump without ducts		30,000	\$4,200
210857423	Cooper&Hunter	CH-HPR18-230VO	CH-18MCT1W-230VI		14,500	\$2,030
210857422	Cooper&Hunter	CH-HPR12-230VO	CH-12MCT1W-230VI		9,500	\$1,330
210799549	Cooper&Hunter	CH-HPR12-230VO	CH-12MASTWM-230VI		10,000	\$1,400
210799675	Cooper&Hunter	CH-HPR12-230VO	CH-12MMC-230VI		10,200	\$1,428
210799550	Cooper&Hunter	CH-HPR18-230VO	CH-18MASTWM-230VI		15,000	\$2,100
210799632	COOPER&HUNTER	CH-HPR28M-230VO	Heat pump with ducts		27,000	\$3,780
210799645	COOPER&HUNTER	CH-HPR55M-230VO	Heat pump with ducts		35,200	\$4,928
208101232	Cooper&Hunter	CH-HPR24-230VO	CH-M24AHU		16,900	\$2,366
208141205	Cooper&Hunter	CH-HPR18-230VO	CH-M18AHU		15,400	\$2,156
210799593	Cooper&Hunter	CH-HPR12-230VO	CH-12MSPHCT-230VI		9,900	\$1,386
210799595	Cooper&Hunter	CH-HPR12-230VO	CH-12MSPHMC-230VI		9,600	\$1,344
210799597	Cooper&Hunter	CH-HPR18-230VO	CH-M18DTUI		15,000	\$2,100
210799633	COOPER&HUNTER	CH-HPR28M-230VO	Combination heat pumps with or without ducts		26,800	\$3,752
210799646	COOPER&HUNTER	CH-HPR55M-230VO	Combination heat pumps with or without ducts		34,800	\$4,872
210799599	Cooper&Hunter	CH-HPR24-230VO	CH-N24MSPHCT-230VI		21,000	\$2,940
210799551	Cooper&Hunter	CH-HPR24-230VO	CH-24MASTWM-230VI		21,200	\$2,968
213265563	COOPER&HUNTER	CH-HPR12-230VO	CH-12MCT-W		9,900	\$1,386
213265577	COOPER&HUNTER	CH-HPR18-230VO	CH-18MDT-W		15,000	\$2,100
213265567	COOPER&HUNTER	CH-HPR24-230VO	CH-24MCT-W		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213265600	COOPER&HUNTER	CH-HPR12-230VO	CH-12MCT1W-W		9,500	\$1,330
213265602	COOPER&HUNTER	CH-HPR18-230VO	CH-18MCT1W-W		14,500	\$2,030
213265606	COOPER&HUNTER	CH-HPR24-230VO	CH-M24AHU-W		16,900	\$2,366
213265604	COOPER&HUNTER	CH-HPR18-230VO	CH-M18AHU-W		15,400	\$2,156
210799644	COOPER&HUNTER	CH-HPR55M-230VO	Heat pump without ducts		34,400	\$4,816
210799636	COOPER&HUNTER	CH-HPR48M-230VO	Heat pump without ducts		36,000	\$5,040
210799631	COOPER&HUNTER	CH-HPR28M-230VO	Heat pump without ducts		26,600	\$3,724
210799628	COOPER&HUNTER	CH-HPR19M-230VO	Heat pump without ducts		15,000	\$2,100
210799692	COOPER&HUNTER	CH-HPR12-230VO	CH-B12MOLVWM-230VI		10,300	\$1,442
210799567	COOPER&HUNTER	CH-HPR12-230VO	CH-12MOLVWM-230VI		10,300	\$1,442
210799568	COOPER&HUNTER	CH-HPR18-230VO	CH-18MOLVWM-230VI		11,100	\$1,554
210799693	COOPER&HUNTER	CH-HPR18-230VO	CH-B18MOLVWM-230VI		11,100	\$1,554
210799694	COOPER&HUNTER	CH-HPR24-230VO	CH-B24MOLVWM-230VI		18,900	\$2,646
210799569	COOPER&HUNTER	CH-HPR24-230VO	CH-24MOLVWM-230VI		18,900	\$2,646
213265589	COOPER&HUNTER	CH-HPR24-230VO	CH-24MFC-W		19,000	\$2,660
210799629	COOPER&HUNTER	CH-HPR19M-230VO	Heat pump with ducts		16,000	\$2,240
210799638	COOPER&HUNTER	CH-HPR48M-230VO	Combination heat pumps with or without ducts		36,000	\$5,040
210799600	Cooper&Hunter	CH-HPR24-230VO	CH-M24DTUI		21,000	\$2,940
210799630	COOPER&HUNTER	CH-HPR19M-230VO	Combination heat pumps with or without ducts		15,500	\$2,170
210799594	Cooper&Hunter	CH-HPR12-230VO	CH-M12DTUI		10,600	\$1,484
210799601	Cooper&Hunter	CH-HPR24-230VO	CH-24MSPHFC-230VI		19,000	\$2,660
210799634	COOPER&HUNTER	CH-HPR36M-230VO	Heat pump without ducts		33,000	\$4,620
210799637	COOPER&HUNTER	CH-HPR48M-230VO	Heat pump with ducts		36,000	\$5,040
210799639	COOPER&HUNTER	CH-HPR36M-230VO	Combination heat pumps with or without ducts		34,000	\$4,760
213265575	COOPER&HUNTER	CH-HPR12-230VO	CH-12MDT-W		10,600	\$1,484
213265579	COOPER&HUNTER	CH-HPR24-230VO	CH-24MDT-W		21,000	\$2,940
216763040	COOPER&HUNTER	CH-RHP15-230VO	CH-PRO15MASTWM-230VI		15,000	\$2,100
216763039	COOPER&HUNTER	CH-RHP15-230VO	CH-RH15MASTWM-230VI		15,000	\$2,100
216706043	COOPER&HUNTER	CH-RHP33-230VO	CH-R33HOLVWM-230VI		29,600	\$4,144
216706045	COOPER&HUNTER	CH-RHP33-230VO	CH-RH33HASTWM-230VI		30,000	\$4,200
216706044	COOPER&HUNTER	CH-RHP33-230VO	CH-PRO33HASTWM-230VI		30,000	\$4,200
215864175	COOPER&HUNTER	CH-RHP18-230VO	CH-PRO18MASTWM-230VI		16,600	\$2,324
215864181	COOPER&HUNTER	CH-RHP18-230VO	CH-RH18MASTWM-230VI		16,600	\$2,324

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864233	COOPER&HUNTER	CH-RHP12-230VO	CH-RSH12MMC		9,800	\$1,372
215864180	COOPER&HUNTER	CH-RHP12-230VO	CH-RH12MASTWM-230VI		9,800	\$1,372
215864174	COOPER&HUNTER	CH-RHP12-230VO	CH-PRO12MASTWM-230VI		9,800	\$1,372
210799607	COOPER&HUNTER	CH-N48LCU-230VO	CH-48LCFC/I		29,000	\$4,060
213265592	COOPER&HUNTER	CH-N48LCU-230VO	CH-48LCFC-W		29,000	\$4,060
215864155	COOPER&HUNTER	CH-RHP24-230VO	CH-R24MOLVWM-230VI		21,600	\$3,024
215864167	COOPER&HUNTER	CH-RHP24-230VO	CH-RB24MOLVWM-230VI		21,600	\$3,024
215864125	COOPER&HUNTER	CH-PQ55-230VO	CH-PQ55AHU		35,000	\$4,900
215864124	COOPER&HUNTER	CH-PQ48-230VO	CH-PQ48AHU		34,000	\$4,760
215864123	COOPER&HUNTER	CH-PQ36-230VO	CH-PQ36AHU		24,600	\$3,444
215864122	COOPER&HUNTER	CH-PQ33-230VO	CH-PQ33AHU		24,000	\$3,360
215864121	COOPER&HUNTER	CH-PQ24-230VO	CH-PQ24AHU		19,000	\$2,660
215864120	COOPER&HUNTER	CH-PQ18-230VO	CH-PQ18AHU		14,700	\$2,058
215864130	COOPER&HUNTER	CH-RHP60LCU-230VO	CH-RS60LCAHU		41,000	\$5,740
215864129	COOPER&HUNTER	CH-RHP48LCU-230VO	CH-RS48LCAHU		40,000	\$5,600
215864128	COOPER&HUNTER	CH-RHP36LCU-230VO	CH-RS36LCAHU		28,000	\$3,920
215864127	COOPER&HUNTER	CH-RHP24-230VO	CH-RS24MAHU		16,900	\$2,366
215864126	COOPER&HUNTER	CH-RHP18-230VO	CH-RS18MAHU		14,000	\$1,960
210799614	Cooper&Hunter	CH-NHPR48LCU-230VO	CH-48LCDTU/I		39,500	\$5,530
210799615	Cooper&Hunter	CH-NHPR48LCU-230VO	CH-48LCFC/I		35,000	\$4,900
213265569	COOPER&HUNTER	CH-NHPR36LCU-230VO	CH-36LCCT-W		33,000	\$4,620
210799610	Cooper&Hunter	CH-NHPR36LCU-230VO	CH-N36LCCT-230VI		33,000	\$4,620
213265571	COOPER&HUNTER	CH-NHPR48LCU-230VO	CH-48LCCT-W		35,000	\$4,900
210799613	Cooper&Hunter	CH-NHPR48LCU-230VO	CH-N48LCCT-230VI		35,000	\$4,900
213265593	COOPER&HUNTER	CH-NHPR48LCU-230VO	CH-48LCFC-W		35,000	\$4,900
213265583	COOPER&HUNTER	CH-NHPR48LCU-230VO	CH-48LCDT-W		39,500	\$5,530
213265610	COOPER&HUNTER	CH-NHPR48LCU-230VO	CH-48AHU-W		38,000	\$5,320
208141208	Cooper&Hunter	CH-NHPR48LCU-230VO	CH-48AHU		38,000	\$5,320
213265612	COOPER&HUNTER	CH-NHPR60LCU-230VO	CH-60AHU-W		41,000	\$5,740
213265608	COOPER&HUNTER	CH-NHPR36LCU-230VO	CH-36AHU-W		28,600	\$4,004
213265585	COOPER&HUNTER	CH-NHPR60LCU-230VO	CH-60LCDT-W		40,000	\$5,600
213265595	COOPER&HUNTER	CH-NHPR60LCU-230VO	CH-60LCFC-W		40,000	\$5,600
213265591	COOPER&HUNTER	CH-NHPR36LCU-230VO	CH-36LCFC-W		32,000	\$4,480
210799612	Cooper&Hunter	CH-NHPR36LCU-230VO	CH-36LCFC/I		32,000	\$4,480
212528018	COOPER&HUNTER	CH-HPR35-230VO	CH-35HASTWM-230VI		28,800	\$4,032
211246029	Cooper&Hunter	CH-NHPR60LCU-230VO	CH-60AHU		41,000	\$5,740
208141207	Cooper&Hunter	CH-NHPR36LCU-230VO	CH-36AHU		28,600	\$4,004

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211246028	COOPER&HUNTER	CH-NHPR60LCU-230VO	CH-60LCDTU/I		40,000	\$5,600
211246027	COOPER&HUNTER	CH-NHPR60LCU-230VO	CH-60LCFC/I		40,000	\$5,600
216773247	CUSTOM COMFORT	CCOXHB24V60HP	CCOBCC4860D		36,000	\$5,040
215746013	CUSTOM COMFORT	CCOXHBMZ536HP	Combination heat pumps with or without ducts		31,400	\$4,396
215746011	CUSTOM COMFORT	CCOXHBMZ536HP	Heat pump without ducts		30,000	\$4,200
212365432	CUSTOM COMFORT	CCOXHASZ17HP	CCOXHA1C18		14,500	\$2,030
212365431	CUSTOM COMFORT	CCOXHASZ12HP	CCOXHA1C12		9,500	\$1,330
212365422	CUSTOM COMFORT	CCOXHASZ12HP	CCOXHAFM12		10,200	\$1,428
212365443	CUSTOM COMFORT	CCOXHAMZ555HP	Heat pump with ducts		35,200	\$4,928
212365412	CUSTOM COMFORT	CCOXHASZ24HP	CCOXHA4C24		21,000	\$2,940
212365417	CUSTOM COMFORT	CCOXHASZ17HP	CCOXHASD18		15,000	\$2,100
212365410	CUSTOM COMFORT	CCOXHASZ12HP	CCOXHA4C12		9,900	\$1,386
212365407	CUSTOM COMFORT	CCOXHASZ24HP	CCOXHAWM24		21,200	\$2,968
212365406	CUSTOM COMFORT	CCOXHASZ17HP	CCOXHAWM18		15,000	\$2,100
212365405	CUSTOM COMFORT	CCOXHASZ12HP	CCOXHAWM12		10,000	\$1,400
212365445	CUSTOM COMFORT	CCOXHASZ17HP	CCOXHAAHU18		15,400	\$2,156
212365446	CUSTOM COMFORT	CCOXHASZ24HP	CCOXHAAHU24		16,900	\$2,366
212365451	CUSTOM COMFORT	CCOXHA24V24HP	CCOXHAAH24V24		19,200	\$2,688
212365450	CUSTOM COMFORT	CCOXHA24V18HP	CCOXHAAH24V18		13,500	\$1,890
212365444	CUSTOM COMFORT	CCOXHAMZ555HP	Combination heat pumps with or without ducts		34,800	\$4,872
212365433	CUSTOM COMFORT	CCOXHAMZ218HP	Heat pump without ducts		15,000	\$2,100
212365439	CUSTOM COMFORT	CCOXHAMZ548HP	Heat pump without ducts		36,000	\$5,040
212365442	CUSTOM COMFORT	CCOXHAMZ555HP	Heat pump without ducts		34,400	\$4,816
212365452	CUSTOM COMFORT	CCOXHA24V30HP	CCOXHAAH24V30		21,000	\$2,940
212365453	CUSTOM COMFORT	CCOXHA24V36HP	CCOXHAAH24V36		30,400	\$4,256
212365416	CUSTOM COMFORT	CCOXHASZ12HP	CCOXHASD12		10,600	\$1,484
212365435	CUSTOM COMFORT	CCOXHAMZ218HP	Combination heat pumps with or without ducts		15,500	\$2,170
212365438	CUSTOM COMFORT	CCOXHAMZ436HP	Combination heat pumps with or without ducts		34,000	\$4,760
212365436	CUSTOM COMFORT	CCOXHAMZ436HP	Heat pump without ducts		33,000	\$4,620
212365418	CUSTOM COMFORT	CCOXHASZ24HP	CCOXHASD24		21,000	\$2,940
212365434	CUSTOM COMFORT	CCOXHAMZ218HP	Heat pump with ducts		16,000	\$2,240
212365425	CUSTOM COMFORT	CCOXHASZ24HP	CCOXHAFM24		19,000	\$2,660
212365440	CUSTOM COMFORT	CCOXHAMZ548HP	Heat pump with ducts		36,000	\$5,040

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212365441	CUSTOM COMFORT	CCOXHAMZ548HP	Combination heat pumps with or without ducts		36,000	\$5,040
212365457	CUSTOM COMFORT	CCOXHA24V24HP	CCOACC1824B		21,000	\$2,940
216773245	CUSTOM COMFORT	CCOXHB24V48HP	CCOBCC4860C		34,400	\$4,816
216773246	CUSTOM COMFORT	CCOXHB24V60HP	CCOBCC4860C		37,800	\$5,292
216773243	CUSTOM COMFORT	CCOXHB24V30HP	CCOBCC3036C		25,000	\$3,500
216773241	CUSTOM COMFORT	CCOXHB24V30HP	CCOBCC3036B		25,000	\$3,500
216773244	CUSTOM COMFORT	CCOXHB24V36HP	CCOBCC3036C		29,200	\$4,088
216773242	CUSTOM COMFORT	CCOXHB24V36HP	CCOBCC3036B		29,200	\$4,088
216773240	CUSTOM COMFORT	CCOXHB24V24HP	CCOBCC1824B		19,700	\$2,758
216773238	CUSTOM COMFORT	CCOXHB24V24HP	CCOBCC1824A		19,700	\$2,758
216773239	CUSTOM COMFORT	CCOXHB24V18HP	CCOBCC1824B		15,200	\$2,128
216773237	CUSTOM COMFORT	CCOXHB24V18HP	CCOBCC1824A		15,200	\$2,128
215745976	CUSTOM COMFORT	CCOXHBSZ17HP	CCOXHBWM18		16,600	\$2,324
215746026	CUSTOM COMFORT	CCOXHB24V18HP	CCOXHBAH24V18		15,000	\$2,100
215745989	CUSTOM COMFORT	CCOXHBSZ12HP	CCOXHBFM12		9,800	\$1,372
215745975	CUSTOM COMFORT	CCOXHBSZ12HP	CCOXHBWM12		9,800	\$1,372
215746027	CUSTOM COMFORT	CCOXHB24V24HP	CCOXHBAH24V24		20,000	\$2,800
215746029	CUSTOM COMFORT	CCOXHB24V36HP	CCOXHBAH24V36		31,800	\$4,452
212365459	CUSTOM COMFORT	CCOXHA24V36HP	CCOACC3036C		33,000	\$4,620
215746001	CUSTOM COMFORT	CCOXHBSZ60CHP	CCOXHBSD60		45,000	\$6,300
215746000	CUSTOM COMFORT	CCOXHBSZ48CHP	CCOXHBSD48		45,000	\$6,300
215745999	CUSTOM COMFORT	CCOXHBSZ36CHP	CCOXHBSD36		31,600	\$4,424
215745987	CUSTOM COMFORT	CCOXHBSZ24HP	CCOXHBSD24		21,600	\$3,024
215745986	CUSTOM COMFORT	CCOXHBSZ17HP	CCOXHBSD18		15,000	\$2,100
215745985	CUSTOM COMFORT	CCOXHBSZ12HP	CCOXHBSD12		10,200	\$1,428
215746019	CUSTOM COMFORT	CCOXHBMZ655HP	Combination heat pumps with or without ducts		44,500	\$6,230
215746018	CUSTOM COMFORT	CCOXHBMZ655HP	Heat pump with ducts		45,000	\$6,300
215746017	CUSTOM COMFORT	CCOXHBMZ655HP	Heat pump without ducts		44,000	\$6,160
215746016	CUSTOM COMFORT	CCOXHBMZ648HP	Combination heat pumps with or without ducts		44,000	\$6,160
215746015	CUSTOM COMFORT	CCOXHBMZ648HP	Heat pump with ducts		44,500	\$6,230
215746014	CUSTOM COMFORT	CCOXHBMZ648HP	Heat pump without ducts		44,000	\$6,160
215746012	CUSTOM COMFORT	CCOXHBMZ536HP	Heat pump with ducts		33,000	\$4,620
215746010	CUSTOM COMFORT	CCOXHBMZ427HP	Combination heat pumps with or without ducts		24,000	\$3,360
215746009	CUSTOM COMFORT	CCOXHBMZ427HP	Heat pump with ducts		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215746008	CUSTOM COMFORT	CCOXHBMZ427HP	Heat pump without ducts		25,000	\$3,500
215746007	CUSTOM COMFORT	CCOXHBMZ318HP	Combination heat pumps with or without ducts		17,300	\$2,422
215746006	CUSTOM COMFORT	CCOXHBMZ318HP	Heat pump with ducts		17,000	\$2,380
215746005	CUSTOM COMFORT	CCOXHBMZ318HP	Heat pump without ducts		17,600	\$2,464
215745992	CUSTOM COMFORT	CCOXHBSZ24HP	CCOXHBFC24		20,200	\$2,828
215745982	CUSTOM COMFORT	CCOXHBSZ24HP	CCOXHB4C24		20,400	\$2,856
215745991	CUSTOM COMFORT	CCOXHBSZ17HP	CCOXHBFC18		14,400	\$2,016
215745990	CUSTOM COMFORT	CCOXHBSZ17HP	CCOXHBFM18		14,200	\$1,988
215745981	CUSTOM COMFORT	CCOXHBSZ17HP	CCOXHB4C18		14,900	\$2,086
215745996	CUSTOM COMFORT	CCOXHBSZ17HP	CCOXHB1C18		14,500	\$2,030
215745980	CUSTOM COMFORT	CCOXHBSZ12HP	CCOXHB4C12		10,000	\$1,400
215745995	CUSTOM COMFORT	CCOXHBSZ12HP	CCOXHB1C12		9,600	\$1,344
215746004	CUSTOM COMFORT	CCOXHBSZ60CHP	CCOXHBFC60		41,000	\$5,740
215746003	CUSTOM COMFORT	CCOXHBSZ48CHP	CCOXHBFC48		38,500	\$5,390
215745998	CUSTOM COMFORT	CCOXHBSZ48CHP	CCOXHB4C48		44,000	\$6,160
215746002	CUSTOM COMFORT	CCOXHBSZ36CHP	CCOXHBFC36		30,200	\$4,228
215745997	CUSTOM COMFORT	CCOXHBSZ36CHP	CCOXHB4C36		30,600	\$4,284
215745978	CUSTOM COMFORT	CCOXHBSZ33HP	CCOXHBWM33		30,000	\$4,200
215745977	CUSTOM COMFORT	CCOXHBSZ24HP	CCOXHBWM24		21,000	\$2,940
215746031	CUSTOM COMFORT	CCOXHB24V60HP	CCOXHBAH24V60		45,000	\$6,300
215746030	CUSTOM COMFORT	CCOXHB24V48HP	CCOXHBAH24V48		37,000	\$5,180
215746028	CUSTOM COMFORT	CCOXHB24V30HP	CCOXHBAH24V30		23,800	\$3,332
215746025	CUSTOM COMFORT	CCOXHBSZ60CHP	CCOXHBAHUC60		41,000	\$5,740
215746024	CUSTOM COMFORT	CCOXHBSZ48CHP	CCOXHBAHUC48		40,000	\$5,600
215746023	CUSTOM COMFORT	CCOXHBSZ36CHP	CCOXHBAHUC36		28,000	\$3,920
215746022	CUSTOM COMFORT	CCOXHBSZ33HP	CCOXHBAHU36		27,400	\$3,836
215746021	CUSTOM COMFORT	CCOXHBSZ24HP	CCOXHBAHU24		16,900	\$2,366
215746020	CUSTOM COMFORT	CCOXHBSZ17HP	CCOXHBAHU18		14,000	\$1,960
213785772	CUSTOM COMFORT	CCOXHA24V30HP	CCOACC3036B		19,600	\$2,744
213307871	CUSTOM COMFORT	CCOXHA24V30HP	CCOEHACC3036B		19,600	\$2,744
212365414	CUSTOM COMFORT	CCOXHASZ48CHP	CCOXHA4C48		35,000	\$4,900
212365413	CUSTOM COMFORT	CCOXHASZ36CHP	CCOXHA4C36		33,000	\$4,620
212365427	CUSTOM COMFORT	CCOXHASZ48CHP	CCOXHAFC48		35,000	\$4,900
212365420	CUSTOM COMFORT	CCOXHASZ48CHP	CCOXHASD48		39,500	\$5,530
212365448	CUSTOM COMFORT	CCOXHASZ48CHP	CCOXHAAHUC48		38,000	\$5,320
213785773	CUSTOM COMFORT	CCOXHA24V36HP	CCOACC3036B		27,400	\$3,836
213307872	CUSTOM COMFORT	CCOXHA24V36HP	CCOEHACC3036B		27,400	\$3,836

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212631690	CUSTOM COMFORT	CCOXHAMZ327HP	Heat pump without ducts		23,000	\$3,220
213879957	CUSTOM COMFORT	CCOXHA24V60HP	CCOEHACC60D		37,000	\$5,180
214391158	CUSTOM COMFORT	CCOXHA24V60HP	CCOACC60D		37,000	\$5,180
212365454	CUSTOM COMFORT	CCOXHA24V48HP	CCOXHAAH24V48		36,000	\$5,040
212365458	CUSTOM COMFORT	CCOXHA24V30HP	CCOACC3036C		22,600	\$3,164
212365447	CUSTOM COMFORT	CCOXHASZ36CHP	CCOXHAAHUC36		28,600	\$4,004
212365455	CUSTOM COMFORT	CCOXHA24V60HP	CCOXHAAH24V60		42,000	\$5,880
212365449	CUSTOM COMFORT	CCOXHASZ60CHP	CCOXHAAHUC60		41,000	\$5,740
212365426	CUSTOM COMFORT	CCOXHASZ36CHP	CCOXHAF36		32,000	\$4,480
212365428	CUSTOM COMFORT	CCOXHASZ60CHP	CCOXHAF60		40,000	\$5,600
212365421	CUSTOM COMFORT	CCOXHASZ60CHP	CCOXHASD60		40,000	\$5,600
212365408	CUSTOM COMFORT	CCOXHASZ33HP	CCOXHAWM33		28,800	\$4,032
212631692	CUSTOM COMFORT	CCOXHAMZ327HP	Combination heat pumps with or without ducts		23,000	\$3,220
216699841	DAIKIN	DH9VSA361CA*	CHPEA4830*3A*	D*97MC0804CNA*	30,800	\$4,312
216699839	DAIKIN	DH9VSA361CA*	CHPEA4830*3A*	D*97MC1005CNA*	30,800	\$4,312
216699837	DAIKIN	DH9VSA361CA*	CHPEA4830*3A*	D*80SC0805CUA*	30,800	\$4,312
216699835	DAIKIN	DH9VSA361CA*	CHPEA4830*3A*	D*80TC0804C*A*	30,800	\$4,312
216699833	DAIKIN	DH9VSA361CA*	CHPEA4830*3A*	D*80TC0805C*A*	30,800	\$4,312
216699831	DAIKIN	DH9VSA361CA*	CHPEA4830*3A*	D*80TC1005C*A*	30,800	\$4,312
216699829	DAIKIN	DH9VSA361CA*	CHPEA4830*3A*	D*96TC0804CNA*	30,800	\$4,312
216699827	DAIKIN	DH9VSA361CA*	CHPEA4830*3A*	D*96TC1005CNA*	30,800	\$4,312
216699825	DAIKIN	DH9VSA361CA*	CHPEA4830*3A*+MBVK16C P1X00A*		30,800	\$4,312
217049704	DAIKIN	DH7VSA6010A*	CAHEA3630C3A*+MBVK16C H*X00A*		33,400	\$4,676
217049703	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*97MC1005CNA*	33,400	\$4,676
217049702	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*97MC1005CNA*	33,400	\$4,676
217049701	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*97MC1205DNA*	33,400	\$4,676
217049700	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*97MC1205DNA*	33,400	\$4,676
217049699	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*80SC0805CUA*	33,400	\$4,676
217049698	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*80SC0805CUA*	33,400	\$4,676
217049697	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*80TC0804C*A*	33,400	\$4,676
217049696	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*80TC0804C*A*	33,400	\$4,676
217049695	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*80TC0805C*A*	33,400	\$4,676
217049694	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*80TC0805C*A*	33,400	\$4,676
217049693	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*80TC0805D*A*	33,400	\$4,676
217049692	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*80TC0805D*A*	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
217049691	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*80TC1005C*A*	33,400	\$4,676
217049690	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*80TC1005C*A*	33,400	\$4,676
217049689	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*96TC0804CNA*	33,400	\$4,676
217049688	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*96TC0804CNA*	33,400	\$4,676
217049687	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*96TC1005CNA*	33,400	\$4,676
217049686	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*96TC1005CNA*	33,400	\$4,676
217049685	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*96TC1005DNA*	33,400	\$4,676
217049684	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*96TC1005DNA*	33,400	\$4,676
217049683	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*	D*96TC1205DNA*	33,400	\$4,676
217049682	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*	D*96TC1205DNA*	33,400	\$4,676
217049681	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*+MBVK16CP1X00A*		33,400	\$4,676
217049680	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*+MBVK16CP1X00A*		33,400	\$4,676
217049679	DAIKIN	DH7VSA6010A*	CA*EA6030*3A*+MBVK20DP1X00A*		33,400	\$4,676
217049678	DAIKIN	DH7VSA6010A*	CHPEA6030*3A*+MBVK20DP1X00A*		33,400	\$4,676
217049677	DAIKIN	DH7VSA6010A*	DFVE60DP0300A*		33,400	\$4,676
217049676	DAIKIN	DH7VSA6010A*	DFVE60DP1300A*		33,400	\$4,676
2109791258	DAIKIN	DZ6VSA3010A*	DV35FECC14A*		17,600	\$2,464
210722659	DAIKIN	2MXS18WMVJU*	Heat pump without ducts		12,000	\$1,680
210722664	DAIKIN	2MXL18WMVJU*	Heat pump without ducts		12,000	\$1,680
210722661	DAIKIN	3MXS24WMVJU*	Heat pump without ducts		15,500	\$2,170
210722663	DAIKIN	5MXS48WVJU*	Heat pump without ducts		31,000	\$4,340
205663350	DAIKIN	RXL15QMVJU*	FVXS15NVJU		11,500	\$1,610
213797272	DAIKIN	RXL15WMVJU*	FVXS15NVJU		11,500	\$1,610
213797274	DAIKIN	RXL24WMVJU*	FTX24UVJU		15,800	\$2,212
213797278	DAIKIN	RXM24WVJU*	FTXM24VVJU		16,000	\$2,240
213797276	DAIKIN	RXM12WVJU*	FTXM12VVJU		8,600	\$1,204
216699792	DAIKIN	DH9VSA361CA*	CAHEA3630C3A*+MBVK16CH*X00A*		34,200	\$4,788
216699791	DAIKIN	DH9VSA241CA*	CAHEA3630C3A*+MBVK16CH*X00A*		24,000	\$3,360
216699842	DAIKIN	DH9VSA361CA*	CA*EA6030*3A*	D*97MC0804CNA*	31,000	\$4,340
216699840	DAIKIN	DH9VSA361CA*	CA*EA6030*3A*	D*97MC1005CNA*	31,000	\$4,340
216699838	DAIKIN	DH9VSA361CA*	CA*EA6030*3A*	D*80SC0805CUA*	31,000	\$4,340
216699836	DAIKIN	DH9VSA361CA*	CA*EA6030*3A*	D*80TC0804C*A*	31,000	\$4,340
216699834	DAIKIN	DH9VSA361CA*	CA*EA6030*3A*	D*80TC0805C*A*	31,000	\$4,340

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216699832	DAIKIN	DH9VSA361CA*	CA*EA6030*3A*	D*80TC1005C*A*	31,000	\$4,340
216699830	DAIKIN	DH9VSA361CA*	CA*EA6030*3A*	D*96TC0804CNA*	31,000	\$4,340
216699828	DAIKIN	DH9VSA361CA*	CA*EA6030*3A*	D*96TC1005CNA*	31,000	\$4,340
216699826	DAIKIN	DH9VSA361CA*	CA*EA6030*3A*+MBVK16CP1X00A*		31,000	\$4,340
216699824	DAIKIN	DH9VSA361CA*	DFVE48CP0300A*		32,000	\$4,480
216699823	DAIKIN	DH9VSA361CA*	DFVE48CP1300A*		32,000	\$4,480
216699822	DAIKIN	DH9VSA361CA*	DFVE48DP0300A*		32,000	\$4,480
216699821	DAIKIN	DH9VSA361CA*	DFVE48DP1300A*		32,000	\$4,480
216699820	DAIKIN	DH9VSA361CA*	DFVE60DP0300A*		32,000	\$4,480
216699819	DAIKIN	DH9VSA361CA*	DFVE60DP1300A*		32,000	\$4,480
216699818	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*	D*97MC0804CNA*	22,000	\$3,080
216699817	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*	D*97MC0804CNA*	21,000	\$2,940
216699816	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*	D*97MC1005CNA*	22,000	\$3,080
216699815	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*	D*97MC1005CNA*	21,000	\$2,940
216699814	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*	D*80SC0805CUA*	22,000	\$3,080
216699813	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*	D*80SC0805CUA*	21,000	\$2,940
216699812	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*	D*96SC0805CUA*	22,000	\$3,080
216699811	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*	D*96SC0805CUA*	21,000	\$2,940
216699810	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*	D*80TC0804C*A*	22,000	\$3,080
216699809	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*	D*80TC0804C*A*	21,000	\$2,940
216699808	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*	D*80TC0805C*A*	22,000	\$3,080
216699807	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*	D*80TC0805C*A*	21,000	\$2,940
216699806	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*	D*80TC1005C*A*	22,000	\$3,080
216699805	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*	D*80TC1005C*A*	21,000	\$2,940
216699804	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*	D*96TC0804CNA*	22,000	\$3,080
216699803	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*	D*96TC0804CNA*	21,000	\$2,940
216699802	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*	D*96TC1005CNA*	22,000	\$3,080
216699801	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*	D*96TC1005CNA*	21,000	\$2,940
216699800	DAIKIN	DH9VSA241CA*	CA*EA4830*3A*+MBVK16CP1X00A*		22,000	\$3,080
216699799	DAIKIN	DH9VSA241CA*	CHPEA4830*3A*+MBVK16CP1X00A*		21,000	\$2,940
216699798	DAIKIN	DH9VSA241CA*	DFVE48CP0300A*		23,000	\$3,220
216699797	DAIKIN	DH9VSA241CA*	DFVE48CP1300A*		23,000	\$3,220
216618814	DAIKIN	RXT15AVJU*	FTXV15AVJU*		13,000	\$1,820
214025276	DAIKIN	RZQ36TBVJU*	FTQ36TBVJU*A*		28,400	\$3,976
214025273	DAIKIN	RZQ30TBVJU*	FTQ30TBVJU*A*		24,000	\$3,360

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214725904	DAIKIN	RZQ18TBVJU*	FTQ18TBVJU*A*		13,600	\$1,904
205663349	DAIKIN	RXL15QMVMJU*	FTX15NMVMJU*		11,500	\$1,610
213872282	DAIKIN	DZ6VSA421EA*	CAPEA6030*4A*	D*80VC0804C*A*	27,800	\$3,892
213872276	DAIKIN	DZ6VSA481EA*	CAPEA6030*4A*	D*80VC1005C*A*	28,000	\$3,920
214491628	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*80SC0604BUA*	10,800	\$1,512
214491629	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*80VC0603B*A*	10,800	\$1,512
214491630	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*80VC0604B*A*	10,800	\$1,512
214491631	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*80VC0803B*A*	10,800	\$1,512
214491632	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*96SC0603BUA*	10,800	\$1,512
214491633	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*96VC0403BNA*	10,800	\$1,512
214491634	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*96VC0603BNA*	10,800	\$1,512
214491635	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*96VC0803BNA*	10,800	\$1,512
214491636	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*97MC0603BNA*	10,800	\$1,512
214491637	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*97MC0803BNA*	10,800	\$1,512
214491638	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*+MBVC1200* *-1A*		10,800	\$1,512
214491639	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*80SC0805CUA*	10,800	\$1,512
214491640	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*80VC0804C*A*	10,800	\$1,512
214491641	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*80VC0805C*A*	10,800	\$1,512
214491642	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*96SC0805CUA*	10,800	\$1,512
214491643	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*96VC0804CNA*	10,800	\$1,512
214491644	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*	D*97MC0804CNA*	10,800	\$1,512
214491645	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*+MBVC1600* *-1A*		10,800	\$1,512
214491646	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*80SC0604BUA*	10,800	\$1,512
214491647	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*80VC0603B*A*	10,800	\$1,512
214491648	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*80VC0604B*A*	10,800	\$1,512
214491649	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*80VC0803B*A*	10,800	\$1,512
214491650	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*96SC0603BUA*	10,800	\$1,512
214491651	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*96VC0403BNA*	10,800	\$1,512
214491652	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*96VC0603BNA*	10,800	\$1,512
214491653	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*96VC0803BNA*	10,800	\$1,512
214491654	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*97MC0603BNA*	10,800	\$1,512
214491655	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*97MC0803BNA*	10,800	\$1,512
214491656	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*+MBVC1200* *-1A*		10,800	\$1,512
214491657	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*80SC0805CUA*	10,800	\$1,512
214491658	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*80VC0804C*A*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214491659	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*80VC0805C*A*	10,800	\$1,512
214491660	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*96SC0805CUA*	10,800	\$1,512
214491661	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*96VC0804CNA*	10,800	\$1,512
214491662	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*	D*97MC0804CNA*	10,800	\$1,512
214491663	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*+MBVC1600* *-1A*		10,800	\$1,512
214500305	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*+MBVK12BP 1X00A*		10,800	\$1,512
214500306	DAIKIN	DZ6VSA1810A*	CA*EA1818*4B*+MBVK16CP 1X00A*		10,800	\$1,512
214500307	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*+MBVK12BP 1X00A*		10,800	\$1,512
214500308	DAIKIN	DZ6VSA1810A*	CA*EA2422*4B*+MBVK16CP 1X00A*		10,800	\$1,512
214505160	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*+MBVC1200* *-1A*		16,000	\$2,240
214505163	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*+MBVC1600* *-1A*		16,000	\$2,240
214505166	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*80VC0603B*A*	16,000	\$2,240
214505169	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*80VC0604B*A*	16,000	\$2,240
214505171	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*80SC0604BUA*	16,000	\$2,240
214505174	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*80VC0803B*A*	16,000	\$2,240
214505177	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*80VC0804C*A*	16,000	\$2,240
214505179	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*80VC0805C*A*	16,000	\$2,240
214505182	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*80SC0805CUA*	16,000	\$2,240
214505185	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*80VC1005C*A*	16,000	\$2,240
214505187	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*96VC0403BNA*	16,000	\$2,240
214505190	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*96VC0603BNA*	16,000	\$2,240
214505193	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*96SC0603BUA*	16,000	\$2,240
214505196	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*96VC0803BNA*	16,000	\$2,240
214505199	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*96VC0804CNA*	16,000	\$2,240
214505202	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*96SC0805CUA*	16,000	\$2,240
214505205	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*96VC1005CNA*	16,000	\$2,240
214505208	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*97MC0603BNA*	16,000	\$2,240
214505211	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*97MC0803BNA*	16,000	\$2,240
214505214	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*97MC0804CNA*	16,000	\$2,240
214505217	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*	D*97MC1005CNA*	16,000	\$2,240
214505221	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*+MBVC1200* *-1A*		16,000	\$2,240

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214505225	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*+MBVC1600* *-1A*		16,000	\$2,240
214505227	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*80VC0603B*A*	16,000	\$2,240
214505231	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*80VC0604B*A*	16,000	\$2,240
214505234	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*80SC0604BUA*	16,000	\$2,240
214505238	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*80VC0803B*A*	16,000	\$2,240
214505242	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*80VC0804C*A*	16,000	\$2,240
214505245	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*80VC0805C*A*	16,000	\$2,240
214505248	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*80SC0805CUA*	16,000	\$2,240
214505250	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*80VC1005C*A*	16,000	\$2,240
214505252	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*96VC0403BNA*	16,000	\$2,240
214505254	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*96VC0603BNA*	16,000	\$2,240
214505256	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*96SC0603BUA*	16,000	\$2,240
214505257	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*96VC0803BNA*	16,000	\$2,240
214505260	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*96VC0804CNA*	16,000	\$2,240
214505262	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*96SC0805CUA*	16,000	\$2,240
214505264	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*96VC1005CNA*	16,000	\$2,240
214505266	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*97MC0603BNA*	16,000	\$2,240
214505268	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*97MC0803BNA*	16,000	\$2,240
214505270	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*97MC0804CNA*	16,000	\$2,240
214505271	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*	D*97MC1005CNA*	16,000	\$2,240
214505401	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*+MBVK12BP 1X00A*		16,000	\$2,240
214505403	DAIKIN	DZ6VSA241EA*	CA*EA2422*4B*+MBVK16CP 1X00A*		16,000	\$2,240
214505405	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*+MBVK12BP 1X00A*		16,000	\$2,240
214505408	DAIKIN	DZ6VSA241EA*	CA*EA3026*4B*+MBVK16CP 1X00A*		16,000	\$2,240
215487462	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*96VC1205DNA*	29,000	\$4,060
215487461	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*96VC1005DNA*	29,000	\$4,060
215487460	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*80VC0805D*A*	29,000	\$4,060
215487459	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*96VC1005CNA*	29,000	\$4,060
215487458	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*96VC0804CNA*	29,000	\$4,060
215487457	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*80VC1005C*A*	29,000	\$4,060
215487456	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*80VC0805C*A*	29,000	\$4,060
215487455	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*80VC0804C*A*	29,000	\$4,060
215487454	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*96VC1205DNA*	28,400	\$3,976

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215487453	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*96VC1005DNA*	28,400	\$3,976
215487452	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*80VC0805D*A*	28,400	\$3,976
215487451	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*96VC1005CNA*	28,400	\$3,976
215487450	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*96VC0804CNA*	28,400	\$3,976
215487449	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*80VC1005C*A*	28,400	\$3,976
215487448	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*80VC0805C*A*	28,400	\$3,976
215487447	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*80VC0804C*A*	28,400	\$3,976
215487446	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*96VC1205DNA*	29,000	\$4,060
215487445	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*96VC1005DNA*	29,000	\$4,060
215487444	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*80VC0805D*A*	29,000	\$4,060
215487443	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*96VC1005CNA*	29,000	\$4,060
215487442	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*96VC0804CNA*	29,000	\$4,060
215487441	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*80VC1005C*A*	29,000	\$4,060
215487440	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*80VC0805C*A*	29,000	\$4,060
215487439	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*80VC0804C*A*	29,000	\$4,060
215487438	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*96VC1205DNA*	28,000	\$3,920
215487437	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*96VC1005DNA*	28,000	\$3,920
215487436	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*96VC1005CNA*	28,000	\$3,920
215487435	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*96VC0804CNA*	28,000	\$3,920
215487434	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*80VC1005C*A*	28,000	\$3,920
215487433	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*80VC0805D*A*	28,000	\$3,920
215487432	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*80VC0805C*A*	28,000	\$3,920
215487431	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*80VC0804C*A*	28,000	\$3,920
215487430	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*96VC1205DNA*	28,000	\$3,920
215487429	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*96VC1005DNA*	28,000	\$3,920
215487428	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*96VC1005CNA*	28,000	\$3,920
215487427	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*96VC0804CNA*	28,000	\$3,920
215487426	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*80VC1005C*A*	28,000	\$3,920
215487425	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*80VC0805D*A*	28,000	\$3,920
215487424	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*80VC0805C*A*	28,000	\$3,920
215487423	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*80VC0804C*A*	28,000	\$3,920
215487422	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*96VC1205DNA*	28,000	\$3,920
215487421	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*96VC1005DNA*	28,000	\$3,920
215487420	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*96VC1005CNA*	28,000	\$3,920
215487419	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*96VC0804CNA*	28,000	\$3,920
215487418	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*80VC1005C*A*	28,000	\$3,920
215487417	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*80VC0805D*A*	28,000	\$3,920
215487416	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*80VC0805C*A*	28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215487415	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*80VC0804C*A*	28,000	\$3,920
215487414	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*80VC0804C*A*	22,000	\$3,080
215487413	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*80VC0805C*A*	22,000	\$3,080
215487412	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*80VC0805D*A*	22,000	\$3,080
215487411	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*80VC1005C*A*	22,000	\$3,080
215487410	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*96VC0804CNA*	22,000	\$3,080
215487409	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*96VC1005CNA*	22,000	\$3,080
215487408	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*96VC1005DNA*	22,000	\$3,080
215487407	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*96VC1205DNA*	22,000	\$3,080
215487406	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*80VC0804C*A*	22,000	\$3,080
215487405	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*80VC0805C*A*	22,000	\$3,080
215487404	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*80VC0805D*A*	22,000	\$3,080
215487403	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*80VC1005C*A*	22,000	\$3,080
215487402	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*80VC0804C*A*	22,000	\$3,080
215487401	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*80VC0805C*A*	22,000	\$3,080
215487400	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*80VC0805D*A*	22,000	\$3,080
215487399	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*80VC1005C*A*	22,000	\$3,080
215487398	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*96VC0804CNA*	22,000	\$3,080
215487397	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*96VC1005CNA*	22,000	\$3,080
215487396	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*96VC1005DNA*	22,000	\$3,080
215487395	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*96VC1205DNA*	22,000	\$3,080
215487394	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96VC1005CNA*	15,800	\$2,212
215487393	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96VC0804CNA*	15,800	\$2,212
215487392	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96VC0803BNA*	15,800	\$2,212
215487391	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96VC0603BNA*	15,800	\$2,212
215487390	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96VC0403BNA*	15,800	\$2,212
215487389	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80VC1005C*A*	15,800	\$2,212
215487388	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80VC0805C*A*	15,800	\$2,212
215487387	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80VC0804C*A*	15,800	\$2,212
215487386	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80VC0803B*A*	15,800	\$2,212
215487385	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80VC0604B*A*	15,800	\$2,212
215487384	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80VC0603B*A*	15,800	\$2,212
215487383	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96VC1005CNA*	15,800	\$2,212
215487382	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96VC0804CNA*	15,800	\$2,212
215487381	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96VC0803BNA*	15,800	\$2,212
215487380	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96VC0603BNA*	15,800	\$2,212
215487379	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96VC0403BNA*	15,800	\$2,212
215487378	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80VC1005C*A*	15,800	\$2,212

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215487377	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80VC0805C*A*	15,800	\$2,212
215487376	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80VC0804C*A*	15,800	\$2,212
215487375	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80VC0803B*A*	15,800	\$2,212
215487374	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80VC0604B*A*	15,800	\$2,212
215487373	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80VC0603B*A*	15,800	\$2,212
215487372	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96VC1005CNA*	15,800	\$2,212
215487371	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96VC0804CNA*	15,800	\$2,212
215487370	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96VC0803BNA*	15,800	\$2,212
215487369	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96VC0603BNA*	15,800	\$2,212
215487368	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96VC0403BNA*	15,800	\$2,212
215487367	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80VC1005C*A*	15,800	\$2,212
215487366	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80VC0805C*A*	15,800	\$2,212
215487365	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80VC0804C*A*	15,800	\$2,212
215487364	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80VC0803B*A*	15,800	\$2,212
215487363	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80VC0603B*A*	15,800	\$2,212
215439657	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80TC0603B*A*	10,800	\$1,512
215439656	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80TC0603B*A*	10,800	\$1,512
215439655	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*80TC0603B*A*	10,800	\$1,512
215439654	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80TC0604B*A*	10,800	\$1,512
215439653	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80TC0604B*A*	10,800	\$1,512
215439652	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*80TC0604B*A*	10,800	\$1,512
215439651	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80TC0803B*A*	10,800	\$1,512
215439650	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80TC0803B*A*	10,800	\$1,512
215439649	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*80TC0803B*A*	10,800	\$1,512
215439648	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80TC0804C*A*	10,800	\$1,512
215439647	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80TC0804C*A*	10,800	\$1,512
215439646	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80TC0805C*A*	10,800	\$1,512
215439645	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80TC0805C*A*	10,800	\$1,512
215439644	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96TC0403BNA*	10,800	\$1,512
215439643	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96TC0403BNA*	10,800	\$1,512
215439642	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*96TC0403BNA*	10,800	\$1,512
215439641	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96TC0603BNA*	10,800	\$1,512
215439640	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96TC0603BNA*	10,800	\$1,512
215439639	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*96TC0603BNA*	10,800	\$1,512
215439638	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96TC0803BNA*	10,800	\$1,512
215439637	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96TC0803BNA*	10,800	\$1,512
215439636	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*96TC0803BNA*	10,800	\$1,512
215439635	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96TC0804CNA*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215439634	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96TC0804CNA*	10,800	\$1,512
215439675	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*97MC0603BNA*	10,800	\$1,512
215439674	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*97MC0603BNA*	10,800	\$1,512
215439673	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*97MC0603BNA*	10,800	\$1,512
215439672	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*97MC0803BNA*	10,800	\$1,512
215439671	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*97MC0803BNA*	10,800	\$1,512
215439670	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*97MC0803BNA*	10,800	\$1,512
215439669	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*97MC0804CNA*	10,800	\$1,512
215439668	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*97MC0804CNA*	10,800	\$1,512
215439667	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80SC0604BUA*	10,800	\$1,512
215439666	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80SC0604BUA*	10,800	\$1,512
215439665	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*80SC0604BUA*	10,800	\$1,512
215439664	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80SC0805CUA*	10,800	\$1,512
215439663	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80SC0805CUA*	10,800	\$1,512
215439662	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96SC0603BUA*	10,800	\$1,512
215439661	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96SC0603BUA*	10,800	\$1,512
215439660	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*96SC0603BUA*	10,800	\$1,512
215439659	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96SC0805CUA*	10,800	\$1,512
215439658	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96SC0805CUA*	10,800	\$1,512
215487486	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80VC0603B*A*	10,800	\$1,512
215487485	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80VC0603B*A*	10,800	\$1,512
215487484	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*80VC0603B*A*	10,800	\$1,512
215487483	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80VC0604B*A*	10,800	\$1,512
215487482	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80VC0604B*A*	10,800	\$1,512
215487481	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*80VC0604B*A*	10,800	\$1,512
215487480	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80VC0803B*A*	10,800	\$1,512
215487479	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80VC0803B*A*	10,800	\$1,512
215487478	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*80VC0803B*A*	10,800	\$1,512
215487477	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80VC0804C*A*	10,800	\$1,512
215487476	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80VC0804C*A*	10,800	\$1,512
215487475	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*80VC0805C*A*	10,800	\$1,512
215487474	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*80VC0805C*A*	10,800	\$1,512
215487473	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96VC0403BNA*	10,800	\$1,512
215487472	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96VC0403BNA*	10,800	\$1,512
215487471	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*96VC0403BNA*	10,800	\$1,512
215487470	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96VC0603BNA*	10,800	\$1,512
215487469	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96VC0603BNA*	10,800	\$1,512
215487468	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*96VC0603BNA*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215487467	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96VC0803BNA*	10,800	\$1,512
215487466	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96VC0803BNA*	10,800	\$1,512
215487465	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*	D*96VC0803BNA*	10,800	\$1,512
215487464	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*	D*96VC0804CNA*	10,800	\$1,512
215487463	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*	D*96VC0804CNA*	10,800	\$1,512
215439764	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*+MBVK12BP1X00A*		10,800	\$1,512
215439763	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*+MBVK12BP1X00A*		10,800	\$1,512
215439762	DAIKIN	DH6VSA1810A*	CHPEA2422*3A*+MBVK12BP1X00A*		10,800	\$1,512
215439761	DAIKIN	DH6VSA1810A*	CA*EA2418*3A*+MBVK16CP1X00A*		10,800	\$1,512
215439760	DAIKIN	DH6VSA1810A*	CA*EA3022*3A*+MBVK16CP1X00A*		10,800	\$1,512
215429753	DAIKIN	DH6VSA1810A*	DFVE24BP0300A*		10,800	\$1,512
215415502	DAIKIN	DH6VSA1810A*	DFVE24BP1300A*		10,800	\$1,512
215389736	DAIKIN	RXT24AVJU*	FTXV24AVJU*		16,800	\$2,352
215389735	DAIKIN	RXT18AVJU*	FTXV18AVJU*		15,200	\$2,128
214837761	DAIKIN	2MXT18AVJU*	Heat pump without ducts		12,000	\$1,680
214837760	DAIKIN	2MXT18AVJU*	Heat pump without ducts		12,000	\$1,680
214837759	DAIKIN	4MXM36AVJU*	Heat pump without ducts		21,600	\$3,024
214837758	DAIKIN	3MXM24AVJU*	Heat pump without ducts		15,500	\$2,170
214837757	DAIKIN	2MXM18AVJU*	Heat pump without ducts		12,000	\$1,680
215433952	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*+MBVK20DP1X00A*		29,000	\$4,060
215434386	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*97MC1205DNA*	29,000	\$4,060
215434385	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*96TC1205DNA*	29,000	\$4,060
215434384	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*96TC1005DNA*	29,000	\$4,060
215434383	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*80TC0805D*A*	29,000	\$4,060
215433951	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*+MBVK16CP1X00A*		29,000	\$4,060
215434382	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*97MC1005CNA*	29,000	\$4,060
215434381	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*97MC0804CNA*	29,000	\$4,060
215434380	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*96TC1005CNA*	29,000	\$4,060
215434379	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*96TC0804CNA*	29,000	\$4,060
215434378	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*96SC0805CUA*	29,000	\$4,060
215434377	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*80TC1005C*A*	29,000	\$4,060
215434376	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*80TC0805C*A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434375	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*80TC0804C*A*	29,000	\$4,060
215434374	DAIKIN	DH7VSA4810A*	CHPEA6030*3A*	D*80SC0805CUA*	29,000	\$4,060
215433950	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*+MBVK20D P1X00A*		28,400	\$3,976
215434373	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*97MC1205DNA*	28,400	\$3,976
215434372	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*96TC1205DNA*	28,400	\$3,976
215434371	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*96TC1005DNA*	28,400	\$3,976
215434370	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*80TC0805D*A*	28,400	\$3,976
215433949	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*+MBVK16C P1X00A*		28,400	\$3,976
215434369	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*97MC1005CNA*	28,400	\$3,976
215434368	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*97MC0804CNA*	28,400	\$3,976
215434367	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*96TC1005CNA*	28,400	\$3,976
215434366	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*96TC0804CNA*	28,400	\$3,976
215434365	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*96SC0805CUA*	28,400	\$3,976
215434364	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*80TC1005C*A*	28,400	\$3,976
215434363	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*80TC0805C*A*	28,400	\$3,976
215434362	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*80TC0804C*A*	28,400	\$3,976
215434361	DAIKIN	DH7VSA4810A*	CHPEA4830*3A*	D*80SC0805CUA*	28,400	\$3,976
215433948	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*+MBVK20DP 1X00A*		29,000	\$4,060
215434360	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*97MC1205DNA*	29,000	\$4,060
215434359	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*96TC1205DNA*	29,000	\$4,060
215434358	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*96TC1005DNA*	29,000	\$4,060
215434357	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*80TC0805D*A*	29,000	\$4,060
215433947	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*+MBVK16CP 1X00A*		29,000	\$4,060
215434356	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*97MC1005CNA*	29,000	\$4,060
215434355	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*97MC0804CNA*	29,000	\$4,060
215434354	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*96TC1005CNA*	29,000	\$4,060
215434353	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*96TC0804CNA*	29,000	\$4,060
215434352	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*96SC0805CUA*	29,000	\$4,060
215434351	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*80TC1005C*A*	29,000	\$4,060
215434350	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*80TC0805C*A*	29,000	\$4,060
215434349	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*80TC0804C*A*	29,000	\$4,060
215434348	DAIKIN	DH7VSA4810A*	CA*EA6030*3A*	D*80SC0805CUA*	29,000	\$4,060
215429732	DAIKIN	DH7VSA4810A*	DFVE60DP0300A*		29,000	\$4,060
215415511	DAIKIN	DH7VSA4810A*	DFVE60DP1300A*		29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215433934	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*+MBVK20D P1X00A*		28,000	\$3,920
215433933	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*+MBVK16C P1X00A*		28,000	\$3,920
215434269	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*96TC1205DNA*	28,000	\$3,920
215434268	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*96TC1005DNA*	28,000	\$3,920
215434267	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*96TC1005CNA*	28,000	\$3,920
215434266	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*96TC0804CNA*	28,000	\$3,920
215434265	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*80TC1005C*A*	28,000	\$3,920
215434264	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*80TC0805D*A*	28,000	\$3,920
215434263	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*80TC0805C*A*	28,000	\$3,920
215434262	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*80TC0804C*A*	28,000	\$3,920
215434261	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*96SC0805CUA*	28,000	\$3,920
215434260	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*80SC0805CUA*	28,000	\$3,920
215434259	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*97MC1205DNA*	28,000	\$3,920
215434258	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*97MC1005CNA*	28,000	\$3,920
215434257	DAIKIN	DH7VSA4210A*	CHPEA6030*3A*	D*97MC0804CNA*	28,000	\$3,920
215433932	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*+MBVK20D P1X00A*		28,000	\$3,920
215433931	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*+MBVK16C P1X00A*		28,000	\$3,920
215434256	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*96TC1205DNA*	28,000	\$3,920
215434255	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*96TC1005DNA*	28,000	\$3,920
215434254	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*96TC1005CNA*	28,000	\$3,920
215434253	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*96TC0804CNA*	28,000	\$3,920
215434252	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*80TC1005C*A*	28,000	\$3,920
215434251	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*80TC0805D*A*	28,000	\$3,920
215434250	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*80TC0805C*A*	28,000	\$3,920
215434249	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*80TC0804C*A*	28,000	\$3,920
215434248	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*96SC0805CUA*	28,000	\$3,920
215434247	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*80SC0805CUA*	28,000	\$3,920
215434246	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*97MC1205DNA*	28,000	\$3,920
215434245	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*97MC1005CNA*	28,000	\$3,920
215434244	DAIKIN	DH7VSA4210A*	CHPEA4830*3A*	D*97MC0804CNA*	28,000	\$3,920
215433930	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*+MBVK20DP 1X00A*		28,000	\$3,920
215433929	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*+MBVK16CP 1X00A*		28,000	\$3,920
215434243	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*96TC1205DNA*	28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434242	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*96TC1005DNA*	28,000	\$3,920
215434241	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*96TC1005CNA*	28,000	\$3,920
215434240	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*96TC0804CNA*	28,000	\$3,920
215434239	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*80TC1005C*A*	28,000	\$3,920
215434238	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*80TC0805D*A*	28,000	\$3,920
215434237	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*80TC0805C*A*	28,000	\$3,920
215434236	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*80TC0804C*A*	28,000	\$3,920
215434235	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*96SC0805CUA*	28,000	\$3,920
215434234	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*80SC0805CUA*	28,000	\$3,920
215434233	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*97MC1205DNA*	28,000	\$3,920
215434232	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*97MC1005CNA*	28,000	\$3,920
215434231	DAIKIN	DH7VSA4210A*	CA*EA6030*3A*	D*97MC0804CNA*	28,000	\$3,920
215429731	DAIKIN	DH7VSA4210A*	DFVE60DP0300A*		28,000	\$3,920
215415510	DAIKIN	DH7VSA4210A*	DFVE60DP1300A*		28,000	\$3,920
215434166	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*97MC0804CNA*	22,000	\$3,080
215434165	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*97MC1005CNA*	22,000	\$3,080
215434164	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*97MC1205DNA*	22,000	\$3,080
215434163	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*80SC0805CUA*	22,000	\$3,080
215434162	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*96SC0805CUA*	22,000	\$3,080
215434161	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*80TC0804C*A*	22,000	\$3,080
215434160	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*80TC0805C*A*	22,000	\$3,080
215434159	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*80TC0805D*A*	22,000	\$3,080
215434158	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*80TC1005C*A*	22,000	\$3,080
215434157	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*96TC0804CNA*	22,000	\$3,080
215434156	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*96TC1005CNA*	22,000	\$3,080
215434155	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*96TC1005DNA*	22,000	\$3,080
215434154	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*	D*96TC1205DNA*	22,000	\$3,080
215433916	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*+MBVK16C P1X00A*		22,000	\$3,080
215433915	DAIKIN	DH7VSA3610A*	CHPEA4830*3A*+MBVK20D P1X00A*		22,000	\$3,080
215434153	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*80SC0805CUA*	22,000	\$3,080
215434152	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*96SC0805CUA*	22,000	\$3,080
215434151	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*80TC0804C*A*	22,000	\$3,080
215434150	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*80TC0805C*A*	22,000	\$3,080
215434149	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*80TC0805D*A*	22,000	\$3,080
215434148	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*	D*80TC1005C*A*	22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215433914	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*+MBVK16CP1X00A*		22,000	\$3,080
215433913	DAIKIN	DH7VSA3610A*	CA*EA6030*3A*+MBVK20DP1X00A*		22,000	\$3,080
215434147	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*97MC0804CNA*	22,000	\$3,080
215434146	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*97MC1005CNA*	22,000	\$3,080
215434145	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*97MC1205DNA*	22,000	\$3,080
215434144	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*80SC0805CUA*	22,000	\$3,080
215434143	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*96SC0805CUA*	22,000	\$3,080
215434142	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*80TC0804C*A*	22,000	\$3,080
215434141	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*80TC0805C*A*	22,000	\$3,080
215434140	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*80TC0805D*A*	22,000	\$3,080
215434139	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*80TC1005C*A*	22,000	\$3,080
215434138	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*96TC0804CNA*	22,000	\$3,080
215434137	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*96TC1005CNA*	22,000	\$3,080
215434136	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*96TC1005DNA*	22,000	\$3,080
215434135	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*	D*96TC1205DNA*	22,000	\$3,080
215433912	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*+MBVK16CP1X00A*		22,000	\$3,080
215433911	DAIKIN	DH7VSA3610A*	CA*EA4830*3A*+MBVK20DP1X00A*		22,000	\$3,080
215429730	DAIKIN	DH7VSA3610A*	DFVE60DP0300A*		22,000	\$3,080
215429729	DAIKIN	DH7VSA3610A*	DFVE60DP1300A*		22,000	\$3,080
215429728	DAIKIN	DH7VSA3610A*	DFVE48CP0300A*		22,000	\$3,080
215429727	DAIKIN	DH7VSA3610A*	DFVE48CP1300A*		22,000	\$3,080
215429726	DAIKIN	DH7VSA3610A*	DFVE42CP0300A*		22,000	\$3,080
215429725	DAIKIN	DH7VSA3610A*	DFVE42CP1300A*		22,000	\$3,080
215429724	DAIKIN	DH7VSA3610A*	DFVE48DP0300A*		22,000	\$3,080
215415509	DAIKIN	DH7VSA3610A*	DFVE48DP1300A*		22,000	\$3,080
215433898	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*+MBVK16CP1X00A*		15,800	\$2,212
215433897	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*+MBVK12BP1X00A*		15,800	\$2,212
215434022	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96TC1005CNA*	15,800	\$2,212
215434021	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96TC0804CNA*	15,800	\$2,212
215434020	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96TC0803BNA*	15,800	\$2,212
215434019	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96TC0603BNA*	15,800	\$2,212
215434018	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96TC0403BNA*	15,800	\$2,212
215434017	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80TC1005C*A*	15,800	\$2,212

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434016	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80TC0805C*A*	15,800	\$2,212
215434015	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80TC0804C*A*	15,800	\$2,212
215434014	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80TC0803B*A*	15,800	\$2,212
215434013	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80TC0604B*A*	15,800	\$2,212
215434012	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80TC0603B*A*	15,800	\$2,212
215434011	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96SC0805CUA*	15,800	\$2,212
215434010	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*96SC0603BUA*	15,800	\$2,212
215434009	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80SC0805CUA*	15,800	\$2,212
215434008	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*80SC0604BUA*	15,800	\$2,212
215434007	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*97MC1005CNA*	15,800	\$2,212
215434006	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*97MC0804CNA*	15,800	\$2,212
215434005	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*97MC0803BNA*	15,800	\$2,212
215434004	DAIKIN	DH7VSA2410A*	CHPEA3026*3A*	D*97MC0603BNA*	15,800	\$2,212
215433896	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*+MBVK16CP1X00A*		15,800	\$2,212
215433895	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*+MBVK12BP1X00A*		15,800	\$2,212
215434003	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96TC1005CNA*	15,800	\$2,212
215434002	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96TC0804CNA*	15,800	\$2,212
215434001	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96TC0803BNA*	15,800	\$2,212
215434000	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96TC0603BNA*	15,800	\$2,212
215433999	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96TC0403BNA*	15,800	\$2,212
215433998	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80TC1005C*A*	15,800	\$2,212
215433997	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80TC0805C*A*	15,800	\$2,212
215433996	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80TC0804C*A*	15,800	\$2,212
215433995	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80TC0803B*A*	15,800	\$2,212
215433994	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80TC0604B*A*	15,800	\$2,212
215433993	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80TC0603B*A*	15,800	\$2,212
215433992	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96SC0805CUA*	15,800	\$2,212
215433991	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*96SC0603BUA*	15,800	\$2,212
215433990	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80SC0805CUA*	15,800	\$2,212
215433989	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*80SC0604BUA*	15,800	\$2,212
215433988	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*97MC1005CNA*	15,800	\$2,212
215433987	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*97MC0804CNA*	15,800	\$2,212
215433986	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*97MC0803BNA*	15,800	\$2,212
215433985	DAIKIN	DH7VSA2410A*	CA*EA3626*3A*	D*97MC0603BNA*	15,800	\$2,212
215433894	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*+MBVK16CP1X00A*		15,800	\$2,212

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215433893	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*+MBVK12BP1X00A*		15,800	\$2,212
215433984	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96TC1005CNA*	15,800	\$2,212
215433983	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96TC0804CNA*	15,800	\$2,212
215433982	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96TC0803BNA*	15,800	\$2,212
215433981	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96TC0603BNA*	15,800	\$2,212
215433980	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96TC0403BNA*	15,800	\$2,212
215433979	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80TC1005C*A*	15,800	\$2,212
215433978	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80TC0805C*A*	15,800	\$2,212
215433977	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80TC0804C*A*	15,800	\$2,212
215433976	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80TC0803B*A*	15,800	\$2,212
215433975	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80TC0603B*A*	15,800	\$2,212
215433974	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96SC0805CUA*	15,800	\$2,212
215433973	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*96SC0603BUA*	15,800	\$2,212
215433972	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80SC0805CUA*	15,800	\$2,212
215433971	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*80SC0604BUA*	15,800	\$2,212
215433970	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*97MC1005CNA*	15,800	\$2,212
215433969	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*97MC0804CNA*	15,800	\$2,212
215433968	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*97MC0803BNA*	15,800	\$2,212
215433967	DAIKIN	DH7VSA2410A*	CA*EA3022*3A*	D*97MC0603BNA*	15,800	\$2,212
215429723	DAIKIN	DH7VSA2410A*	DFVE36CP0300A*		15,800	\$2,212
215415508	DAIKIN	DH7VSA2410A*	DFVE36CP1300A*		15,800	\$2,212
213156959	DAIKIN	DZ6VSA481EA*	CA*EA6030*4A*	D*80VC0805D*A*	28,000	\$3,920
213156958	DAIKIN	DZ6VSA421EA*	CA*EA6030*4A*	D*80VC0805D*A*	28,000	\$3,920
207158011	DAIKIN	RXM18VVJU	FTXM18VVJU		15,400	\$2,156
207158012	DAIKIN	RXM24VVJU	FTXM24VVJU		16,000	\$2,240
205663342	DAIKIN	RXL18UMVJU*	FTX18UVJU		14,000	\$1,960
205663344	DAIKIN	RXL24UMVJU*	FTX24UVJU		15,800	\$2,212
207172944	DAIKIN	DZ17VSA181B*	CA*EA1818*4A*	D*80VC0603B*A*	10,800	\$1,512
210692320	DAIKIN	DZ9VCA3610A*	CA*F3743*6D*+TXV	D*97MC1205DNA*	21,400	\$2,996
210692319	DAIKIN	DZ9VCA3610A*	CA*F3743*6D*+TXV	D*97MC1005CNA*	21,400	\$2,996
210692318	DAIKIN	DZ9VCA3610A*	CA*F3743*6D*+TXV	D*97MC0804CNA*	21,400	\$2,996
210609965	DAIKIN	DZ9VCA3610A*	DMVE48DP1400A*		21,400	\$2,996
212604426	DAIKIN	4MXLH36WVJU*	Heat pump without ducts		22,400	\$3,136
212604425	DAIKIN	3MXLH24WVJU*	Heat pump without ducts		15,500	\$2,170
212494266	DAIKIN	RXL24WMVJU*	FDMQ24WVJU*		16,000	\$2,240
212494265	DAIKIN	RXL18WMVJU*	FDMQ18WVJU*		14,600	\$2,044
212494259	DAIKIN	RXM18WVJU*	FTXM18WVJU*		15,400	\$2,156

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212494258	DAIKIN	RXM12WVJU*	FTXM12WVJU*		8,600	\$1,204
212494264	DAIKIN	RXL24WMVJU*	FTX24WVJU*		15,800	\$2,212
212604432	DAIKIN	4MXLH36WVJU*	Combination heat pumps with or without ducts		22,200	\$3,108
212604429	DAIKIN	2MXLH18WVJU*	Combination heat pumps with or without ducts		11,800	\$1,652
212604424	DAIKIN	2MXLH18WVJU*	Heat pump without ducts		12,000	\$1,680
212506084	DAIKIN	RXL15WMVJU*	FVXS15WVJU*		11,500	\$1,610
212506077	DAIKIN	RXL15WMVJU*	FTX15WMVJU*		11,500	\$1,610
212494263	DAIKIN	RXL18WMVJU*	FTX18WVJU*		14,000	\$1,960
212494260	DAIKIN	RXM24WVJU*	FTXM24WVJU*		16,000	\$2,240
210800990	DAIKIN	4MXL36WVJU*	Combination heat pumps with or without ducts		22,200	\$3,108
210800989	DAIKIN	3MXL24WMVJU*	Combination heat pumps with or without ducts		15,200	\$2,128
210800988	DAIKIN	2MXL18WMVJU*	Combination heat pumps with or without ducts		11,800	\$1,652
210800987	DAIKIN	5MXS48WVJU*	Combination heat pumps with or without ducts		30,600	\$4,284
210725100	DAIKIN	2MXL18WMVJU*	Heat pump with ducts		11,600	\$1,624
210725099	DAIKIN	5MXS48WVJU*	Heat pump with ducts		30,200	\$4,228
213815733	DAIKIN	DZ6VSA481EA*	CAPEA6030*4A*+MBVK20D P1X00A*		28,000	\$3,920
213815732	DAIKIN	DZ6VSA421EA*	CAPEA6030*4A*+MBVK20D P1X00A*		28,000	\$3,920
213815731	DAIKIN	DZ6VSA361EA*	CAPEA4830*4A*+MBVK16C P1X00A*		23,000	\$3,220
213815730	DAIKIN	DZ6VSA361EA*	CAPEA6030*4A*+MBVK20D P1X00A*		23,000	\$3,220
213815729	DAIKIN	DZ6VSA241EA*	CAPEA3026*4A*+MBVK16C P1X00A*		16,000	\$2,240
213815728	DAIKIN	DZ6VSA241EA*	CAPEA3026*4A*+MBVK12B P1X00A*		16,000	\$2,240
213815727	DAIKIN	DZ6VSA241EA*	CAPEA2422*4A*+MBVK16C P1X00A*		16,000	\$2,240
213815726	DAIKIN	DZ6VSA241EA*	CAPEA2422*4A*+MBVK12B P1X00A*		16,000	\$2,240
213613334	DAIKIN	DZ6VSA361EA*	DFVE42CP1400B*		23,000	\$3,220
213613332	DAIKIN	DZ6VSA481EA*	DFVE60DP1400B*		28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213613331	DAIKIN	DZ6VSA421EA*	DFVE60DP1400B*		28,000	\$3,920
213613330	DAIKIN	DZ6VSA361EA*	DFVE48DP1400B*		23,000	\$3,220
213613333	DAIKIN	DZ6VSA361EA*	DFVE60DP1400B*		23,000	\$3,220
213613329	DAIKIN	DZ6VSA241EA*	DFVE36CP1400B*		16,000	\$2,240
213872275	DAIKIN	DZ6VSA481EA*	CA*EA6030*4A*	D*96VC0804CNA*	28,000	\$3,920
213872273	DAIKIN	DZ6VSA481EA*	CA*EA6030*4A*	D*96VC1005CNA*	28,000	\$3,920
213872271	DAIKIN	DZ6VSA481EA*	CA*EA6030*4A*	D*97MC0804CNA*	28,000	\$3,920
213872269	DAIKIN	DZ6VSA481EA*	CA*EA6030*4A*	D*97MC1005CNA*	28,000	\$3,920
213872267	DAIKIN	DZ6VSA421EA*	CA*EA6030*4A*	D*96VC0804CNA*	28,000	\$3,920
213872265	DAIKIN	DZ6VSA421EA*	CA*EA6030*4A*	D*96VC1005CNA*	28,000	\$3,920
213872263	DAIKIN	DZ6VSA421EA*	CA*EA6030*4A*	D*97MC0804CNA*	28,000	\$3,920
213872261	DAIKIN	DZ6VSA421EA*	CA*EA6030*4A*	D*97MC1005CNA*	28,000	\$3,920
213255536	DAIKIN	DZ6VSA1810A*	DFVE24BP0400A*		10,800	\$1,512
210791261	DAIKIN	DZ6VSA6010A*	DV59FECD14A*		34,500	\$4,830
210791260	DAIKIN	DZ6VSA4210A*	DV47FECD14A*		25,200	\$3,528
213354819	DAIKIN	DZ9VCA3610A*	DV37PECC14A*		21,600	\$3,024
211635176	DAIKIN	RZQ18TBVJU*	FTQ18TAVJU*A*		13,600	\$1,904
212614864	DAIKIN	DZ6VSA241EA*	DFVE36CP1400A*		16,000	\$2,240
212614872	DAIKIN	DZ6VSA241EA*	DFVE36CP0400A*		16,000	\$2,240
212614873	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*+MBVC1200* *-1A*		16,000	\$2,240
212614874	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*+MBVC1600* *-1A*		16,000	\$2,240
212614875	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*80VC0603B*A*	16,000	\$2,240
212614876	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*80VC0604B*A*	16,000	\$2,240
212614877	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*80SC0604BUA*	16,000	\$2,240
212614878	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*80VC0803B*A*	16,000	\$2,240
212614879	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*80VC0804C*A*	16,000	\$2,240
212614880	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*80VC0805C*A*	16,000	\$2,240
212614881	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*80SC0805CUA*	16,000	\$2,240
212614882	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*80VC1005C*A*	16,000	\$2,240
212614883	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*96VC0403BNA*	16,000	\$2,240
212614884	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*96VC0603BNA*	16,000	\$2,240
212614885	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*96SC0603BUA*	16,000	\$2,240
212614886	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*96VC0803BNA*	16,000	\$2,240
212614887	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*96VC0804CNA*	16,000	\$2,240
212614888	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*96SC0805CUA*	16,000	\$2,240
212614889	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*96VC1005CNA*	16,000	\$2,240

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212614890	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*97MC0603BNA*	16,000	\$2,240
212614891	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*97MC0803BNA*	16,000	\$2,240
212614892	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*97MC0804CNA*	16,000	\$2,240
212614893	DAIKIN	DZ6VSA241EA*	CA*EA2422*4A*	D*97MC1005CNA*	16,000	\$2,240
212614894	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*+MBVC1200* *-1A*		16,000	\$2,240
212614895	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*+MBVC1600* *-1A*		16,000	\$2,240
212614896	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*80VC0603B*A*	16,000	\$2,240
212614897	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*80VC0604B*A*	16,000	\$2,240
212614898	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*80SC0604BUA*	16,000	\$2,240
212614899	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*80VC0803B*A*	16,000	\$2,240
212614900	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*80VC0804C*A*	16,000	\$2,240
212614901	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*80VC0805C*A*	16,000	\$2,240
212614902	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*80SC0805CUA*	16,000	\$2,240
212614903	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*80VC1005C*A*	16,000	\$2,240
212614904	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*96VC0403BNA*	16,000	\$2,240
212614905	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*96VC0603BNA*	16,000	\$2,240
212614906	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*96SC0603BUA*	16,000	\$2,240
212614907	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*96VC0803BNA*	16,000	\$2,240
212614908	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*96VC0804CNA*	16,000	\$2,240
212614909	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*96SC0805CUA*	16,000	\$2,240
212614910	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*96VC1005CNA*	16,000	\$2,240
212614911	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*97MC0603BNA*	16,000	\$2,240
212614912	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*97MC0803BNA*	16,000	\$2,240
212614913	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*97MC0804CNA*	16,000	\$2,240
212614914	DAIKIN	DZ6VSA241EA*	CA*EA3026*4A*	D*97MC1005CNA*	16,000	\$2,240
212614942	DAIKIN	DZ6VSA481EA*	CA*EA6030*4A*	D*96VC1005DNA*	28,000	\$3,920
212614941	DAIKIN	DZ6VSA481EA*	CA*EA6030*4A*	D*96VC1205DNA*	28,000	\$3,920
212614940	DAIKIN	DZ6VSA481EA*	CA*EA6030*4A*	D*97MC1205DNA*	28,000	\$3,920
212614939	DAIKIN	DZ6VSA481EA*	CA*EA6030*4A*+MBVC2000* *-1A*		28,000	\$3,920
212614938	DAIKIN	DZ6VSA481EA*	DFVE60DP0400A*		28,000	\$3,920
212614867	DAIKIN	DZ6VSA481EA*	DFVE60DP1400A*		28,000	\$3,920
212614937	DAIKIN	DZ6VSA421EA*	CA*EA6030*4A*	D*96VC1005DNA*	28,000	\$3,920
212614936	DAIKIN	DZ6VSA421EA*	CA*EA6030*4A*	D*96VC1205DNA*	28,000	\$3,920
212614935	DAIKIN	DZ6VSA421EA*	CA*EA6030*4A*	D*97MC1205DNA*	28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212614934	DAIKIN	DZ6VSA421EA*	CA*EA6030*4A*+MBVC2000* *-1A*		28,000	\$3,920
212614933	DAIKIN	DZ6VSA421EA*	DFVE60DP0400A*		28,000	\$3,920
212614866	DAIKIN	DZ6VSA421EA*	DFVE60DP1400A*		28,000	\$3,920
212928695	DAIKIN	DZ6VSA361EA*	DFVE42CP1400A*		23,000	\$3,220
212928694	DAIKIN	DZ6VSA361EA*	DFVE42CP0400A*		23,000	\$3,220
212614932	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*	D*96SC0805CUA*	23,000	\$3,220
212614931	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*	D*80SC0805CUA*	23,000	\$3,220
212614930	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*	D*97MC0804CNA*	23,000	\$3,220
212614929	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*	D*80VC0804C*A*	23,000	\$3,220
212614928	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*	D*80VC0805C*A*	23,000	\$3,220
212614927	DAIKIN	DZ6VSA361EA*	CA*EA6030*4A*	D*80VC0805D*A*	23,000	\$3,220
212614926	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*	D*80VC1005C*A*	23,000	\$3,220
212614925	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*	D*96VC0804CNA*	23,000	\$3,220
212614924	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*	D*96VC1005CNA*	23,000	\$3,220
212614923	DAIKIN	DZ6VSA361EA*	CA*EA6030*4A*	D*96VC1005DNA*	23,000	\$3,220
212614922	DAIKIN	DZ6VSA361EA*	CA*EA6030*4A*	D*96VC1205DNA*	23,000	\$3,220
212614921	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*	D*97MC1005CNA*	23,000	\$3,220
212614920	DAIKIN	DZ6VSA361EA*	CA*EA6030*4A*	D*97MC1205DNA*	23,000	\$3,220
212614919	DAIKIN	DZ6VSA361EA*	CA*EA4830*4A*+MBVC1600* *-1A*		23,000	\$3,220
212614918	DAIKIN	DZ6VSA361EA*	CA*EA6030*4A*+MBVC2000* *-1A*		23,000	\$3,220
212614917	DAIKIN	DZ6VSA361EA*	DFVE48DP0400A*		23,000	\$3,220
212614916	DAIKIN	DZ6VSA361EA*	DFVE60DP0400A*		23,000	\$3,220
212614915	DAIKIN	DZ6VSA361EA*	DFVE60DP1400A*		23,000	\$3,220
212614865	DAIKIN	DZ6VSA361EA*	DFVE48DP1400A*		23,000	\$3,220
8849445	DAIKIN	RXL15QMVJU	FVXS15NVJU		11,500	\$1,610
8849330	DAIKIN	RXL15QMVJU	FTX15NMVJU		11,500	\$1,610
205663345	DAIKIN	RXL24UMVJU*	FDMQ24RVJU		16,000	\$2,240
205663343	DAIKIN	RXL18UMVJU*	FDMQ18RVJU		14,600	\$2,044
207599997	DAIKIN	DZ17VSA601B*	DV59FEC14A*		34,400	\$4,816
205706994	DAIKIN	RZQ36TAVJU*	FBQ36PVJU		27,400	\$3,836
205707006	DAIKIN	RZQ30TAVJU*	FBQ30PVJU		23,400	\$3,276
205801306	DAIKIN	RZQ18TAVJU*	FBQ18PVJU		13,200	\$1,848
205707005	DAIKIN	RZQ24TAVJU*	FBQ24PVJU		18,800	\$2,632
205707009	DAIKIN	RZQ30TAVJU*	FCQ30TAVJU		22,800	\$3,192
205707008	DAIKIN	RZQ24TAVJU*	FCQ24TAVJU		18,000	\$2,520

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205754949	DAIKIN	RZQ30TAVJU*	FTQ30TAVJU*A*		24,000	\$3,360
205707002	DAIKIN	RZQ24TAVJU*	FTQ24TAVJU*A*		19,400	\$2,716
205707003	DAIKIN	RZQ36TAVJU*	FTQ36TAVJU*A*		29,000	\$4,060
204875639	DAIKIN	DZ17VSA181A*	CA*EA1818*4A*+MBVC1200* *-1A*		10,500	\$1,470
204875381	DAIKIN	DZ17VSA181A*	DV24FECB14A*		10,500	\$1,470
211635181	DAIKIN	RZQ36TBVJU*	FTQ36TAVJU*A*		28,400	\$3,976
211635180	DAIKIN	RZQ30TBVJU*	FTQ30TAVJU*A*		24,000	\$3,360
211635175	DAIKIN	RZQ48TBVJU*	FBQ48TBVJU		38,000	\$5,320
211635174	DAIKIN	RZQ42TBVJU*	FBQ42TBVJU		32,400	\$4,536
211635173	DAIKIN	RZQ36TBVJU*	FBQ36TBVJU		28,000	\$3,920
211635172	DAIKIN	RZQ30TBVJU*	FBQ30TBVJU		24,000	\$3,360
211635170	DAIKIN	RZQ18TBVJU*	FBQ18TBVJU		14,000	\$1,960
210791259	DAIKIN	DZ6VSA3610A*	DV35FECC14A*		22,000	\$3,080
210791258	DAIKIN	DZ6VSA3010A*	DV35FECC14A*		17,600	\$2,464
207172948	DAIKIN	DZ17VSA181B*	CA*EA1818*4A*+MBVC1200* *-1A*		10,800	\$1,512
207168336	DAIKIN	DZ17VSA181B*	DV24FECB14A*		10,800	\$1,512
210607577	DAIKIN	DZ9VCA3610A*	CA*F3743*6D*+MBVC1600** 1A*+TX		21,600	\$3,024
207599994	DAIKIN	DZ17VSA301B*	DV35FECC14A*		17,600	\$2,464
207599995	DAIKIN	DZ17VSA361B*	DV35FECC14A*		22,000	\$3,080
207599996	DAIKIN	DZ17VSA421B*	DV47FECD14A*		25,200	\$3,528
210435088	DAIKIN	DZ6VSA1810A*	DV24FECB14A*		10,800	\$1,512
210435106	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*	D*96SC0603BUA*	10,800	\$1,512
210435107	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*	D*96VC0403BNA*	10,800	\$1,512
210435108	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*	D*96VC0603BNA*	10,800	\$1,512
210435109	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*	D*96VC0803BNA*	10,800	\$1,512
210435110	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*	D*97MC0603BNA*	10,800	\$1,512
210435111	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*	D*97MC0803BNA*	10,800	\$1,512
210435112	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*+MBVC1200* *-1A*		10,800	\$1,512
210435117	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*	D*96VC0804CNA*	10,800	\$1,512
210435118	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*	D*97MC0804CNA*	10,800	\$1,512
210435119	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*+MBVC1600* *-1A*		10,800	\$1,512
210435125	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*	D*96VC0403BNA*	10,800	\$1,512
210435126	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*	D*96VC0603BNA*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210435127	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*	D*96VC0803BNA*	10,800	\$1,512
210435128	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*	D*97MC0603BNA*	10,800	\$1,512
210435129	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*	D*97MC0803BNA*	10,800	\$1,512
210435130	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*+MBVC1200* *-1A*		10,800	\$1,512
210435135	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*	D*96VC0804CNA*	10,800	\$1,512
210435136	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*	D*97MC0804CNA*	10,800	\$1,512
210435137	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*+MBVC1600* *-1A*		10,800	\$1,512
210435081	DAIKIN	DZ6VSA1810A*	DFVE24BP1400A*		10,800	\$1,512
2109791259	DAIKIN	DZ6VSA3610A*	DV35FECC14A*		22,000	\$3,080
2109791260	DAIKIN	DZ6VSA4210A*	DV47FECD14A*		25,200	\$3,528
2109791261	DAIKIN	DZ6VSA6010A*	DV59FECD14A*		34,500	\$4,830
213613318	DAIKIN	DZ6VSA1810A*	DFVE24BP1400B*		10,800	\$1,512
213815091	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*+MBVK16CP 1X00A*		10,800	\$1,512
213815090	DAIKIN	DZ6VSA1810A*	CA*EA2422*4A*+MBVK12BP 1X00A*		10,800	\$1,512
213815089	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*+MBVK16CP 1X00A*		10,800	\$1,512
213815088	DAIKIN	DZ6VSA1810A*	CA*EA1818*4A*+MBVK12BP 1X00A*		10,800	\$1,512
206361880	DAY & NIGHT	DLCSRBH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361882	DAY & NIGHT	DLCSRBH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361881	DAY & NIGHT	DLCSRBH18AAK	DLFSHBH18XAK		11,100	\$1,554
210857435	DAY & NIGHT	DLCSRBH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857436	DAY & NIGHT	DLCSRBH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132687	DAY & NIGHT	DLCSRBH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948193	DAY & NIGHT	DLCSRBH12AAK	DLFSFBH12XAK		10,200	\$1,428
207683341	DAY & NIGHT	DLCSRBH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447631	DAY & NIGHT	DLCSRBH24AAK	DLFSCH24XAK		21,200	\$2,968
208447635	DAY & NIGHT	DLCSRBH18AAK	DLFSCH18XAK		15,000	\$2,100
208447630	DAY & NIGHT	DLCSRBH12AAK	DLFSCH12XAK		10,000	\$1,400
206771762	DAY & NIGHT	CVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0701716A*	31,600	\$4,424
211132720	DAY & NIGHT	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
206773532	DAY & NIGHT	CVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
211132685	DAY & NIGHT	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
206765551	DAY & NIGHT	CVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
206767547	DAY & NIGHT	CVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206767556	DAY & NIGHT	CVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
206771906	DAY & NIGHT	CVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	31,400	\$4,396
206771258	DAY & NIGHT	CVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206771357	DAY & NIGHT	CVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206771627	DAY & NIGHT	CVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206773424	DAY & NIGHT	CVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206773433	DAY & NIGHT	CVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	31,800	\$4,452
206773487	DAY & NIGHT	CVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	31,600	\$4,424
206771276	DAY & NIGHT	CVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206771726	DAY & NIGHT	CVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206771780	DAY & NIGHT	CVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206773478	DAY & NIGHT	CVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206773523	DAY & NIGHT	CVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206766037	DAY & NIGHT	CVH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
206773505	DAY & NIGHT	CVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206771861	DAY & NIGHT	CVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	31,400	\$4,396
206771897	DAY & NIGHT	CVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206771645	DAY & NIGHT	CVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206773514	DAY & NIGHT	CVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
215324263	DAY & NIGHT	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215323727	DAY & NIGHT	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215324274	DAY & NIGHT	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324273	DAY & NIGHT	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324270	DAY & NIGHT	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324268	DAY & NIGHT	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324266	DAY & NIGHT	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324265	DAY & NIGHT	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324264	DAY & NIGHT	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324261	DAY & NIGHT	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324260	DAY & NIGHT	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324259	DAY & NIGHT	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324258	DAY & NIGHT	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215413242	DAY & NIGHT	D5CPRAH18AA	D5FPHAH18XAK		19,300	\$2,702
215413241	DAY & NIGHT	D5CPRAH12AAK	D5FPHAH12XAK		11,000	\$1,540
215357243	DAY & NIGHT	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357242	DAY & NIGHT	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357241	DAY & NIGHT	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215324269	DAY & NIGHT	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324262	DAY & NIGHT	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215357269	DAY & NIGHT	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357252	DAY & NIGHT	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357251	DAY & NIGHT	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357250	DAY & NIGHT	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357249	DAY & NIGHT	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357248	DAY & NIGHT	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357247	DAY & NIGHT	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357246	DAY & NIGHT	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357245	DAY & NIGHT	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357244	DAY & NIGHT	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357240	DAY & NIGHT	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357239	DAY & NIGHT	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357238	DAY & NIGHT	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357234	DAY & NIGHT	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357233	DAY & NIGHT	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357232	DAY & NIGHT	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324311	DAY & NIGHT	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324309	DAY & NIGHT	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324308	DAY & NIGHT	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324306	DAY & NIGHT	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324305	DAY & NIGHT	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324272	DAY & NIGHT	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324267	DAY & NIGHT	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324312	DAY & NIGHT	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324310	DAY & NIGHT	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324307	DAY & NIGHT	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324257	DAY & NIGHT	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215318959	DAY & NIGHT	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215318958	DAY & NIGHT	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215318957	DAY & NIGHT	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215318967	DAY & NIGHT	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215318965	DAY & NIGHT	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215318955	DAY & NIGHT	D5CURAH48AAK	D5FUAH48XAK		32,400	\$4,536
215318952	DAY & NIGHT	D5CURAH24AAK	D5FUAH24XAK		20,000	\$2,800
215318950	DAY & NIGHT	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215318949	DAY & NIGHT	D5CUHAH60AAK	D5FUAH60XAK		45,000	\$6,300
215318948	DAY & NIGHT	D5CUHAH48AAK	D5FUAH48XAK		37,000	\$5,180
215318947	DAY & NIGHT	D5CUHAH36AAK	D5FUAH36XAK		31,800	\$4,452
215318946	DAY & NIGHT	D5CUHAH30AAK	D5FUAH30XAK		23,800	\$3,332
215318945	DAY & NIGHT	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215318944	DAY & NIGHT	D5CUHAH24AAK	D5FUAH24XAK		20,000	\$2,800
215318943	DAY & NIGHT	D5CUHAH18AAK	D5FUAH18XAK		15,000	\$2,100
215318966	DAY & NIGHT	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215318962	DAY & NIGHT	D5CSHAH33AAK	D5FSAH36XBK		27,400	\$3,836
215318961	DAY & NIGHT	D5CSHAH24AAK	D5FSAH24XBK		16,900	\$2,366
215318960	DAY & NIGHT	D5CSHAH18AAK	D5FSAH18XBK		14,000	\$1,960
212982942	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MSU0802120A*	23,200	\$3,248
212982402	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80MSU0401712A*	12,200	\$1,708
212982630	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MSU0601716A*	23,200	\$3,248
212982378	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80MSU0401712A*	12,200	\$1,708
213079315	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0802120A*	29,200	\$4,088
212982438	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU0401712A*	12,300	\$1,722
213078931	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	29,400	\$4,116
212982390	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80MSU0401712A*	12,400	\$1,736
213079183	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0601716A*	29,200	\$4,088
212982366	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0401712A*	19,100	\$2,674
213079279	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MSU0802120A*	29,000	\$4,060
213079015	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MSU0401712A*	29,000	\$4,060
213079327	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0802120A*	29,200	\$4,088
213079147	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MSU0601716A*	29,000	\$4,060
212982414	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80MSU0401712A*	12,300	\$1,722
213078907	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU1002120A*	29,600	\$4,144
212982306	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80MSU0401712A*	18,800	\$2,632
212988101	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	23,600	\$3,304
212988065	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96MSN1002120A*	23,600	\$3,304
212982294	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MSU0401712A*	19,100	\$2,674
212982138	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80MSU0401712A*	23,400	\$3,276
212982702	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MSU0601716A*	19,000	\$2,660
212982690	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212981598	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MSU1002120A*	23,200	\$3,248
212982666	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MSU0601716A*	23,200	\$3,248
212982714	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80MSU0601716A*	18,600	\$2,604
212982330	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU0401712A*	19,400	\$2,716
212981610	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80MSU1002120A*	23,600	\$3,304
212983002	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	23,600	\$3,304
212982426	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU0401712A*	12,400	\$1,736
213078991	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MSU0401712A*	29,000	\$4,060
213078955	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80MSU0401712A*	29,400	\$4,116
212988053	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*96MSN1002120A*	23,600	\$3,304
212988041	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96MSN1002120A*	23,400	\$3,276
212982222	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80MSU0401712A*	23,400	\$3,276
212982726	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0601716A*	19,000	\$2,660
212982642	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80MSU0601716A*	23,400	\$3,276
212982354	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU0401712A*	19,100	\$2,674
213078883	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MSU1002120A*	29,200	\$4,088
213078859	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MSU1002120A*	29,200	\$4,088
213079063	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0401712A*	29,400	\$4,116
213079051	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80MSU0401712A*	29,200	\$4,088
212982342	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU0401712A*	19,100	\$2,674
212982174	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MSU0401712A*	23,200	\$3,248
212982282	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80MSU0401712A*	19,000	\$2,660
212982270	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80MSU0401712A*	19,100	\$2,674
212982246	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80MSU0401712A*	19,400	\$2,716
212981682	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	23,600	\$3,304
212981622	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MSU1002120A*	23,200	\$3,248
212981538	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MSU1002120A*	29,000	\$4,060
209852065	DAY & NIGHT	DLCURAH36ABK	DLFUAAH36XAK		30,400	\$4,256
213079219	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MSU0802120A*	29,000	\$4,060
212982318	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80MSU0401712A*	18,700	\$2,618
213079231	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MSU0802120A*	29,400	\$4,116
213079171	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	29,400	\$4,116
213079099	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MSU0601716A*	29,000	\$4,060
212982258	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80MSU0401712A*	18,600	\$2,604
213079207	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MSU0802120A*	29,400	\$4,116
213079303	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	29,400	\$4,116
213079243	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MSU0802120A*	29,400	\$4,116
213079111	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MSU0601716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079087	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MSU0601716A*	29,400	\$4,116
212982978	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MSU0802120A*	23,200	\$3,248
213079255	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MSU0802120A*	29,000	\$4,060
212982162	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80MSU0401712A*	23,400	\$3,276
212982150	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MSU0401712A*	23,200	\$3,248
213079003	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MSU0401712A*	29,400	\$4,116
213080398	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002122A*	29,400	\$4,116
213080357	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002120A*	29,200	\$4,088
213080345	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	29,400	\$4,116
213079267	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MSU0802120A*	29,000	\$4,060
213079135	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MSU0601716A*	29,000	\$4,060
212988005	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002120A*	29,000	\$4,060
213080407	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002122A*	29,400	\$4,116
213079159	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU0601716A*	29,600	\$4,144
213078967	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MSU0401712A*	29,400	\$4,116
210470535	DAY & NIGHT	CVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470392	DAY & NIGHT	CVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470271	DAY & NIGHT	CVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	31,000	\$4,340
213080434	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002122A*	29,400	\$4,116
213080416	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002122A*	29,200	\$4,088
213080389	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002122A*	29,200	\$4,088
213080380	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002122A*	29,400	\$4,116
213080369	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002120A*	29,200	\$4,088
213080321	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002120A*	29,200	\$4,088
213080285	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002120A*	29,200	\$4,088
213079075	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0401712A*	29,200	\$4,088
213078943	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU1002120A*	29,200	\$4,088
212988017	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002120A*	29,000	\$4,060
212988220	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002122A*	29,000	\$4,060
210470502	DAY & NIGHT	CVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0901716A*	31,200	\$4,368
210470436	DAY & NIGHT	CVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0701716A*	31,400	\$4,396
213080309	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002120A*	29,400	\$4,116
213080297	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002120A*	29,400	\$4,116
212982090	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MSU0401712A*	28,800	\$4,032
212988229	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002122A*	29,000	\$4,060
212969731	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412B*	19,300	\$2,702
210470524	DAY & NIGHT	CVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470381	DAY & NIGHT	CVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU0802120A*	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210470238	DAY & NIGHT	CVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	31,000	\$4,340
213080452	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002122A*	29,200	\$4,088
213080443	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002122A*	29,200	\$4,088
213080273	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002120A*	29,400	\$4,116
213078871	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MSU1002120A*	29,400	\$4,116
213078835	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MSU1002120A*	29,400	\$4,116
212988077	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96MSN1002120A*	23,200	\$3,248
210470568	DAY & NIGHT	CVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL1352422A*	31,200	\$4,368
210473112	DAY & NIGHT	CVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210473101	DAY & NIGHT	CVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
210470557	DAY & NIGHT	CVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470447	DAY & NIGHT	CVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470249	DAY & NIGHT	CVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU1002122A*	31,000	\$4,340
210470282	DAY & NIGHT	CVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL1352422A*	31,000	\$4,340
213078979	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80MSU0401712A*	29,200	\$4,088
211712145	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ESU1002120A*	23,200	\$3,248
211712133	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*95ESU1002120A*	23,400	\$3,276
211712122	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80VSL0701716A*	23,400	\$3,276
211712111	DAY & NIGHT	DLCURAH30ABK	EA*4X36L21A*	*80ESU1002120A*	23,600	\$3,304
211712099	DAY & NIGHT	DLCURAH30ABK	EA*4X36L21A*	*95ESU1002120A*	23,600	\$3,304
211709689	DAY & NIGHT	DLCURAH30ABK	FJMA4*30L*B*		23,400	\$3,276
213353860	DAY & NIGHT	DLCURAH36ABK	F5MA4*42L*C*		29,200	\$4,088
213353850	DAY & NIGHT	DLCURAH36ABK	F5MA4*36L*B*		29,400	\$4,116
213249340	DAY & NIGHT	DLCURAH36ABK	FEVA0036**+NAVA43601CK		29,400	\$4,116
213080878	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU0802120A*	29,200	\$4,088
213080866	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0802120A*	29,200	\$4,088
213080854	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	29,400	\$4,116
213080842	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*95MSU0802120A*	29,600	\$4,144
213080830	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95MSU0802120A*	29,200	\$4,088
213080818	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95MSU0802120A*	29,400	\$4,116
213080806	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95MSU0802120A*	29,400	\$4,116
213080794	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95MSU0802120A*	29,200	\$4,088
213080782	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95MSU0802120A*	29,400	\$4,116
213080770	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0601716A*	29,200	\$4,088
213080758	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	29,600	\$4,144
213080746	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*95MSU0601716A*	29,400	\$4,116
213080710	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95MSU0601716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080698	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95MSU0601716A*	29,400	\$4,116
213080686	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95MSU0601716A*	29,200	\$4,088
213080674	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*95MSU0601716A*	29,400	\$4,116
213080662	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95MSU0601716A*	29,400	\$4,116
213080650	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*95MSU0601716A*	29,600	\$4,144
213080638	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0401712A*	29,400	\$4,116
213080626	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0401712A*	29,600	\$4,144
213080614	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*95MSU0401712A*	29,400	\$4,116
213080578	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95MSU0401712A*	29,200	\$4,088
211274900	DAY & NIGHT	DLCURAH30ABK	FVM4X48***L		23,000	\$3,220
213080566	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95MSU0401712A*	29,200	\$4,088
213080554	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95MSU0401712A*	29,600	\$4,144
213080542	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95MSU0401712A*	29,200	\$4,088
213080530	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*95MSU0401712A*	29,400	\$4,116
213080518	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95MSU0401712A*	29,600	\$4,144
213080506	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*95MSU0401712A*	29,600	\$4,144
213080496	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1402422A*	29,200	\$4,088
213080486	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96MSN1402422A*	29,400	\$4,116
213080474	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1202422A*	29,200	\$4,088
213080462	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96MSN1202422A*	29,400	\$4,116
213080261	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN0802120A*	29,200	\$4,088
213080249	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0802120A*	29,200	\$4,088
211222782	DAY & NIGHT	DLCURAH30ABK	FVM4X24***L		23,600	\$3,304
213080237	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0802120A*	29,400	\$4,116
213080213	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96MSN0802120A*	29,000	\$4,060
213080201	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96MSN0802120A*	29,000	\$4,060
211222766	DAY & NIGHT	DLCURAH30ABK	FMA4X36**AL*		23,800	\$3,332
213080189	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96MSN0802120A*	29,200	\$4,088
213080177	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96MSN0802120A*	29,400	\$4,116
211222758	DAY & NIGHT	DLCURAH30ABK	FMA4X30**AL*		23,800	\$3,332
213080165	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96MSN0802120A*	29,400	\$4,116
213080153	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96MSN0802120A*	29,200	\$4,088
211222750	DAY & NIGHT	DLCURAH30ABK	FM(C,U)4Z36**AL*		23,600	\$3,304
213080141	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96MSN0802120A*	29,600	\$4,144
213080129	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0801716A*	29,200	\$4,088
211222742	DAY & NIGHT	DLCURAH30ABK	FM(C,U)4Z30**AL*		23,600	\$3,304
213080117	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	29,600	\$4,144
213080105	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*96MSN0801716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211222726	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	OMV098J12*	23,200	\$3,248
211222718	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	OLV098A12*	23,200	\$3,248
213080069	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96MSN0801716A*	29,000	\$4,060
213080057	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96MSN0801716A*	29,200	\$4,088
211222710	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122A*	23,000	\$3,220
213080045	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96MSN0801716A*	29,400	\$4,116
213080033	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96MSN0801716A*	29,200	\$4,088
211222702	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120A*	23,200	\$3,248
213080021	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96MSN0801716A*	29,400	\$4,116
213080009	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96MSN0801716A*	29,600	\$4,144
211222694	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120A*	23,000	\$3,220
213079997	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*96MSN0801716A*	29,600	\$4,144
213079987	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*96MSN0601412A*	29,600	\$4,144
211222686	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VTN0601714A*	23,200	\$3,248
213079967	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96MSN0601412A*	29,400	\$4,116
213079957	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*96MSN0601412A*	29,600	\$4,144
211222678	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*95ESU0601716A*	23,400	\$3,276
213079946	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1202420A*	29,200	\$4,088
213079935	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*92MSN1202420A*	29,000	\$4,060
211222670	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*95ESU0401712A*	23,200	\$3,248
213079924	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*92MSN1202420A*	29,400	\$4,116
213079914	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002122A*	29,200	\$4,088
211222662	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120A*	23,200	\$3,248
213079905	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002122A*	29,200	\$4,088
213079896	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002122A*	29,400	\$4,116
211222654	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120A*	23,000	\$3,220
213079878	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002122A*	29,000	\$4,060
211222646	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716A*	23,200	\$3,248
213079869	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002122A*	29,400	\$4,116
213079860	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002122A*	29,400	\$4,116
211222638	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0601714A*	23,200	\$3,248
213079851	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002122A*	29,000	\$4,060
213079842	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002122A*	29,400	\$4,116
213079831	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002120A*	29,200	\$4,088
211222630	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*95ESN0802120A*	23,200	\$3,248
213079819	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002120A*	29,200	\$4,088
213079807	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	29,400	\$4,116
211222622	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*95ESN0601714A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079795	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN1002120A*	29,600	\$4,144
213079783	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002120A*	29,000	\$4,060
211222614	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*92ESN1002120A*	23,200	\$3,248
213079771	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002120A*	29,400	\$4,116
211222606	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*92ESN0802120A*	23,200	\$3,248
213079759	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002120A*	29,400	\$4,116
213079747	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002120A*	29,000	\$4,060
211222598	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*92ESN0801716A*	23,400	\$3,276
213079735	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002120A*	29,400	\$4,116
213079725	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN0802120A*	29,200	\$4,088
211222590	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*92ESN0601714A*	23,400	\$3,276
213079715	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0802120A*	29,200	\$4,088
213079705	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	29,400	\$4,116
211222566	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122A*	23,200	\$3,248
213079695	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN0802120A*	29,600	\$4,144
213079685	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92MSN0802120A*	29,200	\$4,088
211222558	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120A*	23,200	\$3,248
213079675	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*92MSN0802120A*	29,400	\$4,116
213079665	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92MSN0802120A*	29,400	\$4,116
211222550	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716A*	23,200	\$3,248
213079655	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92MSN0802120A*	29,200	\$4,088
213079645	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92MSN0802120A*	29,400	\$4,116
211222542	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ESU0802120A	23,400	\$3,276
213079633	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0801716A*	29,200	\$4,088
213079621	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0801716A*	29,400	\$4,116
211222534	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ESU0601716A	23,200	\$3,248
213079609	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*92MSN0801716A*	29,200	\$4,088
211222526	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ESU0401712A*	23,200	\$3,248
211222518	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VSL0902120A*	23,200	\$3,248
213079573	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92MSN0801716A*	29,000	\$4,060
213079561	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92MSN0801716A*	29,400	\$4,116
211222510	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VSL0702120A*	23,200	\$3,248
213079549	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92MSN0801716A*	29,000	\$4,060
211222502	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VSL0701716A*	23,200	\$3,248
213079537	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*92MSN0801716A*	29,400	\$4,116
213079525	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92MSN0801716A*	29,400	\$4,116
213079513	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*92MSN0801716A*	29,400	\$4,116
211222494	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VSL0451716A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079501	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0601714A*	29,200	\$4,088
213079489	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0601714A*	29,400	\$4,116
211222486	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	23,200	\$3,248
213079477	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*92MSN0601714A*	29,400	\$4,116
211222478	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
211222470	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
213079441	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92MSN0601714A*	29,200	\$4,088
213079429	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92MSN0601714A*	29,400	\$4,116
211222462	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
213079417	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92MSN0601714A*	29,200	\$4,088
213079403	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601714A*	29,400	\$4,116
211222454	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
213079391	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92MSN0601714A*	29,400	\$4,116
213079379	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601714A*	29,400	\$4,116
211222446	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
213079369	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*92MSN0601412A*	29,400	\$4,116
211222438	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
213079349	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601412A*	29,400	\$4,116
213079339	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601412A*	29,600	\$4,144
211222398	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	OMV098J12*	23,400	\$3,276
211222390	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*96VTN0601714A*	23,400	\$3,276
211222382	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*95ESU0601716A*	23,400	\$3,276
211222374	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*95ESU0401712A*	23,400	\$3,276
211222366	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716A*	23,400	\$3,276
211222358	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*95ESN0601714A*	23,400	\$3,276
213079195	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0601716A*	29,200	\$4,088
211222350	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*92ESN0801716A*	23,400	\$3,276
211222342	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601714A*	23,400	\$3,276
211222334	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601412A*	23,400	\$3,276
213079123	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MSU0601716A*	29,200	\$4,088
211222326	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716A*	23,200	\$3,248
211222318	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412A*	23,400	\$3,276
211222310	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80ESU0601716A	23,400	\$3,276
211222302	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80ESU0401712A*	23,400	\$3,276
211222294	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451716A*	23,400	\$3,276
211222286	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412A*	23,400	\$3,276
211222278	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	23,200	\$3,248
211222270	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078919	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80MSU1002120A*	29,400	\$4,116
213078895	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	29,600	\$4,144
213078847	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80MSU1002120A*	29,400	\$4,116
213078823	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80MSU1002120A*	29,600	\$4,144
211222262	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	23,400	\$3,276
213078813	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1552420A*	29,200	\$4,088
213078803	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1552420A*	29,000	\$4,060
213078793	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	29,400	\$4,116
213078782	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1352420A*	29,200	\$4,088
213078771	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	29,400	\$4,116
213078761	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102420A*	29,200	\$4,088
213078751	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102420A*	29,000	\$4,060
213078741	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	29,400	\$4,116
213078729	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102120A*	29,200	\$4,088
213078717	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)1102120A*	29,200	\$4,088
213078705	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	29,400	\$4,116
213078681	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078669	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078657	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078645	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078633	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078621	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078609	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078599	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902420A*	29,200	\$4,088
213078590	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	29,400	\$4,116
213078580	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902120A*	29,200	\$4,088
213078569	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902120A*	29,200	\$4,088
213078558	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	29,400	\$4,116
211222149	DAY & NIGHT	DLCURAH30ABK	EA*4X36L21A*	*92ESN1002120A*	23,400	\$3,276
211222139	DAY & NIGHT	DLCURAH30ABK	EA*4X36L21A*	*92ESN0802120A*	23,400	\$3,276
213078536	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078525	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078514	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078503	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078492	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078481	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902116A*	29,200	\$4,088
213078470	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902116A*	29,200	\$4,088
213078459	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712504	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
211712491	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	23,400	\$3,276
213078437	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
213078426	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078415	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078404	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
211712478	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078393	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078381	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0901714A*	29,200	\$4,088
211712465	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	23,400	\$3,276
213078369	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0901714A*	29,400	\$4,116
213078357	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0901714A*	29,200	\$4,088
213078321	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
213078309	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078297	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
211221999	DAY & NIGHT	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078285	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078273	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078261	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078251	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0702116A*	29,200	\$4,088
213078241	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0702116A*	29,200	\$4,088
211712428	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122A*	23,400	\$3,276
213078231	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0702116A*	29,400	\$4,116
213078211	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
211221982	DAY & NIGHT	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078201	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078191	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078181	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
213078171	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078159	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701716A*	29,200	\$4,088
213078147	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	29,400	\$4,116
213078135	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701716A*	29,400	\$4,116
213078123	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	29,600	\$4,144
213078111	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	29,600	\$4,144
213078099	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078087	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078075	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078063	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078051	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078039	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	29,600	\$4,144
213078028	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701712A*	29,200	\$4,088
213078017	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	29,400	\$4,116
213078006	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701712A*	29,400	\$4,116
211712383	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716A*	23,400	\$3,276
213077973	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077962	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077951	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077940	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077929	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
211712371	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*95ESN1002120A*	23,600	\$3,304
213077918	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077906	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701412A*	29,400	\$4,116
213077882	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
213077870	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
211712359	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*95ESN0802120A*	23,400	\$3,276
213077858	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0451412A*	29,400	\$4,116
213077834	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	29,400	\$4,116
211712541	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*92ESN0802120A*	23,400	\$3,276
213077821	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	29,600	\$4,144
213077810	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422B*	29,200	\$4,088
213077798	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422B*	29,400	\$4,116
213077786	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122B*	29,200	\$4,088
213077776	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122B*	29,200	\$4,088
213077766	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	29,400	\$4,116
213077756	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN1002122B*	29,600	\$4,144
213077746	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122B*	29,000	\$4,060
213077736	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122B*	29,400	\$4,116
213077726	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122B*	29,400	\$4,116
213077716	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122B*	29,000	\$4,060
213077706	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122B*	29,400	\$4,116
213077695	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120B*	29,200	\$4,088
213077682	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120B*	29,200	\$4,088
211712333	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80ESU0401712A*	23,400	\$3,276
213077669	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	29,400	\$4,116
213077643	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120B*	29,000	\$4,060
213077630	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077617	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120B*	29,400	\$4,116
213077604	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120B*	29,000	\$4,060
213077591	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120B*	29,400	\$4,116
211712321	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80ESU1002120A*	23,600	\$3,304
213077579	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120B*	29,200	\$4,088
213077568	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120B*	29,200	\$4,088
213077557	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	29,400	\$4,116
213077546	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN0802120B*	29,600	\$4,144
213077535	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120B*	29,000	\$4,060
213077524	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120B*	29,200	\$4,088
213077513	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120B*	29,400	\$4,116
213077502	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120B*	29,400	\$4,116
213077491	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120B*	29,200	\$4,088
213077480	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120B*	29,400	\$4,116
213077468	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0801716B*	29,200	\$4,088
211712553	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*92ESN1002120A*	23,400	\$3,276
213077455	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0801716B*	29,600	\$4,144
211712297	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*95ESU1002120A*	23,600	\$3,304
213077442	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*96VTN0801716B*	29,400	\$4,116
213077403	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VTN0801716B*	29,200	\$4,088
213077390	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716B*	29,400	\$4,116
213077377	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VTN0801716B*	29,200	\$4,088
213077364	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96VTN0801716B*	29,400	\$4,116
213077351	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VTN0801716B*	29,400	\$4,116
213077338	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*96VTN0801716B*	29,600	\$4,144
211712276	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80VSL0702120A*	23,400	\$3,276
213077326	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*96VTN0601412B*	29,400	\$4,116
213077304	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601412B*	29,400	\$4,116
213077293	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601412B*	29,600	\$4,144
213077282	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0401712B*	29,400	\$4,116
213077271	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0401712B*	29,200	\$4,088
213077260	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422B*	29,200	\$4,088
213077250	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422B*	29,000	\$4,060
213077240	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422B*	29,400	\$4,116
213077230	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120B*	29,200	\$4,088
211712565	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*95ESN0601714A*	23,600	\$3,304
213077220	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120B*	29,200	\$4,088
213077210	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077190	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120B*	29,000	\$4,060
213077180	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120B*	29,000	\$4,060
213077170	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120B*	29,400	\$4,116
213077160	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120B*	29,400	\$4,116
213077150	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120B*	29,000	\$4,060
213077140	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120B*	29,400	\$4,116
213077130	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120B*	29,200	\$4,088
213077120	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120B*	29,200	\$4,088
213077110	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	29,400	\$4,116
213077100	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*96VSN0802120B*	29,600	\$4,144
213077090	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120B*	29,000	\$4,060
213077080	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120B*	29,200	\$4,088
213077070	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120B*	29,400	\$4,116
213077060	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120B*	29,400	\$4,116
213077050	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120B*	29,200	\$4,088
211712234	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	23,600	\$3,304
213077040	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120B*	29,400	\$4,116
213077030	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716B*	29,200	\$4,088
213077020	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716B*	29,600	\$4,144
213077010	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*96VSN0801716B*	29,400	\$4,116
213076980	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716B*	29,200	\$4,088
213076970	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716B*	29,400	\$4,116
213076960	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716B*	29,200	\$4,088
213076950	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716B*	29,400	\$4,116
213076940	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716B*	29,400	\$4,116
213076930	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716B*	29,600	\$4,144
213076920	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*96VSN0601412B*	29,400	\$4,116
213076900	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412B*	29,400	\$4,116
211712211	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*96VSN0801716A*	23,400	\$3,276
213076890	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601412B*	29,600	\$4,144
213076880	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0401712B*	29,400	\$4,116
213076870	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0401712B*	29,200	\$4,088
213076853	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122B*	29,200	\$4,088
213076841	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122B*	29,200	\$4,088
213076829	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122B*	29,400	\$4,116
213076805	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122B*	29,000	\$4,060
213076793	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122B*	29,000	\$4,060
213076781	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122B*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712589	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80ESU0601716A	23,400	\$3,276
213076769	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122B*	29,400	\$4,116
213076757	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122B*	29,400	\$4,116
213076745	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122B*	29,200	\$4,088
213076733	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122B*	29,400	\$4,116
213076722	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120B*	29,200	\$4,088
213076711	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120B*	29,200	\$4,088
213076700	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	29,400	\$4,116
213076689	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*80VTL0902120B*	29,600	\$4,144
213076678	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120B*	29,200	\$4,088
213076667	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120B*	29,400	\$4,116
211712169	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
213076656	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120B*	29,400	\$4,116
213076645	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120B*	29,200	\$4,088
213076634	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120B*	29,400	\$4,116
211712661	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80VSL0702120A*	23,400	\$3,276
211712157	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*95ESN1002120A*	23,600	\$3,304
213076579	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716B*	29,200	\$4,088
213076568	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	29,400	\$4,116
213076557	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80VTL0701716B*	29,400	\$4,116
213076524	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716B*	29,000	\$4,060
213076513	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716B*	29,400	\$4,116
213076502	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716B*	29,000	\$4,060
211712681	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902420A*	23,400	\$3,276
213076491	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716B*	29,400	\$4,116
213076480	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716B*	29,400	\$4,116
213076469	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716B*	29,400	\$4,116
213076449	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80VTL0451412B*	29,400	\$4,116
211712691	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80VSL1102422A*	23,400	\$3,276
213076425	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412B*	29,200	\$4,088
213076413	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412B*	29,400	\$4,116
213076338	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002122A*	29,200	\$4,088
213076329	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002122A*	29,200	\$4,088
213076320	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002122A*	29,400	\$4,116
211712702	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*95ESU1002120A*	23,600	\$3,304
213076302	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002122A*	29,000	\$4,060
213076293	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002122A*	29,000	\$4,060
213076284	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002122A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076275	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002122A*	29,400	\$4,116
213076266	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002122A*	29,400	\$4,116
213076257	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002122A*	29,000	\$4,060
213076248	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002122A*	29,400	\$4,116
213076000	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002120A*	29,200	\$4,088
211712714	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80ESU1002120A*	23,600	\$3,304
213075988	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002120A*	29,200	\$4,088
213075976	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002120A*	29,400	\$4,116
213075952	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002120A*	29,000	\$4,060
213075940	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002120A*	29,000	\$4,060
213075928	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002120A*	29,000	\$4,060
213075916	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002120A*	29,400	\$4,116
213075904	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002120A*	29,400	\$4,116
213075892	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002120A*	29,000	\$4,060
213075880	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002120A*	29,400	\$4,116
212989507	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95MSU0802120A*	29,000	\$4,060
212989495	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95MSU0802120A*	29,000	\$4,060
212988979	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95MSU0601716A*	29,000	\$4,060
212988407	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96MSN1402422A*	29,000	\$4,060
211712740	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*95ESN0802120A*	23,400	\$3,276
212988323	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96MSN1202422A*	29,000	\$4,060
212985520	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002122A*	29,000	\$4,060
211712752	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*95ESN1002120A*	23,600	\$3,304
212985511	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002122A*	29,000	\$4,060
212985245	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002120A*	28,800	\$4,032
212985233	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002120A*	28,800	\$4,032
212984955	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*92MSN0802120A*	28,800	\$4,032
212984945	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92MSN0802120A*	28,800	\$4,032
212984415	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92MSN0801716A*	29,000	\$4,060
212983875	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92MSN0601714A*	29,000	\$4,060
212982606	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MSU0601716A*	28,800	\$4,032
212981212	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1352420A*	29,000	\$4,060
212980693	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902420A*	29,000	\$4,060
212980492	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980481	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980173	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902116A*	28,800	\$4,032
212980162	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902116A*	28,800	\$4,032
212979659	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0901714A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979417	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0702116A*	28,800	\$4,032
212979407	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0702116A*	28,800	\$4,032
212978969	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701716A*	29,000	\$4,060
212978483	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
212977257	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422B*	29,000	\$4,060
212977093	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122B*	28,800	\$4,032
212977083	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122B*	28,800	\$4,032
212976812	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120B*	29,000	\$4,060
211712798	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122A*	23,400	\$3,276
212976799	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120B*	29,000	\$4,060
212976530	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120B*	28,800	\$4,032
212976307	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0801716B*	29,000	\$4,060
212974417	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120B*	29,000	\$4,060
212974197	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120B*	28,800	\$4,032
212974057	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716B*	29,000	\$4,060
212972247	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120B*	29,000	\$4,060
212972236	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120B*	29,000	\$4,060
212971880	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716B*	29,000	\$4,060
212970741	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120B*	29,200	\$4,088
212970731	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120B*	29,200	\$4,088
211712822	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	23,600	\$3,304
212970721	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	29,400	\$4,116
212970711	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*80VSL0902120B*	29,600	\$4,144
212970701	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120B*	29,000	\$4,060
212970691	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120B*	29,000	\$4,060
212970681	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120B*	29,200	\$4,088
212970671	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120B*	29,400	\$4,116
212970661	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120B*	29,400	\$4,116
211712835	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	23,400	\$3,276
212970651	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120B*	29,200	\$4,088
212970641	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120B*	29,400	\$4,116
212970481	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716B*	29,200	\$4,088
212970471	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	29,400	\$4,116
212970461	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80VSL0701716B*	29,400	\$4,116
212970431	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716B*	29,000	\$4,060
211712848	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	23,400	\$3,276
212970421	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716B*	29,200	\$4,088
212970411	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212970401	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716B*	29,200	\$4,088
212970391	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716B*	29,400	\$4,116
212970381	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716B*	29,600	\$4,144
212970371	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716B*	29,600	\$4,144
212969961	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80VSL0451412B*	29,400	\$4,116
211712861	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	23,600	\$3,304
212969941	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412B*	29,200	\$4,088
212969931	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412B*	29,400	\$4,116
212390903	DAY & NIGHT	DLCURAH36ABK	FJMA4*36L*B*		29,400	\$4,116
212384856	DAY & NIGHT	DLCURAH36ABK	FVM4X36***L		29,400	\$4,116
212384832	DAY & NIGHT	DLCURAH36ABK	FJMA4*42L*C*		29,200	\$4,088
211712874	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	23,400	\$3,276
212384792	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0801716A*	29,200	\$4,088
212384780	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701716A*	29,200	\$4,088
212384769	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV112A16A	29,600	\$4,144
212384759	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV112K14A	29,400	\$4,116
212384749	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV098A12*	29,600	\$4,144
212384739	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV098J12*	29,600	\$4,144
212384728	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	29,400	\$4,116
211712887	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	23,600	\$3,304
212384716	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0802120A	29,600	\$4,144
212384704	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0601714A*	29,400	\$4,116
212384692	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	29,400	\$4,116
212384680	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	29,400	\$4,116
212384668	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0801716A*	29,400	\$4,116
212384656	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0601714A*	29,400	\$4,116
211712900	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*92ESN0802120A*	23,400	\$3,276
212384643	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	29,400	\$4,116
212384630	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	29,400	\$4,116
212384617	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701712A*	29,600	\$4,144
212384604	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0451712A*	29,400	\$4,116
212384593	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	29,400	\$4,116
211712912	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*92ESN1002120A*	23,400	\$3,276
212384582	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120A*	29,600	\$4,144
212384571	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	29,400	\$4,116
212384559	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	29,600	\$4,144
212384548	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120A*	29,400	\$4,116
212384533	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384521	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	29,400	\$4,116
211712958	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	OLV154F20A	23,600	\$3,304
211712968	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	OMV154L20A	23,600	\$3,304
211712978	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0601714A*	23,200	\$3,248
211712988	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120A*	23,000	\$3,220
211712998	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120A*	23,200	\$3,248
211713008	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716A*	23,200	\$3,248
211713019	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*95ESU0401712A*	23,200	\$3,248
211713031	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
211713043	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122A*	23,000	\$3,220
211713053	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VSL0451716A*	23,200	\$3,248
211713063	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VSL0701716A*	23,200	\$3,248
211713073	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VSL0702120A*	23,200	\$3,248
211713083	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VSL0902120A*	23,200	\$3,248
211713094	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*95ESU1002120A*	23,400	\$3,276
211713106	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*95ESU0601716A*	23,400	\$3,276
211713118	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ESU1002120A*	23,400	\$3,276
211713130	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ESU0401712A*	23,200	\$3,248
213353888	DAY & NIGHT	DLCURAH60ABK	F5MA4*60L*D*		37,800	\$5,292
213607818	DAY & NIGHT	DLCURAH60ABK	FTMA4B60L0D*		37,400	\$5,236
211713145	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120A*	23,200	\$3,248
211713156	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*95ESN0802120A*	23,200	\$3,248
211713168	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*95ESN1002120A*	23,600	\$3,304
211713180	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716A*	23,200	\$3,248
211713192	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VTN0601714A*	23,200	\$3,248
211713203	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120A*	23,000	\$3,220
211713214	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120A*	23,200	\$3,248
211713225	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122A*	23,200	\$3,248
210025743	DAY & NIGHT	DLCURAH60ABK	DLFUAAH60XAK		42,000	\$5,880
212384509	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	29,400	\$4,116
212384498	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120A*	29,400	\$4,116
211713236	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
212384488	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	29,400	\$4,116
212384478	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716A*	29,400	\$4,116
212384468	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002122A*	29,600	\$4,144
212384458	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002122A*	29,600	\$4,144
212384448	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002122A*	29,600	\$4,144
212384437	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713249	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
212384426	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	29,400	\$4,116
212384416	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	29,400	\$4,116
212384406	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120A*	29,400	\$4,116
212384396	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0601714A*	29,400	\$4,116
212384386	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	OMV112K14A	29,400	\$4,116
212384376	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	OLV098A12*	29,400	\$4,116
211713262	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
212384366	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	OMV098J12*	29,400	\$4,116
212384355	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80ESU0601716A	29,400	\$4,116
212384342	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701412A*	29,400	\$4,116
212384330	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*92ESN0801716A*	29,200	\$4,088
212384318	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*92ESN0601714A*	29,200	\$4,088
211713275	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
212384306	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*92ESN0601412A*	29,400	\$4,116
212384293	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0901714A*	29,400	\$4,116
212384280	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701712A*	29,400	\$4,116
212384267	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451712A*	29,400	\$4,116
211713288	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
212384254	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451412A*	29,600	\$4,144
212384240	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80VTL0451412A*	29,400	\$4,116
212384229	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80VSL0701716A*	29,200	\$4,088
212384219	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80VSL0451716A*	29,400	\$4,116
211713301	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
212384208	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701716A*	29,200	\$4,088
212384144	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*80ESU0802120A	29,800	\$4,172
212384132	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002120A*	29,600	\$4,144
211713314	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	23,400	\$3,276
212384120	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN0802120A*	29,600	\$4,144
211713327	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*92ESN0601714A*	23,000	\$3,220
211713339	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*92ESN0801716A*	23,400	\$3,276
211713351	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*92ESN0802120A*	23,200	\$3,248
212383813	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESU1002122A*	29,800	\$4,172
212383803	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESN1002122A*	29,800	\$4,172
211713363	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*92ESN1002120A*	23,200	\$3,248
212383793	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002122A*	29,800	\$4,172
211713375	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*95ESN0601714A*	23,200	\$3,248
211713387	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ESU0802120A	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383486	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701716A*	29,000	\$4,060
212383474	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92ESN0801716A*	29,000	\$4,060
211713399	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80ESU0601716A	23,200	\$3,248
212383462	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
212383451	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	OLV112A16A	29,400	\$4,116
212383440	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002120A*	29,200	\$4,088
212383429	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120A*	29,000	\$4,060
211713410	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	OMV098J12*	23,200	\$3,248
212383417	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95ESU0601716A*	29,200	\$4,088
212383405	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
212383393	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80ESU0601716A	29,200	\$4,088
212383381	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ESU0601716A	29,400	\$4,116
211713420	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	OLV098A12*	23,200	\$3,248
212383369	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ESU0802120A	29,600	\$4,144
212383357	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002120A*	29,400	\$4,116
212383345	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92ESN0802120A*	29,400	\$4,116
212383333	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92ESN0801716A*	29,400	\$4,116
212383320	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
212383307	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
212383294	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	29,600	\$4,144
212383281	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
212383270	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122A*	29,600	\$4,144
212383259	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VTN0601714A*	29,600	\$4,144
212383247	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716A*	29,400	\$4,116
212383235	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95ESN0802120A*	29,600	\$4,144
212383224	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120A*	29,400	\$4,116
212383212	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002120A*	29,400	\$4,116
212383201	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120A*	29,400	\$4,116
212383191	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0702120A*	29,400	\$4,116
212383181	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716A*	29,400	\$4,116
212383170	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95ESU0802120A*	29,800	\$4,172
212383159	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002122A*	29,600	\$4,144
212383148	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
212383137	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716A*	29,400	\$4,116
212383127	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120A*	29,400	\$4,116
212383117	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120A*	29,400	\$4,116
212383107	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0601714A*	29,600	\$4,144
212383097	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	OLV098A12*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383087	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	OMV098J12*	29,600	\$4,144
212383076	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80ESU0601716A	29,600	\$4,144
212383063	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	29,600	\$4,144
212383051	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*95ESN0601714A*	29,600	\$4,144
212383039	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*92ESN0801716A*	29,400	\$4,116
212383027	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601714A*	29,400	\$4,116
212383015	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601412A*	29,600	\$4,144
212383002	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	29,600	\$4,144
212382989	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	29,600	\$4,144
212382976	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	29,600	\$4,144
212382963	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	29,800	\$4,172
212382952	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601714A*	29,600	\$4,144
212382940	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716A*	29,400	\$4,116
212382923	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412A*	29,600	\$4,144
212382911	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*95ESU0601716A*	29,400	\$4,116
212382900	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716A*	29,400	\$4,116
212382890	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451716A*	29,600	\$4,144
212382879	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
212382868	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716A*	29,400	\$4,116
212382858	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601714A*	29,600	\$4,144
212382848	DAY & NIGHT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412A*	29,600	\$4,144
211230931	DAY & NIGHT	DLCURAH36ABK	FXM4X48**AL		29,000	\$4,060
211230920	DAY & NIGHT	DLCURAH36ABK	FXM4X42**AL		29,000	\$4,060
211230899	DAY & NIGHT	DLCURAH36ABK	FVM4X48***L		28,600	\$4,004
211230888	DAY & NIGHT	DLCURAH36ABK	FMA4X36**AL*		29,600	\$4,144
211230866	DAY & NIGHT	DLCURAH36ABK	FM(C,U)4Z36**AL*		29,600	\$4,144
211230810	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	OMV154L20A	29,200	\$4,088
211230801	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	OLV154F20A	29,400	\$4,116
211230792	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	OLV112A16A	29,200	\$4,088
211230783	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422A*	29,200	\$4,088
211230773	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122A*	29,200	\$4,088
211230764	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120A*	29,200	\$4,088
211230754	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120A*	29,200	\$4,088
211230744	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002122A*	29,400	\$4,116
211230734	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002120A*	29,200	\$4,088
211230723	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU0802120A*	29,600	\$4,144
211230713	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422A*	29,200	\$4,088
211230704	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230695	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120A*	29,200	\$4,088
211230685	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1402422A*	29,400	\$4,116
211230674	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1202422A*	29,400	\$4,116
211230664	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002122A*	29,400	\$4,116
211230654	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002120A*	29,200	\$4,088
211230643	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN0802120A*	29,400	\$4,116
211230632	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1202420A*	29,200	\$4,088
211230622	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002122A*	29,400	\$4,116
211230612	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002120A*	29,200	\$4,088
211230601	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN0802120A*	29,000	\$4,060
211230571	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122A*	29,200	\$4,088
211230561	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120A*	29,200	\$4,088
211230550	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU1002120A*	29,200	\$4,088
211230539	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU0802120A	29,400	\$4,116
211230529	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL1102422A*	29,200	\$4,088
211230520	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902420A*	29,200	\$4,088
211230511	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120A*	29,200	\$4,088
211230502	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0702120A*	29,200	\$4,088
211230493	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1552420A*	29,200	\$4,088
211230481	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1352420A*	29,200	\$4,088
211230469	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102420A*	29,200	\$4,088
211230457	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102120A*	29,200	\$4,088
211230445	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902420A*	29,200	\$4,088
211230433	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902120A*	29,200	\$4,088
211230421	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902116A*	29,200	\$4,088
211230409	DAY & NIGHT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0702116A*	29,200	\$4,088
211230381	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV112K14A	29,200	\$4,088
211230372	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV098J12*	29,200	\$4,088
211230363	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV112A16A	29,200	\$4,088
211230354	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV098A12*	29,200	\$4,088
211230345	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122A*	29,200	\$4,088
211230336	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120A*	29,200	\$4,088
211230326	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120A*	29,200	\$4,088
211230316	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0601714A*	29,400	\$4,116
211230296	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002122A*	29,400	\$4,116
211230286	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002120A*	29,200	\$4,088
211230275	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0802120A*	29,600	\$4,144
211230264	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0601716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230254	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120A*	29,200	\$4,088
211230245	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120A*	29,200	\$4,088
211230236	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716A*	29,200	\$4,088
211230227	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0601714A*	29,200	\$4,088
211230209	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002122A*	29,400	\$4,116
211230199	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002120A*	29,200	\$4,088
211230188	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0802120A*	29,400	\$4,116
211230177	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0801716A*	29,200	\$4,088
211230166	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0601714A*	29,200	\$4,088
211230156	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002122A*	29,400	\$4,116
211230146	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002120A*	29,200	\$4,088
211230135	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0802120A*	29,000	\$4,060
211230124	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0601714A*	29,200	\$4,088
211230087	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122A*	29,200	\$4,088
211230077	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120A*	29,200	\$4,088
211230065	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716A*	29,200	\$4,088
211230054	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU1002120A*	29,200	\$4,088
211230043	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0802120A	29,400	\$4,116
211230032	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0601716A	29,000	\$4,060
211230021	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0401712A*	29,600	\$4,144
211230011	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120A*	29,200	\$4,088
211230002	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0702120A*	29,200	\$4,088
211229993	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716A*	29,200	\$4,088
211229984	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0451716A*	29,200	\$4,088
211229973	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)1102120A*	29,200	\$4,088
211229961	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902120A*	29,200	\$4,088
211229949	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902116A*	29,200	\$4,088
211229937	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0901714A*	29,200	\$4,088
211229925	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0702116A*	29,200	\$4,088
211229913	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701712A*	29,400	\$4,116
211229901	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0451712A*	29,200	\$4,088
211229855	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	29,400	\$4,116
211229846	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120A*	29,400	\$4,116
211229836	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0601714A*	29,600	\$4,144
211229825	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002120A*	29,400	\$4,116
211229804	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0451716A*	29,400	\$4,116
211229793	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	29,400	\$4,116
211229781	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229769	DAY & NIGHT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	29,400	\$4,116
211229750	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*96VTN0601714A*	29,400	\$4,116
211229739	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*95ESU0601716A*	29,200	\$4,088
211229729	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*96VSN0801716A*	29,400	\$4,116
211229720	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*96VSN0601714A*	29,400	\$4,116
211229692	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*95ESN0601714A*	29,400	\$4,116
211229673	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80VTL0701716A*	29,200	\$4,088
211229661	DAY & NIGHT	DLCURAH36ABK	END4X42L17**	*80VSL0451412A*	29,400	\$4,116
211229652	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	OMV154L20A	29,000	\$4,060
211229643	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	OLV154F20A	29,200	\$4,088
211229634	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	OLV112A16A	29,000	\$4,060
211229625	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422A*	29,000	\$4,060
211229615	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122A*	28,800	\$4,032
211229606	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120A*	29,000	\$4,060
211229596	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120A*	28,800	\$4,032
211714019	DAY & NIGHT	DLCURAH30ABK	EN(A,D)4X36L21**	*80ESU0802120A	23,600	\$3,304
211229586	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002122A*	29,200	\$4,088
211229576	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002120A*	29,000	\$4,060
211229565	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95ESU0802120A*	29,400	\$4,116
211229555	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422A*	29,000	\$4,060
211229546	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120A*	29,000	\$4,060
211229537	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120A*	29,000	\$4,060
211229527	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95ESN1402422A*	29,200	\$4,088
211229516	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95ESN1202422A*	29,200	\$4,088
211229506	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002122A*	29,200	\$4,088
211229496	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002120A*	29,000	\$4,060
211714042	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80VSL0451412A*	23,400	\$3,276
211229485	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*95ESN0802120A*	29,200	\$4,088
211229474	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*92ESN1202420A*	29,000	\$4,060
211229464	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002122A*	29,200	\$4,088
211229454	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002120A*	28,800	\$4,032
211714052	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*96VSN0801716A*	23,400	\$3,276
211229443	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*92ESN0802120A*	28,800	\$4,032
211229413	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122A*	29,000	\$4,060
211229403	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120A*	28,800	\$4,032
211229392	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ESU1002120A*	29,000	\$4,060
211229381	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ESU0802120A	29,200	\$4,088
211714063	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*95ESU0401712A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229371	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80VSL1102422A*	28,800	\$4,032
211229362	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902420A*	28,800	\$4,032
211229353	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120A*	28,800	\$4,032
211229344	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80VSL0702120A*	29,000	\$4,060
211229335	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1552420A*	29,200	\$4,088
211229323	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1352420A*	29,000	\$4,060
211714075	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701716A*	23,600	\$3,304
211229311	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102420A*	28,800	\$4,032
211229299	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102120A*	29,000	\$4,060
211229287	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902420A*	29,000	\$4,060
211229275	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902120A*	29,000	\$4,060
211714086	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80VSL0451716A*	23,400	\$3,276
211229263	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902116A*	29,000	\$4,060
211229251	DAY & NIGHT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0702116A*	28,800	\$4,032
211229223	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	OMV112K14A	29,000	\$4,060
211229214	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	OMV098J12*	29,000	\$4,060
211714096	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80VSL0701716A*	23,400	\$3,276
211229205	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	OLV112A16A	29,000	\$4,060
211229196	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	OLV098A12*	29,000	\$4,060
211229187	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122A*	28,800	\$4,032
211229178	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120A*	29,000	\$4,060
211229168	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120A*	29,000	\$4,060
211714107	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*95ESU0601716A*	23,600	\$3,304
211229158	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0601714A*	29,200	\$4,088
211229148	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002122A*	29,200	\$4,088
211229138	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002120A*	29,000	\$4,060
211229127	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95ESU0802120A*	29,400	\$4,116
211229116	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95ESU0601716A*	29,000	\$4,060
211714119	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80ESU0401712A*	23,400	\$3,276
211229106	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120A*	29,000	\$4,060
211229097	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120A*	29,000	\$4,060
211229088	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716A*	29,000	\$4,060
211229079	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0601714A*	29,000	\$4,060
211229061	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002122A*	29,200	\$4,088
211714131	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80VTL0451412A*	23,400	\$3,276
211229051	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002120A*	29,000	\$4,060
211229040	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95ESN0802120A*	29,200	\$4,088
211229029	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95ESN0801716A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229018	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*95ESN0601714A*	29,000	\$4,060
211229008	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002122A*	29,200	\$4,088
211228998	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002120A*	28,800	\$4,032
211228987	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92ESN0802120A*	28,800	\$4,032
211228976	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92ESN0801716A*	29,000	\$4,060
211714148	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80VTL0701716A*	23,400	\$3,276
211228965	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*92ESN0601714A*	29,000	\$4,060
211228928	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122A*	29,000	\$4,060
211228918	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120A*	28,800	\$4,032
211228906	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716A*	29,000	\$4,060
211228895	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ESU1002120A*	29,000	\$4,060
211714160	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*96VTN0601714A*	23,400	\$3,276
211228884	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ESU0802120A	29,200	\$4,088
211228873	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ESU0601716A	29,000	\$4,060
211228862	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ESU0401712A*	29,400	\$4,116
211228852	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120A*	28,800	\$4,032
211228843	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0702120A*	29,000	\$4,060
211714171	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0451412A*	23,400	\$3,276
211228834	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716A*	29,000	\$4,060
211228825	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0451716A*	29,000	\$4,060
211228814	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)1102120A*	29,000	\$4,060
211228802	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902120A*	29,000	\$4,060
211228790	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211228778	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0901714A*	29,000	\$4,060
211714184	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701712A*	23,400	\$3,276
211228766	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0702116A*	28,800	\$4,032
211228754	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701712A*	29,000	\$4,060
211228742	DAY & NIGHT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228696	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	OMV112K14A	29,200	\$4,088
211228687	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	OMV098J12*	29,200	\$4,088
211228678	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	OLV112A16A	29,200	\$4,088
211714197	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0901714A*	23,400	\$3,276
211228669	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	OLV098A12*	29,200	\$4,088
211228660	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122A*	29,000	\$4,060
211228651	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120A*	29,200	\$4,088
211228641	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120A*	29,200	\$4,088
211228631	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VTN0601714A*	29,200	\$4,088
211714210	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*92ESN0601412A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228611	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002122A*	29,200	\$4,088
211228601	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002120A*	29,000	\$4,060
211228590	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95ESU0802120A*	29,400	\$4,116
211228579	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95ESU0601716A*	29,200	\$4,088
211714222	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*92ESN0601714A*	23,200	\$3,248
211228569	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120A*	29,000	\$4,060
211228560	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120A*	29,000	\$4,060
211228551	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716A*	29,200	\$4,088
211228542	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0601714A*	29,200	\$4,088
211714234	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*92ESN0801716A*	23,200	\$3,248
211228524	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002122A*	29,200	\$4,088
211228514	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002120A*	29,200	\$4,088
211228503	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95ESN0802120A*	29,200	\$4,088
211228481	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*95ESN0601714A*	29,400	\$4,116
211714246	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*95ESN0601714A*	23,400	\$3,276
211228471	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002122A*	29,400	\$4,116
211228461	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002120A*	29,200	\$4,088
211228450	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92ESN0802120A*	29,200	\$4,088
211714258	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701412A*	23,200	\$3,248
211228439	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*92ESN0601714A*	29,000	\$4,060
211228402	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122A*	29,200	\$4,088
211228392	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120A*	29,000	\$4,060
211228380	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716A*	29,000	\$4,060
211714271	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80ESU0601716A	23,400	\$3,276
211228369	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ESU1002120A*	29,000	\$4,060
211228358	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ESU0802120A	29,200	\$4,088
211228347	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ESU0601716A	29,200	\$4,088
211714282	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	OMV098J12*	23,400	\$3,276
211228336	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ESU0401712A*	29,400	\$4,116
211228326	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120A*	29,000	\$4,060
211714292	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	OLV098A12*	23,400	\$3,276
211228317	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0702120A*	29,000	\$4,060
211228308	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716A*	29,200	\$4,088
211228299	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0451716A*	29,200	\$4,088
211228288	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211228276	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211714312	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	23,400	\$3,276
211228264	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228252	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211714322	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	23,400	\$3,276
211228240	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211228228	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211228216	DAY & NIGHT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228170	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	OMV154L20A	29,400	\$4,116
211228161	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	OLV154F20A	29,600	\$4,144
211714345	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	23,600	\$3,304
211714357	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	23,400	\$3,276
211714387	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	23,400	\$3,276
211714408	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	23,600	\$3,304
212970761	DAY & NIGHT	DLCURAH48AAK	EA*4X48L24A*	*80VSL0902120B*	32,600	\$4,564
212970751	DAY & NIGHT	DLCURAH48AAK	EA*4X48L21A*	*80VSL0902120B*	32,600	\$4,564
211714420	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	23,600	\$3,304
211714432	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	23,600	\$3,304
211714444	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0401712A*	23,400	\$3,276
212970801	DAY & NIGHT	DLCURAH48ABK	EA*4X48L21A*	*80VSL0902120B*	31,400	\$4,396
212970811	DAY & NIGHT	DLCURAH48ABK	EA*4X48L24A*	*80VSL0902120B*	31,400	\$4,396
212970821	DAY & NIGHT	DLCURAH48ABK	EA*4X60L24A*	*80VSL0902120B*	31,000	\$4,340
212970841	DAY & NIGHT	DLCURAH48ABK	EA*4X61L24A*	*80VSL0902120B*	31,000	\$4,340
212970831	DAY & NIGHT	DLCURAH48ABK	EA*4X61L21A*	*80VSL0902120B*	31,000	\$4,340
211714470	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	23,400	\$3,276
211714482	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	23,400	\$3,276
211714515	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	23,400	\$3,276
211714539	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	23,600	\$3,304
211714552	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	23,400	\$3,276
211714565	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	23,600	\$3,304
211714578	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	23,400	\$3,276
211714591	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	23,600	\$3,304
211714628	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	23,400	\$3,276
211714640	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	23,400	\$3,276
211714664	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	23,400	\$3,276
211714689	DAY & NIGHT	DLCURAH30ABK	FJMA4*36L*B*		23,400	\$3,276
212969881	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412B*	23,400	\$3,276
212969921	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80VSL0451412B*	23,400	\$3,276
212970301	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80VSL0701716B*	23,600	\$3,304
212970361	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	23,600	\$3,304
212970591	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80VSL0902120B*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212970601	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902120B*	23,600	\$3,304
212970631	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	23,600	\$3,304
212971296	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412B*	23,400	\$3,276
212971344	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80VTL0451412B*	23,400	\$3,276
212971781	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716B*	23,400	\$3,276
212971792	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716B*	23,200	\$3,248
212971803	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716B*	23,600	\$3,304
212971814	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716B*	23,200	\$3,248
212971858	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80VTL0701716B*	23,400	\$3,276
212971869	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	23,600	\$3,304
212972170	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120B*	23,200	\$3,248
212972181	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80VTL0902120B*	23,600	\$3,304
212972192	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80VTL0902120B*	23,600	\$3,304
212972203	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120B*	23,200	\$3,248
212972225	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	23,600	\$3,304
212972452	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122B*	23,400	\$3,276
212972464	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122B*	23,400	\$3,276
212972476	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122B*	23,400	\$3,276
212972488	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122B*	23,200	\$3,248
212973647	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*96VSN0601412B*	23,600	\$3,304
212973967	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716B*	23,400	\$3,276
212973977	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716B*	23,400	\$3,276
212973997	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716B*	23,200	\$3,248
212974037	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*96VSN0801716B*	23,400	\$3,276
212974137	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120B*	23,200	\$3,248
212974147	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*96VSN0802120B*	23,400	\$3,276
212974157	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96VSN0802120B*	23,400	\$3,276
212974167	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120B*	23,200	\$3,248
212974187	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	23,600	\$3,304
212974357	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120B*	23,200	\$3,248
212974367	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*96VSN1002120B*	23,600	\$3,304
212974377	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96VSN1002120B*	23,600	\$3,304
212974387	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120B*	23,200	\$3,248
212974407	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	23,600	\$3,304
212974527	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96VSN1202422B*	23,600	\$3,304
212975766	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*96VTN0601412B*	23,600	\$3,304
212976181	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*96VTN0801716B*	23,400	\$3,276
212976194	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VTN0801716B*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976220	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VTN0801716B*	23,200	\$3,248
212976272	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*96VTN0801716B*	23,400	\$3,276
212976449	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120B*	23,200	\$3,248
212976463	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*96VTN0802120B*	23,400	\$3,276
212976477	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96VTN0802120B*	23,400	\$3,276
212976491	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120B*	23,200	\$3,248
212976518	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	23,600	\$3,304
212976721	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120B*	23,200	\$3,248
212976734	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002120B*	23,600	\$3,304
212976747	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002120B*	23,600	\$3,304
212976760	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120B*	23,200	\$3,248
212976786	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	23,600	\$3,304
212977023	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122B*	23,200	\$3,248
212977033	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002122B*	23,400	\$3,276
212977043	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002122B*	23,400	\$3,276
212977053	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122B*	23,200	\$3,248
212977073	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	23,400	\$3,276
212977245	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96VTN1202422B*	23,600	\$3,304
212977520	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	23,400	\$3,276
212977556	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0451412A*	23,400	\$3,276
212978024	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	23,400	\$3,276
212978072	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701412A*	23,400	\$3,276
212978527	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978538	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978549	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978560	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978604	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701712A*	23,400	\$3,276
212978615	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	23,400	\$3,276
212979017	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	23,400	\$3,276
212979029	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979041	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	23,600	\$3,304
212979053	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979101	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701716A*	23,400	\$3,276
212979113	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	23,600	\$3,304
212979437	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	23,200	\$3,248
212979447	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979457	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979467	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979707	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979719	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979731	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979743	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979791	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0901714A*	23,400	\$3,276
212980195	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980228	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980250	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	23,600	\$3,304
212980514	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980525	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	23,600	\$3,304
212980547	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980569	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	23,600	\$3,304
212980702	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	23,600	\$3,304
212980904	DAY & NIGHT	DLCURAH30ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980916	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980928	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980940	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980952	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980976	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	23,600	\$3,304
212981114	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	23,400	\$3,276
212981223	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	23,600	\$3,304
212981324	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	23,400	\$3,276
212981586	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*80MSU1002120A*	23,400	\$3,276
212981670	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*80MSU1002120A*	23,400	\$3,276
212982654	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*80MSU0601716A*	23,400	\$3,276
212983472	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601412A*	23,400	\$3,276
212983502	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*92MSN0601412A*	23,600	\$3,304
212983923	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601714A*	23,400	\$3,276
212983935	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*92MSN0601714A*	23,200	\$3,248
212983959	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*92MSN0601714A*	23,200	\$3,248
212984007	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*92MSN0601714A*	23,400	\$3,276
212984463	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*92MSN0801716A*	23,400	\$3,276
212984475	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*92MSN0801716A*	23,200	\$3,248
212984487	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*92MSN0801716A*	23,400	\$3,276
212984499	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*92MSN0801716A*	23,200	\$3,248
212984547	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*92MSN0801716A*	23,400	\$3,276
212984975	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*92MSN0802120A*	23,200	\$3,248
212984985	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*92MSN0802120A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984995	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*92MSN0802120A*	23,400	\$3,276
212985005	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*92MSN0802120A*	23,200	\$3,248
212985025	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	23,600	\$3,304
212985269	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*92MSN1002120A*	23,200	\$3,248
212985281	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*92MSN1002120A*	23,400	\$3,276
212985293	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*92MSN1002120A*	23,400	\$3,276
212985305	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*92MSN1002120A*	23,600	\$3,304
212985329	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	23,600	\$3,304
212985618	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*92MSN1202420A*	23,400	\$3,276
212985749	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*96MSN0261410A*	23,600	\$3,304
212986853	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*96MSN0601412A*	23,600	\$3,304
212987261	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*96MSN0801716A*	23,400	\$3,276
212987273	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96MSN0801716A*	23,200	\$3,248
212987297	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96MSN0801716A*	23,400	\$3,276
212987345	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*96MSN0801716A*	23,600	\$3,304
212987357	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	23,600	\$3,304
212987729	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*96MSN0802120A*	23,200	\$3,248
212987753	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96MSN0802120A*	23,400	\$3,276
212987765	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*96MSN0802120A*	23,200	\$3,248
212988335	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96MSN1202422A*	23,400	\$3,276
212988417	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*96MSN1402422A*	23,600	\$3,304
212988583	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*95MSU0401712A*	23,600	\$3,304
212988595	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*95MSU0401712A*	23,200	\$3,248
212988619	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*95MSU0401712A*	23,200	\$3,248
212988631	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*95MSU0401712A*	23,600	\$3,304
212989027	DAY & NIGHT	DLCURAH30ABK	EA*4X37L17A*	*95MSU0601716A*	23,400	\$3,276
212989039	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*95MSU0601716A*	23,200	\$3,248
212989051	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*95MSU0601716A*	23,600	\$3,304
212989063	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*95MSU0601716A*	23,200	\$3,248
212989111	DAY & NIGHT	DLCURAH30ABK	END4X42L17**	*95MSU0601716A*	23,400	\$3,276
212989123	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	23,600	\$3,304
212989531	DAY & NIGHT	DLCURAH30ABK	EA*4X37L21A*	*95MSU0802120A*	23,200	\$3,248
212989543	DAY & NIGHT	DLCURAH30ABK	EA*4X42L21A*	*95MSU0802120A*	23,600	\$3,304
212989555	DAY & NIGHT	DLCURAH30ABK	EA*4X42L24A*	*95MSU0802120A*	23,600	\$3,304
212989567	DAY & NIGHT	DLCURAH30ABK	EA*4X43L21A*	*95MSU0802120A*	23,200	\$3,248
212989591	DAY & NIGHT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	23,600	\$3,304
213249296	DAY & NIGHT	DLCURAH30ABK	FEVA0036**+NAVA43601CK		23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213353812	DAY & NIGHT	DLCURAH30ABK	F5MA4*30L*B*		23,400	\$3,276
213353822	DAY & NIGHT	DLCURAH30ABK	F5MA4*36L*B*		23,600	\$3,304
211226264	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	29,600	\$4,144
211226276	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	29,600	\$4,144
211226288	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211226299	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0451716A*	29,600	\$4,144
211226309	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*80ESU1002120A*	29,400	\$4,116
211226331	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92ESN0601714A*	29,400	\$4,116
211226341	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002122A*	29,600	\$4,144
211226351	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95ESN0601714A*	29,400	\$4,116
211226362	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95ESN0801716A*	29,400	\$4,116
211226373	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002120A*	29,600	\$4,144
211226383	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002122A*	29,600	\$4,144
211226393	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*95ESU0601716A*	29,400	\$4,116
211226404	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120A*	29,400	\$4,116
211226414	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120A*	29,600	\$4,144
211226423	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122A*	29,400	\$4,116
211226432	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	OLV098A12*	29,600	\$4,144
211226441	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	OLV112A16A	29,600	\$4,144
211226450	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	OMV098J12*	29,600	\$4,144
211226459	DAY & NIGHT	DLCURAH36ABK	EA*4X36L21A*	OMV112K14A	29,600	\$4,144
211226487	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	29,400	\$4,116
211226499	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	29,200	\$4,088
211226511	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701712A*	29,400	\$4,116
211226523	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
211226534	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226545	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412A*	29,400	\$4,116
211226554	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451716A*	29,400	\$4,116
211226563	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716A*	29,400	\$4,116
211226584	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412A*	29,400	\$4,116
211226596	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716A*	29,400	\$4,116
211226617	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601412A*	29,400	\$4,116
211226628	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601714A*	29,200	\$4,088
211226639	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*92ESN0801716A*	29,400	\$4,116
211226661	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*95ESN0601714A*	29,400	\$4,116
211226671	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412A*	29,400	\$4,116
211226680	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601714A*	29,400	\$4,116
211226689	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226699	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*95ESU0601716A*	29,400	\$4,116
211226710	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601714A*	29,400	\$4,116
211226719	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	OLV098A12*	29,400	\$4,116
211226728	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	OMV098J12*	29,400	\$4,116
211226737	DAY & NIGHT	DLCURAH36ABK	EA*4X37L17A*	OMV112K14A	29,400	\$4,116
211226795	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211226807	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211226819	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226831	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211226843	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211226855	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211226866	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0451716A*	29,200	\$4,088
211226875	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716A*	29,200	\$4,088
211226884	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0702120A*	29,000	\$4,060
211226893	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120A*	29,000	\$4,060
211226903	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ESU0401712A*	29,400	\$4,116
211226914	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ESU0601716A	29,200	\$4,088
211226925	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ESU0802120A	29,400	\$4,116
211226936	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80ESU1002120A*	29,000	\$4,060
211226947	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716A*	29,000	\$4,060
211226959	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122A*	29,200	\$4,088
211226996	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92ESN0601714A*	29,000	\$4,060
211227007	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92ESN0801716A*	29,000	\$4,060
211227018	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92ESN0802120A*	29,200	\$4,088
211227028	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002122A*	29,400	\$4,116
211227038	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95ESN0601714A*	29,400	\$4,116
211227060	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95ESN0802120A*	29,200	\$4,088
211227071	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002120A*	29,200	\$4,088
211227081	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002122A*	29,200	\$4,088
211227099	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0601714A*	29,200	\$4,088
211227108	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716A*	29,200	\$4,088
211227117	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120A*	29,000	\$4,060
211227126	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120A*	29,000	\$4,060
211227136	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95ESU0802120A*	29,400	\$4,116
211227147	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002120A*	29,000	\$4,060
211227157	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002122A*	29,200	\$4,088
211227177	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VTN0601714A*	29,200	\$4,088
211227187	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227197	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120A*	29,200	\$4,088
211227206	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122A*	29,000	\$4,060
211227215	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	OLV098A12*	29,200	\$4,088
211227224	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	OLV112A16A	29,200	\$4,088
211227233	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	OMV098J12*	29,200	\$4,088
211227242	DAY & NIGHT	DLCURAH36ABK	EA*4X37L21A*	OMV112K14A	29,200	\$4,088
211227288	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0451712A*	29,400	\$4,116
211227300	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701712A*	29,400	\$4,116
211227312	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
211227323	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227335	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	29,400	\$4,116
211227347	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227359	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227371	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227382	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0451716A*	29,400	\$4,116
211227391	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716A*	29,400	\$4,116
211227400	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0702120A*	29,400	\$4,116
211227409	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120A*	29,400	\$4,116
211227430	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ESU0601716A	29,200	\$4,088
211227441	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ESU0802120A	29,600	\$4,144
211227452	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80ESU1002120A*	29,400	\$4,116
211227463	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716A*	29,400	\$4,116
211227475	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120A*	29,400	\$4,116
211227485	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122A*	29,400	\$4,116
211227513	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92ESN0601714A*	29,400	\$4,116
211227524	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92ESN0801716A*	29,400	\$4,116
211227535	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92ESN0802120A*	29,200	\$4,088
211227546	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002120A*	29,200	\$4,088
211227556	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002122A*	29,600	\$4,144
211227566	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95ESN0601714A*	29,400	\$4,116
211227577	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95ESN0802120A*	29,400	\$4,116
211227587	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95ESN1002122A*	29,600	\$4,144
211227596	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0601714A*	29,400	\$4,116
211227605	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716A*	29,400	\$4,116
211227614	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120A*	29,400	\$4,116
211227623	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120A*	29,400	\$4,116
211227633	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95ESU0601716A*	29,400	\$4,116
211227644	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95ESU0802120A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227655	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002120A*	29,400	\$4,116
211227665	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002122A*	29,600	\$4,144
211227675	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0601714A*	29,600	\$4,144
211227685	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716A*	29,400	\$4,116
211227695	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120A*	29,400	\$4,116
211227705	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120A*	29,400	\$4,116
211227714	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122A*	29,200	\$4,088
211227723	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	OLV098A12*	29,400	\$4,116
211227732	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	OMV098J12*	29,400	\$4,116
211227741	DAY & NIGHT	DLCURAH36ABK	EA*4X42L21A*	OMV112K14A	29,400	\$4,116
211227769	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227781	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227793	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227805	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	29,400	\$4,116
211227817	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227829	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	29,200	\$4,088
211227841	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	29,400	\$4,116
211227853	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1552420A*	29,400	\$4,116
211227862	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80VSL0702120A*	29,400	\$4,116
211227871	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120A*	29,400	\$4,116
211227880	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902420A*	29,400	\$4,116
211227889	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80VSL1102422A*	29,200	\$4,088
211227899	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ESU0802120A	29,600	\$4,144
211227910	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80ESU1002120A*	29,400	\$4,116
211227921	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120A*	29,400	\$4,116
211227931	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122A*	29,400	\$4,116
211227961	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*92ESN0802120A*	29,200	\$4,088
211227972	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002120A*	29,200	\$4,088
211227982	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002122A*	29,600	\$4,144
211227992	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*92ESN1202420A*	29,400	\$4,116
211228003	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95ESN0802120A*	29,400	\$4,116
211228014	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002120A*	29,400	\$4,116
211228024	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002122A*	29,600	\$4,144
211228034	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95ESN1202422A*	29,600	\$4,144
211228045	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95ESN1402422A*	29,600	\$4,144
211228055	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120A*	29,400	\$4,116
211228064	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120A*	29,400	\$4,116
211228073	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228083	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95ESU0802120A*	29,600	\$4,144
211228094	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002120A*	29,400	\$4,116
211228104	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002122A*	29,600	\$4,144
211228114	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120A*	29,400	\$4,116
211228124	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120A*	29,400	\$4,116
211228133	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122A*	29,200	\$4,088
211228143	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422A*	29,400	\$4,116
211228152	DAY & NIGHT	DLCURAH36ABK	EA*4X42L24A*	OLV112A16A	29,400	\$4,116
213353782	DAY & NIGHT	DLCURAH24ABK	F5MA4*30L*B*		19,100	\$2,674
213353772	DAY & NIGHT	DLCURAH24ABK	F5MA4*24L*B*		19,300	\$2,702
213249274	DAY & NIGHT	DLCURAH24ABK	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076402	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601716B*	19,400	\$2,716
213076376	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601716B*	19,400	\$2,716
213076365	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002122A*	19,100	\$2,674
213076347	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95MSU1002122A*	19,000	\$2,660
213076120	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002120A*	19,200	\$2,688
213076108	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*95MSU1002120A*	18,500	\$2,590
212989627	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0802120A*	19,100	\$2,674
212989615	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*95MSU0802120A*	18,600	\$2,604
212989603	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95MSU0802120A*	19,100	\$2,674
212989255	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0601716A*	19,100	\$2,674
212989243	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0601716A*	19,100	\$2,674
212989231	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0601716A*	19,100	\$2,674
212989219	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0601716A*	19,400	\$2,716
212989207	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*95MSU0601716A*	18,700	\$2,618
212989195	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*95MSU0601716A*	18,900	\$2,646
212989183	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95MSU0601716A*	19,100	\$2,674
212989171	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95MSU0601716A*	19,100	\$2,674
212989159	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95MSU0601716A*	19,100	\$2,674
212989147	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*95MSU0601716A*	18,600	\$2,604
212989135	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95MSU0601716A*	19,400	\$2,716
212988763	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0401712A*	19,200	\$2,688
212988751	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0401712A*	19,200	\$2,688
212988739	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0401712A*	19,200	\$2,688
212988727	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0401712A*	19,500	\$2,730
212988715	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*95MSU0401712A*	18,600	\$2,604
212988703	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*95MSU0401712A*	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988691	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95MSU0401712A*	19,000	\$2,660
212988679	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95MSU0401712A*	19,100	\$2,674
212988667	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95MSU0401712A*	19,200	\$2,688
212988655	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*95MSU0401712A*	18,700	\$2,618
212988643	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95MSU0401712A*	19,500	\$2,730
212987825	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0802120A*	19,100	\$2,674
212987813	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96MSN0802120A*	18,700	\$2,618
212987801	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96MSN0802120A*	19,100	\$2,674
212987489	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0801716A*	19,200	\$2,688
212987477	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0801716A*	19,200	\$2,688
212987465	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0801716A*	19,200	\$2,688
212987453	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0801716A*	19,500	\$2,730
212987441	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96MSN0801716A*	19,800	\$2,772
212987429	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96MSN0801716A*	18,800	\$2,632
212987417	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96MSN0801716A*	19,000	\$2,660
212987405	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96MSN0801716A*	19,100	\$2,674
212987393	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96MSN0801716A*	19,200	\$2,688
212987381	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96MSN0801716A*	18,700	\$2,618
212987369	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96MSN0801716A*	19,400	\$2,716
212986973	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0601412A*	19,200	\$2,688
212986963	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0601412A*	19,200	\$2,688
212986953	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0601412A*	19,200	\$2,688
212986943	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0601412A*	19,500	\$2,730
212986933	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0601412A*	19,500	\$2,730
212986923	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96MSN0601412A*	18,800	\$2,632
212986913	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96MSN0601412A*	19,100	\$2,674
212986903	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96MSN0601412A*	19,100	\$2,674
212986893	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96MSN0601412A*	19,200	\$2,688
212986883	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96MSN0601412A*	18,700	\$2,618
212986873	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96MSN0601412A*	19,400	\$2,716
212986863	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96MSN0601412A*	19,400	\$2,716
212986649	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0401712A*	19,100	\$2,674
212986637	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401712A*	19,100	\$2,674
212986625	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401712A*	19,100	\$2,674
212986613	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401712A*	19,700	\$2,758
211289633	DAY & NIGHT	DLCURAH60ABK	FVM4X60***L		37,800	\$5,292
213607743	DAY & NIGHT	DLCURAH36ABK	FTMA4B48LOC*		28,800	\$4,032
213607728	DAY & NIGHT	DLCURAH36ABK	FTMA4B36LOC*		29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213607683	DAY & NIGHT	DLCURAH30ABK	FTMA4B36L0C*		23,600	\$3,304
213607653	DAY & NIGHT	DLCURAH24ABK	FTMA4X24L0B*		19,300	\$2,702
213607638	DAY & NIGHT	DLCURAH24ABK	FTMA4B36L0C*		19,100	\$2,674
213607593	DAY & NIGHT	DLCURAH18ABK	FTMA4X24L0B*		12,400	\$1,736
212986601	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96MSN0401712A*	18,800	\$2,632
212986589	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401712A*	19,000	\$2,660
212986577	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96MSN0401712A*	19,200	\$2,688
212986565	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401712A*	19,200	\$2,688
212986553	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401712A*	19,200	\$2,688
212986541	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401712A*	18,900	\$2,646
212986529	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401712A*	19,500	\$2,730
212986265	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401410A*	19,200	\$2,688
212986253	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401410A*	19,200	\$2,688
212986145	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401410A*	19,500	\$2,730
212986133	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96MSN0401410A*	19,500	\$2,730
212985869	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0261410A*	19,000	\$2,660
212985859	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0261410A*	19,000	\$2,660
212985849	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0261410A*	19,100	\$2,674
212985839	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0261410A*	19,500	\$2,730
212985829	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0261410A*	19,500	\$2,730
212985819	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96MSN0261410A*	18,800	\$2,632
212985809	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96MSN0261410A*	19,100	\$2,674
212985799	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96MSN0261410A*	19,100	\$2,674
212985789	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96MSN0261410A*	19,200	\$2,688
212985779	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96MSN0261410A*	18,700	\$2,618
212985769	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96MSN0261410A*	19,500	\$2,730
212985759	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96MSN0261410A*	19,500	\$2,730
212985365	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN1002120A*	19,100	\$2,674
212985353	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*92MSN1002120A*	18,700	\$2,618
212985341	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92MSN1002120A*	19,100	\$2,674
212985055	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0802120A*	19,000	\$2,660
212985045	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*92MSN0802120A*	18,900	\$2,646
212985035	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92MSN0802120A*	19,000	\$2,660
212984691	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0801716A*	19,100	\$2,674
212984679	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0801716A*	19,100	\$2,674
212984667	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0801716A*	19,100	\$2,674
212984655	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0801716A*	19,500	\$2,730
212984643	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*92MSN0801716A*	18,400	\$2,576

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984631	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*92MSN0801716A*	18,900	\$2,646
212984619	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92MSN0801716A*	19,000	\$2,660
212984607	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*92MSN0801716A*	19,000	\$2,660
212984595	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*92MSN0801716A*	19,100	\$2,674
212984583	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*92MSN0801716A*	18,500	\$2,590
212984571	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*92MSN0801716A*	19,300	\$2,702
212984151	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0601714A*	19,100	\$2,674
212984139	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601714A*	19,100	\$2,674
212984127	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601714A*	19,100	\$2,674
212984115	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601714A*	19,400	\$2,716
212984103	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*92MSN0601714A*	18,700	\$2,618
212984091	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601714A*	18,900	\$2,646
212984079	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92MSN0601714A*	19,100	\$2,674
212984067	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601714A*	19,100	\$2,674
212984055	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601714A*	19,100	\$2,674
212984043	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601714A*	18,700	\$2,618
212984031	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601714A*	19,400	\$2,716
212983622	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601412A*	19,200	\$2,688
212983612	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601412A*	19,200	\$2,688
212983602	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*92MSN0601412A*	19,200	\$2,688
212983592	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601412A*	19,500	\$2,730
212983582	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*92MSN0601412A*	19,500	\$2,730
212983572	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601412A*	19,000	\$2,660
212983562	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601412A*	19,200	\$2,688
212983552	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601412A*	19,200	\$2,688
212983542	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*92MSN0601412A*	19,200	\$2,688
212983532	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601412A*	18,800	\$2,632
212983522	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601412A*	19,500	\$2,730
212983512	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*92MSN0601412A*	19,500	\$2,730
212983245	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0401712A*	19,200	\$2,688
212983234	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0401712A*	19,200	\$2,688
212983223	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0401712A*	19,200	\$2,688
212983212	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0401712A*	19,600	\$2,744
212983201	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*92MSN0401712A*	18,800	\$2,632
212983190	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*92MSN0401712A*	19,000	\$2,660
212983179	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92MSN0401712A*	19,200	\$2,688
212983168	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*92MSN0401712A*	19,200	\$2,688
212983157	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*92MSN0401712A*	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983146	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*92MSN0401712A*	18,800	\$2,632
212983135	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*92MSN0401712A*	19,500	\$2,730
212981814	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU1002120A*	19,100	\$2,674
212981802	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	19,200	\$2,688
212981790	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU1002120A*	19,200	\$2,688
212981778	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU1002120A*	19,500	\$2,730
212981754	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80MSU1002120A*	18,800	\$2,632
212981742	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MSU1002120A*	19,100	\$2,674
212981730	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80MSU1002120A*	19,000	\$2,660
212981718	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80MSU1002120A*	19,100	\$2,674
212981706	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80MSU1002120A*	18,700	\$2,618
212981694	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80MSU1002120A*	19,500	\$2,730
212981012	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)1102120A*	19,100	\$2,674
212981000	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	18,800	\$2,632
212980988	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	19,000	\$2,660
212980602	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902120A*	19,100	\$2,674
212980591	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	18,600	\$2,604
212980580	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	19,100	\$2,674
212980283	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902116A*	19,100	\$2,674
212980272	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	18,600	\$2,604
212980261	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	19,000	\$2,660
212979935	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0901714A*	19,100	\$2,674
212979923	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979911	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979899	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	19,500	\$2,730
212979887	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979875	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979863	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979851	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979839	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979827	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	18,600	\$2,604
212979815	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	19,400	\$2,716
212979517	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0702116A*	19,200	\$2,688
212979507	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	18,600	\$2,604
212979497	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	19,100	\$2,674
212979245	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	19,100	\$2,674
212979233	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979221	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701716A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979209	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701716A*	19,400	\$2,716
212979197	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979185	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979173	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979161	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979149	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979137	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212978648	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978637	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	18,600	\$2,604
212978626	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	19,400	\$2,716
212978216	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978204	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978192	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	19,100	\$2,674
212978180	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	19,400	\$2,716
212978168	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	19,400	\$2,716
212978156	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	18,700	\$2,618
212978144	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	19,000	\$2,660
212978132	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978120	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978108	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	18,600	\$2,604
212978096	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	19,400	\$2,716
212978084	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	19,300	\$2,702
212977700	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977688	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977676	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	19,000	\$2,660
212977664	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	19,500	\$2,730
212977652	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	19,500	\$2,730
212977640	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977628	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977616	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977604	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977592	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977580	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977568	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977003	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122B*	19,200	\$2,688
212976983	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122B*	19,100	\$2,674
212976695	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120B*	19,100	\$2,674
212976682	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002120B*	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976669	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120B*	19,000	\$2,660
212976421	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120B*	19,200	\$2,688
212976407	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120B*	18,600	\$2,604
212976393	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120B*	19,100	\$2,674
212976129	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716B*	18,900	\$2,646
212976116	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716B*	18,900	\$2,646
212976103	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716B*	18,900	\$2,646
212976090	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716B*	19,500	\$2,730
212976064	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716B*	19,000	\$2,660
212976051	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716B*	19,000	\$2,660
212976038	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716B*	19,000	\$2,660
212976025	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716B*	19,100	\$2,674
212976012	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0801716B*	18,800	\$2,632
212975999	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716B*	19,500	\$2,730
212975755	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412B*	19,100	\$2,674
212975744	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412B*	19,100	\$2,674
212975733	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412B*	19,000	\$2,660
212975722	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412B*	19,500	\$2,730
212975711	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412B*	19,500	\$2,730
212975700	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412B*	18,800	\$2,632
212975689	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412B*	19,100	\$2,674
212975678	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412B*	19,100	\$2,674
212975667	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412B*	19,100	\$2,674
212975656	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412B*	18,600	\$2,604
212975645	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412B*	19,400	\$2,716
212975634	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412B*	19,400	\$2,716
212975370	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712B*	19,200	\$2,688
212975359	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712B*	19,200	\$2,688
212975348	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712B*	19,200	\$2,688
212975337	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712B*	19,600	\$2,744
212975326	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712B*	18,900	\$2,646
212975315	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401712B*	18,900	\$2,646
212975304	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712B*	19,100	\$2,674
212975293	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712B*	19,100	\$2,674
212975282	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712B*	19,200	\$2,688
212975271	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712B*	18,800	\$2,632
212975260	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712B*	19,500	\$2,730
212975061	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410B*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975048	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410B*	19,200	\$2,688
212975035	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410B*	19,100	\$2,674
212975022	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410B*	19,600	\$2,744
212975009	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410B*	19,600	\$2,744
212974996	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410B*	18,800	\$2,632
212974983	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410B*	19,200	\$2,688
212974970	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410B*	19,200	\$2,688
212974957	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410B*	19,200	\$2,688
212974944	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401410B*	18,700	\$2,618
212974931	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410B*	19,500	\$2,730
212974918	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410B*	19,500	\$2,730
212974327	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VSN1002120B*	18,900	\$2,646
212974317	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120B*	19,000	\$2,660
212974117	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120B*	19,200	\$2,688
212974107	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VSN0802120B*	18,600	\$2,604
212974097	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120B*	19,100	\$2,674
212973927	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716B*	18,900	\$2,646
212973917	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716B*	18,900	\$2,646
212973907	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716B*	18,900	\$2,646
212973897	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716B*	19,500	\$2,730
212973877	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716B*	19,000	\$2,660
212973867	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716B*	19,000	\$2,660
212973857	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716B*	19,000	\$2,660
212973847	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716B*	19,100	\$2,674
212973837	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0801716B*	18,800	\$2,632
212973827	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716B*	19,500	\$2,730
212973637	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412B*	19,100	\$2,674
212973627	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412B*	19,100	\$2,674
212973617	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412B*	19,000	\$2,660
212973607	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412B*	19,500	\$2,730
212973597	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412B*	19,500	\$2,730
212973587	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412B*	18,800	\$2,632
212973577	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412B*	19,100	\$2,674
212973567	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412B*	19,100	\$2,674
212973557	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412B*	19,100	\$2,674
212973547	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412B*	18,600	\$2,604
212973537	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412B*	19,400	\$2,716
212973527	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412B*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973287	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712B*	19,200	\$2,688
212973277	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712B*	19,200	\$2,688
212973267	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712B*	19,200	\$2,688
212973257	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712B*	19,600	\$2,744
212973247	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712B*	18,900	\$2,646
212973237	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401712B*	18,900	\$2,646
212973227	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712B*	19,100	\$2,674
212973217	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712B*	19,100	\$2,674
212973207	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712B*	19,200	\$2,688
212973197	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712B*	18,800	\$2,632
212973187	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712B*	19,500	\$2,730
212973007	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410B*	19,200	\$2,688
212972997	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410B*	19,200	\$2,688
212972987	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410B*	19,200	\$2,688
212972977	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410B*	19,500	\$2,730
212972967	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410B*	19,500	\$2,730
212972957	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410B*	19,000	\$2,660
212972947	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410B*	19,200	\$2,688
212972937	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410B*	19,200	\$2,688
212972927	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410B*	19,200	\$2,688
212972917	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401410B*	18,800	\$2,632
212972907	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410B*	19,500	\$2,730
212972897	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410B*	19,500	\$2,730
212972428	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122B*	19,200	\$2,688
212972416	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122B*	18,800	\$2,632
212972404	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122B*	19,100	\$2,674
212972148	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120B*	19,100	\$2,674
212972137	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80VTL0902120B*	18,900	\$2,646
212972126	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120B*	19,100	\$2,674
212971737	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716B*	19,100	\$2,674
212971726	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716B*	19,100	\$2,674
212971715	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716B*	19,100	\$2,674
212971704	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716B*	19,500	\$2,730
212971693	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80VTL0701716B*	18,700	\$2,618
212971682	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716B*	18,700	\$2,618
212971671	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716B*	19,100	\$2,674
212971660	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716B*	19,100	\$2,674
212971649	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716B*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971638	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80VTL0701716B*	18,600	\$2,604
212971627	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716B*	19,400	\$2,716
212971248	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412B*	19,100	\$2,674
212971236	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412B*	19,100	\$2,674
212971224	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412B*	19,000	\$2,660
212971212	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412B*	19,500	\$2,730
212971200	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412B*	19,500	\$2,730
212971188	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412B*	18,700	\$2,618
212971176	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412B*	19,000	\$2,660
212971164	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412B*	19,100	\$2,674
212969841	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412B*	19,100	\$2,674
212969831	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412B*	19,100	\$2,674
212969821	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412B*	19,000	\$2,660
212969811	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412B*	19,500	\$2,730
212969801	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412B*	19,500	\$2,730
212969791	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451412B*	18,700	\$2,618
212969781	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412B*	19,000	\$2,660
212969771	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412B*	19,100	\$2,674
212969761	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412B*	19,100	\$2,674
212969751	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80VSL0451412B*	18,500	\$2,590
212969741	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412B*	19,300	\$2,702
211245985	DAY & NIGHT	DLCURAH24ABK	FVM4X36***L		19,000	\$2,660
211245975	DAY & NIGHT	DLCURAH24ABK	FVM4X24***L		19,000	\$2,660
211245964	DAY & NIGHT	DLCURAH24ABK	FM(C,U)4Z36**AL*		19,300	\$2,702
211245953	DAY & NIGHT	DLCURAH24ABK	FM(C,U)4Z30**AL*		19,300	\$2,702
211245942	DAY & NIGHT	DLCURAH24ABK	FM(C,U)4Z24**AL*		19,500	\$2,730
211245931	DAY & NIGHT	DLCURAH24ABK	FM(C,U)4X36**AL*		19,900	\$2,786
211245920	DAY & NIGHT	DLCURAH24ABK	FM(C,U)4X30**AL*		19,900	\$2,786
211245909	DAY & NIGHT	DLCURAH24ABK	FMA4X36**AL*		19,600	\$2,744
211245898	DAY & NIGHT	DLCURAH24ABK	FMA4X30**AL*		19,600	\$2,744
211245887	DAY & NIGHT	DLCURAH24ABK	FMA4X24**AL*		19,600	\$2,744
211245865	DAY & NIGHT	DLCURAH24ABK	FMA4P24**AL*		19,900	\$2,786
211245854	DAY & NIGHT	DLCURAH24ABK	FXM4X36**AL		18,500	\$2,590
211245843	DAY & NIGHT	DLCURAH24ABK	FXM4X30**AL		19,100	\$2,674
211245832	DAY & NIGHT	DLCURAH24ABK	FXM4X24**AL		19,100	\$2,674
211245821	DAY & NIGHT	DLCURAH24ABK	FEM4X30**BL		19,100	\$2,674
211245809	DAY & NIGHT	DLCURAH24ABK	FEM4X24**CL		19,000	\$2,660
211245797	DAY & NIGHT	DLCURAH24ABK	FEM4P30**AL		19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245786	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	OLV112A16A	19,300	\$2,702
211245777	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	OMV112K14A	19,200	\$2,688
211245768	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	OLV098A12*	18,900	\$2,646
211245759	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	OMV098J12*	19,000	\$2,660
211245749	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0601716A	19,300	\$2,702
211245738	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0802120A	19,100	\$2,674
211245727	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0401712A*	19,100	\$2,674
211245716	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0801716A*	19,500	\$2,730
211245705	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0601714A*	19,400	\$2,716
211245694	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN1002120A*	19,300	\$2,702
211245683	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0802120A*	19,300	\$2,702
211245672	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0801716A*	19,100	\$2,674
211245661	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0601714A*	19,100	\$2,674
211245649	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)1102120A*	19,400	\$2,716
211245637	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0902120A*	19,300	\$2,702
211245625	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0901714A*	19,200	\$2,688
211245613	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0702116A*	19,100	\$2,674
211245601	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701712A*	19,200	\$2,688
211245589	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0451712A*	19,100	\$2,674
211245579	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122A*	19,000	\$2,660
211245569	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120A*	19,000	\$2,660
211245559	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120A*	18,900	\$2,646
211245549	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0601714A*	19,100	\$2,674
211245538	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0401712A*	19,400	\$2,716
211245528	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716A*	19,100	\$2,674
211245518	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716A*	19,100	\$2,674
211245507	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0802120A*	19,300	\$2,702
211245497	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712A*	19,000	\$2,660
211245487	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120A*	19,000	\$2,660
211245474	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0401712A*	19,000	\$2,660
211245463	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0601716A*	19,100	\$2,674
211245453	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0902120A*	19,000	\$2,660
211245444	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0702120A*	19,300	\$2,702
211245435	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0701716A*	19,000	\$2,660
211245426	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0451716A*	19,200	\$2,688
211245381	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122A*	18,900	\$2,646
211245371	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701716A*	19,400	\$2,716
211245360	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0401712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245350	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716A*	19,100	\$2,674
211245341	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712A*	19,000	\$2,660
211245332	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN1002120A*	19,000	\$2,660
211245323	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120A*	19,000	\$2,660
211245314	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0601714A*	18,900	\$2,646
211245278	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV112K14A	19,200	\$2,688
211245269	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	OLV098A12*	18,900	\$2,646
211245260	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV098J12*	19,000	\$2,660
211245250	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0601716A	19,300	\$2,702
211245238	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211245227	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401712A*	19,100	\$2,674
211245216	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401410A*	19,400	\$2,716
211245205	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0801716A*	19,500	\$2,730
211245194	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601714A*	19,400	\$2,716
211245183	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0801716A*	19,100	\$2,674
211245172	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601714A*	19,100	\$2,674
211245161	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601412A*	18,900	\$2,646
211245149	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211245137	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211245125	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211245113	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211245103	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601714A*	19,100	\$2,674
211245092	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0261410A*	18,900	\$2,646
211245082	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412A*	19,000	\$2,660
211245072	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410A*	19,000	\$2,660
211245061	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601412A*	19,400	\$2,716
211245050	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401712A*	19,400	\$2,716
211245039	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401410A*	19,500	\$2,730
211245029	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716A*	19,100	\$2,674
211245019	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716A*	19,100	\$2,674
211245009	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712A*	19,000	\$2,660
211244995	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412A*	19,100	\$2,674
211244984	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0401712A*	19,000	\$2,660
211244973	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0601716A*	19,100	\$2,674
211244963	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0701716A*	19,000	\$2,660
211244954	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451716A*	19,200	\$2,688
211244926	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244915	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0401712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244905	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716A*	19,100	\$2,674
211244896	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412A*	19,000	\$2,660
211244887	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712A*	19,000	\$2,660
211244878	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410A*	19,000	\$2,660
211244869	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601714A*	18,900	\$2,646
211244851	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412A*	18,900	\$2,646
211244842	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	OMV112K14A	19,200	\$2,688
211244833	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	OLV098A12*	18,900	\$2,646
211244824	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	OMV098J12*	19,000	\$2,660
213372139	DAY & NIGHT	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372135	DAY & NIGHT	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
211244814	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0601716A	19,300	\$2,702
211244802	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211244791	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401712A*	19,100	\$2,674
211244780	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401410A*	19,400	\$2,716
211244769	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0801716A*	19,500	\$2,730
211244758	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601714A*	19,400	\$2,716
211244747	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0801716A*	19,100	\$2,674
211244736	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601714A*	19,100	\$2,674
211244725	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601412A*	18,900	\$2,646
211244713	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211244701	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211244689	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211244677	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211244667	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601714A*	19,100	\$2,674
211244656	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0261410A*	18,900	\$2,646
211244646	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412A*	19,000	\$2,660
211244636	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410A*	19,000	\$2,660
211244625	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601412A*	19,400	\$2,716
211244614	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401712A*	19,400	\$2,716
211244603	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401410A*	19,500	\$2,730
211244593	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716A*	19,100	\$2,674
211244583	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716A*	19,100	\$2,674
211244573	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712A*	19,000	\$2,660
211244559	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412A*	19,100	\$2,674
211244548	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0401712A*	19,000	\$2,660
211244537	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0601716A*	19,100	\$2,674
211244527	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0701716A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244518	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451716A*	19,200	\$2,688
211244490	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244479	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0401712A*	19,000	\$2,660
211244469	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716A*	19,100	\$2,674
211244460	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412A*	19,000	\$2,660
211244451	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712A*	19,000	\$2,660
211244442	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410A*	19,000	\$2,660
211244433	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601714A*	18,900	\$2,646
211244415	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412A*	18,900	\$2,646
211244404	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	19,100	\$2,674
211244393	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0401410A*	19,400	\$2,716
211244382	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0601412A*	18,900	\$2,646
211244370	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	19,300	\$2,702
211244359	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0261410A*	19,500	\$2,730
211244349	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412A*	19,000	\$2,660
211244339	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410A*	19,100	\$2,674
211244328	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0601412A*	19,400	\$2,716
211244317	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0401410A*	19,500	\$2,730
211244305	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412A*	19,100	\$2,674
211244295	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412A*	19,000	\$2,660
211244286	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410A*	19,100	\$2,674
211244277	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412A*	19,200	\$2,688
211244268	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	OMV112K14A	19,700	\$2,758
211244259	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	OLV098A12*	19,300	\$2,702
211244250	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	OMV098J12*	19,400	\$2,716
211244240	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0601716A	19,600	\$2,744
211244228	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	19,500	\$2,730
211244217	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401712A*	19,500	\$2,730
211244206	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401410A*	19,700	\$2,758
211244195	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0801716A*	19,800	\$2,772
211244184	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601714A*	19,700	\$2,758
211244173	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0801716A*	19,400	\$2,716
211244162	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601714A*	19,500	\$2,730
211244151	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601412A*	19,600	\$2,744
211244139	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0901714A*	19,500	\$2,730
211244127	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	19,500	\$2,730
211244115	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	19,400	\$2,716
211244103	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	19,600	\$2,744

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244093	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601714A*	19,400	\$2,716
211244082	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0261410A*	19,900	\$2,786
211244072	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412A*	19,300	\$2,702
211244062	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410A*	19,500	\$2,730
211244051	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601412A*	19,700	\$2,758
211244040	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401712A*	19,700	\$2,758
211244029	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401410A*	19,800	\$2,772
211244019	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716A*	19,400	\$2,716
211244009	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716A*	19,500	\$2,730
211243999	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712A*	19,700	\$2,758
211243985	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412A*	19,500	\$2,730
211243974	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0401712A*	19,300	\$2,702
211243963	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0601716A*	19,400	\$2,716
211243953	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0701716A*	19,400	\$2,716
211243944	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451716A*	19,500	\$2,730
211243916	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701716A*	19,700	\$2,758
211243905	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0401712A*	19,300	\$2,702
211243895	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716A*	19,500	\$2,730
211243886	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412A*	19,300	\$2,702
211243877	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712A*	19,700	\$2,758
211243868	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410A*	19,500	\$2,730
211243859	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601714A*	19,500	\$2,730
211243841	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412A*	19,500	\$2,730
211243830	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	19,500	\$2,730
211243819	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0401410A*	19,700	\$2,758
211243808	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0601412A*	19,600	\$2,744
211243796	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	19,600	\$2,744
211243785	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0261410A*	19,900	\$2,786
211243775	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412A*	19,300	\$2,702
211243765	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410A*	19,500	\$2,730
211243754	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0601412A*	19,700	\$2,758
211243743	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0401410A*	19,800	\$2,772
211243731	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412A*	19,500	\$2,730
211243721	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412A*	19,300	\$2,702
211243712	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410A*	19,500	\$2,730
211243703	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412A*	19,500	\$2,730
211243676	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	OLV098A12*	18,400	\$2,576
211243487	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122A*	18,500	\$2,590

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243467	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120A*	18,400	\$2,576
211243405	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712A*	18,500	\$2,590
211243289	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002122A*	18,400	\$2,576
211243249	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712A*	18,500	\$2,590
211243177	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	OLV098A12*	18,700	\$2,618
211243168	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	OMV098J12*	18,800	\$2,632
211243146	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	18,900	\$2,646
211243135	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*92ESN0401712A*	18,900	\$2,646
211243091	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*92ESN0801716A*	18,900	\$2,646
211243080	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*92ESN0601714A*	18,900	\$2,646
211243033	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0451712A*	18,900	\$2,646
211243011	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601714A*	18,900	\$2,646
211242990	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412A*	18,700	\$2,618
211242980	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410A*	18,900	\$2,646
211242937	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716A*	18,800	\$2,632
211242927	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716A*	18,900	\$2,646
211242903	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412A*	18,900	\$2,646
211242892	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80ESU0401712A*	18,700	\$2,618
211242881	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*95ESU0601716A*	18,900	\$2,646
211242871	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80VSL0701716A*	18,800	\$2,632
211242862	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451716A*	19,000	\$2,660
211242823	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*95ESU0401712A*	18,700	\$2,618
211242813	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716A*	18,900	\$2,646
211242804	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412A*	18,700	\$2,618
211242786	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410A*	18,900	\$2,646
211242777	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601714A*	19,000	\$2,660
211242750	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	OLV112A16A	19,200	\$2,688
211242741	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	OMV112K14A	19,100	\$2,674
211242732	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	OLV098A12*	18,900	\$2,646
211242723	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	OMV098J12*	18,900	\$2,646
211242713	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ESU0601716A	19,300	\$2,702
211242702	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ESU0802120A	19,100	\$2,674
211242691	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92ESN0401712A*	19,100	\$2,674
211242680	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95ESN0801716A*	19,400	\$2,716
211242669	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95ESN0601714A*	19,300	\$2,702
211242658	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92ESN1002120A*	19,300	\$2,702
211242647	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92ESN0802120A*	19,300	\$2,702
211242636	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92ESN0801716A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242625	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*92ESN0601714A*	19,100	\$2,674
211242613	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	19,400	\$2,716
211242601	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	19,200	\$2,688
211242589	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242577	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	19,100	\$2,674
211242565	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	18,800	\$2,632
211242553	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242543	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122A*	18,900	\$2,646
211242533	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120A*	19,000	\$2,660
211242523	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120A*	18,900	\$2,646
211242513	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0601714A*	19,100	\$2,674
211242502	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95ESN0401712A*	19,300	\$2,702
211242492	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716A*	19,000	\$2,660
211242482	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716A*	19,100	\$2,674
211242471	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95ESN0802120A*	19,300	\$2,702
211242461	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712A*	19,000	\$2,660
211242451	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120A*	19,000	\$2,660
211242438	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ESU0401712A*	18,900	\$2,646
211242427	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95ESU0601716A*	19,100	\$2,674
211242417	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VSL0902120A*	19,000	\$2,660
211242408	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VSL0702120A*	19,300	\$2,702
211242399	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VSL0701716A*	19,000	\$2,660
211242390	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80VSL0451716A*	18,800	\$2,632
211242345	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122A*	18,900	\$2,646
211242335	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	19,400	\$2,716
211242324	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*95ESU0401712A*	18,900	\$2,646
211242314	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716A*	19,100	\$2,674
211242305	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712A*	19,000	\$2,660
211242296	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120A*	18,900	\$2,646
211242287	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120A*	19,000	\$2,660
211242278	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0601714A*	18,900	\$2,646
211242242	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	OMV112K14A	19,200	\$2,688
211242233	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	OLV098A12*	18,900	\$2,646
211242224	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	OMV098J12*	18,900	\$2,646
211242214	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80ESU0601716A	19,300	\$2,702
211242202	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	19,100	\$2,674
211242191	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401712A*	19,100	\$2,674
211242180	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401410A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242169	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0801716A*	19,400	\$2,716
211242158	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601714A*	19,300	\$2,702
211242147	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0801716A*	19,100	\$2,674
211242136	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601714A*	19,100	\$2,674
211242125	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601412A*	18,800	\$2,632
211242113	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242101	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211242089	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242077	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	19,300	\$2,702
211242067	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601714A*	19,100	\$2,674
211242056	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0261410A*	18,900	\$2,646
211242046	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412A*	18,900	\$2,646
211242036	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410A*	18,900	\$2,646
211242025	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601412A*	19,300	\$2,702
211242014	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401712A*	19,300	\$2,702
211242003	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401410A*	19,400	\$2,716
211241993	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716A*	19,000	\$2,660
211241983	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716A*	19,100	\$2,674
211241973	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712A*	18,900	\$2,646
211241959	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412A*	19,100	\$2,674
211241948	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80ESU0401712A*	18,900	\$2,646
211241937	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95ESU0601716A*	19,100	\$2,674
211241927	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80VSL0701716A*	19,000	\$2,660
211241918	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451716A*	19,100	\$2,674
211241890	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241879	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*95ESU0401712A*	18,900	\$2,646
211241869	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716A*	19,100	\$2,674
211241860	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412A*	18,900	\$2,646
211241851	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712A*	18,900	\$2,646
211241842	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410A*	18,900	\$2,646
211241833	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601714A*	18,900	\$2,646
211241815	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412A*	18,800	\$2,632
211241806	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	OMV112K14A	19,200	\$2,688
211241797	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	OLV098A12*	18,900	\$2,646
211241788	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	OMV098J12*	19,000	\$2,660
211241778	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80ESU0601716A	19,300	\$2,702
211241766	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241755	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401712A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241744	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401410A*	19,400	\$2,716
211241733	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0801716A*	19,500	\$2,730
211241722	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601714A*	19,400	\$2,716
211241711	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0801716A*	19,100	\$2,674
211241700	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601714A*	19,200	\$2,688
211241689	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601412A*	18,900	\$2,646
211241677	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211241665	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211241653	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211241641	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	19,400	\$2,716
211241631	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601714A*	19,100	\$2,674
211241620	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0261410A*	18,900	\$2,646
211241610	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412A*	19,000	\$2,660
211241600	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410A*	19,000	\$2,660
211241589	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601412A*	19,400	\$2,716
211241578	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401712A*	19,400	\$2,716
211241567	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401410A*	19,500	\$2,730
211241557	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716A*	19,100	\$2,674
211241547	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716A*	19,200	\$2,688
211241537	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712A*	19,000	\$2,660
211241523	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412A*	19,200	\$2,688
211241512	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80ESU0401712A*	19,000	\$2,660
211241501	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95ESU0601716A*	19,100	\$2,674
211241491	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80VSL0701716A*	19,100	\$2,674
211241482	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451716A*	19,200	\$2,688
211241454	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241443	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*95ESU0401712A*	19,000	\$2,660
211241433	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716A*	19,200	\$2,688
211241424	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412A*	19,000	\$2,660
211241415	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712A*	19,000	\$2,660
211241406	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410A*	19,000	\$2,660
211241397	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601714A*	18,900	\$2,646
211241379	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412A*	18,900	\$2,646
211241368	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241357	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*92ESN0401410A*	19,400	\$2,716
211241346	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*92ESN0601412A*	18,900	\$2,646
211241334	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	19,300	\$2,702
211241323	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*95ESN0261410A*	19,600	\$2,744

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241313	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412A*	19,000	\$2,660
211241303	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410A*	19,100	\$2,674
211241292	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*95ESN0601412A*	19,400	\$2,716
211241281	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*95ESN0401410A*	19,500	\$2,730
211241269	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*80VTL0451412A*	19,100	\$2,674
211241259	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412A*	19,000	\$2,660
211241250	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410A*	19,100	\$2,674
211241241	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412A*	19,200	\$2,688
211241223	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	OLV098A12*	18,600	\$2,604
211241214	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	OMV098J12*	18,600	\$2,604
211241115	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*92ESN0601412A*	18,500	\$2,590
211241036	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412A*	18,600	\$2,604
211240963	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712A*	18,600	\$2,604
211240938	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80ESU0401712A*	18,600	\$2,604
211240917	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*80VSL0701716A*	18,700	\$2,618
211240869	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*95ESU0401712A*	18,600	\$2,604
211240850	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412A*	18,600	\$2,604
211240841	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712A*	18,600	\$2,604
211240796	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	OMV112K14A	19,500	\$2,730
211240787	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	OLV098A12*	19,200	\$2,688
211240778	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	OMV098J12*	19,300	\$2,702
211240768	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80ESU0601716A	19,600	\$2,744
211240756	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240745	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401712A*	19,400	\$2,716
211240734	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401410A*	19,700	\$2,758
211240723	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0801716A*	19,700	\$2,758
211240712	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601714A*	19,600	\$2,744
211240701	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0801716A*	19,400	\$2,716
211240690	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601714A*	19,400	\$2,716
211240679	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601412A*	19,200	\$2,688
211240667	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0901714A*	19,500	\$2,730
211240655	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	19,500	\$2,730
211240643	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	19,400	\$2,716
211240631	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240621	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601714A*	19,400	\$2,716
211240610	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0261410A*	19,800	\$2,772
211240600	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412A*	19,300	\$2,702
211240590	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240579	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601412A*	19,600	\$2,744
211240568	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401712A*	19,700	\$2,758
211240557	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401410A*	19,700	\$2,758
211240547	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716A*	19,300	\$2,702
211240537	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716A*	19,400	\$2,716
211240527	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712A*	19,300	\$2,702
211240513	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80VTL0451412A*	19,400	\$2,716
211240502	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80ESU0401712A*	19,300	\$2,702
211240491	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95ESU0601716A*	19,400	\$2,716
211240481	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80VSL0701716A*	19,300	\$2,702
211240472	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451716A*	19,400	\$2,716
211240444	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701716A*	19,700	\$2,758
211240433	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*95ESU0401712A*	19,300	\$2,702
211240423	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716A*	19,400	\$2,716
211240414	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412A*	19,300	\$2,702
211240405	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712A*	19,300	\$2,702
211240396	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410A*	19,400	\$2,716
211240387	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601714A*	19,500	\$2,730
211240369	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412A*	19,500	\$2,730
211240358	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240347	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*92ESN0401410A*	19,700	\$2,758
211240336	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*92ESN0601412A*	19,600	\$2,744
211240324	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240313	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*95ESN0261410A*	19,800	\$2,772
211240303	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412A*	19,300	\$2,702
211240293	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410A*	19,400	\$2,716
211240282	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*95ESN0601412A*	19,600	\$2,744
211240271	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*95ESN0401410A*	19,700	\$2,758
211240259	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*80VTL0451412A*	19,400	\$2,716
211240249	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412A*	19,300	\$2,702
211240240	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410A*	19,400	\$2,716
211240231	DAY & NIGHT	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412A*	19,500	\$2,730
211239226	DAY & NIGHT	DLCURAH24ABK	FJMA4*24L*B*		19,200	\$2,688
213353742	DAY & NIGHT	DLCURAH18ABK	F5MA4*24L*B*		12,500	\$1,750
213353732	DAY & NIGHT	DLCURAH18ABK	F5MA4*18L*A*		12,800	\$1,792
213249252	DAY & NIGHT	DLCURAH18ABK	FEVA0024**+NAVA43601CK		12,300	\$1,722
213076389	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601716B*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989327	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0601716A*	12,200	\$1,708
212989315	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0601716A*	12,300	\$1,722
212989303	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*95MSU0601716A*	12,200	\$1,708
212989291	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*95MSU0601716A*	12,000	\$1,680
212989279	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*95MSU0601716A*	12,300	\$1,722
212989267	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*95MSU0601716A*	12,100	\$1,694
212988835	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0401712A*	12,200	\$1,708
212988823	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0401712A*	12,500	\$1,750
212988811	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*95MSU0401712A*	12,200	\$1,708
212988799	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*95MSU0401712A*	12,000	\$1,680
212988787	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*95MSU0401712A*	12,300	\$1,722
212988775	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*95MSU0401712A*	12,100	\$1,694
212987561	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0801716A*	12,200	\$1,708
212987549	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0801716A*	12,500	\$1,750
212987537	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96MSN0801716A*	12,100	\$1,694
212987525	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96MSN0801716A*	12,200	\$1,708
212987513	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96MSN0801716A*	12,500	\$1,750
212987501	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96MSN0801716A*	12,300	\$1,722
212987083	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0601412A*	12,200	\$1,708
212987073	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0601412A*	12,200	\$1,708
212987063	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0601412A*	12,300	\$1,722
212987053	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0601412A*	12,300	\$1,722
212987043	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0601412A*	12,500	\$1,750
212987033	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96MSN0601412A*	12,200	\$1,708
212987023	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96MSN0601412A*	12,200	\$1,708
212987013	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96MSN0601412A*	12,000	\$1,680
212987003	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96MSN0601412A*	12,300	\$1,722
212986993	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96MSN0601412A*	12,300	\$1,722
212986983	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96MSN0601412A*	12,100	\$1,694
212986721	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401712A*	12,300	\$1,722
212986709	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401712A*	12,500	\$1,750
212986697	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401712A*	12,300	\$1,722
212986685	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96MSN0401712A*	12,100	\$1,694
212986673	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401712A*	12,300	\$1,722
212986661	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401712A*	12,100	\$1,694
212986385	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401410A*	12,300	\$1,722
212986373	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0401410A*	12,300	\$1,722
212986361	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401410A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986349	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0401410A*	12,400	\$1,736
212986337	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0401410A*	12,400	\$1,736
212986325	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401410A*	12,300	\$1,722
212986313	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96MSN0401410A*	12,300	\$1,722
212986301	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401410A*	12,400	\$1,736
212986289	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96MSN0401410A*	12,400	\$1,736
212986277	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401410A*	12,200	\$1,708
212985979	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0261410A*	12,300	\$1,722
212985969	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0261410A*	12,200	\$1,708
212985959	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0261410A*	12,300	\$1,722
212985949	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0261410A*	12,300	\$1,722
212985939	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0261410A*	12,500	\$1,750
212985929	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96MSN0261410A*	12,200	\$1,708
212985919	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96MSN0261410A*	12,200	\$1,708
212985909	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96MSN0261410A*	12,100	\$1,694
212985899	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96MSN0261410A*	12,300	\$1,722
212985889	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96MSN0261410A*	12,300	\$1,722
212985879	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96MSN0261410A*	12,100	\$1,694
212984763	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0801716A*	12,100	\$1,694
212984751	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0801716A*	12,500	\$1,750
212984739	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*92MSN0801716A*	12,400	\$1,736
212984727	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*92MSN0801716A*	12,200	\$1,708
212984715	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*92MSN0801716A*	12,500	\$1,750
212984703	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*92MSN0801716A*	12,300	\$1,722
212984223	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601714A*	12,300	\$1,722
212984211	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601714A*	12,400	\$1,736
212984199	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601714A*	12,300	\$1,722
212984187	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601714A*	12,200	\$1,708
212984175	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601714A*	12,400	\$1,736
212984163	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601714A*	12,200	\$1,708
212983733	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601412A*	12,200	\$1,708
212983723	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*92MSN0601412A*	12,200	\$1,708
212983712	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601412A*	12,400	\$1,736
212983702	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*92MSN0601412A*	12,400	\$1,736
212983692	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*92MSN0601412A*	12,400	\$1,736
212983682	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601412A*	12,200	\$1,708
212983672	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*92MSN0601412A*	12,300	\$1,722
212983662	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601412A*	12,000	\$1,680

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983652	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601412A*	12,400	\$1,736
212983642	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*92MSN0601412A*	12,400	\$1,736
212983632	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601412A*	12,100	\$1,694
212983311	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0401712A*	12,300	\$1,722
212983300	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0401712A*	12,400	\$1,736
212983289	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*92MSN0401712A*	12,200	\$1,708
212983278	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*92MSN0401712A*	12,100	\$1,694
212983267	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*92MSN0401712A*	12,300	\$1,722
212983256	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*92MSN0401712A*	12,200	\$1,708
212981886	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU1002120A*	12,300	\$1,722
212981874	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU1002120A*	12,600	\$1,764
212981862	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80MSU1002120A*	12,300	\$1,722
212981850	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80MSU1002120A*	12,100	\$1,694
212981838	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80MSU1002120A*	12,300	\$1,722
212981826	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80MSU1002120A*	12,200	\$1,708
212980007	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	12,300	\$1,722
212979995	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	12,400	\$1,736
212979983	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	12,300	\$1,722
212979971	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212979959	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	12,400	\$1,736
212979947	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212978802	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978791	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978780	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978769	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978758	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978747	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978350	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	12,200	\$1,708
212978338	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	12,200	\$1,708
212978326	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	12,400	\$1,736
212978314	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978302	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978289	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	12,100	\$1,694
212978276	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	12,300	\$1,722
212978264	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212978252	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978240	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978228	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701412A*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212977832	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	12,300	\$1,722
212977820	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	12,300	\$1,722
212977808	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	12,400	\$1,736
212977796	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977784	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977772	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977760	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977748	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	12,100	\$1,694
212977736	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	12,400	\$1,736
212977724	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977712	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0451412A*	12,200	\$1,708
212975843	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716B*	12,200	\$1,708
212975830	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716B*	12,500	\$1,750
212975817	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716B*	12,200	\$1,708
212975804	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716B*	12,000	\$1,680
212975791	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716B*	12,300	\$1,722
212975778	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716B*	12,100	\$1,694
212975491	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412B*	12,200	\$1,708
212975480	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412B*	12,200	\$1,708
212975469	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412B*	12,400	\$1,736
212975458	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412B*	12,400	\$1,736
212975447	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412B*	12,400	\$1,736
212975436	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412B*	12,200	\$1,708
212975425	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412B*	12,200	\$1,708
212975414	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412B*	12,000	\$1,680
212975403	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412B*	12,300	\$1,722
212975392	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412B*	12,200	\$1,708
212975381	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412B*	12,100	\$1,694
212975128	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712B*	12,200	\$1,708
212975117	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712B*	12,500	\$1,750
212975106	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712B*	12,200	\$1,708
212975095	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712B*	12,100	\$1,694
212975084	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712B*	12,300	\$1,722
212975073	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712B*	12,100	\$1,694
212974749	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410B*	12,200	\$1,708
212974736	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410B*	12,200	\$1,708
212974723	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410B*	12,400	\$1,736
212974710	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410B*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974697	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410B*	12,400	\$1,736
212974684	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410B*	12,200	\$1,708
212974671	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410B*	12,200	\$1,708
212974658	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410B*	12,100	\$1,694
212974645	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410B*	12,300	\$1,722
212974632	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410B*	12,400	\$1,736
212974619	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410B*	12,100	\$1,694
212973707	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716B*	12,200	\$1,708
212973697	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716B*	12,500	\$1,750
212973687	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716B*	12,200	\$1,708
212973677	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716B*	12,000	\$1,680
212973667	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716B*	12,300	\$1,722
212973657	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716B*	12,100	\$1,694
212973397	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412B*	12,200	\$1,708
212973387	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412B*	12,200	\$1,708
212973377	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412B*	12,400	\$1,736
212973367	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412B*	12,400	\$1,736
212973357	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412B*	12,400	\$1,736
212973347	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412B*	12,200	\$1,708
212973337	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412B*	12,200	\$1,708
212973327	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412B*	12,000	\$1,680
212973317	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412B*	12,300	\$1,722
212973307	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412B*	12,200	\$1,708
212973297	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412B*	12,100	\$1,694
212973067	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712B*	12,200	\$1,708
212973057	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712B*	12,500	\$1,750
212973047	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712B*	12,200	\$1,708
212973037	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712B*	12,100	\$1,694
212973027	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712B*	12,300	\$1,722
212973017	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712B*	12,100	\$1,694
212972767	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410B*	12,200	\$1,708
212972757	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410B*	12,200	\$1,708
212972747	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410B*	12,400	\$1,736
212972737	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410B*	12,400	\$1,736
212972727	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410B*	12,400	\$1,736
212972717	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410B*	12,200	\$1,708
212972707	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410B*	12,200	\$1,708
212972697	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410B*	12,100	\$1,694

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972687	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410B*	12,300	\$1,722
212972677	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410B*	12,300	\$1,722
212972667	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410B*	12,100	\$1,694
212971495	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716B*	12,300	\$1,722
212971484	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716B*	12,400	\$1,736
212971473	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716B*	12,300	\$1,722
212971462	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716B*	12,100	\$1,694
212971451	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716B*	12,400	\$1,736
212971440	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716B*	12,200	\$1,708
212969601	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412B*	12,200	\$1,708
212969591	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412B*	12,200	\$1,708
212969581	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412B*	12,500	\$1,750
212969571	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412B*	12,500	\$1,750
212969561	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412B*	12,500	\$1,750
212969551	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412B*	12,400	\$1,736
212969541	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412B*	12,200	\$1,708
212969531	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412B*	12,500	\$1,750
212969521	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412B*	12,500	\$1,750
212969511	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412B*	12,300	\$1,722
211265039	DAY & NIGHT	DLCURAH18ABK	FVM4X24***L		12,400	\$1,736
211265017	DAY & NIGHT	DLCURAH18ABK	FM(C,U)4Z30**AL*		12,400	\$1,736
211264996	DAY & NIGHT	DLCURAH18ABK	FM(C,U)4Z24**AL*		12,500	\$1,750
211264974	DAY & NIGHT	DLCURAH18ABK	FM(C,U)4Z18**AL*		12,500	\$1,750
211264952	DAY & NIGHT	DLCURAH18ABK	FMA4X24**AL*		12,400	\$1,736
211264930	DAY & NIGHT	DLCURAH18ABK	FMA4X18**AL*		12,400	\$1,736
211264909	DAY & NIGHT	DLCURAH18ABK	FXM4X30**AL		12,400	\$1,736
211264887	DAY & NIGHT	DLCURAH18ABK	FXM4X24**AL		12,400	\$1,736
211264766	DAY & NIGHT	DLCURAH18ABK	FEM4P18**AL		12,300	\$1,722
211264742	DAY & NIGHT	DLCURAH18ABK	FJMA4*18L*A*		12,700	\$1,778
211264716	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	OMV112K14A	12,600	\$1,764
211264698	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	OLV098A12*	12,600	\$1,764
211264681	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	OMV098J12*	12,600	\$1,764
211264660	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0601716A	12,700	\$1,778
211264636	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	12,300	\$1,722
211264613	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401712A*	12,500	\$1,750
211264591	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401410A*	12,500	\$1,750
211264570	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601714A*	12,300	\$1,722
211264547	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601412A*	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211264523	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	12,500	\$1,750
211264500	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	12,400	\$1,736
211264475	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	12,500	\$1,750
211264455	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601714A*	12,400	\$1,736
211264431	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0261410A*	12,600	\$1,764
211264410	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412A*	12,400	\$1,736
211264384	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410A*	12,300	\$1,722
211264319	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0601412A*	12,400	\$1,736
211264279	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401712A*	12,200	\$1,708
211264245	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401410A*	12,400	\$1,736
211264215	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716A*	12,200	\$1,708
211264179	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716A*	12,200	\$1,708
211264144	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712A*	12,400	\$1,736
211264113	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0451412A*	12,300	\$1,722
211264091	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0401712A*	12,700	\$1,778
211264071	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0701716A*	12,200	\$1,708
211264053	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451716A*	12,300	\$1,722
211264008	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESU0401712A*	12,400	\$1,736
211263988	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716A*	12,200	\$1,708
211263970	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412A*	12,400	\$1,736
211263953	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712A*	12,400	\$1,736
211263934	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410A*	12,300	\$1,722
211263916	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601714A*	12,400	\$1,736
211263879	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412A*	12,400	\$1,736
211263856	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	12,300	\$1,722
211263833	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0401410A*	12,500	\$1,750
211263812	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0601412A*	12,500	\$1,750
211263787	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	12,500	\$1,750
211263764	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0261410A*	12,500	\$1,750
211263744	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412A*	12,400	\$1,736
211263723	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410A*	12,200	\$1,708
211263698	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0601412A*	12,400	\$1,736
211263675	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0401410A*	12,400	\$1,736
211263650	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*80VTL0451412A*	12,300	\$1,722
211263629	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412A*	12,400	\$1,736
211263611	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410A*	12,200	\$1,708
211263592	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412A*	12,400	\$1,736
211263574	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	OMV112K14A	12,800	\$1,792

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263555	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	OLV098A12*	12,700	\$1,778
211263536	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	OMV098J12*	12,800	\$1,792
211263515	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0601716A	12,800	\$1,792
211263490	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	12,400	\$1,736
211263467	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401712A*	12,600	\$1,764
211263444	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401410A*	12,600	\$1,764
211263421	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0801716A*	12,900	\$1,806
211263399	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601714A*	12,400	\$1,736
211263376	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601412A*	12,600	\$1,764
211263351	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	12,600	\$1,764
211263326	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	12,900	\$1,806
211263301	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	12,600	\$1,764
211263280	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601714A*	12,500	\$1,750
211263255	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0261410A*	12,700	\$1,778
211263234	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412A*	12,500	\$1,750
211263213	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410A*	12,300	\$1,722
211263189	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0601412A*	12,500	\$1,750
211263166	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401712A*	12,300	\$1,722
211263143	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401410A*	12,500	\$1,750
211263128	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716A*	12,300	\$1,722
211263107	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716A*	12,300	\$1,722
211263086	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712A*	12,500	\$1,750
211263058	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0451412A*	12,400	\$1,736
211263037	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0401712A*	12,700	\$1,778
211263015	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0601716A*	12,900	\$1,806
211262995	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0701716A*	12,300	\$1,722
211262977	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451716A*	12,400	\$1,736
211262922	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0401712A*	12,400	\$1,736
211262903	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716A*	12,300	\$1,722
211262885	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412A*	12,500	\$1,750
211262868	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712A*	12,500	\$1,750
211262850	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410A*	12,300	\$1,722
211262832	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601714A*	12,400	\$1,736
211262796	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412A*	12,400	\$1,736
211262774	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262751	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0401410A*	12,600	\$1,764
211262729	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0601412A*	12,600	\$1,764
211262705	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262683	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0261410A*	12,700	\$1,778
211262663	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412A*	12,500	\$1,750
211262642	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410A*	12,300	\$1,722
211262619	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0601412A*	12,500	\$1,750
211262596	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0401410A*	12,500	\$1,750
211262572	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*80VTL0451412A*	12,400	\$1,736
211262553	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412A*	12,500	\$1,750
211262534	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410A*	12,300	\$1,722
211262516	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412A*	12,400	\$1,736
211262494	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262472	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0401410A*	12,600	\$1,764
211262450	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0601412A*	12,600	\$1,764
211262427	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262405	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0261410A*	12,700	\$1,778
211262384	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412A*	12,500	\$1,750
211262364	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410A*	12,300	\$1,722
211262340	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0601412A*	12,500	\$1,750
211262318	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0401410A*	12,500	\$1,750
211262294	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*80VTL0451412A*	12,400	\$1,736
211262275	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412A*	12,500	\$1,750
211262257	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410A*	12,300	\$1,722
211262239	DAY & NIGHT	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412A*	12,500	\$1,750
211262221	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	OMV112K14A	12,600	\$1,764
211262204	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	OLV098A12*	12,600	\$1,764
211262186	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	OMV098J12*	12,600	\$1,764
211262164	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	12,300	\$1,722
211262143	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401712A*	12,500	\$1,750
211262122	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401410A*	12,500	\$1,750
211262100	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601714A*	12,300	\$1,722
211262078	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601412A*	12,500	\$1,750
211262055	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	12,500	\$1,750
211262029	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	12,400	\$1,736
211262002	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261980	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601714A*	12,400	\$1,736
211261956	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*95ESN0261410A*	12,600	\$1,764
211261937	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412A*	12,500	\$1,750
211261921	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410A*	12,200	\$1,708
211261898	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*95ESN0601412A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261870	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401712A*	12,200	\$1,708
211261847	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401410A*	12,400	\$1,736
211261831	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716A*	12,200	\$1,708
211261816	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716A*	12,200	\$1,708
211261794	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712A*	12,400	\$1,736
211261767	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80VTL0451412A*	12,300	\$1,722
211261745	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80ESU0401712A*	12,700	\$1,778
211261725	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80VSL0701716A*	12,200	\$1,708
211261707	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451716A*	12,300	\$1,722
211261652	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*95ESU0401712A*	12,300	\$1,722
211261632	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716A*	12,200	\$1,708
211261614	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412A*	12,500	\$1,750
211261596	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712A*	12,400	\$1,736
211261578	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410A*	12,200	\$1,708
211261560	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601714A*	12,400	\$1,736
211261525	DAY & NIGHT	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451412A*	12,400	\$1,736
211261503	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211261481	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*92ESN0401410A*	12,500	\$1,750
211261459	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*92ESN0601412A*	12,500	\$1,750
211261435	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261414	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*95ESN0261410A*	12,500	\$1,750
211261394	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412A*	12,400	\$1,736
211261374	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410A*	12,200	\$1,708
211261352	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*95ESN0601412A*	12,400	\$1,736
211261330	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*95ESN0401410A*	12,400	\$1,736
211261306	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*80VTL0451412A*	12,300	\$1,722
211261285	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412A*	12,400	\$1,736
211261268	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410A*	12,200	\$1,708
211261249	DAY & NIGHT	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412A*	12,400	\$1,736
211261230	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	OMV112K14A	12,500	\$1,750
211261212	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	OLV098A12*	12,500	\$1,750
211261194	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	OMV098J12*	12,500	\$1,750
211261160	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80ESU0601716A	12,600	\$1,764
211261119	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701412A*	12,100	\$1,694
211261071	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401712A*	12,400	\$1,736
211261051	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401410A*	12,400	\$1,736
211261038	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601714A*	12,200	\$1,708
211261025	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601412A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261010	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211260996	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211260981	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211260969	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601714A*	12,200	\$1,708
211260955	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*95ESN0261410A*	12,400	\$1,736
211260943	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412A*	12,300	\$1,722
211260930	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410A*	12,100	\$1,694
211260916	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*95ESN0601412A*	12,300	\$1,722
211260902	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401712A*	12,100	\$1,694
211260889	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401410A*	12,300	\$1,722
211260877	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716A*	12,000	\$1,680
211260864	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716A*	12,100	\$1,694
211260851	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712A*	12,300	\$1,722
211260834	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80VTL0451412A*	12,200	\$1,708
211260821	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80ESU0401712A*	12,500	\$1,750
211260807	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80VSL0701716A*	12,100	\$1,694
211260796	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451716A*	12,200	\$1,708
211260762	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*95ESU0401712A*	12,200	\$1,708
211260750	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716A*	12,100	\$1,694
211260739	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412A*	12,300	\$1,722
211260729	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712A*	12,300	\$1,722
211260718	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410A*	12,100	\$1,694
211260707	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601714A*	12,200	\$1,708
211260686	DAY & NIGHT	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412A*	12,200	\$1,708
211260676	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	OMV112K14A	12,700	\$1,778
211260665	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	OLV098A12*	12,700	\$1,778
211260655	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	OMV098J12*	12,700	\$1,778
211260643	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80ESU0601716A	12,800	\$1,792
211260629	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	12,400	\$1,736
211260617	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401712A*	12,600	\$1,764
211260605	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401410A*	12,600	\$1,764
211260594	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601714A*	12,400	\$1,736
211260580	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601412A*	12,600	\$1,764
211260566	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	12,600	\$1,764
211260552	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	12,900	\$1,806
211260537	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260525	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601714A*	12,400	\$1,736
211260511	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*95ESN0261410A*	12,700	\$1,778

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260499	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412A*	12,500	\$1,750
211260487	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410A*	12,300	\$1,722
211260473	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*95ESN0601412A*	12,500	\$1,750
211260460	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401712A*	12,300	\$1,722
211260447	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401410A*	12,500	\$1,750
211260435	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716A*	12,200	\$1,708
211260423	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716A*	12,300	\$1,722
211260409	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712A*	12,500	\$1,750
211260393	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80VTL0451412A*	12,400	\$1,736
211260379	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80ESU0401712A*	12,700	\$1,778
211260367	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80VSL0701716A*	12,300	\$1,722
211260356	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451716A*	12,400	\$1,736
211260323	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*95ESU0401712A*	12,400	\$1,736
211260311	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716A*	12,300	\$1,722
211260300	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412A*	12,500	\$1,750
211260289	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712A*	12,500	\$1,750
211260278	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410A*	12,300	\$1,722
211260268	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601714A*	12,400	\$1,736
211260246	DAY & NIGHT	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412A*	12,400	\$1,736
211260233	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211260220	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*92ESN0401410A*	12,600	\$1,764
211260207	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*92ESN0601412A*	12,600	\$1,764
211260192	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260178	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*95ESN0261410A*	12,600	\$1,764
211260168	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412A*	12,500	\$1,750
211260158	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410A*	12,300	\$1,722
211260144	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*95ESN0601412A*	12,500	\$1,750
211260128	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*95ESN0401410A*	12,500	\$1,750
211260114	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*80VTL0451412A*	12,400	\$1,736
211260102	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412A*	12,500	\$1,750
211260088	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410A*	12,300	\$1,722
211260075	DAY & NIGHT	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412A*	12,400	\$1,736
211260061	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	OMV112K14A	12,600	\$1,764
211260047	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	OLV098A12*	12,500	\$1,750
211260034	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	OMV098J12*	12,600	\$1,764
211260019	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80ESU0601716A	12,700	\$1,778
211260002	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701412A*	12,200	\$1,708
211259987	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401712A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211259971	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401410A*	12,400	\$1,736
211259955	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601714A*	12,200	\$1,708
211259940	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601412A*	12,500	\$1,750
211259923	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211259909	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211259892	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211259878	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601714A*	12,300	\$1,722
211259862	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*95ESN0261410A*	12,500	\$1,750
211259849	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412A*	12,400	\$1,736
211259838	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410A*	12,100	\$1,694
211259825	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*95ESN0601412A*	12,300	\$1,722
211259813	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401712A*	12,100	\$1,694
211259801	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401410A*	12,400	\$1,736
211259790	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716A*	12,000	\$1,680
211259779	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716A*	12,100	\$1,694
211259767	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712A*	12,300	\$1,722
211259750	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80VTL0451412A*	12,200	\$1,708
211259735	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80ESU0401712A*	12,600	\$1,764
211259721	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80VSL0701716A*	12,100	\$1,694
211259709	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451716A*	12,200	\$1,708
211259671	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*95ESU0401712A*	12,200	\$1,708
211259657	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716A*	12,100	\$1,694
211259644	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412A*	12,400	\$1,736
211259632	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712A*	12,300	\$1,722
211259619	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410A*	12,100	\$1,694
211259607	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601714A*	12,300	\$1,722
211259583	DAY & NIGHT	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412A*	12,300	\$1,722
211257339	DAY & NIGHT	DLCURAH18ABK	FJMA4*24L*B*		12,800	\$1,792
201835630	DAY & NIGHT	DLCSRAH12AAK	DLFSCAH12XAK		8,200	\$1,148
201835634	DAY & NIGHT	DLCSRAH18AAK	DLFSCAH18XAK		12,000	\$1,680
201835632	DAY & NIGHT	DLCSRAH12AAK	DLFSDAH12XAK		8,100	\$1,134
201835636	DAY & NIGHT	DLCSRAH24AAK	DLFSFAH24XAK		17,200	\$2,408
201835641	DAY & NIGHT	DLCLRAH48AAK	DLFLFAH48XAK		35,000	\$4,900
201835613	DAY & NIGHT	DLCSRAH18AAK	DLFSHAH18XAK		11,900	\$1,666
201835614	DAY & NIGHT	DLCSRAH24AAK	DLFSHAH24XAK		15,000	\$2,100
201835635	DAY & NIGHT	DLCSRAH24AAK	DLFSDAH24XAK		17,400	\$2,436
202463647	DAY & NIGHT	DLCPRAH24AAK	DLFPHAH24XAK		15,450	\$2,163
201835637	DAY & NIGHT	DLCSRAH24AAK	DLFSCAH24XAK		16,200	\$2,268

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205921374	DAY & NIGHT	DLCSRAH24AAK	DLFSAAH24XAK		17,500	\$2,450
206350408	DAY & NIGHT	DLCSRBH12AAK	DLFSFAH12XAK		8,400	\$1,176
206350406	DAY & NIGHT	DLCSRBH12AAK	DLFSCAH12XAK		7,900	\$1,106
206396089	DAY & NIGHT	DLCSRAH12AAK	DLFSHBH12XAK		7,500	\$1,050
206350407	DAY & NIGHT	DLCSRBH12AAK	DLFSDAH12XAK		8,300	\$1,162
206350413	DAY & NIGHT	DLCSRBH24AAK	DLFSDAH24XAK		14,500	\$2,030
206188302	DAY & NIGHT	DLCSRBH24AAK	DLFSAAH24XAK		16,500	\$2,310
206350410	DAY & NIGHT	DLCSRBH18AAK	DLFSDAH18XAK		12,700	\$1,778
206350411	DAY & NIGHT	DLCSRBH18AAK	DLFSFAH18XAK		12,000	\$1,680
206350414	DAY & NIGHT	DLCSRBH24AAK	DLFSFAH24XAK		14,500	\$2,030
207643043	DAY & NIGHT	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340
207643037	DAY & NIGHT	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207643046	DAY & NIGHT	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643042	DAY & NIGHT	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207643045	DAY & NIGHT	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220
207643036	DAY & NIGHT	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643044	DAY & NIGHT	DLCMHBH36DAK	Heat pump without ducts		22,000	\$3,080
207643041	DAY & NIGHT	DLCMHBH48EAK	Heat pump without ducts		34,000	\$4,760
207643035	DAY & NIGHT	DLCMHBH30DAK	Heat pump without ducts		18,500	\$2,590
211222790	DAY & NIGHT	DLCURAH30ABK	FXM4X36**AL		23,200	\$3,248
211230820	DAY & NIGHT	DLCURAH36ABK	FEM4P42**AL		29,200	\$4,088
211230831	DAY & NIGHT	DLCURAH36ABK	FEM4P48**AL		29,400	\$4,116
211230843	DAY & NIGHT	DLCURAH36ABK	FEM4X42**BL		29,200	\$4,088
211230855	DAY & NIGHT	DLCURAH36ABK	FEM4X48**BL		29,400	\$4,116
211230877	DAY & NIGHT	DLCURAH36ABK	FMA4P36**AL*		29,800	\$4,172
211230909	DAY & NIGHT	DLCURAH36ABK	FXM4X36**AL		29,000	\$4,060
211719731	DAY & NIGHT	DLCURAH18ABK	FMA4P18**AL*		12,700	\$1,778
211264865	DAY & NIGHT	DLCURAH18ABK	FXM4X18**AL		12,300	\$1,722
211264843	DAY & NIGHT	DLCURAH18ABK	FEM4X24**CL		12,100	\$1,694
211264812	DAY & NIGHT	DLCURAH18ABK	FEM4X18**BL		12,300	\$1,722
211264788	DAY & NIGHT	DLCURAH18ABK	FEM4P24**AL		12,300	\$1,722
209852058	DAY & NIGHT	DLCURAH18ABK	DLFUAH18XAK		13,500	\$1,890
209852059	DAY & NIGHT	DLCURAH24ABK	DLFUAH24XAK		19,200	\$2,688
209852061	DAY & NIGHT	DLCURAH48ABK	DLFUAH48XAK		36,000	\$5,040
212978659	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978670	DAY & NIGHT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978681	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	18,700	\$2,618
212978692	DAY & NIGHT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	18,500	\$2,590
212978703	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	19,400	\$2,716
212978714	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	18,900	\$2,646
212978725	DAY & NIGHT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701712A*	18,900	\$2,646
212978736	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701712A*	19,000	\$2,660
212979125	DAY & NIGHT	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701716A*	19,400	\$2,716
212986157	DAY & NIGHT	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401410A*	18,800	\$2,632
212986169	DAY & NIGHT	DLCURAH24ABK	EA*4X30L14A*	*96MSN0401410A*	19,200	\$2,688
212986181	DAY & NIGHT	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401410A*	19,200	\$2,688
212986193	DAY & NIGHT	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401410A*	19,200	\$2,688
212986205	DAY & NIGHT	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401410A*	18,800	\$2,632
212986217	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0401410A*	19,500	\$2,730
212986229	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401410A*	19,500	\$2,730
212986241	DAY & NIGHT	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0401410A*	19,200	\$2,688
207801570	DAY & NIGHT	DLCSRBH18AAK	DLFSDAH24XAK		12,600	\$1,764
207826599	DAY & NIGHT	DLCSRBH18AAK	DLFSABH18XBK		12,000	\$1,680
206350412	DAY & NIGHT	DLCSRBH24AAK	DLFSCAH24XAK		14,500	\$2,030
207614964	DAY&NIGHT	DLCPRBH12AAK	DLFPHBH12XAK		10,400	\$1,456
207826646	DAY&NIGHT	DLCPRBH18AAK	DLFPHBH18XAK		20,200	\$2,828
210365431	Dettson	EVD-18-O	EVD-18-I		13,500	\$1,890
210365432	Dettson	EVD-24-O	EVD-24-I		19,200	\$2,688
210365433	DETTSON	EVD-30-O	EVD-30-I		21,000	\$2,940
210365434	DETTSON	EVD-36-O	EVD-36-I		30,400	\$4,256
213160480	DETTSON	EVD-24-O	MAC24H1718E		21,000	\$2,940
213160483	DETTSON	EVD-36-O	MAC36H2124E		33,000	\$4,620
213160481	DETTSON	EVD-36-O	MAC36H1724E		27,400	\$3,836
213386697	DETTSON	EVD-36-O-S	MAC36H2124E		27,000	\$3,780
213386696	DETTSON	EVD-36-O-S	MAC36H1724E		27,000	\$3,780
213488871	DETTSON	EVD-36-O-S	EVD-36-I		31,800	\$4,452
210365428	DETTSON	MHD-24	MHD-CC2.0-17.5-M		22,000	\$3,080
210365436	Dettson	EVD-60-O	EVD-60-I		42,000	\$5,880
210365435	Dettson	EVD-48-O	EVD-48-I		36,000	\$5,040
213160482	DETTSON	EVD-30-O	MAC36H2124E		22,600	\$3,164
213160485	DETTSON	EVD-60-O	MAC60H2428E		37,000	\$5,180
216623494	DIRECT AIR	DIRM4-60MAGICPRO20-OU	DIRM4-6024MAGICP20-CCOIL		36,000	\$5,040

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215213807	DIRECT AIR	DIRM4-36HXPRO28-4Z	Combination heat pumps with or without ducts		31,400	\$4,396
215213805	DIRECT AIR	DIRM4-36HXPRO28-4Z	Heat pump without ducts		30,000	\$4,200
207743725	DIRECT AIR	DIRM-12HXPRO28-1Z	DIRM-12HP-WM		10,000	\$1,400
207743726	DIRECT AIR	DIRM-18HXPRO28-1Z	DIRM-18HP-WM		15,000	\$2,100
207743727	DIRECT AIR	DIRM-24HXPRO28-1Z	DIRM-24HP-WM		21,200	\$2,968
207743740	DIRECT AIR	DIRM-12HXPRO28-1Z	DIRM-12HP-CA		9,900	\$1,386
207743765	DIRECT AIR	DIRM-12HXPRO28-1Z	DIRM-12HP-CO		9,600	\$1,344
207743757	DIRECT AIR	DIRM-18HXPRO28-1Z	DIRM-18HP-DUH		15,000	\$2,100
207743758	DIRECT AIR	DIRM-18HXPRO28-1Z	DIRM-18HP-DUV		15,000	\$2,100
207743789	DIRECT AIR	DIRM-28HXPRO28-3Z	Heat pump with ducts		27,000	\$3,780
207706563	DIRECT AIR	DIRM-18MAGICPRO20-OU	DIRM-18MAGICPRO20-AH		13,500	\$1,890
207706564	DIRECT AIR	DIRM-24MAGICPRO20-OU	DIRM-24MAGICPRO20-AH		19,200	\$2,688
207743790	DIRECT AIR	DIRM-28HXPRO28-3Z	Combination heat pumps with or without ducts		26,800	\$3,752
207743744	DIRECT AIR	DIRM-24HXPRO28-1Z	DIRM-24HP-CA		21,000	\$2,940
206377760	DIRECT AIR	MOX430-17HFN1-MT0W	MTIU-18HWFN1-M		15,000	\$2,100
207743794	DIRECT AIR	DIRM-48HXPRO28-5Z	Heat pump without ducts		36,000	\$5,040
207743788	DIRECT AIR	DIRM-28HXPRO28-3Z	Heat pump without ducts		26,600	\$3,724
207743785	DIRECT AIR	DIRM-18HXPRO28-2Z	Heat pump without ducts		15,000	\$2,100
207706565	DIRECT AIR	DIRM-30MAGICPRO20-OU	DIRM-30MAGICPRO20-AH		21,000	\$2,940
207706566	DIRECT AIR	DIRM-36MAGICPRO20-OU	DIRM-36MAGICPRO20-AH		30,400	\$4,256
207743733	DIRECT AIR	DIRM-24HXPRO28-1Z	DIRM-24HP-CF		19,000	\$2,660
207743760	DIRECT AIR	DIRM-24HXPRO28-1Z	DIRM-24HP-DU		21,000	\$2,940
207743787	DIRECT AIR	DIRM-18HXPRO28-2Z	Combination heat pumps with or without ducts		15,500	\$2,170
207743791	DIRECT AIR	DIRM-36HXPRO28-4Z	Heat pump without ducts		33,000	\$4,620
207743793	DIRECT AIR	DIRM-36HXPRO28-4Z	Combination heat pumps with or without ducts		34,000	\$4,760
207743795	DIRECT AIR	DIRM-48HXPRO28-5Z	Heat pump with ducts		36,000	\$5,040
207743753	DIRECT AIR	DIRM-12HXPRO28-1Z	DIRM-12HP-DUH		10,600	\$1,484
207743754	DIRECT AIR	DIRM-12HXPRO28-1Z	DIRM-12HP-DUV		10,600	\$1,484
207743786	DIRECT AIR	DIRM-18HXPRO28-2Z	Heat pump with ducts		16,000	\$2,240
207743796	DIRECT AIR	DIRM-48HXPRO28-5Z	Combination heat pumps with or without ducts		36,000	\$5,040

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212101619	DIRECT AIR	DIRM-24MAGICPRO20-OU	DIRM-24MAGICPRO20-COIL		21,000	\$2,940
216788535	DIRECT AIR	DIRM4-48LCHX-1Z	DIRM4-48HP-DU		45,000	\$6,300
216788534	DIRECT AIR	DIRM4-48LCHX-1Z	DIRM4-48HP-CA		44,000	\$6,160
216788531	DIRECT AIR	DIRM4-36LCHX-1Z	DIRM4-36HP-DU		31,600	\$4,424
216788530	DIRECT AIR	DIRM4-36LCHX-1Z	DIRM4-36HP-CA		30,600	\$4,284
216788527	DIRECT AIR	DIRM4-24HXPRO28-1Z	DIRM4-24HP-DU		21,600	\$3,024
216788526	DIRECT AIR	DIRM4-24HXPRO28-1Z	DIRM4-24HP-CA		20,400	\$2,856
216788522	DIRECT AIR	DIRM4-18HXPRO28-1Z	DIRM4-18HP-DUV		15,000	\$2,100
216788521	DIRECT AIR	DIRM4-18HXPRO28-1Z	DIRM4-18HP-DUH		15,000	\$2,100
216788520	DIRECT AIR	DIRM4-18HXPRO28-1Z	DIRM4-18HP-CA		14,900	\$2,086
216788516	DIRECT AIR	DIRM4-12HXPRO28-1Z	DIRM4-12HP-DUV		10,200	\$1,428
216788515	DIRECT AIR	DIRM4-12HXPRO28-1Z	DIRM4-12HP-DUH		10,200	\$1,428
216788514	DIRECT AIR	DIRM4-12HXPRO28-1Z	DIRM4-12HP-CA		10,000	\$1,400
216790061	DIRECT AIR	DIRM4-36CS19-OU	DIRM4-3621MAGICP20-CCOIL*		24,200	\$3,388
216790059	DIRECT AIR	DIRM4-36MAGICPRO20-OU	DIRM4-3621MAGICP20-CCOIL*		29,200	\$4,088
216790058	DIRECT AIR	DIRM4-30MAGICPRO20-OU	DIRM4-3621MAGICP20-CCOIL*		25,000	\$3,500
216790057	DIRECT AIR	DIRM4-30MAGICPRO20-OU	DIRM4-3617MAGICP20-CCOIL*		25,000	\$3,500
216790056	DIRECT AIR	DIRM4-36CS19-OU	DIRM4-3617MAGICP20-CCOIL		24,200	\$3,388
216790054	DIRECT AIR	DIRM4-36MAGICPRO20-OU	DIRM4-3617MAGICP20-CCOIL		29,200	\$4,088
216571374	DIRECT AIR	DIRM4-18HXPRO28-1Z	DIRM4-18HP-WM		16,600	\$2,324
216571361	DIRECT AIR	DIRM4-18MAGICPRO20-OU	DIRM4-18MAGICPRO20-AH		15,000	\$2,100
216571388	DIRECT AIR	DIRM4-12HXPRO28-1Z	DIRM4-12HP-CO		9,800	\$1,372
216571373	DIRECT AIR	DIRM4-12HXPRO28-1Z	DIRM4-12HP-WM		9,800	\$1,372
216571362	DIRECT AIR	DIRM4-24MAGICPRO20-OU	DIRM4-24MAGICPRO20-AH		20,000	\$2,800
216571364	DIRECT AIR	DIRM4-36MAGICPRO20-OU	DIRM4-36MAGICPRO20-AH		31,800	\$4,452
216623488	DIRECT AIR	DIRM4-24MAGICPRO20-OU	DIRM4-2417MAGICP20-CCOIL		19,700	\$2,758
216623487	DIRECT AIR	DIRM4-24MAGICPRO20-OU	DIRM4-2414MAGICP20-CCOIL		19,700	\$2,758

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216623486	DIRECT AIR	DIRM4-18MAGICPRO20-OU	DIRM4-2417MAGICP20-CCOIL		15,200	\$2,128
216623485	DIRECT AIR	DIRM4-18MAGICPRO20-OU	DIRM4-2414MAGICP20-CCOIL		15,200	\$2,128
216623491	DIRECT AIR	DIRM4-30MAGICPRO20-OU	DIRM4-4821MAGICP20-CCOIL		25,000	\$3,500
216623490	DIRECT AIR	DIRM4-30MAGICPRO20-OU	DIRM4-3621MAGICP20-CCOIL		25,000	\$3,500
216623489	DIRECT AIR	DIRM4-30MAGICPRO20-OU	DIRM4-3617MAGICP20-CCOIL		23,400	\$3,276
216623493	DIRECT AIR	DIRM4-36MAGICPRO20-OU	DIRM4-4821MAGICP20-CCOIL		29,200	\$4,088
216623492	DIRECT AIR	DIRM4-36MAGICPRO20-OU	DIRM4-3621MAGICP20-CCOIL		29,200	\$4,088
216623498	DIRECT AIR	DIRM4-24CS19-OU	DIRM4-2417MAGICP20-CCOIL		19,700	\$2,758
216623497	DIRECT AIR	DIRM4-24CS19-OU	DIRM4-2414MAGICP20-CCOIL		19,700	\$2,758
216623499	DIRECT AIR	DIRM4-60MAGICPRO20-OU	DIRM4-6021MAGICP20-CCOIL		38,000	\$5,320
216683821	DIRECT AIR	DIRM4-27DA25-3Z*	Heat pump with ducts		18,400	\$2,576
215213798	DIRECT AIR	DIRM4-48DA25-5Z	Combination heat pumps with or without ducts		37,400	\$5,236
215213796	DIRECT AIR	DIRM4-48DA25-5Z	Heat pump without ducts		38,000	\$5,320
216684040	DIRECT AIR	DIRM4-48MAGICPRO20-OU	DIRM4-6021MAGICP20-CCOIL		32,000	\$4,480
216684039	DIRECT AIR	DIRM4-36CS19-OU	DIRM4-4821MAGICP20-CCOIL		24,200	\$3,388
216684038	DIRECT AIR	DIRM4-36CS19-OU	DIRM4-3621MAGICP20-CCOIL		24,200	\$3,388
216571356	DIRECT AIR	DIRM4-24CS19-OU	DIRM4-24MAGICPRO20-AH		20,000	\$2,800
216571359	DIRECT AIR	DIRM4-48CS19-OU	DIRM4-48MAGICPRO20-AH		32,400	\$4,536
216571366	DIRECT AIR	DIRM4-60MAGICPRO20-OU	DIRM4-60MAGICPRO20-AH		45,000	\$6,300
216571365	DIRECT AIR	DIRM4-48MAGICPRO20-OU	DIRM4-48MAGICPRO20-AH		37,000	\$5,180

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216571363	DIRECT AIR	DIRM4-30MAGICPRO20-OU	DIRM4-30MAGICPRO20-AH		23,800	\$3,332
216571375	DIRECT AIR	DIRM4-24HXPRO28-1Z	DIRM4-24HP-WM		21,000	\$2,940
216571384	DIRECT AIR	DIRM4-24HXPRO28-1Z	DIRM4-24HP-CF		20,200	\$2,828
216571383	DIRECT AIR	DIRM4-18HXPRO28-1Z	DIRM4-18HP-CF		14,400	\$2,016
216571386	DIRECT AIR	DIRM4-48LCHX-1Z	DIRM4-48HP-CF		38,500	\$5,390
216571385	DIRECT AIR	DIRM4-36LCHX-1Z	DIRM4-36HP-CF		30,200	\$4,228
207743735	DIRECT AIR	DIRM-48LCDA25-1Z	DIRM-48HP-CF		29,000	\$4,060
212388351	DIRECT AIR	DIRM-36MAGICPRO20-OU	DIRM-36MAGICPRO20-COIL		33,000	\$4,620
203269783	DIRECT AIR	M3OH-27HFN1-M	Heat pump without ducts		18,000	\$2,520
215213797	DIRECT AIR	DIRM4-48DA25-5Z	Heat pump with ducts		37,000	\$5,180
215213810	DIRECT AIR	DIRM4-48HXPRO28-5Z	Combination heat pumps with or without ducts		44,000	\$6,160
215213809	DIRECT AIR	DIRM4-48HXPRO28-5Z	Heat pump with ducts		44,500	\$6,230
215213808	DIRECT AIR	DIRM4-48HXPRO28-5Z	Heat pump without ducts		44,000	\$6,160
215213806	DIRECT AIR	DIRM4-36HXPRO28-4Z	Heat pump with ducts		33,000	\$4,620
215213792	DIRECT AIR	DIRM4-27DA25-3Z	Combination heat pumps with or without ducts		24,000	\$3,360
215213804	DIRECT AIR	DIRM4-28HXPRO28-3Z	Combination heat pumps with or without ducts		24,000	\$3,360
215213803	DIRECT AIR	DIRM4-28HXPRO28-3Z	Heat pump with ducts		23,000	\$3,220
215213791	DIRECT AIR	DIRM4-27DA25-3Z	Heat pump with ducts		23,000	\$3,220
215213790	DIRECT AIR	DIRM4-27DA25-3Z	Heat pump without ducts		25,000	\$3,500
215213802	DIRECT AIR	DIRM4-28HXPRO28-3Z	Heat pump without ducts		25,000	\$3,500
215213801	DIRECT AIR	DIRM4-18HXPRO28-2Z	Combination heat pumps with or without ducts		17,300	\$2,422
215213800	DIRECT AIR	DIRM4-18HXPRO28-2Z	Heat pump with ducts		17,000	\$2,380
215213799	DIRECT AIR	DIRM4-18HXPRO28-2Z	Heat pump without ducts		17,600	\$2,464
213160449	DIRECT AIR	DIRM-36MAGICPRO20-OU	DIRM-36MAGICPRO20-175-COIL		27,400	\$3,836
213425838	DIRECT AIR	DIRM-36MAGICPRO20-OU1F	DIRM-36MAGICPRO20-COIL		27,000	\$3,780
213425841	DIRECT AIR	DIRM-36MAGICPRO20-OU1F	DIRM-36MAGICPRO20-175-COIL		27,000	\$3,780
213481579	DIRECT AIR	DIRM-36MAGICPRO20-OU1F	DIRM-36MAGICPRO20-AH		31,800	\$4,452
213160448	DIRECT AIR	DIRM-60MAGICPRO20-OU	DIRM-60MAGICPRO20-COIL*		37,000	\$5,180

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205920170	DIRECT AIR	M5OG-48HFN1-M-[X]	Heat pump with ducts		28,000	\$3,920
205816491	DIRECT AIR	MOX430-17HFN1-MT0W	CS11M-18HRFN1-MT0W		10,900	\$1,526
207743792	DIRECT AIR	DIRM-36HXPRO28-4Z	Heat pump with ducts		23,000	\$3,220
205920169	DIRECT AIR	M5OG-48HFN1-M-[X]	Heat pump without ducts		30,000	\$4,200
212388353	DIRECT AIR	DIRM-30MAGICPRO20-OU	DIRM-36MAGICPRO20-COIL		22,600	\$3,164
210342132	DIRECT AIR	DIRM-60MAGICPRO20-OU	DIRM-60MAGICPRO20-AH		42,000	\$5,880
207706567	DIRECT AIR	DIRM-48MAGICPRO20-OU	DIRM-48MAGICPRO20-AH		36,000	\$5,040
213160453	DIRECT AIR	DIRM-60MAGICPRO20-OU	DIRM-60MAGICPRO20-COIL**		37,000	\$5,180
210857336	DIYCOOL	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MC		10,000	\$1,400
207825551	DIYCOOL	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MB		10,000	\$1,400
210857351	DIYCOOL	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MC		10,200	\$1,428
207825552	DIYCOOL	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MB		15,000	\$2,100
210857337	DIYCOOL	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MC		15,000	\$2,100
210857338	DIYCOOL	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MC		21,200	\$2,968
207825592	DIYCOOL	ACIQ-27Z-HH-M3B	Heat pump with ducts		27,000	\$3,780
210857399	DIYCOOL	ACIQ-55Z-HH-M5B	Heat pump with ducts		35,200	\$4,928
210857349	DIYCOOL	ACIQ-12ZPL-HP230B	SCC-1218-HH-M		9,500	\$1,330
210857350	DIYCOOL	ACIQ-18ZPL-HP230B	SCC-1218-HH-M		14,500	\$2,030
208106632	DIYCOOL	ACIQ-24-HPB	ACIQ-24-AHB		19,200	\$2,688
210857361	DIYCOOL	ACIQ-24ZPL-HP230B	ACIQ-24AHB-HH-M		16,900	\$2,366
210857360	DIYCOOL	ACIQ-18ZPL-HP230B	ACIQ-18AHB-HH-M		15,400	\$2,156
207825555	DIYCOOL	ACIQ-12ZPL-HP230B	ACIQ-12CC-HH-MB		9,900	\$1,386
207825561	DIYCOOL	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MB		9,600	\$1,344
207825559	DIYCOOL	ACIQ-18ZPL-HP230B	ACIQ-18CD-HH-MB		15,000	\$2,100
207825593	DIYCOOL	ACIQ-27Z-HH-M3B	Combination heat pumps with or without ducts		26,800	\$3,752
210857400	DIYCOOL	ACIQ-55Z-HH-M5B	Combination heat pumps with or without ducts		34,800	\$4,872
207825553	DIYCOOL	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MB		21,200	\$2,968
210857398	DIYCOOL	ACIQ-55Z-HH-M5B	Heat pump without ducts		34,400	\$4,816
207825597	DIYCOOL	ACIQ-48Z-HH-M5B	Heat pump without ducts		36,000	\$5,040
207825591	DIYCOOL	ACIQ-27Z-HH-M3B	Heat pump without ducts		26,600	\$3,724
207825588	DIYCOOL	ACIQ-18Z-HH-M2B	Heat pump without ducts		15,000	\$2,100
208106633	DIYCOOL	ACIQ-36-HPB	ACIQ-36-AHB		30,400	\$4,256
213492141	DIYCOOL	ACIQ-36-HPC	ACIQ-36-AHB		30,400	\$4,256

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214810549	DIYCOOL	ACIQ-18-HPB	ACIQ-18-AHB		13,500	\$1,890
207825558	DIYCOOL	ACIQ-12ZPL-HP230B	ACIQ-12CD-HH-MB		10,600	\$1,484
207825560	DIYCOOL	ACIQ-24ZPL-HP230B	ACIQ-24CD-HH-MB		21,000	\$2,940
207825594	DIYCOOL	ACIQ-36Z-HH-M4B	Heat pump without ducts		33,000	\$4,620
207825598	DIYCOOL	ACIQ-48Z-HH-M5B	Heat pump with ducts		36,000	\$5,040
207825563	DIYCOOL	ACIQ-24ZPL-HP230B	ACIQ-24FM-HH-MB		19,000	\$2,660
207825590	DIYCOOL	ACIQ-18Z-HH-M2B	Combination heat pumps with or without ducts		15,500	\$2,170
207825599	DIYCOOL	ACIQ-48Z-HH-M5B	Combination heat pumps with or without ducts		36,000	\$5,040
207825589	DIYCOOL	ACIQ-18Z-HH-M2B	Heat pump with ducts		16,000	\$2,240
207825596	DIYCOOL	ACIQ-36Z-HH-M4B	Combination heat pumps with or without ducts		34,000	\$4,760
215570369	DIYCOOL	ACIQ-30-HPB	ACIQ-30-AHB		21,000	\$2,940
212394334	DIYCOOL	ACIQ-24-HPB	ACIQ-24-ACL		21,000	\$2,940
216980848	DIYCOOL	EZ-60-HPB	EZ-60-AHB		45,000	\$6,300
216980847	DIYCOOL	EZ-48-HPB	EZ-48-AHB		37,000	\$5,180
216980846	DIYCOOL	EZ-36-HPB	EZ-36-AHB		31,800	\$4,452
216980845	DIYCOOL	EZ-24-HPB	EZ-24-AHB		20,000	\$2,800
216980843	DIYCOOL	EZ-48-EHPB	EZ-48-AHB		32,400	\$4,536
216980841	DIYCOOL	EZ-24-EHPB	EZ-24-AHB		20,000	\$2,800
212394336	DIYCOOL	ACIQ-36-HPB	ACIQ-36-ACL		33,000	\$4,620
213492149	DIYCOOL	ACIQ-30-HPB	ACIQ-36-ACL-17		19,600	\$2,744
210857339	DIYCOOL	ACIQ-36ZPL-HP230B	ACIQ-36CC-HH-MB		33,000	\$4,620
210857340	DIYCOOL	ACIQ-48ZPL-HP230B	ACIQ-48CC-HH-MB		35,000	\$4,900
210857345	DIYCOOL	ACIQ-48ZPL-HP230B	ACIQ-48FM-HH-MB		35,000	\$4,900
210857342	DIYCOOL	ACIQ-48ZPL-HP230B	ACIQ-48CD-HH-MB		39,500	\$5,530
206315650	DIYCOOL	ACIQ-27Z-HH-M3	Heat pump without ducts		18,000	\$2,520
214810550	DIYCOOL	EZ-24-HP	EZ-24-AH		19,200	\$2,688
214810551	DIYCOOL	EZ-48-HP	EZ-48-AH		36,000	\$5,040
214810552	DIYCOOL	EZ-60-HP	EZ-60-AH		42,000	\$5,880
213492151	DIYCOOL	ACIQ-36-HPB	ACIQ-36-ACL-17		27,400	\$3,836
210857343	DIYCOOL	ACIQ-60ZPL-HP230B	ACIQ-60CD-HH-MB		40,000	\$5,600
213492143	DIYCOOL	ACIQ-36-HPC	ACIQ-36-ACL		27,000	\$3,780
213492142	DIYCOOL	ACIQ-36-HPC	ACIQ-36-ACL-17		27,000	\$3,780
213500938	DIYCOOL	ACIQ-36-HPC	ACIQ-36-AHB*		31,800	\$4,452
213433274	DIYCOOL	ACIQ-36-HPB	ACIQ-36W-P		32,800	\$4,592
213433272	DIYCOOL	ACIQ-24-HPB	ACIQ-24W-P		19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213433271	DIYCOOL	ACIQ-18-HPB	ACIQ-18W-P		13,500	\$1,890
213433273	DIYCOOL	ACIQ-30-HPB	ACIQ-30W-P		20,000	\$2,800
213433267	DIYCOOL	ACIQ-18-HPB	ACIQ-18W-WM		15,800	\$2,212
213433268	DIYCOOL	ACIQ-24-HPB	ACIQ-24W-WM		20,000	\$2,800
213433262	DIYCOOL	ACIQ-60HPB	ACIQ-60-ACL		37,000	\$5,180
213492148	DIYCOOL	ACIQ-30-HPB	ACIQ-36-ACL		22,600	\$3,164
207825595	DIYCOOL	ACIQ-36Z-HH-M4B	Heat pump with ducts		23,000	\$3,220
206315628	DIYCOOL	ACIQ-24-HP	ACIQ-24-AH		16,500	\$2,310
210857344	DIYCOOL	ACIQ-36ZPL-HP230B	ACIQ-36FM-HH-MB		32,000	\$4,480
206315652	DIYCOOL	ACIQ-48Z-HH-M5	Heat pump without ducts		30,000	\$4,200
212394335	DIYCOOL	ACIQ-30-HPB	ACIQ-30-ACL		22,600	\$3,164
210857359	DIYCOOL	ACIQ-60HPB	ACIQ-60AHB		42,000	\$5,880
208106634	DIYCOOL	ACIQ-48-HPB	ACIQ-48-AHB		36,000	\$5,040
210857346	DIYCOOL	ACIQ-60ZPL-HP230B	ACIQ-60FM-HH-MB		40,000	\$5,600
208106854	DUCANE	4DHP2S48M-1P	Heat pump without ducts		36,000	\$5,040
216769825	DUCANE	7SCP18V60P-**A	7EH60DX-**+TDR	97G2UH135DV20*	44,000	\$6,160
216769821	DUCANE	7SCP18V60P-**A	7ED60DX-**+TDR	97G2DF110CV20*	44,000	\$6,160
216769819	DUCANE	7SCP18V60P-**A	7ED60DX-**+TDR	97G2DF090CV20*	44,000	\$6,160
216769817	DUCANE	7SCP18V60P-**A	7E[C,U]60DX-**+TDR	97G2UH135DV20*	44,000	\$6,160
216769815	DUCANE	7SCP18V60P-**A	7EH50/60CX-**+TDR	97G2UH090CV20*	44,500	\$6,230
216769813	DUCANE	7SCP18V60P-**A	7EH50/60CX-**+TDR	97G2UH110CV20*	44,000	\$6,160
216769811	DUCANE	7SCP18V60P-**A	7E[C,U]60CX-**+TDR	97G2UH090CV20*	44,000	\$6,160
216769809	DUCANE	7SCP18V60P-**A	7E[C,U]60CX-**+TDR	97G2UH110CV20*	43,500	\$6,090
216769789	DUCANE	7SCP18V60P-**A	7ED48CX-**+TDR	97G2DF110CV20*	39,500	\$5,530
216769787	DUCANE	7SCP18V60P-**A	7ED48CX-**+TDR	97G2DF090CV20*	39,500	\$5,530
216769783	DUCANE	7SCP18V60P-**A	7EH48CX-**+TDR	97G2UH110CV20*	39,500	\$5,530
216769781	DUCANE	7SCP18V60P-**A	7EH42CX-**+TDR	97G2UH090CV20*	39,500	\$5,530
216769779	DUCANE	7SCP18V60P-**A	7EH42CX-**+TDR	97G2UH110CV20*	39,500	\$5,530
216769777	DUCANE	7SCP18V60P-**A	7E[C,U]49CX-**+TDR	97G2UH090CV20*	39,500	\$5,530
216769775	DUCANE	7SCP18V60P-**A	7E[C,U]49CX-**+TDR	97G2UH110CV20*	39,000	\$5,460
216769773	DUCANE	7SCP18V60P-**A	7E[C,U]48CX-**+TDR	97G2UH090CV20*	39,500	\$5,530
216769771	DUCANE	7SCP18V60P-**A	7E[C,U]48CX-**+TDR	97G2UH110CV20*	39,500	\$5,530
216769785	DUCANE	7SCP18V60P-**A	7ED42BX-**+TDR	97G2DF070BV16*	40,000	\$5,600
216769735	DUCANE	7SCP18V36P-**A	7ED42BX-**+TDR	97G2DF070BV16*	29,000	\$4,060
216769733	DUCANE	7SCP18V36P-**A	7ED30/36BX-**+TDR	97G2DF070BV16*	29,000	\$4,060
216769731	DUCANE	7SCP18V36P-**A	7EH36CX-**+TDR	97G2UH090CV12*	28,600	\$4,004
216769729	DUCANE	7SCP18V36P-**A	7EH36BX-**+TDR	97G2UH070BV12*	28,800	\$4,032
216769727	DUCANE	7SCP18V36P-**A	7EH36BX-**+TDR	97G2UH045BV12*	28,800	\$4,032

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216769725	DUCANE	7SCP18V36P-**-A	7EH30BX-**-TDR	97G2UH070BV12*	28,800	\$4,032
216769674	DUCANE	7SCP18V24P-**-A	7EH30BX-**-TDR	97G2UH070BV12*	19,800	\$2,772
216769672	DUCANE	7SCP18V24P-**-A	7EH30BX-**-TDR	97G2UH045BV12*	19,800	\$2,772
216769670	DUCANE	7SCP18V24P-**-A	7EH24BX-**-TDR	97G2UH070BV12*	19,800	\$2,772
216769668	DUCANE	7SCP18V24P-**-A	7EH24BX-**-TDR	97G2UH045BV12*	19,800	\$2,772
216769721	DUCANE	7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	97G2UH070BV12*	28,800	\$4,032
216769666	DUCANE	7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	97G2UH070BV12*	19,800	\$2,772
216769719	DUCANE	7SCP18V36P-**-A	7E[C,U]36BX-**-TDR	97G2UH045BV12*	28,800	\$4,032
216769664	DUCANE	7SCP18V24P-**-A	7E[C,U]36BX-**-TDR	97G2UH045BV12*	19,800	\$2,772
216769717	DUCANE	7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	97G2UH070BV12*	28,800	\$4,032
216769662	DUCANE	7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	97G2UH070BV12*	19,800	\$2,772
216769715	DUCANE	7SCP18V36P-**-A	7E[C,U]30BX-**-TDR	97G2UH045BV12*	29,000	\$4,060
216769660	DUCANE	7SCP18V24P-**-A	7E[C,U]30BX-**-TDR	97G2UH045BV12*	19,800	\$2,772
216619116	DUCANE	7SCP18V60P-**-A	7ED60DX-**-TDR		43,500	\$6,090
216619115	DUCANE	7SCP18V60P-**-A	7ED50/60CX-**-TDR		43,500	\$6,090
216619114	DUCANE	7SCP18V60P-**-A	7EH60DX-**-TDR		43,500	\$6,090
216619113	DUCANE	7SCP18V60P-**-A	7EH50/60CX-**-TDR		43,500	\$6,090
216619112	DUCANE	7SCP18V60P-**-A	7E[C,U]60DX-**-TDR		42,000	\$5,880
216619111	DUCANE	7SCP18V60P-**-A	7ED48CX-**-TDR		40,000	\$5,600
216619110	DUCANE	7SCP18V60P-**-A	7ED42BX-**-TDR		40,500	\$5,670
216619108	DUCANE	7SCP18V60P-**-A	7EH48BX-**-TDR		40,500	\$5,670
216619107	DUCANE	7SCP18V60P-**-A	7EH42CX-**-TDR		40,500	\$5,670
216619106	DUCANE	7SCP18V60P-**-A	7EH42BX-**-TDR		40,000	\$5,600
216619105	DUCANE	7SCP18V60P-**-A	7E[C,U]49CX-**-TDR		40,000	\$5,600
216619082	DUCANE	7SCP18V60P-**-A	7AH1AE60PX-**-		43,000	\$6,020
216619081	DUCANE	7SCP18V60P-**-A	7AH1AE48PX-**-		39,000	\$5,460
216619080	DUCANE	7SCP18V60P-**-A	7AH1AV42PX-**-		38,500	\$5,390
216619079	DUCANE	7SCP18V60P-**-A	7AH1AE42PX-**-		39,000	\$5,460
216013469	DUCANE	7SCP18V36P-**-A	7AH1AV36PX-**-		28,000	\$3,920
216619103	DUCANE	7SCP18V36P-**-A	7ED42BX-**-TDR		28,000	\$3,920
216619102	DUCANE	7SCP18V36P-**-A	7ED30/36BX-**-TDR		28,000	\$3,920
216619101	DUCANE	7SCP18V36P-**-A	7EH36CX-**-TDR		28,000	\$3,920
216619099	DUCANE	7SCP18V36P-**-A	7EH36AX-**-TDR		28,400	\$3,976
216619098	DUCANE	7SCP18V36P-**-A	7EH30BX-**-TDR		28,000	\$3,920
216619097	DUCANE	7SCP18V36P-**-A	7EH30AX-**-TDR		28,000	\$3,920
216619096	DUCANE	7SCP18V36P-**-A	7E[C,U]36AX-**-TDR		28,000	\$3,920
216619095	DUCANE	7SCP18V36P-**-A	7E[C,U]30BX-**-TDR		28,000	\$3,920
216619094	DUCANE	7SCP18V36P-**-A	7E[C,U]30AX-**-TDR		28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216619078	DUCANE	7SCP18V36P-**A	7AH1AV42PX-**		28,000	\$3,920
216619077	DUCANE	7SCP18V36P-**A	7AH1AE42PX-**		28,000	\$3,920
216619076	DUCANE	7SCP18V36P-**A	7AH1AC42PX-**		28,400	\$3,976
216619075	DUCANE	7SCP18V36P-**A	7AH1AE36PX-**		28,000	\$3,920
216619074	DUCANE	7SCP18V36P-**A	7AH1AC36PX-**		28,400	\$3,976
216013468	DUCANE	7SCP18V24P-**A	7AH1AV24PX-**		18,000	\$2,520
216619090	DUCANE	7SCP18V24P-**A	7EH30AX-**+TDR		19,600	\$2,744
216619088	DUCANE	7SCP18V24P-**A	7EH24AX-**+TDR		19,600	\$2,744
216619086	DUCANE	7SCP18V24P-**A	7E[C,U]36BX-**+TDR		19,600	\$2,744
216619085	DUCANE	7SCP18V24P-**A	7E[C,U]36AX-**+TDR		19,600	\$2,744
216619071	DUCANE	7SCP18V24P-**A	7AH1AE24PX-**		19,200	\$2,688
216619070	DUCANE	7SCP18V24P-**A	7AH1AC24PX-**		19,600	\$2,744
215359258	DURASTAR	DRA1H18S2A	DRAW18F2A		14,400	\$2,016
215359252	DURASTAR	DRA1H12S2A	DRAW12F2A		10,000	\$1,400
210568112	Durastar	DRA1H12S1A	DRAC12F1A		9,900	\$1,386
211497017	Durastar	DRA1H12S1A	DRAS12F1B		9,600	\$1,344
210568117	Durastar	DRA1H18S1A	DRAD18F1A		15,000	\$2,100
210568114	Durastar	DRA1H24S1A	DRAC24F1B		21,000	\$2,940
210568215	Durastar	DRA3H28M1A	Heat pump with ducts		27,000	\$3,780
210568224	Durastar	DRA5H55M1A	Heat pump with ducts		35,200	\$4,928
210568109	Durastar	DRA1H12S1A	DRAS12F1C		10,200	\$1,428
210568104	Durastar	DRA1H12S1A	DRAL12F1A		9,500	\$1,330
210568105	Durastar	DRA1H18S1A	DRAL18F1A		14,500	\$2,030
210568222	DURASTAR	DRA5H48M1A	Combination heat pumps with or without ducts		37,400	\$5,236
210568216	DURASTAR	DRA3H28M1A	Combination heat pumps with or without ducts		26,200	\$3,668
210568225	DURASTAR	DRA5H55M1A	Combination heat pumps with or without ducts		35,000	\$4,900
213350741	DURASTAR	DRA1H24S1A	DRAM24F1A		16,900	\$2,366
213350738	DURASTAR	DRA1H18S1A	DRAM18F1A		15,400	\$2,156
210568223	Durastar	DRA5H55M1A	Heat pump without ducts		34,800	\$4,872
210568214	Durastar	DRA3H28M1A	Heat pump without ducts		25,600	\$3,584
210568211	Durastar	DRA2H18M1A	Heat pump without ducts		13,500	\$1,890
210568099	DURASTAR	DRA1H12S1A	DRAW12F1B		10,300	\$1,442
210568100	DURASTAR	DRA1H18S1A	DRAW18F1B		11,100	\$1,554
210568101	DURASTAR	DRA1H24S1A	DRAW24F1B		18,900	\$2,646
210568118	Durastar	DRA1H24S1A	DRAD24F1A		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210568116	Durastar	DRA1H12S1A	DRAD12F1A		10,600	\$1,484
210568120	Durastar	DRA1H24S1A	DRAF24F1A		19,000	\$2,660
210568212	Durastar	DRA2H18M1A	Heat pump with ducts		16,000	\$2,240
210568217	Durastar	DRA4H36M1A	Heat pump without ducts		35,000	\$4,900
210568221	Durastar	DRA5H48M1A	Heat pump with ducts		36,000	\$5,040
210568213	DURASTAR	DRA2H18M1A	Combination heat pumps with or without ducts		14,700	\$2,058
210568219	DURASTAR	DRA4H36M1A	Combination heat pumps with or without ducts		35,000	\$4,900
210568220	Durastar	DRA5H48M1A	Heat pump without ducts		39,000	\$5,460
215359255	DURASTAR	DRA1H12S2A	DRAS12F2A		9,800	\$1,372
215374885	DURASTAR	DRU1H24S2A	DRUM1824S2A		20,000	\$2,800
215374887	DURASTAR	DRU1H36S2A	DRUM3036S2A		31,800	\$4,452
215359266	DURASTAR	DRA1H24S2A	DRAC24F2A		20,400	\$2,856
215415539	DURASTAR	DRA6U48M2A	Heat pump with ducts		37,000	\$5,180
215415537	DURASTAR	DRA6H55M2A	Combination heat pumps with or without ducts		45,000	\$6,300
215415536	DURASTAR	DRA6H55M2A	Heat pump with ducts		45,000	\$6,300
215415535	DURASTAR	DRA6H55M2A	Heat pump without ducts		45,000	\$6,300
215415534	DURASTAR	DRA6H48M2A	Combination heat pumps with or without ducts		42,500	\$5,950
215415533	DURASTAR	DRA6H48M2A	Heat pump with ducts		44,500	\$6,230
215415532	DURASTAR	DRA6H48M2A	Heat pump without ducts		40,500	\$5,670
215415501	DURASTAR	DRU1H30S2A	DRUM3036S2A		23,800	\$3,332
215359268	DURASTAR	DRA1H24S2A	DRADH24F2A		21,600	\$3,024
215359264	DURASTAR	DRA1H18S2A	DRADH18F2A		15,000	\$2,100
215359263	DURASTAR	DRA1H18S2A	DRADL18F2A		15,000	\$2,100
215359257	DURASTAR	DRA1H12S2A	DRADH0912F2A		10,200	\$1,428
215359256	DURASTAR	DRA1H12S2A	DRADL0612F2A		9,600	\$1,344
215359240	DURASTAR	DRA5U48M2A	Heat pump with ducts		37,000	\$5,180
215359229	DURASTAR	DRA5H55M2A	Combination heat pumps with or without ducts		45,000	\$6,300
215359228	DURASTAR	DRA5H55M2A	Heat pump with ducts		45,000	\$6,300
215359227	DURASTAR	DRA5H55M2A	Heat pump without ducts		45,000	\$6,300
215359226	DURASTAR	DRA5H48M2A	Combination heat pumps with or without ducts		42,500	\$5,950
215359225	DURASTAR	DRA5H48M2A	Heat pump with ducts		44,500	\$6,230
215359224	DURASTAR	DRA5H48M2A	Heat pump without ducts		40,500	\$5,670

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215359223	DURASTAR	DRA5H36M2A	Combination heat pumps with or without ducts		34,800	\$4,872
215359222	DURASTAR	DRA5H36M2A	Heat pump with ducts		33,000	\$4,620
215359221	DURASTAR	DRA5H36M2A	Heat pump without ducts		36,600	\$5,124
215359220	DURASTAR	DRA4H28M2A	Combination heat pumps with or without ducts		23,200	\$3,248
215359219	DURASTAR	DRA4H28M2A	Heat pump with ducts		23,000	\$3,220
215359218	DURASTAR	DRA4H28M2A	Heat pump without ducts		23,600	\$3,304
215359217	DURASTAR	DRA3H18M2A	Combination heat pumps with or without ducts		16,700	\$2,338
215359216	DURASTAR	DRA3H18M2A	Heat pump with ducts		17,000	\$2,380
215359215	DURASTAR	DRA3H18M2A	Heat pump without ducts		16,400	\$2,296
215359269	DURASTAR	DRA1H33S2A	DRAW33F2A		29,600	\$4,144
215359267	DURASTAR	DRA1H24S2A	DRAF24F2A		20,200	\$2,828
215359262	DURASTAR	DRA1H18S2A	DRAF18F2A		14,400	\$2,016
215359261	DURASTAR	DRA1H18S2A	DRAS16F2A		14,200	\$1,988
215359260	DURASTAR	DRA1H18S2A	DRAC18F2A		14,900	\$2,086
215359259	DURASTAR	DRA1H18S2A	DRAL18F2A		14,500	\$2,030
215359254	DURASTAR	DRA1H12S2A	DRAC0912F2A		10,000	\$1,400
215359253	DURASTAR	DRA1H12S2A	DRAL0612F2A		9,600	\$1,344
215359265	DURASTAR	DRA1H24S2A	DRAW24F2A		21,600	\$3,024
215374888	DURASTAR	DRU1H42S2A	DRUM4260S2A		37,000	\$5,180
215374896	DURASTAR	DRU1U48S2A	DRUM4260S2A		32,400	\$4,536
215374889	DURASTAR	DRU1H48S2A	DRUM4260S2A		37,000	\$5,180
215374886	DURASTAR	DRA1H30S2A	DRUM3036S2A		23,800	\$3,332
215374884	DURASTAR	DRU1H18S2A	DRUM1824S2A		15,000	\$2,100
215374893	DURASTAR	DRU1U24S2A	DRUM1824S2A		20,000	\$2,800
215374891	DURASTAR	DRU1H60S2A	DRUM4260S2A		45,000	\$6,300
215374890	DURASTAR	DRU1H49S2A	DRUM4260S2A		45,000	\$6,300
215374883	DURASTAR	DRA1H24S2A	DRAM24F2A		16,900	\$2,366
215374882	DURASTAR	DRA1H18S2A	DRAM18F2A		14,000	\$1,960
213160486	DURASTAR	DRA1H33S1A	DRAW33F1B		27,800	\$3,892
213088008	ECO AC	EMH-5048BBH	Combination heat pumps with or without ducts		37,400	\$5,236
210586155	ECO AC	EMH-3027BBH	Heat pump with ducts		27,000	\$3,780
211253515	ECO AC	EH1-O18BAH	EH1-V18BA		13,500	\$1,890
211253516	ECO AC	EH1-O24BAH	EH1-V24BA		19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210586156	ECO AC	EMH-3027BBH	Combination heat pumps with or without ducts		26,200	\$3,668
210586151	ECO AC	EMH-2018BBH	Heat pump without ducts		13,500	\$1,890
210586154	ECO AC	EMH-3027BBH	Heat pump without ducts		25,600	\$3,584
211253517	ECO AC	EH1-O30BAH	EH1-V30BA		21,000	\$2,940
211253518	ECO AC	EH1-O36BAH	EH1-V36BA		30,400	\$4,256
214232433	ECO AC	EHP-O12BB	EHP-W12BB		10,300	\$1,442
214232434	ECO AC	EHP-O18BB	EHP-W18BB		11,100	\$1,554
214232435	ECO AC	EHP-O24BB	EHP-W24BB		18,900	\$2,646
210586157	ECO AC	EMH-4036BBH	Heat pump without ducts		35,000	\$4,900
210586159	ECO AC	EMH-4036BBH	Combination heat pumps with or without ducts		35,000	\$4,900
213088006	ECO AC	EMH-5048BBH	Heat pump without ducts		39,000	\$5,460
213088007	ECO AC	EMH-5048BBH	Heat pump with ducts		36,000	\$5,040
210586152	ECO AC	EMH-2018BBH	Heat pump with ducts		16,000	\$2,240
210586153	ECO AC	EMH-2018BBH	Combination heat pumps with or without ducts		14,700	\$2,058
215416031	ECO AC	EHH-O18KBA	EHH-W18KBA		10,800	\$1,512
215428290	ECO AC	EH1-O36KBA	EH1-V24KBA		20,000	\$2,800
215428291	ECO AC	EH1-O36KBA	EH1-V36KBA		29,000	\$4,060
215428292	ECO AC	EH1-O60KBA	EH1-V48KBA		39,500	\$5,530
215428293	ECO AC	EH1-O60KBA	EH1-V60KBA		44,000	\$6,160
215416008	ECO AC	EHH-O30KBA	EHH-W30KBA		24,000	\$3,360
215416009	ECO AC	EHH-O36KBA	EHH-W36KBA		27,800	\$3,892
215416010	ECO AC	EHP-O18KBA	EHP-W18KBA		15,100	\$2,114
215416011	ECO AC	EHP-O24KBA	EHP-W24KBA		20,000	\$2,800
215416012	ECO AC	EHP-O12KBA	EHP-W12KBA		10,300	\$1,442
215416025	ECO AC	EHH-O12KBA	EHH-W12KBA		10,000	\$1,400
215416026	ECO AC	EHH-O24KBA	EHH-D24KBA		19,400	\$2,716
215420702	ECO AC	EMH-4036KBA	Heat pump without ducts		30,800	\$4,312
215420703	ECO AC	EMH-5042KBA	Heat pump without ducts		35,600	\$4,984
215420704	ECO AC	EMH-2018KBA	Heat pump without ducts		15,000	\$2,100
215420705	ECO AC	EMH-3024KBA	Heat pump without ducts		23,600	\$3,304
215420706	ECO AC	EMH-4030KBA	Heat pump without ducts		27,200	\$3,808
215420707	ECO AC	EMH-2018KBA	Heat pump with ducts		15,000	\$2,100
215420708	ECO AC	EMH-3024KBA	Heat pump with ducts		23,000	\$3,220
215420709	ECO AC	EMH-4030KBA	Heat pump with ducts		26,800	\$3,752
215420710	ECO AC	EMH-4036KBA	Heat pump with ducts		30,000	\$4,200

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215420711	ECO AC	EMH-5O42KBA	Heat pump with ducts		32,400	\$4,536
215420712	ECO AC	EMH-2O18KBA	Combination heat pumps with or without ducts		15,000	\$2,100
215420713	ECO AC	EMH-3O24KBA	Combination heat pumps with or without ducts		23,000	\$3,220
215420714	ECO AC	EMH-4O30KBA	Combination heat pumps with or without ducts		27,000	\$3,780
215420715	ECO AC	EMH-4O36KBA	Combination heat pumps with or without ducts		30,200	\$4,228
215420716	ECO AC	EMH-5O42KBA	Combination heat pumps with or without ducts		32,600	\$4,564
215416032	ECO AC	EHH-O18KBA	EHH-D18KBA		14,600	\$2,044
216772325	ECO AC	EHP-O24KBB	EHP-W24KBB		15,000	\$2,100
216772334	ECO AC	EHS-O30KBB	EHS-W30KBB		24,000	\$3,360
216772333	ECO AC	EHS-O36KBB	EHS-W36KBB		27,400	\$3,836
216772344	ECO AC	EMH-*O48KBB	Heat pump without ducts		40,000	\$5,600
216772329	ECO AC	EHH-O24KBB	EHH-W24KBB		19,000	\$2,660
216772343	ECO AC	EMH-5O42KBB	Heat pump without ducts		40,000	\$5,600
216772342	ECO AC	EMH-4O36KBB	Heat pump without ducts		36,000	\$5,040
216772341	ECO AC	EMH-4O30KBB	Heat pump without ducts		28,000	\$3,920
216772340	ECO AC	EMH-3O24KBB	Heat pump without ducts		23,600	\$3,304
216772339	ECO AC	EMH-2O18KBB	Heat pump without ducts		16,000	\$2,240
216772330	ECO AC	EHH-O12KBB	EHH-W12KBB		10,000	\$1,400
215428297	ECO AC	EH1-O60KBA	EKCA60*I		44,500	\$6,230
215428296	ECO AC	EH1-O60KBA	EKCA48*I		39,000	\$5,460
215428295	ECO AC	EH1-O36KBA	EKCA36*I		23,200	\$3,248
215428294	ECO AC	EH1-O36KBA	EKCA24*I		19,600	\$2,744
211253520	ECO AC	EH1-O60BAH	EH1-V60BA		42,000	\$5,880
211253519	ECO AC	EH1-O48BAH	EH1-V48BA		36,000	\$5,040
209319638	ECO AIR	M2OI-18HFN1-M	Heat pump without ducts		15,000	\$2,100
209319639	ECO AIR	M2OI-18HFN1-M	Heat pump with ducts		16,000	\$2,240
209319640	ECO AIR	M2OI-18HFN1-M	Combination heat pumps with or without ducts		15,500	\$2,170
209319641	ECO AIR	M3OI-28HFN1-M	Heat pump without ducts		26,600	\$3,724
209319642	ECO AIR	M3OI-28HFN1-M	Heat pump with ducts		27,000	\$3,780
209319643	ECO AIR	M3OI-28HFN1-M	Combination heat pumps with or without ducts		26,800	\$3,752
209319644	ECO AIR	M4OI-36HFN1-M	Heat pump without ducts		33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
209319646	ECO AIR	M4OI-36HFN1-M	Combination heat pumps with or without ducts		34,000	\$4,760
209319650	ECO AIR	M5OA-55HFN1-M-[X]	Heat pump without ducts		34,400	\$4,816
209319651	ECO AIR	M5OA-55HFN1-M-[X]	Heat pump with ducts		35,200	\$4,928
209319652	ECO AIR	M5OA-55HFN1-M-[X]	Combination heat pumps with or without ducts		34,800	\$4,872
209319647	ECO AIR	M5OG-48HFN1-M-[X]	Heat pump without ducts		36,000	\$5,040
209319648	ECO AIR	M5OG-48HFN1-M-[X]	Heat pump with ducts		36,000	\$5,040
209319649	ECO AIR	M5OG-48HFN1-M-[X]	Combination heat pumps with or without ducts		36,000	\$5,040
209319645	ECO-AIR	M4OI-36HFN1-M	Heat pump with ducts		23,000	\$3,220
216760000	ECO-AIR	EDMO-18H	Heat pump without ducts		17,600	\$2,464
216760001	ECO-AIR	EDMO-18H	Heat pump with ducts		17,000	\$2,380
216760002	ECO-AIR	EDMO-18H	Combination heat pumps with or without ducts		17,300	\$2,422
216760003	ECO-AIR	EDMO-27H	Heat pump without ducts		25,000	\$3,500
216760004	ECO-AIR	EDMO-27H	Heat pump with ducts		23,000	\$3,220
216760005	ECO-AIR	EDMO-27H	Combination heat pumps with or without ducts		24,000	\$3,360
216760006	ECO-AIR	EDMO-36H	Heat pump without ducts		30,000	\$4,200
216760007	ECO-AIR	EDMO-36H	Heat pump with ducts		33,000	\$4,620
216760008	ECO-AIR	EDMO-36H	Combination heat pumps with or without ducts		31,400	\$4,396
216759995	ECO-AIR	EDMO-48E	Heat pump with ducts		37,000	\$5,180
216760009	ECO-AIR	EDMO-48H	Heat pump without ducts		44,000	\$6,160
216760010	ECO-AIR	EDMO-48H	Heat pump with ducts		44,500	\$6,230
216760011	ECO-AIR	EDMO-48H	Combination heat pumps with or without ducts		44,000	\$6,160
216760012	ECO-AIR	EDMO-53H	Heat pump without ducts		44,000	\$6,160
216760013	ECO-AIR	EDMO-53H	Heat pump with ducts		45,000	\$6,300
216760014	ECO-AIR	EDMO-53H	Combination heat pumps with or without ducts		44,500	\$6,230
216759946	ECO-AIR	EDSO-12H	ED4W-12U		10,000	\$1,400
216759953	ECO-AIR	EDSO-12H	ED1W-12U		9,600	\$1,344
216759960	ECO-AIR	EDSO-12H	EDLS-12U		9,600	\$1,344
216759966	ECO-AIR	EDSO-12H	EDHS-12U		10,200	\$1,428
216759981	ECO-AIR	EDSO-12H	EDWM-12U		9,800	\$1,372
216759947	ECO-AIR	EDSO-18H	ED4W-18U		14,900	\$2,086
216759954	ECO-AIR	EDSO-18H	ED1W-18U		14,500	\$2,030

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216759961	ECO-AIR	EDSO-18H	EDLS-18U		15,000	\$2,100
216759967	ECO-AIR	EDSO-18H	EDHS-18U		15,000	\$2,100
216759982	ECO-AIR	EDSO-18H	EDWM-18U		15,000	\$2,100
216759948	ECO-AIR	EDSO-24H	ED4W-24U		20,400	\$2,856
216759968	ECO-AIR	EDSO-24H	EDHS-24U		21,600	\$3,024
216759983	ECO-AIR	EDSO-24H	EDWM-24U		21,000	\$2,940
216759984	ECO-AIR	EDSO-33H	EDWM-33U		30,000	\$4,200
216759949	ECO-AIR	EDSO-36H	ED4W-36U		30,600	\$4,284
216759969	ECO-AIR	EDSO-36H	EDHS-36U		31,600	\$4,424
216759950	ECO-AIR	EDSO-48H	ED4W-48U		44,000	\$6,160
216759970	ECO-AIR	EDSO-48H	EDHS-48U		45,000	\$6,300
216759971	ECO-AIR	EDSO-60H	EDHS-60U		45,000	\$6,300
213307915	ECO-AIR	M4OX630-36HFN1-M1X	Heat pump without ducts		27,400	\$3,836
213307916	ECO-AIR	M4OX630-36HFN1-M1X	Heat pump with ducts		30,000	\$4,200
213307917	ECO-AIR	M4OX630-36HFN1-M1X	Combination heat pumps with or without ducts		28,600	\$4,004
208121867	ECO-AIR	MOD30-24HFN1-MU0W	MSEPD-24HRFN1-MU0W		21,200	\$2,968
211644065	ECO-AIR	MOD30-24HFN1-MU0W	MTIU-24HWFN1-M		21,000	\$2,940
211644072	ECO-AIR	MOE30U-36HFN1-M(GA)	MCD1-36HRFN1-M(GA)		33,000	\$4,620
211644073	ECO-AIR	MOE30U-48HFN1-M-[X](GA)	MCD1-48HRFN1-M(GA)		35,000	\$4,900
208121865	ECO-AIR	MOX330-12HFN1-MW5W	MSEPB-12HRFN1-MW5W(GA)		10,000	\$1,400
211644063	ECO-AIR	MOX330-12HFN1-MW5W	MTIU-12HWFN1-M		10,600	\$1,484
211644069	ECO-AIR	MOX330-12HFN1-MW5W	CCA3U-12HRFN1-M(C)		9,900	\$1,386
211644094	ECO-AIR	MOX330-12HFN1-MW5W	MCBU-12HRFN1-MV0W		9,500	\$1,330
208121866	ECO-AIR	MOX430-17HFN1-MT0W	MSEPC-18HRFN1-MU0W		15,000	\$2,100
211644064	ECO-AIR	MOX430-17HFN1-MT0W	MTIU-18HWFN1-M		15,000	\$2,100
211644095	ECO-AIR	MOX430-17HFN1-MT0W	MCBU-18HRFN1-MU2W		14,500	\$2,030
216759912	ECO-AIR	ECUO-18H	ECCB-24U		15,200	\$2,128
216759893	ECO-AIR	ECUO-18H	ECMP-18U		15,000	\$2,100
216759910	ECO-AIR	ECUO-18H	ECCA-24U		15,200	\$2,128
216759904	ECO-AIR	ECUO-24E	ECCA-24U		19,700	\$2,758
216759905	ECO-AIR	ECUO-24E	ECCB-24U		19,700	\$2,758
216759888	ECO-AIR	ECUO-24E	ECMP-24U		20,000	\$2,800
216759911	ECO-AIR	ECUO-24H	ECCA-24U		19,700	\$2,758
216759913	ECO-AIR	ECUO-24H	ECCB-24U		19,700	\$2,758
216759894	ECO-AIR	ECUO-24H	ECMP-24U		20,000	\$2,800

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216759915	ECO-AIR	ECUO-30H	ECCB-36U		25,000	\$3,500
216759917	ECO-AIR	ECUO-30H	ECCC-36U		25,000	\$3,500
216759895	ECO-AIR	ECUO-30H	ECMP-30U		23,800	\$3,332
216759896	ECO-AIR	ECUO-33H	ECMP-33U		23,200	\$3,248
216759925	ECO-AIR	ECUO-36E	ECPA-36U		24,600	\$3,444
216759916	ECO-AIR	ECUO-36H	ECCB-36U		29,200	\$4,088
216759918	ECO-AIR	ECUO-36H	ECCC-36U		29,200	\$4,088
216759898	ECO-AIR	ECUO-42H	ECMP-48U		37,000	\$5,180
216759891	ECO-AIR	ECUO-48E	ECMP-48U		32,400	\$4,536
216759899	ECO-AIR	ECUO-48H	ECMP-48U		37,000	\$5,180
216759919	ECO-AIR	ECUO-48H	ECCC-60U		34,400	\$4,816
216759900	ECO-AIR	ECUO-48H	ECMP-60U		45,000	\$6,300
216759901	ECO-AIR	ECUO-60H	ECMP-60U		45,000	\$6,300
216759920	ECO-AIR	ECUO-60H	ECCC-60U		37,800	\$5,292
216759921	ECO-AIR	ECUO-60H	ECCD-60U		36,000	\$5,040
211644113	ECO-AIR	MOD30-24HFN1-MU0W	MVC-23HWFN1-M		16,900	\$2,366
208130403	ECO-AIR	MOD30-24HFN1-MW	MVC-24HWFN1-M		19,200	\$2,688
209270320	ECO-AIR	MOD30-24HFN1-MW	MAC-24HWDN1-MN0		21,000	\$2,940
213081460	ECO-AIR	MOD30-24HFN1-MW	MVBE-24HWFN1-MM3E		20,000	\$2,800
208130404	ECO-AIR	MOD30U-30HFN1-MR0(X)	MVC-30HWFN1-M		21,000	\$2,940
209270321	ECO-AIR	MOD30U-30HFN1-MR0(X)	MAC-36HWFN1-M		22,600	\$3,164
213363366	ECO-AIR	MOE30U-45HFN1-M	MAC-60HWDN1-MN0		37,000	\$5,180
208130406	ECO-AIR	MOE30U-48HFN1-M-[X1]	MVC-48HWFN1-M		36,000	\$5,040
213081459	ECO-AIR	MOE30U-55HFN1-M	MVC-60HWFN1-M		42,000	\$5,880
208130405	ECO-AIR	MOE31U-36HFN1-M	MVC-36HWFN1-M		30,400	\$4,256
209270322	ECO-AIR	MOE31U-36HFN1-M	MAC-36HWFN1-M		33,000	\$4,620
213386480	ECO-AIR	MOE31U-36HFN1-M	MVB-36B23T4N1		27,400	\$3,836
211644112	ECO-AIR	MOX430-17HFN1-MT0W	MVC-18HWFN1-MW(GA)		15,400	\$2,156
208130402	ECO-AIR	MOX430U-18HFN1-M	MVC-18HWFN1-M		13,500	\$1,890
213307908	ECO-AIR	MOX430U-18HFN1-M	MVBE-18HWFN1-MM3E		15,800	\$2,212
213386481	ECO-AIR	MOX630-36HFN1-M3X	MVB-36B23T4N1		27,000	\$3,780
213386482	ECO-AIR	MOX630-36HFN1-M3X	MAC-36HWDN1-MN0		27,000	\$3,780
213485863	ECO-AIR	MOX630-36HFN1-M3X	MVC-36HWFN1-M		31,800	\$4,452
214442632	ECO-AIR	MOX630-36HFN1-M3X	MAC-36HWFN1-M		27,000	\$3,780
211594473	ECOER	ESCA16H-36	EAHAEC-36		30,400	\$4,256
216980950	ECOER	ESCA17H-60ABA	EAHDEC-60AB*		45,000	\$6,300

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216980949	ECOER	ESCA17H-36ABA	EAHDEC-36AB*		31,800	\$4,452
216707853	ECOER	ESCA17H-60ABA	EAHDEC-60ABA*		45,000	\$6,300
216707852	ECOER	ESCA17H-36ABA	EAHDEC-36ABA*		31,800	\$4,452
216706027	ECOER	ESCA16H-24BBA	EAHDEC-24ABA		20,000	\$2,800
216706025	ECOER	ESCA17H-48ABA	EAHDEC-48ABA		37,000	\$5,180
216706032	ECOER	ESCA17H-60ABA	ESCT4860CBA		37,800	\$5,292
216706031	ECOER	ESCA17H-36ABA	ESCT3036BBA		29,200	\$4,088
216706029	ECOER	ESCA16H-48BBA	EAHDEC-48ABA		32,400	\$4,536
216706033	ECOER	ESCA16H-36BBA	ESCT3036BBA		24,200	\$3,388
216706023	ECOER	ESCA17H-24ABA	EAHDEC-24ABA		20,000	\$2,800
216620321	ECOER	EODA19H-4860AB*	EAHDEN-36AB*		35,200	\$4,928
213880755	ECOER	ESCA16H-60	SNC48DPT*		37,000	\$5,180
213617765	ECOER	ESCA16H-60	SNC48DPT		37,000	\$5,180
213386491	ECOER	ESCA16H-60	SNC60CPT		37,000	\$5,180
211594474	ECOER	ESCA16H-60	EAHAEC-60		42,000	\$5,880
216623476	ELIOS	ESHMA60R2AN1	GCHMA60RDAS1		36,000	\$5,040
216046615	ELIOS	ESHMA18C2AN1	EWHMA18C2AS1		14,400	\$2,016
216046614	ELIOS	ESHMA12C2AN1	EWHMA12C2AS1		10,000	\$1,400
217114378	ELIOS	ESHEA36R2AN1	GPHLA36R2AS1		24,600	\$3,444
207742430	ELIOS	DEA12HOS28230E8	DEA12HIW25230E8		10,000	\$1,400
207742431	ELIOS	DEA18HOS28230E8	DEA18HIW25230E8		15,000	\$2,100
207742440	ELIOS	DEA12HOS28230E8	DUA12HICU230X5		9,900	\$1,386
207742458	ELIOS	DEA12HOS28230E8	DUA12HIFU230E5		9,600	\$1,344
207742454	ELIOS	DEA18HOS28230E8	DUA18HIDU230X5		15,000	\$2,100
206401446	ELIOS	DE18HOS25230E3A	DM18HIDU230X5		15,000	\$2,100
213081442	ELIOS	DEA24HOS20230E7	FEA24HIAHUU230X7		19,200	\$2,688
213081441	ELIOS	DEA18HOS20230E7	FEA18HIAHUU230X7		13,500	\$1,890
207742442	ELIOS	DEA24HOS28230E8	DUA24HICU230X5		21,000	\$2,940
207742464	ELIOS	DEA27HOM25230X3	Heat pump with ducts		27,000	\$3,780
208136314	ELIOS	DEA55HOM25230X3	Heat pump with ducts		35,200	\$4,928
207742465	ELIOS	DEA27HOM25230X3	Combination heat pumps with or without ducts		26,800	\$3,752
208136315	ELIOS	DEA55HOM25230X3	Combination heat pumps with or without ducts		34,800	\$4,872
208136313	ELIOS	DEA55HOM25230X3	Heat pump without ducts		34,400	\$4,816
207742469	ELIOS	DEA48HOM25230X3	Heat pump without ducts		36,000	\$5,040
207742463	ELIOS	DEA27HOM25230X3	Heat pump without ducts		26,600	\$3,724
207742460	ELIOS	DEA18HOM25230X3	Heat pump without ducts		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213081443	ELIOS	DEA30HOS20230E7	FEA30HIAHUU230X7		21,000	\$2,940
213081444	ELIOS	DEA36HOS20230E7	FEA36HIAHUU230X7		30,400	\$4,256
214844432	ELIOS	DEA12HOS28230E8	DUB12HIFU230X5A		10,200	\$1,428
207742453	ELIOS	DEA12HOS28230E8	DUA12HIDU230X5		10,600	\$1,484
207742466	ELIOS	DEA36HOM25230X3	Heat pump without ducts		33,000	\$4,620
207742470	ELIOS	DEA48HOM25230X3	Heat pump with ducts		36,000	\$5,040
206401449	ELIOS	DE24HOS25230E3A	DM24HIDU230X5		21,000	\$2,940
207742455	ELIOS	DEA24HOS28230E8	DUA24HIDU230X5		21,000	\$2,940
207742461	ELIOS	DEA18HOM25230X3	Heat pump with ducts		16,000	\$2,240
207742462	ELIOS	DEA18HOM25230X3	Combination heat pumps with or without ducts		15,500	\$2,170
207742471	ELIOS	DEA48HOM25230X3	Combination heat pumps with or without ducts		36,000	\$5,040
207742468	ELIOS	DEA36HOM25230X3	Combination heat pumps with or without ducts		34,000	\$4,760
213081449	ELIOS	DEA24HOS20230E7	CUB24HAC20BWT7A		21,000	\$2,940
216718862	ELIOS	ESHMA48R2AN1	GCHMA48RCAS1		34,400	\$4,816
216760016	ELIOS	ESHMB36R2AN1	GUHMA36RCAS1		29,200	\$4,088
216760015	ELIOS	ESHMB36R2AN1	GUHMA36RBAS1		29,200	\$4,088
216046597	ELIOS	ESHMA24R2AN1	EAHMA24R4AS1		20,000	\$2,800
216618899	ELIOS	ESHMB36R2AN1	EAHMA36R4AS1		31,800	\$4,452
216623472	ELIOS	ESHMA18R2AN1	GCHMA24RBAS1		15,200	\$2,128
216623475	ELIOS	ESHMA30R2AN1	GCHMA36RCAS1		25,000	\$3,500
216623474	ELIOS	ESHMA30R2AN1	GCHMA36RBAS1		25,000	\$3,500
216623473	ELIOS	ESHMA24R2AN1	GCHMA24RBAS1		19,700	\$2,758
216623482	ELIOS	ESHMA30R2AN1	GUHMA36RCAS1		25,000	\$3,500
216623481	ELIOS	ESHMA30R2AN1	GUHMA36RBAS1		25,000	\$3,500
216623478	ELIOS	ESHEA24R2AN1	GUHMA24RBAS1		19,700	\$2,758
216623480	ELIOS	ESHMA24R2AN1	GUHMA24RBAS1		19,700	\$2,758
216623479	ELIOS	ESHMA18R2AN1	GUHMA24RBAS1		15,200	\$2,128
216623811	ELIOS	ESHMB36R2AN1	GCHMA36RBAS1		29,200	\$4,088
216623812	ELIOS	ESHMB36R2AN1	GCHMA36RCAS1		29,200	\$4,088
216684117	ELIOS	ESHEA36R2AN1	GUHMA36RCAS1		24,200	\$3,388
216684116	ELIOS	ESHEA36R2AN1	GUHMA36RBAS1		24,200	\$3,388
216046616	ELIOS	ESHMA24C2AN1	EWHMA24C2AS1		21,600	\$3,024
216046617	ELIOS	ESHMA33C2AN1	EWHMA33C2AS1		29,600	\$4,144
216046639	ELIOS	EXHSA2742AV1	Heat pump without ducts		18,000	\$2,520
216046640	ELIOS	EXHSA2742AV1	Heat pump with ducts		18,400	\$2,576

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216046641	ELIOS	EXHSA2742AV1	Combination heat pumps with or without ducts		18,200	\$2,548
216046642	ELIOS	EXHSA3652AV1	Heat pump without ducts		27,000	\$3,780
216046643	ELIOS	EXHSA3652AV1	Heat pump with ducts		26,400	\$3,696
216046644	ELIOS	EXHSA3652AV1	Combination heat pumps with or without ducts		26,600	\$3,724
216046645	ELIOS	EXHSA4862AV1	Heat pump without ducts		34,000	\$4,760
216046646	ELIOS	EXHSA4862AV1	Heat pump with ducts		37,000	\$5,180
216046647	ELIOS	EXHSA4862AV1	Combination heat pumps with or without ducts		35,400	\$4,956
216046600	ELIOS	ESHMA48R2AN1	EAHMA48R4AS1		37,000	\$5,180
216046598	ELIOS	ESHMA30R2AN1	EAHMA30R4AS1		23,800	\$3,332
216046601	ELIOS	ESHMA60R2AN1	EAHMA60R4AS1		45,000	\$6,300
216505496	ELIOS	ESHEA36R2AN1	GGHLA36R2AS1		24,800	\$3,472
213081451	ELIOS	DEA36HOS20230E7	CUB36HAC20CWT7A		33,000	\$4,620
213081453	ELIOS	DEA48HOS20230E7	CUB48HAC20CWT7A		32,000	\$4,480
214215183	ELIOS	DEA30HOS20230E7	CUB36HAC20BWT7A		19,600	\$2,744
207742444	ELIOS	DEA48HOS28230E8	DUA48HICU230X5		35,000	\$4,900
207742457	ELIOS	DEA48HOS28230E8	DUA48HIDU230X5		39,500	\$5,530
207742443	ELIOS	DEA36HOS28230E8	DUA36HICU230X5		33,000	\$4,620
204005788	ELIOS	DE27HOM25230X3	Heat pump without ducts		18,000	\$2,520
208119831	ELIOS	DEA24HOS28230E8	DE24HIW23230E3		19,400	\$2,716
206401448	ELIOS	DE24HOS25230E3A	DE24HIW23230E3		19,400	\$2,716
213081452	ELIOS	DEA36HOS20230E7	CUB36HAC20BWT7A		27,400	\$3,836
207645902	ELIOS	DE36HOS25230E3	DM36HICU230X5		25,400	\$3,556
205300176	ELIOS	DE24HOS25230E3	DM24HIDU230X5		17,200	\$2,408
204005781	ELIOS	DE24HOS25230E3	DE24HIDU230X5		17,200	\$2,408
206377757	ELIOS	DE12HOS42230E4	DE12HIW42230E4		6,800	\$952
206401445	ELIOS	DE18HOS25230E3A	DE18HIW23230E3		10,900	\$1,526
207742467	ELIOS	DEA36HOM25230X3	Heat pump with ducts		23,000	\$3,220
206853242	ELIOS	DE36HOS25230E3	DM36HIDU230X5		28,000	\$3,920
206853243	ELIOS	DE48HOS25230E3	DM48HIDU230X5		33,000	\$4,620
207645903	ELIOS	DE48HOS25230E3	DM48HICU230X5		35,000	\$4,900
213081445	ELIOS	DEA48HOS20230E7	FEA48HIAHUU230X7		36,000	\$5,040
213081450	ELIOS	DEA30HOS20230E7	CUB36HAC20CWT7A		22,600	\$3,164
213081446	ELIOS	DEA60HOS20230E7	FEA60HIAHUU230X7		42,000	\$5,880
213081454	ELIOS	DEA60HOS20230E7	CUB60HAC20DWT7A		37,000	\$5,180

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215444948	EMI	EMXMZ436DA	Combination heat pumps with or without ducts		31,400	\$4,396
215444946	EMI	EMXMZ436DA	Heat pump without ducts		30,000	\$4,200
208121925	EMI	MHSZ112DA	MHWAL12DA		10,000	\$1,400
208121926	EMI	MHSZ118DA	MHWAL18DA		15,000	\$2,100
208121927	EMI	MHSZ124DA	MHWAL24DA		21,200	\$2,968
208121929	EMI	MHSZ112DA	MHCAS12DA		9,900	\$1,386
208121936	EMI	MHMZ327DA	Heat pump with ducts		27,000	\$3,780
208121937	EMI	MHMZ327DA	Combination heat pumps with or without ducts		26,800	\$3,752
208121931	EMI	MHSZ124DA	MHCAS24DA		21,000	\$2,940
208121941	EMI	MHMZ548DA	Heat pump without ducts		36,000	\$5,040
208121932	EMI	MHMZ218DA	Heat pump without ducts		15,000	\$2,100
208121935	EMI	MHMZ327DA	Heat pump without ducts		26,600	\$3,724
208121933	EMI	MHMZ218DA	Heat pump with ducts		16,000	\$2,240
208121938	EMI	MHMZ436DA	Heat pump without ducts		33,000	\$4,620
208121942	EMI	MHMZ548DA	Heat pump with ducts		36,000	\$5,040
208121940	EMI	MHMZ436DA	Combination heat pumps with or without ducts		34,000	\$4,760
208121934	EMI	MHMZ218DA	Combination heat pumps with or without ducts		15,500	\$2,170
208121943	EMI	MHMZ548DA	Combination heat pumps with or without ducts		36,000	\$5,040
216372807	EMI	MHSD118DACFC	MHAH118DACFC		13,500	\$1,890
216372808	EMI	MHSD124DACFC	MHAH124DACFC		19,200	\$2,688
216372809	EMI	MHSD130DACFC	MHAH130DACFC		21,000	\$2,940
216372810	EMI	MHSD136DACFC	MHAH136DACFC		30,400	\$4,256
215444938	EMI	EMXSZ118DA	EMXWAL18DA		16,600	\$2,324
215444937	EMI	EMXSZ112DA	EMXWAL12DA		9,800	\$1,372
216372812	EMI	MHSD160DACFC	MHAH160DACFC		42,000	\$5,880
216372811	EMI	MHSD148DACFC	MHAH148DACFC		36,000	\$5,040
215444951	EMI	EMXMZ548DA	Combination heat pumps with or without ducts		44,000	\$6,160
215444950	EMI	EMXMZ548DA	Heat pump with ducts		44,500	\$6,230
215444949	EMI	EMXMZ548DA	Heat pump without ducts		44,000	\$6,160
215444947	EMI	EMXMZ436DA	Heat pump with ducts		33,000	\$4,620
215444945	EMI	EMXMZ327DA	Combination heat pumps with or without ducts		24,000	\$3,360
215444944	EMI	EMXMZ327DA	Heat pump with ducts		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215444943	EMI	EMXMZ327DA	Heat pump without ducts		25,000	\$3,500
215444942	EMI	EMXMZ218DA	Combination heat pumps with or without ducts		17,300	\$2,422
215444941	EMI	EMXMZ218DA	Heat pump with ducts		17,000	\$2,380
215444940	EMI	EMXMZ218DA	Heat pump without ducts		17,600	\$2,464
215444939	EMI	EMXSZ124DA	EMXWAL24DA		21,000	\$2,940
203514062	EMI	DHMZ327DA	Heat pump without ducts		18,000	\$2,520
208121939	EMI	MHMZ436DA	Heat pump with ducts		23,000	\$3,220
206720377	FORESTAIR	FGH-18ES/E-38-O	FGH-18ES/E-38-I		14,200	\$1,988
208939391	FORESTAIR	FAD36W/A-D(U)	FAD24AH2/A-D(U)		16,300	\$2,282
208939395	FORESTAIR	FAD60W/A-D(U)	FAD60AH2/A-D(U)		23,000	\$3,220
208939393	FORESTAIR	FAD60W/A-D(U)	FAD48AH2/A-D(U)		21,000	\$2,940
208939392	FORESTAIR	FAD36W/A-D(U)	FAD36AH2/A-D(U)		24,000	\$3,360
206900433	FRANKLIN	MSH123E23MCAA	MST123E20ACAA		9,900	\$1,386
206900429	FRANKLIN	MSH183E23MCAA	MST183E21ADAA		15,000	\$2,100
214383439	FRANKLIN	MST183F25MHAA	Heat pump without ducts		15,000	\$2,100
214383448	FRANKLIN	MST483F25MHAA	Heat pump without ducts		36,000	\$5,040
214383436	FRANKLIN	MSH243F25MCAA	MSH243F25AXAA		21,200	\$2,968
214383435	FRANKLIN	MSH183F25MCAA	MSH183F25AXAA		15,000	\$2,100
214383434	FRANKLIN	MSH123F25MCAA	MSH123F25AXAA		10,000	\$1,400
206764068	FRANKLIN	MST183E23MHAA	Heat pump without ducts		15,000	\$2,100
214383441	FRANKLIN	MST183F25MHAA	Combination heat pumps with or without ducts		15,500	\$2,170
214383449	FRANKLIN	MST483F25MHAA	Heat pump with ducts		36,000	\$5,040
214383450	FRANKLIN	MST483F25MHAA	Combination heat pumps with or without ducts		36,000	\$5,040
206764069	FRANKLIN	MST183E23MHAA	Heat pump with ducts		16,000	\$2,240
206900430	FRANKLIN	MSH243E23MCAA	MST243E21ADAA		21,000	\$2,940
214383440	FRANKLIN	MST183F25MHAA	Heat pump with ducts		16,000	\$2,240
206900428	FRANKLIN	MSH123E23MCAA	MST123E21ADAA		10,600	\$1,484
214594909	FRANKLIN	MSH243F25MCAA	MST243E21ADAA		21,000	\$2,940
214594908	FRANKLIN	MSH183F25MCAA	MST183E21ADAA		15,000	\$2,100
214594907	FRANKLIN	MSH123F25MCAA	MST123E21ADAA		10,600	\$1,484
214594905	FRANKLIN	MSH123F25MCAA	MST123E20ACAA		9,900	\$1,386
214595281	FRANKLIN	MSH123E23MCAA	MSH123F25AXAA		10,000	\$1,400
206764065	FRANKLIN	MSH243E23MCAA	MSH243E23AXAA		19,400	\$2,716
214383442	FRANKLIN	MST273F25MHAA	Heat pump without ducts		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214383444	FRANKLIN	MST273F25MHAA	Combination heat pumps with or without ducts		23,000	\$3,220
214383445	FRANKLIN	MST363F25MHAA	Heat pump without ducts		27,400	\$3,836
214383446	FRANKLIN	MST363F25MHAA	Heat pump with ducts		30,000	\$4,200
214383447	FRANKLIN	MST363F25MHAA	Combination heat pumps with or without ducts		28,600	\$4,004
206764064	FRANKLIN	MSH183E23MCAA	MSH183E23AXAA		10,900	\$1,526
206764070	FRANKLIN	MST183E23MHAA	Combination heat pumps with or without ducts		11,500	\$1,610
206764071	FRANKLIN	MST303E23MHAA	Heat pump without ducts		18,000	\$2,520
210609970	FRANKLIN	GSZV903610A*	AMVE36CP1400A*		21,600	\$3,024
210609971	FRANKLIN	GSZV903610A*	AMVE48DP1400A*		21,600	\$3,024
210692904	FRANKLIN	GSZV903610A*	CA*F3137*6A*+MBVC1201**-1A*+TXV		21,600	\$3,024
210692907	FRANKLIN	GSZV903610A*	CA*F3137*6A*+TXV	G*VC960403BNB*	21,600	\$3,024
210692908	FRANKLIN	GSZV903610A*	CA*F3137*6A*+TXV	G*VS960603BUA*	21,600	\$3,024
210692909	FRANKLIN	GSZV903610A*	CA*F3137*6A*+TXV	G*VC960603BNB*	21,600	\$3,024
210692910	FRANKLIN	GSZV903610A*	CA*F3137*6A*+TXV	G*VC960803BNB*	21,600	\$3,024
210692911	FRANKLIN	GSZV903610A*	CA*F3137*6A*+TXV	G*VM970603BNB*	21,600	\$3,024
210692912	FRANKLIN	GSZV903610A*	CA*F3137*6A*+TXV	G*VM970803BNB*	21,600	\$3,024
210692913	FRANKLIN	GSZV903610A*	CA*F3743*6D*+MBVC1201**-1A*+TXV		21,600	\$3,024
210607413	FRANKLIN	GSZV903610A*	CA*F3743*6D*+MBVC1601**-1A*+TX		21,600	\$3,024
210692920	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC960403BNB*	21,600	\$3,024
210692921	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VS960603BUA*	21,600	\$3,024
210692922	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC960603BNB*	21,600	\$3,024
210692923	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC960803BNB*	21,600	\$3,024
210692924	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC960804CNB*	21,600	\$3,024
210692925	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VS960805CUA*	21,600	\$3,024
210692926	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC961005CNB*	21,600	\$3,024
210692927	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC961205DNB*	21,600	\$3,024
210692928	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM970603BNB*	21,600	\$3,024
210692929	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM970803BNB*	21,600	\$3,024
210692930	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM970804CNB*	21,600	\$3,024
210692931	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM971005CNB*	21,600	\$3,024
210692932	FRANKLIN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM971205DNB*	21,600	\$3,024
210692933	FRANKLIN	GSZV903610A*	CHPF3642C6C*+MBVC1201*-1A*+TXV		21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210692934	FRANKLIN	GSZV903610A*	CHPF3642C6C*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210692941	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC960403BNB*	21,600	\$3,024
210692942	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VS960603BUA*	21,600	\$3,024
210692943	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC960603BNB*	21,600	\$3,024
210692944	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC960803BNB*	21,600	\$3,024
210692945	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC960804CNB*	21,600	\$3,024
210692946	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VS960805CUA*	21,600	\$3,024
210692947	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC961005CNB*	21,600	\$3,024
210692948	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VM970603BNB*	21,600	\$3,024
210692949	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VM970803BNB*	21,600	\$3,024
210692950	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VM970804CNB*	21,600	\$3,024
210692951	FRANKLIN	GSZV903610A*	CHPF3642C6C*+TXV	G*VM971005CNB*	21,600	\$3,024
210692952	FRANKLIN	GSZV903610A*	CHPF3743C6B*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210692953	FRANKLIN	GSZV903610A*	CHPF3743C6B*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210692960	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC960403BNB*	21,600	\$3,024
210692961	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VS960603BUA*	21,600	\$3,024
210692962	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC960603BNB*	21,600	\$3,024
210692963	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC960803BNB*	21,600	\$3,024
210692964	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC960804CNB*	21,600	\$3,024
210692965	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VS960805CUA*	21,600	\$3,024
210692966	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC961005CNB*	21,600	\$3,024
210692967	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VM970603BNB*	21,600	\$3,024
210692968	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VM970803BNB*	21,600	\$3,024
210692969	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VM970804CNB*	21,600	\$3,024
210692970	FRANKLIN	GSZV903610A*	CHPF3743C6B*+TXV	G*VM971005CNB*	21,600	\$3,024
210692971	FRANKLIN	GSZV903610A*	CSCF3642N6D*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210692972	FRANKLIN	GSZV903610A*	CSCF3642N6D*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210692979	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC960403BNB*	21,600	\$3,024
210692980	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VS960603BUA*	21,600	\$3,024
210692981	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC960603BNB*	21,600	\$3,024
210692982	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC960803BNB*	21,600	\$3,024
210692983	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC960804CNB*	21,600	\$3,024
210692984	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VS960805CUA*	21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210692985	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC961005CNB*	21,600	\$3,024
210692986	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC961205DNB*	21,600	\$3,024
210692987	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM970603BNB*	21,600	\$3,024
210692988	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM970803BNB*	21,600	\$3,024
210692989	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM970804CNB*	21,600	\$3,024
210692990	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM971005CNB*	21,600	\$3,024
210692991	FRANKLIN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM971205DNB*	21,600	\$3,024
210609972	FRANKLIN	ASZV903610A*	AMVE36CP1400A*		21,600	\$3,024
210609973	FRANKLIN	ASZV903610A*	AMVE48DP1400A*		21,600	\$3,024
210693108	FRANKLIN	ASZV903610A*	CA*F3137*6A*+MBVC1201** 1A*+TXV		21,600	\$3,024
210693111	FRANKLIN	ASZV903610A*	CA*F3137*6A*+TXV	G*VC960403BNB*	21,600	\$3,024
210693112	FRANKLIN	ASZV903610A*	CA*F3137*6A*+TXV	G*VS960603BUA*	21,600	\$3,024
210693113	FRANKLIN	ASZV903610A*	CA*F3137*6A*+TXV	G*VC960603BNB*	21,600	\$3,024
210693114	FRANKLIN	ASZV903610A*	CA*F3137*6A*+TXV	G*VC960803BNB*	21,600	\$3,024
210693115	FRANKLIN	ASZV903610A*	CA*F3137*6A*+TXV	G*VM970603BNB*	21,600	\$3,024
210693116	FRANKLIN	ASZV903610A*	CA*F3137*6A*+TXV	G*VM970803BNB*	21,600	\$3,024
210693117	FRANKLIN	ASZV903610A*	CA*F3743*6D*+MBVC1201** 1A*+TXV		21,600	\$3,024
210607414	FRANKLIN	ASZV903610A*	CA*F3743*6D*+MBVC1601** 1A*+TX		21,600	\$3,024
210693124	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VC960403BNB*	21,600	\$3,024
210693125	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VS960603BUA*	21,600	\$3,024
210693126	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VC960603BNB*	21,600	\$3,024
210693127	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VC960803BNB*	21,600	\$3,024
210693128	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VC960804CNB*	21,600	\$3,024
210693129	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VS960805CUA*	21,600	\$3,024
210693130	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VC961005CNB*	21,600	\$3,024
210693131	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VC961205DNB*	21,600	\$3,024
210693132	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VM970603BNB*	21,600	\$3,024
210693133	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VM970803BNB*	21,600	\$3,024
210693134	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VM970804CNB*	21,600	\$3,024
210693135	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VM971005CNB*	21,600	\$3,024
210693136	FRANKLIN	ASZV903610A*	CA*F3743*6D*+TXV	G*VM971205DNB*	21,600	\$3,024
210693137	FRANKLIN	ASZV903610A*	CHPF3642C6C*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210693138	FRANKLIN	ASZV903610A*	CHPF3642C6C*+MBVC1601* *-1A*+TXV		21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210693145	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VC960403BNB*	21,600	\$3,024
210693146	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VS960603BUA*	21,600	\$3,024
210693147	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VC960603BNB*	21,600	\$3,024
210693148	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VC960803BNB*	21,600	\$3,024
210693149	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VC960804CNB*	21,600	\$3,024
210693150	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VS960805CUA*	21,600	\$3,024
210693151	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VC961005CNB*	21,600	\$3,024
210693152	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VM970603BNB*	21,600	\$3,024
210693153	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VM970803BNB*	21,600	\$3,024
210693154	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VM970804CNB*	21,600	\$3,024
210693155	FRANKLIN	ASZV903610A*	CHPF3642C6C*+TXV	G*VM971005CNB*	21,600	\$3,024
210693156	FRANKLIN	ASZV903610A*	CHPF3743C6B*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210693157	FRANKLIN	ASZV903610A*	CHPF3743C6B*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210693164	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VC960403BNB*	21,600	\$3,024
210693165	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VS960603BUA*	21,600	\$3,024
210693166	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VC960603BNB*	21,600	\$3,024
210693167	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VC960803BNB*	21,600	\$3,024
210693168	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VC960804CNB*	21,600	\$3,024
210693169	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VS960805CUA*	21,600	\$3,024
210693170	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VC961005CNB*	21,600	\$3,024
210693171	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VM970603BNB*	21,600	\$3,024
210693172	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VM970803BNB*	21,600	\$3,024
210693173	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VM970804CNB*	21,600	\$3,024
210693174	FRANKLIN	ASZV903610A*	CHPF3743C6B*+TXV	G*VM971005CNB*	21,600	\$3,024
210693175	FRANKLIN	ASZV903610A*	CSCF3642N6D*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210693176	FRANKLIN	ASZV903610A*	CSCF3642N6D*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210693183	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VC960403BNB*	21,600	\$3,024
210693184	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VS960603BUA*	21,600	\$3,024
210693185	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VC960603BNB*	21,600	\$3,024
210693186	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VC960803BNB*	21,600	\$3,024
210693187	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VC960804CNB*	21,600	\$3,024
210693188	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VS960805CUA*	21,600	\$3,024
210693189	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VC961005CNB*	21,600	\$3,024
210693190	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VC961205DNB*	21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210693191	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VM970603BNB*	21,600	\$3,024
210693192	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VM970803BNB*	21,600	\$3,024
210693193	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VM970804CNB*	21,600	\$3,024
210693194	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VM971005CNB*	21,600	\$3,024
210693195	FRANKLIN	ASZV903610A*	CSCF3642N6D*+TXV	G*VM971205DNB*	21,600	\$3,024
214066916	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR921V0855A21M4	31,400	\$4,396
214066913	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR921V0703A17M4	31,400	\$4,396
214066912	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR801V0504A17UHN	31,400	\$4,396
214066900	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR951V0703A17M4	31,400	\$4,396
214066886	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR962V0855A21M4	31,400	\$4,396
214066879	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR951V0403A17M4	31,400	\$4,396
214066877	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR921V0603A17M4	31,600	\$4,424
214066873	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR97MV0703A17DH	31,400	\$4,396
214066866	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR951V0603A17M4	31,600	\$4,424
214066855	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR962V1005A21M4	31,400	\$4,396
214066837	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR97MV0603A17DH	31,400	\$4,396
214066833	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR98MV0703A17UP	31,400	\$4,396
214066795	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR801V0704A17UHU	31,400	\$4,396
214066777	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR98MV0855A21UP	31,200	\$4,368
214066771	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR97MV0855A21DH	31,200	\$4,368
214066764	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR801V0754A17DZ	31,400	\$4,396
214066757	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR951V1005A21M4	31,400	\$4,396
214066755	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR802V0504A17UHN	31,400	\$4,396
214066733	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR951V0403A17UHU	31,600	\$4,424
214066731	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR801V0504A17UHS	31,400	\$4,396
214066677	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR802V0754A17DZ	31,400	\$4,396
214066663	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR962V0403A17M4	31,400	\$4,396
214066621	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR98MV0603A17UP	31,600	\$4,424
214066616	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR962V0603A17M4	31,600	\$4,424
214066596	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR951V0603A17UHU	31,600	\$4,424
214066589	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR951V0855A21M4	31,400	\$4,396
214066557	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR921V0403A17M4	31,400	\$4,396
214066550	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR921V1005A21M4	31,400	\$4,396
214066540	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR802V0504A17UHS	31,400	\$4,396
214066538	FRIEDRICH	RD17AZ36AJ3N	TCFZ3621MTANM	FR801V0504A17UHU	31,600	\$4,424
214075548	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR98MV0603A17UP	19,000	\$2,660
214075534	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR802V0754A17DZ	18,900	\$2,646
214075528	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR962V0403A17M4	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214075524	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR921V0403A17M4	19,000	\$2,660
214075523	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR802V1004A17UH	18,900	\$2,646
214075510	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR802V0754A17UHN	18,900	\$2,646
214075505	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR801V0504A17UHU	19,000	\$2,660
214075501	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR801V0503A14UH	19,000	\$2,660
214075500	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR962V0703A17M4	19,000	\$2,660
214075498	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR802V0504A17UHN	19,000	\$2,660
214075497	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR951V0603A17M4	19,000	\$2,660
214075496	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR801V0504A17UHN	19,000	\$2,660
214075493	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR97MV0603A17DH	19,000	\$2,660
214075491	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR801V0754A17DZ	18,900	\$2,646
214075490	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR951V0603A17UHU	19,100	\$2,674
214075489	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR921V0703A17M4	19,000	\$2,660
214075484	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR98MV0703A17UP	19,000	\$2,660
214075481	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR802V0754A17UH	18,900	\$2,646
214075480	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR802V0503A14UH	19,000	\$2,660
214075478	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR951V0403A17M4	19,000	\$2,660
214075471	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR801V0503A14DZ	18,900	\$2,646
214075452	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR951V0403A17UHU	19,100	\$2,674
214075445	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR801V1004A17UH	18,800	\$2,632
214075443	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR802V0504A17UHS	19,000	\$2,660
214075439	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR97MV0703A17DH	19,000	\$2,660
214075421	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR801V0704A17UHU	19,000	\$2,660
214075407	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR802V0503A14DZ	18,900	\$2,646
214075587	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR962V0603A17M4	19,000	\$2,660
214075579	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR921V0603A17M4	19,000	\$2,660
214075572	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR801V0504A17UHS	19,000	\$2,660
214075571	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR951V0703A17M4	19,000	\$2,660
214075569	FRIEDRICH	RD17AZ24AJ3N	TCFZ2417MTANM	FR801V0754A17UH	18,900	\$2,646
214233329	FRIEDRICH	RD17AZ36AJ3N	FRH3VZ4821STACN		31,200	\$4,368
214097944	FRIEDRICH	RD17AZ48AJ3N	FRH3VZ6024STACN		43,000	\$6,020
214095453	FRIEDRICH	RD17AZ24AJ3N	FRH3VZ3617STACN		18,700	\$2,618
205123805	FRIEDRICH	FPHFR24A3A	FPHFC24A3B		19,600	\$2,744
205142789	FRIEDRICH	FRHSR12A3A-A	FRHSW12A3B		8,000	\$1,120
206319902	FRIEDRICH	VRP24R*****_*	VRP24R*****_*		13,000	\$1,820
206319900	FRIEDRICH	VRP24K*****_*	VRP24K*****_*		13,000	\$1,820
208127840	FRIGIDAIRE	GXH24-36MSK4DH	GMH24-36MSK4DH1		20,000	\$2,800
208127834	FRIGIDAIRE	GXH24-36MSK4DH	GMH24-36MSK4DH1		29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208127835	FRIGIDAIRE	GXH48-60MSK4DH	GMH48-**-MSK4DH1		39,500	\$5,530
208127836	FRIGIDAIRE	GXH48-60MSK4DH	GMH**-60MSK4DH1		44,000	\$6,160
8063924	FUJITSU	AOU18RLXFZH	Combination heat pumps with or without ducts		14,200	\$1,988
8063925	FUJITSU	AOU24RLXFZH	Combination heat pumps with or without ducts		15,400	\$2,156
8912450	FUJITSU	AOU36RLXFZH	Combination heat pumps with or without ducts		21,400	\$2,996
204740068	FUJITSU	AOUG12LZAS1	ASUG12LZAS		10,000	\$1,400
204740069	FUJITSU	AOUG12LZAH1	ASUG12LZAS		10,000	\$1,400
204740070	FUJITSU	AOUG15LZAS1	ASUG15LZAS		11,200	\$1,568
204740071	FUJITSU	AOUG15LZAH1	ASUG15LZAS		11,200	\$1,568
8912454	FUJITSU	AOU30RLXEH	ASU30RLE		18,900	\$2,646
6936997	FUJITSU	AOU15RLFF	AGU15RLF		11,600	\$1,624
6937311	FUJITSU	AOU15RLFFH	AGU15RLF		11,600	\$1,624
6937310	FUJITSU	AOU12RLFFH	AGU12RLF		10,600	\$1,484
206597213	FUJITSU	AOUG15LZAH1	ASUG15LZBS		11,200	\$1,568
206597212	FUJITSU	AOUG15LZAS1	ASUG15LZBS		11,200	\$1,568
207131734	FUJITSU	AOUH18LPAS1	ASUH18LPAS		11,200	\$1,568
206597210	FUJITSU	AOUG12LZAS1	ASUG12LZBS		10,000	\$1,400
206597211	FUJITSU	AOUG12LZAH1	ASUG12LZBS		10,000	\$1,400
207657377	FUJITSU	AOUH36LMAH1	AMUG36LMAS		25,600	\$3,584
215812201	FUJITSU	AOUH48KUAS1	AUUH48KUAS		36,000	\$5,040
215434557	FUJITSU	AOUH18KUAS1	ARUH18KUAS		14,400	\$2,016
215647924	FUJITSU	AOUH24KZAH1	ASUH24KZAS		15,900	\$2,226
215647921	FUJITSU	AOUH18KZAH1	ASUH18KZAS		13,600	\$1,904
216018257	FUJITSU	AOUH15KTAP1	ASUH15KTAS		10,800	\$1,512
216018256	FUJITSU	AOUH12KTAP1	ASUH12KTAS		9,600	\$1,344
215434558	FUJITSU	AOUH24KUAS1	ARUH24KUAS		17,800	\$2,492
214390708	FUJITSU	AOUH12KMAS1	ASUH12KMAS		8,700	\$1,218
215812203	FUJITSU	AOUH48KUAS1	ARUH48KUAS		36,000	\$5,040
215812202	FUJITSU	AOUH42KUAS1	ARUH42KUAS		32,000	\$4,480
215434559	FUJITSU	AOUH30KUAS1	ARUH30KUAS		21,200	\$2,968
215434560	FUJITSU	AOUH36KUAS1	ARUH36KUAS		25,400	\$3,556
215434546	FUJITSU	AOUH12KUAS1	ACUH12KUAS		10,700	\$1,498
215434550	FUJITSU	AOUH30KUAS1	ABUH30KUAS		21,200	\$2,968
215434552	FUJITSU	AOUH18KUAS1	AUUH18KUAS		14,400	\$2,016
215434547	FUJITSU	AOUH18KUAS1	ACUH18KUAS		14,400	\$2,016

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215812200	FUJITSU	AOUH42KUAS1	AUUH42KUAS		32,000	\$4,480
215434555	FUJITSU	AOUH36KUAS1	AUUH36KUAS		25,400	\$3,556
215434554	FUJITSU	AOUH30KUAS1	AUUH30KUAS		21,200	\$2,968
215434553	FUJITSU	AOUH24KUAS1	AUUH24KUAS		17,800	\$2,492
215434551	FUJITSU	AOUH36KUAS	ABUH36KUAS		25,400	\$3,556
215434548	FUJITSU	AOUH18KUAS1	ABUH18KUAS		14,400	\$2,016
215441047	FUJITSU	AOUH24KPAS1	ASUH24KPAS		14,800	\$2,072
215441046	FUJITSU	AOUH18KPAS1	ASUH18KPAS		11,300	\$1,582
215390440	FUJITSU	AOUH30KPAS1	ASUH30KPAS		19,600	\$2,744
215390441	FUJITSU	AOUH36KPAS1	ASUH36KPAS		22,400	\$3,136
215434549	FUJITSU	AOUH24KUAS1	ABUH24KUAS		17,800	\$2,492
215434556	FUJITSU	AOUH12KUAS1	ARUH12KUAS		10,700	\$1,498
215735285	FUJITSU	AOUH36KWAH4	Combination heat pumps with or without ducts		23,800	\$3,332
215735283	FUJITSU	AOUH36KWAH4	Heat pump with ducts		23,400	\$3,276
215735282	FUJITSU	AOUH36KWAH4	Heat pump without ducts		24,400	\$3,416
215447699	FUJITSU	AOUH24KWAH3	Combination heat pumps with or without ducts		16,200	\$2,268
215447694	FUJITSU	AOUH24KWAH3	Heat pump with ducts		16,200	\$2,268
215447693	FUJITSU	AOUH24KWAH3	Heat pump without ducts		16,200	\$2,268
215447698	FUJITSU	AOUH18KWAH2	Combination heat pumps with or without ducts		14,800	\$2,072
215447692	FUJITSU	AOUH18KWAH2	Heat pump with ducts		14,800	\$2,072
215447691	FUJITSU	AOUH18KWAH2	Heat pump without ducts		14,800	\$2,072
214888804	FUJITSU	AOUH15KZAH1	ASUH15KZAS		11,400	\$1,596
214888802	FUJITSU	AOUH12KZAH1	ASUH12KZAS		10,000	\$1,400
215735281	FUJITSU	AOUH45KWAS5	Heat pump with ducts		30,600	\$4,284
215735284	FUJITSU	AOUH45KWAS5	Combination heat pumps with or without ducts		30,800	\$4,312
215735280	FUJITSU	AOUH45KWAS5	Heat pump without ducts		31,000	\$4,340
215447686	FUJITSU	AOUH18KWAS2	Heat pump with ducts		15,100	\$2,114
215447685	FUJITSU	AOUH18KWAS2	Heat pump without ducts		14,300	\$2,002
206347276	FUJITSU	AOU36RLAVM4	Heat pump with ducts		28,200	\$3,948
206347272	FUJITSU	AOU60RLAVM4	Heat pump with ducts		41,500	\$5,810
206347303	FUJITSU	AOU36RLAVS4	Combination heat pumps with or without ducts		26,200	\$3,668
206347301	FUJITSU	AOU36RLAVM4	Combination heat pumps with or without ducts		27,000	\$3,780
206347275	FUJITSU	AOU48RLAVM4	Heat pump without ducts		33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206347273	FUJITSU	AOU60RLAVM4	Heat pump without ducts		41,500	\$5,810
206347299	FUJITSU	AOU60RLAVM4	Combination heat pumps with or without ducts		43,500	\$6,090
206347300	FUJITSU	AOU48RLAVM4	Combination heat pumps with or without ducts		33,600	\$4,704
206347281	FUJITSU	AOU36RLAVS4	Heat pump without ducts		26,600	\$3,724
206347274	FUJITSU	AOU48RLAVM4	Heat pump with ducts		34,400	\$4,816
206347277	FUJITSU	AOU36RLAVM4	Heat pump without ducts		25,800	\$3,612
206347280	FUJITSU	AOU36RLAVS4	Heat pump with ducts		25,400	\$3,556
7937663	FUJITSU	AOU18RLB	ASU18RLB		11,500	\$1,610
8718495	FUJITSU	AOU18RLXFW1	ASU18RLF		14,600	\$2,044
5839957	FUJITSU	AOU18RLFC	ARU18RLF		13,600	\$1,904
7940753	FUJITSU	AOU24RLB	ASU24RLB		15,300	\$2,142
8693475	FUJITSU	AOU60RLAVM	Combination heat pumps with or without ducts		41,500	\$5,810
8693473	FUJITSU	AOU60RLAVM	Heat pump with ducts		41,500	\$5,810
9962522	FUJITSU	AOU36RLAVS	Heat pump with ducts		26,000	\$3,640
9962524	FUJITSU	AOU36RLAVS	Combination heat pumps with or without ducts		26,200	\$3,668
8693476	FUJITSU	AOU48RLAVM	Heat pump with ducts		34,000	\$4,760
8693481	FUJITSU	AOU36RLAVM	Combination heat pumps with or without ducts		26,000	\$3,640
8693479	FUJITSU	AOU36RLAVM	Heat pump with ducts		26,400	\$3,696
8693478	FUJITSU	AOU48RLAVM	Combination heat pumps with or without ducts		33,400	\$4,676
206579741	FUJITSU	AOUH12LUAS1	ADUH12LUAS1		10,500	\$1,470
8693474	FUJITSU	AOU60RLAVM	Heat pump without ducts		41,500	\$5,810
8693480	FUJITSU	AOU36RLAVM	Heat pump without ducts		25,800	\$3,612
9962523	FUJITSU	AOU36RLAVS	Heat pump without ducts		26,600	\$3,724
211078833	FUJITSU	AOUH36LUAS1	AUHH36LUAS		24,600	\$3,444
211078832	FUJITSU	AOUH30LUAS1	AUHH30LUAS		20,800	\$2,912
211078831	FUJITSU	AOUH24LUAS1	AUHH24LUAS		18,000	\$2,520
211078840	FUJITSU	AOUH36LUAS1	ARUH36LUAS		25,800	\$3,612
211078837	FUJITSU	AOUH30LUAS1	ARUH30LUAS		21,200	\$2,968
211078834	FUJITSU	AOUH24LUAS1	ARUH24LUAS		18,100	\$2,534
211078838	FUJITSU	AOUH30LUAS1	AMUG30LMAS		21,800	\$3,052
211078835	FUJITSU	AOUH24LUAS1	AMUG24LMAS		18,700	\$2,618
211078841	FUJITSU	AOUH36LUAS1	ABUH36LUAS		24,200	\$3,388
211078839	FUJITSU	AOUH30LUAS1	ABUH30LUAS		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211078836	FUJITSU	AOUH24LUAS1	ABUH24LUAS		17,500	\$2,450
202208444	FUJITSU	AOU24RGLX	AUU24RGLX		16,400	\$2,296
202534923	FUJITSU	AOU18RGLX	ARU18RGLX		12,700	\$1,778
8033586	FUJITSU	AOU24RLXFZH	Minibibloc		15,400	\$2,156
8033742	FUJITSU	AOU24RLXFZH	Minibibloc		15,400	\$2,156
8033585	FUJITSU	AOU18RLXFZH	Minibibloc		14,200	\$1,988
207657376	FUJITSU	AOUH30LUAH1	AMUG30LMAS		21,600	\$3,024
8908615	FUJITSU	AOU36RLXFZH	Minibibloc		21,400	\$2,996
8033584	FUJITSU	AOU18RLXFZH	Minibibloc		14,200	\$1,988
207334301	FUJITSU	AOUH12LUAS1	ARUH12LUAS		10,500	\$1,470
207657378	FUJITSU	AOUH48LMAH1	AMUG48LMAS		34,400	\$4,816
206913027	FUJITSU	AOUH18LMAS1	ASUH18LMAS		13,600	\$1,904
207590837	FUJITSU	AOUH36LPAS1	ASUH36LPAS		22,400	\$3,136
207590836	FUJITSU	AOUH30LPAS1	ASUH30LPAS		19,400	\$2,716
206579744	FUJITSU	AOUH12LUAS1	ACUH12LUAS1		10,700	\$1,498
206579745	FUJITSU	AOUH18LUAS1	ACUH18LUAS1		14,700	\$2,058
8908616	FUJITSU	AOU36RLXFZH	Minibibloc		21,400	\$2,996
202537550	FUJITSU	AOU42RGLX	ARU42RGLX		29,600	\$4,144
202537548	FUJITSU	AOU30RGLX	ARU30RGLX		19,600	\$2,744
8779045	FUJITSU	AOU18RLXFWH	ASU18RLF		14,600	\$2,044
6936996	FUJITSU	AOU12RLFF	AGU12RLF		10,600	\$1,484
202195637	FUJITSU	AOU36RGLX	AUU36RGLX		23,200	\$3,248
202195636	FUJITSU	AOU30RGLX	AUU30RGLX		20,200	\$2,828
202195106	FUJITSU	AOU18RGLX	AUU18RGLX		12,300	\$1,722
5751314	FUJITSU	AOU12RLFC	ARU12RLF		9,500	\$1,330
5751313	FUJITSU	AOU12RLFC	AUU12RLF		10,200	\$1,428
8703507	FUJITSU	AOU15RLS3	ASU15RLS3Y		11,200	\$1,568
8703506	FUJITSU	AOU12RLS3H	ASU12RLS3Y		9,600	\$1,344
8703508	FUJITSU	AOU15RLS3H	ASU15RLS3Y		11,200	\$1,568
202537546	FUJITSU	AOU12RLFC	ARU12RGLX		10,400	\$1,456
8703350	FUJITSU	AOU12RLS3	ASU12RLS3Y		9,600	\$1,344
5839958	FUJITSU	AOU18RLFC	AUU18RLF		13,600	\$1,904
9962520	FUJITSU	AOU48RLAVS	Heat pump without ducts		33,400	\$4,676
9962519	FUJITSU	AOU48RLAVS	Heat pump with ducts		34,600	\$4,844
9962521	FUJITSU	AOU48RLAVS	Combination heat pumps with or without ducts		34,000	\$4,760
8693477	FUJITSU	AOU48RLAVM	Heat pump without ducts		33,000	\$4,620
212924870	GE	AUH2436ZGDA*	C(A,C,D,E)24B34+TDR		14,000	\$1,960

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212396412	GE	NS22H24MA4-**A	NAM30V2TA4		14,900	\$2,086
210154187	GE APPLIANCES	ASH220NCDD**	Heat pump without ducts		14,000	\$1,960
210154196	GE APPLIANCES	ASH436NCDD**	Heat pump without ducts		23,600	\$3,304
210154192	GE APPLIANCES	ASH324NCDD**	Heat pump without ducts		17,000	\$2,380
217124728	GE APPLIANCES	1G24CB2BE**	GS24WB2BE**		14,400	\$2,016
217124727	GE APPLIANCES	1G18CB2BE**	GS18WB2BE**		12,000	\$1,680
216968353	GE APPLIANCES	1G3036AD2BE**	GS30WB2BE**		18,600	\$2,604
216968352	GE APPLIANCES	1G24AD2BE**	GS24WB2BE**		14,400	\$2,016
216968351	GE APPLIANCES	1G18AD2BE**	GS18WB2BE**		12,000	\$1,680
216968350	GE APPLIANCES	1G15AD2BE**	GS15WB2BE**		10,200	\$1,428
217036496	GE APPLIANCES	1G18ED2BE**	US18FB2BE**		14,400	\$2,016
217036495	GE APPLIANCES	1G12ED2BE**	US12FB2BE**		9,400	\$1,316
217036502	GE APPLIANCES	1G18ED2BE**	US18MB2BE**		17,000	\$2,380
217036499	GE APPLIANCES	1G18ED2BE**	US18CB2BE**		14,400	\$2,016
217036498	GE APPLIANCES	1G12ED2BE**	US12CB2BE**		9,600	\$1,344
207590958	GE APPLIANCES	AUH4860ZGDA*	TUY48ZPDA		31,400	\$4,396
207590956	GE APPLIANCES	AUH2436ZGDA*	TUY24ZPDA		16,000	\$2,240
206842133	GE APPLIANCES	ASH112URDSE*	ASYW12URDWD*		9,300	\$1,302
210154194	GE APPLIANCES	ASH324NCDD**	Heat pump with ducts		17,400	\$2,436
210154190	GE APPLIANCES	ASH220NCDD**	Heat pump with ducts		14,800	\$2,072
206753163	GE Appliances	AUH4860ZGDA*	UUY48ZGDAB*		31,400	\$4,396
206799410	GE Appliances	AUH2436ZGDA*	UUY24ZGDAB*		16,000	\$2,240
206799411	GE Appliances	AUH2436ZGDA*	UUY36ZGDAB*		24,000	\$3,360
206842134	GE APPLIANCES	ASH118URDSE*	ASYW18URDWD*		15,300	\$2,142
215876553	GE APPLIANCES	1G18ED2BE**	GS18WP2BE**		12,000	\$1,680
215876552	GE APPLIANCES	1G12ED2BE**	GS12WP2BE**		8,700	\$1,218
216759803	GE APPLIANCES	NS18H60HA5***	NCHC51CT5****+TDR	NF97U090V5C***	44,500	\$6,230
216759802	GE APPLIANCES	NS18H60HA5***	NCHC51CT5****+TDR	NF97U110V5C***	44,000	\$6,160
216759801	GE APPLIANCES	NS18H60HA5***	NCHC51CT5****+TDR	NF97X080V5C***	44,500	\$6,230
216759800	GE APPLIANCES	NS18H36HA5***	NCDC3036BT5****+TDR	NF97D070V4B***	29,000	\$4,060
216743614	GE APPLIANCES	NS18H60HA5***	NCDC60DT5****+TDR	NF97D110V5C***	44,000	\$6,160
216743613	GE APPLIANCES	NS18H60HA5***	NCDC60DT5****+TDR	NF97D090V5C***	44,000	\$6,160
216743612	GE APPLIANCES	NS18H60HA5***	NCHC60DT5****+TDR	NF97U135V5D***	44,000	\$6,160
216743611	GE APPLIANCES	NS18H60HA5***	NCUC60DT5****+TDR	NF97U135V5D***	44,000	\$6,160
216743610	GE APPLIANCES	NS18H60HA5***	NCUC60CT5****+TDR	NF97U090V5C***	44,000	\$6,160
216743609	GE APPLIANCES	NS18H60HA5***	NCUC60CT5****+TDR	NF97U110V5C***	43,500	\$6,090
216743608	GE APPLIANCES	NS18H60HA5***	NCUC60CT5****+TDR	NF97X080V5C***	44,000	\$6,160
216743607	GE APPLIANCES	NS18H60HA5***	NCDC48CT5****+TDR	NF97D110V5C***	39,500	\$5,530

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216743606	GE APPLIANCES	NS18H60HA5***	NCDC48CT5****+TDR	NF97D090V5C***	39,500	\$5,530
216743605	GE APPLIANCES	NS18H60HA5***	NCDC42BT5****+TDR	NF97D070V4B***	40,000	\$5,600
216743604	GE APPLIANCES	NS18H60HA5***	NCHC48CT5****+TDR	NF97U110V5C***	39,500	\$5,530
216743603	GE APPLIANCES	NS18H60HA5***	NCHC48CT5****+TDR	NF97X080V5C***	39,500	\$5,530
216743602	GE APPLIANCES	NS18H60HA5***	NCHC42CT5****+TDR	NF97U090V5C***	39,500	\$5,530
216743601	GE APPLIANCES	NS18H60HA5***	NCHC42CT5****+TDR	NF97U110V5C***	39,500	\$5,530
216743600	GE APPLIANCES	NS18H60HA5***	NCHC42CT5****+TDR	NF97X080V5C***	39,500	\$5,530
216743599	GE APPLIANCES	NS18H60HA5***	NCHC42CT5****+TDR	NF97X080V4C***	39,500	\$5,530
216743598	GE APPLIANCES	NS18H60HA5***	NCUC49CT5****+TDR	NF97U090V5C***	39,500	\$5,530
216743597	GE APPLIANCES	NS18H60HA5***	NCUC49CT5****+TDR	NF97U110V5C***	39,000	\$5,460
216743596	GE APPLIANCES	NS18H60HA5***	NCUC49CT5****+TDR	NF97X080V5C***	39,000	\$5,460
216743595	GE APPLIANCES	NS18H60HA5***	NCUC49CT5****+TDR	NF97X080V4C***	39,000	\$5,460
216743594	GE APPLIANCES	NS18H60HA5***	NCUC48CT5****+TDR	NF97U090V5C***	39,500	\$5,530
216743593	GE APPLIANCES	NS18H60HA5***	NCUC48CT5****+TDR	NF97U110V5C***	39,500	\$5,530
216743592	GE APPLIANCES	NS18H60HA5***	NCUC48CT5****+TDR	NF97X080V5C***	39,500	\$5,530
216743591	GE APPLIANCES	NS18H60HA5***	NCUC48CT5****+TDR	NF97X080V4C***	39,500	\$5,530
216743590	GE APPLIANCES	NS18H36HA5***	NCDC42BT5****+TDR	NF97D070V4B***	29,000	\$4,060
216743589	GE APPLIANCES	NS18H36HA5***	NCHC36CT5****+TDR	NF97X080V4C***	28,600	\$4,004
216743588	GE APPLIANCES	NS18H36HA5***	NCHC36CT5****+TDR	NF97U090V3C***	28,600	\$4,004
216743587	GE APPLIANCES	NS18H36HA5***	NCHC36BT5****+TDR	NF97U070V3B***	28,800	\$4,032
216743586	GE APPLIANCES	NS18H36HA5***	NCHC36BT5****+TDR	NF97U045V3B***	28,800	\$4,032
216743585	GE APPLIANCES	NS18H36HA5***	NCHC36BT5****+TDR	NF97X060V3B***	28,800	\$4,032
216743584	GE APPLIANCES	NS18H36HA5***	NCHC36BT5****+TDR	NF97X040V3B***	28,800	\$4,032
216743583	GE APPLIANCES	NS18H36HA5***	NCHC30BT5****+TDR	NF97U070V3B***	28,800	\$4,032
216743582	GE APPLIANCES	NS18H36HA5***	NCHC30BT5****+TDR	NF97U045V3B***	28,800	\$4,032
216743581	GE APPLIANCES	NS18H36HA5***	NCHC30BT5****+TDR	NF97X060V3B***	28,800	\$4,032
216743580	GE APPLIANCES	NS18H36HA5***	NCHC30BT5****+TDR	NF97X040V3B***	28,800	\$4,032
216743579	GE APPLIANCES	NS18H36HA5***	NCUC36BT5****+TDR	NF97U070V3B***	28,800	\$4,032
216743578	GE APPLIANCES	NS18H36HA5***	NCUC36BT5****+TDR	NF97U045V3B***	28,800	\$4,032
216743577	GE APPLIANCES	NS18H36HA5***	NCUC36BT5****+TDR	NF97X060V3B***	28,800	\$4,032
216743576	GE APPLIANCES	NS18H36HA5***	NCUC36BT5****+TDR	NF97X040V3B***	28,800	\$4,032
216743575	GE APPLIANCES	NS18H36HA5***	NCUC30BT5****+TDR	NF97U070V3B***	28,800	\$4,032
216743574	GE APPLIANCES	NS18H36HA5***	NCUC30BT5****+TDR	NF97U045V3B***	29,000	\$4,060
216743573	GE APPLIANCES	NS18H36HA5***	NCUC30BT5****+TDR	NF97X060V3B***	29,000	\$4,060
216743572	GE APPLIANCES	NS18H36HA5***	NCUC30BT5****+TDR	NF97X040V3B***	28,800	\$4,032
216743571	GE APPLIANCES	NS18H24HA5***	NCHC30BT5****+TDR	NF97U070V3B***	19,800	\$2,772
216743570	GE APPLIANCES	NS18H24HA5***	NCHC30BT5****+TDR	NF97U045V3B***	19,800	\$2,772
216743569	GE APPLIANCES	NS18H24HA5***	NCHC30BT5****+TDR	NF97X060V3B***	19,800	\$2,772

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216743568	GE APPLIANCES	NS18H24HA5***	NCHC30BT5****+TDR	NF97X040V3B***	19,800	\$2,772
216743567	GE APPLIANCES	NS18H24HA5***	NCHC24BT5****+TDR	NF97U070V3B***	19,800	\$2,772
216743566	GE APPLIANCES	NS18H24HA5***	NCHC24BT5****+TDR	NF97U045V3B***	19,800	\$2,772
216743565	GE APPLIANCES	NS18H24HA5***	NCHC24BT5****+TDR	NF97X060V3B***	19,800	\$2,772
216743564	GE APPLIANCES	NS18H24HA5***	NCHC24BT5****+TDR	NF97X040V3B***	19,800	\$2,772
216743563	GE APPLIANCES	NS18H24HA5***	NCUC36BT5****+TDR	NF97U070V3B***	19,800	\$2,772
216743562	GE APPLIANCES	NS18H24HA5***	NCUC36BT5****+TDR	NF97U045V3B***	19,800	\$2,772
216743561	GE APPLIANCES	NS18H24HA5***	NCUC36BT5****+TDR	NF97X060V3B***	19,800	\$2,772
216743560	GE APPLIANCES	NS18H24HA5***	NCUC36BT5****+TDR	NF97X040V3B***	19,800	\$2,772
216743559	GE APPLIANCES	NS18H24HA5***	NCUC30BT5****+TDR	NF97U070V3B***	19,800	\$2,772
216743558	GE APPLIANCES	NS18H24HA5***	NCUC30BT5****+TDR	NF97U045V3B***	19,800	\$2,772
216743557	GE APPLIANCES	NS18H24HA5***	NCUC30BT5****+TDR	NF97X060V3B***	19,800	\$2,772
216743556	GE APPLIANCES	NS18H24HA5***	NCUC30BT5****+TDR	NF97X040V3B***	19,800	\$2,772
216604794	GE APPLIANCES	NS18H60HA5***	NCDC60DT5****+TDR		43,500	\$6,090
216604793	GE APPLIANCES	NS18H60HA5***	NCDC60CT5****+TDR		43,500	\$6,090
216604792	GE APPLIANCES	NS18H60HA5***	NCHC60DT5****+TDR		43,500	\$6,090
216604791	GE APPLIANCES	NS18H60HA5***	NCHC60CT5****+TDR		43,500	\$6,090
216604790	GE APPLIANCES	NS18H60HA5***	NCUC60DT5****+TDR		42,000	\$5,880
216604789	GE APPLIANCES	NS18H60HA5***	NCDC48CT5****+TDR		40,000	\$5,600
216604788	GE APPLIANCES	NS18H60HA5***	NCDC42BT5****+TDR		40,500	\$5,670
216604786	GE APPLIANCES	NS18H60HA5***	NCHC48BT5****+TDR		40,500	\$5,670
216604785	GE APPLIANCES	NS18H60HA5***	NCHC42CT5****+TDR		40,500	\$5,670
216604784	GE APPLIANCES	NS18H60HA5***	NCHC42BT5****+TDR		40,000	\$5,600
216604783	GE APPLIANCES	NS18H60HA5***	NCUC49CT5****+TDR		40,000	\$5,600
216604781	GE APPLIANCES	NS18H36HA5***	NCDC42BT5****+TDR		28,000	\$3,920
216604780	GE APPLIANCES	NS18H36HA5***	NCDC36BT5****+TDR		28,000	\$3,920
216604779	GE APPLIANCES	NS18H36HA5***	NCHC36CT5****+TDR		28,000	\$3,920
216604777	GE APPLIANCES	NS18H36HA5***	NCHC36AT5****+TDR		28,400	\$3,976
216604776	GE APPLIANCES	NS18H36HA5***	NCHC30BT5****+TDR		28,000	\$3,920
216604775	GE APPLIANCES	NS18H36HA5***	NCHC30AT5****+TDR		28,000	\$3,920
216604774	GE APPLIANCES	NS18H36HA5***	NCUC36AT5****+TDR		28,000	\$3,920
216604773	GE APPLIANCES	NS18H36HA5***	NCUC30BT5****+TDR		28,000	\$3,920
216604772	GE APPLIANCES	NS18H36HA5***	NCUC30AT5****+TDR		28,000	\$3,920
216604768	GE APPLIANCES	NS18H24HA5***	NCHC30AT5****+TDR		19,600	\$2,744
216604766	GE APPLIANCES	NS18H24HA5***	NCHC24AT5****+TDR		19,600	\$2,744
216604764	GE APPLIANCES	NS18H24HA5***	NCUC36BT5****+TDR		19,600	\$2,744
216604763	GE APPLIANCES	NS18H24HA5***	NCUC36AT5****+TDR		19,600	\$2,744
216604760	GE APPLIANCES	NS18H60HA5***	NAM60V2TA5****		43,500	\$6,090

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216604759	GE APPLIANCES	NS18H60HA5***	NAM60E1TA5****		43,000	\$6,020
216604758	GE APPLIANCES	NS18H60HA5***	NAM48V2TA5****		38,000	\$5,320
216604757	GE APPLIANCES	NS18H60HA5***	NAM42V2TA5****		38,500	\$5,390
216604756	GE APPLIANCES	NS18H60HA5***	NAM48E1TA5****		39,000	\$5,460
216604755	GE APPLIANCES	NS18H60HA5***	NAM42V1TA5****		38,500	\$5,390
216604754	GE APPLIANCES	NS18H60HA5***	NAM42E1TA5****		39,000	\$5,460
216604753	GE APPLIANCES	NS18H36HA5***	NAM42V2TA5****		28,000	\$3,920
216604752	GE APPLIANCES	NS18H36HA5***	NAM36V2TA5****		28,000	\$3,920
216604751	GE APPLIANCES	NS18H36HA5***	NAM42V1TA5****		28,000	\$3,920
216604750	GE APPLIANCES	NS18H36HA5***	NAM42E1TA5****		28,000	\$3,920
216604749	GE APPLIANCES	NS18H36HA5***	NAM42P1TA5****		28,400	\$3,976
216604748	GE APPLIANCES	NS18H36HA5***	NAM36E1TA5****		28,000	\$3,920
216604747	GE APPLIANCES	NS18H36HA5***	NAM36P1TA5****		28,400	\$3,976
216604746	GE APPLIANCES	NS18H24HA5***	NAM30V2TA5****		19,400	\$2,716
216604745	GE APPLIANCES	NS18H24HA5***	NAM24V2TA5****		19,600	\$2,744
216604742	GE APPLIANCES	NS18H24HA5***	NAM24E1TA5****		19,200	\$2,688
216604741	GE APPLIANCES	NS18H24HA5***	NAM24P1TA5****		19,600	\$2,744
215869481	GE APPLIANCES	NS18H36HA5***	NAM36V1TA5****		28,000	\$3,920
215869480	GE APPLIANCES	NS18H24HA5***	NAM24V1TA5****		18,000	\$2,520
207590957	GE APPLIANCES	AUH2436ZGDA*	TUY36ZPDA		24,200	\$3,388
206842136	GE APPLIANCES	ASH112URDSE*	USYM12UCDSA*		9,300	\$1,302
203862746	GE APPLIANCES	ASH324NCDWA	Heat pump without ducts		16,000	\$2,240
204035456	GE APPLIANCES	ASH220NCDWA	Heat pump with ducts		14,000	\$1,960
206842137	GE APPLIANCES	ASH118URDSE*	USYM18UCDSA*		15,000	\$2,100
204878533	GE APPLIANCES	ASH436NCDW**	Heat pump without ducts		22,000	\$3,080
203862745	GE APPLIANCES	ASH220NCDWA	Heat pump without ducts		14,000	\$1,960
211744610	GE Appliances	ASH3036UCDD**	USYL30UCDD**		22,000	\$3,080
211744609	GE Appliances	ASH124UCDD**	ASYW24TRDF**		17,000	\$2,380
206753162	GE Appliances	AUH4860ZGDA*	UUY60ZGDAB*		36,000	\$5,040
212578538	GE APPLIANCES	AUH2436ZGDA*	NCCC24BT4**		15,000	\$2,100
212409457	GE APPLIANCES	ASH112URDE**	ASYW12URDE**		10,800	\$1,512
212409458	GE APPLIANCES	ASH118URDE**	ASYW18URDE**		15,300	\$2,142
207590959	GE APPLIANCES	AUH4860ZGDA*	TUY60ZPDA		36,000	\$5,040
205756418	GE APPLIANCES	AUH2436ZGDA*	UUY24ZGDA**		16,300	\$2,282
205977486	GE APPLIANCES	AUH4860ZGDA*	UUY48ZGDA**		32,800	\$4,592
205977487	GE APPLIANCES	AUH4860ZGDA*	UUY60ZGDA**		37,200	\$5,208
205756419	GE APPLIANCES	AUH2436ZGDA*	UUY36ZGDA**		24,400	\$3,416
212924874	GE APPLIANCES	AUH2436ZGDA*	D(A,C,E)25B34+TDR		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212924873	GE APPLIANCES	AUH2436ZGDA*	D(A,C,E)24D34+TDR		15,000	\$2,100
212924872	GE APPLIANCES	AUH2436ZGDA*	D(A,C,E)24C34+TDR		15,000	\$2,100
212924871	GE APPLIANCES	AUH2436ZGDA*	D(A,C,E)24A44+TDR		15,000	\$2,100
210474662	GE APPLIANCES	ASH220NCDD**	Combination heat pumps with or without ducts		14,400	\$2,016
216765722	GENERALLUX	TSHG12E2M23NAR45O	TSCAS12CD2VIR45I		7,600	\$1,064
216011769	GIBSON	DXH12PSK3IH	DHH12PUK3IH		10,000	\$1,400
216011806	GIBSON	DXH12PSK3IH	DKH12FMK3IH		10,000	\$1,400
215746315	GIBSON	DXH18FMK3IH	Heat pump with ducts		15,000	\$2,100
215746310	GIBSON	DXH18FMK3IH	Heat pump without ducts		16,000	\$2,240
215746316	GIBSON	DXH18FMK3IH	Combination heat pumps with or without ducts		15,400	\$2,156
215746317	GIBSON	DXH24FMK3IH	Heat pump with ducts		22,000	\$3,080
215746311	GIBSON	DXH24FMK3IH	Heat pump without ducts		23,600	\$3,304
215746321	GIBSON	DXH24FMK3IH	Combination heat pumps with or without ducts		22,800	\$3,192
215746318	GIBSON	DXH30FMK3IH	Heat pump with ducts		27,200	\$3,808
215746312	GIBSON	DXH30FMK3IH	Heat pump without ducts		28,000	\$3,920
215746322	GIBSON	DXH30FMK3IH	Combination heat pumps with or without ducts		27,600	\$3,864
216011763	GIBSON	DXH36ESK3IL	DHH36ESK3IL		27,400	\$3,836
215746319	GIBSON	DXH36FMK3IH	Heat pump with ducts		36,000	\$5,040
215746313	GIBSON	DXH36FMK3IH	Heat pump without ducts		36,000	\$5,040
215746323	GIBSON	DXH36FMK3IH	Combination heat pumps with or without ducts		36,000	\$5,040
215746320	GIBSON	DXH42FMK3IH	Heat pump with ducts		40,000	\$5,600
215746314	GIBSON	DXH42FMK3IH	Heat pump without ducts		40,000	\$5,600
215746324	GIBSON	DXH42FMK3IH	Combination heat pumps with or without ducts		40,000	\$5,600
210534171	GIBSON	GXH12(3.5)LSK4DH2	GHH12(3.5)LUK4DH2		10,000	\$1,400
210276800	GIBSON	GXH18(5.3)FMK4DH-1	Heat pump without ducts		15,000	\$2,100
210276801	GIBSON	GXH24(7.0)FMK4DH-1	Heat pump without ducts		23,600	\$3,304
210276802	GIBSON	GXH30(8.8)FMK4DH-1	Heat pump without ducts		27,200	\$3,808
210276798	GIBSON	GXH36(10.6)FMK4DH-1	Heat pump without ducts		30,800	\$4,312
210276799	GIBSON	GXH42(12.3)FMK4DH-1	Heat pump without ducts		35,600	\$4,984
208127828	GIBSON	GXH24-36MSK4DH	GMH**-36MSK4DH1		29,000	\$4,060
208127838	GIBSON	GXH24-36MSK4DH	GMH24-**-36MSK4DH1		20,000	\$2,800
208127829	GIBSON	GXH48-60MSK4DH	GMH48-**-60MSK4DH1		39,500	\$5,530
208127830	GIBSON	GXH48-60MSK4DH	GMH**-60MSK4DH1		44,000	\$6,160

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214438120	GOODMAN	MSH123G26MCAA	MSH123G26AXAA		11,400	\$1,596
214438121	GOODMAN	MSH183G26MCAA	MSH183G26AXAA		20,200	\$2,828
214438125	GOODMAN	MST183G22MHAA	Heat pump without ducts		13,500	\$1,890
214438134	GOODMAN	MST483G22MHAA	Heat pump without ducts		39,000	\$5,460
214438135	GOODMAN	MST483G22MHAA	Heat pump with ducts		36,000	\$5,040
214438136	GOODMAN	MST483G22MHAA	Combination heat pumps with or without ducts		37,400	\$5,236
214438126	GOODMAN	MST183G22MHAA	Heat pump with ducts		16,000	\$2,240
214438127	GOODMAN	MST183G22MHAA	Combination heat pumps with or without ducts		14,700	\$2,058
206900425	GOODMAN	MSH123E23MCAA	MST123E20ACAA		9,900	\$1,386
206900421	GOODMAN	MSH183E23MCAA	MST183E21ADAA		15,000	\$2,100
214438117	GOODMAN	MSH123G22MCAA	MSH123G22AXAA		10,300	\$1,442
214438118	GOODMAN	MSH183G22MCAA	MSH183G22AXAA		11,100	\$1,554
214438123	GOODMAN	MSH243G22MCAA	MSH243G22AXAA		18,900	\$2,646
206900422	GOODMAN	MSH243E23MCAA	MST243E21ADAA		21,000	\$2,940
214594904	GOODMAN	MSH243G22MCAA	MST243E21ADAA		21,000	\$2,940
214594903	GOODMAN	MSH183G22MCAA	MST183E21ADAA		15,000	\$2,100
214594902	GOODMAN	MSH123G22MCAA	MST123E21ADAA		10,600	\$1,484
214594900	GOODMAN	MSH123G22MCAA	MST123E20ACAA		9,900	\$1,386
216835372	GOODMAN	GZV7SA6010A*	CAHEA3630C3A*+MBVK16C H*X00A*		33,400	\$4,676
216835370	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VM971005CNA*	33,400	\$4,676
216835367	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VM971005CNA*	33,400	\$4,676
216835365	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VM971205DNA*	33,400	\$4,676
216835362	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VM971205DNA*	33,400	\$4,676
216835360	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VS800805CUA*	33,400	\$4,676
216835358	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VS800805CUA*	33,400	\$4,676
216835356	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VT800804C*A*	33,400	\$4,676
216835353	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VT800804C*A*	33,400	\$4,676
216835351	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VT800805C*A*	33,400	\$4,676
216835349	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VT800805C*A*	33,400	\$4,676
216835346	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VT800805D*A*	33,400	\$4,676
216835344	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VT800805D*A*	33,400	\$4,676
216835342	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VT801005C*A*	33,400	\$4,676
216835340	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VT801005C*A*	33,400	\$4,676
216835338	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VT960804CNA*	33,400	\$4,676
216835335	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VT960804CNA*	33,400	\$4,676

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216835333	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VT961005CNA*	33,400	\$4,676
216835331	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VT961005CNA*	33,400	\$4,676
216835329	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VT961005DNA*	33,400	\$4,676
216835327	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VT961005DNA*	33,400	\$4,676
216835324	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*	G*VT961205DNA*	33,400	\$4,676
216835321	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*	G*VT961205DNA*	33,400	\$4,676
216835319	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*+MBVK16CP1X00A*		33,400	\$4,676
216835317	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*+MBVK16CP1X00A*		33,400	\$4,676
216835314	GOODMAN	GZV7SA6010A*	CA*EA6030*3A*+MBVK20DP1X00A*		33,400	\$4,676
216835312	GOODMAN	GZV7SA6010A*	CHPEA6030*3A*+MBVK20DP1X00A*		33,400	\$4,676
216835310	GOODMAN	GZV7SA6010A*	AHVE60DP0300A*		33,400	\$4,676
216835221	GOODMAN	GZV7SA6010A*	AHVE60DP1300A*		33,400	\$4,676
215488127	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VC800804C*A*	29,000	\$4,060
215488126	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VM971205DNB*	28,400	\$3,976
215488125	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VC961205DNB*	28,400	\$3,976
215488124	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VC800805D*A*	28,400	\$3,976
215488123	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VM971005CNB*	28,400	\$3,976
215488122	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VM970804CNB*	28,400	\$3,976
215488121	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VC961005CNB*	28,400	\$3,976
215488120	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VC960804CNB*	28,400	\$3,976
215488119	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VC801005C*A*	28,400	\$3,976
215488118	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VC800805C*A*	28,400	\$3,976
215488117	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VC800804C*A*	28,400	\$3,976
215488116	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VM971205DNB*	29,000	\$4,060
215488115	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VC961205DNB*	29,000	\$4,060
215488114	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VC800805D*A*	29,000	\$4,060
215488113	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VM971005CNB*	29,000	\$4,060
215488112	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VM970804CNB*	29,000	\$4,060
215488111	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VC961005CNB*	29,000	\$4,060
215488110	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VC960804CNB*	29,000	\$4,060
215488109	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VC801005C*A*	29,000	\$4,060
215488108	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VC800805C*A*	29,000	\$4,060
215488107	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VC800804C*A*	29,000	\$4,060
215488106	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VC961205DNB*	28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215488105	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VC961005CNB*	28,000	\$3,920
215488104	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VC960804CNB*	28,000	\$3,920
215488103	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VC801005C*A*	28,000	\$3,920
215488102	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VC800805D*A*	28,000	\$3,920
215488101	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VC800805C*A*	28,000	\$3,920
215488100	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VC800804C*A*	28,000	\$3,920
215488099	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VM971205DNB*	28,000	\$3,920
215488098	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VM971005CNB*	28,000	\$3,920
215488097	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VM970804CNB*	28,000	\$3,920
215488096	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VC961205DNB*	28,000	\$3,920
215488095	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VC961005CNB*	28,000	\$3,920
215488094	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VC960804CNB*	28,000	\$3,920
215488093	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VC801005C*A*	28,000	\$3,920
215488092	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VC800805D*A*	28,000	\$3,920
215488091	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VC800805C*A*	28,000	\$3,920
215488090	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VC800804C*A*	28,000	\$3,920
215488089	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VM971205DNB*	28,000	\$3,920
215488088	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VM971005CNB*	28,000	\$3,920
215488087	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VM970804CNB*	28,000	\$3,920
215488086	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VC961205DNB*	28,000	\$3,920
215488085	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VC961005CNB*	28,000	\$3,920
215488084	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VC960804CNB*	28,000	\$3,920
215488083	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VC801005C*A*	28,000	\$3,920
215488082	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VC800805D*A*	28,000	\$3,920
215488081	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VC800805C*A*	28,000	\$3,920
215488080	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VC800804C*A*	28,000	\$3,920
215488079	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VM971205DNB*	28,000	\$3,920
215488078	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VM971005CNB*	28,000	\$3,920
215488077	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VM970804CNB*	28,000	\$3,920
215488076	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VM970804CNB*	22,000	\$3,080
215488075	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VM971005CNB*	22,000	\$3,080
215488074	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VM971205DNB*	22,000	\$3,080
215488073	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VC800804C*A*	22,000	\$3,080
215488072	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VC800805C*A*	22,000	\$3,080
215488071	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VC800805D*A*	22,000	\$3,080
215488070	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VC801005C*A*	22,000	\$3,080
215488069	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VC960804CNB*	22,000	\$3,080
215488068	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VC961005CNB*	22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215488067	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VC961205DNB*	22,000	\$3,080
215488066	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VC800804C*A*	22,000	\$3,080
215488065	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VC800805C*A*	22,000	\$3,080
215488064	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VC800805D*A*	22,000	\$3,080
215488063	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VC801005C*A*	22,000	\$3,080
215488062	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VM970804CNB*	22,000	\$3,080
215488061	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VM971005CNB*	22,000	\$3,080
215488060	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VM971205DNB*	22,000	\$3,080
215488059	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VC800804C*A*	22,000	\$3,080
215488058	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VC800805C*A*	22,000	\$3,080
215488057	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VC800805D*A*	22,000	\$3,080
215488056	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VC801005C*A*	22,000	\$3,080
215488055	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VC960804CNB*	22,000	\$3,080
215488054	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VC961005CNB*	22,000	\$3,080
215488053	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VC961205DNB*	22,000	\$3,080
215488052	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC961005CNB*	15,800	\$2,212
215488051	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC960804CNB*	15,800	\$2,212
215488050	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC960803BNB*	15,800	\$2,212
215488049	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC960603BNB*	15,800	\$2,212
215488048	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC960403BNB*	15,800	\$2,212
215488047	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC801005C*A*	15,800	\$2,212
215488046	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC800805C*A*	15,800	\$2,212
215488045	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC800804C*A*	15,800	\$2,212
215488044	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC800803B*A*	15,800	\$2,212
215488043	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC800604B*A*	15,800	\$2,212
215488042	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VC800603B*A*	15,800	\$2,212
215488041	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VM971005CNB*	15,800	\$2,212
215488040	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VM970804CNB*	15,800	\$2,212
215488039	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VM970803BNB*	15,800	\$2,212
215488038	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VM970603BNB*	15,800	\$2,212
215488037	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC961005CNB*	15,800	\$2,212
215488036	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC960804CNB*	15,800	\$2,212
215488035	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC960803BNB*	15,800	\$2,212
215488034	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC960603BNB*	15,800	\$2,212
215488033	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC960403BNB*	15,800	\$2,212
215488032	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC801005C*A*	15,800	\$2,212
215488031	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC800805C*A*	15,800	\$2,212
215488030	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC800804C*A*	15,800	\$2,212

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215488029	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC800803B*A*	15,800	\$2,212
215488028	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC800604B*A*	15,800	\$2,212
215488027	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VC800603B*A*	15,800	\$2,212
215488026	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VM971005CNB*	15,800	\$2,212
215488025	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VM970804CNB*	15,800	\$2,212
215488024	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VM970803BNB*	15,800	\$2,212
215488023	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VM970603BNB*	15,800	\$2,212
215488022	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC961005CNB*	15,800	\$2,212
215488021	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC960804CNB*	15,800	\$2,212
215488020	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC960803BNB*	15,800	\$2,212
215488019	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC960603BNB*	15,800	\$2,212
215488018	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC960403BNB*	15,800	\$2,212
215488017	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC801005C*A*	15,800	\$2,212
215488016	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC800805C*A*	15,800	\$2,212
215488015	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC800804C*A*	15,800	\$2,212
215488014	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC800803B*A*	15,800	\$2,212
215488013	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VC800603B*A*	15,800	\$2,212
215488012	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VM971005CNB*	15,800	\$2,212
215488011	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VM970804CNB*	15,800	\$2,212
215488010	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VM970803BNB*	15,800	\$2,212
215488009	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VM970603BNB*	15,800	\$2,212
215488136	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VM971205DNB*	29,000	\$4,060
215488135	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VC961205DNB*	29,000	\$4,060
215488134	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VC800805D*A*	29,000	\$4,060
215488133	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VM971005CNB*	29,000	\$4,060
215488132	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VM970804CNB*	29,000	\$4,060
215488131	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VC961005CNB*	29,000	\$4,060
215488130	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VC960804CNB*	29,000	\$4,060
215488129	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VC801005C*A*	29,000	\$4,060
215488128	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VC800805C*A*	29,000	\$4,060
215439759	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VM970603BNA*	10,800	\$1,512
215439758	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VM970603BNA*	10,800	\$1,512
215439757	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VM970603BNA*	10,800	\$1,512
215439756	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VM970803BNA*	10,800	\$1,512
215439755	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VM970803BNA*	10,800	\$1,512
215439754	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VM970803BNA*	10,800	\$1,512
215439753	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VM970804CNA*	10,800	\$1,512
215439752	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VM970804CNA*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215439741	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VT800603B*A*	10,800	\$1,512
215439740	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VT800603B*A*	10,800	\$1,512
215439739	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VT800603B*A*	10,800	\$1,512
215439738	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VT800604B*A*	10,800	\$1,512
215439737	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VT800604B*A*	10,800	\$1,512
215439736	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VT800604B*A*	10,800	\$1,512
215439735	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VT800803B*A*	10,800	\$1,512
215439734	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VT800803B*A*	10,800	\$1,512
215439733	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VT800803B*A*	10,800	\$1,512
215439732	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VT800804C*A*	10,800	\$1,512
215439731	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VT800804C*A*	10,800	\$1,512
215439730	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VT800805C*A*	10,800	\$1,512
215439729	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VT800805C*A*	10,800	\$1,512
215439728	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VT960403BNA*	10,800	\$1,512
215439727	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VT960403BNA*	10,800	\$1,512
215439726	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VT960403BNA*	10,800	\$1,512
215439725	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VT960603BNA*	10,800	\$1,512
215439724	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VT960603BNA*	10,800	\$1,512
215439723	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VT960603BNA*	10,800	\$1,512
215439722	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VT960803BNA*	10,800	\$1,512
215439721	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VT960803BNA*	10,800	\$1,512
215439720	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VT960803BNA*	10,800	\$1,512
215439719	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VT960804CNA*	10,800	\$1,512
215439718	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VT960804CNA*	10,800	\$1,512
215488168	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VM970603BNB*	10,800	\$1,512
215488167	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VM970603BNB*	10,800	\$1,512
215488166	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VM970603BNB*	10,800	\$1,512
215488165	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VM970803BNB*	10,800	\$1,512
215488164	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VM970803BNB*	10,800	\$1,512
215488163	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VM970803BNB*	10,800	\$1,512
215488162	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VM970804CNB*	10,800	\$1,512
215488161	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VM970804CNB*	10,800	\$1,512
215439751	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VS800604BUA*	10,800	\$1,512
215439750	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VS800604BUA*	10,800	\$1,512
215439749	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VS800604BUA*	10,800	\$1,512
215439748	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VS800805CUA*	10,800	\$1,512
215439747	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VS800805CUA*	10,800	\$1,512
215439746	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VS960603BUA*	10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215439745	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VS960603BUA*	10,800	\$1,512
215439744	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VS960603BUA*	10,800	\$1,512
215439743	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VS960805CUA*	10,800	\$1,512
215439742	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VS960805CUA*	10,800	\$1,512
215488160	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VC800603B*A*	10,800	\$1,512
215488159	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VC800603B*A*	10,800	\$1,512
215488158	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VC800603B*A*	10,800	\$1,512
215488157	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VC800604B*A*	10,800	\$1,512
215488156	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VC800604B*A*	10,800	\$1,512
215488155	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VC800604B*A*	10,800	\$1,512
215488154	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VC800803B*A*	10,800	\$1,512
215488153	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VC800803B*A*	10,800	\$1,512
215488152	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VC800803B*A*	10,800	\$1,512
215488151	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VC800804C*A*	10,800	\$1,512
215488150	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VC800804C*A*	10,800	\$1,512
215488149	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VC800805C*A*	10,800	\$1,512
215488148	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VC800805C*A*	10,800	\$1,512
215488147	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VC960403BNB*	10,800	\$1,512
215488146	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VC960403BNB*	10,800	\$1,512
215488145	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VC960403BNB*	10,800	\$1,512
215488144	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VC960603BNB*	10,800	\$1,512
215488143	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VC960603BNB*	10,800	\$1,512
215488142	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VC960603BNB*	10,800	\$1,512
215488141	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VC960803BNB*	10,800	\$1,512
215488140	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VC960803BNB*	10,800	\$1,512
215488139	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*	G*VC960803BNB*	10,800	\$1,512
215488138	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*	G*VC960804CNB*	10,800	\$1,512
215488137	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*	G*VC960804CNB*	10,800	\$1,512
215439774	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*+MBVK12BP1X00A*		10,800	\$1,512
215439773	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*+MBVK12BP1X00A*		10,800	\$1,512
215439772	GOODMAN	GZV6SA1810A*	CHPEA2422*3A*+MBVK12BP1X00A*		10,800	\$1,512
215439771	GOODMAN	GZV6SA1810A*	CA*EA2418*3A*+MBVK16CP1X00A*		10,800	\$1,512
215439770	GOODMAN	GZV6SA1810A*	CA*EA3022*3A*+MBVK16CP1X00A*		10,800	\$1,512

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215429783	GOODMAN	GZV6SA1810A*	AHVE24BP0300A*		10,800	\$1,512
215429190	GOODMAN	GZV6SA1810A*	AHVE24BP1300A*		10,800	\$1,512
215433964	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*+MBVK20D P1X00A*		29,000	\$4,060
215434464	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VM971205DNA*	29,000	\$4,060
215434463	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VT961205DNA*	29,000	\$4,060
215434462	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VT961005DNA*	29,000	\$4,060
215434461	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VT800805D*A*	29,000	\$4,060
215433963	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*+MBVK16C P1X00A*		29,000	\$4,060
215434460	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VM971005CNA*	29,000	\$4,060
215434459	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VM970804CNA*	29,000	\$4,060
215434458	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VT961005CNA*	29,000	\$4,060
215434457	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VT960804CNA*	29,000	\$4,060
215434456	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VS960805CUA*	29,000	\$4,060
215434455	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VT801005C*A*	29,000	\$4,060
215434454	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VT800805C*A*	29,000	\$4,060
215434453	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VT800804C*A*	29,000	\$4,060
215434452	GOODMAN	GZV7SA4810A*	CHPEA6030*3A*	G*VS800805CUA*	29,000	\$4,060
215433962	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*+MBVK20D P1X00A*		28,400	\$3,976
215434451	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VM971205DNA*	28,400	\$3,976
215434450	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VT961205DNA*	28,400	\$3,976
215434449	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VT961005DNA*	28,400	\$3,976
215434448	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VT800805D*A*	28,400	\$3,976
215433961	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*+MBVK16C P1X00A*		28,400	\$3,976
215434447	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VM971005CNA*	28,400	\$3,976
215434446	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VM970804CNA*	28,400	\$3,976
215434445	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VT961005CNA*	28,400	\$3,976
215434444	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VT960804CNA*	28,400	\$3,976
215434443	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VS960805CUA*	28,400	\$3,976
215434442	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VT801005C*A*	28,400	\$3,976
215434441	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VT800805C*A*	28,400	\$3,976
215434440	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VT800804C*A*	28,400	\$3,976
215434439	GOODMAN	GZV7SA4810A*	CHPEA4830*3A*	G*VS800805CUA*	28,400	\$3,976
215433960	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*+MBVK20DP 1X00A*		29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434438	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VM971205DNA*	29,000	\$4,060
215434437	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VT961205DNA*	29,000	\$4,060
215434436	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VT961005DNA*	29,000	\$4,060
215434435	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VT800805D*A*	29,000	\$4,060
215433959	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*+MBVK16CP1X00A*		29,000	\$4,060
215434434	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VM971005CNA*	29,000	\$4,060
215434433	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VM970804CNA*	29,000	\$4,060
215434432	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VT961005CNA*	29,000	\$4,060
215434431	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VT960804CNA*	29,000	\$4,060
215434430	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VS960805CUA*	29,000	\$4,060
215434429	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VT801005C*A*	29,000	\$4,060
215434428	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VT800805C*A*	29,000	\$4,060
215434427	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VT800804C*A*	29,000	\$4,060
215434426	GOODMAN	GZV7SA4810A*	CA*EA6030*3A*	G*VS800805CUA*	29,000	\$4,060
215429752	GOODMAN	GZV7SA4810A*	AHVE60DP0300A*		29,000	\$4,060
215429199	GOODMAN	GZV7SA4810A*	AHVE60DP1300A*		29,000	\$4,060
215433946	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*+MBVK20DP1X00A*		28,000	\$3,920
215433945	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*+MBVK16CP1X00A*		28,000	\$3,920
215434347	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VT961205DNA*	28,000	\$3,920
215434346	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VT961005DNA*	28,000	\$3,920
215434345	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VT961005CNA*	28,000	\$3,920
215434344	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VT960804CNA*	28,000	\$3,920
215434343	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VT801005C*A*	28,000	\$3,920
215434342	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VT800805D*A*	28,000	\$3,920
215434341	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VT800805C*A*	28,000	\$3,920
215434340	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VT800804C*A*	28,000	\$3,920
215434339	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VS960805CUA*	28,000	\$3,920
215434338	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VS800805CUA*	28,000	\$3,920
215434337	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VM971205DNA*	28,000	\$3,920
215434336	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VM971005CNA*	28,000	\$3,920
215434335	GOODMAN	GZV7SA4210A*	CHPEA6030*3A*	G*VM970804CNA*	28,000	\$3,920
215433944	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*+MBVK20DP1X00A*		28,000	\$3,920
215433943	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*+MBVK16CP1X00A*		28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434334	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VT961205DNA*	28,000	\$3,920
215434333	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VT961005DNA*	28,000	\$3,920
215434332	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VT961005CNA*	28,000	\$3,920
215434331	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VT960804CNA*	28,000	\$3,920
215434330	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VT801005C*A*	28,000	\$3,920
215434329	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VT800805D*A*	28,000	\$3,920
215434328	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VT800805C*A*	28,000	\$3,920
215434327	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VT800804C*A*	28,000	\$3,920
215434326	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VS960805CUA*	28,000	\$3,920
215434325	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VS800805CUA*	28,000	\$3,920
215434324	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VM971205DNA*	28,000	\$3,920
215434323	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VM971005CNA*	28,000	\$3,920
215434322	GOODMAN	GZV7SA4210A*	CHPEA4830*3A*	G*VM970804CNA*	28,000	\$3,920
215433942	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*+MBVK20DP1X00A*		28,000	\$3,920
215433941	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*+MBVK16CP1X00A*		28,000	\$3,920
215434321	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VT961205DNA*	28,000	\$3,920
215434320	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VT961005DNA*	28,000	\$3,920
215434319	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VT961005CNA*	28,000	\$3,920
215434318	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VT960804CNA*	28,000	\$3,920
215434317	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VT801005C*A*	28,000	\$3,920
215434316	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VT800805D*A*	28,000	\$3,920
215434315	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VT800805C*A*	28,000	\$3,920
215434314	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VT800804C*A*	28,000	\$3,920
215434313	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VS960805CUA*	28,000	\$3,920
215434312	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VS800805CUA*	28,000	\$3,920
215434311	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VM971205DNA*	28,000	\$3,920
215434310	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VM971005CNA*	28,000	\$3,920
215434309	GOODMAN	GZV7SA4210A*	CA*EA6030*3A*	G*VM970804CNA*	28,000	\$3,920
215429751	GOODMAN	GZV7SA4210A*	AHVE60DP0300A*		28,000	\$3,920
215429198	GOODMAN	GZV7SA4210A*	AHVE60DP1300A*		28,000	\$3,920
215434230	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VM970804CNA*	22,000	\$3,080
215434229	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VM971005CNA*	22,000	\$3,080
215434228	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VM971205DNA*	22,000	\$3,080
215434227	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VS800805CUA*	22,000	\$3,080
215434226	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VS960805CUA*	22,000	\$3,080
215434225	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VT800804C*A*	22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434224	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VT800805C*A*	22,000	\$3,080
215434223	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VT800805D*A*	22,000	\$3,080
215434222	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VT801005C*A*	22,000	\$3,080
215434221	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VT960804CNA*	22,000	\$3,080
215434220	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VT961005CNA*	22,000	\$3,080
215434219	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VT961005DNA*	22,000	\$3,080
215434218	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*	G*VT961205DNA*	22,000	\$3,080
215433928	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*+MBVK16C P1X00A*		22,000	\$3,080
215433927	GOODMAN	GZV7SA3610A*	CHPEA4830*3A*+MBVK20D P1X00A*		22,000	\$3,080
215434217	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VS800805CUA*	22,000	\$3,080
215434216	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VS960805CUA*	22,000	\$3,080
215434215	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VT800804C*A*	22,000	\$3,080
215434214	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VT800805C*A*	22,000	\$3,080
215434213	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VT800805D*A*	22,000	\$3,080
215434212	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*	G*VT801005C*A*	22,000	\$3,080
215433926	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*+MBVK16CP 1X00A*		22,000	\$3,080
215433925	GOODMAN	GZV7SA3610A*	CA*EA6030*3A*+MBVK20DP 1X00A*		22,000	\$3,080
215434211	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VM970804CNA*	22,000	\$3,080
215434210	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VM971005CNA*	22,000	\$3,080
215434209	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VM971205DNA*	22,000	\$3,080
215434208	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VS800805CUA*	22,000	\$3,080
215434207	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VS960805CUA*	22,000	\$3,080
215434206	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VT800804C*A*	22,000	\$3,080
215434205	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VT800805C*A*	22,000	\$3,080
215434204	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VT800805D*A*	22,000	\$3,080
215434203	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VT801005C*A*	22,000	\$3,080
215434202	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VT960804CNA*	22,000	\$3,080
215434201	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VT961005CNA*	22,000	\$3,080
215434200	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VT961005DNA*	22,000	\$3,080
215434199	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*	G*VT961205DNA*	22,000	\$3,080
215433924	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*+MBVK16CP 1X00A*		22,000	\$3,080
215433923	GOODMAN	GZV7SA3610A*	CA*EA4830*3A*+MBVK20DP 1X00A*		22,000	\$3,080
215429748	GOODMAN	GZV7SA3610A*	AHVE60DP0300A*		22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215429747	GOODMAN	GZV7SA3610A*	AHVE60DP1300A*		22,000	\$3,080
215429746	GOODMAN	GZV7SA3610A*	AHVE48CP0300A*		22,000	\$3,080
215429745	GOODMAN	GZV7SA3610A*	AHVE48CP1300A*		22,000	\$3,080
215429744	GOODMAN	GZV7SA3610A*	AHVE42CP0300A*		22,000	\$3,080
215429743	GOODMAN	GZV7SA3610A*	AHVE42CP1300A*		22,000	\$3,080
215429742	GOODMAN	GZV7SA3610A*	AHVE48DP0300A*		22,000	\$3,080
215429197	GOODMAN	GZV7SA3610A*	AHVE48DP1300A*		22,000	\$3,080
215433910	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*+MBVK16C P1X00A*		15,800	\$2,212
215433909	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*+MBVK12B P1X00A*		15,800	\$2,212
215434134	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT961005CNA*	15,800	\$2,212
215434133	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT960804CNA*	15,800	\$2,212
215434132	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT960803BNA*	15,800	\$2,212
215434131	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT960603BNA*	15,800	\$2,212
215434130	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT960403BNA*	15,800	\$2,212
215434129	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT801005C*A*	15,800	\$2,212
215434128	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT800805C*A*	15,800	\$2,212
215434127	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT800804C*A*	15,800	\$2,212
215434126	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT800803B*A*	15,800	\$2,212
215434125	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT800604B*A*	15,800	\$2,212
215434124	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VT800603B*A*	15,800	\$2,212
215434123	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VS960805CUA*	15,800	\$2,212
215434122	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VS960603BUA*	15,800	\$2,212
215434121	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VS800805CUA*	15,800	\$2,212
215434120	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VS800604BUA*	15,800	\$2,212
215434119	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VM971005CNA*	15,800	\$2,212
215434118	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VM970804CNA*	15,800	\$2,212
215434117	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VM970803BNA*	15,800	\$2,212
215434116	GOODMAN	GZV7SA2410A*	CHPEA3026*3A*	G*VM970603BNA*	15,800	\$2,212
215433908	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*+MBVK16CP 1X00A*		15,800	\$2,212
215433907	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*+MBVK12BP 1X00A*		15,800	\$2,212
215434115	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT961005CNA*	15,800	\$2,212
215434114	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT960804CNA*	15,800	\$2,212
215434113	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT960803BNA*	15,800	\$2,212
215434112	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT960603BNA*	15,800	\$2,212

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215434111	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT960403BNA*	15,800	\$2,212
215434110	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT801005C*A*	15,800	\$2,212
215434109	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT800805C*A*	15,800	\$2,212
215434108	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT800804C*A*	15,800	\$2,212
215434107	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT800803B*A*	15,800	\$2,212
215434106	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT800604B*A*	15,800	\$2,212
215434105	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VT800603B*A*	15,800	\$2,212
215434104	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VS960805CUA*	15,800	\$2,212
215434103	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VS960603BUA*	15,800	\$2,212
215434102	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VS800805CUA*	15,800	\$2,212
215434101	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VS800604BUA*	15,800	\$2,212
215434100	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VM971005CNA*	15,800	\$2,212
215434099	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VM970804CNA*	15,800	\$2,212
215434098	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VM970803BNA*	15,800	\$2,212
215434097	GOODMAN	GZV7SA2410A*	CA*EA3626*3A*	G*VM970603BNA*	15,800	\$2,212
215433906	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*+MBVK16CP1X00A*		15,800	\$2,212
215433905	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*+MBVK12BP1X00A*		15,800	\$2,212
215434096	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT961005CNA*	15,800	\$2,212
215434095	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT960804CNA*	15,800	\$2,212
215434094	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT960803BNA*	15,800	\$2,212
215434093	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT960603BNA*	15,800	\$2,212
215434092	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT960403BNA*	15,800	\$2,212
215434091	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT801005C*A*	15,800	\$2,212
215434090	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT800805C*A*	15,800	\$2,212
215434089	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT800804C*A*	15,800	\$2,212
215434088	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT800803B*A*	15,800	\$2,212
215434087	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VT800603B*A*	15,800	\$2,212
215434086	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VS960805CUA*	15,800	\$2,212
215434085	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VS960603BUA*	15,800	\$2,212
215434084	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VS800805CUA*	15,800	\$2,212
215434083	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VS800604BUA*	15,800	\$2,212
215434082	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VM971005CNA*	15,800	\$2,212
215434081	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VM970804CNA*	15,800	\$2,212
215434080	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VM970803BNA*	15,800	\$2,212
215434079	GOODMAN	GZV7SA2410A*	CA*EA3022*3A*	G*VM970603BNA*	15,800	\$2,212
215429734	GOODMAN	GZV7SA2410A*	AHVE36CP0300A*		15,800	\$2,212

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215429196	GOODMAN	GZV7SA2410A*	AHVE36CP1300A*		15,800	\$2,212
210692728	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM971205DNB*	21,400	\$2,996
210692727	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM971005CNB*	21,400	\$2,996
210692726	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM970804CNB*	21,400	\$2,996
210609967	GOODMAN	GSZV903610A*	AMVE48DP1400A*		21,400	\$2,996
213386630	GOODMAN	GSZS601810A*	AHVE24BP0400A*		10,800	\$1,512
213349160	GOODMAN	GSZS601810A*	CA*EA2422*4A*+MBVC1600* *-1A*		10,800	\$1,512
213349159	GOODMAN	GSZS601810A*	CA*EA2422*4A*+MBVC1200* *-1A*		10,800	\$1,512
213349062	GOODMAN	GSZS601810A*	CA*EA2422*4A*	G*VS960805CUA*	10,800	\$1,512
213349053	GOODMAN	GSZS601810A*	CA*EA2422*4A*	G*VS960603BUA*	10,800	\$1,512
213349064	GOODMAN	GSZS601810A*	CA*EA2422*4A*	G*VM970804CNB*	10,800	\$1,512
213349058	GOODMAN	GSZS601810A*	CA*EA2422*4A*	G*VM970803BNB*	10,800	\$1,512
213349057	GOODMAN	GSZS601810A*	CA*EA2422*4A*	G*VM970603BNB*	10,800	\$1,512
213349063	GOODMAN	GSZS601810A*	CA*EA2422*4A*	G*VC960804CNB*	10,800	\$1,512
213349056	GOODMAN	GSZS601810A*	CA*EA2422*4A*	G*VC960803BNB*	10,800	\$1,512
213349055	GOODMAN	GSZS601810A*	CA*EA2422*4A*	G*VC960603BNB*	10,800	\$1,512
213349054	GOODMAN	GSZS601810A*	CA*EA2422*4A*	G*VC960403BNB*	10,800	\$1,512
213349158	GOODMAN	GSZS601810A*	CA*EA1818*4A*+MBVC1600* *-1A*		10,800	\$1,512
213349157	GOODMAN	GSZS601810A*	CA*EA1818*4A*+MBVC1200* *-1A*		10,800	\$1,512
213349046	GOODMAN	GSZS601810A*	CA*EA1818*4A*	G*VS960805CUA*	10,800	\$1,512
213349037	GOODMAN	GSZS601810A*	CA*EA1818*4A*	G*VS960603BUA*	10,800	\$1,512
213349048	GOODMAN	GSZS601810A*	CA*EA1818*4A*	G*VM970804CNB*	10,800	\$1,512
213349042	GOODMAN	GSZS601810A*	CA*EA1818*4A*	G*VM970803BNB*	10,800	\$1,512
213349041	GOODMAN	GSZS601810A*	CA*EA1818*4A*	G*VM970603BNB*	10,800	\$1,512
213349047	GOODMAN	GSZS601810A*	CA*EA1818*4A*	G*VC960804CNB*	10,800	\$1,512
213349040	GOODMAN	GSZS601810A*	CA*EA1818*4A*	G*VC960803BNB*	10,800	\$1,512
213349039	GOODMAN	GSZS601810A*	CA*EA1818*4A*	G*VC960603BNB*	10,800	\$1,512
213349038	GOODMAN	GSZS601810A*	CA*EA1818*4A*	G*VC960403BNB*	10,800	\$1,512
213349022	GOODMAN	GSZS601810A*	AHVE24BP1400A*		10,800	\$1,512
210609966	GOODMAN	GSZV903610A*	AMVE36CP1400A*		21,600	\$3,024
210692700	GOODMAN	GSZV903610A*	CA*F3137*6A*+MBVC1201** 1A*+TXV		21,600	\$3,024
210692703	GOODMAN	GSZV903610A*	CA*F3137*6A*+TXV	G*VC960403BNB*	21,600	\$3,024
210692704	GOODMAN	GSZV903610A*	CA*F3137*6A*+TXV	G*VS960603BUA*	21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210692705	GOODMAN	GSZV903610A*	CA*F3137*6A*+TXV	G*VC960603BNB*	21,600	\$3,024
210692706	GOODMAN	GSZV903610A*	CA*F3137*6A*+TXV	G*VC960803BNB*	21,600	\$3,024
210692707	GOODMAN	GSZV903610A*	CA*F3137*6A*+TXV	G*VM970603BNB*	21,600	\$3,024
210692708	GOODMAN	GSZV903610A*	CA*F3137*6A*+TXV	G*VM970803BNB*	21,600	\$3,024
210692709	GOODMAN	GSZV903610A*	CA*F3743*6D*+MBVC1201** -1A*+TXV		21,600	\$3,024
210607412	GOODMAN	GSZV903610A*	CA*F3743*6D*+MBVC1601** -1A*+TX		21,600	\$3,024
210692716	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC960403BNB*	21,600	\$3,024
210692717	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VS960603BUA*	21,600	\$3,024
210692718	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC960603BNB*	21,600	\$3,024
210692719	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC960803BNB*	21,600	\$3,024
210692720	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC960804CNB*	21,600	\$3,024
210692721	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VS960805CUA*	21,600	\$3,024
210692722	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC961005CNB*	21,600	\$3,024
210692723	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VC961205DNB*	21,600	\$3,024
210692724	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM970603BNB*	21,600	\$3,024
210692725	GOODMAN	GSZV903610A*	CA*F3743*6D*+TXV	G*VM970803BNB*	21,600	\$3,024
210692729	GOODMAN	GSZV903610A*	CHPF3642C6C*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210692730	GOODMAN	GSZV903610A*	CHPF3642C6C*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210692737	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC960403BNB*	21,600	\$3,024
210692738	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VS960603BUA*	21,600	\$3,024
210692739	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC960603BNB*	21,600	\$3,024
210692740	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC960803BNB*	21,600	\$3,024
210692741	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC960804CNB*	21,600	\$3,024
210692742	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VS960805CUA*	21,600	\$3,024
210692743	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VC961005CNB*	21,600	\$3,024
210692744	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VM970603BNB*	21,600	\$3,024
210692745	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VM970803BNB*	21,600	\$3,024
210692746	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VM970804CNB*	21,600	\$3,024
210692747	GOODMAN	GSZV903610A*	CHPF3642C6C*+TXV	G*VM971005CNB*	21,600	\$3,024
210692748	GOODMAN	GSZV903610A*	CHPF3743C6B*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210692749	GOODMAN	GSZV903610A*	CHPF3743C6B*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210692756	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC960403BNB*	21,600	\$3,024
210692757	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VS960603BUA*	21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210692758	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC960603BNB*	21,600	\$3,024
210692759	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC960803BNB*	21,600	\$3,024
210692760	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC960804CNB*	21,600	\$3,024
210692761	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VS960805CUA*	21,600	\$3,024
210692762	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VC961005CNB*	21,600	\$3,024
210692763	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VM970603BNB*	21,600	\$3,024
210692764	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VM970803BNB*	21,600	\$3,024
210692765	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VM970804CNB*	21,600	\$3,024
210692766	GOODMAN	GSZV903610A*	CHPF3743C6B*+TXV	G*VM971005CNB*	21,600	\$3,024
210692767	GOODMAN	GSZV903610A*	CSCF3642N6D*+MBVC1201* *-1A*+TXV		21,600	\$3,024
210692768	GOODMAN	GSZV903610A*	CSCF3642N6D*+MBVC1601* *-1A*+TXV		21,600	\$3,024
210692775	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC960403BNB*	21,600	\$3,024
210692776	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VS960603BUA*	21,600	\$3,024
210692777	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC960603BNB*	21,600	\$3,024
210692778	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC960803BNB*	21,600	\$3,024
210692779	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC960804CNB*	21,600	\$3,024
210692780	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VS960805CUA*	21,600	\$3,024
210692781	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC961005CNB*	21,600	\$3,024
210692782	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VC961205DNB*	21,600	\$3,024
210692783	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM970603BNB*	21,600	\$3,024
210692784	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM970803BNB*	21,600	\$3,024
210692785	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM970804CNB*	21,600	\$3,024
210692786	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM971005CNB*	21,600	\$3,024
210692787	GOODMAN	GSZV903610A*	CSCF3642N6D*+TXV	G*VM971205DNB*	21,600	\$3,024
213816052	GOODMAN	GSZS601810A*	CA*EA2422*4A*+MBVK16CP 1X00A*		10,800	\$1,512
213816051	GOODMAN	GSZS601810A*	CA*EA2422*4A*+MBVK12BP 1X00A*		10,800	\$1,512
213816050	GOODMAN	GSZS601810A*	CA*EA1818*4A*+MBVK16CP 1X00A*		10,800	\$1,512
213816049	GOODMAN	GSZS601810A*	CA*EA1818*4A*+MBVK12BP 1X00A*		10,800	\$1,512
213613307	GOODMAN	GSZS601810A*	AHVE24BP1400B*		10,800	\$1,512
214438133	GOODMAN	MST363G22MHAA	Combination heat pumps with or without ducts		28,600	\$4,004
214438131	GOODMAN	MST363G22MHAA	Heat pump without ducts		27,400	\$3,836
214438132	GOODMAN	MST363G22MHAA	Heat pump with ducts		30,000	\$4,200

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214438130	GOODMAN	MST273G22MHAA	Combination heat pumps with or without ducts		22,600	\$3,164
214438128	GOODMAN	MST273G22MHAA	Heat pump without ducts		22,400	\$3,136
215324962	GRANDAIR	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324963	GRANDAIR	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324964	GRANDAIR	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324965	GRANDAIR	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324967	GRANDAIR	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324966	GRANDAIR	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324968	GRANDAIR	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324969	GRANDAIR	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215357652	GRANDAIR	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215357653	GRANDAIR	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357654	GRANDAIR	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357661	GRANDAIR	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215357662	GRANDAIR	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357663	GRANDAIR	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357664	GRANDAIR	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357665	GRANDAIR	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357666	GRANDAIR	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357667	GRANDAIR	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357668	GRANDAIR	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357669	GRANDAIR	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357670	GRANDAIR	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357671	GRANDAIR	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357672	GRANDAIR	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357689	GRANDAIR	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215413367	GRANDAIR	D5CPRAH12AAK	D5FPHAH12XAK		11,000	\$1,540
215413368	GRANDAIR	D5CPRAH18AA	D5FPHAH18XAK		19,300	\$2,702
215324914	GRANDAIR	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215324916	GRANDAIR	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324915	GRANDAIR	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215324917	GRANDAIR	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324918	GRANDAIR	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215324919	GRANDAIR	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215324920	GRANDAIR	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215324921	GRANDAIR	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324922	GRANDAIR	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324923	GRANDAIR	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324924	GRANDAIR	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324925	GRANDAIR	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324926	GRANDAIR	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324927	GRANDAIR	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324929	GRANDAIR	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324930	GRANDAIR	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324931	GRANDAIR	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215319217	GRANDAIR	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215319218	GRANDAIR	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215319219	GRANDAIR	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215319212	GRANDAIR	D5CSHAH18AAK	D5FSAAH18XBK		14,000	\$1,960
215319213	GRANDAIR	D5CSHAH24AAK	D5FSAAH24XBK		16,900	\$2,366
215319214	GRANDAIR	D5CSHAH33AAK	D5FSAAH36XBK		27,400	\$3,836
215319195	GRANDAIR	D5CUHAH18AAK	D5FUAH18XAK		15,000	\$2,100
215319209	GRANDAIR	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215319196	GRANDAIR	D5CUHAH24AAK	D5FUAH24XAK		20,000	\$2,800
215319197	GRANDAIR	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215319210	GRANDAIR	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215319198	GRANDAIR	D5CUHAH30AAK	D5FUAH30XAK		23,800	\$3,332
215319199	GRANDAIR	D5CUHAH36AAK	D5FUAH36XAK		31,800	\$4,452
215323736	GRANDAIR	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215319200	GRANDAIR	D5CUHAH48AAK	D5FUAH48XAK		37,000	\$5,180
215319211	GRANDAIR	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215319201	GRANDAIR	D5CUHAH60AAK	D5FUAH60XAK		45,000	\$6,300
215319202	GRANDAIR	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215319204	GRANDAIR	D5CURAH24AAK	D5FUAH24XAK		20,000	\$2,800
215319207	GRANDAIR	D5CURAH48AAK	D5FUAH48XAK		32,400	\$4,536
217123259	GREE	FXU60HP230V1R32AO	FXE60HP230V1R32AH		45,000	\$6,300
217123258	GREE	FXU60HP230V1R32AO	FXE48HP230V1R32AH		39,500	\$5,530
217123257	GREE	FXU36HP230V1R32AO	FXE36HP230V1R32AH		28,200	\$3,948
217123256	GREE	FXU36HP230V1R32AO	FXE24HP230V1R32AH		20,600	\$2,884
217120762	GREE	GUD60W2/NHE-D(U)	GUD60AH2/G-D(U)		45,000	\$6,300
217120761	GREE	GUD60W2/NHE-D(U)	GUD48AH2/G-D(U)		39,500	\$5,530

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
217120760	GREE	GUD36W2/NHE-D(U)	GUD36AH2/G-D(U)		28,200	\$3,948
217120759	GREE	GUD36W2/NHE-D(U)	GUD24AH2/G-D(U)		20,600	\$2,884
217052374	GREE	GUD18W2/NHE-D(U)	GUD18AH2/E-D(U)		14,500	\$2,030
217052373	GREE	GUD12W2/NHE-D(U)	GUD12AH2/E-D(U)		13,700	\$1,918
216765690	GREE	GWH12AUCXD-D6DNA1E/O	GWH12AUCXD-D6DN***I		7,500	\$1,050
214931600	GREE	GWHD(42)ND6MO	Combination heat pumps with or without ducts		40,000	\$5,600
214931599	GREE	GWHD(36)ND6MO	Combination heat pumps with or without ducts		36,000	\$5,040
214931598	GREE	GWHD(30)ND6MO	Combination heat pumps with or without ducts		27,600	\$3,864
214931597	GREE	GWHD(24)ND6MO	Combination heat pumps with or without ducts		23,000	\$3,220
214931592	GREE	GWHD(18)ND6MO	Combination heat pumps with or without ducts		15,400	\$2,156
214931590	GREE	GWHD(42)ND6MO	Heat pump without ducts		40,000	\$5,600
214931589	GREE	GWHD(36)ND6MO	Heat pump without ducts		36,000	\$5,040
214931588	GREE	GWHD(30)ND6MO	Heat pump without ducts		28,000	\$3,920
214931587	GREE	GWHD(24)ND6MO	Heat pump without ducts		23,600	\$3,304
214931586	GREE	GWHD(18)ND6MO	Heat pump without ducts		16,000	\$2,240
10146838	GREE	GWH15QD-D3DNA5G/O	GWH15QD-D3DN***I		10,100	\$1,414
206249116	GREE	GUD36W/A-D(U)	GUD24AH2/A-D(U)		20,000	\$2,800
206249117	GREE	GUD36W/A-D(U)	GUD36AH2/A-D(U)		29,000	\$4,060
206249118	GREE	GUD60W/A-D(U)	GUD60AH2/A-D(U)		44,000	\$6,160
206249119	GREE	GUD60W/A-D(U)	GUD48AH2/A-D(U)		39,500	\$5,530
207256440	GREE	FLEXX36HP230V1AO	FLEXX24HP230V1BH		20,000	\$2,800
207256441	GREE	FLEXX36HP230V1AO	FLEXX36HP230V1BH		29,000	\$4,060
207256442	GREE	FLEXX60HP230V1AO	FLEXX60HP230V1BH		44,000	\$6,160
207256443	GREE	FLEXX60HP230V1AO	FLEXX48HP230V1BH		39,500	\$5,530
9102074	GREE	GWH18YE-D3DNA1A/O	GWH18QE-D3DN***I		15,100	\$2,114
9102794	GREE	GWH24YE-D3DNA1A/O	GWH24QE-D3DN***I		20,000	\$2,800
9114294	GREE	GWH18YE-D3DNA1A/O	GWH18AAE-D3DN***I		15,100	\$2,114
9116197	GREE	GWH12YD-D3DNA1A/O	GWH12QD-D3DN***I		10,300	\$1,442
9123256	GREE	GWH24YE-D3DNA1A/O	GWH24AAE-D3DN***I		20,000	\$2,800
9944776	GREE	GWH12YD-D3DNA1A/O	GWH12AAD-D3DN***I		10,300	\$1,442
10149903	GREE	SAP12HP230V1AO	SAP12HP230V1AH		10,300	\$1,442
10157570	GREE	SAP18HP230V1AO	SAP18HP230V1AH		15,100	\$2,114
10157571	GREE	SAP24HP230V1AO	SAP24HP230V1AH		20,000	\$2,800

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
202557960	GREE	GWHD(18)ND3JO	Heat pump without ducts		17,000	\$2,380
202557961	GREE	GWHD(24)ND3JO	Heat pump without ducts		17,900	\$2,506
203989085	GREE	MULTIU18HP230V1DO	Heat pump without ducts		17,000	\$2,380
203989086	GREE	MULTIU24HP230V1DO	Heat pump without ducts		17,900	\$2,506
208071173	GREE	GWH12AGCXD-D3DNA1A/O	GWH12AGCXD-D3DN***I		10,000	\$1,400
208120572	GREE	GWH12AGCXD-D3DNA1A/O	GWH12QCXD-D3DN***I		10,000	\$1,400
208158334	GREE	GWH24AGEXH-D3DNA1A/O	GFH(24)DB-D3DN***I		19,400	\$2,716
208786087	GREE	GWHD(36)ND3MO	Heat pump without ducts		30,800	\$4,312
208786088	GREE	GWHD(42)ND3MO	Heat pump without ducts		35,600	\$4,984
208786089	GREE	GWHD(18)ND3MO	Heat pump without ducts		15,000	\$2,100
208786090	GREE	GWHD(24)ND3MO	Heat pump without ducts		23,600	\$3,304
208786091	GREE	GWHD(30)ND3MO	Heat pump without ducts		27,200	\$3,808
208786092	GREE	GWHD(18)ND3MO	Heat pump with ducts		15,000	\$2,100
208786093	GREE	GWHD(24)ND3MO	Heat pump with ducts		23,000	\$3,220
208786094	GREE	GWHD(30)ND3MO	Heat pump with ducts		26,800	\$3,752
208786095	GREE	GWHD(36)ND3MO	Heat pump with ducts		30,000	\$4,200
208786096	GREE	GWHD(42)ND3MO	Heat pump with ducts		32,400	\$4,536
208786097	GREE	GWHD(18)ND3MO	Combination heat pumps with or without ducts		15,000	\$2,100
208786098	GREE	GWHD(24)ND3MO	Combination heat pumps with or without ducts		23,200	\$3,248
208786099	GREE	GWHD(30)ND3MO	Combination heat pumps with or without ducts		27,000	\$3,780
208786100	GREE	GWHD(36)ND3MO	Combination heat pumps with or without ducts		30,400	\$4,256
208786101	GREE	GWHD(42)ND3MO	Combination heat pumps with or without ducts		34,000	\$4,760
208798357	GREE	GWH30QFXH-D3DNB2A/O	GWH30QFXH-D3DN***I		24,000	\$3,360
208798358	GREE	GWH36QFXH-D3DNB2B/O	GWH36QFXH-D3DN***I		27,800	\$3,892
209248922	GREE	GWH12AGCXD-D3DNA1A/O	GWH12AFCXD-D3DN***I		10,000	\$1,400
210278965	GREE	4LIV36HP230V1AO	4LIV36HP230V1AH		27,800	\$3,892
210278969	GREE	4LIV30HP230V1AO	4LIV30HP230V1AH		24,000	\$3,360
210278970	GREE	3VIR12HP230V1BO	3VIR12HP230V1AH		10,000	\$1,400

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210278973	GREE	MULTI18HP230V1EO	Heat pump without ducts		15,000	\$2,100
210278974	GREE	MULTI18HP230V1EO	Heat pump with ducts		15,000	\$2,100
210278975	GREE	MULTI24HP230V1EO	Heat pump without ducts		23,600	\$3,304
210278976	GREE	MULTI24HP230V1EO	Heat pump with ducts		23,000	\$3,220
210278977	GREE	MULTI30HP230V1EO	Heat pump without ducts		27,200	\$3,808
210278978	GREE	MULTI30HP230V1EO	Heat pump with ducts		26,800	\$3,752
210278979	GREE	MULTI36HP230V1EO	Heat pump without ducts		30,800	\$4,312
210278980	GREE	MULTI36HP230V1EO	Heat pump with ducts		30,000	\$4,200
210278981	GREE	MULTI42HP230V1EO	Heat pump without ducts		35,600	\$4,984
210278982	GREE	MULTI42HP230V1EO	Heat pump with ducts		32,400	\$4,536
210485365	GREE	GWHD(36)ND3NO	Heat pump without ducts		30,800	\$4,312
210485366	GREE	GWHD(42)ND3NO	Heat pump without ducts		35,600	\$4,984
211078862	GREE	GWH18QDXF-D3DNB2A/O	GWH18AFDXF-D3DN***/I		14,600	\$2,044
216618245	GREE	GWH24AVEXH-D6DNA1B/O	GTH(24)CB-D6DN***/I		20,000	\$2,800
216618244	GREE	GWH24AVEXH-D6DNA1B/O	GFH(24)DB-D6DN***/I		20,000	\$2,800
216618237	GREE	GWH18AVEXF-D6DNA1B/O	GTH(18)CA-D6DN***/I		15,500	\$2,170
216618236	GREE	GWH18AVEXF-D6DNA1B/O	GKH(18)EB-D6DN***/I		15,500	\$2,170
216618235	GREE	GWH18AVEXF-D6DNA1B/O	GKH(18)DA-D6DN***/I		15,500	\$2,170
216618234	GREE	GWH18AVEXF-D6DNA1B/O	GFH(18)DB-D6DN***/I		15,500	\$2,170
216618233	GREE	GWH18AGDXF-D6DNA4B/O	GEH(18)AA-D6DN***/I		14,700	\$2,058
216618232	GREE	GWH18AGDXF-D6DNA4B/O	GTH(18)CA-D6DN***/I		14,700	\$2,058
216618231	GREE	GWH18AGDXF-D6DNA4B/O	GFH(18)DB-D6DN***/I		14,700	\$2,058
216618225	GREE	GWH12AVDXE-D6DNA1B/O	GEH(12)AA-D6DNA1A/I		10,300	\$1,442
216618224	GREE	GWH12AVDXE-D6DNA1B/O	GTH(12)CA-D6DN***/I		10,300	\$1,442
216618223	GREE	GWH12AVDXE-D6DNA1B/O	GKH(12)DA-D6DN***/I		10,300	\$1,442

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216618222	GREE	GWH12AVDXE-D6DNA1B/O	GKH(12)EB-D6DN***I		10,300	\$1,442
216618221	GREE	GWH12AVDXE-D6DNA1B/O	GFH(12)DA-D6DN***I		10,300	\$1,442
216618220	GREE	GWH18AGDXF-D6DNA4B/O	GKH(18)EB-D6DN***I		14,700	\$2,058
216618219	GREE	GWH18AGDXF-D6DNA4B/O	GKH(18)DA-D6DN***I		14,700	\$2,058
216618218	GREE	GWH24AGEXF-D6DNA4J/O	GTH(24)CB-D6DN***I		20,000	\$2,800
216618216	GREE	GWH24AGEXF-D6DNA4J/O	GFH(24)DB-D6DN***I		19,800	\$2,772
216618215	GREE	GWH12AGCXD-D6DNA4D/O	GEH(12)AA-D6DN***I		10,000	\$1,400
216618214	GREE	GWH12AGCXD-D6DNA4D/O	GTH(12)CA-D6DN***I		10,000	\$1,400
216618213	GREE	GWH12AGCXD-D6DNA4D/O	GKH(12)DA-D6DN***I		10,000	\$1,400
216618212	GREE	GWH12AGCXD-D6DNA4D/O	GKH(12)EB-D6DN***I		10,000	\$1,400
216618211	GREE	GWH12AGCXD-D6DNA4D/O	GFH(12)DA-D6DN***I		10,000	\$1,400
216573053	GREE	GWHD(48)ND6MO	Combination heat pumps with or without ducts		40,000	\$5,600
216573052	GREE	GWHD(48)ND6MO	Heat pump with ducts		40,000	\$5,600
216573051	GREE	GWHD(48)ND6MO	Heat pump without ducts		40,000	\$5,600
216571404	GREE	GWH24AWEXF-D6DNA1I/O	GWH24AUDXF-D6DN***I		19,000	\$2,660
216052270	GREE	GWH18AGDXF-D6DNA4B/O	GWH18AUDXF-D6DN***I		14,700	\$2,058
216032436	GREE	GWH12AGCXD-D6DNA4D/O	GWH12AUCXD-D6DN***I		10,000	\$1,400
215887359	GREE	GWH12ATCXB-A6DNA5B/O	GWH12ATCXB-A6DN***I		9,700	\$1,358
215725427	GREE	GWH30ATEXH-D6DNA1G/O	GWH30AWEXH-D6DN***I		24,000	\$3,360
215417460	GREE	VIR18HP230V1R32AO	FLR18HP230V1R32AH		14,700	\$2,058
215417453	GREE	ENV18HP230V1R32AO	FLR18HP230V1R32AH		14,700	\$2,058

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215416018	GREE	GWH18AVEXF-D6DNA1A/O	GKH(18)EB-D6DN***I		15,500	\$2,170
215415571	GREE	ENV12HP230V1R32AO	CON12HP230V1R32AH		10,000	\$1,400
215415568	GREE	ENV12HP230V1R32AO	CAS12HP230V1R32AH		10,000	\$1,400
215415567	GREE	ENV12HP230V1R32AO	DUC12HP230V1R32AH		10,000	\$1,400
215415566	GREE	VIR12HP230V1R32AO	CON12HP230V1R32AH		10,000	\$1,400
215415563	GREE	VIR12HP230V1R32AO	CAS12HP230V1R32AH		10,000	\$1,400
215415562	GREE	VIR12HP230V1R32AO	DUC12HP230V1R32AH		10,000	\$1,400
215415554	GREE	GWH18AUDXF-D6DNA1A/O	GTH(18)CA-D6DN***I		14,700	\$2,058
215415530	GREE	SAP12HP230V1R32AO	CON12HP230V1R32AH		10,300	\$1,442
215415528	GREE	SAP12HP230V1R32AO	CAS12HP230V1R32AH		10,300	\$1,442
215415527	GREE	SAP12HP230V1R32AO	DUC12HP230V1R32AH		10,300	\$1,442
215415524	GREE	GWH12AVDXE-D6DNA1A/O	GKH(12)EB-D6DN***I		10,300	\$1,442
215415523	GREE	GWH12AVDXE-D6DNA1A/O	GFH(12)DA-D6DN***I		10,300	\$1,442
215415520	GREE	ENV24HP230V1R32AO	FLR24HP230V1R32AH		20,000	\$2,800
215415518	GREE	ENV24HP230V1R32AO	DUC24HP230V1R32AH		19,800	\$2,772
215415517	GREE	VIR24HP230V1R32AO	FLR24HP230V1R32AH		20,000	\$2,800
215415515	GREE	VIR24HP230V1R32AO	DUC24HP230V1R32AH		19,800	\$2,772
215415514	GREE	GWH24AWEXF-D6DNA1I/O	GTH(24)CB-D6DN***I		20,000	\$2,800
215415512	GREE	GWH24AWEXF-D6DNA1I/O	GFH(24)DB-D6DN***I		19,800	\$2,772
215414351	GREE	GWH12AUCXD-D6DNA1B/O	GEH(12)AA-D6DN***I		10,000	\$1,400
215414348	GREE	GWH12AUCXD-D6DNA1B/O	GKH(12)EB-D6DN***I		10,000	\$1,400
215414347	GREE	GWH12AUCXD-D6DNA1B/O	GFH(12)DA-D6DN***I		10,000	\$1,400
215402266	GREE	GWH12AGCXD-D6DNA4D/O	GWH12AGCXD-D6DN***I		10,000	\$1,400
215402236	GREE	GWH12ATCXB-D6DNA4B/O	GWH12ATCXB-D6DN***I		9,700	\$1,358
215390442	GREE	GWH24ATEXF-D6DNA4H/O	GWH24ATEXF-D6DN***I		19,200	\$2,688
215387336	GREE	GWH18AGDXF-D6DNA4B/O	GWH18AGDXF-D6DN***I		14,700	\$2,058

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215386340	GREE	GWH18AVEXF-D6DNA1B/O	GWH18**EXF-D6DN***/I		15,500	\$2,170
215386339	GREE	GWH24AVEXH-D6DNA1B/O	GWH24***XH-D6DN***/I		20,000	\$2,800
215386290	GREE	GWH12AVDXE-D6DNA1B/O	GWH12AVDXE-D6DN***/I		10,300	\$1,442
215283088	GREE	SAP24HP230V1R32AO	SAP24HP230V1R32AH		20,000	\$2,800
215278609	GREE	GWH24AVEXH-D6DNA1A/O	GWH24AVEXH-D6DN***/I		15,000	\$2,100
215218927	GREE	MUL42HP230V1R32AO	Combination heat pumps with or without ducts		40,000	\$5,600
215218926	GREE	MUL36HP230V1R32AO	Combination heat pumps with or without ducts		36,000	\$5,040
215218925	GREE	MUL30HP230V1R32AO	Combination heat pumps with or without ducts		27,600	\$3,864
215218924	GREE	MUL24HP230V1R32AO	Combination heat pumps with or without ducts		23,000	\$3,220
215218923	GREE	MUL18HP230V1R32AO	Combination heat pumps with or without ducts		15,400	\$2,156
215218922	GREE	MUL42HP230V1R32AO	Heat pump with ducts		40,000	\$5,600
215218921	GREE	MUL36HP230V1R32AO	Heat pump with ducts		36,000	\$5,040
215218920	GREE	MUL30HP230V1R32AO	Heat pump with ducts		27,200	\$3,808
215218919	GREE	MUL24HP230V1R32AO	Heat pump with ducts		22,000	\$3,080
215218918	GREE	MUL18HP230V1R32AO	Heat pump with ducts		15,000	\$2,100
215218917	GREE	MUL42HP230V1R32AO	Heat pump without ducts		40,000	\$5,600
215218916	GREE	MUL36HP230V1R32AO	Heat pump without ducts		36,000	\$5,040
215218915	GREE	MUL30HP230V1R32AO	Heat pump without ducts		28,000	\$3,920
215218914	GREE	MUL24HP230V1R32AO	Heat pump without ducts		23,600	\$3,304
215218913	GREE	MUL18HP230V1R32AO	Heat pump without ducts		16,000	\$2,240
214931596	GREE	GWHD(42)ND6MO	Heat pump with ducts		40,000	\$5,600
214931595	GREE	GWHD(36)ND6MO	Heat pump with ducts		36,000	\$5,040
214931594	GREE	GWHD(30)ND6MO	Heat pump with ducts		27,200	\$3,808
214931593	GREE	GWHD(24)ND6MO	Heat pump with ducts		22,000	\$3,080
214931591	GREE	GWHD(18)ND6MO	Heat pump with ducts		15,000	\$2,100
214813257	GREE	VIR12HP230V1R32AO	VIR12HP230V1R32AH		10,000	\$1,400
214802443	GREE	LIV30HP230V1R32AO	LIV30HP230V1R32AH		24,000	\$3,360
214797816	GREE	GWH30ATEXH-D6DNA1G/O	GWH30ATEXH-D6DN***/I		24,000	\$3,360

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214796624	GREE	GWH12AUCXD-D6DNA1B/O	GWH12AGCXD-D6DN***/I		10,000	\$1,400
214779344	GREE	ENV12HP230V1R32AO	ENV12HP230V1R32AH		10,000	\$1,400
214568849	GREE	GWH36ATEXH-D6DNA1G/O	GWH36ATEXH-D6DN***/I		27,400	\$3,836
214387779	GREE	SAP12HP230V1AO	SAP12HP230V1AH*		10,300	\$1,442
214075152	GREE	GWH18QDXF-D3DNB2A/O	GWH18AFDXF-D3DNA1A/I		14,600	\$2,044
213927625	GREE	GWH12AUCXD-D6DNA1B/O	GWH12AUCXD-D6DN***/I		10,000	\$1,400
211755706	GREE	3VIR12HP230V1BO	3VIR12HP230V1BH		10,000	\$1,400
211752944	GREE	GWHD(18)ND3PO	Heat pump without ducts		15,200	\$2,128
211726658	GREE	3VIR24HP230V1BO	DUCT24HP230V1BD		19,400	\$2,716
211726655	GREE	3VIR18HP230V1BO	DUCT18HP230V1BD		14,600	\$2,044
211497198	GREE	GWH18QDXF-D3DNB2A/O	GFH(18)DB-D3DN***/I		14,600	\$2,044
211497195	GREE	GWH18AGDXF-D3DNA1A/O	GFH(18)DB-D3DN***/I		14,600	\$2,044
210278961	GREE	4LIV12HP230V1AO	4LIV12HP230V1AH		9,700	\$1,358
209276088	GREE	GWH12ATCXB-D3DNA1C/O	GWH12ATCXB-D3DN***/I		9,700	\$1,358
216765698	GREE	GUD60W2/NXF-D(U)	GCAC60H/NXA		35,200	\$4,928
216768112	GREE	GUD60W2/NXF-D(U)	GCAC48H/NXA		31,200	\$4,368
216765696	GREE	GUD36W2/NXF-D(U)	GCAC36F/NXA		22,000	\$3,080
216768111	GREE	GUD36W2/NXF-D(U)	GCAC24F/NXA		15,000	\$2,100
216765694	GREE	GUD60W2/NHE-D(U)	GCAC60H/NHA		35,200	\$4,928
216768110	GREE	GUD60W2/NHE-D(U)	GCAC48H/NHA		31,200	\$4,368
216765692	GREE	GUD36W2/NHE-D(U)	GCAC36F/NHA		22,000	\$3,080
216768109	GREE	GUD36W2/NHE-D(U)	GCAC24F/NHA		15,000	\$2,100
216626011	GREE	FXE60HP230V1R32AO	FXE60HP230V1R32AH		43,000	\$6,020
216626010	GREE	FXE60HP230V1R32AO	FXE48HP230V1R32AH		38,500	\$5,390
216626006	GREE	GUD60W2/NXF-D(U)	GUD48AH2/F-D(U)		39,000	\$5,460
216626005	GREE	GUD36W2/NXF-D(U)	GUD24AH2/F-D(U)		20,000	\$2,800
216621484	GREE	GUD60W2/NHE-D(U)	GUD48AH2/E-D(U)		39,500	\$5,530
216621482	GREE	GUD36W2/NHE-D(U)	GUD24AH2/E-D(U)		20,600	\$2,884
216621481	GREE	GUD60W2/NHG-D(U)	GUD48AH2/G-D(U)		38,500	\$5,390
215889445	GREE	GUD48W2/NHG-D(U)	GUD48AH2/G-D(U)		38,500	\$5,390
215889444	GREE	GUD60W2/NHG-D(U)	GUD60AH2/G-D(U)		43,000	\$6,020
215494740	GREE	GUD48W2/NXF-D(U)	GUD48AH2/F-D(U)		39,000	\$5,460

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215494739	GREE	GUD36W2/NXF-D(U)	GUD36AH2/F-D(U)		28,200	\$3,948
215494738	GREE	GUD24W2/NXF-D(U)	GUD24AH2/F-D(U)		20,000	\$2,800
215213332	GREE	FXU60HP230V1R32AO	FXU60HP230V1R32AH		45,000	\$6,300
215213331	GREE	FXU48HP230V1R32AO	FXU48HP230V1R32AH		39,500	\$5,530
215213330	GREE	FXU36HP230V1R32AO	FXU36HP230V1R32AH		28,200	\$3,948
215213329	GREE	FXU24HP230V1R32AO	FXU24HP230V1R32AH		20,600	\$2,884
214568857	GREE	GUD60W2/NHE-D(U)	GUD60AH2/E-D(U)		45,000	\$6,300
214568858	GREE	GUD48W2/NHE-D(U)	GUD48AH2/E-D(U)		39,500	\$5,530
214568826	GREE	GUD36W2/NHE-D(U)	GUD36AH2/E-D(U)		28,200	\$3,948
214610240	GREE	GUD24W2/NHE-D(U)	GUD24AH2/E-D(U)		20,600	\$2,884
214333171	GREE	FLEXX24HP230V1AO	FLEXX24C		20,000	\$2,800
214303507	GREE	GUD24W/A-D(U)	GCAT24*/NAA		20,000	\$2,800
214138028	GREE	GUD42W2/D-D(U)	GCAT24*/NAA		19,600	\$2,744
212924813	GREE	FLEXX60HP230V1AO	ENVBR60HPJ11B		44,000	\$6,160
212924812	GREE	FLEXX60HP230V1AO	ENVBR48HPJ11B		39,500	\$5,530
212924811	GREE	FLEXX36HP230V1AO	ENVBR36HPJ11B		29,000	\$4,060
212924810	GREE	FLEXX36HP230V1AO	ENVBR24HPJ11B		20,000	\$2,800
211717300	GREE	FLEXX60HP230V1AO	FLEXX60C		44,500	\$6,230
211717299	GREE	FLEXX60HP230V1AO	FLEXX48C		39,000	\$5,460
211717298	GREE	FLEXX36HP230V1AO	FLEXX36C		23,200	\$3,248
211717297	GREE	FLEXX36HP230V1AO	FLEXX24C		19,600	\$2,744
211644153	GREE	GUD60W/A-D(U)	GCAT60*/NAA		44,500	\$6,230
211644152	GREE	GUD60W/A-D(U)	GCAT48*/NAA		39,000	\$5,460
211644151	GREE	GUD36W/A-D(U)	GCAT36*/NAA		23,200	\$3,248
211644150	GREE	GUD36W/A-D(U)	GCAT24*/NAA		19,600	\$2,744
210278987	GREE	MULTI42HP230V1EO	Combination heat pumps with or without ducts		34,000	\$4,760
210278986	GREE	MULTI36HP230V1EO	Combination heat pumps with or without ducts		30,400	\$4,256
210278985	GREE	MULTI30HP230V1EO	Combination heat pumps with or without ducts		27,000	\$3,780
210278984	GREE	MULTI24HP230V1EO	Combination heat pumps with or without ducts		23,200	\$3,248
210278983	GREE	MULTI18HP230V1EO	Combination heat pumps with or without ducts		14,300	\$2,002
211698448	GREE	GMV-V36WL/C-T(U)	Heat pump without ducts		22,000	\$3,080
211698447	GREE	GMV-V48WL/C-T(U)	Heat pump without ducts		30,000	\$4,200
211694660	GREE	GMV-V60WL/C-T(U)	Heat pump without ducts		42,000	\$5,880

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
8654210	GREE	GMV-48WL/B-T(U)	Heat pump with ducts		38,000	\$5,320
7280511	GREE	GUHD42ND3FO	GFH42D3FI		24,800	\$3,472
7280525	GREE	GUHD48ND3FO	GFH48D3FI		30,600	\$4,284
7607469	GREE	GWH18UC-D3DNA4C/O	GWH18UC-D3DN***I		12,717	\$1,780
8654209	GREE	GMV-36WL/B-T(U)	Heat pump with ducts		29,400	\$4,116
8654208	GREE	GMV-36WL/B-T(U)	Heat pump without ducts		29,400	\$4,116
10392955	GREE	GWHD(48S)HD3DO	Heat pump with ducts		37,000	\$5,180
204043222	GREE	GUD36W/A-D(U)	GUD36A/A-D(U)		24,400	\$3,416
10384787	GREE	GWHD(48S)HD3DO	Heat pump without ducts		38,000	\$5,320
205747610	GREE	GUD60W/A-D(U)	GUD48A/A-D(U)		32,800	\$4,592
205564529	GREE	GUD36W/A-D(U)	GUD24A/A-D(U)		16,300	\$2,282
205724738	GREE	GUD60W/A-D(U)	GUD60A/A-D(U)		37,200	\$5,208
205993850	GREE	FLEX60HP230V1AO	FLEX48HP230V1AH		33,000	\$4,620
205993849	GREE	FLEX36HP230V1AO	FLEX24HP230V1AH		16,300	\$2,282
205984663	GREE	FLEX36HP230V1AO	FLEX36HP230V1AH		24,400	\$3,416
205984664	GREE	FLEX60HP230V1AO	FLEX60HP230V1AH		38,000	\$5,320
202557965	GREE	GWHD(18)ND3JO	Heat pump without ducts		17,000	\$2,380
8654211	GREE	GMV-48WL/B-T(U)	Heat pump without ducts		38,000	\$5,320
8796414	GREE	GMV-36WL/B-T(U)	Combination heat pumps with or without ducts		29,400	\$4,116
8654212	GREE	GMV-48WL/B-T(U)	Combination heat pumps with or without ducts		38,000	\$5,320
215225062	GUARDIAN	UMC18CN23STG1	Heat pump without ducts		11,500	\$1,610
215747714	GUARDIAN	UMC18CN23STG1	Heat pump with ducts		11,900	\$1,666
215747715	GUARDIAN	UMC18CN23STG1	Combination heat pumps with or without ducts		11,700	\$1,638
215225063	GUARDIAN	UMC24CN23STG1	Heat pump without ducts		17,600	\$2,464
215747717	GUARDIAN	UMC24CN23STG1	Combination heat pumps with or without ducts		18,000	\$2,520
215747716	GUARDIAN	UMC24CN23STG1	Heat pump with ducts		18,200	\$2,548
215747721	GUARDIAN	UMC36CN23STG1	Heat pump with ducts		21,000	\$2,940
215747723	GUARDIAN	UMC36CN23STG1	Combination heat pumps with or without ducts		21,800	\$3,052
215747722	GUARDIAN	UMC36CN23STG1	Heat pump without ducts		22,600	\$3,164
215747719	GUARDIAN	UMC48CN23STG1	Heat pump without ducts		28,200	\$3,948
215747720	GUARDIAN	UMC48CN23STG1	Combination heat pumps with or without ducts		27,800	\$3,892
215747718	GUARDIAN	UMC48CN23STG1	Heat pump with ducts		27,400	\$3,836
215439627	GUARDIAN	UPC12CN23STG1	UNI12HW23STG1		8,900	\$1,246

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215743600	GUARDIAN	UPC18CN23STG1	UNI18HW23STG1		13,400	\$1,876
216445265	GUARDIAN	UPC18CN23STG1	UNI18DT23STG1		13,200	\$1,848
216017246	GUARDIAN	UPC24CN23STG1	UNI24HW23STG1		17,000	\$2,380
216019853	GUARDIAN	UPC24CN23STG1	UNI24CS23STG1		19,100	\$2,674
216445266	GUARDIAN	UPC24CN23STG1	UNI24DT23STG1		18,200	\$2,548
216346013	GUARDIAN	UPC36CN23STG1	UNI36HW23STG1		26,000	\$3,640
215270361	GUARDIAN	URC12CN15STG1	URD12HW15STG1		9,300	\$1,302
214803265	GUARDIAN	URC12CN23STG1	UNI12HW23STG1		10,800	\$1,512
214803266	GUARDIAN	URC18CN23STG1	UNI18HW23STG1		18,000	\$2,520
214803267	GUARDIAN	URC24CN23STG1	UNI24HW23STG1		22,000	\$3,080
217124724	HAIER	1Q24TE2BE**	QS24WB2BE**		14,400	\$2,016
217124723	HAIER	1Q18TE2BE**	QS18WB2BE**		12,000	\$1,680
216968346	HAIER	1Q3036FF2BE**	QS30WB2BE**		18,600	\$2,604
216968345	HAIER	1Q24FF2BE**	QS24WB2BE**		14,400	\$2,016
216968344	HAIER	1Q18FF2BE**	QS18WB2BE**		12,000	\$1,680
216968343	HAIER	1Q15FF2BE**	QS15WB2BE**		10,200	\$1,428
217036487	HAIER	1Q18ED2BE**	US18FB2BE**		14,400	\$2,016
217036486	HAIER	1Q12ED2BE**	US12FB2BE**		9,400	\$1,316
217036493	HAIER	1Q18ED2BE**	US18MB2BE**		17,000	\$2,380
217036490	HAIER	1Q18ED2BE**	US18CB2BE**		14,400	\$2,016
217036489	HAIER	1Q12ED2BE**	US12CB2BE**		9,600	\$1,344
206389351	HAIER	1U12EH2VHE*	AW12EH2VHD*		9,300	\$1,302
210082199	HAIER	3U24EH2HD**	Heat pump with ducts		17,400	\$2,436
210082198	HAIER	3U24EH2HD**	Heat pump without ducts		17,000	\$2,380
210151026	HAIER	2U20EH2HD**	Heat pump with ducts		14,800	\$2,072
210082195	HAIER	2U20EH2HD**	Heat pump without ducts		14,000	\$1,960
206445820	HAIER	1U18EH2VHE*	AW18EH2VHD*		15,300	\$2,142
215876550	HAIER	1Q18RT2BE**	QS18WP2BE**		12,000	\$1,680
215876549	HAIER	1Q12RT2BE**	QS12WP2BE**		8,700	\$1,218
206608651	HAIER	1U18EH2VHE*	USYM18UCDSA*		15,000	\$2,100
206389354	HAIER	1U12EH2VHE*	USYM12UCDSA*		9,300	\$1,302
202449650	HAIER	3U24EH2VHA	Heat pump without ducts		16,000	\$2,240
202449649	HAIER	2U20EH2VHA	Heat pump without ducts		14,000	\$1,960
211744602	Haier	1U3036LP2HD**	USYL30UCDD**		22,000	\$3,080
211744601	Haier	1U24LP2HD**	AW24TL2HF**		17,000	\$2,380
210082201	HAIER	4U36EH2HD**	Heat pump without ducts		23,600	\$3,304
212409448	HAIER	1U12EH2HE**	AW12EH2HE**		10,800	\$1,512
212409449	HAIER	1U18EH2HE**	AW18EH2HE**		15,300	\$2,142

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206389356	HAIER	1U12EH2VHE*	AB12SC2VHA*		8,500	\$1,190
215588561	HAVELLS	GSSHAX7641	Heat pump without ducts		12,000	\$1,680
215588562	HAVELLS	GSSHAX7642	Heat pump without ducts		23,600	\$3,304
215588563	HAVELLS	GSSHAX7643	Heat pump without ducts		27,200	\$3,808
215864436	HAVELLS	GSSHAX7644	Heat pump without ducts		27,200	\$3,808
205921365	HAXXAIR	HVHSC-12T2D	HAHC-12T2D		7,600	\$1,064
208650724	HAXXAIR	HVHM-18T2D	Heat pump without ducts		12,700	\$1,778
204628477	HAXXAIR	HVH-24T2D	HAH-24T2D		14,500	\$2,030
204032227	HAXXAIR	HVHM-36T2D	Combination heat pumps with or without ducts		22,600	\$3,164
204628475	HAXXAIR	HVH-12T2D	HAH-12T2D		7,500	\$1,050
208650723	HAXXAIR	HVHM-18T2D	Heat pump with ducts		12,700	\$1,778
212396481	HAXXAIR	HVHM-42T2D	Combination heat pumps with or without ducts		27,600	\$3,864
212510995	HAXXAIR	HVHM-42T2D	Heat pump with ducts		28,400	\$3,976
204032226	HAXXAIR	HVHM-24T2D	Combination heat pumps with or without ducts		14,800	\$2,072
205921367	HAXXAIR	HVHSC-18T2D	HAHC-18T2D		12,000	\$1,680
204032225	HAXXAIR	HVHM-36T2D	Heat pump with ducts		23,000	\$3,220
212510994	HAXXAIR	HVHM-42T2D	Heat pump without ducts		27,000	\$3,780
204628476	HAXXAIR	HVH-18T2D	HAH-18T2D		10,000	\$1,400
207036462	HAXXAIR	HVHD-24E2D2	HAHD-24E2D2		16,000	\$2,240
214855369	HAXXAIR	HVHSC-24T2D	HAH-24T2D		19,000	\$2,660
204032224	HAXXAIR	HVHM-24T2D	Heat pump with ducts		14,600	\$2,044
204100526	HAXXAIR	HVHM-36T2D	Heat pump without ducts		22,400	\$3,136
207036468	HAXXAIR	HVHD-36E2D2	HAHD-36E2D2		24,000	\$3,360
207036473	HAXXAIR	HVHD-48E2D2	HAHD-48E2D2		31,000	\$4,340
204198639	HAXXAIR	HVHM-24T2D	Heat pump without ducts		15,000	\$2,100
214855370	HAXXAIR	HVHSC-36T2D	HAH-36T2D		28,000	\$3,920
216707872	HAXXAIR	HVHMZ-42V2D	Heat pump without ducts		28,200	\$3,948
216707865	HAXXAIR	HVHMZ-18V2D	Heat pump without ducts		11,500	\$1,610
216014851	HAXXAIR	HVHDZ-36V2D	HAHDZ-36V2D		32,000	\$4,480
216707875	HAXXAIR	HVHMZ-36V2D	Heat pump without ducts		22,600	\$3,164
216707873	HAXXAIR	HVHMZ-42V2D	Combination heat pumps with or without ducts		27,800	\$3,892
216014853	HAXXAIR	HVHDZ-60V2D	HAHDZ-60V2D		37,000	\$5,180
216014852	HAXXAIR	HVHDZ-48V2D	HAHDZ-48V2D		36,600	\$5,124
216014850	HAXXAIR	HVHDZ-24V2D	HAHDZ-24V2D		20,400	\$2,856

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216012011	HAXXAIR	HVHZ-12V2D	HAHZ-12V2D		10,800	\$1,512
215887342	HAXXAIR	HVHZ-24V2D	HAHZ-24V2D		22,000	\$3,080
215887341	HAXXAIR	HVHZ-18V2D	HAHZ-18V2D		18,000	\$2,520
214855371	HAXXAIR	HVHSC-12T2D	HAH-12T2D		8,000	\$1,120
214855372	HAXXAIR	HVHSC-18T2D	HAH-18T2D		12,000	\$1,680
214264495	HAXXAIR	HVHD-48E2D2	DC61A44-245R		31,200	\$4,368
214264494	HAXXAIR	HVHD-36E2D2	DC37A44-210L		23,000	\$3,220
205726755	HAXXAIR	HVHD-36E2D	HAHD-36E2D		25,000	\$3,500
215682295	HEIL	H5H0V48*K*AAA*	EVD5X60M21A*+WALLCON	*96CTN0802120B*	46,500	\$6,510
215935666	HEIL	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL1102120B*	32,000	\$4,480
215940006	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN1202422A*	30,600	\$4,284
215676335	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*95CSU1002122B*	46,000	\$6,440
215682835	HEIL	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*80CSU1002120B*	56,000	\$7,840
215933236	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*96CTN0601714B*	30,200	\$4,228
215674146	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*96CTN1002122B*	42,500	\$5,950
215935656	HEIL	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0902120B*	32,000	\$4,480
215939996	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN1002122A*	30,600	\$4,284
215934366	HEIL	H5H3V48*K*AAA*	EA*5X61M24A*+WALLCON	*97CMN0602120B*	40,500	\$5,670
215676325	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL1352422B*	46,000	\$6,440
215933226	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*96CTN0401410B*	30,000	\$4,200
215682285	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*97CTN1202422A*	46,000	\$6,440
215682815	HEIL	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*80CSU0601716B*	54,000	\$7,560
215682275	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*97CTN1002122A*	46,000	\$6,440

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215939986	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN0802120A*	30,800	\$4,312
215676315	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL1102120B*	46,000	\$6,440
215935646	HEIL	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0901716B*	32,200	\$4,508
215674126	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN1002122B*	42,500	\$5,950
215933216	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN1202422B*	30,600	\$4,284
215939976	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN0801716A*	31,000	\$4,340
215676305	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL0902120B*	46,000	\$6,440
215682805	HEIL	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*80CSU0401712B*	54,000	\$7,560
215935636	HEIL	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0702120B*	32,200	\$4,508
215682265	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*97CTN0802120A*	46,000	\$6,440
215933206	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN1002122B*	30,600	\$4,284
215682795	HEIL	H5H0V60*K*AAA*	EVM5X60M21A*+WALLCON	*96CTN0802120B*	56,000	\$7,840
215682255	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CSU1002120B*	46,000	\$6,440
215939966	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CTN0601716A*	31,400	\$4,396
215676295	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CTL0702120B*	46,500	\$6,510
215674116	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN0802120B*	42,500	\$5,950
215933196	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0802120B*	30,600	\$4,284
215935626	HEIL	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0701716B*	32,400	\$4,536
215939956	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*80CSU0601716B*	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215676275	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*96CTN1202422B*	45,500	\$6,370
215674106	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN0801714B*	43,000	\$6,020
215935616	HEIL	H5H3V36*K*AAA*	EVD5X36M21A*+WALLCON	*80CTL0451712B*	33,000	\$4,620
215933186	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0801714B*	31,200	\$4,368
215682245	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*80CSU0802120B*	46,000	\$6,440
215682775	HEIL	H5H0V60*K*AAA*	ESH5X60M12A*+WALLCON	*97CTN1002122A*	51,500	\$7,210
215939946	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*80CSU0401712B*	30,600	\$4,284
215676265	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CMN1202422B*	45,500	\$6,370
215682235	HEIL	H5H0V48*K*AAA*	EVD5X49M24A*+WALLCON	*96CTN0802120B*	46,000	\$6,440
215674096	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*97CMN0602120B*	43,000	\$6,020
215935576	HEIL	H5H3V36*K*AAA*	EVD5X36M17A*+WALLCON	*96CTN0601714B*	30,600	\$4,284
215939936	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*96CTN0802120B*	30,800	\$4,312
215676255	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CMN0802120B*	45,500	\$6,370
215933176	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0602120B*	31,000	\$4,340
215674086	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*95CSU0802120B*	42,500	\$5,950
215935566	HEIL	H5H3V36*K*AAA*	EVD5X36M17A*+WALLCON	*97CMN0601714B*	30,600	\$4,284
215682765	HEIL	H5H0V60*K*AAA*	ESH5X60M12A*+WALLCON	*97CTN0802120A*	51,500	\$7,210
215934286	HEIL	H5H3V48*K*AAA*	EA*5X61M21A*+WALLCON	*96CTN1002122B*	40,000	\$5,600
215933166	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*97CMN0601714B*	30,200	\$4,228

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215682225	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CTN1202422A*	45,500	\$6,370
215676245	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*95CSU1002122B*	45,500	\$6,370
215682215	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CTN1002122A*	45,500	\$6,370
215674076	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*95CSU0601716B*	43,000	\$6,020
215935556	HEIL	H5H3V36*K*AAA*	EVD5X31M17A*+WALLCON	*96CTN0601714B*	31,800	\$4,452
215676235	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*95CSU0802120B*	46,000	\$6,440
215933156	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*95CSU1002122B*	30,400	\$4,256
215933146	HEIL	H5H3V36*K*AAA*	ESH5X36M12A*+WALLCON	*95CSU0802120B*	30,800	\$4,312
215674066	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL1102120B*	42,500	\$5,950
215682205	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*97CTN0802120A*	46,000	\$6,440
215676225	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL1352422B*	45,500	\$6,370
215674056	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0902120B*	42,500	\$5,950
215676215	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL1102120B*	45,500	\$6,370
215674046	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0901716B*	42,500	\$5,950
215676205	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL0902120B*	45,500	\$6,370
215674036	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0702120B*	42,500	\$5,950
215676195	HEIL	H5H0V48*K*AAA*	EVD5X48M24A*+WALLCON	*80CTL0702120B*	46,000	\$6,440
215674026	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0701716B*	43,000	\$6,020
215676165	HEIL	H5H0V48*K*AAA*	EVD5X48M21A*+WALLCON	*96CTN1002122B*	45,500	\$6,370

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215674016	HEIL	H5H0V48*K*AAA*	EA*5X48M21A*+WALLCON	*80CTL0451712B*	43,500	\$6,090
215662861	HEIL	H5H0V48*K*AAA*	FCMA5B48L0C*+WALLCON		42,000	\$5,880
207614966	HEIL	DLCPRBH12AAK	DLFPHBH12XAK		10,400	\$1,456
207826647	HEIL	DLCPRBH18AAK	DLFPHBH18XAK		20,200	\$2,828
206361885	HEIL	DLCSRBH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361887	HEIL	DLCSRBH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361886	HEIL	DLCSRBH18AAK	DLFSHBH18XAK		11,100	\$1,554
210857439	HEIL	DLCSRBH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857440	HEIL	DLCSRBH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132690	HEIL	DLCSRBH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948194	HEIL	DLCSRBH12AAK	DLFSFBH12XAK		10,200	\$1,428
207683348	HEIL	DLCSRBH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447639	HEIL	DLCSRBH24AAK	DLFSCH24XAK		21,200	\$2,968
208447643	HEIL	DLCSRBH18AAK	DLFSCH18XAK		15,000	\$2,100
208447638	HEIL	DLCSRBH12AAK	DLFSCH12XAK		10,000	\$1,400
206773940	HEIL	HVH848GKA2*	EA*4X60L24A*+WALLCON	*97CMN1002122A*	36,000	\$5,040
206773904	HEIL	HVH848GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	36,000	\$5,040
206773967	HEIL	HVH848GKA2*	EA*4X60L24A*+WALLCON	*96CTN1002122A*	36,000	\$5,040
206774902	HEIL	HVH848GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	36,000	\$5,040
206771758	HEIL	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0701716A*	31,600	\$4,424
211132724	HEIL	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
211132688	HEIL	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
206765547	HEIL	HVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
206765556	HEIL	HVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
206767543	HEIL	HVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
206773528	HEIL	HVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206767552	HEIL	HVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
206771902	HEIL	HVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	31,400	\$4,396
206766033	HEIL	HVH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
206774480	HEIL	HVH848GKA2*	EHD4X48AAL+WALLCON	*80CTL1352422A*	37,200	\$5,208
206771254	HEIL	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206773474	HEIL	HVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206773483	HEIL	HVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	31,600	\$4,424
206771272	HEIL	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206771353	HEIL	HVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206771722	HEIL	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206771776	HEIL	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206773420	HEIL	HVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206773429	HEIL	HVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	31,800	\$4,452
206773519	HEIL	HVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206774282	HEIL	HVH848GKA2*	EN(A,D)4X48L24**+WALLCON	*96CTN1202422A*	37,200	\$5,208
206771623	HEIL	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206774821	HEIL	HVH848GKA2*	EHD4X48AAL+WALLCON	*80CSU0802120A*	37,200	\$5,208
206773501	HEIL	HVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206771641	HEIL	HVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206771857	HEIL	HVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	31,400	\$4,396
206773510	HEIL	HVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206771893	HEIL	HVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
215324336	HEIL	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215323728	HEIL	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215324347	HEIL	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324346	HEIL	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324343	HEIL	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324341	HEIL	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324339	HEIL	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324338	HEIL	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324337	HEIL	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324334	HEIL	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324333	HEIL	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324332	HEIL	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324331	HEIL	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215413256	HEIL	D5CPRAH18AA	D5FPAH18XAK		19,300	\$2,702
215413255	HEIL	D5CPRAH12AAK	D5FPAH12XAK		11,000	\$1,540
215357285	HEIL	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357284	HEIL	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357283	HEIL	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215324342	HEIL	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324335	HEIL	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215357311	HEIL	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357294	HEIL	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357293	HEIL	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357292	HEIL	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357291	HEIL	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357290	HEIL	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357289	HEIL	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357288	HEIL	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357287	HEIL	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357286	HEIL	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357282	HEIL	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357281	HEIL	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357280	HEIL	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357276	HEIL	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357275	HEIL	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357274	HEIL	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324384	HEIL	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324382	HEIL	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324381	HEIL	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324379	HEIL	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324378	HEIL	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324345	HEIL	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324340	HEIL	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324385	HEIL	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324383	HEIL	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324380	HEIL	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324330	HEIL	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215318987	HEIL	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215318986	HEIL	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215318985	HEIL	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215318995	HEIL	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215318993	HEIL	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215318983	HEIL	D5CURAH48AAK	D5FUAAH48XAK		32,400	\$4,536
215318980	HEIL	D5CURAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215318978	HEIL	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215318977	HEIL	D5CUHAH60AAK	D5FUAAH60XAK		45,000	\$6,300
215318976	HEIL	D5CUHAH48AAK	D5FUAAH48XAK		37,000	\$5,180

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215318975	HEIL	D5CUHAH36AAK	D5FUAAH36XAK		31,800	\$4,452
215318974	HEIL	D5CUHAH30AAK	D5FUAAH30XAK		23,800	\$3,332
215318973	HEIL	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215318972	HEIL	D5CUHAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215318971	HEIL	D5CUHAH18AAK	D5FUAAH18XAK		15,000	\$2,100
215318994	HEIL	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215318990	HEIL	D5CSHAH33AAK	D5FSAAH36XBK		27,400	\$3,836
215318989	HEIL	D5CSHAH24AAK	D5FSAAH24XBK		16,900	\$2,366
215318988	HEIL	D5CSHAH18AAK	D5FSAAH18XBK		14,000	\$1,960
212982379	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80MSU0401712A*	12,200	\$1,708
212982403	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80MSU0401712A*	12,200	\$1,708
212982943	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MSU0802120A*	23,200	\$3,248
212982631	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MSU0601716A*	23,200	\$3,248
213079328	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0802120A*	29,200	\$4,088
212982439	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU0401712A*	12,300	\$1,722
212982391	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80MSU0401712A*	12,400	\$1,736
213078932	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	29,400	\$4,116
213078860	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MSU1002120A*	29,200	\$4,088
212982715	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80MSU0601716A*	18,600	\$2,604
213079184	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0601716A*	29,200	\$4,088
212982367	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0401712A*	19,100	\$2,674
212982175	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MSU0401712A*	23,200	\$3,248
212981683	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	23,600	\$3,304
212981539	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MSU1002120A*	29,000	\$4,060
213079280	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MSU0802120A*	29,000	\$4,060
212988042	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96MSN1002120A*	23,400	\$3,276
212982355	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU0401712A*	19,100	\$2,674
213078884	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MSU1002120A*	29,200	\$4,088
212988102	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	23,600	\$3,304
212988066	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96MSN1002120A*	23,600	\$3,304
212982283	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80MSU0401712A*	19,000	\$2,660
212982139	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80MSU0401712A*	23,400	\$3,276
212981599	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MSU1002120A*	23,200	\$3,248
213079016	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MSU0401712A*	29,000	\$4,060
212988054	HEIL	DLCURAH30ABK	EA*4X42L21A*	*96MSN1002120A*	23,600	\$3,304
212982343	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU0401712A*	19,100	\$2,674
212982307	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80MSU0401712A*	18,800	\$2,632
212982295	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MSU0401712A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982271	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80MSU0401712A*	19,100	\$2,674
213079316	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0802120A*	29,200	\$4,088
212981611	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80MSU1002120A*	23,600	\$3,304
213078908	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU1002120A*	29,600	\$4,144
212983003	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	23,600	\$3,304
213079052	HEIL	DLCURAH36ABK	END4X42L17**	*80MSU0401712A*	29,200	\$4,088
212982703	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MSU0601716A*	19,000	\$2,660
212982691	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	23,400	\$3,276
212982427	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU0401712A*	12,400	\$1,736
213079064	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0401712A*	29,400	\$4,116
213078992	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MSU0401712A*	29,000	\$4,060
213078956	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80MSU0401712A*	29,400	\$4,116
212982727	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0601716A*	19,000	\$2,660
212982667	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MSU0601716A*	23,200	\$3,248
212981623	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MSU1002120A*	23,200	\$3,248
212982415	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80MSU0401712A*	12,300	\$1,722
212982331	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU0401712A*	19,400	\$2,716
213079148	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MSU0601716A*	29,000	\$4,060
212982643	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80MSU0601716A*	23,400	\$3,276
212982223	HEIL	DLCURAH30ABK	END4X42L17**	*80MSU0401712A*	23,400	\$3,276
212982247	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80MSU0401712A*	19,400	\$2,716
209852076	HEIL	DLCURAH36ABK	DLFUAAH36XAK		30,400	\$4,256
213079256	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MSU0802120A*	29,000	\$4,060
213079220	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MSU0802120A*	29,000	\$4,060
213079208	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MSU0802120A*	29,400	\$4,116
212982163	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80MSU0401712A*	23,400	\$3,276
212982319	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80MSU0401712A*	18,700	\$2,618
213079172	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	29,400	\$4,116
213079112	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MSU0601716A*	29,200	\$4,088
212982151	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MSU0401712A*	23,200	\$3,248
213079304	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	29,400	\$4,116
212982979	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MSU0802120A*	23,200	\$3,248
212982259	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80MSU0401712A*	18,600	\$2,604
213079244	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MSU0802120A*	29,400	\$4,116
213079232	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MSU0802120A*	29,400	\$4,116
213079100	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MSU0601716A*	29,000	\$4,060
213079088	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MSU0601716A*	29,400	\$4,116
213080444	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002122A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078944	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU1002120A*	29,200	\$4,088
213079004	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MSU0401712A*	29,400	\$4,116
212971117	HEIL	DLCURAH24ABK	EA*4X24L14A*	*80VTL0451412B*	19,300	\$2,702
212969732	HEIL	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412B*	19,300	\$2,702
213079160	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU0601716A*	29,600	\$4,144
212988221	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002122A*	29,000	\$4,060
210473239	HEIL	HVH825GKA3*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210470497	HEIL	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0901716A*	31,200	\$4,368
210470376	HEIL	HVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470431	HEIL	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0701716A*	31,400	\$4,396
210470233	HEIL	HVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	31,000	\$4,340
213080370	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002120A*	29,200	\$4,088
213080346	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	29,400	\$4,116
213080286	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002120A*	29,200	\$4,088
213080274	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002120A*	29,400	\$4,116
213079136	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MSU0601716A*	29,000	\$4,060
212988078	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96MSN1002120A*	23,200	\$3,248
212988018	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002120A*	29,000	\$4,060
212988006	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002120A*	29,000	\$4,060
212982091	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MSU0401712A*	28,800	\$4,032
213078968	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MSU0401712A*	29,400	\$4,116
210470387	HEIL	HVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
213080435	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002122A*	29,400	\$4,116
213080417	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002122A*	29,200	\$4,088
213080358	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002120A*	29,200	\$4,088
213080322	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002120A*	29,200	\$4,088
213080310	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002120A*	29,400	\$4,116
213079268	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MSU0802120A*	29,000	\$4,060
213079076	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0401712A*	29,200	\$4,088
213078872	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MSU1002120A*	29,400	\$4,116
212988230	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002122A*	29,000	\$4,060
210470563	HEIL	HVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL1352422A*	31,200	\$4,368
210470519	HEIL	HVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470266	HEIL	HVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	31,000	\$4,340
213080453	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002122A*	29,200	\$4,088
213080399	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002122A*	29,400	\$4,116
213080390	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002122A*	29,200	\$4,088
213080381	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002122A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080298	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002120A*	29,400	\$4,116
213078836	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MSU1002120A*	29,400	\$4,116
213080408	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002122A*	29,400	\$4,116
210470530	HEIL	HVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470552	HEIL	HVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470442	HEIL	HVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470244	HEIL	HVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU1002122A*	31,000	\$4,340
210470277	HEIL	HVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL1352422A*	31,000	\$4,340
210473107	HEIL	HVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210473096	HEIL	HVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
213078980	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80MSU0401712A*	29,200	\$4,088
211712146	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ESU1002120A*	23,200	\$3,248
211712134	HEIL	DLCURAH30ABK	EA*4X37L21A*	*95ESU1002120A*	23,400	\$3,276
211712123	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80VSL0701716A*	23,400	\$3,276
211712112	HEIL	DLCURAH30ABK	EA*4X36L21A*	*80ESU1002120A*	23,600	\$3,304
211712100	HEIL	DLCURAH30ABK	EA*4X36L21A*	*95ESU1002120A*	23,600	\$3,304
211709690	HEIL	DLCURAH30ABK	FJMA4*30L*B*		23,400	\$3,276
213353861	HEIL	DLCURAH36ABK	F5MA4*42L*C*		29,200	\$4,088
213353851	HEIL	DLCURAH36ABK	F5MA4*36L*B*		29,400	\$4,116
213249341	HEIL	DLCURAH36ABK	FEVA0036**+NAVA43601CK		29,400	\$4,116
213080879	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU0802120A*	29,200	\$4,088
213080867	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0802120A*	29,200	\$4,088
213080855	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	29,400	\$4,116
213080843	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*95MSU0802120A*	29,600	\$4,144
213080831	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95MSU0802120A*	29,200	\$4,088
213080819	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95MSU0802120A*	29,400	\$4,116
213080807	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95MSU0802120A*	29,400	\$4,116
213080795	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95MSU0802120A*	29,200	\$4,088
213080783	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95MSU0802120A*	29,400	\$4,116
213080771	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0601716A*	29,200	\$4,088
213080759	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	29,600	\$4,144
213080747	HEIL	DLCURAH36ABK	END4X42L17**	*95MSU0601716A*	29,400	\$4,116
213080711	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95MSU0601716A*	29,200	\$4,088
213080699	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95MSU0601716A*	29,400	\$4,116
213080687	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95MSU0601716A*	29,200	\$4,088
213080675	HEIL	DLCURAH36ABK	EA*4X37L17A*	*95MSU0601716A*	29,400	\$4,116
213080663	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95MSU0601716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080651	HEIL	DLCURAH36ABK	EA*4X36L17A*	*95MSU0601716A*	29,600	\$4,144
213080639	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0401712A*	29,400	\$4,116
213080627	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0401712A*	29,600	\$4,144
213080615	HEIL	DLCURAH36ABK	END4X42L17**	*95MSU0401712A*	29,400	\$4,116
213080579	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95MSU0401712A*	29,200	\$4,088
211274901	HEIL	DLCURAH30ABK	FVM4X48***L		23,000	\$3,220
213080567	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95MSU0401712A*	29,200	\$4,088
213080555	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95MSU0401712A*	29,600	\$4,144
213080543	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95MSU0401712A*	29,200	\$4,088
213080531	HEIL	DLCURAH36ABK	EA*4X37L17A*	*95MSU0401712A*	29,400	\$4,116
213080519	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95MSU0401712A*	29,600	\$4,144
213080507	HEIL	DLCURAH36ABK	EA*4X36L17A*	*95MSU0401712A*	29,600	\$4,144
213080497	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1402422A*	29,200	\$4,088
213080487	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96MSN1402422A*	29,400	\$4,116
213080475	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1202422A*	29,200	\$4,088
213080463	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96MSN1202422A*	29,400	\$4,116
213080262	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN0802120A*	29,200	\$4,088
213080250	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0802120A*	29,200	\$4,088
211222783	HEIL	DLCURAH30ABK	FVM4X24***L		23,600	\$3,304
213080238	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0802120A*	29,400	\$4,116
213080214	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96MSN0802120A*	29,000	\$4,060
213080202	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96MSN0802120A*	29,000	\$4,060
211222767	HEIL	DLCURAH30ABK	FMA4X36**AL*		23,800	\$3,332
213080190	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96MSN0802120A*	29,200	\$4,088
213080178	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96MSN0802120A*	29,400	\$4,116
211222759	HEIL	DLCURAH30ABK	FMA4X30**AL*		23,800	\$3,332
213080166	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96MSN0802120A*	29,400	\$4,116
213080154	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96MSN0802120A*	29,200	\$4,088
211222751	HEIL	DLCURAH30ABK	FM(C,U)4Z36**AL*		23,600	\$3,304
213080142	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96MSN0802120A*	29,600	\$4,144
213080130	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0801716A*	29,200	\$4,088
211222743	HEIL	DLCURAH30ABK	FM(C,U)4Z30**AL*		23,600	\$3,304
213080118	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	29,600	\$4,144
213080106	HEIL	DLCURAH36ABK	END4X42L17**	*96MSN0801716A*	29,400	\$4,116
211222727	HEIL	DLCURAH30ABK	EA*4X37L21A*	OMV098J12*	23,200	\$3,248
211222719	HEIL	DLCURAH30ABK	EA*4X37L21A*	OLV098A12*	23,200	\$3,248
213080070	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96MSN0801716A*	29,000	\$4,060
211222711	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122A*	23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080058	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96MSN0801716A*	29,200	\$4,088
213080046	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96MSN0801716A*	29,400	\$4,116
213080034	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96MSN0801716A*	29,200	\$4,088
211222703	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120A*	23,200	\$3,248
213080022	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96MSN0801716A*	29,400	\$4,116
213080010	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96MSN0801716A*	29,600	\$4,144
211222695	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120A*	23,000	\$3,220
213079998	HEIL	DLCURAH36ABK	EA*4X36L17A*	*96MSN0801716A*	29,600	\$4,144
213079988	HEIL	DLCURAH36ABK	END4X42L17**	*96MSN0601412A*	29,600	\$4,144
211222687	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VTN0601714A*	23,200	\$3,248
213079968	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96MSN0601412A*	29,400	\$4,116
213079958	HEIL	DLCURAH36ABK	EA*4X36L17A*	*96MSN0601412A*	29,600	\$4,144
211222679	HEIL	DLCURAH30ABK	EA*4X37L21A*	*95ESU0601716A*	23,400	\$3,276
213079947	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1202420A*	29,200	\$4,088
213079936	HEIL	DLCURAH36ABK	EA*4X48L24A*	*92MSN1202420A*	29,000	\$4,060
211222671	HEIL	DLCURAH30ABK	EA*4X37L21A*	*95ESU0401712A*	23,200	\$3,248
213079925	HEIL	DLCURAH36ABK	EA*4X42L24A*	*92MSN1202420A*	29,400	\$4,116
213079915	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002122A*	29,200	\$4,088
211222663	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120A*	23,200	\$3,248
213079906	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002122A*	29,200	\$4,088
213079897	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002122A*	29,400	\$4,116
211222655	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120A*	23,000	\$3,220
213079879	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002122A*	29,000	\$4,060
211222647	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716A*	23,200	\$3,248
213079870	HEIL	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002122A*	29,400	\$4,116
213079861	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002122A*	29,400	\$4,116
211222639	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VSN0601714A*	23,200	\$3,248
213079852	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002122A*	29,000	\$4,060
213079843	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002122A*	29,400	\$4,116
211222631	HEIL	DLCURAH30ABK	EA*4X37L21A*	*95ESN0802120A*	23,200	\$3,248
213079832	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002120A*	29,200	\$4,088
213079820	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002120A*	29,200	\$4,088
211222623	HEIL	DLCURAH30ABK	EA*4X37L21A*	*95ESN0601714A*	23,200	\$3,248
213079808	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	29,400	\$4,116
213079796	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN1002120A*	29,600	\$4,144
213079784	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002120A*	29,000	\$4,060
211222615	HEIL	DLCURAH30ABK	EA*4X37L21A*	*92ESN1002120A*	23,200	\$3,248
213079772	HEIL	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211222607	HEIL	DLCURAH30ABK	EA*4X37L21A*	*92ESN0802120A*	23,200	\$3,248
213079760	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002120A*	29,400	\$4,116
213079748	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002120A*	29,000	\$4,060
211222599	HEIL	DLCURAH30ABK	EA*4X37L21A*	*92ESN0801716A*	23,400	\$3,276
213079736	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002120A*	29,400	\$4,116
213079726	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN0802120A*	29,200	\$4,088
211222591	HEIL	DLCURAH30ABK	EA*4X37L21A*	*92ESN0601714A*	23,400	\$3,276
213079716	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0802120A*	29,200	\$4,088
213079706	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	29,400	\$4,116
211222567	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122A*	23,200	\$3,248
213079696	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN0802120A*	29,600	\$4,144
213079686	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92MSN0802120A*	29,200	\$4,088
211222559	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120A*	23,200	\$3,248
213079676	HEIL	DLCURAH36ABK	EA*4X42L24A*	*92MSN0802120A*	29,400	\$4,116
213079666	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92MSN0802120A*	29,400	\$4,116
211222551	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716A*	23,200	\$3,248
213079656	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92MSN0802120A*	29,200	\$4,088
213079646	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92MSN0802120A*	29,400	\$4,116
211222543	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ESU0802120A	23,400	\$3,276
213079634	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0801716A*	29,200	\$4,088
213079622	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0801716A*	29,400	\$4,116
211222535	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ESU0601716A	23,200	\$3,248
213079610	HEIL	DLCURAH36ABK	END4X42L17**	*92MSN0801716A*	29,200	\$4,088
211222527	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ESU0401712A*	23,200	\$3,248
211222519	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VSL0902120A*	23,200	\$3,248
213079574	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92MSN0801716A*	29,000	\$4,060
213079562	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92MSN0801716A*	29,400	\$4,116
211222511	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VSL0702120A*	23,200	\$3,248
213079550	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92MSN0801716A*	29,000	\$4,060
211222503	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VSL0701716A*	23,200	\$3,248
213079538	HEIL	DLCURAH36ABK	EA*4X37L17A*	*92MSN0801716A*	29,400	\$4,116
213079526	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92MSN0801716A*	29,400	\$4,116
211222495	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VSL0451716A*	23,200	\$3,248
213079514	HEIL	DLCURAH36ABK	EA*4X36L17A*	*92MSN0801716A*	29,400	\$4,116
213079502	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0601714A*	29,200	\$4,088
213079490	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0601714A*	29,400	\$4,116
211222487	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	23,200	\$3,248
213079478	HEIL	DLCURAH36ABK	END4X42L17**	*92MSN0601714A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211222479	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
211222471	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
213079442	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92MSN0601714A*	29,200	\$4,088
211222463	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
213079430	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92MSN0601714A*	29,400	\$4,116
213079418	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92MSN0601714A*	29,200	\$4,088
213079404	HEIL	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601714A*	29,400	\$4,116
211222455	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
213079392	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92MSN0601714A*	29,400	\$4,116
211222447	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
213079380	HEIL	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601714A*	29,400	\$4,116
213079370	HEIL	DLCURAH36ABK	END4X42L17**	*92MSN0601412A*	29,400	\$4,116
211222439	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
213079350	HEIL	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601412A*	29,400	\$4,116
213079340	HEIL	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601412A*	29,600	\$4,144
211222399	HEIL	DLCURAH30ABK	EA*4X37L17A*	OMV098J12*	23,400	\$3,276
211222391	HEIL	DLCURAH30ABK	EA*4X37L17A*	*96VTN0601714A*	23,400	\$3,276
211222383	HEIL	DLCURAH30ABK	EA*4X37L17A*	*95ESU0601716A*	23,400	\$3,276
211222375	HEIL	DLCURAH30ABK	EA*4X37L17A*	*95ESU0401712A*	23,400	\$3,276
211222367	HEIL	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716A*	23,400	\$3,276
211222359	HEIL	DLCURAH30ABK	EA*4X37L17A*	*95ESN0601714A*	23,400	\$3,276
213079196	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0601716A*	29,200	\$4,088
211222351	HEIL	DLCURAH30ABK	EA*4X37L17A*	*92ESN0801716A*	23,400	\$3,276
211222343	HEIL	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601714A*	23,400	\$3,276
211222335	HEIL	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601412A*	23,400	\$3,276
213079124	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MSU0601716A*	29,200	\$4,088
211222327	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716A*	23,200	\$3,248
211222319	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412A*	23,400	\$3,276
211222311	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80ESU0601716A	23,400	\$3,276
211222303	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80ESU0401712A*	23,400	\$3,276
211222295	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451716A*	23,400	\$3,276
211222287	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412A*	23,400	\$3,276
211222279	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	23,200	\$3,248
211222271	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	23,400	\$3,276
213078920	HEIL	DLCURAH36ABK	END4X42L17**	*80MSU1002120A*	29,400	\$4,116
213078896	HEIL	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	29,600	\$4,144
213078848	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80MSU1002120A*	29,400	\$4,116
213078824	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80MSU1002120A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211222263	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	23,400	\$3,276
213078814	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1552420A*	29,200	\$4,088
213078804	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1552420A*	29,000	\$4,060
213078794	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	29,400	\$4,116
213078783	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1352420A*	29,200	\$4,088
213078772	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	29,400	\$4,116
213078762	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102420A*	29,200	\$4,088
213078752	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102420A*	29,000	\$4,060
213078742	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	29,400	\$4,116
213078730	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102120A*	29,200	\$4,088
213078718	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)1102120A*	29,200	\$4,088
213078706	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	29,400	\$4,116
213078682	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078670	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078658	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078646	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078634	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078622	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078610	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078600	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902420A*	29,200	\$4,088
213078591	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	29,400	\$4,116
213078581	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902120A*	29,200	\$4,088
213078570	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902120A*	29,200	\$4,088
211222151	HEIL	DLCURAH30ABK	EA*4X36L21A*	*92ESN1002120A*	23,400	\$3,276
213078559	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	29,400	\$4,116
211222140	HEIL	DLCURAH30ABK	EA*4X36L21A*	*92ESN0802120A*	23,400	\$3,276
213078537	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078526	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078515	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078504	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078493	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078482	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902116A*	29,200	\$4,088
213078471	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902116A*	29,200	\$4,088
213078460	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	29,400	\$4,116
211712492	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	23,400	\$3,276
211712505	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078438	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
213078427	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902116A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078416	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078405	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
211712479	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078394	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078382	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0901714A*	29,200	\$4,088
211712466	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	23,400	\$3,276
213078370	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0901714A*	29,400	\$4,116
213078358	HEIL	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0901714A*	29,200	\$4,088
213078322	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
213078310	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078298	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
211222000	HEIL	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078286	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078274	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078262	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078252	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0702116A*	29,200	\$4,088
213078242	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0702116A*	29,200	\$4,088
211712429	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122A*	23,400	\$3,276
213078232	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0702116A*	29,400	\$4,116
211221983	HEIL	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078212	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
213078202	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078192	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078182	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
213078172	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078160	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701716A*	29,200	\$4,088
213078148	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	29,400	\$4,116
213078136	HEIL	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701716A*	29,400	\$4,116
213078124	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	29,600	\$4,144
213078112	HEIL	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	29,600	\$4,144
213078100	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078088	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078076	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078064	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078052	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078040	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	29,600	\$4,144
213078029	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701712A*	29,200	\$4,088
213078018	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078007	HEIL	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701712A*	29,400	\$4,116
211712384	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716A*	23,400	\$3,276
213077974	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077963	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077952	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077941	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
211712372	HEIL	DLCURAH30ABK	EA*4X42L21A*	*95ESN1002120A*	23,600	\$3,304
213077930	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077919	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077907	HEIL	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701412A*	29,400	\$4,116
213077883	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
213077871	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
211712360	HEIL	DLCURAH30ABK	EA*4X42L21A*	*95ESN0802120A*	23,400	\$3,276
213077859	HEIL	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0451412A*	29,400	\$4,116
213077835	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	29,400	\$4,116
213077822	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	29,600	\$4,144
213077811	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422B*	29,200	\$4,088
211712542	HEIL	DLCURAH30ABK	EA*4X42L21A*	*92ESN0802120A*	23,400	\$3,276
213077799	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422B*	29,400	\$4,116
213077787	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122B*	29,200	\$4,088
213077777	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122B*	29,200	\$4,088
213077767	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	29,400	\$4,116
213077757	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN1002122B*	29,600	\$4,144
213077747	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122B*	29,000	\$4,060
213077737	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122B*	29,400	\$4,116
213077727	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122B*	29,400	\$4,116
213077717	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122B*	29,000	\$4,060
213077707	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122B*	29,400	\$4,116
213077696	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120B*	29,200	\$4,088
211712334	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80ESU0401712A*	23,400	\$3,276
213077683	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120B*	29,200	\$4,088
213077670	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	29,400	\$4,116
213077644	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120B*	29,000	\$4,060
213077631	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120B*	29,400	\$4,116
213077618	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120B*	29,400	\$4,116
213077605	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120B*	29,000	\$4,060
213077592	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120B*	29,400	\$4,116
211712322	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80ESU1002120A*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077580	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120B*	29,200	\$4,088
213077569	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120B*	29,200	\$4,088
213077558	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	29,400	\$4,116
213077547	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN0802120B*	29,600	\$4,144
213077536	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120B*	29,000	\$4,060
213077525	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120B*	29,200	\$4,088
213077514	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120B*	29,400	\$4,116
213077503	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120B*	29,400	\$4,116
213077492	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120B*	29,200	\$4,088
213077481	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120B*	29,400	\$4,116
213077469	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0801716B*	29,200	\$4,088
213077456	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0801716B*	29,600	\$4,144
211712298	HEIL	DLCURAH30ABK	EA*4X42L21A*	*95ESU1002120A*	23,600	\$3,304
213077443	HEIL	DLCURAH36ABK	END4X42L17**	*96VTN0801716B*	29,400	\$4,116
211712554	HEIL	DLCURAH30ABK	EA*4X42L21A*	*92ESN1002120A*	23,400	\$3,276
213077404	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VTN0801716B*	29,200	\$4,088
213077391	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716B*	29,400	\$4,116
213077378	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VTN0801716B*	29,200	\$4,088
213077365	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96VTN0801716B*	29,400	\$4,116
213077352	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VTN0801716B*	29,400	\$4,116
213077339	HEIL	DLCURAH36ABK	EA*4X36L17A*	*96VTN0801716B*	29,600	\$4,144
211712277	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80VSL0702120A*	23,400	\$3,276
213077327	HEIL	DLCURAH36ABK	END4X42L17**	*96VTN0601412B*	29,400	\$4,116
213077305	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601412B*	29,400	\$4,116
213077294	HEIL	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601412B*	29,600	\$4,144
213077283	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0401712B*	29,400	\$4,116
213077272	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VTN0401712B*	29,200	\$4,088
213077261	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422B*	29,200	\$4,088
213077251	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422B*	29,000	\$4,060
213077241	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422B*	29,400	\$4,116
213077231	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120B*	29,200	\$4,088
213077221	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120B*	29,200	\$4,088
213077211	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	29,400	\$4,116
213077191	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120B*	29,000	\$4,060
213077181	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120B*	29,000	\$4,060
211712566	HEIL	DLCURAH30ABK	EA*4X42L21A*	*95ESN0601714A*	23,600	\$3,304
213077171	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120B*	29,400	\$4,116
213077161	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077151	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120B*	29,000	\$4,060
213077141	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120B*	29,400	\$4,116
213077131	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120B*	29,200	\$4,088
213077121	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120B*	29,200	\$4,088
213077111	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	29,400	\$4,116
213077101	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*96VSN0802120B*	29,600	\$4,144
213077091	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120B*	29,000	\$4,060
213077081	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120B*	29,200	\$4,088
213077071	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120B*	29,400	\$4,116
213077061	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120B*	29,400	\$4,116
211712235	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	23,600	\$3,304
213077051	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120B*	29,200	\$4,088
213077041	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120B*	29,400	\$4,116
213077031	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716B*	29,200	\$4,088
213077021	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716B*	29,600	\$4,144
213077011	HEIL	DLCURAH36ABK	END4X42L17**	*96VSN0801716B*	29,400	\$4,116
213076981	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716B*	29,200	\$4,088
213076971	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716B*	29,400	\$4,116
213076961	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716B*	29,200	\$4,088
213076951	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716B*	29,400	\$4,116
213076941	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716B*	29,400	\$4,116
213076931	HEIL	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716B*	29,600	\$4,144
213076921	HEIL	DLCURAH36ABK	END4X42L17**	*96VSN0601412B*	29,400	\$4,116
211712212	HEIL	DLCURAH30ABK	EA*4X42L21A*	*96VSN0801716A*	23,400	\$3,276
213076901	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412B*	29,400	\$4,116
213076891	HEIL	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601412B*	29,600	\$4,144
213076881	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0401712B*	29,400	\$4,116
213076871	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VSN0401712B*	29,200	\$4,088
213076854	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122B*	29,200	\$4,088
213076842	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122B*	29,200	\$4,088
213076830	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122B*	29,400	\$4,116
213076806	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122B*	29,000	\$4,060
213076794	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122B*	29,000	\$4,060
213076782	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122B*	29,200	\$4,088
211712590	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80ESU0601716A	23,400	\$3,276
213076770	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122B*	29,400	\$4,116
213076758	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122B*	29,400	\$4,116
213076746	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122B*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076734	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122B*	29,400	\$4,116
213076723	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120B*	29,200	\$4,088
213076712	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120B*	29,200	\$4,088
213076701	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	29,400	\$4,116
213076690	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*80VTL0902120B*	29,600	\$4,144
213076679	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120B*	29,200	\$4,088
213076668	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120B*	29,400	\$4,116
211712170	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
213076657	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120B*	29,400	\$4,116
213076646	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120B*	29,200	\$4,088
213076635	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120B*	29,400	\$4,116
211712158	HEIL	DLCURAH30ABK	EA*4X37L21A*	*95ESN1002120A*	23,600	\$3,304
211712662	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80VSL0702120A*	23,400	\$3,276
213076580	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716B*	29,200	\$4,088
213076569	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	29,400	\$4,116
213076558	HEIL	DLCURAH36ABK	END4X42L17**	*80VTL0701716B*	29,400	\$4,116
213076525	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716B*	29,000	\$4,060
213076514	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716B*	29,400	\$4,116
213076503	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716B*	29,000	\$4,060
213076492	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716B*	29,400	\$4,116
211712682	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902420A*	23,400	\$3,276
213076481	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716B*	29,400	\$4,116
213076470	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716B*	29,400	\$4,116
213076450	HEIL	DLCURAH36ABK	END4X42L17**	*80VTL0451412B*	29,400	\$4,116
211712692	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80VSL1102422A*	23,400	\$3,276
213076426	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412B*	29,200	\$4,088
213076414	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412B*	29,400	\$4,116
213076339	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002122A*	29,200	\$4,088
213076330	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002122A*	29,200	\$4,088
213076321	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002122A*	29,400	\$4,116
213076303	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002122A*	29,000	\$4,060
211712703	HEIL	DLCURAH30ABK	EA*4X42L24A*	*95ESU1002120A*	23,600	\$3,304
213076294	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002122A*	29,000	\$4,060
213076285	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002122A*	29,000	\$4,060
213076276	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002122A*	29,400	\$4,116
213076267	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002122A*	29,400	\$4,116
213076258	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002122A*	29,000	\$4,060
213076249	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002122A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076001	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002120A*	29,200	\$4,088
213075989	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002120A*	29,200	\$4,088
211712715	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80ESU1002120A*	23,600	\$3,304
213075977	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002120A*	29,400	\$4,116
213075953	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002120A*	29,000	\$4,060
213075941	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002120A*	29,000	\$4,060
213075929	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002120A*	29,000	\$4,060
213075917	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002120A*	29,400	\$4,116
213075905	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002120A*	29,400	\$4,116
213075893	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002120A*	29,000	\$4,060
213075881	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002120A*	29,400	\$4,116
212989508	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95MSU0802120A*	29,000	\$4,060
212989496	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95MSU0802120A*	29,000	\$4,060
212988980	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95MSU0601716A*	29,000	\$4,060
212988408	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96MSN1402422A*	29,000	\$4,060
212988324	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96MSN1202422A*	29,000	\$4,060
211712741	HEIL	DLCURAH30ABK	EA*4X42L24A*	*95ESN0802120A*	23,400	\$3,276
212985521	HEIL	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002122A*	29,000	\$4,060
212985512	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002122A*	29,000	\$4,060
211712753	HEIL	DLCURAH30ABK	EA*4X42L24A*	*95ESN1002120A*	23,600	\$3,304
212985246	HEIL	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002120A*	28,800	\$4,032
212985234	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002120A*	28,800	\$4,032
212984956	HEIL	DLCURAH36ABK	EA*4X48L24A*	*92MSN0802120A*	28,800	\$4,032
212984946	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92MSN0802120A*	28,800	\$4,032
212984416	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92MSN0801716A*	29,000	\$4,060
212983876	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92MSN0601714A*	29,000	\$4,060
212982607	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MSU0601716A*	28,800	\$4,032
212981213	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1352420A*	29,000	\$4,060
212980694	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902420A*	29,000	\$4,060
212980493	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980482	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980174	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902116A*	28,800	\$4,032
212980163	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902116A*	28,800	\$4,032
212979660	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
212979418	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0702116A*	28,800	\$4,032
212979408	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0702116A*	28,800	\$4,032
212978970	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701716A*	29,000	\$4,060
212978484	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701712A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212977258	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422B*	29,000	\$4,060
212977094	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122B*	28,800	\$4,032
212977084	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122B*	28,800	\$4,032
212976813	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120B*	29,000	\$4,060
211712799	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122A*	23,400	\$3,276
212976800	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120B*	29,000	\$4,060
212976531	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120B*	28,800	\$4,032
212976308	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VTN0801716B*	29,000	\$4,060
212974418	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120B*	29,000	\$4,060
212974198	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120B*	28,800	\$4,032
212974058	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716B*	29,000	\$4,060
212972248	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120B*	29,000	\$4,060
212972237	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120B*	29,000	\$4,060
212971881	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716B*	29,000	\$4,060
212970742	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120B*	29,200	\$4,088
212970732	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120B*	29,200	\$4,088
211712823	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	23,600	\$3,304
212970722	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	29,400	\$4,116
212970712	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*80VSL0902120B*	29,600	\$4,144
212970702	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120B*	29,000	\$4,060
212970692	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120B*	29,000	\$4,060
212970682	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120B*	29,200	\$4,088
212970672	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120B*	29,400	\$4,116
212970662	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120B*	29,400	\$4,116
212970652	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120B*	29,200	\$4,088
211712836	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	23,400	\$3,276
212970642	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120B*	29,400	\$4,116
212970482	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716B*	29,200	\$4,088
212970472	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	29,400	\$4,116
212970462	HEIL	DLCURAH36ABK	END4X42L17**	*80VSL0701716B*	29,400	\$4,116
212970432	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716B*	29,000	\$4,060
211712849	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	23,400	\$3,276
212970422	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716B*	29,200	\$4,088
212970412	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716B*	29,400	\$4,116
212970402	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716B*	29,200	\$4,088
212970392	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716B*	29,400	\$4,116
212970382	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716B*	29,600	\$4,144
212970372	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716B*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212969962	HEIL	DLCURAH36ABK	END4X42L17**	*80VSL0451412B*	29,400	\$4,116
211712862	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	23,600	\$3,304
212969942	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412B*	29,200	\$4,088
212969932	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412B*	29,400	\$4,116
212390904	HEIL	DLCURAH36ABK	FJMA4*36L*B*		29,400	\$4,116
212384857	HEIL	DLCURAH36ABK	FVM4X36***L		29,400	\$4,116
212384833	HEIL	DLCURAH36ABK	FJMA4*42L*C*		29,200	\$4,088
211712875	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	23,400	\$3,276
212384793	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0801716A*	29,200	\$4,088
212384781	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701716A*	29,200	\$4,088
212384770	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV112A16A	29,600	\$4,144
212384760	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV112K14A	29,400	\$4,116
212384750	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV098A12*	29,600	\$4,144
212384740	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV098J12*	29,600	\$4,144
212384729	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	29,400	\$4,116
212384717	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0802120A	29,600	\$4,144
211712888	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	23,600	\$3,304
212384705	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0601714A*	29,400	\$4,116
212384693	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	29,400	\$4,116
212384681	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	29,400	\$4,116
212384669	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0801716A*	29,400	\$4,116
212384657	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0601714A*	29,400	\$4,116
212384644	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	29,400	\$4,116
211712901	HEIL	DLCURAH30ABK	EA*4X42L24A*	*92ESN0802120A*	23,400	\$3,276
212384631	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	29,400	\$4,116
212384618	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701712A*	29,600	\$4,144
212384605	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0451712A*	29,400	\$4,116
212384594	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	29,400	\$4,116
212384583	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120A*	29,600	\$4,144
211712913	HEIL	DLCURAH30ABK	EA*4X42L24A*	*92ESN1002120A*	23,400	\$3,276
212384572	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	29,400	\$4,116
212384560	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	29,600	\$4,144
212384549	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120A*	29,400	\$4,116
212384534	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	29,400	\$4,116
212384522	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	29,400	\$4,116
211712959	HEIL	DLCURAH30ABK	EA*4X42L24A*	OLV154F20A	23,600	\$3,304
211712969	HEIL	DLCURAH30ABK	EA*4X42L24A*	OMV154L20A	23,600	\$3,304
211712979	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VSN0601714A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712989	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120A*	23,000	\$3,220
211712999	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120A*	23,200	\$3,248
211713009	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716A*	23,200	\$3,248
211713020	HEIL	DLCURAH30ABK	EA*4X43L21A*	*95ESU0401712A*	23,200	\$3,248
211713032	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
211713044	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122A*	23,000	\$3,220
211713054	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VSL0451716A*	23,200	\$3,248
211713064	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VSL0701716A*	23,200	\$3,248
211713074	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VSL0702120A*	23,200	\$3,248
211713084	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VSL0902120A*	23,200	\$3,248
211713095	HEIL	DLCURAH30ABK	EA*4X43L21A*	*95ESU1002120A*	23,400	\$3,276
211713107	HEIL	DLCURAH30ABK	EA*4X43L21A*	*95ESU0601716A*	23,400	\$3,276
211713119	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ESU1002120A*	23,400	\$3,276
211713131	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ESU0401712A*	23,200	\$3,248
213353889	HEIL	DLCURAH60ABK	F5MA4*60L*D*		37,800	\$5,292
213607819	HEIL	DLCURAH60ABK	FTMA4B60L0D*		37,400	\$5,236
211713146	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120A*	23,200	\$3,248
211713157	HEIL	DLCURAH30ABK	EA*4X43L21A*	*95ESN0802120A*	23,200	\$3,248
211713169	HEIL	DLCURAH30ABK	EA*4X43L21A*	*95ESN1002120A*	23,600	\$3,304
211713181	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716A*	23,200	\$3,248
211713193	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VTN0601714A*	23,200	\$3,248
211713204	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120A*	23,000	\$3,220
211713215	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120A*	23,200	\$3,248
211713226	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122A*	23,200	\$3,248
210025744	HEIL	DLCURAH60ABK	DLFUAAH60XAK		42,000	\$5,880
212384510	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	29,400	\$4,116
212384499	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120A*	29,400	\$4,116
211713237	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
212384489	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	29,400	\$4,116
212384479	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716A*	29,400	\$4,116
212384469	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002122A*	29,600	\$4,144
212384459	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002122A*	29,600	\$4,144
212384449	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002122A*	29,600	\$4,144
212384438	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	29,400	\$4,116
211713250	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
212384427	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	29,400	\$4,116
212384417	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	29,400	\$4,116
212384407	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384397	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0601714A*	29,400	\$4,116
212384387	HEIL	DLCURAH36ABK	END4X42L17**	OMV112K14A	29,400	\$4,116
212384377	HEIL	DLCURAH36ABK	END4X42L17**	OLV098A12*	29,400	\$4,116
211713263	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
212384367	HEIL	DLCURAH36ABK	END4X42L17**	OMV098J12*	29,400	\$4,116
212384356	HEIL	DLCURAH36ABK	END4X42L17**	*80ESU0601716A	29,400	\$4,116
212384343	HEIL	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701412A*	29,400	\$4,116
212384331	HEIL	DLCURAH36ABK	END4X42L17**	*92ESN0801716A*	29,200	\$4,088
212384319	HEIL	DLCURAH36ABK	END4X42L17**	*92ESN0601714A*	29,200	\$4,088
211713276	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
212384307	HEIL	DLCURAH36ABK	END4X42L17**	*92ESN0601412A*	29,400	\$4,116
212384294	HEIL	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0901714A*	29,400	\$4,116
212384281	HEIL	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701712A*	29,400	\$4,116
212384268	HEIL	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451712A*	29,400	\$4,116
212384255	HEIL	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451412A*	29,600	\$4,144
211713289	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
212384241	HEIL	DLCURAH36ABK	END4X42L17**	*80VTL0451412A*	29,400	\$4,116
212384230	HEIL	DLCURAH36ABK	END4X42L17**	*80VSL0701716A*	29,200	\$4,088
212384220	HEIL	DLCURAH36ABK	END4X42L17**	*80VSL0451716A*	29,400	\$4,116
212384209	HEIL	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701716A*	29,200	\$4,088
211713302	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
212384145	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*80ESU0802120A	29,800	\$4,172
212384133	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002120A*	29,600	\$4,144
212384121	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN0802120A*	29,600	\$4,144
211713315	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	23,400	\$3,276
211713328	HEIL	DLCURAH30ABK	EA*4X43L21A*	*92ESN0601714A*	23,000	\$3,220
211713340	HEIL	DLCURAH30ABK	EA*4X43L21A*	*92ESN0801716A*	23,400	\$3,276
211713352	HEIL	DLCURAH30ABK	EA*4X43L21A*	*92ESN0802120A*	23,200	\$3,248
212383814	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESU1002122A*	29,800	\$4,172
212383804	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESN1002122A*	29,800	\$4,172
211713364	HEIL	DLCURAH30ABK	EA*4X43L21A*	*92ESN1002120A*	23,200	\$3,248
212383794	HEIL	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002122A*	29,800	\$4,172
211713376	HEIL	DLCURAH30ABK	EA*4X43L21A*	*95ESN0601714A*	23,200	\$3,248
211713388	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ESU0802120A	23,400	\$3,276
212383487	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701716A*	29,000	\$4,060
212383475	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92ESN0801716A*	29,000	\$4,060
211713400	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80ESU0601716A	23,200	\$3,248
212383463	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383452	HEIL	DLCURAH36ABK	EA*4X42L21A*	OLV112A16A	29,400	\$4,116
212383441	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002120A*	29,200	\$4,088
212383430	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120A*	29,000	\$4,060
212383418	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95ESU0601716A*	29,200	\$4,088
211713411	HEIL	DLCURAH30ABK	EA*4X43L21A*	OMV098J12*	23,200	\$3,248
212383406	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
212383394	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80ESU0601716A	29,200	\$4,088
212383382	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ESU0601716A	29,400	\$4,116
211713421	HEIL	DLCURAH30ABK	EA*4X43L21A*	OLV098A12*	23,200	\$3,248
212383370	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ESU0802120A	29,600	\$4,144
212383358	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002120A*	29,400	\$4,116
212383346	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92ESN0802120A*	29,400	\$4,116
212383334	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92ESN0801716A*	29,400	\$4,116
212383321	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
212383308	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
212383295	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	29,600	\$4,144
212383282	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
212383271	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122A*	29,600	\$4,144
212383260	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VTN0601714A*	29,600	\$4,144
212383248	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716A*	29,400	\$4,116
212383236	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95ESN0802120A*	29,600	\$4,144
212383225	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120A*	29,400	\$4,116
212383213	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002120A*	29,400	\$4,116
212383202	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120A*	29,400	\$4,116
212383192	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VSL0702120A*	29,400	\$4,116
212383182	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716A*	29,400	\$4,116
212383171	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95ESU0802120A*	29,800	\$4,172
212383160	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002122A*	29,600	\$4,144
212383149	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
212383138	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716A*	29,400	\$4,116
212383128	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120A*	29,400	\$4,116
212383118	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120A*	29,400	\$4,116
212383108	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VSN0601714A*	29,600	\$4,144
212383098	HEIL	DLCURAH36ABK	EA*4X36L17A*	OLV098A12*	29,600	\$4,144
212383088	HEIL	DLCURAH36ABK	EA*4X36L17A*	OMV098J12*	29,600	\$4,144
212383077	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80ESU0601716A	29,600	\$4,144
212383064	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	29,600	\$4,144
212383052	HEIL	DLCURAH36ABK	EA*4X36L17A*	*95ESN0601714A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383040	HEIL	DLCURAH36ABK	EA*4X36L17A*	*92ESN0801716A*	29,400	\$4,116
212383028	HEIL	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601714A*	29,400	\$4,116
212383016	HEIL	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601412A*	29,600	\$4,144
212383003	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	29,600	\$4,144
212382990	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	29,600	\$4,144
212382977	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	29,600	\$4,144
212382964	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	29,800	\$4,172
212382953	HEIL	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601714A*	29,600	\$4,144
212382941	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716A*	29,400	\$4,116
212382924	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412A*	29,600	\$4,144
212382912	HEIL	DLCURAH36ABK	EA*4X36L17A*	*95ESU0601716A*	29,400	\$4,116
212382901	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716A*	29,400	\$4,116
212382891	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451716A*	29,600	\$4,144
212382880	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
212382869	HEIL	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716A*	29,400	\$4,116
212382859	HEIL	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601714A*	29,600	\$4,144
212382849	HEIL	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412A*	29,600	\$4,144
211230932	HEIL	DLCURAH36ABK	FXM4X48**AL		29,000	\$4,060
211230921	HEIL	DLCURAH36ABK	FXM4X42**AL		29,000	\$4,060
211230900	HEIL	DLCURAH36ABK	FVM4X48***L		28,600	\$4,004
211230889	HEIL	DLCURAH36ABK	FMA4X36**AL*		29,600	\$4,144
211230867	HEIL	DLCURAH36ABK	FM(C,U)4Z36**AL*		29,600	\$4,144
211230811	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	OMV154L20A	29,200	\$4,088
211230802	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	OLV154F20A	29,400	\$4,116
211230793	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	OLV112A16A	29,200	\$4,088
211230784	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422A*	29,200	\$4,088
211230774	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122A*	29,200	\$4,088
211230765	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120A*	29,200	\$4,088
211230755	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120A*	29,200	\$4,088
211230745	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002122A*	29,400	\$4,116
211230735	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002120A*	29,200	\$4,088
211230724	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU0802120A*	29,600	\$4,144
211230714	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422A*	29,200	\$4,088
211230705	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120A*	29,200	\$4,088
211230696	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120A*	29,200	\$4,088
211230686	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1402422A*	29,400	\$4,116
211230675	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1202422A*	29,400	\$4,116
211230665	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002122A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230655	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002120A*	29,200	\$4,088
211230644	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN0802120A*	29,400	\$4,116
211230633	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1202420A*	29,200	\$4,088
211230623	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002122A*	29,400	\$4,116
211230613	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002120A*	29,200	\$4,088
211230602	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN0802120A*	29,000	\$4,060
211230572	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122A*	29,200	\$4,088
211230562	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120A*	29,200	\$4,088
211230551	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU1002120A*	29,200	\$4,088
211230540	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU0802120A	29,400	\$4,116
211230530	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL1102422A*	29,200	\$4,088
211230521	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902420A*	29,200	\$4,088
211230512	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120A*	29,200	\$4,088
211230503	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0702120A*	29,200	\$4,088
211230494	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1552420A*	29,200	\$4,088
211230482	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1352420A*	29,200	\$4,088
211230470	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102420A*	29,200	\$4,088
211230458	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102120A*	29,200	\$4,088
211230446	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902420A*	29,200	\$4,088
211230434	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902120A*	29,200	\$4,088
211230422	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902116A*	29,200	\$4,088
211230410	HEIL	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0702116A*	29,200	\$4,088
211230382	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV112K14A	29,200	\$4,088
211230373	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV098J12*	29,200	\$4,088
211230364	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV112A16A	29,200	\$4,088
211230355	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV098A12*	29,200	\$4,088
211230346	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122A*	29,200	\$4,088
211230337	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120A*	29,200	\$4,088
211230327	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120A*	29,200	\$4,088
211230317	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0601714A*	29,400	\$4,116
211230297	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002122A*	29,400	\$4,116
211230287	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002120A*	29,200	\$4,088
211230276	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0802120A*	29,600	\$4,144
211230265	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0601716A*	29,200	\$4,088
211230255	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120A*	29,200	\$4,088
211230246	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120A*	29,200	\$4,088
211230237	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716A*	29,200	\$4,088
211230228	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0601714A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230210	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002122A*	29,400	\$4,116
211230200	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002120A*	29,200	\$4,088
211230189	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0802120A*	29,400	\$4,116
211230178	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0801716A*	29,200	\$4,088
211230167	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0601714A*	29,200	\$4,088
211230157	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002122A*	29,400	\$4,116
211230147	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002120A*	29,200	\$4,088
211230136	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0802120A*	29,000	\$4,060
211230125	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0601714A*	29,200	\$4,088
211230088	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122A*	29,200	\$4,088
211230078	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120A*	29,200	\$4,088
211230066	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716A*	29,200	\$4,088
211230055	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU1002120A*	29,200	\$4,088
211230044	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0802120A	29,400	\$4,116
211230033	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0601716A	29,000	\$4,060
211230022	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0401712A*	29,600	\$4,144
211230012	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120A*	29,200	\$4,088
211230003	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0702120A*	29,200	\$4,088
211229994	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716A*	29,200	\$4,088
211229985	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0451716A*	29,200	\$4,088
211229974	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)1102120A*	29,200	\$4,088
211229962	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902120A*	29,200	\$4,088
211229950	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902116A*	29,200	\$4,088
211229938	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0901714A*	29,200	\$4,088
211229926	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0702116A*	29,200	\$4,088
211229914	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701712A*	29,400	\$4,116
211229902	HEIL	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0451712A*	29,200	\$4,088
211229856	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	29,400	\$4,116
211229847	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120A*	29,400	\$4,116
211229837	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0601714A*	29,600	\$4,144
211229826	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002120A*	29,400	\$4,116
211229805	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0451716A*	29,400	\$4,116
211229794	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	29,400	\$4,116
211229782	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	29,400	\$4,116
211229770	HEIL	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	29,400	\$4,116
211229751	HEIL	DLCURAH36ABK	END4X42L17**	*96VTN0601714A*	29,400	\$4,116
211229740	HEIL	DLCURAH36ABK	END4X42L17**	*95ESU0601716A*	29,200	\$4,088
211229730	HEIL	DLCURAH36ABK	END4X42L17**	*96VSN0801716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229721	HEIL	DLCURAH36ABK	END4X42L17**	*96VSN0601714A*	29,400	\$4,116
211229693	HEIL	DLCURAH36ABK	END4X42L17**	*95ESN0601714A*	29,400	\$4,116
211229674	HEIL	DLCURAH36ABK	END4X42L17**	*80VTL0701716A*	29,200	\$4,088
211229662	HEIL	DLCURAH36ABK	END4X42L17**	*80VSL0451412A*	29,400	\$4,116
211229653	HEIL	DLCURAH36ABK	EA*4X48L24A*	OMV154L20A	29,000	\$4,060
211229644	HEIL	DLCURAH36ABK	EA*4X48L24A*	OLV154F20A	29,200	\$4,088
211229635	HEIL	DLCURAH36ABK	EA*4X48L24A*	OLV112A16A	29,000	\$4,060
211229626	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422A*	29,000	\$4,060
211229616	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122A*	28,800	\$4,032
211229607	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120A*	29,000	\$4,060
211229597	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120A*	28,800	\$4,032
211714020	HEIL	DLCURAH30ABK	EN(A,D)4X36L21**	*80ESU0802120A	23,600	\$3,304
211229587	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002122A*	29,200	\$4,088
211229577	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002120A*	29,000	\$4,060
211229566	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95ESU0802120A*	29,400	\$4,116
211229556	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422A*	29,000	\$4,060
211229547	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120A*	29,000	\$4,060
211229538	HEIL	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120A*	29,000	\$4,060
211229528	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95ESN1402422A*	29,200	\$4,088
211229517	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95ESN1202422A*	29,200	\$4,088
211229507	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002122A*	29,200	\$4,088
211229497	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002120A*	29,000	\$4,060
211229486	HEIL	DLCURAH36ABK	EA*4X48L24A*	*95ESN0802120A*	29,200	\$4,088
211714043	HEIL	DLCURAH30ABK	END4X42L17**	*80VSL0451412A*	23,400	\$3,276
211229475	HEIL	DLCURAH36ABK	EA*4X48L24A*	*92ESN1202420A*	29,000	\$4,060
211229465	HEIL	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002122A*	29,200	\$4,088
211229455	HEIL	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002120A*	28,800	\$4,032
211229444	HEIL	DLCURAH36ABK	EA*4X48L24A*	*92ESN0802120A*	28,800	\$4,032
211714053	HEIL	DLCURAH30ABK	END4X42L17**	*96VSN0801716A*	23,400	\$3,276
211229414	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122A*	29,000	\$4,060
211229404	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120A*	28,800	\$4,032
211229393	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ESU1002120A*	29,000	\$4,060
211229382	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ESU0802120A	29,200	\$4,088
211229372	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80VSL1102422A*	28,800	\$4,032
211714064	HEIL	DLCURAH30ABK	END4X42L17**	*95ESU0401712A*	23,400	\$3,276
211229363	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902420A*	28,800	\$4,032
211229354	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120A*	28,800	\$4,032
211229345	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80VSL0702120A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229336	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1552420A*	29,200	\$4,088
211229324	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1352420A*	29,000	\$4,060
211714076	HEIL	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701716A*	23,600	\$3,304
211229312	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102420A*	28,800	\$4,032
211229300	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102120A*	29,000	\$4,060
211229288	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902420A*	29,000	\$4,060
211229276	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902120A*	29,000	\$4,060
211714087	HEIL	DLCURAH30ABK	END4X42L17**	*80VSL0451716A*	23,400	\$3,276
211229264	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902116A*	29,000	\$4,060
211229252	HEIL	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0702116A*	28,800	\$4,032
211229224	HEIL	DLCURAH36ABK	EA*4X48L21A*	OMV112K14A	29,000	\$4,060
211229215	HEIL	DLCURAH36ABK	EA*4X48L21A*	OMV098J12*	29,000	\$4,060
211229206	HEIL	DLCURAH36ABK	EA*4X48L21A*	OLV112A16A	29,000	\$4,060
211714097	HEIL	DLCURAH30ABK	END4X42L17**	*80VSL0701716A*	23,400	\$3,276
211229197	HEIL	DLCURAH36ABK	EA*4X48L21A*	OLV098A12*	29,000	\$4,060
211229188	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122A*	28,800	\$4,032
211229179	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120A*	29,000	\$4,060
211229169	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120A*	29,000	\$4,060
211714108	HEIL	DLCURAH30ABK	END4X42L17**	*95ESU0601716A*	23,600	\$3,304
211229159	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VTN0601714A*	29,200	\$4,088
211229149	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002122A*	29,200	\$4,088
211229139	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002120A*	29,000	\$4,060
211229128	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95ESU0802120A*	29,400	\$4,116
211229117	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95ESU0601716A*	29,000	\$4,060
211714120	HEIL	DLCURAH30ABK	END4X42L17**	*80ESU0401712A*	23,400	\$3,276
211229107	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120A*	29,000	\$4,060
211229098	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120A*	29,000	\$4,060
211229089	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716A*	29,000	\$4,060
211229080	HEIL	DLCURAH36ABK	EA*4X48L21A*	*96VSN0601714A*	29,000	\$4,060
211229062	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002122A*	29,200	\$4,088
211229052	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002120A*	29,000	\$4,060
211714132	HEIL	DLCURAH30ABK	END4X42L17**	*80VTL0451412A*	23,400	\$3,276
211229041	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95ESN0802120A*	29,200	\$4,088
211229030	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95ESN0801716A*	29,000	\$4,060
211229019	HEIL	DLCURAH36ABK	EA*4X48L21A*	*95ESN0601714A*	29,000	\$4,060
211229009	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002122A*	29,200	\$4,088
211228999	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002120A*	28,800	\$4,032
211228988	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92ESN0802120A*	28,800	\$4,032

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228977	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92ESN0801716A*	29,000	\$4,060
211714149	HEIL	DLCURAH30ABK	END4X42L17**	*80VTL0701716A*	23,400	\$3,276
211228966	HEIL	DLCURAH36ABK	EA*4X48L21A*	*92ESN0601714A*	29,000	\$4,060
211228929	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122A*	29,000	\$4,060
211228919	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120A*	28,800	\$4,032
211228907	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716A*	29,000	\$4,060
211228896	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ESU1002120A*	29,000	\$4,060
211714161	HEIL	DLCURAH30ABK	END4X42L17**	*96VTN0601714A*	23,400	\$3,276
211228885	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ESU0802120A	29,200	\$4,088
211228874	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ESU0601716A	29,000	\$4,060
211228863	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ESU0401712A*	29,400	\$4,116
211228853	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120A*	28,800	\$4,032
211228844	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VSL0702120A*	29,000	\$4,060
211228835	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716A*	29,000	\$4,060
211714172	HEIL	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0451412A*	23,400	\$3,276
211228826	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80VSL0451716A*	29,000	\$4,060
211228815	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)1102120A*	29,000	\$4,060
211228803	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902120A*	29,000	\$4,060
211228791	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211228779	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0901714A*	29,000	\$4,060
211228767	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0702116A*	28,800	\$4,032
211714185	HEIL	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701712A*	23,400	\$3,276
211228755	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701712A*	29,000	\$4,060
211228743	HEIL	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228697	HEIL	DLCURAH36ABK	EA*4X43L21A*	OMV112K14A	29,200	\$4,088
211228688	HEIL	DLCURAH36ABK	EA*4X43L21A*	OMV098J12*	29,200	\$4,088
211228679	HEIL	DLCURAH36ABK	EA*4X43L21A*	OLV112A16A	29,200	\$4,088
211714198	HEIL	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0901714A*	23,400	\$3,276
211228670	HEIL	DLCURAH36ABK	EA*4X43L21A*	OLV098A12*	29,200	\$4,088
211228661	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122A*	29,000	\$4,060
211228652	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120A*	29,200	\$4,088
211228642	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120A*	29,200	\$4,088
211228632	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VTN0601714A*	29,200	\$4,088
211228612	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002122A*	29,200	\$4,088
211714211	HEIL	DLCURAH30ABK	END4X42L17**	*92ESN0601412A*	23,400	\$3,276
211228602	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002120A*	29,000	\$4,060
211228591	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95ESU0802120A*	29,400	\$4,116
211228580	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95ESU0601716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714223	HEIL	DLCURAH30ABK	END4X42L17**	*92ESN0601714A*	23,200	\$3,248
211228570	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120A*	29,000	\$4,060
211228561	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120A*	29,000	\$4,060
211228552	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716A*	29,200	\$4,088
211228543	HEIL	DLCURAH36ABK	EA*4X43L21A*	*96VSN0601714A*	29,200	\$4,088
211714235	HEIL	DLCURAH30ABK	END4X42L17**	*92ESN0801716A*	23,200	\$3,248
211228525	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002122A*	29,200	\$4,088
211228515	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002120A*	29,200	\$4,088
211228504	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95ESN0802120A*	29,200	\$4,088
211228482	HEIL	DLCURAH36ABK	EA*4X43L21A*	*95ESN0601714A*	29,400	\$4,116
211714247	HEIL	DLCURAH30ABK	END4X42L17**	*95ESN0601714A*	23,400	\$3,276
211228472	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002122A*	29,400	\$4,116
211228462	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002120A*	29,200	\$4,088
211228451	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92ESN0802120A*	29,200	\$4,088
211228440	HEIL	DLCURAH36ABK	EA*4X43L21A*	*92ESN0601714A*	29,000	\$4,060
211714259	HEIL	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701412A*	23,200	\$3,248
211228403	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122A*	29,200	\$4,088
211228393	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120A*	29,000	\$4,060
211228381	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716A*	29,000	\$4,060
211714272	HEIL	DLCURAH30ABK	END4X42L17**	*80ESU0601716A	23,400	\$3,276
211228370	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ESU1002120A*	29,000	\$4,060
211228359	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ESU0802120A	29,200	\$4,088
211228348	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ESU0601716A	29,200	\$4,088
211714283	HEIL	DLCURAH30ABK	END4X42L17**	OMV098J12*	23,400	\$3,276
211228337	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ESU0401712A*	29,400	\$4,116
211228327	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120A*	29,000	\$4,060
211714293	HEIL	DLCURAH30ABK	END4X42L17**	OLV098A12*	23,400	\$3,276
211228318	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VSL0702120A*	29,000	\$4,060
211228309	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716A*	29,200	\$4,088
211228300	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80VSL0451716A*	29,200	\$4,088
211228289	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211228277	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211714313	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	23,400	\$3,276
211228265	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211228253	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211228241	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211714323	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	23,400	\$3,276
211228229	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228217	HEIL	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228171	HEIL	DLCURAH36ABK	EA*4X42L24A*	OMV154L20A	29,400	\$4,116
211228162	HEIL	DLCURAH36ABK	EA*4X42L24A*	OLV154F20A	29,600	\$4,144
211714346	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	23,600	\$3,304
211714358	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	23,400	\$3,276
211714388	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	23,400	\$3,276
211714409	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	23,600	\$3,304
212970762	HEIL	DLCURAH48AAK	EA*4X48L24A*	*80VSL0902120B*	32,600	\$4,564
212970752	HEIL	DLCURAH48AAK	EA*4X48L21A*	*80VSL0902120B*	32,600	\$4,564
211714421	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	23,600	\$3,304
211714433	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	23,600	\$3,304
211714445	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0401712A*	23,400	\$3,276
212970802	HEIL	DLCURAH48ABK	EA*4X48L21A*	*80VSL0902120B*	31,400	\$4,396
212970812	HEIL	DLCURAH48ABK	EA*4X48L24A*	*80VSL0902120B*	31,400	\$4,396
212970822	HEIL	DLCURAH48ABK	EA*4X60L24A*	*80VSL0902120B*	31,000	\$4,340
212970842	HEIL	DLCURAH48ABK	EA*4X61L24A*	*80VSL0902120B*	31,000	\$4,340
212970832	HEIL	DLCURAH48ABK	EA*4X61L21A*	*80VSL0902120B*	31,000	\$4,340
211714471	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	23,400	\$3,276
211714483	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	23,400	\$3,276
211714516	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	23,400	\$3,276
211714540	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	23,600	\$3,304
211714553	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	23,400	\$3,276
211714566	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	23,600	\$3,304
211714579	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	23,400	\$3,276
211714592	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	23,600	\$3,304
211714629	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	23,400	\$3,276
211714641	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	23,400	\$3,276
211714665	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	23,400	\$3,276
211714690	HEIL	DLCURAH30ABK	FJMA4*36L*B*		23,400	\$3,276
212969882	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412B*	23,400	\$3,276
212969922	HEIL	DLCURAH30ABK	END4X42L17**	*80VSL0451412B*	23,400	\$3,276
212970302	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80VSL0701716B*	23,600	\$3,304
212970352	HEIL	DLCURAH30ABK	END4X42L17**	*80VSL0701716B*	23,400	\$3,276
212970362	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	23,600	\$3,304
212970592	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80VSL0902120B*	23,600	\$3,304
212970602	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902120B*	23,600	\$3,304
212970632	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	23,600	\$3,304
212971297	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412B*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971345	HEIL	DLCURAH30ABK	END4X42L17**	*80VTL0451412B*	23,400	\$3,276
212971782	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716B*	23,400	\$3,276
212971793	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716B*	23,200	\$3,248
212971804	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716B*	23,600	\$3,304
212971815	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716B*	23,200	\$3,248
212971859	HEIL	DLCURAH30ABK	END4X42L17**	*80VTL0701716B*	23,400	\$3,276
212971870	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	23,600	\$3,304
212972171	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120B*	23,200	\$3,248
212972182	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80VTL0902120B*	23,600	\$3,304
212972193	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80VTL0902120B*	23,600	\$3,304
212972204	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120B*	23,200	\$3,248
212972226	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	23,600	\$3,304
212972453	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122B*	23,400	\$3,276
212972465	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122B*	23,400	\$3,276
212972477	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122B*	23,400	\$3,276
212972489	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122B*	23,200	\$3,248
212973648	HEIL	DLCURAH30ABK	END4X42L17**	*96VSN0601412B*	23,600	\$3,304
212973968	HEIL	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716B*	23,400	\$3,276
212973978	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716B*	23,400	\$3,276
212973998	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716B*	23,200	\$3,248
212974038	HEIL	DLCURAH30ABK	END4X42L17**	*96VSN0801716B*	23,400	\$3,276
212974138	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120B*	23,200	\$3,248
212974148	HEIL	DLCURAH30ABK	EA*4X42L21A*	*96VSN0802120B*	23,400	\$3,276
212974158	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96VSN0802120B*	23,400	\$3,276
212974168	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120B*	23,200	\$3,248
212974188	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	23,600	\$3,304
212974358	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120B*	23,200	\$3,248
212974368	HEIL	DLCURAH30ABK	EA*4X42L21A*	*96VSN1002120B*	23,600	\$3,304
212974378	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96VSN1002120B*	23,600	\$3,304
212974388	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120B*	23,200	\$3,248
212974408	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	23,600	\$3,304
212974528	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96VSN1202422B*	23,600	\$3,304
212975767	HEIL	DLCURAH30ABK	END4X42L17**	*96VTN0601412B*	23,600	\$3,304
212976182	HEIL	DLCURAH30ABK	EA*4X37L17A*	*96VTN0801716B*	23,400	\$3,276
212976195	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VTN0801716B*	23,400	\$3,276
212976221	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VTN0801716B*	23,200	\$3,248
212976273	HEIL	DLCURAH30ABK	END4X42L17**	*96VTN0801716B*	23,400	\$3,276
212976451	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120B*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976464	HEIL	DLCURAH30ABK	EA*4X42L21A*	*96VTN0802120B*	23,400	\$3,276
212976478	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96VTN0802120B*	23,400	\$3,276
212976492	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120B*	23,200	\$3,248
212976519	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	23,600	\$3,304
212976722	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120B*	23,200	\$3,248
212976735	HEIL	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002120B*	23,600	\$3,304
212976748	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002120B*	23,600	\$3,304
212976761	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120B*	23,200	\$3,248
212976787	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	23,600	\$3,304
212977024	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122B*	23,200	\$3,248
212977034	HEIL	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002122B*	23,400	\$3,276
212977044	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002122B*	23,400	\$3,276
212977054	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122B*	23,200	\$3,248
212977074	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	23,400	\$3,276
212977246	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96VTN1202422B*	23,600	\$3,304
212977521	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	23,400	\$3,276
212977557	HEIL	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0451412A*	23,400	\$3,276
212978025	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	23,400	\$3,276
212978073	HEIL	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701412A*	23,400	\$3,276
212978528	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978539	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978550	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978561	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978605	HEIL	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701712A*	23,400	\$3,276
212978616	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	23,400	\$3,276
212979018	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	23,400	\$3,276
212979030	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979042	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	23,600	\$3,304
212979054	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979102	HEIL	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701716A*	23,400	\$3,276
212979114	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	23,600	\$3,304
212979438	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	23,200	\$3,248
212979448	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979458	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979468	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	23,200	\$3,248
212979708	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979720	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979732	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979744	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979792	HEIL	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0901714A*	23,400	\$3,276
212980196	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980229	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980251	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	23,600	\$3,304
212980515	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980526	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	23,600	\$3,304
212980548	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980570	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	23,600	\$3,304
212980703	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	23,600	\$3,304
212980905	HEIL	DLCURAH30ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980917	HEIL	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980929	HEIL	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980941	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980953	HEIL	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980977	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	23,600	\$3,304
212981115	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	23,400	\$3,276
212981224	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	23,600	\$3,304
212981325	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	23,400	\$3,276
212981587	HEIL	DLCURAH30ABK	EA*4X37L17A*	*80MSU1002120A*	23,400	\$3,276
212981671	HEIL	DLCURAH30ABK	END4X42L17**	*80MSU1002120A*	23,400	\$3,276
212982655	HEIL	DLCURAH30ABK	EA*4X42L24A*	*80MSU0601716A*	23,400	\$3,276
212983473	HEIL	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601412A*	23,400	\$3,276
212983503	HEIL	DLCURAH30ABK	END4X42L17**	*92MSN0601412A*	23,600	\$3,304
212983924	HEIL	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601714A*	23,400	\$3,276
212983936	HEIL	DLCURAH30ABK	EA*4X37L21A*	*92MSN0601714A*	23,200	\$3,248
212983960	HEIL	DLCURAH30ABK	EA*4X43L21A*	*92MSN0601714A*	23,200	\$3,248
212984008	HEIL	DLCURAH30ABK	END4X42L17**	*92MSN0601714A*	23,400	\$3,276
212984464	HEIL	DLCURAH30ABK	EA*4X37L17A*	*92MSN0801716A*	23,400	\$3,276
212984476	HEIL	DLCURAH30ABK	EA*4X37L21A*	*92MSN0801716A*	23,200	\$3,248
212984488	HEIL	DLCURAH30ABK	EA*4X42L21A*	*92MSN0801716A*	23,400	\$3,276
212984500	HEIL	DLCURAH30ABK	EA*4X43L21A*	*92MSN0801716A*	23,200	\$3,248
212984548	HEIL	DLCURAH30ABK	END4X42L17**	*92MSN0801716A*	23,400	\$3,276
212984976	HEIL	DLCURAH30ABK	EA*4X37L21A*	*92MSN0802120A*	23,200	\$3,248
212984986	HEIL	DLCURAH30ABK	EA*4X42L21A*	*92MSN0802120A*	23,400	\$3,276
212984996	HEIL	DLCURAH30ABK	EA*4X42L24A*	*92MSN0802120A*	23,400	\$3,276
212985006	HEIL	DLCURAH30ABK	EA*4X43L21A*	*92MSN0802120A*	23,200	\$3,248
212985026	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212985270	HEIL	DLCURAH30ABK	EA*4X37L21A*	*92MSN1002120A*	23,200	\$3,248
212985282	HEIL	DLCURAH30ABK	EA*4X42L21A*	*92MSN1002120A*	23,400	\$3,276
212985294	HEIL	DLCURAH30ABK	EA*4X42L24A*	*92MSN1002120A*	23,400	\$3,276
212985306	HEIL	DLCURAH30ABK	EA*4X43L21A*	*92MSN1002120A*	23,600	\$3,304
212985330	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	23,600	\$3,304
212985619	HEIL	DLCURAH30ABK	EA*4X42L24A*	*92MSN1202420A*	23,400	\$3,276
212985750	HEIL	DLCURAH30ABK	END4X42L17**	*96MSN0261410A*	23,600	\$3,304
212986854	HEIL	DLCURAH30ABK	END4X42L17**	*96MSN0601412A*	23,600	\$3,304
212987262	HEIL	DLCURAH30ABK	EA*4X37L17A*	*96MSN0801716A*	23,400	\$3,276
212987274	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96MSN0801716A*	23,200	\$3,248
212987298	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96MSN0801716A*	23,400	\$3,276
212987346	HEIL	DLCURAH30ABK	END4X42L17**	*96MSN0801716A*	23,600	\$3,304
212987358	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	23,600	\$3,304
212987730	HEIL	DLCURAH30ABK	EA*4X37L21A*	*96MSN0802120A*	23,200	\$3,248
212987754	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96MSN0802120A*	23,400	\$3,276
212987766	HEIL	DLCURAH30ABK	EA*4X43L21A*	*96MSN0802120A*	23,200	\$3,248
212988336	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96MSN1202422A*	23,400	\$3,276
212988418	HEIL	DLCURAH30ABK	EA*4X42L24A*	*96MSN1402422A*	23,600	\$3,304
212988584	HEIL	DLCURAH30ABK	EA*4X37L17A*	*95MSU0401712A*	23,600	\$3,304
212988596	HEIL	DLCURAH30ABK	EA*4X37L21A*	*95MSU0401712A*	23,200	\$3,248
212988620	HEIL	DLCURAH30ABK	EA*4X43L21A*	*95MSU0401712A*	23,200	\$3,248
212988632	HEIL	DLCURAH30ABK	END4X42L17**	*95MSU0401712A*	23,600	\$3,304
212989028	HEIL	DLCURAH30ABK	EA*4X37L17A*	*95MSU0601716A*	23,400	\$3,276
212989040	HEIL	DLCURAH30ABK	EA*4X37L21A*	*95MSU0601716A*	23,200	\$3,248
212989052	HEIL	DLCURAH30ABK	EA*4X42L21A*	*95MSU0601716A*	23,600	\$3,304
212989064	HEIL	DLCURAH30ABK	EA*4X43L21A*	*95MSU0601716A*	23,200	\$3,248
212989112	HEIL	DLCURAH30ABK	END4X42L17**	*95MSU0601716A*	23,400	\$3,276
212989124	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	23,600	\$3,304
212989532	HEIL	DLCURAH30ABK	EA*4X37L21A*	*95MSU0802120A*	23,200	\$3,248
212989544	HEIL	DLCURAH30ABK	EA*4X42L21A*	*95MSU0802120A*	23,600	\$3,304
212989556	HEIL	DLCURAH30ABK	EA*4X42L24A*	*95MSU0802120A*	23,600	\$3,304
212989568	HEIL	DLCURAH30ABK	EA*4X43L21A*	*95MSU0802120A*	23,200	\$3,248
212989592	HEIL	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	23,600	\$3,304
213249297	HEIL	DLCURAH30ABK	FEVA0036**+NAVA43601CK		23,600	\$3,304
213353813	HEIL	DLCURAH30ABK	F5MA4*30L*B*		23,400	\$3,276
213353823	HEIL	DLCURAH30ABK	F5MA4*36L*B*		23,600	\$3,304
211226265	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226277	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	29,600	\$4,144
211226289	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211226300	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80VSL0451716A*	29,600	\$4,144
211226310	HEIL	DLCURAH36ABK	EA*4X36L21A*	*80ESU1002120A*	29,400	\$4,116
211226332	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92ESN0601714A*	29,400	\$4,116
211226342	HEIL	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002122A*	29,600	\$4,144
211226352	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95ESN0601714A*	29,400	\$4,116
211226363	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95ESN0801716A*	29,400	\$4,116
211226374	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002120A*	29,600	\$4,144
211226384	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002122A*	29,600	\$4,144
211226394	HEIL	DLCURAH36ABK	EA*4X36L21A*	*95ESU0601716A*	29,400	\$4,116
211226405	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120A*	29,400	\$4,116
211226415	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120A*	29,600	\$4,144
211226424	HEIL	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122A*	29,400	\$4,116
211226433	HEIL	DLCURAH36ABK	EA*4X36L21A*	OLV098A12*	29,600	\$4,144
211226442	HEIL	DLCURAH36ABK	EA*4X36L21A*	OLV112A16A	29,600	\$4,144
211226451	HEIL	DLCURAH36ABK	EA*4X36L21A*	OMV098J12*	29,600	\$4,144
211226460	HEIL	DLCURAH36ABK	EA*4X36L21A*	OMV112K14A	29,600	\$4,144
211226488	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	29,400	\$4,116
211226500	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	29,200	\$4,088
211226512	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701712A*	29,400	\$4,116
211226524	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
211226535	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226546	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412A*	29,400	\$4,116
211226555	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451716A*	29,400	\$4,116
211226564	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716A*	29,400	\$4,116
211226585	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412A*	29,400	\$4,116
211226597	HEIL	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716A*	29,400	\$4,116
211226618	HEIL	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601412A*	29,400	\$4,116
211226629	HEIL	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601714A*	29,200	\$4,088
211226640	HEIL	DLCURAH36ABK	EA*4X37L17A*	*92ESN0801716A*	29,400	\$4,116
211226662	HEIL	DLCURAH36ABK	EA*4X37L17A*	*95ESN0601714A*	29,400	\$4,116
211226672	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412A*	29,400	\$4,116
211226681	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601714A*	29,400	\$4,116
211226690	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716A*	29,400	\$4,116
211226700	HEIL	DLCURAH36ABK	EA*4X37L17A*	*95ESU0601716A*	29,400	\$4,116
211226711	HEIL	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601714A*	29,400	\$4,116
211226720	HEIL	DLCURAH36ABK	EA*4X37L17A*	OLV098A12*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226729	HEIL	DLCURAH36ABK	EA*4X37L17A*	OMV098J12*	29,400	\$4,116
211226738	HEIL	DLCURAH36ABK	EA*4X37L17A*	OMV112K14A	29,400	\$4,116
211226796	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211226808	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211226820	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226832	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211226844	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211226856	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211226867	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VSL0451716A*	29,200	\$4,088
211226876	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716A*	29,200	\$4,088
211226885	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VSL0702120A*	29,000	\$4,060
211226894	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120A*	29,000	\$4,060
211226904	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ESU0401712A*	29,400	\$4,116
211226915	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ESU0601716A	29,200	\$4,088
211226926	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ESU0802120A	29,400	\$4,116
211226937	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80ESU1002120A*	29,000	\$4,060
211226948	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716A*	29,000	\$4,060
211226960	HEIL	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122A*	29,200	\$4,088
211226997	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92ESN0601714A*	29,000	\$4,060
211227008	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92ESN0801716A*	29,000	\$4,060
211227019	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92ESN0802120A*	29,200	\$4,088
211227029	HEIL	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002122A*	29,400	\$4,116
211227039	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95ESN0601714A*	29,400	\$4,116
211227061	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95ESN0802120A*	29,200	\$4,088
211227072	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002120A*	29,200	\$4,088
211227082	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002122A*	29,200	\$4,088
211227100	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VSN0601714A*	29,200	\$4,088
211227109	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716A*	29,200	\$4,088
211227118	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120A*	29,000	\$4,060
211227127	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120A*	29,000	\$4,060
211227137	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95ESU0802120A*	29,400	\$4,116
211227148	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002120A*	29,000	\$4,060
211227158	HEIL	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002122A*	29,200	\$4,088
211227178	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VTN0601714A*	29,200	\$4,088
211227188	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120A*	29,200	\$4,088
211227198	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120A*	29,200	\$4,088
211227207	HEIL	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122A*	29,000	\$4,060
211227216	HEIL	DLCURAH36ABK	EA*4X37L21A*	OLV098A12*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227225	HEIL	DLCURAH36ABK	EA*4X37L21A*	OLV112A16A	29,200	\$4,088
211227234	HEIL	DLCURAH36ABK	EA*4X37L21A*	OMV098J12*	29,200	\$4,088
211227243	HEIL	DLCURAH36ABK	EA*4X37L21A*	OMV112K14A	29,200	\$4,088
211227289	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0451712A*	29,400	\$4,116
211227301	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701712A*	29,400	\$4,116
211227313	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
211227324	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227336	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	29,400	\$4,116
211227348	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227360	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227372	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227383	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VSL0451716A*	29,400	\$4,116
211227392	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716A*	29,400	\$4,116
211227401	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VSL0702120A*	29,400	\$4,116
211227410	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120A*	29,400	\$4,116
211227431	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ESU0601716A	29,200	\$4,088
211227442	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ESU0802120A	29,600	\$4,144
211227453	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80ESU1002120A*	29,400	\$4,116
211227464	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716A*	29,400	\$4,116
211227476	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120A*	29,400	\$4,116
211227486	HEIL	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122A*	29,400	\$4,116
211227514	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92ESN0601714A*	29,400	\$4,116
211227525	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92ESN0801716A*	29,400	\$4,116
211227536	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92ESN0802120A*	29,200	\$4,088
211227547	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002120A*	29,200	\$4,088
211227557	HEIL	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002122A*	29,600	\$4,144
211227567	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95ESN0601714A*	29,400	\$4,116
211227578	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95ESN0802120A*	29,400	\$4,116
211227588	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95ESN1002122A*	29,600	\$4,144
211227597	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VSN0601714A*	29,400	\$4,116
211227606	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716A*	29,400	\$4,116
211227615	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120A*	29,400	\$4,116
211227624	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120A*	29,400	\$4,116
211227634	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95ESU0601716A*	29,400	\$4,116
211227645	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95ESU0802120A*	29,600	\$4,144
211227656	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002120A*	29,400	\$4,116
211227666	HEIL	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002122A*	29,600	\$4,144
211227676	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VTN0601714A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227686	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716A*	29,400	\$4,116
211227696	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120A*	29,400	\$4,116
211227706	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120A*	29,400	\$4,116
211227715	HEIL	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122A*	29,200	\$4,088
211227724	HEIL	DLCURAH36ABK	EA*4X42L21A*	OLV098A12*	29,400	\$4,116
211227733	HEIL	DLCURAH36ABK	EA*4X42L21A*	OMV098J12*	29,400	\$4,116
211227742	HEIL	DLCURAH36ABK	EA*4X42L21A*	OMV112K14A	29,400	\$4,116
211227770	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227782	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227794	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227806	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	29,400	\$4,116
211227818	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227830	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	29,200	\$4,088
211227842	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	29,400	\$4,116
211227854	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1552420A*	29,400	\$4,116
211227863	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80VSL0702120A*	29,400	\$4,116
211227872	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120A*	29,400	\$4,116
211227881	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902420A*	29,400	\$4,116
211227890	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80VSL1102422A*	29,200	\$4,088
211227900	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ESU0802120A	29,600	\$4,144
211227911	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80ESU1002120A*	29,400	\$4,116
211227922	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120A*	29,400	\$4,116
211227932	HEIL	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122A*	29,400	\$4,116
211227962	HEIL	DLCURAH36ABK	EA*4X42L24A*	*92ESN0802120A*	29,200	\$4,088
211227973	HEIL	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002120A*	29,200	\$4,088
211227983	HEIL	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002122A*	29,600	\$4,144
211227993	HEIL	DLCURAH36ABK	EA*4X42L24A*	*92ESN1202420A*	29,400	\$4,116
211228004	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95ESN0802120A*	29,400	\$4,116
211228015	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002120A*	29,400	\$4,116
211228025	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002122A*	29,600	\$4,144
211228035	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95ESN1202422A*	29,600	\$4,144
211228046	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95ESN1402422A*	29,600	\$4,144
211228056	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120A*	29,400	\$4,116
211228065	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120A*	29,400	\$4,116
211228074	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422A*	29,400	\$4,116
211228084	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95ESU0802120A*	29,600	\$4,144
211228095	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002120A*	29,400	\$4,116
211228105	HEIL	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002122A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228115	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120A*	29,400	\$4,116
211228125	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120A*	29,400	\$4,116
211228134	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122A*	29,200	\$4,088
211228144	HEIL	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422A*	29,400	\$4,116
211228153	HEIL	DLCURAH36ABK	EA*4X42L24A*	OLV112A16A	29,400	\$4,116
213353783	HEIL	DLCURAH24ABK	F5MA4*30L*B*		19,100	\$2,674
213353773	HEIL	DLCURAH24ABK	F5MA4*24L*B*		19,300	\$2,702
213249275	HEIL	DLCURAH24ABK	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076403	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601716B*	19,400	\$2,716
213076377	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601716B*	19,400	\$2,716
213076366	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002122A*	19,100	\$2,674
213076348	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95MSU1002122A*	19,000	\$2,660
213076121	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002120A*	19,200	\$2,688
213076109	HEIL	DLCURAH24ABK	EA*4X37L21A*	*95MSU1002120A*	18,500	\$2,590
212989628	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0802120A*	19,100	\$2,674
212989616	HEIL	DLCURAH24ABK	EA*4X37L21A*	*95MSU0802120A*	18,600	\$2,604
212989604	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95MSU0802120A*	19,100	\$2,674
212989256	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0601716A*	19,100	\$2,674
212989244	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0601716A*	19,100	\$2,674
212989232	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0601716A*	19,100	\$2,674
212989220	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0601716A*	19,400	\$2,716
212989208	HEIL	DLCURAH24ABK	EA*4X37L21A*	*95MSU0601716A*	18,700	\$2,618
212989196	HEIL	DLCURAH24ABK	EA*4X37L17A*	*95MSU0601716A*	18,900	\$2,646
212989184	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95MSU0601716A*	19,100	\$2,674
212989172	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95MSU0601716A*	19,100	\$2,674
212989160	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95MSU0601716A*	19,100	\$2,674
212989148	HEIL	DLCURAH24ABK	EA*4X25L17A*	*95MSU0601716A*	18,600	\$2,604
212989136	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95MSU0601716A*	19,400	\$2,716
212988764	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0401712A*	19,200	\$2,688
212988752	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0401712A*	19,200	\$2,688
212988740	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0401712A*	19,200	\$2,688
212988728	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0401712A*	19,500	\$2,730
212988716	HEIL	DLCURAH24ABK	EA*4X37L21A*	*95MSU0401712A*	18,600	\$2,604
212988704	HEIL	DLCURAH24ABK	EA*4X37L17A*	*95MSU0401712A*	18,800	\$2,632
212988692	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95MSU0401712A*	19,000	\$2,660
212988680	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95MSU0401712A*	19,100	\$2,674
212988668	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95MSU0401712A*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988656	HEIL	DLCURAH24ABK	EA*4X25L17A*	*95MSU0401712A*	18,700	\$2,618
212988644	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95MSU0401712A*	19,500	\$2,730
212987826	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0802120A*	19,100	\$2,674
212987814	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96MSN0802120A*	18,700	\$2,618
212987802	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96MSN0802120A*	19,100	\$2,674
212987490	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0801716A*	19,200	\$2,688
212987478	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0801716A*	19,200	\$2,688
212987466	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0801716A*	19,200	\$2,688
212987454	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0801716A*	19,500	\$2,730
212987442	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96MSN0801716A*	19,800	\$2,772
212987430	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96MSN0801716A*	18,800	\$2,632
212987418	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96MSN0801716A*	19,000	\$2,660
212987406	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96MSN0801716A*	19,100	\$2,674
212987394	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96MSN0801716A*	19,200	\$2,688
212987382	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96MSN0801716A*	18,700	\$2,618
212987370	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96MSN0801716A*	19,400	\$2,716
212986974	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0601412A*	19,200	\$2,688
212986964	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0601412A*	19,200	\$2,688
212986954	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0601412A*	19,200	\$2,688
212986944	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0601412A*	19,500	\$2,730
212986934	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0601412A*	19,500	\$2,730
212986924	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96MSN0601412A*	18,800	\$2,632
212986914	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96MSN0601412A*	19,100	\$2,674
212986904	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96MSN0601412A*	19,100	\$2,674
212986894	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96MSN0601412A*	19,200	\$2,688
212986884	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96MSN0601412A*	18,700	\$2,618
212986874	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96MSN0601412A*	19,400	\$2,716
212986864	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96MSN0601412A*	19,400	\$2,716
212986650	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0401712A*	19,100	\$2,674
212986638	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401712A*	19,100	\$2,674
212986626	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401712A*	19,100	\$2,674
212986614	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401712A*	19,700	\$2,758
211289634	HEIL	DLCURAH60ABK	FVM4X60***L		37,800	\$5,292
213607744	HEIL	DLCURAH36ABK	FTMA4B48L0C*		28,800	\$4,032
213607729	HEIL	DLCURAH36ABK	FTMA4B36L0C*		29,400	\$4,116
213607684	HEIL	DLCURAH30ABK	FTMA4B36L0C*		23,600	\$3,304
213607654	HEIL	DLCURAH24ABK	FTMA4X24L0B*		19,300	\$2,702
213607639	HEIL	DLCURAH24ABK	FTMA4B36L0C*		19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213607594	HEIL	DLCURAH18ABK	FTMA4X24L0B*		12,400	\$1,736
212986602	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96MSN0401712A*	18,800	\$2,632
212986590	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401712A*	19,000	\$2,660
212986578	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96MSN0401712A*	19,200	\$2,688
212986566	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401712A*	19,200	\$2,688
212986554	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401712A*	19,200	\$2,688
212986542	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401712A*	18,900	\$2,646
212986530	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401712A*	19,500	\$2,730
212986266	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401410A*	19,200	\$2,688
212986254	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401410A*	19,200	\$2,688
212986146	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401410A*	19,500	\$2,730
212986134	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96MSN0401410A*	19,500	\$2,730
212985870	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0261410A*	19,000	\$2,660
212985860	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0261410A*	19,000	\$2,660
212985850	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0261410A*	19,100	\$2,674
212985840	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0261410A*	19,500	\$2,730
212985830	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0261410A*	19,500	\$2,730
212985820	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96MSN0261410A*	18,800	\$2,632
212985810	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96MSN0261410A*	19,100	\$2,674
212985800	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96MSN0261410A*	19,100	\$2,674
212985790	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96MSN0261410A*	19,200	\$2,688
212985780	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96MSN0261410A*	18,700	\$2,618
212985770	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96MSN0261410A*	19,500	\$2,730
212985760	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96MSN0261410A*	19,500	\$2,730
212985366	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN1002120A*	19,100	\$2,674
212985354	HEIL	DLCURAH24ABK	EA*4X37L21A*	*92MSN1002120A*	18,700	\$2,618
212985342	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92MSN1002120A*	19,100	\$2,674
212985056	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0802120A*	19,000	\$2,660
212985046	HEIL	DLCURAH24ABK	EA*4X37L21A*	*92MSN0802120A*	18,900	\$2,646
212985036	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92MSN0802120A*	19,000	\$2,660
212984692	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0801716A*	19,100	\$2,674
212984680	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0801716A*	19,100	\$2,674
212984668	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0801716A*	19,100	\$2,674
212984656	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0801716A*	19,500	\$2,730
212984644	HEIL	DLCURAH24ABK	EA*4X37L21A*	*92MSN0801716A*	18,400	\$2,576
212984632	HEIL	DLCURAH24ABK	EA*4X37L17A*	*92MSN0801716A*	18,900	\$2,646
212984620	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92MSN0801716A*	19,000	\$2,660
212984608	HEIL	DLCURAH24ABK	EA*4X36L17A*	*92MSN0801716A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984596	HEIL	DLCURAH24ABK	EA*4X30L17A*	*92MSN0801716A*	19,100	\$2,674
212984584	HEIL	DLCURAH24ABK	EA*4X25L17A*	*92MSN0801716A*	18,500	\$2,590
212984572	HEIL	DLCURAH24ABK	EA*4X24L17A*	*92MSN0801716A*	19,300	\$2,702
212984152	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0601714A*	19,100	\$2,674
212984140	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601714A*	19,100	\$2,674
212984128	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601714A*	19,100	\$2,674
212984116	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601714A*	19,400	\$2,716
212984104	HEIL	DLCURAH24ABK	EA*4X37L21A*	*92MSN0601714A*	18,700	\$2,618
212984092	HEIL	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601714A*	18,900	\$2,646
212984080	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92MSN0601714A*	19,100	\$2,674
212984068	HEIL	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601714A*	19,100	\$2,674
212984056	HEIL	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601714A*	19,100	\$2,674
212984044	HEIL	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601714A*	18,700	\$2,618
212984032	HEIL	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601714A*	19,400	\$2,716
212983623	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601412A*	19,200	\$2,688
212983613	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601412A*	19,200	\$2,688
212983603	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*92MSN0601412A*	19,200	\$2,688
212983593	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601412A*	19,500	\$2,730
212983583	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*92MSN0601412A*	19,500	\$2,730
212983573	HEIL	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601412A*	19,000	\$2,660
212983563	HEIL	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601412A*	19,200	\$2,688
212983553	HEIL	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601412A*	19,200	\$2,688
212983543	HEIL	DLCURAH24ABK	EA*4X30L14A*	*92MSN0601412A*	19,200	\$2,688
212983533	HEIL	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601412A*	18,800	\$2,632
212983523	HEIL	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601412A*	19,500	\$2,730
212983513	HEIL	DLCURAH24ABK	EA*4X24L14A*	*92MSN0601412A*	19,500	\$2,730
212983246	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0401712A*	19,200	\$2,688
212983235	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0401712A*	19,200	\$2,688
212983224	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0401712A*	19,200	\$2,688
212983213	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0401712A*	19,600	\$2,744
212983202	HEIL	DLCURAH24ABK	EA*4X37L21A*	*92MSN0401712A*	18,800	\$2,632
212983191	HEIL	DLCURAH24ABK	EA*4X37L17A*	*92MSN0401712A*	19,000	\$2,660
212983180	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92MSN0401712A*	19,200	\$2,688
212983169	HEIL	DLCURAH24ABK	EA*4X36L17A*	*92MSN0401712A*	19,200	\$2,688
212983158	HEIL	DLCURAH24ABK	EA*4X30L17A*	*92MSN0401712A*	19,300	\$2,702
212983147	HEIL	DLCURAH24ABK	EA*4X25L17A*	*92MSN0401712A*	18,800	\$2,632
212983136	HEIL	DLCURAH24ABK	EA*4X24L17A*	*92MSN0401712A*	19,500	\$2,730
212981815	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU1002120A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212981803	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	19,200	\$2,688
212981791	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU1002120A*	19,200	\$2,688
212981779	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU1002120A*	19,500	\$2,730
212981755	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80MSU1002120A*	18,800	\$2,632
212981743	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MSU1002120A*	19,100	\$2,674
212981731	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80MSU1002120A*	19,000	\$2,660
212981719	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80MSU1002120A*	19,100	\$2,674
212981707	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80MSU1002120A*	18,700	\$2,618
212981695	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80MSU1002120A*	19,500	\$2,730
212981013	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)1102120A*	19,100	\$2,674
212981001	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	18,800	\$2,632
212980989	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	19,000	\$2,660
212980603	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902120A*	19,100	\$2,674
212980592	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	18,600	\$2,604
212980581	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	19,100	\$2,674
212980284	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902116A*	19,100	\$2,674
212980273	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	18,600	\$2,604
212980262	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	19,000	\$2,660
212979936	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0901714A*	19,100	\$2,674
212979924	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979912	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979900	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	19,500	\$2,730
212979888	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979876	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979864	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979852	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979840	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979828	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	18,600	\$2,604
212979816	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	19,400	\$2,716
212979518	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0702116A*	19,200	\$2,688
212979508	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	18,600	\$2,604
212979498	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	19,100	\$2,674
212979246	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	19,100	\$2,674
212979234	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979222	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979210	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701716A*	19,400	\$2,716
212979198	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979186	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	18,700	\$2,618

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979174	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979162	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979150	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979138	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212978649	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978638	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	18,600	\$2,604
212978627	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	19,400	\$2,716
212978217	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978205	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978193	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	19,100	\$2,674
212978181	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	19,400	\$2,716
212978169	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	19,400	\$2,716
212978157	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	18,700	\$2,618
212978145	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	19,000	\$2,660
212978133	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978121	HEIL	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978109	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	18,600	\$2,604
212978097	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	19,400	\$2,716
212978085	HEIL	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	19,300	\$2,702
212977701	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977689	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977677	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	19,000	\$2,660
212977665	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	19,500	\$2,730
212977653	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	19,500	\$2,730
212977641	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977629	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977617	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977605	HEIL	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977593	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977581	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977569	HEIL	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977004	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122B*	19,200	\$2,688
212976984	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122B*	19,100	\$2,674
212976696	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120B*	19,100	\$2,674
212976683	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002120B*	18,600	\$2,604
212976670	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120B*	19,000	\$2,660
212976422	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120B*	19,200	\$2,688
212976408	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120B*	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976395	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120B*	19,100	\$2,674
212976130	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716B*	18,900	\$2,646
212976117	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716B*	18,900	\$2,646
212976104	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716B*	18,900	\$2,646
212976091	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716B*	19,500	\$2,730
212976065	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716B*	19,000	\$2,660
212976052	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716B*	19,000	\$2,660
212976039	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716B*	19,000	\$2,660
212976026	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716B*	19,100	\$2,674
212976013	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VTN0801716B*	18,800	\$2,632
212976000	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716B*	19,500	\$2,730
212975756	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412B*	19,100	\$2,674
212975745	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412B*	19,100	\$2,674
212975734	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412B*	19,000	\$2,660
212975723	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412B*	19,500	\$2,730
212975712	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412B*	19,500	\$2,730
212975701	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412B*	18,800	\$2,632
212975690	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412B*	19,100	\$2,674
212975679	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412B*	19,100	\$2,674
212975668	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412B*	19,100	\$2,674
212975657	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412B*	18,600	\$2,604
212975646	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412B*	19,400	\$2,716
212975635	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412B*	19,400	\$2,716
212975371	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712B*	19,200	\$2,688
212975360	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712B*	19,200	\$2,688
212975349	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712B*	19,200	\$2,688
212975338	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712B*	19,600	\$2,744
212975327	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712B*	18,900	\$2,646
212975316	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401712B*	18,900	\$2,646
212975305	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712B*	19,100	\$2,674
212975294	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712B*	19,100	\$2,674
212975283	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712B*	19,200	\$2,688
212975272	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712B*	18,800	\$2,632
212975261	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712B*	19,500	\$2,730
212975062	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410B*	19,200	\$2,688
212975049	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410B*	19,200	\$2,688
212975036	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410B*	19,100	\$2,674
212975023	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410B*	19,600	\$2,744

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975010	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410B*	19,600	\$2,744
212974997	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410B*	18,800	\$2,632
212974984	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410B*	19,200	\$2,688
212974971	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410B*	19,200	\$2,688
212974958	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410B*	19,200	\$2,688
212974945	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401410B*	18,700	\$2,618
212974932	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410B*	19,500	\$2,730
212974919	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410B*	19,500	\$2,730
212974328	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VSN1002120B*	18,900	\$2,646
212974318	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120B*	19,000	\$2,660
212974118	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120B*	19,200	\$2,688
212974108	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VSN0802120B*	18,600	\$2,604
212974098	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120B*	19,100	\$2,674
212973928	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716B*	18,900	\$2,646
212973918	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716B*	18,900	\$2,646
212973908	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716B*	18,900	\$2,646
212973898	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716B*	19,500	\$2,730
212973878	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716B*	19,000	\$2,660
212973868	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716B*	19,000	\$2,660
212973858	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716B*	19,000	\$2,660
212973848	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716B*	19,100	\$2,674
212973838	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VSN0801716B*	18,800	\$2,632
212973828	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716B*	19,500	\$2,730
212973638	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412B*	19,100	\$2,674
212973628	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412B*	19,100	\$2,674
212973618	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412B*	19,000	\$2,660
212973608	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412B*	19,500	\$2,730
212973598	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412B*	19,500	\$2,730
212973588	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412B*	18,800	\$2,632
212973578	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412B*	19,100	\$2,674
212973568	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412B*	19,100	\$2,674
212973558	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412B*	19,100	\$2,674
212973548	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412B*	18,600	\$2,604
212973538	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412B*	19,400	\$2,716
212973528	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412B*	19,400	\$2,716
212973288	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712B*	19,200	\$2,688
212973278	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712B*	19,200	\$2,688
212973268	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712B*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973258	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712B*	19,600	\$2,744
212973248	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712B*	18,900	\$2,646
212973238	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401712B*	18,900	\$2,646
212973228	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712B*	19,100	\$2,674
212973218	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712B*	19,100	\$2,674
212973208	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712B*	19,200	\$2,688
212973198	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712B*	18,800	\$2,632
212973188	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712B*	19,500	\$2,730
212973008	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410B*	19,200	\$2,688
212972998	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410B*	19,200	\$2,688
212972988	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410B*	19,200	\$2,688
212972978	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410B*	19,500	\$2,730
212972968	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410B*	19,500	\$2,730
212972958	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410B*	19,000	\$2,660
212972948	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410B*	19,200	\$2,688
212972938	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410B*	19,200	\$2,688
212972928	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410B*	19,200	\$2,688
212972918	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401410B*	18,800	\$2,632
212972908	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410B*	19,500	\$2,730
212972898	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410B*	19,500	\$2,730
212972429	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122B*	19,200	\$2,688
212972417	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122B*	18,800	\$2,632
212972405	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122B*	19,100	\$2,674
212972149	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120B*	19,100	\$2,674
212972138	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80VTL0902120B*	18,900	\$2,646
212972127	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120B*	19,100	\$2,674
212971738	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716B*	19,100	\$2,674
212971727	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716B*	19,100	\$2,674
212971716	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716B*	19,100	\$2,674
212971705	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716B*	19,500	\$2,730
212971694	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80VTL0701716B*	18,700	\$2,618
212971683	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716B*	18,700	\$2,618
212971672	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716B*	19,100	\$2,674
212971661	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716B*	19,100	\$2,674
212971650	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716B*	19,100	\$2,674
212971639	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80VTL0701716B*	18,600	\$2,604
212971628	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716B*	19,400	\$2,716
212971249	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412B*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971237	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412B*	19,100	\$2,674
212971225	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412B*	19,000	\$2,660
212971213	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412B*	19,500	\$2,730
212971201	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412B*	19,500	\$2,730
212971189	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412B*	18,700	\$2,618
212971177	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412B*	19,000	\$2,660
212971165	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412B*	19,100	\$2,674
212971153	HEIL	DLCURAH24ABK	EA*4X30L14A*	*80VTL0451412B*	19,100	\$2,674
212969842	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412B*	19,100	\$2,674
212969832	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412B*	19,100	\$2,674
212969822	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412B*	19,000	\$2,660
212969812	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412B*	19,500	\$2,730
212969802	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412B*	19,500	\$2,730
212969792	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451412B*	18,700	\$2,618
212969782	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412B*	19,000	\$2,660
212969772	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412B*	19,100	\$2,674
212969762	HEIL	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412B*	19,100	\$2,674
212969752	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80VSL0451412B*	18,500	\$2,590
212969742	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412B*	19,300	\$2,702
211245986	HEIL	DLCURAH24ABK	FVM4X36***L		19,000	\$2,660
211245976	HEIL	DLCURAH24ABK	FVM4X24***L		19,000	\$2,660
211245965	HEIL	DLCURAH24ABK	FM(C,U)4Z36**AL*		19,300	\$2,702
211245954	HEIL	DLCURAH24ABK	FM(C,U)4Z30**AL*		19,300	\$2,702
211245943	HEIL	DLCURAH24ABK	FM(C,U)4Z24**AL*		19,500	\$2,730
211245932	HEIL	DLCURAH24ABK	FM(C,U)4X36**AL*		19,900	\$2,786
211245921	HEIL	DLCURAH24ABK	FM(C,U)4X30**AL*		19,900	\$2,786
211245910	HEIL	DLCURAH24ABK	FMA4X36**AL*		19,600	\$2,744
211245899	HEIL	DLCURAH24ABK	FMA4X30**AL*		19,600	\$2,744
211245888	HEIL	DLCURAH24ABK	FMA4X24**AL*		19,600	\$2,744
211245866	HEIL	DLCURAH24ABK	FMA4P24**AL*		19,900	\$2,786
211245855	HEIL	DLCURAH24ABK	FXM4X36**AL		18,500	\$2,590
211245844	HEIL	DLCURAH24ABK	FXM4X30**AL		19,100	\$2,674
211245833	HEIL	DLCURAH24ABK	FXM4X24**AL		19,100	\$2,674
211245822	HEIL	DLCURAH24ABK	FEM4X30**BL		19,100	\$2,674
211245810	HEIL	DLCURAH24ABK	FEM4X24**CL		19,000	\$2,660
211245798	HEIL	DLCURAH24ABK	FEM4P30**AL		19,100	\$2,674
211245787	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	OLV112A16A	19,300	\$2,702
211245778	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	OMV112K14A	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245769	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	OLV098A12*	18,900	\$2,646
211245760	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	OMV098J12*	19,000	\$2,660
211245750	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0601716A	19,300	\$2,702
211245739	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0802120A	19,100	\$2,674
211245728	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0401712A*	19,100	\$2,674
211245717	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0801716A*	19,500	\$2,730
211245706	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0601714A*	19,400	\$2,716
211245695	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN1002120A*	19,300	\$2,702
211245684	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0802120A*	19,300	\$2,702
211245673	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0801716A*	19,100	\$2,674
211245662	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0601714A*	19,100	\$2,674
211245650	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)1102120A*	19,400	\$2,716
211245638	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0902120A*	19,300	\$2,702
211245626	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0901714A*	19,200	\$2,688
211245614	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0702116A*	19,100	\$2,674
211245602	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701712A*	19,200	\$2,688
211245590	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0451712A*	19,100	\$2,674
211245580	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122A*	19,000	\$2,660
211245570	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120A*	19,000	\$2,660
211245560	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120A*	18,900	\$2,646
211245550	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0601714A*	19,100	\$2,674
211245539	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0401712A*	19,400	\$2,716
211245529	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716A*	19,100	\$2,674
211245519	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716A*	19,100	\$2,674
211245508	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0802120A*	19,300	\$2,702
211245498	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712A*	19,000	\$2,660
211245488	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120A*	19,000	\$2,660
211245475	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0401712A*	19,000	\$2,660
211245464	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0601716A*	19,100	\$2,674
211245454	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0902120A*	19,000	\$2,660
211245445	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0702120A*	19,300	\$2,702
211245436	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0701716A*	19,000	\$2,660
211245427	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0451716A*	19,200	\$2,688
211245382	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122A*	18,900	\$2,646
211245372	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701716A*	19,400	\$2,716
211245361	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0401712A*	19,000	\$2,660
211245351	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716A*	19,100	\$2,674
211245342	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245333	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN1002120A*	19,000	\$2,660
211245324	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120A*	19,000	\$2,660
211245315	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0601714A*	18,900	\$2,646
211245279	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV112K14A	19,200	\$2,688
211245270	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	OLV098A12*	18,900	\$2,646
211245261	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV098J12*	19,000	\$2,660
211245251	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0601716A	19,300	\$2,702
211245239	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211245228	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401712A*	19,100	\$2,674
211245217	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401410A*	19,400	\$2,716
211245206	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0801716A*	19,500	\$2,730
211245195	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601714A*	19,400	\$2,716
211245184	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0801716A*	19,100	\$2,674
211245173	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601714A*	19,100	\$2,674
211245162	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601412A*	18,900	\$2,646
211245150	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211245138	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211245126	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211245114	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211245104	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601714A*	19,100	\$2,674
211245093	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0261410A*	18,900	\$2,646
211245083	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412A*	19,000	\$2,660
211245073	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410A*	19,000	\$2,660
211245062	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601412A*	19,400	\$2,716
211245051	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401712A*	19,400	\$2,716
211245040	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401410A*	19,500	\$2,730
211245030	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716A*	19,100	\$2,674
211245020	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716A*	19,100	\$2,674
211245010	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712A*	19,000	\$2,660
211244996	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412A*	19,100	\$2,674
211244985	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0401712A*	19,000	\$2,660
211244974	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0601716A*	19,100	\$2,674
211244964	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0701716A*	19,000	\$2,660
211244955	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451716A*	19,200	\$2,688
211244927	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244916	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0401712A*	19,000	\$2,660
211244906	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716A*	19,100	\$2,674
211244897	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244888	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712A*	19,000	\$2,660
211244879	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410A*	19,000	\$2,660
211244870	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601714A*	18,900	\$2,646
211244852	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412A*	18,900	\$2,646
211244843	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	OMV112K14A	19,200	\$2,688
211244834	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	OLV098A12*	18,900	\$2,646
211244825	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	OMV098J12*	19,000	\$2,660
213372147	HEIL	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372143	HEIL	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
211244815	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0601716A	19,300	\$2,702
211244803	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211244792	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401712A*	19,100	\$2,674
211244781	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401410A*	19,400	\$2,716
211244770	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0801716A*	19,500	\$2,730
211244759	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601714A*	19,400	\$2,716
211244748	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0801716A*	19,100	\$2,674
211244737	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601714A*	19,100	\$2,674
211244726	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601412A*	18,900	\$2,646
211244714	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211244702	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211244690	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211244678	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211244668	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601714A*	19,100	\$2,674
211244657	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0261410A*	18,900	\$2,646
211244647	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412A*	19,000	\$2,660
211244637	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410A*	19,000	\$2,660
211244626	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601412A*	19,400	\$2,716
211244615	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401712A*	19,400	\$2,716
211244604	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401410A*	19,500	\$2,730
211244594	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716A*	19,100	\$2,674
211244584	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716A*	19,100	\$2,674
211244574	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712A*	19,000	\$2,660
211244560	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412A*	19,100	\$2,674
211244549	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0401712A*	19,000	\$2,660
211244538	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0601716A*	19,100	\$2,674
211244528	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0701716A*	19,000	\$2,660
211244519	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451716A*	19,200	\$2,688
211244491	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701716A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244480	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0401712A*	19,000	\$2,660
211244470	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716A*	19,100	\$2,674
211244461	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412A*	19,000	\$2,660
211244452	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712A*	19,000	\$2,660
211244443	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410A*	19,000	\$2,660
211244434	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601714A*	18,900	\$2,646
211244416	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412A*	18,900	\$2,646
211244405	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	19,100	\$2,674
211244394	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0401410A*	19,400	\$2,716
211244383	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0601412A*	18,900	\$2,646
211244371	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	19,300	\$2,702
211244360	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0261410A*	19,500	\$2,730
211244350	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412A*	19,000	\$2,660
211244340	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410A*	19,100	\$2,674
211244329	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0601412A*	19,400	\$2,716
211244318	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0401410A*	19,500	\$2,730
211244306	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412A*	19,100	\$2,674
211244296	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412A*	19,000	\$2,660
211244287	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410A*	19,100	\$2,674
211244278	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412A*	19,200	\$2,688
211244269	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	OMV112K14A	19,700	\$2,758
211244260	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	OLV098A12*	19,300	\$2,702
211244251	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	OMV098J12*	19,400	\$2,716
211244241	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0601716A	19,600	\$2,744
211244229	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	19,500	\$2,730
211244218	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401712A*	19,500	\$2,730
211244207	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401410A*	19,700	\$2,758
211244196	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0801716A*	19,800	\$2,772
211244185	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601714A*	19,700	\$2,758
211244174	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0801716A*	19,400	\$2,716
211244163	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601714A*	19,500	\$2,730
211244152	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601412A*	19,600	\$2,744
211244140	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0901714A*	19,500	\$2,730
211244128	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	19,500	\$2,730
211244116	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	19,400	\$2,716
211244104	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	19,600	\$2,744
211244094	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601714A*	19,400	\$2,716
211244083	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0261410A*	19,900	\$2,786

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244073	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412A*	19,300	\$2,702
211244063	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410A*	19,500	\$2,730
211244052	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601412A*	19,700	\$2,758
211244041	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401712A*	19,700	\$2,758
211244030	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401410A*	19,800	\$2,772
211244020	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716A*	19,400	\$2,716
211244010	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716A*	19,500	\$2,730
211244000	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712A*	19,700	\$2,758
211243986	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412A*	19,500	\$2,730
211243975	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0401712A*	19,300	\$2,702
211243964	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0601716A*	19,400	\$2,716
211243954	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0701716A*	19,400	\$2,716
211243945	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451716A*	19,500	\$2,730
211243917	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701716A*	19,700	\$2,758
211243906	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0401712A*	19,300	\$2,702
211243896	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716A*	19,500	\$2,730
211243887	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412A*	19,300	\$2,702
211243878	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712A*	19,700	\$2,758
211243869	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410A*	19,500	\$2,730
211243860	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601714A*	19,500	\$2,730
211243842	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412A*	19,500	\$2,730
211243831	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	19,500	\$2,730
211243820	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0401410A*	19,700	\$2,758
211243809	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0601412A*	19,600	\$2,744
211243797	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	19,600	\$2,744
211243786	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0261410A*	19,900	\$2,786
211243776	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412A*	19,300	\$2,702
211243766	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410A*	19,500	\$2,730
211243755	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0601412A*	19,700	\$2,758
211243744	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0401410A*	19,800	\$2,772
211243732	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412A*	19,500	\$2,730
211243722	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412A*	19,300	\$2,702
211243713	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410A*	19,500	\$2,730
211243704	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412A*	19,500	\$2,730
211243677	HEIL	DLCURAH24ABK	EA*4X37L21A*	OLV098A12*	18,400	\$2,576
211243488	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122A*	18,500	\$2,590
211243468	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120A*	18,400	\$2,576
211243406	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712A*	18,500	\$2,590

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243290	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002122A*	18,400	\$2,576
211243250	HEIL	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712A*	18,500	\$2,590
211243178	HEIL	DLCURAH24ABK	EA*4X37L17A*	OLV098A12*	18,700	\$2,618
211243169	HEIL	DLCURAH24ABK	EA*4X37L17A*	OMV098J12*	18,800	\$2,632
211243147	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	18,900	\$2,646
211243136	HEIL	DLCURAH24ABK	EA*4X37L17A*	*92ESN0401712A*	18,900	\$2,646
211243092	HEIL	DLCURAH24ABK	EA*4X37L17A*	*92ESN0801716A*	18,900	\$2,646
211243081	HEIL	DLCURAH24ABK	EA*4X37L17A*	*92ESN0601714A*	18,900	\$2,646
211243034	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0451712A*	18,900	\$2,646
211243012	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601714A*	18,900	\$2,646
211242991	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412A*	18,700	\$2,618
211242981	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410A*	18,900	\$2,646
211242938	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716A*	18,800	\$2,632
211242928	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716A*	18,900	\$2,646
211242904	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412A*	18,900	\$2,646
211242893	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80ESU0401712A*	18,700	\$2,618
211242882	HEIL	DLCURAH24ABK	EA*4X37L17A*	*95ESU0601716A*	18,900	\$2,646
211242872	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80VSL0701716A*	18,800	\$2,632
211242863	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451716A*	19,000	\$2,660
211242824	HEIL	DLCURAH24ABK	EA*4X37L17A*	*95ESU0401712A*	18,700	\$2,618
211242814	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716A*	18,900	\$2,646
211242805	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412A*	18,700	\$2,618
211242787	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410A*	18,900	\$2,646
211242778	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601714A*	19,000	\$2,660
211242751	HEIL	DLCURAH24ABK	EA*4X36L21A*	OLV112A16A	19,200	\$2,688
211242742	HEIL	DLCURAH24ABK	EA*4X36L21A*	OMV112K14A	19,100	\$2,674
211242733	HEIL	DLCURAH24ABK	EA*4X36L21A*	OLV098A12*	18,900	\$2,646
211242724	HEIL	DLCURAH24ABK	EA*4X36L21A*	OMV098J12*	18,900	\$2,646
211242714	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ESU0601716A	19,300	\$2,702
211242703	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ESU0802120A	19,100	\$2,674
211242692	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92ESN0401712A*	19,100	\$2,674
211242681	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95ESN0801716A*	19,400	\$2,716
211242670	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95ESN0601714A*	19,300	\$2,702
211242659	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92ESN1002120A*	19,300	\$2,702
211242648	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92ESN0802120A*	19,300	\$2,702
211242637	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92ESN0801716A*	19,100	\$2,674
211242626	HEIL	DLCURAH24ABK	EA*4X36L21A*	*92ESN0601714A*	19,100	\$2,674
211242614	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242602	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	19,200	\$2,688
211242590	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242578	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	19,100	\$2,674
211242566	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	18,800	\$2,632
211242554	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242544	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122A*	18,900	\$2,646
211242534	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120A*	19,000	\$2,660
211242524	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120A*	18,900	\$2,646
211242514	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN0601714A*	19,100	\$2,674
211242503	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95ESN0401712A*	19,300	\$2,702
211242493	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716A*	19,000	\$2,660
211242483	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716A*	19,100	\$2,674
211242472	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95ESN0802120A*	19,300	\$2,702
211242462	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712A*	19,000	\$2,660
211242452	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120A*	19,000	\$2,660
211242439	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ESU0401712A*	18,900	\$2,646
211242428	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95ESU0601716A*	19,100	\$2,674
211242418	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VSL0902120A*	19,000	\$2,660
211242409	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VSL0702120A*	19,300	\$2,702
211242400	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VSL0701716A*	19,000	\$2,660
211242391	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80VSL0451716A*	18,800	\$2,632
211242346	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122A*	18,900	\$2,646
211242336	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	19,400	\$2,716
211242325	HEIL	DLCURAH24ABK	EA*4X36L21A*	*95ESU0401712A*	18,900	\$2,646
211242315	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716A*	19,100	\$2,674
211242306	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712A*	19,000	\$2,660
211242297	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120A*	18,900	\$2,646
211242288	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120A*	19,000	\$2,660
211242279	HEIL	DLCURAH24ABK	EA*4X36L21A*	*96VSN0601714A*	18,900	\$2,646
211242243	HEIL	DLCURAH24ABK	EA*4X36L17A*	OMV112K14A	19,200	\$2,688
211242234	HEIL	DLCURAH24ABK	EA*4X36L17A*	OLV098A12*	18,900	\$2,646
211242225	HEIL	DLCURAH24ABK	EA*4X36L17A*	OMV098J12*	18,900	\$2,646
211242215	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80ESU0601716A	19,300	\$2,702
211242203	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	19,100	\$2,674
211242192	HEIL	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401712A*	19,100	\$2,674
211242181	HEIL	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401410A*	19,400	\$2,716
211242170	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95ESN0801716A*	19,400	\$2,716
211242159	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601714A*	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242148	HEIL	DLCURAH24ABK	EA*4X36L17A*	*92ESN0801716A*	19,100	\$2,674
211242137	HEIL	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601714A*	19,100	\$2,674
211242126	HEIL	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601412A*	18,800	\$2,632
211242114	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242102	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211242090	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242078	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	19,300	\$2,702
211242068	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601714A*	19,100	\$2,674
211242057	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95ESN0261410A*	18,900	\$2,646
211242047	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412A*	18,900	\$2,646
211242037	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410A*	18,900	\$2,646
211242026	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601412A*	19,300	\$2,702
211242015	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401712A*	19,300	\$2,702
211242004	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401410A*	19,400	\$2,716
211241994	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716A*	19,000	\$2,660
211241984	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716A*	19,100	\$2,674
211241974	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712A*	18,900	\$2,646
211241960	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412A*	19,100	\$2,674
211241949	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80ESU0401712A*	18,900	\$2,646
211241938	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95ESU0601716A*	19,100	\$2,674
211241928	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80VSL0701716A*	19,000	\$2,660
211241919	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451716A*	19,100	\$2,674
211241891	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241880	HEIL	DLCURAH24ABK	EA*4X36L17A*	*95ESU0401712A*	18,900	\$2,646
211241870	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716A*	19,100	\$2,674
211241861	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412A*	18,900	\$2,646
211241852	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712A*	18,900	\$2,646
211241843	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410A*	18,900	\$2,646
211241834	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601714A*	18,900	\$2,646
211241816	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412A*	18,800	\$2,632
211241807	HEIL	DLCURAH24ABK	EA*4X30L17A*	OMV112K14A	19,200	\$2,688
211241798	HEIL	DLCURAH24ABK	EA*4X30L17A*	OLV098A12*	18,900	\$2,646
211241789	HEIL	DLCURAH24ABK	EA*4X30L17A*	OMV098J12*	19,000	\$2,660
211241779	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80ESU0601716A	19,300	\$2,702
211241767	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241756	HEIL	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401712A*	19,100	\$2,674
211241745	HEIL	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401410A*	19,400	\$2,716
211241734	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95ESN0801716A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241723	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601714A*	19,400	\$2,716
211241712	HEIL	DLCURAH24ABK	EA*4X30L17A*	*92ESN0801716A*	19,100	\$2,674
211241701	HEIL	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601714A*	19,200	\$2,688
211241690	HEIL	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601412A*	18,900	\$2,646
211241678	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211241666	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211241654	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211241642	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	19,400	\$2,716
211241632	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601714A*	19,100	\$2,674
211241621	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95ESN0261410A*	18,900	\$2,646
211241611	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412A*	19,000	\$2,660
211241601	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410A*	19,000	\$2,660
211241590	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601412A*	19,400	\$2,716
211241579	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401712A*	19,400	\$2,716
211241568	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401410A*	19,500	\$2,730
211241558	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716A*	19,100	\$2,674
211241548	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716A*	19,200	\$2,688
211241538	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712A*	19,000	\$2,660
211241524	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412A*	19,200	\$2,688
211241513	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80ESU0401712A*	19,000	\$2,660
211241502	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95ESU0601716A*	19,100	\$2,674
211241492	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80VSL0701716A*	19,100	\$2,674
211241483	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451716A*	19,200	\$2,688
211241455	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241444	HEIL	DLCURAH24ABK	EA*4X30L17A*	*95ESU0401712A*	19,000	\$2,660
211241434	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716A*	19,200	\$2,688
211241425	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412A*	19,000	\$2,660
211241416	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712A*	19,000	\$2,660
211241407	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410A*	19,000	\$2,660
211241398	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601714A*	18,900	\$2,646
211241380	HEIL	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412A*	18,900	\$2,646
211241369	HEIL	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241358	HEIL	DLCURAH24ABK	EA*4X30L14A*	*92ESN0401410A*	19,400	\$2,716
211241347	HEIL	DLCURAH24ABK	EA*4X30L14A*	*92ESN0601412A*	18,900	\$2,646
211241335	HEIL	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	19,300	\$2,702
211241324	HEIL	DLCURAH24ABK	EA*4X30L14A*	*95ESN0261410A*	19,600	\$2,744
211241314	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412A*	19,000	\$2,660
211241304	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241293	HEIL	DLCURAH24ABK	EA*4X30L14A*	*95ESN0601412A*	19,400	\$2,716
211241282	HEIL	DLCURAH24ABK	EA*4X30L14A*	*95ESN0401410A*	19,500	\$2,730
211241270	HEIL	DLCURAH24ABK	EA*4X30L14A*	*80VTL0451412A*	19,100	\$2,674
211241260	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412A*	19,000	\$2,660
211241251	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410A*	19,100	\$2,674
211241242	HEIL	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412A*	19,200	\$2,688
211241224	HEIL	DLCURAH24ABK	EA*4X25L17A*	OLV098A12*	18,600	\$2,604
211241215	HEIL	DLCURAH24ABK	EA*4X25L17A*	OMV098J12*	18,600	\$2,604
211241116	HEIL	DLCURAH24ABK	EA*4X25L17A*	*92ESN0601412A*	18,500	\$2,590
211241037	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412A*	18,600	\$2,604
211240964	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712A*	18,600	\$2,604
211240939	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80ESU0401712A*	18,600	\$2,604
211240918	HEIL	DLCURAH24ABK	EA*4X25L17A*	*80VSL0701716A*	18,700	\$2,618
211240870	HEIL	DLCURAH24ABK	EA*4X25L17A*	*95ESU0401712A*	18,600	\$2,604
211240851	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412A*	18,600	\$2,604
211240842	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712A*	18,600	\$2,604
211240797	HEIL	DLCURAH24ABK	EA*4X24L17A*	OMV112K14A	19,500	\$2,730
211240788	HEIL	DLCURAH24ABK	EA*4X24L17A*	OLV098A12*	19,200	\$2,688
211240779	HEIL	DLCURAH24ABK	EA*4X24L17A*	OMV098J12*	19,300	\$2,702
211240769	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80ESU0601716A	19,600	\$2,744
211240757	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240746	HEIL	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401712A*	19,400	\$2,716
211240735	HEIL	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401410A*	19,700	\$2,758
211240724	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95ESN0801716A*	19,700	\$2,758
211240713	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601714A*	19,600	\$2,744
211240702	HEIL	DLCURAH24ABK	EA*4X24L17A*	*92ESN0801716A*	19,400	\$2,716
211240691	HEIL	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601714A*	19,400	\$2,716
211240680	HEIL	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601412A*	19,200	\$2,688
211240668	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0901714A*	19,500	\$2,730
211240656	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	19,500	\$2,730
211240644	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	19,400	\$2,716
211240632	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240622	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601714A*	19,400	\$2,716
211240611	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95ESN0261410A*	19,800	\$2,772
211240601	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412A*	19,300	\$2,702
211240591	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410A*	19,400	\$2,716
211240580	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601412A*	19,600	\$2,744
211240569	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401712A*	19,700	\$2,758

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240558	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401410A*	19,700	\$2,758
211240548	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716A*	19,300	\$2,702
211240538	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716A*	19,400	\$2,716
211240528	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712A*	19,300	\$2,702
211240514	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80VTL0451412A*	19,400	\$2,716
211240503	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80ESU0401712A*	19,300	\$2,702
211240492	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95ESU0601716A*	19,400	\$2,716
211240482	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80VSL0701716A*	19,300	\$2,702
211240473	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451716A*	19,400	\$2,716
211240445	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701716A*	19,700	\$2,758
211240434	HEIL	DLCURAH24ABK	EA*4X24L17A*	*95ESU0401712A*	19,300	\$2,702
211240424	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716A*	19,400	\$2,716
211240415	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412A*	19,300	\$2,702
211240406	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712A*	19,300	\$2,702
211240397	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410A*	19,400	\$2,716
211240388	HEIL	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601714A*	19,500	\$2,730
211240370	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412A*	19,500	\$2,730
211240359	HEIL	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240348	HEIL	DLCURAH24ABK	EA*4X24L14A*	*92ESN0401410A*	19,700	\$2,758
211240337	HEIL	DLCURAH24ABK	EA*4X24L14A*	*92ESN0601412A*	19,600	\$2,744
211240325	HEIL	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240314	HEIL	DLCURAH24ABK	EA*4X24L14A*	*95ESN0261410A*	19,800	\$2,772
211240304	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412A*	19,300	\$2,702
211240294	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410A*	19,400	\$2,716
211240283	HEIL	DLCURAH24ABK	EA*4X24L14A*	*95ESN0601412A*	19,600	\$2,744
211240272	HEIL	DLCURAH24ABK	EA*4X24L14A*	*95ESN0401410A*	19,700	\$2,758
211240260	HEIL	DLCURAH24ABK	EA*4X24L14A*	*80VTL0451412A*	19,400	\$2,716
211240250	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412A*	19,300	\$2,702
211240241	HEIL	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410A*	19,400	\$2,716
211240232	HEIL	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412A*	19,500	\$2,730
211239227	HEIL	DLCURAH24ABK	FJMA4*24L*B*		19,200	\$2,688
213353743	HEIL	DLCURAH18ABK	F5MA4*24L*B*		12,500	\$1,750
213353733	HEIL	DLCURAH18ABK	F5MA4*18L*A*		12,800	\$1,792
213249253	HEIL	DLCURAH18ABK	FEVA0024**+NAVA43601CK		12,300	\$1,722
213076390	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601716B*	12,400	\$1,736
212989328	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0601716A*	12,200	\$1,708
212989316	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0601716A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989304	HEIL	DLCURAH18ABK	EA*4X30L17A*	*95MSU0601716A*	12,200	\$1,708
212989292	HEIL	DLCURAH18ABK	EA*4X25L17A*	*95MSU0601716A*	12,000	\$1,680
212989280	HEIL	DLCURAH18ABK	EA*4X24L17A*	*95MSU0601716A*	12,300	\$1,722
212989268	HEIL	DLCURAH18ABK	EA*4X19L17A*	*95MSU0601716A*	12,100	\$1,694
212988836	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0401712A*	12,200	\$1,708
212988824	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0401712A*	12,500	\$1,750
212988812	HEIL	DLCURAH18ABK	EA*4X30L17A*	*95MSU0401712A*	12,200	\$1,708
212988800	HEIL	DLCURAH18ABK	EA*4X25L17A*	*95MSU0401712A*	12,000	\$1,680
212988788	HEIL	DLCURAH18ABK	EA*4X24L17A*	*95MSU0401712A*	12,300	\$1,722
212988776	HEIL	DLCURAH18ABK	EA*4X19L17A*	*95MSU0401712A*	12,100	\$1,694
212987562	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0801716A*	12,200	\$1,708
212987550	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0801716A*	12,500	\$1,750
212987538	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96MSN0801716A*	12,100	\$1,694
212987526	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96MSN0801716A*	12,200	\$1,708
212987514	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96MSN0801716A*	12,500	\$1,750
212987502	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96MSN0801716A*	12,300	\$1,722
212987084	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0601412A*	12,200	\$1,708
212987074	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0601412A*	12,200	\$1,708
212987064	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0601412A*	12,300	\$1,722
212987054	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0601412A*	12,300	\$1,722
212987044	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0601412A*	12,500	\$1,750
212987034	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96MSN0601412A*	12,200	\$1,708
212987024	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96MSN0601412A*	12,200	\$1,708
212987014	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96MSN0601412A*	12,000	\$1,680
212987004	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96MSN0601412A*	12,300	\$1,722
212986994	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96MSN0601412A*	12,300	\$1,722
212986984	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96MSN0601412A*	12,100	\$1,694
212986722	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401712A*	12,300	\$1,722
212986710	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401712A*	12,500	\$1,750
212986698	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401712A*	12,300	\$1,722
212986686	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96MSN0401712A*	12,100	\$1,694
212986674	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401712A*	12,300	\$1,722
212986662	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401712A*	12,100	\$1,694
212986386	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401410A*	12,300	\$1,722
212986374	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0401410A*	12,300	\$1,722
212986362	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401410A*	12,400	\$1,736
212986350	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0401410A*	12,400	\$1,736
212986338	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0401410A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986326	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401410A*	12,300	\$1,722
212986314	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96MSN0401410A*	12,300	\$1,722
212986302	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401410A*	12,400	\$1,736
212986290	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96MSN0401410A*	12,400	\$1,736
212986278	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401410A*	12,200	\$1,708
212985980	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0261410A*	12,300	\$1,722
212985970	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0261410A*	12,200	\$1,708
212985960	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0261410A*	12,300	\$1,722
212985950	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0261410A*	12,300	\$1,722
212985940	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0261410A*	12,500	\$1,750
212985930	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96MSN0261410A*	12,200	\$1,708
212985920	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96MSN0261410A*	12,200	\$1,708
212985910	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96MSN0261410A*	12,100	\$1,694
212985900	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96MSN0261410A*	12,300	\$1,722
212985890	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96MSN0261410A*	12,300	\$1,722
212985880	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96MSN0261410A*	12,100	\$1,694
212984764	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0801716A*	12,100	\$1,694
212984752	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0801716A*	12,500	\$1,750
212984740	HEIL	DLCURAH18ABK	EA*4X30L17A*	*92MSN0801716A*	12,400	\$1,736
212984728	HEIL	DLCURAH18ABK	EA*4X25L17A*	*92MSN0801716A*	12,200	\$1,708
212984716	HEIL	DLCURAH18ABK	EA*4X24L17A*	*92MSN0801716A*	12,500	\$1,750
212984704	HEIL	DLCURAH18ABK	EA*4X19L17A*	*92MSN0801716A*	12,300	\$1,722
212984224	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601714A*	12,300	\$1,722
212984212	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601714A*	12,400	\$1,736
212984200	HEIL	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601714A*	12,300	\$1,722
212984188	HEIL	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601714A*	12,200	\$1,708
212984176	HEIL	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601714A*	12,400	\$1,736
212984164	HEIL	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601714A*	12,200	\$1,708
212983734	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601412A*	12,200	\$1,708
212983724	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*92MSN0601412A*	12,200	\$1,708
212983713	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601412A*	12,400	\$1,736
212983703	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*92MSN0601412A*	12,400	\$1,736
212983693	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*92MSN0601412A*	12,400	\$1,736
212983683	HEIL	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601412A*	12,200	\$1,708
212983673	HEIL	DLCURAH18ABK	EA*4X30L14A*	*92MSN0601412A*	12,300	\$1,722
212983663	HEIL	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601412A*	12,000	\$1,680
212983653	HEIL	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601412A*	12,400	\$1,736
212983643	HEIL	DLCURAH18ABK	EA*4X24L14A*	*92MSN0601412A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983633	HEIL	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601412A*	12,100	\$1,694
212983312	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0401712A*	12,300	\$1,722
212983301	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0401712A*	12,400	\$1,736
212983290	HEIL	DLCURAH18ABK	EA*4X30L17A*	*92MSN0401712A*	12,200	\$1,708
212983279	HEIL	DLCURAH18ABK	EA*4X25L17A*	*92MSN0401712A*	12,100	\$1,694
212983268	HEIL	DLCURAH18ABK	EA*4X24L17A*	*92MSN0401712A*	12,300	\$1,722
212983257	HEIL	DLCURAH18ABK	EA*4X19L17A*	*92MSN0401712A*	12,200	\$1,708
212981887	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU1002120A*	12,300	\$1,722
212981875	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU1002120A*	12,600	\$1,764
212981863	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80MSU1002120A*	12,300	\$1,722
212981851	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80MSU1002120A*	12,100	\$1,694
212981839	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80MSU1002120A*	12,300	\$1,722
212981827	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80MSU1002120A*	12,200	\$1,708
212980008	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	12,300	\$1,722
212979996	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	12,400	\$1,736
212979984	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	12,300	\$1,722
212979972	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212979960	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	12,400	\$1,736
212979948	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212978803	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978792	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978781	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978770	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978759	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978748	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978351	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	12,200	\$1,708
212978339	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	12,200	\$1,708
212978327	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	12,400	\$1,736
212978315	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978303	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978291	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	12,100	\$1,694
212978277	HEIL	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	12,300	\$1,722
212978265	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212978253	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978241	HEIL	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978229	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212977833	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	12,300	\$1,722
212977821	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212977809	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	12,400	\$1,736
212977797	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977785	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977773	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977761	HEIL	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977749	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	12,100	\$1,694
212977737	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	12,400	\$1,736
212977725	HEIL	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977713	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0451412A*	12,200	\$1,708
212975844	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716B*	12,200	\$1,708
212975831	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716B*	12,500	\$1,750
212975818	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716B*	12,200	\$1,708
212975805	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716B*	12,000	\$1,680
212975792	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716B*	12,300	\$1,722
212975779	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716B*	12,100	\$1,694
212975492	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412B*	12,200	\$1,708
212975481	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412B*	12,200	\$1,708
212975470	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412B*	12,400	\$1,736
212975459	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412B*	12,400	\$1,736
212975448	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412B*	12,400	\$1,736
212975437	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412B*	12,200	\$1,708
212975426	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412B*	12,200	\$1,708
212975415	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412B*	12,000	\$1,680
212975404	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412B*	12,300	\$1,722
212975393	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412B*	12,200	\$1,708
212975382	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412B*	12,100	\$1,694
212975129	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712B*	12,200	\$1,708
212975118	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712B*	12,500	\$1,750
212975107	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712B*	12,200	\$1,708
212975096	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712B*	12,100	\$1,694
212975085	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712B*	12,300	\$1,722
212975074	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712B*	12,100	\$1,694
212974750	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410B*	12,200	\$1,708
212974737	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410B*	12,200	\$1,708
212974724	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410B*	12,400	\$1,736
212974711	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410B*	12,400	\$1,736
212974698	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410B*	12,400	\$1,736
212974685	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410B*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974672	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410B*	12,200	\$1,708
212974659	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410B*	12,100	\$1,694
212974646	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410B*	12,300	\$1,722
212974633	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410B*	12,400	\$1,736
212974620	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410B*	12,100	\$1,694
212973708	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716B*	12,200	\$1,708
212973698	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716B*	12,500	\$1,750
212973688	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716B*	12,200	\$1,708
212973678	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716B*	12,000	\$1,680
212973668	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716B*	12,300	\$1,722
212973658	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716B*	12,100	\$1,694
212973398	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412B*	12,200	\$1,708
212973388	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412B*	12,200	\$1,708
212973378	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412B*	12,400	\$1,736
212973368	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412B*	12,400	\$1,736
212973358	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412B*	12,400	\$1,736
212973348	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412B*	12,200	\$1,708
212973338	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412B*	12,200	\$1,708
212973328	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412B*	12,000	\$1,680
212973318	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412B*	12,300	\$1,722
212973308	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412B*	12,200	\$1,708
212973298	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412B*	12,100	\$1,694
212973068	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712B*	12,200	\$1,708
212973058	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712B*	12,500	\$1,750
212973048	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712B*	12,200	\$1,708
212973038	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712B*	12,100	\$1,694
212973028	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712B*	12,300	\$1,722
212973018	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712B*	12,100	\$1,694
212972768	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410B*	12,200	\$1,708
212972758	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410B*	12,200	\$1,708
212972748	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410B*	12,400	\$1,736
212972738	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410B*	12,400	\$1,736
212972728	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410B*	12,400	\$1,736
212972718	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410B*	12,200	\$1,708
212972708	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410B*	12,200	\$1,708
212972698	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410B*	12,100	\$1,694
212972688	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410B*	12,300	\$1,722
212972678	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410B*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972668	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410B*	12,100	\$1,694
212971496	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716B*	12,300	\$1,722
212971485	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716B*	12,400	\$1,736
212971474	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716B*	12,300	\$1,722
212971463	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716B*	12,100	\$1,694
212971452	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716B*	12,400	\$1,736
212971441	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716B*	12,200	\$1,708
212969602	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412B*	12,200	\$1,708
212969592	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412B*	12,200	\$1,708
212969582	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412B*	12,500	\$1,750
212969572	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412B*	12,500	\$1,750
212969562	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412B*	12,500	\$1,750
212969552	HEIL	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412B*	12,400	\$1,736
212969542	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412B*	12,200	\$1,708
212969532	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412B*	12,500	\$1,750
212969522	HEIL	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412B*	12,500	\$1,750
212969512	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412B*	12,300	\$1,722
211265042	HEIL	DLCURAH18ABK	FVM4X24***L		12,400	\$1,736
211265019	HEIL	DLCURAH18ABK	FM(C,U)4Z30**AL*		12,400	\$1,736
211264998	HEIL	DLCURAH18ABK	FM(C,U)4Z24**AL*		12,500	\$1,750
211264976	HEIL	DLCURAH18ABK	FM(C,U)4Z18**AL*		12,500	\$1,750
211264954	HEIL	DLCURAH18ABK	FMA4X24**AL*		12,400	\$1,736
211264932	HEIL	DLCURAH18ABK	FMA4X18**AL*		12,400	\$1,736
211264911	HEIL	DLCURAH18ABK	FXM4X30**AL		12,400	\$1,736
211264889	HEIL	DLCURAH18ABK	FXM4X24**AL		12,400	\$1,736
211264768	HEIL	DLCURAH18ABK	FEM4P18**AL		12,300	\$1,722
211264744	HEIL	DLCURAH18ABK	FJMA4*18L*A*		12,700	\$1,778
211264718	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	OMV112K14A	12,600	\$1,764
211264700	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	OLV098A12*	12,600	\$1,764
211264683	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	OMV098J12*	12,600	\$1,764
211264662	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0601716A	12,700	\$1,778
211264638	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	12,300	\$1,722
211264615	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401712A*	12,500	\$1,750
211264594	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401410A*	12,500	\$1,750
211264572	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601714A*	12,300	\$1,722
211264549	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601412A*	12,500	\$1,750
211264525	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	12,500	\$1,750
211264502	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211264477	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	12,500	\$1,750
211264457	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601714A*	12,400	\$1,736
211264433	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0261410A*	12,600	\$1,764
211264412	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412A*	12,400	\$1,736
211264387	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410A*	12,300	\$1,722
211264322	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0601412A*	12,400	\$1,736
211264283	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401712A*	12,200	\$1,708
211264248	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401410A*	12,400	\$1,736
211264220	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716A*	12,200	\$1,708
211264181	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716A*	12,200	\$1,708
211264147	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712A*	12,400	\$1,736
211264115	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0451412A*	12,300	\$1,722
211264093	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0401712A*	12,700	\$1,778
211264073	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0701716A*	12,200	\$1,708
211264055	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451716A*	12,300	\$1,722
211264010	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESU0401712A*	12,400	\$1,736
211263990	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716A*	12,200	\$1,708
211263972	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412A*	12,400	\$1,736
211263955	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712A*	12,400	\$1,736
211263936	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410A*	12,300	\$1,722
211263918	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601714A*	12,400	\$1,736
211263881	HEIL	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412A*	12,400	\$1,736
211263858	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	12,300	\$1,722
211263835	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0401410A*	12,500	\$1,750
211263814	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0601412A*	12,500	\$1,750
211263789	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	12,500	\$1,750
211263767	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0261410A*	12,500	\$1,750
211263746	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412A*	12,400	\$1,736
211263725	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410A*	12,200	\$1,708
211263700	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0601412A*	12,400	\$1,736
211263677	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0401410A*	12,400	\$1,736
211263652	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*80VTL0451412A*	12,300	\$1,722
211263631	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412A*	12,400	\$1,736
211263613	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410A*	12,200	\$1,708
211263594	HEIL	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412A*	12,400	\$1,736
211263576	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	OMV112K14A	12,800	\$1,792
211263557	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	OLV098A12*	12,700	\$1,778
211263538	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	OMV098J12*	12,800	\$1,792

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263517	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0601716A	12,800	\$1,792
211263493	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	12,400	\$1,736
211263469	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401712A*	12,600	\$1,764
211263446	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401410A*	12,600	\$1,764
211263424	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0801716A*	12,900	\$1,806
211263401	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601714A*	12,400	\$1,736
211263378	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601412A*	12,600	\$1,764
211263353	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	12,600	\$1,764
211263328	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	12,900	\$1,806
211263303	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	12,600	\$1,764
211263282	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601714A*	12,500	\$1,750
211263257	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0261410A*	12,700	\$1,778
211263236	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412A*	12,500	\$1,750
211263215	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410A*	12,300	\$1,722
211263190	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0601412A*	12,500	\$1,750
211263168	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401712A*	12,300	\$1,722
211263145	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401410A*	12,500	\$1,750
211263130	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716A*	12,300	\$1,722
211263109	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716A*	12,300	\$1,722
211263088	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712A*	12,500	\$1,750
211263060	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0451412A*	12,400	\$1,736
211263039	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0401712A*	12,700	\$1,778
211263017	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0601716A*	12,900	\$1,806
211262997	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0701716A*	12,300	\$1,722
211262979	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451716A*	12,400	\$1,736
211262924	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0401712A*	12,400	\$1,736
211262904	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716A*	12,300	\$1,722
211262887	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412A*	12,500	\$1,750
211262870	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712A*	12,500	\$1,750
211262852	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410A*	12,300	\$1,722
211262834	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601714A*	12,400	\$1,736
211262798	HEIL	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412A*	12,400	\$1,736
211262776	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262754	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0401410A*	12,600	\$1,764
211262731	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0601412A*	12,600	\$1,764
211262707	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262685	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0261410A*	12,700	\$1,778
211262665	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412A*	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262644	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410A*	12,300	\$1,722
211262621	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0601412A*	12,500	\$1,750
211262598	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0401410A*	12,500	\$1,750
211262574	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*80VTL0451412A*	12,400	\$1,736
211262555	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412A*	12,500	\$1,750
211262536	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410A*	12,300	\$1,722
211262518	HEIL	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412A*	12,400	\$1,736
211262496	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262474	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0401410A*	12,600	\$1,764
211262452	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0601412A*	12,600	\$1,764
211262429	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262407	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0261410A*	12,700	\$1,778
211262386	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412A*	12,500	\$1,750
211262366	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410A*	12,300	\$1,722
211262342	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0601412A*	12,500	\$1,750
211262320	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0401410A*	12,500	\$1,750
211262296	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*80VTL0451412A*	12,400	\$1,736
211262277	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412A*	12,500	\$1,750
211262259	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410A*	12,300	\$1,722
211262241	HEIL	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412A*	12,500	\$1,750
211262224	HEIL	DLCURAH18ABK	EA*4X30L17A*	OMV112K14A	12,600	\$1,764
211262206	HEIL	DLCURAH18ABK	EA*4X30L17A*	OLV098A12*	12,600	\$1,764
211262188	HEIL	DLCURAH18ABK	EA*4X30L17A*	OMV098J12*	12,600	\$1,764
211262166	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	12,300	\$1,722
211262145	HEIL	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401712A*	12,500	\$1,750
211262124	HEIL	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401410A*	12,500	\$1,750
211262102	HEIL	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601714A*	12,300	\$1,722
211262080	HEIL	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601412A*	12,500	\$1,750
211262057	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	12,500	\$1,750
211262031	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	12,400	\$1,736
211262004	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261983	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601714A*	12,400	\$1,736
211261958	HEIL	DLCURAH18ABK	EA*4X30L17A*	*95ESN0261410A*	12,600	\$1,764
211261938	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412A*	12,500	\$1,750
211261923	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410A*	12,200	\$1,708
211261900	HEIL	DLCURAH18ABK	EA*4X30L17A*	*95ESN0601412A*	12,400	\$1,736
211261872	HEIL	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401712A*	12,200	\$1,708
211261849	HEIL	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401410A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261833	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716A*	12,200	\$1,708
211261818	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716A*	12,200	\$1,708
211261796	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712A*	12,400	\$1,736
211261769	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80VTL0451412A*	12,300	\$1,722
211261747	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80ESU0401712A*	12,700	\$1,778
211261727	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80VSL0701716A*	12,200	\$1,708
211261709	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451716A*	12,300	\$1,722
211261654	HEIL	DLCURAH18ABK	EA*4X30L17A*	*95ESU0401712A*	12,300	\$1,722
211261634	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716A*	12,200	\$1,708
211261616	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412A*	12,500	\$1,750
211261598	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712A*	12,400	\$1,736
211261580	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410A*	12,200	\$1,708
211261562	HEIL	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601714A*	12,400	\$1,736
211261527	HEIL	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451412A*	12,400	\$1,736
211261505	HEIL	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211261483	HEIL	DLCURAH18ABK	EA*4X30L14A*	*92ESN0401410A*	12,500	\$1,750
211261461	HEIL	DLCURAH18ABK	EA*4X30L14A*	*92ESN0601412A*	12,500	\$1,750
211261437	HEIL	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261416	HEIL	DLCURAH18ABK	EA*4X30L14A*	*95ESN0261410A*	12,500	\$1,750
211261396	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412A*	12,400	\$1,736
211261376	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410A*	12,200	\$1,708
211261354	HEIL	DLCURAH18ABK	EA*4X30L14A*	*95ESN0601412A*	12,400	\$1,736
211261332	HEIL	DLCURAH18ABK	EA*4X30L14A*	*95ESN0401410A*	12,400	\$1,736
211261308	HEIL	DLCURAH18ABK	EA*4X30L14A*	*80VTL0451412A*	12,300	\$1,722
211261288	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412A*	12,400	\$1,736
211261269	HEIL	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410A*	12,200	\$1,708
211261251	HEIL	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412A*	12,400	\$1,736
211261232	HEIL	DLCURAH18ABK	EA*4X25L17A*	OMV112K14A	12,500	\$1,750
211261214	HEIL	DLCURAH18ABK	EA*4X25L17A*	OLV098A12*	12,500	\$1,750
211261196	HEIL	DLCURAH18ABK	EA*4X25L17A*	OMV098J12*	12,500	\$1,750
211261163	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80ESU0601716A	12,600	\$1,764
211261122	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701412A*	12,100	\$1,694
211261075	HEIL	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401712A*	12,400	\$1,736
211261052	HEIL	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401410A*	12,400	\$1,736
211261039	HEIL	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601714A*	12,200	\$1,708
211261026	HEIL	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601412A*	12,400	\$1,736
211261012	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211260997	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451712A*	12,700	\$1,778

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260983	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211260970	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601714A*	12,200	\$1,708
211260956	HEIL	DLCURAH18ABK	EA*4X25L17A*	*95ESN0261410A*	12,400	\$1,736
211260944	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412A*	12,300	\$1,722
211260931	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410A*	12,100	\$1,694
211260917	HEIL	DLCURAH18ABK	EA*4X25L17A*	*95ESN0601412A*	12,300	\$1,722
211260903	HEIL	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401712A*	12,100	\$1,694
211260890	HEIL	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401410A*	12,300	\$1,722
211260878	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716A*	12,000	\$1,680
211260866	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716A*	12,100	\$1,694
211260852	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712A*	12,300	\$1,722
211260835	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80VTL0451412A*	12,200	\$1,708
211260822	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80ESU0401712A*	12,500	\$1,750
211260808	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80VSL0701716A*	12,100	\$1,694
211260797	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451716A*	12,200	\$1,708
211260764	HEIL	DLCURAH18ABK	EA*4X25L17A*	*95ESU0401712A*	12,200	\$1,708
211260751	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716A*	12,100	\$1,694
211260740	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412A*	12,300	\$1,722
211260730	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712A*	12,300	\$1,722
211260719	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410A*	12,100	\$1,694
211260709	HEIL	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601714A*	12,200	\$1,708
211260688	HEIL	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412A*	12,200	\$1,708
211260677	HEIL	DLCURAH18ABK	EA*4X24L17A*	OMV112K14A	12,700	\$1,778
211260666	HEIL	DLCURAH18ABK	EA*4X24L17A*	OLV098A12*	12,700	\$1,778
211260656	HEIL	DLCURAH18ABK	EA*4X24L17A*	OMV098J12*	12,700	\$1,778
211260644	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80ESU0601716A	12,800	\$1,792
211260630	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	12,400	\$1,736
211260618	HEIL	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401712A*	12,600	\$1,764
211260607	HEIL	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401410A*	12,600	\$1,764
211260595	HEIL	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601714A*	12,400	\$1,736
211260582	HEIL	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601412A*	12,600	\$1,764
211260567	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	12,600	\$1,764
211260553	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	12,900	\$1,806
211260539	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260527	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601714A*	12,400	\$1,736
211260512	HEIL	DLCURAH18ABK	EA*4X24L17A*	*95ESN0261410A*	12,700	\$1,778
211260500	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412A*	12,500	\$1,750
211260488	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260474	HEIL	DLCURAH18ABK	EA*4X24L17A*	*95ESN0601412A*	12,500	\$1,750
211260461	HEIL	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401712A*	12,300	\$1,722
211260448	HEIL	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401410A*	12,500	\$1,750
211260436	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716A*	12,200	\$1,708
211260424	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716A*	12,300	\$1,722
211260410	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712A*	12,500	\$1,750
211260394	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80VTL0451412A*	12,400	\$1,736
211260381	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80ESU0401712A*	12,700	\$1,778
211260368	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80VSL0701716A*	12,300	\$1,722
211260358	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451716A*	12,400	\$1,736
211260324	HEIL	DLCURAH18ABK	EA*4X24L17A*	*95ESU0401712A*	12,400	\$1,736
211260312	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716A*	12,300	\$1,722
211260301	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412A*	12,500	\$1,750
211260290	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712A*	12,500	\$1,750
211260280	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410A*	12,300	\$1,722
211260269	HEIL	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601714A*	12,400	\$1,736
211260247	HEIL	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412A*	12,400	\$1,736
211260234	HEIL	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211260221	HEIL	DLCURAH18ABK	EA*4X24L14A*	*92ESN0401410A*	12,600	\$1,764
211260208	HEIL	DLCURAH18ABK	EA*4X24L14A*	*92ESN0601412A*	12,600	\$1,764
211260193	HEIL	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260179	HEIL	DLCURAH18ABK	EA*4X24L14A*	*95ESN0261410A*	12,600	\$1,764
211260169	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412A*	12,500	\$1,750
211260159	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410A*	12,300	\$1,722
211260145	HEIL	DLCURAH18ABK	EA*4X24L14A*	*95ESN0601412A*	12,500	\$1,750
211260129	HEIL	DLCURAH18ABK	EA*4X24L14A*	*95ESN0401410A*	12,500	\$1,750
211260115	HEIL	DLCURAH18ABK	EA*4X24L14A*	*80VTL0451412A*	12,400	\$1,736
211260103	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412A*	12,500	\$1,750
211260090	HEIL	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410A*	12,300	\$1,722
211260076	HEIL	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412A*	12,400	\$1,736
211260063	HEIL	DLCURAH18ABK	EA*4X19L17A*	OMV112K14A	12,600	\$1,764
211260050	HEIL	DLCURAH18ABK	EA*4X19L17A*	OLV098A12*	12,500	\$1,750
211260036	HEIL	DLCURAH18ABK	EA*4X19L17A*	OMV098J12*	12,600	\$1,764
211260020	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80ESU0601716A	12,700	\$1,778
211260004	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701412A*	12,200	\$1,708
211259988	HEIL	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401712A*	12,400	\$1,736
211259973	HEIL	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401410A*	12,400	\$1,736
211259957	HEIL	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601714A*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211259941	HEIL	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601412A*	12,500	\$1,750
211259924	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211259910	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211259894	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211259879	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601714A*	12,300	\$1,722
211259863	HEIL	DLCURAH18ABK	EA*4X19L17A*	*95ESN0261410A*	12,500	\$1,750
211259850	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412A*	12,400	\$1,736
211259839	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410A*	12,100	\$1,694
211259826	HEIL	DLCURAH18ABK	EA*4X19L17A*	*95ESN0601412A*	12,300	\$1,722
211259814	HEIL	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401712A*	12,100	\$1,694
211259802	HEIL	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401410A*	12,400	\$1,736
211259791	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716A*	12,000	\$1,680
211259780	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716A*	12,100	\$1,694
211259768	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712A*	12,300	\$1,722
211259751	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80VTL0451412A*	12,200	\$1,708
211259736	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80ESU0401712A*	12,600	\$1,764
211259722	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80VSL0701716A*	12,100	\$1,694
211259711	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451716A*	12,200	\$1,708
211259672	HEIL	DLCURAH18ABK	EA*4X19L17A*	*95ESU0401712A*	12,200	\$1,708
211259658	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716A*	12,100	\$1,694
211259645	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412A*	12,400	\$1,736
211259633	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712A*	12,300	\$1,722
211259620	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410A*	12,100	\$1,694
211259609	HEIL	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601714A*	12,300	\$1,722
211259584	HEIL	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412A*	12,300	\$1,722
211257340	HEIL	DLCURAH18ABK	FJMA4*24L*B*		12,800	\$1,792
201835708	HEIL	DLCSRAH12AAK	DLFSCAH12XAK		8,200	\$1,148
201835716	HEIL	DLCSRAH18AAK	DLFSCAH18XAK		12,000	\$1,680
201835712	HEIL	DLCSRAH12AAK	DLFSDAH12XAK		8,100	\$1,134
201835720	HEIL	DLCSRAH24AAK	DLFSFAH24XAK		17,200	\$2,408
201835730	HEIL	DLCLRAH48AAK	DLFLFAH48XAK		35,000	\$4,900
201835674	HEIL	DLCSRAH18AAK	DLFSHAH18XAK		11,900	\$1,666
201835676	HEIL	DLCSRAH24AAK	DLFSHAH24XAK		15,000	\$2,100
201835718	HEIL	DLCSRAH24AAK	DLFSDAH24XAK		17,400	\$2,436
202463649	HEIL	DLCPRAH24AAK	DLFPHAH24XAK		15,450	\$2,163
201835722	HEIL	DLCSRAH24AAK	DLFSCAH24XAK		16,200	\$2,268
205921375	HEIL	DLCSRAH24AAK	DLFSAAH24XAK		17,500	\$2,450
206350419	HEIL	DLCSRBH12AAK	DLFSFAH12XAK		8,400	\$1,176

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206350417	HEIL	DLCSRBH12AAK	DLFSCAH12XAK		7,900	\$1,106
206396099	HEIL	DLCSTRAH12AAK	DLFSHBH12XAK		7,500	\$1,050
206350418	HEIL	DLCSRBH12AAK	DLFSDAH12XAK		8,300	\$1,162
206350424	HEIL	DLCSRBH24AAK	DLFSDAH24XAK		14,500	\$2,030
206350421	HEIL	DLCSRBH18AAK	DLFSDAH18XAK		12,700	\$1,778
206188309	HEIL	DLCSTRAH24AAK	DLFSAAH24XAK		16,500	\$2,310
206350423	HEIL	DLCSTRAH24AAK	DLFSCAH24XAK		14,500	\$2,030
206350422	HEIL	DLCSTRAH18AAK	DLFSFAH18XAK		12,000	\$1,680
206350425	HEIL	DLCSTRAH24AAK	DLFSFAH24XAK		14,500	\$2,030
207643064	HEIL	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340
207643067	HEIL	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643058	HEIL	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207643063	HEIL	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207643057	HEIL	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643066	HEIL	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220
207643065	HEIL	DLCMHBH36DAK	Heat pump without ducts		22,000	\$3,080
207643062	HEIL	DLCMHBH48EAK	Heat pump without ducts		34,000	\$4,760
207643056	HEIL	DLCMHBH30DAK	Heat pump without ducts		18,500	\$2,590
211222791	HEIL	DLCURAH30ABK	FXM4X36**AL		23,200	\$3,248
211230821	HEIL	DLCURAH36ABK	FEM4P42**AL		29,200	\$4,088
211230832	HEIL	DLCURAH36ABK	FEM4P48**AL		29,400	\$4,116
211230844	HEIL	DLCURAH36ABK	FEM4X42**BL		29,200	\$4,088
211230856	HEIL	DLCURAH36ABK	FEM4X48**BL		29,400	\$4,116
211230878	HEIL	DLCURAH36ABK	FMA4P36**AL*		29,800	\$4,172
211230910	HEIL	DLCURAH36ABK	FXM4X36**AL		29,000	\$4,060
211719732	HEIL	DLCURAH18ABK	FMA4P18**AL*		12,700	\$1,778
211264867	HEIL	DLCURAH18ABK	FXM4X18**AL		12,300	\$1,722
211264845	HEIL	DLCURAH18ABK	FEM4X24**CL		12,100	\$1,694
211264814	HEIL	DLCURAH18ABK	FEM4X18**BL		12,300	\$1,722
211264790	HEIL	DLCURAH18ABK	FEM4P24**AL		12,300	\$1,722
209852069	HEIL	DLCURAH18ABK	DLFUAH18XAK		13,500	\$1,890
209852070	HEIL	DLCURAH24ABK	DLFUAH24XAK		19,200	\$2,688
209852072	HEIL	DLCURAH48ABK	DLFUAH48XAK		36,000	\$5,040
212978660	HEIL	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978671	HEIL	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978682	HEIL	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	18,700	\$2,618
212978693	HEIL	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	18,500	\$2,590
212978704	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	19,400	\$2,716
212978715	HEIL	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	18,900	\$2,646
212978726	HEIL	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701712A*	18,900	\$2,646
212978737	HEIL	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701712A*	19,000	\$2,660
212979126	HEIL	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701716A*	19,400	\$2,716
212986158	HEIL	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401410A*	18,800	\$2,632
212986170	HEIL	DLCURAH24ABK	EA*4X30L14A*	*96MSN0401410A*	19,200	\$2,688
212986182	HEIL	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401410A*	19,200	\$2,688
212986194	HEIL	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401410A*	19,200	\$2,688
212986206	HEIL	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401410A*	18,800	\$2,632
212986218	HEIL	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0401410A*	19,500	\$2,730
212986230	HEIL	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401410A*	19,500	\$2,730
212986242	HEIL	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0401410A*	19,200	\$2,688
207826601	HEIL	DLCSRBI18AAK	DLFSABH18XBK		12,000	\$1,680
207801571	HEIL	DLCSRBI18AAK	DLFSDAH24XAK		12,600	\$1,764
217106871	HISENSE	AO-24U3R25E	AS-24U3RHB25E		20,800	\$2,912
217106870	HISENSE	AO-18U3R25E	AS-18U3RHB25E		14,800	\$2,072
214855379	HISENSE	AUWR-6024P	AUH-6024		37,000	\$5,180
215278607	HISENSE	AUWR-4824P	AUH-4824		36,600	\$5,124
214855378	HISENSE	AUWR-3624P	AUH-3624		32,000	\$4,480
214855377	HISENSE	AUWR-2424P	AUH-2424		20,400	\$2,856
204976793	HISENSE	AUW-12U3SS	ACT-12UR3SCA		7,600	\$1,064
205141567	HISENSE	AUW-36U3ST1	AUC-36UR3SHB1		28,000	\$3,920
206903532	HISENSE	AUWR-24U3SF2	AUH-24UX3SDH2		16,000	\$2,240
206903533	HISENSE	AUWR-48U3SP2	AUH-48UX3SEH2		31,000	\$4,340
204816953	HISENSE	AMW2-18U3SFA	Heat pump without ducts		12,700	\$1,778
203978137	HISENSE	AMW3-24U3SAA	Heat pump without ducts		15,000	\$2,100
203978166	HISENSE	AMW4-36U3STA	Heat pump without ducts		22,400	\$3,136
208193233	HISENSE	AST-12UW3SXE02	AST-12UW3SXE**02		6,800	\$952
208193234	HISENSE	AST-18UW3SBB01	AST-18UW3SBB**01		10,500	\$1,470
206903535	HISENSE	AUWR-36U3SA2	AUH-36UX3SDH2		24,000	\$3,360
203167189	HISENSE	AUW-24U3SA	ACT-24UR3SGB		19,000	\$2,660
203377564	HISENSE	AS-12UW1SXE00	AS-12UW1SXE**00		7,500	\$1,050
203383847	HISENSE	AST-24UW3SDB01	AST-24UW3SDB**01		14,500	\$2,030
203845999	HISENSE	AST-12UW3SXE01	AST-12UW3SXE**01		7,500	\$1,050

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205123813	HISENSE	AMW5-42U3STA	Combination heat pumps with or without ducts		27,600	\$3,864
203459336	HISENSE	AMW4-36U3STA	Heat pump with ducts		23,000	\$3,220
203978167	HISENSE	AMW3-24U3SAA	Combination heat pumps with or without ducts		14,800	\$2,072
204816625	HISENSE	AMW2-18U3SFA	Heat pump with ducts		12,700	\$1,778
205013613	HISENSE	AUW-18U3SF	ACT-18UR3SGB		12,000	\$1,680
205123811	HISENSE	AMW5-42U3STA	Heat pump with ducts		28,400	\$3,976
204976869	HISENSE	AUW-24U3SA	ADT-24UX3SLM		19,300	\$2,702
203446790	HISENSE	AMW3-24U3SAA	Heat pump with ducts		14,600	\$2,044
205092766	HISENSE	AST-24UW3SDN01A	AST-24UW3SDN**01A		12,500	\$1,750
205092762	HISENSE	AST-12UW3SXG01A	AST-12UW3SXG**01A		7,500	\$1,050
216741715	HISENSE	AO-12U3T25P	AS-12U3THB25P		13,000	\$1,820
216598645	HISENSE	AO-24U3R25SS	AS-24U3RDL25SS		21,000	\$2,940
216030254	HISENSE	AO-18U3R25SS	AS-18U3RDL25SS		14,800	\$2,072
216618253	Hisense	AVW-60F3DAH2	Heat pump with ducts		63,000	\$8,820
216618254	Hisense	AVW-60F3DAH2	Heat pump without ducts		63,000	\$8,820
216618255	Hisense	AVW-60F3DAH2	Combination heat pumps with or without ducts		63,000	\$8,820
216618250	Hisense	AVW-48F3DAH2	Heat pump with ducts		54,000	\$7,560
216618251	Hisense	AVW-48F3DAH2	Heat pump without ducts		54,000	\$7,560
216618252	Hisense	AVW-48F3DAH2	Combination heat pumps with or without ducts		54,000	\$7,560
216618247	Hisense	AVW-36F3DAH2	Heat pump with ducts		42,000	\$5,880
216618248	Hisense	AVW-36F3DAH2	Heat pump without ducts		42,000	\$5,880
216618249	Hisense	AVW-36F3DAH2	Combination heat pumps with or without ducts		42,000	\$5,880
216498638	HISENSE	AOU-18U3T25U	ADU-18U3T25U		13,200	\$1,848
216498636	HISENSE	AOU-36U3T25U	AD-36U3T25U		25,600	\$3,584
216498639	HISENSE	AOU-24U3T25U	ADU-24U3T25U		18,200	\$2,548
216498631	HISENSE	AOU-12U3T25U	ADU-12U3T25U		8,700	\$1,218
216498637	HISENSE	AOU-36U3T25U	AC-36U3T25U		25,600	\$3,584
216498635	HISENSE	AOU-24U3T25U	ACU-24U3T25U		19,100	\$2,674
216498634	HISENSE	AOU-18U3T25U	ACU-18U3T25U		14,100	\$1,974
216498633	HISENSE	AOU-12U3T25U	ACU-12U3T25U		8,900	\$1,246
216472836	HISENSE	AMO5-45U3T25U	Combination heat pumps with or without ducts		27,800	\$3,892
216472839	HISENSE	AMO4-36U3T25U	Combination heat pumps with or without ducts		21,800	\$3,052

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216472842	HISENSE	AMO3-27U3T25U	Combination heat pumps with or without ducts		18,000	\$2,520
216472840	HISENSE	AMO2-18U3T25U	Combination heat pumps with or without ducts		11,700	\$1,638
216472834	HISENSE	AMO5-45U3T25U	Heat pump with ducts		27,400	\$3,836
216472837	HISENSE	AMO4-36U3T25U	Heat pump with ducts		21,000	\$2,940
216472841	HISENSE	AMO3-27U3T25U	Heat pump with ducts		18,200	\$2,548
216472833	HISENSE	AMO2-18U3T25U	Heat pump with ducts		11,900	\$1,666
216472835	HISENSE	AMO5-45U3T25U	Heat pump without ducts		28,200	\$3,948
216472838	HISENSE	AMO4-36U3T25U	Heat pump without ducts		22,600	\$3,164
216472832	HISENSE	AMO3-27U3T25U	Heat pump without ducts		17,600	\$2,464
216472831	HISENSE	AMO2-18U3T25U	Heat pump without ducts		11,500	\$1,610
216664722	HISENSE	AOH-48U3T25U	AHU-48U3T24		32,200	\$4,508
216664720	HISENSE	AOH-24U3T25U	AHU-24U3T24		17,000	\$2,380
214091821	HISENSE	AST-2424TUO	AST-2424DLSI		22,000	\$3,080
214097915	HISENSE	AST-1824TXO	AST-1824DLSI		18,000	\$2,520
214232473	HISENSE	AST-1224TUO	AST-1224DLSI		10,800	\$1,512
216370235	HISENSE	AO-24U3T25U	ASU-24U3THB25U		22,000	\$3,080
216370236	HISENSE	AO-18U3T25U	ASU-18U3THB25U		18,000	\$2,520
216370237	HISENSE	AO-12U3T25U	ASU-12U3THB25U		10,800	\$1,512
216558230	HISENSE	AOH-60U3T24P	AHU-60U3T24		37,000	\$5,180
216558231	HISENSE	AOH-48U3T24P	AHU-48U3T24		36,600	\$5,124
216558229	HISENSE	AOH-36U3T24P	AHU-36U3T24		32,000	\$4,480
216558228	HISENSE	AOH-24U3T24P	AHU-24U3T24		20,400	\$2,856
216010670	HISENSE	AST-18UW3SBN00B	AST-18UW3SBN**00B		10,000	\$1,400
216010669	HISENSE	AST-12UW3SXG01B	AST-12UW3SXG**01B		7,500	\$1,050
216010671	HISENSE	AST-24UW3SDN01B	AST-24UW3SDN**01B		12,500	\$1,750
211302341	HISENSE	AUW-24U3SA	AST-24UW3SDBDL01		19,000	\$2,660
211302339	HISENSE	AUW-12U3SS	AST-12UW3SXEDL01		8,000	\$1,120
214841713	HISENSE	AUWR-36U3SA2	DC37A44-210L		23,000	\$3,220
214841714	HISENSE	AUWR-48U3SP2	DC61A44-245R		31,200	\$4,368
211302340	HISENSE	AUW-18U3SF	AST-18UW3SBBDL00		12,000	\$1,680
215224721	HITACHI	RAC-DJ18WHAA	RAK-DJ18PHAA		13,300	\$1,862
216097707	HITACHI	RAM-G24N3HAA	Heat pump without ducts		16,000	\$2,240
216097710	HITACHI	RAM-G24N3HAA	Heat pump with ducts		16,000	\$2,240
216439115	HITACHI	PAS-30BLFASDQ1	PPK-B30UFA1DQ		26,800	\$3,752
216439113	HITACHI	PAS-36BLFASDQ1	JPE36B3XD2HS1A		35,200	\$4,928
216439112	HITACHI	PAS-24BLFASDQ1	JPE24B3XC2HS1A		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216439111	HITACHI	PAS-18BLFASDQ1	JPE18B3XB2HS1A		17,300	\$2,422
216618246	HITACHI	RAC-GJ15WHAA	RAK-GJ15PHAA		12,600	\$1,764
216439097	HITACHI	PAS-24BUFASDQ1	PPK-B24UFA1DQ		16,800	\$2,352
214991606	HITACHI	PAS-36BUFASDQ1	JPE36B3XD2HS1A		28,000	\$3,920
214991605	HITACHI	PAS-30BUFASDQ1	JPE30B3XD2HS1A		28,000	\$3,920
216011944	HITACHI	RAC-XJ24WHAA	RAK-XJ24PHAA		16,000	\$2,240
215911632	HITACHI	RAC-XJ18WHAA	RAK-XJ18PHAA		16,000	\$2,240
215911631	HITACHI	RAC-XJ12WHAA	RAK-XJ12PHAA		11,000	\$1,540
215413021	HITACHI	RAC-GJ24WHAA	RAK-GJ24PHAA		16,700	\$2,338
215413020	HITACHI	RAC-GJ18WHAA	RAK-GJ18PHAA		15,000	\$2,100
215413019	HITACHI	RAC-GJ12WHAA	RAK-GJ12PHAA		9,400	\$1,316
215224720	HITACHI	RAC-DJ12WHAA	RAK-DJ12PHAA		8,400	\$1,176
215359322	HITACHI	PAS-12BLFASDQ1	PCIM-B12UFA1DQ		12,500	\$1,750
215359321	HITACHI	PAS-12BLFASDQ1	PPIM-B12UFA1DQ		12,500	\$1,750
215222842	HITACHI	PAS-36BLFASDQ1	PCI-B36UFA1DQ		34,200	\$4,788
215222826	HITACHI	PAS-30BLFASDQ1	PCI-B30UFA1DQ		28,600	\$4,004
215222825	HITACHI	PAS-24BLFASDQ1	PCI-B24UFA1DQ		21,600	\$3,024
215222824	HITACHI	PAS-18BLFASDQ1	PCI-B18UFA1DQ		18,000	\$2,520
215222841	HITACHI	PAS-36BLFASDQ1	PPIM-B36UFA1DQ		34,200	\$4,788
215222843	HITACHI	PAS-30BLFASDQ1	PPIM-B30UFA1DQ		28,600	\$4,004
215222823	HITACHI	PAS-24BLFASDQ1	PPIM-B24UFA1DQ		21,600	\$3,024
215222822	HITACHI	PAS-18BLFASDQ1	PPIM-B18UFA1DQ		18,000	\$2,520
213685841	HITACHI	PAS-36BUFASDQ1	PPIM-B36UFA1DQ		34,400	\$4,816
213685840	HITACHI	PAS-30BUFASDQ1	PPIM-B30UFA1DQ		28,600	\$4,004
207200483	HITACHI	RAC-PH24WHLAE	RAS-PH24PHLAE		15,300	\$2,142
207200484	HITACHI	RAC-PH18WHLAE	RAS-PH18PHLAE		13,300	\$1,862
207200482	HITACHI	RAC-PH12WHLAE	RAS-PH12PHLAE		9,500	\$1,330
206750859	HITACHI	RAS-4.0PNNBDH1	RCI-4.0PNN1DH		27,200	\$3,808
206750860	HITACHI	RAS-4.0PNNBDH1	RPIM-4.0PNN1DH		26,000	\$3,640
206750858	HITACHI	RAS-3.0PNNBDH1	RPIM-3.0PNN1DH		19,200	\$2,688
212546249	IFLOW	70HPIC24A	70C1824BA		21,000	\$2,940
212546252	IFLOW	70HPIC36A	70C3036CA		33,000	\$4,620
213279900	IFLOW	70HPIC36A	70C3036BA		27,400	\$3,836
213279880	IFLOW	70HPIC45A	70C5460DA		37,000	\$5,180
213279901	IFLOW	70HPIC55A	70C5460CA		37,000	\$5,180
212546250	IFLOW	70HPIC30A	70C3036CA		22,600	\$3,164
216980840	INFINITYLIVING	EZ-60-HPB	EZ-60-AHB		45,000	\$6,300
216980835	INFINITYLIVING	EZ-48-EHPB	EZ-48-AHB		32,400	\$4,536

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216980839	INFINITYLIVING	EZ-48-HPB	EZ-48-AHB		37,000	\$5,180
216980838	INFINITYLIVING	EZ-36-HPB	EZ-36-AHB		31,800	\$4,452
216980833	INFINITYLIVING	EZ-24-EHPB	EZ-24-AHB		20,000	\$2,800
216980837	INFINITYLIVING	EZ-24-HPB	EZ-24-AHB		20,000	\$2,800
214810558	INFINITYLIVING	EZ-24-HP	EZ-24-AH		19,200	\$2,688
214810559	INFINITYLIVING	EZ-48-HP	EZ-48-AH		36,000	\$5,040
214810560	INFINITYLIVING	EZ-60-HP	EZ-60-AH		42,000	\$5,880
216607265	INNOVA	HP36R	THAH-AIRHANDLER36		24,000	\$3,360
214606640	INNOVA	HP36R410A	THAH-AIRHANDLER36		24,000	\$3,360
208978283	INNOVA	THTU-HEATPUMP24	THAH-AIRHANDLER36		24,000	\$3,360
216623513	INNOVAIR	SHV60H2BA	MAC60H2428B		36,000	\$5,040
215725539	INNOVAIR	MOM36H2BH5B	Combination heat pumps with or without ducts		31,400	\$4,396
215725537	INNOVAIR	MOM36H2BH5B	Heat pump without ducts		30,000	\$4,200
210343158	INNOVAIR	SHV24H2R20	DEV24H2R19		19,200	\$2,688
213386877	INNOVAIR	SHV18H2R20	DEV18H2R19		13,500	\$1,890
208286574	INNOVAIR	WIN12H7H51(O)	WIN12H7H51(I)		6,800	\$952
207821948	INNOVAIR	VOM18H7R2P7	Heat pump without ducts		12,700	\$1,778
207821954	INNOVAIR	VOM36H7R4P7	Heat pump without ducts		22,400	\$3,136
207821951	INNOVAIR	VOM24H7R3P7	Heat pump without ducts		15,000	\$2,100
213386878	INNOVAIR	SHV30H2R20	DEV30H2R19		21,000	\$2,940
210343156	INNOVAIR	SHV36H2R20	DEV36H2R19		30,400	\$4,256
206330208	INNOVAIR	EIN13H2V32(O)	EIN13H2V32(I)		8,100	\$1,134
207821947	INNOVAIR	VOM18H7R2P7	Heat pump with ducts		12,700	\$1,778
207821949	INNOVAIR	VOM18H7R2P7	Combination heat pumps with or without ducts		12,700	\$1,778
207821953	INNOVAIR	VOM36H7R4P7	Heat pump with ducts		23,000	\$3,220
207821952	INNOVAIR	VOM24H7R3P7	Combination heat pumps with or without ducts		14,800	\$2,072
207821955	INNOVAIR	VOM36H7R4P7	Combination heat pumps with or without ducts		22,600	\$3,164
207821957	INNOVAIR	VOM42H7R5P7	Heat pump without ducts		27,000	\$3,780
207821950	INNOVAIR	VOM24H7R3P7	Heat pump with ducts		14,600	\$2,044
207821956	INNOVAIR	VOM42H7R5P7	Heat pump with ducts		28,400	\$3,976
207821958	INNOVAIR	VOM42H7R5P7	Combination heat pumps with or without ducts		27,600	\$3,864
213160473	INNOVAIR	SHV24H2R20	MAC24H1718E		21,000	\$2,940
216768191	INNOVAIR	SOV36H2BA	SFV36BDA		24,600	\$3,444

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216768195	INNOVAIR	SHV36H2BB	SFV36BDA		31,200	\$4,368
216768194	INNOVAIR	SHV30H2BA	SFV30BDA		24,000	\$3,360
216768192	INNOVAIR	SHV18H2BA	SFV18BDA		15,000	\$2,100
215725445	INNOVAIR	MOS18H2BH0A	MHW18H2BHRB		16,600	\$2,324
215408661	INNOVAIR	SHV18H2BA	SAV18BDA		15,000	\$2,100
215725476	INNOVAIR	MOS12H2BH0A	MCW12H2BHRB		9,800	\$1,372
215725444	INNOVAIR	MOS12H2BH0A	MHW12H2BHRB		9,800	\$1,372
215408662	INNOVAIR	SHV24H2BA	SAV24BDA		20,000	\$2,800
215408664	INNOVAIR	SHV36H2BB	SAV36BDA		31,800	\$4,452
216623503	INNOVAIR	SOV24H2BA	MAC24H1718B		19,700	\$2,758
216623502	INNOVAIR	SOV24H2BA	MAC24H1418B		19,700	\$2,758
216623506	INNOVAIR	SHV24H2BA	MAC24H1418B		19,700	\$2,758
216623505	INNOVAIR	SHV18H2BA	MAC24H1718B		15,200	\$2,128
216623504	INNOVAIR	SHV18H2BA	MAC24H1418B		15,200	\$2,128
216623509	INNOVAIR	SHV30H2BA	MAC36H1724B		25,000	\$3,500
216623508	INNOVAIR	SHV30H2BA	MAC36H1424B		23,400	\$3,276
216623507	INNOVAIR	SHV24H2BA	MAC24H1718B		19,700	\$2,758
216623510	INNOVAIR	SHV30H2BA	MAC36H2124B		25,000	\$3,500
216623512	INNOVAIR	SHV60H2BA	MMC60H2128B		38,000	\$5,320
216623511	INNOVAIR	SHV36H2BB	MAC36H2124B		29,200	\$4,088
215747783	INNOVAIR	QOM42H2BM5A	Combination heat pumps with or without ducts		27,800	\$3,892
215747786	INNOVAIR	QOM36H2BM4A	Combination heat pumps with or without ducts		21,800	\$3,052
215747780	INNOVAIR	QOM27H2BM3A	Combination heat pumps with or without ducts		18,000	\$2,520
215747777	INNOVAIR	QOM18H2BM2A	Combination heat pumps with or without ducts		11,700	\$1,638
215747781	INNOVAIR	QOM42H2BM5A	Heat pump with ducts		27,400	\$3,836
215747784	INNOVAIR	QOM36H2BM4A	Heat pump with ducts		21,000	\$2,940
215747779	INNOVAIR	QOM27H2BM3A	Heat pump with ducts		18,200	\$2,548
215747776	INNOVAIR	QOM18H2BM2A	Heat pump with ducts		11,900	\$1,666
215747782	INNOVAIR	QOM42H2BM5A	Heat pump without ducts		28,200	\$3,948
215747785	INNOVAIR	QOM36H2BM4A	Heat pump without ducts		22,600	\$3,164
215747778	INNOVAIR	QOM27H2BM3A	Heat pump without ducts		17,600	\$2,464
215747775	INNOVAIR	QOM18H2BM2A	Heat pump without ducts		11,500	\$1,610
216445290	INNOVAIR	QOS12H1BM0A	QHW12H1UZRA		9,300	\$1,302
216445280	INNOVAIR	QOS24H2BM0A	QHW24H2UZRA		22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216445279	INNOVAIR	QOS18H2BM0A	QHW18H2UZRA		18,000	\$2,520
216445278	INNOVAIR	QOS12H2BM0A	QHW12H2UZRA		10,800	\$1,512
216684126	INNOVAIR	SHV48H2BA	MMC60H2128B		32,000	\$4,480
216684125	INNOVAIR	SOV36H2BA	MAC36H2124B		24,200	\$3,388
216684124	INNOVAIR	SOV36H2BA	MAC36H1724B		24,200	\$3,388
216027612	INNOVAIR	SHV18H2BA	SWV18BDA		15,300	\$2,142
216027611	INNOVAIR	SOV36H2BA	SWV36BDA		24,800	\$3,472
216027615	INNOVAIR	SHV36H2BB	SWV36BDA		30,200	\$4,228
216027614	INNOVAIR	SHV30H2BA	SWV30BDA		23,200	\$3,248
215408658	INNOVAIR	SOV36H2BA	SAV36BDA		25,600	\$3,584
215408660	INNOVAIR	SOV60H2BA	SAV60BDA		33,000	\$4,620
215835704	INNOVAIR	MOM60H2BH6A	Combination heat pumps with or without ducts		44,500	\$6,230
215835703	INNOVAIR	MOM60H2BH6A	Heat pump with ducts		45,000	\$6,300
215835702	INNOVAIR	MOM60H2BH6A	Heat pump without ducts		44,000	\$6,160
215835707	INNOVAIR	MOM60H2BH6B	Combination heat pumps with or without ducts		44,500	\$6,230
215835706	INNOVAIR	MOM60H2BH6B	Heat pump with ducts		45,000	\$6,300
215835705	INNOVAIR	MOM60H2BH6B	Heat pump without ducts		44,000	\$6,160
215798837	INNOVAIR	SHV36H2BA	SAV36BDA		23,200	\$3,248
213160476	INNOVAIR	SHV36H2R20	MAC36H2124E		33,000	\$4,620
213160477	INNOVAIR	SHV48H2R20	MAC48H2124E		32,000	\$4,480
215735337	INNOVAIR	MOS60H2BH0A	MDH60H2MHW		45,000	\$6,300
215735336	INNOVAIR	MOS48H2BH0A	MDH48H2MHW		45,000	\$6,300
215735335	INNOVAIR	MOS36H2BH0A	MDH36H2MHW		31,600	\$4,424
215725542	INNOVAIR	MOM48H2BH6B	Combination heat pumps with or without ducts		44,000	\$6,160
215725541	INNOVAIR	MOM48H2BH6B	Heat pump with ducts		44,500	\$6,230
215725540	INNOVAIR	MOM48H2BH6B	Heat pump without ducts		44,000	\$6,160
215725538	INNOVAIR	MOM36H2BH5B	Heat pump with ducts		33,000	\$4,620
215725536	INNOVAIR	MOM27H2BH4B	Combination heat pumps with or without ducts		24,000	\$3,360
215725535	INNOVAIR	MOM27H2BH4B	Heat pump with ducts		23,000	\$3,220
215725534	INNOVAIR	MOM27H2BH4B	Heat pump without ducts		25,000	\$3,500
215725533	INNOVAIR	MOM18H2BH3B	Combination heat pumps with or without ducts		17,300	\$2,422
215725532	INNOVAIR	MOM18H2BH3B	Heat pump with ducts		17,000	\$2,380
215735340	INNOVAIR	MOS60H2BH0A	MFC60H2BHRB		41,000	\$5,740

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215735339	INNOVAIR	MOS48H2BH0A	MFC48H2BHRB		38,500	\$5,390
215735334	INNOVAIR	MOS48H2BH0A	MCS48H2BHRB		44,000	\$6,160
215735338	INNOVAIR	MOS36H2BH0A	MFC36H2BHRB		30,200	\$4,228
215735333	INNOVAIR	MOS36H2BH0A	MCS36H2BHRB		30,600	\$4,284
215725473	INNOVAIR	MOS24H2BH0A	MDH24H2MHWA		21,600	\$3,024
215725472	INNOVAIR	MOS18H2BH0A	MDH18H2MHWA		15,000	\$2,100
215725469	INNOVAIR	MOS18H2BH0A	MDL18H2MHWA		15,000	\$2,100
215725471	INNOVAIR	MOS12H2BH0A	MDH12H2MHWA		10,200	\$1,428
215725468	INNOVAIR	MOS12H2BH0A	MDL12H2MHWA		9,600	\$1,344
215725499	INNOVAIR	MOM48H2BM6A	Heat pump with ducts		37,000	\$5,180
215725527	INNOVAIR	MOM48H2BH6A	Combination heat pumps with or without ducts		44,000	\$6,160
215725526	INNOVAIR	MOM48H2BH6A	Heat pump with ducts		44,500	\$6,230
215725525	INNOVAIR	MOM48H2BH6A	Heat pump without ducts		44,000	\$6,160
215725524	INNOVAIR	MOM36H2BH5A	Combination heat pumps with or without ducts		31,400	\$4,396
215725523	INNOVAIR	MOM36H2BH5A	Heat pump with ducts		33,000	\$4,620
215725522	INNOVAIR	MOM36H2BH5A	Heat pump without ducts		30,000	\$4,200
215725521	INNOVAIR	MOM27H2BH4A	Combination heat pumps with or without ducts		24,000	\$3,360
215725520	INNOVAIR	MOM27H2BH4A	Heat pump with ducts		23,000	\$3,220
215725519	INNOVAIR	MOM27H2BH4A	Heat pump without ducts		25,000	\$3,500
215725518	INNOVAIR	MOM18H2BH3A	Combination heat pumps with or without ducts		17,300	\$2,422
215725517	INNOVAIR	MOM18H2BH3A	Heat pump with ducts		17,000	\$2,380
215725516	INNOVAIR	MOM18H2BH3A	Heat pump without ducts		17,600	\$2,464
215725511	INNOVAIR	MOM48H2BM6B	Heat pump with ducts		37,000	\$5,180
215725531	INNOVAIR	MOM18H2BH3B	Heat pump without ducts		17,600	\$2,464
215725484	INNOVAIR	MOS24H2BH0A	MFC24H2BHRB		20,200	\$2,828
215725456	INNOVAIR	MOS24H2BH0A	MCS24H2BHRB		20,400	\$2,856
215725483	INNOVAIR	MOS18H2BH0A	MFC18H2BHRB		14,400	\$2,016
215725477	INNOVAIR	MOS18H2BH0A	MCW16H2BHRB		14,200	\$1,988
215725455	INNOVAIR	MOS18H2BH0A	MCS18H2BHRB		14,900	\$2,086
215725488	INNOVAIR	MOS18H2BH0A	MCO18H2BHRB		14,500	\$2,030
215725454	INNOVAIR	MOS12H2BH0A	MCS12H2BHRB		10,000	\$1,400
215725446	INNOVAIR	MOS24H2BH0A	MHW24H2BHRB		21,000	\$2,940
215493759	INNOVAIR	QOS12H1BM5A	QHW12H1UZRA		9,300	\$1,302
215493763	INNOVAIR	QOS24H2BM5A	QHW24H2UZRA		22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215493762	INNOVAIR	QOS18H2BM5A	QHW18H2UZRA		18,000	\$2,520
215493761	INNOVAIR	QOS12H2BM5A	QHW12H2UZRA		10,800	\$1,512
215408659	INNOVAIR	SOV48H2BA	SAV48BDA		32,400	\$4,536
215408656	INNOVAIR	SOV24H2BA	SAV24BDA		20,000	\$2,800
215408666	INNOVAIR	SHV60H2BA	SAV60BDA		45,000	\$6,300
215408665	INNOVAIR	SHV48H2BA	SAV48BDA		37,000	\$5,180
215408663	INNOVAIR	SHV30H2BA	SAV30BDA		23,800	\$3,332
213160474	INNOVAIR	SHV36H2R20	MAC36H1724E		27,400	\$3,836
213386880	INNOVAIR	SHV36H2R20-S	MAC36H2124E		27,000	\$3,780
213386879	INNOVAIR	SHV36H2R20-S	MAC36H1724E		27,000	\$3,780
213386548	INNOVAIR	SHV36H2R20	FEV36H2R19		32,800	\$4,592
213363369	INNOVAIR	SHV24H2R20	FEV24H2R19		19,200	\$2,688
213363368	INNOVAIR	SHV18H2R20	FEV18H2R19		13,500	\$1,890
213363370	INNOVAIR	SHV30H2R20	FEV30H2R19		20,000	\$2,800
213489790	INNOVAIR	SHV36H2R20-S	DEV36H2R19		31,800	\$4,452
213255597	INNOVAIR	SHV18H2R20	WEV18H2R19		15,800	\$2,212
213255598	INNOVAIR	SHV24H2R20	WEV24H2R19		20,000	\$2,800
206330209	INNOVAIR	EIN18H2V32(O)	EIN18H2V32(I)		14,200	\$1,988
210365430	INNOVAIR	MHD-24	MHD-CC2.0-17.5-M		22,000	\$3,080
210343157	INNOVAIR	SHV48H2R20	DEV48H2R19		36,000	\$5,040
210343159	INNOVAIR	SHV60H2R20	DEV60H2R19		42,000	\$5,880
213160475	INNOVAIR	SHV30H2R20	MAC36H2124E		22,600	\$3,164
213160478	INNOVAIR	SHV60H2R20	MAC60H2428E		37,000	\$5,180
216011781	Intertherm	DXH12PSK3IH	DHH12PUK3IH		10,000	\$1,400
216011810	Intertherm	DXH12PSK3IH	DKH12FMK3IH		10,000	\$1,400
215746330	Intertherm	DXH18FMK3IH	Heat pump with ducts		15,000	\$2,100
215746325	Intertherm	DXH18FMK3IH	Heat pump without ducts		16,000	\$2,240
215746331	Intertherm	DXH18FMK3IH	Combination heat pumps with or without ducts		15,400	\$2,156
215746332	Intertherm	DXH24FMK3IH	Heat pump with ducts		22,000	\$3,080
215746326	Intertherm	DXH24FMK3IH	Heat pump without ducts		23,600	\$3,304
215746336	Intertherm	DXH24FMK3IH	Combination heat pumps with or without ducts		22,800	\$3,192
215746333	Intertherm	DXH30FMK3IH	Heat pump with ducts		27,200	\$3,808
215746327	Intertherm	DXH30FMK3IH	Heat pump without ducts		28,000	\$3,920
215746337	Intertherm	DXH30FMK3IH	Combination heat pumps with or without ducts		27,600	\$3,864
216011775	Intertherm	DXH36ESK3IL	DHH36ESK3IL		27,400	\$3,836

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215746334	Intertherm	DXH36FMK3IH	Heat pump with ducts		36,000	\$5,040
215746328	Intertherm	DXH36FMK3IH	Heat pump without ducts		36,000	\$5,040
215746338	Intertherm	DXH36FMK3IH	Combination heat pumps with or without ducts		36,000	\$5,040
215746335	Intertherm	DXH42FMK3IH	Heat pump with ducts		40,000	\$5,600
215746329	Intertherm	DXH42FMK3IH	Heat pump without ducts		40,000	\$5,600
215746339	Intertherm	DXH42FMK3IH	Combination heat pumps with or without ducts		40,000	\$5,600
211583740	J-KU	JKS12HP230V1XC	JKS12HP230V1XE		7,000	\$980
213088032	J-KU	JKS24HP230V1XC	JKS24HP230V1XE		14,500	\$2,030
216607266	K2	HP36R	THAH-AIRHANDLER36		24,000	\$3,360
214606641	K2	HP36R410A	THAH-AIRHANDLER36		24,000	\$3,360
208978284	K2	THTU-HEATPUMP24	THAH-AIRHANDLER36		24,000	\$3,360
208836319	KANARTIC	KEOS-12UHE-NA	KEOS-12UHE-NA		10,300	\$1,442
208836317	KANARTIC	KEOS-18UHE-NA	KEOS-18UHE-NA		11,100	\$1,554
213160464	KANIONCO	KWSM-24IR410AHS21.5ODU	KWSM-24IR410AHS21.5IDU		21,200	\$2,968
213160463	KANIONCO	KWSM-18IR410AHS21.5ODU	KWSM-18IR410AHS21.5IDU		15,000	\$2,100
213160462	KANIONCO	KWSM-12IR410AHS25.5ODU	KWSM-12IR410AHS25.5IDU		10,000	\$1,400
212615050	KANIONCO	KD-18IR410AHSODU	KD-18IR410AHSIDU		15,000	\$2,100
212615048	KANIONCO	KD-24IR410AHSODU	KD-24IR410AHSIDU		21,000	\$2,940
212615049	KANIONCO	KD-12IR410AHSODU	KD-12IR410AHSIDU		10,600	\$1,484
210410112	KARDA	3KARDA12SZO	3KARDA12CON-2		10,200	\$1,428
207796638	KARDA	3KARDA12SZO	3KARDA12UVC		9,900	\$1,386
207796640	KARDA	3KARDA12SZO	3KARDA12CON		9,600	\$1,344
207796642	KARDA	3KARDA18SZO	3KARDA18UVD		15,000	\$2,100
206348122	KARDA	2KARDA18SZO20	2PAMSDH18		15,000	\$2,100
207796643	KARDA	3KARDA24SZO	3KARDA24UVC		21,000	\$2,940
213785827	KARDA	3KARDA12SZO	2KARDA12UVC		9,900	\$1,386
213785826	KARDA	3KARDA12SZO	2KARDA12UVCS		9,600	\$1,344
207430432	KARDA	3KARDA12SZO	3KARDA12UVW		10,300	\$1,442
207430430	KARDA	3KARDA18SZO	3KARDA18UVW		11,100	\$1,554
207430431	KARDA	3KARDA24SZO	3KARDA24UVW		18,900	\$2,646
206348123	KARDA	1KARDA24SZO20.5	2PAMSDH24		21,000	\$2,940
207796644	KARDA	3KARDA24SZO	3KARDA24UVD		21,000	\$2,940
207796639	KARDA	3KARDA12SZO	3KARDA12UVD		10,600	\$1,484

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
201830346	KARDA	1PAMSHH12-SZO-22.5	1PAMSHH12-SZW-22.5		7,800	\$1,092
201830348	KARDA	1PAMSHH24-SZO-20.5	1PAMSHH24-SZW-20.5		15,400	\$2,156
205921401	KARDA	1PAMSHH24-SZO-20.5	2KARDA24UVD		17,200	\$2,408
207614968	KEEPRITE	DLCPRBH12AAK	DLFPHBH12XAK		10,400	\$1,456
207826648	KEEPRITE	DLCPRBH18AAK	DLFPHBH18XAK		20,200	\$2,828
206361890	KEEPRITE	DLCSRBH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361892	KEEPRITE	DLCSRBH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361891	KEEPRITE	DLCSRBH18AAK	DLFSHBH18XAK		11,100	\$1,554
210857443	KEEPRITE	DLCSRBH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857444	KEEPRITE	DLCSRBH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132693	KEEPRITE	DLCSRBH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948195	KEEPRITE	DLCSRBH12AAK	DLFSFBH12XAK		10,200	\$1,428
207683355	KEEPRITE	DLCSRBH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447647	KEEPRITE	DLCSRBH24AAK	DLFSCH24XAK		21,200	\$2,968
208447651	KEEPRITE	DLCSRBH18AAK	DLFSCH18XAK		15,000	\$2,100
208447646	KEEPRITE	DLCSRBH12AAK	DLFSCH12XAK		10,000	\$1,400
206771763	KEEPRITE	CVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0701716A*	31,600	\$4,424
211132728	KEEPRITE	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
206765561	KEEPRITE	CVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
211132691	KEEPRITE	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
206771907	KEEPRITE	CVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	31,400	\$4,396
206765552	KEEPRITE	CVH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
206767548	KEEPRITE	CVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
206767557	KEEPRITE	CVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
206773533	KEEPRITE	CVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206771628	KEEPRITE	CVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206773425	KEEPRITE	CVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206771259	KEEPRITE	CVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206773479	KEEPRITE	CVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206766038	KEEPRITE	CVH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
206771277	KEEPRITE	CVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206771358	KEEPRITE	CVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206771727	KEEPRITE	CVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206771781	KEEPRITE	CVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206773434	KEEPRITE	CVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	31,800	\$4,452
206773488	KEEPRITE	CVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	31,600	\$4,424
206773524	KEEPRITE	CVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206771646	KEEPRITE	CVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206773506	KEEPRITE	CVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206773515	KEEPRITE	CVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206771862	KEEPRITE	CVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	31,400	\$4,396
206771898	KEEPRITE	CVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
215324409	KEEPRITE	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215389781	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601716B*	29,600	\$4,144
215323729	KEEPRITE	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215324420	KEEPRITE	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324419	KEEPRITE	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324416	KEEPRITE	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324414	KEEPRITE	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324412	KEEPRITE	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324411	KEEPRITE	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324410	KEEPRITE	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324407	KEEPRITE	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324406	KEEPRITE	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324405	KEEPRITE	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324404	KEEPRITE	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215413270	KEEPRITE	D5CPRAH18AA	D5FPHAH18XAK		19,300	\$2,702
215413269	KEEPRITE	D5CPRAH12AAK	D5FPHAH12XAK		11,000	\$1,540
215357327	KEEPRITE	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357326	KEEPRITE	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357325	KEEPRITE	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215324415	KEEPRITE	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324408	KEEPRITE	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215357353	KEEPRITE	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357336	KEEPRITE	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357335	KEEPRITE	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357334	KEEPRITE	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357333	KEEPRITE	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357332	KEEPRITE	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357331	KEEPRITE	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357330	KEEPRITE	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357329	KEEPRITE	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357328	KEEPRITE	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357324	KEEPRITE	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357323	KEEPRITE	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357322	KEEPRITE	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357318	KEEPRITE	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357317	KEEPRITE	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357316	KEEPRITE	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324457	KEEPRITE	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324455	KEEPRITE	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324454	KEEPRITE	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324452	KEEPRITE	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324451	KEEPRITE	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324418	KEEPRITE	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324413	KEEPRITE	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324458	KEEPRITE	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324456	KEEPRITE	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324453	KEEPRITE	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324403	KEEPRITE	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215319015	KEEPRITE	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215319014	KEEPRITE	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215319013	KEEPRITE	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215319023	KEEPRITE	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215319021	KEEPRITE	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215319011	KEEPRITE	D5CURAH48AAK	D5FUAAH48XAK		32,400	\$4,536
215319008	KEEPRITE	D5CURAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215319006	KEEPRITE	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215319005	KEEPRITE	D5CUHAH60AAK	D5FUAAH60XAK		45,000	\$6,300
215319004	KEEPRITE	D5CUHAH48AAK	D5FUAAH48XAK		37,000	\$5,180
215319003	KEEPRITE	D5CUHAH36AAK	D5FUAAH36XAK		31,800	\$4,452
215319002	KEEPRITE	D5CUHAH30AAK	D5FUAAH30XAK		23,800	\$3,332
215319001	KEEPRITE	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215319000	KEEPRITE	D5CUHAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215318999	KEEPRITE	D5CUHAH18AAK	D5FUAAH18XAK		15,000	\$2,100
215319022	KEEPRITE	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215319018	KEEPRITE	D5CSAH33AAK	D5FSAAH36XBK		27,400	\$3,836
215319017	KEEPRITE	D5CSAH24AAK	D5FSAAH24XBK		16,900	\$2,366

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215319016	KEEPRITE	D5CSHAH18AAK	D5FSAAH18XBK		14,000	\$1,960
212982632	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MSU0601716A*	23,200	\$3,248
212982380	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80MSU0401712A*	12,200	\$1,708
212982944	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MSU0802120A*	23,200	\$3,248
212982404	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80MSU0401712A*	12,200	\$1,708
212982440	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU0401712A*	12,300	\$1,722
212982368	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0401712A*	19,100	\$2,674
213078909	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU1002120A*	29,600	\$4,144
212988103	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	23,600	\$3,304
212982392	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80MSU0401712A*	12,400	\$1,736
213079185	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0601716A*	29,200	\$4,088
213079281	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MSU0802120A*	29,000	\$4,060
213079017	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MSU0401712A*	29,000	\$4,060
212982356	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU0401712A*	19,100	\$2,674
213078885	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MSU1002120A*	29,200	\$4,088
212982140	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80MSU0401712A*	23,400	\$3,276
212981684	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	23,600	\$3,304
212981624	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MSU1002120A*	23,200	\$3,248
213078957	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80MSU0401712A*	29,400	\$4,116
212988043	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96MSN1002120A*	23,400	\$3,276
212982728	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0601716A*	19,000	\$2,660
212982644	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80MSU0601716A*	23,400	\$3,276
212982416	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80MSU0401712A*	12,300	\$1,722
212982344	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU0401712A*	19,100	\$2,674
212982332	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU0401712A*	19,400	\$2,716
213079329	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0802120A*	29,200	\$4,088
212982248	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80MSU0401712A*	19,400	\$2,716
213078933	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	29,400	\$4,116
213078861	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MSU1002120A*	29,200	\$4,088
212988067	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96MSN1002120A*	23,600	\$3,304
212983004	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	23,600	\$3,304
212982428	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU0401712A*	12,400	\$1,736
212982716	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80MSU0601716A*	18,600	\$2,604
212982704	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MSU0601716A*	19,000	\$2,660
213079053	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80MSU0401712A*	29,200	\$4,088
213078993	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MSU0401712A*	29,000	\$4,060
212982176	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MSU0401712A*	23,200	\$3,248
212982296	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MSU0401712A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982284	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80MSU0401712A*	19,000	\$2,660
212982272	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80MSU0401712A*	19,100	\$2,674
213079317	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0802120A*	29,200	\$4,088
213079149	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MSU0601716A*	29,000	\$4,060
212981600	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MSU1002120A*	23,200	\$3,248
213079065	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0401712A*	29,400	\$4,116
212982692	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	23,400	\$3,276
212988055	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*96MSN1002120A*	23,600	\$3,304
212982668	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MSU0601716A*	23,200	\$3,248
212982308	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80MSU0401712A*	18,800	\$2,632
212982224	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80MSU0401712A*	23,400	\$3,276
212981540	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MSU1002120A*	29,000	\$4,060
212981612	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80MSU1002120A*	23,600	\$3,304
209852087	KEEPRITE	DLCURAH36ABK	DLFUAAH36XAK		30,400	\$4,256
213079101	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MSU0601716A*	29,000	\$4,060
212982980	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MSU0802120A*	23,200	\$3,248
212982320	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80MSU0401712A*	18,700	\$2,618
213079257	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MSU0802120A*	29,000	\$4,060
213079221	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MSU0802120A*	29,000	\$4,060
213079089	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MSU0601716A*	29,400	\$4,116
212982164	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80MSU0401712A*	23,400	\$3,276
213079209	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MSU0802120A*	29,400	\$4,116
213079233	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MSU0802120A*	29,400	\$4,116
213079173	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	29,400	\$4,116
213079113	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MSU0601716A*	29,200	\$4,088
212982152	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MSU0401712A*	23,200	\$3,248
212982260	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80MSU0401712A*	18,600	\$2,604
213079245	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MSU0802120A*	29,400	\$4,116
213079305	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	29,400	\$4,116
213080359	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002120A*	29,200	\$4,088
213078873	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MSU1002120A*	29,400	\$4,116
212988079	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96MSN1002120A*	23,200	\$3,248
213079005	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MSU0401712A*	29,400	\$4,116
210470569	KEEPRITE	CVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL1352422A*	31,200	\$4,368
210470536	KEEPRITE	CVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470437	KEEPRITE	CVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0701716A*	31,400	\$4,396
213080454	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002122A*	29,200	\$4,088
213080445	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002122A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080391	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002122A*	29,200	\$4,088
213080382	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002122A*	29,400	\$4,116
213080311	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002120A*	29,400	\$4,116
213080299	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002120A*	29,400	\$4,116
212982092	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MSU0401712A*	28,800	\$4,032
213080409	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002122A*	29,400	\$4,116
212971118	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*80VTL0451412B*	19,300	\$2,702
213080436	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002122A*	29,400	\$4,116
213080418	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002122A*	29,200	\$4,088
213080400	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002122A*	29,400	\$4,116
213080371	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002120A*	29,200	\$4,088
213080347	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	29,400	\$4,116
213080323	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002120A*	29,200	\$4,088
213080287	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002120A*	29,200	\$4,088
213080275	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002120A*	29,400	\$4,116
213079137	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MSU0601716A*	29,000	\$4,060
213078945	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU1002120A*	29,200	\$4,088
212988019	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002120A*	29,000	\$4,060
212988007	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002120A*	29,000	\$4,060
210470525	KEEPRITE	CVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470272	KEEPRITE	CVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	31,000	\$4,340
210470393	KEEPRITE	CVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470382	KEEPRITE	CVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470239	KEEPRITE	CVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	31,000	\$4,340
213079269	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MSU0802120A*	29,000	\$4,060
213079077	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0401712A*	29,200	\$4,088
213078837	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MSU1002120A*	29,400	\$4,116
212988231	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002122A*	29,000	\$4,060
213079161	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU0601716A*	29,600	\$4,144
213078969	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MSU0401712A*	29,400	\$4,116
212988222	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002122A*	29,000	\$4,060
212969733	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412B*	19,300	\$2,702
210473245	KEEPRITE	CVH825GKA3*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210470503	KEEPRITE	CVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0901716A*	31,200	\$4,368
210470250	KEEPRITE	CVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU1002122A*	31,000	\$4,340
210473102	KEEPRITE	CVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
210470448	KEEPRITE	CVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470283	KEEPRITE	CVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL1352422A*	31,000	\$4,340

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210473113	KEEPRITE	CVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210470558	KEEPRITE	CVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
213078981	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80MSU0401712A*	29,200	\$4,088
211712147	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ESU1002120A*	23,200	\$3,248
211712135	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*95ESU1002120A*	23,400	\$3,276
211712124	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80VSL0701716A*	23,400	\$3,276
211712113	KEEPRITE	DLCURAH30ABK	EA*4X36L21A*	*80ESU1002120A*	23,600	\$3,304
211712101	KEEPRITE	DLCURAH30ABK	EA*4X36L21A*	*95ESU1002120A*	23,600	\$3,304
211709691	KEEPRITE	DLCURAH30ABK	FJMA4*30L*B*		23,400	\$3,276
213353862	KEEPRITE	DLCURAH36ABK	F5MA4*42L*C*		29,200	\$4,088
213353852	KEEPRITE	DLCURAH36ABK	F5MA4*36L*B*		29,400	\$4,116
213249342	KEEPRITE	DLCURAH36ABK	FEVA0036**+NAVA43601CK		29,400	\$4,116
213080880	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU0802120A*	29,200	\$4,088
213080868	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0802120A*	29,200	\$4,088
213080856	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	29,400	\$4,116
213080844	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*95MSU0802120A*	29,600	\$4,144
213080832	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95MSU0802120A*	29,200	\$4,088
213080820	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95MSU0802120A*	29,400	\$4,116
213080808	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95MSU0802120A*	29,400	\$4,116
213080796	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95MSU0802120A*	29,200	\$4,088
213080784	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95MSU0802120A*	29,400	\$4,116
213080772	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0601716A*	29,200	\$4,088
213080760	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	29,600	\$4,144
213080748	KEEPRITE	DLCURAH36ABK	END4X42L17**	*95MSU0601716A*	29,400	\$4,116
213080712	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95MSU0601716A*	29,200	\$4,088
213080700	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95MSU0601716A*	29,400	\$4,116
213080688	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95MSU0601716A*	29,200	\$4,088
213080676	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*95MSU0601716A*	29,400	\$4,116
213080664	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95MSU0601716A*	29,400	\$4,116
213080652	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*95MSU0601716A*	29,600	\$4,144
213080640	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0401712A*	29,400	\$4,116
213080628	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0401712A*	29,600	\$4,144
213080616	KEEPRITE	DLCURAH36ABK	END4X42L17**	*95MSU0401712A*	29,400	\$4,116
213080580	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95MSU0401712A*	29,200	\$4,088
211274902	KEEPRITE	DLCURAH30ABK	FVM4X48***L		23,000	\$3,220
213080568	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95MSU0401712A*	29,200	\$4,088
213080556	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95MSU0401712A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080544	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95MSU0401712A*	29,200	\$4,088
213080532	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*95MSU0401712A*	29,400	\$4,116
213080520	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95MSU0401712A*	29,600	\$4,144
213080508	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*95MSU0401712A*	29,600	\$4,144
213080498	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1402422A*	29,200	\$4,088
213080488	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96MSN1402422A*	29,400	\$4,116
213080476	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1202422A*	29,200	\$4,088
213080464	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96MSN1202422A*	29,400	\$4,116
213080263	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN0802120A*	29,200	\$4,088
213080251	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0802120A*	29,200	\$4,088
211222784	KEEPRITE	DLCURAH30ABK	FVM4X24***L		23,600	\$3,304
213080239	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0802120A*	29,400	\$4,116
213080215	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96MSN0802120A*	29,000	\$4,060
213080203	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96MSN0802120A*	29,000	\$4,060
211222768	KEEPRITE	DLCURAH30ABK	FMA4X36**AL*		23,800	\$3,332
213080191	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96MSN0802120A*	29,200	\$4,088
211222760	KEEPRITE	DLCURAH30ABK	FMA4X30**AL*		23,800	\$3,332
213080179	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96MSN0802120A*	29,400	\$4,116
213080167	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96MSN0802120A*	29,400	\$4,116
213080155	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96MSN0802120A*	29,200	\$4,088
211222752	KEEPRITE	DLCURAH30ABK	FM(C,U)4Z36**AL*		23,600	\$3,304
213080143	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96MSN0802120A*	29,600	\$4,144
213080131	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0801716A*	29,200	\$4,088
211222744	KEEPRITE	DLCURAH30ABK	FM(C,U)4Z30**AL*		23,600	\$3,304
213080119	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	29,600	\$4,144
213080107	KEEPRITE	DLCURAH36ABK	END4X42L17**	*96MSN0801716A*	29,400	\$4,116
213080071	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96MSN0801716A*	29,000	\$4,060
211222712	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122A*	23,000	\$3,220
213080059	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96MSN0801716A*	29,200	\$4,088
213080047	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96MSN0801716A*	29,400	\$4,116
213080035	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96MSN0801716A*	29,200	\$4,088
211222704	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120A*	23,200	\$3,248
213080023	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96MSN0801716A*	29,400	\$4,116
211222696	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120A*	23,000	\$3,220
213080011	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96MSN0801716A*	29,600	\$4,144
213079999	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96MSN0801716A*	29,600	\$4,144
213079989	KEEPRITE	DLCURAH36ABK	END4X42L17**	*96MSN0601412A*	29,600	\$4,144
211222688	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VTN0601714A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079969	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96MSN0601412A*	29,400	\$4,116
213079959	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96MSN0601412A*	29,600	\$4,144
211222680	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*95ESU0601716A*	23,400	\$3,276
213079948	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1202420A*	29,200	\$4,088
213079937	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*92MSN1202420A*	29,000	\$4,060
211222672	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*95ESU0401712A*	23,200	\$3,248
213079926	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*92MSN1202420A*	29,400	\$4,116
213079916	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002122A*	29,200	\$4,088
211222664	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120A*	23,200	\$3,248
213079907	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002122A*	29,200	\$4,088
213079898	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002122A*	29,400	\$4,116
211222656	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120A*	23,000	\$3,220
213079880	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002122A*	29,000	\$4,060
211222648	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716A*	23,200	\$3,248
213079871	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002122A*	29,400	\$4,116
213079862	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002122A*	29,400	\$4,116
211222640	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0601714A*	23,200	\$3,248
213079853	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002122A*	29,000	\$4,060
213079844	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002122A*	29,400	\$4,116
211222632	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*95ESN0802120A*	23,200	\$3,248
213079833	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002120A*	29,200	\$4,088
213079821	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002120A*	29,200	\$4,088
211222624	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*95ESN0601714A*	23,200	\$3,248
213079809	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	29,400	\$4,116
213079797	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN1002120A*	29,600	\$4,144
213079785	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002120A*	29,000	\$4,060
211222616	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*92ESN1002120A*	23,200	\$3,248
213079773	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002120A*	29,400	\$4,116
211222608	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*92ESN0802120A*	23,200	\$3,248
213079761	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002120A*	29,400	\$4,116
213079749	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002120A*	29,000	\$4,060
211222600	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*92ESN0801716A*	23,400	\$3,276
213079737	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002120A*	29,400	\$4,116
211222592	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*92ESN0601714A*	23,400	\$3,276
213079727	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN0802120A*	29,200	\$4,088
213079717	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0802120A*	29,200	\$4,088
211222568	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122A*	23,200	\$3,248
213079707	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079697	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN0802120A*	29,600	\$4,144
213079687	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92MSN0802120A*	29,200	\$4,088
211222560	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120A*	23,200	\$3,248
213079677	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*92MSN0802120A*	29,400	\$4,116
211222552	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716A*	23,200	\$3,248
213079667	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92MSN0802120A*	29,400	\$4,116
213079657	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92MSN0802120A*	29,200	\$4,088
213079647	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92MSN0802120A*	29,400	\$4,116
211222544	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ESU0802120A	23,400	\$3,276
213079635	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0801716A*	29,200	\$4,088
213079623	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0801716A*	29,400	\$4,116
211222536	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ESU0601716A	23,200	\$3,248
213079611	KEEPRITE	DLCURAH36ABK	END4X42L17**	*92MSN0801716A*	29,200	\$4,088
211222528	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ESU0401712A*	23,200	\$3,248
211222520	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VSL0902120A*	23,200	\$3,248
213079575	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92MSN0801716A*	29,000	\$4,060
211222512	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VSL0702120A*	23,200	\$3,248
213079563	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92MSN0801716A*	29,400	\$4,116
213079551	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92MSN0801716A*	29,000	\$4,060
211222504	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VSL0701716A*	23,200	\$3,248
213079539	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*92MSN0801716A*	29,400	\$4,116
213079527	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92MSN0801716A*	29,400	\$4,116
211222496	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VSL0451716A*	23,200	\$3,248
213079515	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*92MSN0801716A*	29,400	\$4,116
213079503	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0601714A*	29,200	\$4,088
211222488	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	23,200	\$3,248
213079491	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0601714A*	29,400	\$4,116
213079479	KEEPRITE	DLCURAH36ABK	END4X42L17**	*92MSN0601714A*	29,400	\$4,116
211222480	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
211222472	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
213079443	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92MSN0601714A*	29,200	\$4,088
211222464	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
213079431	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92MSN0601714A*	29,400	\$4,116
213079419	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92MSN0601714A*	29,200	\$4,088
211222456	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
213079405	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601714A*	29,400	\$4,116
213079393	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92MSN0601714A*	29,400	\$4,116
211222448	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079381	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601714A*	29,400	\$4,116
213079371	KEEPRITE	DLCURAH36ABK	END4X42L17**	*92MSN0601412A*	29,400	\$4,116
211222440	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
213079351	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601412A*	29,400	\$4,116
213079341	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601412A*	29,600	\$4,144
211222392	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*96VTN0601714A*	23,400	\$3,276
211222384	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*95ESU0601716A*	23,400	\$3,276
211222376	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*95ESU0401712A*	23,400	\$3,276
211222368	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716A*	23,400	\$3,276
211222360	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*95ESN0601714A*	23,400	\$3,276
213079197	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0601716A*	29,200	\$4,088
211222352	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*92ESN0801716A*	23,400	\$3,276
211222344	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601714A*	23,400	\$3,276
211222336	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601412A*	23,400	\$3,276
213079125	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MSU0601716A*	29,200	\$4,088
211222328	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716A*	23,200	\$3,248
211222320	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412A*	23,400	\$3,276
211222312	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80ESU0601716A	23,400	\$3,276
211222304	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80ESU0401712A*	23,400	\$3,276
211222296	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451716A*	23,400	\$3,276
211222288	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412A*	23,400	\$3,276
211222280	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	23,200	\$3,248
211222272	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	23,400	\$3,276
213078921	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80MSU1002120A*	29,400	\$4,116
213078897	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	29,600	\$4,144
213078849	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80MSU1002120A*	29,400	\$4,116
213078825	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80MSU1002120A*	29,600	\$4,144
211222264	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	23,400	\$3,276
213078815	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1552420A*	29,200	\$4,088
213078805	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1552420A*	29,000	\$4,060
213078795	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	29,400	\$4,116
213078784	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1352420A*	29,200	\$4,088
213078773	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	29,400	\$4,116
213078763	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102420A*	29,200	\$4,088
213078753	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102420A*	29,000	\$4,060
213078743	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	29,400	\$4,116
213078731	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102120A*	29,200	\$4,088
213078719	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)1102120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078707	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	29,400	\$4,116
213078683	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078671	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078659	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078647	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078635	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078623	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078611	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078601	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902420A*	29,200	\$4,088
213078592	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	29,400	\$4,116
213078582	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902120A*	29,200	\$4,088
213078571	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902120A*	29,200	\$4,088
211222152	KEEPRITE	DLCURAH30ABK	EA*4X36L21A*	*92ESN1002120A*	23,400	\$3,276
213078560	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	29,400	\$4,116
211222141	KEEPRITE	DLCURAH30ABK	EA*4X36L21A*	*92ESN0802120A*	23,400	\$3,276
213078538	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078527	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078516	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078505	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078494	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078483	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902116A*	29,200	\$4,088
213078472	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902116A*	29,200	\$4,088
213078461	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	29,400	\$4,116
211712493	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	23,400	\$3,276
213078439	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
213078428	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902116A*	29,400	\$4,116
211712506	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078417	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078406	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	29,000	\$4,060
211712480	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078395	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	29,400	\$4,116
213078383	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0901714A*	29,200	\$4,088
211712467	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	23,400	\$3,276
213078371	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0901714A*	29,400	\$4,116
213078359	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0901714A*	29,200	\$4,088
213078323	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
213078311	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078299	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211222002	KEEPRITE	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078287	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078275	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078263	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078253	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0702116A*	29,200	\$4,088
211712430	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122A*	23,400	\$3,276
213078243	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0702116A*	29,200	\$4,088
213078233	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0702116A*	29,400	\$4,116
211221984	KEEPRITE	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078213	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
213078203	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078193	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078183	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	29,000	\$4,060
213078173	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	29,400	\$4,116
213078161	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701716A*	29,200	\$4,088
213078149	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	29,400	\$4,116
213078137	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701716A*	29,400	\$4,116
213078125	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	29,600	\$4,144
213078113	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	29,600	\$4,144
213078101	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078089	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078077	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078065	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078053	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078041	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	29,600	\$4,144
213078030	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701712A*	29,200	\$4,088
213078019	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	29,400	\$4,116
213078008	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701712A*	29,400	\$4,116
211712385	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716A*	23,400	\$3,276
213077975	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077964	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077953	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
213077942	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
211712373	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*95ESN1002120A*	23,600	\$3,304
213077931	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077920	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	29,400	\$4,116
213077908	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701412A*	29,400	\$4,116
213077884	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712361	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*95ESN0802120A*	23,400	\$3,276
213077872	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
213077860	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0451412A*	29,400	\$4,116
213077836	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	29,400	\$4,116
213077823	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	29,600	\$4,144
213077812	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422B*	29,200	\$4,088
213077800	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422B*	29,400	\$4,116
213077788	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122B*	29,200	\$4,088
211712543	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*92ESN0802120A*	23,400	\$3,276
213077778	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122B*	29,200	\$4,088
213077768	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	29,400	\$4,116
213077758	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN1002122B*	29,600	\$4,144
213077748	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122B*	29,000	\$4,060
213077738	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122B*	29,400	\$4,116
213077728	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122B*	29,400	\$4,116
213077718	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122B*	29,000	\$4,060
213077708	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122B*	29,400	\$4,116
213077697	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120B*	29,200	\$4,088
211712335	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80ESU0401712A*	23,400	\$3,276
213077684	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120B*	29,200	\$4,088
213077671	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	29,400	\$4,116
213077645	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120B*	29,000	\$4,060
213077632	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120B*	29,400	\$4,116
213077619	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120B*	29,400	\$4,116
213077606	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120B*	29,000	\$4,060
211712323	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80ESU1002120A*	23,600	\$3,304
213077593	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120B*	29,400	\$4,116
213077581	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120B*	29,200	\$4,088
213077570	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120B*	29,200	\$4,088
213077559	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	29,400	\$4,116
213077548	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN0802120B*	29,600	\$4,144
213077537	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120B*	29,000	\$4,060
213077526	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120B*	29,200	\$4,088
213077515	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120B*	29,400	\$4,116
213077504	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120B*	29,400	\$4,116
213077493	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120B*	29,200	\$4,088
213077482	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120B*	29,400	\$4,116
213077470	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0801716B*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077457	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0801716B*	29,600	\$4,144
211712299	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*95ESU1002120A*	23,600	\$3,304
213077444	KEEPRITE	DLCURAH36ABK	END4X42L17**	*96VTN0801716B*	29,400	\$4,116
211712555	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*92ESN1002120A*	23,400	\$3,276
213077405	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VTN0801716B*	29,200	\$4,088
213077392	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716B*	29,400	\$4,116
213077379	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VTN0801716B*	29,200	\$4,088
213077366	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96VTN0801716B*	29,400	\$4,116
213077353	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VTN0801716B*	29,400	\$4,116
211712278	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80VSL0702120A*	23,400	\$3,276
213077340	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96VTN0801716B*	29,600	\$4,144
213077328	KEEPRITE	DLCURAH36ABK	END4X42L17**	*96VTN0601412B*	29,400	\$4,116
213077306	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601412B*	29,400	\$4,116
213077295	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601412B*	29,600	\$4,144
213077284	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0401712B*	29,400	\$4,116
213077273	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0401712B*	29,200	\$4,088
213077262	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422B*	29,200	\$4,088
213077252	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422B*	29,000	\$4,060
213077242	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422B*	29,400	\$4,116
213077232	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120B*	29,200	\$4,088
213077222	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120B*	29,200	\$4,088
213077212	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	29,400	\$4,116
213077192	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120B*	29,000	\$4,060
213077182	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120B*	29,000	\$4,060
213077172	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120B*	29,400	\$4,116
213077162	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120B*	29,400	\$4,116
213077152	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120B*	29,000	\$4,060
211712567	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*95ESN0601714A*	23,600	\$3,304
213077142	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120B*	29,400	\$4,116
213077132	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120B*	29,200	\$4,088
213077122	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120B*	29,200	\$4,088
213077112	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	29,400	\$4,116
213077102	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*96VSN0802120B*	29,600	\$4,144
213077092	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120B*	29,000	\$4,060
213077082	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120B*	29,200	\$4,088
213077072	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120B*	29,400	\$4,116
213077062	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120B*	29,400	\$4,116
211712236	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077052	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120B*	29,200	\$4,088
213077042	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120B*	29,400	\$4,116
213077032	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716B*	29,200	\$4,088
213077022	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716B*	29,600	\$4,144
213077012	KEEPRITE	DLCURAH36ABK	END4X42L17**	*96VSN0801716B*	29,400	\$4,116
213076982	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716B*	29,200	\$4,088
213076972	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716B*	29,400	\$4,116
213076962	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716B*	29,200	\$4,088
213076952	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716B*	29,400	\$4,116
213076942	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716B*	29,400	\$4,116
213076932	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716B*	29,600	\$4,144
211712213	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*96VSN0801716A*	23,400	\$3,276
213076922	KEEPRITE	DLCURAH36ABK	END4X42L17**	*96VSN0601412B*	29,400	\$4,116
213076902	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412B*	29,400	\$4,116
213076892	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601412B*	29,600	\$4,144
213076882	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0401712B*	29,400	\$4,116
213076872	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0401712B*	29,200	\$4,088
213076855	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122B*	29,200	\$4,088
213076843	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122B*	29,200	\$4,088
213076831	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122B*	29,400	\$4,116
213076807	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122B*	29,000	\$4,060
213076795	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122B*	29,000	\$4,060
213076783	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122B*	29,200	\$4,088
213076771	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122B*	29,400	\$4,116
211712591	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80ESU0601716A	23,400	\$3,276
213076759	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122B*	29,400	\$4,116
213076747	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122B*	29,200	\$4,088
213076735	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122B*	29,400	\$4,116
213076724	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120B*	29,200	\$4,088
213076713	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120B*	29,200	\$4,088
213076702	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	29,400	\$4,116
213076691	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*80VTL0902120B*	29,600	\$4,144
213076680	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120B*	29,200	\$4,088
213076669	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120B*	29,400	\$4,116
211712171	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
213076658	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120B*	29,400	\$4,116
213076647	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120B*	29,200	\$4,088
213076636	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712159	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*95ESN1002120A*	23,600	\$3,304
213076581	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716B*	29,200	\$4,088
211712663	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80VSL0702120A*	23,400	\$3,276
213076570	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	29,400	\$4,116
213076559	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80VTL0701716B*	29,400	\$4,116
213076526	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716B*	29,000	\$4,060
213076515	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716B*	29,400	\$4,116
213076504	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716B*	29,000	\$4,060
213076493	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716B*	29,400	\$4,116
211712683	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902420A*	23,400	\$3,276
213076482	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716B*	29,400	\$4,116
213076471	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716B*	29,400	\$4,116
213076451	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80VTL0451412B*	29,400	\$4,116
213076427	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412B*	29,200	\$4,088
211712693	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80VSL1102422A*	23,400	\$3,276
213076415	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412B*	29,400	\$4,116
213076340	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002122A*	29,200	\$4,088
213076331	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002122A*	29,200	\$4,088
213076322	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002122A*	29,400	\$4,116
213076304	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002122A*	29,000	\$4,060
211712704	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*95ESU1002120A*	23,600	\$3,304
213076295	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002122A*	29,000	\$4,060
213076286	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002122A*	29,000	\$4,060
213076277	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002122A*	29,400	\$4,116
213076268	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002122A*	29,400	\$4,116
213076259	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002122A*	29,000	\$4,060
213076250	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002122A*	29,400	\$4,116
213076002	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002120A*	29,200	\$4,088
213075990	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002120A*	29,200	\$4,088
211712716	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80ESU1002120A*	23,600	\$3,304
213075978	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002120A*	29,400	\$4,116
213075954	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002120A*	29,000	\$4,060
213075942	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002120A*	29,000	\$4,060
213075930	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002120A*	29,000	\$4,060
213075918	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002120A*	29,400	\$4,116
213075906	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002120A*	29,400	\$4,116
213075894	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002120A*	29,000	\$4,060
213075882	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989509	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95MSU0802120A*	29,000	\$4,060
212989497	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95MSU0802120A*	29,000	\$4,060
212988981	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95MSU0601716A*	29,000	\$4,060
212988409	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96MSN1402422A*	29,000	\$4,060
212988325	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96MSN1202422A*	29,000	\$4,060
211712742	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*95ESN0802120A*	23,400	\$3,276
212985522	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002122A*	29,000	\$4,060
212985513	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002122A*	29,000	\$4,060
212985247	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002120A*	28,800	\$4,032
211712754	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*95ESN1002120A*	23,600	\$3,304
212985235	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002120A*	28,800	\$4,032
212984957	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*92MSN0802120A*	28,800	\$4,032
212984947	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92MSN0802120A*	28,800	\$4,032
212984417	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92MSN0801716A*	29,000	\$4,060
212983877	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92MSN0601714A*	29,000	\$4,060
212982608	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MSU0601716A*	28,800	\$4,032
212981214	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1352420A*	29,000	\$4,060
212980695	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902420A*	29,000	\$4,060
212980494	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980483	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902120A*	29,000	\$4,060
212980175	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902116A*	28,800	\$4,032
212980164	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902116A*	28,800	\$4,032
212979661	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
212979419	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0702116A*	28,800	\$4,032
212979409	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0702116A*	28,800	\$4,032
212978971	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701716A*	29,000	\$4,060
212978485	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701712A*	29,000	\$4,060
212977259	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422B*	29,000	\$4,060
212977095	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122B*	28,800	\$4,032
212977085	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122B*	28,800	\$4,032
212976814	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120B*	29,000	\$4,060
212976801	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120B*	29,000	\$4,060
211712800	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122A*	23,400	\$3,276
212976532	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120B*	28,800	\$4,032
212976310	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0801716B*	29,000	\$4,060
212974419	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120B*	29,000	\$4,060
212974199	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120B*	28,800	\$4,032
212974059	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716B*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972249	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120B*	29,000	\$4,060
212972238	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120B*	29,000	\$4,060
212971882	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716B*	29,000	\$4,060
212970743	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120B*	29,200	\$4,088
212970733	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120B*	29,200	\$4,088
212970723	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	29,400	\$4,116
211712824	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	23,600	\$3,304
212970713	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*80VSL0902120B*	29,600	\$4,144
212970703	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120B*	29,000	\$4,060
212970693	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120B*	29,000	\$4,060
212970683	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120B*	29,200	\$4,088
212970673	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120B*	29,400	\$4,116
212970663	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120B*	29,400	\$4,116
212970653	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120B*	29,200	\$4,088
212970643	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120B*	29,400	\$4,116
211712837	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	23,400	\$3,276
212970483	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716B*	29,200	\$4,088
212970473	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	29,400	\$4,116
212970463	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80VSL0701716B*	29,400	\$4,116
212970433	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716B*	29,000	\$4,060
212970423	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716B*	29,200	\$4,088
211712850	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	23,400	\$3,276
212970413	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716B*	29,400	\$4,116
212970403	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716B*	29,200	\$4,088
212970393	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716B*	29,400	\$4,116
212970383	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716B*	29,600	\$4,144
212970373	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716B*	29,600	\$4,144
212969963	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80VSL0451412B*	29,400	\$4,116
212969943	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412B*	29,200	\$4,088
211712863	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	23,600	\$3,304
212969933	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412B*	29,400	\$4,116
212390905	KEEPRITE	DLCURAH36ABK	FJMA4*36L*B*		29,400	\$4,116
212384858	KEEPRITE	DLCURAH36ABK	FVM4X36***L		29,400	\$4,116
212384834	KEEPRITE	DLCURAH36ABK	FJMA4*42L*C*		29,200	\$4,088
212384794	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0801716A*	29,200	\$4,088
211712876	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	23,400	\$3,276
212384782	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701716A*	29,200	\$4,088
212384730	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384718	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0802120A	29,600	\$4,144
212384706	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0601714A*	29,400	\$4,116
211712889	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	23,600	\$3,304
212384694	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	29,400	\$4,116
212384682	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	29,400	\$4,116
212384670	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0801716A*	29,400	\$4,116
212384658	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0601714A*	29,400	\$4,116
212384645	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	29,400	\$4,116
211712902	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*92ESN0802120A*	23,400	\$3,276
212384632	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	29,400	\$4,116
212384619	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701712A*	29,600	\$4,144
212384606	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0451712A*	29,400	\$4,116
212384595	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	29,400	\$4,116
212384584	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120A*	29,600	\$4,144
212384573	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	29,400	\$4,116
211712914	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*92ESN1002120A*	23,400	\$3,276
212384561	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	29,600	\$4,144
212384550	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120A*	29,400	\$4,116
212384535	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	29,400	\$4,116
212384523	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	29,400	\$4,116
211712980	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0601714A*	23,200	\$3,248
211712990	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120A*	23,000	\$3,220
211713000	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120A*	23,200	\$3,248
211713010	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716A*	23,200	\$3,248
211713021	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*95ESU0401712A*	23,200	\$3,248
211713033	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
211713045	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122A*	23,000	\$3,220
211713055	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VSL0451716A*	23,200	\$3,248
211713065	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VSL0701716A*	23,200	\$3,248
211713075	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VSL0702120A*	23,200	\$3,248
211713085	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VSL0902120A*	23,200	\$3,248
211713096	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*95ESU1002120A*	23,400	\$3,276
211713108	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*95ESU0601716A*	23,400	\$3,276
211713120	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ESU1002120A*	23,400	\$3,276
211713132	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ESU0401712A*	23,200	\$3,248
213353890	KEEPRITE	DLCURAH60ABK	F5MA4*60L*D*		37,800	\$5,292
213607820	KEEPRITE	DLCURAH60ABK	FTMA4B60L0D*		37,400	\$5,236
211713147	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713158	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*95ESN0802120A*	23,200	\$3,248
211713170	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*95ESN1002120A*	23,600	\$3,304
211713182	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716A*	23,200	\$3,248
211713194	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VTN0601714A*	23,200	\$3,248
211713205	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120A*	23,000	\$3,220
211713216	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120A*	23,200	\$3,248
211713227	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122A*	23,200	\$3,248
210025745	KEEPRITE	DLCURAH60ABK	DLFUAAH60XAK		42,000	\$5,880
212384511	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	29,400	\$4,116
212384500	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120A*	29,400	\$4,116
212384490	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	29,400	\$4,116
211713238	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
212384480	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716A*	29,400	\$4,116
212384470	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002122A*	29,600	\$4,144
212384460	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002122A*	29,600	\$4,144
212384450	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002122A*	29,600	\$4,144
212384439	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	29,400	\$4,116
212384428	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	29,400	\$4,116
211713251	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
212384418	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	29,400	\$4,116
212384408	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120A*	29,400	\$4,116
212384398	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0601714A*	29,400	\$4,116
211713264	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
212384357	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80ESU0601716A	29,400	\$4,116
212384344	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701412A*	29,400	\$4,116
212384332	KEEPRITE	DLCURAH36ABK	END4X42L17**	*92ESN0801716A*	29,200	\$4,088
212384320	KEEPRITE	DLCURAH36ABK	END4X42L17**	*92ESN0601714A*	29,200	\$4,088
212384308	KEEPRITE	DLCURAH36ABK	END4X42L17**	*92ESN0601412A*	29,400	\$4,116
211713277	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
212384295	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0901714A*	29,400	\$4,116
212384282	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701712A*	29,400	\$4,116
212384269	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451712A*	29,400	\$4,116
212384256	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451412A*	29,600	\$4,144
211713290	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
212384242	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80VTL0451412A*	29,400	\$4,116
212384231	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80VSL0701716A*	29,200	\$4,088
212384221	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80VSL0451716A*	29,400	\$4,116
212384210	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713303	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
212384146	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*80ESU0802120A	29,800	\$4,172
212384134	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002120A*	29,600	\$4,144
212384122	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN0802120A*	29,600	\$4,144
211713316	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	23,400	\$3,276
211713329	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*92ESN0601714A*	23,000	\$3,220
211713341	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*92ESN0801716A*	23,400	\$3,276
211713353	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*92ESN0802120A*	23,200	\$3,248
212383815	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESU1002122A*	29,800	\$4,172
212383805	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESN1002122A*	29,800	\$4,172
212383795	KEEPRITE	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002122A*	29,800	\$4,172
211713365	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*92ESN1002120A*	23,200	\$3,248
211713377	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*95ESN0601714A*	23,200	\$3,248
211713389	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ESU0802120A	23,400	\$3,276
212383488	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701716A*	29,000	\$4,060
212383476	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92ESN0801716A*	29,000	\$4,060
211713401	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80ESU0601716A	23,200	\$3,248
212383464	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
212383442	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002120A*	29,200	\$4,088
212383431	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120A*	29,000	\$4,060
212383419	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95ESU0601716A*	29,200	\$4,088
212383407	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
212383395	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80ESU0601716A	29,200	\$4,088
212383383	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ESU0601716A	29,400	\$4,116
212383371	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ESU0802120A	29,600	\$4,144
212383359	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002120A*	29,400	\$4,116
212383347	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92ESN0802120A*	29,400	\$4,116
212383335	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92ESN0801716A*	29,400	\$4,116
212383322	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
212383309	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
212383296	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	29,600	\$4,144
212383283	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
212383272	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122A*	29,600	\$4,144
212383261	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VTN0601714A*	29,600	\$4,144
212383249	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716A*	29,400	\$4,116
212383237	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95ESN0802120A*	29,600	\$4,144
212383226	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120A*	29,400	\$4,116
212383214	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383203	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120A*	29,400	\$4,116
212383193	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0702120A*	29,400	\$4,116
212383183	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716A*	29,400	\$4,116
212383172	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95ESU0802120A*	29,800	\$4,172
212383161	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002122A*	29,600	\$4,144
212383150	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
212383139	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716A*	29,400	\$4,116
212383129	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120A*	29,400	\$4,116
212383119	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120A*	29,400	\$4,116
212383109	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VSN0601714A*	29,600	\$4,144
212383078	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80ESU0601716A	29,600	\$4,144
212383065	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	29,600	\$4,144
212383053	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*95ESN0601714A*	29,600	\$4,144
212383041	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*92ESN0801716A*	29,400	\$4,116
212383029	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601714A*	29,400	\$4,116
212383017	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601412A*	29,600	\$4,144
212383004	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	29,600	\$4,144
212382991	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	29,600	\$4,144
212382978	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	29,600	\$4,144
212382965	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	29,800	\$4,172
212382954	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601714A*	29,600	\$4,144
212382942	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716A*	29,400	\$4,116
212382925	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412A*	29,600	\$4,144
212382913	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*95ESU0601716A*	29,400	\$4,116
212382902	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716A*	29,400	\$4,116
212382892	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451716A*	29,600	\$4,144
212382881	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
212382870	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716A*	29,400	\$4,116
212382860	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601714A*	29,600	\$4,144
212382850	KEEPRITE	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412A*	29,600	\$4,144
211230933	KEEPRITE	DLCURAH36ABK	FXM4X48**AL		29,000	\$4,060
211230922	KEEPRITE	DLCURAH36ABK	FXM4X42**AL		29,000	\$4,060
211230901	KEEPRITE	DLCURAH36ABK	FVM4X48***L		28,600	\$4,004
211230890	KEEPRITE	DLCURAH36ABK	FMA4X36**AL*		29,600	\$4,144
211230868	KEEPRITE	DLCURAH36ABK	FM(C,U)4Z36**AL*		29,600	\$4,144
211230785	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422A*	29,200	\$4,088
211230775	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122A*	29,200	\$4,088
211230766	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230756	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120A*	29,200	\$4,088
211230746	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002122A*	29,400	\$4,116
211230736	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002120A*	29,200	\$4,088
211230725	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU0802120A*	29,600	\$4,144
211230715	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422A*	29,200	\$4,088
211230706	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120A*	29,200	\$4,088
211230697	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120A*	29,200	\$4,088
211230687	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1402422A*	29,400	\$4,116
211230676	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1202422A*	29,400	\$4,116
211230666	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002122A*	29,400	\$4,116
211230656	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002120A*	29,200	\$4,088
211230645	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN0802120A*	29,400	\$4,116
211230634	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1202420A*	29,200	\$4,088
211230624	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002122A*	29,400	\$4,116
211230614	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002120A*	29,200	\$4,088
211230603	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN0802120A*	29,000	\$4,060
211230573	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122A*	29,200	\$4,088
211230563	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120A*	29,200	\$4,088
211230552	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU1002120A*	29,200	\$4,088
211230541	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU0802120A	29,400	\$4,116
211230531	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL1102422A*	29,200	\$4,088
211230522	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902420A*	29,200	\$4,088
211230513	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120A*	29,200	\$4,088
211230504	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0702120A*	29,200	\$4,088
211230495	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1552420A*	29,200	\$4,088
211230483	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1352420A*	29,200	\$4,088
211230471	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102420A*	29,200	\$4,088
211230459	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102120A*	29,200	\$4,088
211230447	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902420A*	29,200	\$4,088
211230435	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902120A*	29,200	\$4,088
211230423	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902116A*	29,200	\$4,088
211230411	KEEPRITE	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0702116A*	29,200	\$4,088
211230347	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122A*	29,200	\$4,088
211230338	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120A*	29,200	\$4,088
211230328	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120A*	29,200	\$4,088
211230318	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0601714A*	29,400	\$4,116
211230298	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002122A*	29,400	\$4,116
211230288	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230277	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0802120A*	29,600	\$4,144
211230266	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0601716A*	29,200	\$4,088
211230256	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120A*	29,200	\$4,088
211230247	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120A*	29,200	\$4,088
211230238	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716A*	29,200	\$4,088
211230229	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0601714A*	29,200	\$4,088
211230211	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002122A*	29,400	\$4,116
211230201	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002120A*	29,200	\$4,088
211230190	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0802120A*	29,400	\$4,116
211230179	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0801716A*	29,200	\$4,088
211230168	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0601714A*	29,200	\$4,088
211230158	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002122A*	29,400	\$4,116
211230148	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002120A*	29,200	\$4,088
211230137	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0802120A*	29,000	\$4,060
211230126	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0601714A*	29,200	\$4,088
211230089	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122A*	29,200	\$4,088
211230079	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120A*	29,200	\$4,088
211230067	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716A*	29,200	\$4,088
211230056	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU1002120A*	29,200	\$4,088
211230045	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0802120A	29,400	\$4,116
211230034	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0601716A	29,000	\$4,060
211230023	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0401712A*	29,600	\$4,144
211230013	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120A*	29,200	\$4,088
211230004	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0702120A*	29,200	\$4,088
211229995	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716A*	29,200	\$4,088
211229986	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0451716A*	29,200	\$4,088
211229975	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)1102120A*	29,200	\$4,088
211229963	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902120A*	29,200	\$4,088
211229951	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902116A*	29,200	\$4,088
211229939	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0901714A*	29,200	\$4,088
211229927	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0702116A*	29,200	\$4,088
211229915	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701712A*	29,400	\$4,116
211229903	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0451712A*	29,200	\$4,088
211229857	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	29,400	\$4,116
211229848	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120A*	29,400	\$4,116
211229838	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0601714A*	29,600	\$4,144
211229827	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002120A*	29,400	\$4,116
211229806	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0451716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229795	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	29,400	\$4,116
211229783	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	29,400	\$4,116
211229771	KEEPRITE	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	29,400	\$4,116
211229752	KEEPRITE	DLCURAH36ABK	END4X42L17**	*96VTN0601714A*	29,400	\$4,116
211229741	KEEPRITE	DLCURAH36ABK	END4X42L17**	*95ESU0601716A*	29,200	\$4,088
211229731	KEEPRITE	DLCURAH36ABK	END4X42L17**	*96VSN0801716A*	29,400	\$4,116
211229722	KEEPRITE	DLCURAH36ABK	END4X42L17**	*96VSN0601714A*	29,400	\$4,116
211229694	KEEPRITE	DLCURAH36ABK	END4X42L17**	*95ESN0601714A*	29,400	\$4,116
211229675	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80VTL0701716A*	29,200	\$4,088
211229663	KEEPRITE	DLCURAH36ABK	END4X42L17**	*80VSL0451412A*	29,400	\$4,116
211229627	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422A*	29,000	\$4,060
211229617	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122A*	28,800	\$4,032
211229608	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120A*	29,000	\$4,060
211229598	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120A*	28,800	\$4,032
211229588	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002122A*	29,200	\$4,088
211714021	KEEPRITE	DLCURAH30ABK	EN(A,D)4X36L21**	*80ESU0802120A	23,600	\$3,304
211229578	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002120A*	29,000	\$4,060
211229567	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95ESU0802120A*	29,400	\$4,116
211229557	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422A*	29,000	\$4,060
211229548	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120A*	29,000	\$4,060
211229539	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120A*	29,000	\$4,060
211229529	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95ESN1402422A*	29,200	\$4,088
211229518	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95ESN1202422A*	29,200	\$4,088
211229508	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002122A*	29,200	\$4,088
211229498	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002120A*	29,000	\$4,060
211229487	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*95ESN0802120A*	29,200	\$4,088
211714044	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80VSL0451412A*	23,400	\$3,276
211229476	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*92ESN1202420A*	29,000	\$4,060
211229466	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002122A*	29,200	\$4,088
211229456	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002120A*	28,800	\$4,032
211229445	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*92ESN0802120A*	28,800	\$4,032
211714054	KEEPRITE	DLCURAH30ABK	END4X42L17**	*96VSN0801716A*	23,400	\$3,276
211229415	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122A*	29,000	\$4,060
211229405	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120A*	28,800	\$4,032
211229394	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ESU1002120A*	29,000	\$4,060
211229383	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ESU0802120A	29,200	\$4,088
211229373	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80VSL1102422A*	28,800	\$4,032
211714065	KEEPRITE	DLCURAH30ABK	END4X42L17**	*95ESU0401712A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229364	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902420A*	28,800	\$4,032
211229355	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120A*	28,800	\$4,032
211229346	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80VSL0702120A*	29,000	\$4,060
211229337	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1552420A*	29,200	\$4,088
211229325	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1352420A*	29,000	\$4,060
211714077	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701716A*	23,600	\$3,304
211229313	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102420A*	28,800	\$4,032
211229301	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102120A*	29,000	\$4,060
211229289	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902420A*	29,000	\$4,060
211229277	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902120A*	29,000	\$4,060
211229265	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902116A*	29,000	\$4,060
211714088	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80VSL0451716A*	23,400	\$3,276
211229253	KEEPRITE	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0702116A*	28,800	\$4,032
211714098	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80VSL0701716A*	23,400	\$3,276
211229189	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122A*	28,800	\$4,032
211229180	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120A*	29,000	\$4,060
211229170	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120A*	29,000	\$4,060
211229160	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VTN0601714A*	29,200	\$4,088
211714109	KEEPRITE	DLCURAH30ABK	END4X42L17**	*95ESU0601716A*	23,600	\$3,304
211229150	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002122A*	29,200	\$4,088
211229140	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002120A*	29,000	\$4,060
211229129	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95ESU0802120A*	29,400	\$4,116
211229118	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95ESU0601716A*	29,000	\$4,060
211229108	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120A*	29,000	\$4,060
211714121	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80ESU0401712A*	23,400	\$3,276
211229099	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120A*	29,000	\$4,060
211229090	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716A*	29,000	\$4,060
211229081	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*96VSN0601714A*	29,000	\$4,060
211229063	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002122A*	29,200	\$4,088
211229053	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002120A*	29,000	\$4,060
211714133	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80VTL0451412A*	23,400	\$3,276
211229042	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95ESN0802120A*	29,200	\$4,088
211229031	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95ESN0801716A*	29,000	\$4,060
211229020	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*95ESN0601714A*	29,000	\$4,060
211229010	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002122A*	29,200	\$4,088
211229000	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002120A*	28,800	\$4,032
211228989	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92ESN0802120A*	28,800	\$4,032
211228978	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92ESN0801716A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228967	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*92ESN0601714A*	29,000	\$4,060
211714150	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80VTL0701716A*	23,400	\$3,276
211228930	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122A*	29,000	\$4,060
211228920	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120A*	28,800	\$4,032
211228908	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716A*	29,000	\$4,060
211228897	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ESU1002120A*	29,000	\$4,060
211228886	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ESU0802120A	29,200	\$4,088
211714162	KEEPRITE	DLCURAH30ABK	END4X42L17**	*96VTN0601714A*	23,400	\$3,276
211228875	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ESU0601716A	29,000	\$4,060
211228864	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ESU0401712A*	29,400	\$4,116
211228854	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120A*	28,800	\$4,032
211228845	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0702120A*	29,000	\$4,060
211228836	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716A*	29,000	\$4,060
211714173	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0451412A*	23,400	\$3,276
211228827	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80VSL0451716A*	29,000	\$4,060
211228816	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)1102120A*	29,000	\$4,060
211228804	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902120A*	29,000	\$4,060
211228792	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211228780	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0901714A*	29,000	\$4,060
211228768	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0702116A*	28,800	\$4,032
211714186	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701712A*	23,400	\$3,276
211228756	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701712A*	29,000	\$4,060
211228744	KEEPRITE	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211714199	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0901714A*	23,400	\$3,276
211228662	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122A*	29,000	\$4,060
211228653	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120A*	29,200	\$4,088
211228643	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120A*	29,200	\$4,088
211228633	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VTN0601714A*	29,200	\$4,088
211228613	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002122A*	29,200	\$4,088
211228603	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002120A*	29,000	\$4,060
211714212	KEEPRITE	DLCURAH30ABK	END4X42L17**	*92ESN0601412A*	23,400	\$3,276
211228592	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95ESU0802120A*	29,400	\$4,116
211228581	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95ESU0601716A*	29,200	\$4,088
211228571	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120A*	29,000	\$4,060
211714224	KEEPRITE	DLCURAH30ABK	END4X42L17**	*92ESN0601714A*	23,200	\$3,248
211228562	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120A*	29,000	\$4,060
211228553	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716A*	29,200	\$4,088
211228544	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*96VSN0601714A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228526	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002122A*	29,200	\$4,088
211714236	KEEPRITE	DLCURAH30ABK	END4X42L17**	*92ESN0801716A*	23,200	\$3,248
211228516	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002120A*	29,200	\$4,088
211228505	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95ESN0802120A*	29,200	\$4,088
211228483	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*95ESN0601714A*	29,400	\$4,116
211228473	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002122A*	29,400	\$4,116
211714248	KEEPRITE	DLCURAH30ABK	END4X42L17**	*95ESN0601714A*	23,400	\$3,276
211228463	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002120A*	29,200	\$4,088
211228452	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92ESN0802120A*	29,200	\$4,088
211228441	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*92ESN0601714A*	29,000	\$4,060
211714260	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701412A*	23,200	\$3,248
211228404	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122A*	29,200	\$4,088
211228394	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120A*	29,000	\$4,060
211228382	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716A*	29,000	\$4,060
211714273	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80ESU0601716A	23,400	\$3,276
211228371	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ESU1002120A*	29,000	\$4,060
211228360	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ESU0802120A	29,200	\$4,088
211228349	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ESU0601716A	29,200	\$4,088
211228338	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ESU0401712A*	29,400	\$4,116
211228328	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120A*	29,000	\$4,060
211228319	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0702120A*	29,000	\$4,060
211228310	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716A*	29,200	\$4,088
211228301	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80VSL0451716A*	29,200	\$4,088
211228290	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211228278	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211228266	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211714314	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	23,400	\$3,276
211228254	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211228242	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211714324	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	23,400	\$3,276
211228230	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211228218	KEEPRITE	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211714347	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	23,600	\$3,304
211714359	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	23,400	\$3,276
211714389	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	23,400	\$3,276
211714410	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	23,600	\$3,304
212970763	KEEPRITE	DLCURAH48AAK	EA*4X48L24A*	*80VSL0902120B*	32,600	\$4,564
212970753	KEEPRITE	DLCURAH48AAK	EA*4X48L21A*	*80VSL0902120B*	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714422	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	23,600	\$3,304
211714434	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	23,600	\$3,304
211714446	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0401712A*	23,400	\$3,276
212970803	KEEPRITE	DLCURAH48ABK	EA*4X48L21A*	*80VSL0902120B*	31,400	\$4,396
212970813	KEEPRITE	DLCURAH48ABK	EA*4X48L24A*	*80VSL0902120B*	31,400	\$4,396
212970823	KEEPRITE	DLCURAH48ABK	EA*4X60L24A*	*80VSL0902120B*	31,000	\$4,340
212970843	KEEPRITE	DLCURAH48ABK	EA*4X61L24A*	*80VSL0902120B*	31,000	\$4,340
212970833	KEEPRITE	DLCURAH48ABK	EA*4X61L21A*	*80VSL0902120B*	31,000	\$4,340
211714472	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	23,400	\$3,276
211714484	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	23,400	\$3,276
211714517	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	23,400	\$3,276
211714541	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	23,600	\$3,304
211714554	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	23,400	\$3,276
211714567	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	23,600	\$3,304
211714580	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	23,400	\$3,276
211714593	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	23,600	\$3,304
211714630	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	23,400	\$3,276
211714642	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	23,400	\$3,276
211714666	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	23,400	\$3,276
211714691	KEEPRITE	DLCURAH30ABK	FJMA4*36L*B*		23,400	\$3,276
212969883	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412B*	23,400	\$3,276
212969923	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80VSL0451412B*	23,400	\$3,276
212970303	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80VSL0701716B*	23,600	\$3,304
212970353	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80VSL0701716B*	23,400	\$3,276
212970363	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	23,600	\$3,304
212970593	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80VSL0902120B*	23,600	\$3,304
212970603	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902120B*	23,600	\$3,304
212970633	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	23,600	\$3,304
212971298	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412B*	23,400	\$3,276
212971346	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80VTL0451412B*	23,400	\$3,276
212971783	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716B*	23,400	\$3,276
212971794	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716B*	23,200	\$3,248
212971805	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716B*	23,600	\$3,304
212971816	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716B*	23,200	\$3,248
212971860	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80VTL0701716B*	23,400	\$3,276
212971871	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	23,600	\$3,304
212972172	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120B*	23,200	\$3,248
212972183	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80VTL0902120B*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972194	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80VTL0902120B*	23,600	\$3,304
212972205	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120B*	23,200	\$3,248
212972227	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	23,600	\$3,304
212972454	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122B*	23,400	\$3,276
212972466	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122B*	23,400	\$3,276
212972478	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122B*	23,400	\$3,276
212972490	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122B*	23,200	\$3,248
212973649	KEEPRITE	DLCURAH30ABK	END4X42L17**	*96VSN0601412B*	23,600	\$3,304
212973969	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716B*	23,400	\$3,276
212973979	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716B*	23,400	\$3,276
212973999	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716B*	23,200	\$3,248
212974039	KEEPRITE	DLCURAH30ABK	END4X42L17**	*96VSN0801716B*	23,400	\$3,276
212974139	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120B*	23,200	\$3,248
212974149	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*96VSN0802120B*	23,400	\$3,276
212974159	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96VSN0802120B*	23,400	\$3,276
212974169	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120B*	23,200	\$3,248
212974189	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	23,600	\$3,304
212974359	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120B*	23,200	\$3,248
212974369	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*96VSN1002120B*	23,600	\$3,304
212974379	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96VSN1002120B*	23,600	\$3,304
212974389	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120B*	23,200	\$3,248
212974409	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	23,600	\$3,304
212974529	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96VSN1202422B*	23,600	\$3,304
212975768	KEEPRITE	DLCURAH30ABK	END4X42L17**	*96VTN0601412B*	23,600	\$3,304
212976183	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*96VTN0801716B*	23,400	\$3,276
212976196	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VTN0801716B*	23,400	\$3,276
212976222	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VTN0801716B*	23,200	\$3,248
212976274	KEEPRITE	DLCURAH30ABK	END4X42L17**	*96VTN0801716B*	23,400	\$3,276
212976452	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120B*	23,200	\$3,248
212976466	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*96VTN0802120B*	23,400	\$3,276
212976479	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96VTN0802120B*	23,400	\$3,276
212976494	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120B*	23,200	\$3,248
212976520	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	23,600	\$3,304
212976723	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120B*	23,200	\$3,248
212976736	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002120B*	23,600	\$3,304
212976749	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002120B*	23,600	\$3,304
212976762	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120B*	23,200	\$3,248
212976788	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212977025	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122B*	23,200	\$3,248
212977035	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002122B*	23,400	\$3,276
212977045	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002122B*	23,400	\$3,276
212977055	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122B*	23,200	\$3,248
212977075	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	23,400	\$3,276
212977247	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96VTN1202422B*	23,600	\$3,304
212977522	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	23,400	\$3,276
212977558	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0451412A*	23,400	\$3,276
212978026	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	23,400	\$3,276
212978074	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701412A*	23,400	\$3,276
212978529	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978540	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978551	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701712A*	23,400	\$3,276
212978562	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701712A*	23,200	\$3,248
212978606	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701712A*	23,400	\$3,276
212978617	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701712A*	23,400	\$3,276
212979019	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	23,400	\$3,276
212979031	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979043	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	23,600	\$3,304
212979055	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979103	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701716A*	23,400	\$3,276
212979115	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	23,600	\$3,304
212979439	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	23,200	\$3,248
212979449	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979459	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0702116A*	23,400	\$3,276
212979469	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0702116A*	23,200	\$3,248
212979709	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979721	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979733	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979745	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979793	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0901714A*	23,400	\$3,276
212980197	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980230	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902116A*	23,200	\$3,248
212980252	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902116A*	23,600	\$3,304
212980516	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980527	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	23,600	\$3,304
212980549	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980571	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980704	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)0902420A*	23,600	\$3,304
212980906	KEEPRITE	DLCURAH30ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980918	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980930	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980942	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980954	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980978	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	23,600	\$3,304
212981116	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102420A*	23,400	\$3,276
212981225	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1352420A*	23,600	\$3,304
212981326	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1552420A*	23,400	\$3,276
212981588	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*80MSU1002120A*	23,400	\$3,276
212981672	KEEPRITE	DLCURAH30ABK	END4X42L17**	*80MSU1002120A*	23,400	\$3,276
212982656	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*80MSU0601716A*	23,400	\$3,276
212983474	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601412A*	23,400	\$3,276
212983504	KEEPRITE	DLCURAH30ABK	END4X42L17**	*92MSN0601412A*	23,600	\$3,304
212983925	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601714A*	23,400	\$3,276
212983937	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*92MSN0601714A*	23,200	\$3,248
212983961	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*92MSN0601714A*	23,200	\$3,248
212984009	KEEPRITE	DLCURAH30ABK	END4X42L17**	*92MSN0601714A*	23,400	\$3,276
212984465	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*92MSN0801716A*	23,400	\$3,276
212984477	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*92MSN0801716A*	23,200	\$3,248
212984489	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*92MSN0801716A*	23,400	\$3,276
212984501	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*92MSN0801716A*	23,200	\$3,248
212984549	KEEPRITE	DLCURAH30ABK	END4X42L17**	*92MSN0801716A*	23,400	\$3,276
212984977	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*92MSN0802120A*	23,200	\$3,248
212984987	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*92MSN0802120A*	23,400	\$3,276
212984997	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*92MSN0802120A*	23,400	\$3,276
212985007	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*92MSN0802120A*	23,200	\$3,248
212985027	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	23,600	\$3,304
212985271	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*92MSN1002120A*	23,200	\$3,248
212985283	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*92MSN1002120A*	23,400	\$3,276
212985295	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*92MSN1002120A*	23,400	\$3,276
212985307	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*92MSN1002120A*	23,600	\$3,304
212985331	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	23,600	\$3,304
212985620	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*92MSN1202420A*	23,400	\$3,276
212985751	KEEPRITE	DLCURAH30ABK	END4X42L17**	*96MSN0261410A*	23,600	\$3,304
212986855	KEEPRITE	DLCURAH30ABK	END4X42L17**	*96MSN0601412A*	23,600	\$3,304
212987263	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*96MSN0801716A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212987275	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96MSN0801716A*	23,200	\$3,248
212987299	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96MSN0801716A*	23,400	\$3,276
212987347	KEEPRITE	DLCURAH30ABK	END4X42L17**	*96MSN0801716A*	23,600	\$3,304
212987359	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	23,600	\$3,304
212987731	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*96MSN0802120A*	23,200	\$3,248
212987755	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96MSN0802120A*	23,400	\$3,276
212987767	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*96MSN0802120A*	23,200	\$3,248
212988337	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96MSN1202422A*	23,400	\$3,276
212988419	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*96MSN1402422A*	23,600	\$3,304
212988585	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*95MSU0401712A*	23,600	\$3,304
212988597	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*95MSU0401712A*	23,200	\$3,248
212988621	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*95MSU0401712A*	23,200	\$3,248
212988633	KEEPRITE	DLCURAH30ABK	END4X42L17**	*95MSU0401712A*	23,600	\$3,304
212989029	KEEPRITE	DLCURAH30ABK	EA*4X37L17A*	*95MSU0601716A*	23,400	\$3,276
212989041	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*95MSU0601716A*	23,200	\$3,248
212989053	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*95MSU0601716A*	23,600	\$3,304
212989065	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*95MSU0601716A*	23,200	\$3,248
212989113	KEEPRITE	DLCURAH30ABK	END4X42L17**	*95MSU0601716A*	23,400	\$3,276
212989125	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	23,600	\$3,304
212989533	KEEPRITE	DLCURAH30ABK	EA*4X37L21A*	*95MSU0802120A*	23,200	\$3,248
212989545	KEEPRITE	DLCURAH30ABK	EA*4X42L21A*	*95MSU0802120A*	23,600	\$3,304
212989557	KEEPRITE	DLCURAH30ABK	EA*4X42L24A*	*95MSU0802120A*	23,600	\$3,304
212989569	KEEPRITE	DLCURAH30ABK	EA*4X43L21A*	*95MSU0802120A*	23,200	\$3,248
212989593	KEEPRITE	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	23,600	\$3,304
213249298	KEEPRITE	DLCURAH30ABK	FEVA0036**+NAVA43601CK		23,600	\$3,304
213353814	KEEPRITE	DLCURAH30ABK	F5MA4*30L*B*		23,400	\$3,276
213353824	KEEPRITE	DLCURAH30ABK	F5MA4*36L*B*		23,600	\$3,304
211226266	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	29,600	\$4,144
211226278	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	29,600	\$4,144
211226290	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211226301	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80VSL0451716A*	29,600	\$4,144
211226311	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*80ESU1002120A*	29,400	\$4,116
211226333	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92ESN0601714A*	29,400	\$4,116
211226343	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002122A*	29,600	\$4,144
211226353	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95ESN0601714A*	29,400	\$4,116
211226364	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95ESN0801716A*	29,400	\$4,116
211226375	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002120A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226385	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002122A*	29,600	\$4,144
211226395	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*95ESU0601716A*	29,400	\$4,116
211226406	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120A*	29,400	\$4,116
211226416	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120A*	29,600	\$4,144
211226425	KEEPRITE	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122A*	29,400	\$4,116
211226489	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	29,400	\$4,116
211226501	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	29,200	\$4,088
211226513	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701712A*	29,400	\$4,116
211226525	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
211226536	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226547	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412A*	29,400	\$4,116
211226556	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451716A*	29,400	\$4,116
211226565	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716A*	29,400	\$4,116
211226586	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412A*	29,400	\$4,116
211226598	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716A*	29,400	\$4,116
211226619	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601412A*	29,400	\$4,116
211226630	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601714A*	29,200	\$4,088
211226641	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*92ESN0801716A*	29,400	\$4,116
211226663	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*95ESN0601714A*	29,400	\$4,116
211226673	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412A*	29,400	\$4,116
211226682	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601714A*	29,400	\$4,116
211226691	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716A*	29,400	\$4,116
211226701	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*95ESU0601716A*	29,400	\$4,116
211226712	KEEPRITE	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601714A*	29,400	\$4,116
211226797	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211226809	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211226821	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226833	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211226845	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211226857	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211226868	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0451716A*	29,200	\$4,088
211226877	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716A*	29,200	\$4,088
211226886	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0702120A*	29,000	\$4,060
211226895	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120A*	29,000	\$4,060
211226905	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ESU0401712A*	29,400	\$4,116
211226916	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ESU0601716A	29,200	\$4,088
211226927	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ESU0802120A	29,400	\$4,116
211226938	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80ESU1002120A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226949	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716A*	29,000	\$4,060
211226961	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122A*	29,200	\$4,088
211226998	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92ESN0601714A*	29,000	\$4,060
211227009	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92ESN0801716A*	29,000	\$4,060
211227020	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92ESN0802120A*	29,200	\$4,088
211227030	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002122A*	29,400	\$4,116
211227040	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95ESN0601714A*	29,400	\$4,116
211227062	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95ESN0802120A*	29,200	\$4,088
211227073	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002120A*	29,200	\$4,088
211227083	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002122A*	29,200	\$4,088
211227101	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0601714A*	29,200	\$4,088
211227110	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716A*	29,200	\$4,088
211227119	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120A*	29,000	\$4,060
211227128	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120A*	29,000	\$4,060
211227138	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95ESU0802120A*	29,400	\$4,116
211227149	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002120A*	29,000	\$4,060
211227159	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002122A*	29,200	\$4,088
211227179	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VTN0601714A*	29,200	\$4,088
211227189	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120A*	29,200	\$4,088
211227199	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120A*	29,200	\$4,088
211227208	KEEPRITE	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122A*	29,000	\$4,060
211227290	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0451712A*	29,400	\$4,116
211227302	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701712A*	29,400	\$4,116
211227314	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
211227325	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227337	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	29,400	\$4,116
211227349	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227361	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227373	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227384	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0451716A*	29,400	\$4,116
211227393	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716A*	29,400	\$4,116
211227402	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0702120A*	29,400	\$4,116
211227411	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120A*	29,400	\$4,116
211227432	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ESU0601716A	29,200	\$4,088
211227443	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ESU0802120A	29,600	\$4,144
211227454	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80ESU1002120A*	29,400	\$4,116
211227465	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716A*	29,400	\$4,116
211227477	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227487	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122A*	29,400	\$4,116
211227515	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92ESN0601714A*	29,400	\$4,116
211227526	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92ESN0801716A*	29,400	\$4,116
211227537	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92ESN0802120A*	29,200	\$4,088
211227548	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002120A*	29,200	\$4,088
211227558	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002122A*	29,600	\$4,144
211227568	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95ESN0601714A*	29,400	\$4,116
211227579	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95ESN0802120A*	29,400	\$4,116
211227589	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95ESN1002122A*	29,600	\$4,144
211227598	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0601714A*	29,400	\$4,116
211227607	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716A*	29,400	\$4,116
211227616	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120A*	29,400	\$4,116
211227625	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120A*	29,400	\$4,116
211227635	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95ESU0601716A*	29,400	\$4,116
211227646	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95ESU0802120A*	29,600	\$4,144
211227657	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002120A*	29,400	\$4,116
211227667	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002122A*	29,600	\$4,144
211227677	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0601714A*	29,600	\$4,144
211227687	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716A*	29,400	\$4,116
211227697	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120A*	29,400	\$4,116
211227707	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120A*	29,400	\$4,116
211227716	KEEPRITE	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122A*	29,200	\$4,088
211227771	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227783	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227795	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227807	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	29,400	\$4,116
211227819	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227831	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	29,200	\$4,088
211227843	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	29,400	\$4,116
211227855	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1552420A*	29,400	\$4,116
211227864	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80VSL0702120A*	29,400	\$4,116
211227873	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120A*	29,400	\$4,116
211227882	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902420A*	29,400	\$4,116
211227891	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80VSL1102422A*	29,200	\$4,088
211227901	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ESU0802120A	29,600	\$4,144
211227912	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80ESU1002120A*	29,400	\$4,116
211227923	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120A*	29,400	\$4,116
211227933	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227963	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*92ESN0802120A*	29,200	\$4,088
211227974	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002120A*	29,200	\$4,088
211227984	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002122A*	29,600	\$4,144
211227994	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*92ESN1202420A*	29,400	\$4,116
211228005	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95ESN0802120A*	29,400	\$4,116
211228016	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002120A*	29,400	\$4,116
211228026	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002122A*	29,600	\$4,144
211228036	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95ESN1202422A*	29,600	\$4,144
211228047	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95ESN1402422A*	29,600	\$4,144
211228057	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120A*	29,400	\$4,116
211228066	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120A*	29,400	\$4,116
211228075	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422A*	29,400	\$4,116
211228085	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95ESU0802120A*	29,600	\$4,144
211228096	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002120A*	29,400	\$4,116
211228106	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002122A*	29,600	\$4,144
211228116	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120A*	29,400	\$4,116
211228126	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120A*	29,400	\$4,116
211228135	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122A*	29,200	\$4,088
211228145	KEEPRITE	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422A*	29,400	\$4,116
213353784	KEEPRITE	DLCURAH24ABK	F5MA4*30L*B*		19,100	\$2,674
213353774	KEEPRITE	DLCURAH24ABK	F5MA4*24L*B*		19,300	\$2,702
213249276	KEEPRITE	DLCURAH24ABK	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076404	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601716B*	19,400	\$2,716
213076378	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601716B*	19,400	\$2,716
213076367	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002122A*	19,100	\$2,674
213076349	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95MSU1002122A*	19,000	\$2,660
213076122	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002120A*	19,200	\$2,688
213076110	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*95MSU1002120A*	18,500	\$2,590
212989629	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0802120A*	19,100	\$2,674
212989617	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*95MSU0802120A*	18,600	\$2,604
212989605	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95MSU0802120A*	19,100	\$2,674
212989257	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0601716A*	19,100	\$2,674
212989245	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0601716A*	19,100	\$2,674
212989233	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0601716A*	19,100	\$2,674
212989221	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0601716A*	19,400	\$2,716
212989209	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*95MSU0601716A*	18,700	\$2,618
212989197	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*95MSU0601716A*	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989185	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95MSU0601716A*	19,100	\$2,674
212989173	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95MSU0601716A*	19,100	\$2,674
212989161	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95MSU0601716A*	19,100	\$2,674
212989149	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*95MSU0601716A*	18,600	\$2,604
212989137	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95MSU0601716A*	19,400	\$2,716
212988765	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0401712A*	19,200	\$2,688
212988753	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0401712A*	19,200	\$2,688
212988741	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0401712A*	19,200	\$2,688
212988729	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0401712A*	19,500	\$2,730
212988717	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*95MSU0401712A*	18,600	\$2,604
212988705	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*95MSU0401712A*	18,800	\$2,632
212988693	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95MSU0401712A*	19,000	\$2,660
212988681	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95MSU0401712A*	19,100	\$2,674
212988669	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95MSU0401712A*	19,200	\$2,688
212988657	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*95MSU0401712A*	18,700	\$2,618
212988645	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95MSU0401712A*	19,500	\$2,730
212987827	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0802120A*	19,100	\$2,674
212987815	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96MSN0802120A*	18,700	\$2,618
212987803	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96MSN0802120A*	19,100	\$2,674
212987491	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0801716A*	19,200	\$2,688
212987479	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0801716A*	19,200	\$2,688
212987467	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0801716A*	19,200	\$2,688
212987455	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0801716A*	19,500	\$2,730
212987443	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96MSN0801716A*	19,800	\$2,772
212987431	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0801716A*	18,800	\$2,632
212987419	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96MSN0801716A*	19,000	\$2,660
212987407	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0801716A*	19,100	\$2,674
212987395	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0801716A*	19,200	\$2,688
212987383	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0801716A*	18,700	\$2,618
212987371	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0801716A*	19,400	\$2,716
212986975	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0601412A*	19,200	\$2,688
212986965	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0601412A*	19,200	\$2,688
212986955	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0601412A*	19,200	\$2,688
212986945	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0601412A*	19,500	\$2,730
212986935	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0601412A*	19,500	\$2,730
212986925	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0601412A*	18,800	\$2,632
212986915	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0601412A*	19,100	\$2,674
212986905	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0601412A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986895	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96MSN0601412A*	19,200	\$2,688
212986885	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0601412A*	18,700	\$2,618
212986875	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0601412A*	19,400	\$2,716
212986865	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96MSN0601412A*	19,400	\$2,716
212986651	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0401712A*	19,100	\$2,674
212986639	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401712A*	19,100	\$2,674
212986627	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401712A*	19,100	\$2,674
212986615	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401712A*	19,700	\$2,758
211289635	KEEPRITE	DLCURAH60ABK	FVM4X60***L		37,800	\$5,292
213607745	KEEPRITE	DLCURAH36ABK	FTMA4B48L0C*		28,800	\$4,032
213607730	KEEPRITE	DLCURAH36ABK	FTMA4B36L0C*		29,400	\$4,116
213607685	KEEPRITE	DLCURAH30ABK	FTMA4B36L0C*		23,600	\$3,304
213607655	KEEPRITE	DLCURAH24ABK	FTMA4X24L0B*		19,300	\$2,702
213607640	KEEPRITE	DLCURAH24ABK	FTMA4B36L0C*		19,100	\$2,674
213607595	KEEPRITE	DLCURAH18ABK	FTMA4X24L0B*		12,400	\$1,736
212986603	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96MSN0401712A*	18,800	\$2,632
212986591	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401712A*	19,000	\$2,660
212986579	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96MSN0401712A*	19,200	\$2,688
212986567	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401712A*	19,200	\$2,688
212986555	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401712A*	19,200	\$2,688
212986543	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401712A*	18,900	\$2,646
212986531	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401712A*	19,500	\$2,730
212986267	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401410A*	19,200	\$2,688
212986255	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401410A*	19,200	\$2,688
212986147	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401410A*	19,500	\$2,730
212986135	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96MSN0401410A*	19,500	\$2,730
212985871	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0261410A*	19,000	\$2,660
212985861	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0261410A*	19,000	\$2,660
212985851	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0261410A*	19,100	\$2,674
212985841	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0261410A*	19,500	\$2,730
212985831	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0261410A*	19,500	\$2,730
212985821	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0261410A*	18,800	\$2,632
212985811	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0261410A*	19,100	\$2,674
212985801	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0261410A*	19,100	\$2,674
212985791	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96MSN0261410A*	19,200	\$2,688
212985781	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0261410A*	18,700	\$2,618
212985771	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96MSN0261410A*	19,500	\$2,730
212985761	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96MSN0261410A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212985367	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN1002120A*	19,100	\$2,674
212985355	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*92MSN1002120A*	18,700	\$2,618
212985343	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92MSN1002120A*	19,100	\$2,674
212985057	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0802120A*	19,000	\$2,660
212985047	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*92MSN0802120A*	18,900	\$2,646
212985037	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92MSN0802120A*	19,000	\$2,660
212984693	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0801716A*	19,100	\$2,674
212984681	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0801716A*	19,100	\$2,674
212984669	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0801716A*	19,100	\$2,674
212984657	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0801716A*	19,500	\$2,730
212984645	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*92MSN0801716A*	18,400	\$2,576
212984633	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*92MSN0801716A*	18,900	\$2,646
212984621	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92MSN0801716A*	19,000	\$2,660
212984609	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*92MSN0801716A*	19,000	\$2,660
212984597	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*92MSN0801716A*	19,100	\$2,674
212984585	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*92MSN0801716A*	18,500	\$2,590
212984573	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*92MSN0801716A*	19,300	\$2,702
212984153	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0601714A*	19,100	\$2,674
212984141	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601714A*	19,100	\$2,674
212984129	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601714A*	19,100	\$2,674
212984117	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601714A*	19,400	\$2,716
212984105	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*92MSN0601714A*	18,700	\$2,618
212984093	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601714A*	18,900	\$2,646
212984081	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92MSN0601714A*	19,100	\$2,674
212984069	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601714A*	19,100	\$2,674
212984057	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601714A*	19,100	\$2,674
212984045	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601714A*	18,700	\$2,618
212984033	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601714A*	19,400	\$2,716
212983624	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601412A*	19,200	\$2,688
212983614	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601412A*	19,200	\$2,688
212983604	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*92MSN0601412A*	19,200	\$2,688
212983594	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601412A*	19,500	\$2,730
212983584	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*92MSN0601412A*	19,500	\$2,730
212983574	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601412A*	19,000	\$2,660
212983564	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601412A*	19,200	\$2,688
212983554	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601412A*	19,200	\$2,688
212983544	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*92MSN0601412A*	19,200	\$2,688
212983534	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601412A*	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983524	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601412A*	19,500	\$2,730
212983514	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*92MSN0601412A*	19,500	\$2,730
212983247	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0401712A*	19,200	\$2,688
212983236	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0401712A*	19,200	\$2,688
212983225	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0401712A*	19,200	\$2,688
212983214	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0401712A*	19,600	\$2,744
212983203	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*92MSN0401712A*	18,800	\$2,632
212983192	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*92MSN0401712A*	19,000	\$2,660
212983181	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92MSN0401712A*	19,200	\$2,688
212983170	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*92MSN0401712A*	19,200	\$2,688
212983159	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*92MSN0401712A*	19,300	\$2,702
212983148	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*92MSN0401712A*	18,800	\$2,632
212983137	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*92MSN0401712A*	19,500	\$2,730
212981816	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU1002120A*	19,100	\$2,674
212981804	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	19,200	\$2,688
212981792	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU1002120A*	19,200	\$2,688
212981780	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU1002120A*	19,500	\$2,730
212981756	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80MSU1002120A*	18,800	\$2,632
212981744	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MSU1002120A*	19,100	\$2,674
212981732	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80MSU1002120A*	19,000	\$2,660
212981720	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80MSU1002120A*	19,100	\$2,674
212981708	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80MSU1002120A*	18,700	\$2,618
212981696	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80MSU1002120A*	19,500	\$2,730
212981014	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)1102120A*	19,100	\$2,674
212981002	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	18,800	\$2,632
212980990	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	19,000	\$2,660
212980604	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902120A*	19,100	\$2,674
212980593	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	18,600	\$2,604
212980582	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	19,100	\$2,674
212980285	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902116A*	19,100	\$2,674
212980274	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902116A*	18,600	\$2,604
212980263	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902116A*	19,000	\$2,660
212979937	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0901714A*	19,100	\$2,674
212979925	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979913	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979901	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	19,500	\$2,730
212979889	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979877	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	18,700	\$2,618

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979865	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979853	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979841	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979829	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	18,600	\$2,604
212979817	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	19,400	\$2,716
212979519	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0702116A*	19,200	\$2,688
212979509	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0702116A*	18,600	\$2,604
212979499	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0702116A*	19,100	\$2,674
212979247	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	19,100	\$2,674
212979235	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979223	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979211	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701716A*	19,400	\$2,716
212979199	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979187	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979175	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979163	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979151	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979139	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212978650	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978639	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	18,600	\$2,604
212978628	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	19,400	\$2,716
212978218	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978206	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978194	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	19,100	\$2,674
212978182	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	19,400	\$2,716
212978170	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	19,400	\$2,716
212978158	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	18,700	\$2,618
212978146	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	19,000	\$2,660
212978134	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978122	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978110	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	18,600	\$2,604
212978098	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	19,400	\$2,716
212978086	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	19,300	\$2,702
212977702	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977690	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977678	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	19,000	\$2,660
212977666	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	19,500	\$2,730
212977654	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212977642	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977630	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977618	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977606	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977594	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977582	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977570	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977005	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122B*	19,200	\$2,688
212976985	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122B*	19,100	\$2,674
212976697	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120B*	19,100	\$2,674
212976684	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002120B*	18,600	\$2,604
212976671	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120B*	19,000	\$2,660
212976423	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120B*	19,200	\$2,688
212976409	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120B*	18,600	\$2,604
212976396	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120B*	19,100	\$2,674
212976131	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716B*	18,900	\$2,646
212976118	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716B*	18,900	\$2,646
212976105	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716B*	18,900	\$2,646
212976092	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716B*	19,500	\$2,730
212976066	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716B*	19,000	\$2,660
212976053	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716B*	19,000	\$2,660
212976040	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716B*	19,000	\$2,660
212976027	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716B*	19,100	\$2,674
212976014	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0801716B*	18,800	\$2,632
212976001	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716B*	19,500	\$2,730
212975757	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412B*	19,100	\$2,674
212975746	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412B*	19,100	\$2,674
212975735	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412B*	19,000	\$2,660
212975724	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412B*	19,500	\$2,730
212975713	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412B*	19,500	\$2,730
212975702	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412B*	18,800	\$2,632
212975691	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412B*	19,100	\$2,674
212975680	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412B*	19,100	\$2,674
212975669	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412B*	19,100	\$2,674
212975658	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412B*	18,600	\$2,604
212975647	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412B*	19,400	\$2,716
212975636	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412B*	19,400	\$2,716
212975372	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712B*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975361	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712B*	19,200	\$2,688
212975350	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712B*	19,200	\$2,688
212975339	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712B*	19,600	\$2,744
212975328	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712B*	18,900	\$2,646
212975317	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401712B*	18,900	\$2,646
212975306	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712B*	19,100	\$2,674
212975295	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712B*	19,100	\$2,674
212975284	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712B*	19,200	\$2,688
212975273	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712B*	18,800	\$2,632
212975262	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712B*	19,500	\$2,730
212975063	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410B*	19,200	\$2,688
212975050	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410B*	19,200	\$2,688
212975037	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410B*	19,100	\$2,674
212975024	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410B*	19,600	\$2,744
212975011	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410B*	19,600	\$2,744
212974998	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410B*	18,800	\$2,632
212974985	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410B*	19,200	\$2,688
212974972	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410B*	19,200	\$2,688
212974959	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410B*	19,200	\$2,688
212974946	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401410B*	18,700	\$2,618
212974933	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410B*	19,500	\$2,730
212974920	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410B*	19,500	\$2,730
212974329	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VSN1002120B*	18,900	\$2,646
212974319	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120B*	19,000	\$2,660
212974119	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120B*	19,200	\$2,688
212974109	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VSN0802120B*	18,600	\$2,604
212974099	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120B*	19,100	\$2,674
212973929	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716B*	18,900	\$2,646
212973919	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716B*	18,900	\$2,646
212973909	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716B*	18,900	\$2,646
212973899	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716B*	19,500	\$2,730
212973879	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716B*	19,000	\$2,660
212973869	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716B*	19,000	\$2,660
212973859	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716B*	19,000	\$2,660
212973849	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716B*	19,100	\$2,674
212973839	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0801716B*	18,800	\$2,632
212973829	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716B*	19,500	\$2,730
212973639	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412B*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973629	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412B*	19,100	\$2,674
212973619	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412B*	19,000	\$2,660
212973609	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412B*	19,500	\$2,730
212973599	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412B*	19,500	\$2,730
212973589	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412B*	18,800	\$2,632
212973579	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412B*	19,100	\$2,674
212973569	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412B*	19,100	\$2,674
212973559	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412B*	19,100	\$2,674
212973549	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412B*	18,600	\$2,604
212973539	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412B*	19,400	\$2,716
212973529	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412B*	19,400	\$2,716
212973289	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712B*	19,200	\$2,688
212973279	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712B*	19,200	\$2,688
212973269	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712B*	19,200	\$2,688
212973259	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712B*	19,600	\$2,744
212973249	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712B*	18,900	\$2,646
212973239	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401712B*	18,900	\$2,646
212973229	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712B*	19,100	\$2,674
212973219	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712B*	19,100	\$2,674
212973209	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712B*	19,200	\$2,688
212973199	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712B*	18,800	\$2,632
212973189	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712B*	19,500	\$2,730
212973009	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410B*	19,200	\$2,688
212972999	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410B*	19,200	\$2,688
212972989	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410B*	19,200	\$2,688
212972979	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410B*	19,500	\$2,730
212972969	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410B*	19,500	\$2,730
212972959	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410B*	19,000	\$2,660
212972949	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410B*	19,200	\$2,688
212972939	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410B*	19,200	\$2,688
212972929	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410B*	19,200	\$2,688
212972919	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401410B*	18,800	\$2,632
212972909	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410B*	19,500	\$2,730
212972899	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410B*	19,500	\$2,730
212972430	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122B*	19,200	\$2,688
212972418	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122B*	18,800	\$2,632
212972406	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122B*	19,100	\$2,674
212972150	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120B*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972139	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80VTL0902120B*	18,900	\$2,646
212972128	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120B*	19,100	\$2,674
212971739	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716B*	19,100	\$2,674
212971728	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716B*	19,100	\$2,674
212971717	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716B*	19,100	\$2,674
212971706	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716B*	19,500	\$2,730
212971695	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80VTL0701716B*	18,700	\$2,618
212971684	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716B*	18,700	\$2,618
212971673	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716B*	19,100	\$2,674
212971662	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716B*	19,100	\$2,674
212971651	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716B*	19,100	\$2,674
212971640	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80VTL0701716B*	18,600	\$2,604
212971629	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716B*	19,400	\$2,716
212971250	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412B*	19,100	\$2,674
212971238	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412B*	19,100	\$2,674
212971226	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412B*	19,000	\$2,660
212971214	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412B*	19,500	\$2,730
212971202	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412B*	19,500	\$2,730
212971190	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412B*	18,700	\$2,618
212971178	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412B*	19,000	\$2,660
212971166	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412B*	19,100	\$2,674
212971154	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*80VTL0451412B*	19,100	\$2,674
212969843	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412B*	19,100	\$2,674
212969833	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412B*	19,100	\$2,674
212969823	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412B*	19,000	\$2,660
212969813	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412B*	19,500	\$2,730
212969803	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412B*	19,500	\$2,730
212969793	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451412B*	18,700	\$2,618
212969783	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412B*	19,000	\$2,660
212969773	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412B*	19,100	\$2,674
212969763	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412B*	19,100	\$2,674
212969753	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80VSL0451412B*	18,500	\$2,590
212969743	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412B*	19,300	\$2,702
211245987	KEEPRITE	DLCURAH24ABK	FVM4X36***L		19,000	\$2,660
211245977	KEEPRITE	DLCURAH24ABK	FVM4X24***L		19,000	\$2,660
211245966	KEEPRITE	DLCURAH24ABK	FM(C,U)4Z36**AL*		19,300	\$2,702
211245955	KEEPRITE	DLCURAH24ABK	FM(C,U)4Z30**AL*		19,300	\$2,702
211245944	KEEPRITE	DLCURAH24ABK	FM(C,U)4Z24**AL*		19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245933	KEEPRITE	DLCURAH24ABK	FM(C,U)4X36**AL*		19,900	\$2,786
211245922	KEEPRITE	DLCURAH24ABK	FM(C,U)4X30**AL*		19,900	\$2,786
211245911	KEEPRITE	DLCURAH24ABK	FMA4X36**AL*		19,600	\$2,744
211245900	KEEPRITE	DLCURAH24ABK	FMA4X30**AL*		19,600	\$2,744
211245889	KEEPRITE	DLCURAH24ABK	FMA4X24**AL*		19,600	\$2,744
211245867	KEEPRITE	DLCURAH24ABK	FMA4P24**AL*		19,900	\$2,786
211245856	KEEPRITE	DLCURAH24ABK	FXM4X36**AL		18,500	\$2,590
211245845	KEEPRITE	DLCURAH24ABK	FXM4X30**AL		19,100	\$2,674
211245834	KEEPRITE	DLCURAH24ABK	FXM4X24**AL		19,100	\$2,674
211245823	KEEPRITE	DLCURAH24ABK	FEM4X30**BL		19,100	\$2,674
211245811	KEEPRITE	DLCURAH24ABK	FEM4X24**CL		19,000	\$2,660
211245799	KEEPRITE	DLCURAH24ABK	FEM4P30**AL		19,100	\$2,674
211245751	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0601716A	19,300	\$2,702
211245740	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0802120A	19,100	\$2,674
211245729	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0401712A*	19,100	\$2,674
211245718	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0801716A*	19,500	\$2,730
211245707	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0601714A*	19,400	\$2,716
211245696	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN1002120A*	19,300	\$2,702
211245685	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0802120A*	19,300	\$2,702
211245674	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0801716A*	19,100	\$2,674
211245663	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0601714A*	19,100	\$2,674
211245651	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)1102120A*	19,400	\$2,716
211245639	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0902120A*	19,300	\$2,702
211245627	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0901714A*	19,200	\$2,688
211245615	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0702116A*	19,100	\$2,674
211245603	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701712A*	19,200	\$2,688
211245591	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0451712A*	19,100	\$2,674
211245581	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122A*	19,000	\$2,660
211245571	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120A*	19,000	\$2,660
211245561	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120A*	18,900	\$2,646
211245551	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0601714A*	19,100	\$2,674
211245540	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0401712A*	19,400	\$2,716
211245530	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716A*	19,100	\$2,674
211245520	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716A*	19,100	\$2,674
211245509	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0802120A*	19,300	\$2,702
211245499	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712A*	19,000	\$2,660
211245489	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120A*	19,000	\$2,660
211245476	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0401712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245465	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0601716A*	19,100	\$2,674
211245455	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0902120A*	19,000	\$2,660
211245446	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0702120A*	19,300	\$2,702
211245437	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0701716A*	19,000	\$2,660
211245428	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0451716A*	19,200	\$2,688
211245383	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122A*	18,900	\$2,646
211245373	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701716A*	19,400	\$2,716
211245362	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0401712A*	19,000	\$2,660
211245352	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716A*	19,100	\$2,674
211245343	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712A*	19,000	\$2,660
211245334	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN1002120A*	19,000	\$2,660
211245325	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120A*	19,000	\$2,660
211245316	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0601714A*	18,900	\$2,646
211245252	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0601716A	19,300	\$2,702
211245240	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211245229	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401712A*	19,100	\$2,674
211245218	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401410A*	19,400	\$2,716
211245207	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0801716A*	19,500	\$2,730
211245196	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601714A*	19,400	\$2,716
211245185	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0801716A*	19,100	\$2,674
211245174	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601714A*	19,100	\$2,674
211245163	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601412A*	18,900	\$2,646
211245151	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211245139	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211245127	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211245115	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211245105	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601714A*	19,100	\$2,674
211245094	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0261410A*	18,900	\$2,646
211245084	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412A*	19,000	\$2,660
211245074	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410A*	19,000	\$2,660
211245063	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601412A*	19,400	\$2,716
211245052	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401712A*	19,400	\$2,716
211245041	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401410A*	19,500	\$2,730
211245031	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716A*	19,100	\$2,674
211245021	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716A*	19,100	\$2,674
211245011	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712A*	19,000	\$2,660
211244997	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412A*	19,100	\$2,674
211244986	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0401712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244975	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0601716A*	19,100	\$2,674
211244965	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0701716A*	19,000	\$2,660
211244956	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451716A*	19,200	\$2,688
211244928	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244917	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0401712A*	19,000	\$2,660
211244907	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716A*	19,100	\$2,674
211244898	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412A*	19,000	\$2,660
211244889	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712A*	19,000	\$2,660
211244880	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410A*	19,000	\$2,660
211244871	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601714A*	18,900	\$2,646
211244853	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412A*	18,900	\$2,646
213372155	KEEPRITE	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372151	KEEPRITE	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
211244816	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0601716A	19,300	\$2,702
211244804	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211244793	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401712A*	19,100	\$2,674
211244782	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401410A*	19,400	\$2,716
211244771	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0801716A*	19,500	\$2,730
211244760	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601714A*	19,400	\$2,716
211244749	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0801716A*	19,100	\$2,674
211244738	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601714A*	19,100	\$2,674
211244727	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601412A*	18,900	\$2,646
211244715	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211244703	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211244691	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211244679	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211244669	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601714A*	19,100	\$2,674
211244658	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0261410A*	18,900	\$2,646
211244648	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412A*	19,000	\$2,660
211244638	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410A*	19,000	\$2,660
211244627	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601412A*	19,400	\$2,716
211244616	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401712A*	19,400	\$2,716
211244605	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401410A*	19,500	\$2,730
211244595	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716A*	19,100	\$2,674
211244585	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716A*	19,100	\$2,674
211244575	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712A*	19,000	\$2,660
211244561	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412A*	19,100	\$2,674
211244550	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0401712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244539	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0601716A*	19,100	\$2,674
211244529	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0701716A*	19,000	\$2,660
211244520	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451716A*	19,200	\$2,688
211244492	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244481	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0401712A*	19,000	\$2,660
211244471	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716A*	19,100	\$2,674
211244462	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412A*	19,000	\$2,660
211244453	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712A*	19,000	\$2,660
211244444	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410A*	19,000	\$2,660
211244435	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601714A*	18,900	\$2,646
211244417	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412A*	18,900	\$2,646
211244406	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	19,100	\$2,674
211244395	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0401410A*	19,400	\$2,716
211244384	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0601412A*	18,900	\$2,646
211244372	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	19,300	\$2,702
211244361	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0261410A*	19,500	\$2,730
211244351	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412A*	19,000	\$2,660
211244341	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410A*	19,100	\$2,674
211244330	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0601412A*	19,400	\$2,716
211244319	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0401410A*	19,500	\$2,730
211244307	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412A*	19,100	\$2,674
211244297	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412A*	19,000	\$2,660
211244288	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410A*	19,100	\$2,674
211244279	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412A*	19,200	\$2,688
211244242	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0601716A	19,600	\$2,744
211244230	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	19,500	\$2,730
211244219	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401712A*	19,500	\$2,730
211244208	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401410A*	19,700	\$2,758
211244197	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0801716A*	19,800	\$2,772
211244186	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601714A*	19,700	\$2,758
211244175	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0801716A*	19,400	\$2,716
211244164	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601714A*	19,500	\$2,730
211244153	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601412A*	19,600	\$2,744
211244141	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0901714A*	19,500	\$2,730
211244129	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	19,500	\$2,730
211244117	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	19,400	\$2,716
211244105	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	19,600	\$2,744
211244095	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601714A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244084	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0261410A*	19,900	\$2,786
211244074	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412A*	19,300	\$2,702
211244064	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410A*	19,500	\$2,730
211244053	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601412A*	19,700	\$2,758
211244042	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401712A*	19,700	\$2,758
211244031	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401410A*	19,800	\$2,772
211244021	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716A*	19,400	\$2,716
211244011	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716A*	19,500	\$2,730
211244001	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712A*	19,700	\$2,758
211243987	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412A*	19,500	\$2,730
211243976	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0401712A*	19,300	\$2,702
211243965	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0601716A*	19,400	\$2,716
211243955	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0701716A*	19,400	\$2,716
211243946	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451716A*	19,500	\$2,730
211243918	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701716A*	19,700	\$2,758
211243907	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0401712A*	19,300	\$2,702
211243897	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716A*	19,500	\$2,730
211243888	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412A*	19,300	\$2,702
211243879	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712A*	19,700	\$2,758
211243870	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410A*	19,500	\$2,730
211243861	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601714A*	19,500	\$2,730
211243843	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412A*	19,500	\$2,730
211243832	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	19,500	\$2,730
211243821	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0401410A*	19,700	\$2,758
211243810	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0601412A*	19,600	\$2,744
211243798	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	19,600	\$2,744
211243787	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0261410A*	19,900	\$2,786
211243777	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412A*	19,300	\$2,702
211243767	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410A*	19,500	\$2,730
211243756	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0601412A*	19,700	\$2,758
211243745	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0401410A*	19,800	\$2,772
211243733	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412A*	19,500	\$2,730
211243723	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412A*	19,300	\$2,702
211243714	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410A*	19,500	\$2,730
211243705	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412A*	19,500	\$2,730
211243489	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122A*	18,500	\$2,590
211243469	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120A*	18,400	\$2,576
211243407	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712A*	18,500	\$2,590

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243291	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002122A*	18,400	\$2,576
211243251	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712A*	18,500	\$2,590
211243148	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	18,900	\$2,646
211243137	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*92ESN0401712A*	18,900	\$2,646
211243093	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*92ESN0801716A*	18,900	\$2,646
211243082	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*92ESN0601714A*	18,900	\$2,646
211243035	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0451712A*	18,900	\$2,646
211243013	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601714A*	18,900	\$2,646
211242992	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412A*	18,700	\$2,618
211242982	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410A*	18,900	\$2,646
211242939	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716A*	18,800	\$2,632
211242929	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716A*	18,900	\$2,646
211242905	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412A*	18,900	\$2,646
211242894	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80ESU0401712A*	18,700	\$2,618
211242883	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*95ESU0601716A*	18,900	\$2,646
211242873	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80VSL0701716A*	18,800	\$2,632
211242864	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451716A*	19,000	\$2,660
211242825	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*95ESU0401712A*	18,700	\$2,618
211242815	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716A*	18,900	\$2,646
211242806	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412A*	18,700	\$2,618
211242788	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410A*	18,900	\$2,646
211242779	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601714A*	19,000	\$2,660
211242715	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ESU0601716A	19,300	\$2,702
211242704	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ESU0802120A	19,100	\$2,674
211242693	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92ESN0401712A*	19,100	\$2,674
211242682	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95ESN0801716A*	19,400	\$2,716
211242671	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95ESN0601714A*	19,300	\$2,702
211242660	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92ESN1002120A*	19,300	\$2,702
211242649	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92ESN0802120A*	19,300	\$2,702
211242638	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92ESN0801716A*	19,100	\$2,674
211242627	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*92ESN0601714A*	19,100	\$2,674
211242615	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	19,400	\$2,716
211242603	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	19,200	\$2,688
211242591	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242579	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	19,100	\$2,674
211242567	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	18,800	\$2,632
211242555	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242545	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122A*	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242535	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120A*	19,000	\$2,660
211242525	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120A*	18,900	\$2,646
211242515	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0601714A*	19,100	\$2,674
211242504	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95ESN0401712A*	19,300	\$2,702
211242494	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716A*	19,000	\$2,660
211242484	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716A*	19,100	\$2,674
211242473	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95ESN0802120A*	19,300	\$2,702
211242463	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712A*	19,000	\$2,660
211242453	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120A*	19,000	\$2,660
211242440	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ESU0401712A*	18,900	\$2,646
211242429	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95ESU0601716A*	19,100	\$2,674
211242419	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VSL0902120A*	19,000	\$2,660
211242410	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VSL0702120A*	19,300	\$2,702
211242401	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VSL0701716A*	19,000	\$2,660
211242392	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80VSL0451716A*	18,800	\$2,632
211242347	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122A*	18,900	\$2,646
211242337	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	19,400	\$2,716
211242326	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*95ESU0401712A*	18,900	\$2,646
211242316	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716A*	19,100	\$2,674
211242307	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712A*	19,000	\$2,660
211242298	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120A*	18,900	\$2,646
211242289	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120A*	19,000	\$2,660
211242280	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*96VSN0601714A*	18,900	\$2,646
211242216	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80ESU0601716A	19,300	\$2,702
211242204	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	19,100	\$2,674
211242193	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401712A*	19,100	\$2,674
211242182	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401410A*	19,400	\$2,716
211242171	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0801716A*	19,400	\$2,716
211242160	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601714A*	19,300	\$2,702
211242149	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0801716A*	19,100	\$2,674
211242138	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601714A*	19,100	\$2,674
211242127	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601412A*	18,800	\$2,632
211242115	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242103	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211242091	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242079	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	19,300	\$2,702
211242069	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601714A*	19,100	\$2,674
211242058	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0261410A*	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242048	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412A*	18,900	\$2,646
211242038	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410A*	18,900	\$2,646
211242027	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601412A*	19,300	\$2,702
211242016	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401712A*	19,300	\$2,702
211242005	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401410A*	19,400	\$2,716
211241995	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716A*	19,000	\$2,660
211241985	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716A*	19,100	\$2,674
211241975	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712A*	18,900	\$2,646
211241961	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412A*	19,100	\$2,674
211241950	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80ESU0401712A*	18,900	\$2,646
211241939	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95ESU0601716A*	19,100	\$2,674
211241929	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80VSL0701716A*	19,000	\$2,660
211241920	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451716A*	19,100	\$2,674
211241892	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241881	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*95ESU0401712A*	18,900	\$2,646
211241871	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716A*	19,100	\$2,674
211241862	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412A*	18,900	\$2,646
211241853	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712A*	18,900	\$2,646
211241844	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410A*	18,900	\$2,646
211241835	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601714A*	18,900	\$2,646
211241817	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412A*	18,800	\$2,632
211241780	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80ESU0601716A	19,300	\$2,702
211241768	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241757	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401712A*	19,100	\$2,674
211241746	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401410A*	19,400	\$2,716
211241735	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0801716A*	19,500	\$2,730
211241724	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601714A*	19,400	\$2,716
211241713	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0801716A*	19,100	\$2,674
211241702	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601714A*	19,200	\$2,688
211241691	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601412A*	18,900	\$2,646
211241679	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211241667	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211241655	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211241643	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	19,400	\$2,716
211241633	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601714A*	19,100	\$2,674
211241622	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0261410A*	18,900	\$2,646
211241612	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412A*	19,000	\$2,660
211241602	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241591	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601412A*	19,400	\$2,716
211241580	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401712A*	19,400	\$2,716
211241569	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401410A*	19,500	\$2,730
211241559	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716A*	19,100	\$2,674
211241549	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716A*	19,200	\$2,688
211241539	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712A*	19,000	\$2,660
211241525	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412A*	19,200	\$2,688
211241514	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80ESU0401712A*	19,000	\$2,660
211241503	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95ESU0601716A*	19,100	\$2,674
211241493	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80VSL0701716A*	19,100	\$2,674
211241484	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451716A*	19,200	\$2,688
211241456	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241445	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*95ESU0401712A*	19,000	\$2,660
211241435	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716A*	19,200	\$2,688
211241426	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412A*	19,000	\$2,660
211241417	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712A*	19,000	\$2,660
211241408	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410A*	19,000	\$2,660
211241399	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601714A*	18,900	\$2,646
211241381	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412A*	18,900	\$2,646
211241370	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241359	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*92ESN0401410A*	19,400	\$2,716
211241348	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*92ESN0601412A*	18,900	\$2,646
211241336	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	19,300	\$2,702
211241325	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*95ESN0261410A*	19,600	\$2,744
211241315	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412A*	19,000	\$2,660
211241305	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410A*	19,100	\$2,674
211241294	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*95ESN0601412A*	19,400	\$2,716
211241283	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*95ESN0401410A*	19,500	\$2,730
211241271	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*80VTL0451412A*	19,100	\$2,674
211241261	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412A*	19,000	\$2,660
211241252	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410A*	19,100	\$2,674
211241243	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412A*	19,200	\$2,688
211241117	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*92ESN0601412A*	18,500	\$2,590
211241038	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412A*	18,600	\$2,604
211240965	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712A*	18,600	\$2,604
211240940	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80ESU0401712A*	18,600	\$2,604
211240919	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*80VSL0701716A*	18,700	\$2,618
211240871	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*95ESU0401712A*	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240852	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412A*	18,600	\$2,604
211240843	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712A*	18,600	\$2,604
211240770	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80ESU0601716A	19,600	\$2,744
211240758	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240747	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401712A*	19,400	\$2,716
211240736	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401410A*	19,700	\$2,758
211240725	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0801716A*	19,700	\$2,758
211240714	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601714A*	19,600	\$2,744
211240703	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0801716A*	19,400	\$2,716
211240692	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601714A*	19,400	\$2,716
211240681	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601412A*	19,200	\$2,688
211240669	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0901714A*	19,500	\$2,730
211240657	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	19,500	\$2,730
211240645	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	19,400	\$2,716
211240633	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240623	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601714A*	19,400	\$2,716
211240612	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0261410A*	19,800	\$2,772
211240602	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412A*	19,300	\$2,702
211240592	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410A*	19,400	\$2,716
211240581	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601412A*	19,600	\$2,744
211240570	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401712A*	19,700	\$2,758
211240559	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401410A*	19,700	\$2,758
211240549	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716A*	19,300	\$2,702
211240539	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716A*	19,400	\$2,716
211240529	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712A*	19,300	\$2,702
211240515	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80VTL0451412A*	19,400	\$2,716
211240504	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80ESU0401712A*	19,300	\$2,702
211240493	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95ESU0601716A*	19,400	\$2,716
211240483	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80VSL0701716A*	19,300	\$2,702
211240474	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451716A*	19,400	\$2,716
211240446	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701716A*	19,700	\$2,758
211240435	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*95ESU0401712A*	19,300	\$2,702
211240425	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716A*	19,400	\$2,716
211240416	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412A*	19,300	\$2,702
211240407	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712A*	19,300	\$2,702
211240398	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410A*	19,400	\$2,716
211240389	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601714A*	19,500	\$2,730
211240371	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240360	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240349	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*92ESN0401410A*	19,700	\$2,758
211240338	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*92ESN0601412A*	19,600	\$2,744
211240326	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240315	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*95ESN0261410A*	19,800	\$2,772
211240305	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412A*	19,300	\$2,702
211240295	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410A*	19,400	\$2,716
211240284	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*95ESN0601412A*	19,600	\$2,744
211240273	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*95ESN0401410A*	19,700	\$2,758
211240261	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*80VTL0451412A*	19,400	\$2,716
211240251	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412A*	19,300	\$2,702
211240242	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410A*	19,400	\$2,716
211240233	KEEPRITE	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412A*	19,500	\$2,730
211239228	KEEPRITE	DLCURAH24ABK	FJMA4*24L*B*		19,200	\$2,688
213353744	KEEPRITE	DLCURAH18ABK	F5MA4*24L*B*		12,500	\$1,750
213353734	KEEPRITE	DLCURAH18ABK	F5MA4*18L*A*		12,800	\$1,792
213249254	KEEPRITE	DLCURAH18ABK	FEVA0024**+NAVA43601CK		12,300	\$1,722
213076391	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601716B*	12,400	\$1,736
212989329	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0601716A*	12,200	\$1,708
212989317	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0601716A*	12,300	\$1,722
212989305	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*95MSU0601716A*	12,200	\$1,708
212989293	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*95MSU0601716A*	12,000	\$1,680
212989281	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*95MSU0601716A*	12,300	\$1,722
212989269	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*95MSU0601716A*	12,100	\$1,694
212988837	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0401712A*	12,200	\$1,708
212988825	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0401712A*	12,500	\$1,750
212988813	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*95MSU0401712A*	12,200	\$1,708
212988801	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*95MSU0401712A*	12,000	\$1,680
212988789	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*95MSU0401712A*	12,300	\$1,722
212988777	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*95MSU0401712A*	12,100	\$1,694
212987563	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0801716A*	12,200	\$1,708
212987551	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0801716A*	12,500	\$1,750
212987539	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0801716A*	12,100	\$1,694
212987527	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96MSN0801716A*	12,200	\$1,708
212987515	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0801716A*	12,500	\$1,750
212987503	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0801716A*	12,300	\$1,722
212987085	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0601412A*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212987075	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0601412A*	12,200	\$1,708
212987065	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0601412A*	12,300	\$1,722
212987055	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0601412A*	12,300	\$1,722
212987045	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0601412A*	12,500	\$1,750
212987035	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0601412A*	12,200	\$1,708
212987025	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96MSN0601412A*	12,200	\$1,708
212987015	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96MSN0601412A*	12,000	\$1,680
212987005	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0601412A*	12,300	\$1,722
212986995	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96MSN0601412A*	12,300	\$1,722
212986985	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0601412A*	12,100	\$1,694
212986723	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401712A*	12,300	\$1,722
212986711	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401712A*	12,500	\$1,750
212986699	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401712A*	12,300	\$1,722
212986687	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96MSN0401712A*	12,100	\$1,694
212986675	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401712A*	12,300	\$1,722
212986663	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401712A*	12,100	\$1,694
212986387	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401410A*	12,300	\$1,722
212986375	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0401410A*	12,300	\$1,722
212986363	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401410A*	12,400	\$1,736
212986351	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0401410A*	12,400	\$1,736
212986339	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0401410A*	12,400	\$1,736
212986327	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401410A*	12,300	\$1,722
212986315	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96MSN0401410A*	12,300	\$1,722
212986303	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401410A*	12,400	\$1,736
212986291	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96MSN0401410A*	12,400	\$1,736
212986279	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401410A*	12,200	\$1,708
212985981	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0261410A*	12,300	\$1,722
212985971	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0261410A*	12,200	\$1,708
212985961	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0261410A*	12,300	\$1,722
212985951	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0261410A*	12,300	\$1,722
212985941	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0261410A*	12,500	\$1,750
212985931	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96MSN0261410A*	12,200	\$1,708
212985921	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96MSN0261410A*	12,200	\$1,708
212985911	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96MSN0261410A*	12,100	\$1,694
212985901	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96MSN0261410A*	12,300	\$1,722
212985891	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96MSN0261410A*	12,300	\$1,722
212985881	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96MSN0261410A*	12,100	\$1,694
212984765	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0801716A*	12,100	\$1,694

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984753	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0801716A*	12,500	\$1,750
212984741	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*92MSN0801716A*	12,400	\$1,736
212984729	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*92MSN0801716A*	12,200	\$1,708
212984717	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*92MSN0801716A*	12,500	\$1,750
212984705	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*92MSN0801716A*	12,300	\$1,722
212984225	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601714A*	12,300	\$1,722
212984213	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601714A*	12,400	\$1,736
212984201	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601714A*	12,300	\$1,722
212984189	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601714A*	12,200	\$1,708
212984177	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601714A*	12,400	\$1,736
212984165	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601714A*	12,200	\$1,708
212983735	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601412A*	12,200	\$1,708
212983725	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*92MSN0601412A*	12,200	\$1,708
212983714	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601412A*	12,400	\$1,736
212983704	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*92MSN0601412A*	12,400	\$1,736
212983694	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*92MSN0601412A*	12,400	\$1,736
212983684	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601412A*	12,200	\$1,708
212983674	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*92MSN0601412A*	12,300	\$1,722
212983664	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601412A*	12,000	\$1,680
212983654	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601412A*	12,400	\$1,736
212983644	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*92MSN0601412A*	12,400	\$1,736
212983634	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601412A*	12,100	\$1,694
212983313	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0401712A*	12,300	\$1,722
212983302	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0401712A*	12,400	\$1,736
212983291	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*92MSN0401712A*	12,200	\$1,708
212983280	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*92MSN0401712A*	12,100	\$1,694
212983269	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*92MSN0401712A*	12,300	\$1,722
212983258	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*92MSN0401712A*	12,200	\$1,708
212981888	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU1002120A*	12,300	\$1,722
212981876	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU1002120A*	12,600	\$1,764
212981864	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80MSU1002120A*	12,300	\$1,722
212981852	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80MSU1002120A*	12,100	\$1,694
212981840	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80MSU1002120A*	12,300	\$1,722
212981828	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80MSU1002120A*	12,200	\$1,708
212980009	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	12,300	\$1,722
212979997	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	12,400	\$1,736
212979985	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	12,300	\$1,722
212979973	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979961	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	12,400	\$1,736
212979949	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212978804	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978793	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	12,300	\$1,722
212978782	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978771	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978760	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701712A*	12,300	\$1,722
212978749	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701712A*	12,100	\$1,694
212978352	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	12,200	\$1,708
212978340	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	12,200	\$1,708
212978328	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	12,400	\$1,736
212978316	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978304	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978292	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	12,100	\$1,694
212978278	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	12,300	\$1,722
212978266	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212978254	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978242	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978230	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212977834	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	12,300	\$1,722
212977822	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	12,300	\$1,722
212977810	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	12,400	\$1,736
212977798	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977786	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977774	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977762	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977750	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	12,100	\$1,694
212977738	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	12,400	\$1,736
212977726	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977714	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0451412A*	12,200	\$1,708
212975845	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716B*	12,200	\$1,708
212975832	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716B*	12,500	\$1,750
212975819	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716B*	12,200	\$1,708
212975806	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716B*	12,000	\$1,680
212975793	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716B*	12,300	\$1,722
212975780	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716B*	12,100	\$1,694
212975493	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412B*	12,200	\$1,708
212975482	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412B*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975471	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412B*	12,400	\$1,736
212975460	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412B*	12,400	\$1,736
212975449	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412B*	12,400	\$1,736
212975438	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412B*	12,200	\$1,708
212975427	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412B*	12,200	\$1,708
212975416	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412B*	12,000	\$1,680
212975405	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412B*	12,300	\$1,722
212975394	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412B*	12,200	\$1,708
212975383	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412B*	12,100	\$1,694
212975130	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712B*	12,200	\$1,708
212975119	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712B*	12,500	\$1,750
212975108	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712B*	12,200	\$1,708
212975097	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712B*	12,100	\$1,694
212975086	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712B*	12,300	\$1,722
212975075	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712B*	12,100	\$1,694
212974751	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410B*	12,200	\$1,708
212974738	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410B*	12,200	\$1,708
212974725	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410B*	12,400	\$1,736
212974712	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410B*	12,400	\$1,736
212974699	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410B*	12,400	\$1,736
212974686	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410B*	12,200	\$1,708
212974673	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410B*	12,200	\$1,708
212974660	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410B*	12,100	\$1,694
212974647	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410B*	12,300	\$1,722
212974634	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410B*	12,400	\$1,736
212974621	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410B*	12,100	\$1,694
212973709	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716B*	12,200	\$1,708
212973699	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716B*	12,500	\$1,750
212973689	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716B*	12,200	\$1,708
212973679	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716B*	12,000	\$1,680
212973669	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716B*	12,300	\$1,722
212973659	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716B*	12,100	\$1,694
212973399	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412B*	12,200	\$1,708
212973389	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412B*	12,200	\$1,708
212973379	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412B*	12,400	\$1,736
212973369	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412B*	12,400	\$1,736
212973359	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412B*	12,400	\$1,736
212973349	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412B*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973339	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412B*	12,200	\$1,708
212973329	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412B*	12,000	\$1,680
212973319	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412B*	12,300	\$1,722
212973309	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412B*	12,200	\$1,708
212973299	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412B*	12,100	\$1,694
212973069	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712B*	12,200	\$1,708
212973059	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712B*	12,500	\$1,750
212973049	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712B*	12,200	\$1,708
212973039	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712B*	12,100	\$1,694
212973029	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712B*	12,300	\$1,722
212973019	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712B*	12,100	\$1,694
212972769	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410B*	12,200	\$1,708
212972759	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410B*	12,200	\$1,708
212972749	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410B*	12,400	\$1,736
212972739	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410B*	12,400	\$1,736
212972729	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410B*	12,400	\$1,736
212972719	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410B*	12,200	\$1,708
212972709	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410B*	12,200	\$1,708
212972699	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410B*	12,100	\$1,694
212972689	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410B*	12,300	\$1,722
212972679	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410B*	12,300	\$1,722
212972669	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410B*	12,100	\$1,694
212971497	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716B*	12,300	\$1,722
212971486	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716B*	12,400	\$1,736
212971475	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716B*	12,300	\$1,722
212971464	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716B*	12,100	\$1,694
212971453	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716B*	12,400	\$1,736
212971442	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716B*	12,200	\$1,708
212969603	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412B*	12,200	\$1,708
212969593	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412B*	12,200	\$1,708
212969583	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412B*	12,500	\$1,750
212969573	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412B*	12,500	\$1,750
212969563	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412B*	12,500	\$1,750
212969553	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412B*	12,400	\$1,736
212969543	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412B*	12,200	\$1,708
212969533	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412B*	12,500	\$1,750
212969523	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412B*	12,500	\$1,750
212969513	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412B*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211265044	KEEPRITE	DLCURAH18ABK	FVM4X24***L		12,400	\$1,736
211265021	KEEPRITE	DLCURAH18ABK	FM(C,U)4Z30**AL*		12,400	\$1,736
211265000	KEEPRITE	DLCURAH18ABK	FM(C,U)4Z24**AL*		12,500	\$1,750
211264978	KEEPRITE	DLCURAH18ABK	FM(C,U)4Z18**AL*		12,500	\$1,750
211264956	KEEPRITE	DLCURAH18ABK	FMA4X24**AL*		12,400	\$1,736
211264934	KEEPRITE	DLCURAH18ABK	FMA4X18**AL*		12,400	\$1,736
211264913	KEEPRITE	DLCURAH18ABK	FXM4X30**AL		12,400	\$1,736
211264890	KEEPRITE	DLCURAH18ABK	FXM4X24**AL		12,400	\$1,736
211264770	KEEPRITE	DLCURAH18ABK	FEM4P18**AL		12,300	\$1,722
211264746	KEEPRITE	DLCURAH18ABK	FJMA4*18L*A*		12,700	\$1,778
211264664	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0601716A	12,700	\$1,778
211264640	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	12,300	\$1,722
211264617	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401712A*	12,500	\$1,750
211264596	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401410A*	12,500	\$1,750
211264571	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601714A*	12,300	\$1,722
211264551	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601412A*	12,500	\$1,750
211264527	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	12,500	\$1,750
211264504	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	12,400	\$1,736
211264479	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	12,500	\$1,750
211264459	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601714A*	12,400	\$1,736
211264435	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0261410A*	12,600	\$1,764
211264414	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412A*	12,400	\$1,736
211264390	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410A*	12,300	\$1,722
211264330	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0601412A*	12,400	\$1,736
211264285	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401712A*	12,200	\$1,708
211264251	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401410A*	12,400	\$1,736
211264222	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716A*	12,200	\$1,708
211264184	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716A*	12,200	\$1,708
211264149	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712A*	12,400	\$1,736
211264118	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0451412A*	12,300	\$1,722
211264095	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0401712A*	12,700	\$1,778
211264075	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0701716A*	12,200	\$1,708
211264057	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451716A*	12,300	\$1,722
211264011	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESU0401712A*	12,400	\$1,736
211263992	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716A*	12,200	\$1,708
211263974	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412A*	12,400	\$1,736
211263956	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712A*	12,400	\$1,736
211263938	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263920	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601714A*	12,400	\$1,736
211263883	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412A*	12,400	\$1,736
211263860	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	12,300	\$1,722
211263837	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0401410A*	12,500	\$1,750
211263816	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0601412A*	12,500	\$1,750
211263791	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	12,500	\$1,750
211263768	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0261410A*	12,500	\$1,750
211263748	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412A*	12,400	\$1,736
211263727	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410A*	12,200	\$1,708
211263702	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0601412A*	12,400	\$1,736
211263679	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0401410A*	12,400	\$1,736
211263654	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*80VTL0451412A*	12,300	\$1,722
211263633	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412A*	12,400	\$1,736
211263615	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410A*	12,200	\$1,708
211263596	KEEPRITE	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412A*	12,400	\$1,736
211263519	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0601716A*	12,800	\$1,792
211263495	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	12,400	\$1,736
211263472	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401712A*	12,600	\$1,764
211263448	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401410A*	12,600	\$1,764
211263426	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0801716A*	12,900	\$1,806
211263403	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601714A*	12,400	\$1,736
211263380	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601412A*	12,600	\$1,764
211263355	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	12,600	\$1,764
211263330	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	12,900	\$1,806
211263305	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	12,600	\$1,764
211263284	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601714A*	12,500	\$1,750
211263259	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0261410A*	12,700	\$1,778
211263238	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412A*	12,500	\$1,750
211263217	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410A*	12,300	\$1,722
211263192	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0601412A*	12,500	\$1,750
211263170	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401712A*	12,300	\$1,722
211263147	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401410A*	12,500	\$1,750
211263132	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716A*	12,300	\$1,722
211263111	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716A*	12,300	\$1,722
211263090	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712A*	12,500	\$1,750
211263062	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0451412A*	12,400	\$1,736
211263040	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0401712A*	12,700	\$1,778
211263019	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0601716A*	12,900	\$1,806

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262999	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0701716A*	12,300	\$1,722
211262981	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451716A*	12,400	\$1,736
211262925	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0401712A*	12,400	\$1,736
211262906	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716A*	12,300	\$1,722
211262889	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412A*	12,500	\$1,750
211262872	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712A*	12,500	\$1,750
211262854	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410A*	12,300	\$1,722
211262836	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601714A*	12,400	\$1,736
211262800	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412A*	12,400	\$1,736
211262778	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262756	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0401410A*	12,600	\$1,764
211262733	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0601412A*	12,600	\$1,764
211262709	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262687	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0261410A*	12,700	\$1,778
211262667	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412A*	12,500	\$1,750
211262647	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410A*	12,300	\$1,722
211262623	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0601412A*	12,500	\$1,750
211262601	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0401410A*	12,500	\$1,750
211262576	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*80VTL0451412A*	12,400	\$1,736
211262557	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412A*	12,500	\$1,750
211262538	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410A*	12,300	\$1,722
211262520	KEEPRITE	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412A*	12,400	\$1,736
211262498	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262476	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0401410A*	12,600	\$1,764
211262454	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0601412A*	12,600	\$1,764
211262430	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262409	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0261410A*	12,700	\$1,778
211262388	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412A*	12,500	\$1,750
211262368	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410A*	12,300	\$1,722
211262344	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0601412A*	12,500	\$1,750
211262322	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0401410A*	12,500	\$1,750
211262298	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*80VTL0451412A*	12,400	\$1,736
211262279	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412A*	12,500	\$1,750
211262261	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410A*	12,300	\$1,722
211262243	KEEPRITE	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412A*	12,500	\$1,750
211262168	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	12,300	\$1,722
211262147	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401712A*	12,500	\$1,750
211262125	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401410A*	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262104	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601714A*	12,300	\$1,722
211262082	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601412A*	12,500	\$1,750
211262059	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	12,500	\$1,750
211262033	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	12,400	\$1,736
211262007	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261986	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601714A*	12,400	\$1,736
211261960	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*95ESN0261410A*	12,600	\$1,764
211261940	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412A*	12,500	\$1,750
211261925	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410A*	12,200	\$1,708
211261901	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*95ESN0601412A*	12,400	\$1,736
211261874	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401712A*	12,200	\$1,708
211261851	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401410A*	12,400	\$1,736
211261834	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716A*	12,200	\$1,708
211261820	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716A*	12,200	\$1,708
211261798	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712A*	12,400	\$1,736
211261771	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80VTL0451412A*	12,300	\$1,722
211261750	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80ESU0401712A*	12,700	\$1,778
211261729	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80VSL0701716A*	12,200	\$1,708
211261711	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451716A*	12,300	\$1,722
211261656	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*95ESU0401712A*	12,300	\$1,722
211261636	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716A*	12,200	\$1,708
211261618	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412A*	12,500	\$1,750
211261600	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712A*	12,400	\$1,736
211261582	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410A*	12,200	\$1,708
211261564	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601714A*	12,400	\$1,736
211261529	KEEPRITE	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451412A*	12,400	\$1,736
211261507	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211261485	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*92ESN0401410A*	12,500	\$1,750
211261463	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*92ESN0601412A*	12,500	\$1,750
211261439	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261418	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*95ESN0261410A*	12,500	\$1,750
211261398	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412A*	12,400	\$1,736
211261378	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410A*	12,200	\$1,708
211261355	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*95ESN0601412A*	12,400	\$1,736
211261334	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*95ESN0401410A*	12,400	\$1,736
211261310	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*80VTL0451412A*	12,300	\$1,722
211261290	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412A*	12,400	\$1,736
211261271	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410A*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261253	KEEPRITE	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412A*	12,400	\$1,736
211261166	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80ESU0601716A	12,600	\$1,764
211261126	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701412A*	12,100	\$1,694
211261078	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401712A*	12,400	\$1,736
211261053	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401410A*	12,400	\$1,736
211261040	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601714A*	12,200	\$1,708
211261027	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601412A*	12,400	\$1,736
211261013	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211260999	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211260984	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211260972	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601714A*	12,200	\$1,708
211260957	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*95ESN0261410A*	12,400	\$1,736
211260945	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412A*	12,300	\$1,722
211260933	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410A*	12,100	\$1,694
211260918	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*95ESN0601412A*	12,300	\$1,722
211260904	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401712A*	12,100	\$1,694
211260891	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401410A*	12,300	\$1,722
211260879	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716A*	12,000	\$1,680
211260867	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716A*	12,100	\$1,694
211260853	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712A*	12,300	\$1,722
211260836	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80VTL0451412A*	12,200	\$1,708
211260823	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80ESU0401712A*	12,500	\$1,750
211260809	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80VSL0701716A*	12,100	\$1,694
211260799	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451716A*	12,200	\$1,708
211260765	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*95ESU0401712A*	12,200	\$1,708
211260752	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716A*	12,100	\$1,694
211260741	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412A*	12,300	\$1,722
211260731	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712A*	12,300	\$1,722
211260720	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410A*	12,100	\$1,694
211260710	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601714A*	12,200	\$1,708
211260689	KEEPRITE	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412A*	12,200	\$1,708
211260645	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80ESU0601716A	12,800	\$1,792
211260631	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	12,400	\$1,736
211260619	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401712A*	12,600	\$1,764
211260608	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401410A*	12,600	\$1,764
211260596	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601714A*	12,400	\$1,736
211260583	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601412A*	12,600	\$1,764
211260568	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260554	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	12,900	\$1,806
211260540	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260528	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601714A*	12,400	\$1,736
211260513	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*95ESN0261410A*	12,700	\$1,778
211260502	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412A*	12,500	\$1,750
211260490	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410A*	12,300	\$1,722
211260475	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*95ESN0601412A*	12,500	\$1,750
211260462	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401712A*	12,300	\$1,722
211260449	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401410A*	12,500	\$1,750
211260437	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716A*	12,200	\$1,708
211260425	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716A*	12,300	\$1,722
211260412	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712A*	12,500	\$1,750
211260395	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80VTL0451412A*	12,400	\$1,736
211260382	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80ESU0401712A*	12,700	\$1,778
211260370	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80VSL0701716A*	12,300	\$1,722
211260359	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451716A*	12,400	\$1,736
211260325	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*95ESU0401712A*	12,400	\$1,736
211260313	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716A*	12,300	\$1,722
211260302	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412A*	12,500	\$1,750
211260292	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712A*	12,500	\$1,750
211260281	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410A*	12,300	\$1,722
211260270	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601714A*	12,400	\$1,736
211260249	KEEPRITE	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412A*	12,400	\$1,736
211260235	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211260222	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*92ESN0401410A*	12,600	\$1,764
211260209	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*92ESN0601412A*	12,600	\$1,764
211260194	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260180	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*95ESN0261410A*	12,600	\$1,764
211260170	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412A*	12,500	\$1,750
211260160	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410A*	12,300	\$1,722
211260146	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*95ESN0601412A*	12,500	\$1,750
211260130	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*95ESN0401410A*	12,500	\$1,750
211260116	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*80VTL0451412A*	12,400	\$1,736
211260104	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412A*	12,500	\$1,750
211260092	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410A*	12,300	\$1,722
211260078	KEEPRITE	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412A*	12,400	\$1,736
211260022	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80ESU0601716A	12,700	\$1,778
211260005	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701412A*	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211259989	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401712A*	12,400	\$1,736
211259974	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401410A*	12,400	\$1,736
211259958	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601714A*	12,200	\$1,708
211259942	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601412A*	12,500	\$1,750
211259925	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211259911	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211259895	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211259882	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601714A*	12,300	\$1,722
211259865	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*95ESN0261410A*	12,500	\$1,750
211259851	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412A*	12,400	\$1,736
211259840	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410A*	12,100	\$1,694
211259827	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*95ESN0601412A*	12,300	\$1,722
211259815	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401712A*	12,100	\$1,694
211259803	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401410A*	12,400	\$1,736
211259792	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716A*	12,000	\$1,680
211259781	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716A*	12,100	\$1,694
211259769	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712A*	12,300	\$1,722
211259752	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80VTL0451412A*	12,200	\$1,708
211259737	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80ESU0401712A*	12,600	\$1,764
211259724	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80VSL0701716A*	12,100	\$1,694
211259712	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451716A*	12,200	\$1,708
211259673	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*95ESU0401712A*	12,200	\$1,708
211259659	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716A*	12,100	\$1,694
211259647	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412A*	12,400	\$1,736
211259635	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712A*	12,300	\$1,722
211259622	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410A*	12,100	\$1,694
211259610	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601714A*	12,300	\$1,722
211259585	KEEPRITE	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412A*	12,300	\$1,722
211257341	KEEPRITE	DLCURAH18ABK	FJMA4*24L*B*		12,800	\$1,792
201835709	KEEPRITE	DLCSRAH12AAK	DLFSCAH12XAK		8,200	\$1,148
201835717	KEEPRITE	DLCSRAH18AAK	DLFSCAH18XAK		12,000	\$1,680
201835713	KEEPRITE	DLCSRAH12AAK	DLFSDAH12XAK		8,100	\$1,134
201835721	KEEPRITE	DLCSRAH24AAK	DLFSFAH24XAK		17,200	\$2,408
201835731	KEEPRITE	DLCLRAH48AAK	DLFLFAH48XAK		35,000	\$4,900
201835675	KEEPRITE	DLCSRAH18AAK	DLFSAH18XAK		11,900	\$1,666
201835677	KEEPRITE	DLCSRAH24AAK	DLFSAH24XAK		15,000	\$2,100
201835719	KEEPRITE	DLCSRAH24AAK	DLFSDAH24XAK		17,400	\$2,436
202463651	KEEPRITE	DLCPRAH24AAK	DLFPHAH24XAK		15,450	\$2,163

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
201835723	KEEPRITE	DLCSRAH24AAK	DLFSCAH24XAK		16,200	\$2,268
205921376	KEEPRITE	DLCSRAH24AAK	DLFSAAH24XAK		17,500	\$2,450
206350430	KEEPRITE	DLCSRBH12AAK	DLFSFAH12XAK		8,400	\$1,176
206350428	KEEPRITE	DLCSRBH12AAK	DLFSCAH12XAK		7,900	\$1,106
206396109	KEEPRITE	DLCSRAH12AAK	DLFSHBH12XAK		7,500	\$1,050
206350435	KEEPRITE	DLCSRBH24AAK	DLFSDAH24XAK		14,500	\$2,030
206350429	KEEPRITE	DLCSRBH12AAK	DLFSDAH12XAK		8,300	\$1,162
206188316	KEEPRITE	DLCSRBH24AAK	DLFSAAH24XAK		16,500	\$2,310
206350433	KEEPRITE	DLCSRBH18AAK	DLFSFAH18XAK		12,000	\$1,680
206350436	KEEPRITE	DLCSRBH24AAK	DLFSFAH24XAK		14,500	\$2,030
206350432	KEEPRITE	DLCSRBH18AAK	DLFSDAH18XAK		12,700	\$1,778
206350434	KEEPRITE	DLCSRBH24AAK	DLFSCAH24XAK		14,500	\$2,030
207643088	KEEPRITE	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643079	KEEPRITE	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207643085	KEEPRITE	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340
207643084	KEEPRITE	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207643087	KEEPRITE	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220
207643078	KEEPRITE	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643086	KEEPRITE	DLCMHBH36DAK	Heat pump without ducts		22,000	\$3,080
207643083	KEEPRITE	DLCMHBH48EAK	Heat pump without ducts		34,000	\$4,760
207643077	KEEPRITE	DLCMHBH30DAK	Heat pump without ducts		18,500	\$2,590
211222792	KEEPRITE	DLCURAH30ABK	FXM4X36**AL		23,200	\$3,248
211230822	KEEPRITE	DLCURAH36ABK	FEM4P42**AL		29,200	\$4,088
211230833	KEEPRITE	DLCURAH36ABK	FEM4P48**AL		29,400	\$4,116
211230845	KEEPRITE	DLCURAH36ABK	FEM4X42**BL		29,200	\$4,088
211230857	KEEPRITE	DLCURAH36ABK	FEM4X48**BL		29,400	\$4,116
211230879	KEEPRITE	DLCURAH36ABK	FMA4P36**AL*		29,800	\$4,172
211230911	KEEPRITE	DLCURAH36ABK	FXM4X36**AL		29,000	\$4,060
211719733	KEEPRITE	DLCURAH18ABK	FMA4P18**AL*		12,700	\$1,778
211264869	KEEPRITE	DLCURAH18ABK	FXM4X18**AL		12,300	\$1,722
211264846	KEEPRITE	DLCURAH18ABK	FEM4X24**CL		12,100	\$1,694
211264816	KEEPRITE	DLCURAH18ABK	FEM4X18**BL		12,300	\$1,722
211264792	KEEPRITE	DLCURAH18ABK	FEM4P24**AL		12,300	\$1,722
209852080	KEEPRITE	DLCURAH18ABK	DLFUAH18XAK		13,500	\$1,890
209852081	KEEPRITE	DLCURAH24ABK	DLFUAH24XAK		19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
209852083	KEEPRITE	DLCURAH48ABK	DLFUAAH48XAK		36,000	\$5,040
212978661	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978672	KEEPRITE	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701712A*	19,000	\$2,660
212978683	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701712A*	18,700	\$2,618
212978694	KEEPRITE	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701712A*	18,500	\$2,590
212978705	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701712A*	19,400	\$2,716
212978716	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701712A*	18,900	\$2,646
212978727	KEEPRITE	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701712A*	18,900	\$2,646
212978738	KEEPRITE	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701712A*	19,000	\$2,660
212979127	KEEPRITE	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701716A*	19,400	\$2,716
212986159	KEEPRITE	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401410A*	18,800	\$2,632
212986171	KEEPRITE	DLCURAH24ABK	EA*4X30L14A*	*96MSN0401410A*	19,200	\$2,688
212986183	KEEPRITE	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401410A*	19,200	\$2,688
212986195	KEEPRITE	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401410A*	19,200	\$2,688
212986207	KEEPRITE	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401410A*	18,800	\$2,632
212986219	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0401410A*	19,500	\$2,730
212986231	KEEPRITE	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401410A*	19,500	\$2,730
212986243	KEEPRITE	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0401410A*	19,200	\$2,688
207801572	KEEPRITE	DLCSRBH18AAK	DLFSDAH24XAK		12,600	\$1,764
207826603	KEEPRITE	DLCSRBH18AAK	DLFSABH18XBK		12,000	\$1,680
204456362	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L14A*+WALLCON	*80CTL0701412A*	21,000	\$2,940
204456371	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L17A*+WALLCON	*80CTL0451712A*	21,200	\$2,968
204456380	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L17A*+WALLCON	*80CTL0701716A*	21,000	\$2,940
204456389	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L17A*+WALLCON	*96CTN0601714A*	21,200	\$2,968
204456416	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L17A*+WALLCON	*97CMN0801714A*	21,200	\$2,968
204456425	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L17A*+WALLCON	*80CTL0701412A*	21,000	\$2,940
204456434	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L17A*+WALLCON	*80CTL0901716A*	21,000	\$2,940
204456443	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
204456452	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*80CTL0701716A*	20,600	\$2,884
204456461	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*96CTN0601714A*	20,800	\$2,912
204456470	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*96CTN0801714A*	20,600	\$2,884
204456488	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*97CMN0801714A*	20,800	\$2,912
204456497	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
204456506	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
204456515	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L14A*+WALLCON	*80CTL0701412A*	20,800	\$2,912
204456533	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L17A*+WALLCON	*80CTL0701716A*	20,800	\$2,912
204456542	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L17A*+WALLCON	*96CTN0601714A*	20,800	\$2,912
204456551	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L17A*+WALLCON	*96CTN0801714A*	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204456569	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L17A*+WALLCON	*97CMN0801714A*	20,800	\$2,912
204456578	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L17A*+WALLCON	*80CTL0701412A*	20,800	\$2,912
204456587	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L17A*+WALLCON	*80CTL0901716A*	20,800	\$2,912
204456596	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
204456605	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*80CTL0701716A*	20,800	\$2,912
204456614	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*96CTN0601714A*	20,800	\$2,912
204456623	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*96CTN0801714A*	20,800	\$2,912
204456632	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*97CMN0601714A*	20,800	\$2,912
204456641	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*97CMN0801714A*	20,800	\$2,912
204456650	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
204456659	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
204456668	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
204456677	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*80CTL0701716A*	20,800	\$2,912
204456704	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*96CTN0601714A*	20,800	\$2,912
204456713	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*96CTN0801714A*	20,800	\$2,912
204456722	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*97CMN0601714A*	20,800	\$2,912
204456743	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*97CMN0801714A*	20,800	\$2,912
204456768	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*97CMN1002122A*	20,600	\$2,884
204456786	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*96CTN1002122A*	20,600	\$2,884
204456795	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
204456813	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*97CMN0602120A*	20,800	\$2,912
204456822	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
204456831	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*80CTL0701716A*	20,800	\$2,912
204456840	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*96CTN0601714A*	20,800	\$2,912
204456850	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*96CTN0801714A*	20,800	\$2,912
204456859	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*97CMN0601714A*	20,800	\$2,912
204456868	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*97CMN0801714A*	20,800	\$2,912
204456877	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
204456886	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
204456910	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X24L14**+WALLCON	*80CTL0701412A*	21,000	\$2,940
204456973	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X24L17**+WALLCON	*80CTL0701412A*	21,000	\$2,940
204456982	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X24L17**+WALLCON	*80CTL0901716A*	21,000	\$2,940
204459059	KENMORE	(C,H,T)VH825GKA2*	EHD4X24AAL+WALLCON	*80CTL0701412A*	21,000	\$2,940
204459068	KENMORE	(C,H,T)VH825GKA2*	EHD4X24AAL+WALLCON	*80CTL0901716A*	21,000	\$2,940
204459239	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*80CTL0701412A*	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204459248	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*80CTL0901716A*	20,800	\$2,912
204459284	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*80CTL0701716A*	20,800	\$2,912
204459311	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*80CTL1352422A*	20,800	\$2,912
204459338	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*96CTN1202422A*	20,600	\$2,884
204459374	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*97CMN1002122A*	20,600	\$2,884
204459401	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*96CTN1002122A*	20,600	\$2,884
204459410	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*80CTL0701412A*	20,600	\$2,884
204459419	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*80CTL0901716A*	20,600	\$2,884
205750637	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
205750645	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*80CTL0701716A*	20,600	\$2,884
205750669	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*96CTN0601714A*	20,600	\$2,884
205750677	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*96CTN0801714A*	20,600	\$2,884
205750685	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*97CMN0601714A*	20,800	\$2,912
205750693	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*97CMN0801714A*	20,600	\$2,884
205750709	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*97CMN1002122A*	20,600	\$2,884
205750725	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*96CTN1002122A*	20,600	\$2,884
205750733	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
205750749	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*97CMN0602120A*	20,600	\$2,884
206133302	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L17A*+WALLCON	*80CSU0401712A*	21,000	\$2,940
206133312	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L17A*+WALLCON	*80CSU0601716A*	21,000	\$2,940
206133322	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*80CSU0401712A*	20,600	\$2,884
206133332	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*80CSU0601716A*	20,600	\$2,884
206133342	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L17A*+WALLCON	*80CSU0401712A*	20,800	\$2,912
206133352	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L17A*+WALLCON	*80CSU0601716A*	20,800	\$2,912
206133362	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*80CSU0401712A*	20,800	\$2,912
206133372	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*80CSU0601716A*	20,800	\$2,912
206133382	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*80CSU0401712A*	20,600	\$2,884
206133392	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*80CSU0601716A*	20,800	\$2,912
206133412	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*80CSU1002120A*	20,800	\$2,912
206133422	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*80CSU0401712A*	20,600	\$2,884
206133432	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*80CSU0601716A*	20,800	\$2,912
206133442	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*80CSU0401712A*	20,600	\$2,884
206133452	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*80CSU0601716A*	20,600	\$2,884
206133472	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*80CSU1002120A*	20,600	\$2,884
206133482	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X24L17**+WALLCON	*80CSU0401712A*	21,400	\$2,996
206133654	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*80CSU0401712A*	21,000	\$2,940
206133694	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*80CSU0401712A*	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206133704	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*80CSU0601716A*	20,800	\$2,912
206133734	KENMORE	(C,H,T)VH825GKA2*	EA*4X24L17A*+WALLCON	*95CSU0601716A*	21,200	\$2,968
206133744	KENMORE	(C,H,T)VH825GKA2*	EA*4X25L17A*+WALLCON	*95CSU0601716A*	20,800	\$2,912
206133754	KENMORE	(C,H,T)VH825GKA2*	EA*4X30L17A*+WALLCON	*95CSU0601716A*	20,800	\$2,912
206133764	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L17A*+WALLCON	*95CSU0601716A*	20,800	\$2,912
206133774	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*95CSU0601716A*	20,800	\$2,912
206133784	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
206133794	KENMORE	(C,H,T)VH825GKA2*	EA*4X36L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
206133804	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L17A*+WALLCON	*95CSU0601716A*	20,800	\$2,912
206133814	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*95CSU0601716A*	20,800	\$2,912
206133824	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
206133834	KENMORE	(C,H,T)VH825GKA2*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
206133960	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*95CSU0802120A*	21,000	\$2,940
206133990	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*95CSU0802120A*	20,600	\$2,884
206134000	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*95CSU1002122A*	20,600	\$2,884
206998291	KENMORE	(C,H,T)VH825GKA3*	EA*4X24L14A*+WALLCON	*80CTL0701412A*	21,000	\$2,940
206998292	KENMORE	(C,H,T)VH825GKA3*	EA*4X24L17A*+WALLCON	*80CTL0451712A*	21,200	\$2,968
206998293	KENMORE	(C,H,T)VH825GKA3*	EA*4X24L17A*+WALLCON	*80CTL0701716A*	21,000	\$2,940
206998298	KENMORE	(C,H,T)VH825GKA3*	EA*4X24L17A*+WALLCON	*80CTL0701412A*	21,000	\$2,940
206998299	KENMORE	(C,H,T)VH825GKA3*	EA*4X24L17A*+WALLCON	*80CTL0901716A*	21,000	\$2,940
206998300	KENMORE	(C,H,T)VH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
206998301	KENMORE	(C,H,T)VH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0701716A*	20,600	\$2,884
206998306	KENMORE	(C,H,T)VH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
206998307	KENMORE	(C,H,T)VH825GKA3*	EA*4X25L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
206998308	KENMORE	(C,H,T)VH825GKA3*	EA*4X30L14A*+WALLCON	*80CTL0701412A*	20,800	\$2,912
206998309	KENMORE	(C,H,T)VH825GKA3*	EA*4X30L17A*+WALLCON	*80CTL0451712A*	21,000	\$2,940
206998310	KENMORE	(C,H,T)VH825GKA3*	EA*4X30L17A*+WALLCON	*80CTL0701716A*	20,800	\$2,912
206998315	KENMORE	(C,H,T)VH825GKA3*	EA*4X30L17A*+WALLCON	*80CTL0701412A*	20,800	\$2,912
206998316	KENMORE	(C,H,T)VH825GKA3*	EA*4X30L17A*+WALLCON	*80CTL0901716A*	20,800	\$2,912
206998317	KENMORE	(C,H,T)VH825GKA3*	EA*4X36L17A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
206998318	KENMORE	(C,H,T)VH825GKA3*	EA*4X36L17A*+WALLCON	*80CTL0701716A*	20,800	\$2,912
206998323	KENMORE	(C,H,T)VH825GKA3*	EA*4X36L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
206998324	KENMORE	(C,H,T)VH825GKA3*	EA*4X36L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
206998325	KENMORE	(C,H,T)VH825GKA3*	EA*4X36L21A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
206998326	KENMORE	(C,H,T)VH825GKA3*	EA*4X36L21A*+WALLCON	*80CTL0701716A*	20,800	\$2,912
206998337	KENMORE	(C,H,T)VH825GKA3*	EA*4X36L21A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
206998340	KENMORE	(C,H,T)VH825GKA3*	EA*4X37L17A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
206998341	KENMORE	(C,H,T)VH825GKA3*	EA*4X37L17A*+WALLCON	*80CTL0701716A*	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206998346	KENMORE	(C,H,T)VH825GKA3*	EA*4X37L17A*+WALLCON	*80CTL0701412A*	20,600	\$2,884
206998347	KENMORE	(C,H,T)VH825GKA3*	EA*4X37L17A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
206998348	KENMORE	(C,H,T)VH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
206998349	KENMORE	(C,H,T)VH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0701716A*	20,600	\$2,884
206998360	KENMORE	(C,H,T)VH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
206998363	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X24L14**+WALLCON	*80CTL0701412A*	21,000	\$2,940
206998365	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X24L17**+WALLCON	*80CTL0701716A*	21,200	\$2,968
206998370	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X24L17**+WALLCON	*80CTL0701412A*	21,000	\$2,940
206998371	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X24L17**+WALLCON	*80CTL0901716A*	21,000	\$2,940
206998372	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X30L14**+WALLCON	*80CTL0701412A*	20,800	\$2,912
206998374	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X30L17**+WALLCON	*80CTL0701716A*	20,800	\$2,912
206998379	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X30L17**+WALLCON	*80CTL0701412A*	20,800	\$2,912
206998380	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X30L17**+WALLCON	*80CTL0901716A*	20,800	\$2,912
206998382	KENMORE	(C,H,T)VH825GKA3*	EN(A,D,W)4X36L17**+WALLCON	*80CTL0701716A*	20,800	\$2,912
206998387	KENMORE	(C,H,T)VH825GKA3*	EN(A,D,W)4X36L17**+WALLCON	*80CTL0701412A*	20,800	\$2,912
206998388	KENMORE	(C,H,T)VH825GKA3*	EN(A,D,W)4X36L17**+WALLCON	*80CTL0901716A*	20,800	\$2,912
206998390	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X36L21**+WALLCON	*80CTL0701716A*	20,800	\$2,912
206998401	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X36L21**+WALLCON	*80CTL0901716A*	20,800	\$2,912
206998435	KENMORE	(C,H,T)VH825GKA3*	EHD4X24AAL+WALLCON	*80CTL0701412A*	21,000	\$2,940
206998436	KENMORE	(C,H,T)VH825GKA3*	EHD4X24AAL+WALLCON	*80CTL0901716A*	21,000	\$2,940
206998454	KENMORE	(C,H,T)VH825GKA3*	EHD4X30AAL+WALLCON	*80CTL0701412A*	20,800	\$2,912
206998455	KENMORE	(C,H,T)VH825GKA3*	EHD4X30AAL+WALLCON	*80CTL0901716A*	20,800	\$2,912
206998459	KENMORE	(C,H,T)VH825GKA3*	EHD4X36AAL+WALLCON	*80CTL0701716A*	20,800	\$2,912
206998462	KENMORE	(C,H,T)VH825GKA3*	EHD4X36AAL+WALLCON	*80CTL1352422A*	20,800	\$2,912
206998473	KENMORE	(C,H,T)VH825GKA3*	EHD4X36AAL+WALLCON	*80CTL0701412A*	20,600	\$2,884
206998474	KENMORE	(C,H,T)VH825GKA3*	EHD4X36AAL+WALLCON	*80CTL0901716A*	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206361895	KENMORE	DLCSRBH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361897	KENMORE	DLCSRBH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361896	KENMORE	DLCSRBH18AAK	DLFSHBH18XAK		11,100	\$1,554
210857447	KENMORE	DLCSRBH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857448	KENMORE	DLCSRBH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132696	KENMORE	DLCSRBH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948196	KENMORE	DLCSRBH12AAK	DLFSFBH12XAK		10,200	\$1,428
207683362	KENMORE	DLCSRBH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447655	KENMORE	DLCSRBH24AAK	DLFSHCH24XAK		21,200	\$2,968
208447659	KENMORE	DLCSRBH18AAK	DLFSHCH18XAK		15,000	\$2,100
208447654	KENMORE	DLCSRBH12AAK	DLFSHCH12XAK		10,000	\$1,400
206997499	KENMORE	(C,H,T)VH848GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	36,000	\$5,040
206997506	KENMORE	(C,H,T)VH848GKA2*	EA*4X60L24A*+WALLCON	*96CTN1002122A*	36,000	\$5,040
206997503	KENMORE	(C,H,T)VH848GKA2*	EA*4X60L24A*+WALLCON	*97CMN1002122A*	36,000	\$5,040
206997610	KENMORE	(C,H,T)VH848GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	36,000	\$5,040
206997713	KENMORE	(C,H,T)VH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0701716A*	31,600	\$4,424
211132732	KENMORE	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
206997911	KENMORE	(C,H,T)VH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206998530	KENMORE	(C,H,T)VH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
206997729	KENMORE	(C,H,T)VH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	31,400	\$4,396
206998531	KENMORE	(C,H,T)VH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
211132694	KENMORE	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
206997698	KENMORE	(C,H,T)VH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206997709	KENMORE	(C,H,T)VH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206997905	KENMORE	(C,H,T)VH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206997906	KENMORE	(C,H,T)VH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	31,600	\$4,424
206997657	KENMORE	(C,H,T)VH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206997541	KENMORE	(C,H,T)VH848GKA2*	EN(A,D)4X48L24**+WALLCON	*96CTN1202422A*	37,200	\$5,208
206997563	KENMORE	(C,H,T)VH848GKA2*	EHD4X48AAL+WALLCON	*80CTL1352422A*	37,200	\$5,208
206997601	KENMORE	(C,H,T)VH848GKA2*	EHD4X48AAL+WALLCON	*80CSU0802120A*	37,200	\$5,208
206997659	KENMORE	(C,H,T)VH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206997668	KENMORE	(C,H,T)VH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206997899	KENMORE	(C,H,T)VH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206997910	KENMORE	(C,H,T)VH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206997715	KENMORE	(C,H,T)VH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206997900	KENMORE	(C,H,T)VH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	31,800	\$4,452
206997724	KENMORE	(C,H,T)VH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206997728	KENMORE	(C,H,T)VH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206997908	KENMORE	(C,H,T)VH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206997909	KENMORE	(C,H,T)VH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206997700	KENMORE	(C,H,T)VH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
216591920	KENMORE	HH836E2S11	CTF36C5CDS1	Z8ES100C20SMPS1	28,600	\$4,004
216591724	KENMORE	HH836E2S11	CTF36C5CDS1	Z8ES080C20SMPS1	29,400	\$4,116
216591823	KENMORE	HH836E2S11	CTM36C5CDS1	Z8ES100C20SMPS1	28,600	\$4,004
216591867	KENMORE	HH836E2S11	CTF36C5CDS1	Z8ES120C16SMPS1	28,000	\$3,920
216591679	KENMORE	HH836E2S11	CTF36C5CDS1	Z8ES120C20SMPS1	28,600	\$4,004
216726270	KENMORE	HH836E2S11	CTM36C5CDS1	Z9ES080C20SMPS1	28,600	\$4,004
216591917	KENMORE	HH836E2S11	CTM36C5CDS1	Z8ES120C20SMPS1	28,600	\$4,004
216591880	KENMORE	HH836E2S11	CTM36C5CDS1	Z8ES080C16SMPS1	27,600	\$3,864
216591919	KENMORE	HH836E2S11	CTF36C5CDS1	Z8ES080C16SMPS1	27,600	\$3,864
216591879	KENMORE	HH836E2S11	CTM36C5CDS1	Z8ES120C16SMPS1	28,000	\$3,920
216591697	KENMORE	HH836E2S11	CTM36C5CDS1	Z8ES080C20SMPS1	28,400	\$3,976
216591902	KENMORE	HH836E2S11	CTM36C5CDS1	Z8ES100C16SMPS1	28,200	\$3,948
216591885	KENMORE	HH836E2S11	CTF36C5CDS1	Z9ET100C20SMPS1	27,600	\$3,864
216591690	KENMORE	HH836E2S11	CTF36C5CDS1	Z8ES100C16SMPS1	28,200	\$3,948
216591909	KENMORE	HH836E2S11	CTF36C5CDS1	Z9ET080C16SMPS1	27,600	\$3,864
216591910	KENMORE	HH836E2S11	CTM36C5CDS1	Z9ET080C16SMPS1	27,600	\$3,864
215324482	KENMORE	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
216591568	KENMORE	HH860E2S11	JSE60D5CJ2SS1		37,200	\$5,208
216591570	KENMORE	HH860E2S11	JSC60D5CJ2SS1		37,200	\$5,208
216591567	KENMORE	HH860E2S11	JHC60D5CJ2SS1		37,200	\$5,208
216591188	KENMORE	HH824E2S11	CTU30B5XCS1+JME12B2SN 1+TXV		17,500	\$2,450
216591185	KENMORE	HH824E2S11	CTF30B5ACS1+JME12B2SN 1		17,500	\$2,450
216591581	KENMORE	HH824E2S11	CTM30B5ACS1	Z8ES100B12SMPS1	17,700	\$2,478
216591927	KENMORE	HH836E2S11	CTM36B5CDS1	Z9ET060B12SMPS1	28,200	\$3,948
216591871	KENMORE	HH836E2S11	CTU36B5XDS1+JME12B2SN 1+TXV		26,800	\$3,752
216591870	KENMORE	HH836E2S11	CTF36B5CDS1+JME12B2SN 1		26,800	\$3,752
216591901	KENMORE	HH836E2S11	CTM36B5CDS1	Z8ES100B12SMPS1	27,000	\$3,780
216726252	KENMORE	HH836E2S11	CTM48C5CFS1	Z9ES080C16SMPS1	26,400	\$3,696
216591630	KENMORE	HH836E2S11	CTM48C5CFS1+JME16C2S N1		25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216591891	KENMORE	HH836E2S11	CTM48C5CFS1+JME12C2S N1		25,800	\$3,612
216591680	KENMORE	HH860E2S11	CTM60C5CHS1	Z9ET100C20SMPS1	37,400	\$5,236
216591785	KENMORE	HH860E2S11	CTM60D5CHS1+JME18D2S N1		36,600	\$5,124
216591197	KENMORE	HH860E2S11	CTM60C5CGS1	Z8ES100C20SMPS1	32,800	\$4,592
216591502	KENMORE	HH860E2S11	CTM60C5CGS1	Z8ES120C16SMPS1	32,200	\$4,508
216591657	KENMORE	HH824E2S11	JHE24B5AC2SS1		18,600	\$2,604
216591836	KENMORE	HH836E2S11	CTU36B5XDS1+TXV	Z8ET080B12LMPS1	26,800	\$3,752
216591835	KENMORE	HH836E2S11	CTF36B5CDS1	Z8ET080B12LMPS1	26,800	\$3,752
216591699	KENMORE	HH836E2S11	CTU36B5XDS1+TXV	Z8ES080B12SMPS1	26,800	\$3,752
216591698	KENMORE	HH836E2S11	CTF36B5CDS1	Z8ES080B12SMPS1	26,800	\$3,752
216591863	KENMORE	HH836E2S11	CTU36B5XDS1+TXV	Z8ES100B12SMPS1	27,200	\$3,808
216591862	KENMORE	HH836E2S11	CTF36B5CDS1	Z8ES100B12SMPS1	27,200	\$3,808
216591703	KENMORE	HH836E2S11	CTF36C5CDS1+JME16C2SN 1		28,200	\$3,948
216591759	KENMORE	HH836E2S11	JHC36B5CD2SS1		26,600	\$3,724
216591320	KENMORE	HH860E2S11	CTU60D5XHS1+TXV	Z8ES130D20SMPS1	37,000	\$5,180
216591317	KENMORE	HH860E2S11	CTF60D5CHS1	Z8ES130D20SMPS1	37,000	\$5,180
216591592	KENMORE	HH860E2S11	CTU60C5XGS1+TXV	Z8ES120C16SMPS1	32,000	\$4,480
216591591	KENMORE	HH860E2S11	CTF60C5CGS1	Z8ES120C16SMPS1	32,000	\$4,480
216591104	KENMORE	HH860E2S11	JHE60C5CH2SS1		37,000	\$5,180
216591566	KENMORE	HH860E2S11	JHE60D5CJ2SS1		37,400	\$5,236
216591721	KENMORE	HH824E2S11	CTM30B5ACS1	Z8ES080B12SMPS1	17,700	\$2,478
216591194	KENMORE	HH824E2S11	CTU30B5XCS1+TXV	Z8ES080B12SMPS1	17,700	\$2,478
216591191	KENMORE	HH824E2S11	CTF30B5ACS1	Z8ES080B12SMPS1	17,700	\$2,478
216591713	KENMORE	HH836E2S11	CTU36B5XDS1+TXV	Z9ET060B12SMPS1	28,200	\$3,948
216591712	KENMORE	HH836E2S11	CTF36B5CDS1	Z9ET060B12SMPS1	28,200	\$3,948
216726258	KENMORE	HH836E2S11	CTM36B5CDS1	Z9ES080B12SMPS1	27,600	\$3,864
216591907	KENMORE	HH836E2S11	CTM48C5CFS1	Z8ES120C20SMPS1	26,200	\$3,668
216591735	KENMORE	HH836E2S11	CTM48C5CFS1	Z8ES080C16SMPS1	26,200	\$3,668
216591732	KENMORE	HH836E2S11	CTU48C5XFS1+JME16C2SN 1+TXV		25,800	\$3,612
216591731	KENMORE	HH836E2S11	CTF48C5CFS1+JME16C2SN 1		25,800	\$3,612
216591793	KENMORE	HH836E2S11	CTU48C5XFS1+TXV	Z8ES100C20SMPS1	26,000	\$3,640
216591792	KENMORE	HH836E2S11	CTF48C5CFS1	Z8ES100C20SMPS1	26,000	\$3,640
216591805	KENMORE	HH836E2S11	JHE36C5CD2SS1		27,200	\$3,808

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216591754	KENMORE	HH860E2S11	CTM60D5CHS1	Z9ET120D20SMPS1	38,000	\$5,320
216591771	KENMORE	HH860E2S11	CTM60C5CHS1+JME16C2S N1		36,600	\$5,124
216591073	KENMORE	HH860E2S11	CTU60D5XHS1+JME18D2SN 1+TXV		36,600	\$5,124
216591071	KENMORE	HH860E2S11	CTF60D5CHS1+JME18D2SN 1		36,600	\$5,124
216591784	KENMORE	HH860E2S11	CTF60C5CHS1+JME16C2SN 1		36,600	\$5,124
216591043	KENMORE	HH860E2S11	CTU60D5XGS1+JME18D2S N1+TXV		34,400	\$4,816
216591042	KENMORE	HH860E2S11	CTF60D5CGS1+JME18D2SN 1		34,400	\$4,816
216591580	KENMORE	HH860E2S11	CTM60D5CJS1	Z8ES130D20SMPS1	38,000	\$5,320
216591718	KENMORE	HH860E2S11	CTM60D5CJS1+JME18D2SN 1		37,200	\$5,208
216591653	KENMORE	HH860E2S11	JHE60D5CH2SS1		36,800	\$5,152
216591656	KENMORE	HH824E2S11	CTU30B5XCS1+JME08B2SN 1+TXV		17,600	\$2,464
216591655	KENMORE	HH824E2S11	CTF30B5ACS1+JME08B2SN 1		17,600	\$2,464
216591884	KENMORE	HH836E2S11	CTM36B5CDS1	Z9ET080B12SMPS1	28,000	\$3,920
216591734	KENMORE	HH836E2S11	CTU48C5XFS1+TXV	Z8ES080C16SMPS1	26,200	\$3,668
216591733	KENMORE	HH836E2S11	CTF48C5CFS1	Z8ES080C16SMPS1	26,200	\$3,668
216591598	KENMORE	HH860E2S11	CTF60C5CHS1	Z9ET100C20SMPS1	37,400	\$5,236
216591068	KENMORE	HH860E2S11	CTM60C5CHS1	Z8ES120C20SMPS1	36,600	\$5,124
216726251	KENMORE	HH860E2S11	CTM60C5CGS1	Z9ES100C16SMPS1	33,600	\$4,704
216591719	KENMORE	HH860E2S11	CTF60D5CJS1	Z8ES130D20SMPS1	37,600	\$5,264
216591388	KENMORE	HH824E2S11	CTU30B5XCS1+TXV	Z8ET080B12LMPS1	17,800	\$2,492
216591385	KENMORE	HH824E2S11	CTF30B5ACS1	Z8ET080B12LMPS1	17,800	\$2,492
216591807	KENMORE	HH824E2S11	CTM30B5ACS1+JME12B2SN 1		17,600	\$2,464
216591929	KENMORE	HH836E2S11	CTU36B5XDS1+TXV	Z9ET080B12SMPS1	28,000	\$3,920
216591928	KENMORE	HH836E2S11	CTF36B5CDS1	Z9ET080B12SMPS1	28,000	\$3,920
216591883	KENMORE	HH836E2S11	CTF36C5CDS1	Z9ET100C16SMPS1	26,800	\$3,752
216726263	KENMORE	HH836E2S11	CTF36C5CDS1	Z9ES080C16SMPS1	27,000	\$3,780
216591861	KENMORE	HH836E2S11	CTF36C5CDS1+JME12C2SN 1		27,000	\$3,780
216591783	KENMORE	HH836E2S11	CTM48C5CFS1	Z8ES120C16SMPS1	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216591582	KENMORE	HH824E2S11	CTM30B5ACS1+JME08B2SN1		17,700	\$2,478
216591720	KENMORE	HH824E2S11	CTM30B5ACS1	Z8ET080B12LMPS1	17,800	\$2,492
216591908	KENMORE	HH836E2S11	CTM36C5CDS1	Z9ET100C16SMPS1	28,000	\$3,920
216591809	KENMORE	HH836E2S11	CTM36C5CDS1+JME12C2SN1		26,800	\$3,752
216591704	KENMORE	HH836E2S11	JHE36B5CD2SS1		28,400	\$3,976
216591629	KENMORE	HH836E2S11	CTU48C5XFS1+TXV	Z8ES120C16SMPS1	25,800	\$3,612
216591628	KENMORE	HH836E2S11	CTF48C5CFS1	Z8ES120C16SMPS1	25,800	\$3,612
216591730	KENMORE	HH836E2S11	JHC42C5CF2SS1		25,800	\$3,612
216591323	KENMORE	HH860E2S11	CTM60D5CHS1	Z8ES130D20SMPS1	37,000	\$5,180
216591314	KENMORE	HH860E2S11	CTM60C5CHS1	Z8ES100C20SMPS1	36,600	\$5,124
216591659	KENMORE	HH860E2S11	CTU60D5XGS1+TXV	Z8ES130D20SMPS1	32,400	\$4,536
216591658	KENMORE	HH860E2S11	CTF60D5CGS1	Z8ES130D20SMPS1	32,400	\$4,536
216726267	KENMORE	HH860E2S11	CTU60C5XGS1+TXV	Z9ES100C20SMPS1	33,800	\$4,732
216726266	KENMORE	HH860E2S11	CTF60C5CGS1	Z9ES100C20SMPS1	33,800	\$4,732
216591395	KENMORE	HH860E2S11	CTM60D5CGS1+JME18D2SN1		32,000	\$4,480
216620839	KENMORE	HH860E2S11	CTF60D5CJS1	Z9ES120D20SMPS1	37,600	\$5,264
216620838	KENMORE	HH824E2S11	CTM30B5ACS1	Z9ES060B12SMPS1	17,900	\$2,506
216620822	KENMORE	HH860E2S11	CTM60C5CGS1	Z9ES080C20SMPS1	32,600	\$4,564
216620819	KENMORE	HH836E2S11	CTM36B5CDS1	Z9ES060B12SMPS1	27,400	\$3,836
216620818	KENMORE	HH836E2S11	CTF36C5CDS1	Z9ES100C20SMPS1	29,600	\$4,144
216620817	KENMORE	HH860E2S11	CTM60C5CHS1	Z9ES080C20SMPS1	37,400	\$5,236
216620816	KENMORE	HH824E2S11	CTM36B5ADS1	Z9ES060B12SMPS1	18,300	\$2,562
216620798	KENMORE	HH836E2S11	CTF36C5CDS1	Z9ES100C16SMPS1	29,200	\$4,088
216620797	KENMORE	HH836E2S11	CTM48C5CFS1	Z9ES080C20SMPS1	26,200	\$3,668
216620796	KENMORE	HH860E2S11	CTU60D5XHS1+TXV	Z9ES120D20SMPS1	37,000	\$5,180
216620795	KENMORE	HH860E2S11	CTF60D5CHS1	Z9ES120D20SMPS1	37,000	\$5,180
216620794	KENMORE	HH860E2S11	CTM60D5CJS1	Z9ES120D20SMPS1	38,000	\$5,320
216620780	KENMORE	HH860E2S11	CTM60C5CGS1	Z9ES100C20SMPS1	34,600	\$4,844
216620775	KENMORE	HH836E2S11	CTM36C5CDS1	Z9ES100C16SMPS1	29,200	\$4,088
216620778	KENMORE	HH836E2S11	CTU48C5XFS1+TXV	Z9ES080C20SMPS1	26,200	\$3,668
216620774	KENMORE	HH836E2S11	CTF48C5CFS1	Z9ES080C20SMPS1	26,200	\$3,668
216620773	KENMORE	HH860E2S11	CTF60C5CHS1	Z9ES080C20SMPS1	37,200	\$5,208
216620772	KENMORE	HH824E2S11	CTU36B5XDS1+TXV	Z9ES060B12SMPS1	18,400	\$2,576
216620771	KENMORE	HH824E2S11	CTF36B5ADS1	Z9ES060B12SMPS1	18,400	\$2,576
216620756	KENMORE	HH860E2S11	CTU60D5XGS1+TXV	Z9ES120D20SMPS1	34,400	\$4,816

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216620755	KENMORE	HH860E2S11	CTF60D5CGS1	Z9ES120D20SMPS1	34,400	\$4,816
216620749	KENMORE	HH836E2S11	CTF36C5CDS1	Z9ES080C20SMPS1	28,600	\$4,004
216620748	KENMORE	HH860E2S11	CTM60D5CHS1	Z9ES120D20SMPS1	37,000	\$5,180
216620747	KENMORE	HH824E2S11	CTU30B5XCS1+TXV	Z9ES060B12SMPS1	17,900	\$2,506
216620746	KENMORE	HH824E2S11	CTF30B5ACS1	Z9ES060B12SMPS1	17,900	\$2,506
216620732	KENMORE	HH860E2S11	CTU60C5XGS1+TXV	Z9ES080C16SMPS1	33,200	\$4,648
216620731	KENMORE	HH860E2S11	CTF60C5CGS1	Z9ES080C16SMPS1	33,200	\$4,648
216620728	KENMORE	HH836E2S11	CTU36B5XDS1+TXV	Z9ES060B12SMPS1	27,600	\$3,864
216620727	KENMORE	HH836E2S11	CTF36B5CDS1	Z9ES060B12SMPS1	27,600	\$3,864
216620726	KENMORE	HH836E2S11	CTU36B5XDS1+TXV	Z9ES080B12SMPS1	27,800	\$3,892
216620725	KENMORE	HH836E2S11	CTF36B5CDS1	Z9ES080B12SMPS1	27,800	\$3,892
216620724	KENMORE	HH860E2S11	CTF60C5CHS1	Z9ES100C20SMPS1	37,200	\$5,208
216620723	KENMORE	HH824E2S11	CTU30B5XCS1+TXV	Z9ES080B12SMPS1	17,900	\$2,506
216620722	KENMORE	HH824E2S11	CTF30B5ACS1	Z9ES080B12SMPS1	17,900	\$2,506
216620710	KENMORE	HH860E2S11	CTM60D5CGS1	Z9ES120D20SMPS1	34,400	\$4,816
216620705	KENMORE	HH836E2S11	CTM36C5CDS1	Z9ES080C16SMPS1	27,600	\$3,864
216620704	KENMORE	HH860E2S11	CTM60C5CHS1	Z9ES100C20SMPS1	37,200	\$5,208
216591626	KENMORE	HH836E2S11	JHC36C5CD2SS1		26,600	\$3,724
216591132	KENMORE	HH824E2S11	JHC24B5AC2SS1		18,400	\$2,576
216591762	KENMORE	HH836E2S11	JHE42C5CF2SS1		25,800	\$3,612
216591772	KENMORE	HH824E2S11	JHE36B5AD2SS1		18,200	\$2,548
216591841	KENMORE	HH824E2S11	JHC36B5AD2SS1		18,400	\$2,576
216591509	KENMORE	HH824E2S11	JHE30B5AD2SS1		17,700	\$2,478
215323730	KENMORE	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215324493	KENMORE	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324492	KENMORE	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324489	KENMORE	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324487	KENMORE	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324485	KENMORE	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324484	KENMORE	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324483	KENMORE	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324480	KENMORE	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324479	KENMORE	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324478	KENMORE	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324477	KENMORE	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215413284	KENMORE	D5CPRAH18AA	D5FPHAH18XAK		19,300	\$2,702
215413283	KENMORE	D5CPRAH12AAK	D5FPHAH12XAK		11,000	\$1,540

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357369	KENMORE	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357368	KENMORE	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357367	KENMORE	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215324488	KENMORE	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324481	KENMORE	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215357395	KENMORE	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357378	KENMORE	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357377	KENMORE	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357376	KENMORE	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357375	KENMORE	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357374	KENMORE	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357373	KENMORE	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357372	KENMORE	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357371	KENMORE	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357370	KENMORE	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357366	KENMORE	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357365	KENMORE	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357364	KENMORE	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357360	KENMORE	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357359	KENMORE	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357358	KENMORE	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324530	KENMORE	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324528	KENMORE	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324527	KENMORE	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324525	KENMORE	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324524	KENMORE	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324491	KENMORE	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324486	KENMORE	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324531	KENMORE	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324529	KENMORE	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324526	KENMORE	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324476	KENMORE	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215319043	KENMORE	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215319042	KENMORE	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215319041	KENMORE	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215319051	KENMORE	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215319049	KENMORE	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215319039	KENMORE	D5CURAH48AAK	D5FUAH48XAK		32,400	\$4,536
215319036	KENMORE	D5CURAH24AAK	D5FUAH24XAK		20,000	\$2,800
215319034	KENMORE	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215319033	KENMORE	D5CUHAH60AAK	D5FUAH60XAK		45,000	\$6,300
215319032	KENMORE	D5CUHAH48AAK	D5FUAH48XAK		37,000	\$5,180
215319031	KENMORE	D5CUHAH36AAK	D5FUAH36XAK		31,800	\$4,452
215319030	KENMORE	D5CUHAH30AAK	D5FUAH30XAK		23,800	\$3,332
215319029	KENMORE	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215319028	KENMORE	D5CUHAH24AAK	D5FUAH24XAK		20,000	\$2,800
215319027	KENMORE	D5CUHAH18AAK	D5FUAH18XAK		15,000	\$2,100
215319050	KENMORE	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215319046	KENMORE	D5CSAH33AAK	D5FSAH36XAK		27,400	\$3,836
215319045	KENMORE	D5CSAH24AAK	D5FSAH24XAK		16,900	\$2,366
215319044	KENMORE	D5CSAH18AAK	D5FSAH18XAK		14,000	\$1,960
210470570	KENMORE	(C,H,T)VH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL1352422A*	31,200	\$4,368
210470537	KENMORE	(C,H,T)VH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470383	KENMORE	(C,H,T)VH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470526	KENMORE	(C,H,T)VH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210473246	KENMORE	(C,H,T)VH825GKA3*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210470394	KENMORE	(C,H,T)VH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470504	KENMORE	(C,H,T)VH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0901716A*	31,200	\$4,368
210470438	KENMORE	(C,H,T)VH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0701716A*	31,400	\$4,396
210470240	KENMORE	(C,H,T)VH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	31,000	\$4,340
210470273	KENMORE	(C,H,T)VH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	31,000	\$4,340
210470559	KENMORE	(C,H,T)VH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470284	KENMORE	(C,H,T)VH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL1352422A*	31,000	\$4,340
210473114	KENMORE	(C,H,T)VH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210473103	KENMORE	(C,H,T)VH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
210470449	KENMORE	(C,H,T)VH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470251	KENMORE	(C,H,T)VH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU1002122A*	31,000	\$4,340
210025746	KENMORE	DLCURAH60ABK	DLFUAH60XAK		42,000	\$5,880
213372163	KENMORE	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372159	KENMORE	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
206998458	KENMORE	(C,H,T)VH825GKA3*	EHD4X36AAL+WALLCON	*80CTL0451712A*	20,800	\$2,912

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206998443	KENMORE	(C,H,T)VH825GKA3*	EHD4X30AAL+WALLCON	*80CTL1352422A*	21,000	\$2,940
206998440	KENMORE	(C,H,T)VH825GKA3*	EHD4X30AAL+WALLCON	*80CTL0701716A*	21,000	\$2,940
206998439	KENMORE	(C,H,T)VH825GKA3*	EHD4X30AAL+WALLCON	*80CTL0451712A*	21,000	\$2,940
206998424	KENMORE	(C,H,T)VH825GKA3*	EHD4X24AAL+WALLCON	*80CTL1352422A*	21,200	\$2,968
206998421	KENMORE	(C,H,T)VH825GKA3*	EHD4X24AAL+WALLCON	*80CTL0701716A*	21,200	\$2,968
206998420	KENMORE	(C,H,T)VH825GKA3*	EHD4X24AAL+WALLCON	*80CTL0451712A*	21,200	\$2,968
206998364	KENMORE	(C,H,T)VH825GKA3*	EN(A,D)4X24L17**+WALLCON	*80CTL0451712A*	21,200	\$2,968
210595739	KENMORE	(C,H,T)VH825GKA2*	END4X42L17**+WALLCON	*97CMN0801714A*	20,800	\$2,912
210595737	KENMORE	(C,H,T)VH825GKA2*	END4X42L17**+WALLCON	*96CTN0801714A*	20,800	\$2,912
210595736	KENMORE	(C,H,T)VH825GKA2*	END4X42L17**+WALLCON	*96CTN0601714A*	20,800	\$2,912
210595735	KENMORE	(C,H,T)VH825GKA2*	END4X42L17**+WALLCON	*95CSU0601716A*	20,800	\$2,912
210595734	KENMORE	(C,H,T)VH825GKA2*	END4X42L17**+WALLCON	*80CTL0901716A*	20,600	\$2,884
210595733	KENMORE	(C,H,T)VH825GKA2*	END4X42L17**+WALLCON	*80CTL0701716A*	20,800	\$2,912
210595732	KENMORE	(C,H,T)VH825GKA2*	END4X42L17**+WALLCON	*80CTL0701412A*	20,600	\$2,884
210595730	KENMORE	(C,H,T)VH825GKA2*	END4X42L17**+WALLCON	*80CSU0601716A*	20,800	\$2,912
210595729	KENMORE	(C,H,T)VH825GKA2*	END4X42L17**+WALLCON	*80CSU0401712A*	20,600	\$2,884
210595728	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALLCON	*97CMN1002122A*	20,600	\$2,884
210595727	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALLCON	*97CMN0801714A*	20,600	\$2,884
210595726	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALLCON	*97CMN0602120A*	20,600	\$2,884
210595725	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALLCON	*97CMN0601714A*	20,800	\$2,912
210595724	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALLCON	*96CTN1002122A*	20,600	\$2,884
210595723	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALLCON	*96CTN0801714A*	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210595722	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*96CTN0601714A*	20,800	\$2,912
210595721	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*95CSU1002122A*	20,600	\$2,884
210595720	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*95CSU0802120A*	20,600	\$2,884
210595719	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*95CSU0601716A*	20,600	\$2,884
210595718	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*80CTL0901716A*	20,600	\$2,884
210595717	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*80CTL0701716A*	20,600	\$2,884
210595716	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*80CTL0451712A*	20,800	\$2,912
210595715	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*80CSU1002120A*	20,600	\$2,884
210595714	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*80CSU0601716A*	20,600	\$2,884
210595713	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X48L21**+WALL CON	*80CSU0401712A*	20,600	\$2,884
210595702	KENMORE	(C,H,T)VH825GKA2*	EN(A,D,W)4X42L21**+WALL CON	*80CTL0901716A*	20,600	\$2,884
210595696	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X48L24**+WALLCO N	*97CMN1202422A*	20,600	\$2,884
210595695	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X48L24**+WALLCO N	*97CMN1002122A*	20,600	\$2,884
210595694	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X48L24**+WALLCO N	*97CMN0602120A*	20,600	\$2,884
210595693	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X48L24**+WALLCO N	*96CTN1202422A*	20,600	\$2,884
210595692	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X48L24**+WALLCO N	*96CTN1002122A*	20,600	\$2,884
210595691	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X48L24**+WALLCO N	*95CSU1002122A*	20,600	\$2,884
210595690	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X48L24**+WALLCO N	*95CSU0802120A*	20,600	\$2,884
210595689	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X48L24**+WALLCO N	*80CTL1352422A*	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210595688	KENMORE	(C,H,T)VH825GKA2*	EN(A,D)4X48L24**+WALLCON	*80CSU1002120A*	20,600	\$2,884
210595687	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*97CMN1202422A*	20,600	\$2,884
210595686	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*97CMN1002122A*	20,600	\$2,884
210595685	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*97CMN0801714A*	20,600	\$2,884
210595684	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*97CMN0602120A*	20,600	\$2,884
210595683	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*97CMN0601714A*	20,800	\$2,912
210595682	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*96CTN1202422A*	20,600	\$2,884
210595681	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*96CTN1002122A*	20,600	\$2,884
210595680	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*96CTN0801714A*	20,600	\$2,884
210595679	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*96CTN0601714A*	20,600	\$2,884
210595678	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*95CSU1002122A*	20,600	\$2,884
210595677	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*95CSU0802120A*	20,600	\$2,884
210595676	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*95CSU0601716A*	20,600	\$2,884
210595675	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*80CTL1352422A*	20,600	\$2,884
210595674	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*80CTL0901716A*	20,600	\$2,884
210595673	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*80CTL0701716A*	20,600	\$2,884
210595672	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*80CTL0701412A*	20,600	\$2,884
210595671	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*80CTL0451712A*	20,800	\$2,912
210595670	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*80CSU1002120A*	20,600	\$2,884
210595669	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*80CSU0601716A*	20,600	\$2,884
210595668	KENMORE	(C,H,T)VH825GKA2*	EHD4X48AAL+WALLCON	*80CSU0401712A*	20,600	\$2,884
210595667	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*97CMN1202422A*	20,600	\$2,884
210595666	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*97CMN1002122A*	20,600	\$2,884
210595665	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*97CMN0801714A*	20,800	\$2,912
210595664	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*97CMN0602120A*	20,800	\$2,912
210595663	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*97CMN0601714A*	20,800	\$2,912
210595662	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*96CTN1202422A*	20,600	\$2,884
210595661	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*96CTN1002122A*	20,600	\$2,884
210595660	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*96CTN0801714A*	20,800	\$2,912
210595659	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*96CTN0601714A*	20,800	\$2,912
210595658	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*95CSU1002122A*	20,600	\$2,884
210595657	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*95CSU0802120A*	20,600	\$2,884
210595656	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*95CSU0601716A*	20,800	\$2,912
210595655	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*80CTL1352422A*	20,600	\$2,884
210595654	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*80CTL0901716A*	20,600	\$2,884
210595653	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*80CTL0701716A*	20,600	\$2,884
210595652	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*80CTL0701412A*	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210595651	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*80CTL0451712A*	20,800	\$2,912
210595650	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*80CSU1002120A*	20,600	\$2,884
210595649	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*80CSU0601716A*	20,600	\$2,884
210595648	KENMORE	(C,H,T)VH825GKA2*	EHD4X42AAL+WALLCON	*80CSU0401712A*	20,600	\$2,884
210595647	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L24A*+WALLCON	*97CMN1202422A*	20,400	\$2,856
210595646	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L24A*+WALLCON	*97CMN1002122A*	20,400	\$2,856
210595645	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L24A*+WALLCON	*97CMN0602120A*	20,400	\$2,856
210595644	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L24A*+WALLCON	*96CTN1202422A*	20,400	\$2,856
210595643	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L24A*+WALLCON	*96CTN1002122A*	20,400	\$2,856
210595642	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L24A*+WALLCON	*95CSU1002122A*	20,400	\$2,856
210595641	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L24A*+WALLCON	*95CSU0802120A*	20,400	\$2,856
210595640	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	20,400	\$2,856
210595639	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L24A*+WALLCON	*80CSU1002120A*	20,400	\$2,856
210595638	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*97CMN1002122A*	20,400	\$2,856
210595637	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*97CMN0801714A*	20,600	\$2,884
210595636	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*97CMN0602120A*	20,600	\$2,884
210595635	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*97CMN0601714A*	20,600	\$2,884
210595634	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*96CTN1002122A*	20,400	\$2,856
210595633	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*96CTN0801714A*	20,400	\$2,856
210595632	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*96CTN0601714A*	20,600	\$2,884
210595631	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*95CSU1002122A*	20,400	\$2,856
210595630	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*95CSU0802120A*	20,400	\$2,856
210595629	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*95CSU0601716A*	20,600	\$2,884
210595628	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210595627	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*80CTL0701716A*	20,400	\$2,856
210595626	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*80CTL0451712A*	20,600	\$2,884
210595625	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*80CSU1002120A*	20,400	\$2,856
210595624	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*80CSU0601716A*	20,400	\$2,856
210595623	KENMORE	(C,H,T)VH825GKA2*	EA*4X48L21A*+WALLCON	*80CSU0401712A*	20,400	\$2,856
210595622	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*97CMN1002122A*	20,600	\$2,884
210595621	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*97CMN0801714A*	20,600	\$2,884
210595620	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*97CMN0602120A*	20,600	\$2,884
210595619	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*97CMN0601714A*	20,800	\$2,912
210595618	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*96CTN1002122A*	20,600	\$2,884
210595617	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*96CTN0801714A*	20,600	\$2,884
210595616	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*96CTN0601714A*	20,600	\$2,884
210595615	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210595614	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210595613	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*95CSU0601716A*	20,600	\$2,884
210595612	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210595611	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	20,600	\$2,884
210595610	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
210595609	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*80CSU1002120A*	20,600	\$2,884
210595608	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*80CSU0601716A*	20,600	\$2,884
210595607	KENMORE	(C,H,T)VH825GKA2*	EA*4X43L21A*+WALLCON	*80CSU0401712A*	20,600	\$2,884
210595606	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L24A*+WALLCON	*97CMN1202422A*	20,800	\$2,912
210595605	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L24A*+WALLCON	*97CMN1002122A*	20,600	\$2,884
210595604	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L24A*+WALLCON	*97CMN0602120A*	20,800	\$2,912
210595603	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L24A*+WALLCON	*96CTN1202422A*	20,600	\$2,884
210595602	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L24A*+WALLCON	*96CTN1002122A*	20,600	\$2,884
210595601	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L24A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210595600	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L24A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
210595599	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L24A*+WALLCON	*80CTL1352422A*	20,600	\$2,884
210595598	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L24A*+WALLCON	*80CSU1002120A*	20,800	\$2,912
210595597	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*97CMN1002122A*	20,600	\$2,884
210595596	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*97CMN0801714A*	20,800	\$2,912
210595595	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*97CMN0602120A*	20,800	\$2,912
210595594	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*97CMN0601714A*	20,800	\$2,912
210595593	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*96CTN1002122A*	20,600	\$2,884
210595592	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*96CTN0801714A*	20,800	\$2,912
210595591	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*96CTN0601714A*	20,800	\$2,912
210595590	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
210595589	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
210595588	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*95CSU0601716A*	20,800	\$2,912
210595587	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*80CTL0901716A*	20,600	\$2,884
210595586	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*80CTL0701716A*	20,600	\$2,884
210595585	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*80CTL0451712A*	20,800	\$2,912
210595584	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*80CSU1002120A*	20,800	\$2,912
210595583	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*80CSU0601716A*	20,600	\$2,884
210595582	KENMORE	(C,H,T)VH825GKA2*	EA*4X42L21A*+WALLCON	*80CSU0401712A*	20,600	\$2,884
206133980	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*95CSU0601716A*	20,800	\$2,912
206133970	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*95CSU1002122A*	21,000	\$2,940
206133950	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*95CSU0601716A*	21,000	\$2,940
206133724	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*80CSU1002120A*	20,800	\$2,912
206133684	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*80CSU1002120A*	21,000	\$2,940
206133664	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*80CSU0601716A*	21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
204459437	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*97CMN0602120A*	20,800	\$2,912
204459383	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*97CMN1202422A*	20,800	\$2,912
204459356	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*97CMN0801714A*	20,800	\$2,912
204459329	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*96CTN0801714A*	20,800	\$2,912
204459320	KENMORE	(C,H,T)VH825GKA2*	EHD4X36AAL+WALLCON	*96CTN0601714A*	20,800	\$2,912
204459230	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*96CTN1002122A*	21,000	\$2,940
204459212	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*97CMN1202422A*	21,000	\$2,940
204459203	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*97CMN1002122A*	21,000	\$2,940
204459185	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*97CMN0801714A*	21,000	\$2,940
204459167	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*96CTN1202422A*	21,000	\$2,940
204459158	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*96CTN0801714A*	21,000	\$2,940
204459140	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*80CTL1352422A*	21,000	\$2,940
204459104	KENMORE	(C,H,T)VH825GKA2*	EHD4X30AAL+WALLCON	*80CTL0701716A*	21,000	\$2,940
201835805	KENMORE	DLCSRAH12AAK	DLFSCAH12XAK		8,200	\$1,148
201835813	KENMORE	DLCSRAH18AAK	DLFSCAH18XAK		12,000	\$1,680
201835809	KENMORE	DLCSRAH12AAK	DLFSDAH12XAK		8,100	\$1,134
201835817	KENMORE	DLCSRAH24AAK	DLFSFAH24XAK		17,200	\$2,408
201835827	KENMORE	DLCLRAH48AAK	DLFLFAH48XAK		35,000	\$4,900
201835770	KENMORE	DLCSRAH18AAK	DLFSHAH18XAK		11,900	\$1,666
201835772	KENMORE	DLCSRAH24AAK	DLFSHAH24XAK		15,000	\$2,100
201835815	KENMORE	DLCSRAH24AAK	DLFSDAH24XAK		17,400	\$2,436
202463653	KENMORE	DLCPRAH24AAK	DLFPHAH24XAK		15,450	\$2,163
201835819	KENMORE	DLCSRAH24AAK	DLFSCAH24XAK		16,200	\$2,268
205921377	KENMORE	DLCSRAH24AAK	DLFSAAH24XAK		17,500	\$2,450
206350441	KENMORE	DLCSRBH12AAK	DLFSFAH12XAK		8,400	\$1,176
206350439	KENMORE	DLCSRBH12AAK	DLFSCAH12XAK		7,900	\$1,106
206396119	KENMORE	DLCSRAH12AAK	DLFSHBH12XAK		7,500	\$1,050
206350440	KENMORE	DLCSRBH12AAK	DLFSDAH12XAK		8,300	\$1,162
206350446	KENMORE	DLCSRBH24AAK	DLFSDAH24XAK		14,500	\$2,030
206350443	KENMORE	DLCSRBH18AAK	DLFSDAH18XAK		12,700	\$1,778
206350444	KENMORE	DLCSRBH18AAK	DLFSFAH18XAK		12,000	\$1,680
206350447	KENMORE	DLCSRBH24AAK	DLFSFAH24XAK		14,500	\$2,030
206350445	KENMORE	DLCSRBH24AAK	DLFSCAH24XAK		14,500	\$2,030
206188323	KENMORE	DLCSRBH24AAK	DLFSAAH24XAK		16,500	\$2,310
207643100	KENMORE	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207643106	KENMORE	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207643109	KENMORE	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643105	KENMORE	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207643099	KENMORE	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643108	KENMORE	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220
207643107	KENMORE	DLCMHBH36DAK	Heat pump without ducts		22,000	\$3,080
207643104	KENMORE	DLCMHBH48EAK	Heat pump without ducts		34,000	\$4,760
207643098	KENMORE	DLCMHBH30DAK	Heat pump without ducts		18,500	\$2,590
207801573	KENMORE	DLCSRBH18AAK	DLFSDAH24XAK		12,600	\$1,764
207826605	KENMORE	DLCSRBH18AAK	DLFSABH18XBK		12,000	\$1,680
213062288	KEPLER	AZPN/24WD	AZPN/24WAH		19,200	\$2,688
213062287	KEPLER	AZPN/18WD	AZPN/18WAH		13,500	\$1,890
213608176	KEPLER	ODUMOD30-24HFN1MU0W	IDUMSEPD-24HRFN1MU0W		21,200	\$2,968
213608175	KEPLER	ODUMOX430-17HFN1MT0W	IDUMSEPC-18HRFN1MU0W		15,000	\$2,100
213608174	KEPLER	ODUMOX330-12HFN1MW5W	IDUMSEPB-12HRFN1MW5W(GA)		10,000	\$1,400
214377775	KEPLER	ODUMOX330-12HFN1MW5W	IDUMFA2U-12HRFN1-MW5W		10,200	\$1,428
214377793	KEPLER	ODUM5OA-55HFN1-M-[X]	Combination heat pumps with or without ducts		34,800	\$4,872
214377792	KEPLER	ODUM5OA-55HFN1-M-[X]	Heat pump with ducts		35,200	\$4,928
214377791	KEPLER	ODUM5OA-55HFN1-M-[X]	Heat pump without ducts		34,400	\$4,816
214377774	KEPLER	ODUMOD30-24HFN1MU0W	IDUMCD1-24HRFN1-MT0W(GA)		21,000	\$2,940
214377776	KEPLER	ODUM2OI-18HFN1-M	Heat pump without ducts		15,000	\$2,100
214377788	KEPLER	ODUM5OG-48HFN1-M-[X]	Heat pump without ducts		36,000	\$5,040
214377769	KEPLER	ODUMOX430-17HFN1MT0W	IDUMTIU-18HWFN1-M		15,000	\$2,100
214377772	KEPLER	ODUMOX330-12HFN1MW5W	IDUCCA3U-12HRFN1-M(C)		9,900	\$1,386
214610376	KEPLER	AZPN/24WD	AZPN/B24WAC-UC		21,000	\$2,940
213062289	KEPLER	AZPN/30WD	AZPN/30WAH		21,000	\$2,940
213062290	KEPLER	AZPN/36WD	AZPN/36WAH		30,400	\$4,256
214377777	KEPLER	ODUM2OI-18HFN1-M	Heat pump with ducts		16,000	\$2,240
214377770	KEPLER	ODUMOD30-24HFN1MU0W	IDUMTIU-24HWFN1-M		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214377778	KEPLER	ODUM2OI-18HFN1-M	Combination heat pumps with or without ducts		15,500	\$2,170
214377784	KEPLER	ODUM4OI-36HFN1-M	Combination heat pumps with or without ducts		34,000	\$4,760
214377790	KEPLER	ODUM5OG-48HFN1-M-[X]	Combination heat pumps with or without ducts		36,000	\$5,040
214377782	KEPLER	ODUM4OI-36HFN1-M	Heat pump without ducts		33,000	\$4,620
214377789	KEPLER	ODUM5OG-48HFN1-M-[X]	Heat pump with ducts		36,000	\$5,040
214377768	KEPLER	ODUMOX330-12HFN1MW5W	IDUMTIU-12HWFN1-M		10,600	\$1,484
213062282	KEPLER	AZPN/24WD	AZPN/B24WAC		21,000	\$2,940
213062285	KEPLER	AZPN/36WD	AZPN/C36WAC		33,000	\$4,620
214610377	KEPLER	AZPN/30WD	AZPN/B36WAC-UC		19,600	\$2,744
213433213	KEPLER	AZPN/30WD	AZPN/B36WACUID		19,600	\$2,744
214610379	KEPLER	AZPN/36WD	AZPN/B36WAC-UC		27,400	\$3,836
213062283	KEPLER	AZPN/36WAC	AZPN/B36WAC		27,400	\$3,836
214610382	KEPLER	AZPN/B36WDUID	AZPN/C36WAC-UC		27,000	\$3,780
214610381	KEPLER	AZPN/B36WDUID	AZPN/B36WAC-UC		27,000	\$3,780
214610384	KEPLER	AZPN/45WD	AZPN/D60WAC-UC		37,000	\$5,180
214610385	KEPLER	AZPN/60WD	AZPN/D60WAC-UC		37,000	\$5,180
214610380	KEPLER	AZPN/36WD	AZPN/C36WAC-UC		33,000	\$4,620
214610378	KEPLER	AZPN/30WD	AZPN/C36WAC-UC		22,600	\$3,164
214078219	KEPLER	AZPN/B36WDUID	AZPN/C36WAC		27,000	\$3,780
214377779	KEPLER	ODUM3OK-27HFN1-M	Heat pump without ducts		23,000	\$3,220
214377781	KEPLER	ODUM3OK-27HFN1-M	Combination heat pumps with or without ducts		23,000	\$3,220
214377785	KEPLER	ODUM4OX630-36HFN1-M1X	Heat pump without ducts		27,400	\$3,836
214377786	KEPLER	ODUM4OX630-36HFN1-M1X	Heat pump with ducts		30,000	\$4,200
214377787	KEPLER	ODUM4OX630-36HFN1-M1X	Combination heat pumps with or without ducts		28,600	\$4,004
213608177	KEPLER	ODUMOD30-33HFN1MSR0W	IDUMSEPD-33HFN1MSR0W		28,800	\$4,032
213433215	KEPLER	AZPN/C36WDUID	AZPN/C36WAC		27,000	\$3,780
213433214	KEPLER	AZPN/B36WDUID	AZPN/B36WACUID		27,000	\$3,780
213500528	KEPLER	AZPN/B36WDUID	AZPN/36WAH		31,800	\$4,452
213062291	KEPLER	AZPN/48WD	AZPN/48WAH		36,000	\$5,040
213062284	KEPLER	AZPN/30WD	AZPN/C36WAC		22,600	\$3,164

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213062292	KEPLER	AZPN/60WD	AZPN/60WAH		42,000	\$5,880
213062286	KEPLER	AZPN/60WD	AZPN/D60WAC		37,000	\$5,180
214568859	KEPLER	AZPN/45WD	AZPN/D60WAC		37,000	\$5,180
216097148	KERR	A-KHP365A-1	Combination heat pumps with or without ducts		31,400	\$4,396
216097145	KERR	A-KHP365A-1	Heat pump without ducts		30,000	\$4,200
207657395	KERR	A-KMH12SV-1	B-KMH12SV-1		10,000	\$1,400
208141200	KERR	A-KMH18SU-1	B-KMH18SV-1		15,000	\$2,100
207657396	KERR	A-KMH18SV-1	B-KMH18SV-1		15,000	\$2,100
207657397	KERR	A-KMH24SV-1	B-KMH24SV-1		21,200	\$2,968
208141201	KERR	A-KMH24SU-1	B-KMH24SV-1		21,200	\$2,968
207657602	KERR	A-KMH28TV-1	Heat pump with ducts		27,000	\$3,780
210568256	KERR	A-KMH12SV-1	B-KMH12CU-1		9,900	\$1,386
210568251	KERR	A-KMH12SV-1	B-KMH12FU-1		9,600	\$1,344
210568253	KERR	A-KMH18SV-1	B-KMH18DU-1		15,000	\$2,100
206347320	KERR	A-KMH18SU-1A	B-KMH18DU-1		15,000	\$2,100
207657400	KERR	A-KMH24SV-1	C-VMH24CV-1		21,000	\$2,940
210568248	KERR	A-KMH24SV-1	B-KMH24CV-1		21,000	\$2,940
214232460	KERR	A-KMH55PV-1	Combination heat pumps with or without ducts		34,800	\$4,872
214232459	KERR	A-KMH55PV-1	Heat pump with ducts		35,200	\$4,928
214232458	KERR	A-KMH55PV-1	Heat pump without ducts		34,400	\$4,816
207657603	KERR	A-KMH28TV-1	Combination heat pumps with or without ducts		26,800	\$3,752
213265614	KERR	A-KCD18SA-1	B-KCD18SA-1		13,500	\$1,890
213348322	KERR	A-KCD18SA-1	B-VCD18SA-1		13,500	\$1,890
213348323	KERR	A-KCD24SA-1	B-VCD24SA-1		19,200	\$2,688
213349770	KERR	A-KCD24SA-1	B-KCD24SA-1		19,200	\$2,688
213916259	KERR	A-KMH12SV-1	B-KMH12FV-1		10,200	\$1,428
207657606	KERR	A-KMH48PV-1	Heat pump without ducts		36,000	\$5,040
207657599	KERR	A-KMH18DV-1	Heat pump without ducts		15,000	\$2,100
207657601	KERR	A-KMH28TV-1	Heat pump without ducts		26,600	\$3,724
213349771	KERR	A-KCD30SA-1	B-KCD30SA-1		21,000	\$2,940
213348324	KERR	A-KCD30SA-1	B-VCD30SA-1		21,000	\$2,940
213348325	KERR	A-KCD36SA-1	B-VCD36SA-1		30,400	\$4,256
213349772	KERR	A-KCD36SA-1	B-KCD36SA-1		30,400	\$4,256
206347323	KERR	A-KMH24SU-1A	B-KMH24UU-1		19,000	\$2,660
207657604	KERR	A-KMH36QV-1	Heat pump without ducts		33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207657600	KERR	A-KMH18DV-1	Combination heat pumps with or without ducts		15,500	\$2,170
207657607	KERR	A-KMH48PV-1	Heat pump with ducts		36,000	\$5,040
207657621	KERR	A-KMH36QV-1	Combination heat pumps with or without ducts		34,000	\$4,760
210568247	KERR	A-KMH24SV-1	B-KMH24DU-1		21,000	\$2,940
210568252	KERR	A-KMH24SV-1	B-KMH24UU-1		19,000	\$2,660
206347321	KERR	A-KMH24SU-1A	B-KMH24DU-1		21,000	\$2,940
207657598	KERR	A-KMH18DV-1	Heat pump with ducts		16,000	\$2,240
207657608	KERR	A-KMH48PV-1	Combination heat pumps with or without ducts		36,000	\$5,040
210568257	KERR	A-KMH12SV-1	B-KMH12DU-1		10,600	\$1,484
212631694	KERR	A-KCD24SA-1	MCD18/24B1A		21,000	\$2,940
216097113	KERR	A-KHP18SA-1	B-KHP18SA-1		16,600	\$2,324
216097083	KERR	A-KXP18TA-1	B-KXP18TA-1		15,000	\$2,100
216097112	KERR	A-KHP12SA-1	B-KHP12SA-1		9,800	\$1,372
216097084	KERR	A-KXP24TA-1	B-KXP24TA-1		20,000	\$2,800
216097086	KERR	A-KXP36TA-1	B-KXP36TA-1		31,800	\$4,452
216623774	KERR	A-KXP24TA-1	KXP18/24A1A		19,700	\$2,758
216623773	KERR	A-KXP18TA-1	KXP18/24B1A		15,200	\$2,128
216623772	KERR	A-KXP18TA-1	KXP18/24A1A		15,200	\$2,128
216623775	KERR	A-KXP24TA-1	KXP18/24B1A		19,700	\$2,758
216623778	KERR	A-KXP30TA-1	KXP30/36C1A		25,000	\$3,500
216623777	KERR	A-KXP30TA-1	KXP30/36B1A		25,000	\$3,500
216623776	KERR	A-KXP30TA-1	KXP30/36A1A		23,400	\$3,276
216623780	KERR	A-KXP36TA-1	KXP30/36C1A		29,200	\$4,088
216623779	KERR	A-KXP36TA-1	KXP30/36B1A		29,200	\$4,088
216684131	KERR	A-KXP48TA-1	KXP48/60C1A		32,000	\$4,480
216097114	KERR	A-KHP24SA-1	B-KHP24SA-1		21,000	\$2,940
216097115	KERR	A-KHP33SA-1	B-KHP33SA-1		30,000	\$4,200
216097122	KERR	A-KZP12SA-1	B-ZKP12SA-1		11,000	\$1,540
216097123	KERR	A-KZP18SA-1	B-ZKP18SA-1		19,300	\$2,702
216097139	KERR	A-KHP183A-1	Heat pump without ducts		17,600	\$2,464
216097140	KERR	A-KHP183A-1	Heat pump with ducts		17,000	\$2,380
216097141	KERR	A-KHP183A-1	Combination heat pumps with or without ducts		17,300	\$2,422
216097142	KERR	A-KHP284A-1	Heat pump without ducts		25,000	\$3,500
216097143	KERR	A-KHP284A-1	Heat pump with ducts		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216097144	KERR	A-KHP284A-1	Combination heat pumps with or without ducts		24,000	\$3,360
216097146	KERR	A-KHP365A-1	Heat pump with ducts		33,000	\$4,620
216097149	KERR	A-KHP486A-1	Heat pump without ducts		44,000	\$6,160
216097150	KERR	A-KHP486A-1	Heat pump with ducts		44,500	\$6,230
216097152	KERR	A-KHP486A-1	Combination heat pumps with or without ducts		44,000	\$6,160
216097153	KERR	A-KHP556A-1	Heat pump without ducts		44,000	\$6,160
216097154	KERR	A-KHP556A-1	Heat pump with ducts		45,000	\$6,300
216097155	KERR	A-KHP556A-1	Combination heat pumps with or without ducts		44,500	\$6,230
216097085	KERR	A-KXP30TA-1	B-KXP30TA-1		23,800	\$3,332
216097088	KERR	A-KXP60TA-1	B-KXP60TA-1		45,000	\$6,300
216097087	KERR	A-KXP48TA-1	B-KXP48TA-1		37,000	\$5,180
216097090	KERR	A-KHP24SA-1	B-KHP24AA-1		16,900	\$2,366
216097089	KERR	A-KHP18SA-1	B-KHP18AA-1		14,000	\$1,960
216097091	KERR	A-KHP33SA-1	B-KHP30AA-1		27,400	\$3,836
212631696	KERR	A-KCD36SA-1	MCD30/36C1A		33,000	\$4,620
201866480	KERR	A-KMH28TU-1	Heat pump without ducts		18,000	\$2,520
208141196	KERR	A-KMH24SV-1	B-KMH24SU-1		19,400	\$2,716
206913573	KERR	A-KMH24SU-1	B-KMH24SU-1A		19,400	\$2,716
206913038	KERR	A-KMH24SU-1A	B-KMH24SU-1		19,400	\$2,716
206221393	KERR	A-KMH24SU-1A	B-KMH24SU-1A		19,400	\$2,716
213348327	KERR	A-KCD60SA-1	B-VCD60SA-1		42,000	\$5,880
213348326	KERR	A-KCD48SA-1	B-VCD48SA-1		36,000	\$5,040
213349773	KERR	A-KCD48SA-1	B-KCD48SA-1		36,000	\$5,040
207691817	KERR	A-KCD48SA-1	B-KCD48SA-1		32,000	\$4,480
207691815	KERR	A-KCD30SA-1	B-KCD30SA-1		19,400	\$2,716
202111000	KERR	A-KMH24SU-1	B-KMH24DU-1		17,200	\$2,408
207691816	KERR	A-KCD36SA-1	B-KCD36SA-1		24,000	\$3,360
207691814	KERR	A-KCD24SA-1	B-KCD24SA-1		16,700	\$2,338
207657605	KERR	A-KMH36QV-1	Heat pump with ducts		23,000	\$3,220
206061624	KERR	A-VMH24SU-1A	B-VMH24SU-1A		19,400	\$2,716
210857424	KERR	A-KCD60SA-1	B-KCD60SA-1		42,000	\$5,880
212631695	KERR	A-KCD30SA-1	MCD30/36C1A		22,600	\$3,164
212631698	KERR	A-KCD60SA-1	MCD60D1A		37,000	\$5,180
217052380	KINGHOME	KU60UXO	KCAC60H/NHA		35,200	\$4,928
217052379	KINGHOME	KU60UXO	KCAC48H/NHA		31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
217052378	KINGHOME	KU36UXO	KCAC36F/NHA		22,000	\$3,080
217052377	KINGHOME	KU36UXO	KCAC24F/NHA		15,000	\$2,100
216772304	KINGHOME	KW24XQ25SDO	KW24XQ25SDI		20,000	\$2,800
206414276	KINGHOME	KU36UHO	KU24UH2I		20,000	\$2,800
206414277	KINGHOME	KU36UHO	KU36UH2I		29,000	\$4,060
206414278	KINGHOME	KU60UHO	KU60UH2I		44,000	\$6,160
206414279	KINGHOME	KU60UHO	KU48UH2I		39,500	\$5,530
203493070	KINGHOME	KW12HQ3D6DO	KW12HQ3D6DI		10,300	\$1,442
203493071	KINGHOME	KW18HQ3D6DO	KW18HQ3D6DI		15,100	\$2,114
203498481	KINGHOME	KW24HQ3D6DO	KW24HQ3D6DI		20,000	\$2,800
204462622	KINGHOME	KM18UH5O	Heat pump without ducts		17,000	\$2,380
204462623	KINGHOME	KM24UH5O	Heat pump without ducts		17,900	\$2,506
209847247	KINGHOME	KW12HQ25SDO	KW12HQ25SDI		10,000	\$1,400
211151018	KINGHOME	KW18HQ25SDO	KW18HQ25SDI		14,600	\$2,044
211164219	KINGHOME	KW30HQ20SDO	KW30HQ20SDI		24,000	\$3,360
211177527	KINGHOME	KW36HQ20SDO	KW36HQ20SDI		27,800	\$3,892
216799667	KINGHOME	KW18XQ29SDO	KM18XK8DI		15,500	\$2,170
216799659	KINGHOME	KW12XQ29SDO	KM12XK8DI		10,300	\$1,442
216799658	KINGHOME	KW12XQ29SDO	KM12XFDI		10,300	\$1,442
216799671	KINGHOME	KW24XQ25SDO	KM24XTDI		20,000	\$2,800
216799669	KINGHOME	KW24XQ25SDO	KM24XFDI		19,800	\$2,772
216799646	KINGHOME	KW18XQ25SDO	KM18XTDI		14,700	\$2,058
216799641	KINGHOME	KW12XQ25SDO	KM12XEDI		10,000	\$1,400
216799638	KINGHOME	KW12XQ25SDO	KM12XK8DI		10,000	\$1,400
216799637	KINGHOME	KW12XQ25SDO	KM12XFDI		10,000	\$1,400
216372816	KINGHOME	KW12XQ25SDO	KW12XQ25SDI		10,000	\$1,400
216020673	KINGHOME	KW12XQ25PDO	KW12XQ25PDI		10,000	\$1,400
215876652	KINGHOME	KW30XQ21SDO	KW30XQ21SDI		24,000	\$3,360
215876650	KINGHOME	KW24XQ29SDO	KW24XQ29SDI		20,000	\$2,800
215708455	KINGHOME	KM42X6O	Combination heat pumps with or without ducts		40,000	\$5,600
215708454	KINGHOME	KM36X6O	Combination heat pumps with or without ducts		36,000	\$5,040
215708453	KINGHOME	KM30X6O	Combination heat pumps with or without ducts		27,600	\$3,864
215708452	KINGHOME	KM24X6O	Combination heat pumps with or without ducts		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215708451	KINGHOME	KM18X6O	Combination heat pumps with or without ducts		15,400	\$2,156
215708450	KINGHOME	KM42X6O	Heat pump with ducts		40,000	\$5,600
215708449	KINGHOME	KM36X6O	Heat pump with ducts		36,000	\$5,040
215708448	KINGHOME	KM30X6O	Heat pump with ducts		27,200	\$3,808
215708447	KINGHOME	KM24X6O	Heat pump with ducts		22,000	\$3,080
215708446	KINGHOME	KM18X6O	Heat pump with ducts		15,000	\$2,100
215708445	KINGHOME	KM42X6O	Heat pump without ducts		40,000	\$5,600
215708444	KINGHOME	KM36X6O	Heat pump without ducts		36,000	\$5,040
215708443	KINGHOME	KM30X6O	Heat pump without ducts		28,000	\$3,920
215708442	KINGHOME	KM24X6O	Heat pump without ducts		23,600	\$3,304
215708441	KINGHOME	KM18X6O	Heat pump without ducts		16,000	\$2,240
214655286	KINGHOME	KM18H5O3	Heat pump without ducts		15,200	\$2,128
212437233	KINGHOME	KW24HQ25SDO	KM24HF1DI		19,400	\$2,716
212437230	KINGHOME	KW18HQ25SDO	KM18HF1DI		14,600	\$2,044
212396483	KINGHOME	KW12HQ19SDO	KW12HQ19SDI		9,700	\$1,358
211497161	KINGHOME	KM42H5O	Heat pump with ducts		32,400	\$4,536
211497160	KINGHOME	KM36H5O	Heat pump with ducts		30,000	\$4,200
211497159	KINGHOME	KM30H5O	Heat pump with ducts		26,800	\$3,752
211497158	KINGHOME	KM24H5O	Heat pump with ducts		23,000	\$3,220
211497157	KINGHOME	KM18H5O	Heat pump with ducts		15,000	\$2,100
211497156	KINGHOME	KM42H5O	Heat pump without ducts		35,600	\$4,984
211497155	KINGHOME	KM36H5O	Heat pump without ducts		30,800	\$4,312
211497154	KINGHOME	KM30H5O	Heat pump without ducts		27,200	\$3,808
211497153	KINGHOME	KM24H5O	Heat pump without ducts		23,600	\$3,304
211497152	KINGHOME	KM18H5O	Heat pump without ducts		15,000	\$2,100
216772303	KINGHOME	KM48X6O	Combination heat pumps with or without ducts		40,000	\$5,600
216772302	KINGHOME	KM48X6O	Heat pump with ducts		40,000	\$5,600
216772301	KINGHOME	KM48X6O	Heat pump without ducts		40,000	\$5,600
216772293	KINGHOME	KW36XQ21CDO	KW36XQ21CDI		27,400	\$3,836
216772294	KINGHOME	KW30XQ21CDO	KW30XQ21CDI		24,000	\$3,360
216772323	KINGHOME	KD48UXO	KD48UXI		38,500	\$5,390
216626176	KINGHOME	KD60UXO	KD60UXI		43,000	\$6,020
216626175	KINGHOME	KD60UXO	KD48UXI		38,500	\$5,390
214215182	KINGHOME	KU24UHO	KCA24*I		19,600	\$2,744
212361364	KINGHOME	KU60UHO	KCA60*I		44,500	\$6,230
212361363	KINGHOME	KU60UHO	KCA48*I		39,000	\$5,460

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212361362	KINGHOME	KU36UHO	KCA36*I		23,200	\$3,248
212361361	KINGHOME	KU36UHO	KCA24*I		19,600	\$2,744
10338140	KINGHOME	KW24HQ2B8DO	KW24HQ2B8DI		14,600	\$2,044
211497166	KINGHOME	KM42H5O	Combination heat pumps with or without ducts		34,000	\$4,760
211497165	KINGHOME	KM36H5O	Combination heat pumps with or without ducts		30,400	\$4,256
211497164	KINGHOME	KM30H5O	Combination heat pumps with or without ducts		27,000	\$3,780
211497163	KINGHOME	KM24H5O	Combination heat pumps with or without ducts		23,200	\$3,248
211497162	KINGHOME	KM18H5O	Combination heat pumps with or without ducts		14,300	\$2,002
213685846	KINGHOME	KRH02TCU			23,400	\$3,276
213685844	KINGHOME	KRH04TCU			36,000	\$5,040
213685843	KINGHOME	KRH05TCU			37,000	\$5,180
10333040	KINGHOME	KW18HQ2B8DO	KW18HQ2B8DI		12,400	\$1,736
204462626	KINGHOME	KM48UH5O	Heat pump without ducts		38,000	\$5,320
204743192	KINGHOME	KU36UHO	KU36UHI		24,400	\$3,416
206322337	KINGHOME	KU60UHO	KU48UHI		32,800	\$4,592
205756438	KINGHOME	KU36UHO	KU24UHI		16,300	\$2,282
205724739	KINGHOME	KU60UHO	KU60UHI		38,000	\$5,320
214779546	KWIIK	KKCA-12EX2-SCU	KKCA-12WA2-SCU		10,800	\$1,512
214779547	KWIIK	KKCA-18EX2-SCU	KKCA-18WA2-SCU		18,000	\$2,520
207629154	LBG PRODUCTS	LBHB12DYWO	LBHB12DYWI		11,400	\$1,596
208130832	LBG Products	LBHB12DVWO	LMHB12DSI		9,900	\$1,386
208130843	LBG Products	LBHB12DVWO	LMHB12DZGI		9,600	\$1,344
208130839	LBG Products	LBHB18DVWO	LMHB18DFI		15,000	\$2,100
207641321	LBG PRODUCTS	LMUHB27DO	Combination heat pumps with or without ducts		26,200	\$3,668
208130834	LBG Products	LBHB24DVWO	LMHB24DSI		21,000	\$2,940
207641327	LBG PRODUCTS	LMUHB48DO	Combination heat pumps with or without ducts		37,400	\$5,236
207629155	LBG Products	LBHB18DYWO	LBHB18DYWI		21,200	\$2,968
213307918	LBG PRODUCTS	LCUHB18DO	LCHB18DHNI		13,500	\$1,890
213307919	LBG PRODUCTS	LCUHB24DO	LCHB24DHNI		19,200	\$2,688
207641316	LBG Products	LMUHB18DO	Heat pump without ducts		13,500	\$1,890
207641320	LBG Products	LMUHB27DO	Heat pump without ducts		25,600	\$3,584
213307920	LBG PRODUCTS	LCUHB30DO	LCHB30DHNI		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213307921	LBG PRODUCTS	LCUHB36DO	LCHB36DHNI		30,400	\$4,256
208130828	LBG PRODUCTS	LBHB12DVWO	LBHB12DUWI		10,300	\$1,442
208130829	LBG PRODUCTS	LBHB18DVWO	LBHB18DUWI		11,100	\$1,554
208130830	LBG PRODUCTS	LBHB24DVWO	LBHB24DUWI		18,900	\$2,646
207641317	LBG Products	LMUHB18DO	Heat pump with ducts		16,000	\$2,240
207641325	LBG Products	LMUHB48DO	Heat pump without ducts		39,000	\$5,460
207641326	LBG Products	LMUHB48DO	Heat pump with ducts		36,000	\$5,040
208130840	LBG Products	LBHB24DVWO	LMHB24DFI		21,000	\$2,940
207641318	LBG PRODUCTS	LMUHB18DO	Combination heat pumps with or without ducts		14,700	\$2,058
207641322	LBG PRODUCTS	LMUHB36DO	Heat pump without ducts		35,000	\$4,900
207641324	LBG PRODUCTS	LMUHB36DO	Combination heat pumps with or without ducts		35,000	\$4,900
208130838	LBG Products	LBHB12DVWO	LMHB12DFI		10,600	\$1,484
208130845	LBG Products	LBHB24DVWO	LMHB24DZDI		19,000	\$2,660
208130824	LBG PRODUCTS	LUHB48DO	LUHB48DZDI		29,000	\$4,060
208130836	LBG Products	LUUHB48DO	LUHB48DSI		35,000	\$4,900
208130835	LBG Products	LUUHB36DO	LUHB36DSI		33,000	\$4,620
208130847	LBG Products	LUUHB48DO	LUHB48DZDI		35,000	\$4,900
208130842	LBG Products	LUUHB48DO	LUHB48DFI		39,500	\$5,530
213307923	LBG PRODUCTS	LCUHB60DO	LCHB60DHNI		42,000	\$5,880
213307922	LBG PRODUCTS	LCUHB48DO	LCHB48DHNI		36,000	\$5,040
206726719	LBG PRODUCTS	LCH24036DO	LCH36DGHNI		24,000	\$3,360
207641323	LBG PRODUCTS	LMUHB36DO	Heat pump with ducts		23,000	\$3,220
208130846	LBG Products	LUUHB36DO	LUHB36DZDI		32,000	\$4,480
212331390	LBG PRODUCTS	LCUHB30DO	LCHB36DA		22,600	\$3,164
212386768	LBG PRODUCTS	LCUHB60DO	LCHB60DA		37,000	\$5,180
216581340	LENNOX	MMPD048S6S-1P	MMD048S6-1P		34,600	\$4,844
216581339	LENNOX	MMPD036S6S-1P	MMD036S6-1P		27,400	\$3,836
216760264	LENNOX	MMPD036S6M-1P	Heat pump without ducts		21,000	\$2,940
216581338	LENNOX	MMPD030S6S-1P	MMD030S6-1P		21,200	\$2,968
216581337	LENNOX	MMPD024S6S-1P	MMD024S6-1P		15,000	\$2,100
216760266	LENNOX	MMPD020S6M-1P	Heat pump without ducts		12,800	\$1,792
216581336	LENNOX	MMPD018S6S-1P	MMD018S6-1P		12,700	\$1,778
216760275	LENNOX	MMLD036S6M-1P	Heat pump without ducts		23,000	\$3,220
216760283	LENNOX	MMLD036S6M-1P	Combination heat pumps with or without ducts		21,800	\$3,052
216760279	LENNOX	MMLD036S6M-1P	Heat pump with ducts		20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216760276	LENNOX	MMLD030S6M-1P	Heat pump without ducts		17,500	\$2,450
216760284	LENNOX	MMLD030S6M-1P	Combination heat pumps with or without ducts		17,300	\$2,422
216760280	LENNOX	MMLD030S6M-1P	Heat pump with ducts		17,200	\$2,408
216581332	LENNOX	MMLD024S6S-1P	MMD024S6-1P		19,300	\$2,702
216760277	LENNOX	MMLD024S6M-1P	Heat pump without ducts		15,200	\$2,128
216760285	LENNOX	MMLD024S6M-1P	Combination heat pumps with or without ducts		15,100	\$2,114
216760281	LENNOX	MMLD024S6M-1P	Heat pump with ducts		15,000	\$2,100
216760278	LENNOX	MMLD020S6M-1P	Heat pump without ducts		13,200	\$1,848
216760286	LENNOX	MMLD020S6M-1P	Combination heat pumps with or without ducts		13,200	\$1,848
216760282	LENNOX	MMLD020S6M-1P	Heat pump with ducts		13,200	\$1,848
216581331	LENNOX	MMLD018S6S-1P	MMD018S6-1P		14,000	\$1,960
216411317	LENNOX	MWHD015S6S-1P	MWHD015S6-1P		13,000	\$1,820
216411314	LENNOX	MWPD024S6S-1P	MWMD024S6-1P		28,000	\$3,920
216411313	LENNOX	MWPD018S6S-1P	MWMD018S6-1P		17,500	\$2,450
216411312	LENNOX	MWPD015S6S-1P	MWMD015S6-1P		14,000	\$1,960
216411311	LENNOX	MWPD012S6S-1P	MWMD012S6-1P		10,600	\$1,484
216411309	LENNOX	MWLD024S6S-1P	MWMD024S6-1P		28,000	\$3,920
216411308	LENNOX	MWLD018S6S-1P	MWMD018S6-1P		17,500	\$2,450
216411307	LENNOX	MWLD015S6S-1P	MWMD015S6-1P		14,000	\$1,960
216411306	LENNOX	MWLD012S6S-1P	MWMD012S6-1P		10,600	\$1,484
216581335	LENNOX	MMLD048S6S-1P	MMD048S6-1P		41,500	\$5,810
216581334	LENNOX	MMLD036S6S-1P	MMD036S6-1P		29,000	\$4,060
216581333	LENNOX	MMLD030S6S-1P	MMD030S6-1P		25,400	\$3,556
216581330	LENNOX	MMLD018S6S-1P	MFMD018S6-1P		11,900	\$1,666
216776134	Lennox	SL22KLV-060-230A**	CK40[C,U]T-49C-**+TDR	SL280UH100NV60C*	54,000	\$7,560
216776133	Lennox	SL22KLV-060-230A**	CK40[C,U]T-49C-**+TDR	SL280UH090XV60C*	54,500	\$7,630
216776132	Lennox	SL22KLV-060-230A**	CK40[C,U]T-49C-**+TDR	SL280UH090V60C*	54,500	\$7,630
216776131	Lennox	SL22KLV-060-230A**	CK40[C,U]T-49C-**+TDR	SL280UH080NV60C*	54,000	\$7,560
216776123	Lennox	SL22KLV-060-230A**	CK40[C,U]T-60C-**+TDR	SL280UH100NV60C*	60,000	\$8,400
216776122	Lennox	SL22KLV-060-230A**	CK40[C,U]T-60C-**+TDR	SL280UH090XV60C*	60,000	\$8,400
216776121	Lennox	SL22KLV-060-230A**	CK40[C,U]T-60C-**+TDR	SL280UH090V60C*	60,000	\$8,400
216776120	Lennox	SL22KLV-060-230A**	CK40[C,U]T-60C-**+TDR	SL280UH080NV60C*	48,500	\$6,790
216776104	Lennox	SL22KLV-048-230A**	CK40[C,U]T-49C-**+TDR	SL280UH110XV60C*	45,500	\$6,370
216776103	Lennox	SL22KLV-048-230A**	CK40[C,U]T-49C-**+TDR	SL280UH110V60C*	45,500	\$6,370
216776102	Lennox	SL22KLV-048-230A**	CK40[C,U]T-49C-**+TDR	SL280UH100NV60C*	45,000	\$6,300

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216776101	Lennox	SL22KLV-048-230A**	CK40[C,U]T-49C-**+TDR	SL280UH090XV60C*	45,500	\$6,370
216776100	Lennox	SL22KLV-048-230A**	CK40[C,U]T-49C-**+TDR	SL280UH090V60C*	45,500	\$6,370
216776099	Lennox	SL22KLV-048-230A**	CK40[C,U]T-49C-**+TDR	SL280UH080NV60C*	45,000	\$6,300
216776098	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	EL297UH110XV60C*	43,000	\$6,020
216776097	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	EL297UH090XV60C*	43,000	\$6,020
216776096	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	SLP99UH110XV60C*	43,000	\$6,020
216776095	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	SLP99UH090XV60C*	43,000	\$6,020
216776094	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	SL297UH080NV60C*	43,000	\$6,020
216776093	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	SL280UH110XV60C*	43,000	\$6,020
216776092	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	SL280UH110V60C*	43,000	\$6,020
216776091	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	SL280UH100NV60C*	42,500	\$5,950
216776090	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	SL280UH090XV60C*	42,500	\$5,950
216776089	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	SL280UH090V60C*	42,500	\$5,950
216776088	Lennox	SL22KLV-048-230A**	CK40[C,U]T-60C-**+TDR	SL280UH080NV60C*	42,500	\$5,950
216776012	Lennox	SL22KLV-048-230A**	CBK48MVT-060-230-**		44,000	\$6,160
216776086	Lennox	SL22KLV-036-230A**	CK40HT-42B-**+TDR	EL297UH110XV60C*	33,800	\$4,732
216776085	Lennox	SL22KLV-036-230A**	CK40HT-42B-**+TDR	SL280UH090XV48B*	33,800	\$4,732
216776084	Lennox	SL22KLV-036-230A**	CK40HT-42B-**+TDR	SL280UH090V48B*	33,800	\$4,732
216776083	Lennox	SL22KLV-036-230A**	CK40HT-42B-**+TDR	SL280UH080NV48B*	33,600	\$4,704
216776082	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	EL297UH110XV60C*	33,800	\$4,732
216776081	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	EL297UH110XV48C*	33,800	\$4,732
216776080	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	EL297UH090XV60C*	33,800	\$4,732
216776079	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	EL297UH090XV48C*	33,800	\$4,732
216776078	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SLP99UH110XV60C*	33,800	\$4,732
216776077	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SLP99UH090XV60C*	33,800	\$4,732
216776076	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SLP99UH090XV48C*	33,800	\$4,732
216776075	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SL297UH080NV60C*	33,800	\$4,732
216776074	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SL297UH080NV48C*	33,800	\$4,732
216776073	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SL280UH110XV60C*	33,800	\$4,732
216776072	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SL280UH110V60C*	33,800	\$4,732
216776071	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SL280UH100NV60C*	33,400	\$4,676
216776070	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SL280UH090XV60C*	33,600	\$4,704
216776069	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SL280UH090V60C*	33,600	\$4,704
216776068	Lennox	SL22KLV-036-230A**	CK40[C,U]T-49C-**+TDR	SL280UH080NV60C*	33,400	\$4,676
216776011	Lennox	SL22KLV-036-230A**	CBK48MVT-060-230-**		33,600	\$4,704
216968307	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-**+TDR	EL297UH110XV60C*	18,700	\$2,618
216968306	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-**+TDR	EL297UH070XV36B*	18,700	\$2,618
216968305	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-**+TDR	EL297UH045XV36B*	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216968304	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-***+TDR	SLP99UH070XV36B*	18,700	\$2,618
216968303	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-***+TDR	SL297UH060NV36B*	18,800	\$2,632
216968302	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-***+TDR	SL297UH040NV36B*	18,700	\$2,618
216968301	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-***+TDR	SL280UH090XV48B*	18,700	\$2,618
216968300	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-***+TDR	SL280UH090V48B*	18,700	\$2,618
216968299	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-***+TDR	SL280UH090V36B*	18,600	\$2,604
216968298	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48B-***+TDR	SL280UH080NV48B*	18,600	\$2,604
216968297	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	EL297UH110XV60C*	18,600	\$2,604
216968296	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	EL297UH110XV48C*	18,600	\$2,604
216968295	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	EL297UH090XV60C*	18,600	\$2,604
216968294	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	EL297UH090XV48C*	18,600	\$2,604
216968293	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	EL297UH090XV36C*	18,600	\$2,604
216968292	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SLP99UH110XV60C*	18,700	\$2,618
216968291	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SLP99UH090XV60C*	18,600	\$2,604
216968290	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SLP99UH090XV48C*	18,600	\$2,604
216968289	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SLP99UH090XV36C*	18,600	\$2,604
216968288	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SL297UH080NV60C*	18,700	\$2,618
216968287	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SL297UH080NV48C*	18,700	\$2,618
216968286	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SL280UH110XV60C*	18,700	\$2,618
216968285	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SL280UH110V60C*	18,700	\$2,618
216968284	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SL280UH100NV60C*	18,600	\$2,604
216968283	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SL280UH090XV60C*	18,600	\$2,604
216968282	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SL280UH090V60C*	18,600	\$2,604
216968281	Lennox	SL22KLV-024-230A**	CK40[C,U]T-48C-***+TDR	SL280UH080NV60C*	18,600	\$2,604
216776062	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36A-***+TDR	SL280UH070XV36A*	22,800	\$3,192
216776061	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36A-***+TDR	SL280UH070V36A*	22,800	\$3,192
216776060	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36A-***+TDR	SL280UH060NV36A*	22,800	\$3,192
216776059	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SL280UH090XV60C*	21,600	\$3,024
216776058	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SL280UH100NV60C*	21,600	\$3,024
216776057	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SL280UH110V60C*	21,800	\$3,052
216776056	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SL280UH110XV60C*	21,800	\$3,052
216776055	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SL297UH080NV48C*	21,800	\$3,052
216776054	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SL297UH080NV60C*	21,800	\$3,052
216776053	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SLP99UH090XV36C*	21,600	\$3,024
216776052	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SLP99UH090XV48C*	21,600	\$3,024
216776051	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SLP99UH090XV60C*	21,600	\$3,024
216776050	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	SLP99UH110XV60C*	21,800	\$3,052
216776049	Lennox	SL22KLV-024-230A**	CK40HT-42C-***+TDR	EL297UH110XV60C*	21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216776048	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	EL297UH110XV48C*	21,800	\$3,052
216776047	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	EL297UH090XV60C*	21,600	\$3,024
216776046	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	EL297UH090XV48C*	21,600	\$3,024
216776045	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	EL297UH090XV36C*	21,600	\$3,024
216776044	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	EL297UH045XV36B*	21,800	\$3,052
216776043	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	SL297UH060NV36B*	21,800	\$3,052
216776042	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	SL297UH040NV36B*	21,800	\$3,052
216776041	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	SL280UH080NV48B*	21,600	\$3,024
216776040	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	SL280UH090V60C*	21,600	\$3,024
216776039	Lennox	SL22KLV-024-230A**	CK40HT-42C-***TDR	SL280UH080NV60C*	21,600	\$3,024
216776038	Lennox	SL22KLV-024-230A**	CK40HT-42B-***TDR	EL297UH110XV60C*	28,800	\$4,032
216776037	Lennox	SL22KLV-024-230A**	CK40HT-42B-***TDR	SL280UH090XV48B*	21,800	\$3,052
216776036	Lennox	SL22KLV-024-230A**	CK40HT-42B-***TDR	SL280UH090V48B*	21,800	\$3,052
216776035	Lennox	SL22KLV-024-230A**	CK40HT-42B-***TDR	SL280UH090V36B*	21,800	\$3,052
216776034	Lennox	SL22KLV-024-230A**	CK40HT-42B-***TDR	SL280UH080NV48B*	21,800	\$3,052
216776024	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	EL297UH110XV60C*	22,800	\$3,192
216776023	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	EL297UH070XV36B*	22,800	\$3,192
216776022	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	EL297UH045XV36B*	23,000	\$3,220
216776021	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	SLP99UH070XV36B*	22,800	\$3,192
216776020	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	SL297UH060NV36B*	22,800	\$3,192
216776019	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	SL297UH040NV36B*	22,800	\$3,192
216776018	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	SL280UH090XV48B*	22,800	\$3,192
216776017	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	SL280UH090V48B*	22,800	\$3,192
216776016	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	SL280UH090V36B*	22,800	\$3,192
216776015	Lennox	SL22KLV-024-230A**	CK40[C,U]T-36B-***TDR	SL280UH080NV48B*	22,800	\$3,192
216776013	Lennox	SL22KLV-024-230A**	CBK48MVT-018/024-230-**		23,200	\$3,248
212348050	LENNOX	MLB024S4S-1P	MMA024SM4-*P		16,900	\$2,366
212348049	LENNOX	MLB018S4S-1P	MMA018SM4-*P		15,400	\$2,156
211034429	LENNOX	MPC012S4S-1P	MFMA012S4-*P		9,000	\$1,260
211034441	LENNOX	MLB012S4S-1P	MWMC012S4-*P		10,000	\$1,400
211034442	LENNOX	MLB018S4S-1P	MWMC018S4-*P		15,000	\$2,100
211034443	LENNOX	MLB024S4S-1P	MWMC024S4-*P		21,200	\$2,968
211034446	LENNOX	MLB018S4S-1P	MMDB018S4-*P		15,000	\$2,100
211034456	LENNOX	MLB012S4S-1P	M22A012S4-*P		9,900	\$1,386
211034458	LENNOX	MLB024S4S-1P	M33C024S4-*P		21,000	\$2,940
207683509	LENNOX	MPC012S4S-1P	MFMA012S4-1P		9,000	\$1,260
207683523	LENNOX	MLB024S4S-1P	MWMC024S4-1P		21,200	\$2,968
207683522	LENNOX	MLB018S4S-1P	MWMC018S4-1P		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207683521	LENNOX	MLB012S4S-1P	MWMC012S4-1P		10,000	\$1,400
207683532	LENNOX	MLB012S4S-1P	M22A012S4-2P		9,900	\$1,386
207436156	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	SLP99UH070XV36B*	24,200	\$3,388
207436165	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	SLP99UH070XV36B*	24,200	\$3,388
207436177	LENNOX	SL25XPV-024-230A**	CH35-42C+TDR+TXV	EL296UH090XV36C*	23,800	\$3,332
207436190	LENNOX	SL25XPV-024-230A**	CH35-42C+TDR+TXV	SLP99UH090XV36C*	23,800	\$3,332
207436269	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	SLP99UH070XV36B*	33,400	\$4,676
207436283	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SLP99UH090XV36C*	33,200	\$4,648
207436308	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SLP99UH090XV36C*	30,800	\$4,312
207436188	LENNOX	SL25XPV-024-230A**	CH35-42C+TDR+TXV	SL297UH080NV48C*	23,800	\$3,332
10528572	LENNOX	MLA024S4S-1P	MMDB024S4-2P		23,000	\$3,220
207436144	LENNOX	SL25XPV-048-230A**	CBA38MV-060-230*+TDR		43,000	\$6,020
207436146	LENNOX	SL25XPV-024-230A**	C35-36A+TDR+TXV	SL280UH060NV36A*	24,200	\$3,388
207436148	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	EL296UH045XV36B*	24,200	\$3,388
207436151	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	SL280UH090V36B*	24,200	\$3,388
207436154	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	SL297UH040NV36B*	24,200	\$3,388
207436166	LENNOX	SL25XPV-024-230A**	CBA38MV-030-230*+TDR		25,200	\$3,528
207436167	LENNOX	SL25XPV-024-230A**	CBA38MV-036-230*+TDR		25,400	\$3,556
207436169	LENNOX	SL25XPV-024-230A**	CH35-42B+TDR+TXV	EL296UH070XV36B*	23,600	\$3,304
207436174	LENNOX	SL25XPV-024-230A**	CH35-42B+TDR+TXV	SL297UH040NV36B*	23,400	\$3,276
207436178	LENNOX	SL25XPV-024-230A**	CH35-42C+TDR+TXV	EL296UH090XV48C*	23,800	\$3,332
207436191	LENNOX	SL25XPV-024-230A**	CH35-42C+TDR+TXV	SLP99UH090XV48C*	23,800	\$3,332
207436198	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	SL280UH090V48B*	23,600	\$3,304
207436199	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	SL280UH090XV48B*	23,600	\$3,304
207436200	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	SL297UH040NV36B*	23,400	\$3,276
207436201	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	SL297UH060NV36B*	23,600	\$3,304
207436214	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	SL297UH080NV48C*	23,800	\$3,332
207436240	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	EL296UH045XV36B*	24,200	\$3,388
207436243	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	SL280UH090V36B*	24,200	\$3,388
207436246	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	SL297UH040NV36B*	24,200	\$3,388
207436271	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL296UH090XV48C*	33,200	\$4,648
207436272	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL296UH090XV60C*	33,200	\$4,648
207436281	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SL297UH080NV48C*	33,000	\$4,620
207436282	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SL297UH080NV60C*	33,200	\$4,648
207436287	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL296UH090XV36C*	30,800	\$4,312
207436288	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL296UH090XV48C*	30,600	\$4,284
207436290	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL296UH110XV48C*	30,600	\$4,284
207436293	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SL280UH090V60C*	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207436294	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SL280UH090XV60C*	30,600	\$4,284
207436314	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SLP99UH090XV48C*	30,600	\$4,284
207436326	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SLP99UH090XV60C*	30,600	\$4,284
207436328	LENNOX	SL25XPV-036-230A**	CBA38MV-036-230*+TDR		34,000	\$4,760
207436330	LENNOX	SL25XPV-036-230A**	CH35-42B+TDR+TXV	EL296UH070XV36B*	30,800	\$4,312
207436337	LENNOX	SL25XPV-036-230A**	CH35-42B+TDR+TXV	SLP99UH070XV36B*	30,800	\$4,312
207436356	LENNOX	SL25XPV-036-230A**	CH35-48B+TDR+TXV	EL296UH070XV36B*	31,400	\$4,396
207436363	LENNOX	SL25XPV-036-230A**	CH35-48B+TDR+TXV	SLP99UH070XV36B*	31,400	\$4,396
207436382	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	EL296UH070XV36B*	30,800	\$4,312
207436387	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	SL297UH040NV36B*	30,600	\$4,284
207436388	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	SL297UH060NV36B*	30,600	\$4,284
207436389	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	SLP99UH070XV36B*	30,800	\$4,312
207436410	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	SL280UH090V36B*	31,000	\$4,340
207436411	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	SL280UH090V48B*	31,200	\$4,368
207436412	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	SL280UH090XV48B*	31,200	\$4,368
207436414	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	SL297UH060NV36B*	31,400	\$4,396
207436470	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	SL280UH080NV48B*	33,000	\$4,620
207436471	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	SL280UH090V36B*	33,200	\$4,648
207436472	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	SL280UH090V48B*	33,200	\$4,648
207436477	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL296UH090XV36C*	33,200	\$4,648
207436478	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL296UH090XV48C*	33,200	\$4,648
207436483	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SL280UH090V60C*	33,000	\$4,620
207436484	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SL280UH090XV60C*	33,000	\$4,620
207436485	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SL280UH100NV60C*	32,800	\$4,592
207436491	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SLP99UH090XV48C*	33,200	\$4,648
207436492	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SLP99UH090XV60C*	33,200	\$4,648
207436503	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SL280UH110V60C*	30,600	\$4,284
207436507	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SLP99UH090XV36C*	30,800	\$4,312
207436516	LENNOX	SL25XPV-048-230A**	C35-49C+TDR+TXV	SL280UH090V60C*	43,000	\$6,020
207436540	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SLP99UH110XV60C*	42,500	\$5,950
207436542	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	EL296UH090XV48C*	46,000	\$6,440
207436544	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	EL296UH110XV48C*	46,000	\$6,440
207436547	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SL280UH090V60C*	45,500	\$6,370
207436552	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SL297UH080NV48C*	46,000	\$6,440
207436553	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SL297UH080NV60C*	46,000	\$6,440
207436554	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SLP99UH090XV48C*	46,000	\$6,440
207436561	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	EL296UH090XV60C*	46,000	\$6,440
207436565	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SL280UH090V60C*	45,500	\$6,370

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207436568	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SL280UH110V60C*	45,500	\$6,370
207436574	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SLP99UH110XV60C*	46,000	\$6,440
207436577	LENNOX	SL25XPV-048-230A**	CHX35-60D-**-**+TDR	SLP99UH135XV60D*	42,000	\$5,880
207436578	LENNOX	SL25XPV-048-230A**	CR33-50/60+TDR+TXV	EL296DF090XV60C*	41,000	\$5,740
207436591	LENNOX	SL25XPV-048-230A**	CX35-49C+TDR	SL280UH090V60C*	43,000	\$6,020
207436606	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SL280UH090V60C*	42,000	\$5,880
207768727	LENNOX	MLB018S4M-1P	Heat pump without ducts		15,000	\$2,100
211034450	LENNOX	MLB012S4S-1P	MFMA012S4-*P		9,600	\$1,344
207436147	LENNOX	SL25XPV-024-230A**	C35-36A+TDR+TXV	SL280UH070XV36A*	24,200	\$3,388
207436150	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	SL280UH080NV48B*	24,200	\$3,388
207436152	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	SL280UH090V48B*	24,200	\$3,388
207436157	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	EL296UH045XV36B*	24,200	\$3,388
207436162	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	SL280UH090XV48B*	24,200	\$3,388
207436168	LENNOX	SL25XPV-024-230A**	CH35-42B+TDR+TXV	EL296UH045XV36B*	23,600	\$3,304
207436171	LENNOX	SL25XPV-024-230A**	CH35-42B+TDR+TXV	SL280UH090V36B*	23,400	\$3,276
207436172	LENNOX	SL25XPV-024-230A**	CH35-42B+TDR+TXV	SL280UH090V48B*	23,600	\$3,304
207436175	LENNOX	SL25XPV-024-230A**	CH35-42B+TDR+TXV	SL297UH060NV36B*	23,600	\$3,304
207436182	LENNOX	SL25XPV-024-230A**	CH35-42C+TDR+TXV	SL280UH080NV60C*	23,600	\$3,304
207436194	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	EL296UH045XV36B*	23,600	\$3,304
207436195	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	EL296UH070XV36B*	23,600	\$3,304
207436197	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	SL280UH090V36B*	23,400	\$3,276
207436204	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	EL296UH090XV48C*	23,800	\$3,332
207436231	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	EL296UH045XV36B*	24,200	\$3,388
207436232	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	EL296UH070XV36B*	24,200	\$3,388
207436244	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	SL280UH090V48B*	24,200	\$3,388
207436261	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	EL296UH045XV36B*	33,400	\$4,676
207436262	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	EL296UH070XV36B*	33,400	\$4,676
207436263	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	SL280UH080NV48B*	33,000	\$4,620
207436264	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	SL280UH090V36B*	33,200	\$4,648
207436270	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL296UH090XV36C*	33,200	\$4,648
207436274	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL296UH110XV60C*	33,200	\$4,648
207436275	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SL280UH080NV60C*	33,000	\$4,620
207436276	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SL280UH090V60C*	33,000	\$4,620
207436278	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SL280UH100NV60C*	32,800	\$4,592
207436280	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SL280UH110XV60C*	33,000	\$4,620
207436284	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SLP99UH090XV48C*	33,200	\$4,648
207436300	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SL280UH110XV60C*	30,600	\$4,284
207436333	LENNOX	SL25XPV-036-230A**	CH35-42B+TDR+TXV	SL280UH090V48B*	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207436336	LENNOX	SL25XPV-036-230A**	CH35-42B+TDR+TXV	SL297UH060NV36B*	30,600	\$4,284
207436359	LENNOX	SL25XPV-036-230A**	CH35-48B+TDR+TXV	SL280UH090V48B*	31,200	\$4,368
207436360	LENNOX	SL25XPV-036-230A**	CH35-48B+TDR+TXV	SL280UH090XV48B*	31,200	\$4,368
207436385	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	SL280UH090V48B*	30,600	\$4,284
207436386	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	SL280UH090XV48B*	30,600	\$4,284
207436407	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	EL296UH045XV36B*	31,400	\$4,396
207436473	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	SL280UH090XV48B*	33,200	\$4,648
207436488	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SL297UH080NV48C*	33,000	\$4,620
207436489	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SL297UH080NV60C*	33,200	\$4,648
207436493	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SLP99UH110XV60C*	33,200	\$4,648
207436495	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL296UH090XV48C*	30,600	\$4,284
207436496	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL296UH090XV60C*	30,600	\$4,284
207436501	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SL280UH090XV60C*	30,600	\$4,284
207436506	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SL297UH080NV60C*	30,600	\$4,284
207436508	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SLP99UH090XV48C*	30,600	\$4,284
207436509	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SLP99UH090XV60C*	30,600	\$4,284
207436510	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SLP99UH110XV60C*	30,600	\$4,284
207436533	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SL280UH100NV60C*	42,000	\$5,880
207436534	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SL280UH110V60C*	42,000	\$5,880
207436541	LENNOX	SL25XPV-048-230A**	CBA38MV-048-230*+TDR		45,500	\$6,370
207436546	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SL280UH080NV60C*	45,500	\$6,370
207436555	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SLP99UH090XV60C*	46,000	\$6,440
207436559	LENNOX	SL25XPV-048-230A**	CH35-60D+TDR+TXV	SLP99UH135XV60D*	42,000	\$5,880
207436560	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	EL296UH090XV48C*	46,000	\$6,440
207436563	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	EL296UH110XV60C*	46,000	\$6,440
207436566	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SL280UH090XV60C*	45,500	\$6,370
207436569	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SL280UH110XV60C*	45,500	\$6,370
207436572	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SLP99UH090XV48C*	46,000	\$6,440
207436576	LENNOX	SL25XPV-048-230A**	CHX35-60D-**-**+TDR	SL280UH135V60D*	42,000	\$5,880
207436581	LENNOX	SL25XPV-048-230A**	CR33-50/60+TDR+TXV	SL280DF090V60C*	41,000	\$5,740
207436582	LENNOX	SL25XPV-048-230A**	CR33-50/60+TDR+TXV	SL280DF110V60C*	41,000	\$5,740
207436583	LENNOX	SL25XPV-048-230A**	CR33-50/60+TDR+TXV	SLP99DF090XV48C*	41,000	\$5,740
207436602	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	EL296UH090XV60C*	42,500	\$5,950
207436604	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	EL296UH110XV60C*	42,500	\$5,950
207436605	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SL280UH080NV60C*	42,000	\$5,880
207436607	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SL280UH090XV60C*	42,000	\$5,880
207436608	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SL280UH100NV60C*	42,000	\$5,880
207436609	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SL280UH110V60C*	42,000	\$5,880

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207436611	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SL297UH080NV48C*	42,000	\$5,880
207574744	LENNOX	SL25XPV-036-230A**	CBA38MV-042-230*+TDR		31,800	\$4,452
207436206	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	EL296UH110XV48C*	23,800	\$3,332
207436239	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	SLP99UH070XV36B*	24,200	\$3,388
207436357	LENNOX	SL25XPV-036-230A**	CH35-48B+TDR+TXV	SL280UH080NV48B*	31,000	\$4,340
207436497	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL296UH110XV48C*	30,600	\$4,284
207436601	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	EL296UH090XV48C*	42,500	\$5,950
207436142	LENNOX	SL25XPV-024-230A**	CBA38MV-042-230*+TDR		25,200	\$3,528
207436149	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	EL296UH070XV36B*	24,200	\$3,388
207436163	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	SL297UH040NV36B*	24,200	\$3,388
207436164	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	SL297UH060NV36B*	24,200	\$3,388
207436180	LENNOX	SL25XPV-024-230A**	CH35-42C+TDR+TXV	EL296UH110XV48C*	23,800	\$3,332
207436217	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	SLP99UH090XV48C*	23,800	\$3,332
207436229	LENNOX	SL25XPV-024-230A**	CX35-36A+TDR	SL280UH060NV36A*	24,200	\$3,388
207436234	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	SL280UH090V36B*	24,200	\$3,388
207436236	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	SL280UH090XV48B*	24,200	\$3,388
207436237	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	SL297UH040NV36B*	24,200	\$3,388
207436241	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	EL296UH070XV36B*	24,200	\$3,388
207436247	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	SL297UH060NV36B*	24,200	\$3,388
207436265	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	SL280UH090V48B*	33,200	\$4,648
207436266	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	SL280UH090XV48B*	33,200	\$4,648
207436285	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SLP99UH090XV60C*	33,200	\$4,648
207436289	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL296UH090XV60C*	30,600	\$4,284
207436291	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL296UH110XV60C*	30,600	\$4,284
207436292	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SL280UH080NV60C*	30,400	\$4,256
207436305	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SL297UH080NV60C*	30,600	\$4,284
207436327	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SLP99UH110XV60C*	30,600	\$4,284
207436355	LENNOX	SL25XPV-036-230A**	CH35-48B+TDR+TXV	EL296UH045XV36B*	31,400	\$4,396
207436358	LENNOX	SL25XPV-036-230A**	CH35-48B+TDR+TXV	SL280UH090V36B*	31,000	\$4,340
207436361	LENNOX	SL25XPV-036-230A**	CH35-48B+TDR+TXV	SL297UH040NV36B*	31,200	\$4,368
207436362	LENNOX	SL25XPV-036-230A**	CH35-48B+TDR+TXV	SL297UH060NV36B*	31,400	\$4,396
207436383	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	SL280UH080NV48B*	30,400	\$4,256
207436415	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	SLP99UH070XV36B*	31,400	\$4,396
207436469	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	EL296UH070XV36B*	33,400	\$4,676
207436476	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	SLP99UH070XV36B*	33,400	\$4,676
207436479	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL296UH090XV60C*	33,200	\$4,648
207436480	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL296UH110XV48C*	33,000	\$4,620
207436482	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SL280UH080NV60C*	33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207436494	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL296UH090XV36C*	30,800	\$4,312
207436500	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SL280UH090V60C*	30,600	\$4,284
207436505	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SL297UH080NV48C*	30,600	\$4,284
207436526	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	EL296UH090XV48C*	42,500	\$5,950
207436527	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	EL296UH090XV60C*	42,500	\$5,950
207436528	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	EL296UH110XV48C*	42,500	\$5,950
207436530	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SL280UH080NV60C*	42,000	\$5,880
207436531	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SL280UH090V60C*	42,000	\$5,880
207436532	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SL280UH090XV60C*	42,000	\$5,880
207436535	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SL280UH110XV60C*	42,000	\$5,880
207436545	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	EL296UH110XV60C*	46,000	\$6,440
207436548	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SL280UH090XV60C*	45,500	\$6,370
207436549	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SL280UH100NV60C*	45,500	\$6,370
207436551	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SL280UH110XV60C*	45,500	\$6,370
207436557	LENNOX	SL25XPV-048-230A**	CH35-60D+TDR+TXV	EL296UH135XV60D*	42,000	\$5,880
207436558	LENNOX	SL25XPV-048-230A**	CH35-60D+TDR+TXV	SL280UH135V60D*	42,000	\$5,880
207436562	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	EL296UH110XV48C*	46,000	\$6,440
207436564	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SL280UH080NV60C*	45,500	\$6,370
207436567	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SL280UH100NV60C*	45,500	\$6,370
207436570	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SL297UH080NV48C*	46,000	\$6,440
207436571	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SL297UH080NV60C*	46,000	\$6,440
207436573	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	SLP99UH090XV60C*	46,000	\$6,440
207436575	LENNOX	SL25XPV-048-230A**	CHX35-60D-**-**+TDR	EL296UH135XV60D*	42,000	\$5,880
207436580	LENNOX	SL25XPV-048-230A**	CR33-50/60+TDR+TXV	SL280DF080NV60C*	41,000	\$5,740
207436592	LENNOX	SL25XPV-048-230A**	CX35-49C+TDR	SL280UH090XV60C*	43,000	\$6,020
207436603	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	EL296UH110XV48C*	42,500	\$5,950
207436612	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SL297UH080NV60C*	42,000	\$5,880
207436613	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SLP99UH090XV48C*	42,500	\$5,950
207436614	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SLP99UH090XV60C*	42,500	\$5,950
207436615	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SLP99UH110XV60C*	42,500	\$5,950
10528570	LENNOX	MLA012S4S-1P	MMDB012S4-2P		10,600	\$1,484
207436153	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	SL280UH090XV48B*	24,200	\$3,388
207436155	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	SL297UH060NV36B*	24,200	\$3,388
207436158	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	EL296UH070XV36B*	24,200	\$3,388
207436160	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	SL280UH090V36B*	24,200	\$3,388
207436161	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	SL280UH090V48B*	24,200	\$3,388
207436170	LENNOX	SL25XPV-024-230A**	CH35-42B+TDR+TXV	SL280UH080NV48B*	23,400	\$3,276
207436173	LENNOX	SL25XPV-024-230A**	CH35-42B+TDR+TXV	SL280UH090XV48B*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207436176	LENNOX	SL25XPV-024-230A**	CH35-42B+TDR+TXV	SLP99UH070XV36B*	23,600	\$3,304
207436196	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	SL280UH080NV48B*	23,400	\$3,276
207436202	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	SLP99UH070XV36B*	23,600	\$3,304
207436203	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	EL296UH090XV36C*	23,800	\$3,332
207436208	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	SL280UH080NV60C*	23,600	\$3,304
207436216	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	SLP99UH090XV36C*	23,800	\$3,332
207436230	LENNOX	SL25XPV-024-230A**	CX35-36A+TDR	SL280UH070XV36A*	24,200	\$3,388
207436233	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	SL280UH080NV48B*	24,200	\$3,388
207436235	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	SL280UH090V48B*	24,200	\$3,388
207436238	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	SL297UH060NV36B*	24,200	\$3,388
207436245	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	SL280UH090XV48B*	24,200	\$3,388
207436248	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	SLP99UH070XV36B*	24,200	\$3,388
207436267	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	SL297UH040NV36B*	33,400	\$4,676
207436268	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	SL297UH060NV36B*	33,400	\$4,676
207436273	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL296UH110XV48C*	33,000	\$4,620
207436277	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SL280UH090XV60C*	33,000	\$4,620
207436279	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SL280UH110V60C*	33,000	\$4,620
207436286	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SLP99UH110XV60C*	33,200	\$4,648
207436295	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SL280UH100NV60C*	30,400	\$4,256
207436297	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SL280UH110V60C*	30,600	\$4,284
207436302	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SL297UH080NV48C*	30,600	\$4,284
207436329	LENNOX	SL25XPV-036-230A**	CH35-42B+TDR+TXV	EL296UH045XV36B*	30,800	\$4,312
207436331	LENNOX	SL25XPV-036-230A**	CH35-42B+TDR+TXV	SL280UH080NV48B*	30,400	\$4,256
207436332	LENNOX	SL25XPV-036-230A**	CH35-42B+TDR+TXV	SL280UH090V36B*	30,400	\$4,256
207436334	LENNOX	SL25XPV-036-230A**	CH35-42B+TDR+TXV	SL280UH090XV48B*	30,600	\$4,284
207436335	LENNOX	SL25XPV-036-230A**	CH35-42B+TDR+TXV	SL297UH040NV36B*	30,600	\$4,284
207436381	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	EL296UH045XV36B*	30,800	\$4,312
207436384	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	SL280UH090V36B*	30,400	\$4,256
207436408	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	EL296UH070XV36B*	31,400	\$4,396
207436409	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	SL280UH080NV48B*	31,000	\$4,340
207436413	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	SL297UH040NV36B*	31,200	\$4,368
207436468	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	EL296UH045XV36B*	33,400	\$4,676
207436474	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	SL297UH040NV36B*	33,400	\$4,676
207436475	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	SL297UH060NV36B*	33,400	\$4,676
207436481	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL296UH110XV60C*	33,200	\$4,648
207436486	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SL280UH110V60C*	33,000	\$4,620
207436487	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SL280UH110XV60C*	33,000	\$4,620
207436490	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	SLP99UH090XV36C*	33,200	\$4,648

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207436498	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL296UH110XV60C*	30,600	\$4,284
207436499	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SL280UH080NV60C*	30,400	\$4,256
207436502	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SL280UH100NV60C*	30,400	\$4,256
207436504	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	SL280UH110XV60C*	30,600	\$4,284
207436517	LENNOX	SL25XPV-048-230A**	C35-49C+TDR+TXV	SL280UH090XV60C*	43,000	\$6,020
207436529	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	EL296UH110XV60C*	42,500	\$5,950
207436536	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SL297UH080NV48C*	42,000	\$5,880
207436537	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SL297UH080NV60C*	42,000	\$5,880
207436538	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SLP99UH090XV48C*	42,500	\$5,950
207436539	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	SLP99UH090XV60C*	42,500	\$5,950
207436543	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	EL296UH090XV60C*	46,000	\$6,440
207436550	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SL280UH110V60C*	45,500	\$6,370
207436556	LENNOX	SL25XPV-048-230A**	CH35-51C+TDR+TXV	SLP99UH110XV60C*	46,000	\$6,440
207436579	LENNOX	SL25XPV-048-230A**	CR33-50/60+TDR+TXV	EL296DF110XV60C*	41,000	\$5,740
207436584	LENNOX	SL25XPV-048-230A**	CR33-50/60+TDR+TXV	SLP99DF090XV60C*	41,000	\$5,740
207436585	LENNOX	SL25XPV-048-230A**	CR33-50/60+TDR+TXV	SLP99DF110XV60C*	41,000	\$5,740
207436610	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	SL280UH110XV60C*	42,000	\$5,880
201771989	LENNOX	MLA036S4M-1P	Heat pump without ducts		16,800	\$2,352
207699107	LENNOX	MLB048S4M-2P	Heat pump without ducts		36,000	\$5,040
207683530	LENNOX	MLB024S4S-1P	MCFA024S4-2P		19,000	\$2,660
211034447	LENNOX	MLB024S4S-1P	MMDB024S4-*P		21,000	\$2,940
211034452	LENNOX	MLB024S4S-1P	MCFA024S4-*P		19,000	\$2,660
207683527	LENNOX	MLB024S4S-1P	MMDB024S4-2P		21,000	\$2,940
207699108	LENNOX	MLB048S4M-2P	MMDB009S4-2P		36,000	\$5,040
207699104	LENNOX	MLB036S4M-1P	Heat pump without ducts		33,000	\$4,620
207768728	LENNOX	MLB018S4M-1P	Heat pump with ducts		16,000	\$2,240
214626266	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SL280UH110XV60C*	42,000	\$5,880
214626204	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SL280UH110XV60C*	30,600	\$4,284
214626202	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SL280UH100NV60C*	30,400	\$4,256
214626199	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SL280UH080NV60C*	30,400	\$4,256
214626185	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SLP99UH090XV36C*	33,200	\$4,648
214626182	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SL280UH110XV60C*	33,000	\$4,620
214626181	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SL280UH110V60C*	33,000	\$4,620
214626165	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	SL297UH060NV36B*	33,400	\$4,676
214626164	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	SL297UH040NV36B*	33,400	\$4,676
214626109	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	SL297UH040NV36B*	31,200	\$4,368
214626105	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	SL280UH080NV48B*	31,000	\$4,340
214626073	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	SL280UH090V36B*	30,400	\$4,256

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214626067	LENNOX	SL25XPV-024-230A**	CK40CT-48B-0*+TDR	SLP99UH070XV36B*	24,200	\$3,388
214626064	LENNOX	SL25XPV-024-230A**	CK40CT-48B-0*+TDR	SL280UH090XV48B*	24,200	\$3,388
214626055	LENNOX	SL25XPV-024-230A**	CK40CT-36B-0*+TDR	SL297UH060NV36B*	24,200	\$3,388
214626052	LENNOX	SL25XPV-024-230A**	CK40CT-36B-0*+TDR	SL280UH090V48B*	24,200	\$3,388
214626050	LENNOX	SL25XPV-024-230A**	CK40CT-36B-0*+TDR	SL280UH080NV48B*	24,200	\$3,388
214626045	LENNOX	SL25XPV-024-230A**	CK40CT-36A-0*+TDR	SL280UH070XV36A*	24,200	\$3,388
214626040	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	SLP99UH090XV36C*	23,800	\$3,332
214626038	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	SL280UH080NV60C*	23,600	\$3,304
214626031	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	SLP99UH070XV36B*	23,600	\$3,304
214626025	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	SL280UH080NV48B*	23,400	\$3,276
214626271	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SLP99UH110XV60C*	42,500	\$5,950
214626270	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SLP99UH090XV60C*	42,500	\$5,950
214626269	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SLP99UH090XV48C*	42,500	\$5,950
214626268	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SL297UH080NV60C*	42,000	\$5,880
214626244	LENNOX	SL25XPV-048-230A**	CK40CT-49C-0*+TDR	SL280UH090XV60C*	43,000	\$6,020
214626228	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SLP99UH090XV60C*	46,000	\$6,440
214626226	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SL297UH080NV60C*	46,000	\$6,440
214626225	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SL297UH080NV48C*	46,000	\$6,440
214626222	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SL280UH100NV60C*	45,500	\$6,370
214626219	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SL280UH080NV60C*	45,500	\$6,370
214626205	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SL297UH080NV48C*	30,600	\$4,284
214626200	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SL280UH090V60C*	30,600	\$4,284
214626177	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SL280UH080NV60C*	33,000	\$4,620
214626166	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	SLP99UH070XV36B*	33,400	\$4,676
214626111	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	SLP99UH070XV36B*	31,400	\$4,396
214626072	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	SL280UH080NV48B*	30,400	\$4,256
214626066	LENNOX	SL25XPV-024-230A**	CK40CT-48B-0*+TDR	SL297UH060NV36B*	24,200	\$3,388
214626054	LENNOX	SL25XPV-024-230A**	CK40CT-36B-0*+TDR	SL297UH040NV36B*	24,200	\$3,388
214626053	LENNOX	SL25XPV-024-230A**	CK40CT-36B-0*+TDR	SL280UH090XV48B*	24,200	\$3,388
214626051	LENNOX	SL25XPV-024-230A**	CK40CT-36B-0*+TDR	SL280UH090V36B*	24,200	\$3,388
214626044	LENNOX	SL25XPV-024-230A**	CK40CT-36A-0*+TDR	SL280UH060NV36A*	24,200	\$3,388
214626041	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	SLP99UH090XV48C*	23,800	\$3,332
214626056	LENNOX	SL25XPV-024-230A**	CK40CT-36B-0*+TDR	SLP99UH070XV36B*	24,200	\$3,388
214626267	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SL297UH080NV48C*	42,000	\$5,880
214626265	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SL280UH110V60C*	42,000	\$5,880
214626264	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SL280UH100NV60C*	42,000	\$5,880
214626263	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SL280UH090XV60C*	42,000	\$5,880
214626261	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SL280UH080NV60C*	42,000	\$5,880

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214626232	LENNOX	SL25XPV-048-230A**	CK40HT-60D-0*+TDR	SL280UH135V60D*	42,000	\$5,880
214626227	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SLP99UH090XV48C*	46,000	\$6,440
214626224	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SL280UH110XV60C*	45,500	\$6,370
214626221	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SL280UH090XV60C*	45,500	\$6,370
214626210	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SLP99UH110XV60C*	30,600	\$4,284
214626209	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SLP99UH090XV60C*	30,600	\$4,284
214626208	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SLP99UH090XV48C*	30,600	\$4,284
214626206	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SL297UH080NV60C*	30,600	\$4,284
214626201	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SL280UH090XV60C*	30,600	\$4,284
214626188	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SLP99UH110XV60C*	33,200	\$4,648
214626184	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SL297UH080NV60C*	33,200	\$4,648
214626183	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SL297UH080NV48C*	33,000	\$4,620
214626163	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	SL280UH090XV48B*	33,200	\$4,648
214626075	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	SL280UH090XV48B*	30,600	\$4,284
214626074	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	SL280UH090V48B*	30,600	\$4,284
214626063	LENNOX	SL25XPV-024-230A**	CK40CT-48B-0*+TDR	SL280UH090V48B*	24,200	\$3,388
214626026	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	SL280UH090V36B*	23,400	\$3,276
214626262	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	SL280UH090V60C*	42,000	\$5,880
214626243	LENNOX	SL25XPV-048-230A**	CK40CT-49C-0*+TDR	SL280UH090V60C*	43,000	\$6,020
214626233	LENNOX	SL25XPV-048-230A**	CK40HT-60D-0*+TDR	SLP99UH135XV60D*	42,000	\$5,880
214626229	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SLP99UH110XV60C*	46,000	\$6,440
214626223	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SL280UH110V60C*	45,500	\$6,370
214626220	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	SL280UH090V60C*	45,500	\$6,370
214626207	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SLP99UH090XV36C*	30,800	\$4,312
214626203	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	SL280UH110V60C*	30,600	\$4,284
214626187	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SLP99UH090XV60C*	33,200	\$4,648
214626186	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SLP99UH090XV48C*	33,200	\$4,648
214626180	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SL280UH100NV60C*	32,800	\$4,592
214626179	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SL280UH090XV60C*	33,000	\$4,620
214626178	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	SL280UH090V60C*	33,000	\$4,620
214626162	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	SL280UH090V48B*	33,200	\$4,648
214626161	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	SL280UH090V36B*	33,200	\$4,648
214626160	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	SL280UH080NV48B*	33,000	\$4,620
214626110	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	SL297UH060NV36B*	31,400	\$4,396
214626108	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	SL280UH090XV48B*	31,200	\$4,368
214626107	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	SL280UH090V48B*	31,200	\$4,368
214626106	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	SL280UH090V36B*	31,000	\$4,340
214626078	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	SLP99UH070XV36B*	30,800	\$4,312

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214626077	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	SL297UH060NV36B*	30,600	\$4,284
214626076	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	SL297UH040NV36B*	30,600	\$4,284
214626065	LENNOX	SL25XPV-024-230A**	CK40CT-48B-0*+TDR	SL297UH040NV36B*	24,200	\$3,388
214626062	LENNOX	SL25XPV-024-230A**	CK40CT-48B-0*+TDR	SL280UH090V36B*	24,200	\$3,388
214626039	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	SL297UH080NV48C*	23,800	\$3,332
214626030	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	SL297UH060NV36B*	23,600	\$3,304
214626029	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	SL297UH040NV36B*	23,400	\$3,276
214626028	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	SL280UH090XV48B*	23,600	\$3,304
214626027	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	SL280UH090V48B*	23,600	\$3,304
216769626	LENNOX	EL18KSLV-060-230A**	CK40HT-60D-***+TDR	EL297UH135XV60D*	44,000	\$6,160
216769625	LENNOX	EL18KSLV-060-230A**	CK40DT-60D-***+TDR	EL297DF110XV60C*	44,000	\$6,160
216769624	LENNOX	EL18KSLV-060-230A**	CK40DT-60D-***+TDR	EL297DF090XV60C*	44,000	\$6,160
216769623	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-60D-***+TDR	EL297UH135XV60D*	44,000	\$6,160
216769622	LENNOX	EL18KSLV-060-230A**	CK40HT-51/61C-***+TDR	EL297UH090XV60C*	44,500	\$6,230
216769621	LENNOX	EL18KSLV-060-230A**	CK40HT-51/61C-***+TDR	EL297UH110XV60C*	44,000	\$6,160
216769620	LENNOX	EL18KSLV-060-230A**	CK40HT-51/61C-***+TDR	SL297UH080NV60C*	44,500	\$6,230
216769619	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-60C-***+TDR	EL297UH090XV60C*	44,000	\$6,160
216769618	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-60C-***+TDR	EL297UH110XV60C*	43,500	\$6,090
216769617	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-60C-***+TDR	SL297UH080NV60C*	44,000	\$6,160
216769616	LENNOX	EL18KSLV-060-230A**	CK40DT-48C-***+TDR	EL297DF110XV60C*	39,500	\$5,530
216769615	LENNOX	EL18KSLV-060-230A**	CK40DT-48C-***+TDR	EL297DF090XV60C*	39,500	\$5,530
216769613	LENNOX	EL18KSLV-060-230A**	CK40HT-48C-***+TDR	EL297UH110XV60C*	39,500	\$5,530
216769612	LENNOX	EL18KSLV-060-230A**	CK40HT-48C-***+TDR	SL297UH080NV60C*	39,500	\$5,530
216769611	LENNOX	EL18KSLV-060-230A**	CK40HT-42C-***+TDR	EL297UH090XV60C*	39,500	\$5,530
216769610	LENNOX	EL18KSLV-060-230A**	CK40HT-42C-***+TDR	EL297UH110XV60C*	39,500	\$5,530
216769609	LENNOX	EL18KSLV-060-230A**	CK40HT-42C-***+TDR	SL297UH080NV60C*	39,500	\$5,530
216769608	LENNOX	EL18KSLV-060-230A**	CK40HT-42C-***+TDR	SL297UH080NV48C*	39,500	\$5,530
216769607	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-49C-***+TDR	EL297UH090XV60C*	39,500	\$5,530
216769606	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-49C-***+TDR	EL297UH110XV60C*	39,000	\$5,460
216769605	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-49C-***+TDR	SL297UH080NV60C*	39,000	\$5,460
216769604	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-49C-***+TDR	SL297UH080NV48C*	39,000	\$5,460
216769603	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-48C-***+TDR	EL297UH090XV60C*	39,500	\$5,530
216769602	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-48C-***+TDR	EL297UH110XV60C*	39,500	\$5,530
216769601	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-48C-***+TDR	SL297UH080NV60C*	39,500	\$5,530
216769600	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-48C-***+TDR	SL297UH080NV48C*	39,500	\$5,530
216769614	LENNOX	EL18KSLV-060-230A**	CK40DT-42B-***+TDR	EL297DF070XV48B*	40,000	\$5,600
216769599	LENNOX	EL18KSLV-036-230A**	CK40DT-42B-***+TDR	EL297DF070XV48B*	29,000	\$4,060
216769598	LENNOX	EL18KSLV-036-230A**	CK40DT-30/36B-***+TDR	EL297DF070XV48B*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216769597	LENNOX	EL18KSLV-036-230A**	CK40HT-36C-***+TDR	SL297UH080NV48C*	28,600	\$4,004
216769596	LENNOX	EL18KSLV-036-230A**	CK40HT-36C-***+TDR	EL297UH090XV36C*	28,600	\$4,004
216769595	LENNOX	EL18KSLV-036-230A**	CK40HT-36B-***+TDR	EL297UH070XV36B*	28,800	\$4,032
216769594	LENNOX	EL18KSLV-036-230A**	CK40HT-36B-***+TDR	EL297UH045XV36B*	28,800	\$4,032
216769593	LENNOX	EL18KSLV-036-230A**	CK40HT-36B-***+TDR	SL297UH060NV36B*	28,800	\$4,032
216769592	LENNOX	EL18KSLV-036-230A**	CK40HT-36B-***+TDR	SL297UH040NV36B*	28,800	\$4,032
216769591	LENNOX	EL18KSLV-036-230A**	CK40HT-30B-***+TDR	EL297UH070XV36B*	28,800	\$4,032
216769579	LENNOX	EL18KSLV-024-230A**	CK40HT-30B-***+TDR	EL297UH070XV36B*	19,800	\$2,772
216769590	LENNOX	EL18KSLV-036-230A**	CK40HT-30B-***+TDR	EL297UH045XV36B*	28,800	\$4,032
216769578	LENNOX	EL18KSLV-024-230A**	CK40HT-30B-***+TDR	EL297UH045XV36B*	19,800	\$2,772
216769589	LENNOX	EL18KSLV-036-230A**	CK40HT-30B-***+TDR	SL297UH060NV36B*	28,800	\$4,032
216769577	LENNOX	EL18KSLV-024-230A**	CK40HT-30B-***+TDR	SL297UH060NV36B*	19,800	\$2,772
216769588	LENNOX	EL18KSLV-036-230A**	CK40HT-30B-***+TDR	SL297UH040NV36B*	28,800	\$4,032
216769576	LENNOX	EL18KSLV-024-230A**	CK40HT-30B-***+TDR	SL297UH040NV36B*	19,800	\$2,772
216769575	LENNOX	EL18KSLV-024-230A**	CK40HT-24B-***+TDR	EL297UH070XV36B*	19,800	\$2,772
216769574	LENNOX	EL18KSLV-024-230A**	CK40HT-24B-***+TDR	EL297UH045XV36B*	19,800	\$2,772
216769573	LENNOX	EL18KSLV-024-230A**	CK40HT-24B-***+TDR	SL297UH060NV36B*	19,800	\$2,772
216769572	LENNOX	EL18KSLV-024-230A**	CK40HT-24B-***+TDR	SL297UH040NV36B*	19,800	\$2,772
216769587	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-36B-***+TDR	EL297UH070XV36B*	28,800	\$4,032
216769571	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-36B-***+TDR	EL297UH070XV36B*	19,800	\$2,772
216769586	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-36B-***+TDR	EL297UH045XV36B*	28,800	\$4,032
216769570	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-36B-***+TDR	EL297UH045XV36B*	19,800	\$2,772
216769585	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-36B-***+TDR	SL297UH060NV36B*	28,800	\$4,032
216769569	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-36B-***+TDR	SL297UH060NV36B*	19,800	\$2,772
216769584	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-36B-***+TDR	SL297UH040NV36B*	28,800	\$4,032
216769568	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-36B-***+TDR	SL297UH040NV36B*	19,800	\$2,772
216769583	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-30B-***+TDR	EL297UH070XV36B*	28,800	\$4,032
216769567	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-30B-***+TDR	EL297UH070XV36B*	19,800	\$2,772
216769582	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-30B-***+TDR	EL297UH045XV36B*	29,000	\$4,060
216769566	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-30B-***+TDR	EL297UH045XV36B*	19,800	\$2,772
216769581	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-30B-***+TDR	SL297UH060NV36B*	29,000	\$4,060
216769565	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-30B-***+TDR	SL297UH060NV36B*	19,800	\$2,772
216769580	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-30B-***+TDR	SL297UH040NV36B*	28,800	\$4,032
216769564	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-30B-***+TDR	SL297UH040NV36B*	19,800	\$2,772
216581389	LENNOX	EL18KSLV-036-230A**	CBK45UHVT-036-230-**		28,000	\$3,920
216581388	LENNOX	EL18KSLV-024-230A**	CBK45UHVT-024-230-**		18,000	\$2,520
216618955	LENNOX	EL18KSLV-060-230A**	CK40DT-60D-***+TDR		43,500	\$6,090
216618954	LENNOX	EL18KSLV-060-230A**	CK40DT-50/60C-***+TDR		43,500	\$6,090

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216618953	LENNOX	EL18KSLV-060-230A**	CK40HT-60D-***+TDR		43,500	\$6,090
216618952	LENNOX	EL18KSLV-060-230A**	CK40HT-51/61C-***+TDR		43,500	\$6,090
216618951	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-60D-***+TDR		42,000	\$5,880
216618950	LENNOX	EL18KSLV-060-230A**	CK40DT-48C-***+TDR		40,000	\$5,600
216618949	LENNOX	EL18KSLV-060-230A**	CK40DT-42B-***+TDR		40,500	\$5,670
216618947	LENNOX	EL18KSLV-060-230A**	CK40HT-48B-***+TDR		40,500	\$5,670
216618946	LENNOX	EL18KSLV-060-230A**	CK40HT-42C-***+TDR		40,500	\$5,670
216618945	LENNOX	EL18KSLV-060-230A**	CK40HT-42B-***+TDR		40,000	\$5,600
216618944	LENNOX	EL18KSLV-060-230A**	CK40[C,U]T-49C-***+TDR		40,000	\$5,600
216618921	LENNOX	EL18KSLV-060-230A**	CBK48MVT-060-230-**		43,500	\$6,090
216618920	LENNOX	EL18KSLV-060-230A**	CBK45UHET-060-230-**		43,000	\$6,020
216618919	LENNOX	EL18KSLV-060-230A**	CBK48MVT-048-230-**		38,000	\$5,320
216618918	LENNOX	EL18KSLV-060-230A**	CBK48MVT-042-230-**		38,500	\$5,390
216618917	LENNOX	EL18KSLV-060-230A**	CBK45UHET-048-230-**		39,000	\$5,460
216618916	LENNOX	EL18KSLV-060-230A**	CBK45UHVT-042-230-**		38,500	\$5,390
216618915	LENNOX	EL18KSLV-060-230A**	CBK45UHET-042-230-**		39,000	\$5,460
216618942	LENNOX	EL18KSLV-036-230A**	CK40DT-42B-***+TDR		28,000	\$3,920
216618941	LENNOX	EL18KSLV-036-230A**	CK40DT-30/36B-***+TDR		28,000	\$3,920
216618940	LENNOX	EL18KSLV-036-230A**	CK40HT-36C-***+TDR		28,000	\$3,920
216618938	LENNOX	EL18KSLV-036-230A**	CK40HT-36A-***+TDR		28,400	\$3,976
216618937	LENNOX	EL18KSLV-036-230A**	CK40HT-30B-***+TDR		28,000	\$3,920
216618936	LENNOX	EL18KSLV-036-230A**	CK40HT-30A-***+TDR		28,000	\$3,920
216618935	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-36A-***+TDR		28,000	\$3,920
216618934	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-30B-***+TDR		28,000	\$3,920
216618933	LENNOX	EL18KSLV-036-230A**	CK40[C,U]T-30A-***+TDR		28,000	\$3,920
216618914	LENNOX	EL18KSLV-036-230A**	CBK48MVT-042-230-**		28,000	\$3,920
216618913	LENNOX	EL18KSLV-036-230A**	CBK48MVT-036-230-**		28,000	\$3,920
216618912	LENNOX	EL18KSLV-036-230A**	CBK45UHVT-042-230-**		28,000	\$3,920
216618911	LENNOX	EL18KSLV-036-230A**	CBK45UHET-042-230-**		28,000	\$3,920
216618910	LENNOX	EL18KSLV-036-230A**	CBK45UHPT-042-230-**		28,400	\$3,976
216618909	LENNOX	EL18KSLV-036-230A**	CBK45UHET-036-230-**		28,000	\$3,920
216618908	LENNOX	EL18KSLV-036-230A**	CBK45UHPT-036-230-**		28,400	\$3,976
216618929	LENNOX	EL18KSLV-024-230A**	CK40HT-30A-***+TDR		19,600	\$2,744
216618927	LENNOX	EL18KSLV-024-230A**	CK40HT-24A-***+TDR		19,600	\$2,744
216618925	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-36B-***+TDR		19,600	\$2,744
216618924	LENNOX	EL18KSLV-024-230A**	CK40[C,U]T-36A-***+TDR		19,600	\$2,744
216618907	LENNOX	EL18KSLV-024-230A**	CBK48MVT-030-230-**		19,400	\$2,716
216618906	LENNOX	EL18KSLV-024-230A**	CBK48MVT-018/024-230-**		19,600	\$2,744

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216618903	LENNOX	EL18KSLV-024-230A**	CBK45UHET-024-230-**		19,200	\$2,688
216618902	LENNOX	EL18KSLV-024-230A**	CBK45UHPT-024-230-**		19,600	\$2,744
216379010	Lennox	SL22KLV-024-230A**	CBK48MVT-042-230-**		24,000	\$3,360
215810033	LENNOX	MMLD048S6S-1P	MDDD048S6-1P		41,000	\$5,740
215810026	LENNOX	MMLD018S6S-1P	MMDD018S6-1P		16,200	\$2,268
215810027	LENNOX	MMLD018S6S-1P	M22D018S6-1P		15,600	\$2,184
215810023	LENNOX	MMLD018S6S-1P	M1WD018S6-1P		16,000	\$2,240
216411316	LENNOX	MWHD012S6S-1P	MWHD012S6-1P		10,900	\$1,526
214626215	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	EL297UH090XV48C*	46,000	\$6,440
214626035	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	EL297UH090XV36C*	23,800	\$3,332
214626070	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	EL297UH045XV36B*	30,800	\$4,312
214626104	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	EL297UH070XV36B*	31,400	\$4,396
214626173	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL297UH090XV48C*	33,200	\$4,648
214626196	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL297UH090XV60C*	30,600	\$4,284
214626258	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	EL297UH090XV60C*	42,500	\$5,950
214626022	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	EL297UH045XV36B*	23,600	\$3,304
214626023	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	EL297UH070XV36B*	23,600	\$3,304
214626036	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	EL297UH090XV48C*	23,800	\$3,332
214626037	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	EL297UH110XV48C*	23,800	\$3,332
214626048	LENNOX	SL25XPV-024-230A**	CK40CT-36B-0*+TDR	EL297UH045XV36B*	24,200	\$3,388
214626158	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	EL297UH045XV36B*	33,400	\$4,676
214626172	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL297UH090XV36C*	33,200	\$4,648
214626175	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL297UH110XV48C*	33,000	\$4,620
214626194	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL297UH090XV36C*	30,800	\$4,312
214626195	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL297UH090XV48C*	30,600	\$4,284
214626259	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	EL297UH110XV48C*	42,500	\$5,950
214626049	LENNOX	SL25XPV-024-230A**	CK40CT-36B-0*+TDR	EL297UH070XV36B*	24,200	\$3,388
214626216	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	EL297UH090XV60C*	46,000	\$6,440
214626218	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	EL297UH110XV60C*	46,000	\$6,440
214626231	LENNOX	SL25XPV-048-230A**	CK40HT-60D-0*+TDR	EL297UH135XV60D*	42,000	\$5,880
214626059	LENNOX	SL25XPV-024-230A**	CK40CT-48B-0*+TDR	EL297UH045XV36B*	24,200	\$3,388
214626060	LENNOX	SL25XPV-024-230A**	CK40CT-48B-0*+TDR	EL297UH070XV36B*	24,200	\$3,388
214626071	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	EL297UH070XV36B*	30,800	\$4,312
214626103	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	EL297UH045XV36B*	31,400	\$4,396
214626159	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	EL297UH070XV36B*	33,400	\$4,676
214626174	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL297UH090XV60C*	33,200	\$4,648
214626176	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL297UH110XV60C*	33,200	\$4,648
214626197	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL297UH110XV48C*	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214626198	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL297UH110XV60C*	30,600	\$4,284
214626217	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	EL297UH110XV48C*	46,000	\$6,440
214626257	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	EL297UH090XV48C*	42,500	\$5,950
214626260	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	EL297UH110XV60C*	42,500	\$5,950
214626230	LENNOX	SL25XPV-048-230A**	CK40HT-60D-0*+TDR	EL296UH135XV60D*	42,000	\$5,880
214626214	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	EL296UH110XV60C*	46,000	\$6,440
214626213	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	EL296UH110XV48C*	46,000	\$6,440
214626212	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	EL296UH090XV60C*	46,000	\$6,440
214626211	LENNOX	SL25XPV-048-230A**	CK40HT-51/61C-0*+TDR	EL296UH090XV48C*	46,000	\$6,440
214626102	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	EL296UH070XV36B*	31,400	\$4,396
214626101	LENNOX	SL25XPV-036-230A**	CK40HT-48B-0*+TDR	EL296UH045XV36B*	31,400	\$4,396
214626069	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	EL296UH070XV36B*	30,800	\$4,312
214626068	LENNOX	SL25XPV-036-230A**	CK40HT-42B-0*+TDR	EL296UH045XV36B*	30,800	\$4,312
214626034	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	EL296UH110XV48C*	23,800	\$3,332
214626033	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	EL296UH090XV48C*	23,800	\$3,332
214626032	LENNOX	SL25XPV-024-230A**	CK40HT-42C-0*+TDR	EL296UH090XV36C*	23,800	\$3,332
214626021	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	EL296UH070XV36B*	23,600	\$3,304
214626020	LENNOX	SL25XPV-024-230A**	CK40HT-42B-0*+TDR	EL296UH045XV36B*	23,600	\$3,304
214626256	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	EL296UH110XV60C*	42,500	\$5,950
214626255	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	EL296UH110XV48C*	42,500	\$5,950
214626254	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	EL296UH090XV60C*	42,500	\$5,950
214626253	LENNOX	SL25XPV-048-230A**	CK40CT-60C-0*+TDR	EL296UH090XV48C*	42,500	\$5,950
214626193	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL296UH110XV60C*	30,600	\$4,284
214626192	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL296UH110XV48C*	30,600	\$4,284
214626191	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL296UH090XV60C*	30,600	\$4,284
214626190	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL296UH090XV48C*	30,600	\$4,284
214626189	LENNOX	SL25XPV-036-230A**	CK40CT-50/60C-0*+TDR	EL296UH090XV36C*	30,800	\$4,312
214626171	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL296UH110XV60C*	33,200	\$4,648
214626170	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL296UH110XV48C*	33,000	\$4,620
214626169	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL296UH090XV60C*	33,200	\$4,648
214626168	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL296UH090XV48C*	33,200	\$4,648
214626167	LENNOX	SL25XPV-036-230A**	CK40CT-48C-0*+TDR	EL296UH090XV36C*	33,200	\$4,648
214626157	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	EL296UH070XV36B*	33,400	\$4,676
214626156	LENNOX	SL25XPV-036-230A**	CK40CT-48B-0*+TDR	EL296UH045XV36B*	33,400	\$4,676
211034459	LENNOX	MLB036S4S-2P	M33C036S4.*P		33,000	\$4,620
211034454	LENNOX	MLB048S4S-2P	MCFA048S4.*P		35,000	\$4,900
205782161	LENNOX	MLB048S4S-1P	MMDB048S4-2P		39,500	\$5,530
211034460	LENNOX	MLB048S4S-2P	M33C048S4.*P		35,000	\$4,900

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211034449	LENNOX	MLB048S4S-2P	MMDB048S4-*P		39,500	\$5,530
205782160	LENNOX	MLB036S4S-1P	MMDB036S4-2P		34,000	\$4,760
211034448	LENNOX	MLB036S4S-2P	MMDB036S4-*P		33,400	\$4,676
207699106	LENNOX	MLB036S4M-1P			23,000	\$3,220
207768729	LENNOX	MLB018S4M-1P			11,000	\$1,540
213194324	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	EL297UH110XV60C*	42,500	\$5,950
213194321	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	EL297UH090XV48C*	42,500	\$5,950
213194314	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	EL297UH110XV48C*	46,000	\$6,440
213194309	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	EL297UH090XV60C*	42,500	\$5,950
213194303	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL297UH110XV60C*	30,600	\$4,284
213194302	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL297UH110XV48C*	30,600	\$4,284
213194298	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL297UH110XV60C*	33,200	\$4,648
213194296	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL297UH090XV60C*	33,200	\$4,648
213194293	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	EL297UH070XV36B*	33,400	\$4,676
213194283	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	EL297UH045XV36B*	31,400	\$4,396
213194277	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	EL297UH070XV36B*	30,800	\$4,312
213194274	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL297UH110XV48C*	30,600	\$4,284
213194271	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL297UH090XV36C*	30,800	\$4,312
213194267	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL297UH090XV48C*	33,200	\$4,648
213194265	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	EL297UH070XV36B*	33,400	\$4,676
213194261	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	EL297UH070XV36B*	24,200	\$3,388
213194260	LENNOX	SL25XPV-024-230A**	CX35-48B+TDR	EL297UH045XV36B*	24,200	\$3,388
212523825	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SLP98UH090XV60C*	33,200	\$4,648
212523823	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SLP98UH090XV36C*	33,200	\$4,648
212523822	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	SLP98UH070XV36B*	33,400	\$4,676
213194316	LENNOX	SL25XPV-048-230A**	CHX35-60D-**-**+TDR	EL297UH135XV60D*	42,000	\$5,880
213194315	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	EL297UH110XV60C*	46,000	\$6,440
213194313	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	EL297UH090XV60C*	46,000	\$6,440
213194275	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL297UH110XV60C*	30,600	\$4,284
213194264	LENNOX	SL25XPV-036-230A**	C35-48B+TDR+TXV	EL297UH045XV36B*	33,400	\$4,676
213194259	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	EL297UH070XV36B*	24,200	\$3,388
212523828	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SLP98UH090XV60C*	30,600	\$4,284
212523824	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	SLP98UH090XV48C*	33,200	\$4,648
212523820	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	SLP98UH070XV36B*	24,200	\$3,388
213194323	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	EL297UH110XV48C*	42,500	\$5,950
213194311	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	EL297UH110XV60C*	42,500	\$5,950
213194310	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	EL297UH110XV48C*	42,500	\$5,950
213194300	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL297UH090XV48C*	30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213194299	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL297UH090XV36C*	30,800	\$4,312
213194297	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL297UH110XV48C*	33,000	\$4,620
213194294	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL297UH090XV36C*	33,200	\$4,648
213194292	LENNOX	SL25XPV-036-230A**	CX35-48B+TDR	EL297UH045XV36B*	33,400	\$4,676
213194270	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL297UH110XV60C*	33,200	\$4,648
213194266	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL297UH090XV36C*	33,200	\$4,648
213194258	LENNOX	SL25XPV-024-230A**	CX35-36B+TDR	EL297UH045XV36B*	24,200	\$3,388
213194257	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	EL297UH110XV48C*	23,800	\$3,332
213194256	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	EL297UH090XV48C*	23,800	\$3,332
213194254	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	EL297UH070XV36B*	23,600	\$3,304
213194253	LENNOX	SL25XPV-024-230A**	CHX35-42B-**-**+TDR	EL297UH045XV36B*	23,600	\$3,304
213194252	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	EL297UH070XV36B*	24,200	\$3,388
213194251	LENNOX	SL25XPV-024-230A**	C35-48B+TDR+TXV	EL297UH045XV36B*	24,200	\$3,388
213194249	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	EL297UH045XV36B*	24,200	\$3,388
212523826	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SLP98UH090XV36C*	30,800	\$4,312
213194322	LENNOX	SL25XPV-048-230A**	CX35-60C+TDR	EL297UH090XV60C*	42,500	\$5,950
213194308	LENNOX	SL25XPV-048-230A**	C35-60C+TDR+TXV	EL297UH090XV48C*	42,500	\$5,950
213194301	LENNOX	SL25XPV-036-230A**	CX35-50/60C+TDR	EL297UH090XV60C*	30,600	\$4,284
213194295	LENNOX	SL25XPV-036-230A**	CX35-48C+TDR	EL297UH090XV48C*	33,200	\$4,648
213194284	LENNOX	SL25XPV-036-230A**	CHX35-48B-**-**+TDR	EL297UH070XV36B*	31,400	\$4,396
213194276	LENNOX	SL25XPV-036-230A**	CHX35-42B-**-**+TDR	EL297UH045XV36B*	30,800	\$4,312
213194273	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL297UH090XV60C*	30,600	\$4,284
213194272	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	EL297UH090XV48C*	30,600	\$4,284
213194269	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL297UH110XV48C*	33,000	\$4,620
213194268	LENNOX	SL25XPV-036-230A**	C35-48C+TDR+TXV	EL297UH090XV60C*	33,200	\$4,648
213194255	LENNOX	SL25XPV-024-230A**	CHX35-42C-**-**+TDR	EL297UH090XV36C*	23,800	\$3,332
213194250	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	EL297UH070XV36B*	24,200	\$3,388
212523827	LENNOX	SL25XPV-036-230A**	C35-50/60C+TDR+TXV	SLP98UH090XV48C*	30,600	\$4,284
212523819	LENNOX	SL25XPV-024-230A**	C35-36B+TDR+TXV	SLP98UH070XV36B*	24,200	\$3,388
212348052	LENNOX	MLB048S4S-2P	MMA048S4-*P		38,000	\$5,320
211694775	LENNOX	EL22XPV-024-230A**	CBA27UHE-030-230*+TDR		14,300	\$2,002
211694663	LENNOX	EL22XPV-024-230A**	CBA38MV-030-230*+TDR		14,300	\$2,002
213194312	LENNOX	SL25XPV-048-230A**	CHX35-51/61C-**-**+TDR	EL297UH090XV48C*	46,000	\$6,440
205747589	LENNOX	MLB048S4M-1P	Heat pump with ducts		28,000	\$3,920
205782163	LENNOX	MLB048S4S-1P	MCFA048S4-2P		35,000	\$4,900
207683534	LENNOX	MLB024S4S-1P	M33C024S4-1P		15,000	\$2,100
207683529	LENNOX	MLB018S4S-1P	MCFB018S4-2P		12,000	\$1,680

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207683526	LENNOX	MLB018S4S-1P	MMDB018S4-2P		12,700	\$1,778
207683528	LENNOX	MLB012S4S-1P	MFMA012S4-1P		8,400	\$1,176
205747588	LENNOX	MLB048S4M-1P	Heat pump without ducts		30,000	\$4,200
205782164	LENNOX	MLB036S4S-1P	M33A036S4-2P		25,400	\$3,556
205782165	LENNOX	MLB048S4S-1P	M33B048S4-2P		35,000	\$4,900
207699100	LENNOX	MLB048S4S-2P	M33C048S4-1P		35,000	\$4,900
207699098	LENNOX	MLB048S4S-2P	MCFA048S4-2P		35,000	\$4,900
207699096	LENNOX	MLB048S4S-2P	MMDB048S4-2P		33,000	\$4,620
207699099	LENNOX	MLB036S4S-2P	M33C036S4-1P		25,000	\$3,500
207699095	LENNOX	MLB036S4S-2P	MMDB036S4-2P		28,000	\$3,920
9920055	LENNOX	MLA036S4M-1P	Heat pump without ducts		23,200	\$3,248
201771988	LENNOX	MLA030S4M-1P	Heat pump without ducts		18,000	\$2,520
212348051	LENNOX	MLB036S4S-2P	MMA036S4-*P		28,600	\$4,004
207699109	LENNOX	MLB048S4M-2P	Combination heat pumps with or without ducts		29,000	\$4,060
216445263	LG	KUSXB601A	LKMMA48C1		32,000	\$4,480
216445262	LG	KUSXA482A	LKMMA48D1		32,600	\$4,564
216445261	LG	KUSXA482A	LKMMA48C1		32,600	\$4,564
216445260	LG	KUSXA422A	LKMMA42C1		29,000	\$4,060
214914956	LG	ZRUN024GSS0	Heat pump with ducts		18,000	\$2,520
214914954	LG	ZRUN024GSS0	Heat pump without ducts		17,000	\$2,380
215223214	LG	ZRUN024GSS0	Combination heat pumps with or without ducts		17,500	\$2,450
214914949	LG	ZRUM048GSS0	Heat pump with ducts		36,000	\$5,040
214914947	LG	ZRUM048GSS0	Heat pump without ducts		33,000	\$4,620
215223215	LG	ZRUM048GSS0	Combination heat pumps with or without ducts		34,400	\$4,816
214914952	LG	ZRUM036GSS0	Heat pump with ducts		27,000	\$3,780
214914950	LG	ZRUM036GSS0	Heat pump without ducts		26,000	\$3,640
215223216	LG	ZRUM036GSS0	Combination heat pumps with or without ducts		26,400	\$3,696
215408636	LG	KUMXA481A	Heat pump without ducts		35,000	\$4,900
215408637	LG	KUMXA481A	Heat pump with ducts		34,000	\$4,760
215408638	LG	KUMXA481A	Combination heat pumps with or without ducts		34,400	\$4,816
215402347	LG	KUMXA421A	Heat pump without ducts		31,600	\$4,424
215402348	LG	KUMXA421A	Heat pump with ducts		31,600	\$4,424
215408635	LG	KUMXA421A	Combination heat pumps with or without ducts		31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215402345	LG	KUMXA361A	Heat pump without ducts		29,600	\$4,144
215402346	LG	KUMXA361A	Heat pump with ducts		25,000	\$3,500
215408634	LG	KUMXA361A	Combination heat pumps with or without ducts		27,200	\$3,808
214848475	LG	KUMXA241A	Heat pump without ducts		17,800	\$2,492
214848476	LG	KUMXA241A	Heat pump with ducts		15,000	\$2,100
214848480	LG	KUMXA241A	Combination heat pumps with or without ducts		16,400	\$2,296
214848473	LG	KUMXA181A	Heat pump without ducts		13,900	\$1,946
214848474	LG	KUMXA181A	Heat pump with ducts		13,500	\$1,890
214848479	LG	KUMXA181A	Combination heat pumps with or without ducts		13,700	\$1,918
215828273	LG	KUSAL241A	KNSAL241A		15,800	\$2,212
215828275	LG	KUSAL181A	KNSAL181A		13,100	\$1,834
215828274	LG	KUSAL151A	KNSAL151A		10,900	\$1,526
214837926	LG	KUSXB361A	KNUJB361A		26,400	\$3,696
214837929	LG	KUSXA361A	KNUJB361A		26,400	\$3,696
214796354	LG	KUSXB301A	KNUJB301A		23,000	\$3,220
214837928	LG	KUSXA301A	KNUJB301A		21,400	\$2,996
214796353	LG	KUSXB241A	KNUJB241A		17,500	\$2,450
214796351	LG	KUSXA241A	KNUJB241A		17,000	\$2,380
214796352	LG	KUSXB181A	KNUJB181A		12,500	\$1,750
214796350	LG	KUSXA181A	KNUJB181A		13,000	\$1,820
214825953	LG	KUSXB181A	KNUDB181A		13,000	\$1,820
214825952	LG	KUSXA181A	KNUDB181A		13,600	\$1,904
215588574	LG	KUSXB601A	KNSLB601A		35,000	\$4,900
215588580	LG	KUSXB481A	KNSLB481A		31,400	\$4,396
215735574	LG	KUSXA482A	KNSLB481A		30,400	\$4,256
215588573	LG	KUSXB421A	KNSLB421A		31,000	\$4,340
215735573	LG	KUSXA422A	KNSLB421A		29,800	\$4,172
215812199	LG	KUSXB361A	KNSLB361A		27,000	\$3,780
215588579	LG	KUSXB301A	KNSLB301A		21,400	\$2,996
215588578	LG	KUSXB241A	KNSLB241A		17,500	\$2,450
215588571	LG	KUSXB181A	KNSLB181A		12,500	\$1,750
215588566	LG	KUSXA121A	KNSLB121A		8,600	\$1,204
215588576	LG	KUSXA361A	KNSLA361A		25,400	\$3,556
215588575	LG	KUSXA301A	KNSLA301A		21,600	\$3,024
215588567	LG	KUSXA181A	KNSLA181A		13,000	\$1,820

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214836843	LG	KUSXB481A	KNSJB481A		32,000	\$4,480
214837931	LG	KUSXA481A	KNSJB481A		33,400	\$4,676
214825958	LG	KUSXB421A	KNSJB421A		28,600	\$4,004
214837932	LG	KUSXA421A	KNSJB421A		30,800	\$4,312
214836842	LG	KUSXB481A	KNSCB481A		32,200	\$4,508
214837933	LG	KUSXA481A	KNSCB481A		31,800	\$4,452
214837927	LG	KUSXB421A	KNSCB421A		30,000	\$4,200
214837930	LG	KUSXA421A	KNSCB421A		28,600	\$4,004
214837925	LG	KUSXB361A	KNSCB361A		24,800	\$3,472
214825957	LG	KUSXA361A	KNSCB361A		24,800	\$3,472
214825956	LG	KUSXB301A	KNSCB301A		21,000	\$2,940
214826535	LG	KUSXA301A	KNSCB301A		20,400	\$2,856
214825955	LG	KUSXB241A	KNSCB241A		17,000	\$2,380
214825954	LG	KUSXA241A	KNSCB241A		17,000	\$2,380
216445264	LG	KUSXA301A	LKMMA24B1		16,000	\$2,240
216445259	LG	KUSXA361A	LKMMA36C1		24,000	\$3,360
216445258	LG	KUSXA361A	LKMMA36B1		24,000	\$3,360
216445257	LG	KUSXA301A	LKMMA30B1		22,000	\$3,080
216445256	LG	KUSXA241A	LKMMA24B1		16,000	\$2,240
216445255	LG	KUSXA181A	LKMMA18B1		13,000	\$1,820
216445254	LG	KUSXA181A	LKMMA18A1		13,000	\$1,820
216445253	LG	KUSXB601A	LKMMA60D1		36,400	\$5,096
216445252	LG	KUSXB601A	LKMMA60C1		36,400	\$5,096
216445251	LG	KUSXB481A	LKMMA48D1		32,000	\$4,480
216445250	LG	KUSXB481A	LKMMA48C1		32,000	\$4,480
216445249	LG	KUSXB421A	LKMMA42C1		29,000	\$4,060
216445248	LG	KUSXB361A	LKMMA36C1		24,000	\$3,360
216445247	LG	KUSXB361A	LKMMA36B1		24,000	\$3,360
216445246	LG	KUSXB301A	LKMMA30B1		20,000	\$2,800
216445245	LG	KUSXB241A	LKMMA24B1		16,000	\$2,240
216445244	LG	KUSXB181A	LKMMA18B1		13,000	\$1,820
216445243	LG	KUSXB181A	LKMMA18A1		13,000	\$1,820
216368960	LG	KUSAL121A	KNSAL121A		8,400	\$1,176
205967237	LG	ARUM036GSS5	Heat pump without ducts		33,400	\$4,676
205967240	LG	ARUM036GSS5	Combination heat pumps with or without ducts		30,600	\$4,284
205967236	LG	ARUM048GSS5	Heat pump with ducts		36,400	\$5,096
205967238	LG	ARUM036GSS5	Heat pump with ducts		28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
205967235	LG	ARUM048GSS5	Heat pump without ducts		38,500	\$5,390
205788773	LG	LUU360HHV	LVN361HV4		23,800	\$3,332
205967239	LG	ARUM048GSS5	Combination heat pumps with or without ducts		37,400	\$5,236
211234507	LG	LUU240HV	LVN241HV4		18,700	\$2,618
211234510	LG	LUU360HV	LVN361HV4		23,800	\$3,332
10445372	LG	LMU180HHV	Heat pump without ducts		14,700	\$2,058
10445374	LG	LMU240HHV	Heat pump without ducts		17,400	\$2,436
10445376	LG	LMU300HHV	Heat pump without ducts		18,900	\$2,646
206717007	LG	LMU361HHV	Heat pump without ducts		29,600	\$4,144
206717001	LG	LMU421HHV	Heat pump without ducts		31,600	\$4,424
206717002	LG	LMU480HHV	Heat pump without ducts		35,000	\$4,900
208131884	LG	LMU183HV	Heat pump without ducts		13,800	\$1,932
211234515	LG	LUU420HV	LVN420HV		29,200	\$4,088
212578842	LG	LUU180HHV	LHN188HV1		11,400	\$1,596
212578843	LG	LUU240HV	LHN248HV1		17,500	\$2,450
212578844	LG	LUU180HV	LHN188HV1		12,400	\$1,736
213307509	LG	LUU480HV	C74B(A,H)MX48C-C	FG7TC100D-V35C	32,400	\$4,536
213307508	LG	LUU480HV	C74B(A,H)MX48C-C	FG7TC080D-V35C	32,400	\$4,536
213307889	LG	LUU420HV	C74B(A,H)MX48C-C	FG7TC100D-V35C	28,000	\$3,920
213307888	LG	LUU420HV	C74B(A,H)MX48C-C	FG7TC080D-V35C	28,000	\$3,920
213307507	LG	LUU360HV	C74B(A,H)MX36C-C	FG7TC100D-V35C	24,400	\$3,416
213307506	LG	LUU360HV	C74B(A,H)MX36C-C	FG7TC080D-V35C	24,400	\$3,416
213307505	LG	LUU360HV	C74B(A,H)MX36C-B	FG7TC060D-V24B	20,200	\$2,828
213307504	LG	LUU240HV	C74B(A,H)MX24C-B	FG7TC060D-V24B	16,500	\$2,310
213307887	LG	LUU180HV	C74B(A,H)MX24C-B	FG7TC060D-V24B	13,300	\$1,862
9680934	LG	LAU180HYV2	LAN180HYV2		13,500	\$1,890
10443474	LG	LMU420HHV	Heat pump with ducts		29,000	\$4,060
10443475	LG	LMU360HHV	Heat pump with ducts		27,000	\$3,780
10445111	LG	LMU360HHV	Combination heat pumps with or without ducts		27,500	\$3,850
203161150	LG	LUU249HV	LCN248HV		17,500	\$2,450
205788766	LG	LUU180HHV	LDN187HV4		12,200	\$1,708
206221550	LG	LMU180HV	Combination heat pumps with or without ducts		13,700	\$1,918
10444103	LG	LMU420HHV	Combination heat pumps with or without ducts		29,000	\$4,060
10443472	LG	LMU360HHV	Heat pump without ducts		28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
10443471	LG	LMU420HHV	Heat pump without ducts		29,000	\$4,060
211234509	LG	LUU360HV	LHN368HV		24,000	\$3,360
211234508	LG	LUU360HV	LCN369HV		24,000	\$3,360
211234513	LG	LUU240HV	LCN249HV		17,400	\$2,436
211234506	LG	LUU240HV	LHN248HV		17,500	\$2,450
203161354	LG	LUU369HV	LHN368HV		24,000	\$3,360
206717014	LG	LMU480HHV	Combination heat pumps with or without ducts		35,000	\$4,900
206717009	LG	LMU480HHV	Heat pump with ducts		35,000	\$4,900
206717008	LG	LMU421HHV	Heat pump with ducts		31,600	\$4,424
203161352	LG	LUU249HV	LVN241HV4		18,700	\$2,618
205788769	LG	LUU360HHV	LHN368HV		25,000	\$3,500
205788767	LG	LUU240HHV	LHN248HV		18,200	\$2,548
205788764	LG	LUU240HHV	LCN249HV		17,400	\$2,436
205788768	LG	LUU360HHV	LCN369HV		25,400	\$3,556
205788763	LG	LUU180HHV	LCN188HV4		13,600	\$1,904
203162003	LG	LUU369HV	LVN361HV4		23,800	\$3,332
204825179	LG	LAU150HYV3	LAN150HYV3		10,900	\$1,526
206717013	LG	LMU421HHV	Combination heat pumps with or without ducts		31,600	\$4,424
206717006	LG	LMU361HHV	Heat pump with ducts		29,600	\$4,144
203161353	LG	LUU249HV	LHN248HV		17,500	\$2,450
208132537	LG	LMU183HV	Combination heat pumps with or without ducts		13,600	\$1,904
208131885	LG	LMU183HV	Heat pump with ducts		13,400	\$1,876
206221543	LG	LMU180HV	Heat pump without ducts		14,500	\$2,030
206717012	LG	LMU361HHV	Combination heat pumps with or without ducts		29,600	\$4,144
206221549	LG	LMU180HV	Heat pump with ducts		13,000	\$1,820
10445377	LG	LMU300HHV	Heat pump with ducts		17,700	\$2,478
10525928	LG	LMU300HHV	Combination heat pumps with or without ducts		18,300	\$2,562
10445375	LG	LMU240HHV	Heat pump with ducts		15,200	\$2,128
10516997	LG	LMU240HHV	Combination heat pumps with or without ducts		16,300	\$2,282
10445373	LG	LMU180HHV	Heat pump with ducts		14,700	\$2,058
10516996	LG	LMU180HHV	Combination heat pumps with or without ducts		14,700	\$2,058
211756564	LPS LEGACY	DLCSRBH12AAK	DLFSHBH12XAK		10,300	\$1,442

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211756566	LPS LEGACY	DLCSRBH24AAK	DLFSHBH24XAK		18,900	\$2,646
211756565	LPS LEGACY	DLCSRBH18AAK	DLFSHBH18XAK		11,100	\$1,554
211756594	LPS LEGACY	DLCSRBH18AAK	DLFSOAH18XAK		14,500	\$2,030
211756595	LPS LEGACY	DLCSRBH12AAK	DLFSOAH18XAK		9,500	\$1,330
211756588	LPS LEGACY	DLCSRBH12AAK	DLFSDAH12XHK		9,700	\$1,358
211756591	LPS LEGACY	DLCSRBH12AAK	DLFSFBH12XAK		10,200	\$1,428
211756560	LPS LEGACY	DLCSRBH24AAK	DLFSCBH24XAK		21,000	\$2,940
211756584	LPS LEGACY	DLCSRBH24AAK	DLFSCH24XAK		21,200	\$2,968
211756603	LPS LEGACY	DLCSRBH18AAK	DLFSCH18XAK		15,000	\$2,100
211756583	LPS LEGACY	DLCSRBH12AAK	DLFSCH12XAK		10,000	\$1,400
211756590	LPS LEGACY	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
211756586	LPS LEGACY	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
215324847	LPS LEGACY	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215357647	LPS LEGACY	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215323735	LPS LEGACY	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215319183	LPS LEGACY	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215319182	LPS LEGACY	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215319181	LPS LEGACY	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215319191	LPS LEGACY	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215319189	LPS LEGACY	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215319179	LPS LEGACY	D5CURAH48AAK	D5FUAH48XAK		32,400	\$4,536
215319176	LPS LEGACY	D5CURAH24AAK	D5FUAH24XAK		20,000	\$2,800
215319174	LPS LEGACY	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215319173	LPS LEGACY	D5CUHAH60AAK	D5FUAH60XAK		45,000	\$6,300
215319172	LPS LEGACY	D5CUHAH48AAK	D5FUAH48XAK		37,000	\$5,180
215319171	LPS LEGACY	D5CUHAH36AAK	D5FUAH36XAK		31,800	\$4,452
215319170	LPS LEGACY	D5CUHAH30AAK	D5FUAH30XAK		23,800	\$3,332
215319169	LPS LEGACY	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215319168	LPS LEGACY	D5CUHAH24AAK	D5FUAH24XAK		20,000	\$2,800
215319167	LPS LEGACY	D5CUHAH18AAK	D5FUAH18XAK		15,000	\$2,100
215324858	LPS LEGACY	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324857	LPS LEGACY	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324854	LPS LEGACY	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324852	LPS LEGACY	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324850	LPS LEGACY	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324849	LPS LEGACY	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324848	LPS LEGACY	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324845	LPS LEGACY	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215324844	LPS LEGACY	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324843	LPS LEGACY	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324842	LPS LEGACY	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215413354	LPS LEGACY	D5CPRAH18AA	D5FPHAH18XAK		19,300	\$2,702
215413353	LPS LEGACY	D5CPRAH12AAK	D5FPHAH12XAK		11,000	\$1,540
215357621	LPS LEGACY	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357620	LPS LEGACY	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357619	LPS LEGACY	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215324853	LPS LEGACY	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324846	LPS LEGACY	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215357630	LPS LEGACY	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357629	LPS LEGACY	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357628	LPS LEGACY	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357627	LPS LEGACY	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357626	LPS LEGACY	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357625	LPS LEGACY	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357624	LPS LEGACY	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357623	LPS LEGACY	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357622	LPS LEGACY	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357618	LPS LEGACY	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357617	LPS LEGACY	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357616	LPS LEGACY	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357612	LPS LEGACY	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357611	LPS LEGACY	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357610	LPS LEGACY	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324895	LPS LEGACY	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324893	LPS LEGACY	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324892	LPS LEGACY	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324890	LPS LEGACY	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324889	LPS LEGACY	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324856	LPS LEGACY	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324851	LPS LEGACY	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324896	LPS LEGACY	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215324894	LPS LEGACY	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324891	LPS LEGACY	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324841	LPS LEGACY	D5CSHAH12AAK	D5FSAH12XAK		9,800	\$1,372
215319190	LPS LEGACY	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215319186	LPS LEGACY	D5CSHAH33AAK	D5FSAH36XBK		27,400	\$3,836
215319185	LPS LEGACY	D5CSHAH24AAK	D5FSAH24XBK		16,900	\$2,366
215319184	LPS LEGACY	D5CSHAH18AAK	D5FSAH18XBK		14,000	\$1,960
211756651	LPS LEGACY	DLCURAH60ABK	DLFUAAH60XAK		42,000	\$5,880
213372203	LPS LEGACY	DLCURAH60ABK	DLFULAH60DX + CI		37,000	\$5,180
213372199	LPS LEGACY	DLCURAH30ABK	DLFULAH36CX + CI		22,600	\$3,164
216623437	MAINLINE	ML60HP230LMNTH-O	ML60HP230CC24-I		36,000	\$5,040
215864341	MAINLINE	ML18HP230NEXH-O	ML18HP230NEX-I		14,400	\$2,016
215864340	MAINLINE	ML12HP230NEXH-O	ML12HP230NEX-I		10,000	\$1,400
216623573	MAINLINE	ML36HP230MULH-O*	Combination heat pumps with or without ducts		31,400	\$4,396
216623571	MAINLINE	ML36HP230MULH-O*	Heat pump without ducts		30,000	\$4,200
215864310	MAINLINE	ML18HP230LMNTH-O	ML18HP230LMNTAHU-I		15,000	\$2,100
215864382	MAINLINE	ML12HP230NEXH-O	ML12HP230CON-I		9,800	\$1,372
215864311	MAINLINE	ML24HP230LMNTH-O	ML24HP230LMNTAHU-I		20,000	\$2,800
215864314	MAINLINE	ML36HP230LMNTH-O	ML36HP230LMNTAHU-I		31,800	\$4,452
216623563	MAINLINE	ML48HP230MUL-O*	Heat pump with ducts		37,000	\$5,180
216623565	MAINLINE	ML18HP230MULH-O*	Heat pump without ducts		17,600	\$2,464
216623566	MAINLINE	ML18HP230MULH-O*	Heat pump with ducts		17,000	\$2,380
216623567	MAINLINE	ML18HP230MULH-O*	Combination heat pumps with or without ducts		17,300	\$2,422
216623568	MAINLINE	ML27HP230MULH-O*	Heat pump without ducts		25,000	\$3,500
216623569	MAINLINE	ML27HP230MULH-O*	Heat pump with ducts		23,000	\$3,220
216623570	MAINLINE	ML27HP230MULH-O*	Combination heat pumps with or without ducts		24,000	\$3,360
216623572	MAINLINE	ML36HP230MULH-O*	Heat pump with ducts		33,000	\$4,620
216623574	MAINLINE	ML48HP230MULH-O*	Heat pump without ducts		44,000	\$6,160
216623575	MAINLINE	ML48HP230MULH-O*	Heat pump with ducts		44,500	\$6,230
216623576	MAINLINE	ML48HP230MULH-O*	Combination heat pumps with or without ducts		44,000	\$6,160
216623577	MAINLINE	ML55HP230MULH-O*	Heat pump without ducts		44,000	\$6,160
216623578	MAINLINE	ML55HP230MULH-O*	Heat pump with ducts		45,000	\$6,300
216623579	MAINLINE	ML55HP230MULH-O*	Combination heat pumps with or without ducts		44,500	\$6,230

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216623398	MAINLINE	ML18HP230LMNTH-O	ML18HP230G3AHU-I		14,700	\$2,058
216623402	MAINLINE	ML36HP230LMNTH-O	ML36HP230G3AHU-I		31,000	\$4,340
216623401	MAINLINE	ML33HP230LMNTH-O	ML36HP230G3AHU-I		24,600	\$3,444
216623400	MAINLINE	ML30HP230LMNTH-O	ML30HP230G3AHU-I		24,000	\$3,360
216623399	MAINLINE	ML24HP230LMNTH-O	ML24HP230G3AHU-I		19,000	\$2,660
216623403	MAINLINE	ML48HP230LMNTH-O	ML48HP230G3AHU-I		34,000	\$4,760
216623405	MAINLINE	ML18HP230LMNTH-O	ML24HP230G3AHU-I		14,700	\$2,058
216623404	MAINLINE	ML60HP230LMNTH-O	ML60HP230G3AHU-I		35,000	\$4,900
216623406	MAINLINE	ML30HP230LMNTH-O	ML36HP230G3AHU-I		24,000	\$3,360
216623407	MAINLINE	ML48HP230LMNTH-O	ML60HP230G3AHU-I		34,000	\$4,760
216623411	MAINLINE	ML36HP230LMNT-O	ML36HP230WMAHU-I		24,800	\$3,472
216623412	MAINLINE	ML18HP230LMNTH-O	ML18HP230WMAHU-I		15,300	\$2,142
216623415	MAINLINE	ML36HP230LMNTH-O	ML36HP230WMAHU-I		30,200	\$4,228
216623414	MAINLINE	ML30HP230LMNTH-O	ML30HP230WMAHU-I		23,200	\$3,248
216623418	MAINLINE	ML36HP230LMNT-O	ML36HP230PCAHU-I		24,600	\$3,444
216623419	MAINLINE	ML18HP230LMNTH-O	ML18HP230PCAHU-I		15,000	\$2,100
216623422	MAINLINE	ML36HP230LMNTH-O	ML36HP230PCAHU-I		31,200	\$4,368
216623421	MAINLINE	ML30HP230LMNTH-O	ML30HP230PCAHU-I		24,000	\$3,360
216623426	MAINLINE	ML24HP230LMNT-O	ML24HP230CC17-I		19,700	\$2,758
216623425	MAINLINE	ML24HP230LMNT-O	ML24HP230CC14-I		19,700	\$2,758
216623427	MAINLINE	ML18HP230LMNTH-O	ML24HP230CC14-I		15,200	\$2,128
216623430	MAINLINE	ML24HP230LMNTH-O	ML24HP230CC17-I		19,700	\$2,758
216623428	MAINLINE	ML24HP230LMNTH-O	ML24HP230CC14-I		19,700	\$2,758
216623429	MAINLINE	ML18HP230LMNTH-O	ML24HP230CC17-I		15,200	\$2,128
216623432	MAINLINE	ML30HP230LMNTH-O	ML36HP230CC17-I		25,000	\$3,500
216623431	MAINLINE	ML30HP230LMNTH-O	ML36HP230CC14-I		23,400	\$3,276
216623436	MAINLINE	ML60HP230LMNTH-O	ML60HP230CC21-I		38,000	\$5,320
216623434	MAINLINE	ML30HP230LMNTH-O	ML36HP230CC21-I		25,000	\$3,500
216623435	MAINLINE	ML36HP230LMNTH-O	ML36HP230CC21-I		29,200	\$4,088
216623433	MAINLINE	ML36HP230LMNTH-O	ML36HP230CC17-I		29,200	\$4,088
216623440	MAINLINE	ML48HP230LMNT-O	ML60HP230LMNTAHU-I		32,400	\$4,536
216623441	MAINLINE	ML18HP230LMNTH-O	ML24HP230LMNTAHU-I		15,000	\$2,100
216623443	MAINLINE	ML48HP230LMNTH-O	ML60HP230LMNTAHU-I		37,000	\$5,180
216623442	MAINLINE	ML30HP230LMNTH-O	ML36HP230LMNTAHU-I		23,800	\$3,332
215864417	MAINLINE	ML48HP230MUL-O	Combination heat pumps with or without ducts		35,400	\$4,956
215864415	MAINLINE	ML48HP230MUL-O	Heat pump without ducts		34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864414	MAINLINE	ML36HP230MUL-O	Combination heat pumps with or without ducts		26,600	\$3,724
215864413	MAINLINE	ML36HP230MUL-O	Heat pump with ducts		26,400	\$3,696
215864412	MAINLINE	ML36HP230MUL-O	Heat pump without ducts		27,000	\$3,780
215864411	MAINLINE	ML27HP230MUL-O	Combination heat pumps with or without ducts		18,200	\$2,548
215864410	MAINLINE	ML27HP230MUL-O	Heat pump with ducts		18,400	\$2,576
215864409	MAINLINE	ML27HP230MUL-O	Heat pump without ducts		18,000	\$2,520
215864406	MAINLINE	ML18HP230MUL-O	Heat pump without ducts		13,500	\$1,890
215864337	MAINLINE	ML24HP230NEX-O	ML24HP230NEX-I		19,500	\$2,730
215864336	MAINLINE	ML18HP230NEX-O	ML18HP230NEX-I		13,000	\$1,820
215864335	MAINLINE	ML12HP230NEX-O	ML12HP230NEX-I		9,600	\$1,344
216684104	MAINLINE	ML48HP230LMNTH-O	ML60HP230CC21-I		32,000	\$4,480
216684106	MAINLINE	ML36HP230LMNT-O	ML36HP230CC21-I		24,200	\$3,388
216684105	MAINLINE	ML36HP230LMNT-O	ML36HP230CC17-I		24,200	\$3,388
215864295	MAINLINE	ML18HP230NEXH-O	ML18HP230AHU-I		14,000	\$1,960
215864297	MAINLINE	ML33HP230NEXH-O	ML36HP230AHU-I		27,400	\$3,836
215864296	MAINLINE	ML24HP230NEXH-O	ML24HP230AHU-I		16,900	\$2,366
215864303	MAINLINE	ML60HP230LCMH-O	ML60HP230RS485AHU-I		41,000	\$5,740
215864302	MAINLINE	ML48HP230LCMH-O	ML48HP230RS485AHU-I		40,000	\$5,600
215864301	MAINLINE	ML36HP230LCMH-O	ML36HP230RS485AHU-I		28,000	\$3,920
215864308	MAINLINE	ML48HP230LMNT-O	ML48HP230LMNTAHU-I		32,400	\$4,536
215864305	MAINLINE	ML24HP230LMNT-O	ML24HP230LMNTAHU-I		20,000	\$2,800
215864313	MAINLINE	ML33HP230LMNTH-O	ML36HP230LMNTAHU-I		23,200	\$3,248
215864312	MAINLINE	ML30HP230LMNTH-O	ML30HP230LMNTAHU-I		23,800	\$3,332
215864317	MAINLINE	ML50HP230LMNTH-O	ML50HP230LMNTAHU-I		45,000	\$6,300
215864316	MAINLINE	ML48HP230LMNTH-O	ML48HP230LMNTAHU-I		37,000	\$5,180
215864315	MAINLINE	ML42HP230LMNTH-O	ML42HP230LMNTAHU-I		37,000	\$5,180
215864318	MAINLINE	ML60HP230LMNTH-O	ML60HP230LMNTAHU-I		45,000	\$6,300
215864342	MAINLINE	ML24HP230NEXH-O	ML24HP230NEX-I		21,600	\$3,024
215864343	MAINLINE	ML33HP230NEXH-O	ML33HP230NEX-I		29,600	\$4,144
215864347	MAINLINE	ML18HP230CALH-O	ML18HP230CALH-I		19,300	\$2,702
215864346	MAINLINE	ML12HP230CALH-O	ML12HP230CALH-I		11,000	\$1,540
215864349	MAINLINE	ML33HP230CALH-O	ML33HP230CALH-I		30,000	\$4,200
215864348	MAINLINE	ML24HP230CALH-O	ML24HP230CALH-I		21,000	\$2,940
215864371	MAINLINE	ML18HP230NEXH-O	ML18HP230STDCAS-I		14,900	\$2,086
215864370	MAINLINE	ML12HP230NEXH-O	ML12HP230STDCAS-I		10,000	\$1,400
215864372	MAINLINE	ML24HP230NEXH-O	ML24HP230STDCAS-I		20,400	\$2,856

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864375	MAINLINE	ML12HP230NEXH-O	ML12HP230LSDUC-I		9,600	\$1,344
215864376	MAINLINE	ML18HP230NEXH-O	ML18HP230LSDUC-I		15,000	\$2,100
215864379	MAINLINE	ML18HP230NEXH-O	ML18HP230HSDUC-I		15,000	\$2,100
215864378	MAINLINE	ML12HP230NEXH-O	ML12HP230HSDUC-I		10,200	\$1,428
215864380	MAINLINE	ML24HP230NEXH-O	ML24HP230HSDUC-I		21,600	\$3,024
215864383	MAINLINE	ML18HP230NEXH-O	ML16HP230CON-I		14,200	\$1,988
215864385	MAINLINE	ML24HP230NEXH-O	ML24HP230FLO-I		20,200	\$2,828
215864384	MAINLINE	ML18HP230NEXH-O	ML18HP230FLO-I		14,400	\$2,016
215864389	MAINLINE	ML18HP230NEXH-O	ML18HP2301WYCAS-I		14,500	\$2,030
215864388	MAINLINE	ML12HP230NEXH-O	ML12HP2301WYCAS-I		9,600	\$1,344
215864398	MAINLINE	ML36HP230LCMH-O	ML36HP230STDCAS-I		30,600	\$4,284
215864400	MAINLINE	ML36HP230LCMH-O	ML36HP230HSDUC-I		31,600	\$4,424
215864399	MAINLINE	ML48HP230LCMH-O	ML48HP230STDCAS-I		44,000	\$6,160
215864401	MAINLINE	ML48HP230LCMH-O	ML48HP230HSDUC-I		45,000	\$6,300
215864402	MAINLINE	ML60HP230LCMH-O	ML60HP230HSDUC-I		45,000	\$6,300
215864403	MAINLINE	ML36HP230LCMH-O	ML36HP230FLO-I		30,200	\$4,228
215864404	MAINLINE	ML48HP230LCMH-O	ML48HP230FLO-I		38,500	\$5,390
215864405	MAINLINE	ML60HP230LCMH-O	ML60HP230FLO-I		41,000	\$5,740
215864416	MAINLINE	ML48HP230MUL-O	Heat pump with ducts		37,000	\$5,180
215864421	MAINLINE	ML18HP230MULH-O	Heat pump without ducts		16,400	\$2,296
215864423	MAINLINE	ML18HP230MULH-O	Combination heat pumps with or without ducts		16,700	\$2,338
215864422	MAINLINE	ML18HP230MULH-O	Heat pump with ducts		17,000	\$2,380
215864424	MAINLINE	ML27HP230MULH-O	Heat pump without ducts		23,600	\$3,304
215864427	MAINLINE	ML36HP230MULH-O	Heat pump without ducts		36,600	\$5,124
215864426	MAINLINE	ML27HP230MULH-O	Combination heat pumps with or without ducts		23,200	\$3,248
215864425	MAINLINE	ML27HP230MULH-O	Heat pump with ducts		23,000	\$3,220
215864428	MAINLINE	ML36HP230MULH-O	Heat pump with ducts		33,000	\$4,620
215864430	MAINLINE	ML48HP230MULH-O	Heat pump without ducts		40,500	\$5,670
215864429	MAINLINE	ML36HP230MULH-O	Combination heat pumps with or without ducts		34,800	\$4,872
215864432	MAINLINE	ML48HP230MULH-O	Combination heat pumps with or without ducts		42,500	\$5,950
215864431	MAINLINE	ML48HP230MULH-O	Heat pump with ducts		44,500	\$6,230
215864434	MAINLINE	ML55HP230MULH-O	Heat pump with ducts		45,000	\$6,300
215864433	MAINLINE	ML55HP230MULH-O	Heat pump without ducts		45,000	\$6,300

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864435	MAINLINE	ML55HP230MULH-O	Combination heat pumps with or without ducts		45,000	\$6,300
215402352	MAPLE HEAT	NE-T52-MHEAT3012E	NE-T52-MHEAT3012I		10,000	\$1,400
215402351	MAPLE HEAT	NE-T52-MHEAT3018E	NE-T52-MHEAT3018I		15,000	\$2,100
212348360	MAXI AIR	NE-T52-SUPAE12E	NE-T52-SUPAE12I		10,000	\$1,400
212348362	MAXI AIR	NE-T52-SUPAE18E	NE-T52-SUPAE18I		15,000	\$2,100
213927611	MAXI AIR	NE-T53-AEG12EXT	NE-T53-AEG12INT		10,000	\$1,400
213927612	MAXI AIR	NE-T53-AEG18EXT	NE-T53-AEG18INT		15,000	\$2,100
213927619	MAXI AIR	NE-T53-MULTI28E	Heat pump without ducts		26,600	\$3,724
213927620	MAXI AIR	NE-T53-MULTI28E	Heat pump with ducts		27,000	\$3,780
213927621	MAXI AIR	NE-T53-MULTI28E	Combination heat pumps with or without ducts		26,800	\$3,752
210426580	MAXI AIR	MAXS-2430	AHMS-3015		21,000	\$2,940
213927622	MAXI AIR	NE-T53-MULTI36E	Heat pump without ducts		33,000	\$4,620
213927624	MAXI AIR	NE-T53-MULTI36E	Combination heat pumps with or without ducts		34,000	\$4,760
213265613	MAXI AIR	MAXS-2430	NE-F52-MAC36HWD		22,600	\$3,164
210426581	MAXI AIR	MAXS-4260	AHMS-6020		42,000	\$5,880
210372390	MAXI AIR CENTRAL	CLASS30CC	AHAN3615		18,000	\$2,520
212940831	MAXI AIR CENTRAL	CLASS30CC	F45-SPLTAH36		18,000	\$2,520
206799639	MAXI AIR CENTRAL	CLASS24CC	AHAN3615		16,000	\$2,240
206799638	MAXI AIR CENTRAL	CLASS24CC	AHAN2410		16,000	\$2,240
204012250	MAX-R	MAX-R(MZ)27K30	Heat pump without ducts		18,000	\$2,520
216623451	MDV	MOE30-60HFN10-M3X	MVBM-60D28T6N10-MAS		35,600	\$4,984
216620311	MDV	MOE30-60HFN10-M3X	MVBM-60D28T6N10		36,000	\$5,040
214311117	MDV	MOX430-18HFN10-M1X	MSAG11D-18HRFN10-M1		14,400	\$2,016
214311109	MDV	MOX330-12HFN10-M1X	MSAG11BM-12HRFN10-M1		10,000	\$1,400
214861817	MDV	M5OX631-36HFN10-M1XD-D	Combination heat pumps with or without ducts		31,400	\$4,396
214861815	MDV	M5OX631-36HFN10-M1XD-D	Heat pump without ducts		30,000	\$4,200
214861700	MDV	M5OX631-36HFN10-M1XD	Combination heat pumps with or without ducts		31,400	\$4,396
214861698	MDV	M5OX631-36HFN10-M1XD	Heat pump without ducts		30,000	\$4,200
210857292	MDV	MOX430-17HFN1-MT0W	MCBU-18HRFN1-MW-CA		14,500	\$2,030
210857290	MDV	MOX330-12HFN1-MW5W	MCBU-18HRFN1-MW-CA		9,500	\$1,330
206361863	MDV	MOD30-24HFN1-MU0W	MSAG11D-23HRFN1-MU0W		18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206361862	MDV	MOX430-17HFN1-MT0W	MSAG11D-18HRFN1-MT8W		11,100	\$1,554
206361861	MDV	MOX330-12HFN1-MW5W	MSAG11B-12HRFN1-MV0W(GA)		10,300	\$1,442
205993855	MDV	MOD30-24HFN1-MU0W	MSEPD-24HRFN1-MU0W		21,200	\$2,968
205993854	MDV	MOX430-17HFN1-MT0W	MSEPC-18HRFN1-MU0W		15,000	\$2,100
205993846	MDV	MOX330-12HFN1-MW5W	MSEPB-12HRFN1-MW5W(GA)		10,000	\$1,400
210299304	MDV	MOX330-12HFN1-MW5W	MTI-12HWFN1-MST0		9,700	\$1,358
206330129	MDV	MOX430-17HFN1-MT0W	MTIU-18HWFN1-M		15,000	\$2,100
206330126	MDV	MOX330-12HFN1-MW5W	MCA3U-12HRFN1-M(C)		9,900	\$1,386
209270214	MDV	MOX430-17HFN1-MT0W	MCBU-18HRFN1-MU2W		14,500	\$2,030
209270211	MDV	MOX330-12HFN1-MW5W	MCBU-12HRFN1-MV0W		9,500	\$1,330
209248924	MDV	MOX330-12HFN1-MW5W	MFA2U-12HRFN1-MW5W		10,200	\$1,428
206330128	MDV	MOX330-12HFN1-MW5W	MFAU-12HRFN1-M(C)		9,600	\$1,344
207338219	MDV	MOD30-24HFN1-MU0W	MCD1-24HRFN1-MT0W(GA)		21,000	\$2,940
207613860	MDV	MOD30-18HFN1-MZ20W	MSEPD-18HRFN1-MZ22W		20,200	\$2,828
207591142	MDV	MOX430-12HFN1-MZ60W	MSEPC-12HRFN1-MZ40W		11,400	\$1,596
207591140	MDV	MOX430-12HFN1-MZ60W	MSOP1B-12HRFN1-MZ60W		10,400	\$1,456
208132553	MDV	M5OA-55HFN1-M-[X]*	Combination heat pumps with or without ducts		35,000	\$4,900
208132544	MDV	M5OA-55HFN1-M-[X]*	Heat pump with ducts		35,200	\$4,928
208132552	MDV	M5OA-55HFN1-M-[X]	Combination heat pumps with or without ducts		34,800	\$4,872
208132542	MDV	M5OA-55HFN1-M-[X]	Heat pump with ducts		35,200	\$4,928
207641251	MDV	M5OG-48HFN1-M-[X]-20*	Combination heat pumps with or without ducts		37,400	\$5,236
207641259	MDV	M3OI-28HFN1-M*	Combination heat pumps with or without ducts		26,200	\$3,668
207641247	MDV	M3OI-28HFN1-M*	Heat pump with ducts		27,000	\$3,780
206716990	MDV	M3OI-28HFN1-M	Combination heat pumps with or without ducts		26,800	\$3,752
206714982	MDV	M3OI-28HFN1-M	Heat pump with ducts		27,000	\$3,780
207618261	MDV	M3OI-24HFN1-M	Combination heat pumps with or without ducts		24,000	\$3,360
207617656	MDV	M3OI-24HFN1-M	Heat pump with ducts		24,000	\$3,360
207803596	MDV	MOX430-17HFN1-MT0W	MVC-18HWFN1-MW(GA)		15,400	\$2,156

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207802615	MDV	MOD30-24HFN1-MU0W	MVC-23HWFN1-M		16,900	\$2,366
207699007	MDV	MOX430U-18HFN1-M	MVC-18HWFN1-M		13,500	\$1,890
207699008	MDV	MOD30-24HFN1-MW	MVC-24HWFN1-M		19,200	\$2,688
209960479	MDV	MOX430-17HFN1-MT0Q1W	MVC-18HWFN1-MQ1W		15,000	\$2,100
210135403	MDV	MOD30-24HFN1-MU0Q1W	MVC-23HWFN1-MQ1W		18,400	\$2,576
209960480	MDV	MOD30U-30HFN1-MP0-Q1W	MVC-30HWFN1-MQ1W		21,000	\$2,940
208132541	MDV	M5OA-55HFN1-M-[X]	Heat pump without ducts		34,400	\$4,816
208132543	MDV	M5OA-55HFN1-M-[X]*	Heat pump without ducts		34,800	\$4,872
206716986	MDV	M2OI-18HFN1-M	Heat pump without ducts		15,000	\$2,100
206714984	MDV	M5OG-48HFN1-M-[X]-20	Heat pump without ducts		36,000	\$5,040
206714976	MDV	M3OI-28HFN1-M	Heat pump without ducts		26,600	\$3,724
207617655	MDV	M3OI-24HFN1-M	Heat pump without ducts		24,000	\$3,360
207641258	MDV	M3OI-28HFN1-M*	Heat pump without ducts		25,600	\$3,584
207641236	MDV	M2OI-18HFN1-M*	Heat pump without ducts		13,500	\$1,890
210135401	MDV	MOE30U-48HFN1-M[X]	MHG-48HWFN1-MW		40,000	\$5,600
212519803	MDV	MOD30-18HFN1-MZ22W	MSEPD-18HRFN1-MZ22W		12,300	\$1,722
210299845	MDV	MOX430-17HFN1-MT0W	MTI-18HWFN1-MSP0		15,700	\$2,198
210299844	MDV	MOD30-24HFN1-MU0W	MTI-24HWFN1-MSP5		21,000	\$2,940
206330134	MDV	MOD30-24HFN1-MU0W	MUEU-24HRFN1-M(C)		19,000	\$2,660
206330136	MDV	MOD30-24HFN1-MU0W	MTIU-24HWFN1-M		21,000	\$2,940
206714974	MDV	M2OI-18HFN1-M	Heat pump with ducts		16,000	\$2,240
206716993	MDV	M5OG-48HFN1-M-[X]-20	Combination heat pumps with or without ducts		36,000	\$5,040
207641231	MDV	M4OI-36HFN1-M	Combination heat pumps with or without ducts		34,000	\$4,760
207641249	MDV	M4OI-36HFN1-M*	Combination heat pumps with or without ducts		35,000	\$4,900
206716988	MDV	M2OI-18HFN1-M	Combination heat pumps with or without ducts		15,500	\$2,170
207641237	MDV	M4OI-36HFN1-M*	Heat pump without ducts		35,000	\$4,900
207641250	MDV	M5OG-48HFN1-M-[X]-20*	Heat pump with ducts		36,000	\$5,040
206714985	MDV	M5OG-48HFN1-M-[X]-20	Heat pump with ducts		36,000	\$5,040
207641256	MDV	M2OI-18HFN1-M*	Heat pump with ducts		16,000	\$2,240
206330127	MDV	MOX330-12HFN1-MW5W	MTIU-12HWFN1-M		10,600	\$1,484
207641228	MDV	M4OI-36HFN1-M	Heat pump without ducts		33,000	\$4,620
207641238	MDV	M5OG-48HFN1-M-[X]-20*	Heat pump without ducts		39,000	\$5,460

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207641257	MDV	M2OI-18HFN1-M*	Combination heat pumps with or without ducts		14,700	\$2,058
207699010	MDV	MOE31U-36HFN1-M	MVC-36HWFN1-M		30,400	\$4,256
207699009	MDV	MOD30U-30HFN1-MR0(X)	MVC-30HWFN1-M		21,000	\$2,940
216684113	MDV	MOX630-48HFN10-M3X	MVBM-60C28T6N10-MAS		34,400	\$4,816
216626168	MDV	MOX630-48HFN10-M3X	MVBM-60C28T6N10		34,400	\$4,816
216626167	MDV	MOD30-36HFN10-M3	MVBM-36C24T4N10		24,200	\$3,388
216626166	MDV	MOD30-36HFN10-M3	MVBM-36B24T4N10		24,200	\$3,388
216623450	MDV	MOX630-36HFN10-M3X	MVBM-36C24T4N10-MAS		29,200	\$4,088
216623448	MDV	MOD30-30HFN10-M3X	MVBM-36C24T4N10-MAS		25,000	\$3,500
216623449	MDV	MOX630-36HFN10-M3X	MVBM-36B24T4N10-MAS		29,200	\$4,088
216623447	MDV	MOD30-30HFN10-M3X	MVBM-36B24T4N10-MAS		25,000	\$3,500
216623446	MDV	MOX430-24HFN10-M3X	MVBM-24B18T3N10-MAS		19,700	\$2,758
216623445	MDV	MOX430-18HFN10-M3X	MVBM-24B18T3N10-MAS		15,200	\$2,128
216621508	MDV	MOE30-60HFN10-M3X	MVBM-60C28T6N10		37,800	\$5,292
216620310	MDV	MOD30-30HFN10-M3X	MVBM-36C24T4N10		25,000	\$3,500
216620309	MDV	MOD30-30HFN10-M3X	MVBM-36B24T4N10		25,000	\$3,500
216620307	MDV	MOX630-36HFN10-M3X	MVBM-36C24T4N10		29,200	\$4,088
216620306	MDV	MOX630-36HFN10-M3X	MVBM-36B24T4N10		29,200	\$4,088
216620305	MDV	MOX430-24HFN10-M3	MVBM-24B18T3N10		19,700	\$2,758
216620304	MDV	MOX430-24HFN10-M3	MVBM-24A18T3N10		19,700	\$2,758
216620303	MDV	MOX430-24HFN10-M3X	MVBM-24B18T3N10		19,700	\$2,758
216620302	MDV	MOX430-24HFN10-M3X	MVBM-24A18T3N10		19,700	\$2,758
216620299	MDV	MOX430-18HFN10-M3X	MVBM-24B18T3N10		15,200	\$2,128
216620298	MDV	MOX430-18HFN10-M3X	MVBM-24A18T3N10		15,200	\$2,128
216620323	MDV	MOD30-36HFN10-M3	MVBL-36HWFN10-WK3		24,600	\$3,444
216620296	MDV	MOX630-36HFN10-M3X	MVBL-36HWFN10-WK3		31,200	\$4,368
216620295	MDV	MOD30-30HFN10-M3X	MVBL-30HWFN10-WJ3		24,000	\$3,360
216620291	MDV	MOX430-18HFN10-M3X	MVBL-18HWFN10-MH3		15,000	\$2,100
216018272	MDV	MOX430-15HFN10-M1X	MSEPC-15HRFN10-M1-D		15,000	\$2,100
216498629	MDV	MOX330-15HFN10-M1	MSEPB-15HRFN10-M1		10,100	\$1,414
216472805	MDV	M3OX430-18HFN10-M1**	Heat pump without ducts		15,000	\$2,100
214861585	MDV	MOX430-18HFN10-M3X	MVBC-18HWFN10-MB3E-D		15,000	\$2,100
214861539	MDV	MOX430-18HFN10-M3X	MVBC-18HWFN10-MB3E		15,000	\$2,100
214855566	MDV	MOX330-12HFN10-M1X	MFA2M-12HRFN10-M1-D		9,800	\$1,372
214855412	MDV	MOX330-12HFN10-M1X	MFA2M-12HRFN10-M1		9,800	\$1,372

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214855563	MDV	MOX330-12HFN10-M1X	MSEPBM-12HRFN10-M1-D		9,800	\$1,372
214311112	MDV	MOX330-12HFN10-M1X	MSEPBM-12HRFN10-M1		9,800	\$1,372
214861587	MDV	MOX430-24HFN10-M3X	MVBC-24HWFN10-MB3E-D		20,000	\$2,800
214861541	MDV	MOX430-24HFN10-M3X	MVBC-24HWFN10-MB3E		20,000	\$2,800
214861592	MDV	MOX630-36HFN10-M3X	MVBC-36HWFN10-MC3E-D		31,800	\$4,452
214861546	MDV	MOX630-36HFN10-M3X	MVBC-36HWFN10-MC3E		31,800	\$4,452
216021097	MDV	M6OE31-53HFPN10-M1XD	Heat pump with ducts		42,500	\$5,950
216030946	MDV	MOD30-36HFN10-M3	MVBE-36HWFN10-WL3E-MAS		24,800	\$3,472
216030944	MDV	MOX630-36HFN10-M3X	MVBDM-36HWFN10-WB3-MAS		31,000	\$4,340
216030943	MDV	MOE30-60HFN10-M3X	MVBDM-60HWFN10-WC3-MAS		35,000	\$4,900
216030942	MDV	MOX630-48HFN10-M3X	MVBDM-48HWFN10-WC3-MAS		34,000	\$4,760
216030940	MDV	MOX630-48HFN10-M3	MVBC-48HWFN10-MD3E-MAS		32,400	\$4,536
216030937	MDV	MOX430-24HFN10-M3	MVBC-24HWFN10-MB3E-MAS		20,000	\$2,800
216030935	MDV	MOX630-36HFN10-M3X	MVBC-36HWFN10-MC3E-MAS		31,800	\$4,452
216030934	MDV	MOD30-30HFN10-M3X	MVBDM-30HWFN10-WB3-MAS		24,000	\$3,360
216030933	MDV	MOX430-24HFN10-M3X	MVBDM-24HWFN10-WA3-MAS		19,000	\$2,660
216030932	MDV	MOX430-18HFN10-M3X	MVBDM-18HWFN10-WA3-MAS		14,700	\$2,058
216032496	MDV	MOD30-30HFN10-M3X	MVBC-30HWFN10-MC3E		23,800	\$3,332
216025755	MDV	MOX430-18HFN10-M3X	MVBE-18HWFN10-WM3E		15,300	\$2,142
216025754	MDV	MOX630-36HFN10-M3X	MVBE-36HWFN10-WL3E		30,200	\$4,228
216025753	MDV	MOD30-30HFN10-M3X	MVBE-30HWFN10-WL3E		23,200	\$3,248
216021106	MDV	MOX430-18HFPN10-M1	MSAB3E-18HRFPN10-M1		15,200	\$2,128
216021099	MDV	MOX330-12HFPN10-M1X	MSAB3B-12HRFPN10-M1		8,900	\$1,246
216021098	MDV	MOX430-18HFPN10-M1X	MSAB3E-18HRFPN10-M1		15,200	\$2,128
216021119	MDV	M6OE31-53HFPN10-M1XD	MSAB3B-06HRFPN10-M1		43,250	\$6,055

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216021096	MDV	M6OE31-53HFPN10-M1XD	MSAB3B-06HRFPN10-M1		44,000	\$6,160
216021087	MDV	MOX430-18HFPN10-M1X	MCB-18HRFPN10-M1		14,800	\$2,072
216021086	MDV	MOX330-12HFPN10-M1X	MCBM-12HRFPN10-M1		9,100	\$1,274
215894241	MDV	MOD30-36HFN10-M3	MVBE-36HWFN10-WL3E		24,800	\$3,472
215865889	MDV	MOE30-60HFN10-M3X	MVBC-60HWFPN10-MD3E		45,000	\$6,300
215865887	MDV	MOX630-48HFN10-M3	MVBC-48HWFPN10-MD3E		32,400	\$4,536
215865886	MDV	MOX630-48HFN10-M3X	MVBC-48HWFPN10-MD3E		37,000	\$5,180
215865884	MDV	MOX630-36HFN10-M3X	MVBC-36HWFPN10-MC3E		31,800	\$4,452
215865883	MDV	MOX430-24HFN10-M3	MVBC-24HWFPN10-MB3E		20,000	\$2,800
215865882	MDV	MOX430-24HFN10-M3X	MVBC-24HWFPN10-MB3E		20,000	\$2,800
215797518	MDV	MOD30-36HFN10-M3X	MVBC-36HWFN10-MC3E-D		23,200	\$3,248
215797517	MDV	MOD30-36HFN10-M3X	MVBC-36HWFN10-MC3E		23,200	\$3,248
215449739	MDV	MOX630-36HFN10-M3X	MVBDM-36HWFN10-WB3-D		31,000	\$4,340
213301873	MDV	MOD30U-30HFN1-MR0(X)	MVB-36B23T4N1		19,600	\$2,744
214855572	MDV	MOD30-24HFN10-M1X	MCD-24HRFN10-M1-D		20,400	\$2,856
207338213	MDV	MOE30U-36HFN1-M(GA)	MCD1-36HRFN1-M(GA)		33,000	\$4,620
207338216	MDV	MOE30U-48HFN1-M-[X](GA)	MCD1-48HRFN1-M(GA)		35,000	\$4,900
207338217	MDV	MOE30U-48HFN1-M-[X](GA)	MTI-48HWFN1-M		39,500	\$5,530
207338215	MDV	MOE30U-48HFN1-M-[X](GA)	MUE-48HRFN1-M(C)		35,000	\$4,900
201810023	MDV	M3OH-27HFN1-M	CS11M-09HRFN1-MX0W(A)		18,000	\$2,520
205746255	MDV	MOD30-24HFN1-MU0W	CS11M-23HRFN1-MT0W		19,400	\$2,716
215323719	MDV	MOX630-36HFN10-M3X	MVBDM-36HWFN10-WB3		31,000	\$4,340
215374763	MDV	MOX630-42HFN10-M3X-D	MVBC-48HWFN10-MD3E-DD		37,000	\$5,180
215359331	MDV	MOX630-48HFN10-M3X	MVBDM-60HWFN10-WC3-D		34,000	\$4,760
215359330	MDV	MOX630-48HFN10-M3	MVBC-60HWFN10-MD3E-D		32,400	\$4,536
215359327	MDV	MOX630-48HFN10-M3X	MVBC-60HWFN10-MD3E-D		37,000	\$5,180

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215359326	MDV	MOD30-30HFN10-M3X	MVBDM-36HWFN10-WB3-D		24,000	\$3,360
215359325	MDV	MOD30-30HFN10-M3X	MVBC-36HWFN10-MC3E-D		23,800	\$3,332
215359324	MDV	MOX430-18HFN10-M3X	MVBDM-24HWFN10-WA3-D		14,700	\$2,058
215359323	MDV	MOX430-18HFN10-M3X	MVBC-24HWFN10-MB3E-D		15,000	\$2,100
215318732	MDV	MOX630-48HFN10-M3X	MVBDM-60HWFN10-WC3		34,000	\$4,760
215318731	MDV	MOD30-30HFN10-M3X	MVBDM-36HWFN10-WB3		24,000	\$3,360
215318730	MDV	MOX430-18HFN10-M3X	MVBDM-24HWFN10-WA3		14,700	\$2,058
215351191	MDV	M5OX631-30HFN10-M1XD	Combination heat pumps with or without ducts		31,400	\$4,396
215351188	MDV	M5OX631-30HFN10-M1XD	Heat pump with ducts		33,000	\$4,620
215351187	MDV	M5OX631-30HFN10-M1XD	Heat pump without ducts		30,000	\$4,200
214861615	MDV	MOE30-60HFN10-M3X	MVBDM-60HWFN10-WC3-D		35,000	\$4,900
214861614	MDV	MOX630-48HFN10-M3X	MVBDM-48HWFN10-WC3-D		34,000	\$4,760
214861601	MDV	MOX630-48HFN10-M3	MVBC-48HWFN10-MD3E-D		32,400	\$4,536
214861598	MDV	MOX430-24HFN10-M3	MVBC-24HWFN10-MB3E-D		20,000	\$2,800
214861596	MDV	MOE30-60HFN10-M3X	MVBC-60HWFN10-MD3E-D		45,000	\$6,300
214861595	MDV	MOE30-48HFN10-M3X-D	MVBC-48HWFN10-MD3E-DD		45,000	\$6,300
214861594	MDV	MOX630-48HFN10-M3X	MVBC-48HWFN10-MD3E-D		37,000	\$5,180
214861593	MDV	MOX630-42HFN10-M3X-D	MVBC-42HWFN10-MD3E-DD		37,000	\$5,180
214861591	MDV	MOD30-36HFN10-M3X	MVBDM-36HWFN10-WB3-D		24,600	\$3,444
214861590	MDV	MOD30-30HFN10-M3X	MVBDM-30HWFN10-WB3-D		24,000	\$3,360
214861589	MDV	MOD30-30HFN10-M3X	MVBC-30HWFN10-MC3E-D		23,800	\$3,332

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214861588	MDV	MOX430-24HFN10-M3X	MVBDM-24HWFN10-WA3-D		19,000	\$2,660
214861586	MDV	MOX430-18HFN10-M3X	MVBDM-18HWFN10-WA3-D		14,700	\$2,058
214861577	MDV	MOE30-60HFN10-M2X	MVBC-60HWFN10-MD2-D		41,000	\$5,740
214861576	MDV	MOE30-48HFN10-M2X	MVBC-48HWFN10-MD2-D		40,000	\$5,600
214861575	MDV	MOX630-36HFN10-M2X	MVBC-36HWFN10-MC2-D		28,000	\$3,920
214861574	MDV	MOD30-33HFN10-M1X	MVBC-36HWFN10-MC1-D		27,400	\$3,836
214861573	MDV	MOD30-24HFN10-M1X	MVBC-24HWFN10-MB1-D		16,900	\$2,366
214861572	MDV	MOX430-18HFN10-M1X	MVBC-18HWFN10-MB1-D		14,000	\$1,960
214861567	MDV	MOE30-60HFN10-M2X	MVBC-60HWFN10-MD2		41,000	\$5,740
214861566	MDV	MOX630-36HFN10-M2X	MVBC-36HWFN10-MC2		28,000	\$3,920
214861555	MDV	MOX630-48HFN10-M3	MVBC-48HWFN10-MD3E		32,400	\$4,536
214861552	MDV	MOX430-24HFN10-M3	MVBC-24HWFN10-MB3E		20,000	\$2,800
214861550	MDV	MOE30-60HFN10-M3X	MVBDM-60HWFN10-WC3		35,000	\$4,900
214861549	MDV	MOE30-60HFN10-M3X	MVBC-60HWFN10-MD3E		45,000	\$6,300
214861548	MDV	MOX630-48HFN10-M3X	MVBDM-48HWFN10-WC3		34,000	\$4,760
214861547	MDV	MOX630-48HFN10-M3X	MVBC-48HWFN10-MD3E		37,000	\$5,180
214861545	MDV	MOD30-36HFN10-M3X	MVBDM-36HWFN10-WB3		24,600	\$3,444
214861544	MDV	MOD30-30HFN10-M3X	MVBDM-30HWFN10-WB3		24,000	\$3,360
214861543	MDV	MOD30-30HFN10-M3X	MVBC-30HWFN10-MC3E		23,800	\$3,332
214861542	MDV	MOX430-24HFN10-M3X	MVBDM-24HWFN10-WA3		19,000	\$2,660
214861540	MDV	MOX430-18HFN10-M3X	MVBDM-18HWFN10-WA3		14,700	\$2,058
214861531	MDV	MOE30-48HFN10-M2X	MVBC-48HWFN10-MD2		40,000	\$5,600
214861530	MDV	MOD30-33HFN10-M1X	MVBC-36HWFN10-MC1		27,400	\$3,836
214861529	MDV	MOD30-24HFN10-M1X	MVBC-24HWFN10-MB1		16,900	\$2,366
214861528	MDV	MOX430-18HFN10-M1X	MVBC-18HWFN10-MB1		14,000	\$1,960
214855573	MDV	MOD30-24HFN10-M1X	MUE-24HRFN10-M1-D		20,200	\$2,828
214855571	MDV	MOX430-18HFN10-M1X	MUE-18HRFN10-M1-D		14,400	\$2,016
214855570	MDV	MOX430-18HFN10-M1X	MFA2-16HRFN10-M1-D		14,200	\$1,988
214855569	MDV	MOX430-18HFN10-M1X	MCA4-18HRFN10-M1-D		14,900	\$2,086
214855568	MDV	MOX430-18HFN10-M1X	MCB-18HRFN10-M1-D		14,500	\$2,030
214855565	MDV	MOX330-12HFN10-M1X	MCA4M-12HRFN10-M1-D		10,000	\$1,400
214855564	MDV	MOX330-12HFN10-M1X	MCBM-12HRFN10-M1-D		9,600	\$1,344
214855545	MDV	MOE30-60HFN10-M2X	MUE-60HRFN10-M2-D		41,000	\$5,740
214855544	MDV	MOE30-48HFN10-M2X	MUE-48HRFN10-M2-D		38,500	\$5,390
214855543	MDV	MOE30-48HFN10-M2X	MCD-48HRFN10-M2-D		44,000	\$6,160
214855542	MDV	MOX630-36HFN10-M2X	MUE-36HRFN10-M2-D		30,200	\$4,228

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214855541	MDV	MOX630-36HFN10-M2X	MCD-36HRFN10-M2-D		30,600	\$4,284
214855493	MDV	MOE30-60HFN10-M2X	MUE-60HRFN10-M2		41,000	\$5,740
214855492	MDV	MOE30-48HFN10-M2X	MUE-48HRFN10-M2		38,500	\$5,390
214855491	MDV	MOE30-48HFN10-M2X	MCD-48HRFN10-M2		44,000	\$6,160
214855490	MDV	MOX630-36HFN10-M2X	MUE-36HRFN10-M2		30,200	\$4,228
214855489	MDV	MOX630-36HFN10-M2X	MCD-36HRFN10-M2		30,600	\$4,284
214855485	MDV	MOD30-24HFN10-M1X	MUE-24HRFN10-M1		20,200	\$2,828
214855483	MDV	MOX430-18HFN10-M1X	MUE-18HRFN10-M1		14,400	\$2,016
214855416	MDV	MOX430-18HFN10-M1X	MFA2-16HRFN10-M1		14,200	\$1,988
214855415	MDV	MOX430-18HFN10-M1X	MCA4-18HRFN10-M1		14,900	\$2,086
214855414	MDV	MOX430-18HFN10-M1X	MCB-18HRFN10-M1		14,500	\$2,030
214855411	MDV	MOX330-12HFN10-M1X	MCA4M-12HRFN10-M1		10,000	\$1,400
214855410	MDV	MOX330-12HFN10-M1X	MCBM-12HRFN10-M1		9,600	\$1,344
214861958	MDV	MOE30-60HFN10-M2X	MHJ-60HWFN10-M2-D		45,000	\$6,300
214861955	MDV	MOE30-48HFN10-M2X	MTJ-48HWFN10-M2-D		45,000	\$6,300
214861954	MDV	MOX630-36HFN10-M2X	MTJ-36HWFN10-M2-D		31,600	\$4,424
214861944	MDV	MOD30-24HFN10-M1X	MTJ-24HWFN10-M1-D		21,600	\$3,024
214861943	MDV	MOX430-18HFN10-M1X	MTJ-18HWFN10-M1-D		15,000	\$2,100
214861942	MDV	MOX430-18HFN10-M1X	MTI-18HWFN10-M1-D		15,000	\$2,100
214861941	MDV	MOX330-12HFN10-M1X	MTJM-12HWFN10-M1-D		10,200	\$1,428
214861940	MDV	MOX330-12HFN10-M1X	MTIM-12HWFN10-M1-D		9,600	\$1,344
214861928	MDV	MOX430-18HFN10-M1X	MTJ-18HWFN10-M1		15,000	\$2,100
214861927	MDV	MOX330-12HFN10-M1X	MTJM-12HWFN10-M1		10,200	\$1,428
214855477	MDV	MOE30-60HFN10-M2X	MHJ-60HWFN10-M2		45,000	\$6,300
214855476	MDV	MOE30-48HFN10-M2X	MTJ-48HWFN10-M2		45,000	\$6,300
214855475	MDV	MOX630-36HFN10-M2X	MTJ-36HWFN10-M2		31,600	\$4,424
214855420	MDV	MOD30-24HFN10-M1X	MTJ-24HWFN10-M1		21,600	\$3,024
214855417	MDV	MOX430-18HFN10-M1X	MTI-18HWFN10-M1		15,000	\$2,100
214855413	MDV	MOX330-12HFN10-M1X	MTIM-12HWFN10-M1		9,600	\$1,344
214861336	MDV	MOD30-33HFN10-M1X	MSAG11F-33HRFN10-M1		29,600	\$4,144
214855567	MDV	MOX430-18HFN10-M1X	MSEPC-18HRFN10-M1-D		15,000	\$2,100
214855510	MDV	MOD30-33HFN10-M1X	MSEPD-33HRFN10-M1-D		30,000	\$4,200
214855509	MDV	MOD30-24HFN10-M1X	MSEPD-24HRFN10-M1-D		21,000	\$2,940
214855504	MDV	MOD30-18HFN10-M1H	MSEPD-18HRFN10-M1H-D		19,300	\$2,702
214855503	MDV	MOX430-12HFN10-M1H	MSEPC-12HRFN10-M1H-D		11,000	\$1,540
214855500	MDV	MOD30-18HFN10-M1H	MSEPD-18HRFN10-M1H-C		19,300	\$2,702
214855499	MDV	MOX430-12HFN10-M1H	MSEPC-12HRFN10-M1H-C		11,000	\$1,540
214855421	MDV	MOD30-33HFN10-M1X	MSEPD-33HRFN10-M1		30,000	\$4,200

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214855419	MDV	MOD30-24HFN10-M1X	MSAG11D-23HRFN10-M1		21,600	\$3,024
214855418	MDV	MOD30-24HFN10-M1X	MSEPD-24HRFN10-M1		21,000	\$2,940
214855399	MDV	MOD30-18HFN10-M1H	MSEPD-18HRFN10-M1H		19,300	\$2,702
214855398	MDV	MOX430-12HFN10-M1H	MSEPC-12HRFN10-M1H		11,000	\$1,540
214311116	MDV	MOX430-18HFN10-M1X	MSEPC-18HRFN10-M1		15,000	\$2,100
214861918	MDV	M6OE30-48HFN10-M1-D*	Heat pump with ducts		37,000	\$5,180
214861906	MDV	M6OE30-48HFN10-M1-D	Heat pump with ducts		37,000	\$5,180
214861898	MDV	M6OE31-53HFN10-M1X-D*	Combination heat pumps with or without ducts		45,000	\$6,300
214861897	MDV	M6OE31-53HFN10-M1X-D*	Heat pump with ducts		45,000	\$6,300
214861896	MDV	M6OE31-53HFN10-M1X-D*	Heat pump without ducts		45,000	\$6,300
214861895	MDV	M6OE31-48HFN10-M1X-D*	Combination heat pumps with or without ducts		42,500	\$5,950
214861894	MDV	M6OE31-48HFN10-M1X-D*	Heat pump with ducts		44,500	\$6,230
214861893	MDV	M6OE31-48HFN10-M1X-D*	Heat pump without ducts		40,500	\$5,670
214861892	MDV	M5OX631-36HFN10-M1X-D*	Combination heat pumps with or without ducts		34,800	\$4,872
214861891	MDV	M5OX631-36HFN10-M1X-D*	Heat pump with ducts		33,000	\$4,620
214861890	MDV	M5OX631-36HFN10-M1X-D*	Heat pump without ducts		36,600	\$5,124
214861889	MDV	M4OD31-27HFN10-M1X-D*	Combination heat pumps with or without ducts		23,200	\$3,248
214861888	MDV	M4OD31-27HFN10-M1X-D*	Heat pump with ducts		23,000	\$3,220
214861887	MDV	M4OD31-27HFN10-M1X-D*	Heat pump without ducts		23,600	\$3,304
214861886	MDV	M3OD31-18HFN10-M1X-D*	Combination heat pumps with or without ducts		16,700	\$2,338
214861885	MDV	M3OD31-18HFN10-M1X-D*	Heat pump with ducts		17,000	\$2,380
214861884	MDV	M3OD31-18HFN10-M1X-D*	Heat pump without ducts		16,400	\$2,296
214861883	MDV	M6OE31-53HFN10-M1X-D	Combination heat pumps with or without ducts		44,500	\$6,230

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214861882	MDV	M6OE31-53HFN10-M1X-D	Heat pump with ducts		45,000	\$6,300
214861881	MDV	M6OE31-53HFN10-M1X-D	Heat pump without ducts		44,000	\$6,160
214861880	MDV	M6OE31-48HFN10-M1X-D	Combination heat pumps with or without ducts		44,000	\$6,160
214861879	MDV	M6OE31-48HFN10-M1X-D	Heat pump with ducts		44,500	\$6,230
214861878	MDV	M6OE31-48HFN10-M1X-D	Heat pump without ducts		44,000	\$6,160
214861877	MDV	M5OX631-36HFN10-M1X-D	Combination heat pumps with or without ducts		31,400	\$4,396
214861876	MDV	M5OX631-36HFN10-M1X-D	Heat pump with ducts		33,000	\$4,620
214861875	MDV	M5OX631-36HFN10-M1X-D	Heat pump without ducts		30,000	\$4,200
214861874	MDV	M4OD31-27HFN10-M1X-D	Combination heat pumps with or without ducts		24,000	\$3,360
214861873	MDV	M4OD31-27HFN10-M1X-D	Heat pump with ducts		23,000	\$3,220
214861872	MDV	M4OD31-27HFN10-M1X-D	Heat pump without ducts		25,000	\$3,500
214861871	MDV	M3OD31-18HFN10-M1X-D	Combination heat pumps with or without ducts		17,300	\$2,422
214861870	MDV	M3OD31-18HFN10-M1X-D	Heat pump with ducts		17,000	\$2,380
214861869	MDV	M3OD31-18HFN10-M1X-D	Heat pump without ducts		17,600	\$2,464
214861864	MDV	M6OE30-48HFN10-M1D-D*	Heat pump with ducts		37,000	\$5,180
214861849	MDV	M6OE30-48HFN10-M1D-D	Heat pump with ducts		37,000	\$5,180
214861838	MDV	M6OE31-53HFN10-M1XD-D*	Combination heat pumps with or without ducts		45,000	\$6,300
214861837	MDV	M6OE31-53HFN10-M1XD-D*	Heat pump with ducts		45,000	\$6,300
214861836	MDV	M6OE31-53HFN10-M1XD-D*	Heat pump without ducts		45,000	\$6,300

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214861835	MDV	M6OE31-48HFN10-M1XD-D*	Combination heat pumps with or without ducts		42,500	\$5,950
214861834	MDV	M6OE31-48HFN10-M1XD-D*	Heat pump with ducts		44,500	\$6,230
214861833	MDV	M6OE31-48HFN10-M1XD-D*	Heat pump without ducts		40,500	\$5,670
214861832	MDV	M5OX631-36HFN10-M1XD-D*	Combination heat pumps with or without ducts		34,800	\$4,872
214861831	MDV	M5OX631-36HFN10-M1XD-D*	Heat pump with ducts		33,000	\$4,620
214861830	MDV	M5OX631-36HFN10-M1XD-D*	Heat pump without ducts		36,600	\$5,124
214861829	MDV	M4OD31-27HFN10-M1XD-D*	Combination heat pumps with or without ducts		23,200	\$3,248
214861828	MDV	M4OD31-27HFN10-M1XD-D*	Heat pump with ducts		23,000	\$3,220
214861827	MDV	M4OD31-27HFN10-M1XD-D*	Heat pump without ducts		23,600	\$3,304
214861826	MDV	M3OD31-18HFN10-M1XD-D*	Combination heat pumps with or without ducts		16,700	\$2,338
214861825	MDV	M3OD31-18HFN10-M1XD-D*	Heat pump with ducts		17,000	\$2,380
214861824	MDV	M3OD31-18HFN10-M1XD-D*	Heat pump without ducts		16,400	\$2,296
214861823	MDV	M6OE31-53HFN10-M1XD-D	Combination heat pumps with or without ducts		44,500	\$6,230
214861822	MDV	M6OE31-53HFN10-M1XD-D	Heat pump with ducts		45,000	\$6,300
214861821	MDV	M6OE31-53HFN10-M1XD-D	Heat pump without ducts		44,000	\$6,160
214861820	MDV	M6OE31-48HFN10-M1XD-D	Combination heat pumps with or without ducts		44,000	\$6,160
214861819	MDV	M6OE31-48HFN10-M1XD-D	Heat pump with ducts		44,500	\$6,230
214861818	MDV	M6OE31-48HFN10-M1XD-D	Heat pump without ducts		44,000	\$6,160
214861816	MDV	M5OX631-36HFN10-M1XD-D	Heat pump with ducts		33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214861814	MDV	M4OD31-27HFN10-M1XD-D	Combination heat pumps with or without ducts		24,000	\$3,360
214861813	MDV	M4OD31-27HFN10-M1XD-D	Heat pump with ducts		23,000	\$3,220
214861812	MDV	M4OD31-27HFN10-M1XD-D	Heat pump without ducts		25,000	\$3,500
214861811	MDV	M3OD31-18HFN10-M1XD-D	Combination heat pumps with or without ducts		17,300	\$2,422
214861810	MDV	M3OD31-18HFN10-M1XD-D	Heat pump with ducts		17,000	\$2,380
214861809	MDV	M3OD31-18HFN10-M1XD-D	Heat pump without ducts		17,600	\$2,464
214861804	MDV	M6OE30-48HFN10-M1*	Heat pump with ducts		37,000	\$5,180
214861796	MDV	M6OE31-53HFN10-M1X*	Combination heat pumps with or without ducts		45,000	\$6,300
214861795	MDV	M6OE31-53HFN10-M1X*	Heat pump with ducts		45,000	\$6,300
214861794	MDV	M6OE31-53HFN10-M1X*	Heat pump without ducts		45,000	\$6,300
214861793	MDV	M6OE31-48HFN10-M1X*	Combination heat pumps with or without ducts		42,500	\$5,950
214861792	MDV	M6OE31-48HFN10-M1X*	Heat pump with ducts		44,500	\$6,230
214861791	MDV	M6OE31-48HFN10-M1X*	Heat pump without ducts		40,500	\$5,670
214861790	MDV	M5OX631-36HFN10-M1X**	Combination heat pumps with or without ducts		34,800	\$4,872
214861789	MDV	M5OX631-36HFN10-M1X**	Heat pump with ducts		33,000	\$4,620
214861788	MDV	M5OX631-36HFN10-M1X**	Heat pump without ducts		36,600	\$5,124
214861787	MDV	M5OX631-36HFN10-M1X*	Combination heat pumps with or without ducts		31,400	\$4,396
214861786	MDV	M5OX631-36HFN10-M1X*	Heat pump with ducts		33,000	\$4,620
214861785	MDV	M5OX631-36HFN10-M1X*	Heat pump without ducts		30,000	\$4,200
214861784	MDV	M4OD31-27HFN10-M1X*	Combination heat pumps with or without ducts		23,200	\$3,248
214861783	MDV	M4OD31-27HFN10-M1X*	Heat pump with ducts		23,000	\$3,220
214861782	MDV	M4OD31-27HFN10-M1X*	Heat pump without ducts		23,600	\$3,304
214861781	MDV	M3OD31-18HFN10-M1X*	Combination heat pumps with or without ducts		16,700	\$2,338
214861780	MDV	M3OD31-18HFN10-M1X*	Heat pump with ducts		17,000	\$2,380
214861779	MDV	M3OD31-18HFN10-M1X*	Heat pump without ducts		16,400	\$2,296

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214861774	MDV	M6OE30-48HFN10-M1D*	Heat pump with ducts		37,000	\$5,180
214861763	MDV	M6OE31-53HFN10-M1XD*	Combination heat pumps with or without ducts		45,000	\$6,300
214861762	MDV	M6OE31-53HFN10-M1XD*	Heat pump with ducts		45,000	\$6,300
214861761	MDV	M6OE31-53HFN10-M1XD*	Heat pump without ducts		45,000	\$6,300
214861760	MDV	M6OE31-48HFN10-M1XD*	Combination heat pumps with or without ducts		42,500	\$5,950
214861759	MDV	M6OE31-48HFN10-M1XD*	Heat pump with ducts		44,500	\$6,230
214861758	MDV	M6OE31-48HFN10-M1XD*	Heat pump without ducts		40,500	\$5,670
214861757	MDV	M5OX631-36HFN10-M1XD*	Combination heat pumps with or without ducts		34,800	\$4,872
214861756	MDV	M5OX631-36HFN10-M1XD*	Heat pump with ducts		33,000	\$4,620
214861755	MDV	M5OX631-36HFN10-M1XD*	Heat pump without ducts		36,600	\$5,124
214861754	MDV	M4OD31-27HFN10-M1XD*	Combination heat pumps with or without ducts		23,200	\$3,248
214861753	MDV	M4OD31-27HFN10-M1XD*	Heat pump with ducts		23,000	\$3,220
214861752	MDV	M4OD31-27HFN10-M1XD*	Heat pump without ducts		23,600	\$3,304
214861751	MDV	M3OD31-18HFN10-M1XD*	Combination heat pumps with or without ducts		16,700	\$2,338
214861750	MDV	M3OD31-18HFN10-M1XD*	Heat pump with ducts		17,000	\$2,380
214861749	MDV	M3OD31-18HFN10-M1XD*	Heat pump without ducts		16,400	\$2,296
214861741	MDV	M6OE30-48HFN10-M1	Heat pump with ducts		37,000	\$5,180
214861731	MDV	M6OE31-53HFN10-M1X	Combination heat pumps with or without ducts		44,500	\$6,230
214861730	MDV	M6OE31-53HFN10-M1X	Heat pump with ducts		45,000	\$6,300
214861729	MDV	M6OE31-53HFN10-M1X	Heat pump without ducts		44,000	\$6,160
214861728	MDV	M6OE31-48HFN10-M1X	Combination heat pumps with or without ducts		44,000	\$6,160
214861727	MDV	M6OE31-48HFN10-M1X	Heat pump with ducts		44,500	\$6,230

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214861726	MDV	M6OE31-48HFN10-M1X	Heat pump without ducts		44,000	\$6,160
214861724	MDV	M4OD31-27HFN10-M1X	Combination heat pumps with or without ducts		24,000	\$3,360
214861723	MDV	M4OD31-27HFN10-M1X	Heat pump with ducts		23,000	\$3,220
214861722	MDV	M4OD31-27HFN10-M1X	Heat pump without ducts		25,000	\$3,500
214861721	MDV	M3OD31-18HFN10-M1X	Combination heat pumps with or without ducts		17,300	\$2,422
214861720	MDV	M3OD31-18HFN10-M1X	Heat pump with ducts		17,000	\$2,380
214861719	MDV	M3OD31-18HFN10-M1X	Heat pump without ducts		17,600	\$2,464
214861717	MDV	M6OE30-48HFN10-M1D	Heat pump with ducts		37,000	\$5,180
214861706	MDV	M6OE31-53HFN10-M1XD	Combination heat pumps with or without ducts		44,500	\$6,230
214861705	MDV	M6OE31-53HFN10-M1XD	Heat pump with ducts		45,000	\$6,300
214861704	MDV	M6OE31-53HFN10-M1XD	Heat pump without ducts		44,000	\$6,160
214861703	MDV	M6OE31-48HFN10-M1XD	Combination heat pumps with or without ducts		44,000	\$6,160
214861702	MDV	M6OE31-48HFN10-M1XD	Heat pump with ducts		44,500	\$6,230
214861701	MDV	M6OE31-48HFN10-M1XD	Heat pump without ducts		44,000	\$6,160
214861699	MDV	M5OX631-36HFN10-M1XD	Heat pump with ducts		33,000	\$4,620
214861697	MDV	M4OD31-27HFN10-M1XD	Combination heat pumps with or without ducts		24,000	\$3,360
214861696	MDV	M4OD31-27HFN10-M1XD	Heat pump with ducts		23,000	\$3,220
214861695	MDV	M4OD31-27HFN10-M1XD	Heat pump without ducts		25,000	\$3,500
214861694	MDV	M3OD31-18HFN10-M1XD	Combination heat pumps with or without ducts		17,300	\$2,422
214861693	MDV	M3OD31-18HFN10-M1XD	Heat pump with ducts		17,000	\$2,380
214861692	MDV	M3OD31-18HFN10-M1XD	Heat pump without ducts		17,600	\$2,464
212928549	MDV	MOE31U-36HFN1-M	MVB-36B23T4N1		27,400	\$3,836
212360172	MDV	M3OK-27HFN1-M	Heat pump without ducts		23,000	\$3,220
212360173	MDV	M3OK-27HFN1-M*	Heat pump without ducts		22,400	\$3,136
213301876	MDV	M4OX630-36HFN1-M1X	Heat pump without ducts		27,400	\$3,836
207617657	MDV	M5OG-42HFN1-M-[X]	MSEP8-09HFRN1-MY5W(GA)		30,000	\$4,200
213479413	MDV	MOX630-36HFN1-M3X	MVC-36HWFN1-M		31,800	\$4,452
213386476	MDV	MOX630-36HFN1-M3X	MAC-36HWDN1-MN0		27,000	\$3,780
213386475	MDV	MOX630-36HFN1-M3X	MVB-36B23T4N1		27,000	\$3,780
213386477	MDV	MOE31U-36HFN1-M	MVBL-36HWFN1-MK3		32,800	\$4,592
213352879	MDV	MOD30-24HFN1-MW	MVBL-24HWFN1-MI3		19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213352878	MDV	MOX430U-18HFN1-M	MVBL-18HWFN1-MH3		13,500	\$1,890
213352801	MDV	MOD30U-30HFN1-MR0(X)	MVBL-30HWFN1-MJ3		20,000	\$2,800
213301879	MDV	M4OX630-36HFN1-M1X*	Combination heat pumps with or without ducts		28,600	\$4,004
213301878	MDV	M4OX630-36HFN1-M1X*	Heat pump with ducts		30,000	\$4,200
213301877	MDV	M4OX630-36HFN1-M1X*	Heat pump without ducts		27,400	\$3,836
213301880	MDV	M4OX630-36HFN1-M1X	Combination heat pumps with or without ducts		28,600	\$4,004
213301875	MDV	M4OX630-36HFN1-M1X	Heat pump with ducts		30,000	\$4,200
213214820	MDV	MOD30U-36HFN1-MR0	MVC-30HWFN1-M		17,000	\$2,380
212360177	MDV	M3OK-27HFN1-M*	Combination heat pumps with or without ducts		22,600	\$3,164
212360176	MDV	M3OK-27HFN1-M	Combination heat pumps with or without ducts		23,000	\$3,220
205767336	MDV	MOE30U-36HFN1-M-[X]	MCD-36HRFN1-M(C)		25,400	\$3,556
204829818	MDV	MOE30U-48HFN1-M-[X]	MUE-48HRFN1-M(C)		35,000	\$4,900
207690463	MDV	MOD30U-30HFN1-MR0(X)	MVC-30HWFN1-M		19,400	\$2,716
207690465	MDV	MOE30U-48HFN1-M-[X1]	MVC-48HWFN1-M		32,000	\$4,480
202415590	MDV	MOD30-22HFN1-MW5W	MSAB2F-22HRFN1-MW5W		15,400	\$2,156
200059283	MDV	MOCA30-12HFN1-MZ50W	MSOP1B-12HRFN1-MZ50W		6,800	\$952
10028966	MDV	MOD30-24HFN1-MT0W*	MTIU-24HWFN1-M		17,200	\$2,408
205767337	MDV	MOE30U-36HFN1-M-[X]	MTI-36HWFN1-M		28,000	\$3,920
205306855	MDV	M5OG-48HFN1-M-[X]	MTIU-09HWFN1-M		28,000	\$3,920
204829821	MDV	MOE30U-48HFN1-M-[X]	MTI-48HWFN1-M		33,000	\$4,620
204829817	MDV	MOE30U-48HFN1-M-[X]	MCD-48HRFN1-M(D)		35,000	\$4,900
205782859	MDV	MOD30-24HFN1-MT0W	MVB-24HWFN1-M		17,500	\$2,450
205823026	MDV	MOE30U-32HFN1-M-[X]	MTI-32HWFN1-M		25,000	\$3,500
206143051	MDV	MOD30-24HFN1-MU0W	MVB-24HWFN1-M		16,500	\$2,310
205746254	MDV	MOX430-17HFN1-MT0W	CS11M-18HRFN1-MT0W		10,900	\$1,526
207742580	MDV	MOD30-24HFN1-MU0W	MVB-24HWFN1-M		16,500	\$2,310
207742579	MDV	MOD30-24HFN1-MT0W	MVB-24HWFN1-M		17,500	\$2,450
207690464	MDV	MOE31U-36HFN1-M	MVC-36HWFN1-M		24,000	\$3,360
207690461	MDV	MOX430U-18HFN1-M	MVC-18HWFN1-M		13,000	\$1,820
207690462	MDV	MOD30-24HFN1-MW	MVC-24HWFN1-M		16,700	\$2,338
207641229	MDV	M4OI-36HFN1-M	MTIU-09HWFN1-M		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207618262	MDV	M5OG-42HFN1-M-[X]	42		29,000	\$4,060
207617659	MDV	M5OG-42HFN1-M-[X]	MTIU-09HWFN1-M		28,000	\$3,920
207641248	MDV	M4OI-36HFN1-M*	MTIU-09HWFN1-M		23,000	\$3,220
205306856	MDV	M5OG-48HFN1-M-[X]	Heat pump without ducts		30,000	\$4,200
208101911	MDV	MOD30U-30HFN1-MR0(X)	MAC-36HWDN1-MN0		22,600	\$3,164
209960477	MDV	MOE30U-55HFN1-MQ3	MVC-60HWFN1-MR0		42,000	\$5,880
210191039	MDV	MOE30U-48HFN1-M-[X]	MVC-48HWFN1-MQ3		36,000	\$5,040
209960476	MDV	MOE30U-55HFN1-M	MVC-60HWFN1-M		42,000	\$5,880
207699011	MDV	MOE30U-48HFN1-M-[X1]	MVC-48HWFN1-M		36,000	\$5,040
209960478	MDV	MOE30U-55HFN1-M-[X](GA)	MVC-60HWFN1-M(GA)		41,000	\$5,740
208128249	MDV	MOE30U-48HFN1-M-[X](GA)	MVC-48HWFN1-M(GA)		38,000	\$5,320
208128248	MDV	MOE30U-36HFN1-M(GA)	MVC-36HWFN1-M(GA)		28,600	\$4,004
210321397	MDV	MOD30-24HFN1-MU0W	MAC-24HWDN1-MN0-N		22,000	\$3,080
213156951	MDV	MOX430U-18HFN1-M	MVBE-18HWFN1-MM3E		15,800	\$2,212
211497142	MDV	MOD30-24HFN1-MW-[X1]	MVC-24HWFN1-MSQ4		19,200	\$2,688
212924805	MDV	MOD30-24HFN1-MW	MVBE-24HWFN1-MM3E		20,000	\$2,800
212365390	MDV	MOE30U-55HFN1-M	MAC-60HWDN1-MN0		37,000	\$5,180
212365391	MDV	MOE30U-45HFN1-M	MAC-60HWDN1-MN0		37,000	\$5,180
207338212	MDV	MOE30U-36HFN1-M(GA)	MUE-36HRFN1-M(C)		32,000	\$4,480
210135400	MDV	MOE30U-55HFN1-M-[X](GA)	MUE-60HRFN1-MW		40,000	\$5,600
210135402	MDV	MOE30U-55HFN1-M-[X](GA)	MHG-60HWFN1-MW		40,000	\$5,600
211749869	MDV	MOD30-33HFN1-MSR0W	MSAGF-33HRFN1-MSR0W		27,800	\$3,892
211749870	MDV	MOD30-33HFN1-MSR0W	MSEPD-33HRFN1-MSR0W		28,800	\$4,032
217154263	MIDEA	DLCURAH24ABK	DLFULAH24XBX		21,000	\$2,940
217154267	MIDEA	DLCURAH36ACK	DLFULAH36XCX		27,000	\$3,780
217154266	MIDEA	DLCURAH36ACK	DLFULAH36XBX		27,000	\$3,780
217154268	MIDEA	DLCURAH36ABK	DLFULAH36XBX		27,400	\$3,836
217154265	MIDEA	DLCURAH30ABK	DLFULAH36XCX		22,600	\$3,164
217154269	MIDEA	DLCURAH36ABK	DLFULAH36XCX		33,000	\$4,620
217154271	MIDEA	DLCURAH60ABK	DLFULAH60XDX		37,000	\$5,180
216623528	MIDEA	MO1HE-H60B-2A	MAAHE-H60B-DA		36,000	\$5,040
215471465	MIDEA	MO5HX-H36B-2A	Combination heat pumps with or without ducts		31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215471463	MIDEA	MO5HX-H36B-2A	Heat pump without ducts		30,000	\$4,200
206361900	MIDEA	DLCSRBH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361902	MIDEA	DLCSRBH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361901	MIDEA	DLCSRBH18AAK	DLFSHBH18XAK		11,100	\$1,554
207614972	MIDEA	DLCPRBH12AAK	DLFPHBH12XAK		10,400	\$1,456
210857451	MIDEA	DLCSRBH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857452	MIDEA	DLCSRBH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132699	MIDEA	DLCSRBH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948197	MIDEA	DLCSRBH12AAK	DLFSFBH12XAK		10,200	\$1,428
207826650	MIDEA	DLCPRBH18AAK	DLFPHBH18XAK		20,200	\$2,828
207683369	MIDEA	DLCSRBH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447663	MIDEA	DLCSRBH24AAK	DLFSCH24XAK		21,200	\$2,968
208447667	MIDEA	DLCSRBH18AAK	DLFSCH18XAK		15,000	\$2,100
208447662	MIDEA	DLCSRBH12AAK	DLFSCH12XAK		10,000	\$1,400
211132736	MIDEA	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
211132697	MIDEA	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
216021082	MIDEA	MDV-V60WMN10T	Combination heat pumps with or without ducts		42,000	\$5,880
216021081	MIDEA	MDV-V60WMN10T	Heat pump without ducts		42,000	\$5,880
216021080	MIDEA	MDV-V48WMN10T	Combination heat pumps with or without ducts		35,000	\$4,900
216021061	MIDEA	MDV-V48WMN10T	Heat pump with ducts		35,000	\$4,900
215323789	MIDEA	37MAHAQ18AA3	D5MAHAQ18XA3		16,600	\$2,324
215324555	MIDEA	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
216021074	MIDEA	MDV-V24WMN10T	Combination heat pumps with or without ducts		18,000	\$2,520
216021079	MIDEA	MDV-V48WMN10T	Heat pump without ducts		35,000	\$4,900
216021078	MIDEA	MDV-V36WMN10T	Combination heat pumps with or without ducts		29,200	\$4,088
216021077	MIDEA	MDV-V36WMN10T	Heat pump without ducts		27,800	\$3,892
216021076	MIDEA	MDV-V30WMN10T	Combination heat pumps with or without ducts		26,000	\$3,640
216021075	MIDEA	MDV-V30WMN10T	Heat pump without ducts		26,000	\$3,640
216021073	MIDEA	MDV-V24WMN10T	Heat pump without ducts		18,300	\$2,562
216021072	MIDEA	MDV-V18WMN10T	Combination heat pumps with or without ducts		17,600	\$2,464
216021071	MIDEA	MDV-V18WMN10T	Heat pump without ducts		17,600	\$2,464
216021062	MIDEA	MDV-V60WMN10T	Heat pump with ducts		42,000	\$5,880
216021060	MIDEA	MDV-V36WMN10T	Heat pump with ducts		30,600	\$4,284

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216021059	MIDEA	MDV-V30WMN10T	Heat pump with ducts		26,000	\$3,640
216021058	MIDEA	MDV-V24WMN10T	Heat pump with ducts		17,700	\$2,478
216021057	MIDEA	MDV-V18WMN10T	Heat pump with ducts		17,600	\$2,464
215471382	MIDEA	MO1HS-H18B-2A	MSEHU-H18B-2A		16,600	\$2,324
216441713	MIDEA	MDV-V60WMN10T	MCPM4860DN10TH		38,000	\$5,320
216441719	MIDEA	MDV-V60WMN10T	MIH54VMN10		40,000	\$5,600
216051346	MIDEA	MDV-V60WMN10T	MVME60C2MN10TB		38,000	\$5,320
216441712	MIDEA	MDV-V48WMN10T	MCPM4860DN10TH		36,000	\$5,040
216441718	MIDEA	MDV-V48WMN10T	MIH48VMN10		36,800	\$5,152
216051345	MIDEA	MDV-V48WMN10T	MVME48C2MN10TB		36,000	\$5,040
216440560	MIDEA	MDV-V30WMN10T	MHVE30B1MN10TB		26,200	\$3,668
216441716	MIDEA	MDV-V30WMN10T	MIH30VMN10		26,000	\$3,640
216054429	MIDEA	MDV-V24WMN10T	MCPM3036BN10TH	MGV96U060B3C	17,600	\$2,464
216441715	MIDEA	MDV-V24WMN10T	MIH24VMN10		18,000	\$2,520
216706219	MIDEA	MDV-V36WMN10T-H	MCPM3036BN10TH		29,400	\$4,116
216706218	MIDEA	MDV-V30WMN10T-H	MCPM3036BN10TH		24,000	\$3,360
216706217	MIDEA	MDV-V24WMN10T-H	MCPM3036BN10TH		19,400	\$2,716
215471331	MIDEA	MO1HE-H18B-2A	MAUHE-H18B-2A		15,000	\$2,100
215471433	MIDEA	MO1HS-H12B-2A	MFAHU-H12B-2A		9,800	\$1,372
215471381	MIDEA	MO1HS-H12B-2A	MSEHU-H12B-2A		9,800	\$1,372
215471332	MIDEA	MO1HE-H24B-2A	MAUHE-H24B-2A		20,000	\$2,800
215471334	MIDEA	MO1SE-H36B-2A	MAUHE-H36B-2A		31,800	\$4,452
216054431	MIDEA	MDV-V60WMN10T	MCPM4860CN10TH	MGV96U100C5C	38,000	\$5,320
216046596	MIDEA	MDV-V60WMN10T	MCPM4860DN10TH	MGV96U100D5C	38,000	\$5,320
216440563	MIDEA	MDV-V36WMN10T	MPCE36B1MN10TA		31,200	\$4,368
216440562	MIDEA	MDV-V36WMN10T	MHVE36B1MN10TB		32,000	\$4,480
216441717	MIDEA	MDV-V36WMN10T	MIH36VMN10		31,200	\$4,368
216441711	MIDEA	MDV-V36WMN10T	MCPM4860DN10TH		31,000	\$4,340
216046594	MIDEA	MDV-V36WMN10T	MCPM3036BN10TH	MGV96U080B3C	29,000	\$4,060
216051344	MIDEA	MDV-V36WMN10T	MVME36B2MN10TB		27,800	\$3,892
216440561	MIDEA	MDV-V30WMN10T	MPCE30B1MN10TA		26,200	\$3,668
216441710	MIDEA	MDV-V30WMN10T	MCPM4860DN10TH		24,000	\$3,360
216046593	MIDEA	MDV-V30WMN10T	MCPM3036BN10TH	MGV96U080B3C	24,400	\$3,416
216440559	MIDEA	MDV-V24WMN10T	MPCE24A1MN10TA		18,400	\$2,576
216441707	MIDEA	MDV-V24WMN10T	MHVE24A1MN10TB		18,400	\$2,576
216441709	MIDEA	MDV-V24WMN10T	MCPM4860DN10TH		18,000	\$2,520
216441706	MIDEA	MDV-V18WMN10T	MHVE18A1MN10TB		15,600	\$2,184
216441708	MIDEA	MDV-V18WMN10T	MCPM3036BN10TH		17,000	\$2,380

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216441714	MIDEA	MDV-V18WMN10T	MIH18VMN10		15,600	\$2,184
216046591	MIDEA	MDV-V18WMN10T	MCPM3036BN10TH	MGV96U080B3C	15,700	\$2,198
216051341	MIDEA	MDV-V18WMN10T	MVME24B2MN10TB		15,100	\$2,114
216054428	MIDEA	MDV-V18WMN10T	MCPM3036BN10TH	MGV96U060B3C	15,700	\$2,198
216440558	MIDEA	MDV-V18WMN10T	MPCE18A1MN10TA		15,600	\$2,184
216623517	MIDEA	MO1BE-H24B-2A	MAAHE-H24B-BA		19,700	\$2,758
216623516	MIDEA	MO1BE-H24B-2A	MAAHE-H24B-AA		19,700	\$2,758
216623519	MIDEA	MO1HE-H24B-2A	MAAHE-H24B-AA		19,700	\$2,758
216623518	MIDEA	MO1HE-H18B-2A	MAAHE-H24B-AA		15,200	\$2,128
216623521	MIDEA	MO1HE-H24B-2A	MAAHE-H24B-BA		19,700	\$2,758
216623520	MIDEA	MO1HE-H18B-2A	MAAHE-H24B-BA		15,200	\$2,128
216623523	MIDEA	MO1HE-H30B-2A	MAAHE-H36B-BA		25,000	\$3,500
216623522	MIDEA	MO1HE-H30B-2A	MAAHE-H36B-AA		23,400	\$3,276
216623525	MIDEA	MO1HE-H30B-2A	MAAHE-H36B-CA		25,000	\$3,500
216623524	MIDEA	MO1SE-H36B-2A	MAAHE-H36B-BA		29,200	\$4,088
216623527	MIDEA	MO1HE-H60B-2A	MAAHE-H60B-CA		38,000	\$5,320
216623526	MIDEA	MO1SE-H36B-2A	MAAHE-H36B-CA		29,200	\$4,088
216623532	MIDEA	MO1BE-H36B-2A	MAPHE-H36B-2A		24,600	\$3,444
216623533	MIDEA	MO1HE-H18B-2A	MAPHE-H18B-2A		15,000	\$2,100
216623535	MIDEA	MO1HE-H30B-2A	MAPHE-H30B-2A		24,000	\$3,360
216623536	MIDEA	MO1SE-H36B-2A	MAPHE-H36B-2A		31,200	\$4,368
216621475	MIDEA	MO1HE-H36B-2A	MAUHE-H36B-2A		23,200	\$3,248
216684129	MIDEA	MO1HE-H48B-2A	MAAHE-H60B-CA		32,000	\$4,480
216684128	MIDEA	MO1BE-H36B-2A	MAAHE-H36B-CA		24,200	\$3,388
216684127	MIDEA	MO1BE-H36B-2A	MAAHE-H36B-BA		24,200	\$3,388
216607264	MIDEA	MO1SE-H36B-2A	MAWHE-H36B-2A		30,200	\$4,228
216607263	MIDEA	MO1HE-H30B-2A	MAWHE-H30B-2A		23,200	\$3,248
216607261	MIDEA	MO1HE-H18B-2A	MAWHE-H18B-2A		15,300	\$2,142
216607260	MIDEA	MO1BE-H36B-2A	MAWHE-H36B-2A		24,800	\$3,472
215357789	MIDEA	37MGHAQ30EA3	Combination heat pumps with or without ducts		31,400	\$4,396
215357788	MIDEA	37MGHAQ30EA3	Heat pump with ducts		33,000	\$4,620
215357787	MIDEA	37MGHAQ30EA3	Heat pump without ducts		30,000	\$4,200
215357815	MIDEA	37MGRAQ48FA3	Heat pump with ducts		37,000	\$5,180
215357798	MIDEA	37MGHAQ55FA3	Combination heat pumps with or without ducts		44,500	\$6,230
215357797	MIDEA	37MGHAQ55FA3	Heat pump with ducts		45,000	\$6,300
215357796	MIDEA	37MGHAQ55FA3	Heat pump without ducts		44,000	\$6,160

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357795	MIDEA	37MGHAQ48FA3	Combination heat pumps with or without ducts		44,000	\$6,160
215357794	MIDEA	37MGHAQ48FA3	Heat pump with ducts		44,500	\$6,230
215357793	MIDEA	37MGHAQ48FA3	Heat pump without ducts		44,000	\$6,160
214594893	MIDEA	MOD30U-30HFN1-MR0(X)	MVBL-30HWFN1-MJ3		20,000	\$2,800
214594891	MIDEA	MOX430U-18HFN1-M	MVBL-18HWFN1-MH3		13,500	\$1,890
214594892	MIDEA	MOD30-24HFN1-MW	MVBL-24HWFN1-MI3		19,200	\$2,688
214594894	MIDEA	MOE31U-36HFN1-M	MVBL-36HWFN1-MK3		32,800	\$4,592
215323790	MIDEA	37MAHAQ24AA3	D5MAHAQ24XA3		21,000	\$2,940
215324057	MIDEA	37MAHAQ18AA3	45MBDAQ18XA3		15,000	\$2,100
215324055	MIDEA	37MAHAQ18AA3	45MBFAQ16XA3		14,200	\$1,988
215324054	MIDEA	37MAHAQ18AA3	45MBCAQ18XA3		14,900	\$2,086
215324053	MIDEA	37MAHAQ18AA3	45MCCAQ18XA3		14,500	\$2,030
215324051	MIDEA	37MAHAQ12AA3	45MBDAQ12XA3		9,600	\$1,344
215324050	MIDEA	37MAHAQ12AA3	45MBFAQ12XA3		9,800	\$1,372
215324049	MIDEA	37MAHAQ12AA3	45MBCAQ12XA3		10,000	\$1,400
215324048	MIDEA	37MAHAQ12AA3	45MCCAQ12XA3		9,600	\$1,344
215323788	MIDEA	37MAHAQ12AA3	D5MAHAQ12XA3		9,800	\$1,372
215323731	MIDEA	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215323724	MIDEA	37MUHAQ36AA3	45MUHAQ36XX3		31,000	\$4,340
215471343	MIDEA	MO1SE-H36B-2A	MAUSE-H36B-2A		31,000	\$4,340
215324566	MIDEA	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324565	MIDEA	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324562	MIDEA	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324560	MIDEA	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324558	MIDEA	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324557	MIDEA	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324556	MIDEA	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324553	MIDEA	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324552	MIDEA	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324551	MIDEA	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324550	MIDEA	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215324060	MIDEA	37MAHAQ24AA3	45MCFAQ24XA3		20,200	\$2,828
215324059	MIDEA	37MAHAQ24AA3	45MBCAQ24XA3		20,400	\$2,856
215324056	MIDEA	37MAHAQ18AA3	45MCFAQ18XA3		14,400	\$2,016
215324093	MIDEA	37MBHAQ58AA3	45MBDAQ58XH3		45,000	\$6,300
215324091	MIDEA	37MBHAQ48AA3	45MBDAQ48XH3		45,000	\$6,300

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215324088	MIDEA	37MBHAQ36AA3	45MBDAQ36XH3		31,600	\$4,424
215323791	MIDEA	37MAHAQ33AA3	D5MAHAQ33XA3		30,000	\$4,200
215324061	MIDEA	37MAHAQ24AA3	45MBDAQ24XH3		21,600	\$3,024
215471428	MIDEA	MO1HU-H60B-2A	MDHHS-H60B-2A		45,000	\$6,300
215471427	MIDEA	MO1HU-H48B-2A	MDHHS-H48B-2A		45,000	\$6,300
215471426	MIDEA	MO1HU-H36B-2A	MDHHS-H36B-2A		31,600	\$4,424
215471425	MIDEA	MO1HS-H24B-2A	MDHHU-H24B-2A		21,600	\$3,024
215471424	MIDEA	MO1HS-H18B-2A	MDHHU-H18B-2A		15,000	\$2,100
215471414	MIDEA	MO1HS-H18B-2A	MDLHU-H18B-2A		15,000	\$2,100
215471423	MIDEA	MO1HS-H12B-2A	MDHHU-H12B-2A		10,200	\$1,428
215471413	MIDEA	MO1HS-H12B-2A	MDLHU-H12B-2A		9,600	\$1,344
215471452	MIDEA	MO6EX-H48B-2A	Heat pump with ducts		37,000	\$5,180
215471471	MIDEA	MO6HX-H60B-2A	Combination heat pumps with or without ducts		44,500	\$6,230
215471470	MIDEA	MO6HX-H60B-2A	Heat pump with ducts		45,000	\$6,300
215471469	MIDEA	MO6HX-H60B-2A	Heat pump without ducts		44,000	\$6,160
215471468	MIDEA	MO6HX-H48B-2A	Combination heat pumps with or without ducts		44,000	\$6,160
215471467	MIDEA	MO6HX-H48B-2A	Heat pump with ducts		44,500	\$6,230
215471466	MIDEA	MO6HX-H48B-2A	Heat pump without ducts		44,000	\$6,160
215471464	MIDEA	MO5HX-H36B-2A	Heat pump with ducts		33,000	\$4,620
215471462	MIDEA	MO4HX-H27B-2A	Combination heat pumps with or without ducts		24,000	\$3,360
215471461	MIDEA	MO4HX-H27B-2A	Heat pump with ducts		23,000	\$3,220
215471460	MIDEA	MO4HX-H27B-2A	Heat pump without ducts		25,000	\$3,500
215471459	MIDEA	MO3HX-H18B-2A	Combination heat pumps with or without ducts		17,300	\$2,422
215471458	MIDEA	MO3HX-H18B-2A	Heat pump with ducts		17,000	\$2,380
215471457	MIDEA	MO3HX-H18B-2A	Heat pump without ducts		17,600	\$2,464
215471441	MIDEA	MO1HS-H24B-2A	MFBHU-H24B-2A		20,200	\$2,828
215471398	MIDEA	MO1HS-H24B-2A	MCDHU-H24B-2A		20,400	\$2,856
215471440	MIDEA	MO1HS-H18B-2A	MFBHU-H18B-2A		14,400	\$2,016
215471434	MIDEA	MO1HS-H18B-2A	MFAHU-H16B-2A		14,200	\$1,988
215471397	MIDEA	MO1HS-H18B-2A	MCDHU-H18B-2A		14,900	\$2,086
215471407	MIDEA	MO1HS-H18B-2A	MCAHU-H18B-2A		14,500	\$2,030
215471396	MIDEA	MO1HS-H12B-2A	MCDHU-H12B-2A		10,000	\$1,400
215471406	MIDEA	MO1HS-H12B-2A	MCAHU-H12B-2A		9,600	\$1,344
215471444	MIDEA	MO1HU-H60B-2A	MFBHS-H60B-2A		41,000	\$5,740

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215471443	MIDEA	MO1HU-H48B-2A	MFBHS-H48B-2A		38,500	\$5,390
215471400	MIDEA	MO1HU-H48B-2A	MCDHS-H48B-2A		44,000	\$6,160
215471442	MIDEA	MO1HU-H36B-2A	MFBHS-H36B-2A		30,200	\$4,228
215471399	MIDEA	MO1HU-H36B-2A	MCDHS-H36B-2A		30,600	\$4,284
215471384	MIDEA	MO1HS-H33B-2A	MSEHU-H33B-2A		30,000	\$4,200
215471383	MIDEA	MO1HS-H24B-2A	MSEHU-H24B-2A		21,000	\$2,940
215471388	MIDEA	MO1SS-H18B-2A	MSESU-H18B-2A		19,300	\$2,702
215471387	MIDEA	MO1SS-H12B-2A	MSESU-H12B-2A		11,000	\$1,540
215471345	MIDEA	MO1HE-H60B-2A	MAUSE-H60B-2A		35,000	\$4,900
215471344	MIDEA	MO1HE-H48B-2A	MAUSE-H48B-2A		34,000	\$4,760
215471329	MIDEA	MO1BE-H48B-2A	MAUHE-H48B-2A		32,400	\$4,536
215471326	MIDEA	MO1BE-H24B-2A	MAUHE-H24B-2A		20,000	\$2,800
215471338	MIDEA	MO1HE-H60B-2A	MAUHE-H60B-2A		45,000	\$6,300
215471337	MIDEA	MO1SE-H48B-2A	MAUHE-H60B-2A		45,000	\$6,300
215471336	MIDEA	MO1HE-H48B-2A	MAUHE-H48B-2A		37,000	\$5,180
215471335	MIDEA	MO1HE-H42B-2A	MAUHE-H48B-2A		37,000	\$5,180
215471342	MIDEA	MO1HE-H36B-2A	MAUSE-H36B-2A		24,600	\$3,444
215471341	MIDEA	MO1HE-H30B-2A	MAUSE-H30B-2A		24,000	\$3,360
215471333	MIDEA	MO1HE-H30B-2A	MAUHE-H30B-2A		23,800	\$3,332
215471340	MIDEA	MO1HE-H24B-2A	MAUSE-H24B-2A		19,000	\$2,660
215471339	MIDEA	MO1HE-H18B-2A	MAUSE-H18B-2A		14,700	\$2,058
215471356	MIDEA	MO1HU-H60B-2A	MASHS-H60B-2A		41,000	\$5,740
215471355	MIDEA	MO1HU-H48B-2A	MASHS-H48B-2A		40,000	\$5,600
215471354	MIDEA	MO1HU-H36B-2A	MASHS-H36B-2A		28,000	\$3,920
215471353	MIDEA	MO1HS-H33B-2A	MACHU-H36B-2A		27,400	\$3,836
215471352	MIDEA	MO1HS-H24B-2A	MACHU-H24B-2A		16,900	\$2,366
215471351	MIDEA	MO1HS-H18B-2A	MACHU-H18B-2A		14,000	\$1,960
215413298	MIDEA	D5CPRAH18AA	D5FPAH18XAK		19,300	\$2,702
215413297	MIDEA	D5CPRAH12AAK	D5FPAH12XAK		11,000	\$1,540
215413168	MIDEA	37MPRAQ18AA3	D5MPHAQ18XA3		19,300	\$2,702
215413167	MIDEA	37MPRAQ12AA3	D5MPHAQ12XA3		11,000	\$1,540
215357792	MIDEA	37MGHAQ36EA3	Combination heat pumps with or without ducts		31,400	\$4,396
215357791	MIDEA	37MGHAQ36EA3	Heat pump with ducts		33,000	\$4,620
215357790	MIDEA	37MGHAQ36EA3	Heat pump without ducts		30,000	\$4,200
215357786	MIDEA	37MGHAQ27DA3	Combination heat pumps with or without ducts		24,000	\$3,360
215357785	MIDEA	37MGHAQ27DA3	Heat pump with ducts		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357784	MIDEA	37MGHAQ27DA3	Heat pump without ducts		25,000	\$3,500
215357780	MIDEA	37MGHAQ18CA3	Combination heat pumps with or without ducts		17,300	\$2,422
215357779	MIDEA	37MGHAQ18CA3	Heat pump with ducts		17,000	\$2,380
215357778	MIDEA	37MGHAQ18CA3	Heat pump without ducts		17,600	\$2,464
215357411	MIDEA	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357410	MIDEA	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357409	MIDEA	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215324561	MIDEA	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324554	MIDEA	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215357445	MIDEA	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357420	MIDEA	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357419	MIDEA	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357418	MIDEA	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357417	MIDEA	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357416	MIDEA	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357415	MIDEA	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357414	MIDEA	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357413	MIDEA	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357412	MIDEA	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357408	MIDEA	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357407	MIDEA	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357406	MIDEA	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357402	MIDEA	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357401	MIDEA	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357400	MIDEA	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324603	MIDEA	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324601	MIDEA	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324600	MIDEA	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324598	MIDEA	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324597	MIDEA	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324564	MIDEA	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324559	MIDEA	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215324604	MIDEA	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324602	MIDEA	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324599	MIDEA	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324549	MIDEA	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215324058	MIDEA	37MAHAQ18AA3	45MBDAQ18XH3		15,000	\$2,100
215324052	MIDEA	37MAHAQ12AA3	45MBDAQ12XH3		10,200	\$1,428
215324092	MIDEA	37MBHAQ58AA3	45MCFAQ58XA3		41,000	\$5,740
215324090	MIDEA	37MBHAQ48AA3	45MCFAQ48XA3		38,500	\$5,390
215324089	MIDEA	37MBHAQ48AA3	45MBCAQ48XA3		44,000	\$6,160
215324087	MIDEA	37MBHAQ36AA3	45MCFAQ36XA3		30,200	\$4,228
215324086	MIDEA	37MBHAQ36AA3	45MBCAQ36XA3		30,600	\$4,284
215318875	MIDEA	37MUHAQ48AA3	45MUHAQ60XX3		34,000	\$4,760
215319071	MIDEA	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215319070	MIDEA	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215318874	MIDEA	37MUHAQ30AA3	45MUHAQ36XX3		24,000	\$3,360
215318873	MIDEA	37MUHAQ18AA3	45MUHAQ24XX3		14,700	\$2,058
215319069	MIDEA	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215319079	MIDEA	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215318883	MIDEA	37MBHAQ58AA3	45MBAAQ60XA3		41,000	\$5,740
215318881	MIDEA	37MBHAQ36AA3	45MBAAQ36XA3		28,000	\$3,920
215319077	MIDEA	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215318871	MIDEA	37MURAQ48AA3	45MUAAQ48XX3		32,400	\$4,536
215319067	MIDEA	D5CURAH48AAK	D5FUAAH48XAK		32,400	\$4,536
215319064	MIDEA	D5CURAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215318868	MIDEA	37MURAQ24AA3	45MUAAQ24XX3		20,000	\$2,800
215319062	MIDEA	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215318866	MIDEA	37MUHAQ60AA3	45MUHAQ60XX3		35,000	\$4,900
215318865	MIDEA	37MUHAQ60AA3	45MUAAQ60XX3		45,000	\$6,300
215319061	MIDEA	D5CUHAH60AAK	D5FUAAH60XAK		45,000	\$6,300
215319060	MIDEA	D5CUHAH48AAK	D5FUAAH48XAK		37,000	\$5,180
215318864	MIDEA	37MUHAQ48AA3	45MUAAQ48XX3		37,000	\$5,180
215318863	MIDEA	37MUHAQ36AA3	45MUAAQ36XX3		31,800	\$4,452
215319059	MIDEA	D5CUHAH36AAK	D5FUAAH36XAK		31,800	\$4,452
215319058	MIDEA	D5CUHAH30AAK	D5FUAAH30XAK		23,800	\$3,332
215318862	MIDEA	37MUHAQ30AA3	45MUAAQ30XX3		23,800	\$3,332
215318861	MIDEA	37MUHAQ24AA3	45MUHAQ24XX3		19,000	\$2,660
215319057	MIDEA	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215319056	MIDEA	D5CUHAH24AAK	D5FUAAH24XAK		20,000	\$2,800

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215318860	MIDEA	37MUHAQ24AA3	45MUAAQ24XX3		20,000	\$2,800
215318859	MIDEA	37MUHAQ18AA3	45MUAAQ18XX3		15,000	\$2,100
215319055	MIDEA	D5CUHAH18AAK	D5FUAAH18XAK		15,000	\$2,100
215318882	MIDEA	37MBHAQ48AA3	45MBAAQ48XA3		40,000	\$5,600
215319078	MIDEA	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215319074	MIDEA	D5CSHAH33AAK	D5FSAAH36XBK		27,400	\$3,836
215318878	MIDEA	37MAHAQ33AA3	45MBAAQ36XB3		27,400	\$3,836
215318877	MIDEA	37MAHAQ24AA3	45MBAAQ24XB3		16,900	\$2,366
215319073	MIDEA	D5CSHAH24AAK	D5FSAAH24XBK		16,900	\$2,366
215319072	MIDEA	D5CSHAH18AAK	D5FSAAH18XBK		14,000	\$1,960
215318876	MIDEA	37MAHAQ18AA3	45MBAAQ18XB3		14,000	\$1,960
208447919	MIDEA	38MURAQ36AB3	40MUAAQ36XA3		30,400	\$4,256
209852109	MIDEA	DLCURAH36ABK	DLFUAAH36XAK		30,400	\$4,256
210025747	MIDEA	DLCURAH60ABK	DLFUAAH60XAK		42,000	\$5,880
213372243	MIDEA	38MURAQ60AB3	40MULAQ60XDX + CI		37,000	\$5,180
213372239	MIDEA	38MURAQ30AB3	40MULAQ36XCX + CI		22,600	\$3,164
213372171	MIDEA	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372167	MIDEA	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
201846998	MIDEA	38MAQB24R--3	40MBDQ24---3		17,300	\$2,422
201796607	MIDEA	DLCSRAH12AAK	DLFSCAH12XAK		8,200	\$1,148
201796611	MIDEA	DLCSRAH18AAK	DLFSCAH18XAK		12,000	\$1,680
201796609	MIDEA	DLCSRAH12AAK	DLFSDAH12XAK		8,100	\$1,134
201796613	MIDEA	DLCSRAH24AAK	DLFSFAH24XAK		17,200	\$2,408
201846993	MIDEA	38MAQB12R--3	40MBCQ12---3		8,700	\$1,218
201796618	MIDEA	DLCLRAH48AAK	DLFLFAH48XAK		35,000	\$4,900
201756549	MIDEA	DLCSRAH18AAK	DLFSHAH18XAK		11,900	\$1,666
201756550	MIDEA	DLCSRAH24AAK	DLFSHAH24XAK		15,000	\$2,100
201796612	MIDEA	DLCSRAH24AAK	DLFSDAH24XAK		17,400	\$2,436
201753971	MIDEA	38MPRAQ12AA3	DHMPHAQ12XA3		6,800	\$952
202463641	MIDEA	38MPRAQ24AA3	DHMPHAQ24XA3		15,450	\$2,163
202463655	MIDEA	DLCPRAH24AAK	DLFPHAH24XAK		15,450	\$2,163
201846989	MIDEA	38MAQB12R--3	DHMSHAQ12XA3		7,800	\$1,092
201796614	MIDEA	DLCSRAH24AAK	DLFSCAH24XAK		16,200	\$2,268
205921378	MIDEA	DLCSRAH24AAK	DLFSAAH24XAK		17,500	\$2,450
206350375	MIDEA	38MARBQ12AA3	40MBFQ12--3		8,400	\$1,176
206350450	MIDEA	DLCSRBAH12AAK	DLFSCAH12XAK		7,900	\$1,106
206350373	MIDEA	38MARBQ12AA3	40MBCQ12--3		7,900	\$1,106
206350452	MIDEA	DLCSRBAH12AAK	DLFSFAH12XAK		8,400	\$1,176

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206396129	MIDEA	DLCSRAH12AAK	DLFSHBH12XAK		7,500	\$1,050
206396052	MIDEA	38MAQB12R--3	DHMAHBQ12XA3		7,500	\$1,050
206350374	MIDEA	38MARBQ12AA3	40MBDQ12--3		8,300	\$1,162
206350380	MIDEA	38MARBQ24AA3	40MBDQ24--3		14,500	\$2,030
206350451	MIDEA	DLCSRBH12AAK	DLFSDAH12XAK		8,300	\$1,162
206350457	MIDEA	DLCSRBH24AAK	DLFSDAH24XAK		14,500	\$2,030
206350378	MIDEA	38MARBQ18AA3	40MBFQ18--3		12,000	\$1,680
206350381	MIDEA	38MARBQ24AA3	40MBFQ24--3		14,500	\$2,030
206350321	MIDEA	38MARBQ24AA3	DHMAHBQ24XA3		19,800	\$2,772
206350320	MIDEA	38MARBQ18AA3	DHMAHBQ18XA3		10,800	\$1,512
206350319	MIDEA	38MARBQ12AA3	DHMAHBQ12XA3		7,500	\$1,050
206350377	MIDEA	38MARBQ18AA3	40MBDQ18--3		12,700	\$1,778
206350454	MIDEA	DLCSRBH18AAK	DLFSDAH18XAK		12,700	\$1,778
206350455	MIDEA	DLCSRBH18AAK	DLFSFAH18XAK		12,000	\$1,680
206350456	MIDEA	DLCSRBH24AAK	DLFSCAH24XAK		14,500	\$2,030
206350458	MIDEA	DLCSRBH24AAK	DLFSFAH24XAK		14,500	\$2,030
206188330	MIDEA	DLCSRBH24AAK	DLFSAAH24XAK		16,500	\$2,310
201846996	MIDEA	38MAQB12R--3	40MBDQ12---3		8,500	\$1,190
207642974	MIDEA	38MGHBQ48EA3	Combination heat pumps with or without ducts		29,000	\$4,060
207642977	MIDEA	38MGHBQ36DA3	Combination heat pumps with or without ducts		23,000	\$3,220
207642968	MIDEA	38MGHBQ30DA3	Combination heat pumps with or without ducts		18,200	\$2,548
207642973	MIDEA	38MGHBQ48EA3	Heat pump with ducts		28,000	\$3,920
207642976	MIDEA	38MGHBQ36DA3	Heat pump with ducts		23,000	\$3,220
207642967	MIDEA	38MGHBQ30DA3	Heat pump with ducts		19,000	\$2,660
207643130	MIDEA	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643127	MIDEA	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340
207643121	MIDEA	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207643129	MIDEA	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220
207643126	MIDEA	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207643120	MIDEA	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643128	MIDEA	DLCMHBH36DAK	Heat pump without ducts		22,000	\$3,080
207643125	MIDEA	DLCMHBH48EAK	Heat pump without ducts		34,000	\$4,760
207643119	MIDEA	DLCMHBH30DAK	Heat pump without ducts		18,500	\$2,590

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207642975	MIDEA	38MGHBQ36DA3	Heat pump without ducts		23,200	\$3,248
207642972	MIDEA	38MGHBQ48EA3	Heat pump without ducts		30,000	\$4,200
207642966	MIDEA	38MGHBQ30DA3	Heat pump without ducts		17,500	\$2,450
204722815	MIDEA	38MGRQ30D--3	Heat pump without ducts		17,400	\$2,436
201847004	MIDEA	38MGRQ36D--3	Heat pump without ducts		23,200	\$3,248
208447921	MIDEA	38MURAQ18AB3	40MUAAQ18XA3		13,500	\$1,890
208447923	MIDEA	38MURAQ24AB3	40MUAAQ24XA3		19,200	\$2,688
208447918	MIDEA	38MURAQ48AB3	40MUAAQ48XA3		36,000	\$5,040
209852102	MIDEA	DLCURAH18ABK	DLFUAH18XAK		13,500	\$1,890
209852103	MIDEA	DLCURAH24ABK	DLFUAH24XAK		19,200	\$2,688
209852105	MIDEA	DLCURAH48ABK	DLFUAH48XAK		36,000	\$5,040
207801582	MIDEA	38MARBQ18AA3	40MBDQ24---3		12,600	\$1,764
207826679	MIDEA	38MARBQ18AA3	40MBABQ18XB3		12,000	\$1,680
207801574	MIDEA	DLCSR BH18AAK	DLFSDAH24XAK		12,600	\$1,764
207826607	MIDEA	DLCSR BH18AAK	DLFSABH18XBK		12,000	\$1,680
216505928	mitsubishi electric	MXZ-2D20NLHZ***	Heat pump with ducts		12,500	\$1,750
216505931	mitsubishi electric	MXZ-2D20NLHZ***	Combination heat pumps with or without ducts		13,400	\$1,876
216505933	mitsubishi electric	MXZ-3D24NLHZ***	Heat pump without ducts		15,400	\$2,156
216505925	mitsubishi electric	MXZ-2D20NLHZ***	Heat pump without ducts		14,300	\$2,002
216505934	mitsubishi electric	MXZ-3D30NLHZ***	Heat pump without ducts		18,300	\$2,562
216505942	mitsubishi electric	MXZ-3D30NLHZ***	Combination heat pumps with or without ducts		17,600	\$2,464
216505941	mitsubishi electric	MXZ-3D24NLHZ***	Combination heat pumps with or without ducts		15,400	\$2,156
216505938	mitsubishi electric	MXZ-3D30NLHZ***	Heat pump with ducts		17,000	\$2,380
216798016	mitsubishi electric	MUZ-FX12NLHZ2***	MSZ-FX12NL***		9,300	\$1,302
215912359	mitsubishi electric	MUZ-FX24NLHZ***	MSZ-FX24NL***		13,600	\$1,904
215611128	mitsubishi electric	MUZ-FX18NLHZ***	MSZ-FX18NL***		12,700	\$1,778
215611127	mitsubishi electric	MUZ-FX15NLHZ***	MSZ-FX15NL***		10,600	\$1,484
215712224	mitsubishi electric	PUZ-AK48NLHZ***	PLA-AE48NL***		36,600	\$5,124
215712215	mitsubishi electric	PUZ-AK36NLHZ***	PEAD-AA36NL***		24,400	\$3,416
215712208	mitsubishi electric	PUZ-AK30NLHZ***	PEAD-AA30NL***		21,800	\$3,052
215712199	mitsubishi electric	PUZ-AK24NLHZ***	PEAD-AA24NL***		17,000	\$2,380
215712241	mitsubishi electric	SUZ-AK36NLHZ***	PEAD-AA36NL***		24,400	\$3,416
215712239	mitsubishi electric	SUZ-AK30NLHZ***	PEAD-AA30NL***		21,800	\$3,052
215712237	mitsubishi electric	SUZ-AK24NLHZ***	PEAD-AA24NL***		17,000	\$2,380
215734922	mitsubishi electric	SUZ-AA18NLHZ***	PEAD-AA18NL***		13,100	\$1,834

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215734918	mitsubishi electric	SUZ-AA15NLHZ***	PEAD-AA15NL***		11,600	\$1,624
215734914	mitsubishi electric	SUZ-AA12NLHZ***	PEAD-AA12NL***		9,300	\$1,302
207679255	Mitsubishi Electric	MUZ-GS18NAHZ***	MSZ-GS18NA***		11,700	\$1,638
211016463	Mitsubishi Electric	MXZ-SM60NAM2	Combination heat pumps with or without ducts		41,000	\$5,740
211016454	Mitsubishi Electric	MXZ-SM42NAMHZ2	Combination heat pumps with or without ducts		32,000	\$4,480
211016451	Mitsubishi Electric	MXZ-SM36NAMHZ2	Combination heat pumps with or without ducts		29,600	\$4,144
211259273	mitsubishi electric	PUZ-HA30NKA	PCA-A30KA*		22,200	\$3,108
209832205	mitsubishi electric	MUZ-FS15NA***	MSZ-FS15NA***		10,000	\$1,400
209832206	mitsubishi electric	MUZ-FS15NAH***	MSZ-FS15NA***		10,000	\$1,400
209832207	mitsubishi electric	MUZ-FS18NA***	MSZ-FS18NA***		12,800	\$1,792
209832208	mitsubishi electric	MUZ-FS18NAH***	MSZ-FS18NA***		12,800	\$1,792
209836186	mitsubishi electric	MXZ-2C20NAHZ3***	Heat pump without ducts		13,000	\$1,820
209836203	mitsubishi electric	MXZ-3C24NAHZ3***	Heat pump without ducts		14,000	\$1,960
209836204	mitsubishi electric	MXZ-3C30NAHZ3***	Heat pump without ducts		18,000	\$2,520
211016453	Mitsubishi Electric	MXZ-SM42NAMHZ2	Heat pump with ducts		32,000	\$4,480
211016456	Mitsubishi Electric	MXZ-SM48NAM2	Heat pump with ducts		35,000	\$4,900
211016459	Mitsubishi Electric	MXZ-SM48NAMHZ2	Heat pump with ducts		41,000	\$5,740
211016460	Mitsubishi Electric	MXZ-SM48NAMHZ2	Combination heat pumps with or without ducts		40,000	\$5,600
211016462	Mitsubishi Electric	MXZ-SM60NAM2	Heat pump with ducts		40,500	\$5,670
211259270	mitsubishi electric	PUZ-HA24NHA1	PCA-A24KA*		17,700	\$2,478
211259269	mitsubishi electric	PUZ-HA24NHA1	PKA-A24KA*		17,200	\$2,408
211273264	mitsubishi electric	PUZ-HA24NHA1	PLA-A24EA*		17,300	\$2,422
207702686	mitsubishi electric	PUZ-HA24NHA1	PEAD-A24AA*		18,000	\$2,520
211259274	mitsubishi electric	PUZ-HA30NKA	PVA-A30AA*		21,000	\$2,940
207702688	mitsubishi electric	PUZ-HA30NKA	PEAD-A30AA*		21,000	\$2,940
210435438	mitsubishi electric	PUZ-HA30NKA*	PAA-A30BA1		23,200	\$3,248
210435437	mitsubishi electric	PUZ-HA30NKA*	PAA-A30AA1		23,200	\$3,248
211259279	mitsubishi electric	PUZ-HA36NKA	PVA-A36AA*		24,600	\$3,444
211259278	mitsubishi electric	PUZ-HA36NKA	PCA-A36KA*		25,400	\$3,556
211259276	mitsubishi electric	PUZ-HA36NKA	PKA-A36KA*		25,400	\$3,556
211259275	mitsubishi electric	PUZ-HA36NKA	PLA-A36EA*		24,200	\$3,388
207702691	mitsubishi electric	PUZ-HA36NKA	PEAD-A36AA*		24,800	\$3,472
207702706	mitsubishi electric	SUZ-KA12NAHZ	PEAD-A12AA*		8,800	\$1,232
211289249	mitsubishi electric	SUZ-KA12NAHZ	SLZ-KF12NA*		8,300	\$1,162

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206328096	mitsubishi electric	SUZ-KA12NAHZ	NTXCK12A112AA		8,300	\$1,162
207702716	mitsubishi electric	SUZ-KA24NAHZ	PEAD-A24AA*		18,000	\$2,520
207702722	mitsubishi electric	SUZ-KA30NAHZ	PEAD-A30AA*		21,000	\$2,940
211497055	mitsubishi electric	TRUZH0361KA00NA	TPKA0A0361KA***		25,400	\$3,556
211259272	mitsubishi electric	PUZ-HA24NHA1	PVA-A24AA*		17,500	\$2,450
215712240	mitsubishi electric	SUZ-AK30NLHZ***	SVZ-AP30NL***		23,600	\$3,304
215712221	mitsubishi electric	PUZ-AK42NLHZ***	PVA-AA42NL***		32,200	\$4,508
215712216	mitsubishi electric	PUZ-AK36NLHZ***	PVA-AA36NL***		24,400	\$3,416
215712209	mitsubishi electric	PUZ-AK30NLHZ***	PVA-AA30NL***		21,600	\$3,024
215712200	mitsubishi electric	PUZ-AK24NLHZ***	PVA-AA24NL***		17,000	\$2,380
215748479	Mitsubishi Electric	SUZ-AA18NLHZ***	MSZ-EX18NLS***		13,100	\$1,834
215748477	Mitsubishi Electric	SUZ-AA18NLHZ***	MSZ-EX18NLB***		13,100	\$1,834
215748510	Mitsubishi Electric	SUZ-AA15NLHZ***	MSZ-EX15NLS***		10,900	\$1,526
215748508	Mitsubishi Electric	SUZ-AA15NLHZ***	MSZ-EX15NLB***		10,900	\$1,526
215748497	Mitsubishi Electric	SUZ-AA12NLHZ***	MSZ-EX12NLS***		9,400	\$1,316
215748495	Mitsubishi Electric	SUZ-AA12NLHZ***	MSZ-EX12NLB***		9,400	\$1,316
215748482	Mitsubishi Electric	SUZ-AA18NLHZ***	MSZ-EX18NLW***		13,100	\$1,834
215748513	Mitsubishi Electric	SUZ-AA15NLHZ***	MSZ-EX15NLW***		10,900	\$1,526
215748500	Mitsubishi Electric	SUZ-AA12NLHZ***	MSZ-EX12NLW***		9,400	\$1,316
215734920	Mitsubishi Electric	SUZ-AA18NLHZ***	MLZ-KX18NL***		12,000	\$1,680
215734912	Mitsubishi Electric	SUZ-AA12NLHZ***	MLZ-KX12NL***		9,500	\$1,330
215734921	Mitsubishi Electric	SUZ-AA18NLHZ***	MFZ-KX18NL***		13,400	\$1,876
215734917	Mitsubishi Electric	SUZ-AA15NLHZ***	MFZ-KX15NL***		10,900	\$1,526
215734913	Mitsubishi Electric	SUZ-AA12NLHZ***	MFZ-KX12NL***		9,300	\$1,302
215862743	Mitsubishi Electric	MUZ-HX24NL***	MSZ-HX24NL***		17,200	\$2,408
215712242	mitsubishi electric	SUZ-AK36NLHZ***	SVZ-AP36NL***		25,800	\$3,612
215712238	mitsubishi electric	SUZ-AK24NLHZ***	SVZ-AP24NL***		19,000	\$2,660
215734923	mitsubishi electric	SUZ-AA18NLHZ***	SVZ-AP18NL***		12,800	\$1,792
215734915	mitsubishi electric	SUZ-AA12NLHZ***	SVZ-AP12NL***		9,300	\$1,302
215712170	mitsubishi electric	MXZ-SM60NL***	Combination heat pumps with or without ducts		41,000	\$5,740
215712169	mitsubishi electric	MXZ-SM60NL***	Heat pump with ducts		40,500	\$5,670
215685468	mitsubishi electric	MXZ-SM60NL***	Heat pump without ducts		41,500	\$5,810
215712168	mitsubishi electric	MXZ-SM48NLHZ***	Combination heat pumps with or without ducts		38,000	\$5,320
215712167	mitsubishi electric	MXZ-SM48NLHZ***	Heat pump with ducts		38,000	\$5,320
215685467	mitsubishi electric	MXZ-SM48NLHZ***	Heat pump without ducts		38,000	\$5,320

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215712166	mitsubishi electric	MXZ-SM48NL***	Combination heat pumps with or without ducts		32,400	\$4,536
215712165	mitsubishi electric	MXZ-SM48NL***	Heat pump with ducts		33,400	\$4,676
215685466	mitsubishi electric	MXZ-SM48NL***	Heat pump without ducts		31,400	\$4,396
215712164	mitsubishi electric	MXZ-SM42NLHZ***	Combination heat pumps with or without ducts		33,000	\$4,620
215712163	mitsubishi electric	MXZ-SM42NLHZ***	Heat pump with ducts		32,000	\$4,480
215685465	mitsubishi electric	MXZ-SM42NLHZ***	Heat pump without ducts		34,000	\$4,760
215712162	mitsubishi electric	MXZ-SM36NLHZ***	Combination heat pumps with or without ducts		29,600	\$4,144
215712161	mitsubishi electric	MXZ-SM36NLHZ***	Heat pump with ducts		26,600	\$3,724
215685464	mitsubishi electric	MXZ-SM36NLHZ***	Heat pump without ducts		32,600	\$4,564
215712160	mitsubishi electric	MXZ-SM36NL***	Combination heat pumps with or without ducts		26,400	\$3,696
215712159	mitsubishi electric	MXZ-SM36NL***	Heat pump with ducts		26,600	\$3,724
215685463	mitsubishi electric	MXZ-SM36NL***	Heat pump without ducts		26,400	\$3,696
215734911	mitsubishi electric	SUZ-AA12NLHZ***	SLZ-AF12NL***		9,600	\$1,344
216801485	mitsubishi electric	MUZ-GX24NLHZ2***	MSZ-GX24NL***		19,200	\$2,688
216801484	mitsubishi electric	MUZ-GX18NLHZ2***	MSZ-GX18NL***		13,700	\$1,918
216801483	mitsubishi electric	MUZ-GX15NLHZ2***	MSZ-GX15NL***		11,400	\$1,596
216801482	mitsubishi electric	MUZ-GX12NLHZ2***	MSZ-GX12NL***		9,000	\$1,260
216801492	mitsubishi electric	MUZ-GX24NLHZ2***	MSZ-GX24NL***		14,000	\$1,960
216801491	mitsubishi electric	MUZ-GX18NLHZ2***	MSZ-GX18NL***		12,000	\$1,680
216801490	mitsubishi electric	MUZ-GX15NLHZ2***	MSZ-GX15NL***		8,700	\$1,218
216801489	mitsubishi electric	MUZ-GX12NLHZ2***	MSZ-GX12NL***		7,600	\$1,064
216798019	mitsubishi electric	MUZ-FX24NLHZ2***	MSZ-FX24NL***		13,600	\$1,904
216798018	mitsubishi electric	MUZ-FX18NLHZ2***	MSZ-FX18NL***		12,700	\$1,778
216798017	mitsubishi electric	MUZ-FX15NLHZ2***	MSZ-FX15NL***		10,600	\$1,484
215712213	Mitsubishi Electric	PUZ-AK36NLHZ***	PKA-AK36NL***		24,200	\$3,388
215712206	Mitsubishi Electric	PUZ-AK30NLHZ***	PKA-AK30NL***		22,000	\$3,080
215712197	Mitsubishi Electric	PUZ-AK24NLHZ***	PKA-AK24NL***		17,000	\$2,380
215712219	Mitsubishi Electric	PUZ-AK42NLHZ***	PLA-AE42NL***		32,400	\$4,536
215712212	Mitsubishi Electric	PUZ-AK36NLHZ***	PLA-AE36NL***		24,000	\$3,360
215712205	Mitsubishi Electric	PUZ-AK30NLHZ***	PLA-AE30NL***		21,600	\$3,024
215712196	Mitsubishi Electric	PUZ-AK24NLHZ***	PLA-AE24NL***		16,400	\$2,296
215712214	Mitsubishi Electric	PUZ-AK36NLHZ***	PCA-AK36NL***		24,200	\$3,388
215712207	Mitsubishi Electric	PUZ-AK30NLHZ***	PCA-AK30NL***		22,400	\$3,136
215712198	Mitsubishi Electric	PUZ-AK24NLHZ***	PCA-AK24NL***		17,000	\$2,380

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213248845	mitsubishi electric	MXZ-SM60NAM2***	Heat pump without ducts		41,500	\$5,810
213248844	mitsubishi electric	MXZ-SM60NAM***	Heat pump without ducts		41,500	\$5,810
213248842	mitsubishi electric	MXZ-SM48NAMHZ2***	Heat pump without ducts		39,000	\$5,460
213248840	mitsubishi electric	MXZ-SM48NAMHZ***	Heat pump without ducts		39,000	\$5,460
213248838	mitsubishi electric	MXZ-SM48NAM2***	Heat pump without ducts		31,400	\$4,396
213248834	mitsubishi electric	MXZ-SM42NAMHZ2***	Heat pump without ducts		32,000	\$4,480
213248833	mitsubishi electric	MXZ-SM42NAMHZ***	Heat pump without ducts		32,000	\$4,480
213248831	mitsubishi electric	MXZ-SM36NAMHZ2***	Heat pump without ducts		32,600	\$4,564
213248830	mitsubishi electric	MXZ-SM36NAMHZ***	Heat pump without ducts		32,600	\$4,564
213248828	mitsubishi electric	MXZ-SM36NAM2***	Heat pump without ducts		26,400	\$3,696
207702726	mitsubishi electric	SUZ-KA36NAHZ	PEAD-A36AA*		24,800	\$3,472
213617714	mitsubishi electric	SUZ-KA30NAHZ1***	SVZ-KP30NA*		21,400	\$2,996
206331446	mitsubishi electric	SUZ-KA30NAHZ	NAXAMT30A112AA		21,400	\$2,996
206331452	mitsubishi electric	SUZ-KA30NAHZ	NTXAMT30A112AA		21,400	\$2,996
211273652	mitsubishi electric	SUZ-KA30NAHZ	SVZ-KP30NA*		21,400	\$2,996
213617713	mitsubishi electric	PUZ-HA42NKA2***	PVA-A42AA*		38,500	\$5,390
211259282	mitsubishi electric	PUZ-HA42NKA1	PVA-A42AA*		38,500	\$5,390
207702694	mitsubishi electric	PUZ-HA42NKA1	PEAD-A42AA*		39,500	\$5,530
213617710	mitsubishi electric	PUZ-HA36NKA1***	PVA-A36AA*		24,600	\$3,444
209484153	mitsubishi electric	PUZ-HA36NKA*	PAA-A36BA1		28,400	\$3,976
210435439	mitsubishi electric	PUZ-HA36NKA*	PAA-A36CA1		28,400	\$3,976
209447988	mitsubishi electric	PUZ-HA24NHA*	PAA-A24AA1		16,000	\$2,240
209447989	mitsubishi electric	PUZ-HA24NHA*	PAA-A24BA1		16,000	\$2,240
212925868	mitsubishi electric	MXZ-3C30NAHZ4-**	Heat pump without ducts		18,000	\$2,520
212925882	mitsubishi electric	MXZ-3C30NAHZ4-**	Combination heat pumps with or without ducts		18,500	\$2,590
212925537	mitsubishi electric	MXZ-3C24NAHZ4-**	Heat pump without ducts		14,000	\$1,960
212925538	mitsubishi electric	MXZ-3C24NAHZ4-**	Combination heat pumps with or without ducts		14,700	\$2,058
212925867	mitsubishi electric	MXZ-2C20NAHZ4-**	Heat pump without ducts		13,700	\$1,918
212925881	mitsubishi electric	MXZ-2C20NAHZ4-**	Combination heat pumps with or without ducts		13,700	\$1,918
201754637	mitsubishi electric	MXZ-8C60NA-U*	Heat pump without ducts		41,500	\$5,810
207525858	mitsubishi electric	MXZ-SM48NAMHZ	Combination heat pumps with or without ducts		40,500	\$5,670
207517160	mitsubishi electric	MXZ-SM60NAM	Heat pump without ducts		41,500	\$5,810
204629179	mitsubishi electric	MUFZ-KJ15NAHZ***	NTXFKS15A112A*		12,000	\$1,680
210819447	mitsubishi electric	MUFZ-KJ15NAHZ***	MFZ-KJ15NA***		12,000	\$1,680

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207525856	MITSUBISHI ELECTRIC	MXZ-SM42NAMHZ	Combination heat pumps with or without ducts		32,000	\$4,480
207517158	MITSUBISHI ELECTRIC	MXZ-SM48NAMHZ	Heat pump without ducts		39,000	\$5,460
207517152	MITSUBISHI ELECTRIC	MXZ-SM36NAMHZ	Heat pump without ducts		32,600	\$4,564
207525859	MITSUBISHI ELECTRIC	MXZ-SM60NAM	Combination heat pumps with or without ducts		41,000	\$5,740
207525855	MITSUBISHI ELECTRIC	MXZ-SM36NAMHZ	Combination heat pumps with or without ducts		29,600	\$4,144
206709491	MITSUBISHI ELECTRIC	NTXSPF18A112A*	MFZ-KJ18NA***		12,800	\$1,792
204629180	MITSUBISHI ELECTRIC	MUFZ-KJ18NAHZ***	NTXFKS18A112A*		12,800	\$1,792
207517154	MITSUBISHI ELECTRIC	MXZ-SM42NAMHZ	Heat pump without ducts		32,000	\$4,480
207517153	MITSUBISHI ELECTRIC	MXZ-SM36NAMHZ	Heat pump with ducts		26,600	\$3,724
206709490	MITSUBISHI ELECTRIC	NTXSPF15A112A*	MFZ-KJ15NA***		12,000	\$1,680
204629575	MITSUBISHI ELECTRIC	MUFZ-KJ18NAHZ***	NAXFKS18A112A*		12,800	\$1,792
204629574	MITSUBISHI ELECTRIC	MUFZ-KJ15NAHZ***	NAXFKS15A112A*		12,000	\$1,680
211016663	Mitsubishi Electric	PUMY-P60NKMU4	Combination heat pumps with or without ducts		41,000	\$5,740
211016660	Mitsubishi Electric	PUMY-HP42NKMU2	Combination heat pumps with or without ducts		32,000	\$4,480
211016659	Mitsubishi Electric	PUMY-HP36NKMU2	Combination heat pumps with or without ducts		29,600	\$4,144
201754495	MITSUBISHI ELECTRIC	PUZ-HA42NKA	PVA-A42AA*		42,000	\$5,880
201754301	MITSUBISHI ELECTRIC	MUZ-FH15NAH	MSZ-FH15NA**		11,000	\$1,540
213617706	MITSUBISHI ELECTRIC	PUZ-HA30NKA1***	PVA-A30AA*		21,000	\$2,940
204926518	MITSUBISHI ELECTRIC	MXZ-8C60NA2	Combination heat pumps with or without ducts		41,000	\$5,740
202411913	MITSUBISHI ELECTRIC	PUMY-P60NKMU2	Heat pump with ducts		40,500	\$5,670
201755016	MITSUBISHI ELECTRIC	MXZ-3C24NAHZ2	Combination heat pumps with or without ducts		14,000	\$1,960
209949005	MITSUBISHI ELECTRIC	MXZ-3C24NAHZ3***	Combination heat pumps with or without ducts		14,000	\$1,960
209949006	MITSUBISHI ELECTRIC	MXZ-3C30NAHZ3***	Combination heat pumps with or without ducts		17,200	\$2,408
211016651	Mitsubishi Electric	PUMY-HP42NKMU2	Heat pump with ducts		32,000	\$4,480
202426339	MITSUBISHI ELECTRIC	PUMY-P60NKMU2	Combination heat pumps with or without ducts		45,144	\$6,320
201754441	MITSUBISHI ELECTRIC	MXZ-5C42NAHZ	Heat pump with ducts		36,600	\$5,124
201754322	MITSUBISHI ELECTRIC	PUZ-HA36NHA5	PEAD-A36AA*		27,000	\$3,780
201754323	MITSUBISHI ELECTRIC	PUZ-HA36NHA5	PVA-A36AA*		25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
201754321	mitsubishi electric	PUZ-HA36NHA5	PLA-A36EA*		28,000	\$3,920
202426335	mitsubishi electric	PUMY-HP36NKMU	Combination heat pumps with or without ducts		45,898	\$6,426
204627021	mitsubishi electric	SUZ-KA15NAHZ	SEZ-KD15NA4		12,200	\$1,708
204627020	mitsubishi electric	SUZ-KA12NAHZ	SEZ-KD12NA4		9,000	\$1,260
204276761	mitsubishi electric	PUZ-HA24NHA	PKA-A24KA7		17,200	\$2,408
204276767	mitsubishi electric	PUZ-HA24NHA	PEAD-A24AA7		18,000	\$2,520
202426336	mitsubishi electric	PUMY-HP48NKMU	Combination heat pumps with or without ducts		40,500	\$5,670
202423533	mitsubishi electric	PUMY-HP36NKMU	Heat pump with ducts		32,000	\$4,480
202423535	mitsubishi electric	PUMY-HP48NKMU	Heat pump with ducts		42,000	\$5,880
204926517	mitsubishi electric	MXZ-8C48NAHZ2	Combination heat pumps with or without ducts		38,000	\$5,320
204926514	mitsubishi electric	MXZ-5C42NAHZ2	Combination heat pumps with or without ducts		34,000	\$4,760
204926512	mitsubishi electric	MXZ-4C36NAHZ2	Combination heat pumps with or without ducts		32,000	\$4,480
204834268	mitsubishi electric	MXZ-8C48NAHZ2	Heat pump with ducts		38,000	\$5,320
204834266	mitsubishi electric	MXZ-5C42NAHZ2	Heat pump with ducts		36,000	\$5,040
204834293	mitsubishi electric	MXZ-4C36NAHZ2	Heat pump with ducts		34,000	\$4,760
204834294	mitsubishi electric	MXZ-5C42NAHZ2	Heat pump without ducts		32,000	\$4,480
204834292	mitsubishi electric	MXZ-4C36NAHZ2	Heat pump without ducts		30,000	\$4,200
204834267	mitsubishi electric	MXZ-8C48NAHZ2	Heat pump without ducts		38,000	\$5,320
204276538	mitsubishi electric	PUZ-HA24NHA	PLA-A24EA7		17,300	\$2,422
204281760	mitsubishi electric	PUZ-HA24NHA	PVA-A24AA7		17,500	\$2,450
204276762	mitsubishi electric	PUZ-HA24NHA	PCA-A24KA7		17,700	\$2,478
206374539	mitsubishi electric	SUZ-KA15NAHZ	TPEADA0151AA70A		11,700	\$1,638
206374537	mitsubishi electric	SUZ-KA12NAHZ	TPEADA0121AA70A		9,000	\$1,260
206223048	mitsubishi electric	PUZ-HA30NKA	PVA-A30AA7		21,000	\$2,940
204834269	mitsubishi electric	MXZ-8C60NA2	Heat pump with ducts		40,500	\$5,670
204834295	mitsubishi electric	MXZ-8C60NA2	Heat pump without ducts		41,500	\$5,810
201755028	mitsubishi electric	PUMY-P60NKMU*	Combination heat pumps with or without ducts		41,500	\$5,810
201754444	mitsubishi electric	PUMY-P36NKMU*	Heat pump with ducts		26,600	\$3,724
201754640	mitsubishi electric	PUMY-P60NKMU1	Heat pump without ducts		41,500	\$5,810
201754490	mitsubishi electric	PUZ-HA36NHA5	PLA-A36BA*		28,000	\$3,920
206908464	mitsubishi electric	MXZ-2C20NAHZ2***	Heat pump without ducts		13,000	\$1,820
206908469	mitsubishi electric	MXZ-2C20NAHZ2***	Combination heat pumps with or without ducts		13,300	\$1,862

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
201755024	mitsubishi electric	MXZ-8C48NAHZ	Combination heat pumps with or without ducts		41,500	\$5,810
201755022	mitsubishi electric	MXZ-5C42NAHZ	Combination heat pumps with or without ducts		36,200	\$5,068
201754912	mitsubishi electric	MXZ-4C36NAHZ	Heat pump with ducts		36,000	\$5,040
201754635	mitsubishi electric	MXZ-8C48NAHZ	Heat pump without ducts		40,000	\$5,600
201755020	mitsubishi electric	MXZ-4C36NAHZ	Combination heat pumps with or without ducts		35,000	\$4,900
201754911	mitsubishi electric	MXZ-4C36NAHZ	Heat pump without ducts		34,000	\$4,760
201754926	mitsubishi electric	MXZ-5C42NAHZ	Heat pump without ducts		35,800	\$5,012
201754904	mitsubishi electric	MXZ-3C24NAHZ2	Heat pump without ducts		14,000	\$1,960
202732309	mitsubishi electric	MXZ-2C20NAHZ2	MSZ-FH09NAMSZ-FH09NA		13,000	\$1,820
202412089	mitsubishi electric	PUMY-P60NKMU2	Heat pump without ducts		41,500	\$5,810
202412088	mitsubishi electric	PUMY-HP48NKMU	Heat pump without ducts		39,000	\$5,460
202412085	mitsubishi electric	PUMY-HP36NKMU	Heat pump without ducts		33,000	\$4,620
204834273	mitsubishi electric	PUMY-HP36NKMU1			32,000	\$4,480
204926535	mitsubishi electric	PUMY-HP36NKMU1	Combination heat pumps with or without ducts		32,400	\$4,536
204834272	mitsubishi electric	PUMY-HP36NKMU1	Heat pump without ducts		33,000	\$4,620
204834216	mitsubishi electric	PUMY-HP48NKMU1	Heat pump with ducts		42,000	\$5,880
204926537	mitsubishi electric	PUMY-HP48NKMU1	Combination heat pumps with or without ducts		40,500	\$5,670
204834275	mitsubishi electric	PUMY-HP48NKMU1	Heat pump without ducts		39,000	\$5,460
207702709	mitsubishi electric	SUZ-KA15NAHZ	PEAD-A15AA*		11,700	\$1,638
210819448	mitsubishi electric	MUFZ-KJ18NAHZ***	MFZ-KJ18NA***		12,800	\$1,792
206223050	mitsubishi electric	PUZ-HA30NKA	PEAD-A30AA7		21,000	\$2,940
206374536	mitsubishi electric	SUZ-KA12NAHZ	APEADA0121AA70A		9,000	\$1,260
206374538	mitsubishi electric	SUZ-KA15NAHZ	APEADA0151AA70A		11,700	\$1,638
211016646	Mitsubishi Electric	PUMY-P36NKMU4	Heat pump without ducts		26,400	\$3,696
211016648	Mitsubishi Electric	PUMY-HP36NKMU2	Heat pump without ducts		32,600	\$4,564
211016650	Mitsubishi Electric	PUMY-HP42NKMU2	Heat pump without ducts		32,000	\$4,480
211016652	Mitsubishi Electric	PUMY-P48NKMU4	Heat pump without ducts		31,400	\$4,396
211016654	Mitsubishi Electric	PUMY-HP48NKMU2	Heat pump without ducts		39,000	\$5,460
211016656	Mitsubishi Electric	PUMY-P60NKMU4	Heat pump without ducts		41,500	\$5,810
211016647	Mitsubishi Electric	PUMY-P36NKMU4	Heat pump with ducts		26,600	\$3,724
211016649	Mitsubishi Electric	PUMY-HP36NKMU2	Heat pump with ducts		26,600	\$3,724
211016653	Mitsubishi Electric	PUMY-P48NKMU4	Heat pump with ducts		35,000	\$4,900
211016655	Mitsubishi Electric	PUMY-HP48NKMU2	Heat pump with ducts		41,000	\$5,740

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211016657	Mitsubishi Electric	PUMY-P60NKMU4	Heat pump with ducts		40,500	\$5,670
211016662	Mitsubishi Electric	PUMY-HP48NKMU2	Combination heat pumps with or without ducts		40,000	\$5,600
204629176	MITSUBISHI ELECTRIC	MUZ-FH15NAH	NTXWPH15A112A*		11,000	\$1,540
217120756	MOOVAIR	DMB12HOS42230E8	DMA12HIW42230E4		10,400	\$1,456
216623471	MOOVAIR	MSHMA60R2AN1	MCHMA60RDAS1		35,600	\$4,984
216623458	MOOVAIR	MSHMA60R2AN1	GCHMA60RDAS1		36,000	\$5,040
216031076	MOOVAIR	MXHZA3652AV1	Combination heat pumps with or without ducts		31,400	\$4,396
216031074	MOOVAIR	MXHZA3652AV1	Heat pump without ducts		30,000	\$4,200
207742496	MOOVAIR	DMA12HOS28230E8	DMA12HIW25230E8		10,000	\$1,400
207742497	MOOVAIR	DMA18HOS28230E8	DMA18HIW25230E8		15,000	\$2,100
207742498	MOOVAIR	DMA24HOS28230E8	DMA24HIW25230E8		21,200	\$2,968
207742509	MOOVAIR	DMA12HOS28230E8	DUA12HICU230X5		9,900	\$1,386
207742527	MOOVAIR	DMA12HOS28230E8	DUA12HIFU230E5		9,600	\$1,344
207742523	MOOVAIR	DMA18HOS28230E8	DUA18HIDU230X5		15,000	\$2,100
206401440	MOOVAIR	DM18HOS25230E3A	DM18HIDU230X5		15,000	\$2,100
213088010	MOOVAIR	DMB12HOS42230E8	DMB12HIW42230E8		11,400	\$1,596
207742501	MOOVAIR	DMA18HOS42230E4	DMA18HIW42230E4		20,200	\$2,828
207742500	MOOVAIR	DMA12HOS42230E4	DMA12HIW42230E4		10,400	\$1,456
212596840	MOOVAIR	DMA12HOS28230E8	DUB12HIFU230X5A		10,200	\$1,428
208136320	MOOVAIR	DMA55HOM25230X3	Heat pump with ducts		35,200	\$4,928
207742545	MOOVAIR	DMA27HOM25230X3	Heat pump with ducts		27,000	\$3,780
207742511	MOOVAIR	DMA24HOS28230E8	DUA24HICU230X5		21,000	\$2,940
207706559	MOOVAIR	DMA24HOS20230E7	FMA24HIAHUU230X7		19,200	\$2,688
207764688	MOOVAIR	DMA18HOS20230E7	FMA18HIAHUU230X7		13,500	\$1,890
207742546	MOOVAIR	DMA27HOM25230X3	Combination heat pumps with or without ducts		26,800	\$3,752
208136321	MOOVAIR	DMA55HOM25230X3	Combination heat pumps with or without ducts		34,800	\$4,872
213369384	MOOVAIR	DMB18HOS42230E8B	DMB18HIW42230E8		20,200	\$2,828
208136319	MOOVAIR	DMA55HOM25230X3	Heat pump without ducts		34,400	\$4,816
207742550	MOOVAIR	DMA48HOM25230X3	Heat pump without ducts		36,000	\$5,040
207742544	MOOVAIR	DMA27HOM25230X3	Heat pump without ducts		26,600	\$3,724
207742541	MOOVAIR	DMA18HOM25230X3	Heat pump without ducts		15,000	\$2,100
214731128	MOOVAIR	SHC24VH2AG	SHC24VH2AG		11,400	\$1,596
214731129	MOOVAIR	DMA12HOS42230E4	DMB12HIW42230E8		11,400	\$1,596
207706560	MOOVAIR	DMA30HOS20230E7	FMA30HIAHUU230X7		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207706561	MOOVAIR	DMA36HOS20230E7	FMA36HIAHUU230X7		30,400	\$4,256
207742549	MOOVAIR	DMA36HOM25230X3	Combination heat pumps with or without ducts		34,000	\$4,760
206401443	MOOVAIR	DM24HOS25230E3A	DM24HIDU230X5		21,000	\$2,940
207742552	MOOVAIR	DMA48HOM25230X3	Combination heat pumps with or without ducts		36,000	\$5,040
207742524	MOOVAIR	DMA24HOS28230E8	DUA24HIDU230X5		21,000	\$2,940
207742542	MOOVAIR	DMA18HOM25230X3	Heat pump with ducts		16,000	\$2,240
207742547	MOOVAIR	DMA36HOM25230X3	Heat pump without ducts		33,000	\$4,620
207742522	MOOVAIR	DMA12HOS28230E8	DUA12HIDU230X5		10,600	\$1,484
207742543	MOOVAIR	DMA18HOM25230X3	Combination heat pumps with or without ducts		15,500	\$2,170
207742551	MOOVAIR	DMA48HOM25230X3	Heat pump with ducts		36,000	\$5,040
212361759	MOOVAIR	DMA24HOS20230E7	CUB24HAC20BWT7A		21,000	\$2,940
216505504	MOOVAIR	MSHMA15C2AN1	MWHMA15C2AS1*		16,600	\$2,324
216031030	MOOVAIR	MSHMA18C2AN1	MWHMA18C2AS1		16,600	\$2,324
216030964	MOOVAIR	MSHMA18R2AN1	MAHMA18R4AS1		15,000	\$2,100
216031055	MOOVAIR	MSHMA12C2AN1	GFHRA12C2AS1		9,800	\$1,372
216031028	MOOVAIR	MSHMA12C2AN1	MWHMA12C2AS1		9,800	\$1,372
216030965	MOOVAIR	MSHMA24R2AN1	MAHMA24R4AS1		20,000	\$2,800
216030968	MOOVAIR	MSHMB36R2AN1	MAHMA36R4AS1		31,800	\$4,452
216623466	MOOVAIR	MSHMA24R2AN1	MCHMA24RBAS1		19,700	\$2,758
216623470	MOOVAIR	MSHMB36R2AN1	MCHMA36RCAS1		29,200	\$4,088
216623469	MOOVAIR	MSHMB36R2AN1	MCHMA36RBAS1		25,000	\$3,500
216623468	MOOVAIR	MSHMA30R2AN1	MCHMA36RCAS1		29,200	\$4,088
216623452	MOOVAIR	MSHMA18R2AN1	GCHMA24RBAS1		15,200	\$2,128
216623455	MOOVAIR	MSHMA30R2AN1	GCHMA36RCAS1		25,000	\$3,500
216623454	MOOVAIR	MSHMA30R2AN1	GCHMA36RBAS1		25,000	\$3,500
216623457	MOOVAIR	MSHMB36R2AN1	GCHMA36RCAS1		29,200	\$4,088
216623456	MOOVAIR	MSHMB36R2AN1	GCHMA36RBAS1		29,200	\$4,088
216623453	MOOVAIR	MSHMA24R2AN1	GCHMA24RBAS1		19,700	\$2,758
216623459	MOOVAIR	MSHMA18R2AN1	GUHMA24RBAS1		15,200	\$2,128
216623462	MOOVAIR	MSHMA30R2AN1	GUHMA36RCAS1		25,000	\$3,500
216623461	MOOVAIR	MSHMA30R2AN1	GUHMA36RBAS1		25,000	\$3,500
216623463	MOOVAIR	MSHMB36R2AN1	GUHMA36RBAS1		29,200	\$4,088
216623460	MOOVAIR	MSHMA24R2AN1	GUHMA24RBAS1		19,700	\$2,758
216623465	MOOVAIR	MSHMA18R2AN1	MCHMA24RBAS1		15,200	\$2,128
216623464	MOOVAIR	MSHMB36R2AN1	GUHMA36RCAS1		29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216623467	MOOVAIR	MSHMA30R2AN1	MCHMA36RBAS1		25,000	\$3,500
216684114	MOOVAIR	MSHMA48R2AN1	GCHMA48RCAS1		32,000	\$4,480
216684115	MOOVAIR	MSHMA48R2AN1	MCHMA48RCAS1		32,000	\$4,480
216030979	MOOVAIR	MSHMA48R2AN1	MAHHA48R4AS1		34,000	\$4,760
216030980	MOOVAIR	MSHMA60R2AN1	MAHHA60R4AS1		35,000	\$4,900
216030975	MOOVAIR	MSHMA18R2AN1	MAHHA18R4AS1		14,700	\$2,058
216030977	MOOVAIR	MSHMA30R2AN1	MAHHA30R4AS1		24,000	\$3,360
216030978	MOOVAIR	MSHMB36R2AN1	MAHHA36R4AS1		31,000	\$4,340
216030976	MOOVAIR	MSHMA24R2AN1	MAHHA24R4AS1		19,000	\$2,660
216030962	MOOVAIR	MSHEA48R2AN1	MAHMA48R4AS1		32,400	\$4,536
216030959	MOOVAIR	MSHEA24R2AN1	MAHMA24R4AS1		20,000	\$2,800
216505492	MOOVAIR	MSHEA36R2AN1	MGHLA36R2AS1		24,800	\$3,472
216605989	MOOVAIR	MSHHA12C2AN1	MWHHA12C2AS1		11,000	\$1,540
216030969	MOOVAIR	MSHMA48R2AN1	MAHMA48R4AS1		37,000	\$5,180
216030966	MOOVAIR	MSHMA30R2AN1	MAHMA30R4AS1		23,800	\$3,332
216030970	MOOVAIR	MSHMA60R2AN1	MAHMA60R4AS1		45,000	\$6,300
216505503	MOOVAIR	MSHEA15C2AN1	MWHEA15C2AN1*		10,100	\$1,414
216505506	MOOVAIR	MSHMA12C2AN1	GOHRA12C2AS1		9,600	\$1,344
216031022	MOOVAIR	MSHEA12C2AN1	MWHEA12C2AN1		9,300	\$1,302
216031025	MOOVAIR	MSHEA24C2AN1	MWHEA24C2AN1		18,800	\$2,632
216031024	MOOVAIR	MSHEA18C2AN1	MWHEA18C2AN1		13,600	\$1,904
216031032	MOOVAIR	MSHMA33C2AN1	MWHMA33C2AS1		30,000	\$4,200
216031031	MOOVAIR	MSHMA24C2AN1	MWHMA24C2AS1		21,000	\$2,940
216031033	MOOVAIR	MSHHA18C2AN1	MWHHA18C2AS1		19,300	\$2,702
216031039	MOOVAIR	MSHMA12C2AN1	GKHRA12C2AS1		10,000	\$1,400
216031040	MOOVAIR	MSHMA18C2AN1	GKHRA18C2AS1		14,900	\$2,086
216031041	MOOVAIR	MSHMA24C2AN1	GQHRA24C2AS1		20,400	\$2,856
216031045	MOOVAIR	MSHMA18C2AN1	GOHRA18C2AS1		14,500	\$2,030
216031051	MOOVAIR	MSHMA12C2AN1	GDHRA12C2AS1		10,200	\$1,428
216031052	MOOVAIR	MSHMA18C2AN1	GDHRA18C2AS1		15,000	\$2,100
216031053	MOOVAIR	MSHMA24C2AN1	GDHRA24C2AS1		21,600	\$3,024
216031060	MOOVAIR	MXHSA2742AV1	Heat pump with ducts		18,400	\$2,576
216031065	MOOVAIR	MXHSA4862AV1	Heat pump without ducts		38,000	\$5,320
216031066	MOOVAIR	MXHSA4862AV1	Heat pump with ducts		37,000	\$5,180
216031067	MOOVAIR	MXHSA4862AV1	Combination heat pumps with or without ducts		37,400	\$5,236
216031068	MOOVAIR	MXHZA1832AV1	Heat pump without ducts		17,600	\$2,464
216031069	MOOVAIR	MXHZA1832AV1	Heat pump with ducts		17,000	\$2,380

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216031070	MOOVAIR	MXHZA1832AV1	Combination heat pumps with or without ducts		17,300	\$2,422
216031071	MOOVAIR	MXHZA2742AV1	Heat pump without ducts		25,000	\$3,500
216031072	MOOVAIR	MXHZA2742AV1	Heat pump with ducts		23,000	\$3,220
216031073	MOOVAIR	MXHZA2742AV1	Combination heat pumps with or without ducts		24,000	\$3,360
216031075	MOOVAIR	MXHZA3652AV1	Heat pump with ducts		33,000	\$4,620
216031077	MOOVAIR	MXHZA4862AV1	Heat pump without ducts		44,000	\$6,160
216031078	MOOVAIR	MXHZA4862AV1	Heat pump with ducts		44,500	\$6,230
216031079	MOOVAIR	MXHZA4862AV1	Combination heat pumps with or without ducts		44,000	\$6,160
212361761	MOOVAIR	DMA36HOS20230E7	CUB36HAC20CWT7A		33,000	\$4,620
212615028	MOOVAIR	DMA48HOS20230E7	CUB48HAC20CWT7A		32,000	\$4,480
213369385	MOOVAIR	DMA30HOS20230E7	CUB36HAC20BWT7A		19,600	\$2,744
207742513	MOOVAIR	DMA48HOS28230E8	DUA48HICU230X5		35,000	\$4,900
207742526	MOOVAIR	DMA48HOS28230E8	DUA48HIDU230X5		39,500	\$5,530
207742512	MOOVAIR	DMA36HOS28230E8	DUA36HICU230X5		33,000	\$4,620
204005772	MOOVAIR	DM27HOM25230X3	Heat pump without ducts		18,000	\$2,520
206401442	MOOVAIR	DM24HOS25230E3A	DM24HIW23230E3		19,400	\$2,716
208119827	MOOVAIR	DMA24HOS28230E8	DM24HIW23230E3		19,400	\$2,716
212928556	MOOVAIR	DMA36HOS20230E7	CUB36HAC20BWT7A		27,400	\$3,836
207645900	MOOVAIR	DM36HOS25230E3	DM36HICU230X5		25,400	\$3,556
205309414	MOOVAIR	DM48HOM25230X3	Heat pump with ducts		28,000	\$3,920
204005743	MOOVAIR	DM24HOS25230E3	DM24HIDU230X5		17,200	\$2,408
206377756	MOOVAIR	DM12HOS42230E4	DM12HIW42230E4		6,800	\$952
206401439	MOOVAIR	DM18HOS25230E3A	DM18HIW23230E3		10,900	\$1,526
207742582	MOOVAIR	DM24HOS25230E3A	FM24HIAHUU230X6		16,500	\$2,310
207742581	MOOVAIR	DM24HOS25230E3	FM24HIAHUU230X6		17,500	\$2,450
207742548	MOOVAIR	DMA36HOM25230X3	Heat pump with ducts		23,000	\$3,220
205921399	MOOVAIR	DM24HOS25230E3	FM24HIAHUU230X6		17,500	\$2,450
207131748	MOOVAIR	DM24HOS25230E3A	FM24HIAHUU230X6		16,500	\$2,310
206853240	MOOVAIR	DM36HOS25230E3	DM36HIDU230X5		28,000	\$3,920
206853241	MOOVAIR	DM48HOS25230E3	DM48HIDU230X5		33,000	\$4,620
207645901	MOOVAIR	DM48HOS25230E3	DM48HICU230X5		35,000	\$4,900
205309413	MOOVAIR	DM48HOM25230X3	Heat pump without ducts		30,000	\$4,200
207706562	MOOVAIR	DMA48HOS20230E7	FMA48HIAHUU230X7		36,000	\$5,040
210295923	MOOVAIR	DMA60HOS20230E7	FMA60HIAHUU230X7		42,000	\$5,880
212361760	MOOVAIR	DMA30HOS20230E7	CUB36HAC20CWT7A		22,600	\$3,164

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214295965	MOOVAIR	DMC36HOS20230E7	CUB36HAC20BWT7A		27,000	\$3,780
214295966	MOOVAIR	DMC36HOS20230E7	CUB36HAC20CWT7A		27,000	\$3,780
214295967	MOOVAIR	DMC36HOS20230E7	FMA36HIAHUU230X7		31,800	\$4,452
210295922	MOOVAIR	DMA24HOS28230E8	FM24HIAHUU230X6		16,500	\$2,310
212615029	MOOVAIR	DMA60HOS20230E7	CUB60HAC20DWT7A		37,000	\$5,180
207339162	MRCOOL	O-HH-12-HP-C-230A	O-12-HP-WMAH-230B		10,000	\$1,400
208552821	MRCOOL	O-HH-12-HP-C-230B	O-12-HP-WMAH-230B		10,000	\$1,400
207339163	MRCOOL	O-HH-18-HP-C-230A	O-18-HP-WMAH-230B		15,000	\$2,100
208552823	MRCOOL	O-HH-18-HP-C-230B	O-18-HP-WMAH-230B		15,000	\$2,100
208552825	MRCOOL	O-HH-24-HP-C-230B	O-24-HP-WMAH-230B		21,200	\$2,968
207339164	MRCOOL	O-HH-24-HP-C-230A	O-24-HP-WMAH-230B		21,200	\$2,968
210288098	MRCOOL	DIYH-24-HP-C-230C25	DIYH-24-HP-MUAH-230C25		18,400	\$2,576
210288099	MRCOOL	DIYH-30-HP-C-230C25	DIYH-30-HP-MUAH-230C25		21,000	\$2,940
210295926	MRCOOL	DIYH-18-HP-C-230C25	DIYH-18-HP-MUAH-230C25		15,000	\$2,100
210410118	MRCOOL	MDUO18024036	MDUI18036E		24,000	\$3,360
210410117	MRCOOL	MDUO18024036	MDUI18024E		16,000	\$2,240
210410119	MRCOOL	MDUO18048060	MDUI18048E		31,400	\$4,396
216032563	MRCOOL	O-HH-18-HP-C-230C-O	O-18-HP-WMAH-230C-O		16,600	\$2,324
216032560	MRCOOL	O-HH-12-HP-C-230C-O	O-12-HP-WMAH-230C-O		9,800	\$1,372
216032545	MRCOOL	DIY-18-HP-C-230D25-O	DIY-18-HP-WMAH-230D25-O		15,200	\$2,128
216032549	MRCOOL	DIYHH-12-HP-C-230D25-O	DIY-12-HP-WMAH-230D25-O		8,900	\$1,246
216032550	MRCOOL	DIYHH-12-HP-C-230D25-O	DIYCASSETTE12HP-230D25-O		9,100	\$1,274
216032551	MRCOOL	DIYHH-18-HP-C-230D25-O	DIY-18-HP-WMAH-230D25-O		15,200	\$2,128
216032552	MRCOOL	DIYHH-18-HP-C-230D25-O	DIYCASSETTE18HP-230D25-O		14,800	\$2,072
216032561	MRCOOL	O-HH-12-HP-C-230C-O	CASSETTE12HP-230C-O		10,000	\$1,400
216032562	MRCOOL	O-HH-12-HP-C-230C-O	DUCT-12HP-230B-O		9,600	\$1,344
216032564	MRCOOL	O-HH-18-HP-C-230C-O	CASSETTE18HP-230C-O		14,900	\$2,086
216032565	MRCOOL	O-HH-18-HP-C-230C-O	DUCT-18HP-230B-O		15,000	\$2,100
216032566	MRCOOL	O-HH-24-HP-C-230C-O	O-24-HP-WMAH-230C-O		21,000	\$2,940
216032567	MRCOOL	O-HH-24-HP-C-230C-O	CASSETTE24HP-230C-O		20,400	\$2,856
216032568	MRCOOL	O-HH-24-HP-C-230C-O	DUCT-24HP-230B-O		21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216032598	MRCOOL	DIY-MULTI6-55HP230D-O	Heat pump without ducts		44,000	\$6,160
216032599	MRCOOL	DIY-MULTI6-55HP230D-O	Heat pump with ducts		42,500	\$5,950
216032600	MRCOOL	DIY-MULTI6-55HP230D-O	Combination heat pumps with or without ducts		43,250	\$6,055
216032531	MRCOOL	CENTRAL-30-HP-C-230B00-O	MVP-30-HP-MUAH-230A00-O		23,800	\$3,332
216032533	MRCOOL	CENTRAL-48-HP-C-230B00-O	MVP-48-HP-MUAH-230A00-O		37,000	\$5,180
216032532	MRCOOL	CENTRAL-36-HP-C-230B00-O	MVP-36-HP-MUAH-230A00-O		31,800	\$4,452
216032530	MRCOOL	CENTRAL-24-HP-C-230B00-O	MVP-24-HP-MUAH-230A00-O		20,000	\$2,800
216032534	MRCOOL	CENTRAL-60-HP-C-230B00-O	MVP-60-HP-MUAH-230A00-O		45,000	\$6,300
216032536	MRCOOL	MVP-24-HP-C-230A00-O	MVP-24-HP-MUAH-230A00-O		20,000	\$2,800
216032539	MRCOOL	MVP-48-HP-C-230A00-O	MVP-48-HP-MUAH-230A00-O		32,400	\$4,536
210410120	MRCOOL	MDUO18048060	MDUI18060E		36,000	\$5,040
214097894	MRCOOL	MDPH180244			23,400	\$3,276
214097892	MRCOOL	MDPH180484			36,000	\$5,040
214097891	MRCOOL	MDPH180604			37,000	\$5,180
204469771	MRCOOL	O-HH-24-HP-C-230	DUCT-24HP-230		17,200	\$2,408
210279124	MRCOOL	CENTRAL-60-HP-C-230A00	CENTRAL-60-HP-MUAH230A00		42,000	\$5,880
210279123	MRCOOL	CENTRAL-48-HP-C-230A00	CENTRAL-48-HP-MUAH230A00		36,000	\$5,040
211497151	MRCOOL	CENTRAL-24-HP-C-230A00	CENTRAL-24-HP-MUAH230A00		19,200	\$2,688
215213727	NAPOLEON	NDHAMB-36-O	Combination heat pumps with or without ducts		31,400	\$4,396
215931375	NAPOLEON	NDHAMBB-36-O	Heat pump without ducts		30,000	\$4,200
215213725	NAPOLEON	NDHAMB-36-O	Heat pump without ducts		30,000	\$4,200
207683239	NAPOLEON	NDHAM-28-O	Heat pump with ducts		27,000	\$3,780
207683235	NAPOLEON	NDHAS26-18-O	NDHAS26-18-I		15,000	\$2,100
207683240	NAPOLEON	NDHAM-28-O	Combination heat pumps with or without ducts		26,200	\$3,668
207683238	NAPOLEON	NDHAM-28-O	Heat pump without ducts		25,600	\$3,584
207683236	NAPOLEON	NDHAS26-24-O	NDHAS26-24-I		21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207683234	NAPOLEON	NDHAS26-12-O	NDHAS26-12-I		10,000	\$1,400
207335554	NAPOLEON	NS18HV48A60	NPFX48A		31,400	\$4,396
207683241	NAPOLEON	NDHAM-36-O	Heat pump without ducts		35,000	\$4,900
207683243	NAPOLEON	NDHAM-36-O	Combination heat pumps with or without ducts		35,000	\$4,900
211624976	NAPOLEON	WSEHV4860RA1-N	NPFX48A60A		44,000	\$6,160
211624975	NAPOLEON	WSEHV4860RA1-N	NPFX48A		39,500	\$5,530
211624974	NAPOLEON	WSEHV2436RA1-N	NPFX24A36A		29,000	\$4,060
211624973	NAPOLEON	WSEHV2436RA1-N	NPFX24A		20,000	\$2,800
216706205	NAPOLEON	NDHAS26B-33-O	NDHAS26B-33-I		30,000	\$4,200
215213708	NAPOLEON	NDHAS26B-18-O	NDHAS26B-18-I		16,600	\$2,324
215931362	NAPOLEON	NDHAS26BA-18-O	NDHAS26BA-18-I		16,600	\$2,324
215931361	NAPOLEON	NDHAS26BA-12-O	NDHAS26BA-12-I		9,800	\$1,372
215213707	NAPOLEON	NDHAS26B-12-O	NDHAS26B-12-I		9,800	\$1,372
216626013	NAPOLEON	WSEHV4860BA1-N	WPFX48A-N		33,400	\$4,676
216025738	NAPOLEON	WSEHV2436BA1-N	WPFX36A-N		23,000	\$3,220
216626012	NAPOLEON	WSEHV2436BA1-N	WPFX24A-N		18,000	\$2,520
215931356	NAPOLEON	NDHAS22BA-24-O	NDHAS22BB-24-I		19,500	\$2,730
215931355	NAPOLEON	NDHAS22BA-18-O	NDHAS22BB-18-I		13,000	\$1,820
215931354	NAPOLEON	NDHAS22BA-12-O	NDHAS22BB-12-I		9,600	\$1,344
215213705	NAPOLEON	NDHAS22B-24-O	NDHAS22B-24-I		19,500	\$2,730
215213704	NAPOLEON	NDHAS22B-18-O	NDHAS22B-18-I		13,000	\$1,820
215213703	NAPOLEON	NDHAS22B-12-O	NDHAS22B-12-I		9,600	\$1,344
215931363	NAPOLEON	NDHAS26BA-24-O	NDHAS26BA-24-I		21,000	\$2,940
215931364	NAPOLEON	NDHAS26BA-33-O	NDHAS26BA-33-I		30,000	\$4,200
215931374	NAPOLEON	NDHAMB-27-O	Heat pump without ducts		25,000	\$3,500
215931373	NAPOLEON	NDHAMB-18-O	Heat pump without ducts		17,600	\$2,464
215463872	NAPOLEON	CDHAS26B-33-O	CDHAS26B-33-I		30,000	\$4,200
206597272	NAPOLEON	NH25-18H-O	NH25-24F-I		19,400	\$2,716
206598613	NAPOLEON	NH25-24H-O	NH25-24F-I		19,400	\$2,716
207335555	NAPOLEON	NS18HV48A60	NPFX48A60A		36,000	\$5,040
215213709	NAPOLEON	NDHAS26B-24-O	NDHAS26B-24-I		19,300	\$2,702
215213726	NAPOLEON	NDHAMB-36-O	Heat pump with ducts		33,000	\$4,620
215213721	NAPOLEON	NDHAMB-27-O	Combination heat pumps with or without ducts		24,000	\$3,360
215213720	NAPOLEON	NDHAMB-27-O	Heat pump with ducts		23,000	\$3,220
215213719	NAPOLEON	NDHAMB-27-O	Heat pump without ducts		25,000	\$3,500
212404677	NAPOLEON	WSEHV4860RA1-N	H,DE50960	WPV090T5BA	38,000	\$5,320

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207683242	NAPOLEON	NDHAM-36-O	Heat pump with ducts		23,000	\$3,220
212404680	NAPOLEON	WSEHV4860RA1-N	H,DE50960	WPV100T5BA	38,000	\$5,320
212427854	NAPOLEON	WSEHV2436RA1-N	H,DE33(6,9)36	WUV070T3AA	15,000	\$2,100
212427853	NAPOLEON	WSEHV2436RA1-N	H,DE33(6,9)36	WPV070T3AA	15,000	\$2,100
212404696	NAPOLEON	WSEHV2436RA1-N	H,DE33(6,9)36	WUV060T3AA	15,000	\$2,100
212404695	NAPOLEON	WSEHV2436RA1-N	H,DE33(6,9)36	WUV050T3AA	15,000	\$2,100
212404694	NAPOLEON	WSEHV2436RA1-N	H,DE33(6,9)36	WPV060T3AA	15,000	\$2,100
212404693	NAPOLEON	WSEHV2436RA1-N	H,DE33(6,9)36	WPV050T3AA	15,000	\$2,100
212404687	NAPOLEON	NS18HV48A60	H,DE50960	WUV100T5BA	38,000	\$5,320
212404686	NAPOLEON	NS18HV48A60	H,DE50960	WUV090T5BA	38,000	\$5,320
212404688	NAPOLEON	NS18HV48A60	H,DE50960	WPV100T5BA	38,000	\$5,320
212404685	NAPOLEON	NS18HV48A60	H,DE50960	WPV090T5BA	38,000	\$5,320
212404679	NAPOLEON	WSEHV4860RA1-N	H,DE50960	WUV100T5BA	38,000	\$5,320
212404678	NAPOLEON	WSEHV4860RA1-N	H,DE50960	WUV090T5BA	38,000	\$5,320
212603041	NAPOLEON	WSEHV2436RA1-N	H,DE37936	WPV070T3AA	25,600	\$3,584
212603042	NAPOLEON	WSEHV2436RA1-N	H,DE37936	WPV080T3AA	25,600	\$3,584
212920610	NAPOLEON	WSEHV2436RA1-N	H,DE37936	WUV070T3AA	25,600	\$3,584
212920611	NAPOLEON	WSEHV2436RA1-N	H,DE37936	WUV080T3AA	25,600	\$3,584
214377799	NG TRADE	OMEGA121E	IMEGA121E		10,300	\$1,442
214377800	NG TRADE	OMEGA181E	IMEGA181E		11,100	\$1,554
214377801	NG TRADE	OMEGA241E	IMEGA241E		18,900	\$2,646
216763025	NG TRADE	EZCENO48K	EZCENI48K		32,400	\$4,536
216763022	NG TRADE	EZCENO24K	EZCENI24K		20,000	\$2,800
216598398	NG TRADE	MOBMH480D	Heat pump with ducts		37,000	\$5,180
206724396	NORTEK	GXH24-36MSK4DH	GMH24-**MSK4DH1		20,000	\$2,800
206724397	NORTEK	GXH24-36MSK4DH	GMH**-36MSK4DH1		29,000	\$4,060
206724398	NORTEK	GXH48-60MSK4DH	GMH48-**MSK4DH1		39,500	\$5,530
206724399	NORTEK	GXH48-60MSK4DH	GMH**-60MSK4DH1		44,000	\$6,160
209416882	NOVAIR	LEA28MZ-3P-35SK-O	Heat pump with ducts		27,000	\$3,780
211253513	NOVAIR	LEA24-EVOX-30-O	LEA24-EVOX-30-I		19,200	\$2,688
211253511	NOVAIR	LEA18-EVOX-30-O	LEA18-EVOX-30-I		13,500	\$1,890
211709683	NOVAIR	LEA12SZ35SK-O	2LEA12UUSK-I		10,000	\$1,400
211709684	NOVAIR	LEA18SZ35SK-O	2LEA18UUSK-I		15,000	\$2,100
211709685	NOVAIR	LEA24SZ35SK-O	2LEA24UUSK-I		21,200	\$2,968
209416883	NOVAIR	LEA28MZ-3P-35SK-O	Combination heat pumps with or without ducts		26,200	\$3,668
209416881	NOVAIR	LEA28MZ-3P-35SK-O	Heat pump without ducts		25,600	\$3,584
209416884	NOVAIR	LEA20MZ-2P-35SK-O	Heat pump without ducts		13,500	\$1,890

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212920679	NOVAIR	LEA20MZ-2P-35SK-O*	Heat pump without ducts		15,000	\$2,100
211253509	NOVAIR	LEA30-EVOX-30-O	LEA30-EVOX-30-I		21,000	\$2,940
211253510	NOVAIR	LEA36-EVOX-30-O	LEA36-EVOX-30-I		30,400	\$4,256
207539337	NOVAIR	LEA12SZ35SK-O	LEA12UUSK-I		10,300	\$1,442
207526948	NOVAIR	LEA18SZ35SK-O	LEA18UUSK-I		11,100	\$1,554
209416880	NOVAIR	LEA24SZ35SK-O	LEA24UUSK-I		18,900	\$2,646
214867641	NOVAIR	LEA24-EVOX-30-O	LEA-18/24-ACOIL-410A		21,000	\$2,940
209416885	NOVAIR	LEA20MZ-2P-35SK-O	Heat pump with ducts		16,000	\$2,240
212920682	NOVAIR	LEA36MZ-4P-35SK-O*	Heat pump without ducts		33,000	\$4,620
212920680	NOVAIR	LEA20MZ-2P-35SK-O*	Heat pump with ducts		16,000	\$2,240
212920684	NOVAIR	LEA36MZ-4P-35SK-O*	Combination heat pumps with or without ducts		34,000	\$4,760
209416886	NOVAIR	LEA20MZ-2P-35SK-O	Combination heat pumps with or without ducts		14,700	\$2,058
211133300	NOVAIR	LEA36MZ-4P-35SK-O	Heat pump without ducts		35,000	\$4,900
211133301	NOVAIR	LEA36MZ-4P-35SK-O	Combination heat pumps with or without ducts		35,000	\$4,900
212920681	NOVAIR	LEA20MZ-2P-35SK-O*	Combination heat pumps with or without ducts		15,500	\$2,170
214867644	NOVAIR	LEA36-EVOX-30-O	LEA-30/36-ACOIL-410A		33,000	\$4,620
214867642	NOVAIR	LEA30-EVOX-30-O	LEA-30/36-ACOIL-410A		22,600	\$3,164
211253514	NOVAIR	LEA48-EVOX-30-O	LEA48-EVOX-30-I		36,000	\$5,040
211253512	NOVAIR	LEA60-EVOX-30-O	LEA60-EVOX-30-I		42,000	\$5,880
205281392	NOVAIR PLUS	24EVONVO	24EVDNVI		17,200	\$2,408
217037912	OUELLET	OCVX-H12A-O	OFCX1-H12A-I		10,000	\$1,400
217037913	OUELLET	OCVX-H12A-O	OICX1-H12A-I		10,000	\$1,400
216472856	OUELLET	OARX-H12A-O	OARX-H12A-I		10,300	\$1,442
216498641	OUELLET	OARX-H18A-O	OARX-H18A-I		15,500	\$2,170
216498640	OUELLET	OARX-H24A-O	OARX-H24A-I		20,000	\$2,800
216472865	OUELLET	OCHX-H36A-O	OCHX-H36A-I		27,400	\$3,836
216472858	OUELLET	OCVX-H12A-O	OCVX-H12A-I		10,000	\$1,400
216472859	OUELLET	OCVX-H18A-O	OCVX-H18A-I		14,700	\$2,058
216453528	OUELLET	OFRM2X1-H18A-O	Heat pump without ducts		16,000	\$2,240
216453533	OUELLET	OFRM2X1-H18A-O	Heat pump with ducts		15,000	\$2,100
216453538	OUELLET	OFRM2X1-H18A-O	Combination heat pumps with or without ducts		15,400	\$2,156
216453529	OUELLET	OFRM3X1-H24A-O	Heat pump without ducts		23,600	\$3,304
216453534	OUELLET	OFRM3X1-H24A-O	Heat pump with ducts		22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216453539	OUELLET	OFRM3X1-H24A-O	Combination heat pumps with or without ducts		22,800	\$3,192
216453530	OUELLET	OFRM4X1-H30A-O	Heat pump without ducts		28,000	\$3,920
216453535	OUELLET	OFRM4X1-H30A-O	Heat pump with ducts		27,200	\$3,808
216453540	OUELLET	OFRM4X1-H30A-O	Combination heat pumps with or without ducts		27,600	\$3,864
216453531	OUELLET	OFRM4X1-H36A-O	Heat pump without ducts		36,000	\$5,040
216453536	OUELLET	OFRM4X1-H36A-O	Heat pump with ducts		36,000	\$5,040
216453541	OUELLET	OFRM4X1-H36A-O	Combination heat pumps with or without ducts		36,000	\$5,040
216453532	OUELLET	OFRM5X1-H42A-O	Heat pump without ducts		40,000	\$5,600
216453537	OUELLET	OFRM5X1-H42A-O	Heat pump with ducts		40,000	\$5,600
216453542	OUELLET	OFRM5X1-H42A-O	Combination heat pumps with or without ducts		40,000	\$5,600
216440571	OUELLET	OFLX1-H24A-O	OAHX1-H24A-I		20,600	\$2,884
216440572	OUELLET	OFLX1-H36A-O	OAHX1-H36A-I		28,200	\$3,948
216626170	OUELLET	OFLX1-H36A-O	OAHX1-H24A-I		20,600	\$2,884
216440573	OUELLET	OFLX1-H48A-O	OAHX1-H48A-I		39,500	\$5,530
216440574	OUELLET	OFLX1-H60A-O	OAHX1-H60A-I		45,000	\$6,300
216626171	OUELLET	OFLX1-H60A-O	OAHX1-H48A-I		39,500	\$5,530
216472864	OUELLET	OCHX-H30A-O	OCHX-H30A-I		24,000	\$3,360
216472863	OUELLET	OCHX-H24A-O	OCHX-H24A-I		19,200	\$2,688
216472861	OUELLET	OCHX-H12A-O	OCHX-H12A-I		9,700	\$1,358
216621503	PANASONIC	CU-HM55BAHU	CS-HM60BAAU4		36,000	\$5,040
212396492	PANASONIC	CU-HE18YAHK6	CS-HE18YAHK6		13,500	\$1,890
212396493	PANASONIC	CU-HE24YAHK6	CS-HE24YAHK6		19,200	\$2,688
212396494	PANASONIC	CU-HE30YAHK6	CS-HE30YAHK6		21,000	\$2,940
212396495	PANASONIC	CU-HE36YAHK6	CS-HE36YAHK6		30,400	\$4,256
212396505	PANASONIC	CU-HE24YAHK6	CS-HE24YAC6		21,000	\$2,940
216980455	PANASONIC	CU-HM48BAHU	CS-HM60BAMU3		34,400	\$4,816
216980456	PANASONIC	CU-HM55BAHU	CS-HM60BAMU3		37,800	\$5,292
216505879	PANASONIC	CU-HM18BAHU	CS-HM18BAHU		15,000	\$2,100
215711364	PANASONIC	CU-HZ18YAHK6	CS-HZ18YAHK6		15,000	\$2,100
215711365	PANASONIC	CU-HZ24YAHK6	CS-HZ24YAHK6		20,000	\$2,800
216505880	PANASONIC	CU-HM24BAHU	CS-HM24BAHU		20,000	\$2,800
215711367	PANASONIC	CU-HZ36YAHK6	CS-HZ36YAHK6		31,800	\$4,452
216505882	PANASONIC	CU-HM36BAHU	CS-HM36BAHU		31,800	\$4,452
216621498	Panasonic	CU-HM30BAHU	CS-HM36BAAU1		23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216621497	Panasonic	CU-HM24BAHU	CS-HM24BAAU2		19,700	\$2,758
216621496	Panasonic	CU-HM24BAHU	CS-HM24BAAU1		19,700	\$2,758
216621495	Panasonic	CU-HM18BAHU	CS-HM24BAAU2		15,200	\$2,128
216621494	Panasonic	CU-HM18BAHU	CS-HM24BAAU1		15,200	\$2,128
216621500	Panasonic	CU-HM30BAHU	CS-HM36BAAU3		25,000	\$3,500
216621499	Panasonic	CU-HM30BAHU	CS-HM36BAAU2		25,000	\$3,500
216621502	Panasonic	CU-HM36BAHU	CS-HM36BAAU3		29,200	\$4,088
216621501	Panasonic	CU-HM36BAHU	CS-HM36BAAU2		29,200	\$4,088
216621507	Panasonic	CU-M24BAHU	CS-HM24BAAU2		19,700	\$2,758
216621506	Panasonic	CU-M24BAHU	CS-HM24BAAU1		19,700	\$2,758
216621509	Panasonic	CU-HM55BAHU	CS-HM60AMU3		38,000	\$5,320
216684082	PANASONIC	CU-HM48BAHU	CS-HM60AMU3		32,000	\$4,480
216684084	PANASONIC	CU-M36BAHU	CS-HM36BAAU3		24,200	\$3,388
216684083	PANASONIC	CU-M36BAHU	CS-HM36BAAU2		24,200	\$3,388
216505877	PANASONIC	CU-M48BAHU	CS-HM48BAHU		32,400	\$4,536
216505875	PANASONIC	CU-M24BAHU	CS-HM24BAHU		20,000	\$2,800
216505883	PANASONIC	CU-HM48BAHU	CS-HM48BAHU		37,000	\$5,180
216505881	PANASONIC	CU-HM30BAHU	CS-HM30BAHU		23,800	\$3,332
216505884	PANASONIC	CU-HM55BAHU	CS-HM60BAHU		45,000	\$6,300
212396507	PANASONIC	CU-HE36YAHK6	CS-HE36YAC6		33,000	\$4,620
215711362	PANASONIC	CU-Z48YAHK6	CS-HZ48YAHK6		32,400	\$4,536
215711359	PANASONIC	CU-Z24YAHK6	CS-HZ24YAHK6		20,000	\$2,800
215711369	PANASONIC	CU-HZ55YAHK6	CS-HZ60YAHK6		45,000	\$6,300
215711368	PANASONIC	CU-HZ48YAHK6	CS-HZ48YAHK6		37,000	\$5,180
215711366	PANASONIC	CU-HZ30YAHK6	CS-HZ30YAHK6		23,800	\$3,332
214837934	PANASONIC	CU-Z218ABUC	Heat pump without ducts		24,600	\$3,444
213082094	PANASONIC	CU-HE36YAHK6	CS-HE36YAS6		27,400	\$3,836
213160451	PANASONIC	CU-HE36YAHK6	CS-HE36YAS6*		27,400	\$3,836
212396497	PANASONIC	CU-HE55YAHK6	CS-HE60YAHK6		42,000	\$5,880
212396506	PANASONIC	CU-HE30YAHK6	CS-HE30YAC6		22,600	\$3,164
212396496	PANASONIC	CU-HE48YAHK6	CS-HE48YAHK6		36,000	\$5,040
205047853	PANASONIC	CU-XE15WKUA	CS-XE15WKUAW		11,000	\$1,540
201900302	PANASONIC	CU-XE15SKUA-1	CS-XE15SKUA-1		18,200	\$2,548
205047855	PANASONIC	CU-XE24WKUA	CS-XE24WKUAW		18,500	\$2,590
10221207	PANASONIC	CU5E36QBU5	Heat pump without ducts		28,000	\$3,920
213160445	PANASONIC	CU-HE55YAHK6	CS-HE60YAC6		37,000	\$5,180
207683306	Payne	38MARBQ24AA3	40MBCAQ24XA3		21,000	\$2,940
207614954	Payne	38MPRBQ12AA3	DHMPHBQ12XA3		10,400	\$1,456

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207826654	Payne	38MPRBQ18AA3	DHMPHBQ18XA3		20,200	\$2,828
208447903	PAYNE	38MURAQ18AB3	40MUAAQ18XA3		13,500	\$1,890
208447905	PAYNE	38MURAQ24AB3	40MUAAQ24XA3		19,200	\$2,688
208447901	PAYNE	38MURAQ36AB3	40MUAAQ36XA3		30,400	\$4,256
215323767	PAYNE	37MAHAQ18AA3	D5MAHAQ18XA3		16,600	\$2,324
215357705	PAYNE	37MGHAQ30EA3	Combination heat pumps with or without ducts		31,400	\$4,396
215357704	PAYNE	37MGHAQ30EA3	Heat pump with ducts		33,000	\$4,620
215357703	PAYNE	37MGHAQ30EA3	Heat pump without ducts		30,000	\$4,200
215357731	PAYNE	37MGRAQ48FA3	Heat pump with ducts		37,000	\$5,180
215357714	PAYNE	37MGHAQ55FA3	Combination heat pumps with or without ducts		44,500	\$6,230
215357713	PAYNE	37MGHAQ55FA3	Heat pump with ducts		45,000	\$6,300
215357712	PAYNE	37MGHAQ55FA3	Heat pump without ducts		44,000	\$6,160
215357711	PAYNE	37MGHAQ48FA3	Combination heat pumps with or without ducts		44,000	\$6,160
215357710	PAYNE	37MGHAQ48FA3	Heat pump with ducts		44,500	\$6,230
215357709	PAYNE	37MGHAQ48FA3	Heat pump without ducts		44,000	\$6,160
215357708	PAYNE	37MGHAQ36EA3	Combination heat pumps with or without ducts		31,400	\$4,396
215323768	PAYNE	37MAHAQ24AA3	D5MAHAQ24XA3		21,000	\$2,940
215323935	PAYNE	37MAHAQ18AA3	45MBDAQ18XA3		15,000	\$2,100
215323933	PAYNE	37MAHAQ18AA3	45MBFAQ16XA3		14,200	\$1,988
215323932	PAYNE	37MAHAQ18AA3	45MBCAQ18XA3		14,900	\$2,086
215323931	PAYNE	37MAHAQ18AA3	45MCCAQ18XA3		14,500	\$2,030
215323929	PAYNE	37MAHAQ12AA3	45MBDAQ12XA3		9,600	\$1,344
215323928	PAYNE	37MAHAQ12AA3	45MBFAQ12XA3		9,800	\$1,372
215323927	PAYNE	37MAHAQ12AA3	45MBCAQ12XA3		10,000	\$1,400
215323926	PAYNE	37MAHAQ12AA3	45MCCAQ12XA3		9,600	\$1,344
215323766	PAYNE	37MAHAQ12AA3	D5MAHAQ12XA3		9,800	\$1,372
215323722	PAYNE	37MUHAQ36AA3	45MUHAQ36XX3		31,000	\$4,340
215323938	PAYNE	37MAHAQ24AA3	45MCFAQ24XA3		20,200	\$2,828
215323937	PAYNE	37MAHAQ24AA3	45MBCAQ24XA3		20,400	\$2,856
215323934	PAYNE	37MAHAQ18AA3	45MCFAQ18XA3		14,400	\$2,016
215323971	PAYNE	37MBHAQ58AA3	45MBDAQ58XH3		45,000	\$6,300
215323969	PAYNE	37MBHAQ48AA3	45MBDAQ48XH3		45,000	\$6,300
215323966	PAYNE	37MBHAQ36AA3	45MBDAQ36XH3		31,600	\$4,424
215323769	PAYNE	37MAHAQ33AA3	D5MAHAQ33XA3		30,000	\$4,200

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215323939	PAYNE	37MAHAQ24AA3	45MBDAQ24XH3		21,600	\$3,024
215413156	PAYNE	37MPRAQ18AA3	D5MPHAQ18XA3		19,300	\$2,702
215413155	PAYNE	37MPRAQ12AA3	D5MPHAQ12XA3		11,000	\$1,540
215357707	PAYNE	37MGHAQ36EA3	Heat pump with ducts		33,000	\$4,620
215357706	PAYNE	37MGHAQ36EA3	Heat pump without ducts		30,000	\$4,200
215357702	PAYNE	37MGHAQ27DA3	Combination heat pumps with or without ducts		24,000	\$3,360
215357701	PAYNE	37MGHAQ27DA3	Heat pump with ducts		23,000	\$3,220
215357700	PAYNE	37MGHAQ27DA3	Heat pump without ducts		25,000	\$3,500
215357696	PAYNE	37MGHAQ18CA3	Combination heat pumps with or without ducts		17,300	\$2,422
215357695	PAYNE	37MGHAQ18CA3	Heat pump with ducts		17,000	\$2,380
215357694	PAYNE	37MGHAQ18CA3	Heat pump without ducts		17,600	\$2,464
215323936	PAYNE	37MAHAQ18AA3	45MBDAQ18XH3		15,000	\$2,100
215323930	PAYNE	37MAHAQ12AA3	45MBDAQ12XH3		10,200	\$1,428
215323970	PAYNE	37MBHAQ58AA3	45MCFAQ58XA3		41,000	\$5,740
215323968	PAYNE	37MBHAQ48AA3	45MCFAQ48XA3		38,500	\$5,390
215323967	PAYNE	37MBHAQ48AA3	45MBCAQ48XA3		44,000	\$6,160
215323965	PAYNE	37MBHAQ36AA3	45MCFAQ36XA3		30,200	\$4,228
215323964	PAYNE	37MBHAQ36AA3	45MBCAQ36XA3		30,600	\$4,284
215318819	PAYNE	37MUHAQ48AA3	45MUHAQ60XX3		34,000	\$4,760
215318818	PAYNE	37MUHAQ30AA3	45MUHAQ36XX3		24,000	\$3,360
215318817	PAYNE	37MUHAQ18AA3	45MUHAQ24XX3		14,700	\$2,058
215318827	PAYNE	37MBHAQ58AA3	45MBAAQ60XA3		41,000	\$5,740
215318825	PAYNE	37MBHAQ36AA3	45MBAAQ36XA3		28,000	\$3,920
215318815	PAYNE	37MURAQ48AA3	45MUAAQ48XX3		32,400	\$4,536
215318812	PAYNE	37MURAQ24AA3	45MUAAQ24XX3		20,000	\$2,800
215318810	PAYNE	37MUHAQ60AA3	45MUHAQ60XX3		35,000	\$4,900
215318809	PAYNE	37MUHAQ60AA3	45MUAAQ60XX3		45,000	\$6,300
215318808	PAYNE	37MUHAQ48AA3	45MUAAQ48XX3		37,000	\$5,180
215318807	PAYNE	37MUHAQ36AA3	45MUAAQ36XX3		31,800	\$4,452
215318806	PAYNE	37MUHAQ30AA3	45MUAAQ30XX3		23,800	\$3,332
215318805	PAYNE	37MUHAQ24AA3	45MUHAQ24XX3		19,000	\$2,660
215318804	PAYNE	37MUHAQ24AA3	45MUAAQ24XX3		20,000	\$2,800
215318803	PAYNE	37MUHAQ18AA3	45MUAAQ18XX3		15,000	\$2,100
215318826	PAYNE	37MBHAQ48AA3	45MBAAQ48XA3		40,000	\$5,600
215318822	PAYNE	37MAHAQ33AA3	45MBAAQ36XB3		27,400	\$3,836
215318821	PAYNE	37MAHAQ24AA3	45MBAAQ24XB3		16,900	\$2,366

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215318820	PAYNE	37MAHAQ18AA3	45MBAAQ18XB3		14,000	\$1,960
213372227	PAYNE	38MURAQ60AB3	40MULAQ60XDX + CI		37,000	\$5,180
213372223	PAYNE	38MURAQ30AB3	40MULAQ36XCX + CI		22,600	\$3,164
204722802	PAYNE	38MGRQ30D--3	Combination heat pumps with or without ducts		20,200	\$2,828
204722803	PAYNE	38MGRQ36D--3	Combination heat pumps with or without ducts		23,800	\$3,332
204711114	PAYNE	38MGRQ30D--3	Heat pump with ducts		23,000	\$3,220
201847069	PAYNE	38MGRQ36D--3	Heat pump with ducts		24,600	\$3,444
201846978	PAYNE	38MAQB24R--3	40MBDQ24---3		17,300	\$2,422
201846973	PAYNE	38MAQB12R--3	40MBCQ12---3		8,700	\$1,218
201847045	PAYNE	38MAQB24R--3	40MBFQ24---3		17,200	\$2,408
201847047	PAYNE	38MBRQ48A--3	40MBFQ48---3		35,000	\$4,900
201753413	PAYNE	38MPRAQ12AA3	DHMPHAQ12XA3		6,800	\$952
202463639	PAYNE	38MPRAQ24AA3	DHMPHAQ24XA3		15,450	\$2,163
201846969	PAYNE	38MAQB12R--3	DHMSHAQ12XA3		7,800	\$1,092
205921386	PAYNE	38MAQB24R--3	40MBAAQ24XA3		17,500	\$2,450
206350353	PAYNE	38MARBQ12AA3	40MBFQ12--3		8,400	\$1,176
206350351	PAYNE	38MARBQ12AA3	40MBCQ12--3		7,900	\$1,106
206396045	PAYNE	38MAQB12R--3	DHMAHBQ12XA3		7,500	\$1,050
206350352	PAYNE	38MARBQ12AA3	40MBDQ12--3		8,300	\$1,162
206350358	PAYNE	38MARBQ24AA3	40MBDQ24--3		14,500	\$2,030
206350356	PAYNE	38MARBQ18AA3	40MBFQ18--3		12,000	\$1,680
206350359	PAYNE	38MARBQ24AA3	40MBFQ24--3		14,500	\$2,030
206350357	PAYNE	38MARBQ24AA3	40MBCQ24--3		14,500	\$2,030
206350316	PAYNE	38MARBQ24AA3	DHMAHBQ24XA3		19,800	\$2,772
206350315	PAYNE	38MARBQ18AA3	DHMAHBQ18XA3		10,800	\$1,512
206350314	PAYNE	38MARBQ12AA3	DHMAHBQ12XA3		7,500	\$1,050
206188267	PAYNE	38MARBQ24AA3	40MBAAQ24XA3		16,500	\$2,310
206350355	PAYNE	38MARBQ18AA3	40MBDQ18--3		12,700	\$1,778
201846976	PAYNE	38MAQB12R--3	40MBDQ12---3		8,500	\$1,190
207642932	PAYNE	38MGHBQ48EA3	Combination heat pumps with or without ducts		29,000	\$4,060
207642935	PAYNE	38MGHBQ36DA3	Combination heat pumps with or without ducts		23,000	\$3,220
207642926	PAYNE	38MGHBQ30DA3	Combination heat pumps with or without ducts		18,200	\$2,548
207642931	PAYNE	38MGHBQ48EA3	Heat pump with ducts		28,000	\$3,920

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207642925	PAYNE	38MGHBQ30DA3	Heat pump with ducts		19,000	\$2,660
207642934	PAYNE	38MGHBQ36DA3	Heat pump with ducts		23,000	\$3,220
203381005	PAYNE	38MAQB18R--3	FM(C,U)4Z18**AL*		12,600	\$1,764
203381006	PAYNE	38MAQB24R--3	FM(C,U)4Z24**AL*		15,000	\$2,100
204344200	PAYNE	38MAQB18R--3	FV4CNF002		11,000	\$1,540
204344201	PAYNE	38MAQB24R--3	FV4CNF002		14,000	\$1,960
204344202	PAYNE	38MAQB30R--3	FV4CN(B,F)003		20,200	\$2,828
203380989	PAYNE	38MAQB18R--3	FMA4X18**AL*		10,800	\$1,512
207642933	PAYNE	38MGHBQ36DA3	Heat pump without ducts		23,200	\$3,248
207642930	PAYNE	38MGHBQ48EA3	Heat pump without ducts		30,000	\$4,200
207642924	PAYNE	38MGHBQ30DA3	Heat pump without ducts		17,500	\$2,450
204722816	PAYNE	38MGRQ30D--3	Heat pump without ducts		17,400	\$2,436
201846984	PAYNE	38MGRQ36D--3	Heat pump without ducts		23,200	\$3,248
208447900	PAYNE	38MURAQ48AB3	40MUAAQ48XA3		36,000	\$5,040
207801580	PAYNE	38MARBQ18AA3	40MBDQ24---3		12,600	\$1,764
207826669	PAYNE	38MARBQ18AA3	40MBABQ18XB3		12,000	\$1,680
212982374	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80MSUA36040B**	12,200	\$1,708
212982938	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MSUA60080C**	23,200	\$3,248
212982626	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MSUA48060B**	23,200	\$3,248
212982398	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80MSUA36040B**	12,200	\$1,708
213079311	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MSUA60080C**	29,200	\$4,088
213078855	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MSUA60100C**	29,200	\$4,088
212982434	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80MSUA36040B**	12,300	\$1,722
212982686	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80MSUA48060B**	23,400	\$3,276
212982386	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80MSUA36040B**	12,400	\$1,736
212982362	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MSUA36040B**	19,100	\$2,674
212982218	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80MSUA36040B**	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079179	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MSUA48060B**	29,200	\$4,088
213079011	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MSUA36040B**	29,000	\$4,060
212988049	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG96MSAA60100C**	23,600	\$3,304
212988037	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG96MSAA60100C**	23,400	\$3,276
213079143	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MSUA48060B**	29,000	\$4,060
212982662	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MSUA48060B**	23,200	\$3,248
212982350	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80MSUA36040B**	19,100	\$2,674
212982326	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80MSUA36040B**	19,400	\$2,716
212982302	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80MSUA36040B**	18,800	\$2,632
212988097	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG96MSAA60100C**	23,600	\$3,304
212988061	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG96MSAA60100C**	23,600	\$3,304
212982290	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MSUA36040B**	19,100	\$2,674
212982134	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80MSUA36040B**	23,400	\$3,276
212982710	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80MSUA48060B**	18,600	\$2,604
212981606	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80MSUA60100C**	23,600	\$3,304
213079275	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80MSUA60080C**	29,000	\$4,060
213079047	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80MSUA36040B**	29,200	\$4,088
212981534	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MSUA60100C**	29,000	\$4,060
212982638	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80MSUA48060B**	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982998	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80MSUA60080C**	23,600	\$3,304
213079059	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MSUA36040B**	29,400	\$4,116
213078951	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80MSUA36040B**	29,400	\$4,116
212981678	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80MSUA60100C**	23,600	\$3,304
212982338	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80MSUA36040B**	19,100	\$2,674
212982266	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80MSUA36040B**	19,100	\$2,674
212982242	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80MSUA36040B**	19,400	\$2,716
213079323	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80MSUA60080C**	29,200	\$4,088
213078927	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MSUA60100C**	29,400	\$4,116
213078903	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG80MSUA60100C**	29,600	\$4,144
213078879	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MSUA60100C**	29,200	\$4,088
213078987	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MSUA36040B**	29,000	\$4,060
212982698	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MSUA48060B**	19,000	\$2,660
212982422	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80MSUA36040B**	12,400	\$1,736
212982722	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MSUA48060B**	19,000	\$2,660
212982410	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80MSUA36040B**	12,300	\$1,722
212982170	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MSUA36040B**	23,200	\$3,248
212982278	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80MSUA36040B**	19,000	\$2,660
212981618	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MSUA60100C**	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212981594	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MSUA60100C**	23,200	\$3,248
213079251	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MSUA60080C**	29,000	\$4,060
213079215	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MSUA60080C**	29,000	\$4,060
213079167	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MSUA48060B**	29,400	\$4,116
213079203	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MSUA60080C**	29,400	\$4,116
212982314	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80MSUA36040B**	18,700	\$2,618
213079227	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MSUA60080C**	29,400	\$4,116
213079083	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MSUA48060B**	29,400	\$4,116
212982146	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MSUA36040B**	23,200	\$3,248
212982974	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MSUA60080C**	23,200	\$3,248
213079299	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MSUA60080C**	29,400	\$4,116
212982158	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80MSUA36040B**	23,400	\$3,276
213079239	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80MSUA60080C**	29,400	\$4,116
213079107	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MSUA48060B**	29,200	\$4,088
213079095	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MSUA48060B**	29,000	\$4,060
212982254	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80MSUA36040B**	18,600	\$2,604
213079131	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MSUA48060B**	29,000	\$4,060
213079071	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MSUA36040B**	29,200	\$4,088
213078999	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MSUA36040B**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079155	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG80MSUA48060B**	29,600	\$4,144
213080341	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG96MSAA60100C**	29,400	\$4,116
213080317	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG96MSAA60100C**	29,200	\$4,088
213080293	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96MSAA60100C**	29,400	\$4,116
213079263	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MSUA60080C**	29,000	\$4,060
212988073	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG96MSAA60100C**	23,200	\$3,248
212988001	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96MSAA60100C**	29,000	\$4,060
212982086	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MSUA36040B**	28,800	\$4,032
213078963	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MSUA36040B**	29,400	\$4,116
213080365	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96MSAA60100C**	29,200	\$4,088
213080353	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96MSAA60100C**	29,200	\$4,088
213080269	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG96MSAA60100C**	29,400	\$4,116
213078939	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MSUA60100C**	29,200	\$4,088
213078831	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MSUA60100C**	29,400	\$4,116
212988013	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96MSAA60100C**	29,000	\$4,060
213080305	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96MSAA60100C**	29,400	\$4,116
213080281	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG96MSAA60100C**	29,200	\$4,088
213078867	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MSUA60100C**	29,400	\$4,116
213078975	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80MSUA36040B**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712153	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG95ESAA60100C**	23,600	\$3,304
211712141	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ESUA60100C**	23,200	\$3,248
211712129	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG95ESUA60100C**	23,400	\$3,276
211712107	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3621AL*	PG80ESUA60100C**	23,600	\$3,304
211712095	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3621AL*	PG95ESUA60100C**	23,600	\$3,304
211468097	PAYNE HEATING AND COOLING	38MURAQ30AB3*	PF4MN*B30L*		23,400	\$3,276
213249336	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FEVA0036**+NAVA43601CK		29,400	\$4,116
213080874	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG95MSUA60080C**	29,200	\$4,088
213080862	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95MSUA60080C**	29,200	\$4,088
213080850	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG95MSUA60080C**	29,400	\$4,116
213080838	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG95MSUA60080C**	29,600	\$4,144
213080826	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95MSUA60080C**	29,200	\$4,088
213080814	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG95MSUA60080C**	29,400	\$4,116
213080802	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG95MSUA60080C**	29,400	\$4,116
213080790	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95MSUA60080C**	29,200	\$4,088
213080778	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95MSUA60080C**	29,400	\$4,116
213080766	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95MSUA48060B**	29,200	\$4,088
213080754	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG95MSUA48060B**	29,600	\$4,144
213080742	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG95MSUA48060B**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080706	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95MSUA48060B**	29,200	\$4,088
213080694	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG95MSUA48060B**	29,400	\$4,116
213080682	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95MSUA48060B**	29,200	\$4,088
213080670	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG95MSUA48060B**	29,400	\$4,116
213080658	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95MSUA48060B**	29,400	\$4,116
213080646	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG95MSUA48060B**	29,600	\$4,144
213080634	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95MSUA36040B**	29,400	\$4,116
213080622	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG95MSUA36040B**	29,600	\$4,144
213080610	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG95MSUA36040B**	29,400	\$4,116
213080574	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95MSUA36040B**	29,200	\$4,088
213080562	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95MSUA36040B**	29,200	\$4,088
213080550	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG95MSUA36040B**	29,600	\$4,144
211274896	PAYNE HEATING AND COOLING	38MURAQ30AB3*	FV4CN(B,F)005L		23,000	\$3,220
213080538	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95MSUA36040B**	29,200	\$4,088
213080526	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG95MSUA36040B**	29,400	\$4,116
213080514	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95MSUA36040B**	29,600	\$4,144
213080502	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG95MSUA36040B**	29,600	\$4,144
213080492	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96MSAA66140D**	29,200	\$4,088
213080482	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96MSAA66140D**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080470	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96MSAA66120D**	29,200	\$4,088
213080458	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96MSAA66120D**	29,400	\$4,116
213080257	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96MSAA60080C**	29,200	\$4,088
213080245	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96MSAA60080C**	29,200	\$4,088
213080233	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG96MSAA60080C**	29,400	\$4,116
213080209	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96MSAA60080C**	29,000	\$4,060
213080197	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96MSAA60080C**	29,000	\$4,060
213080185	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG96MSAA60080C**	29,200	\$4,088
213080173	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96MSAA60080C**	29,400	\$4,116
213080161	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96MSAA60080C**	29,400	\$4,116
213080149	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG96MSAA60080C**	29,200	\$4,088
213080137	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG96MSAA60080C**	29,600	\$4,144
213080125	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96MSAA48080B**	29,200	\$4,088
213080113	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG96MSAA48080B**	29,600	\$4,144
213080101	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG96MSAA48080B**	29,400	\$4,116
213080065	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96MSAA48080B**	29,000	\$4,060
213080053	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG96MSAA48080B**	29,200	\$4,088
213080041	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96MSAA48080B**	29,400	\$4,116
213080029	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG96MSAA48080B**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080017	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG96MSAA48080B**	29,400	\$4,116
213080005	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG96MSAA48080B**	29,600	\$4,144
213079993	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG96MSAA48080B**	29,600	\$4,144
213079983	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG96MSAA36060A**	29,600	\$4,144
213079963	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG96MSAA36060A**	29,400	\$4,116
213079953	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG96MSAA36060A**	29,600	\$4,144
213079942	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG92MSAA60120D**	29,200	\$4,088
213079931	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG92MSAA60120D**	29,000	\$4,060
213079920	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG92MSAA60120D**	29,400	\$4,116
213079827	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG92MSAA60100C**	29,200	\$4,088
213079815	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG92MSAA60100C**	29,200	\$4,088
213079803	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG92MSAA60100C**	29,400	\$4,116
213079791	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG92MSAA60100C**	29,600	\$4,144
213079779	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG92MSAA60100C**	29,000	\$4,060
213079767	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG92MSAA60100C**	29,400	\$4,116
213079755	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG92MSAA60100C**	29,400	\$4,116
213079743	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG92MSAA60100C**	29,000	\$4,060
213079731	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG92MSAA60100C**	29,400	\$4,116
213079721	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG92MSAA60080C**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079711	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG92MSAA60080C**	29,200	\$4,088
213079701	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG92MSAA60080C**	29,400	\$4,116
213079691	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG92MSAA60080C**	29,600	\$4,144
213079681	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG92MSAA60080C**	29,200	\$4,088
213079671	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG92MSAA60080C**	29,400	\$4,116
213079661	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG92MSAA60080C**	29,400	\$4,116
213079651	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG92MSAA60080C**	29,200	\$4,088
213079641	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG92MSAA60080C**	29,400	\$4,116
213079629	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG92MSAA48080B**	29,200	\$4,088
213079617	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG92MSAA48080B**	29,400	\$4,116
213079605	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG92MSAA48080B**	29,200	\$4,088
213079569	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG92MSAA48080B**	29,000	\$4,060
213079557	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG92MSAA48080B**	29,400	\$4,116
213079545	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG92MSAA48080B**	29,000	\$4,060
213079533	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG92MSAA48080B**	29,400	\$4,116
213079521	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG92MSAA48080B**	29,400	\$4,116
213079509	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG92MSAA48080B**	29,400	\$4,116
213079497	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG92MSAA42060B**	29,200	\$4,088
213079485	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG92MSAA42060B**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079473	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG92MSAA42060B**	29,400	\$4,116
213079437	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG92MSAA42060B**	29,200	\$4,088
213079425	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG92MSAA42060B**	29,400	\$4,116
213079411	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG92MSAA42060B**	29,200	\$4,088
213079399	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG92MSAA42060B**	29,400	\$4,116
213079387	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG92MSAA42060B**	29,400	\$4,116
213079375	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG92MSAA42060B**	29,400	\$4,116
213079365	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG92MSAA36060A**	29,400	\$4,116
213079345	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG92MSAA36060A**	29,400	\$4,116
213079335	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG92MSAA36060A**	29,600	\$4,144
213079191	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80MSUA48060B**	29,200	\$4,088
213079119	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80MSUA48060B**	29,200	\$4,088
213078915	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80MSUA60100C**	29,400	\$4,116
213078891	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3617AL*	PG80MSUA60100C**	29,600	\$4,144
213078843	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80MSUA60100C**	29,400	\$4,116
213078819	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80MSUA60100C**	29,600	\$4,144
213078809	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80MS(A,L)A60155D**	29,200	\$4,088
213078799	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80MS(A,L)A60155D**	29,000	\$4,060
213078789	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80MS(A,L)A60155D**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078778	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80MS(A,L)A60135D**	29,200	\$4,088
213078767	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80MS(A,L)A60135D**	29,400	\$4,116
213078757	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80MS(A,L)A60110D**	29,200	\$4,088
213078747	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80MS(A,L)A60110D**	29,000	\$4,060
213078737	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80MS(A,L)A60110D**	29,400	\$4,116
213078725	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80MS(A,L)A60110C**	29,200	\$4,088
213078713	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MS(A,L)A60110C**	29,200	\$4,088
213078701	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MS(A,L)A60110C**	29,400	\$4,116
213078677	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80MS(A,L)A60110C**	29,000	\$4,060
213078665	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MS(A,L)A60110C**	29,000	\$4,060
213078653	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MS(A,L)A60110C**	29,000	\$4,060
213078641	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80MS(A,L)A60110C**	29,400	\$4,116
213078629	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MS(A,L)A60110C**	29,400	\$4,116
213078617	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MS(A,L)A60110C**	29,000	\$4,060
213078605	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MS(A,L)A60110C**	29,400	\$4,116
213078576	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80MS(A,L)A60090C**	29,200	\$4,088
213078565	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MS(A,L)A60090C**	29,200	\$4,088
213078554	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MS(A,L)A60090C**	29,400	\$4,116
213078532	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MS(A,L)A60090C**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078521	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80MS(A,L)A60090C**	29,400	\$4,116
213078510	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MS(A,L)A60090C**	29,400	\$4,116
213078499	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MS(A,L)A60090C**	29,200	\$4,088
213078488	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MS(A,L)A60090C**	29,400	\$4,116
213078477	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80MS(A,L)A48090C**	29,200	\$4,088
211712500	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80ES(A,L)A60110C**	23,600	\$3,304
213078466	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MS(A,L)A48090C**	29,200	\$4,088
213078455	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MS(A,L)A48090C**	29,400	\$4,116
213078433	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MS(A,L)A48090C**	29,000	\$4,060
211712487	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80ES(A,L)A60090C**	23,400	\$3,276
213078422	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80MS(A,L)A48090C**	29,400	\$4,116
213078411	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MS(A,L)A48090C**	29,400	\$4,116
213078400	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MS(A,L)A48090C**	29,000	\$4,060
211712474	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80ES(A,L)A48090C**	23,600	\$3,304
213078389	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MS(A,L)A48090C**	29,400	\$4,116
213078377	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MS(A,L)A42090B**	29,200	\$4,088
213078365	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MS(A,L)A42090B**	29,400	\$4,116
211712461	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80ES(A,L)A42090B**	23,400	\$3,276
213078353	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80MS(A,L)A42090B**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078317	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MS(A,L)A42090B**	29,000	\$4,060
213078305	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MS(A,L)A42090B**	29,400	\$4,116
213078293	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MS(A,L)A42090B**	29,000	\$4,060
213078281	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80MS(A,L)A42090B**	29,400	\$4,116
213078269	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MS(A,L)A42090B**	29,400	\$4,116
213078257	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80MS(A,L)A42090B**	29,400	\$4,116
213078247	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80MS(A,L)A48070C**	29,200	\$4,088
213078237	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MS(A,L)A48070C**	29,200	\$4,088
213078227	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MS(A,L)A48070C**	29,400	\$4,116
211712424	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80VTLA66110C**	23,400	\$3,276
213078207	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MS(A,L)A48070C**	29,000	\$4,060
213078197	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80MS(A,L)A48070C**	29,400	\$4,116
213078187	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MS(A,L)A48070C**	29,400	\$4,116
213078177	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MS(A,L)A48070C**	29,000	\$4,060
213078167	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MS(A,L)A48070C**	29,400	\$4,116
213078155	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MS(A,L)A48070B**	29,200	\$4,088
213078143	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MS(A,L)A48070B**	29,400	\$4,116
213078131	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80MS(A,L)A48070B**	29,400	\$4,116
213078119	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG80MS(A,L)A48070B**	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078107	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3617AL*	PG80MS(A,L)A48070B**	29,600	\$4,144
213078095	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MS(A,L)A48070B**	29,200	\$4,088
213078083	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MS(A,L)A48070B**	29,400	\$4,116
213078071	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MS(A,L)A48070B**	29,200	\$4,088
213078059	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80MS(A,L)A48070B**	29,400	\$4,116
213078047	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MS(A,L)A48070B**	29,400	\$4,116
213078035	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80MS(A,L)A48070B**	29,600	\$4,144
213078024	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80MS(A,L)A36070B**	29,200	\$4,088
213078013	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80MS(A,L)A36070B**	29,400	\$4,116
213078002	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80MS(A,L)A36070B**	29,400	\$4,116
213077969	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80MS(A,L)A36070B**	29,000	\$4,060
211712379	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80VTLA48070B**	23,400	\$3,276
213077958	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80MS(A,L)A36070B**	29,400	\$4,116
213077947	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80MS(A,L)A36070B**	29,000	\$4,060
213077936	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80MS(A,L)A36070B**	29,400	\$4,116
213077925	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80MS(A,L)A36070B**	29,400	\$4,116
213077914	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80MS(A,L)A36070B**	29,400	\$4,116
211712367	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG95ESAA60100C**	23,600	\$3,304
213077902	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80MS(A,L)A36070A**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712537	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG92ESAA60080C**	23,400	\$3,276
213077878	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80MS(A,L)A36070A**	29,400	\$4,116
213077866	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80MS(A,L)A36070A**	29,400	\$4,116
213077854	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80MS(A,L)A36045A**	29,400	\$4,116
211712355	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG95ESAA60080C**	23,400	\$3,276
213077830	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80MS(A,L)A36045A**	29,400	\$4,116
213077817	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80MS(A,L)A36045A**	29,600	\$4,144
213077806	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96VTAB66120D**	29,200	\$4,088
213077794	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96VTAB66120D**	29,400	\$4,116
213077691	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96VTAB60100C**	29,200	\$4,088
213077678	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96VTAB60100C**	29,200	\$4,088
213077665	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG96VTAB60100C**	29,400	\$4,116
211712329	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80ESUA36040B**	23,400	\$3,276
213077639	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG96VTAB60100C**	29,000	\$4,060
213077626	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96VTAB60100C**	29,400	\$4,116
213077613	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96VTAB60100C**	29,400	\$4,116
211712549	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG92ESAA60100C**	23,400	\$3,276
213077600	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG96VTAB60100C**	29,000	\$4,060
213077587	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG96VTAB60100C**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077575	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96VTAB60080C**	29,200	\$4,088
213077564	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96VTAB60080C**	29,200	\$4,088
213077553	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG96VTAB60080C**	29,400	\$4,116
211712317	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80ESUA60100C**	23,600	\$3,304
213077542	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG96VTAB60080C**	29,600	\$4,144
213077531	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96VTAB60080C**	29,000	\$4,060
213077520	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG96VTAB60080C**	29,200	\$4,088
213077509	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96VTAB60080C**	29,400	\$4,116
213077498	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96VTAB60080C**	29,400	\$4,116
213077487	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG96VTAB60080C**	29,200	\$4,088
213077476	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG96VTAB60080C**	29,400	\$4,116
213077464	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96VTAB48080B**	29,200	\$4,088
213077451	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG96VTAB48080B**	29,600	\$4,144
213077438	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG96VTAB48080B**	29,400	\$4,116
211712293	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG95ESUA60100C**	23,600	\$3,304
213077399	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG96VTAB48080B**	29,200	\$4,088
213077386	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96VTAB48080B**	29,400	\$4,116
213077373	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG96VTAB48080B**	29,200	\$4,088
213077360	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG96VTAB48080B**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077347	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG96VTAB48080B**	29,400	\$4,116
213077334	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG96VTAB48080B**	29,600	\$4,144
213077322	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG96VTAB36060A**	29,400	\$4,116
211712561	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG95ESAA42060B**	23,600	\$3,304
213077300	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG96VTAB36060A**	29,400	\$4,116
213077289	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG96VTAB36060A**	29,600	\$4,144
213077278	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96VTAB36040B**	29,400	\$4,116
213077267	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96VTAB36040B**	29,200	\$4,088
211712230	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80ES(A,L)A48070B**	23,600	\$3,304
211213977	PAYNE HEATING AND COOLING	38MURAQ30AB3*	FV4CNF002L		23,600	\$3,304
211213975	PAYNE HEATING AND COOLING	38MURAQ30AB3*	FMA4X36**AL*		23,800	\$3,332
211213974	PAYNE HEATING AND COOLING	38MURAQ30AB3*	FMA4X30**AL*		23,800	\$3,332
211213973	PAYNE HEATING AND COOLING	38MURAQ30AB3*	FM(C,U)4Z36**AL*		23,600	\$3,304
211213972	PAYNE HEATING AND COOLING	38MURAQ30AB3*	FM(C,U)4Z30**AL*		23,600	\$3,304
211213970	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG96VTAA60100C**	23,200	\$3,248
211213969	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG96VTAA60080C**	23,000	\$3,220
211213968	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG96VTAA42060B**	23,200	\$3,248
211213967	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG95ESUA48060B**	23,400	\$3,276
211213966	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG95ESUA36040B**	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211213965	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG95ESAA60080C**	23,200	\$3,248
211213964	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG95ESAA42060B**	23,200	\$3,248
211213963	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG92ESAA60100C**	23,200	\$3,248
211213962	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG92ESAA60080C**	23,200	\$3,248
211213961	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG92ESAA48080B**	23,400	\$3,276
211213960	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG92ESAA42060B**	23,400	\$3,276
211213959	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80VTLA66110C**	23,200	\$3,248
211213958	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80VTLA60090C**	23,200	\$3,248
211213957	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80VTLA48090B**	23,200	\$3,248
211213956	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80VTLA48070B**	23,200	\$3,248
211213955	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ESUA60080C**	23,400	\$3,276
211213954	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ESUA48060B**	23,200	\$3,248
211213953	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ESUA36040B**	23,200	\$3,248
211213952	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ES(A,L)A60110C**	23,200	\$3,248
211213951	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ES(A,L)A60090C**	23,200	\$3,248
211213950	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ES(A,L)A48090C**	23,400	\$3,276
211213949	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ES(A,L)A42090B**	23,200	\$3,248
213076864	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80VTLB66135D**	32,600	\$4,564
213076861	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80VTLB66135D**	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211213948	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ES(A,L)A48070C**	23,200	\$3,248
211213947	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ES(A,L)A48070B**	23,400	\$3,276
213076849	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80VTLB66110C**	29,200	\$4,088
211213946	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ES(A,L)A36070B**	23,200	\$3,248
211213945	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG96VTAA42060B**	23,400	\$3,276
213076837	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80VTLB66110C**	29,200	\$4,088
211213944	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG95ESUA48060B**	23,400	\$3,276
211213943	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG95ESUA36040B**	23,400	\$3,276
213076825	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80VTLB66110C**	29,400	\$4,116
211213942	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG95ESAA42060B**	23,400	\$3,276
211213941	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG92ESAA48080B**	23,400	\$3,276
211213940	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG92ESAA42060B**	23,400	\$3,276
211213939	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG92ESAA36060A**	23,400	\$3,276
213076801	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80VTLB66110C**	29,000	\$4,060
211213938	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80VTLA48090B**	23,400	\$3,276
211213937	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80VTLA48070B**	23,200	\$3,248
213076789	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80VTLB66110C**	29,000	\$4,060
211213936	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80VTLA36070A**	23,400	\$3,276
211712585	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80ESUA48060B**	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211213935	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80VTLA36045A**	23,400	\$3,276
213076777	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80VTLB66110C**	29,200	\$4,088
211213934	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80ESUA48060B**	23,400	\$3,276
211213933	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80ESUA36040B**	23,400	\$3,276
211213932	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80ES(A,L)A42090B**	23,200	\$3,248
213076765	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80VTLB66110C**	29,400	\$4,116
211213931	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80ES(A,L)A48070B**	23,400	\$3,276
213076753	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80VTLB66110C**	29,400	\$4,116
211213930	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80ES(A,L)A36045A**	23,400	\$3,276
213076741	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80VTLB66110C**	29,200	\$4,088
213076729	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80VTLB66110C**	29,400	\$4,116
213076718	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80VTLB60090C**	29,200	\$4,088
211213923	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3621AL*	PG92ESAA60100C**	23,400	\$3,276
211213922	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3621AL*	PG92ESAA60080C**	23,400	\$3,276
213076707	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80VTLB60090C**	29,200	\$4,088
213076696	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80VTLB60090C**	29,400	\$4,116
213076685	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG80VTLB60090C**	29,600	\$4,144
213076674	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80VTLB60090C**	29,200	\$4,088
213076663	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80VTLB60090C**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076652	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80VTLB60090C**	29,400	\$4,116
211213912	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3621AL*	PG80ES(A,L)A60110C**	23,600	\$3,304
213076641	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80VTLB60090C**	29,200	\$4,088
211213910	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3621AL*	PG80ES(A,L)A48090C**	23,600	\$3,304
211712165	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80ES(A,L)A36045B**	23,400	\$3,276
213076630	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80VTLB60090C**	29,400	\$4,116
213076626	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80VTLB48090B**	29,200	\$4,088
213076622	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80VTLB48090B**	29,400	\$4,116
213076618	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80VTLB48090B**	29,400	\$4,116
213076606	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80VTLB48090B**	29,000	\$4,060
213076602	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80VTLB48090B**	29,400	\$4,116
213076598	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80VTLB48090B**	29,000	\$4,060
213076594	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80VTLB48090B**	29,400	\$4,116
213076590	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80VTLB48090B**	29,400	\$4,116
213076586	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80VTLB48090B**	29,400	\$4,116
213076575	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80VTLB48070B**	29,200	\$4,088
213076564	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80VTLB48070B**	29,400	\$4,116
213076553	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80VTLB48070B**	29,400	\$4,116
213076520	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80VTLB48070B**	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076509	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80VTLB48070B**	29,400	\$4,116
211213867	PAYNE HEATING AND COOLING	38MURAQ30AB3*	FJ4DN*B30L*		23,400	\$3,276
213076498	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80VTLB48070B**	29,000	\$4,060
213076487	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80VTLB48070B**	29,400	\$4,116
213076476	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80VTLB48070B**	29,400	\$4,116
213076465	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80VTLB48070B**	29,400	\$4,116
213076445	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80VTLB36045A**	29,400	\$4,116
213076421	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80VTLB36045A**	29,200	\$4,088
213076409	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80VTLB36045A**	29,400	\$4,116
211712698	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG95ESUA60100C**	23,600	\$3,304
211712710	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80ESUA60100C**	23,600	\$3,304
213075996	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG95MSUA60100C**	29,200	\$4,088
213075984	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95MSUA60100C**	29,200	\$4,088
213075972	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG95MSUA60100C**	29,400	\$4,116
213075948	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG95MSUA60100C**	29,000	\$4,060
213075936	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95MSUA60100C**	29,000	\$4,060
213075924	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95MSUA60100C**	29,000	\$4,060
213075912	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG95MSUA60100C**	29,400	\$4,116
213075900	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG95MSUA60100C**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213075888	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95MSUA60100C**	29,000	\$4,060
213075876	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95MSUA60100C**	29,400	\$4,116
212989503	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG95MSUA60080C**	29,000	\$4,060
211712736	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG95ESAA60080C**	23,400	\$3,276
212989491	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95MSUA60080C**	29,000	\$4,060
212988975	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95MSUA48060B**	29,000	\$4,060
212988403	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96MSAA66140D**	29,000	\$4,060
212988319	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96MSAA66120D**	29,000	\$4,060
211712748	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG95ESAA60100C**	23,600	\$3,304
212985241	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG92MSAA60100C**	28,800	\$4,032
212985229	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG92MSAA60100C**	28,800	\$4,032
212984951	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG92MSAA60080C**	28,800	\$4,032
212984941	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG92MSAA60080C**	28,800	\$4,032
212984411	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG92MSAA48080B**	29,000	\$4,060
212983871	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG92MSAA42060B**	29,000	\$4,060
212982602	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80MSUA48060B**	28,800	\$4,032
212981208	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80MS(A,L)A60135D**	29,000	\$4,060
212980488	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80MS(A,L)A60090C**	29,000	\$4,060
212980477	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MS(A,L)A60090C**	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980169	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80MS(A,L)A48090C**	28,800	\$4,032
212980158	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MS(A,L)A48090C**	28,800	\$4,032
212979655	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MS(A,L)A42090B**	29,000	\$4,060
212979413	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80MS(A,L)A48070C**	28,800	\$4,032
212979403	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MS(A,L)A48070C**	28,800	\$4,032
212978965	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MS(A,L)A48070B**	29,000	\$4,060
212978479	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80MS(A,L)A36070B**	29,000	\$4,060
212977253	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96VTAB66120D**	29,000	\$4,060
211712794	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80VTLA66110C**	23,400	\$3,276
212976808	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96VTAB60100C**	29,000	\$4,060
212976795	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96VTAB60100C**	29,000	\$4,060
212976526	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96VTAB60080C**	28,800	\$4,032
212976300	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96VTAB48080B**	29,000	\$4,060
212972643	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80VTLB66135D**	29,200	\$4,088
212972243	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80VTLB60090C**	29,000	\$4,060
212972232	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80VTLB60090C**	29,000	\$4,060
212972069	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80VTLB48090B**	29,000	\$4,060
211712818	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80ES(A,L)A48090C**	23,600	\$3,304
212971876	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80VTLB48070B**	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712831	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80ES(A,L)A60090C**	23,400	\$3,276
211712844	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80ES(A,L)A60090D**	23,400	\$3,276
211712857	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80ES(A,L)A60110C**	23,600	\$3,304
212384852	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FV4CN(B,F)003L		29,400	\$4,116
211712870	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80ES(A,L)A60110D**	23,400	\$3,276
212384828	PAYNE HEATING AND COOLING	38MURAQ36AB3*	PF4MN*C42L*		29,200	\$4,088
212384827	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FJ4DN*C42L*		29,200	\$4,088
212384788	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG92ESAA48080B**	29,200	\$4,088
212384776	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ES(A,L)A48070B**	29,200	\$4,088
211712883	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80ES(A,L)A60135D**	23,600	\$3,304
212384724	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ESUA48060B**	29,400	\$4,116
212384712	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ESUA60080C**	29,600	\$4,144
212384700	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG95ESAA42060B**	29,400	\$4,116
212384688	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG92ESAA60100C**	29,400	\$4,116
212384676	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG92ESAA60080C**	29,400	\$4,116
211712896	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG92ESAA60080C**	23,400	\$3,276
212384664	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG92ESAA48080B**	29,400	\$4,116
212384652	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG92ESAA42060B**	29,400	\$4,116
212384639	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ES(A,L)A60110C**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384626	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ES(A,L)A48070C**	29,400	\$4,116
212384613	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ES(A,L)A36070B**	29,600	\$4,144
211712908	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG92ESAA60100C**	23,400	\$3,276
212384600	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ES(A,L)A36045B**	29,400	\$4,116
212384589	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80VTLA66110C**	29,400	\$4,116
212384578	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG96VTAA60080C**	29,600	\$4,144
212384567	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80VTLA48070B**	29,400	\$4,116
212384555	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG95ESAA60080C**	29,600	\$4,144
212384544	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80VTLA60090C**	29,400	\$4,116
212384541	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80VTLA48090B**	29,400	\$4,116
212384529	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ESUA60100C**	29,400	\$4,116
212384517	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG95ESUA48060B**	29,400	\$4,116
211713015	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG95ESUA36040B**	23,200	\$3,248
211713027	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ES(A,L)A48070B**	23,400	\$3,276
211713090	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG95ESUA60100C**	23,400	\$3,276
211713102	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG95ESUA48060B**	23,400	\$3,276
211713114	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ESUA60100C**	23,400	\$3,276
211713126	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ESUA36040B**	23,200	\$3,248
213607814	PAYNE HEATING AND COOLING	38MURAQ60AB3*	PF4TNBD60L*		37,400	\$5,236

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713138	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80VTLA48090B**	23,000	\$3,220
211713141	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80VTLA60090C**	23,200	\$3,248
211713152	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG95ESAA60080C**	23,200	\$3,248
211713164	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG95ESAA60100C**	23,600	\$3,304
211713176	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80VTLA48070B**	23,200	\$3,248
211713188	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG96VTAA42060B**	23,200	\$3,248
211713199	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG96VTAA60080C**	23,000	\$3,220
211713210	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG96VTAA60100C**	23,200	\$3,248
211713221	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80VTLA66110C**	23,200	\$3,248
211713232	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ES(A,L)A36045B**	23,400	\$3,276
212384505	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG95ESUA60100C**	29,400	\$4,116
211713245	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ES(A,L)A36070B**	23,200	\$3,248
212384433	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ES(A,L)A48070B**	29,400	\$4,116
211713258	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ES(A,L)A48070C**	23,200	\$3,248
212384351	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80ESUA48060B**	29,400	\$4,116
212384338	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80ES(A,L)A36070A**	29,400	\$4,116
211713271	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ES(A,L)A42090B**	23,200	\$3,248
212384326	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG92ESAA48080B**	29,200	\$4,088
212384314	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG92ESAA42060B**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384302	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG92ESAA36060A**	29,400	\$4,116
212384289	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80ES(A,L)A42090B**	29,400	\$4,116
211713284	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ES(A,L)A48090C**	23,400	\$3,276
212384276	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80ES(A,L)A36070B**	29,400	\$4,116
212384263	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80ES(A,L)A36045B**	29,400	\$4,116
212384250	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80ES(A,L)A36045A**	29,600	\$4,144
212384247	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80VTLA48090B**	29,400	\$4,116
212384236	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80VTLA36045A**	29,400	\$4,116
211713297	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ES(A,L)A60090C**	23,200	\$3,248
212384204	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80ES(A,L)A48070B**	29,200	\$4,088
211713310	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ES(A,L)A60110C**	23,400	\$3,276
212384140	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG80ESUA60080C**	29,800	\$4,172
212384128	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG92ESAA60100C**	29,600	\$4,144
212384116	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*3621AL*	PG92ESAA60080C**	29,600	\$4,144
211713323	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG92ESAA42060B**	23,000	\$3,220
211713335	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG92ESAA48080B**	23,400	\$3,276
211713347	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG92ESAA60080C**	23,200	\$3,248
211713359	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG92ESAA60100C**	23,200	\$3,248
211713371	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG95ESAA42060B**	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713383	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ESUA60080C**	23,400	\$3,276
211713395	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80ESUA48060B**	23,200	\$3,248
212383482	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ES(A,L)A48070B**	29,000	\$4,060
212383470	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG92ESAA48080B**	29,000	\$4,060
212383458	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ES(A,L)A48070B**	29,200	\$4,088
212383436	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG92ESAA60100C**	29,200	\$4,088
212383425	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80VTLA60090C**	29,000	\$4,060
212383413	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95ESUA48060B**	29,200	\$4,088
212383401	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ES(A,L)A48070B**	29,200	\$4,088
212383389	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80ESUA48060B**	29,200	\$4,088
212383377	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ESUA48060B**	29,400	\$4,116
212383365	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ESUA60080C**	29,600	\$4,144
212383353	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG92ESAA60100C**	29,400	\$4,116
212383341	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG92ESAA60080C**	29,400	\$4,116
212383329	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG92ESAA48080B**	29,400	\$4,116
212383316	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ES(A,L)A60090C**	29,400	\$4,116
212383303	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ES(A,L)A48090C**	29,400	\$4,116
212383290	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ES(A,L)A42090B**	29,600	\$4,144
212383277	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ES(A,L)A48070C**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383266	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80VTLA66110C**	29,600	\$4,144
212383255	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG96VTAA42060B**	29,600	\$4,144
212383243	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80VTLA48070B**	29,400	\$4,116
212383231	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95ESAA60080C**	29,600	\$4,144
212383220	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80VTLA60090C**	29,400	\$4,116
212383208	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95ESUA60100C**	29,400	\$4,116
212383166	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95ESUA60080C**	29,800	\$4,172
212383144	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ES(A,L)A48070B**	29,400	\$4,116
212383072	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80ESUA48060B**	29,600	\$4,144
212383059	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80ES(A,L)A36070A**	29,600	\$4,144
212383047	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG95ESAA42060B**	29,600	\$4,144
212383035	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG92ESAA48080B**	29,400	\$4,116
212383023	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG92ESAA42060B**	29,400	\$4,116
212383011	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG92ESAA36060A**	29,600	\$4,144
212382998	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80ES(A,L)A42090B**	29,600	\$4,144
212382985	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80ES(A,L)A36070B**	29,600	\$4,144
212382972	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80ES(A,L)A36045B**	29,600	\$4,144
212382959	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80ES(A,L)A36045A**	29,800	\$4,172
212382948	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG96VTAA42060B**	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212382936	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80VTLA48070B**	29,400	\$4,116
212382933	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80VTLA48090B**	29,400	\$4,116
212382930	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80VTLA36070A**	29,400	\$4,116
212382919	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80VTLA36045A**	29,600	\$4,144
212382907	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG95ESUA48060B**	29,400	\$4,116
212382875	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3617AL*	PG80ES(A,L)A48070B**	29,400	\$4,116
211468638	PAYNE HEATING AND COOLING	38MURAQ36AB3*	PF4MN*B36L*		29,400	\$4,116
211230927	PAYNE HEATING AND COOLING	38MURAQ36AB3*	PF4MNB049L		29,000	\$4,060
211230916	PAYNE HEATING AND COOLING	38MURAQ36AB3*	PF4MNB043L		29,000	\$4,060
211230895	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FV4CN(B,F)005L		28,600	\$4,004
211230884	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FMA4X36**AL*		29,600	\$4,144
211230862	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FM(C,U)4Z36**AL*		29,600	\$4,144
211230779	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96VTAA66120D**	29,200	\$4,088
211230760	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96VTAA60100C**	29,200	\$4,088
211230750	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG96VTAA60080C**	29,200	\$4,088
211230730	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG95ESUA60100C**	29,200	\$4,088
211230719	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG95ESUA60080C**	29,600	\$4,144
211230681	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG95ESAA66140D**	29,400	\$4,116
211230670	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG95ESAA66120D**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230650	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG95ESAA60100C**	29,200	\$4,088
211230639	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG95ESAA60080C**	29,400	\$4,116
211230628	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG92ESAA60120D**	29,200	\$4,088
211230608	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG92ESAA60100C**	29,200	\$4,088
211230597	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG92ESAA60080C**	29,000	\$4,060
211230577	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80VTLA66135D**	29,200	\$4,088
211230567	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80VTLA66110C**	29,200	\$4,088
211230557	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80VTLA60090C**	29,200	\$4,088
211230546	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ESUA60100C**	29,200	\$4,088
211230535	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ESUA60080C**	29,400	\$4,116
211230489	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ES(A,L)A60155D**	29,200	\$4,088
211230477	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ES(A,L)A60135D**	29,200	\$4,088
211230465	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ES(A,L)A60110D**	29,200	\$4,088
211230453	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ES(A,L)A60110C**	29,200	\$4,088
211230441	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ES(A,L)A60090D**	29,200	\$4,088
211230429	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ES(A,L)A60090C**	29,200	\$4,088
211230417	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ES(A,L)A48090C**	29,200	\$4,088
211230405	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4824AL*	PG80ES(A,L)A48070C**	29,200	\$4,088
211230332	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96VTAA60100C**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230322	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96VTAA60080C**	29,200	\$4,088
211230312	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG96VTAA42060B**	29,400	\$4,116
211230282	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95ESUA60100C**	29,200	\$4,088
211230271	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95ESUA60080C**	29,600	\$4,144
211230260	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95ESUA48060B**	29,200	\$4,088
211230195	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95ESAA60100C**	29,200	\$4,088
211230184	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95ESAA60080C**	29,400	\$4,116
211230173	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95ESAA48080B**	29,200	\$4,088
211230162	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG95ESAA42060B**	29,200	\$4,088
211230142	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG92ESAA60100C**	29,200	\$4,088
211230131	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG92ESAA60080C**	29,000	\$4,060
211230120	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG92ESAA42060B**	29,200	\$4,088
211230083	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80VTLA66110C**	29,200	\$4,088
211230073	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80VTLA60090C**	29,200	\$4,088
211230071	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80VTLA48090B**	29,200	\$4,088
211230061	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80VTLA48070B**	29,200	\$4,088
211230050	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ESUA60100C**	29,200	\$4,088
211230039	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ESUA60080C**	29,400	\$4,116
211230028	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ESUA48060B**	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230017	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ESUA36040B**	29,600	\$4,144
211229969	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ES(A,L)A60110C**	29,200	\$4,088
211229957	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ES(A,L)A60090C**	29,200	\$4,088
211229945	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ES(A,L)A48090C**	29,200	\$4,088
211229933	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ES(A,L)A42090B**	29,200	\$4,088
211229921	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ES(A,L)A48070C**	29,200	\$4,088
211229909	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ES(A,L)A36070B**	29,400	\$4,116
211229897	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4821AL*	PG80ES(A,L)A36045B**	29,200	\$4,088
211229842	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG96VTAA60100C**	29,400	\$4,116
211229832	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG96VTAA42060B**	29,600	\$4,144
211229821	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG95ESAA60100C**	29,400	\$4,116
211229789	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ES(A,L)A60090C**	29,400	\$4,116
211229777	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ES(A,L)A48090C**	29,400	\$4,116
211229765	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4221AL*	PG80ES(A,L)A42090B**	29,400	\$4,116
211229746	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG96VTAA42060B**	29,400	\$4,116
211229735	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG95ESUA48060B**	29,200	\$4,088
211229688	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG95ESAA42060B**	29,400	\$4,116
211229669	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80VTLA48070B**	29,200	\$4,088
211229667	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CNPV*4217AL*	PG80VTLA36070A**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229621	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96VTAA66120D**	29,000	\$4,060
211714015	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*3621AL*	PG80ESUA60080C**	23,600	\$3,304
211229602	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96VTAA60100C**	29,000	\$4,060
211229592	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG96VTAA60080C**	28,800	\$4,032
211229572	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG95ESUA60100C**	29,000	\$4,060
211229561	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG95ESUA60080C**	29,400	\$4,116
211229523	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG95ESAA66140D**	29,200	\$4,088
211229512	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG95ESAA66120D**	29,200	\$4,088
211229492	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG95ESAA60100C**	29,000	\$4,060
211229481	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG95ESAA60080C**	29,200	\$4,088
211229470	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG92ESAA60120D**	29,000	\$4,060
211229450	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG92ESAA60100C**	28,800	\$4,032
211229439	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG92ESAA60080C**	28,800	\$4,032
211229419	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80VTLA66135D**	29,000	\$4,060
211229409	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80VTLA66110C**	29,000	\$4,060
211229399	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80VTLA60090C**	28,800	\$4,032
211714059	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG95ESUA36040B**	23,400	\$3,276
211229388	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ESUA60100C**	29,000	\$4,060
211229377	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ESUA60080C**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714071	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80ES(A,L)A48070B**	23,600	\$3,304
211229331	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ES(A,L)A60155D**	29,200	\$4,088
211229319	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ES(A,L)A60135D**	29,000	\$4,060
211229307	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ES(A,L)A60110D**	28,800	\$4,032
211229295	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ES(A,L)A60110C**	29,000	\$4,060
211229283	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ES(A,L)A60090D**	29,000	\$4,060
211229271	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ES(A,L)A60090C**	29,000	\$4,060
211229259	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ES(A,L)A48090C**	29,000	\$4,060
211229247	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4824AL*	PG80ES(A,L)A48070C**	28,800	\$4,032
211714103	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG95ESUA48060B**	23,600	\$3,304
211229174	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96VTAA60100C**	29,000	\$4,060
211229164	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96VTAA60080C**	29,000	\$4,060
211229154	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG96VTAA42060B**	29,200	\$4,088
211229134	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95ESUA60100C**	29,000	\$4,060
211714115	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80ESUA36040B**	23,400	\$3,276
211229123	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95ESUA60080C**	29,400	\$4,116
211229112	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95ESUA48060B**	29,000	\$4,060
211714127	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80VTLA36045A**	23,400	\$3,276
211229047	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95ESAA60100C**	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229036	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95ESAA60080C**	29,200	\$4,088
211229025	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95ESAA48080B**	29,000	\$4,060
211714138	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80VTLA36070A**	23,200	\$3,248
211229014	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG95ESAA42060B**	29,000	\$4,060
211714141	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80VTLA48090B**	23,400	\$3,276
211228994	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG92ESAA60100C**	28,800	\$4,032
211714144	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80VTLA48070B**	23,400	\$3,276
211228983	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG92ESAA60080C**	28,800	\$4,032
211228972	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG92ESAA48080B**	29,000	\$4,060
211228961	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG92ESAA42060B**	29,000	\$4,060
211228924	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80VTLA66110C**	29,000	\$4,060
211228914	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80VTLA60090C**	28,800	\$4,032
211228912	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80VTLA48090B**	29,000	\$4,060
211714156	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG96VTAA42060B**	23,400	\$3,276
211228902	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80VTLA48070B**	29,000	\$4,060
211228891	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ESUA60100C**	29,000	\$4,060
211228880	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ESUA60080C**	29,200	\$4,088
211228869	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ESUA48060B**	29,000	\$4,060
211228858	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ESUA36040B**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714167	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80ES(A,L)A36045A**	23,400	\$3,276
211228810	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ES(A,L)A60110C**	29,000	\$4,060
211228798	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ES(A,L)A60090C**	29,000	\$4,060
211714180	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80ES(A,L)A36070B**	23,400	\$3,276
211228786	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ES(A,L)A48090C**	29,000	\$4,060
211228774	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ES(A,L)A42090B**	29,000	\$4,060
211228762	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ES(A,L)A48070C**	28,800	\$4,032
211228750	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ES(A,L)A36070B**	29,000	\$4,060
211228738	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4821AL*	PG80ES(A,L)A36045B**	29,000	\$4,060
211714193	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80ES(A,L)A42090B**	23,400	\$3,276
211228647	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG96VTAA60100C**	29,200	\$4,088
211228637	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG96VTAA60080C**	29,200	\$4,088
211714206	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG92ESAA36060A**	23,400	\$3,276
211228627	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG96VTAA42060B**	29,200	\$4,088
211228597	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95ESUA60100C**	29,000	\$4,060
211714218	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG92ESAA42060B**	23,200	\$3,248
211228586	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95ESUA60080C**	29,400	\$4,116
211228575	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95ESUA48060B**	29,200	\$4,088
211714230	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG92ESAA48080B**	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228510	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95ESAA60100C**	29,200	\$4,088
211714242	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG95ESAA42060B**	23,400	\$3,276
211228499	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95ESAA60080C**	29,200	\$4,088
211228477	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG95ESAA42060B**	29,400	\$4,116
211228457	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG92ESAA60100C**	29,200	\$4,088
211714254	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80ES(A,L)A36070A**	23,200	\$3,248
211228446	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG92ESAA60080C**	29,200	\$4,088
211228435	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG92ESAA42060B**	29,000	\$4,060
211228398	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80VTLA66110C**	29,200	\$4,088
211714267	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80ESUA48060B**	23,400	\$3,276
211228388	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80VTLA60090C**	29,000	\$4,060
211228386	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80VTLA48090B**	29,000	\$4,060
211228376	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80VTLA48070B**	29,000	\$4,060
211228365	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ESUA60100C**	29,000	\$4,060
211228354	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ESUA60080C**	29,200	\$4,088
211228343	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ESUA48060B**	29,200	\$4,088
211228332	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ESUA36040B**	29,400	\$4,116
211228284	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ES(A,L)A60110C**	29,200	\$4,088
211228272	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ES(A,L)A60090C**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228260	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ES(A,L)A48090C**	29,000	\$4,060
211228248	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ES(A,L)A42090B**	29,200	\$4,088
211228236	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ES(A,L)A48070C**	29,200	\$4,088
211228224	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ES(A,L)A36070B**	29,200	\$4,088
211228212	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4321AL*	PG80ES(A,L)A36045B**	29,000	\$4,060
211714341	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80ES(A,L)A48070B**	23,600	\$3,304
211714404	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG95ESUA60100C**	23,600	\$3,304
211714416	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG95ESUA48060B**	23,600	\$3,304
211714428	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80ESUA60100C**	23,600	\$3,304
211714440	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80ESUA36040B**	23,400	\$3,276
211714466	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG95ESAA60080C**	23,400	\$3,276
211714478	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80VTLA48070B**	23,400	\$3,276
211714511	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80VTLA66110C**	23,400	\$3,276
211714535	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80ES(A,L)A48070C**	23,600	\$3,304
211714548	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80ES(A,L)A42090B**	23,400	\$3,276
211714561	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80ES(A,L)A48090C**	23,600	\$3,304
211714574	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80ES(A,L)A60090C**	23,400	\$3,276
211714587	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80ES(A,L)A60110C**	23,600	\$3,304
211714624	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG92ESAA60080C**	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714636	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG92ESAA60100C**	23,400	\$3,276
211714660	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80ESUA48060B**	23,400	\$3,276
211714684	PAYNE HEATING AND COOLING	38MURAQ30AB3*	FJ4DN*B36L*		23,400	\$3,276
211714685	PAYNE HEATING AND COOLING	38MURAQ30AB3*	PF4MN*B36L*		23,400	\$3,276
212971292	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80VTLB36045A**	23,400	\$3,276
212971340	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80VTLB36045A**	23,400	\$3,276
212971777	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80VTLB48070B**	23,400	\$3,276
212971788	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80VTLB48070B**	23,200	\$3,248
212971799	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80VTLB48070B**	23,600	\$3,304
212971810	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80VTLB48070B**	23,200	\$3,248
212971854	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80VTLB48070B**	23,400	\$3,276
212971865	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80VTLB48070B**	23,600	\$3,304
212972033	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80VTLB48090B**	23,400	\$3,276
212972037	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80VTLB48090B**	23,200	\$3,248
212972045	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80VTLB48090B**	23,200	\$3,248
212972061	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80VTLB48090B**	23,400	\$3,276
212972065	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80VTLB48090B**	23,600	\$3,304
212972166	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80VTLB60090C**	23,200	\$3,248
212972177	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80VTLB60090C**	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972188	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80VTLB60090C**	23,600	\$3,304
212972199	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80VTLB60090C**	23,200	\$3,248
212972221	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80VTLB60090C**	23,600	\$3,304
212972448	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80VTLB66110C**	23,400	\$3,276
212972460	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80VTLB66110C**	23,400	\$3,276
212972472	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80VTLB66110C**	23,400	\$3,276
212972484	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80VTLB66110C**	23,200	\$3,248
212972640	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80VTLB66135D**	29,400	\$4,116
212975762	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG96VTAB36060A**	23,600	\$3,304
212976177	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG96VTAB48080B**	23,400	\$3,276
212976190	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG96VTAB48080B**	23,400	\$3,276
212976216	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG96VTAB48080B**	23,200	\$3,248
212976268	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG96VTAB48080B**	23,400	\$3,276
212976443	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG96VTAB60080C**	23,200	\$3,248
212976458	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG96VTAB60080C**	23,400	\$3,276
212976472	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG96VTAB60080C**	23,400	\$3,276
212976486	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG96VTAB60080C**	23,200	\$3,248
212976513	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG96VTAB60080C**	23,600	\$3,304
212976717	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG96VTAB60100C**	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976730	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG96VTAB60100C**	23,600	\$3,304
212976743	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG96VTAB60100C**	23,600	\$3,304
212976756	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG96VTAB60100C**	23,200	\$3,248
212976782	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG96VTAB60100C**	23,600	\$3,304
212977241	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG96VTAB66120D**	23,600	\$3,304
212977516	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80MS(A,L)A36045A**	23,400	\$3,276
212977552	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80MS(A,L)A36045A**	23,400	\$3,276
212978020	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80MS(A,L)A36070A**	23,400	\$3,276
212978068	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80MS(A,L)A36070A**	23,400	\$3,276
212978523	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80MS(A,L)A36070B**	23,400	\$3,276
212978534	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MS(A,L)A36070B**	23,200	\$3,248
212978545	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80MS(A,L)A36070B**	23,400	\$3,276
212978556	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MS(A,L)A36070B**	23,200	\$3,248
212978600	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80MS(A,L)A36070B**	23,400	\$3,276
212978611	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80MS(A,L)A36070B**	23,400	\$3,276
212979013	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80MS(A,L)A48070B**	23,400	\$3,276
212979025	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MS(A,L)A48070B**	23,200	\$3,248
212979037	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80MS(A,L)A48070B**	23,600	\$3,304
212979049	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MS(A,L)A48070B**	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979097	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80MS(A,L)A48070B**	23,400	\$3,276
212979109	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80MS(A,L)A48070B**	23,600	\$3,304
212979433	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MS(A,L)A48070C**	23,200	\$3,248
212979443	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80MS(A,L)A48070C**	23,400	\$3,276
212979453	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80MS(A,L)A48070C**	23,400	\$3,276
212979463	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MS(A,L)A48070C**	23,200	\$3,248
212979703	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80MS(A,L)A42090B**	23,400	\$3,276
212979715	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MS(A,L)A42090B**	23,200	\$3,248
212979727	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80MS(A,L)A42090B**	23,400	\$3,276
212979739	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MS(A,L)A42090B**	23,200	\$3,248
212979787	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80MS(A,L)A42090B**	23,400	\$3,276
212980191	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MS(A,L)A48090C**	23,200	\$3,248
212980224	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MS(A,L)A48090C**	23,200	\$3,248
212980246	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80MS(A,L)A48090C**	23,600	\$3,304
212980510	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MS(A,L)A60090C**	23,200	\$3,248
212980521	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80MS(A,L)A60090C**	23,600	\$3,304
212980543	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MS(A,L)A60090C**	23,200	\$3,248
212980565	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80MS(A,L)A60090C**	23,600	\$3,304
212980900	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3621AL*	PG80MS(A,L)A60110C**	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980912	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG80MS(A,L)A60110C**	23,200	\$3,248
212980924	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG80MS(A,L)A60110C**	23,600	\$3,304
212980936	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80MS(A,L)A60110C**	23,600	\$3,304
212980948	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG80MS(A,L)A60110C**	23,200	\$3,248
212980972	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG80MS(A,L)A60110C**	23,600	\$3,304
212981110	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80MS(A,L)A60110D**	23,400	\$3,276
212981219	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80MS(A,L)A60135D**	23,600	\$3,304
212981320	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80MS(A,L)A60155D**	23,400	\$3,276
212981582	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG80MSUA60100C**	23,400	\$3,276
212981666	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG80MSUA60100C**	23,400	\$3,276
212982650	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG80MSUA48060B**	23,400	\$3,276
212983468	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG92MSAA36060A**	23,400	\$3,276
212983498	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG92MSAA36060A**	23,600	\$3,304
212983919	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG92MSAA42060B**	23,400	\$3,276
212983931	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG92MSAA42060B**	23,200	\$3,248
212983955	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG92MSAA42060B**	23,200	\$3,248
212984003	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG92MSAA42060B**	23,400	\$3,276
212984459	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG92MSAA48080B**	23,400	\$3,276
212984471	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG92MSAA48080B**	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984483	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG92MSAA48080B**	23,400	\$3,276
212984495	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG92MSAA48080B**	23,200	\$3,248
212984543	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG92MSAA48080B**	23,400	\$3,276
212984971	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG92MSAA60080C**	23,200	\$3,248
212984981	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG92MSAA60080C**	23,400	\$3,276
212984991	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG92MSAA60080C**	23,400	\$3,276
212985001	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG92MSAA60080C**	23,200	\$3,248
212985021	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG92MSAA60080C**	23,600	\$3,304
212985265	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG92MSAA60100C**	23,200	\$3,248
212985277	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG92MSAA60100C**	23,400	\$3,276
212985289	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG92MSAA60100C**	23,400	\$3,276
212985301	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG92MSAA60100C**	23,600	\$3,304
212985325	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG92MSAA60100C**	23,600	\$3,304
212985614	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG92MSAA60120D**	23,400	\$3,276
212985745	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG96MSAA30026A**	23,600	\$3,304
212986849	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG96MSAA36060A**	23,600	\$3,304
212987257	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG96MSAA48080B**	23,400	\$3,276
212987269	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG96MSAA48080B**	23,200	\$3,248
212987293	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG96MSAA48080B**	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212987341	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG96MSAA48080B**	23,600	\$3,304
212987353	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG96MSAA48080B**	23,600	\$3,304
212987725	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG96MSAA60080C**	23,200	\$3,248
212987749	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG96MSAA60080C**	23,400	\$3,276
212987761	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG96MSAA60080C**	23,200	\$3,248
212988331	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG96MSAA66120D**	23,400	\$3,276
212988413	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG96MSAA66140D**	23,600	\$3,304
212988579	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG95MSUA36040B**	23,600	\$3,304
212988591	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG95MSUA36040B**	23,200	\$3,248
212988615	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG95MSUA36040B**	23,200	\$3,248
212988627	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG95MSUA36040B**	23,600	\$3,304
212989023	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3717AL*	PG95MSUA48060B**	23,400	\$3,276
212989035	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG95MSUA48060B**	23,200	\$3,248
212989047	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG95MSUA48060B**	23,600	\$3,304
212989059	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG95MSUA48060B**	23,200	\$3,248
212989107	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4217AL*	PG95MSUA48060B**	23,400	\$3,276
212989119	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG95MSUA48060B**	23,600	\$3,304
212989527	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**3721AL*	PG95MSUA60080C**	23,200	\$3,248
212989539	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4221AL*	PG95MSUA60080C**	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989551	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4224AL*	PG95MSUA60080C**	23,600	\$3,304
212989563	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CAP**4321AL*	PG95MSUA60080C**	23,200	\$3,248
212989587	PAYNE HEATING AND COOLING	38MURAQ30AB3*	CNPV*4221AL*	PG95MSUA60080C**	23,600	\$3,304
213249292	PAYNE HEATING AND COOLING	38MURAQ30AB3*	FEVA0036**+NAVA43601CK		23,600	\$3,304
211225661	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FJ4DN*B36L*		29,400	\$4,116
211226260	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ES(A,L)A36045B**	29,600	\$4,144
211226272	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ES(A,L)A36070B**	29,600	\$4,144
211226284	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ES(A,L)A60110C**	29,400	\$4,116
211226305	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80ESUA60100C**	29,400	\$4,116
211226316	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG80VTLA48090B**	29,400	\$4,116
211226327	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG92ESAA42060B**	29,400	\$4,116
211226347	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95ESAA42060B**	29,400	\$4,116
211226358	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95ESAA48080B**	29,400	\$4,116
211226369	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95ESAA60100C**	29,600	\$4,144
211226389	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG95ESUA48060B**	29,400	\$4,116
211226400	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG96VTAA60080C**	29,400	\$4,116
211226410	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3621AL*	PG96VTAA60100C**	29,600	\$4,144
211226483	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80ES(A,L)A36045A**	29,400	\$4,116
211226495	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80ES(A,L)A36070A**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226507	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80ES(A,L)A36070B**	29,400	\$4,116
211226519	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80ES(A,L)A48070B**	29,400	\$4,116
211226530	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80ES(A,L)A42090B**	29,200	\$4,088
211226580	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80VTLA36045A**	29,400	\$4,116
211226590	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80VTLA36070A**	29,200	\$4,088
211226592	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80VTLA48070B**	29,400	\$4,116
211226602	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG80VTLA48090B**	29,200	\$4,088
211226613	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG92ESAA36060A**	29,400	\$4,116
211226624	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG92ESAA42060B**	29,200	\$4,088
211226635	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG92ESAA48080B**	29,400	\$4,116
211226657	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG95ESAA42060B**	29,400	\$4,116
211226695	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG95ESUA48060B**	29,400	\$4,116
211226706	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3717AL*	PG96VTAA42060B**	29,400	\$4,116
211226791	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ES(A,L)A36070B**	29,200	\$4,088
211226803	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ES(A,L)A48070C**	29,200	\$4,088
211226815	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ES(A,L)A42090B**	29,200	\$4,088
211226827	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ES(A,L)A48090C**	29,000	\$4,060
211226839	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ES(A,L)A60090C**	29,200	\$4,088
211226851	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ES(A,L)A60110C**	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226899	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ESUA36040B**	29,400	\$4,116
211226910	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ESUA48060B**	29,200	\$4,088
211226921	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ESUA60080C**	29,400	\$4,116
211226932	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80ESUA60100C**	29,000	\$4,060
211226943	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80VTLA48070B**	29,000	\$4,060
211226953	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80VTLA48090B**	29,000	\$4,060
211226955	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG80VTLA66110C**	29,200	\$4,088
211226992	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG92ESAA42060B**	29,000	\$4,060
211227003	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG92ESAA48080B**	29,000	\$4,060
211227014	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG92ESAA60080C**	29,200	\$4,088
211227034	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95ESAA42060B**	29,400	\$4,116
211227056	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95ESAA60080C**	29,200	\$4,088
211227067	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95ESAA60100C**	29,200	\$4,088
211227132	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95ESUA60080C**	29,400	\$4,116
211227143	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG95ESUA60100C**	29,000	\$4,060
211227173	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG96VTAA42060B**	29,200	\$4,088
211227183	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG96VTAA60080C**	29,200	\$4,088
211227193	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**3721AL*	PG96VTAA60100C**	29,200	\$4,088
211227284	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ES(A,L)A36045B**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227296	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ES(A,L)A36070B**	29,400	\$4,116
211227308	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ES(A,L)A48070B**	29,400	\$4,116
211227319	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ES(A,L)A48070C**	29,400	\$4,116
211227331	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ES(A,L)A42090B**	29,400	\$4,116
211227343	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ES(A,L)A48090C**	29,400	\$4,116
211227355	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ES(A,L)A60090C**	29,400	\$4,116
211227367	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ES(A,L)A60110C**	29,400	\$4,116
211227426	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ESUA48060B**	29,200	\$4,088
211227437	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ESUA60080C**	29,600	\$4,144
211227448	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80ESUA60100C**	29,400	\$4,116
211227459	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80VTLA48070B**	29,400	\$4,116
211227469	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80VTLA48090B**	29,400	\$4,116
211227471	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80VTLA60090C**	29,400	\$4,116
211227481	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG80VTLA66110C**	29,400	\$4,116
211227509	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG92ESAA42060B**	29,400	\$4,116
211227520	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG92ESAA48080B**	29,400	\$4,116
211227531	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG92ESAA60080C**	29,200	\$4,088
211227542	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG92ESAA60100C**	29,200	\$4,088
211227562	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG95ESAA42060B**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227573	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG95ESAA60080C**	29,400	\$4,116
211227629	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG95ESUA48060B**	29,400	\$4,116
211227640	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG95ESUA60080C**	29,600	\$4,144
211227651	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG95ESUA60100C**	29,400	\$4,116
211227671	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96VTAA42060B**	29,600	\$4,144
211227681	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96VTAA48080B**	29,400	\$4,116
211227691	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96VTAA60080C**	29,400	\$4,116
211227701	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4221AL*	PG96VTAA60100C**	29,400	\$4,116
211227765	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ES(A,L)A48070C**	29,400	\$4,116
211227777	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ES(A,L)A48090C**	29,400	\$4,116
211227789	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ES(A,L)A60090C**	29,400	\$4,116
211227801	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ES(A,L)A60090D**	29,400	\$4,116
211227813	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ES(A,L)A60110C**	29,400	\$4,116
211227825	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ES(A,L)A60110D**	29,200	\$4,088
211227837	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ES(A,L)A60135D**	29,400	\$4,116
211227849	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ES(A,L)A60155D**	29,400	\$4,116
211227895	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ESUA60080C**	29,600	\$4,144
211227906	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80ESUA60100C**	29,400	\$4,116
211227917	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80VTLA60090C**	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227927	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80VTLA66110C**	29,400	\$4,116
211227937	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG80VTLA66135D**	29,400	\$4,116
211227957	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG92ESAA60080C**	29,200	\$4,088
211227968	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG92ESAA60100C**	29,200	\$4,088
211227988	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG92ESAA60120D**	29,400	\$4,116
211227999	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG95ESAA60080C**	29,400	\$4,116
211228010	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG95ESAA60100C**	29,400	\$4,116
211228030	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG95ESAA66120D**	29,600	\$4,144
211228041	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG95ESAA66140D**	29,600	\$4,144
211228079	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG95ESUA60080C**	29,600	\$4,144
211228090	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG95ESUA60100C**	29,400	\$4,116
211228110	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96VTAA60080C**	29,400	\$4,116
211228120	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96VTAA60100C**	29,400	\$4,116
211228139	PAYNE HEATING AND COOLING	38MURAQ36AB3*	CAP**4224AL*	PG96VTAA66120D**	29,400	\$4,116
213249270	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076398	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAB48060B**	19,400	\$2,716
213076372	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAB48060B**	19,400	\$2,716
213076116	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95MSUA60100C**	19,200	\$2,688
212989623	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95MSUA60080C**	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989611	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG95MSUA60080C**	18,600	\$2,604
212989599	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG95MSUA60080C**	19,100	\$2,674
212989251	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95MSUA48060B**	19,100	\$2,674
212989239	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95MSUA48060B**	19,100	\$2,674
212989227	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95MSUA48060B**	19,100	\$2,674
212989215	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95MSUA48060B**	19,400	\$2,716
212989203	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG95MSUA48060B**	18,700	\$2,618
212989191	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG95MSUA48060B**	18,900	\$2,646
212989179	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG95MSUA48060B**	19,100	\$2,674
212989167	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95MSUA48060B**	19,100	\$2,674
212989155	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95MSUA48060B**	19,100	\$2,674
212989143	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG95MSUA48060B**	18,600	\$2,604
212989131	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95MSUA48060B**	19,400	\$2,716
212988759	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95MSUA36040B**	19,200	\$2,688
212988747	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95MSUA36040B**	19,200	\$2,688
212988735	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95MSUA36040B**	19,200	\$2,688
212988723	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95MSUA36040B**	19,500	\$2,730
212988711	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG95MSUA36040B**	18,600	\$2,604
212988699	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG95MSUA36040B**	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988687	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG95MSUA36040B**	19,000	\$2,660
212988675	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95MSUA36040B**	19,100	\$2,674
212988663	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95MSUA36040B**	19,200	\$2,688
212988651	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG95MSUA36040B**	18,700	\$2,618
212988639	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95MSUA36040B**	19,500	\$2,730
212987821	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96MSAA60080C**	19,100	\$2,674
212987809	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG96MSAA60080C**	18,700	\$2,618
212987797	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96MSAA60080C**	19,100	\$2,674
212987485	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96MSAA48080B**	19,200	\$2,688
212987473	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96MSAA48080B**	19,200	\$2,688
212987461	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96MSAA48080B**	19,200	\$2,688
212987449	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96MSAA48080B**	19,500	\$2,730
212987437	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG96MSAA48080B**	19,800	\$2,772
212987425	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96MSAA48080B**	18,800	\$2,632
212987413	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96MSAA48080B**	19,000	\$2,660
212987401	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96MSAA48080B**	19,100	\$2,674
212987389	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96MSAA48080B**	19,200	\$2,688
212987377	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96MSAA48080B**	18,700	\$2,618
212987365	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96MSAA48080B**	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986969	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96MSAA36060A**	19,200	\$2,688
212986959	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96MSAA36060A**	19,200	\$2,688
212986949	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG96MSAA36060A**	19,200	\$2,688
212986939	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96MSAA36060A**	19,500	\$2,730
212986929	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG96MSAA36060A**	19,500	\$2,730
212986919	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96MSAA36060A**	18,800	\$2,632
212986909	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96MSAA36060A**	19,100	\$2,674
212986899	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96MSAA36060A**	19,100	\$2,674
212986889	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG96MSAA36060A**	19,200	\$2,688
212986879	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96MSAA36060A**	18,700	\$2,618
212986869	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96MSAA36060A**	19,400	\$2,716
212986859	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG96MSAA36060A**	19,400	\$2,716
212986645	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96MSAA36040B**	19,100	\$2,674
212986633	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96MSAA36040B**	19,100	\$2,674
212986621	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96MSAA36040B**	19,100	\$2,674
212986609	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96MSAA36040B**	19,700	\$2,758
211289629	PAYNE HEATING AND COOLING	38MURAQ60AB3*	FV4CNB006L		37,800	\$5,292
213607739	PAYNE HEATING AND COOLING	38MURAQ36AB3*	PF4TNXC48L*		28,800	\$4,032
213607724	PAYNE HEATING AND COOLING	38MURAQ36AB3*	PF4TNXC36L*		29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213607679	PAYNE HEATING AND COOLING	38MURAQ30AB3*	PF4TNXC36L*		23,600	\$3,304
213607649	PAYNE HEATING AND COOLING	38MURAQ24AB3*	PF4TNXB24L*		19,300	\$2,702
213607634	PAYNE HEATING AND COOLING	38MURAQ24AB3*	PF4TNXC36L*		19,100	\$2,674
213607589	PAYNE HEATING AND COOLING	38MURAQ18AB3*	PF4TNXB24L*		12,400	\$1,736
212986597	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG96MSAA36040B**	18,800	\$2,632
212986585	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96MSAA36040B**	19,000	\$2,660
212986573	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96MSAA36040B**	19,200	\$2,688
212986561	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96MSAA36040B**	19,200	\$2,688
212986549	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96MSAA36040B**	19,200	\$2,688
212986537	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96MSAA36040B**	18,900	\$2,646
212986525	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96MSAA36040B**	19,500	\$2,730
212986261	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96MSAA30040A**	19,200	\$2,688
212986141	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96MSAA30040A**	19,500	\$2,730
212986129	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG96MSAA30040A**	19,500	\$2,730
212985865	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96MSAA30026A**	19,000	\$2,660
212985855	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96MSAA30026A**	19,000	\$2,660
212985845	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG96MSAA30026A**	19,100	\$2,674
212985835	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96MSAA30026A**	19,500	\$2,730
212985825	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG96MSAA30026A**	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212985815	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96MSAA30026A**	18,800	\$2,632
212985805	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96MSAA30026A**	19,100	\$2,674
212985795	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96MSAA30026A**	19,100	\$2,674
212985785	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG96MSAA30026A**	19,200	\$2,688
212985775	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96MSAA30026A**	18,700	\$2,618
212985765	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96MSAA30026A**	19,500	\$2,730
212985755	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG96MSAA30026A**	19,500	\$2,730
212985361	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92MSAA60100C**	19,100	\$2,674
212985349	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG92MSAA60100C**	18,700	\$2,618
212985337	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92MSAA60100C**	19,100	\$2,674
212985051	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92MSAA60080C**	19,000	\$2,660
212985041	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG92MSAA60080C**	18,900	\$2,646
212985031	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92MSAA60080C**	19,000	\$2,660
212984687	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92MSAA48080B**	19,100	\$2,674
212984675	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG92MSAA48080B**	19,100	\$2,674
212984663	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG92MSAA48080B**	19,100	\$2,674
212984651	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG92MSAA48080B**	19,500	\$2,730
212984639	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG92MSAA48080B**	18,400	\$2,576
212984627	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG92MSAA48080B**	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984615	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92MSAA48080B**	19,000	\$2,660
212984603	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG92MSAA48080B**	19,000	\$2,660
212984591	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG92MSAA48080B**	19,100	\$2,674
212984579	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG92MSAA48080B**	18,500	\$2,590
212984567	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG92MSAA48080B**	19,300	\$2,702
212984147	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92MSAA42060B**	19,100	\$2,674
212984135	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG92MSAA42060B**	19,100	\$2,674
212984123	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG92MSAA42060B**	19,100	\$2,674
212984111	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG92MSAA42060B**	19,400	\$2,716
212984099	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG92MSAA42060B**	18,700	\$2,618
212984087	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG92MSAA42060B**	18,900	\$2,646
212984075	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92MSAA42060B**	19,100	\$2,674
212984063	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG92MSAA42060B**	19,100	\$2,674
212984051	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG92MSAA42060B**	19,100	\$2,674
212984039	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG92MSAA42060B**	18,700	\$2,618
212984027	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG92MSAA42060B**	19,400	\$2,716
212983618	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG92MSAA36060A**	19,200	\$2,688
212983608	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG92MSAA36060A**	19,200	\$2,688
212983598	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG92MSAA36060A**	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983588	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG92MSAA36060A**	19,500	\$2,730
212983578	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG92MSAA36060A**	19,500	\$2,730
212983568	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG92MSAA36060A**	19,000	\$2,660
212983558	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG92MSAA36060A**	19,200	\$2,688
212983548	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG92MSAA36060A**	19,200	\$2,688
212983538	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG92MSAA36060A**	19,200	\$2,688
212983528	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG92MSAA36060A**	18,800	\$2,632
212983518	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG92MSAA36060A**	19,500	\$2,730
212983508	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG92MSAA36060A**	19,500	\$2,730
212983241	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92MSAA36040B**	19,200	\$2,688
212983230	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG92MSAA36040B**	19,200	\$2,688
212983219	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG92MSAA36040B**	19,200	\$2,688
212983208	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG92MSAA36040B**	19,600	\$2,744
212983197	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG92MSAA36040B**	18,800	\$2,632
212983186	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG92MSAA36040B**	19,000	\$2,660
212983175	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92MSAA36040B**	19,200	\$2,688
212983164	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG92MSAA36040B**	19,200	\$2,688
212983153	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG92MSAA36040B**	19,300	\$2,702
212983142	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG92MSAA36040B**	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983131	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG92MSAA36040B**	19,500	\$2,730
212981810	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MSUA60100C**	19,100	\$2,674
212981798	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80MSUA60100C**	19,200	\$2,688
212981786	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80MSUA60100C**	19,200	\$2,688
212981774	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80MSUA60100C**	19,500	\$2,730
212981750	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80MSUA60100C**	18,800	\$2,632
212981738	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MSUA60100C**	19,100	\$2,674
212981726	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80MSUA60100C**	19,000	\$2,660
212981714	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80MSUA60100C**	19,100	\$2,674
212981702	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80MSUA60100C**	18,700	\$2,618
212981690	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80MSUA60100C**	19,500	\$2,730
212981008	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MS(A,L)A60110C**	19,100	\$2,674
212980996	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80MS(A,L)A60110C**	18,800	\$2,632
212980984	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MS(A,L)A60110C**	19,000	\$2,660
212980598	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MS(A,L)A60090C**	19,100	\$2,674
212980587	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80MS(A,L)A60090C**	18,600	\$2,604
212980576	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MS(A,L)A60090C**	19,100	\$2,674
212980279	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MS(A,L)A48090C**	19,100	\$2,674
212980268	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80MS(A,L)A48090C**	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980257	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MS(A,L)A48090C**	19,000	\$2,660
212979931	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MS(A,L)A42090B**	19,100	\$2,674
212979919	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80MS(A,L)A42090B**	19,100	\$2,674
212979907	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80MS(A,L)A42090B**	19,100	\$2,674
212979895	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80MS(A,L)A42090B**	19,500	\$2,730
212979883	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80MS(A,L)A42090B**	18,700	\$2,618
212979871	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80MS(A,L)A42090B**	18,700	\$2,618
212979859	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MS(A,L)A42090B**	19,100	\$2,674
212979847	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80MS(A,L)A42090B**	19,100	\$2,674
212979835	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80MS(A,L)A42090B**	19,100	\$2,674
212979823	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80MS(A,L)A42090B**	18,600	\$2,604
212979811	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80MS(A,L)A42090B**	19,400	\$2,716
212979513	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MS(A,L)A48070C**	19,200	\$2,688
212979503	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80MS(A,L)A48070C**	18,600	\$2,604
212979493	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MS(A,L)A48070C**	19,100	\$2,674
212979241	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MS(A,L)A48070B**	19,100	\$2,674
212979229	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80MS(A,L)A48070B**	19,100	\$2,674
212979217	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80MS(A,L)A48070B**	19,100	\$2,674
212979205	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80MS(A,L)A48070B**	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979193	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80MS(A,L)A48070B**	18,700	\$2,618
212979181	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80MS(A,L)A48070B**	18,700	\$2,618
212979169	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MS(A,L)A48070B**	19,100	\$2,674
212979157	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80MS(A,L)A48070B**	19,100	\$2,674
212979145	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80MS(A,L)A48070B**	19,100	\$2,674
212979133	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80MS(A,L)A48070B**	18,700	\$2,618
212978644	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80MS(A,L)A36070B**	19,000	\$2,660
212978633	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80MS(A,L)A36070B**	18,600	\$2,604
212978622	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80MS(A,L)A36070B**	19,400	\$2,716
212978212	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80MS(A,L)A36070A**	19,000	\$2,660
212978200	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80MS(A,L)A36070A**	19,000	\$2,660
212978188	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG80MS(A,L)A36070A**	19,100	\$2,674
212978176	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80MS(A,L)A36070A**	19,400	\$2,716
212978164	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG80MS(A,L)A36070A**	19,400	\$2,716
212978152	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80MS(A,L)A36070A**	18,700	\$2,618
212978140	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80MS(A,L)A36070A**	19,000	\$2,660
212978128	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80MS(A,L)A36070A**	19,100	\$2,674
212978116	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG80MS(A,L)A36070A**	19,100	\$2,674
212978104	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80MS(A,L)A36070A**	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978092	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80MS(A,L)A36070A**	19,400	\$2,716
212978080	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG80MS(A,L)A36070A**	19,300	\$2,702
212977696	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80MS(A,L)A36045A**	19,100	\$2,674
212977684	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80MS(A,L)A36045A**	19,100	\$2,674
212977672	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG80MS(A,L)A36045A**	19,000	\$2,660
212977660	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80MS(A,L)A36045A**	19,500	\$2,730
212977648	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG80MS(A,L)A36045A**	19,500	\$2,730
212977636	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80MS(A,L)A36045A**	18,700	\$2,618
212977624	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80MS(A,L)A36045A**	19,100	\$2,674
212977612	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80MS(A,L)A36045A**	19,100	\$2,674
212977600	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG80MS(A,L)A36045A**	19,100	\$2,674
212977588	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80MS(A,L)A36045A**	18,700	\$2,618
212977576	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80MS(A,L)A36045A**	19,400	\$2,716
212977564	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG80MS(A,L)A36045A**	19,400	\$2,716
212976691	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96VTAB60100C**	19,100	\$2,674
212976678	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG96VTAB60100C**	18,600	\$2,604
212976665	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96VTAB60100C**	19,000	\$2,660
212976416	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96VTAB60080C**	19,200	\$2,688
212976402	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG96VTAB60080C**	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976388	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96VTAB60080C**	19,100	\$2,674
212976125	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96VTAB48080B**	18,900	\$2,646
212976112	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96VTAB48080B**	18,900	\$2,646
212976099	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96VTAB48080B**	18,900	\$2,646
212976086	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAB48080B**	19,500	\$2,730
212976060	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96VTAB48080B**	19,000	\$2,660
212976047	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96VTAB48080B**	19,000	\$2,660
212976034	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96VTAB48080B**	19,000	\$2,660
212976021	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96VTAB48080B**	19,100	\$2,674
212976008	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96VTAB48080B**	18,800	\$2,632
212975995	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAB48080B**	19,500	\$2,730
212975751	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96VTAB36060A**	19,100	\$2,674
212975740	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96VTAB36060A**	19,100	\$2,674
212975729	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG96VTAB36060A**	19,000	\$2,660
212975718	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAB36060A**	19,500	\$2,730
212975707	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG96VTAB36060A**	19,500	\$2,730
212975696	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96VTAB36060A**	18,800	\$2,632
212975685	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96VTAB36060A**	19,100	\$2,674
212975674	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96VTAB36060A**	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975663	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG96VTAB36060A**	19,100	\$2,674
212975652	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96VTAB36060A**	18,600	\$2,604
212975641	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAB36060A**	19,400	\$2,716
212975630	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG96VTAB36060A**	19,400	\$2,716
212975366	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96VTAB36040B**	19,200	\$2,688
212975355	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96VTAB36040B**	19,200	\$2,688
212975344	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96VTAB36040B**	19,200	\$2,688
212975333	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAB36040B**	19,600	\$2,744
212975322	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG96VTAB36040B**	18,900	\$2,646
212975311	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96VTAB36040B**	18,900	\$2,646
212975300	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96VTAB36040B**	19,100	\$2,674
212975289	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96VTAB36040B**	19,100	\$2,674
212975278	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96VTAB36040B**	19,200	\$2,688
212975267	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96VTAB36040B**	18,800	\$2,632
212975256	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAB36040B**	19,500	\$2,730
212975057	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96VTAB30040A**	19,200	\$2,688
212975044	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96VTAB30040A**	19,200	\$2,688
212975031	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG96VTAB30040A**	19,100	\$2,674
212975018	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAB30040A**	19,600	\$2,744

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975005	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG96VTAB30040A**	19,600	\$2,744
212974992	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96VTAB30040A**	18,800	\$2,632
212974979	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96VTAB30040A**	19,200	\$2,688
212974966	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96VTAB30040A**	19,200	\$2,688
212974953	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG96VTAB30040A**	19,200	\$2,688
212974940	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96VTAB30040A**	18,700	\$2,618
212974927	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAB30040A**	19,500	\$2,730
212974914	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG96VTAB30040A**	19,500	\$2,730
212972424	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80VTLB66110C**	19,200	\$2,688
212972412	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80VTLB66110C**	18,800	\$2,632
212972400	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80VTLB66110C**	19,100	\$2,674
212972144	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80VTLB60090C**	19,100	\$2,674
212972133	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80VTLB60090C**	18,900	\$2,646
212972122	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80VTLB60090C**	19,100	\$2,674
212972017	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80VTLB48090B**	19,100	\$2,674
212972013	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80VTLB48090B**	19,100	\$2,674
212972009	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80VTLB48090B**	19,100	\$2,674
212972005	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80VTLB48090B**	19,500	\$2,730
212972001	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80VTLB48090B**	18,600	\$2,604

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971997	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80VTLB48090B**	18,800	\$2,632
212971993	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80VTLB48090B**	19,000	\$2,660
212971989	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80VTLB48090B**	19,000	\$2,660
212971985	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80VTLB48090B**	19,100	\$2,674
212971981	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80VTLB48090B**	18,700	\$2,618
212971977	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80VTLB48090B**	19,400	\$2,716
212971733	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80VTLB48070B**	19,100	\$2,674
212971722	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80VTLB48070B**	19,100	\$2,674
212971711	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80VTLB48070B**	19,100	\$2,674
212971700	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80VTLB48070B**	19,500	\$2,730
212971689	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80VTLB48070B**	18,700	\$2,618
212971678	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80VTLB48070B**	18,700	\$2,618
212971667	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80VTLB48070B**	19,100	\$2,674
212971656	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80VTLB48070B**	19,100	\$2,674
212971645	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80VTLB48070B**	19,100	\$2,674
212971634	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80VTLB48070B**	18,600	\$2,604
212971623	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80VTLB48070B**	19,400	\$2,716
212971244	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80VTLB36045A**	19,100	\$2,674
212971232	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80VTLB36045A**	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971220	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG80VTLB36045A**	19,000	\$2,660
212971208	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80VTLB36045A**	19,500	\$2,730
212971196	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG80VTLB36045A**	19,500	\$2,730
212971184	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80VTLB36045A**	18,700	\$2,618
212971172	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80VTLB36045A**	19,000	\$2,660
212971160	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80VTLB36045A**	19,100	\$2,674
211727052	PAYNE HEATING AND COOLING	38MURAQ24AB3*	PF4MN*B24L*		19,200	\$2,688
211245981	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FV4CN(B,F)003L		19,000	\$2,660
211245971	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FV4CNF002L		19,000	\$2,660
211245960	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FM(C,U)4Z36**AL*		19,300	\$2,702
211245949	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FM(C,U)4Z30**AL*		19,300	\$2,702
211245938	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FM(C,U)4Z24**AL*		19,500	\$2,730
211245927	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FM(C,U)4X36**AL*		19,900	\$2,786
211245916	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FM(C,U)4X30**AL*		19,900	\$2,786
211245905	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FMA4X36**AL*		19,600	\$2,744
211245894	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FMA4X30**AL*		19,600	\$2,744
211245883	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FMA4X24**AL*		19,600	\$2,744
211245861	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FMA4P24**AL*		19,900	\$2,786
211245850	PAYNE HEATING AND COOLING	38MURAQ24AB3*	PF4MNB037L		18,500	\$2,590

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245839	PAYNE HEATING AND COOLING	38MURAQ24AB3*	PF4MNB031L		19,100	\$2,674
211245828	PAYNE HEATING AND COOLING	38MURAQ24AB3*	PF4MNB025L		19,100	\$2,674
211245817	PAYNE HEATING AND COOLING	38MURAQ24AB3*	PF4MNP030L*		19,100	\$2,674
211245816	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FB4CNP030L		19,100	\$2,674
211245805	PAYNE HEATING AND COOLING	38MURAQ24AB3*	PF4MNP025L*		19,000	\$2,660
211245804	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FB4CNP025L		19,000	\$2,660
211245793	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FB4CNF030L		19,100	\$2,674
211245745	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ESUA48060B**	19,300	\$2,702
211245734	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ESUA60080C**	19,100	\$2,674
211245723	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92ESAA36040B**	19,100	\$2,674
211245712	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95ESAA48080B**	19,500	\$2,730
211245701	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95ESAA42060B**	19,400	\$2,716
211245690	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92ESAA60100C**	19,300	\$2,702
211245679	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92ESAA60080C**	19,300	\$2,702
211245668	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92ESAA48080B**	19,100	\$2,674
211245657	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG92ESAA42060B**	19,100	\$2,674
211245645	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ES(A,L)A60110C**	19,400	\$2,716
211245633	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ES(A,L)A60090C**	19,300	\$2,702
211245621	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ES(A,L)A42090B**	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245609	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ES(A,L)A48070C**	19,100	\$2,674
211245597	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ES(A,L)A36070B**	19,200	\$2,688
211245585	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ES(A,L)A36045B**	19,100	\$2,674
211245575	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80VTLA66110C**	19,000	\$2,660
211245565	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96VTAA60100C**	19,000	\$2,660
211245555	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96VTAA60080C**	18,900	\$2,646
211245545	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96VTAA42060B**	19,100	\$2,674
211245534	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95ESAA36040B**	19,400	\$2,716
211245524	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80VTLA48070B**	19,100	\$2,674
211245514	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96VTAA48080B**	19,100	\$2,674
211245503	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95ESAA60080C**	19,300	\$2,702
211245493	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG96VTAA36040B**	19,000	\$2,660
211245483	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80VTLA60090C**	19,000	\$2,660
211245481	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80VTLA48090B**	19,000	\$2,660
211245470	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ESUA36040B**	19,000	\$2,660
211245459	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95ESUA48060B**	19,100	\$2,674
211245367	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80ES(A,L)A48070B**	19,400	\$2,716
211245356	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG95ESUA36040B**	19,000	\$2,660
211245246	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80ESUA48060B**	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245234	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80ES(A,L)A36070A**	19,100	\$2,674
211245223	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG92ESAA36040B**	19,100	\$2,674
211245212	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG92ESAA30040A**	19,400	\$2,716
211245201	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95ESAA48080B**	19,500	\$2,730
211245190	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95ESAA42060B**	19,400	\$2,716
211245179	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG92ESAA48080B**	19,100	\$2,674
211245168	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG92ESAA42060B**	19,100	\$2,674
211245157	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG92ESAA36060A**	18,900	\$2,646
211245145	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80ES(A,L)A42090B**	19,200	\$2,688
211245133	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80ES(A,L)A36070B**	19,200	\$2,688
211245121	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80ES(A,L)A36045B**	19,100	\$2,674
211245109	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80ES(A,L)A36045A**	19,300	\$2,702
211245099	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96VTAA42060B**	19,100	\$2,674
211245088	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95ESAA30026A**	18,900	\$2,646
211245078	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96VTAA36060A**	19,000	\$2,660
211245068	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96VTAA30040A**	19,000	\$2,660
211245057	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95ESAA36060A**	19,400	\$2,716
211245046	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95ESAA36040B**	19,400	\$2,716
211245035	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95ESAA30040A**	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245025	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80VTLA48070B**	19,100	\$2,674
211245015	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96VTAA48080B**	19,100	\$2,674
211245005	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG96VTAA36040B**	19,000	\$2,660
211245003	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80VTLA48090B**	19,000	\$2,660
211245001	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80VTLA36070A**	19,100	\$2,674
211244991	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80VTLA36045A**	19,100	\$2,674
211244980	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80ESUA36040B**	19,000	\$2,660
211244969	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95ESUA48060B**	19,100	\$2,674
211244922	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80ES(A,L)A48070B**	19,400	\$2,716
211244911	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG95ESUA36040B**	19,000	\$2,660
211244810	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80ESUA48060B**	19,300	\$2,702
211244798	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80ES(A,L)A36070A**	19,100	\$2,674
211244787	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG92ESAA36040B**	19,100	\$2,674
211244776	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG92ESAA30040A**	19,400	\$2,716
211244765	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95ESAA48080B**	19,500	\$2,730
211244754	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95ESAA42060B**	19,400	\$2,716
211244743	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG92ESAA48080B**	19,100	\$2,674
211244732	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG92ESAA42060B**	19,100	\$2,674
211244721	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG92ESAA36060A**	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244709	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80ES(A,L)A42090B**	19,200	\$2,688
211244697	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80ES(A,L)A36070B**	19,200	\$2,688
211244685	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80ES(A,L)A36045B**	19,100	\$2,674
211244673	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80ES(A,L)A36045A**	19,300	\$2,702
211244663	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96VTAA42060B**	19,100	\$2,674
211244652	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95ESAA30026A**	18,900	\$2,646
211244642	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96VTAA36060A**	19,000	\$2,660
211244632	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96VTAA30040A**	19,000	\$2,660
211244621	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95ESAA36060A**	19,400	\$2,716
211244610	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95ESAA36040B**	19,400	\$2,716
211244599	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95ESAA30040A**	19,500	\$2,730
211244589	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80VTLA48070B**	19,100	\$2,674
211244579	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96VTAA48080B**	19,100	\$2,674
211244569	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96VTAA36040B**	19,000	\$2,660
211244567	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80VTLA48090B**	19,000	\$2,660
211244565	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80VTLA36070A**	19,100	\$2,674
211244555	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80VTLA36045A**	19,100	\$2,674
211244544	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80ESUA36040B**	19,000	\$2,660
211244533	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95ESUA48060B**	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244486	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80ES(A,L)A48070B**	19,400	\$2,716
211244475	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG95ESUA36040B**	19,000	\$2,660
211244400	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG80ES(A,L)A36070A**	19,100	\$2,674
211244389	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG92ESAA30040A**	19,400	\$2,716
211244378	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG92ESAA36060A**	18,900	\$2,646
211244366	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG80ES(A,L)A36045A**	19,300	\$2,702
211244355	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG95ESAA30026A**	19,500	\$2,730
211244345	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG96VTAA36060A**	19,000	\$2,660
211244335	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG96VTAA30040A**	19,100	\$2,674
211244324	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG95ESAA36060A**	19,400	\$2,716
211244313	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG95ESAA30040A**	19,500	\$2,730
211244311	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG80VTLA36070A**	19,100	\$2,674
211244301	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG80VTLA36045A**	19,100	\$2,674
211244236	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80ESUA48060B**	19,600	\$2,744
211244224	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80ES(A,L)A36070A**	19,500	\$2,730
211244213	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG92ESAA36040B**	19,500	\$2,730
211244202	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG92ESAA30040A**	19,700	\$2,758
211244191	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95ESAA48080B**	19,800	\$2,772
211244180	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95ESAA42060B**	19,700	\$2,758

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244169	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG92ESAA48080B**	19,400	\$2,716
211244158	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG92ESAA42060B**	19,500	\$2,730
211244147	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG92ESAA36060A**	19,600	\$2,744
211244135	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80ES(A,L)A42090B**	19,500	\$2,730
211244123	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80ES(A,L)A36070B**	19,500	\$2,730
211244111	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80ES(A,L)A36045B**	19,400	\$2,716
211244099	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80ES(A,L)A36045A**	19,600	\$2,744
211244089	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAA42060B**	19,400	\$2,716
211244078	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95ESAA30026A**	19,900	\$2,786
211244068	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAA36060A**	19,300	\$2,702
211244058	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAA30040A**	19,500	\$2,730
211244047	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95ESAA36060A**	19,700	\$2,758
211244036	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95ESAA36040B**	19,700	\$2,758
211244025	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95ESAA30040A**	19,800	\$2,772
211244015	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80VTLA48070B**	19,400	\$2,716
211244005	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAA48080B**	19,500	\$2,730
211243995	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96VTAA36040B**	19,700	\$2,758
211243993	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80VTLA48090B**	19,300	\$2,702
211243991	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80VTLA36070A**	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243981	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80VTLA36045A**	19,500	\$2,730
211243970	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80ESUA36040B**	19,300	\$2,702
211243959	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95ESUA48060B**	19,400	\$2,716
211243912	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80ES(A,L)A48070B**	19,700	\$2,758
211243901	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG95ESUA36040B**	19,300	\$2,702
211243826	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG80ES(A,L)A36070A**	19,500	\$2,730
211243815	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG92ESAA30040A**	19,700	\$2,758
211243804	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG92ESAA36060A**	19,600	\$2,744
211243792	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG80ES(A,L)A36045A**	19,600	\$2,744
211243781	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG95ESAA30026A**	19,900	\$2,786
211243771	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG96VTAA36060A**	19,300	\$2,702
211243761	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG96VTAA30040A**	19,500	\$2,730
211243750	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG95ESAA36060A**	19,700	\$2,758
211243739	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG95ESAA30040A**	19,800	\$2,772
211243737	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG80VTLA36070A**	19,500	\$2,730
211243727	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG80VTLA36045A**	19,500	\$2,730
211243483	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80VTLA66110C**	18,500	\$2,590
211243463	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG96VTAA60080C**	18,400	\$2,576
211243401	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG96VTAA36040B**	18,500	\$2,590

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243142	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80ES(A,L)A36070A**	18,900	\$2,646
211243131	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG92ESAA36040B**	18,900	\$2,646
211243087	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG92ESAA48080B**	18,900	\$2,646
211243076	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG92ESAA42060B**	18,900	\$2,646
211243029	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80ES(A,L)A36045B**	18,900	\$2,646
211243007	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96VTAA42060B**	18,900	\$2,646
211242986	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96VTAA36060A**	18,700	\$2,618
211242976	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96VTAA30040A**	18,900	\$2,646
211242933	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80VTLA48070B**	18,800	\$2,632
211242923	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96VTAA48080B**	18,900	\$2,646
211242911	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80VTLA48090B**	18,700	\$2,618
211242899	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80VTLA36045A**	18,900	\$2,646
211242888	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80ESUA36040B**	18,700	\$2,618
211242877	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG95ESUA48060B**	18,900	\$2,646
211242819	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG95ESUA36040B**	18,700	\$2,618
211242709	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ESUA48060B**	19,300	\$2,702
211242698	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ESUA60080C**	19,100	\$2,674
211242687	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92ESAA36040B**	19,100	\$2,674
211242676	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG95ESAA48080B**	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242665	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG95ESAA42060B**	19,300	\$2,702
211242654	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92ESAA60100C**	19,300	\$2,702
211242643	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92ESAA60080C**	19,300	\$2,702
211242632	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92ESAA48080B**	19,100	\$2,674
211242621	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG92ESAA42060B**	19,100	\$2,674
211242609	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ES(A,L)A60110C**	19,400	\$2,716
211242597	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ES(A,L)A60090C**	19,200	\$2,688
211242585	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ES(A,L)A42090B**	19,200	\$2,688
211242573	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ES(A,L)A48070C**	19,100	\$2,674
211242561	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ES(A,L)A36070B**	18,800	\$2,632
211242549	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ES(A,L)A36045B**	19,100	\$2,674
211242539	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80VTAA66110C**	18,900	\$2,646
211242529	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96VTAA60100C**	19,000	\$2,660
211242519	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96VTAA60080C**	18,900	\$2,646
211242509	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96VTAA42060B**	19,100	\$2,674
211242498	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG95ESAA36040B**	19,300	\$2,702
211242488	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80VTAA48070B**	19,000	\$2,660
211242478	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96VTAA48080B**	19,100	\$2,674
211242467	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG95ESAA60080C**	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242457	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG96VTAA36040B**	19,000	\$2,660
211242447	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80VTLA60090C**	19,000	\$2,660
211242445	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80VTLA48090B**	19,000	\$2,660
211242434	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ESUA36040B**	18,900	\$2,646
211242423	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG95ESUA48060B**	19,100	\$2,674
211242331	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80ES(A,L)A48070B**	19,400	\$2,716
211242320	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG95ESUA36040B**	18,900	\$2,646
211242210	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80ESUA48060B**	19,300	\$2,702
211242198	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80ES(A,L)A36070A**	19,100	\$2,674
211242187	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG92ESAA36040B**	19,100	\$2,674
211242176	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG92ESAA30040A**	19,400	\$2,716
211242165	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95ESAA48080B**	19,400	\$2,716
211242154	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95ESAA42060B**	19,300	\$2,702
211242143	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG92ESAA48080B**	19,100	\$2,674
211242132	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG92ESAA42060B**	19,100	\$2,674
211242121	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG92ESAA36060A**	18,800	\$2,632
211242109	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80ES(A,L)A42090B**	19,200	\$2,688
211242097	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80ES(A,L)A36070B**	19,200	\$2,688
211242085	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80ES(A,L)A36045B**	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242073	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80ES(A,L)A36045A**	19,300	\$2,702
211242063	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96VTAA42060B**	19,100	\$2,674
211242052	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95ESAA30026A**	18,900	\$2,646
211242042	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96VTAA36060A**	18,900	\$2,646
211242032	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96VTAA30040A**	18,900	\$2,646
211242021	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95ESAA36060A**	19,300	\$2,702
211242010	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95ESAA36040B**	19,300	\$2,702
211241999	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95ESAA30040A**	19,400	\$2,716
211241989	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80VTLA48070B**	19,000	\$2,660
211241979	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96VTAA48080B**	19,100	\$2,674
211241969	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96VTAA36040B**	18,900	\$2,646
211241967	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80VTLA48090B**	18,900	\$2,646
211241965	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80VTLA36070A**	19,100	\$2,674
211241955	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80VTLA36045A**	19,100	\$2,674
211241944	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80ESUA36040B**	18,900	\$2,646
211241933	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95ESUA48060B**	19,100	\$2,674
211241886	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80ES(A,L)A48070B**	19,400	\$2,716
211241875	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG95ESUA36040B**	18,900	\$2,646
211241774	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80ESUA48060B**	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241762	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80ES(A,L)A36070A**	19,200	\$2,688
211241751	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG92ESAA36040B**	19,100	\$2,674
211241740	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG92ESAA30040A**	19,400	\$2,716
211241729	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95ESAA48080B**	19,500	\$2,730
211241718	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95ESAA42060B**	19,400	\$2,716
211241707	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG92ESAA48080B**	19,100	\$2,674
211241696	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG92ESAA42060B**	19,200	\$2,688
211241685	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG92ESAA36060A**	18,900	\$2,646
211241673	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80ES(A,L)A42090B**	19,200	\$2,688
211241661	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80ES(A,L)A36070B**	19,200	\$2,688
211241649	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80ES(A,L)A36045B**	19,100	\$2,674
211241637	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80ES(A,L)A36045A**	19,400	\$2,716
211241627	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96VTAA42060B**	19,100	\$2,674
211241616	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95ESAA30026A**	18,900	\$2,646
211241606	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96VTAA36060A**	19,000	\$2,660
211241596	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96VTAA30040A**	19,000	\$2,660
211241585	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95ESAA36060A**	19,400	\$2,716
211241574	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95ESAA36040B**	19,400	\$2,716
211241563	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95ESAA30040A**	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241553	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80VTLA48070B**	19,100	\$2,674
211241543	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96VTAA48080B**	19,200	\$2,688
211241533	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96VTAA36040B**	19,000	\$2,660
211241531	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80VTLA48090B**	19,000	\$2,660
211241529	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80VTLA36070A**	19,200	\$2,688
211241519	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80VTLA36045A**	19,200	\$2,688
211241508	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80ESUA36040B**	19,000	\$2,660
211241497	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95ESUA48060B**	19,100	\$2,674
211241450	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG80ES(A,L)A48070B**	19,400	\$2,716
211241439	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG95ESUA36040B**	19,000	\$2,660
211241364	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG80ES(A,L)A36070A**	19,200	\$2,688
211241353	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG92ESAA30040A**	19,400	\$2,716
211241342	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG92ESAA36060A**	18,900	\$2,646
211241330	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG80ES(A,L)A36045A**	19,300	\$2,702
211241319	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG95ESAA30026A**	19,600	\$2,744
211241309	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG96VTAA36060A**	19,000	\$2,660
211241299	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG96VTAA30040A**	19,100	\$2,674
211241288	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG95ESAA36060A**	19,400	\$2,716
211241277	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG95ESAA30040A**	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241275	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG80VTLA36070A**	19,200	\$2,688
211241265	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG80VTLA36045A**	19,100	\$2,674
211241111	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG92ESAA36060A**	18,500	\$2,590
211241032	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96VTAA36060A**	18,600	\$2,604
211240959	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96VTAA36040B**	18,600	\$2,604
211240957	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80VTLA48090B**	18,600	\$2,604
211240934	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG80ESUA36040B**	18,600	\$2,604
211240865	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG95ESUA36040B**	18,600	\$2,604
211240764	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80ESUA48060B**	19,600	\$2,744
211240752	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80ES(A,L)A36070A**	19,400	\$2,716
211240741	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG92ESAA36040B**	19,400	\$2,716
211240730	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG92ESAA30040A**	19,700	\$2,758
211240719	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95ESAA48080B**	19,700	\$2,758
211240708	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95ESAA42060B**	19,600	\$2,744
211240697	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG92ESAA48080B**	19,400	\$2,716
211240686	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG92ESAA42060B**	19,400	\$2,716
211240675	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG92ESAA36060A**	19,200	\$2,688
211240663	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80ES(A,L)A42090B**	19,500	\$2,730
211240651	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80ES(A,L)A36070B**	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240639	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80ES(A,L)A36045B**	19,400	\$2,716
211240627	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80ES(A,L)A36045A**	19,600	\$2,744
211240617	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAA42060B**	19,400	\$2,716
211240606	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95ESAA30026A**	19,800	\$2,772
211240596	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAA36060A**	19,300	\$2,702
211240586	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAA30040A**	19,400	\$2,716
211240575	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95ESAA36060A**	19,600	\$2,744
211240564	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95ESAA36040B**	19,700	\$2,758
211240553	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95ESAA30040A**	19,700	\$2,758
211240543	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80VTLA48070B**	19,300	\$2,702
211240533	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAA48080B**	19,400	\$2,716
211240523	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG96VTAA36040B**	19,300	\$2,702
211240521	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80VTLA48090B**	19,300	\$2,702
211240519	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80VTLA36070A**	19,400	\$2,716
211240509	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80VTLA36045A**	19,400	\$2,716
211240498	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80ESUA36040B**	19,300	\$2,702
211240487	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95ESUA48060B**	19,400	\$2,716
211240440	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80ES(A,L)A48070B**	19,700	\$2,758
211240429	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG95ESUA36040B**	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240354	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG80ES(A,L)A36070A**	19,400	\$2,716
211240343	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG92ESAA30040A**	19,700	\$2,758
211240332	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG92ESAA36060A**	19,600	\$2,744
211240320	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG80ES(A,L)A36045A**	19,600	\$2,744
211240309	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG95ESAA30026A**	19,800	\$2,772
211240299	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG96VTAA36060A**	19,300	\$2,702
211240289	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG96VTAA30040A**	19,400	\$2,716
211240278	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG95ESAA36060A**	19,600	\$2,744
211240267	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG95ESAA30040A**	19,700	\$2,758
211240265	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG80VTLA36070A**	19,400	\$2,716
211240255	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2414AL*	PG80VTLA36045A**	19,400	\$2,716
211239222	PAYNE HEATING AND COOLING	38MURAQ24AB3*	FJ4DN*B24L*		19,200	\$2,688
213249248	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FEVA0024**+NAVA43601CK		12,300	\$1,722
213076385	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAB48060B**	12,400	\$1,736
212989323	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG95MSUA48060B**	12,200	\$1,708
212989311	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG95MSUA48060B**	12,300	\$1,722
212989299	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG95MSUA48060B**	12,200	\$1,708
212989287	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG95MSUA48060B**	12,000	\$1,680
212989275	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG95MSUA48060B**	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989263	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG95MSUA48060B**	12,100	\$1,694
212988831	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG95MSUA36040B**	12,200	\$1,708
212988819	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG95MSUA36040B**	12,500	\$1,750
212988807	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG95MSUA36040B**	12,200	\$1,708
212988795	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG95MSUA36040B**	12,000	\$1,680
212988783	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG95MSUA36040B**	12,300	\$1,722
212988771	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG95MSUA36040B**	12,100	\$1,694
212987557	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96MSAA48080B**	12,200	\$1,708
212987545	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96MSAA48080B**	12,500	\$1,750
212987533	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG96MSAA48080B**	12,100	\$1,694
212987521	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG96MSAA48080B**	12,200	\$1,708
212987509	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96MSAA48080B**	12,500	\$1,750
212987497	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96MSAA48080B**	12,300	\$1,722
212987079	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96MSAA36060A**	12,200	\$1,708
212987069	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG96MSAA36060A**	12,200	\$1,708
212987059	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96MSAA36060A**	12,300	\$1,722
212987049	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG96MSAA36060A**	12,300	\$1,722
212987039	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG96MSAA36060A**	12,500	\$1,750
212987029	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG96MSAA36060A**	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212987019	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG96MSAA36060A**	12,200	\$1,708
212987009	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG96MSAA36060A**	12,000	\$1,680
212986999	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96MSAA36060A**	12,300	\$1,722
212986989	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG96MSAA36060A**	12,300	\$1,722
212986979	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96MSAA36060A**	12,100	\$1,694
212986717	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96MSAA36040B**	12,300	\$1,722
212986705	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96MSAA36040B**	12,500	\$1,750
212986693	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG96MSAA36040B**	12,300	\$1,722
212986681	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG96MSAA36040B**	12,100	\$1,694
212986669	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96MSAA36040B**	12,300	\$1,722
212986657	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96MSAA36040B**	12,100	\$1,694
212986381	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96MSAA30040A**	12,300	\$1,722
212986369	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG96MSAA30040A**	12,300	\$1,722
212986357	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96MSAA30040A**	12,400	\$1,736
212986345	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG96MSAA30040A**	12,400	\$1,736
212986333	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG96MSAA30040A**	12,400	\$1,736
212986321	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG96MSAA30040A**	12,300	\$1,722
212986309	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG96MSAA30040A**	12,300	\$1,722
212986297	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96MSAA30040A**	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986285	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG96MSAA30040A**	12,400	\$1,736
212986273	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96MSAA30040A**	12,200	\$1,708
212985975	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96MSAA30026A**	12,300	\$1,722
212985965	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG96MSAA30026A**	12,200	\$1,708
212985955	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96MSAA30026A**	12,300	\$1,722
212985945	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG96MSAA30026A**	12,300	\$1,722
212985935	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG96MSAA30026A**	12,500	\$1,750
212985925	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG96MSAA30026A**	12,200	\$1,708
212985915	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG96MSAA30026A**	12,200	\$1,708
212985905	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG96MSAA30026A**	12,100	\$1,694
212985895	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96MSAA30026A**	12,300	\$1,722
212985885	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG96MSAA30026A**	12,300	\$1,722
212985875	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96MSAA30026A**	12,100	\$1,694
212984759	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG92MSAA48080B**	12,100	\$1,694
212984747	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG92MSAA48080B**	12,500	\$1,750
212984735	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG92MSAA48080B**	12,400	\$1,736
212984723	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG92MSAA48080B**	12,200	\$1,708
212984711	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG92MSAA48080B**	12,500	\$1,750
212984699	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG92MSAA48080B**	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984219	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG92MSAA42060B**	12,300	\$1,722
212984207	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG92MSAA42060B**	12,400	\$1,736
212984195	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG92MSAA42060B**	12,300	\$1,722
212984183	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG92MSAA42060B**	12,200	\$1,708
212984171	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG92MSAA42060B**	12,400	\$1,736
212984159	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG92MSAA42060B**	12,200	\$1,708
212983729	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG92MSAA36060A**	12,200	\$1,708
212983719	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG92MSAA36060A**	12,200	\$1,708
212983708	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG92MSAA36060A**	12,400	\$1,736
212983698	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG92MSAA36060A**	12,400	\$1,736
212983688	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG92MSAA36060A**	12,400	\$1,736
212983678	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG92MSAA36060A**	12,200	\$1,708
212983668	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG92MSAA36060A**	12,300	\$1,722
212983658	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG92MSAA36060A**	12,000	\$1,680
212983648	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG92MSAA36060A**	12,400	\$1,736
212983638	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG92MSAA36060A**	12,400	\$1,736
212983628	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG92MSAA36060A**	12,100	\$1,694
212983307	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG92MSAA36040B**	12,300	\$1,722
212983296	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG92MSAA36040B**	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983285	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG92MSAA36040B**	12,200	\$1,708
212983274	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG92MSAA36040B**	12,100	\$1,694
212983263	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG92MSAA36040B**	12,300	\$1,722
212983252	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG92MSAA36040B**	12,200	\$1,708
212981882	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80MSUA60100C**	12,300	\$1,722
212981870	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80MSUA60100C**	12,600	\$1,764
212981858	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80MSUA60100C**	12,300	\$1,722
212981846	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80MSUA60100C**	12,100	\$1,694
212981834	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80MSUA60100C**	12,300	\$1,722
212981822	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80MSUA60100C**	12,200	\$1,708
212980003	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80MS(A,L)A42090B**	12,300	\$1,722
212979991	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80MS(A,L)A42090B**	12,400	\$1,736
212979979	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80MS(A,L)A42090B**	12,300	\$1,722
212979967	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80MS(A,L)A42090B**	12,200	\$1,708
212979955	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80MS(A,L)A42090B**	12,400	\$1,736
212979943	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80MS(A,L)A42090B**	12,200	\$1,708
212978798	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80MS(A,L)A36070B**	12,300	\$1,722
212978787	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80MS(A,L)A36070B**	12,300	\$1,722
212978776	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80MS(A,L)A36070B**	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978765	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80MS(A,L)A36070B**	12,100	\$1,694
212978754	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80MS(A,L)A36070B**	12,300	\$1,722
212978743	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80MS(A,L)A36070B**	12,100	\$1,694
212978346	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80MS(A,L)A36070A**	12,200	\$1,708
212978334	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG80MS(A,L)A36070A**	12,200	\$1,708
212978322	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80MS(A,L)A36070A**	12,400	\$1,736
212978310	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG80MS(A,L)A36070A**	12,400	\$1,736
212978298	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG80MS(A,L)A36070A**	12,400	\$1,736
212978284	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80MS(A,L)A36070A**	12,100	\$1,694
212978272	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG80MS(A,L)A36070A**	12,300	\$1,722
212978260	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80MS(A,L)A36070A**	12,200	\$1,708
212978248	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80MS(A,L)A36070A**	12,400	\$1,736
212978236	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG80MS(A,L)A36070A**	12,400	\$1,736
212978224	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80MS(A,L)A36070A**	12,200	\$1,708
212977828	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80MS(A,L)A36045A**	12,300	\$1,722
212977816	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG80MS(A,L)A36045A**	12,300	\$1,722
212977804	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80MS(A,L)A36045A**	12,400	\$1,736
212977792	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG80MS(A,L)A36045A**	12,400	\$1,736
212977780	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG80MS(A,L)A36045A**	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212977768	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80MS(A,L)A36045A**	12,300	\$1,722
212977756	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG80MS(A,L)A36045A**	12,300	\$1,722
212977744	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80MS(A,L)A36045A**	12,100	\$1,694
212977732	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80MS(A,L)A36045A**	12,400	\$1,736
212977720	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG80MS(A,L)A36045A**	12,300	\$1,722
212977708	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80MS(A,L)A36045A**	12,200	\$1,708
212975839	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96VTAB48080B**	12,200	\$1,708
212975826	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96VTAB48080B**	12,500	\$1,750
212975813	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG96VTAB48080B**	12,200	\$1,708
212975800	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG96VTAB48080B**	12,000	\$1,680
212975787	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAB48080B**	12,300	\$1,722
212975774	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96VTAB48080B**	12,100	\$1,694
212975487	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96VTAB36060A**	12,200	\$1,708
212975476	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG96VTAB36060A**	12,200	\$1,708
212975465	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96VTAB36060A**	12,400	\$1,736
212975454	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG96VTAB36060A**	12,400	\$1,736
212975443	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG96VTAB36060A**	12,400	\$1,736
212975432	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG96VTAB36060A**	12,200	\$1,708
212975421	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG96VTAB36060A**	12,200	\$1,708

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975410	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG96VTAB36060A**	12,000	\$1,680
212975399	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAB36060A**	12,300	\$1,722
212975388	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG96VTAB36060A**	12,200	\$1,708
212975377	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96VTAB36060A**	12,100	\$1,694
212975124	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96VTAB36040B**	12,200	\$1,708
212975113	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96VTAB36040B**	12,500	\$1,750
212975102	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG96VTAB36040B**	12,200	\$1,708
212975091	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG96VTAB36040B**	12,100	\$1,694
212975080	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAB36040B**	12,300	\$1,722
212975069	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96VTAB36040B**	12,100	\$1,694
212974745	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96VTAB30040A**	12,200	\$1,708
212974732	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG96VTAB30040A**	12,200	\$1,708
212974719	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96VTAB30040A**	12,400	\$1,736
212974706	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG96VTAB30040A**	12,400	\$1,736
212974693	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG96VTAB30040A**	12,400	\$1,736
212974680	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG96VTAB30040A**	12,200	\$1,708
212974667	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG96VTAB30040A**	12,200	\$1,708
212974654	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG96VTAB30040A**	12,100	\$1,694
212974641	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAB30040A**	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974628	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG96VTAB30040A**	12,400	\$1,736
212974615	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96VTAB30040A**	12,100	\$1,694
212971929	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80VTLB48090B**	12,300	\$1,722
212971925	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80VTLB48090B**	12,400	\$1,736
212971921	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80VTLB48090B**	12,300	\$1,722
212971917	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80VTLB48090B**	12,100	\$1,694
212971913	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80VTLB48090B**	12,400	\$1,736
212971909	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80VTLB48090B**	12,200	\$1,708
212971491	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80VTLB48070B**	12,300	\$1,722
212971480	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80VTLB48070B**	12,400	\$1,736
212971469	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80VTLB48070B**	12,300	\$1,722
212971458	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80VTLB48070B**	12,100	\$1,694
212971447	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80VTLB48070B**	12,400	\$1,736
212971436	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80VTLB48070B**	12,200	\$1,708
211265031	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FV4CNF002L		12,400	\$1,736
211265010	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FM(C,U)4Z30**AL*		12,400	\$1,736
211264988	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FM(C,U)4Z24**AL*		12,500	\$1,750
211264966	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FM(C,U)4Z18**AL*		12,500	\$1,750
211264944	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FMA4X24**AL*		12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211264923	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FMA4X18**AL*		12,400	\$1,736
211264901	PAYNE HEATING AND COOLING	38MURAQ18AB3*	PF4MNB031L		12,400	\$1,736
211264879	PAYNE HEATING AND COOLING	38MURAQ18AB3*	PF4MNB025L		12,400	\$1,736
211264734	PAYNE HEATING AND COOLING	38MURAQ18AB3*	PF4MN*A18L*		12,700	\$1,778
211264732	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FJ4DN*A18L*		12,700	\$1,778
211264652	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80ESUA48060B**	12,700	\$1,778
211264627	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80ES(A,L)A36070A**	12,300	\$1,722
211264605	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG92ESAA36040B**	12,500	\$1,750
211264584	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG92ESAA30040A**	12,500	\$1,750
211264561	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG92ESAA42060B**	12,300	\$1,722
211264539	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG92ESAA36060A**	12,500	\$1,750
211264515	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80ES(A,L)A36070B**	12,500	\$1,750
211264491	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80ES(A,L)A36045B**	12,400	\$1,736
211264467	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80ES(A,L)A36045A**	12,500	\$1,750
211264447	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96VTAA42060B**	12,400	\$1,736
211264423	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG95ESAA30026A**	12,600	\$1,764
211264401	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96VTAA36060A**	12,400	\$1,736
211264360	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96VTAA30040A**	12,300	\$1,722
211264300	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG95ESAA36060A**	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211264267	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG95ESAA36040B**	12,200	\$1,708
211264233	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG95ESAA30040A**	12,400	\$1,736
211264199	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80VTLA48070B**	12,200	\$1,708
211264167	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96VTAA48080B**	12,200	\$1,708
211264135	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG96VTAA36040B**	12,400	\$1,736
211264130	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80VTLA48090B**	12,300	\$1,722
211264125	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80VTLA36070A**	12,300	\$1,722
211264105	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80VTLA36045A**	12,300	\$1,722
211264083	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG80ESUA36040B**	12,700	\$1,778
211264000	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3017AL*	PG95ESUA36040B**	12,400	\$1,736
211263848	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG80ES(A,L)A36070A**	12,300	\$1,722
211263825	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG92ESAA30040A**	12,500	\$1,750
211263804	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG92ESAA36060A**	12,500	\$1,750
211263779	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG80ES(A,L)A36045A**	12,500	\$1,750
211263756	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG95ESAA30026A**	12,500	\$1,750
211263736	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG96VTAA36060A**	12,400	\$1,736
211263715	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG96VTAA30040A**	12,200	\$1,708
211263690	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG95ESAA36060A**	12,400	\$1,736
211263667	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*3014AL*	PG95ESAA30040A**	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263663	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*3014AL*	PG80VTLA36070A**	12,300	\$1,722
211263642	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*3014AL*	PG80VTLA36045A**	12,300	\$1,722
211263507	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG80ESUA48060B**	12,800	\$1,792
211263482	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG80ES(A,L)A36070A**	12,400	\$1,736
211263459	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG92ESAA36040B**	12,600	\$1,764
211263436	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG92ESAA30040A**	12,600	\$1,764
211263413	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG92ESAA48080B**	12,900	\$1,806
211263390	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG92ESAA42060B**	12,400	\$1,736
211263368	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG92ESAA36060A**	12,600	\$1,764
211263343	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG80ES(A,L)A36070B**	12,600	\$1,764
211263318	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG80ES(A,L)A36045B**	12,900	\$1,806
211263293	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG80ES(A,L)A36045A**	12,600	\$1,764
211263272	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG96VTAA42060B**	12,500	\$1,750
211263246	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG95ESAA30026A**	12,700	\$1,778
211263226	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG96VTAA36060A**	12,500	\$1,750
211263205	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG96VTAA30040A**	12,300	\$1,722
211263180	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG95ESAA36060A**	12,500	\$1,750
211263158	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG95ESAA36040B**	12,300	\$1,722
211263137	PAYNE HEATING AND COOLING	38MURQA18AB3*	CNPV*2417AL*	PG95ESAA30040A**	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263119	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80VTLA48070B**	12,300	\$1,722
211263100	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96VTAA48080B**	12,300	\$1,722
211263078	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG96VTAA36040B**	12,500	\$1,750
211263074	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80VTLA48090B**	12,400	\$1,736
211263070	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80VTLA36070A**	12,400	\$1,736
211263050	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80VTLA36045A**	12,400	\$1,736
211263029	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG80ESUA36040B**	12,700	\$1,778
211263007	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG95ESUA48060B**	12,900	\$1,806
211262914	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2417AL*	PG95ESUA36040B**	12,400	\$1,736
211262766	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG80ES(A,L)A36070A**	12,400	\$1,736
211262743	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG92ESAA30040A**	12,600	\$1,764
211262721	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG92ESAA36060A**	12,600	\$1,764
211262697	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG80ES(A,L)A36045A**	12,600	\$1,764
211262675	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG95ESAA30026A**	12,700	\$1,778
211262655	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG96VTAA36060A**	12,500	\$1,750
211262634	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG96VTAA30040A**	12,300	\$1,722
211262611	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG95ESAA36060A**	12,500	\$1,750
211262589	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG95ESAA30040A**	12,500	\$1,750
211262584	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG80VTLA36070A**	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262564	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*2414AL*	PG80VTLA36045A**	12,400	\$1,736
211262486	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG80ES(A,L)A36070A**	12,400	\$1,736
211262464	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG92ESAA30040A**	12,600	\$1,764
211262443	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG92ESAA36060A**	12,600	\$1,764
211262419	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG80ES(A,L)A36045A**	12,600	\$1,764
211262397	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG95ESAA30026A**	12,700	\$1,778
211262376	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG96VTAA36060A**	12,500	\$1,750
211262356	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG96VTAA30040A**	12,300	\$1,722
211262332	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG95ESAA36060A**	12,500	\$1,750
211262310	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG95ESAA30040A**	12,500	\$1,750
211262306	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG80VTLA36070A**	12,400	\$1,736
211262287	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CNPV*1814AL*	PG80VTLA36045A**	12,400	\$1,736
211262156	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80ES(A,L)A36070A**	12,300	\$1,722
211262135	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG92ESAA36040B**	12,500	\$1,750
211262114	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG92ESAA30040A**	12,500	\$1,750
211262092	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG92ESAA42060B**	12,300	\$1,722
211262070	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG92ESAA36060A**	12,500	\$1,750
211262047	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80ES(A,L)A36070B**	12,500	\$1,750
211262020	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3017AL*	PG80ES(A,L)A36045B**	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261994	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG80ES(A,L)A36045A**	12,500	\$1,750
211261973	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG96VTAA42060B**	12,400	\$1,736
211261947	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG95ESAA30026A**	12,600	\$1,764
211261930	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG96VTAA36060A**	12,500	\$1,750
211261915	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG96VTAA30040A**	12,200	\$1,708
211261888	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG95ESAA36060A**	12,400	\$1,736
211261860	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG95ESAA36040B**	12,200	\$1,708
211261841	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG95ESAA30040A**	12,400	\$1,736
211261826	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG80VTLA48070B**	12,200	\$1,708
211261808	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG96VTAA48080B**	12,200	\$1,708
211261787	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG96VTAA36040B**	12,400	\$1,736
211261783	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG80VTLA48090B**	12,300	\$1,722
211261779	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG80VTLA36070A**	12,300	\$1,722
211261760	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG80VTLA36045A**	12,300	\$1,722
211261737	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG80ESUA36040B**	12,700	\$1,778
211261644	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3017AL*	PG95ESUA36040B**	12,300	\$1,722
211261495	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3014AL*	PG80ES(A,L)A36070A**	12,300	\$1,722
211261473	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3014AL*	PG92ESAA30040A**	12,500	\$1,750
211261452	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**3014AL*	PG92ESAA36060A**	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261428	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG80ES(A,L)A36045A**	12,500	\$1,750
211261406	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG95ESAA30026A**	12,500	\$1,750
211261386	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG96VTAA36060A**	12,400	\$1,736
211261366	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG96VTAA30040A**	12,200	\$1,708
211261344	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG95ESAA36060A**	12,400	\$1,736
211261322	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG95ESAA30040A**	12,400	\$1,736
211261318	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG80VTLA36070A**	12,300	\$1,722
211261298	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**3014AL*	PG80VTLA36045A**	12,300	\$1,722
211261146	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80ESUA48060B**	12,600	\$1,764
211261103	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80ES(A,L)A36070A**	12,100	\$1,694
211261059	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG92ESAA36040B**	12,400	\$1,736
211261046	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG92ESAA30040A**	12,400	\$1,736
211261033	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG92ESAA42060B**	12,200	\$1,708
211261020	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG92ESAA36060A**	12,400	\$1,736
211261006	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80ES(A,L)A36070B**	12,400	\$1,736
211260991	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80ES(A,L)A36045B**	12,700	\$1,778
211260977	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG80ES(A,L)A36045A**	12,400	\$1,736
211260965	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG96VTAA42060B**	12,200	\$1,708
211260950	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2517AL*	PG95ESAA30026A**	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260938	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG96VTAA36060A**	12,300	\$1,722
211260926	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG96VTAA30040A**	12,100	\$1,694
211260911	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG95ESAA36060A**	12,300	\$1,722
211260897	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG95ESAA36040B**	12,100	\$1,694
211260884	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG95ESAA30040A**	12,300	\$1,722
211260872	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG80VTLA48070B**	12,000	\$1,680
211260859	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG96VTAA48080B**	12,100	\$1,694
211260846	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG96VTAA36040B**	12,300	\$1,722
211260843	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG80VTLA48090B**	12,200	\$1,708
211260841	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG80VTLA36070A**	12,200	\$1,708
211260829	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG80VTLA36045A**	12,200	\$1,708
211260814	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG80ESUA36040B**	12,500	\$1,750
211260758	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2517AL*	PG95ESUA36040B**	12,200	\$1,708
211260638	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2417AL*	PG80ESUA48060B**	12,800	\$1,792
211260624	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2417AL*	PG80ES(A,L)A36070A**	12,400	\$1,736
211260613	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2417AL*	PG92ESAA36040B**	12,600	\$1,764
211260601	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2417AL*	PG92ESAA30040A**	12,600	\$1,764
211260589	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2417AL*	PG92ESAA42060B**	12,400	\$1,736
211260576	PAYNE HEATING AND COOLING	38MURQA18AB3*	CAP**2417AL*	PG92ESAA36060A**	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260561	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80ES(A,L)A36070B**	12,600	\$1,764
211260547	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80ES(A,L)A36045B**	12,900	\$1,806
211260533	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80ES(A,L)A36045A**	12,600	\$1,764
211260521	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAA42060B**	12,400	\$1,736
211260506	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG95ESAA30026A**	12,700	\$1,778
211260494	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAA36060A**	12,500	\$1,750
211260482	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAA30040A**	12,300	\$1,722
211260468	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG95ESAA36060A**	12,500	\$1,750
211260455	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG95ESAA36040B**	12,300	\$1,722
211260442	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG95ESAA30040A**	12,500	\$1,750
211260430	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80VTLA48070B**	12,200	\$1,708
211260418	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAA48080B**	12,300	\$1,722
211260405	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG96VTAA36040B**	12,500	\$1,750
211260402	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80VTLA48090B**	12,400	\$1,736
211260400	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80VTLA36070A**	12,400	\$1,736
211260388	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80VTLA36045A**	12,400	\$1,736
211260375	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG80ESUA36040B**	12,700	\$1,778
211260318	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2417AL*	PG95ESUA36040B**	12,400	\$1,736
211260228	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG80ES(A,L)A36070A**	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260215	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG92ESAA30040A**	12,600	\$1,764
211260202	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG92ESAA36060A**	12,600	\$1,764
211260185	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG80ES(A,L)A36045A**	12,600	\$1,764
211260174	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG95ESAA30026A**	12,600	\$1,764
211260164	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG96VTAA36060A**	12,500	\$1,750
211260154	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG96VTAA30040A**	12,300	\$1,722
211260137	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG95ESAA36060A**	12,500	\$1,750
211260123	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG95ESAA30040A**	12,500	\$1,750
211260121	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG80VTLA36070A**	12,400	\$1,736
211260109	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**2414AL*	PG80VTLA36045A**	12,400	\$1,736
211260013	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80ESUA48060B**	12,700	\$1,778
211259997	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80ES(A,L)A36070A**	12,200	\$1,708
211259980	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG92ESAA36040B**	12,400	\$1,736
211259965	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG92ESAA30040A**	12,400	\$1,736
211259949	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG92ESAA42060B**	12,200	\$1,708
211259934	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG92ESAA36060A**	12,500	\$1,750
211259918	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80ES(A,L)A36070B**	12,400	\$1,736
211259903	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80ES(A,L)A36045B**	12,700	\$1,778
211259887	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80ES(A,L)A36045A**	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211259873	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96VTAA42060B**	12,300	\$1,722
211259857	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG95ESAA30026A**	12,500	\$1,750
211259844	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96VTAA36060A**	12,400	\$1,736
211259833	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96VTAA30040A**	12,100	\$1,694
211259820	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG95ESAA36060A**	12,300	\$1,722
211259808	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG95ESAA36040B**	12,100	\$1,694
211259796	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG95ESAA30040A**	12,400	\$1,736
211259786	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80VTLA48070B**	12,000	\$1,680
211259775	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96VTAA48080B**	12,100	\$1,694
211259763	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG96VTAA36040B**	12,300	\$1,722
211259760	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80VTLA48090B**	12,200	\$1,708
211259758	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80VTLA36070A**	12,200	\$1,708
211259744	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80VTLA36045A**	12,200	\$1,708
211259729	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG80ESUA36040B**	12,600	\$1,764
211259665	PAYNE HEATING AND COOLING	38MURAQ18AB3*	CAP**1917AL*	PG95ESUA36040B**	12,200	\$1,708
211257335	PAYNE HEATING AND COOLING	38MURAQ18AB3*	PF4MN*B24L*		12,800	\$1,792
211257334	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FJ4DN*B24L*		12,800	\$1,792
211213978	PAYNE HEATING AND COOLING	38MURAQ30AB3*	PF4MNB037L		23,200	\$3,248
211230816	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FB4CNF042L		29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230827	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FB4CNF048L		29,400	\$4,116
211230838	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FB4CNP042L		29,200	\$4,088
211230839	PAYNE HEATING AND COOLING	38MURAQ36AB3*	PF4MNP042L*		29,200	\$4,088
211230850	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FB4CNP048L		29,400	\$4,116
211230851	PAYNE HEATING AND COOLING	38MURAQ36AB3*	PF4MNP048L*		29,400	\$4,116
211230873	PAYNE HEATING AND COOLING	38MURAQ36AB3*	FMA4P36**AL*		29,800	\$4,172
211230905	PAYNE HEATING AND COOLING	38MURAQ36AB3*	PF4MNB037L		29,000	\$4,060
211719727	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FMA4P18**AL*		12,700	\$1,778
211264857	PAYNE HEATING AND COOLING	38MURAQ18AB3*	PF4MNB019L		12,300	\$1,722
211264835	PAYNE HEATING AND COOLING	38MURAQ18AB3*	PF4MNP025L*		12,100	\$1,694
211264833	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FB4CNP025L		12,100	\$1,694
211264826	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FB4CNP024L		12,300	\$1,722
211264804	PAYNE HEATING AND COOLING	38MURAQ18AB3*	PF4MNP018L*		12,300	\$1,722
211264801	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FB4CNP018L		12,300	\$1,722
211264780	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FB4CNF024L		12,300	\$1,722
211264758	PAYNE HEATING AND COOLING	38MURAQ18AB3*	FB4CNF018L		12,300	\$1,722
212978655	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG80MS(A,L)A36070B**	19,000	\$2,660
212978666	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3621AL*	PG80MS(A,L)A36070B**	19,000	\$2,660
212978677	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG80MS(A,L)A36070B**	18,700	\$2,618

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978688	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3721AL*	PG80MS(A,L)A36070B**	18,500	\$2,590
212978699	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG80MS(A,L)A36070B**	19,400	\$2,716
212978710	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG80MS(A,L)A36070B**	18,900	\$2,646
212978721	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3617AL*	PG80MS(A,L)A36070B**	18,900	\$2,646
212978732	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3621AL*	PG80MS(A,L)A36070B**	19,000	\$2,660
212979121	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2417AL*	PG80MS(A,L)A48070B**	19,400	\$2,716
212986153	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**2517AL*	PG96MSAA30040A**	18,800	\$2,632
212986165	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3014AL*	PG96MSAA30040A**	19,200	\$2,688
212986177	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3017AL*	PG96MSAA30040A**	19,200	\$2,688
212986189	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3617AL*	PG96MSAA30040A**	19,200	\$2,688
212986201	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CAP**3717AL*	PG96MSAA30040A**	18,800	\$2,632
212986213	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2414AL*	PG96MSAA30040A**	19,500	\$2,730
212986225	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*2417AL*	PG96MSAA30040A**	19,500	\$2,730
212986237	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3014AL*	PG96MSAA30040A**	19,200	\$2,688
212986249	PAYNE HEATING AND COOLING	38MURAQ24AB3*	CNPV*3017AL*	PG96MSAA30040A**	19,200	\$2,688
207657338	PERFECTAIRE	3PAMS27-HH-MZO3	Heat pump with ducts		27,000	\$3,780
210410111	PERFECTAIRE	3PAMSHH12-SZO	3PAMSCONH12-2		10,200	\$1,428
207796629	PERFECTAIRE	3PAMSHH12-SZO	3PAMSCH12		9,900	\$1,386
207796631	PERFECTAIRE	3PAMSHH12-SZO	3PAMSCONH12		9,600	\$1,344
207796633	PERFECTAIRE	3PAMSHH18-SZO	3PAMSDH18		15,000	\$2,100
206348126	PERFECTAIRE	2KARDA18SZO20	2PAMSDH18		15,000	\$2,100
211253533	PERFECTAIRE	3PAMS55-HH-MZO5	Heat pump with ducts		35,200	\$4,928
211253524	PERFECTAIRE	3PAHHSD24-SZO	3PAHHSD24-AHU		19,200	\$2,688
211253523	PERFECTAIRE	3PAHHSD18-SZO	3PAHHSD18-AHU		13,500	\$1,890

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207657346	PERFECTAIRE	3PAMS48-HH-MZO5	Combination heat pumps with or without ducts		37,400	\$5,236
207657340	PERFECTAIRE	3PAMS27-HH-MZO3	Combination heat pumps with or without ducts		26,200	\$3,668
207796635	PERFECTAIRE	3PAMSHH24-SZO	3PAMSDH24		21,000	\$2,940
211253534	PERFECTAIRE	3PAMS55-HH-MZO5	Combination heat pumps with or without ducts		35,000	\$4,900
211253532	PERFECTAIRE	3PAMS55-HH-MZO5	Heat pump without ducts		34,800	\$4,872
207657335	PERFECTAIRE	3PAMS18-HH-MZO2	Heat pump without ducts		13,500	\$1,890
207657339	PERFECTAIRE	3PAMS27-HH-MZO3	Heat pump without ducts		25,600	\$3,584
211253525	PERFECTAIRE	3PAHHSD30-SZO	3PAHHSD30-AHU		21,000	\$2,940
211253526	PERFECTAIRE	3PAHHSD36-SZO	3PAHHSD36-AHU		30,400	\$4,256
207614055	PERFECTAIRE	3PAMSHH12-SZO	3PAMSHH12-UVW		10,300	\$1,442
208815368	PERFECTAIRE	3PAMSHH18-SZO	3PAMSHH18-UVW		11,100	\$1,554
214389985	PERFECTAIRE	3PAMSHH18-SZO-20.5	3PAMSHH18-UVW		11,100	\$1,554
207614056	PERFECTAIRE	3PAMSHH24-SZO	3PAMSHH24-UVW		18,900	\$2,646
214389986	PERFECTAIRE	3PAMSHH24-SZO-21	3PAMSHH24-UVW		18,900	\$2,646
207657337	PERFECTAIRE	3PAMS18-HH-MZO2	Combination heat pumps with or without ducts		14,700	\$2,058
207657341	PERFECTAIRE	3PAMS36-HH-MZO4	Heat pump without ducts		35,000	\$4,900
207657343	PERFECTAIRE	3PAMS36-HH-MZO4	Combination heat pumps with or without ducts		35,000	\$4,900
207657345	PERFECTAIRE	3PAMS48-HH-MZO5	Heat pump with ducts		36,000	\$5,040
207796636	PERFECTAIRE	3PAMSHH24-SZO	3PAMSDH24		21,000	\$2,940
207192291	PERFECTAIRE	1PAMSHH24-SZW-20.5	2PAMSDH24		21,000	\$2,940
206348127	PERFECTAIRE	1KARDA24SZO20.5	2PAMSDH24		21,000	\$2,940
207657336	PERFECTAIRE	3PAMS18-HH-MZO2	Heat pump with ducts		16,000	\$2,240
207657344	PERFECTAIRE	3PAMS48-HH-MZO5	Heat pump without ducts		39,000	\$5,460
207796630	PERFECTAIRE	3PAMSHH12-SZO	3PAMSDH12		10,600	\$1,484
205645135	PERFECTAIRE	2PAMS27-HH-MZO3	Heat pump without ducts		18,000	\$2,520
9856845	PERFECTAIRE	1PAMSHH12-SZO-22.5	1PAMSHH12-SZW-22.5		7,800	\$1,092
9856849	PERFECTAIRE	1PAMSHH24-SZO-20.5	1PAMSHH24-SZW-20.5		15,400	\$2,156
205645142	PERFECTAIRE	2PAMS48-HH-MZO5	Heat pump with ducts		28,000	\$3,920
207657342	PERFECTAIRE	3PAMS36-HH-MZO4	Heat pump with ducts		23,000	\$3,220
205645141	PERFECTAIRE	2PAMS48-HH-MZO5	Heat pump without ducts		30,000	\$4,200
211253527	PERFECTAIRE	3PAHHSD48-SZO	3PAHHSD48-AHU		36,000	\$5,040
211253528	PERFECTAIRE	3PAHHSD60-SZO	3PAHHSD60-AHU		42,000	\$5,880
208121960	PIONEER	YN048GMFI18RUE	UB048GMFILCFHD		29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214606643	PIONEER	HP36R410A	THAH-AIRHANDLER36		24,000	\$3,360
208978288	PIONEER	THTU-HEATPUMP24	THAH-AIRHANDLER36		24,000	\$3,360
212316100	PolarWave	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MC		10,000	\$1,400
212316072	PolarWave	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MB		10,000	\$1,400
212316073	PolarWave	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MB		15,000	\$2,100
212316101	PolarWave	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MC		15,000	\$2,100
212316102	PolarWave	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MC		21,200	\$2,968
212316074	PolarWave	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MB		21,200	\$2,968
212316076	PolarWave	ACIQ-12ZPL-HP230B	ACIQ-12CC-HH-MB		9,900	\$1,386
212316082	PolarWave	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MB		9,600	\$1,344
212316080	PolarWave	ACIQ-18ZPL-HP230B	ACIQ-18CD-HH-MB		15,000	\$2,100
212316089	PolarWave	ACIQ-27Z-HH-M3B	Heat pump with ducts		27,000	\$3,780
212316118	PolarWave	ACIQ-55Z-HH-M5B	Heat pump with ducts		35,200	\$4,928
212316115	PolarWave	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MC		10,200	\$1,428
212316113	PolarWave	ACIQ-12ZPL-HP230B	SCC-1218-HH-M		9,500	\$1,330
212316114	PolarWave	ACIQ-18ZPL-HP230B	SCC-1218-HH-M		14,500	\$2,030
212316090	POLARWAVE	ACIQ-27Z-HH-M3B	Combination heat pumps with or without ducts		26,800	\$3,752
212316119	POLARWAVE	ACIQ-55Z-HH-M5B	Combination heat pumps with or without ducts		34,800	\$4,872
212316094	PolarWave	ACIQ-48Z-HH-M5B	Heat pump without ducts		36,000	\$5,040
212316117	PolarWave	ACIQ-55Z-HH-M5B	Heat pump without ducts		34,400	\$4,816
212316085	PolarWave	ACIQ-18Z-HH-M2B	Heat pump without ducts		15,000	\$2,100
212316088	PolarWave	ACIQ-27Z-HH-M3B	Heat pump without ducts		26,600	\$3,724
213492152	POLARWAVE	ACIQ-36-HPC	ACIQ-36-AHB		30,400	\$4,256
214810553	POLARWAVE	ACIQ-18-HPB	ACIQ-18-AHB		13,500	\$1,890
212316079	PolarWave	ACIQ-12ZPL-HP230B	ACIQ-12CD-HH-MB		10,600	\$1,484
212316087	POLARWAVE	ACIQ-18Z-HH-M2B	Combination heat pumps with or without ducts		15,500	\$2,170
212316091	PolarWave	ACIQ-36Z-HH-M4B	Heat pump without ducts		33,000	\$4,620
212316095	PolarWave	ACIQ-48Z-HH-M5B	Heat pump with ducts		36,000	\$5,040
212316081	PolarWave	ACIQ-24ZPL-HP230B	ACIQ-24CD-HH-MB		21,000	\$2,940
212316096	POLARWAVE	ACIQ-48Z-HH-M5B	Combination heat pumps with or without ducts		36,000	\$5,040
212316084	PolarWave	ACIQ-24ZPL-HP230B	ACIQ-24FM-HH-MB		19,000	\$2,660
212316086	PolarWave	ACIQ-18Z-HH-M2B	Heat pump with ducts		16,000	\$2,240
212316093	POLARWAVE	ACIQ-36Z-HH-M4B	Combination heat pumps with or without ducts		34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215570367	POLARWAVE	ACIQ-30-HPB	ACIQ-30-AHB		21,000	\$2,940
212394345	POLARWAVE	ACIQ-24-HPB	ACIQ-24-ACL		21,000	\$2,940
216980864	POLARWAVE	EZ-60-HPB	EZ-60-AHB		45,000	\$6,300
216980859	POLARWAVE	EZ-48-EHPB	EZ-48-AHB		32,400	\$4,536
216980863	POLARWAVE	EZ-48-HPB	EZ-48-AHB		37,000	\$5,180
216980862	POLARWAVE	EZ-36-HPB	EZ-36-AHB		31,800	\$4,452
216980857	POLARWAVE	EZ-24-EHPB	EZ-24-AHB		20,000	\$2,800
216980861	POLARWAVE	EZ-24-HPB	EZ-24-AHB		20,000	\$2,800
212394347	POLARWAVE	ACIQ-36-HPB	ACIQ-36-ACL		33,000	\$4,620
213492159	POLARWAVE	ACIQ-30-HPB	ACIQ-36-ACL-17		19,600	\$2,744
212316109	PolarWave	ACIQ-48ZPL-HP230B	ACIQ-48FM-HH-MB		35,000	\$4,900
212316104	PolarWave	ACIQ-48ZPL-HP230B	ACIQ-48CC-HH-MB		35,000	\$4,900
212316106	PolarWave	ACIQ-48ZPL-HP230B	ACIQ-48CD-HH-MB		39,500	\$5,530
212316103	PolarWave	ACIQ-36ZPL-HP230B	ACIQ-36CC-HH-MB		33,000	\$4,620
214810554	POLARWAVE	EZ-24-HP	EZ-24-AH		19,200	\$2,688
214810555	POLARWAVE	EZ-48-HP	EZ-48-AH		36,000	\$5,040
214810556	POLARWAVE	EZ-60-HP	EZ-60-AH		42,000	\$5,880
213492161	POLARWAVE	ACIQ-36-HPB	ACIQ-36-ACL-17		27,400	\$3,836
213492155	POLARWAVE	ACIQ-36-HPC	ACIQ-36-ACL		27,000	\$3,780
213492154	POLARWAVE	ACIQ-36-HPC	ACIQ-36-ACL-17		27,000	\$3,780
213500939	POLARWAVE	ACIQ-36-HPC	ACIQ-36-AHB*		31,800	\$4,452
213433293	POLARWAVE	ACIQ-36-HPB	ACIQ-36W-P		32,800	\$4,592
213433291	POLARWAVE	ACIQ-24-HPB	ACIQ-24W-P		19,200	\$2,688
213433290	POLARWAVE	ACIQ-18-HPB	ACIQ-18W-P		13,500	\$1,890
213433292	POLARWAVE	ACIQ-30-HPB	ACIQ-30W-P		20,000	\$2,800
213433286	POLARWAVE	ACIQ-18-HPB	ACIQ-18W-WM		15,800	\$2,212
213433287	POLARWAVE	ACIQ-24-HPB	ACIQ-24W-WM		20,000	\$2,800
213433281	POLARWAVE	ACIQ-60HPB	ACIQ-60-ACL		37,000	\$5,180
213492158	POLARWAVE	ACIQ-30-HPB	ACIQ-36-ACL		22,600	\$3,164
212316107	PolarWave	ACIQ-60ZPL-HP230B	ACIQ-60CD-HH-MB		40,000	\$5,600
212316110	PolarWave	ACIQ-60ZPL-HP230B	ACIQ-60FM-HH-MB		40,000	\$5,600
212316108	PolarWave	ACIQ-36ZPL-HP230B	ACIQ-36FM-HH-MB		32,000	\$4,480
212394346	POLARWAVE	ACIQ-30-HPB	ACIQ-30-ACL		22,600	\$3,164
214232461	PREMIUM LEVELLA	PIAW1232580B	PIAW1232579A		10,300	\$1,442
214232464	PREMIUM LEVELLA	PIAW1832580B	PIAW1832579A		11,100	\$1,554
214232462	PREMIUM LEVELLA	PIAW2432580B	PIAW2432579A		18,900	\$2,646
213927609	QUEBEC VAIR	NE-T53-AEG12EXT	NE-T53-AEG12INT		10,000	\$1,400
213927610	QUEBEC VAIR	NE-T53-AEG18EXT	NE-T53-AEG18INT		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213927613	QUEBEC VAIR	NE-T53-MULTI28E	Heat pump without ducts		26,600	\$3,724
213927614	QUEBEC VAIR	NE-T53-MULTI28E	Heat pump with ducts		27,000	\$3,780
213927615	QUEBEC VAIR	NE-T53-MULTI28E	Combination heat pumps with or without ducts		26,800	\$3,752
215402349	QUEBEC VAIR	NE-T52-QVAIR3012E	NE-T52-QVAIR3012I		10,000	\$1,400
215402350	QUEBEC VAIR	NE-T52-QVAIR3018E	NE-T52-QVAIR3018I		15,000	\$2,100
213927616	QUEBEC VAIR	NE-T53-MULTI36E	Heat pump without ducts		33,000	\$4,620
213927618	QUEBEC VAIR	NE-T53-MULTI36E	Combination heat pumps with or without ducts		34,000	\$4,760
210368104	RHEEM	RO1HGZ12AJ1H	RIWHGZ12AJ1S		10,000	\$1,400
210368102	RHEEM	RO1HGZ12AJ1S	RIWHGZ12AJ1S		10,000	\$1,400
210368118	RHEEM	RO1HHZ18AJ3S	RIWHHZ18AJ3S		11,200	\$1,568
210368106	RHEEM	RO1HGZ15AJ1S	RIWHGZ15AJ1S		11,200	\$1,568
210368108	RHEEM	RO1HGZ15AJ1H	RIWHGZ15AJ1S		11,200	\$1,568
210368084	RHEEM	RO1HFZ12AJ2H	RIFHFZ12AJ2S		10,600	\$1,484
210368086	RHEEM	RO1HFZ15AJ2H	RIFHFZ15AJ2S		11,600	\$1,624
210368080	RHEEM	RO1HFZ15AJ2S	RIFHFZ15AJ2S		11,600	\$1,624
210368092	RHEEM	RO1HFZ30AJ2H	RIWHFZ30AJ2S		18,900	\$2,646
10595373	RHEEM	ROSH12AHHJ	RIWH12AHWJ		9,600	\$1,344
10595386	RHEEM	ROSH12AFFHJ	RIFH12AVFJ		10,600	\$1,484
10595375	RHEEM	ROSH15AHHJ	RIWH15AHWJ		11,200	\$1,568
212609395	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802V1005A21UHS	44,500	\$6,230
212609382	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802V1004A17UHS	44,500	\$6,230
210589346	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802VA100521M	44,500	\$6,230
209872705	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R98MV0603A17UPS	41,000	\$5,740
209872704	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R97MV1005A21DHS	40,500	\$5,670
209872703	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R962V1005A21M4S	40,500	\$5,670
209872701	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R962V0705A21M4S	40,500	\$5,670
210589391	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802VA100521Z	40,500	\$5,670
209872721	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R962V1005A21M4S	45,000	\$6,300
209872719	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R962V0705A21M4S	44,500	\$6,230
212609368	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802V0755A21UHN	40,500	\$5,670
212609373	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802V1005A21UHN	44,500	\$6,230
212609367	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802V0504A17UHS	41,000	\$5,740
212609350	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802V0755A21DZ	40,500	\$5,670
212609344	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802V0754A17DZ	41,000	\$5,740
210589390	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802VA100521M	40,500	\$5,670
210589389	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802VA075421Z	40,500	\$5,670

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210589388	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802VA075421M	40,500	\$5,670
210589387	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802VA075317M	40,500	\$5,670
209872725	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R98MV1005A21UPS	45,000	\$6,300
209872723	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R97MV1005A21DHS	44,500	\$6,230
209872708	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R98MV1005A21UPS	41,000	\$5,740
209872707	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R98MV0855A21UPS	40,500	\$5,670
209872706	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R98MV0703A17UPS	41,000	\$5,740
209872699	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R962V0403A17M4S	41,000	\$5,740
213163990	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R97MV0855A21DHS	40,500	\$5,670
212609397	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802V0755A21UHN	44,500	\$6,230
212609393	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802V0755A21UHS	44,500	\$6,230
212609388	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802V0504A17UHN	45,000	\$6,300
212609386	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802V0754A17DZ	45,000	\$6,300
212609383	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802V0504A17UHS	45,000	\$6,300
212609366	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802V0504A17UHN	41,000	\$5,740
212609365	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802V0755A21UHS	40,500	\$5,670
212609359	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802V1004A17UHS	40,500	\$5,670
212609342	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R802V0754A17UHS	40,500	\$5,670
210589347	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802VA100521Z	44,500	\$6,230
210589345	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802VA075421Z	44,500	\$6,230
210589344	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R802VA075421M	44,500	\$6,230
209872724	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R98MV0855A21UPS	44,500	\$6,230
209872722	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R97MV0855A21DHS	44,500	\$6,230
209872720	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R962V0855A21M4S	44,500	\$6,230
209872702	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R962V0855A21M4S	40,500	\$5,670
208552857	RHEEM	RP18AZ36AJVC	RHMOVZ6021SEACA		38,000	\$5,320
214066906	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0603A17M4S	31,600	\$4,424
214066903	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R98MV1005A21UPS	31,400	\$4,396
214066901	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R921V0603A17M4S	31,600	\$4,424
214066892	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R98MV0703A17UPS	31,400	\$4,396
214066875	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R98MV0603A17UPS	31,600	\$4,424
214066834	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R962V0403A17M4S	31,400	\$4,396
214066829	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R98MV0855A21UPS	31,200	\$4,368
214066818	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0855A21M4S	31,400	\$4,396
214066812	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0703A17M4S	31,400	\$4,396
214066810	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R802V0504A17UHS	31,400	\$4,396
214066792	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R962V1005A21M4S	31,400	\$4,396
214066791	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R802V0504A17UHN	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214066781	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R802VA050317M	31,400	\$4,396
214066773	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0704A17UHU	31,400	\$4,396
214066768	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0504A17UHN	31,400	\$4,396
214066739	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0504A17UHS	31,400	\$4,396
214066730	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0403A17M4S	31,400	\$4,396
214066728	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R96VA0602317M	31,600	\$4,424
214066721	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R962V0703A17M4S	31,400	\$4,396
214066709	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R802VA075317Z	31,400	\$4,396
214066689	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R97MV0703A17DHS	31,400	\$4,396
214066679	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R951V1005A21M4S	31,400	\$4,396
214066652	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R962V0855A21M4S	31,400	\$4,396
214066626	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R97MV0603A17DHS	31,400	\$4,396
214066623	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R921V0855A21M4S	31,400	\$4,396
214066562	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R921V0403A17M4S	31,400	\$4,396
214066548	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0403A17UHU	31,600	\$4,424
214066541	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R921V1005A21M4S	31,400	\$4,396
214066536	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0603A17UHU	31,600	\$4,424
214066532	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0504A17UHU	31,600	\$4,424
214066530	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0754A17DZ	31,400	\$4,396
214066525	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R802V0754A17DZ	31,400	\$4,396
214066519	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R921V0703A17M4S	31,400	\$4,396
214066510	RHEEM	RD17AZ36AJ3N	RCFZ3621MTANM	R962V0603A17M4S	31,600	\$4,424
214075564	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0504A17UHN	19,000	\$2,660
214075562	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0503A14DZ	18,900	\$2,646
214075559	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802VA050317M	19,000	\$2,660
214075546	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0504A17UHS	19,000	\$2,660
214075542	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R962V0603A17M4S	19,000	\$2,660
214075530	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0403A17UHU	19,100	\$2,674
214075529	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0503A14UH	19,000	\$2,660
214075527	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0754A17DZ	18,900	\$2,646
214075526	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R962V0403A17M4S	19,000	\$2,660
214075517	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0503A14UHN	19,000	\$2,660
214075515	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R98MV0603A17UPS	19,000	\$2,660
214075511	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0754A17DZ	18,900	\$2,646
214075508	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R962V0703A17M4S	19,000	\$2,660
214075506	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V1004A17UHN	18,900	\$2,646
214075502	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R921V0703A17M4S	19,000	\$2,660
214075488	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0704A17UHU	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214075485	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R921V0603A17M4S	19,000	\$2,660
214075482	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0504A17UHU	19,000	\$2,660
214075479	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V1004A17UH	18,800	\$2,632
214075476	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0703A17M4S	19,000	\$2,660
214075475	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R97MV0603A17DHS	19,000	\$2,660
214075469	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0503A14UHS	19,000	\$2,660
214075466	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V1004A17UHS	18,900	\$2,646
214075463	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0603A17UHU	19,100	\$2,674
214075457	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802VA075317M	18,800	\$2,632
214075442	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R98MV0703A17UPS	19,000	\$2,660
214075440	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802VA075317Z	18,900	\$2,646
214075430	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0403A17M4S	19,000	\$2,660
214075429	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0754A17UHS	18,900	\$2,646
214075426	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R96VA0602317M	19,000	\$2,660
214075415	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0754A17UHN	18,900	\$2,646
214075413	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0603A17M4S	19,000	\$2,660
214075409	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0504A17UHS	19,000	\$2,660
214075585	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0504A17UHN	19,000	\$2,660
214075583	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0754A17UHN	18,900	\$2,646
214075570	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R97MV0703A17DHS	19,000	\$2,660
214075568	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0503A14DZ	18,900	\$2,646
214075566	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0754A17UHS	18,900	\$2,646
214075565	RHEEM	RD17AZ24AJ3N	RCFZ2417MTANM	R921V0403A17M4S	19,000	\$2,660
214233325	RHEEM	RD17AZ36AJ3N	RH3VZ4821STACN		31,200	\$4,368
214097945	RHEEM	RD17AZ48AJ3N	RH3VZ6024STACN		43,000	\$6,020
214095455	RHEEM	RD17AZ24AJ3N	RH3VZ3617STACN		18,700	\$2,618
213164000	RHEEM	RP18AZ36AJVC	RCFZ6021SEAAM	R98VB085M521U	40,500	\$5,670
213164007	RHEEM	RP18AZ48AJVC	RCFZ6021SEAAM	R98VB085M521U	44,500	\$6,230
10595422	RHEEM	ROMH18FXZHJ	Combination heat pumps with or without ducts		14,200	\$1,988
10595434	RHEEM	ROMH36FXZHJ	Combination heat pumps with or without ducts		21,400	\$2,996
202244046	RHEEM	ROSH18VGSN	RICH18AXCJ		12,300	\$1,722
202244731	RHEEM	ROSH24VGSN	RICH24AXCJ		16,400	\$2,296
10595428	RHEEM	ROMH24FXZHJ	Combination heat pumps with or without ducts		15,400	\$2,156
202245032	RHEEM	ROSH30VGSN	RICH30AXCJ		20,200	\$2,828
202245794	RHEEM	ROSH36VGSN	RICH36AXCJ		23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
10061704	RHEEM	ROSH18ASJ	RIWH18ASJ		11,500	\$1,610
10061706	RHEEM	ROSH24ASJ	RIWH24ASJ		15,300	\$2,142
10595403	RHEEM	ROSH18AFCJ	RIDH18AVFJ		13,600	\$1,904
10595396	RHEEM	ROSH15AFFJ	RIFH15AVFJ		11,600	\$1,624
10595394	RHEEM	ROSH12AFFJ	RIFH12AVFJ		10,600	\$1,484
10061720	RHEEM	ROSH18AXFWJ	RIWH18AVFJ		14,600	\$2,044
10595407	RHEEM	ROSH12AFCJ	RICH12AVFJ		10,200	\$1,428
10595409	RHEEM	ROSH18AFCJ	RICH18AVFJ		13,600	\$1,904
10061714	RHEEM	ROSH15AHWJ	RIWH15AHWJ		11,200	\$1,568
10061712	RHEEM	ROSH12AHWJ	RIWH12AHWJ		9,600	\$1,344
10595401	RHEEM	ROSH12AFCJ	RIDH12AVFJ		9,500	\$1,330
10595381	RHEEM	ROSH30AHXHJ	RIWH30AVFJ		18,900	\$2,646
10595377	RHEEM	ROSH18AHXHJ	RIWH18AVFJ		14,600	\$2,044
10595432	RHEEM	ROMH36FXZHJ	Heat pump with ducts		21,400	\$2,996
10595426	RHEEM	ROMH24FXZHJ	Heat pump with ducts		15,400	\$2,156
10595420	RHEEM	ROMH18FXZHJ	Heat pump with ducts		14,200	\$1,988
10595430	RHEEM	ROMH36FXZHJ	Heat pump without ducts		21,400	\$2,996
10595424	RHEEM	ROMH24FXZHJ	Heat pump without ducts		15,400	\$2,156
10595418	RHEEM	ROMH18FXZHJ	Heat pump without ducts		14,200	\$1,988
211044463	RHEEM	RO3HFZ24AJ1H	Heat pump without ducts		15,400	\$2,156
211044465	RHEEM	RO3HFZ24AJ1H	Heat pump with ducts		15,400	\$2,156
211044461	RHEEM	RO2HFZ18AJ1H	Heat pump with ducts		14,200	\$1,988
211781753	RHEEM	RD16AZ30AJHUA	RHMOVZ3021SNAUNJ		21,600	\$3,024
211781754	RHEEM	RD16AZ36AJHUA	RHMOVZ3621MNAUAJ		25,600	\$3,584
210824765	RHEEM	RO4HFZ36AJ1H	Heat pump without ducts		21,400	\$2,996
211044459	RHEEM	RO2HFZ18AJ1H	Heat pump without ducts		14,200	\$1,988
210824722	RHEEM	RO1HHZ12AJ8S	RIMHHZ12AJ8S		10,500	\$1,470
211781755	RHEEM	RD16AZ48AJHUA	RHMOVZ4821SNAUAJ		34,400	\$4,816
210368114	RHEEM	RO1HHZ18AJ2S	RIWHHZ18AJ2S		13,600	\$1,904
210368124	RHEEM	RO1HHZ36AJ3S	RIWHHZ36AJ3S		22,400	\$3,136
210368122	RHEEM	RO1HHZ30AJ3S	RIWHHZ30AJ3S		19,400	\$2,716
210824712	RHEEM	RO1HHZ12AJ8S	RICHHZ12AJ8S		10,700	\$1,498
210824718	RHEEM	RO1HHZ18AJ8S	RICHHZ18AJ8S		14,700	\$2,058
211044469	RHEEM	RO4HFZ36AJ1H	Heat pump with ducts		21,400	\$2,996
210824726	RHEEM	RO1HGZ42AJ8S	RIMHGZ42AJ8S		29,600	\$4,144
210368088	RHEEM	RO1HFZ18AJ2H	RIWHFZ18AJ2S		14,600	\$2,044
210368078	RHEEM	RO1HFZ12AJ2S	RIFHFZ12AJ2S		10,600	\$1,484
211781748	RHEEM	RO1HHZ24AJ8S	RISHHZ24AJ8S		17,500	\$2,450

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211781749	RHEEM	RO1HHZ30AJ8S	RISHHZ30AJ8S		21,000	\$2,940
211781750	RHEEM	RO1HHZ36AJ8S	RISHHZ36AJ8S		24,200	\$3,388
211781751	RHEEM	RD16AZ24AJVUA	RHMOVZ2421MNAUNJ		18,700	\$2,618
211781752	RHEEM	RD16AZ30AJVUA	RHMOVZ3021SNAUNJ		21,800	\$3,052
211781740	RHEEM	RO1HHZ24AJ8S	RIMHHZ24AJ8S		18,100	\$2,534
211781741	RHEEM	RO1HHZ30AJ8S	RIMHHZ30AJ8S		21,200	\$2,968
211781742	RHEEM	RO1HHZ36AJ8S	RIMHHZ36AJ8S		25,800	\$3,612
211781744	RHEEM	RO1HHZ24AJ8S	RIGHHZ24AJ8S		18,000	\$2,520
211781745	RHEEM	RO1HHZ30AJ8S	RIGHHZ30AJ8S		20,800	\$2,912
211781746	RHEEM	RO1HHZ36AJ8S	RIGHHZ36AJ8S		24,600	\$3,444
211749852	RUNTRU	E4HL5048A1000A	E4AH5E48A1K30A		38,000	\$5,320
212617023	RUNTRU	E4HL5048A1000A	E4AH5E36A1J30A		30,000	\$4,200
213894041	RUNTRU	E4HL5030A1000A	A4AH5V30A1B3 + DF		18,000	\$2,520
212617024	RUNTRU	E4HL5042A1000A	E4AH5E36A1J30A		30,000	\$4,200
211749851	RUNTRU	E4HL5042A1000A	E4AH5E48A1K30A		33,000	\$4,620
212510783	RUNTRU	E4HL5024A1000A	4TXCB003DS3	A801X060BM4SCA	20,000	\$2,800
212510784	RUNTRU	E4HL5024A1000A	4TXCB003DS3	A951X060BU4SAB	20,000	\$2,800
212510786	RUNTRU	E4HL5024A1000A	4TXCB003DS3	A952V040BU3SAD	20,000	\$2,800
212510785	RUNTRU	E4HL5024A1000A	4TXCB003DS3	A952V060BU4SAD	20,000	\$2,800
212510787	RUNTRU	E4HL5024A1000A	4TXCB003DS3	A951X040BU3SAB	20,000	\$2,800
212510780	RUNTRU	E4HL5018A1000A	4TXCB003DS3	A801X040BM2SCA	20,000	\$2,800
212510781	RUNTRU	E4HL5018A1000A	4TXCB003DS3	A951X040BU3SAB	20,000	\$2,800
212510782	RUNTRU	E4HL5018A1000A	4TXCB003DS3	A952V040BU3SAD	20,000	\$2,800
212400612	RUNTRU	E4HL5018A1000A	4TXCB003DS3		20,000	\$2,800
211749848	RUNTRU	E4HL5024A1000A	E4AH5E24A1J30A		19,100	\$2,674
211749847	RUNTRU	E4HL5018A1000A	E4AH5E24A1J30A		15,000	\$2,100
212394368	RUNTRU	E4HL5024A1000A	4TXCB004DS3		20,000	\$2,800
212394369	RUNTRU	E4HL5024A1000A	4TXCB003DS3		20,000	\$2,800
205118701	RUNTRU	M4THS1824A11N**	M4MHW1824A1N0**		14,600	\$2,044
210488277	RUNTRU	M4THM1936A14N**	Heat pump without ducts		30,800	\$4,312
210488278	RUNTRU	M4THM1942A15N**	Heat pump without ducts		35,600	\$4,984
213894040	RUNTRU	E4HL5024A1000A	A4AH5V36A1C3 + DF		19,100	\$2,674
213894039	RUNTRU	E4HL5018A1000A	A4AH5V24A1B3 + DF		14,000	\$1,960
214233328	RUSSELL	RD17AZ36AJ3N	SH3VZ4821STACN		31,200	\$4,368
210368105	RUUD	RO1HGZ12AJ1H	UIWHGZ12AJ1S		10,000	\$1,400
210368103	RUUD	RO1HGZ12AJ1S	UIWHGZ12AJ1S		10,000	\$1,400
210368119	RUUD	RO1HHZ18AJ3S	UIWHHZ18AJ3S		11,200	\$1,568
210368107	RUUD	RO1HGZ15AJ1S	UIWHGZ15AJ1S		11,200	\$1,568

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210368109	RUUD	RO1HGZ15AJ1H	UIWHGZ15AJ1S		11,200	\$1,568
210368085	RUUD	RO1HFZ12AJ2H	RIFHFZ12AJ2S		10,600	\$1,484
210368087	RUUD	RO1HFZ15AJ2H	RIFHFZ15AJ2S		11,600	\$1,624
210368081	RUUD	RO1HFZ15AJ2S	RIFHFZ15AJ2S		11,600	\$1,624
210368093	RUUD	RO1HFZ30AJ2H	UIWHFZ30AJ2S		18,900	\$2,646
212609402	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R802V0755A21UHS	44,500	\$6,230
212609374	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R802V0755A21UHN	44,500	\$6,230
210589399	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U802VA100521M	40,500	\$5,670
210589396	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U802VA075317M	40,500	\$5,670
210589355	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	U802VA100521Z	44,500	\$6,230
209872732	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	U98MV1005A21UPS	45,000	\$6,300
209872730	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	U97MV1005A21DHS	44,500	\$6,230
209872728	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R962V1005A21M4S	45,000	\$6,300
209872712	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R962V0855A21M4S	40,500	\$5,670
212609401	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R802V1004A17UHS	44,500	\$6,230
212609352	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R802V1004A17UHS	40,500	\$5,670
210589398	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U802VA075421Z	40,500	\$5,670
209872718	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U98MV1005A21UPS	41,000	\$5,740
209872715	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U98MV0603A17UPS	41,000	\$5,740
209872709	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R962V0403A17M4S	41,000	\$5,740
213163997	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U97MV0855A21DHS	40,500	\$5,670
212609387	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R802V0504A17UHN	45,000	\$6,300
212609385	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R802V0754A17DZ	45,000	\$6,300
212609384	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R802V0504A17UHS	45,000	\$6,300
212609371	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R802V0504A17UHN	41,000	\$5,740
212609370	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R802V0754A17UHS	40,500	\$5,670
212609369	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R802V0504A17UHS	41,000	\$5,740
212609362	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R802V0755A21UHS	40,500	\$5,670
212609358	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R802V0755A21UHN	40,500	\$5,670
212609347	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R802V0755A21DZ	40,500	\$5,670
209872729	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	U97MV0855A21DHS	44,500	\$6,230
209872726	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R962V0705A21M4S	44,500	\$6,230
209872717	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U98MV0855A21UPS	40,500	\$5,670
209872713	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R962V1005A21M4S	40,500	\$5,670
212609399	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R802V1005A21UHN	44,500	\$6,230
212609376	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R802V1005A21UHS	44,500	\$6,230
212609351	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R802V0754A17DZ	41,000	\$5,740
210589400	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U802VA100521Z	40,500	\$5,670

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210589397	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U802VA075421M	40,500	\$5,670
210589354	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	U802VA100521M	44,500	\$6,230
210589353	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	U802VA075421Z	44,500	\$6,230
210589352	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	U802VA075421M	44,500	\$6,230
209872731	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	U98MV0855A21UPS	44,500	\$6,230
209872727	RUUD	UP18AZ48AJVC	RCFZ6021SEAAM	R962V0855A21M4S	44,500	\$6,230
209872716	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U98MV0703A17UPS	41,000	\$5,740
209872714	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	U97MV1005A21DHS	40,500	\$5,670
209872711	RUUD	UP18AZ36AJVC	RCFZ6021SEAAM	R962V0705A21M4S	40,500	\$5,670
208553291	RUUD	UP18AZ36AJVC	RHMOVZ6021SEACA		38,000	\$5,320
214066923	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0504A17UHN	31,400	\$4,396
214066919	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	U802VA075317Z	31,400	\$4,396
214066908	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0403A17M4S	31,400	\$4,396
214066896	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0855A21M4S	31,400	\$4,396
214066878	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0504A17UHS	31,400	\$4,396
214066876	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	U98MV1005A21UPS	31,400	\$4,396
214066856	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0603A17M4S	31,600	\$4,424
214066846	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0704A17UHU	31,400	\$4,396
214066820	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R962V0603A17M4S	31,600	\$4,424
214066817	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R802V0504A17UHS	31,400	\$4,396
214066809	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R802V0754A17DZ	31,400	\$4,396
214066800	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R951V1005A21M4S	31,400	\$4,396
214066794	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	U97MV0703A17DHS	31,400	\$4,396
214066788	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R802V0504A17UHN	31,400	\$4,396
214066765	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R962V1005A21M4S	31,400	\$4,396
214066744	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0504A17UHU	31,600	\$4,424
214066723	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	U802VA050317M	31,400	\$4,396
214066717	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R921V0403A17M4S	31,400	\$4,396
214066710	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R921V0703A17M4S	31,400	\$4,396
214066706	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0403A17UHU	31,600	\$4,424
214066696	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0603A17UHU	31,600	\$4,424
214066673	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	U97MV0855A21DHS	31,200	\$4,368
214066667	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	U98MV0603A17UPS	31,600	\$4,424
214066654	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R962V0403A17M4S	31,400	\$4,396
214066642	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R962V0703A17M4S	31,400	\$4,396
214066631	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	U97MV0603A17DHS	31,400	\$4,396
214066610	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R921V0855A21M4S	31,400	\$4,396
214066583	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R962V0855A21M4S	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214066560	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R951V0703A17M4S	31,400	\$4,396
214066543	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R921V1005A21M4S	31,400	\$4,396
214066528	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R921V0603A17M4S	31,600	\$4,424
214066513	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	R801V0754A17DZ	31,400	\$4,396
214066467	RUUD	RD17AZ36AJ3N	RCFZ3621MTANM	U98MV0703A17UPS	31,400	\$4,396
214075563	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0504A17UHU	19,000	\$2,660
214075555	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V1004A17UHS	18,900	\$2,646
214075551	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	U802VA075317M	18,800	\$2,632
214075550	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	U98MV0703A17UPS	19,000	\$2,660
214075541	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R921V0603A17M4S	19,000	\$2,660
214075538	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R921V0403A17M4S	19,000	\$2,660
214075536	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0503A14DZ	18,900	\$2,646
214075533	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0403A17UHU	19,100	\$2,674
214075532	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V1004A17UH	18,800	\$2,632
214075531	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	U802VA075317Z	18,900	\$2,646
214075522	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0504A17UHS	19,000	\$2,660
214075521	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0503A14UHN	19,000	\$2,660
214075520	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	U97MV0603A17DHS	19,000	\$2,660
214075519	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0754A17DZ	18,900	\$2,646
214075516	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0504A17UHN	19,000	\$2,660
214075513	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0704A17UHU	19,000	\$2,660
214075512	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0603A17UHU	19,100	\$2,674
214075507	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V1004A17UHN	18,900	\$2,646
214075504	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R962V0703A17M4S	19,000	\$2,660
214075503	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0403A17M4S	19,000	\$2,660
214075492	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0503A14UHS	19,000	\$2,660
214075477	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0754A17UHN	18,900	\$2,646
214075468	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R962V0603A17M4S	19,000	\$2,660
214075465	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0503A14DZ	18,900	\$2,646
214075462	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	U98MV0603A17UPS	19,000	\$2,660
214075459	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0703A17M4S	19,000	\$2,660
214075456	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0754A17UHN	18,900	\$2,646
214075453	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R962V0403A17M4S	19,000	\$2,660
214075449	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0754A17UHS	18,900	\$2,646
214075437	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0754A17UHS	18,900	\$2,646
214075435	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0504A17UHS	19,000	\$2,660
214075432	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R951V0603A17M4S	19,000	\$2,660
214075416	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	U97MV0703A17DHS	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214075411	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0754A17DZ	18,900	\$2,646
214075408	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R802V0504A17UHN	19,000	\$2,660
214075592	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	U802VA050317M	19,000	\$2,660
214075581	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R921V0703A17M4S	19,000	\$2,660
214075573	RUUD	RD17AZ24AJ3N	RCFZ2417MTANM	R801V0503A14UH	19,000	\$2,660
214233326	RUUD	RD17AZ36AJ3N	RH3VZ4821STACN		31,200	\$4,368
214097946	RUUD	RD17AZ48AJ3N	RH3VZ6024STACN		43,000	\$6,020
214095454	RUUD	RD17AZ24AJ3N	RH3VZ3617STACN		18,700	\$2,618
206221528	RUUD	ROMH36FXZHJ	Combination heat pumps with or without ducts		21,400	\$2,996
206221538	RUUD	ROSH18VGSN	RICH18AXCJ		12,300	\$1,722
206221540	RUUD	ROSH30VGSN	RICH30AXCJ		20,200	\$2,828
206221541	RUUD	ROSH36VGSN	RICH36AXCJ		23,200	\$3,248
206221491	RUUD	ROSH18ASJ	UIWH18ASJ		11,500	\$1,610
206221516	RUUD	ROSH18AFCJ	RIDH18AVFJ		13,600	\$1,904
206221492	RUUD	ROSH24ASJ	UIWH24ASJ		15,300	\$2,142
206221499	RUUD	ROSH18AXFWJ	UIWH18AVFJ		14,600	\$2,044
206221512	RUUD	ROSH12AFFJ	RIFH12AVFJ		10,600	\$1,484
206221505	RUUD	ROSH18AHXHJ	UIWH18AVFJ		14,600	\$2,044
206221527	RUUD	ROMH36FXZHJ	Heat pump with ducts		21,400	\$2,996
206221526	RUUD	ROMH36FXZHJ	Heat pump without ducts		21,400	\$2,996
206221520	RUUD	ROMH18FXZHJ	Heat pump without ducts		14,200	\$1,988
211044464	RUUD	RO3HFZ24AJ1H	Heat pump without ducts		15,400	\$2,156
211044466	RUUD	RO3HFZ24AJ1H	Heat pump with ducts		15,400	\$2,156
211044462	RUUD	RO2HFZ18AJ1H	Heat pump with ducts		14,200	\$1,988
211781770	RUUD	RD16AZ30AJHUA	RHMOVZ3021SNAUNJ		21,600	\$3,024
211781771	RUUD	RD16AZ36AJHUA	RHMOVZ3621MNAUAJ		25,600	\$3,584
210824767	RUUD	RO4HFZ36AJ1H	Heat pump without ducts		21,400	\$2,996
211044460	RUUD	RO2HFZ18AJ1H	Heat pump without ducts		14,200	\$1,988
210824724	RUUD	RO1HHZ12AJ8S	RIMHHZ12AJ8S		10,500	\$1,470
211781772	RUUD	RD16AZ48AJHUA	RHMOVZ4821SNAUAJ		34,400	\$4,816
210368115	RUUD	RO1HHZ18AJ2S	UIWHHZ18AJ2S		13,600	\$1,904
210368125	RUUD	RO1HHZ36AJ3S	UIWHHZ36AJ3S		22,400	\$3,136
210368123	RUUD	RO1HHZ30AJ3S	UIWHHZ30AJ3S		19,400	\$2,716
210824714	RUUD	RO1HHZ12AJ8S	RICHHZ12AJ8S		10,700	\$1,498
210824720	RUUD	RO1HHZ18AJ8S	RICHHZ18AJ8S		14,700	\$2,058
211044470	RUUD	RO4HFZ36AJ1H	Heat pump with ducts		21,400	\$2,996
210824729	RUUD	RO1HGZ42AJ8S	RIMHGZ42AJ8S		29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210368089	RUUD	RO1HFZ18AJ2H	UIWHFZ18AJ2S		14,600	\$2,044
210368079	RUUD	RO1HFZ12AJ2S	RIFHFZ12AJ2S		10,600	\$1,484
211781765	RUUD	RO1HHZ24AJ8S	RISHHZ24AJ8S		17,500	\$2,450
211781766	RUUD	RO1HHZ30AJ8S	RISHHZ30AJ8S		21,000	\$2,940
211781767	RUUD	RO1HHZ36AJ8S	RISHHZ36AJ8S		24,200	\$3,388
211781768	RUUD	RD16AZ24AJVUA	RHMOVZ2421MNAUNJ		18,700	\$2,618
211781769	RUUD	RD16AZ30AJVUA	RHMOVZ3021SNAUNJ		21,800	\$3,052
211781757	RUUD	RO1HHZ24AJ8S	RIMHHZ24AJ8S		18,100	\$2,534
211781758	RUUD	RO1HHZ30AJ8S	RIMHHZ30AJ8S		21,200	\$2,968
211781759	RUUD	RO1HHZ36AJ8S	RIMHHZ36AJ8S		25,800	\$3,612
211781761	RUUD	RO1HHZ24AJ8S	RIGHHZ24AJ8S		18,000	\$2,520
211781762	RUUD	RO1HHZ30AJ8S	RIGHHZ30AJ8S		20,800	\$2,912
211781763	RUUD	RO1HHZ36AJ8S	RIGHHZ36AJ8S		24,600	\$3,444
206221523	RUUD	ROMH24FXZHJ	Heat pump without ducts		15,400	\$2,156
206221522	RUUD	ROMH18FXZHJ	Combination heat pumps with or without ducts		14,200	\$1,988
206221525	RUUD	ROMH24FXZHJ	Combination heat pumps with or without ducts		15,400	\$2,156
206221539	RUUD	ROSH24VGSN	RICH24AXCJ		16,400	\$2,296
206221513	RUUD	ROSH15AFFJ	RIFH15AVFJ		11,600	\$1,624
206221518	RUUD	ROSH12AFCJ	RICH12AVFJ		10,200	\$1,428
206221519	RUUD	ROSH18AFCJ	RICH18AVFJ		13,600	\$1,904
206221495	RUUD	ROSH12AHWJ	UIWH12AHWJ		9,600	\$1,344
206221496	RUUD	ROSH15AHWJ	UIWH15AHWJ		11,200	\$1,568
206221515	RUUD	ROSH12AFCJ	RIDH12AVFJ		9,500	\$1,330
206221507	RUUD	ROSH30AHXHJ	UIWH30AVFJ		18,900	\$2,646
206221509	RUUD	ROSH12AFFHJ	RIFH12AVFJ		10,600	\$1,484
206221504	RUUD	ROSH15AHHJ	UIWH15AHWJ		11,200	\$1,568
206221503	RUUD	ROSH12AHHJ	UIWH12AHWJ		9,600	\$1,344
206221524	RUUD	ROMH24FXZHJ	Heat pump with ducts		15,400	\$2,156
206221521	RUUD	ROMH18FXZHJ	Heat pump with ducts		14,200	\$1,988
216441735	SAMSUNG	AC048DXSCCG	AC048DNZDCG		41,500	\$5,810
216441734	SAMSUNG	AC036DXSCCG	AC036DNZDCG		29,000	\$4,060
216441733	SAMSUNG	AC030DXSCCG	AC030DNZDCG		25,400	\$3,556
216441726	SAMSUNG	AC018DXSCCG	AC018DNJDCG		11,900	\$1,666
207462389	SAMSUNG	AC024BXADCH	AC024BN4DCH		31,200	\$4,368
207462388	SAMSUNG	AC018BXADCH	AC018BN4DCH		27,600	\$3,864
207698065	SAMSUNG	AC030BXSCCH	AC030BN4DCH		37,000	\$5,180

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207698071	SAMSUNG	AC036BXSCCH	AC036BN4DCH		40,500	\$5,670
207465448	SAMSUNG	AC018BXADCH	AC018BNHDCH		25,600	\$3,584
207698072	SAMSUNG	AC036BXSCCH	AC036BNHDCH		38,500	\$5,390
207698066	SAMSUNG	AC030BXSCCH	AC030BNZDCH		31,800	\$4,452
207465461	SAMSUNG	AC036BXADCH	AC036BN6DCH		33,600	\$4,704
207462390	SAMSUNG	AC036BXADCH	AC036BN4DCH		37,000	\$5,180
207462391	SAMSUNG	AC042BXADCH	AC042BN4DCH		46,000	\$6,440
207465458	SAMSUNG	AC030BXADCH	AC030BNHDCH		33,000	\$4,620
207698067	SAMSUNG	AC036BXSCCH	AC036BNZDCH		37,000	\$5,180
210273924	SAMSUNG	AC036BXUPCH	AV360CT		40,500	\$5,670
207698070	SAMSUNG	AC030BXSCCH	AC030BNHDCH		33,400	\$4,676
202064264	SAMSUNG	AM036NXMDCR	Heat pump with ducts		25,000	\$3,500
202084065	SAMSUNG	AM060NXMDCR	Heat pump with ducts		43,000	\$6,020
10147096	SAMSUNG	AM060MXMDCH	Heat pump with ducts		43,000	\$6,020
205230038	SAMSUNG	AM036TXMDCH	Heat pump with ducts		25,000	\$3,500
206918724	SAMSUNG	AM036TXMDCH	Combination heat pumps with or without ducts		25,000	\$3,500
206918723	SAMSUNG	AM036NXMDCR	Combination heat pumps with or without ducts		25,000	\$3,500
206918726	SAMSUNG	AM048TXMDCH	Combination heat pumps with or without ducts		29,000	\$4,060
206918725	SAMSUNG	AM048NXMDCR	Combination heat pumps with or without ducts		29,000	\$4,060
206918729	SAMSUNG	AM060MXMDCH	Combination heat pumps with or without ducts		43,000	\$6,020
206918730	SAMSUNG	AM060NXMDCR	Combination heat pumps with or without ducts		43,000	\$6,020
202083773	SAMSUNG	AM048NXMDCR	Heat pump with ducts		29,000	\$4,060
205230039	SAMSUNG	AM048TXMDCH	Heat pump with ducts		29,000	\$4,060
210299846	SAMSUNG	AC024BXUPCH	AV240BT		31,200	\$4,368
10147097	SAMSUNG	AM060MXMDCH	Heat pump without ducts		43,000	\$6,020
202057118	SAMSUNG	AM048NXMDCR	Heat pump without ducts		31,600	\$4,424
202083810	SAMSUNG	AM053NXMDCR	Heat pump without ducts		36,400	\$5,096
202083996	SAMSUNG	AM060NXMDCR	Heat pump without ducts		43,000	\$6,020
202098116	SAMSUNG	AM036NXMDCR	Heat pump without ducts		25,000	\$3,500
205142809	SAMSUNG	AM036TXMDCH	Heat pump without ducts		25,000	\$3,500
205142810	SAMSUNG	AM048TXMDCH	Heat pump without ducts		31,600	\$4,424
205230040	SAMSUNG	AM053TXMDCH	Heat pump without ducts		36,400	\$5,096

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206918727	SAMSUNG	AM053NXMDCR	Combination heat pumps with or without ducts		36,400	\$5,096
206918728	SAMSUNG	AM053TXMDCH	Combination heat pumps with or without ducts		36,400	\$5,096
215222779	SAMSUNG	AR15DXDABWKX	AR15DXDABWKN		14,000	\$1,960
215399293	SAMSUNG	AR12DXDABWKX	AR12DXDABWKN		10,600	\$1,484
215220929	SAMSUNG	AC018DXSCCG	AC018DNLDCG		16,200	\$2,268
215220729	SAMSUNG	AC018DXSCCG	AC018DNND CG		15,600	\$2,184
215220726	SAMSUNG	AC018DXSCCG	AC018DN1DCG		16,000	\$2,240
215386399	SAMSUNG	AC048DXSCCG	AC048DNHDCG		41,000	\$5,740
215385460	SAMSUNG	AC048DXSCCG	AC048DN4DCG		42,000	\$5,880
215385461	SAMSUNG	AC048DXSCCG	AC048DN6DCG		40,500	\$5,670
215220727	SAMSUNG	AC018DXSCCG	AC018DN6DCG		13,400	\$1,876
215399295	SAMSUNG	AR12DXFAMWKX	AR12DXKAPWKN		10,900	\$1,526
215399297	SAMSUNG	AR12DXFAMWKX	AR12DXFAMWKN		10,900	\$1,526
215222778	SAMSUNG	AR15DXDACWKX	AR15DXDABWKN		14,000	\$1,960
215399291	SAMSUNG	AR12DXDACWKX	AR12DXDABWKN		10,600	\$1,484
207350834	SAMSUNG	AJ036BXS4CH	Combination heat pumps with or without ducts		21,000	\$2,940
207349919	SAMSUNG	AJ030BXS4CH	Heat pump without ducts		17,500	\$2,450
207350092	SAMSUNG	AJ020BXS3CH	Combination heat pumps with or without ducts		13,000	\$1,820
210273925	SAMSUNG	AC060BXUPCH	AV600CT		54,000	\$7,560
207349917	SAMSUNG	AJ020BXS3CH	Heat pump without ducts		13,100	\$1,834
211133471	SAMSUNG	AC024BXUPCH	BVRMB3925		31,200	\$4,368
211133468	SAMSUNG	AC036BXUDCH	BVRMC3937		36,000	\$5,040
210273923	SAMSUNG	AC036BXUDCH	AV360CT		36,000	\$5,040
205142812	SAMSUNG	AM053TXMDCH	Heat pump with ducts		36,400	\$5,096
202083811	SAMSUNG	AM053NXMDCR	Heat pump with ducts		36,400	\$5,096
213372420	SAMSUNG	AJ036CXS4CH	Combination heat pumps with or without ducts		21,800	\$3,052
213372419	SAMSUNG	AJ030CXS4CH	Combination heat pumps with or without ducts		17,300	\$2,422
213372418	SAMSUNG	AJ024CXS4CH	Combination heat pumps with or without ducts		15,100	\$2,114
213353373	SAMSUNG	AJ030CXS4CH	Heat pump with ducts		17,200	\$2,408
213353372	SAMSUNG	AJ024CXS4CH	Heat pump with ducts		15,000	\$2,100
213353370	SAMSUNG	AJ036CXS4CH	Heat pump without ducts		23,000	\$3,220
213353369	SAMSUNG	AJ030CXS4CH	Heat pump without ducts		17,500	\$2,450

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211133472	SAMSUNG	AC048BXUPCH	BVRMC3948		46,000	\$6,440
211133469	SAMSUNG	AC036BXUPCH	BVRMC3937		40,500	\$5,670
211133470	SAMSUNG	AC060BXUPCH	BVRMC7960		54,000	\$7,560
207349920	SAMSUNG	AJ036BXS4CH	Heat pump without ducts		21,600	\$3,024
207698064	SAMSUNG	AR36BSHUMGMX	AR36BSHUMGMN		30,400	\$4,256
207349918	SAMSUNG	AJ024BXS4CH	Heat pump without ducts		14,600	\$2,044
210299847	SAMSUNG	AC048BXUPCH	AV480CT		46,000	\$6,440
207698063	SAMSUNG	AR15BSFACWKXCV	AR15BSFACWKNCV		11,500	\$1,610
207465436	SAMSUNG	AC048BXADCH	AC048BN4DCH		46,000	\$6,440
208128274	SEA BREEZE+	CSZ36H424ZMO	CA36H424ZMI		33,000	\$4,620
216014139	SEA BREEZE+	CSZ36H525ZMO	CA36H525ZMI		30,600	\$4,284
216014140	SEA BREEZE+	CSZ36H525ZMO	FC36H525ZMI		30,200	\$4,228
208128275	SEA BREEZE+	CSZ48H424ZMO	CA48H424ZMI		35,000	\$4,900
216014141	SEA BREEZE+	CSZ48H525ZMO	CA48H525ZMI		44,000	\$6,160
216014142	SEA BREEZE+	CSZ48H525ZMO	FC48H525ZMI		38,500	\$5,390
216014143	SEA BREEZE+	CSZ60H525ZMO	FC60H525ZMI		41,000	\$5,740
208816892	SEA BREEZE+	HMZ18H424ZMO	Heat pump without ducts		13,500	\$1,890
208816893	SEA BREEZE+	HMZ18H424ZMO	Heat pump with ducts		16,000	\$2,240
208816894	SEA BREEZE+	HMZ18H424ZMO	Combination heat pumps with or without ducts		14,700	\$2,058
216014159	SEA BREEZE+	HMZ18H525ZMO	Heat pump without ducts		17,600	\$2,464
216014161	SEA BREEZE+	HMZ18H525ZMO	Combination heat pumps with or without ducts		17,300	\$2,422
216014160	SEA BREEZE+	HMZ18H525ZMO	Heat pump with ducts		17,000	\$2,380
208816895	SEA BREEZE+	HMZ24H424ZMO	Heat pump without ducts		24,000	\$3,360
208816896	SEA BREEZE+	HMZ24H424ZMO	Heat pump with ducts		24,000	\$3,360
208816897	SEA BREEZE+	HMZ24H424ZMO	Combination heat pumps with or without ducts		24,000	\$3,360
216014163	SEA BREEZE+	HMZ27H525ZMO	Heat pump with ducts		23,000	\$3,220
216014164	SEA BREEZE+	HMZ27H525ZMO	Combination heat pumps with or without ducts		24,000	\$3,360
216014162	SEA BREEZE+	HMZ27H525ZMO	Heat pump without ducts		25,000	\$3,500
208128294	SEA BREEZE+	HMZ28H424ZMO	Heat pump without ducts		25,600	\$3,584
208128295	SEA BREEZE+	HMZ28H424ZMO	Heat pump with ducts		27,000	\$3,780
208128296	SEA BREEZE+	HMZ28H424ZMO	Combination heat pumps with or without ducts		26,200	\$3,668
208128297	SEA BREEZE+	HMZ36H424ZMO	Heat pump without ducts		35,000	\$4,900
208128298	SEA BREEZE+	HMZ36H424ZMO	Heat pump with ducts		23,000	\$3,220

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208128299	SEA BREEZE+	HMZ36H424ZMO	Combination heat pumps with or without ducts		35,000	\$4,900
216014165	SEA BREEZE+	HMZ36H525ZMO	Heat pump without ducts		30,000	\$4,200
216014166	SEA BREEZE+	HMZ36H525ZMO	Heat pump with ducts		33,000	\$4,620
216014167	SEA BREEZE+	HMZ36H525ZMO	Combination heat pumps with or without ducts		31,400	\$4,396
208816898	SEA BREEZE+	HMZ48H424ZMO	Heat pump without ducts		34,800	\$4,872
208816899	SEA BREEZE+	HMZ48H424ZMO	Heat pump with ducts		35,200	\$4,928
208816900	SEA BREEZE+	HMZ48H424ZMO	Combination heat pumps with or without ducts		35,000	\$4,900
216014168	SEA BREEZE+	HMZ48H525ZMO	Heat pump without ducts		44,000	\$6,160
216014170	SEA BREEZE+	HMZ48H525ZMO	Combination heat pumps with or without ducts		44,000	\$6,160
216014169	SEA BREEZE+	HMZ48H525ZMO	Heat pump with ducts		44,500	\$6,230
216014171	SEA BREEZE+	HMZ55H525ZMO	Heat pump without ducts		44,000	\$6,160
216014172	SEA BREEZE+	HMZ55H525ZMO	Heat pump with ducts		45,000	\$6,300
216014173	SEA BREEZE+	HMZ55H525ZMO	Combination heat pumps with or without ducts		44,500	\$6,230
208128267	SEA BREEZE+	HSZ12H424ZMO	WM12H424ZMI		10,300	\$1,442
208128268	SEA BREEZE+	HSZ12H424ZMO	CA12H424ZMI		9,900	\$1,386
208128269	SEA BREEZE+	HSZ12H424ZMO	D12H424ZMI		10,600	\$1,484
212595647	SEA BREEZE+	HSZ12H424ZMO	SCA12H424ZMI		9,500	\$1,330
212595648	SEA BREEZE+	HSZ12H424ZMO	C12H424ZMI		10,200	\$1,428
216014124	SEA BREEZE+	HSZ12H525ZMO	WM12H525ZMI		9,800	\$1,372
216014125	SEA BREEZE+	HSZ12H525ZMO	CA12H525ZMI		10,000	\$1,400
216014126	SEA BREEZE+	HSZ12H525ZMO	SCA12H525ZMI		9,600	\$1,344
216014127	SEA BREEZE+	HSZ12H525ZMO	C12H525ZMI		9,800	\$1,372
216014128	SEA BREEZE+	HSZ12H525ZMO	D12H525ZMI		10,200	\$1,428
208816890	SEA BREEZE+	HSZ18H424ZMO	WM18H424ZMI		11,100	\$1,554
212595650	SEA BREEZE+	HSZ18H424ZMO	SCA18H424ZMI		14,500	\$2,030
212595651	SEA BREEZE+	HSZ18H424ZMO	D18H424ZMI		15,000	\$2,100
216014129	SEA BREEZE+	HSZ18H525ZMO	WM18H525ZMI		16,600	\$2,324
216014130	SEA BREEZE+	HSZ18H525ZMO	CA18H525ZMI		14,900	\$2,086
216014131	SEA BREEZE+	HSZ18H525ZMO	SCA18H525ZMI		14,500	\$2,030
216014132	SEA BREEZE+	HSZ18H525ZMO	C18H525ZMI		14,200	\$1,988
216014133	SEA BREEZE+	HSZ18H525ZMO	FC18H525ZMI		14,400	\$2,016
216014134	SEA BREEZE+	HSZ18H525ZMO	D18H525ZMI		15,000	\$2,100
208816891	SEA BREEZE+	HSZ24H424ZMO	WM24H424ZMI		18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212595654	SEA BREEZE+	HSZ24H424ZMO	CA24H424ZMI		21,000	\$2,940
212595655	SEA BREEZE+	HSZ24H424ZMO	D24H424ZMI		21,000	\$2,940
212595656	SEA BREEZE+	HSZ24H424ZMO	FC24H424ZMI		19,000	\$2,660
216014135	SEA BREEZE+	HSZ24H525ZMO	WM24H525ZMI		21,000	\$2,940
216014136	SEA BREEZE+	HSZ24H525ZMO	CA24H525ZMI		20,400	\$2,856
216014137	SEA BREEZE+	HSZ24H525ZMO	FC24H525ZMI		20,200	\$2,828
216014138	SEA BREEZE+	HSZ24H525ZMO	D24H525ZMI		21,600	\$3,024
216014154	SEA BREEZE+	MZ48H525ZMO	Heat pump with ducts		37,000	\$5,180
216014178	SEA BREEZE+	HSZ18H525ZMO	AH18H525ZMI		14,000	\$1,960
216014179	SEA BREEZE+	HSZ24H525ZMO	AH24H525ZMI		16,900	\$2,366
215735319	SENVILLE	SENA-36HF-MOA	Combination heat pumps with or without ducts		31,400	\$4,396
215735317	SENVILLE	SENA-36HF-MOA	Heat pump without ducts		30,000	\$4,200
207657628	SENVILLE	SENA/12HF/OQ	SENA/12HF/IQ		10,000	\$1,400
207571419	SENVILLE	SENA/12HF/OQ	SENA/12HF/IQ		10,000	\$1,400
207571420	SENVILLE	SENA/18HF/OQ	SENA/18HF/IQ		15,000	\$2,100
207657629	SENVILLE	SENA/18HF/OQ	SENA/18HF/IQ		15,000	\$2,100
207657630	SENVILLE	SENA/24HF/OQ	SENA/24HF/IQ		21,200	\$2,968
207571421	SENVILLE	SENA/24HF/OQ	SENA/24HF/IQ		21,200	\$2,968
207641342	SENVILLE	SENA/12HF/OQ	SENA/12HF/ICZ		9,900	\$1,386
207641349	SENVILLE	SENA/12HF/OQ	SENA/12HF/IFQ		9,600	\$1,344
207641347	SENVILLE	SENA/18HF/OQ	SENA/18HF/ID		15,000	\$2,100
207641344	SENVILLE	SENA/24HF/OQ	SENA/24HF/ICQ		21,000	\$2,940
210372990	SENVILLE	SENA/12HF/OQ	SENA-12HF-IFU		10,200	\$1,428
213386472	SENVILLE	SEND-24HF-OM	SEND-24HF-IM		19,200	\$2,688
213732655	SENVILLE	SENA-28HF-MOB	Combination heat pumps with or without ducts		26,800	\$3,752
213732650	SENVILLE	SENA-18HF-MOB	Heat pump without ducts		15,000	\$2,100
213732659	SENVILLE	SENA-48HF-MOB	Heat pump without ducts		36,000	\$5,040
213732654	SENVILLE	SENA-28HF-MOB	Heat pump with ducts		27,000	\$3,780
213732653	SENVILLE	SENA-28HF-MOB	Heat pump without ducts		26,600	\$3,724
210426579	SENVILLE	SEND-36HF-OM	SEND-36HF-IM		30,400	\$4,256
207641348	SENVILLE	SENA/24HF/OQ	SENA/24HF/ID		21,000	\$2,940
213732660	SENVILLE	SENA-48HF-MOB	Heat pump with ducts		36,000	\$5,040
207641346	SENVILLE	SENA/12HF/OQ	SENA/12HF/ID		10,600	\$1,484
207641351	SENVILLE	SENA/24HF/OQ	SENA/24HF/IF		19,000	\$2,660
213732651	SENVILLE	SENA-18HF-MOB	Heat pump with ducts		16,000	\$2,240

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213732652	SENVILLE	SENA-18HF-MOB	Combination heat pumps with or without ducts		15,500	\$2,170
213732661	SENVILLE	SENA-48HF-MOB	Combination heat pumps with or without ducts		36,000	\$5,040
215735297	SENVILLE	SENA-18HF-OG	SENA-18HF-IGG		16,600	\$2,324
215735308	SENVILLE	SENA-12HF-OG	SENA-12HF-IFG		9,800	\$1,372
215735296	SENVILLE	SENA-12HF-OG	SENA-12HF-IGG		9,800	\$1,372
215735326	SENVILLE	SEND-24HF-OG	SEND-24HF-IG		20,000	\$2,800
215735328	SENVILLE	SEND-36HF-OG	SEND-36HF-IG		31,800	\$4,452
216623594	SENVILLE	SENA-12HF-OG	SENA-12HF-1WCG		9,600	\$1,344
216623595	SENVILLE	SENA-18HF-OG	SENA-18HF-1WCG		14,500	\$2,030
215735303	SENVILLE	SENA-24HF-OG	SENA-24HF-IDG		21,600	\$3,024
215735302	SENVILLE	SENA-18HF-OG	SENA-18HF-IDG		15,000	\$2,100
215735301	SENVILLE	SENA-12HF-OG	SENA-12HF-IDG		9,600	\$1,344
215735325	SENVILLE	SENA-55HF-MOA	Combination heat pumps with or without ducts		44,500	\$6,230
215735324	SENVILLE	SENA-55HF-MOA	Heat pump with ducts		45,000	\$6,300
215735323	SENVILLE	SENA-55HF-MOA	Heat pump without ducts		44,000	\$6,160
215735322	SENVILLE	SENA-48HF-MOA	Combination heat pumps with or without ducts		44,000	\$6,160
215735321	SENVILLE	SENA-48HF-MOA	Heat pump with ducts		44,500	\$6,230
215735320	SENVILLE	SENA-48HF-MOA	Heat pump without ducts		44,000	\$6,160
215735318	SENVILLE	SENA-36HF-MOA	Heat pump with ducts		33,000	\$4,620
215735316	SENVILLE	SENA-28HF-MOA	Combination heat pumps with or without ducts		24,000	\$3,360
215735315	SENVILLE	SENA-28HF-MOA	Heat pump with ducts		23,000	\$3,220
215735314	SENVILLE	SENA-28HF-MOA	Heat pump without ducts		25,000	\$3,500
215735313	SENVILLE	SENA-18HF-MOA	Combination heat pumps with or without ducts		17,300	\$2,422
215735312	SENVILLE	SENA-18HF-MOA	Heat pump with ducts		17,000	\$2,380
215735311	SENVILLE	SENA-18HF-MOA	Heat pump without ducts		17,600	\$2,464
215735310	SENVILLE	SENA-24HF-OG	SENA-24HF-IFG		20,200	\$2,828
215735307	SENVILLE	SENA-24HF-OG	SENA-24HF-ICG		20,400	\$2,856
215735309	SENVILLE	SENA-18HF-OG	SENA-18HF-IFG		14,400	\$2,016
215735306	SENVILLE	SENA-18HF-OG	SENA-18HF-ICG		14,900	\$2,086
215735305	SENVILLE	SENA-12HF-OG	SENA-12HF-ICG		10,000	\$1,400
215735299	SENVILLE	SENA-33HF-OG	SENA-33HF-IGG		30,000	\$4,200
215735298	SENVILLE	SENA-24HF-OG	SENA-24HF-IGG		21,000	\$2,940
215735330	SENVILLE	SEND-60HF-OG	SEND-60HF-IG		45,000	\$6,300

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215735329	SENVILLE	SEND-48HF-OG	SEND-48HF-IG		37,000	\$5,180
215735327	SENVILLE	SEND-30HF-OG	SEND-30HF-IG		23,800	\$3,332
213732656	SENVILLE	SENA-36HF-MOB	Heat pump without ducts		27,400	\$3,836
213732657	SENVILLE	SENA-36HF-MOB	Heat pump with ducts		30,000	\$4,200
213732658	SENVILLE	SENA-36HF-MOB	Combination heat pumps with or without ducts		28,600	\$4,004
213386474	SENVILLE	SEND-60HF-OM	SEND-60HF-IM		42,000	\$5,880
213386473	SENVILLE	SEND-48HF-OM	SEND-48HF-IM		36,000	\$5,040
205921393	SENVILLE	SENA/24HF/OZ	SENA/24HF/ID		17,200	\$2,408
211749871	SENVILLE	SENA-33HF-OQ	SENA-33HF-IQ		28,800	\$4,032
216625965	SHARP	AE-X15ZU1	AY-XP15ZU1-B		18,100	\$2,534
216624517	SHARP	AE-X12CPU	AY-XP12CPU		15,000	\$2,100
209270207	SHARP	AE-X12ZU	AY-XPC12ZU		14,500	\$2,030
209423516	SHARP	AE-X12ZHU	AY-XP12ZHU		18,900	\$2,646
213238803	SHARP	AE-X12ZHU1	AY-XP12ZHU1		18,900	\$2,646
213194987	SHARP	AE-X12ZU1	AY-XP12ZU1		14,500	\$2,030
213239134	SHARP	AE-X15ZU1	AY-XP15ZU1		18,100	\$2,534
213927543	SHARP	AE-X3M24BU	AY-XPC9/12/18BU		25,000	\$3,500
213246054	SHARP	AE-X24ZU1	AY-XP24ZU1		22,400	\$3,136
213246053	SHARP	AE-X18ZU1	AY-XP18ZU1		22,000	\$3,080
210301933	SHARP	AE-X18ZU	AY-XPC18ZU		22,000	\$3,080
210363336	SHARP	AE-X24ZU	AY-XPC24ZU		22,400	\$3,136
216699321	SLIMAIR	SHC18AH2AG	SHM18AE2AG		14,400	\$2,016
216699320	SLIMAIR	SHC12AH2AG	SHM12AE2AG		10,000	\$1,400
213886038	SLIMAIR	SHC2Z18VE2AG	Heat pump without ducts		13,500	\$1,890
213886042	SLIMAIR	SHC3Z27VE2AG	Heat pump with ducts		27,000	\$3,780
213886049	SLIMAIR	SHC5Z48VE2AG	Combination heat pumps with or without ducts		37,400	\$5,236
213886041	SLIMAIR	SHC3Z27VE2AG	Heat pump without ducts		25,600	\$3,584
213886043	SLIMAIR	SHC3Z27VE2AG	Combination heat pumps with or without ducts		26,200	\$3,668
213886050	SLIMAIR	SHC5Z55VE2AG	Heat pump without ducts		34,800	\$4,872
213886051	SLIMAIR	SHC5Z55VE2AG	Heat pump with ducts		35,200	\$4,928
213886052	SLIMAIR	SHC5Z55VE2AG	Combination heat pumps with or without ducts		35,000	\$4,900
214728301	SLIMAIR	SHC12VH2AG	SHLZ12VC2AG		9,900	\$1,386
214728305	SLIMAIR	SHC24VH2AG	SHS24VC2AG		19,000	\$2,660
214728303	SLIMAIR	SHC24VH2AG	SHLZ24VC2AG		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208447941	SLIMAIR	SHCD12VC2AG	SHMZ12VC2AG		10,300	\$1,442
213886032	SLIMAIR	SHC12VH2AG	SHM12VE2AG		10,300	\$1,442
213886033	SLIMAIR	SHC18VH2AG	SHM18VE2AG		11,100	\$1,554
208447942	SLIMAIR	SHCD18VC2AG	SHMZ18VC2AG		11,100	\$1,554
208447943	SLIMAIR	SHCD24VC2AG	SHMZ24VC2AG		18,900	\$2,646
213886034	SLIMAIR	SHC24VH2AG	SHM24VE2AG		18,900	\$2,646
213886046	SLIMAIR	SHC4Z36VE2AG	Combination heat pumps with or without ducts		35,000	\$4,900
213886048	SLIMAIR	SHC5Z48VE2AG	Heat pump with ducts		36,000	\$5,040
213886040	SLIMAIR	SHC2Z18VE2AG	Combination heat pumps with or without ducts		14,700	\$2,058
213886047	SLIMAIR	SHC5Z48VE2AG	Heat pump without ducts		39,000	\$5,460
213886039	SLIMAIR	SHC2Z18VE2AG	Heat pump with ducts		16,000	\$2,240
213886044	SLIMAIR	SHC4Z36VE2AG	Heat pump without ducts		35,000	\$4,900
214606466	SLIMAIR	SHD24VH2AG	SHD24VC2AG		21,000	\$2,940
214606465	SLIMAIR	SHC18VH2AG	SHD18VC2AG		15,000	\$2,100
214606464	SLIMAIR	SHC12VH2AG	SHD12VC2AG		10,600	\$1,484
216763031	SLIMAIR	SHC48AE224V	SHV48AE2AG		32,400	\$4,536
216763028	SLIMAIR	SHC24AE224V	SHV24AE2AG		20,000	\$2,800
216763038	SLIMAIR	SHC60AH224V	SHV60AE2AG		45,000	\$6,300
216763037	SLIMAIR	SHC48AH224V	SHV48AE2AG		37,000	\$5,180
216763036	SLIMAIR	SHC36AH224V	SHV36AE2AG		31,800	\$4,452
216763035	SLIMAIR	SHC30AH224V	SHV30AE2AG		23,800	\$3,332
216763034	SLIMAIR	SHC24AH224V	SHV24AE2AG		20,000	\$2,800
216763033	SLIMAIR	SHC18AH224V	SHV18AE2AG		15,000	\$2,100
216699353	SLIMAIR	SHC48AH2AG	SHL48AC2AG		44,000	\$6,160
216699352	SLIMAIR	SHC36AH2AG	SHL36AC2AG		30,600	\$4,284
216699351	SLIMAIR	SHC24AH2AG	SHL24AC2AG		20,400	\$2,856
216699350	SLIMAIR	SHC18AH2AG	SHL18AC2AG		14,900	\$2,086
216699349	SLIMAIR	SHC12AH2AG	SHL12AC2AG		10,000	\$1,400
216699342	SLIMAIR	SHC55AH2AG	SHS60AC2AG		41,000	\$5,740
216699341	SLIMAIR	SHC48AH2AG	SHS48AC2AG		38,500	\$5,390
216699340	SLIMAIR	SHC36AH2AG	SHS36AC2AG		30,200	\$4,228
216699339	SLIMAIR	SHC24AH2AG	SHS24AC2AG		20,200	\$2,828
216699338	SLIMAIR	SHC18AH2AG	SHS18AC2AG		14,400	\$2,016
216699330	SLIMAIR	SHC55AH2AG	SHD60AC2AG		45,000	\$6,300
216699329	SLIMAIR	SHC48AH2AG	SHD48AC2AG		45,000	\$6,300
216699328	SLIMAIR	SHC36AH2AG	SHD36AC2AG		31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216699327	SLIMAIR	SHC24AH2AG	SHD24AC2AG		21,600	\$3,024
216699326	SLIMAIR	SHC18AH2AG	SHD18AC2AG		15,000	\$2,100
216699325	SLIMAIR	SHC12AH2AG	SHD12AC2AG		10,200	\$1,428
216699323	SLIMAIR	SHC30AH2AG	SHM30AE2AG		29,600	\$4,144
216699322	SLIMAIR	SHC24AH2AG	SHM24AE2AG		21,600	\$3,024
216626018	SLIMAIR	SHC3Z27AH2AG	Heat pump without ducts		23,600	\$3,304
216626017	SLIMAIR	SHC2Z18AH2AG	Combination heat pumps with or without ducts		16,700	\$2,338
216626016	SLIMAIR	SHC2Z18AH2AG	Heat pump with ducts		17,000	\$2,380
216626015	SLIMAIR	SHC2Z18AH2AG	Heat pump without ducts		16,400	\$2,296
216626020	SLIMAIR	SHC3Z27AH2AG	Combination heat pumps with or without ducts		23,200	\$3,248
216626019	SLIMAIR	SHC3Z27AH2AG	Heat pump with ducts		23,000	\$3,220
216626023	SLIMAIR	SHC4Z36AH2AG	Combination heat pumps with or without ducts		34,800	\$4,872
216626022	SLIMAIR	SHC4Z36AH2AG	Heat pump with ducts		33,000	\$4,620
216626021	SLIMAIR	SHC4Z36AH2AG	Heat pump without ducts		36,600	\$5,124
216626024	SLIMAIR	SHC5Z48AH2AG	Heat pump without ducts		40,500	\$5,670
216626026	SLIMAIR	SHC5Z48AH2AG	Combination heat pumps with or without ducts		42,500	\$5,950
216626025	SLIMAIR	SHC5Z48AH2AG	Heat pump with ducts		44,500	\$6,230
216626027	SLIMAIR	SHC5Z55AH2AG	Heat pump without ducts		45,000	\$6,300
216626028	SLIMAIR	SHC5Z55AH2AG	Heat pump with ducts		45,000	\$6,300
216626029	SLIMAIR	SHC5Z55AH2AG	Combination heat pumps with or without ducts		45,000	\$6,300
214606468	SLIMAIR	SHC48VH2AG	SHD48VC2AG		39,500	\$5,530
214606469	SLIMAIR	SHC55VH2AG	SHD60VC2AG		40,000	\$5,600
213927691	SLIMAIR	SHC30VH2AG	SHM30VE2AG		27,800	\$3,892
206361910	SMART COMFORT	DLCSRBH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361912	SMART COMFORT	DLCSRBH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361911	SMART COMFORT	DLCSRBH18AAK	DLFSHBH18XAK		11,100	\$1,554
210857459	SMART COMFORT	DLCSRBH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857460	SMART COMFORT	DLCSRBH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132705	SMART COMFORT	DLCSRBH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948199	SMART COMFORT	DLCSRBH12AAK	DLFSFBH12XAK		10,200	\$1,428
207683383	SMART COMFORT	DLCSRBH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447679	SMART COMFORT	DLCSRBH24AAK	DLFSCHH24XAK		21,200	\$2,968
208447683	SMART COMFORT	DLCSRBH18AAK	DLFSCHH18XAK		15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
208447678	SMART COMFORT	DLCSRBH12AAK	DLFSHCH12XAK		10,000	\$1,400
211132744	SMART COMFORT	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
211132703	SMART COMFORT	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
215324701	SMART COMFORT	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215323733	SMART COMFORT	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215319127	SMART COMFORT	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215319126	SMART COMFORT	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215319125	SMART COMFORT	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215319135	SMART COMFORT	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215319133	SMART COMFORT	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215319123	SMART COMFORT	D5CURAH48AAK	D5FUAAH48XAK		32,400	\$4,536
215319120	SMART COMFORT	D5CURAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215319118	SMART COMFORT	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215319117	SMART COMFORT	D5CUHAH60AAK	D5FUAAH60XAK		45,000	\$6,300
215319116	SMART COMFORT	D5CUHAH48AAK	D5FUAAH48XAK		37,000	\$5,180
215319115	SMART COMFORT	D5CUHAH36AAK	D5FUAAH36XAK		31,800	\$4,452
215319114	SMART COMFORT	D5CUHAH30AAK	D5FUAAH30XAK		23,800	\$3,332
215319113	SMART COMFORT	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215319112	SMART COMFORT	D5CUHAH24AAK	D5FUAAH24XAK		20,000	\$2,800
215324712	SMART COMFORT	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324711	SMART COMFORT	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324708	SMART COMFORT	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324706	SMART COMFORT	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324704	SMART COMFORT	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324703	SMART COMFORT	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324702	SMART COMFORT	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324699	SMART COMFORT	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324698	SMART COMFORT	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324697	SMART COMFORT	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324696	SMART COMFORT	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215413326	SMART COMFORT	D5CPRAH18AA	D5FPHAH18XAK		19,300	\$2,702
215413325	SMART COMFORT	D5CPRAH12AAK	D5FPHAH12XAK		11,000	\$1,540
215357537	SMART COMFORT	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357536	SMART COMFORT	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357535	SMART COMFORT	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215324707	SMART COMFORT	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324700	SMART COMFORT	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357563	SMART COMFORT	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357546	SMART COMFORT	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357545	SMART COMFORT	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357544	SMART COMFORT	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357543	SMART COMFORT	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357542	SMART COMFORT	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357541	SMART COMFORT	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357540	SMART COMFORT	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357539	SMART COMFORT	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620
215357538	SMART COMFORT	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357534	SMART COMFORT	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357533	SMART COMFORT	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357532	SMART COMFORT	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357528	SMART COMFORT	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357527	SMART COMFORT	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357526	SMART COMFORT	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324749	SMART COMFORT	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324747	SMART COMFORT	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324746	SMART COMFORT	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324744	SMART COMFORT	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324743	SMART COMFORT	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324710	SMART COMFORT	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324705	SMART COMFORT	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324750	SMART COMFORT	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324748	SMART COMFORT	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324745	SMART COMFORT	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324695	SMART COMFORT	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215319111	SMART COMFORT	D5CUHAH18AAK	D5FUAAH18XAK		15,000	\$2,100
215319134	SMART COMFORT	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215319130	SMART COMFORT	D5CSHAH33AAK	D5FSAAH36XBK		27,400	\$3,836
215319129	SMART COMFORT	D5CSHAH24AAK	D5FSAAH24XBK		16,900	\$2,366
215319128	SMART COMFORT	D5CSHAH18AAK	D5FSAAH18XBK		14,000	\$1,960
212982945	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80MSU0802120A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212982633	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80MSU0601716A*	23,200	\$3,248
212982405	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80MSU0401712A*	12,200	\$1,708
212982381	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80MSU0401712A*	12,200	\$1,708
213079330	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0802120A*	29,200	\$4,088
213079318	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0802120A*	29,200	\$4,088
213078934	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	29,400	\$4,116
213078910	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU1002120A*	29,600	\$4,144
213079186	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0601716A*	29,200	\$4,088
212982369	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0401712A*	19,100	\$2,674
212982705	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80MSU0601716A*	19,000	\$2,660
212982393	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80MSU0401712A*	12,400	\$1,736
212982225	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80MSU0401712A*	23,400	\$3,276
212982441	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU0401712A*	12,300	\$1,722
212981625	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80MSU1002120A*	23,200	\$3,248
212981541	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80MSU1002120A*	29,000	\$4,060
213078958	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80MSU0401712A*	29,400	\$4,116
212988056	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*96MSN1002120A*	23,600	\$3,304
212982729	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU0601716A*	19,000	\$2,660
212982357	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU0401712A*	19,100	\$2,674
212982333	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU0401712A*	19,400	\$2,716
213078886	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80MSU1002120A*	29,200	\$4,088
212988068	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96MSN1002120A*	23,600	\$3,304
212983005	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	23,600	\$3,304
212982693	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	23,400	\$3,276
213079282	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80MSU0802120A*	29,000	\$4,060
212982669	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80MSU0601716A*	23,200	\$3,248
212982417	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80MSU0401712A*	12,300	\$1,722
212982309	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80MSU0401712A*	18,800	\$2,632
213079150	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80MSU0601716A*	29,000	\$4,060
212981613	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80MSU1002120A*	23,600	\$3,304
212982717	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80MSU0601716A*	18,600	\$2,604
213078994	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80MSU0401712A*	29,000	\$4,060
212982177	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80MSU0401712A*	23,200	\$3,248
212981685	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MSU1002120A*	23,600	\$3,304
212982345	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU0401712A*	19,100	\$2,674
212982249	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80MSU0401712A*	19,400	\$2,716
212982141	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80MSU0401712A*	23,400	\$3,276
212981601	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80MSU1002120A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078862	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80MSU1002120A*	29,200	\$4,088
212988104	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	23,600	\$3,304
213079066	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0401712A*	29,400	\$4,116
213079054	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80MSU0401712A*	29,200	\$4,088
213079018	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80MSU0401712A*	29,000	\$4,060
212988044	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96MSN1002120A*	23,400	\$3,276
212982429	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU0401712A*	12,400	\$1,736
212982645	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80MSU0601716A*	23,400	\$3,276
212982297	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80MSU0401712A*	19,100	\$2,674
212982285	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80MSU0401712A*	19,000	\$2,660
212982273	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80MSU0401712A*	19,100	\$2,674
209852131	SMART COMFORT	DLCURAH36ABK	DLFUAAH36XAK		30,400	\$4,256
213079258	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80MSU0802120A*	29,000	\$4,060
213079222	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80MSU0802120A*	29,000	\$4,060
213079090	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80MSU0601716A*	29,400	\$4,116
212982321	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80MSU0401712A*	18,700	\$2,618
213079234	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80MSU0802120A*	29,400	\$4,116
213079174	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0601716A*	29,400	\$4,116
212982165	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80MSU0401712A*	23,400	\$3,276
213079210	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80MSU0802120A*	29,400	\$4,116
212982261	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80MSU0401712A*	18,600	\$2,604
213079114	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80MSU0601716A*	29,200	\$4,088
213079102	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80MSU0601716A*	29,000	\$4,060
212982153	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80MSU0401712A*	23,200	\$3,248
213079246	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80MSU0802120A*	29,400	\$4,116
213079306	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MSU0802120A*	29,400	\$4,116
212982981	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80MSU0802120A*	23,200	\$3,248
213080372	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002120A*	29,200	\$4,088
213080348	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	29,400	\$4,116
213080276	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002120A*	29,400	\$4,116
213079138	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80MSU0601716A*	29,000	\$4,060
213079078	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU0401712A*	29,200	\$4,088
213078838	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80MSU1002120A*	29,400	\$4,116
212988008	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002120A*	29,000	\$4,060
213079006	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80MSU0401712A*	29,400	\$4,116
213080300	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002120A*	29,400	\$4,116
213080288	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002120A*	29,200	\$4,088
212988080	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96MSN1002120A*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079162	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*80MSU0601716A*	29,600	\$4,144
213078970	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80MSU0401712A*	29,400	\$4,116
213080324	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002120A*	29,200	\$4,088
212982093	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80MSU0401712A*	28,800	\$4,032
213078874	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80MSU1002120A*	29,400	\$4,116
212988020	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002120A*	29,000	\$4,060
212969734	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412B*	19,300	\$2,702
213080360	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002120A*	29,200	\$4,088
213080312	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002120A*	29,400	\$4,116
213079270	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80MSU0802120A*	29,000	\$4,060
213078946	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MSU1002120A*	29,200	\$4,088
212971119	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*80VTL0451412B*	19,300	\$2,702
213078982	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80MSU0401712A*	29,200	\$4,088
211712148	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ESU1002120A*	23,200	\$3,248
211712136	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*95ESU1002120A*	23,400	\$3,276
211712125	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80VSL0701716A*	23,400	\$3,276
211712114	SMART COMFORT	DLCURAH30ABK	EA*4X36L21A*	*80ESU1002120A*	23,600	\$3,304
211712102	SMART COMFORT	DLCURAH30ABK	EA*4X36L21A*	*95ESU1002120A*	23,600	\$3,304
211709692	SMART COMFORT	DLCURAH30ABK	FJMA4*30L*B*		23,400	\$3,276
213353863	SMART COMFORT	DLCURAH36ABK	F5MA4*42L*C*		29,200	\$4,088
213353853	SMART COMFORT	DLCURAH36ABK	F5MA4*36L*B*		29,400	\$4,116
213249343	SMART COMFORT	DLCURAH36ABK	FEVA0036**+NAVA43601CK		29,400	\$4,116
213080881	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU0802120A*	29,200	\$4,088
213080869	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0802120A*	29,200	\$4,088
213080857	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	29,400	\$4,116
213080845	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*95MSU0802120A*	29,600	\$4,144
213080833	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95MSU0802120A*	29,200	\$4,088
213080821	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95MSU0802120A*	29,400	\$4,116
213080809	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95MSU0802120A*	29,400	\$4,116
213080797	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95MSU0802120A*	29,200	\$4,088
213080785	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95MSU0802120A*	29,400	\$4,116
213080773	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0601716A*	29,200	\$4,088
213080761	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	29,600	\$4,144
213080749	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*95MSU0601716A*	29,400	\$4,116
213080713	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95MSU0601716A*	29,200	\$4,088
213080701	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95MSU0601716A*	29,400	\$4,116
213080689	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95MSU0601716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080677	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*95MSU0601716A*	29,400	\$4,116
213080665	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95MSU0601716A*	29,400	\$4,116
213080653	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*95MSU0601716A*	29,600	\$4,144
213080641	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0401712A*	29,400	\$4,116
213080629	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0401712A*	29,600	\$4,144
213080617	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*95MSU0401712A*	29,400	\$4,116
211274903	SMART COMFORT	DLCURAH30ABK	FVM4X48***L		23,000	\$3,220
213080581	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95MSU0401712A*	29,200	\$4,088
213080569	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95MSU0401712A*	29,200	\$4,088
213080557	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95MSU0401712A*	29,600	\$4,144
213080545	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95MSU0401712A*	29,200	\$4,088
213080533	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*95MSU0401712A*	29,400	\$4,116
213080521	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95MSU0401712A*	29,600	\$4,144
213080509	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*95MSU0401712A*	29,600	\$4,144
213080477	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1202422A*	29,200	\$4,088
213080465	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96MSN1202422A*	29,400	\$4,116
213080265	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSM0802120A*	29,200	\$4,088
213080264	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN0802120A*	29,200	\$4,088
213080253	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSM0802120A*	29,200	\$4,088
213080252	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0802120A*	29,200	\$4,088
211222785	SMART COMFORT	DLCURAH30ABK	FVM4X24***L		23,600	\$3,304
213080241	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSM0802120A*	29,400	\$4,116
213080240	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0802120A*	29,400	\$4,116
213080217	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96MSM0802120A*	29,000	\$4,060
213080216	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96MSN0802120A*	29,000	\$4,060
213080205	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96MSM0802120A*	29,000	\$4,060
213080204	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96MSN0802120A*	29,000	\$4,060
211222769	SMART COMFORT	DLCURAH30ABK	FMA4X36**AL*		23,800	\$3,332
213080193	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96MSM0802120A*	29,200	\$4,088
213080192	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96MSN0802120A*	29,200	\$4,088
211222761	SMART COMFORT	DLCURAH30ABK	FMA4X30**AL*		23,800	\$3,332
213080181	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96MSM0802120A*	29,400	\$4,116
213080180	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96MSN0802120A*	29,400	\$4,116
213080169	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96MSM0802120A*	29,400	\$4,116
213080168	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96MSN0802120A*	29,400	\$4,116
213080157	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96MSM0802120A*	29,200	\$4,088
211222753	SMART COMFORT	DLCURAH30ABK	FM(C,U)4Z36**AL*		23,600	\$3,304
213080156	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96MSN0802120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080145	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96MSM0802120A*	29,600	\$4,144
213080144	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96MSN0802120A*	29,600	\$4,144
213080132	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0801716A*	29,200	\$4,088
211222745	SMART COMFORT	DLCURAH30ABK	FM(C,U)4Z30**AL*		23,600	\$3,304
213080120	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	29,600	\$4,144
211222729	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	OMV098J12*	23,200	\$3,248
213080108	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*96MSN0801716A*	29,400	\$4,116
211222721	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	OLV098A12*	23,200	\$3,248
213080072	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96MSN0801716A*	29,000	\$4,060
211222713	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122A*	23,000	\$3,220
213080060	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96MSN0801716A*	29,200	\$4,088
213080048	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96MSN0801716A*	29,400	\$4,116
211222705	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120A*	23,200	\$3,248
213080036	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96MSN0801716A*	29,200	\$4,088
213080024	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*96MSN0801716A*	29,400	\$4,116
211222697	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120A*	23,000	\$3,220
213080012	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96MSN0801716A*	29,600	\$4,144
213080000	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*96MSN0801716A*	29,600	\$4,144
211222689	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VTN0601714A*	23,200	\$3,248
211222681	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*95ESU0601716A*	23,400	\$3,276
211222673	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*95ESU0401712A*	23,200	\$3,248
211222665	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120A*	23,200	\$3,248
211222657	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120A*	23,000	\$3,220
211222649	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716A*	23,200	\$3,248
211222641	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0601714A*	23,200	\$3,248
211222633	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*95ESN0802120A*	23,200	\$3,248
213079834	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002120A*	29,200	\$4,088
213079822	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002120A*	29,200	\$4,088
211222625	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*95ESN0601714A*	23,200	\$3,248
213079810	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	29,400	\$4,116
213079798	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN1002120A*	29,600	\$4,144
211222617	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*92ESN1002120A*	23,200	\$3,248
213079786	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002120A*	29,000	\$4,060
213079774	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002120A*	29,400	\$4,116
211222609	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*92ESN0802120A*	23,200	\$3,248
213079762	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002120A*	29,400	\$4,116
213079750	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002120A*	29,000	\$4,060
211222601	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*92ESN0801716A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079738	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002120A*	29,400	\$4,116
211222593	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*92ESN0601714A*	23,400	\$3,276
211222569	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122A*	23,200	\$3,248
211222561	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120A*	23,200	\$3,248
211222553	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716A*	23,200	\$3,248
211222545	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ESU0802120A	23,400	\$3,276
213079636	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0801716A*	29,200	\$4,088
211222537	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ESU0601716A	23,200	\$3,248
213079624	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0801716A*	29,400	\$4,116
213079612	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*92MSN0801716A*	29,200	\$4,088
211222529	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ESU0401712A*	23,200	\$3,248
211222521	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VSL0902120A*	23,200	\$3,248
213079576	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*92MSN0801716A*	29,000	\$4,060
211222513	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VSL0702120A*	23,200	\$3,248
213079564	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*92MSN0801716A*	29,400	\$4,116
213079552	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*92MSN0801716A*	29,000	\$4,060
211222505	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VSL0701716A*	23,200	\$3,248
213079540	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*92MSN0801716A*	29,400	\$4,116
213079528	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*92MSN0801716A*	29,400	\$4,116
211222497	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VSL0451716A*	23,200	\$3,248
213079516	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*92MSN0801716A*	29,400	\$4,116
213079504	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0601714A*	29,200	\$4,088
211222489	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	23,200	\$3,248
213079492	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0601714A*	29,400	\$4,116
213079480	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*92MSN0601714A*	29,400	\$4,116
211222481	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
211222473	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
213079444	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*92MSN0601714A*	29,200	\$4,088
211222465	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
213079432	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*92MSN0601714A*	29,400	\$4,116
213079420	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*92MSN0601714A*	29,200	\$4,088
211222457	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
213079406	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601714A*	29,400	\$4,116
213079394	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*92MSN0601714A*	29,400	\$4,116
211222449	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
213079382	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601714A*	29,400	\$4,116
211222441	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
211222401	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	OMV098J12*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211222393	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*96VTN0601714A*	23,400	\$3,276
211222385	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*95ESU0601716A*	23,400	\$3,276
211222377	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*95ESU0401712A*	23,400	\$3,276
211222369	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716A*	23,400	\$3,276
211222361	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*95ESN0601714A*	23,400	\$3,276
213079198	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MSU0601716A*	29,200	\$4,088
211222353	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*92ESN0801716A*	23,400	\$3,276
211222345	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601714A*	23,400	\$3,276
211222337	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601412A*	23,400	\$3,276
213079126	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80MSU0601716A*	29,200	\$4,088
211222329	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716A*	23,200	\$3,248
211222321	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412A*	23,400	\$3,276
211222313	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80ESU0601716A	23,400	\$3,276
211222305	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80ESU0401712A*	23,400	\$3,276
211222297	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451716A*	23,400	\$3,276
211222289	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412A*	23,400	\$3,276
211222281	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	23,200	\$3,248
211222273	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	23,400	\$3,276
213078922	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80MSU1002120A*	29,400	\$4,116
213078898	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	29,600	\$4,144
213078850	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80MSU1002120A*	29,400	\$4,116
213078826	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80MSU1002120A*	29,600	\$4,144
211222265	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	23,400	\$3,276
213078732	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)1102120A*	29,200	\$4,088
213078720	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)1102120A*	29,200	\$4,088
213078708	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	29,400	\$4,116
213078684	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078672	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078660	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078648	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078636	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078624	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	29,000	\$4,060
213078612	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	29,400	\$4,116
213078583	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80MS(N,L)0902120A*	29,200	\$4,088
213078572	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0902120A*	29,200	\$4,088
211222153	SMART COMFORT	DLCURAH30ABK	EA*4X36L21A*	*92ESN1002120A*	23,400	\$3,276
213078561	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	29,400	\$4,116
211222143	SMART COMFORT	DLCURAH30ABK	EA*4X36L21A*	*92ESN0802120A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213078539	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078528	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078517	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
213078506	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	29,200	\$4,088
213078495	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	29,400	\$4,116
211712494	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	23,400	\$3,276
211712507	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
211712481	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078384	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0901714A*	29,200	\$4,088
211712468	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	23,400	\$3,276
213078372	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0901714A*	29,400	\$4,116
213078360	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0901714A*	29,200	\$4,088
213078324	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
213078312	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078300	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
211222003	SMART COMFORT	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	23,600	\$3,304
213078288	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078276	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	29,400	\$4,116
213078264	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	29,400	\$4,116
211712431	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122A*	23,400	\$3,276
211221985	SMART COMFORT	DLCURAH30ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	23,600	\$3,304
213078162	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80MS(N,L)0701716A*	29,200	\$4,088
213078150	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	29,400	\$4,116
213078138	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701716A*	29,400	\$4,116
213078126	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	29,600	\$4,144
213078114	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	29,600	\$4,144
213078102	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078090	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078078	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	29,200	\$4,088
213078066	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078054	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	29,400	\$4,116
213078042	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	29,600	\$4,144
211712386	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716A*	23,400	\$3,276
211712374	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*95ESN1002120A*	23,600	\$3,304
213077909	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0701412A*	29,400	\$4,116
213077885	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	29,400	\$4,116
211712362	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*95ESN0802120A*	23,400	\$3,276
213077873	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077861	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80MS(N,L)0451412A*	29,400	\$4,116
213077837	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	29,400	\$4,116
213077824	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	29,600	\$4,144
213077813	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422B*	29,200	\$4,088
213077801	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422B*	29,400	\$4,116
213077789	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122B*	29,200	\$4,088
213077779	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122B*	29,200	\$4,088
213077769	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	29,400	\$4,116
213077759	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN1002122B*	29,600	\$4,144
213077749	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122B*	29,000	\$4,060
211712544	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*92ESN0802120A*	23,400	\$3,276
213077739	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122B*	29,400	\$4,116
213077729	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122B*	29,400	\$4,116
213077719	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122B*	29,000	\$4,060
213077709	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122B*	29,400	\$4,116
211712336	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80ESU0401712A*	23,400	\$3,276
213077698	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120B*	29,200	\$4,088
213077685	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120B*	29,200	\$4,088
213077672	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	29,400	\$4,116
213077646	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120B*	29,000	\$4,060
213077633	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120B*	29,400	\$4,116
213077620	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120B*	29,400	\$4,116
213077607	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120B*	29,000	\$4,060
211712324	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80ESU1002120A*	23,600	\$3,304
213077594	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120B*	29,400	\$4,116
213077582	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120B*	29,200	\$4,088
213077571	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120B*	29,200	\$4,088
213077560	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	29,400	\$4,116
213077549	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN0802120B*	29,600	\$4,144
213077538	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120B*	29,000	\$4,060
213077527	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120B*	29,200	\$4,088
213077516	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120B*	29,400	\$4,116
213077505	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120B*	29,400	\$4,116
213077494	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120B*	29,200	\$4,088
213077483	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120B*	29,400	\$4,116
213077471	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0801716B*	29,200	\$4,088
211712300	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*95ESU1002120A*	23,600	\$3,304
213077458	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0801716B*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077445	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*96VTN0801716B*	29,400	\$4,116
211712556	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*92ESN1002120A*	23,400	\$3,276
213077406	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VTN0801716B*	29,200	\$4,088
213077393	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716B*	29,400	\$4,116
213077380	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VTN0801716B*	29,200	\$4,088
213077367	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*96VTN0801716B*	29,400	\$4,116
213077354	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VTN0801716B*	29,400	\$4,116
211712279	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80VSL0702120A*	23,400	\$3,276
213077341	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*96VTN0801716B*	29,600	\$4,144
213077329	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*96VTN0601412B*	29,400	\$4,116
213077307	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601412B*	29,400	\$4,116
213077296	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601412B*	29,600	\$4,144
213077285	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0401712B*	29,400	\$4,116
213077274	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0401712B*	29,200	\$4,088
213077263	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422B*	29,200	\$4,088
213077253	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422B*	29,000	\$4,060
213077243	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422B*	29,400	\$4,116
213077233	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120B*	29,200	\$4,088
213077223	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120B*	29,200	\$4,088
213077213	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	29,400	\$4,116
213077193	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120B*	29,000	\$4,060
213077183	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120B*	29,000	\$4,060
213077173	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120B*	29,400	\$4,116
213077163	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120B*	29,400	\$4,116
213077153	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120B*	29,000	\$4,060
213077143	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120B*	29,400	\$4,116
211712568	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*95ESN0601714A*	23,600	\$3,304
213077133	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120B*	29,200	\$4,088
213077123	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120B*	29,200	\$4,088
213077113	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	29,400	\$4,116
213077103	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*96VSN0802120B*	29,600	\$4,144
213077093	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120B*	29,000	\$4,060
213077083	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120B*	29,200	\$4,088
213077073	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120B*	29,400	\$4,116
213077063	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120B*	29,400	\$4,116
211712237	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	23,600	\$3,304
213077053	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120B*	29,200	\$4,088
213077043	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120B*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077033	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716B*	29,200	\$4,088
213077023	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716B*	29,600	\$4,144
213077013	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*96VSN0801716B*	29,400	\$4,116
213076983	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716B*	29,200	\$4,088
213076973	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716B*	29,400	\$4,116
213076963	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716B*	29,200	\$4,088
213076953	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716B*	29,400	\$4,116
213076943	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716B*	29,400	\$4,116
213076933	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716B*	29,600	\$4,144
211712214	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*96VSN0801716A*	23,400	\$3,276
213076923	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*96VSN0601412B*	29,400	\$4,116
213076903	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412B*	29,400	\$4,116
213076893	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601412B*	29,600	\$4,144
213076883	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0401712B*	29,400	\$4,116
213076873	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0401712B*	29,200	\$4,088
213076856	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122B*	29,200	\$4,088
213076844	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122B*	29,200	\$4,088
213076832	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122B*	29,400	\$4,116
213076808	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122B*	29,000	\$4,060
213076796	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122B*	29,000	\$4,060
213076784	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122B*	29,200	\$4,088
213076772	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122B*	29,400	\$4,116
211712592	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80ESU0601716A	23,400	\$3,276
213076760	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122B*	29,400	\$4,116
213076748	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122B*	29,200	\$4,088
213076736	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122B*	29,400	\$4,116
213076725	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120B*	29,200	\$4,088
213076714	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120B*	29,200	\$4,088
213076703	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	29,400	\$4,116
213076692	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*80VTL0902120B*	29,600	\$4,144
213076681	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120B*	29,200	\$4,088
211712172	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
213076670	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120B*	29,400	\$4,116
213076659	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120B*	29,400	\$4,116
213076648	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120B*	29,200	\$4,088
213076637	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120B*	29,400	\$4,116
211712160	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*95ESN1002120A*	23,600	\$3,304
213076582	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716B*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712664	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80VSL0702120A*	23,400	\$3,276
213076571	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	29,400	\$4,116
213076560	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80VTL0701716B*	29,400	\$4,116
213076527	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716B*	29,000	\$4,060
213076516	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716B*	29,400	\$4,116
213076505	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716B*	29,000	\$4,060
213076494	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716B*	29,400	\$4,116
213076483	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716B*	29,400	\$4,116
211712684	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902420A*	23,400	\$3,276
213076472	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716B*	29,400	\$4,116
213076452	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80VTL0451412B*	29,400	\$4,116
213076428	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412B*	29,200	\$4,088
211712694	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80VSL1102422A*	23,400	\$3,276
213076416	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412B*	29,400	\$4,116
211712705	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*95ESU1002120A*	23,600	\$3,304
213076003	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002120A*	29,200	\$4,088
213075991	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002120A*	29,200	\$4,088
213075979	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002120A*	29,400	\$4,116
211712717	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80ESU1002120A*	23,600	\$3,304
213075955	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002120A*	29,000	\$4,060
213075943	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002120A*	29,000	\$4,060
213075931	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002120A*	29,000	\$4,060
213075919	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002120A*	29,400	\$4,116
213075907	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002120A*	29,400	\$4,116
213075895	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002120A*	29,000	\$4,060
213075883	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002120A*	29,400	\$4,116
212989510	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95MSU0802120A*	29,000	\$4,060
212989498	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95MSU0802120A*	29,000	\$4,060
212988982	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95MSU0601716A*	29,000	\$4,060
212988326	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96MSN1202422A*	29,000	\$4,060
211712743	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*95ESN0802120A*	23,400	\$3,276
212985248	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002120A*	28,800	\$4,032
211712755	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*95ESN1002120A*	23,600	\$3,304
212985236	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002120A*	28,800	\$4,032
212984418	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*92MSN0801716A*	29,000	\$4,060
212983878	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*92MSN0601714A*	29,000	\$4,060
212982609	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80MSU0601716A*	28,800	\$4,032
212980495	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80MS(N,L)0902120A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980484	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0902120A*	29,000	\$4,060
212979662	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0901714A*	29,000	\$4,060
212978972	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80MS(N,L)0701716A*	29,000	\$4,060
212977260	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422B*	29,000	\$4,060
212977096	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122B*	28,800	\$4,032
212977086	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122B*	28,800	\$4,032
212976815	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120B*	29,000	\$4,060
212976802	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120B*	29,000	\$4,060
211712801	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122A*	23,400	\$3,276
212976533	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120B*	28,800	\$4,032
212976312	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0801716B*	29,000	\$4,060
212974420	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120B*	29,000	\$4,060
212974200	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120B*	28,800	\$4,032
212974060	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716B*	29,000	\$4,060
212972250	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120B*	29,000	\$4,060
212972239	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120B*	29,000	\$4,060
212971883	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716B*	29,000	\$4,060
212970744	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120B*	29,200	\$4,088
212970734	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120B*	29,200	\$4,088
212970724	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	29,400	\$4,116
212970714	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*80VSL0902120B*	29,600	\$4,144
211712825	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	23,600	\$3,304
212970704	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120B*	29,000	\$4,060
212970694	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120B*	29,000	\$4,060
212970684	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120B*	29,200	\$4,088
212970674	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120B*	29,400	\$4,116
212970664	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120B*	29,400	\$4,116
212970654	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120B*	29,200	\$4,088
212970644	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120B*	29,400	\$4,116
211712838	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	23,400	\$3,276
212970484	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716B*	29,200	\$4,088
212970474	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	29,400	\$4,116
212970464	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80VSL0701716B*	29,400	\$4,116
212970434	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716B*	29,000	\$4,060
212970424	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716B*	29,200	\$4,088
212970414	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716B*	29,400	\$4,116
211712851	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	23,400	\$3,276
212970404	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716B*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212970394	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716B*	29,400	\$4,116
212970384	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716B*	29,600	\$4,144
212970374	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716B*	29,600	\$4,144
212969964	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80VSL0451412B*	29,400	\$4,116
212969944	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412B*	29,200	\$4,088
212969934	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412B*	29,400	\$4,116
211712864	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	23,600	\$3,304
212390906	SMART COMFORT	DLCURAH36ABK	FJMA4*36L*B*		29,400	\$4,116
212384859	SMART COMFORT	DLCURAH36ABK	FVM4X36***L		29,400	\$4,116
212384835	SMART COMFORT	DLCURAH36ABK	FJMA4*42L*C*		29,200	\$4,088
212384795	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0801716A*	29,200	\$4,088
212384783	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701716A*	29,200	\$4,088
211712877	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	23,400	\$3,276
212384772	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV112A16A	29,600	\$4,144
212384762	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV112K14A	29,400	\$4,116
212384752	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	OLV098A12*	29,600	\$4,144
212384742	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	OMV098J12*	29,600	\$4,144
212384731	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	29,400	\$4,116
212384719	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU0802120A	29,600	\$4,144
212384707	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0601714A*	29,400	\$4,116
211712890	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	23,600	\$3,304
212384695	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	29,400	\$4,116
212384683	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	29,400	\$4,116
212384671	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0801716A*	29,400	\$4,116
212384659	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0601714A*	29,400	\$4,116
212384646	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	29,400	\$4,116
212384633	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	29,400	\$4,116
211712903	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*92ESN0802120A*	23,400	\$3,276
212384620	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701712A*	29,600	\$4,144
212384607	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0451712A*	29,400	\$4,116
212384596	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	29,400	\$4,116
212384585	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120A*	29,600	\$4,144
212384574	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	29,400	\$4,116
212384562	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	29,600	\$4,144
211712915	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*92ESN1002120A*	23,400	\$3,276
212384551	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VTL0902120A*	29,400	\$4,116
212384536	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	29,400	\$4,116
212384524	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211712961	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	OLV154F20A	23,600	\$3,304
211712971	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	OMV154L20A	23,600	\$3,304
211712981	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0601714A*	23,200	\$3,248
211712991	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120A*	23,000	\$3,220
211713001	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120A*	23,200	\$3,248
211713011	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716A*	23,200	\$3,248
211713022	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*95ESU0401712A*	23,200	\$3,248
211713034	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	23,400	\$3,276
211713046	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122A*	23,000	\$3,220
211713056	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VSL0451716A*	23,200	\$3,248
211713066	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VSL0701716A*	23,200	\$3,248
211713076	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VSL0702120A*	23,200	\$3,248
211713086	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VSL0902120A*	23,200	\$3,248
211713097	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*95ESU1002120A*	23,400	\$3,276
211713109	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*95ESU0601716A*	23,400	\$3,276
211713121	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ESU1002120A*	23,400	\$3,276
211713133	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ESU0401712A*	23,200	\$3,248
213353891	SMART COMFORT	DLCURAH60ABK	F5MA4*60L*D*		37,800	\$5,292
213607821	SMART COMFORT	DLCURAH60ABK	FTMA4B60L0D*		37,400	\$5,236
211713148	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120A*	23,200	\$3,248
211713159	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*95ESN0802120A*	23,200	\$3,248
211713171	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*95ESN1002120A*	23,600	\$3,304
211713183	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716A*	23,200	\$3,248
211713195	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VTN0601714A*	23,200	\$3,248
211713206	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120A*	23,000	\$3,220
211713217	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120A*	23,200	\$3,248
211713228	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122A*	23,200	\$3,248
210025749	SMART COMFORT	DLCURAH60ABK	DLFUAAH60XAK		42,000	\$5,880
212384512	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	29,400	\$4,116
212384501	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0902120A*	29,400	\$4,116
212384491	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	29,400	\$4,116
211713239	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	23,400	\$3,276
212384481	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0701716A*	29,400	\$4,116
212384471	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002122A*	29,600	\$4,144
212384461	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002122A*	29,600	\$4,144
212384451	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002122A*	29,600	\$4,144
212384440	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	29,400	\$4,116
212384429	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211713252	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	23,200	\$3,248
212384419	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	29,400	\$4,116
212384409	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120A*	29,400	\$4,116
212384399	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0601714A*	29,400	\$4,116
212384389	SMART COMFORT	DLCURAH36ABK	END4X42L17**	OMV112K14A	29,400	\$4,116
212384379	SMART COMFORT	DLCURAH36ABK	END4X42L17**	OLV098A12*	29,400	\$4,116
212384369	SMART COMFORT	DLCURAH36ABK	END4X42L17**	OMV098J12*	29,400	\$4,116
211713265	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	23,200	\$3,248
212384358	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80ESU0601716A	29,400	\$4,116
212384345	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701412A*	29,400	\$4,116
212384333	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*92ESN0801716A*	29,200	\$4,088
212384321	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*92ESN0601714A*	29,200	\$4,088
212384309	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*92ESN0601412A*	29,400	\$4,116
211713278	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	23,200	\$3,248
212384296	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0901714A*	29,400	\$4,116
212384283	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701712A*	29,400	\$4,116
212384270	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451712A*	29,400	\$4,116
212384257	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0451412A*	29,600	\$4,144
211713291	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	23,400	\$3,276
212384243	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80VTL0451412A*	29,400	\$4,116
212384232	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80VSL0701716A*	29,200	\$4,088
212384222	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80VSL0451716A*	29,400	\$4,116
212384211	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80ES(N,L)0701716A*	29,200	\$4,088
211713304	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	23,200	\$3,248
212384147	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*80ESU0802120A	29,800	\$4,172
212384135	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002120A*	29,600	\$4,144
212384123	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN0802120A*	29,600	\$4,144
211713317	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	23,400	\$3,276
211713330	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*92ESN0601714A*	23,000	\$3,220
211713342	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*92ESN0801716A*	23,400	\$3,276
211713354	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*92ESN0802120A*	23,200	\$3,248
212383816	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESU1002122A*	29,800	\$4,172
212383806	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESN1002122A*	29,800	\$4,172
212383796	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002122A*	29,800	\$4,172
211713366	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*92ESN1002120A*	23,200	\$3,248
211713378	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*95ESN0601714A*	23,200	\$3,248
211713390	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ESU0802120A	23,400	\$3,276
212383489	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701716A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383477	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*92ESN0801716A*	29,000	\$4,060
212383465	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
211713402	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80ESU0601716A	23,200	\$3,248
212383454	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	OLV112A16A	29,400	\$4,116
212383443	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002120A*	29,200	\$4,088
212383432	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VTL0902120A*	29,000	\$4,060
212383420	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95ESU0601716A*	29,200	\$4,088
212383408	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701716A*	29,200	\$4,088
211713413	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	OMV098J12*	23,200	\$3,248
212383396	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80ESU0601716A	29,200	\$4,088
212383384	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ESU0601716A	29,400	\$4,116
212383372	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ESU0802120A	29,600	\$4,144
211713423	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	OLV098A12*	23,200	\$3,248
212383360	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002120A*	29,400	\$4,116
212383348	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*92ESN0802120A*	29,400	\$4,116
212383336	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*92ESN0801716A*	29,400	\$4,116
212383323	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
212383310	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
212383297	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	29,600	\$4,144
212383284	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
212383273	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VTL1102122A*	29,600	\$4,144
212383262	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VTN0601714A*	29,600	\$4,144
212383250	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VTL0701716A*	29,400	\$4,116
212383238	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95ESN0802120A*	29,600	\$4,144
212383227	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VTL0902120A*	29,400	\$4,116
212383215	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002120A*	29,400	\$4,116
212383204	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0902120A*	29,400	\$4,116
212383194	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0702120A*	29,400	\$4,116
212383184	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0701716A*	29,400	\$4,116
212383173	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95ESU0802120A*	29,800	\$4,172
212383162	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002122A*	29,600	\$4,144
212383151	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
212383140	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716A*	29,400	\$4,116
212383130	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120A*	29,400	\$4,116
212383120	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120A*	29,400	\$4,116
212383110	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VSN0601714A*	29,600	\$4,144
212383100	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	OLV098A12*	29,600	\$4,144
212383090	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	OMV098J12*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383079	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80ESU0601716A	29,600	\$4,144
212383066	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	29,600	\$4,144
212383054	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*95ESN0601714A*	29,600	\$4,144
212383042	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*92ESN0801716A*	29,400	\$4,116
212383030	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601714A*	29,400	\$4,116
212383018	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601412A*	29,600	\$4,144
212383005	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	29,600	\$4,144
212382992	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	29,600	\$4,144
212382979	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	29,600	\$4,144
212382966	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	29,800	\$4,172
212382955	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601714A*	29,600	\$4,144
212382943	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80VTL0701716A*	29,400	\$4,116
212382926	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80VTL0451412A*	29,600	\$4,144
212382914	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*95ESU0601716A*	29,400	\$4,116
212382903	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0701716A*	29,400	\$4,116
212382893	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451716A*	29,600	\$4,144
212382882	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	29,400	\$4,116
212382871	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716A*	29,400	\$4,116
212382861	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601714A*	29,600	\$4,144
212382851	SMART COMFORT	DLCURAH36ABK	EA*4X36L17A*	*80VSL0451412A*	29,600	\$4,144
211230934	SMART COMFORT	DLCURAH36ABK	FXM4X48**AL		29,000	\$4,060
211230923	SMART COMFORT	DLCURAH36ABK	FXM4X42**AL		29,000	\$4,060
211230902	SMART COMFORT	DLCURAH36ABK	FVM4X48***L		28,600	\$4,004
211230891	SMART COMFORT	DLCURAH36ABK	FMA4X36**AL*		29,600	\$4,144
211230869	SMART COMFORT	DLCURAH36ABK	FM(C,U)4Z36**AL*		29,600	\$4,144
211230813	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	OMV154L20A	29,200	\$4,088
211230804	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	OLV154F20A	29,400	\$4,116
211230795	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	OLV112A16A	29,200	\$4,088
211230786	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422A*	29,200	\$4,088
211230776	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122A*	29,200	\$4,088
211230767	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120A*	29,200	\$4,088
211230757	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120A*	29,200	\$4,088
211230747	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002122A*	29,400	\$4,116
211230737	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002120A*	29,200	\$4,088
211230726	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU0802120A*	29,600	\$4,144
211230716	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422A*	29,200	\$4,088
211230707	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120A*	29,200	\$4,088
211230698	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230688	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1402422A*	29,400	\$4,116
211230677	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1202422A*	29,400	\$4,116
211230667	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002122A*	29,400	\$4,116
211230657	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002120A*	29,200	\$4,088
211230646	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN0802120A*	29,400	\$4,116
211230635	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1202420A*	29,200	\$4,088
211230625	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002122A*	29,400	\$4,116
211230615	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002120A*	29,200	\$4,088
211230604	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN0802120A*	29,000	\$4,060
211230574	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL1102122A*	29,200	\$4,088
211230564	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VTL0902120A*	29,200	\$4,088
211230553	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU1002120A*	29,200	\$4,088
211230542	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ESU0802120A	29,400	\$4,116
211230532	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL1102422A*	29,200	\$4,088
211230523	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902420A*	29,200	\$4,088
211230514	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0902120A*	29,200	\$4,088
211230505	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80VSL0702120A*	29,200	\$4,088
211230496	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1552420A*	29,200	\$4,088
211230484	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1352420A*	29,200	\$4,088
211230472	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102420A*	29,200	\$4,088
211230460	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)1102120A*	29,200	\$4,088
211230448	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902420A*	29,200	\$4,088
211230436	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902120A*	29,200	\$4,088
211230424	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0902116A*	29,200	\$4,088
211230412	SMART COMFORT	DLCURAH36ABK	EN(A,D)4X48L24**	*80ES(N,L)0702116A*	29,200	\$4,088
211230384	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV112K14A	29,200	\$4,088
211230375	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	OMV098J12*	29,200	\$4,088
211230366	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV112A16A	29,200	\$4,088
211230357	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	OLV098A12*	29,200	\$4,088
211230348	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122A*	29,200	\$4,088
211230339	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120A*	29,200	\$4,088
211230329	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120A*	29,200	\$4,088
211230319	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0601714A*	29,400	\$4,116
211230299	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002122A*	29,400	\$4,116
211230289	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002120A*	29,200	\$4,088
211230278	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0802120A*	29,600	\$4,144
211230267	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0601716A*	29,200	\$4,088
211230257	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230248	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120A*	29,200	\$4,088
211230239	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716A*	29,200	\$4,088
211230230	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0601714A*	29,200	\$4,088
211230212	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002122A*	29,400	\$4,116
211230202	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002120A*	29,200	\$4,088
211230191	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0802120A*	29,400	\$4,116
211230180	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0801716A*	29,200	\$4,088
211230169	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0601714A*	29,200	\$4,088
211230159	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002122A*	29,400	\$4,116
211230149	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002120A*	29,200	\$4,088
211230138	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0802120A*	29,000	\$4,060
211230127	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0601714A*	29,200	\$4,088
211230090	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL1102122A*	29,200	\$4,088
211230080	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0902120A*	29,200	\$4,088
211230068	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VTL0701716A*	29,200	\$4,088
211230057	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU1002120A*	29,200	\$4,088
211230046	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0802120A	29,400	\$4,116
211230035	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0601716A	29,000	\$4,060
211230024	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ESU0401712A*	29,600	\$4,144
211230014	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0902120A*	29,200	\$4,088
211230005	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0702120A*	29,200	\$4,088
211229996	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0701716A*	29,200	\$4,088
211229987	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80VSL0451716A*	29,200	\$4,088
211229976	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)1102120A*	29,200	\$4,088
211229964	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902120A*	29,200	\$4,088
211229952	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0902116A*	29,200	\$4,088
211229940	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0901714A*	29,200	\$4,088
211229928	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0702116A*	29,200	\$4,088
211229916	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0701712A*	29,400	\$4,116
211229904	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X48L21**	*80ES(N,L)0451712A*	29,200	\$4,088
211229858	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	29,400	\$4,116
211229849	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120A*	29,400	\$4,116
211229839	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0601714A*	29,600	\$4,144
211229828	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002120A*	29,400	\$4,116
211229807	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80VSL0451716A*	29,400	\$4,116
211229796	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	29,400	\$4,116
211229784	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	29,400	\$4,116
211229772	SMART COMFORT	DLCURAH36ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229753	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*96VTN0601714A*	29,400	\$4,116
211229742	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*95ESU0601716A*	29,200	\$4,088
211229732	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*96VSN0801716A*	29,400	\$4,116
211229723	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*96VSN0601714A*	29,400	\$4,116
211229695	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*95ESN0601714A*	29,400	\$4,116
211229676	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80VTL0701716A*	29,200	\$4,088
211229664	SMART COMFORT	DLCURAH36ABK	END4X42L17**	*80VSL0451412A*	29,400	\$4,116
211229655	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	OMV154L20A	29,000	\$4,060
211229646	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	OLV154F20A	29,200	\$4,088
211229637	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	OLV112A16A	29,000	\$4,060
211229628	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422A*	29,000	\$4,060
211229618	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122A*	28,800	\$4,032
211229609	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120A*	29,000	\$4,060
211229599	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120A*	28,800	\$4,032
211229589	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002122A*	29,200	\$4,088
211714022	SMART COMFORT	DLCURAH30ABK	EN(A,D)4X36L21**	*80ESU0802120A	23,600	\$3,304
211229579	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002120A*	29,000	\$4,060
211229568	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95ESU0802120A*	29,400	\$4,116
211229558	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422A*	29,000	\$4,060
211229549	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120A*	29,000	\$4,060
211229540	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120A*	29,000	\$4,060
211229530	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95ESN1402422A*	29,200	\$4,088
211229519	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95ESN1202422A*	29,200	\$4,088
211229509	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002122A*	29,200	\$4,088
211229499	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002120A*	29,000	\$4,060
211229488	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*95ESN0802120A*	29,200	\$4,088
211229477	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*92ESN1202420A*	29,000	\$4,060
211714045	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80VSL0451412A*	23,400	\$3,276
211229467	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002122A*	29,200	\$4,088
211229457	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002120A*	28,800	\$4,032
211229446	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*92ESN0802120A*	28,800	\$4,032
211229416	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80VTL1102122A*	29,000	\$4,060
211714055	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*96VSN0801716A*	23,400	\$3,276
211229406	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80VTL0902120A*	28,800	\$4,032
211229395	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ESU1002120A*	29,000	\$4,060
211229384	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ESU0802120A	29,200	\$4,088
211229374	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80VSL1102422A*	28,800	\$4,032
211229365	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902420A*	28,800	\$4,032

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714066	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*95ESU0401712A*	23,400	\$3,276
211229356	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80VSL0902120A*	28,800	\$4,032
211229347	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80VSL0702120A*	29,000	\$4,060
211229338	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1552420A*	29,200	\$4,088
211229326	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1352420A*	29,000	\$4,060
211229314	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102420A*	28,800	\$4,032
211714078	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701716A*	23,600	\$3,304
211229302	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)1102120A*	29,000	\$4,060
211229290	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902420A*	29,000	\$4,060
211229278	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902120A*	29,000	\$4,060
211229266	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0902116A*	29,000	\$4,060
211714089	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80VSL0451716A*	23,400	\$3,276
211229254	SMART COMFORT	DLCURAH36ABK	EA*4X48L24A*	*80ES(N,L)0702116A*	28,800	\$4,032
211229226	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	OMV112K14A	29,000	\$4,060
211229217	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	OMV098J12*	29,000	\$4,060
211229208	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	OLV112A16A	29,000	\$4,060
211229199	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	OLV098A12*	29,000	\$4,060
211714099	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80VSL0701716A*	23,400	\$3,276
211229190	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122A*	28,800	\$4,032
211229181	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120A*	29,000	\$4,060
211229171	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120A*	29,000	\$4,060
211229161	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VTN0601714A*	29,200	\$4,088
211229151	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002122A*	29,200	\$4,088
211714110	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*95ESU0601716A*	23,600	\$3,304
211229141	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002120A*	29,000	\$4,060
211229130	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95ESU0802120A*	29,400	\$4,116
211229119	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95ESU0601716A*	29,000	\$4,060
211229109	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120A*	29,000	\$4,060
211714122	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80ESU0401712A*	23,400	\$3,276
211229100	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120A*	29,000	\$4,060
211229091	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716A*	29,000	\$4,060
211229082	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*96VSN0601714A*	29,000	\$4,060
211229064	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002122A*	29,200	\$4,088
211229054	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002120A*	29,000	\$4,060
211229043	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95ESN0802120A*	29,200	\$4,088
211714134	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80VTL0451412A*	23,400	\$3,276
211229032	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95ESN0801716A*	29,000	\$4,060
211229021	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*95ESN0601714A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229011	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002122A*	29,200	\$4,088
211229001	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002120A*	28,800	\$4,032
211228990	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*92ESN0802120A*	28,800	\$4,032
211228979	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*92ESN0801716A*	29,000	\$4,060
211228968	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*92ESN0601714A*	29,000	\$4,060
211228931	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VTL1102122A*	29,000	\$4,060
211714151	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80VTL0701716A*	23,400	\$3,276
211228921	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VTL0902120A*	28,800	\$4,032
211228909	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VTL0701716A*	29,000	\$4,060
211228898	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ESU1002120A*	29,000	\$4,060
211228887	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ESU0802120A	29,200	\$4,088
211714163	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*96VTN0601714A*	23,400	\$3,276
211228876	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ESU0601716A	29,000	\$4,060
211228865	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ESU0401712A*	29,400	\$4,116
211228855	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0902120A*	28,800	\$4,032
211228846	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0702120A*	29,000	\$4,060
211228837	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0701716A*	29,000	\$4,060
211228828	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80VSL0451716A*	29,000	\$4,060
211714174	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0451412A*	23,400	\$3,276
211228817	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)1102120A*	29,000	\$4,060
211228805	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902120A*	29,000	\$4,060
211228793	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211228781	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0901714A*	29,000	\$4,060
211228769	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0702116A*	28,800	\$4,032
211714187	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701712A*	23,400	\$3,276
211228757	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0701712A*	29,000	\$4,060
211228745	SMART COMFORT	DLCURAH36ABK	EA*4X48L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228699	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	OMV112K14A	29,200	\$4,088
211228690	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	OMV098J12*	29,200	\$4,088
211228681	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	OLV112A16A	29,200	\$4,088
211228672	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	OLV098A12*	29,200	\$4,088
211714200	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0901714A*	23,400	\$3,276
211228663	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122A*	29,000	\$4,060
211228654	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120A*	29,200	\$4,088
211228644	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120A*	29,200	\$4,088
211228634	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VTN0601714A*	29,200	\$4,088
211228614	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002122A*	29,200	\$4,088
211228604	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002120A*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211714213	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*92ESN0601412A*	23,400	\$3,276
211228593	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95ESU0802120A*	29,400	\$4,116
211228582	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95ESU0601716A*	29,200	\$4,088
211228572	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120A*	29,000	\$4,060
211714225	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*92ESN0601714A*	23,200	\$3,248
211228563	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120A*	29,000	\$4,060
211228554	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716A*	29,200	\$4,088
211228545	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*96VSN0601714A*	29,200	\$4,088
211228527	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002122A*	29,200	\$4,088
211714237	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*92ESN0801716A*	23,200	\$3,248
211228517	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002120A*	29,200	\$4,088
211228506	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95ESN0802120A*	29,200	\$4,088
211228484	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*95ESN0601714A*	29,400	\$4,116
211228474	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002122A*	29,400	\$4,116
211714249	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*95ESN0601714A*	23,400	\$3,276
211228464	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002120A*	29,200	\$4,088
211228453	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*92ESN0802120A*	29,200	\$4,088
211228442	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*92ESN0601714A*	29,000	\$4,060
211228405	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VTL1102122A*	29,200	\$4,088
211714261	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80ES(N,L)0701412A*	23,200	\$3,248
211228395	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VTL0902120A*	29,000	\$4,060
211228383	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VTL0701716A*	29,000	\$4,060
211228372	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ESU1002120A*	29,000	\$4,060
211714274	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80ESU0601716A	23,400	\$3,276
211228361	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ESU0802120A	29,200	\$4,088
211228350	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ESU0601716A	29,200	\$4,088
211228339	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ESU0401712A*	29,400	\$4,116
211714285	SMART COMFORT	DLCURAH30ABK	END4X42L17**	OMV098J12*	23,400	\$3,276
211228329	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0902120A*	29,000	\$4,060
211228320	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0702120A*	29,000	\$4,060
211714295	SMART COMFORT	DLCURAH30ABK	END4X42L17**	OLV098A12*	23,400	\$3,276
211228311	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0701716A*	29,200	\$4,088
211228302	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80VSL0451716A*	29,200	\$4,088
211228291	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211228279	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211228267	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211714315	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	23,400	\$3,276
211228255	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0901714A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228243	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211714325	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	23,400	\$3,276
211228231	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211228219	SMART COMFORT	DLCURAH36ABK	EA*4X43L21A*	*80ES(N,L)0451712A*	29,000	\$4,060
211228173	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	OMV154L20A	29,400	\$4,116
211228164	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	OLV154F20A	29,600	\$4,144
211714348	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0701716A*	23,600	\$3,304
211714360	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	23,400	\$3,276
211714390	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0702120A*	23,400	\$3,276
211714411	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	23,600	\$3,304
212970764	SMART COMFORT	DLCURAH48AAK	EA*4X48L24A*	*80VSL0902120B*	32,600	\$4,564
212970754	SMART COMFORT	DLCURAH48AAK	EA*4X48L21A*	*80VSL0902120B*	32,600	\$4,564
211714423	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	23,600	\$3,304
211714435	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU1002120A*	23,600	\$3,304
211714447	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0401712A*	23,400	\$3,276
212970804	SMART COMFORT	DLCURAH48ABK	EA*4X48L21A*	*80VSL0902120B*	31,400	\$4,396
212970814	SMART COMFORT	DLCURAH48ABK	EA*4X48L24A*	*80VSL0902120B*	31,400	\$4,396
212970824	SMART COMFORT	DLCURAH48ABK	EA*4X60L24A*	*80VSL0902120B*	31,000	\$4,340
212970844	SMART COMFORT	DLCURAH48ABK	EA*4X61L24A*	*80VSL0902120B*	31,000	\$4,340
212970834	SMART COMFORT	DLCURAH48ABK	EA*4X61L21A*	*80VSL0902120B*	31,000	\$4,340
211714473	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	23,400	\$3,276
211714485	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716A*	23,400	\$3,276
211714518	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL1102122A*	23,400	\$3,276
211714542	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0702116A*	23,600	\$3,304
211714555	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0901714A*	23,400	\$3,276
211714568	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902116A*	23,600	\$3,304
211714581	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)0902120A*	23,400	\$3,276
211714594	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ES(N,L)1102120A*	23,600	\$3,304
211714631	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	23,400	\$3,276
211714643	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	23,400	\$3,276
211714667	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80ESU0601716A	23,400	\$3,276
211714692	SMART COMFORT	DLCURAH30ABK	FJMA4*36L*B*		23,400	\$3,276
212969884	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80VSL0451412B*	23,400	\$3,276
212969924	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80VSL0451412B*	23,400	\$3,276
212970304	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80VSL0701716B*	23,600	\$3,304
212970354	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80VSL0701716B*	23,400	\$3,276
212970364	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0701716B*	23,600	\$3,304
212970594	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80VSL0902120B*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212970604	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80VSL0902120B*	23,600	\$3,304
212970634	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VSL0902120B*	23,600	\$3,304
212971299	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80VTL0451412B*	23,400	\$3,276
212971347	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80VTL0451412B*	23,400	\$3,276
212971784	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80VTL0701716B*	23,400	\$3,276
212971795	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VTL0701716B*	23,200	\$3,248
212971806	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80VTL0701716B*	23,600	\$3,304
212971817	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VTL0701716B*	23,200	\$3,248
212971861	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80VTL0701716B*	23,400	\$3,276
212971872	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0701716B*	23,600	\$3,304
212972173	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VTL0902120B*	23,200	\$3,248
212972184	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80VTL0902120B*	23,600	\$3,304
212972195	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80VTL0902120B*	23,600	\$3,304
212972206	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VTL0902120B*	23,200	\$3,248
212972228	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80VTL0902120B*	23,600	\$3,304
212972455	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80VTL1102122B*	23,400	\$3,276
212972467	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80VTL1102122B*	23,400	\$3,276
212972479	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80VTL1102122B*	23,400	\$3,276
212972491	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80VTL1102122B*	23,200	\$3,248
212973650	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*96VSN0601412B*	23,600	\$3,304
212973970	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716B*	23,400	\$3,276
212973980	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716B*	23,400	\$3,276
212974000	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716B*	23,200	\$3,248
212974040	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*96VSN0801716B*	23,400	\$3,276
212974140	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120B*	23,200	\$3,248
212974150	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*96VSN0802120B*	23,400	\$3,276
212974160	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96VSN0802120B*	23,400	\$3,276
212974170	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120B*	23,200	\$3,248
212974190	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	23,600	\$3,304
212974360	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120B*	23,200	\$3,248
212974370	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*96VSN1002120B*	23,600	\$3,304
212974380	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96VSN1002120B*	23,600	\$3,304
212974390	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120B*	23,200	\$3,248
212974410	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	23,600	\$3,304
212974530	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96VSN1202422B*	23,600	\$3,304
212975769	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*96VTN0601412B*	23,600	\$3,304
212976184	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*96VTN0801716B*	23,400	\$3,276
212976197	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VTN0801716B*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976223	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VTN0801716B*	23,200	\$3,248
212976275	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*96VTN0801716B*	23,400	\$3,276
212976453	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120B*	23,200	\$3,248
212976467	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*96VTN0802120B*	23,400	\$3,276
212976481	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96VTN0802120B*	23,400	\$3,276
212976495	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120B*	23,200	\$3,248
212976521	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	23,600	\$3,304
212976724	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120B*	23,200	\$3,248
212976737	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002120B*	23,600	\$3,304
212976750	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002120B*	23,600	\$3,304
212976763	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120B*	23,200	\$3,248
212976789	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	23,600	\$3,304
212977026	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122B*	23,200	\$3,248
212977036	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002122B*	23,400	\$3,276
212977046	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002122B*	23,400	\$3,276
212977056	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122B*	23,200	\$3,248
212977076	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	23,400	\$3,276
212977248	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96VTN1202422B*	23,600	\$3,304
212977523	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	23,400	\$3,276
212977559	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0451412A*	23,400	\$3,276
212978027	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	23,400	\$3,276
212978075	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701412A*	23,400	\$3,276
212979020	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	23,400	\$3,276
212979032	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979044	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0701716A*	23,600	\$3,304
212979056	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0701716A*	23,200	\$3,248
212979104	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0701716A*	23,400	\$3,276
212979116	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0701716A*	23,600	\$3,304
212979710	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979722	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979734	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0901714A*	23,400	\$3,276
212979746	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0901714A*	23,200	\$3,248
212979794	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80MS(N,L)0901714A*	23,400	\$3,276
212980517	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980528	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)0902120A*	23,600	\$3,304
212980550	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)0902120A*	23,200	\$3,248
212980572	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)0902120A*	23,600	\$3,304
212980907	SMART COMFORT	DLCURAH30ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212980919	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980931	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980943	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80MS(N,L)1102120A*	23,600	\$3,304
212980955	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*80MS(N,L)1102120A*	23,200	\$3,248
212980979	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*80MS(N,L)1102120A*	23,600	\$3,304
212981589	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*80MSU1002120A*	23,400	\$3,276
212981673	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*80MSU1002120A*	23,400	\$3,276
212982657	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*80MSU0601716A*	23,400	\$3,276
212983926	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601714A*	23,400	\$3,276
212983938	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*92MSN0601714A*	23,200	\$3,248
212983962	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*92MSN0601714A*	23,200	\$3,248
212984010	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*92MSN0601714A*	23,400	\$3,276
212984466	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*92MSN0801716A*	23,400	\$3,276
212984478	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*92MSN0801716A*	23,200	\$3,248
212984490	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*92MSN0801716A*	23,400	\$3,276
212984502	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*92MSN0801716A*	23,200	\$3,248
212984550	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*92MSN0801716A*	23,400	\$3,276
212985272	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*92MSN1002120A*	23,200	\$3,248
212985284	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*92MSN1002120A*	23,400	\$3,276
212985296	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*92MSN1002120A*	23,400	\$3,276
212985308	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*92MSN1002120A*	23,600	\$3,304
212985332	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	23,600	\$3,304
212987264	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*96MSN0801716A*	23,400	\$3,276
212987276	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96MSN0801716A*	23,200	\$3,248
212987300	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96MSN0801716A*	23,400	\$3,276
212987348	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*96MSN0801716A*	23,600	\$3,304
212987360	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	23,600	\$3,304
212987732	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96MSN0802120A*	23,200	\$3,248
212987733	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*96MSM0802120A*	23,200	\$3,248
212987756	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96MSN0802120A*	23,400	\$3,276
212987757	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96MSM0802120A*	23,400	\$3,276
212987768	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96MSN0802120A*	23,200	\$3,248
212987769	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*96MSM0802120A*	23,200	\$3,248
212988338	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*96MSN1202422A*	23,400	\$3,276
212988586	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*95MSU0401712A*	23,600	\$3,304
212988598	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*95MSU0401712A*	23,200	\$3,248
212988622	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*95MSU0401712A*	23,200	\$3,248
212988634	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*95MSU0401712A*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989030	SMART COMFORT	DLCURAH30ABK	EA*4X37L17A*	*95MSU0601716A*	23,400	\$3,276
212989042	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*95MSU0601716A*	23,200	\$3,248
212989054	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*95MSU0601716A*	23,600	\$3,304
212989066	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*95MSU0601716A*	23,200	\$3,248
212989114	SMART COMFORT	DLCURAH30ABK	END4X42L17**	*95MSU0601716A*	23,400	\$3,276
212989126	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	23,600	\$3,304
212989534	SMART COMFORT	DLCURAH30ABK	EA*4X37L21A*	*95MSU0802120A*	23,200	\$3,248
212989546	SMART COMFORT	DLCURAH30ABK	EA*4X42L21A*	*95MSU0802120A*	23,600	\$3,304
212989558	SMART COMFORT	DLCURAH30ABK	EA*4X42L24A*	*95MSU0802120A*	23,600	\$3,304
212989570	SMART COMFORT	DLCURAH30ABK	EA*4X43L21A*	*95MSU0802120A*	23,200	\$3,248
212989594	SMART COMFORT	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	23,600	\$3,304
213249299	SMART COMFORT	DLCURAH30ABK	FEVA0036**+NAVA43601CK		23,600	\$3,304
213353815	SMART COMFORT	DLCURAH30ABK	F5MA4*30L*B*		23,400	\$3,276
213353825	SMART COMFORT	DLCURAH30ABK	F5MA4*36L*B*		23,600	\$3,304
211226267	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	29,600	\$4,144
211226279	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	29,600	\$4,144
211226291	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211226302	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80VSL0451716A*	29,600	\$4,144
211226312	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*80ESU1002120A*	29,400	\$4,116
211226334	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*92ESN0601714A*	29,400	\$4,116
211226344	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002122A*	29,600	\$4,144
211226354	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95ESN0601714A*	29,400	\$4,116
211226365	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95ESN0801716A*	29,400	\$4,116
211226376	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002120A*	29,600	\$4,144
211226386	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002122A*	29,600	\$4,144
211226396	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*95ESU0601716A*	29,400	\$4,116
211226407	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120A*	29,400	\$4,116
211226417	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120A*	29,600	\$4,144
211226426	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122A*	29,400	\$4,116
211226435	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	OLV098A12*	29,600	\$4,144
211226444	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	OLV112A16A	29,600	\$4,144
211226453	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	OMV098J12*	29,600	\$4,144
211226462	SMART COMFORT	DLCURAH36ABK	EA*4X36L21A*	OMV112K14A	29,600	\$4,144
211226490	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0451412A*	29,400	\$4,116
211226502	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	29,200	\$4,088
211226514	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701712A*	29,400	\$4,116
211226526	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0701716A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211226537	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226548	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451412A*	29,400	\$4,116
211226557	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0451716A*	29,400	\$4,116
211226566	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80VSL0701716A*	29,400	\$4,116
211226587	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80VTL0451412A*	29,400	\$4,116
211226599	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*80VTL0701716A*	29,400	\$4,116
211226620	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601412A*	29,400	\$4,116
211226631	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601714A*	29,200	\$4,088
211226642	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*92ESN0801716A*	29,400	\$4,116
211226664	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*95ESN0601714A*	29,400	\$4,116
211226674	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412A*	29,400	\$4,116
211226683	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601714A*	29,400	\$4,116
211226692	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716A*	29,400	\$4,116
211226702	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*95ESU0601716A*	29,400	\$4,116
211226713	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601714A*	29,400	\$4,116
211226722	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	OLV098A12*	29,400	\$4,116
211226731	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	OMV098J12*	29,400	\$4,116
211226740	SMART COMFORT	DLCURAH36ABK	EA*4X37L17A*	OMV112K14A	29,400	\$4,116
211226798	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0701712A*	29,200	\$4,088
211226810	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0702116A*	29,200	\$4,088
211226822	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0901714A*	29,200	\$4,088
211226834	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902116A*	29,000	\$4,060
211226846	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)0902120A*	29,200	\$4,088
211226858	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ES(N,L)1102120A*	29,200	\$4,088
211226869	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0451716A*	29,200	\$4,088
211226878	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0701716A*	29,200	\$4,088
211226887	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0702120A*	29,000	\$4,060
211226896	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VSL0902120A*	29,000	\$4,060
211226906	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ESU0401712A*	29,400	\$4,116
211226917	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ESU0601716A	29,200	\$4,088
211226928	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ESU0802120A	29,400	\$4,116
211226939	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80ESU1002120A*	29,000	\$4,060
211226950	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VTL0701716A*	29,000	\$4,060
211226962	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*80VTL1102122A*	29,200	\$4,088
211226999	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*92ESN0601714A*	29,000	\$4,060
211227010	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*92ESN0801716A*	29,000	\$4,060
211227021	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*92ESN0802120A*	29,200	\$4,088
211227031	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002122A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227041	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95ESN0601714A*	29,400	\$4,116
211227063	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95ESN0802120A*	29,200	\$4,088
211227074	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002120A*	29,200	\$4,088
211227084	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002122A*	29,200	\$4,088
211227102	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0601714A*	29,200	\$4,088
211227111	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716A*	29,200	\$4,088
211227120	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120A*	29,000	\$4,060
211227129	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120A*	29,000	\$4,060
211227139	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95ESU0802120A*	29,400	\$4,116
211227150	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002120A*	29,000	\$4,060
211227160	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002122A*	29,200	\$4,088
211227180	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VTN0601714A*	29,200	\$4,088
211227190	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120A*	29,200	\$4,088
211227200	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120A*	29,200	\$4,088
211227209	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122A*	29,000	\$4,060
211227218	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	OLV098A12*	29,200	\$4,088
211227227	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	OLV112A16A	29,200	\$4,088
211227236	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	OMV098J12*	29,200	\$4,088
211227245	SMART COMFORT	DLCURAH36ABK	EA*4X37L21A*	OMV112K14A	29,200	\$4,088
211227291	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0451712A*	29,400	\$4,116
211227303	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701712A*	29,400	\$4,116
211227315	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0701716A*	29,400	\$4,116
211227326	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227338	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0901714A*	29,400	\$4,116
211227350	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227362	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227374	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227385	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0451716A*	29,400	\$4,116
211227394	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0701716A*	29,400	\$4,116
211227403	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0702120A*	29,400	\$4,116
211227412	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VSL0902120A*	29,400	\$4,116
211227433	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ESU0601716A	29,200	\$4,088
211227444	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ESU0802120A	29,600	\$4,144
211227455	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80ESU1002120A*	29,400	\$4,116
211227466	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VTL0701716A*	29,400	\$4,116
211227478	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VTL0902120A*	29,400	\$4,116
211227488	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*80VTL1102122A*	29,400	\$4,116
211227516	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*92ESN0601714A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227527	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*92ESN0801716A*	29,400	\$4,116
211227538	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*92ESN0802120A*	29,200	\$4,088
211227549	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002120A*	29,200	\$4,088
211227559	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002122A*	29,600	\$4,144
211227569	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95ESN0601714A*	29,400	\$4,116
211227580	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95ESN0802120A*	29,400	\$4,116
211227590	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95ESN1002122A*	29,600	\$4,144
211227599	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0601714A*	29,400	\$4,116
211227608	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716A*	29,400	\$4,116
211227617	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120A*	29,400	\$4,116
211227626	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120A*	29,400	\$4,116
211227636	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95ESU0601716A*	29,400	\$4,116
211227647	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95ESU0802120A*	29,600	\$4,144
211227658	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002120A*	29,400	\$4,116
211227668	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002122A*	29,600	\$4,144
211227678	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0601714A*	29,600	\$4,144
211227688	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716A*	29,400	\$4,116
211227698	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120A*	29,400	\$4,116
211227708	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120A*	29,400	\$4,116
211227717	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122A*	29,200	\$4,088
211227726	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	OLV098A12*	29,400	\$4,116
211227735	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	OMV098J12*	29,400	\$4,116
211227744	SMART COMFORT	DLCURAH36ABK	EA*4X42L21A*	OMV112K14A	29,400	\$4,116
211227772	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0702116A*	29,400	\$4,116
211227784	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902116A*	29,400	\$4,116
211227796	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902120A*	29,400	\$4,116
211227808	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)0902420A*	29,400	\$4,116
211227820	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102120A*	29,400	\$4,116
211227832	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1102420A*	29,200	\$4,088
211227844	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1352420A*	29,400	\$4,116
211227856	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ES(N,L)1552420A*	29,400	\$4,116
211227865	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80VSL0702120A*	29,400	\$4,116
211227874	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902120A*	29,400	\$4,116
211227883	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80VSL0902420A*	29,400	\$4,116
211227892	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80VSL1102422A*	29,200	\$4,088
211227902	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ESU0802120A	29,600	\$4,144
211227913	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80ESU1002120A*	29,400	\$4,116
211227924	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80VTL0902120A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227934	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*80VTL1102122A*	29,400	\$4,116
211227964	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*92ESN0802120A*	29,200	\$4,088
211227975	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002120A*	29,200	\$4,088
211227985	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002122A*	29,600	\$4,144
211227995	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*92ESN1202420A*	29,400	\$4,116
211228006	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95ESN0802120A*	29,400	\$4,116
211228017	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002120A*	29,400	\$4,116
211228027	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002122A*	29,600	\$4,144
211228037	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95ESN1202422A*	29,600	\$4,144
211228048	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95ESN1402422A*	29,600	\$4,144
211228058	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120A*	29,400	\$4,116
211228067	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120A*	29,400	\$4,116
211228076	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422A*	29,400	\$4,116
211228086	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95ESU0802120A*	29,600	\$4,144
211228097	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002120A*	29,400	\$4,116
211228107	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002122A*	29,600	\$4,144
211228117	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120A*	29,400	\$4,116
211228127	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120A*	29,400	\$4,116
211228136	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122A*	29,200	\$4,088
211228146	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422A*	29,400	\$4,116
211228155	SMART COMFORT	DLCURAH36ABK	EA*4X42L24A*	OLV112A16A	29,400	\$4,116
213353785	SMART COMFORT	DLCURAH24ABK	F5MA4*30L*B*		19,100	\$2,674
213353775	SMART COMFORT	DLCURAH24ABK	F5MA4*24L*B*		19,300	\$2,702
213249277	SMART COMFORT	DLCURAH24ABK	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076405	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601716B*	19,400	\$2,716
213076379	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601716B*	19,400	\$2,716
213076123	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002120A*	19,200	\$2,688
213076111	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*95MSU1002120A*	18,500	\$2,590
212989630	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0802120A*	19,100	\$2,674
212989618	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*95MSU0802120A*	18,600	\$2,604
212989606	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*95MSU0802120A*	19,100	\$2,674
212989258	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0601716A*	19,100	\$2,674
212989246	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0601716A*	19,100	\$2,674
212989234	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0601716A*	19,100	\$2,674
212989222	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0601716A*	19,400	\$2,716
212989210	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*95MSU0601716A*	18,700	\$2,618
212989198	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*95MSU0601716A*	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989186	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*95MSU0601716A*	19,100	\$2,674
212989174	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95MSU0601716A*	19,100	\$2,674
212989162	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95MSU0601716A*	19,100	\$2,674
212989150	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*95MSU0601716A*	18,600	\$2,604
212989138	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95MSU0601716A*	19,400	\$2,716
212988766	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0401712A*	19,200	\$2,688
212988754	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0401712A*	19,200	\$2,688
212988742	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0401712A*	19,200	\$2,688
212988730	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0401712A*	19,500	\$2,730
212988718	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*95MSU0401712A*	18,600	\$2,604
212988706	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*95MSU0401712A*	18,800	\$2,632
212988694	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*95MSU0401712A*	19,000	\$2,660
212988682	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95MSU0401712A*	19,100	\$2,674
212988670	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95MSU0401712A*	19,200	\$2,688
212988658	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*95MSU0401712A*	18,700	\$2,618
212988646	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95MSU0401712A*	19,500	\$2,730
212987829	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSM0802120A*	19,100	\$2,674
212987828	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0802120A*	19,100	\$2,674
212987817	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96MSM0802120A*	18,700	\$2,618
212987816	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96MSN0802120A*	18,700	\$2,618
212987805	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96MSM0802120A*	19,100	\$2,674
212987804	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96MSN0802120A*	19,100	\$2,674
212987492	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0801716A*	19,200	\$2,688
212987480	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0801716A*	19,200	\$2,688
212987468	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0801716A*	19,200	\$2,688
212987456	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0801716A*	19,500	\$2,730
212987444	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96MSN0801716A*	19,800	\$2,772
212987432	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96MSN0801716A*	18,800	\$2,632
212987420	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96MSN0801716A*	19,000	\$2,660
212987408	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96MSN0801716A*	19,100	\$2,674
212987396	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96MSN0801716A*	19,200	\$2,688
212987384	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96MSN0801716A*	18,700	\$2,618
212987372	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96MSN0801716A*	19,400	\$2,716
212986653	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSM0401712A*	19,100	\$2,674
212986652	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0401712A*	19,100	\$2,674
212986641	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSM0401712A*	19,100	\$2,674
212986640	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401712A*	19,100	\$2,674
212986629	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSM0401712A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986628	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401712A*	19,100	\$2,674
212986617	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSM0401712A*	19,700	\$2,758
212986616	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401712A*	19,700	\$2,758
212986605	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96MSM0401712A*	18,800	\$2,632
212986604	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96MSN0401712A*	18,800	\$2,632
211289636	SMART COMFORT	DLCURAH60ABK	FVM4X60***L		37,800	\$5,292
213607746	SMART COMFORT	DLCURAH36ABK	FTMA4B48L0C*		28,800	\$4,032
213607731	SMART COMFORT	DLCURAH36ABK	FTMA4B36L0C*		29,400	\$4,116
213607686	SMART COMFORT	DLCURAH30ABK	FTMA4B36L0C*		23,600	\$3,304
213607656	SMART COMFORT	DLCURAH24ABK	FTMA4X24L0B*		19,300	\$2,702
213607641	SMART COMFORT	DLCURAH24ABK	FTMA4B36L0C*		19,100	\$2,674
213607596	SMART COMFORT	DLCURAH18ABK	FTMA4X24L0B*		12,400	\$1,736
212986593	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96MSM0401712A*	19,000	\$2,660
212986592	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401712A*	19,000	\$2,660
212986581	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96MSM0401712A*	19,200	\$2,688
212986580	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96MSN0401712A*	19,200	\$2,688
212986569	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96MSM0401712A*	19,200	\$2,688
212986568	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401712A*	19,200	\$2,688
212986557	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96MSM0401712A*	19,200	\$2,688
212986556	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401712A*	19,200	\$2,688
212986545	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96MSM0401712A*	18,900	\$2,646
212986544	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401712A*	18,900	\$2,646
212986533	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96MSM0401712A*	19,500	\$2,730
212986532	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401712A*	19,500	\$2,730
212986268	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401410A*	19,200	\$2,688
212986256	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401410A*	19,200	\$2,688
212986148	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401410A*	19,500	\$2,730
212986136	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*96MSN0401410A*	19,500	\$2,730
212985368	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN1002120A*	19,100	\$2,674
212985356	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*92MSN1002120A*	18,700	\$2,618
212985344	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*92MSN1002120A*	19,100	\$2,674
212984694	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0801716A*	19,100	\$2,674
212984682	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0801716A*	19,100	\$2,674
212984670	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0801716A*	19,100	\$2,674
212984658	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0801716A*	19,500	\$2,730
212984646	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*92MSN0801716A*	18,400	\$2,576
212984634	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*92MSN0801716A*	18,900	\$2,646
212984622	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*92MSN0801716A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212984610	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*92MSN0801716A*	19,000	\$2,660
212984598	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*92MSN0801716A*	19,100	\$2,674
212984586	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*92MSN0801716A*	18,500	\$2,590
212984574	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*92MSN0801716A*	19,300	\$2,702
212984154	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0601714A*	19,100	\$2,674
212984142	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601714A*	19,100	\$2,674
212984130	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601714A*	19,100	\$2,674
212984118	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601714A*	19,400	\$2,716
212984106	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*92MSN0601714A*	18,700	\$2,618
212984094	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601714A*	18,900	\$2,646
212984082	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*92MSN0601714A*	19,100	\$2,674
212984070	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601714A*	19,100	\$2,674
212984058	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601714A*	19,100	\$2,674
212984046	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601714A*	18,700	\$2,618
212984034	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601714A*	19,400	\$2,716
212981817	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MSU1002120A*	19,100	\$2,674
212981805	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MSU1002120A*	19,200	\$2,688
212981793	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MSU1002120A*	19,200	\$2,688
212981781	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MSU1002120A*	19,500	\$2,730
212981757	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80MSU1002120A*	18,800	\$2,632
212981745	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80MSU1002120A*	19,100	\$2,674
212981733	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80MSU1002120A*	19,000	\$2,660
212981721	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80MSU1002120A*	19,100	\$2,674
212981709	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80MSU1002120A*	18,700	\$2,618
212981697	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80MSU1002120A*	19,500	\$2,730
212981015	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)1102120A*	19,100	\$2,674
212981003	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)1102120A*	18,800	\$2,632
212980991	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)1102120A*	19,000	\$2,660
212980605	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0902120A*	19,100	\$2,674
212980594	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0902120A*	18,600	\$2,604
212980583	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0902120A*	19,100	\$2,674
212979938	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0901714A*	19,100	\$2,674
212979926	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979914	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	19,100	\$2,674
212979902	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	19,500	\$2,730
212979890	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979878	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0901714A*	18,700	\$2,618
212979866	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0901714A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212979854	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979842	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	19,100	\$2,674
212979830	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	18,600	\$2,604
212979818	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	19,400	\$2,716
212979248	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80MS(N,L)0701716A*	19,100	\$2,674
212979236	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979224	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701716A*	19,100	\$2,674
212979212	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701716A*	19,400	\$2,716
212979200	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979188	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212979176	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979164	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979152	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701716A*	19,100	\$2,674
212979140	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701716A*	18,700	\$2,618
212978219	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978207	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	19,000	\$2,660
212978195	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	19,100	\$2,674
212978183	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	19,400	\$2,716
212978171	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	19,400	\$2,716
212978159	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0701412A*	18,700	\$2,618
212978147	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0701412A*	19,000	\$2,660
212978135	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978123	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	19,100	\$2,674
212978111	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	18,600	\$2,604
212978099	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	19,400	\$2,716
212978087	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	19,300	\$2,702
212977703	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977691	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	19,100	\$2,674
212977679	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	19,000	\$2,660
212977667	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	19,500	\$2,730
212977655	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	19,500	\$2,730
212977643	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977631	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977619	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977607	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	19,100	\$2,674
212977595	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	18,700	\$2,618
212977583	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	19,400	\$2,716
212977571	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212977006	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122B*	19,200	\$2,688
212976986	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122B*	19,100	\$2,674
212976698	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120B*	19,100	\$2,674
212976685	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002120B*	18,600	\$2,604
212976672	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120B*	19,000	\$2,660
212976425	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120B*	19,200	\$2,688
212976411	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120B*	18,600	\$2,604
212976397	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120B*	19,100	\$2,674
212976132	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716B*	18,900	\$2,646
212976119	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716B*	18,900	\$2,646
212976106	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716B*	18,900	\$2,646
212976093	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716B*	19,500	\$2,730
212976067	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716B*	19,000	\$2,660
212976054	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716B*	19,000	\$2,660
212976041	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716B*	19,000	\$2,660
212976028	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716B*	19,100	\$2,674
212976015	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0801716B*	18,800	\$2,632
212976002	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716B*	19,500	\$2,730
212975758	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412B*	19,100	\$2,674
212975747	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412B*	19,100	\$2,674
212975736	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412B*	19,000	\$2,660
212975725	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412B*	19,500	\$2,730
212975714	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412B*	19,500	\$2,730
212975703	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412B*	18,800	\$2,632
212975692	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412B*	19,100	\$2,674
212975681	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412B*	19,100	\$2,674
212975670	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412B*	19,100	\$2,674
212975659	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412B*	18,600	\$2,604
212975648	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412B*	19,400	\$2,716
212975637	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412B*	19,400	\$2,716
212975373	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712B*	19,200	\$2,688
212975362	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712B*	19,200	\$2,688
212975351	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712B*	19,200	\$2,688
212975340	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712B*	19,600	\$2,744
212975329	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712B*	18,900	\$2,646
212975318	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401712B*	18,900	\$2,646
212975307	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712B*	19,100	\$2,674
212975296	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712B*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975285	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712B*	19,200	\$2,688
212975274	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712B*	18,800	\$2,632
212975263	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712B*	19,500	\$2,730
212975064	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410B*	19,200	\$2,688
212975051	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410B*	19,200	\$2,688
212975038	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410B*	19,100	\$2,674
212975025	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410B*	19,600	\$2,744
212975012	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410B*	19,600	\$2,744
212974999	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410B*	18,800	\$2,632
212974986	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410B*	19,200	\$2,688
212974973	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410B*	19,200	\$2,688
212974960	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410B*	19,200	\$2,688
212974947	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401410B*	18,700	\$2,618
212974934	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410B*	19,500	\$2,730
212974921	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410B*	19,500	\$2,730
212974330	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VSN1002120B*	18,900	\$2,646
212974320	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120B*	19,000	\$2,660
212974120	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120B*	19,200	\$2,688
212974110	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VSN0802120B*	18,600	\$2,604
212974100	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120B*	19,100	\$2,674
212973930	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716B*	18,900	\$2,646
212973920	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716B*	18,900	\$2,646
212973910	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716B*	18,900	\$2,646
212973900	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716B*	19,500	\$2,730
212973880	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716B*	19,000	\$2,660
212973870	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716B*	19,000	\$2,660
212973860	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716B*	19,000	\$2,660
212973850	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716B*	19,100	\$2,674
212973840	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0801716B*	18,800	\$2,632
212973830	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716B*	19,500	\$2,730
212973640	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412B*	19,100	\$2,674
212973630	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412B*	19,100	\$2,674
212973620	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412B*	19,000	\$2,660
212973610	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412B*	19,500	\$2,730
212973600	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412B*	19,500	\$2,730
212973590	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412B*	18,800	\$2,632
212973580	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412B*	19,100	\$2,674
212973570	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412B*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973560	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412B*	19,100	\$2,674
212973550	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412B*	18,600	\$2,604
212973540	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412B*	19,400	\$2,716
212973530	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412B*	19,400	\$2,716
212973290	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712B*	19,200	\$2,688
212973280	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712B*	19,200	\$2,688
212973270	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712B*	19,200	\$2,688
212973260	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712B*	19,600	\$2,744
212973250	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712B*	18,900	\$2,646
212973240	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401712B*	18,900	\$2,646
212973230	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712B*	19,100	\$2,674
212973220	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712B*	19,100	\$2,674
212973210	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712B*	19,200	\$2,688
212973200	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712B*	18,800	\$2,632
212973190	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712B*	19,500	\$2,730
212973010	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410B*	19,200	\$2,688
212973000	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410B*	19,200	\$2,688
212972990	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410B*	19,200	\$2,688
212972980	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410B*	19,500	\$2,730
212972970	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410B*	19,500	\$2,730
212972960	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410B*	19,000	\$2,660
212972950	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410B*	19,200	\$2,688
212972940	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410B*	19,200	\$2,688
212972930	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410B*	19,200	\$2,688
212972920	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401410B*	18,800	\$2,632
212972910	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410B*	19,500	\$2,730
212972900	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410B*	19,500	\$2,730
212972431	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122B*	19,200	\$2,688
212972419	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122B*	18,800	\$2,632
212972407	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122B*	19,100	\$2,674
212972151	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120B*	19,100	\$2,674
212972140	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80VTL0902120B*	18,900	\$2,646
212972129	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120B*	19,100	\$2,674
212971740	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716B*	19,100	\$2,674
212971729	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716B*	19,100	\$2,674
212971718	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716B*	19,100	\$2,674
212971707	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716B*	19,500	\$2,730
212971696	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80VTL0701716B*	18,700	\$2,618

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212971685	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716B*	18,700	\$2,618
212971674	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716B*	19,100	\$2,674
212971663	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716B*	19,100	\$2,674
212971652	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716B*	19,100	\$2,674
212971641	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80VTL0701716B*	18,600	\$2,604
212971630	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716B*	19,400	\$2,716
212971251	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412B*	19,100	\$2,674
212971239	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412B*	19,100	\$2,674
212971227	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412B*	19,000	\$2,660
212971215	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412B*	19,500	\$2,730
212971203	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412B*	19,500	\$2,730
212971191	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412B*	18,700	\$2,618
212971179	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412B*	19,000	\$2,660
212971167	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412B*	19,100	\$2,674
212971155	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*80VTL0451412B*	19,100	\$2,674
212969844	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412B*	19,100	\$2,674
212969834	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412B*	19,100	\$2,674
212969824	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412B*	19,000	\$2,660
212969814	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412B*	19,500	\$2,730
212969804	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412B*	19,500	\$2,730
212969794	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451412B*	18,700	\$2,618
212969784	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412B*	19,000	\$2,660
212969774	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412B*	19,100	\$2,674
212969764	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412B*	19,100	\$2,674
212969754	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80VSL0451412B*	18,500	\$2,590
212969744	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412B*	19,300	\$2,702
211245988	SMART COMFORT	DLCURAH24ABK	FVM4X36***L		19,000	\$2,660
211245978	SMART COMFORT	DLCURAH24ABK	FVM4X24***L		19,000	\$2,660
211245967	SMART COMFORT	DLCURAH24ABK	FM(C,U)4Z36**AL*		19,300	\$2,702
211245956	SMART COMFORT	DLCURAH24ABK	FM(C,U)4Z30**AL*		19,300	\$2,702
211245945	SMART COMFORT	DLCURAH24ABK	FM(C,U)4Z24**AL*		19,500	\$2,730
211245934	SMART COMFORT	DLCURAH24ABK	FM(C,U)4X36**AL*		19,900	\$2,786
211245923	SMART COMFORT	DLCURAH24ABK	FM(C,U)4X30**AL*		19,900	\$2,786
211245912	SMART COMFORT	DLCURAH24ABK	FMA4X36**AL*		19,600	\$2,744
211245901	SMART COMFORT	DLCURAH24ABK	FMA4X30**AL*		19,600	\$2,744
211245890	SMART COMFORT	DLCURAH24ABK	FMA4X24**AL*		19,600	\$2,744
211245868	SMART COMFORT	DLCURAH24ABK	FMA4P24**AL*		19,900	\$2,786
211245857	SMART COMFORT	DLCURAH24ABK	FXM4X36**AL		18,500	\$2,590

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245846	SMART COMFORT	DLCURAH24ABK	FXM4X30**AL		19,100	\$2,674
211245835	SMART COMFORT	DLCURAH24ABK	FXM4X24**AL		19,100	\$2,674
211245824	SMART COMFORT	DLCURAH24ABK	FEM4X30**BL		19,100	\$2,674
211245812	SMART COMFORT	DLCURAH24ABK	FEM4X24**CL		19,000	\$2,660
211245800	SMART COMFORT	DLCURAH24ABK	FEM4P30**AL		19,100	\$2,674
211245789	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	OLV112A16A	19,300	\$2,702
211245780	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	OMV112K14A	19,200	\$2,688
211245771	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	OLV098A12*	18,900	\$2,646
211245762	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	OMV098J12*	19,000	\$2,660
211245752	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0601716A	19,300	\$2,702
211245741	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0802120A	19,100	\$2,674
211245730	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0401712A*	19,100	\$2,674
211245719	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0801716A*	19,500	\$2,730
211245708	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0601714A*	19,400	\$2,716
211245697	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN1002120A*	19,300	\$2,702
211245686	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0802120A*	19,300	\$2,702
211245675	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0801716A*	19,100	\$2,674
211245664	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0601714A*	19,100	\$2,674
211245652	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)1102120A*	19,400	\$2,716
211245640	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0902120A*	19,300	\$2,702
211245628	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0901714A*	19,200	\$2,688
211245616	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0702116A*	19,100	\$2,674
211245604	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701712A*	19,200	\$2,688
211245592	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0451712A*	19,100	\$2,674
211245582	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL1102122A*	19,000	\$2,660
211245572	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120A*	19,000	\$2,660
211245562	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120A*	18,900	\$2,646
211245552	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0601714A*	19,100	\$2,674
211245541	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0401712A*	19,400	\$2,716
211245531	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0701716A*	19,100	\$2,674
211245521	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716A*	19,100	\$2,674
211245510	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0802120A*	19,300	\$2,702
211245500	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712A*	19,000	\$2,660
211245490	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VTL0902120A*	19,000	\$2,660
211245477	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ESU0401712A*	19,000	\$2,660
211245466	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0601716A*	19,100	\$2,674
211245456	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0902120A*	19,000	\$2,660
211245447	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0702120A*	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245438	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0701716A*	19,000	\$2,660
211245429	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80VSL0451716A*	19,200	\$2,688
211245384	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122A*	18,900	\$2,646
211245374	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*80ES(N,L)0701716A*	19,400	\$2,716
211245363	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0401712A*	19,000	\$2,660
211245353	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716A*	19,100	\$2,674
211245344	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712A*	19,000	\$2,660
211245335	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN1002120A*	19,000	\$2,660
211245326	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120A*	19,000	\$2,660
211245317	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0601714A*	18,900	\$2,646
211245281	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV112K14A	19,200	\$2,688
211245272	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	OLV098A12*	18,900	\$2,646
211245263	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	OMV098J12*	19,000	\$2,660
211245253	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0601716A	19,300	\$2,702
211245241	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211245230	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401712A*	19,100	\$2,674
211245219	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401410A*	19,400	\$2,716
211245208	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0801716A*	19,500	\$2,730
211245197	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601714A*	19,400	\$2,716
211245186	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0801716A*	19,100	\$2,674
211245175	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601714A*	19,100	\$2,674
211245164	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601412A*	18,900	\$2,646
211245152	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211245140	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211245128	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211245116	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211245106	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601714A*	19,100	\$2,674
211245095	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0261410A*	18,900	\$2,646
211245085	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412A*	19,000	\$2,660
211245075	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410A*	19,000	\$2,660
211245064	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601412A*	19,400	\$2,716
211245053	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401712A*	19,400	\$2,716
211245042	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401410A*	19,500	\$2,730
211245032	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0701716A*	19,100	\$2,674
211245022	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716A*	19,100	\$2,674
211245012	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712A*	19,000	\$2,660
211244998	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VTL0451412A*	19,100	\$2,674
211244987	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ESU0401712A*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244976	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0601716A*	19,100	\$2,674
211244966	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0701716A*	19,000	\$2,660
211244957	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451716A*	19,200	\$2,688
211244929	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244918	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESU0401712A*	19,000	\$2,660
211244908	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716A*	19,100	\$2,674
211244899	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412A*	19,000	\$2,660
211244890	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712A*	19,000	\$2,660
211244881	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410A*	19,000	\$2,660
211244872	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601714A*	18,900	\$2,646
211244854	SMART COMFORT	DLCURAH24ABK	EN(A,D,W)4X36L17**	*80VSL0451412A*	18,900	\$2,646
211244845	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	OMV112K14A	19,200	\$2,688
211244836	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	OLV098A12*	18,900	\$2,646
211244827	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	OMV098J12*	19,000	\$2,660
213372187	SMART COMFORT	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372183	SMART COMFORT	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
211244817	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0601716A	19,300	\$2,702
211244805	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	19,100	\$2,674
211244794	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401712A*	19,100	\$2,674
211244783	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401410A*	19,400	\$2,716
211244772	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0801716A*	19,500	\$2,730
211244761	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601714A*	19,400	\$2,716
211244750	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0801716A*	19,100	\$2,674
211244739	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601714A*	19,100	\$2,674
211244728	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601412A*	18,900	\$2,646
211244716	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0901714A*	19,200	\$2,688
211244704	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	19,200	\$2,688
211244692	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	19,100	\$2,674
211244680	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	19,300	\$2,702
211244670	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601714A*	19,100	\$2,674
211244659	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0261410A*	18,900	\$2,646
211244649	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412A*	19,000	\$2,660
211244639	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410A*	19,000	\$2,660
211244628	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601412A*	19,400	\$2,716
211244617	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401712A*	19,400	\$2,716
211244606	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401410A*	19,500	\$2,730
211244596	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0701716A*	19,100	\$2,674
211244586	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244576	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712A*	19,000	\$2,660
211244562	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VTL0451412A*	19,100	\$2,674
211244551	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ESU0401712A*	19,000	\$2,660
211244540	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0601716A*	19,100	\$2,674
211244530	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0701716A*	19,000	\$2,660
211244521	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451716A*	19,200	\$2,688
211244493	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80ES(N,L)0701716A*	19,400	\$2,716
211244482	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0401712A*	19,000	\$2,660
211244472	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716A*	19,100	\$2,674
211244463	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412A*	19,000	\$2,660
211244454	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712A*	19,000	\$2,660
211244445	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410A*	19,000	\$2,660
211244436	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601714A*	18,900	\$2,646
211244418	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L17**	*80VSL0451412A*	18,900	\$2,646
211244407	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	19,100	\$2,674
211244396	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0401410A*	19,400	\$2,716
211244385	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0601412A*	18,900	\$2,646
211244373	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	19,300	\$2,702
211244362	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0261410A*	19,500	\$2,730
211244352	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412A*	19,000	\$2,660
211244342	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410A*	19,100	\$2,674
211244331	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0601412A*	19,400	\$2,716
211244320	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0401410A*	19,500	\$2,730
211244308	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*80VTL0451412A*	19,100	\$2,674
211244298	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412A*	19,000	\$2,660
211244289	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410A*	19,100	\$2,674
211244280	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*80VSL0451412A*	19,200	\$2,688
211244271	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	OMV112K14A	19,700	\$2,758
211244262	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	OLV098A12*	19,300	\$2,702
211244253	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	OMV098J12*	19,400	\$2,716
211244243	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0601716A	19,600	\$2,744
211244231	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	19,500	\$2,730
211244220	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401712A*	19,500	\$2,730
211244209	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401410A*	19,700	\$2,758
211244198	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0801716A*	19,800	\$2,772
211244187	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601714A*	19,700	\$2,758
211244176	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0801716A*	19,400	\$2,716
211244165	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601714A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244154	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601412A*	19,600	\$2,744
211244142	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0901714A*	19,500	\$2,730
211244130	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	19,500	\$2,730
211244118	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	19,400	\$2,716
211244106	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	19,600	\$2,744
211244096	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601714A*	19,400	\$2,716
211244085	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0261410A*	19,900	\$2,786
211244075	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412A*	19,300	\$2,702
211244065	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410A*	19,500	\$2,730
211244054	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601412A*	19,700	\$2,758
211244043	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401712A*	19,700	\$2,758
211244032	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401410A*	19,800	\$2,772
211244022	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0701716A*	19,400	\$2,716
211244012	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716A*	19,500	\$2,730
211244002	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712A*	19,700	\$2,758
211243988	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VTL0451412A*	19,500	\$2,730
211243977	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ESU0401712A*	19,300	\$2,702
211243966	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0601716A*	19,400	\$2,716
211243956	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0701716A*	19,400	\$2,716
211243947	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451716A*	19,500	\$2,730
211243919	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80ES(N,L)0701716A*	19,700	\$2,758
211243908	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0401712A*	19,300	\$2,702
211243898	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716A*	19,500	\$2,730
211243889	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412A*	19,300	\$2,702
211243880	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712A*	19,700	\$2,758
211243871	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410A*	19,500	\$2,730
211243862	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601714A*	19,500	\$2,730
211243844	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L17**	*80VSL0451412A*	19,500	\$2,730
211243833	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	19,500	\$2,730
211243822	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0401410A*	19,700	\$2,758
211243811	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0601412A*	19,600	\$2,744
211243799	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	19,600	\$2,744
211243788	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0261410A*	19,900	\$2,786
211243778	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412A*	19,300	\$2,702
211243768	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410A*	19,500	\$2,730
211243757	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0601412A*	19,700	\$2,758
211243746	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0401410A*	19,800	\$2,772
211243734	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*80VTL0451412A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243724	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412A*	19,300	\$2,702
211243715	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410A*	19,500	\$2,730
211243706	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X24L14**	*80VSL0451412A*	19,500	\$2,730
211243679	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	OLV098A12*	18,400	\$2,576
211243490	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*80VTL1102122A*	18,500	\$2,590
211243470	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120A*	18,400	\$2,576
211243408	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712A*	18,500	\$2,590
211243292	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002122A*	18,400	\$2,576
211243252	SMART COMFORT	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712A*	18,500	\$2,590
211243180	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	OLV098A12*	18,700	\$2,618
211243171	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	OMV098J12*	18,800	\$2,632
211243149	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0701412A*	18,900	\$2,646
211243138	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*92ESN0401712A*	18,900	\$2,646
211243094	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*92ESN0801716A*	18,900	\$2,646
211243083	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*92ESN0601714A*	18,900	\$2,646
211243036	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80ES(N,L)0451712A*	18,900	\$2,646
211243014	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601714A*	18,900	\$2,646
211242993	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412A*	18,700	\$2,618
211242983	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410A*	18,900	\$2,646
211242940	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80VTL0701716A*	18,800	\$2,632
211242930	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716A*	18,900	\$2,646
211242906	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80VTL0451412A*	18,900	\$2,646
211242895	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80ESU0401712A*	18,700	\$2,618
211242884	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*95ESU0601716A*	18,900	\$2,646
211242874	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80VSL0701716A*	18,800	\$2,632
211242865	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*80VSL0451716A*	19,000	\$2,660
211242826	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*95ESU0401712A*	18,700	\$2,618
211242816	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716A*	18,900	\$2,646
211242807	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412A*	18,700	\$2,618
211242789	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410A*	18,900	\$2,646
211242780	SMART COMFORT	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601714A*	19,000	\$2,660
211242753	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	OLV112A16A	19,200	\$2,688
211242744	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	OMV112K14A	19,100	\$2,674
211242735	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	OLV098A12*	18,900	\$2,646
211242726	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	OMV098J12*	18,900	\$2,646
211242716	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ESU0601716A	19,300	\$2,702
211242705	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ESU0802120A	19,100	\$2,674
211242694	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*92ESN0401712A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242683	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*95ESN0801716A*	19,400	\$2,716
211242672	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*95ESN0601714A*	19,300	\$2,702
211242661	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*92ESN1002120A*	19,300	\$2,702
211242650	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*92ESN0802120A*	19,300	\$2,702
211242639	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*92ESN0801716A*	19,100	\$2,674
211242628	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*92ESN0601714A*	19,100	\$2,674
211242616	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)1102120A*	19,400	\$2,716
211242604	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0902120A*	19,200	\$2,688
211242592	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242580	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0702116A*	19,100	\$2,674
211242568	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701712A*	18,800	\$2,632
211242556	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242546	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VTL1102122A*	18,900	\$2,646
211242536	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120A*	19,000	\$2,660
211242526	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120A*	18,900	\$2,646
211242516	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0601714A*	19,100	\$2,674
211242505	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*95ESN0401712A*	19,300	\$2,702
211242495	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VTL0701716A*	19,000	\$2,660
211242485	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716A*	19,100	\$2,674
211242474	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*95ESN0802120A*	19,300	\$2,702
211242464	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712A*	19,000	\$2,660
211242454	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VTL0902120A*	19,000	\$2,660
211242441	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ESU0401712A*	18,900	\$2,646
211242430	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*95ESU0601716A*	19,100	\$2,674
211242420	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VSL0902120A*	19,000	\$2,660
211242411	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VSL0702120A*	19,300	\$2,702
211242402	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VSL0701716A*	19,000	\$2,660
211242393	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80VSL0451716A*	18,800	\$2,632
211242348	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122A*	18,900	\$2,646
211242338	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*80ES(N,L)0701716A*	19,400	\$2,716
211242327	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*95ESU0401712A*	18,900	\$2,646
211242317	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716A*	19,100	\$2,674
211242308	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712A*	19,000	\$2,660
211242299	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120A*	18,900	\$2,646
211242290	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120A*	19,000	\$2,660
211242281	SMART COMFORT	DLCURAH24ABK	EA*4X36L21A*	*96VSN0601714A*	18,900	\$2,646
211242245	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	OMV112K14A	19,200	\$2,688
211242236	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	OLV098A12*	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242227	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	OMV098J12*	18,900	\$2,646
211242217	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80ESU0601716A	19,300	\$2,702
211242205	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701412A*	19,100	\$2,674
211242194	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401712A*	19,100	\$2,674
211242183	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401410A*	19,400	\$2,716
211242172	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0801716A*	19,400	\$2,716
211242161	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601714A*	19,300	\$2,702
211242150	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0801716A*	19,100	\$2,674
211242139	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601714A*	19,100	\$2,674
211242128	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601412A*	18,800	\$2,632
211242116	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211242104	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211242092	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211242080	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0451412A*	19,300	\$2,702
211242070	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601714A*	19,100	\$2,674
211242059	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0261410A*	18,900	\$2,646
211242049	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412A*	18,900	\$2,646
211242039	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410A*	18,900	\$2,646
211242028	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601412A*	19,300	\$2,702
211242017	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401712A*	19,300	\$2,702
211242006	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401410A*	19,400	\$2,716
211241996	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80VTL0701716A*	19,000	\$2,660
211241986	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716A*	19,100	\$2,674
211241976	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712A*	18,900	\$2,646
211241962	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80VTL0451412A*	19,100	\$2,674
211241951	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80ESU0401712A*	18,900	\$2,646
211241940	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95ESU0601716A*	19,100	\$2,674
211241930	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80VSL0701716A*	19,000	\$2,660
211241921	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451716A*	19,100	\$2,674
211241893	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241882	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*95ESU0401712A*	18,900	\$2,646
211241872	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716A*	19,100	\$2,674
211241863	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412A*	18,900	\$2,646
211241854	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712A*	18,900	\$2,646
211241845	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410A*	18,900	\$2,646
211241836	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601714A*	18,900	\$2,646
211241818	SMART COMFORT	DLCURAH24ABK	EA*4X36L17A*	*80VSL0451412A*	18,800	\$2,632
211241809	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	OMV112K14A	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241800	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	OLV098A12*	18,900	\$2,646
211241791	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	OMV098J12*	19,000	\$2,660
211241781	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80ESU0601716A	19,300	\$2,702
211241769	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241758	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401712A*	19,100	\$2,674
211241747	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401410A*	19,400	\$2,716
211241736	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0801716A*	19,500	\$2,730
211241725	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601714A*	19,400	\$2,716
211241714	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0801716A*	19,100	\$2,674
211241703	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601714A*	19,200	\$2,688
211241692	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601412A*	18,900	\$2,646
211241680	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0901714A*	19,200	\$2,688
211241668	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	19,200	\$2,688
211241656	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	19,100	\$2,674
211241644	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	19,400	\$2,716
211241634	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601714A*	19,100	\$2,674
211241623	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0261410A*	18,900	\$2,646
211241613	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412A*	19,000	\$2,660
211241603	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410A*	19,000	\$2,660
211241592	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601412A*	19,400	\$2,716
211241581	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401712A*	19,400	\$2,716
211241570	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401410A*	19,500	\$2,730
211241560	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80VTL0701716A*	19,100	\$2,674
211241550	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716A*	19,200	\$2,688
211241540	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712A*	19,000	\$2,660
211241526	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80VTL0451412A*	19,200	\$2,688
211241515	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80ESU0401712A*	19,000	\$2,660
211241504	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95ESU0601716A*	19,100	\$2,674
211241494	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80VSL0701716A*	19,100	\$2,674
211241485	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451716A*	19,200	\$2,688
211241457	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80ES(N,L)0701716A*	19,400	\$2,716
211241446	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*95ESU0401712A*	19,000	\$2,660
211241436	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716A*	19,200	\$2,688
211241427	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412A*	19,000	\$2,660
211241418	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712A*	19,000	\$2,660
211241409	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410A*	19,000	\$2,660
211241400	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601714A*	18,900	\$2,646
211241382	SMART COMFORT	DLCURAH24ABK	EA*4X30L17A*	*80VSL0451412A*	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241371	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	19,200	\$2,688
211241360	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*92ESN0401410A*	19,400	\$2,716
211241349	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*92ESN0601412A*	18,900	\$2,646
211241337	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	19,300	\$2,702
211241326	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*95ESN0261410A*	19,600	\$2,744
211241316	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412A*	19,000	\$2,660
211241306	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410A*	19,100	\$2,674
211241295	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*95ESN0601412A*	19,400	\$2,716
211241284	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*95ESN0401410A*	19,500	\$2,730
211241272	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*80VTL0451412A*	19,100	\$2,674
211241262	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412A*	19,000	\$2,660
211241253	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410A*	19,100	\$2,674
211241244	SMART COMFORT	DLCURAH24ABK	EA*4X30L14A*	*80VSL0451412A*	19,200	\$2,688
211241226	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	OLV098A12*	18,600	\$2,604
211241217	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	OMV098J12*	18,600	\$2,604
211241118	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*92ESN0601412A*	18,500	\$2,590
211241039	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412A*	18,600	\$2,604
211240966	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712A*	18,600	\$2,604
211240941	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80ESU0401712A*	18,600	\$2,604
211240920	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*80VSL0701716A*	18,700	\$2,618
211240872	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*95ESU0401712A*	18,600	\$2,604
211240853	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412A*	18,600	\$2,604
211240844	SMART COMFORT	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712A*	18,600	\$2,604
211240799	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	OMV112K14A	19,500	\$2,730
211240790	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	OLV098A12*	19,200	\$2,688
211240781	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	OMV098J12*	19,300	\$2,702
211240771	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80ESU0601716A	19,600	\$2,744
211240759	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240748	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401712A*	19,400	\$2,716
211240737	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401410A*	19,700	\$2,758
211240726	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0801716A*	19,700	\$2,758
211240715	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601714A*	19,600	\$2,744
211240704	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0801716A*	19,400	\$2,716
211240693	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601714A*	19,400	\$2,716
211240682	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601412A*	19,200	\$2,688
211240670	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0901714A*	19,500	\$2,730
211240658	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	19,500	\$2,730
211240646	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240634	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240624	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601714A*	19,400	\$2,716
211240613	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0261410A*	19,800	\$2,772
211240603	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412A*	19,300	\$2,702
211240593	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410A*	19,400	\$2,716
211240582	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601412A*	19,600	\$2,744
211240571	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401712A*	19,700	\$2,758
211240560	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401410A*	19,700	\$2,758
211240550	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80VTL0701716A*	19,300	\$2,702
211240540	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716A*	19,400	\$2,716
211240530	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712A*	19,300	\$2,702
211240516	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80VTL0451412A*	19,400	\$2,716
211240505	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80ESU0401712A*	19,300	\$2,702
211240494	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95ESU0601716A*	19,400	\$2,716
211240484	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80VSL0701716A*	19,300	\$2,702
211240475	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451716A*	19,400	\$2,716
211240447	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80ES(N,L)0701716A*	19,700	\$2,758
211240436	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*95ESU0401712A*	19,300	\$2,702
211240426	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716A*	19,400	\$2,716
211240417	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412A*	19,300	\$2,702
211240408	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712A*	19,300	\$2,702
211240399	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410A*	19,400	\$2,716
211240390	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601714A*	19,500	\$2,730
211240372	SMART COMFORT	DLCURAH24ABK	EA*4X24L17A*	*80VSL0451412A*	19,500	\$2,730
211240361	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	19,400	\$2,716
211240350	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*92ESN0401410A*	19,700	\$2,758
211240339	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*92ESN0601412A*	19,600	\$2,744
211240327	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	19,600	\$2,744
211240316	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*95ESN0261410A*	19,800	\$2,772
211240306	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412A*	19,300	\$2,702
211240296	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410A*	19,400	\$2,716
211240285	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*95ESN0601412A*	19,600	\$2,744
211240274	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*95ESN0401410A*	19,700	\$2,758
211240262	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*80VTL0451412A*	19,400	\$2,716
211240252	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412A*	19,300	\$2,702
211240243	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410A*	19,400	\$2,716
211240234	SMART COMFORT	DLCURAH24ABK	EA*4X24L14A*	*80VSL0451412A*	19,500	\$2,730
211239229	SMART COMFORT	DLCURAH24ABK	FJMA4*24L*B*		19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213353745	SMART COMFORT	DLCURAH18ABK	F5MA4*24L*B*		12,500	\$1,750
213353735	SMART COMFORT	DLCURAH18ABK	F5MA4*18L*A*		12,800	\$1,792
213249255	SMART COMFORT	DLCURAH18ABK	FEVA0024***NAVA43601CK		12,300	\$1,722
213076392	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601716B*	12,400	\$1,736
212989330	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0601716A*	12,200	\$1,708
212989318	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0601716A*	12,300	\$1,722
212989306	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*95MSU0601716A*	12,200	\$1,708
212989294	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*95MSU0601716A*	12,000	\$1,680
212989282	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*95MSU0601716A*	12,300	\$1,722
212989270	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*95MSU0601716A*	12,100	\$1,694
212988838	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0401712A*	12,200	\$1,708
212988826	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0401712A*	12,500	\$1,750
212988814	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*95MSU0401712A*	12,200	\$1,708
212988802	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*95MSU0401712A*	12,000	\$1,680
212988790	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*95MSU0401712A*	12,300	\$1,722
212988778	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*95MSU0401712A*	12,100	\$1,694
212987564	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0801716A*	12,200	\$1,708
212987552	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0801716A*	12,500	\$1,750
212987540	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96MSN0801716A*	12,100	\$1,694
212987528	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96MSN0801716A*	12,200	\$1,708
212987516	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96MSN0801716A*	12,500	\$1,750
212987504	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96MSN0801716A*	12,300	\$1,722
212986725	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSM0401712A*	12,300	\$1,722
212986724	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401712A*	12,300	\$1,722
212986713	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSM0401712A*	12,500	\$1,750
212986712	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401712A*	12,500	\$1,750
212986701	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96MSM0401712A*	12,300	\$1,722
212986700	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401712A*	12,300	\$1,722
212986689	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96MSM0401712A*	12,100	\$1,694
212986688	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96MSN0401712A*	12,100	\$1,694
212986677	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96MSM0401712A*	12,300	\$1,722
212986676	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401712A*	12,300	\$1,722
212986665	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96MSM0401712A*	12,100	\$1,694
212986664	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401712A*	12,100	\$1,694
212986388	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401410A*	12,300	\$1,722
212986376	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0401410A*	12,300	\$1,722
212986364	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401410A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986352	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0401410A*	12,400	\$1,736
212986340	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0401410A*	12,400	\$1,736
212986328	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401410A*	12,300	\$1,722
212986316	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*96MSN0401410A*	12,300	\$1,722
212986304	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401410A*	12,400	\$1,736
212986292	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*96MSN0401410A*	12,400	\$1,736
212986280	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401410A*	12,200	\$1,708
212984766	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0801716A*	12,100	\$1,694
212984754	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0801716A*	12,500	\$1,750
212984742	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*92MSN0801716A*	12,400	\$1,736
212984730	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*92MSN0801716A*	12,200	\$1,708
212984718	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*92MSN0801716A*	12,500	\$1,750
212984706	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*92MSN0801716A*	12,300	\$1,722
212984226	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601714A*	12,300	\$1,722
212984214	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601714A*	12,400	\$1,736
212984202	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601714A*	12,300	\$1,722
212984190	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601714A*	12,200	\$1,708
212984178	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601714A*	12,400	\$1,736
212984166	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601714A*	12,200	\$1,708
212981889	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MSU1002120A*	12,300	\$1,722
212981877	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MSU1002120A*	12,600	\$1,764
212981865	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80MSU1002120A*	12,300	\$1,722
212981853	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80MSU1002120A*	12,100	\$1,694
212981841	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80MSU1002120A*	12,300	\$1,722
212981829	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80MSU1002120A*	12,200	\$1,708
212980010	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0901714A*	12,300	\$1,722
212979998	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0901714A*	12,400	\$1,736
212979986	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0901714A*	12,300	\$1,722
212979974	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212979962	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0901714A*	12,400	\$1,736
212979950	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0901714A*	12,200	\$1,708
212978353	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0701412A*	12,200	\$1,708
212978341	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0701412A*	12,200	\$1,708
212978329	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0701412A*	12,400	\$1,736
212978317	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978305	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0701412A*	12,400	\$1,736
212978293	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0701412A*	12,100	\$1,694
212978279	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0701412A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212978267	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212978255	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978243	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0701412A*	12,400	\$1,736
212978231	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0701412A*	12,200	\$1,708
212977835	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80MS(N,L)0451412A*	12,300	\$1,722
212977823	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*80MS(N,L)0451412A*	12,300	\$1,722
212977811	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80MS(N,L)0451412A*	12,400	\$1,736
212977799	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977787	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*80MS(N,L)0451412A*	12,400	\$1,736
212977775	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977763	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977751	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80MS(N,L)0451412A*	12,100	\$1,694
212977739	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80MS(N,L)0451412A*	12,400	\$1,736
212977727	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*80MS(N,L)0451412A*	12,300	\$1,722
212977715	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80MS(N,L)0451412A*	12,200	\$1,708
212975846	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716B*	12,200	\$1,708
212975833	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716B*	12,500	\$1,750
212975820	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716B*	12,200	\$1,708
212975807	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716B*	12,000	\$1,680
212975794	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716B*	12,300	\$1,722
212975781	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716B*	12,100	\$1,694
212975494	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412B*	12,200	\$1,708
212975483	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412B*	12,200	\$1,708
212975472	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412B*	12,400	\$1,736
212975461	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412B*	12,400	\$1,736
212975450	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412B*	12,400	\$1,736
212975439	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412B*	12,200	\$1,708
212975428	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412B*	12,200	\$1,708
212975417	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412B*	12,000	\$1,680
212975406	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412B*	12,300	\$1,722
212975395	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412B*	12,200	\$1,708
212975384	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412B*	12,100	\$1,694
212975131	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712B*	12,200	\$1,708
212975120	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712B*	12,500	\$1,750
212975109	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712B*	12,200	\$1,708
212975098	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712B*	12,100	\$1,694
212975087	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712B*	12,300	\$1,722
212975076	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712B*	12,100	\$1,694

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974752	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410B*	12,200	\$1,708
212974739	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410B*	12,200	\$1,708
212974726	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410B*	12,400	\$1,736
212974713	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410B*	12,400	\$1,736
212974700	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410B*	12,400	\$1,736
212974687	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410B*	12,200	\$1,708
212974674	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410B*	12,200	\$1,708
212974661	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410B*	12,100	\$1,694
212974648	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410B*	12,300	\$1,722
212974635	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410B*	12,400	\$1,736
212974622	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410B*	12,100	\$1,694
212973710	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716B*	12,200	\$1,708
212973700	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716B*	12,500	\$1,750
212973690	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716B*	12,200	\$1,708
212973680	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716B*	12,000	\$1,680
212973670	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716B*	12,300	\$1,722
212973660	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716B*	12,100	\$1,694
212973400	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412B*	12,200	\$1,708
212973390	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412B*	12,200	\$1,708
212973380	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412B*	12,400	\$1,736
212973370	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412B*	12,400	\$1,736
212973360	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412B*	12,400	\$1,736
212973350	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412B*	12,200	\$1,708
212973340	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412B*	12,200	\$1,708
212973330	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412B*	12,000	\$1,680
212973320	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412B*	12,300	\$1,722
212973310	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412B*	12,200	\$1,708
212973300	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412B*	12,100	\$1,694
212973070	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712B*	12,200	\$1,708
212973060	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712B*	12,500	\$1,750
212973050	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712B*	12,200	\$1,708
212973040	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712B*	12,100	\$1,694
212973030	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712B*	12,300	\$1,722
212973020	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712B*	12,100	\$1,694
212972770	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410B*	12,200	\$1,708
212972760	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410B*	12,200	\$1,708
212972750	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410B*	12,400	\$1,736
212972740	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410B*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212972730	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410B*	12,400	\$1,736
212972720	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410B*	12,200	\$1,708
212972710	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410B*	12,200	\$1,708
212972700	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410B*	12,100	\$1,694
212972690	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410B*	12,300	\$1,722
212972680	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410B*	12,300	\$1,722
212972670	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410B*	12,100	\$1,694
212971498	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716B*	12,300	\$1,722
212971487	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716B*	12,400	\$1,736
212971476	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716B*	12,300	\$1,722
212971465	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716B*	12,100	\$1,694
212971454	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716B*	12,400	\$1,736
212971443	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716B*	12,200	\$1,708
212969604	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412B*	12,200	\$1,708
212969594	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412B*	12,200	\$1,708
212969584	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412B*	12,500	\$1,750
212969574	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412B*	12,500	\$1,750
212969564	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412B*	12,500	\$1,750
212969554	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412B*	12,400	\$1,736
212969544	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412B*	12,200	\$1,708
212969534	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412B*	12,500	\$1,750
212969524	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412B*	12,500	\$1,750
212969514	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412B*	12,300	\$1,722
211265045	SMART COMFORT	DLCURAH18ABK	FVM4X24***L		12,400	\$1,736
211265023	SMART COMFORT	DLCURAH18ABK	FM(C,U)4Z30**AL*		12,400	\$1,736
211265002	SMART COMFORT	DLCURAH18ABK	FM(C,U)4Z24**AL*		12,500	\$1,750
211264980	SMART COMFORT	DLCURAH18ABK	FM(C,U)4Z18**AL*		12,500	\$1,750
211264958	SMART COMFORT	DLCURAH18ABK	FMA4X24**AL*		12,400	\$1,736
211264936	SMART COMFORT	DLCURAH18ABK	FMA4X18**AL*		12,400	\$1,736
211264915	SMART COMFORT	DLCURAH18ABK	FXM4X30**AL		12,400	\$1,736
211264892	SMART COMFORT	DLCURAH18ABK	FXM4X24**AL		12,400	\$1,736
211264772	SMART COMFORT	DLCURAH18ABK	FEM4P18**AL		12,300	\$1,722
211264748	SMART COMFORT	DLCURAH18ABK	FJMA4*18L*A*		12,700	\$1,778
211264722	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	OMV112K14A	12,600	\$1,764
211264704	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	OLV098A12*	12,600	\$1,764
211264686	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	OMV098J12*	12,600	\$1,764
211264666	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0601716A	12,700	\$1,778
211264642	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701412A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211264619	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401712A*	12,500	\$1,750
211264597	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401410A*	12,500	\$1,750
211264576	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601714A*	12,300	\$1,722
211264553	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601412A*	12,500	\$1,750
211264529	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0701712A*	12,500	\$1,750
211264506	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451712A*	12,400	\$1,736
211264481	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ES(N,L)0451412A*	12,500	\$1,750
211264461	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601714A*	12,400	\$1,736
211264436	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0261410A*	12,600	\$1,764
211264416	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412A*	12,400	\$1,736
211264394	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410A*	12,300	\$1,722
211264333	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0601412A*	12,400	\$1,736
211264289	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401712A*	12,200	\$1,708
211264255	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401410A*	12,400	\$1,736
211264225	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0701716A*	12,200	\$1,708
211264186	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716A*	12,200	\$1,708
211264153	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712A*	12,400	\$1,736
211264119	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VTL0451412A*	12,300	\$1,722
211264097	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80ESU0401712A*	12,700	\$1,778
211264077	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0701716A*	12,200	\$1,708
211264059	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451716A*	12,300	\$1,722
211264012	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESU0401712A*	12,400	\$1,736
211263994	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716A*	12,200	\$1,708
211263976	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412A*	12,400	\$1,736
211263958	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712A*	12,400	\$1,736
211263941	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410A*	12,300	\$1,722
211263922	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601714A*	12,400	\$1,736
211263885	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L17**	*80VSL0451412A*	12,400	\$1,736
211263863	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0701412A*	12,300	\$1,722
211263839	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0401410A*	12,500	\$1,750
211263818	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0601412A*	12,500	\$1,750
211263793	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*80ES(N,L)0451412A*	12,500	\$1,750
211263770	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0261410A*	12,500	\$1,750
211263750	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412A*	12,400	\$1,736
211263729	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410A*	12,200	\$1,708
211263704	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0601412A*	12,400	\$1,736
211263681	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0401410A*	12,400	\$1,736
211263656	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*80VTL0451412A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263635	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412A*	12,400	\$1,736
211263617	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410A*	12,200	\$1,708
211263598	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X30L14**	*80VSL0451412A*	12,400	\$1,736
211263580	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	OMV112K14A	12,800	\$1,792
211263561	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	OLV098A12*	12,700	\$1,778
211263543	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	OMV098J12*	12,800	\$1,792
211263522	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0601716A	12,800	\$1,792
211263497	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701412A*	12,400	\$1,736
211263474	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401712A*	12,600	\$1,764
211263451	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401410A*	12,600	\$1,764
211263428	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0801716A*	12,900	\$1,806
211263405	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601714A*	12,400	\$1,736
211263382	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601412A*	12,600	\$1,764
211263357	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0701712A*	12,600	\$1,764
211263332	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451712A*	12,900	\$1,806
211263307	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ES(N,L)0451412A*	12,600	\$1,764
211263286	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601714A*	12,500	\$1,750
211263261	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0261410A*	12,700	\$1,778
211263240	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412A*	12,500	\$1,750
211263219	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410A*	12,300	\$1,722
211263194	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0601412A*	12,500	\$1,750
211263172	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401712A*	12,300	\$1,722
211263149	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401410A*	12,500	\$1,750
211263134	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0701716A*	12,300	\$1,722
211263113	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716A*	12,300	\$1,722
211263092	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712A*	12,500	\$1,750
211263064	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VTL0451412A*	12,400	\$1,736
211263042	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80ESU0401712A*	12,700	\$1,778
211263021	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0601716A*	12,900	\$1,806
211263001	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0701716A*	12,300	\$1,722
211262983	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451716A*	12,400	\$1,736
211262927	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESU0401712A*	12,400	\$1,736
211262908	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716A*	12,300	\$1,722
211262891	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412A*	12,500	\$1,750
211262873	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712A*	12,500	\$1,750
211262856	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410A*	12,300	\$1,722
211262838	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601714A*	12,400	\$1,736
211262802	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L17**	*80VSL0451412A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262779	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262758	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0401410A*	12,600	\$1,764
211262735	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0601412A*	12,600	\$1,764
211262711	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262689	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0261410A*	12,700	\$1,778
211262669	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412A*	12,500	\$1,750
211262649	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410A*	12,300	\$1,722
211262625	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0601412A*	12,500	\$1,750
211262603	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0401410A*	12,500	\$1,750
211262578	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*80VTL0451412A*	12,400	\$1,736
211262558	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412A*	12,500	\$1,750
211262541	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410A*	12,300	\$1,722
211262522	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X24L14**	*80VSL0451412A*	12,400	\$1,736
211262500	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0701412A*	12,400	\$1,736
211262478	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0401410A*	12,600	\$1,764
211262456	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0601412A*	12,600	\$1,764
211262433	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*80ES(N,L)0451412A*	12,600	\$1,764
211262411	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0261410A*	12,700	\$1,778
211262390	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412A*	12,500	\$1,750
211262370	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410A*	12,300	\$1,722
211262346	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0601412A*	12,500	\$1,750
211262324	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0401410A*	12,500	\$1,750
211262300	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*80VTL0451412A*	12,400	\$1,736
211262280	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412A*	12,500	\$1,750
211262263	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410A*	12,300	\$1,722
211262245	SMART COMFORT	DLCURAH18ABK	EN(A,D)4X18L14**	*80VSL0451412A*	12,500	\$1,750
211262228	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	OMV112K14A	12,600	\$1,764
211262209	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	OLV098A12*	12,600	\$1,764
211262192	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	OMV098J12*	12,600	\$1,764
211262170	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701412A*	12,300	\$1,722
211262149	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401712A*	12,500	\$1,750
211262128	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401410A*	12,500	\$1,750
211262106	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601714A*	12,300	\$1,722
211262084	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601412A*	12,500	\$1,750
211262061	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0701712A*	12,500	\$1,750
211262035	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451712A*	12,400	\$1,736
211262009	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261988	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601714A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261962	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*95ESN0261410A*	12,600	\$1,764
211261942	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412A*	12,500	\$1,750
211261926	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410A*	12,200	\$1,708
211261903	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*95ESN0601412A*	12,400	\$1,736
211261876	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401712A*	12,200	\$1,708
211261853	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401410A*	12,400	\$1,736
211261836	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80VTL0701716A*	12,200	\$1,708
211261821	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716A*	12,200	\$1,708
211261800	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712A*	12,400	\$1,736
211261773	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80VTL0451412A*	12,300	\$1,722
211261752	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80ESU0401712A*	12,700	\$1,778
211261731	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80VSL0701716A*	12,200	\$1,708
211261713	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451716A*	12,300	\$1,722
211261658	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*95ESU0401712A*	12,300	\$1,722
211261638	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716A*	12,200	\$1,708
211261620	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412A*	12,500	\$1,750
211261602	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712A*	12,400	\$1,736
211261584	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410A*	12,200	\$1,708
211261566	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601714A*	12,400	\$1,736
211261531	SMART COMFORT	DLCURAH18ABK	EA*4X30L17A*	*80VSL0451412A*	12,400	\$1,736
211261509	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211261487	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*92ESN0401410A*	12,500	\$1,750
211261465	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*92ESN0601412A*	12,500	\$1,750
211261441	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*80ES(N,L)0451412A*	12,500	\$1,750
211261419	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*95ESN0261410A*	12,500	\$1,750
211261400	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412A*	12,400	\$1,736
211261380	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410A*	12,200	\$1,708
211261356	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*95ESN0601412A*	12,400	\$1,736
211261336	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*95ESN0401410A*	12,400	\$1,736
211261312	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*80VTL0451412A*	12,300	\$1,722
211261292	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412A*	12,400	\$1,736
211261273	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410A*	12,200	\$1,708
211261255	SMART COMFORT	DLCURAH18ABK	EA*4X30L14A*	*80VSL0451412A*	12,400	\$1,736
211261236	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	OMV112K14A	12,500	\$1,750
211261218	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	OLV098A12*	12,500	\$1,750
211261200	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	OMV098J12*	12,500	\$1,750
211261169	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80ESU0601716A	12,600	\$1,764
211261130	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701412A*	12,100	\$1,694

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211261082	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401712A*	12,400	\$1,736
211261054	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401410A*	12,400	\$1,736
211261041	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601714A*	12,200	\$1,708
211261028	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601412A*	12,400	\$1,736
211261014	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211261000	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211260985	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211260973	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601714A*	12,200	\$1,708
211260958	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*95ESN0261410A*	12,400	\$1,736
211260947	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412A*	12,300	\$1,722
211260934	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410A*	12,100	\$1,694
211260920	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*95ESN0601412A*	12,300	\$1,722
211260905	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401712A*	12,100	\$1,694
211260892	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401410A*	12,300	\$1,722
211260880	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80VTL0701716A*	12,000	\$1,680
211260868	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716A*	12,100	\$1,694
211260854	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712A*	12,300	\$1,722
211260837	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80VTL0451412A*	12,200	\$1,708
211260824	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80ESU0401712A*	12,500	\$1,750
211260811	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80VSL0701716A*	12,100	\$1,694
211260800	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451716A*	12,200	\$1,708
211260766	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*95ESU0401712A*	12,200	\$1,708
211260754	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716A*	12,100	\$1,694
211260742	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412A*	12,300	\$1,722
211260732	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712A*	12,300	\$1,722
211260722	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410A*	12,100	\$1,694
211260711	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601714A*	12,200	\$1,708
211260690	SMART COMFORT	DLCURAH18ABK	EA*4X25L17A*	*80VSL0451412A*	12,200	\$1,708
211260679	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	OMV112K14A	12,700	\$1,778
211260669	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	OLV098A12*	12,700	\$1,778
211260658	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	OMV098J12*	12,700	\$1,778
211260647	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80ESU0601716A	12,800	\$1,792
211260632	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701412A*	12,400	\$1,736
211260620	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401712A*	12,600	\$1,764
211260609	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401410A*	12,600	\$1,764
211260597	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601714A*	12,400	\$1,736
211260584	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601412A*	12,600	\$1,764
211260570	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0701712A*	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260555	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451712A*	12,900	\$1,806
211260541	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260529	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601714A*	12,400	\$1,736
211260515	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*95ESN0261410A*	12,700	\$1,778
211260503	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412A*	12,500	\$1,750
211260491	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410A*	12,300	\$1,722
211260476	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*95ESN0601412A*	12,500	\$1,750
211260463	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401712A*	12,300	\$1,722
211260450	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401410A*	12,500	\$1,750
211260438	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80VTL0701716A*	12,200	\$1,708
211260426	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716A*	12,300	\$1,722
211260413	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712A*	12,500	\$1,750
211260396	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80VTL0451412A*	12,400	\$1,736
211260383	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80ESU0401712A*	12,700	\$1,778
211260371	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80VSL0701716A*	12,300	\$1,722
211260360	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451716A*	12,400	\$1,736
211260326	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*95ESU0401712A*	12,400	\$1,736
211260314	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716A*	12,300	\$1,722
211260304	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412A*	12,500	\$1,750
211260293	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712A*	12,500	\$1,750
211260282	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410A*	12,300	\$1,722
211260271	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601714A*	12,400	\$1,736
211260250	SMART COMFORT	DLCURAH18ABK	EA*4X24L17A*	*80VSL0451412A*	12,400	\$1,736
211260237	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0701412A*	12,300	\$1,722
211260224	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*92ESN0401410A*	12,600	\$1,764
211260211	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*92ESN0601412A*	12,600	\$1,764
211260196	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*80ES(N,L)0451412A*	12,600	\$1,764
211260181	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*95ESN0261410A*	12,600	\$1,764
211260171	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412A*	12,500	\$1,750
211260161	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410A*	12,300	\$1,722
211260147	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*95ESN0601412A*	12,500	\$1,750
211260132	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*95ESN0401410A*	12,500	\$1,750
211260117	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*80VTL0451412A*	12,400	\$1,736
211260106	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412A*	12,500	\$1,750
211260093	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410A*	12,300	\$1,722
211260079	SMART COMFORT	DLCURAH18ABK	EA*4X24L14A*	*80VSL0451412A*	12,400	\$1,736
211260066	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	OMV112K14A	12,600	\$1,764
211260052	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	OLV098A12*	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260038	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	OMV098J12*	12,600	\$1,764
211260023	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80ESU0601716A	12,700	\$1,778
211260006	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701412A*	12,200	\$1,708
211259991	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401712A*	12,400	\$1,736
211259975	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401410A*	12,400	\$1,736
211259959	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601714A*	12,200	\$1,708
211259943	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601412A*	12,500	\$1,750
211259927	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0701712A*	12,400	\$1,736
211259912	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451712A*	12,700	\$1,778
211259896	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80ES(N,L)0451412A*	12,400	\$1,736
211259883	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601714A*	12,300	\$1,722
211259866	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*95ESN0261410A*	12,500	\$1,750
211259852	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412A*	12,400	\$1,736
211259841	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410A*	12,100	\$1,694
211259828	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*95ESN0601412A*	12,300	\$1,722
211259816	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401712A*	12,100	\$1,694
211259804	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401410A*	12,400	\$1,736
211259793	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80VTL0701716A*	12,000	\$1,680
211259782	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716A*	12,100	\$1,694
211259770	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712A*	12,300	\$1,722
211259754	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80VTL0451412A*	12,200	\$1,708
211259740	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80ESU0401712A*	12,600	\$1,764
211259726	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80VSL0701716A*	12,100	\$1,694
211259713	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451716A*	12,200	\$1,708
211259674	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*95ESU0401712A*	12,200	\$1,708
211259660	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716A*	12,100	\$1,694
211259649	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412A*	12,400	\$1,736
211259636	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712A*	12,300	\$1,722
211259624	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410A*	12,100	\$1,694
211259611	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601714A*	12,300	\$1,722
211259586	SMART COMFORT	DLCURAH18ABK	EA*4X19L17A*	*80VSL0451412A*	12,300	\$1,722
211257342	SMART COMFORT	DLCURAH18ABK	FJMA4*24L*B*		12,800	\$1,792
202119278	SMART COMFORT	DLCSRAH12AAK	DLFSCAH12XAK		8,200	\$1,148
202119282	SMART COMFORT	DLCSRAH18AAK	DLFSCAH18XAK		12,000	\$1,680
202119280	SMART COMFORT	DLCSRAH12AAK	DLFSDAH12XAK		8,100	\$1,134
202119284	SMART COMFORT	DLCSRAH24AAK	DLFSFAH24XAK		17,200	\$2,408
202119336	SMART COMFORT	DLCLRAH48AAK	DLFLFAH48XAK		35,000	\$4,900
202119264	SMART COMFORT	DLCSRAH18AAK	DLFSHAH18XAK		11,900	\$1,666

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
202119265	SMART COMFORT	DLCSTRAH24AAK	DLFSAH24XAK		15,000	\$2,100
202463659	SMART COMFORT	DLCSTRAH24AAK	DLFSAH24XAK		15,450	\$2,163
202119285	SMART COMFORT	DLCSTRAH24AAK	DLFSAH24XAK		16,200	\$2,268
207643169	SMART COMFORT	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340
207643163	SMART COMFORT	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207643172	SMART COMFORT	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643168	SMART COMFORT	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207643171	SMART COMFORT	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220
207643162	SMART COMFORT	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643170	SMART COMFORT	DLCMHBH36DAK	Heat pump without ducts		22,000	\$3,080
207643167	SMART COMFORT	DLCMHBH48EAK	Heat pump without ducts		34,000	\$4,760
207643161	SMART COMFORT	DLCMHBH30DAK	Heat pump without ducts		18,500	\$2,590
211222793	SMART COMFORT	DLCSTRAH30ABK	FXM4X36**AL		23,200	\$3,248
211230823	SMART COMFORT	DLCSTRAH36ABK	FEM4P42**AL		29,200	\$4,088
211230834	SMART COMFORT	DLCSTRAH36ABK	FEM4P48**AL		29,400	\$4,116
211230846	SMART COMFORT	DLCSTRAH36ABK	FEM4X42**BL		29,200	\$4,088
211230858	SMART COMFORT	DLCSTRAH36ABK	FEM4X48**BL		29,400	\$4,116
211230880	SMART COMFORT	DLCSTRAH36ABK	FMA4P36**AL*		29,800	\$4,172
211230912	SMART COMFORT	DLCSTRAH36ABK	FXM4X36**AL		29,000	\$4,060
211719734	SMART COMFORT	DLCSTRAH18ABK	FMA4P18**AL*		12,700	\$1,778
211264871	SMART COMFORT	DLCSTRAH18ABK	FXM4X18**AL		12,300	\$1,722
211264848	SMART COMFORT	DLCSTRAH18ABK	FEM4X24**CL		12,100	\$1,694
211264818	SMART COMFORT	DLCSTRAH18ABK	FEM4X18**BL		12,300	\$1,722
211264794	SMART COMFORT	DLCSTRAH18ABK	FEM4P24**AL		12,300	\$1,722
209852124	SMART COMFORT	DLCSTRAH18ABK	DLFUAH18XAK		13,500	\$1,890
209852125	SMART COMFORT	DLCSTRAH24ABK	DLFUAH24XAK		19,200	\$2,688
209852127	SMART COMFORT	DLCSTRAH48ABK	DLFUAH48XAK		36,000	\$5,040
212979128	SMART COMFORT	DLCSTRAH24ABK	EA*4X24L17A*	*80MS(N,L)0701716A*	19,400	\$2,716
212986160	SMART COMFORT	DLCSTRAH24ABK	EA*4X25L17A*	*96MSN0401410A*	18,800	\$2,632
212986172	SMART COMFORT	DLCSTRAH24ABK	EA*4X30L14A*	*96MSN0401410A*	19,200	\$2,688
212986184	SMART COMFORT	DLCSTRAH24ABK	EA*4X30L17A*	*96MSN0401410A*	19,200	\$2,688
212986196	SMART COMFORT	DLCSTRAH24ABK	EA*4X36L17A*	*96MSN0401410A*	19,200	\$2,688
212986208	SMART COMFORT	DLCSTRAH24ABK	EA*4X37L17A*	*96MSN0401410A*	18,800	\$2,632
212986220	SMART COMFORT	DLCSTRAH24ABK	EN(A,D)4X24L14**	*96MSN0401410A*	19,500	\$2,730
212986232	SMART COMFORT	DLCSTRAH24ABK	EN(A,D)4X24L17**	*96MSN0401410A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986244	SMART COMFORT	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0401410A*	19,200	\$2,688
216369242	STAR AIR KONTROL	SAK-48-QZ/220V	Heat pump with ducts		37,000	\$5,180
216369248	STAR AIR KONTROL	SAK-24FDN2-M18M	SAK-24FDN1-M18M		20,000	\$2,800
216369250	STAR AIR KONTROL	SAK-48FDN2-M18M	SAK-48FDN1-M18M		32,400	\$4,536
213279889	STAR AIR KONTROL	SAK-48CONS/220V	SAK-48CONS/220V		29,000	\$4,060
212316186	STEALTH	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MC		10,000	\$1,400
212316158	STEALTH	ACIQ-12ZPL-HP230B	ACIQ-12W-HH-MB		10,000	\$1,400
212316159	STEALTH	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MB		15,000	\$2,100
212316187	STEALTH	ACIQ-18ZPL-HP230B	ACIQ-18W-HH-MC		15,000	\$2,100
212316188	STEALTH	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MC		21,200	\$2,968
212316160	STEALTH	ACIQ-24ZPL-HP230B	ACIQ-24W-HH-MB		21,200	\$2,968
212316162	STEALTH	ACIQ-12ZPL-HP230B	ACIQ-12CC-HH-MB		9,900	\$1,386
212316168	STEALTH	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MB		9,600	\$1,344
212316166	STEALTH	ACIQ-18ZPL-HP230B	ACIQ-18CD-HH-MB		15,000	\$2,100
212316175	STEALTH	ACIQ-27Z-HH-M3B	Heat pump with ducts		27,000	\$3,780
212316204	STEALTH	ACIQ-55Z-HH-M5B	Heat pump with ducts		35,200	\$4,928
212316201	STEALTH	ACIQ-12ZPL-HP230B	ACIQ-12FM-HH-MC		10,200	\$1,428
212316199	STEALTH	ACIQ-12ZPL-HP230B	SCC-1218-HH-M		9,500	\$1,330
212316200	STEALTH	ACIQ-18ZPL-HP230B	SCC-1218-HH-M		14,500	\$2,030
212316176	STEALTH	ACIQ-27Z-HH-M3B	Combination heat pumps with or without ducts		26,800	\$3,752
212316205	STEALTH	ACIQ-55Z-HH-M5B	Combination heat pumps with or without ducts		34,800	\$4,872
212316171	STEALTH	ACIQ-18Z-HH-M2B	Heat pump without ducts		15,000	\$2,100
212316174	STEALTH	ACIQ-27Z-HH-M3B	Heat pump without ducts		26,600	\$3,724
212316180	STEALTH	ACIQ-48Z-HH-M5B	Heat pump without ducts		36,000	\$5,040
212316203	STEALTH	ACIQ-55Z-HH-M5B	Heat pump without ducts		34,400	\$4,816
213492162	STEALTH	ACIQ-36-HPC	ACIQ-36-AHB		30,400	\$4,256
214810561	STEALTH	ACIQ-18-HPB	ACIQ-18-AHB		13,500	\$1,890
212316173	STEALTH	ACIQ-18Z-HH-M2B	Combination heat pumps with or without ducts		15,500	\$2,170
212316182	STEALTH	ACIQ-48Z-HH-M5B	Combination heat pumps with or without ducts		36,000	\$5,040
212316170	STEALTH	ACIQ-24ZPL-HP230B	ACIQ-24FM-HH-MB		19,000	\$2,660
212316181	STEALTH	ACIQ-48Z-HH-M5B	Heat pump with ducts		36,000	\$5,040
212316172	STEALTH	ACIQ-18Z-HH-M2B	Heat pump with ducts		16,000	\$2,240
212316177	STEALTH	ACIQ-36Z-HH-M4B	Heat pump without ducts		33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212316179	STEALTH	ACIQ-36Z-HH-M4B	Combination heat pumps with or without ducts		34,000	\$4,760
212316165	STEALTH	ACIQ-12ZPL-HP230B	ACIQ-12CD-HH-MB		10,600	\$1,484
212316167	STEALTH	ACIQ-24ZPL-HP230B	ACIQ-24CD-HH-MB		21,000	\$2,940
215570368	STEALTH	ACIQ-30-HPB	ACIQ-30-AHB		21,000	\$2,940
212394356	STEALTH	ACIQ-24-HPB	ACIQ-24-ACL		21,000	\$2,940
212394358	STEALTH	ACIQ-36-HPB	ACIQ-36-ACL		33,000	\$4,620
213492171	STEALTH	ACIQ-30-HPB	ACIQ-36-ACL-17		19,600	\$2,744
212316192	STEALTH	ACIQ-48ZPL-HP230B	ACIQ-48CD-HH-MB		39,500	\$5,530
212316189	STEALTH	ACIQ-36ZPL-HP230B	ACIQ-36CC-HH-MB		33,000	\$4,620
212316195	STEALTH	ACIQ-48ZPL-HP230B	ACIQ-48FM-HH-MB		35,000	\$4,900
212316190	STEALTH	ACIQ-48ZPL-HP230B	ACIQ-48CC-HH-MB		35,000	\$4,900
213492173	STEALTH	ACIQ-36-HPB	ACIQ-36-ACL-17		27,400	\$3,836
213492165	STEALTH	ACIQ-36-HPC	ACIQ-36-ACL		27,000	\$3,780
213492163	STEALTH	ACIQ-36-HPC	ACIQ-36-ACL-17		27,000	\$3,780
213500940	STEALTH	ACIQ-36-HPC	ACIQ-36-AHB*		31,800	\$4,452
213433312	STEALTH	ACIQ-36-HPB	ACIQ-36W-P		32,800	\$4,592
213433310	STEALTH	ACIQ-24-HPB	ACIQ-24W-P		19,200	\$2,688
213433309	STEALTH	ACIQ-18-HPB	ACIQ-18W-P		13,500	\$1,890
213433311	STEALTH	ACIQ-30-HPB	ACIQ-30W-P		20,000	\$2,800
213433305	STEALTH	ACIQ-18-HPB	ACIQ-18W-WM		15,800	\$2,212
213433306	STEALTH	ACIQ-24-HPB	ACIQ-24W-WM		20,000	\$2,800
213433300	STEALTH	ACIQ-60HPB	ACIQ-60-ACL		37,000	\$5,180
213492170	STEALTH	ACIQ-30-HPB	ACIQ-36-ACL		22,600	\$3,164
212316193	STEALTH	ACIQ-60ZPL-HP230B	ACIQ-60CD-HH-MB		40,000	\$5,600
212316196	STEALTH	ACIQ-60ZPL-HP230B	ACIQ-60FM-HH-MB		40,000	\$5,600
212316194	STEALTH	ACIQ-36ZPL-HP230B	ACIQ-36FM-HH-MB		32,000	\$4,480
212394357	STEALTH	ACIQ-30-HPB	ACIQ-30-ACL		22,600	\$3,164
216445286	STELPRO	SELB-H12A-O	SELB-H12A-I		10,800	\$1,512
216445287	STELPRO	SELB-H18A-O	SELB-H18A-I		18,000	\$2,520
216445288	STELPRO	SELB-H24A-O	SELB-H24A-I		22,000	\$3,080
216082322	STELPRO	SEPB-H12A-O	SEPB-H12A-I		9,800	\$1,372
216082329	STELPRO	SEPB-H12A-O	SICB1-H12A-I		10,000	\$1,400
216082335	STELPRO	SEPB-H12A-O	SFCB1-H12A-I		10,200	\$1,428
216082324	STELPRO	SEPB-H18A-O	SEPB-H18A-I		16,600	\$2,324
216082331	STELPRO	SEPB-H18A-O	SICB1-H18A-I		14,900	\$2,086
216082337	STELPRO	SEPB-H18A-O	SFCB1-H18A-I		15,000	\$2,100
216082326	STELPRO	SEPB-H24A-O	SEPB-H24A-I		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216082332	STELPRO	SEP8-H24A-O	SICB1-H24A-I		20,400	\$2,856
216082339	STELPRO	SEP8-H24A-O	SFCB1-H24A-I		21,600	\$3,024
216617670	STELPRO	SMZ2B1-H18A-O	Heat pump without ducts		17,600	\$2,464
216617671	STELPRO	SMZ2B1-H18A-O	Heat pump with ducts		17,000	\$2,380
216617672	STELPRO	SMZ2B1-H18A-O	Combination heat pumps with or without ducts		17,300	\$2,422
216617685	STELPRO	SMZ2B1V-H18A-O	Heat pump without ducts		17,600	\$2,464
216617686	STELPRO	SMZ2B1V-H18A-O	Heat pump with ducts		17,000	\$2,380
216617687	STELPRO	SMZ2B1V-H18A-O	Combination heat pumps with or without ducts		17,300	\$2,422
216617673	STELPRO	SMZ3B1-H27A-O	Heat pump without ducts		25,000	\$3,500
216617674	STELPRO	SMZ3B1-H27A-O	Heat pump with ducts		23,000	\$3,220
216617675	STELPRO	SMZ3B1-H27A-O	Combination heat pumps with or without ducts		24,000	\$3,360
216617688	STELPRO	SMZ3B1V-H27A-O	Heat pump without ducts		25,000	\$3,500
216617689	STELPRO	SMZ3B1V-H27A-O	Heat pump with ducts		23,000	\$3,220
216617690	STELPRO	SMZ3B1V-H27A-O	Combination heat pumps with or without ducts		24,000	\$3,360
216617676	STELPRO	SMZ4B1-H36A-O	Heat pump without ducts		30,000	\$4,200
216617677	STELPRO	SMZ4B1-H36A-O	Heat pump with ducts		33,000	\$4,620
216617678	STELPRO	SMZ4B1-H36A-O	Combination heat pumps with or without ducts		31,400	\$4,396
216617691	STELPRO	SMZ4B1V-H36A-O	Heat pump without ducts		30,000	\$4,200
216617692	STELPRO	SMZ4B1V-H36A-O	Heat pump with ducts		33,000	\$4,620
216617693	STELPRO	SMZ4B1V-H36A-O	Combination heat pumps with or without ducts		31,400	\$4,396
216617679	STELPRO	SMZ5B1-H48A-O	Heat pump without ducts		44,000	\$6,160
216617680	STELPRO	SMZ5B1-H48A-O	Heat pump with ducts		44,500	\$6,230
216617681	STELPRO	SMZ5B1-H48A-O	Combination heat pumps with or without ducts		44,000	\$6,160
216617682	STELPRO	SMZ5B1-H55A-O	Heat pump without ducts		44,000	\$6,160
216617683	STELPRO	SMZ5B1-H55A-O	Heat pump with ducts		45,000	\$6,300
216617684	STELPRO	SMZ5B1-H55A-O	Combination heat pumps with or without ducts		44,500	\$6,230
216617694	STELPRO	SMZ5B1V-H48A-O	Heat pump without ducts		44,000	\$6,160
216617696	STELPRO	SMZ5B1V-H48A-O	Combination heat pumps with or without ducts		44,000	\$6,160
216617695	STELPRO	SMZ5B1V-H48A-O	Heat pump with ducts		44,500	\$6,230
216617697	STELPRO	SMZ5B1V-H55A-O	Heat pump without ducts		44,000	\$6,160

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216617698	STELPRO	SMZ5B1V-H55A-O	Heat pump with ducts		45,000	\$6,300
216617699	STELPRO	SMZ5B1V-H55A-O	Combination heat pumps with or without ducts		44,500	\$6,230
216082172	STELPRO	SDB1-H24A-O	SAHB1-H24A-I		20,000	\$2,800
216760301	STELPRO	SDB1-H24A-O	SACB1-H24A1418-I		19,700	\$2,758
216760302	STELPRO	SDB1-H24A-O	SACB1-H24A1718-I		19,700	\$2,758
216082174	STELPRO	SDB1-H30A-O	SAHB1-H30A-I		23,800	\$3,332
216760304	STELPRO	SDB1-H30A-O	SACB1-H36A1724-I		25,000	\$3,500
216760305	STELPRO	SDB1-H30A-O	SACB1-H36A2124-I		25,000	\$3,500
216082175	STELPRO	SDB1-H36A-O	SAHB1-H36A-I		31,800	\$4,452
216760306	STELPRO	SDB1-H36A-O	SACB1-H36A1724-I		29,200	\$4,088
216760307	STELPRO	SDB1-H36A-O	SACB1-H36A2124-I		29,200	\$4,088
216082177	STELPRO	SDB1-H48A-O	SAHB1-H48A-I		37,000	\$5,180
216760308	STELPRO	SDB1-H48A-O	SMCB1-H60A2128-I		34,400	\$4,816
216082179	STELPRO	SDB1-H60A-O	SAHB1-H60A-I		45,000	\$6,300
216760309	STELPRO	SDB1-H60A-O	SMCB1-H60A2128-I		37,800	\$5,292
216760310	STELPRO	SDB1-H60A-O	SACB1-H60A2428-I		36,000	\$5,040
214855107	SUM X	SM-12HFO2-CU	SM-12HFO2-WU		6,800	\$952
214855108	SUM X	SM-18HFO2-CU	SM-18HFO2-WU		10,500	\$1,470
212579411	SUPREME	NE-T52-SUPAE18E	NE-T52-SUPAE18I		15,000	\$2,100
212579410	SUPREME	NE-T52-SUPAE12E	NE-T52-SUPAE12I		10,000	\$1,400
210372389	SUPREME CENTRAL	SUPRM30CC	AHAN3615		18,000	\$2,520
212940834	SUPREME CENTRAL	SUPRM30CC	F45-SPLTCC30		19,000	\$2,660
212940833	SUPREME CENTRAL	SUPRM30CC	F45-SPLTAH36		18,000	\$2,520
206799642	SUPREME CENTRAL	SUPRM24CC	AHAN3615		16,000	\$2,240
206799641	SUPREME CENTRAL	SUPRM24CC	AHAN2410		16,000	\$2,240
214233327	SURE	RD17AZ36AJ3N	SH3VZ4821STACN		31,200	\$4,368
212617000	TCL	THH42HAI2NAF2U23	THH36IAI2NAF2H23		30,000	\$4,200
212616999	TCL	THH48HAI2NAF2U23	THH36IAI2NAF2H23		30,000	\$4,200
211603991	TCL	THH42HAI2NAF2U23	THH48IAI2NAF2H23		33,000	\$4,620
211603990	TCL	THH30HAI2NAF2U23	THH36IAI2NAF2H23		21,000	\$2,940
211603988	TCL	THH18HAI2NAF2U23	THH24IAI2NAF2H23		15,000	\$2,100
211603987	TCL	THH60HAI2NAF2U23	THH60IAI2NAF2H23		39,000	\$5,460
211603986	TCL	THH48HAI2NAF2U23	THH48IAI2NAF2H23		38,000	\$5,320
211603984	TCL	THH24HAI2NAF2U23	THH24IAI2NAF2H23		19,100	\$2,674
216706226	TCL	H36TDH18XAC	H24AHH17XAE		21,000	\$2,940
216706227	TCL	H24TDH17XAC	H24AHH17XAE		19,000	\$2,660
216706238	TCL	H12SFH25XPC	H12SFH25XPE		8,000	\$1,120

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215570372	TCL	H12SBH23XPC	H12CSHU1XAE		7,800	\$1,092
207614974	TEMPSTAR	DLCPRBH12AAK	DLFPHBH12XAK		10,400	\$1,456
207826651	TEMPSTAR	DLCPRBH18AAK	DLFPHBH18XAK		20,200	\$2,828
206361905	TEMPSTAR	DLCSRBH12AAK	DLFSHBH12XAK		10,300	\$1,442
206361907	TEMPSTAR	DLCSRBH24AAK	DLFSHBH24XAK		18,900	\$2,646
206361906	TEMPSTAR	DLCSRBH18AAK	DLFSHBH18XAK		11,100	\$1,554
210857455	TEMPSTAR	DLCSRBH18AAK	DLFSOAH18XAK		14,500	\$2,030
210857456	TEMPSTAR	DLCSRBH12AAK	DLFSOAH18XAK		9,500	\$1,330
211132702	TEMPSTAR	DLCSRBH12AAK	DLFSDAH12XHK		9,700	\$1,358
209948198	TEMPSTAR	DLCSRBH12AAK	DLFSFBH12XAK		10,200	\$1,428
207683376	TEMPSTAR	DLCSRBH24AAK	DLFSCBH24XAK		21,000	\$2,940
208447671	TEMPSTAR	DLCSRBH24AAK	DLFSCH24XAK		21,200	\$2,968
208447675	TEMPSTAR	DLCSRBH18AAK	DLFSCH18XAK		15,000	\$2,100
208447670	TEMPSTAR	DLCSRBH12AAK	DLFSCH12XAK		10,000	\$1,400
206773947	TEMPSTAR	TVH848GKA2*	EA*4X60L24A*+WALLCON	*97CMN1002122A*	36,000	\$5,040
206773974	TEMPSTAR	TVH848GKA2*	EA*4X60L24A*+WALLCON	*96CTN1002122A*	36,000	\$5,040
206774909	TEMPSTAR	TVH848GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	36,000	\$5,040
211132740	TEMPSTAR	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
206771909	TEMPSTAR	TVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL1352422A*	31,400	\$4,396
206773535	TEMPSTAR	TVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206767550	TEMPSTAR	TVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
211132700	TEMPSTAR	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
206767559	TEMPSTAR	TVH825GKA3*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884
206771279	TEMPSTAR	TVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
206771630	TEMPSTAR	TVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0701716A*	32,000	\$4,480
206771729	TEMPSTAR	TVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206773427	TEMPSTAR	TVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206771783	TEMPSTAR	TVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0902120A*	31,400	\$4,396
206773436	TEMPSTAR	TVH837GKA2*	EA*4X37L21A*+WALLCON	*95CSU1002122A*	31,800	\$4,452
206773481	TEMPSTAR	TVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	31,800	\$4,452
206773490	TEMPSTAR	TVH837GKA2*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	31,600	\$4,424
206774289	TEMPSTAR	TVH848GKA2*	EN(A,D)4X48L24**+WALLCON	*96CTN1202422A*	37,200	\$5,208
206771360	TEMPSTAR	TVH837GKA2*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	31,800	\$4,452
206766040	TEMPSTAR	TVH825GKA3*	EA*4X37L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
206773526	TEMPSTAR	TVH837GKA2*	EA*4X48L24A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206771864	TEMPSTAR	TVH837GKA2*	EA*4X48L21A*+WALLCON	*80CTL0901716A*	31,400	\$4,396
206771900	TEMPSTAR	TVH837GKA2*	EA*4X48L24A*+WALLCON	*80CTL0902120A*	31,400	\$4,396

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
206773508	TEMPSTAR	TVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU0802120A*	31,400	\$4,396
206773517	TEMPSTAR	TVH837GKA2*	EA*4X48L21A*+WALLCON	*95CSU1002122A*	31,400	\$4,396
206771648	TEMPSTAR	TVH837GKA2*	EA*4X43L21A*+WALLCON	*80CTL0902120A*	31,800	\$4,452
215324628	TEMPSTAR	D5CSHAH18AAK	D5FSHAH18XAK		16,600	\$2,324
215323732	TEMPSTAR	D5CUHAH36AAK	D5FUHAH36XAK		31,000	\$4,340
215319107	TEMPSTAR	D5CLHAH58AAK	D5FLAAH60XAK		41,000	\$5,740
215319105	TEMPSTAR	D5CLHAH36AAK	D5FLAAH36XAK		28,000	\$3,920
215324639	TEMPSTAR	D5CSHAH33AAK	D5FSHAH33XAK		30,000	\$4,200
215324638	TEMPSTAR	D5CSHAH24AAK	D5FSDAH24XHK		21,600	\$3,024
215324635	TEMPSTAR	D5CSHAH24AAK	D5FSHAH24XAK		21,000	\$2,940
215324633	TEMPSTAR	D5CSHAH18AAK	D5FSDAH18XAK		15,000	\$2,100
215324631	TEMPSTAR	D5CSHAH18AAK	D5FSFAH16XAK		14,200	\$1,988
215324630	TEMPSTAR	D5CSHAH18AAK	D5FSCAH18XAK		14,900	\$2,086
215324629	TEMPSTAR	D5CSHAH18AAK	D5FSOAH18XAK		14,500	\$2,030
215324626	TEMPSTAR	D5CSHAH12AAK	D5FSDAH12XAK		9,600	\$1,344
215324625	TEMPSTAR	D5CSHAH12AAK	D5FSFAH12XAK		9,800	\$1,372
215324624	TEMPSTAR	D5CSHAH12AAK	D5FSCAH12XAK		10,000	\$1,400
215324623	TEMPSTAR	D5CSHAH12AAK	D5FSOAH12XAK		9,600	\$1,344
215413312	TEMPSTAR	D5CPRAH18AA	D5FPHAH18XAK		19,300	\$2,702
215413311	TEMPSTAR	D5CPRAH12AAK	D5FPHAH12XAK		11,000	\$1,540
215357478	TEMPSTAR	D5CMHAH30EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357476	TEMPSTAR	D5CMHAH30EAK	Heat pump with ducts		33,000	\$4,620
215357474	TEMPSTAR	D5CMHAH30EAK	Heat pump without ducts		30,000	\$4,200
215324634	TEMPSTAR	D5CSHAH18AAK	D5FSDAH18XHK		15,000	\$2,100
215324627	TEMPSTAR	D5CSHAH12AAK	D5FSDAH12XHK		10,200	\$1,428
215357521	TEMPSTAR	D5CMRAH48FAK	Heat pump with ducts		37,000	\$5,180
215357495	TEMPSTAR	D5CMHAH55FAK	Combination heat pumps with or without ducts		44,500	\$6,230
215357493	TEMPSTAR	D5CMHAH55FAK	Heat pump with ducts		45,000	\$6,300
215357491	TEMPSTAR	D5CMHAH55FAK	Heat pump without ducts		44,000	\$6,160
215357489	TEMPSTAR	D5CMHAH48FAK	Combination heat pumps with or without ducts		44,000	\$6,160
215357487	TEMPSTAR	D5CMHAH48FAK	Heat pump with ducts		44,500	\$6,230
215357485	TEMPSTAR	D5CMHAH48FAK	Heat pump without ducts		44,000	\$6,160
215357484	TEMPSTAR	D5CMHAH36EAK	Combination heat pumps with or without ducts		31,400	\$4,396
215357482	TEMPSTAR	D5CMHAH36EAK	Heat pump with ducts		33,000	\$4,620

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215357480	TEMPSTAR	D5CMHAH36EAK	Heat pump without ducts		30,000	\$4,200
215357472	TEMPSTAR	D5CMHAH27DAK	Combination heat pumps with or without ducts		24,000	\$3,360
215357471	TEMPSTAR	D5CMHAH27DAK	Heat pump with ducts		23,000	\$3,220
215357469	TEMPSTAR	D5CMHAH27DAK	Heat pump without ducts		25,000	\$3,500
215357461	TEMPSTAR	D5CMHAH18CAK	Combination heat pumps with or without ducts		17,300	\$2,422
215357459	TEMPSTAR	D5CMHAH18CAK	Heat pump with ducts		17,000	\$2,380
215357457	TEMPSTAR	D5CMHAH18CAK	Heat pump without ducts		17,600	\$2,464
215324676	TEMPSTAR	D5CLHAH58AAK	D5FCFAH58XAK		41,000	\$5,740
215324674	TEMPSTAR	D5CLHAH48AAK	D5FCFAH48XAK		38,500	\$5,390
215324673	TEMPSTAR	D5CLHAH48AAK	D5FLCAH48XAK		44,000	\$6,160
215324671	TEMPSTAR	D5CLHAH36AAK	D5FCFAH36XAK		30,200	\$4,228
215324670	TEMPSTAR	D5CLHAH36AAK	D5FLCAH36XAK		30,600	\$4,284
215324637	TEMPSTAR	D5CSHAH24AAK	D5FCFAH24XAK		20,200	\$2,828
215324632	TEMPSTAR	D5CSHAH18AAK	D5FCFAH18XAK		14,400	\$2,016
215324677	TEMPSTAR	D5CLHAH58AAK	D5FLDAH58XHK		45,000	\$6,300
215324675	TEMPSTAR	D5CLHAH48AAK	D5FLDAH48XHK		45,000	\$6,300
215324672	TEMPSTAR	D5CLHAH36AAK	D5FLDAH36XHK		31,600	\$4,424
215324622	TEMPSTAR	D5CSHAH12AAK	D5FSHAH12XAK		9,800	\$1,372
215319106	TEMPSTAR	D5CLHAH48AAK	D5FLAAH48XAK		40,000	\$5,600
215319099	TEMPSTAR	D5CUHAH48AAK	D5FUHAH60XAK		34,000	\$4,760
215319098	TEMPSTAR	D5CUHAH30AAK	D5FUHAH36XAK		24,000	\$3,360
215319097	TEMPSTAR	D5CUHAH18AAK	D5FUHAH24XAK		14,700	\$2,058
215319095	TEMPSTAR	D5CURAH48AAK	D5FUAH48XAK		32,400	\$4,536
215319092	TEMPSTAR	D5CURAH24AAK	D5FUAH24XAK		20,000	\$2,800
215319090	TEMPSTAR	D5CUHAH60AAK	D5FUHAH60XAK		35,000	\$4,900
215319089	TEMPSTAR	D5CUHAH60AAK	D5FUAH60XAK		45,000	\$6,300
215319088	TEMPSTAR	D5CUHAH48AAK	D5FUAH48XAK		37,000	\$5,180
215319087	TEMPSTAR	D5CUHAH36AAK	D5FUAH36XAK		31,800	\$4,452
215319086	TEMPSTAR	D5CUHAH30AAK	D5FUAH30XAK		23,800	\$3,332
215319085	TEMPSTAR	D5CUHAH24AAK	D5FUHAH24XAK		19,000	\$2,660
215319084	TEMPSTAR	D5CUHAH24AAK	D5FUAH24XAK		20,000	\$2,800
215319083	TEMPSTAR	D5CUHAH18AAK	D5FUAH18XAK		15,000	\$2,100
215319102	TEMPSTAR	D5CSHAH33AAK	D5FSAH36XBK		27,400	\$3,836
215319101	TEMPSTAR	D5CSHAH24AAK	D5FSAH24XBK		16,900	\$2,366
215319100	TEMPSTAR	D5CSHAH18AAK	D5FSAH18XBK		14,000	\$1,960
212988105	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212988069	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96MSN1002120A*	23,600	\$3,304
212988057	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*96MSN1002120A*	23,600	\$3,304
212988045	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96MSN1002120A*	23,400	\$3,276
209852120	TEMPSTAR	DLCURAH36ABK	DLFUAH36XAK		30,400	\$4,256
213080455	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002122A*	32,800	\$4,592
213080401	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002122A*	29,400	\$4,116
213080373	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1002120A*	29,200	\$4,088
213080361	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002120A*	29,200	\$4,088
213080277	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002120A*	29,400	\$4,116
212988214	TEMPSTAR	DLCURAH48ABK	EA*4X61L24A*	*96MSN1002122A*	29,400	\$4,116
212988081	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96MSN1002120A*	23,200	\$3,248
212988021	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96MSN1002120A*	29,000	\$4,060
213080428	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*96MSN1002122A*	29,400	\$4,116
210470538	TEMPSTAR	TVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
210470505	TEMPSTAR	TVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0901716A*	31,200	\$4,368
210470439	TEMPSTAR	TVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0701716A*	31,400	\$4,396
213080392	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002122A*	29,400	\$4,116
213080383	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96MSN1002122A*	29,200	\$4,088
213080349	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002120A*	29,400	\$4,116
213080325	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002120A*	29,200	\$4,088
212983635	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601412A*	12,400	\$1,736
212988223	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002122A*	29,000	\$4,060
210470527	TEMPSTAR	TVH837GKA2*	EA*4X61L24A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
210470571	TEMPSTAR	TVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL1352422A*	31,200	\$4,368
210470395	TEMPSTAR	TVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU1002122A*	31,200	\$4,368
213080446	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN1002122A*	29,200	\$4,088
213080419	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96MSN1002122A*	29,000	\$4,060
210470274	TEMPSTAR	TVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL0902120A*	31,000	\$4,340
210470384	TEMPSTAR	TVH837GKA2*	EA*4X61L21A*+WALLCON	*95CSU0802120A*	31,200	\$4,368
213080437	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN1002122A*	29,200	\$4,088
213080313	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002120A*	29,400	\$4,116
213080301	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96MSN1002120A*	29,400	\$4,116
213080289	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96MSN1002120A*	29,200	\$4,088
213080410	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96MSN1002122A*	29,200	\$4,088
212988009	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96MSN1002120A*	29,000	\$4,060
210473247	TEMPSTAR	TVH825GKA3*	EA*4X43L21A*+WALLCON	*80CTL0901716A*	20,400	\$2,856
210470241	TEMPSTAR	TVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU0802120A*	31,000	\$4,340
210473115	TEMPSTAR	TVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU1002122A*	20,600	\$2,884

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
210470285	TEMPSTAR	TVH837GKA2*	EA*4X60L24A*+WALLCON	*80CTL1352422A*	31,000	\$4,340
210470450	TEMPSTAR	TVH837GKA2*	EA*4X61L21A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210473104	TEMPSTAR	TVH825GKA3*	EA*4X43L21A*+WALLCON	*95CSU0802120A*	20,600	\$2,884
210470560	TEMPSTAR	TVH837GKA2*	EA*4X61L24A*+WALLCON	*80CTL0902120A*	31,200	\$4,368
210470252	TEMPSTAR	TVH837GKA2*	EA*4X60L24A*+WALLCON	*95CSU1002122A*	31,000	\$4,340
211712137	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*95ESU1002120A*	23,400	\$3,276
211712103	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*95ESU1002120A*	23,600	\$3,304
211709693	TEMPSTAR	DLCURAH30ABK	FJMA4*30L*B*		23,400	\$3,276
213353864	TEMPSTAR	DLCURAH36ABK	F5MA4*42L*C*		29,200	\$4,088
213353854	TEMPSTAR	DLCURAH36ABK	F5MA4*36L*B*		29,400	\$4,116
213249344	TEMPSTAR	DLCURAH36ABK	FEVA0036**+NAVA43601CK		29,400	\$4,116
213080882	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU0802120A*	29,200	\$4,088
213080870	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0802120A*	29,200	\$4,088
213080858	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	29,400	\$4,116
213080846	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*95MSU0802120A*	29,600	\$4,144
213080834	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95MSU0802120A*	29,200	\$4,088
213080822	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95MSU0802120A*	29,400	\$4,116
213080810	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95MSU0802120A*	29,400	\$4,116
213080798	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95MSU0802120A*	29,200	\$4,088
213080786	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95MSU0802120A*	29,400	\$4,116
213080774	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0601716A*	29,200	\$4,088
213080762	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	29,600	\$4,144
213080750	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*95MSU0601716A*	29,400	\$4,116
213080714	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95MSU0601716A*	29,200	\$4,088
213080702	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95MSU0601716A*	29,400	\$4,116
213080690	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95MSU0601716A*	29,200	\$4,088
213080678	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*95MSU0601716A*	29,400	\$4,116
213080666	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95MSU0601716A*	29,400	\$4,116
213080654	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*95MSU0601716A*	29,600	\$4,144
213080642	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU0401712A*	29,400	\$4,116
213080630	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU0401712A*	29,600	\$4,144
213080618	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*95MSU0401712A*	29,400	\$4,116
211274904	TEMPSTAR	DLCURAH30ABK	FVM4X48***L		23,000	\$3,220
213080582	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95MSU0401712A*	29,200	\$4,088
213080570	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95MSU0401712A*	29,200	\$4,088
213080558	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95MSU0401712A*	29,600	\$4,144
213080546	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95MSU0401712A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213080534	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*95MSU0401712A*	29,400	\$4,116
213080522	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95MSU0401712A*	29,600	\$4,144
213080510	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*95MSU0401712A*	29,600	\$4,144
213080499	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1402422A*	23,600	\$3,304
213080489	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96MSN1402422A*	29,000	\$4,060
213080478	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96MSN1202422A*	29,200	\$4,088
213080466	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96MSN1202422A*	29,400	\$4,116
213080254	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0802120A*	29,200	\$4,088
211222786	TEMPSTAR	DLCURAH30ABK	FVM4X24***L		23,600	\$3,304
213080242	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0802120A*	29,200	\$4,088
213080230	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*96MSN0802120A*	29,400	\$4,116
213080206	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96MSN0802120A*	29,000	\$4,060
211222770	TEMPSTAR	DLCURAH30ABK	FMA4X36**AL*		23,800	\$3,332
213080194	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96MSN0802120A*	29,000	\$4,060
211222762	TEMPSTAR	DLCURAH30ABK	FMA4X30**AL*		23,800	\$3,332
213080182	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96MSN0802120A*	29,200	\$4,088
213080170	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96MSN0802120A*	29,400	\$4,116
211222754	TEMPSTAR	DLCURAH30ABK	FM(C,U)4Z36**AL*		23,600	\$3,304
213080158	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96MSN0802120A*	29,400	\$4,116
212972891	TEMPSTAR	DLCURAH24AAK	EN(A,D,W)4X36L17**	*96VSN0401410B*	19,500	\$2,730
213080146	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96MSN0802120A*	29,200	\$4,088
211222746	TEMPSTAR	DLCURAH30ABK	FM(C,U)4Z30**AL*		23,600	\$3,304
213080133	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96MSN0801716A*	29,200	\$4,088
213080121	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	29,600	\$4,144
213080109	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*96MSN0801716A*	29,400	\$4,116
213080073	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96MSN0801716A*	29,000	\$4,060
211222714	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122A*	23,000	\$3,220
213080061	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96MSN0801716A*	29,200	\$4,088
213080049	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96MSN0801716A*	29,400	\$4,116
211222706	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120A*	23,200	\$3,248
213080037	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96MSN0801716A*	29,200	\$4,088
213080025	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*96MSN0801716A*	29,400	\$4,116
211222698	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120A*	23,000	\$3,220
213080013	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96MSN0801716A*	29,600	\$4,144
213080001	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*96MSN0801716A*	29,600	\$4,144
211222690	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VTN0601714A*	23,200	\$3,248
213079990	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*96MSN0601412A*	23,600	\$3,304
213079960	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*96MSN0601412A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211222682	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*95ESU0601716A*	23,400	\$3,276
213079949	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1202420A*	29,200	\$4,088
211222674	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*95ESU0401712A*	23,200	\$3,248
213079938	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*92MSN1202420A*	29,000	\$4,060
213079927	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*92MSN1202420A*	29,400	\$4,116
211222666	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120A*	23,200	\$3,248
213079917	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002122A*	32,800	\$4,592
213079908	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002122A*	29,200	\$4,088
211222658	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120A*	23,000	\$3,220
213079899	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002122A*	29,200	\$4,088
213079890	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN1002122A*	29,400	\$4,116
211222650	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VSN0801716A*	23,200	\$3,248
213079881	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002122A*	29,000	\$4,060
213079872	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002122A*	29,000	\$4,060
211222642	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VSN0601714A*	23,200	\$3,248
213079863	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002122A*	29,400	\$4,116
213079854	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002122A*	29,400	\$4,116
213079845	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002122A*	29,000	\$4,060
211222634	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*95ESN0802120A*	23,200	\$3,248
213079835	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*92MSN1002120A*	29,200	\$4,088
213079823	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN1002120A*	29,200	\$4,088
211222626	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*95ESN0601714A*	23,200	\$3,248
213079811	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	29,400	\$4,116
213079799	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN1002120A*	29,600	\$4,144
211222618	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*92ESN1002120A*	23,200	\$3,248
213079787	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92MSN1002120A*	29,000	\$4,060
213079775	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*92MSN1002120A*	29,400	\$4,116
211222610	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*92ESN0802120A*	23,200	\$3,248
213079763	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92MSN1002120A*	29,400	\$4,116
211222602	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*92ESN0801716A*	23,400	\$3,276
213079751	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92MSN1002120A*	29,000	\$4,060
213079739	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92MSN1002120A*	29,400	\$4,116
211222594	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*92ESN0601714A*	23,400	\$3,276
213079718	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0802120A*	29,200	\$4,088
213079708	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0802120A*	29,200	\$4,088
213079698	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*92MSN0802120A*	29,400	\$4,116
213079688	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92MSN0802120A*	28,800	\$4,032
213079678	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*92MSN0802120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213079668	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92MSN0802120A*	29,400	\$4,116
213079658	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92MSN0802120A*	29,400	\$4,116
213079648	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92MSN0802120A*	29,200	\$4,088
213079637	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0801716A*	29,200	\$4,088
213079625	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0801716A*	29,400	\$4,116
213079613	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*92MSN0801716A*	29,200	\$4,088
213079577	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92MSN0801716A*	29,000	\$4,060
213079565	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92MSN0801716A*	29,400	\$4,116
213079553	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92MSN0801716A*	29,000	\$4,060
213079541	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*92MSN0801716A*	29,400	\$4,116
213079529	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92MSN0801716A*	29,400	\$4,116
213079517	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*92MSN0801716A*	29,400	\$4,116
213079505	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92MSN0601714A*	29,200	\$4,088
213079493	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92MSN0601714A*	29,400	\$4,116
213079481	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*92MSN0601714A*	29,400	\$4,116
213079445	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92MSN0601714A*	29,200	\$4,088
213079433	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92MSN0601714A*	29,400	\$4,116
213079421	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92MSN0601714A*	29,200	\$4,088
213079407	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*92MSN0601714A*	29,400	\$4,116
213079395	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92MSN0601714A*	29,400	\$4,116
213079383	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601714A*	29,400	\$4,116
213079362	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X36L17**	*92MSN0601412A*	29,400	\$4,116
213079342	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*92MSN0601412A*	29,400	\$4,116
211222394	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*96VTN0601714A*	23,400	\$3,276
211222386	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*95ESU0601716A*	23,400	\$3,276
211222378	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*95ESU0401712A*	23,400	\$3,276
211222370	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716A*	23,400	\$3,276
211222362	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*95ESN0601714A*	23,400	\$3,276
211222354	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*92ESN0801716A*	23,400	\$3,276
211222346	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601714A*	23,400	\$3,276
211222338	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*92ESN0601412A*	23,400	\$3,276
211222154	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*92ESN1002120A*	23,400	\$3,276
211222144	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*92ESN0802120A*	23,400	\$3,276
211712375	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*95ESN1002120A*	23,600	\$3,304
211712363	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*95ESN0802120A*	23,400	\$3,276
213077814	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422B*	32,800	\$4,592
213077802	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422B*	29,000	\$4,060
213077790	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122B*	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077780	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122B*	29,200	\$4,088
213077770	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	29,200	\$4,088
213077760	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN1002122B*	29,400	\$4,116
213077750	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122B*	28,800	\$4,032
213077740	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122B*	29,000	\$4,060
213077730	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122B*	29,400	\$4,116
213077720	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122B*	29,400	\$4,116
211712545	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*92ESN0802120A*	23,400	\$3,276
213077710	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122B*	29,000	\$4,060
213077699	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120B*	29,200	\$4,088
213077686	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120B*	29,200	\$4,088
213077673	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	29,400	\$4,116
213077647	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120B*	29,000	\$4,060
213077634	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120B*	29,400	\$4,116
213077621	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120B*	29,400	\$4,116
213077608	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120B*	29,000	\$4,060
213077595	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120B*	29,400	\$4,116
213077583	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120B*	32,600	\$4,564
213077572	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120B*	29,200	\$4,088
213077561	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	29,200	\$4,088
213077550	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*96VTN0802120B*	29,400	\$4,116
213077539	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120B*	28,800	\$4,032
213077528	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120B*	29,000	\$4,060
213077517	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120B*	29,200	\$4,088
213077506	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120B*	29,400	\$4,116
213077495	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120B*	29,400	\$4,116
213077484	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120B*	29,200	\$4,088
213077472	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0801716B*	29,200	\$4,088
211712301	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*95ESU1002120A*	23,600	\$3,304
213077459	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0801716B*	29,600	\$4,144
213077446	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*96VTN0801716B*	29,400	\$4,116
213077407	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VTN0801716B*	29,200	\$4,088
211712557	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*92ESN1002120A*	23,400	\$3,276
213077394	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716B*	29,400	\$4,116
213077381	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VTN0801716B*	29,200	\$4,088
213077368	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*96VTN0801716B*	29,400	\$4,116
213077355	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VTN0801716B*	29,400	\$4,116
213077342	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*96VTN0801716B*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213077297	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601412B*	29,400	\$4,116
213077275	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VTN0401712B*	29,400	\$4,116
213077264	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422B*	32,800	\$4,592
213077254	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422B*	29,200	\$4,088
213077244	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422B*	29,000	\$4,060
213077234	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120B*	32,800	\$4,592
213077224	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120B*	29,200	\$4,088
213077214	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	29,200	\$4,088
213077204	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*96VSN1002120B*	29,400	\$4,116
213077184	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120B*	29,000	\$4,060
213077174	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120B*	29,000	\$4,060
213077164	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120B*	29,400	\$4,116
213077154	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120B*	29,400	\$4,116
213077144	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120B*	29,000	\$4,060
213077134	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120B*	32,600	\$4,564
213077124	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120B*	29,200	\$4,088
213077114	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	29,200	\$4,088
211712569	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*95ESN0601714A*	23,600	\$3,304
213077104	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*96VSN0802120B*	29,400	\$4,116
213077094	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120B*	28,800	\$4,032
213077084	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120B*	29,000	\$4,060
213077074	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120B*	29,200	\$4,088
213077064	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120B*	29,400	\$4,116
213077054	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120B*	29,400	\$4,116
213077044	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120B*	29,200	\$4,088
213077024	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716B*	29,200	\$4,088
213077014	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*96VSN0801716B*	29,600	\$4,144
213077004	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*96VSN0801716B*	29,400	\$4,116
213076984	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716B*	29,000	\$4,060
213076974	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716B*	29,200	\$4,088
213076964	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716B*	29,400	\$4,116
213076954	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716B*	29,200	\$4,088
213076944	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716B*	29,400	\$4,116
213076934	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716B*	29,400	\$4,116
211712215	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*96VSN0801716A*	23,400	\$3,276
213076894	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601412B*	29,400	\$4,116
213076874	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VSN0401712B*	29,400	\$4,116
211712161	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*95ESN1002120A*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213076332	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002122A*	29,200	\$4,088
213076323	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002122A*	29,200	\$4,088
213076314	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*95MSU1002122A*	29,400	\$4,116
213076296	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002122A*	29,000	\$4,060
213076287	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002122A*	29,000	\$4,060
211712706	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*95ESU1002120A*	23,600	\$3,304
213076278	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002122A*	29,000	\$4,060
213076269	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002122A*	29,400	\$4,116
213076260	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002122A*	29,400	\$4,116
213076251	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002122A*	29,000	\$4,060
213076004	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95MSU1002120A*	29,200	\$4,088
213075992	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95MSU1002120A*	29,200	\$4,088
213075980	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95MSU1002120A*	29,400	\$4,116
213075956	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95MSU1002120A*	29,000	\$4,060
213075944	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95MSU1002120A*	29,000	\$4,060
213075932	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95MSU1002120A*	29,000	\$4,060
213075920	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95MSU1002120A*	29,400	\$4,116
213075908	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95MSU1002120A*	29,400	\$4,116
213075896	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95MSU1002120A*	29,000	\$4,060
213075884	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95MSU1002120A*	29,400	\$4,116
212989511	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95MSU0802120A*	29,000	\$4,060
212989499	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95MSU0802120A*	29,000	\$4,060
212988983	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95MSU0601716A*	29,000	\$4,060
212988410	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96MSN1402422A*	29,200	\$4,088
212988327	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96MSN1202422A*	29,000	\$4,060
211712744	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*95ESN0802120A*	23,400	\$3,276
212985514	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002122A*	29,000	\$4,060
212985249	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*92MSN1002120A*	28,800	\$4,032
212985237	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92MSN1002120A*	28,800	\$4,032
211712756	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*95ESN1002120A*	23,600	\$3,304
212984958	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*92MSN0802120A*	29,600	\$4,144
212984948	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92MSN0802120A*	28,800	\$4,032
212984419	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92MSN0801716A*	29,000	\$4,060
212983879	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92MSN0601714A*	29,000	\$4,060
212977261	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422B*	29,200	\$4,088
212977097	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122B*	29,600	\$4,144
212977087	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122B*	28,800	\$4,032
212976816	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120B*	29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212976803	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120B*	29,000	\$4,060
212976534	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120B*	29,600	\$4,144
212976313	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VTN0801716B*	29,000	\$4,060
212974421	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120B*	29,000	\$4,060
212974201	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120B*	29,600	\$4,144
212390907	TEMPSTAR	DLCURAH36ABK	FJMA4*36L*B*		29,400	\$4,116
212384860	TEMPSTAR	DLCURAH36ABK	FVM4X36***L		29,400	\$4,116
212384836	TEMPSTAR	DLCURAH36ABK	FJMA4*42L*C*		29,200	\$4,088
212384796	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0801716A*	29,200	\$4,088
212384708	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0601714A*	29,400	\$4,116
212384696	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	29,400	\$4,116
212384684	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	29,400	\$4,116
212384672	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0801716A*	29,400	\$4,116
212384660	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN0601714A*	29,400	\$4,116
211712904	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*92ESN0802120A*	23,400	\$3,276
212384586	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0802120A*	29,600	\$4,144
212384563	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	29,600	\$4,144
211712916	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*92ESN1002120A*	23,400	\$3,276
212384525	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	29,400	\$4,116
213076197	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*95MSU1002122A*	31,200	\$4,368
211712982	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VSN0601714A*	23,200	\$3,248
211712992	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VSN0802120A*	23,000	\$3,220
211713002	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VSN1002120A*	23,200	\$3,248
211713012	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VSN0801716A*	23,200	\$3,248
211713023	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*95ESU0401712A*	23,200	\$3,248
211713047	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002122A*	23,000	\$3,220
211713098	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*95ESU1002120A*	23,400	\$3,276
211713110	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*95ESU0601716A*	23,400	\$3,276
213353892	TEMPSTAR	DLCURAH60ABK	F5MA4*60L*D*		37,800	\$5,292
213607822	TEMPSTAR	DLCURAH60ABK	FTMA4B60L0D*		37,400	\$5,236
211713160	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*95ESN0802120A*	23,200	\$3,248
211713172	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*95ESN1002120A*	23,600	\$3,304
211713196	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VTN0601714A*	23,200	\$3,248
211713207	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VTN0802120A*	23,000	\$3,220
211713218	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120A*	23,200	\$3,248
210025748	TEMPSTAR	DLCURAH60ABK	DLFUAH60XAK		42,000	\$5,880
212384513	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	29,400	\$4,116
212384472	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESU1002122A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212384462	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002122A*	29,600	\$4,144
212384452	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*92ESN1002122A*	29,600	\$4,144
212384430	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	29,400	\$4,116
212384420	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	29,400	\$4,116
212384410	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0802120A*	29,400	\$4,116
212384400	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VSN0601714A*	29,400	\$4,116
212384334	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*92ESN0801716A*	29,200	\$4,088
212384322	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*92ESN0601714A*	29,200	\$4,088
212384310	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*92ESN0601412A*	29,400	\$4,116
212384136	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002120A*	29,600	\$4,144
212384124	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN0802120A*	29,600	\$4,144
211713331	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*92ESN0601714A*	23,000	\$3,220
211713343	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*92ESN0801716A*	23,400	\$3,276
212987674	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*96MSN0802120A*	31,000	\$4,340
211713355	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*92ESN0802120A*	23,200	\$3,248
212383817	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESU1002122A*	29,800	\$4,172
212383807	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*95ESN1002122A*	29,800	\$4,172
212383797	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X36L21**	*92ESN1002122A*	29,800	\$4,172
211713367	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*92ESN1002120A*	23,200	\$3,248
211713379	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*95ESN0601714A*	23,200	\$3,248
212383478	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92ESN0801716A*	29,000	\$4,060
212383444	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002120A*	29,200	\$4,088
212383421	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95ESU0601716A*	29,200	\$4,088
212383361	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002120A*	29,400	\$4,116
212383349	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92ESN0802120A*	29,400	\$4,116
212383337	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92ESN0801716A*	29,400	\$4,116
212383263	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VTN0601714A*	29,600	\$4,144
212383239	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95ESN0802120A*	29,600	\$4,144
212383216	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002120A*	29,400	\$4,116
212383174	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95ESU0802120A*	29,800	\$4,172
212383163	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95ESU1002122A*	29,600	\$4,144
212383141	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VSN0801716A*	29,400	\$4,116
212383131	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VSN1002120A*	29,400	\$4,116
212383121	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VSN0802120A*	29,400	\$4,116
212383111	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VSN0601714A*	29,600	\$4,144
212383055	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*95ESN0601714A*	29,600	\$4,144
212383043	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*92ESN0801716A*	29,400	\$4,116
212383031	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601714A*	29,400	\$4,116

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212383019	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*92ESN0601412A*	29,600	\$4,144
212382956	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*96VTN0601714A*	29,600	\$4,144
212382915	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*95ESU0601716A*	29,400	\$4,116
212382872	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*96VSN0801716A*	29,400	\$4,116
212382862	TEMPSTAR	DLCURAH36ABK	EA*4X36L17A*	*96VSN0601714A*	29,600	\$4,144
212986846	TEMPSTAR	DLCURAH24AAK	EN(A,D,W)4X36L17**	*96MSN0601412A*	29,600	\$4,144
211230935	TEMPSTAR	DLCURAH36ABK	FXM4X48**AL		29,000	\$4,060
211230924	TEMPSTAR	DLCURAH36ABK	FXM4X42**AL		29,000	\$4,060
211230903	TEMPSTAR	DLCURAH36ABK	FVM4X48***L		28,600	\$4,004
211230892	TEMPSTAR	DLCURAH36ABK	FMA4X36**AL*		29,600	\$4,144
211230870	TEMPSTAR	DLCURAH36ABK	FM(C,U)4Z36**AL*		29,600	\$4,144
211230787	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1202422A*	29,200	\$4,088
211230777	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002122A*	29,200	\$4,088
211230768	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN1002120A*	29,200	\$4,088
211230758	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VTN0802120A*	29,200	\$4,088
211230748	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002122A*	29,400	\$4,116
211230738	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU1002120A*	29,200	\$4,088
211230727	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESU0802120A*	29,600	\$4,144
211230717	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1202422A*	29,200	\$4,088
211230708	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN1002120A*	29,200	\$4,088
211230699	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*96VSN0802120A*	29,200	\$4,088
211230689	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1402422A*	29,400	\$4,116
211230678	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1202422A*	29,400	\$4,116
211230668	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002122A*	29,400	\$4,116
211230658	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN1002120A*	29,200	\$4,088
211230647	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*95ESN0802120A*	29,400	\$4,116
211230636	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1202420A*	29,200	\$4,088
211230626	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002122A*	29,400	\$4,116
211230616	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN1002120A*	29,200	\$4,088
211230605	TEMPSTAR	DLCURAH36ABK	EN(A,D)4X48L24**	*92ESN0802120A*	29,000	\$4,060
211230349	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002122A*	29,200	\$4,088
211230340	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN1002120A*	29,200	\$4,088
211230330	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0802120A*	29,200	\$4,088
211230320	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VTN0601714A*	29,400	\$4,116
211230300	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002122A*	29,400	\$4,116
211230290	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU1002120A*	29,200	\$4,088
211230279	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0802120A*	29,600	\$4,144
211230268	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESU0601716A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211230258	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN1002120A*	29,200	\$4,088
211230249	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0802120A*	29,200	\$4,088
212986522	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*96MSN0401712A*	19,500	\$2,730
211230240	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0801716A*	29,200	\$4,088
211230231	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*96VSN0601714A*	29,200	\$4,088
211230213	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002122A*	29,400	\$4,116
211230203	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN1002120A*	29,200	\$4,088
211230192	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0802120A*	29,400	\$4,116
211230181	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0801716A*	29,200	\$4,088
211230170	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*95ESN0601714A*	29,200	\$4,088
211230160	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002122A*	29,400	\$4,116
211230150	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN1002120A*	29,200	\$4,088
211230139	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0802120A*	29,000	\$4,060
211230128	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X48L21**	*92ESN0601714A*	29,200	\$4,088
211229859	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	29,400	\$4,116
211229850	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN1002120A*	29,400	\$4,116
211229840	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*96VTN0601714A*	29,600	\$4,144
211229829	TEMPSTAR	DLCURAH36ABK	EN(A,D,W)4X42L21**	*95ESN1002120A*	29,400	\$4,116
211229754	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*96VTN0601714A*	29,400	\$4,116
211229743	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*95ESU0601716A*	29,200	\$4,088
211229733	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*96VSN0801716A*	29,400	\$4,116
211229724	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*96VSN0601714A*	29,400	\$4,116
211229696	TEMPSTAR	DLCURAH36ABK	END4X42L17**	*95ESN0601714A*	29,400	\$4,116
211229629	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VTN1202422A*	29,000	\$4,060
211229619	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002122A*	28,800	\$4,032
211229610	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VTN1002120A*	29,000	\$4,060
211229600	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VTN0802120A*	28,800	\$4,032
211229590	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002122A*	29,200	\$4,088
211229580	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95ESU1002120A*	29,000	\$4,060
211229569	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95ESU0802120A*	29,400	\$4,116
211229559	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VSN1202422A*	29,000	\$4,060
211229550	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VSN1002120A*	29,000	\$4,060
211229541	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*96VSN0802120A*	29,000	\$4,060
211229531	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95ESN1402422A*	29,200	\$4,088
211229520	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95ESN1202422A*	29,200	\$4,088
211229510	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002122A*	29,200	\$4,088
211229500	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95ESN1002120A*	29,000	\$4,060
211229489	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*95ESN0802120A*	29,200	\$4,088

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211229478	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*92ESN1202420A*	29,000	\$4,060
211229468	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002122A*	29,200	\$4,088
211229458	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*92ESN1002120A*	28,800	\$4,032
211229447	TEMPSTAR	DLCURAH36ABK	EA*4X48L24A*	*92ESN0802120A*	28,800	\$4,032
211714056	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*96VSN0801716A*	23,400	\$3,276
211714067	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*95ESU0401712A*	23,400	\$3,276
211229191	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002122A*	28,800	\$4,032
211229182	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VTN1002120A*	29,000	\$4,060
211229172	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VTN0802120A*	29,000	\$4,060
211229162	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VTN0601714A*	29,200	\$4,088
211229152	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002122A*	29,200	\$4,088
211714111	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*95ESU0601716A*	23,600	\$3,304
211229142	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95ESU1002120A*	29,000	\$4,060
211229131	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95ESU0802120A*	29,400	\$4,116
211229120	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95ESU0601716A*	29,000	\$4,060
211229110	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VSN1002120A*	29,000	\$4,060
211229101	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VSN0802120A*	29,000	\$4,060
211229092	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VSN0801716A*	29,000	\$4,060
211229083	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*96VSN0601714A*	29,000	\$4,060
211229065	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002122A*	29,200	\$4,088
211229055	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95ESN1002120A*	29,000	\$4,060
211229044	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95ESN0802120A*	29,200	\$4,088
211229033	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95ESN0801716A*	29,000	\$4,060
211229022	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*95ESN0601714A*	29,000	\$4,060
211229012	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002122A*	29,200	\$4,088
211229002	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92ESN1002120A*	28,800	\$4,032
211228991	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92ESN0802120A*	28,800	\$4,032
211228980	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92ESN0801716A*	29,000	\$4,060
211228969	TEMPSTAR	DLCURAH36ABK	EA*4X48L21A*	*92ESN0601714A*	29,000	\$4,060
211714164	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*96VTN0601714A*	23,400	\$3,276
211228664	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002122A*	29,000	\$4,060
212985742	TEMPSTAR	DLCURAH24AAK	EN(A,D,W)4X36L17**	*96MSN0261410A*	23,600	\$3,304
211228655	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VTN1002120A*	29,200	\$4,088
211228645	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VTN0802120A*	29,200	\$4,088
211228635	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VTN0601714A*	29,200	\$4,088
211228615	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002122A*	29,200	\$4,088
211228605	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95ESU1002120A*	29,000	\$4,060
211714214	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*92ESN0601412A*	23,400	\$3,276

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211228594	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95ESU0802120A*	29,400	\$4,116
211228583	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95ESU0601716A*	29,200	\$4,088
211228573	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VSN1002120A*	29,000	\$4,060
211228564	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VSN0802120A*	29,000	\$4,060
211714226	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*92ESN0601714A*	23,200	\$3,248
211228555	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VSN0801716A*	29,200	\$4,088
211228546	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*96VSN0601714A*	29,200	\$4,088
211228528	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002122A*	29,200	\$4,088
211228518	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95ESN1002120A*	29,200	\$4,088
211714238	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*92ESN0801716A*	23,200	\$3,248
211228507	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95ESN0802120A*	29,200	\$4,088
211228485	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*95ESN0601714A*	29,400	\$4,116
211228475	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002122A*	29,400	\$4,116
211228465	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92ESN1002120A*	29,200	\$4,088
211714250	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*95ESN0601714A*	23,400	\$3,276
211228454	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92ESN0802120A*	29,200	\$4,088
211228443	TEMPSTAR	DLCURAH36ABK	EA*4X43L21A*	*92ESN0601714A*	29,000	\$4,060
211714316	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120A*	23,400	\$3,276
211714326	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0801716A*	23,400	\$3,276
211714361	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122A*	23,400	\$3,276
211714412	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU1002120A*	23,600	\$3,304
211714424	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESU0601716A*	23,600	\$3,304
213076242	TEMPSTAR	DLCURAH48ABK	EA*4X61L24A*	*95MSU1002122A*	29,400	\$4,116
213076224	TEMPSTAR	DLCURAH48ABK	EA*4X60L24A*	*95MSU1002122A*	31,000	\$4,340
212977217	TEMPSTAR	DLCURAH48ABK	EA*4X61L24A*	*96VTN1002122B*	31,600	\$4,424
212988400	TEMPSTAR	DLCURAH48ABK	EA*4X61L24A*	*96MSN1402422A*	29,400	\$4,116
212987710	TEMPSTAR	DLCURAH48ABK	EA*4X61L24A*	*96MSN0802120A*	29,600	\$4,144
211714474	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95ESN0802120A*	23,400	\$3,276
211714632	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN0802120A*	23,400	\$3,276
211714644	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92ESN1002120A*	23,400	\$3,276
211714693	TEMPSTAR	DLCURAH30ABK	FJMA4*36L*B*		23,400	\$3,276
212973651	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*96VSN0601412B*	29,600	\$4,144
212973961	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*96VSN0801716B*	23,400	\$3,276
212973971	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*96VSN0801716B*	23,400	\$3,276
212973991	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*96VSN0801716B*	23,200	\$3,248
212974031	TEMPSTAR	DLCURAH30ABK	EN(A,D)4X36L21**	*96VSN0801716B*	23,400	\$3,276
212974051	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0801716B*	29,600	\$4,144
212974131	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*96VSN0802120B*	23,200	\$3,248

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974141	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VSN0802120B*	23,400	\$3,276
212974151	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*96VSN0802120B*	23,400	\$3,276
212974161	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96VSN0802120B*	23,200	\$3,248
212974181	TEMPSTAR	DLCURAH30ABK	EN(A,D)4X36L21**	*96VSN0802120B*	23,600	\$3,304
212974191	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN0802120B*	29,400	\$4,116
212974351	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*96VSN1002120B*	23,200	\$3,248
212974361	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VSN1002120B*	23,600	\$3,304
212974371	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*96VSN1002120B*	23,600	\$3,304
212974381	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96VSN1002120B*	23,200	\$3,248
212974401	TEMPSTAR	DLCURAH30ABK	EN(A,D)4X36L21**	*96VSN1002120B*	23,600	\$3,304
212974411	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VSN1002120B*	29,400	\$4,116
212974531	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96VSN1202422B*	29,400	\$4,116
212975770	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*96VTN0601412B*	29,600	\$4,144
212976185	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*96VTN0801716B*	23,400	\$3,276
212976198	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VTN0801716B*	23,400	\$3,276
212976224	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VTN0801716B*	23,200	\$3,248
212976276	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*96VTN0801716B*	23,400	\$3,276
212976440	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*96VTN0802120B*	23,200	\$3,248
212976454	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VTN0802120B*	23,400	\$3,276
212976468	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*96VTN0802120B*	23,400	\$3,276
212976482	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96VTN0802120B*	23,200	\$3,248
212976509	TEMPSTAR	DLCURAH30ABK	EN(A,D)4X36L21**	*96VTN0802120B*	23,600	\$3,304
212976522	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN0802120B*	29,400	\$4,116
212976725	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002120B*	23,200	\$3,248
212976738	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002120B*	23,600	\$3,304
212976751	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002120B*	23,600	\$3,304
212976764	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96VTN1002120B*	23,200	\$3,248
212976790	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002120B*	23,600	\$3,304
212977017	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*96VTN1002122B*	23,200	\$3,248
212977027	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96VTN1002122B*	23,400	\$3,276
212977037	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*96VTN1002122B*	23,400	\$3,276
212977047	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96VTN1002122B*	23,200	\$3,248
212977067	TEMPSTAR	DLCURAH30ABK	EN(A,D)4X36L21**	*96VTN1002122B*	23,400	\$3,276
212977077	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96VTN1002122B*	29,400	\$4,116
212977249	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96VTN1202422B*	29,400	\$4,116
212983465	TEMPSTAR	DLCURAH30ABK	EA*4X36L17A*	*92MSN0601412A*	23,400	\$3,276
212983495	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X36L17**	*92MSN0601412A*	23,600	\$3,304
212983505	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*92MSN0601412A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983927	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*92MSN0601714A*	23,400	\$3,276
212983939	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*92MSN0601714A*	23,200	\$3,248
212983963	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*92MSN0601714A*	23,200	\$3,248
212984011	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*92MSN0601714A*	23,400	\$3,276
212984467	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*92MSN0801716A*	23,400	\$3,276
212984479	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*92MSN0801716A*	23,200	\$3,248
212984491	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*92MSN0801716A*	23,400	\$3,276
212984503	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*92MSN0801716A*	23,200	\$3,248
212984551	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*92MSN0801716A*	23,400	\$3,276
212984968	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*92MSN0802120A*	23,200	\$3,248
212984978	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*92MSN0802120A*	23,400	\$3,276
212984988	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*92MSN0802120A*	23,400	\$3,276
212984998	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*92MSN0802120A*	23,200	\$3,248
212985018	TEMPSTAR	DLCURAH30ABK	EN(A,D)4X36L21**	*92MSN0802120A*	23,600	\$3,304
212985273	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*92MSN1002120A*	23,200	\$3,248
212985285	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*92MSN1002120A*	23,400	\$3,276
212985297	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*92MSN1002120A*	23,400	\$3,276
212985309	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*92MSN1002120A*	23,600	\$3,304
212985333	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*92MSN1002120A*	23,600	\$3,304
212985621	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*92MSN1202420A*	23,400	\$3,276
212985752	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*96MSN0261410A*	19,500	\$2,730
212986856	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*96MSN0601412A*	19,400	\$2,716
212987265	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*96MSN0801716A*	23,400	\$3,276
212987277	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*96MSN0801716A*	23,200	\$3,248
212987301	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*96MSN0801716A*	23,400	\$3,276
212987349	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*96MSN0801716A*	23,600	\$3,304
212987361	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*96MSN0801716A*	23,600	\$3,304
212987722	TEMPSTAR	DLCURAH30ABK	EA*4X36L21A*	*96MSN0802120A*	23,200	\$3,248
212987746	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*96MSN0802120A*	23,400	\$3,276
212987758	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96MSN0802120A*	23,200	\$3,248
212988339	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*96MSN1202422A*	23,400	\$3,276
212988587	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*95MSU0401712A*	23,600	\$3,304
212988599	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*95MSU0401712A*	23,200	\$3,248
212988623	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*95MSU0401712A*	23,200	\$3,248
212988635	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*95MSU0401712A*	23,600	\$3,304
212989031	TEMPSTAR	DLCURAH30ABK	EA*4X37L17A*	*95MSU0601716A*	23,400	\$3,276
212989043	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*95MSU0601716A*	23,200	\$3,248
212989055	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*95MSU0601716A*	23,600	\$3,304

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989067	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*95MSU0601716A*	23,200	\$3,248
212989115	TEMPSTAR	DLCURAH30ABK	END4X42L17**	*95MSU0601716A*	23,400	\$3,276
212989127	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0601716A*	23,600	\$3,304
212989535	TEMPSTAR	DLCURAH30ABK	EA*4X37L21A*	*95MSU0802120A*	23,200	\$3,248
212989547	TEMPSTAR	DLCURAH30ABK	EA*4X42L21A*	*95MSU0802120A*	23,600	\$3,304
212989559	TEMPSTAR	DLCURAH30ABK	EA*4X42L24A*	*95MSU0802120A*	23,600	\$3,304
212989571	TEMPSTAR	DLCURAH30ABK	EA*4X43L21A*	*95MSU0802120A*	23,200	\$3,248
212989595	TEMPSTAR	DLCURAH30ABK	EN(A,D,W)4X42L21**	*95MSU0802120A*	23,600	\$3,304
213249300	TEMPSTAR	DLCURAH30ABK	FEVA0036**+NAVA43601CK		23,600	\$3,304
213353816	TEMPSTAR	DLCURAH30ABK	F5MA4*30L*B*		23,400	\$3,276
213353826	TEMPSTAR	DLCURAH30ABK	F5MA4*36L*B*		23,600	\$3,304
212976977	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*96VTN1002122B*	19,100	\$2,674
212976385	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*96VTN0802120B*	19,100	\$2,674
212975627	TEMPSTAR	DLCURAH24AAK	EN(A,D,W)4X36L17**	*96VTN0601412B*	19,400	\$2,716
211226335	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92ESN0601714A*	29,400	\$4,116
211226345	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*92ESN1002122A*	29,600	\$4,144
211226355	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95ESN0601714A*	29,400	\$4,116
211226366	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95ESN0801716A*	29,400	\$4,116
211226377	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002120A*	29,600	\$4,144
212975253	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*96VTN0401712B*	19,500	\$2,730
211226387	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95ESN1002122A*	29,600	\$4,144
211226397	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*95ESU0601716A*	29,400	\$4,116
211226408	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VTN0802120A*	29,400	\$4,116
211226418	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002120A*	29,600	\$4,144
211226427	TEMPSTAR	DLCURAH36ABK	EA*4X36L21A*	*96VTN1002122A*	29,400	\$4,116
211226621	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601412A*	29,400	\$4,116
211226632	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*92ESN0601714A*	29,200	\$4,088
211226643	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*92ESN0801716A*	29,400	\$4,116
211226665	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*95ESN0601714A*	29,400	\$4,116
211226675	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601412A*	29,400	\$4,116
211226684	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*96VSN0601714A*	29,400	\$4,116
211226693	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*96VSN0801716A*	29,400	\$4,116
211226703	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*95ESU0601716A*	29,400	\$4,116
211226714	TEMPSTAR	DLCURAH36ABK	EA*4X37L17A*	*96VTN0601714A*	29,400	\$4,116
212974311	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*96VSN1002120B*	19,000	\$2,660
212974091	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*96VSN0802120B*	19,100	\$2,674
212973821	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*96VSN0801716B*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227000	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92ESN0601714A*	29,000	\$4,060
211227011	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92ESN0801716A*	29,000	\$4,060
211227022	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92ESN0802120A*	29,200	\$4,088
211227032	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*92ESN1002122A*	29,400	\$4,116
211227042	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95ESN0601714A*	29,400	\$4,116
211227064	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95ESN0802120A*	29,200	\$4,088
211227075	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002120A*	29,200	\$4,088
212983435	TEMPSTAR	DLCURAH24AAK	EN(A,D,W)4X36L17**	*92MSN0601412A*	29,600	\$4,144
211227085	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95ESN1002122A*	29,200	\$4,088
211227103	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VSN0601714A*	29,200	\$4,088
211227112	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VSN0801716A*	29,200	\$4,088
211227121	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VSN0802120A*	29,000	\$4,060
212973521	TEMPSTAR	DLCURAH24AAK	EN(A,D,W)4X36L17**	*96VSN0601412B*	19,400	\$2,716
211227130	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VSN1002120A*	29,000	\$4,060
211227140	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95ESU0802120A*	29,400	\$4,116
211227151	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002120A*	29,000	\$4,060
211227161	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*95ESU1002122A*	29,200	\$4,088
211227181	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VTN0601714A*	29,200	\$4,088
211227191	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VTN0802120A*	29,200	\$4,088
211227201	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002120A*	29,200	\$4,088
211227210	TEMPSTAR	DLCURAH36ABK	EA*4X37L21A*	*96VTN1002122A*	29,000	\$4,060
212973181	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*96VSN0401712B*	19,500	\$2,730
211227517	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92ESN0601714A*	29,400	\$4,116
211227528	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92ESN0801716A*	29,400	\$4,116
211227539	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92ESN0802120A*	29,200	\$4,088
211227550	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002120A*	29,200	\$4,088
211227560	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*92ESN1002122A*	29,600	\$4,144
211227570	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95ESN0601714A*	29,400	\$4,116
211227581	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95ESN0802120A*	29,400	\$4,116
211227591	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95ESN1002122A*	29,600	\$4,144
211227600	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VSN0601714A*	29,400	\$4,116
211227609	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VSN0801716A*	29,400	\$4,116
211227618	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VSN0802120A*	29,400	\$4,116
211227627	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VSN1002120A*	29,400	\$4,116
211227637	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95ESU0601716A*	29,400	\$4,116
211227648	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95ESU0802120A*	29,600	\$4,144
211227659	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002120A*	29,400	\$4,116
211227669	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*95ESU1002122A*	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211227679	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VTN0601714A*	29,600	\$4,144
211227689	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VTN0801716A*	29,400	\$4,116
211227699	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VTN0802120A*	29,400	\$4,116
211227709	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002120A*	29,400	\$4,116
211227718	TEMPSTAR	DLCURAH36ABK	EA*4X42L21A*	*96VTN1002122A*	29,200	\$4,088
211227965	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*92ESN0802120A*	29,200	\$4,088
211227976	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002120A*	29,200	\$4,088
211227986	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*92ESN1002122A*	29,600	\$4,144
211227996	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*92ESN1202420A*	29,400	\$4,116
211228007	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95ESN0802120A*	29,400	\$4,116
211228018	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002120A*	29,400	\$4,116
211228028	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95ESN1002122A*	29,600	\$4,144
211228038	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95ESN1202422A*	29,600	\$4,144
211228049	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95ESN1402422A*	29,600	\$4,144
211228059	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VSN0802120A*	29,400	\$4,116
211228068	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VSN1002120A*	29,400	\$4,116
212984868	TEMPSTAR	DLCURAH24AAK	EN(A,D)4X36L21**	*92MSN0802120A*	31,400	\$4,396
211228077	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VSN1202422A*	29,400	\$4,116
211228087	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95ESU0802120A*	29,600	\$4,144
211228098	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002120A*	29,400	\$4,116
211228108	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*95ESU1002122A*	29,600	\$4,144
211228118	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VTN0802120A*	29,400	\$4,116
211228128	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002120A*	29,400	\$4,116
211228137	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VTN1002122A*	29,200	\$4,088
211228147	TEMPSTAR	DLCURAH36ABK	EA*4X42L24A*	*96VTN1202422A*	29,400	\$4,116
213353786	TEMPSTAR	DLCURAH24ABK	F5MA4*30L*B*		19,100	\$2,674
213353776	TEMPSTAR	DLCURAH24ABK	F5MA4*24L*B*		19,300	\$2,702
213249278	TEMPSTAR	DLCURAH24ABK	FEVA0024**+NAVA43601CK		19,000	\$2,660
213076406	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601716B*	19,400	\$2,716
213076380	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601716B*	19,400	\$2,716
213076368	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002122A*	19,500	\$2,730
213076359	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*95MSU1002122A*	19,100	\$2,674
213076124	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU1002120A*	19,200	\$2,688
213076112	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*95MSU1002120A*	18,500	\$2,590
212989631	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0802120A*	19,100	\$2,674
212989619	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*95MSU0802120A*	18,600	\$2,604
212989607	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*95MSU0802120A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989259	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0601716A*	19,100	\$2,674
212989247	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0601716A*	19,100	\$2,674
212989235	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0601716A*	19,100	\$2,674
212989223	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0601716A*	19,400	\$2,716
212989211	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*95MSU0601716A*	18,700	\$2,618
212989199	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*95MSU0601716A*	18,900	\$2,646
212989187	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*95MSU0601716A*	19,100	\$2,674
212989175	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95MSU0601716A*	19,100	\$2,674
212989163	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95MSU0601716A*	19,100	\$2,674
212989151	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*95MSU0601716A*	18,600	\$2,604
212989139	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95MSU0601716A*	19,400	\$2,716
212988767	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95MSU0401712A*	19,200	\$2,688
212988755	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95MSU0401712A*	19,200	\$2,688
212988743	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95MSU0401712A*	19,200	\$2,688
212988731	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95MSU0401712A*	19,500	\$2,730
212988719	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*95MSU0401712A*	18,600	\$2,604
212988707	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*95MSU0401712A*	18,800	\$2,632
212988695	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*95MSU0401712A*	19,000	\$2,660
212988683	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95MSU0401712A*	19,100	\$2,674
212988671	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95MSU0401712A*	19,200	\$2,688
212988659	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*95MSU0401712A*	18,700	\$2,618
212988647	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95MSU0401712A*	19,500	\$2,730
212987830	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0802120A*	32,800	\$4,592
212987818	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96MSN0802120A*	19,100	\$2,674
212987806	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96MSN0802120A*	18,700	\$2,618
212987493	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96MSN0801716A*	19,200	\$2,688
212987481	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0801716A*	19,200	\$2,688
212987469	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0801716A*	19,200	\$2,688
212987457	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0801716A*	19,500	\$2,730
212987445	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96MSN0801716A*	19,800	\$2,772
212987433	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96MSN0801716A*	18,800	\$2,632
212987421	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96MSN0801716A*	19,000	\$2,660
212987409	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96MSN0801716A*	19,100	\$2,674
212987397	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96MSN0801716A*	19,200	\$2,688
212987385	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96MSN0801716A*	18,700	\$2,618
212987373	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96MSN0801716A*	19,400	\$2,716
212986966	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0601412A*	19,200	\$2,688
212986956	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0601412A*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986946	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0601412A*	19,200	\$2,688
212986936	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0601412A*	19,500	\$2,730
212986926	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96MSN0601412A*	19,500	\$2,730
212986916	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96MSN0601412A*	18,800	\$2,632
212986906	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96MSN0601412A*	19,100	\$2,674
212986896	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96MSN0601412A*	19,100	\$2,674
212986886	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96MSN0601412A*	19,200	\$2,688
212986876	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96MSN0601412A*	18,700	\$2,618
212986866	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96MSN0601412A*	19,400	\$2,716
212986642	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401712A*	19,100	\$2,674
212986630	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401712A*	19,100	\$2,674
212986618	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401712A*	19,100	\$2,674
212986606	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96MSN0401712A*	19,700	\$2,758
211289637	TEMPSTAR	DLCURAH60ABK	FVM4X60***L		37,800	\$5,292
213607747	TEMPSTAR	DLCURAH36ABK	FTMA4B48L0C*		28,800	\$4,032
213607732	TEMPSTAR	DLCURAH36ABK	FTMA4B36L0C*		29,400	\$4,116
213607687	TEMPSTAR	DLCURAH30ABK	FTMA4B36L0C*		23,600	\$3,304
213607657	TEMPSTAR	DLCURAH24ABK	FTMA4X24L0B*		19,300	\$2,702
213607642	TEMPSTAR	DLCURAH24ABK	FTMA4B36L0C*		19,100	\$2,674
213607597	TEMPSTAR	DLCURAH18ABK	FTMA4X24L0B*		12,400	\$1,736
212986594	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401712A*	18,800	\$2,632
212986582	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96MSN0401712A*	19,000	\$2,660
212986570	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401712A*	19,200	\$2,688
212986558	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401712A*	19,200	\$2,688
212986546	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401712A*	19,200	\$2,688
212986534	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401712A*	18,900	\$2,646
212986269	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96MSN0401410A*	19,200	\$2,688
212986257	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0401410A*	19,200	\$2,688
212986149	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96MSN0401410A*	19,500	\$2,730
212986137	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96MSN0401410A*	19,500	\$2,730
212985862	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96MSN0261410A*	19,000	\$2,660
212985852	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0261410A*	19,000	\$2,660
212985842	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0261410A*	19,100	\$2,674
212985832	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0261410A*	19,500	\$2,730
212985822	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96MSN0261410A*	19,500	\$2,730
212985812	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96MSN0261410A*	18,800	\$2,632
212985802	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96MSN0261410A*	19,100	\$2,674
212985792	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96MSN0261410A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212985782	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96MSN0261410A*	19,200	\$2,688
212985772	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96MSN0261410A*	18,700	\$2,618
212985762	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96MSN0261410A*	19,500	\$2,730
212985369	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN1002120A*	19,100	\$2,674
212985357	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*92MSN1002120A*	18,700	\$2,618
212985345	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92MSN1002120A*	19,100	\$2,674
212985058	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0802120A*	32,800	\$4,592
212985048	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*92MSN0802120A*	19,000	\$2,660
212985038	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92MSN0802120A*	18,900	\$2,646
212984695	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0801716A*	19,100	\$2,674
212984683	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0801716A*	19,100	\$2,674
212984671	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0801716A*	19,100	\$2,674
212984659	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0801716A*	19,500	\$2,730
212984647	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*92MSN0801716A*	18,400	\$2,576
212984635	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*92MSN0801716A*	18,900	\$2,646
212984623	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92MSN0801716A*	19,000	\$2,660
212984611	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*92MSN0801716A*	19,000	\$2,660
212984599	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*92MSN0801716A*	19,100	\$2,674
212984587	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*92MSN0801716A*	18,500	\$2,590
212984575	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*92MSN0801716A*	19,300	\$2,702
212984155	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0601714A*	19,100	\$2,674
212984143	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0601714A*	19,100	\$2,674
212984131	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601714A*	19,100	\$2,674
212984119	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601714A*	19,400	\$2,716
212984107	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*92MSN0601714A*	18,700	\$2,618
212984095	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601714A*	18,900	\$2,646
212984083	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92MSN0601714A*	19,100	\$2,674
212984071	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601714A*	19,100	\$2,674
212984059	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601714A*	19,100	\$2,674
212984047	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601714A*	18,700	\$2,618
212984035	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601714A*	19,400	\$2,716
212983615	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0601412A*	19,200	\$2,688
212983605	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*92MSN0601412A*	19,200	\$2,688
212983595	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0601412A*	19,200	\$2,688
212983585	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*92MSN0601412A*	19,500	\$2,730
212983575	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*92MSN0601412A*	19,500	\$2,730
212983565	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*92MSN0601412A*	19,000	\$2,660
212983555	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*92MSN0601412A*	19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983545	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*92MSN0601412A*	19,200	\$2,688
212983535	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*92MSN0601412A*	19,200	\$2,688
212983525	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*92MSN0601412A*	18,800	\$2,632
212983515	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*92MSN0601412A*	19,500	\$2,730
212983248	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92MSN0401712A*	19,200	\$2,688
212983237	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92MSN0401712A*	19,200	\$2,688
212983226	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*92MSN0401712A*	19,200	\$2,688
212983215	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*92MSN0401712A*	19,600	\$2,744
212983204	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*92MSN0401712A*	18,800	\$2,632
212983193	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*92MSN0401712A*	19,000	\$2,660
212983182	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92MSN0401712A*	19,200	\$2,688
212983171	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*92MSN0401712A*	19,200	\$2,688
212983160	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*92MSN0401712A*	19,300	\$2,702
212983149	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*92MSN0401712A*	18,800	\$2,632
212983138	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*92MSN0401712A*	19,500	\$2,730
212976997	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002122B*	19,200	\$2,688
212976699	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120B*	19,100	\$2,674
212976686	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002120B*	18,600	\$2,604
212976673	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120B*	19,000	\$2,660
212976412	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120B*	19,200	\$2,688
212976398	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120B*	18,600	\$2,604
212976133	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716B*	18,900	\$2,646
212976120	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716B*	18,900	\$2,646
212976107	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716B*	18,900	\$2,646
212976094	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716B*	19,500	\$2,730
212976068	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716B*	19,000	\$2,660
212976055	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716B*	19,000	\$2,660
212976042	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716B*	19,000	\$2,660
212976029	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716B*	19,100	\$2,674
212976016	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VTN0801716B*	18,800	\$2,632
212976003	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716B*	19,500	\$2,730
212975759	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412B*	23,600	\$3,304
212975748	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412B*	19,100	\$2,674
212975737	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412B*	19,100	\$2,674
212975726	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412B*	19,000	\$2,660
212975715	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412B*	19,500	\$2,730
212975704	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412B*	19,500	\$2,730
212975693	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412B*	18,800	\$2,632

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212975682	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412B*	19,100	\$2,674
212975671	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412B*	19,100	\$2,674
212975660	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412B*	19,100	\$2,674
212975649	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412B*	18,600	\$2,604
212975638	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412B*	19,400	\$2,716
212975374	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712B*	29,200	\$4,088
212975363	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712B*	19,200	\$2,688
212975352	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712B*	19,200	\$2,688
212975341	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712B*	19,200	\$2,688
212975330	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712B*	19,600	\$2,744
212975319	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401712B*	18,900	\$2,646
212975308	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712B*	18,900	\$2,646
212975297	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712B*	19,100	\$2,674
212975286	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712B*	19,100	\$2,674
212975275	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712B*	19,200	\$2,688
212975264	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712B*	18,800	\$2,632
212975065	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410B*	19,200	\$2,688
212975052	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410B*	19,200	\$2,688
212975039	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410B*	19,100	\$2,674
212975026	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410B*	19,600	\$2,744
212975013	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410B*	19,600	\$2,744
212975000	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410B*	18,800	\$2,632
212974987	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410B*	19,200	\$2,688
212974974	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410B*	19,200	\$2,688
212974961	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410B*	19,200	\$2,688
212974948	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401410B*	18,700	\$2,618
212974935	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410B*	19,500	\$2,730
212974922	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410B*	19,500	\$2,730
212974321	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120B*	18,900	\$2,646
212974111	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VSN0802120B*	19,200	\$2,688
212974101	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120B*	18,600	\$2,604
212973921	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716B*	18,900	\$2,646
212973911	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716B*	18,900	\$2,646
212973901	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716B*	18,900	\$2,646
212973891	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VSN0801716B*	19,500	\$2,730
212973871	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716B*	19,000	\$2,660
212973861	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716B*	19,000	\$2,660
212973851	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716B*	19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212973841	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VSN0801716B*	19,100	\$2,674
212973831	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716B*	18,800	\$2,632
212973641	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412B*	23,600	\$3,304
212973631	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412B*	19,100	\$2,674
212973621	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412B*	19,100	\$2,674
212973611	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412B*	19,000	\$2,660
212973601	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412B*	19,500	\$2,730
212973591	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412B*	19,500	\$2,730
212973581	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412B*	18,800	\$2,632
212973571	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412B*	19,100	\$2,674
212973561	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412B*	19,100	\$2,674
212973551	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412B*	19,100	\$2,674
212973541	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412B*	18,600	\$2,604
212973531	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412B*	19,400	\$2,716
212973291	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712B*	29,200	\$4,088
212973281	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712B*	19,200	\$2,688
212973271	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712B*	19,200	\$2,688
212973261	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712B*	19,200	\$2,688
212973251	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712B*	19,600	\$2,744
212973241	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401712B*	18,900	\$2,646
212973231	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712B*	18,900	\$2,646
212973221	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712B*	19,100	\$2,674
212973211	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712B*	19,100	\$2,674
212973201	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712B*	19,200	\$2,688
212973191	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712B*	18,800	\$2,632
212973001	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410B*	19,200	\$2,688
212972991	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410B*	19,200	\$2,688
212972981	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410B*	19,200	\$2,688
212972971	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410B*	19,500	\$2,730
212972961	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410B*	19,500	\$2,730
212972951	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410B*	19,000	\$2,660
212972941	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410B*	19,200	\$2,688
212972931	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410B*	19,200	\$2,688
212972921	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401410B*	19,200	\$2,688
212972911	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410B*	18,800	\$2,632
212972901	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410B*	19,500	\$2,730
211245989	TEMPSTAR	DLCURAH24ABK	FVM4X36***L		19,000	\$2,660
211245979	TEMPSTAR	DLCURAH24ABK	FVM4X24***L		19,000	\$2,660

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245968	TEMPSTAR	DLCURAH24ABK	FM(C,U)4Z36**AL*		19,300	\$2,702
211245957	TEMPSTAR	DLCURAH24ABK	FM(C,U)4Z30**AL*		19,300	\$2,702
211245946	TEMPSTAR	DLCURAH24ABK	FM(C,U)4Z24**AL*		19,500	\$2,730
211245935	TEMPSTAR	DLCURAH24ABK	FM(C,U)4X36**AL*		19,900	\$2,786
211245924	TEMPSTAR	DLCURAH24ABK	FM(C,U)4X30**AL*		19,900	\$2,786
211245913	TEMPSTAR	DLCURAH24ABK	FMA4X36**AL*		19,600	\$2,744
211245902	TEMPSTAR	DLCURAH24ABK	FMA4X30**AL*		19,600	\$2,744
211245891	TEMPSTAR	DLCURAH24ABK	FMA4X24**AL*		19,600	\$2,744
211245869	TEMPSTAR	DLCURAH24ABK	FMA4P24**AL*		19,900	\$2,786
211245858	TEMPSTAR	DLCURAH24ABK	FXM4X36**AL		18,500	\$2,590
211245847	TEMPSTAR	DLCURAH24ABK	FXM4X30**AL		19,100	\$2,674
211245836	TEMPSTAR	DLCURAH24ABK	FXM4X24**AL		19,100	\$2,674
211245825	TEMPSTAR	DLCURAH24ABK	FEM4X30**BL		19,100	\$2,674
211245813	TEMPSTAR	DLCURAH24ABK	FEM4X24**CL		19,000	\$2,660
211245801	TEMPSTAR	DLCURAH24ABK	FEM4P30**AL		19,100	\$2,674
211245731	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0401712A*	19,100	\$2,674
211245720	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0801716A*	19,500	\$2,730
211245709	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0601714A*	19,400	\$2,716
211245698	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN1002120A*	19,300	\$2,702
211245687	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0802120A*	19,300	\$2,702
211245676	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0801716A*	19,100	\$2,674
211245665	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*92ESN0601714A*	19,100	\$2,674
211245573	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002120A*	19,000	\$2,660
211245563	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0802120A*	18,900	\$2,646
211245553	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0601714A*	19,100	\$2,674
211245542	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0401712A*	19,400	\$2,716
211245522	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0801716A*	19,100	\$2,674
211245511	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESN0802120A*	19,300	\$2,702
211245501	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN0401712A*	19,000	\$2,660
211245467	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0601716A*	19,100	\$2,674
211245385	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VTN1002122A*	18,900	\$2,646
211245364	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*95ESU0401712A*	19,000	\$2,660
211245354	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0801716A*	19,100	\$2,674
211245345	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0401712A*	19,000	\$2,660
211245336	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN1002120A*	19,000	\$2,660
211245327	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0802120A*	19,000	\$2,660
211245318	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X36L21**	*96VSN0601714A*	18,900	\$2,646
211245231	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401712A*	19,100	\$2,674

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211245220	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0401410A*	19,400	\$2,716
211245209	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0801716A*	19,500	\$2,730
211245198	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601714A*	19,400	\$2,716
211245187	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0801716A*	19,100	\$2,674
211245176	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601714A*	19,100	\$2,674
211245165	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*92ESN0601412A*	18,900	\$2,646
211245107	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601714A*	19,100	\$2,674
211245096	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0261410A*	18,900	\$2,646
211245086	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0601412A*	19,000	\$2,660
211245076	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401410A*	19,000	\$2,660
211245065	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601412A*	19,400	\$2,716
211245054	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401712A*	19,400	\$2,716
211245043	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401410A*	19,500	\$2,730
211245023	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0801716A*	19,100	\$2,674
211245013	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VTN0401712A*	19,000	\$2,660
211244977	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0601716A*	19,100	\$2,674
211244919	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*95ESN0401712A*	19,000	\$2,660
211244909	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0801716A*	19,100	\$2,674
211244900	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601412A*	19,000	\$2,660
211244891	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401712A*	19,000	\$2,660
211244882	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0401410A*	19,000	\$2,660
211244873	TEMPSTAR	DLCURAH24ABK	EN(A,D,W)4X36L17**	*96VSN0601714A*	18,900	\$2,646
213372179	TEMPSTAR	DLCURAH60ABK	DLFULAH60XDX + CI		37,000	\$5,180
213372175	TEMPSTAR	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
211244795	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401712A*	19,100	\$2,674
211244784	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0401410A*	19,400	\$2,716
211244773	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0801716A*	19,500	\$2,730
211244762	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601714A*	19,400	\$2,716
211244751	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0801716A*	19,100	\$2,674
211244740	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601714A*	19,100	\$2,674
211244729	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*92ESN0601412A*	18,900	\$2,646
211244671	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601714A*	19,100	\$2,674
211244660	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0261410A*	18,900	\$2,646
211244650	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0601412A*	19,000	\$2,660
211244640	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401410A*	19,000	\$2,660
211244629	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0601412A*	19,400	\$2,716
211244618	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401712A*	19,400	\$2,716
211244607	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESN0401410A*	19,500	\$2,730

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211244587	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0801716A*	19,100	\$2,674
211244577	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VTN0401712A*	19,000	\$2,660
211244541	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0601716A*	19,100	\$2,674
211244483	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*95ESU0401712A*	19,000	\$2,660
211244473	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0801716A*	19,100	\$2,674
211244464	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601412A*	19,000	\$2,660
211244455	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401712A*	19,000	\$2,660
211244446	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0401410A*	19,000	\$2,660
211244437	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L17**	*96VSN0601714A*	18,900	\$2,646
211244397	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0401410A*	19,400	\$2,716
211244386	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*92ESN0601412A*	18,900	\$2,646
211244363	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0261410A*	19,500	\$2,730
211244353	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0601412A*	19,000	\$2,660
211244343	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96VTN0401410A*	19,100	\$2,674
211244332	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0601412A*	19,400	\$2,716
211244321	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*95ESN0401410A*	19,500	\$2,730
211244299	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0601412A*	19,000	\$2,660
211244290	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96VSN0401410A*	19,100	\$2,674
211244221	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401712A*	19,500	\$2,730
211244210	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0401410A*	19,700	\$2,758
211244199	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0801716A*	19,800	\$2,772
211244188	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601714A*	19,700	\$2,758
211244177	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0801716A*	19,400	\$2,716
211244166	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601714A*	19,500	\$2,730
211244155	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*92ESN0601412A*	19,600	\$2,744
211244097	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601714A*	19,400	\$2,716
211244086	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0261410A*	19,900	\$2,786
211244076	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0601412A*	19,300	\$2,702
211244066	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401410A*	19,500	\$2,730
211244055	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0601412A*	19,700	\$2,758
211244044	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401712A*	19,700	\$2,758
211244033	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESN0401410A*	19,800	\$2,772
211244013	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0801716A*	19,500	\$2,730
211244003	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VTN0401712A*	19,700	\$2,758
211243967	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0601716A*	19,400	\$2,716
211243909	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*95ESU0401712A*	19,300	\$2,702
211243899	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0801716A*	19,500	\$2,730
211243890	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601412A*	19,300	\$2,702

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211243881	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401712A*	19,700	\$2,758
211243872	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0401410A*	19,500	\$2,730
211243863	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96VSN0601714A*	19,500	\$2,730
211243823	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0401410A*	19,700	\$2,758
211243812	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*92ESN0601412A*	19,600	\$2,744
211243789	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0261410A*	19,900	\$2,786
211243779	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0601412A*	19,300	\$2,702
211243769	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96VTN0401410A*	19,500	\$2,730
211243758	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0601412A*	19,700	\$2,758
211243747	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*95ESN0401410A*	19,800	\$2,772
211243725	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0601412A*	19,300	\$2,702
211243716	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96VSN0401410A*	19,500	\$2,730
211243471	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VTN0802120A*	18,400	\$2,576
211243409	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VTN0401712A*	18,500	\$2,590
211243293	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VTN1002122A*	18,400	\$2,576
211243253	TEMPSTAR	DLCURAH24ABK	EA*4X37L21A*	*96VSN0401712A*	18,500	\$2,590
211243139	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*92ESN0401712A*	18,900	\$2,646
211243095	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*92ESN0801716A*	18,900	\$2,646
211243084	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*92ESN0601714A*	18,900	\$2,646
211243015	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601714A*	18,900	\$2,646
211242994	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VTN0601412A*	18,700	\$2,618
211242984	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VTN0401410A*	18,900	\$2,646
211242931	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VTN0801716A*	18,900	\$2,646
211242885	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*95ESU0601716A*	18,900	\$2,646
211242827	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*95ESU0401712A*	18,700	\$2,618
211242817	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VSN0801716A*	18,900	\$2,646
211242808	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601412A*	18,700	\$2,618
211242790	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VSN0401410A*	18,900	\$2,646
211242781	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96VSN0601714A*	19,000	\$2,660
211242695	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92ESN0401712A*	19,100	\$2,674
211242684	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*95ESN0801716A*	19,400	\$2,716
211242673	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*95ESN0601714A*	19,300	\$2,702
211242662	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92ESN1002120A*	19,300	\$2,702
211242651	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92ESN0802120A*	19,300	\$2,702
211242640	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92ESN0801716A*	19,100	\$2,674
211242629	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*92ESN0601714A*	19,100	\$2,674
211242537	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002120A*	19,000	\$2,660
211242527	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN0802120A*	18,900	\$2,646

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211242517	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN0601714A*	19,100	\$2,674
211242506	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*95ESN0401712A*	19,300	\$2,702
211242486	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN0801716A*	19,100	\$2,674
211242475	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*95ESN0802120A*	19,300	\$2,702
211242465	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN0401712A*	19,000	\$2,660
211242431	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*95ESU0601716A*	19,100	\$2,674
211242349	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VTN1002122A*	18,900	\$2,646
211242328	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*95ESU0401712A*	18,900	\$2,646
211242318	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VSN0801716A*	19,100	\$2,674
211242309	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VSN0401712A*	19,000	\$2,660
211242300	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VSN1002120A*	18,900	\$2,646
211242291	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VSN0802120A*	19,000	\$2,660
211242282	TEMPSTAR	DLCURAH24ABK	EA*4X36L21A*	*96VSN0601714A*	18,900	\$2,646
211242195	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401712A*	19,100	\$2,674
211242184	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*92ESN0401410A*	19,400	\$2,716
211242173	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95ESN0801716A*	19,400	\$2,716
211242162	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601714A*	19,300	\$2,702
211242151	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*92ESN0801716A*	19,100	\$2,674
211242140	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601714A*	19,100	\$2,674
211242129	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*92ESN0601412A*	18,800	\$2,632
211242071	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601714A*	19,100	\$2,674
211242060	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95ESN0261410A*	18,900	\$2,646
211242050	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VTN0601412A*	18,900	\$2,646
211242040	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401410A*	18,900	\$2,646
211242029	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95ESN0601412A*	19,300	\$2,702
211242018	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401712A*	19,300	\$2,702
211242007	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95ESN0401410A*	19,400	\$2,716
211241987	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VTN0801716A*	19,100	\$2,674
211241977	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VTN0401712A*	18,900	\$2,646
211241941	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95ESU0601716A*	19,100	\$2,674
211241883	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*95ESU0401712A*	18,900	\$2,646
211241873	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VSN0801716A*	19,100	\$2,674
211241864	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601412A*	18,900	\$2,646
211241855	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401712A*	18,900	\$2,646
211241846	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VSN0401410A*	18,900	\$2,646
211241837	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96VSN0601714A*	18,900	\$2,646
211241759	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401712A*	19,100	\$2,674
211241748	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*92ESN0401410A*	19,400	\$2,716

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211241737	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95ESN0801716A*	19,500	\$2,730
211241726	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601714A*	19,400	\$2,716
211241715	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*92ESN0801716A*	19,100	\$2,674
211241704	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601714A*	19,200	\$2,688
211241693	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*92ESN0601412A*	18,900	\$2,646
211241635	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601714A*	19,100	\$2,674
211241624	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95ESN0261410A*	18,900	\$2,646
211241614	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VTN0601412A*	19,000	\$2,660
211241604	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401410A*	19,000	\$2,660
211241593	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95ESN0601412A*	19,400	\$2,716
211241582	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401712A*	19,400	\$2,716
211241571	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95ESN0401410A*	19,500	\$2,730
211241551	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VTN0801716A*	19,200	\$2,688
211241541	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VTN0401712A*	19,000	\$2,660
211241505	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95ESU0601716A*	19,100	\$2,674
211241447	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*95ESU0401712A*	19,000	\$2,660
211241437	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VSN0801716A*	19,200	\$2,688
211241428	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601412A*	19,000	\$2,660
211241419	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401712A*	19,000	\$2,660
211241410	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VSN0401410A*	19,000	\$2,660
211241401	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96VSN0601714A*	18,900	\$2,646
211241361	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*92ESN0401410A*	19,400	\$2,716
211241350	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*92ESN0601412A*	18,900	\$2,646
211241327	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*95ESN0261410A*	19,600	\$2,744
211241317	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96VTN0601412A*	19,000	\$2,660
211241307	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96VTN0401410A*	19,100	\$2,674
211241296	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*95ESN0601412A*	19,400	\$2,716
211241285	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*95ESN0401410A*	19,500	\$2,730
211241263	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96VSN0601412A*	19,000	\$2,660
211241254	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96VSN0401410A*	19,100	\$2,674
211241119	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*92ESN0601412A*	18,500	\$2,590
211241040	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VTN0601412A*	18,600	\$2,604
211240967	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VTN0401712A*	18,600	\$2,604
211240873	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*95ESU0401712A*	18,600	\$2,604
211240854	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VSN0601412A*	18,600	\$2,604
211240845	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96VSN0401712A*	18,600	\$2,604
211240749	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401712A*	19,400	\$2,716
211240738	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*92ESN0401410A*	19,700	\$2,758

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211240727	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95ESN0801716A*	19,700	\$2,758
211240716	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601714A*	19,600	\$2,744
211240705	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*92ESN0801716A*	19,400	\$2,716
211240694	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601714A*	19,400	\$2,716
211240683	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*92ESN0601412A*	19,200	\$2,688
211240625	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601714A*	19,400	\$2,716
211240614	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95ESN0261410A*	19,800	\$2,772
211240604	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0601412A*	19,300	\$2,702
211240594	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401410A*	19,400	\$2,716
211240583	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95ESN0601412A*	19,600	\$2,744
211240572	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401712A*	19,700	\$2,758
211240561	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95ESN0401410A*	19,700	\$2,758
211240541	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0801716A*	19,400	\$2,716
211240531	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VTN0401712A*	19,300	\$2,702
211240495	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95ESU0601716A*	19,400	\$2,716
211240437	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*95ESU0401712A*	19,300	\$2,702
211240427	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VSN0801716A*	19,400	\$2,716
211240418	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601412A*	19,300	\$2,702
211240409	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401712A*	19,300	\$2,702
211240400	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VSN0401410A*	19,400	\$2,716
211240391	TEMPSTAR	DLCURAH24ABK	EA*4X24L17A*	*96VSN0601714A*	19,500	\$2,730
211240351	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*92ESN0401410A*	19,700	\$2,758
211240340	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*92ESN0601412A*	19,600	\$2,744
211240317	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*95ESN0261410A*	19,800	\$2,772
211240307	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96VTN0601412A*	19,300	\$2,702
211240297	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96VTN0401410A*	19,400	\$2,716
211240286	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*95ESN0601412A*	19,600	\$2,744
211240275	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*95ESN0401410A*	19,700	\$2,758
211240253	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96VSN0601412A*	19,300	\$2,702
211240244	TEMPSTAR	DLCURAH24ABK	EA*4X24L14A*	*96VSN0401410A*	19,400	\$2,716
211239230	TEMPSTAR	DLCURAH24ABK	FJMA4*24L*B*		19,200	\$2,688
213353746	TEMPSTAR	DLCURAH18ABK	F5MA4*24L*B*		12,500	\$1,750
213353736	TEMPSTAR	DLCURAH18ABK	F5MA4*18L*A*		12,800	\$1,792
213249256	TEMPSTAR	DLCURAH18ABK	FEVA0024**+NAVA43601CK		12,300	\$1,722
213076393	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601716B*	12,400	\$1,736
212989331	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0601716A*	12,200	\$1,708
212989319	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0601716A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212989307	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*95MSU0601716A*	12,200	\$1,708
212989295	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*95MSU0601716A*	12,000	\$1,680
212989283	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*95MSU0601716A*	12,300	\$1,722
212989271	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*95MSU0601716A*	12,100	\$1,694
212988839	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*95MSU0401712A*	12,200	\$1,708
212988827	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*95MSU0401712A*	12,500	\$1,750
212988815	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*95MSU0401712A*	12,200	\$1,708
212988803	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*95MSU0401712A*	12,000	\$1,680
212988791	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*95MSU0401712A*	12,300	\$1,722
212988779	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*95MSU0401712A*	12,100	\$1,694
212987565	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0801716A*	12,200	\$1,708
212987553	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0801716A*	12,500	\$1,750
212987541	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96MSN0801716A*	12,100	\$1,694
212987529	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96MSN0801716A*	12,200	\$1,708
212987517	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96MSN0801716A*	12,500	\$1,750
212987505	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96MSN0801716A*	12,300	\$1,722
212987086	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0601412A*	20,200	\$2,828
212987076	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0601412A*	12,200	\$1,708
212987066	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0601412A*	12,200	\$1,708
212987056	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0601412A*	12,300	\$1,722
212987046	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0601412A*	12,300	\$1,722
212987036	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96MSN0601412A*	12,500	\$1,750
212987026	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96MSN0601412A*	12,200	\$1,708
212987016	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96MSN0601412A*	12,200	\$1,708
212987006	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96MSN0601412A*	12,000	\$1,680
212986996	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96MSN0601412A*	12,300	\$1,722
212986986	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96MSN0601412A*	12,300	\$1,722
212986726	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401712A*	20,000	\$2,800
212986714	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401712A*	12,300	\$1,722
212986702	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401712A*	12,500	\$1,750
212986690	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96MSN0401712A*	12,300	\$1,722
212986678	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401712A*	12,100	\$1,694
212986666	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401712A*	12,300	\$1,722
212986389	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0401410A*	12,300	\$1,722
212986377	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0401410A*	12,300	\$1,722
212986365	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0401410A*	12,400	\$1,736
212986353	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0401410A*	12,400	\$1,736
212986341	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0401410A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212986329	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96MSN0401410A*	12,300	\$1,722
212986317	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96MSN0401410A*	12,300	\$1,722
212986305	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96MSN0401410A*	12,400	\$1,736
212986293	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96MSN0401410A*	12,400	\$1,736
212986281	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96MSN0401410A*	12,200	\$1,708
212985982	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96MSN0261410A*	20,200	\$2,828
212985972	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96MSN0261410A*	12,300	\$1,722
212985962	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96MSN0261410A*	12,200	\$1,708
212985952	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96MSN0261410A*	12,300	\$1,722
212985942	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96MSN0261410A*	12,300	\$1,722
212985932	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96MSN0261410A*	12,500	\$1,750
212985922	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96MSN0261410A*	12,200	\$1,708
212985912	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96MSN0261410A*	12,200	\$1,708
212985902	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96MSN0261410A*	12,100	\$1,694
212985892	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96MSN0261410A*	12,300	\$1,722
212985882	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96MSN0261410A*	12,300	\$1,722
212984767	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0801716A*	12,100	\$1,694
212984755	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0801716A*	12,500	\$1,750
212984743	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*92MSN0801716A*	12,400	\$1,736
212984731	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*92MSN0801716A*	12,200	\$1,708
212984719	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*92MSN0801716A*	12,500	\$1,750
212984707	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*92MSN0801716A*	12,300	\$1,722
212984227	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601714A*	12,300	\$1,722
212984215	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601714A*	12,400	\$1,736
212984203	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601714A*	12,300	\$1,722
212984191	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601714A*	12,200	\$1,708
212984179	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601714A*	12,400	\$1,736
212984167	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*92MSN0601714A*	12,200	\$1,708
212983736	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0601412A*	20,000	\$2,800
212983726	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*92MSN0601412A*	12,200	\$1,708
212983715	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0601412A*	12,200	\$1,708
212983705	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*92MSN0601412A*	12,400	\$1,736
212983695	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*92MSN0601412A*	12,400	\$1,736
212983685	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*92MSN0601412A*	12,400	\$1,736
212983675	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*92MSN0601412A*	12,200	\$1,708
212983665	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*92MSN0601412A*	12,300	\$1,722
212983655	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*92MSN0601412A*	12,000	\$1,680
212983645	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*92MSN0601412A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212983314	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*92MSN0401712A*	12,300	\$1,722
212983303	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*92MSN0401712A*	12,400	\$1,736
212983292	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*92MSN0401712A*	12,200	\$1,708
212983281	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*92MSN0401712A*	12,100	\$1,694
212983270	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*92MSN0401712A*	12,300	\$1,722
212983259	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*92MSN0401712A*	12,200	\$1,708
212975847	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716B*	12,200	\$1,708
212975834	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716B*	12,500	\$1,750
212975821	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716B*	12,200	\$1,708
212975808	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716B*	12,000	\$1,680
212975795	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716B*	12,300	\$1,722
212975782	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716B*	12,100	\$1,694
212975495	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412B*	20,000	\$2,800
212975484	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412B*	12,200	\$1,708
212975473	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412B*	12,200	\$1,708
212975462	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412B*	12,400	\$1,736
212975451	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412B*	12,400	\$1,736
212975440	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412B*	12,400	\$1,736
212975429	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412B*	12,200	\$1,708
212975418	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412B*	12,200	\$1,708
212975407	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412B*	12,000	\$1,680
212975396	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412B*	12,300	\$1,722
212975385	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412B*	12,200	\$1,708
212975132	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712B*	20,200	\$2,828
212975121	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712B*	12,200	\$1,708
212975110	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712B*	12,500	\$1,750
212975099	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712B*	12,200	\$1,708
212975088	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712B*	12,100	\$1,694
212975077	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712B*	12,300	\$1,722
212974753	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410B*	12,200	\$1,708
212974740	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410B*	12,200	\$1,708
212974727	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410B*	12,400	\$1,736
212974714	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410B*	12,400	\$1,736
212974701	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410B*	12,400	\$1,736
212974688	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410B*	12,200	\$1,708
212974675	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410B*	12,200	\$1,708
212974662	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410B*	12,100	\$1,694
212974649	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410B*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
212974636	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410B*	12,400	\$1,736
212974623	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410B*	12,100	\$1,694
212973711	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716B*	20,200	\$2,828
212973701	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716B*	12,200	\$1,708
212973691	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716B*	12,500	\$1,750
212973681	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716B*	12,200	\$1,708
212973671	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716B*	12,000	\$1,680
212973661	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716B*	12,300	\$1,722
212973401	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412B*	20,000	\$2,800
212973391	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412B*	12,200	\$1,708
212973381	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412B*	12,200	\$1,708
212973371	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412B*	12,400	\$1,736
212973361	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412B*	12,400	\$1,736
212973351	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412B*	12,400	\$1,736
212973341	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412B*	12,200	\$1,708
212973331	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412B*	12,200	\$1,708
212973321	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412B*	12,000	\$1,680
212973311	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412B*	12,300	\$1,722
212973301	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412B*	12,200	\$1,708
212973071	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712B*	20,200	\$2,828
212973061	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712B*	12,200	\$1,708
212973051	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712B*	12,500	\$1,750
212973041	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712B*	12,200	\$1,708
212973031	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712B*	12,100	\$1,694
212973021	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712B*	12,300	\$1,722
212972771	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410B*	20,200	\$2,828
212972761	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410B*	12,200	\$1,708
212972751	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410B*	12,200	\$1,708
212972741	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410B*	12,400	\$1,736
212972731	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410B*	12,400	\$1,736
212972721	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410B*	12,400	\$1,736
212972711	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410B*	12,200	\$1,708
212972701	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410B*	12,200	\$1,708
212972691	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410B*	12,100	\$1,694
212972681	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410B*	12,300	\$1,722
212972671	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410B*	12,300	\$1,722
211265047	TEMPSTAR	DLCURAH18ABK	FVM4X24***L		12,400	\$1,736
211265025	TEMPSTAR	DLCURAH18ABK	FM(C,U)4Z30**AL*		12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211265004	TEMPSTAR	DLCURAH18ABK	FM(C,U)4Z24**AL*		12,500	\$1,750
211264982	TEMPSTAR	DLCURAH18ABK	FM(C,U)4Z18**AL*		12,500	\$1,750
211264960	TEMPSTAR	DLCURAH18ABK	FMA4X24**AL*		12,400	\$1,736
211264938	TEMPSTAR	DLCURAH18ABK	FMA4X18**AL*		12,400	\$1,736
211264917	TEMPSTAR	DLCURAH18ABK	FXM4X30**AL		12,400	\$1,736
211264894	TEMPSTAR	DLCURAH18ABK	FXM4X24**AL		12,400	\$1,736
211264774	TEMPSTAR	DLCURAH18ABK	FEM4P18**AL		12,300	\$1,722
211264750	TEMPSTAR	DLCURAH18ABK	FJMA4*18L*A*		12,700	\$1,778
211264621	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401712A*	12,500	\$1,750
211264599	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0401410A*	12,500	\$1,750
211264578	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601714A*	12,300	\$1,722
211264555	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*92ESN0601412A*	12,500	\$1,750
211264463	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601714A*	12,400	\$1,736
211264439	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0261410A*	12,600	\$1,764
211264418	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0601412A*	12,400	\$1,736
211264396	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401410A*	12,300	\$1,722
211264337	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0601412A*	12,400	\$1,736
211264292	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401712A*	12,200	\$1,708
211264257	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESN0401410A*	12,400	\$1,736
211264188	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0801716A*	12,200	\$1,708
211264156	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VTN0401712A*	12,400	\$1,736
211264013	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*95ESU0401712A*	12,400	\$1,736
211263996	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0801716A*	12,200	\$1,708
211263978	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601412A*	12,400	\$1,736
211263960	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401712A*	12,400	\$1,736
211263943	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0401410A*	12,300	\$1,722
211263924	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L17**	*96VSN0601714A*	12,400	\$1,736
211263841	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0401410A*	12,500	\$1,750
211263819	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*92ESN0601412A*	12,500	\$1,750
211263772	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0261410A*	12,500	\$1,750
211263752	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0601412A*	12,400	\$1,736
211263731	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96VTN0401410A*	12,200	\$1,708
211263706	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0601412A*	12,400	\$1,736
211263683	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*95ESN0401410A*	12,400	\$1,736
211263637	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0601412A*	12,400	\$1,736
211263619	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X30L14**	*96VSN0401410A*	12,200	\$1,708
211263476	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401712A*	12,600	\$1,764
211263452	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0401410A*	12,600	\$1,764

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211263430	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0801716A*	12,900	\$1,806
211263407	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601714A*	12,400	\$1,736
211263384	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*92ESN0601412A*	12,600	\$1,764
211263288	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601714A*	12,500	\$1,750
211263263	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0261410A*	12,700	\$1,778
211263242	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0601412A*	12,500	\$1,750
211263222	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401410A*	12,300	\$1,722
211263196	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0601412A*	12,500	\$1,750
211263174	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401712A*	12,300	\$1,722
211263151	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401410A*	12,500	\$1,750
211263115	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0801716A*	12,300	\$1,722
211263094	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VTN0401712A*	12,500	\$1,750
211263023	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0601716A*	12,900	\$1,806
211262929	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*95ESN0401712A*	12,400	\$1,736
211262910	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0801716A*	12,300	\$1,722
211262893	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601412A*	12,500	\$1,750
211262875	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401712A*	12,500	\$1,750
211262858	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0401410A*	12,300	\$1,722
211262840	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L17**	*96VSN0601714A*	12,400	\$1,736
211262760	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0401410A*	12,600	\$1,764
211262737	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*92ESN0601412A*	12,600	\$1,764
211262691	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0261410A*	12,700	\$1,778
211262671	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0601412A*	12,500	\$1,750
211262651	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96VTN0401410A*	12,300	\$1,722
211262626	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0601412A*	12,500	\$1,750
211262605	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*95ESN0401410A*	12,500	\$1,750
211262560	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0601412A*	12,500	\$1,750
211262542	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X24L14**	*96VSN0401410A*	12,300	\$1,722
211262480	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0401410A*	12,600	\$1,764
211262458	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*92ESN0601412A*	12,600	\$1,764
211262413	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0261410A*	12,700	\$1,778
211262392	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0601412A*	12,500	\$1,750
211262372	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96VTN0401410A*	12,300	\$1,722
211262348	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0601412A*	12,500	\$1,750
211262326	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*95ESN0401410A*	12,500	\$1,750
211262282	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0601412A*	12,500	\$1,750
211262265	TEMPSTAR	DLCURAH18ABK	EN(A,D)4X18L14**	*96VSN0401410A*	12,300	\$1,722
211262150	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401712A*	12,500	\$1,750

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211262129	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*92ESN0401410A*	12,500	\$1,750
211262108	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601714A*	12,300	\$1,722
211262086	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*92ESN0601412A*	12,500	\$1,750
211261990	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601714A*	12,400	\$1,736
211261965	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*95ESN0261410A*	12,600	\$1,764
211261944	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VTN0601412A*	12,500	\$1,750
211261928	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401410A*	12,200	\$1,708
211261906	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*95ESN0601412A*	12,400	\$1,736
211261879	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401712A*	12,200	\$1,708
211261854	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*95ESN0401410A*	12,400	\$1,736
211261823	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VTN0801716A*	12,200	\$1,708
211261802	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VTN0401712A*	12,400	\$1,736
211261660	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*95ESU0401712A*	12,300	\$1,722
211261640	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VSN0801716A*	12,200	\$1,708
211261622	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601412A*	12,500	\$1,750
211261604	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401712A*	12,400	\$1,736
211261586	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VSN0401410A*	12,200	\$1,708
211261568	TEMPSTAR	DLCURAH18ABK	EA*4X30L17A*	*96VSN0601714A*	12,400	\$1,736
211261489	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*92ESN0401410A*	12,500	\$1,750
211261467	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*92ESN0601412A*	12,500	\$1,750
211261422	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*95ESN0261410A*	12,500	\$1,750
211261402	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96VTN0601412A*	12,400	\$1,736
211261382	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96VTN0401410A*	12,200	\$1,708
211261358	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*95ESN0601412A*	12,400	\$1,736
211261338	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*95ESN0401410A*	12,400	\$1,736
211261294	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96VSN0601412A*	12,400	\$1,736
211261275	TEMPSTAR	DLCURAH18ABK	EA*4X30L14A*	*96VSN0401410A*	12,200	\$1,708
211261085	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401712A*	12,400	\$1,736
211261055	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*92ESN0401410A*	12,400	\$1,736
211261043	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601714A*	12,200	\$1,708
211261029	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*92ESN0601412A*	12,400	\$1,736
211260974	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601714A*	12,200	\$1,708
211260960	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*95ESN0261410A*	12,400	\$1,736
211260948	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VTN0601412A*	12,300	\$1,722
211260936	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401410A*	12,100	\$1,694
211260921	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*95ESN0601412A*	12,300	\$1,722
211260906	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401712A*	12,100	\$1,694
211260894	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*95ESN0401410A*	12,300	\$1,722

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211260869	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VTN0801716A*	12,100	\$1,694
211260855	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VTN0401712A*	12,300	\$1,722
211260767	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*95ESU0401712A*	12,200	\$1,708
211260755	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VSN0801716A*	12,100	\$1,694
211260744	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601412A*	12,300	\$1,722
211260733	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401712A*	12,300	\$1,722
211260723	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VSN0401410A*	12,100	\$1,694
211260712	TEMPSTAR	DLCURAH18ABK	EA*4X25L17A*	*96VSN0601714A*	12,200	\$1,708
211260621	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401712A*	12,600	\$1,764
211260610	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*92ESN0401410A*	12,600	\$1,764
211260598	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601714A*	12,400	\$1,736
211260585	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*92ESN0601412A*	12,600	\$1,764
211260530	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601714A*	12,400	\$1,736
211260516	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*95ESN0261410A*	12,700	\$1,778
211260504	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0601412A*	12,500	\$1,750
211260492	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401410A*	12,300	\$1,722
211260478	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*95ESN0601412A*	12,500	\$1,750
211260465	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401712A*	12,300	\$1,722
211260452	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*95ESN0401410A*	12,500	\$1,750
211260427	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0801716A*	12,300	\$1,722
211260414	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VTN0401712A*	12,500	\$1,750
211260328	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*95ESU0401712A*	12,400	\$1,736
211260316	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VSN0801716A*	12,300	\$1,722
211260305	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601412A*	12,500	\$1,750
211260294	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401712A*	12,500	\$1,750
211260283	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VSN0401410A*	12,300	\$1,722
211260272	TEMPSTAR	DLCURAH18ABK	EA*4X24L17A*	*96VSN0601714A*	12,400	\$1,736
211260225	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*92ESN0401410A*	12,600	\$1,764
211260212	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*92ESN0601412A*	12,600	\$1,764
211260182	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*95ESN0261410A*	12,600	\$1,764
211260172	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96VTN0601412A*	12,500	\$1,750
211260162	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96VTN0401410A*	12,300	\$1,722
211260149	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*95ESN0601412A*	12,500	\$1,750
211260133	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*95ESN0401410A*	12,500	\$1,750
211260107	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96VSN0601412A*	12,500	\$1,750
211260094	TEMPSTAR	DLCURAH18ABK	EA*4X24L14A*	*96VSN0401410A*	12,300	\$1,722
211259992	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401712A*	12,400	\$1,736
211259976	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*92ESN0401410A*	12,400	\$1,736

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211259962	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601714A*	12,200	\$1,708
211259945	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*92ESN0601412A*	12,500	\$1,750
211259884	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601714A*	12,300	\$1,722
211259868	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*95ESN0261410A*	12,500	\$1,750
211259854	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VTN0601412A*	12,400	\$1,736
211259842	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401410A*	12,100	\$1,694
211259829	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*95ESN0601412A*	12,300	\$1,722
211259817	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401712A*	12,100	\$1,694
211259805	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*95ESN0401410A*	12,400	\$1,736
211259783	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VTN0801716A*	12,100	\$1,694
211259772	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VTN0401712A*	12,300	\$1,722
211259675	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*95ESU0401712A*	12,200	\$1,708
211259662	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VSN0801716A*	12,100	\$1,694
211259650	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601412A*	12,400	\$1,736
211259638	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401712A*	12,300	\$1,722
211259625	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VSN0401410A*	12,100	\$1,694
211259612	TEMPSTAR	DLCURAH18ABK	EA*4X19L17A*	*96VSN0601714A*	12,300	\$1,722
211257343	TEMPSTAR	DLCURAH18ABK	FJMA4*24L*B*		12,800	\$1,792
201835804	TEMPSTAR	DLCSRAH12AAK	DLFSCAH12XAK		8,200	\$1,148
201835812	TEMPSTAR	DLCSRAH18AAK	DLFSCAH18XAK		12,000	\$1,680
201835808	TEMPSTAR	DLCSRAH12AAK	DLFSDAH12XAK		8,100	\$1,134
201835816	TEMPSTAR	DLCSRAH24AAK	DLFSFAH24XAK		17,200	\$2,408
201835773	TEMPSTAR	DLCSRAH24AAK	DLFSHAH24XAK		15,000	\$2,100
201835826	TEMPSTAR	DLCLRAH48AAK	DLFLFAH48XAK		35,000	\$4,900
201835771	TEMPSTAR	DLCSRAH18AAK	DLFSHAH18XAK		11,900	\$1,666
201835814	TEMPSTAR	DLCSRAH24AAK	DLFSDAH24XAK		17,400	\$2,436
202463657	TEMPSTAR	DLCPRAH24AAK	DLFPHAH24XAK		15,450	\$2,163
201835818	TEMPSTAR	DLCSRAH24AAK	DLFSCAH24XAK		16,200	\$2,268
205921379	TEMPSTAR	DLCSRAH24AAK	DLFSAAH24XAK		17,500	\$2,450
206350463	TEMPSTAR	DLCSRBH12AAK	DLFSFAH12XAK		8,400	\$1,176
206350461	TEMPSTAR	DLCSRBH12AAK	DLFSCAH12XAK		7,900	\$1,106
206396139	TEMPSTAR	DLCSRAH12AAK	DLFSHBH12XAK		7,500	\$1,050
206350468	TEMPSTAR	DLCSRBH24AAK	DLFSDAH24XAK		14,500	\$2,030
206350462	TEMPSTAR	DLCSRBH12AAK	DLFSDAH12XAK		8,300	\$1,162
206350465	TEMPSTAR	DLCSRBH18AAK	DLFSDAH18XAK		12,700	\$1,778
206188337	TEMPSTAR	DLCSRBH24AAK	DLFSAAH24XAK		16,500	\$2,310
206350466	TEMPSTAR	DLCSRBH18AAK	DLFSFAH18XAK		12,000	\$1,680
206350469	TEMPSTAR	DLCSRBH24AAK	DLFSFAH24XAK		14,500	\$2,030

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207643148	TEMPSTAR	DLCMHBH48EAK	Combination heat pumps with or without ducts		31,000	\$4,340
207643151	TEMPSTAR	DLCMHBH36DAK	Combination heat pumps with or without ducts		22,400	\$3,136
207643142	TEMPSTAR	DLCMHBH30DAK	Combination heat pumps with or without ducts		18,700	\$2,618
207643147	TEMPSTAR	DLCMHBH48EAK	Heat pump with ducts		28,000	\$3,920
207643150	TEMPSTAR	DLCMHBH36DAK	Heat pump with ducts		23,000	\$3,220
207643141	TEMPSTAR	DLCMHBH30DAK	Heat pump with ducts		19,000	\$2,660
207643149	TEMPSTAR	DLCMHBH36DAK	Heat pump without ducts		22,000	\$3,080
207643146	TEMPSTAR	DLCMHBH48EAK	Heat pump without ducts		34,000	\$4,760
207643140	TEMPSTAR	DLCMHBH30DAK	Heat pump without ducts		18,500	\$2,590
206350467	TEMPSTAR	DLCSRBH24AAK	DLFSCAH24XAK		14,500	\$2,030
211222794	TEMPSTAR	DLCURAH30ABK	FXM4X36**AL		23,200	\$3,248
211230824	TEMPSTAR	DLCURAH36ABK	FEM4P42**AL		29,200	\$4,088
211230835	TEMPSTAR	DLCURAH36ABK	FEM4P48**AL		29,400	\$4,116
211230847	TEMPSTAR	DLCURAH36ABK	FEM4X42**BL		29,200	\$4,088
211230859	TEMPSTAR	DLCURAH36ABK	FEM4X48**BL		29,400	\$4,116
211230881	TEMPSTAR	DLCURAH36ABK	FMA4P36**AL*		29,800	\$4,172
211230913	TEMPSTAR	DLCURAH36ABK	FXM4X36**AL		29,000	\$4,060
211719735	TEMPSTAR	DLCURAH18ABK	FMA4P18**AL*		12,700	\$1,778
211264873	TEMPSTAR	DLCURAH18ABK	FXM4X18**AL		12,300	\$1,722
211264850	TEMPSTAR	DLCURAH18ABK	FEM4X24**CL		12,100	\$1,694
211264820	TEMPSTAR	DLCURAH18ABK	FEM4X18**BL		12,300	\$1,722
211264796	TEMPSTAR	DLCURAH18ABK	FEM4P24**AL		12,300	\$1,722
209852113	TEMPSTAR	DLCURAH18ABK	DLFUAH18XAK		13,500	\$1,890
209852114	TEMPSTAR	DLCURAH24ABK	DLFUAH24XAK		19,200	\$2,688
209852116	TEMPSTAR	DLCURAH48ABK	DLFUAH48XAK		36,000	\$5,040
212986161	TEMPSTAR	DLCURAH24ABK	EA*4X25L17A*	*96MSN0401410A*	18,800	\$2,632
212986173	TEMPSTAR	DLCURAH24ABK	EA*4X30L14A*	*96MSN0401410A*	19,200	\$2,688
212986185	TEMPSTAR	DLCURAH24ABK	EA*4X30L17A*	*96MSN0401410A*	19,200	\$2,688
212986197	TEMPSTAR	DLCURAH24ABK	EA*4X36L17A*	*96MSN0401410A*	19,200	\$2,688
212986209	TEMPSTAR	DLCURAH24ABK	EA*4X37L17A*	*96MSN0401410A*	18,800	\$2,632
212986221	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L14**	*96MSN0401410A*	19,500	\$2,730
212986233	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X24L17**	*96MSN0401410A*	19,500	\$2,730
212986245	TEMPSTAR	DLCURAH24ABK	EN(A,D)4X30L14**	*96MSN0401410A*	19,200	\$2,688
207801575	TEMPSTAR	DLCSRBH18AAK	DLFSDAH24XAK		12,600	\$1,764
207826609	TEMPSTAR	DLCSRBH18AAK	DLFSABH18XBK		12,000	\$1,680

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
209550324	TGM	MRAPT12AS	MWAPT12S		10,000	\$1,400
209843026	TGM	MRSVHT48AS	MUVHT48S		29,000	\$4,060
211126509	THERMAL ZONE	TZPLV182PA	TZHVLE1817JA		13,500	\$1,890
211126503	THERMAL ZONE	TZPLV242PA	TZHVLE2417JA		19,200	\$2,688
213885866	THERMAL ZONE	TZPLV242PA	MAC-24HWDN1-MN0		21,000	\$2,940
211126506	THERMAL ZONE	TZPLV302PA	TZHVLE3021JA		21,000	\$2,940
213885867	THERMAL ZONE	TZPLV302PA	MAC-36HWDN1-MN0		22,600	\$3,164
211126510	THERMAL ZONE	TZPLV362PA	TZHVLE3621JA		30,400	\$4,256
213885868	THERMAL ZONE	TZPLV362PA	MVB-36B23T4N1		27,400	\$3,836
213885869	THERMAL ZONE	TZPLV362PA	MAC-36HWDN1-MN0		33,000	\$4,620
211126512	THERMAL ZONE	TZPLV482PA	TZHVLE4821JA		36,000	\$5,040
213885871	THERMAL ZONE	TZPLV482PA	MAC-60HWDN1-MN0		37,000	\$5,180
211126504	THERMAL ZONE	TZPLV602PA	TZHVLE6024JA		42,000	\$5,880
10049878	TOSHIBA CARRIER	MCY-MAP0367HS-UL	Heat pump with ducts		25,000	\$3,500
10052879	TOSHIBA CARRIER	MCY-MAP0487HS-UL	Heat pump without ducts		32,000	\$4,480
217120780	TOSOT	TW24WH25A1DO	TW24WH25A1DI		19,000	\$2,660
217120778	TOSOT	TW24WH29D6DO	TW24WH29D6DI		15,000	\$2,100
217120775	TOSOT	TW30WH19D6DO	TW30WH19D6DI		24,000	\$3,360
217120770	TOSOT	TW36WH19D6DO	TW36WH19D6DI		27,400	\$3,836
217120765	TOSOT	TW12WH25A1DO	TW12WH25A1DI		10,000	\$1,400
217120784	TOSOT	TU60W-EDU	TUD60AH2-GDU		45,000	\$6,300
217120783	TOSOT	TU60W-EDU	TUD48AH2-GDU		39,500	\$5,530
217120782	TOSOT	TU36W-EDU	TUD36AH2-GDU		28,200	\$3,948
217120781	TOSOT	TU36W-EDU	TUD24AH2-GDU		20,600	\$2,884
217080961	TOSOT	TU60-32GDU	TU60-32AH2GDU		43,000	\$6,020
217023702	TOSOT	SU-AORAKI12-230/O	SU-AORAKI12-230/I		10,000	\$1,400
206414272	TOSOT	TU36-24WADU	TUD24-24AH2ADU		20,000	\$2,800
206414273	TOSOT	TU36-24WADU	TUD36-24AH2ADU		29,000	\$4,060
206414274	TOSOT	TU60-48WADU	TUD60-24AH2ADU		44,000	\$6,160
206414275	TOSOT	TU60-48WADU	TUD48-24AH2ADU		39,500	\$5,530
209843759	TOSOT	TU60-24WADU	TUD60-24AH2ADU		44,000	\$6,160
209843760	TOSOT	TU60-24WADU	TUD48-24AH2ADU		39,500	\$5,530
10062020	TOSOT	TW18HQ3D6DO	TW18HQ3D6DI		15,100	\$2,114
10062021	TOSOT	TW24HQ3D6DO	TW24HQ3D6DI		20,000	\$2,800
204344218	TOSOT	TM18H5O	Heat pump without ducts		17,000	\$2,380
204344219	TOSOT	TM24H5O	Heat pump without ducts		17,900	\$2,506
210485386	TOSOT	TWH12AG25A2DO	TWH12AG25A2DI		10,000	\$1,400
210485389	TOSOT	TWH36QF25B4DO	TWH36QF25B4DI		27,800	\$3,892

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211164239	TOSOT	TM18HX4O	Heat pump without ducts		15,000	\$2,100
211164240	TOSOT	TM24HX4O	Heat pump without ducts		23,600	\$3,304
211164241	TOSOT	TM30HX4O	Heat pump without ducts		27,200	\$3,808
211164242	TOSOT	TM36HX4O	Heat pump without ducts		30,800	\$4,312
211164243	TOSOT	TM42HX4O	Heat pump without ducts		35,600	\$4,984
211164244	TOSOT	TM18HX4O	Heat pump with ducts		15,000	\$2,100
211164245	TOSOT	TM24HX4O	Heat pump with ducts		23,000	\$3,220
211164246	TOSOT	TM30HX4O	Heat pump with ducts		26,800	\$3,752
211164247	TOSOT	TM36HX4O	Heat pump with ducts		30,000	\$4,200
211164248	TOSOT	TM42HX4O	Heat pump with ducts		32,400	\$4,536
211177521	TOSOT	TW12HXP2A1DO	TW12HXP2A1DI		10,000	\$1,400
211177524	TOSOT	TW30HXQ2B2DO	TW30HXQ2B2DI		24,000	\$3,360
211177525	TOSOT	TW36HXQ2B2DO	TW36HXQ2B2DI		27,800	\$3,892
212365400	TOSOT	TW24HXP2A1DO	TM24HSFDI		19,400	\$2,716
10062019	TOSOT	TW12HQ3D6DO	TW12HQ3D6DI		10,300	\$1,442
216768206	TOSOT	TWH30AT19D6DO	TWH30AT19D6DI		18,800	\$2,632
216768205	TOSOT	TWH36AT19D6DO	TWH36AT19D6DI		22,000	\$3,080
216760023	TOSOT	TW12HP32A2DOC	TW12HCL32A1DIC		7,700	\$1,078
216732463	TOSOT	TAVCI7H4R18	TAPEL7H4R18-S		10,200	\$1,428
216732453	TOSOT	TAVCI7H4R12	TAPES7H4R12-S		7,500	\$1,050
216732450	TOSOT	TAVCI7H4R12	TAPEC7H4R12-4WS		7,500	\$1,050
216732449	TOSOT	TAVCI7H4R12	TAPED7H4R12-S		7,500	\$1,050
216732448	TOSOT	TAVCI7H4R24	TAPEL7H4R24-S		16,000	\$2,240
216732446	TOSOT	TAVCI7H4R24	TAPED7H4R24-S		15,600	\$2,184
216723153	TOSOT	TMSCI7H4R48	Combination heat pumps with or without ducts		40,000	\$5,600
216723152	TOSOT	TMSCI7H4R48	Heat pump with ducts		40,000	\$5,600
216723151	TOSOT	TMSCI7H4R48	Heat pump without ducts		40,000	\$5,600
216723150	TOSOT	TMSCI7H4R42	Combination heat pumps with or without ducts		40,000	\$5,600
216723149	TOSOT	TMSCI7H4R36	Combination heat pumps with or without ducts		36,000	\$5,040
216723148	TOSOT	TMSCI7H4R30	Combination heat pumps with or without ducts		27,600	\$3,864
216723147	TOSOT	TMSCI7H4R24	Combination heat pumps with or without ducts		23,000	\$3,220
216723146	TOSOT	TMSCI7H4R42	Heat pump with ducts		40,000	\$5,600
216723145	TOSOT	TMSCI7H4R36	Heat pump with ducts		36,000	\$5,040

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216723144	TOSOT	TMSCI7H4R30	Heat pump with ducts		27,200	\$3,808
216723143	TOSOT	TMSCI7H4R24	Heat pump with ducts		22,000	\$3,080
216723142	TOSOT	TMSCI7H4R18	Combination heat pumps with or without ducts		14,500	\$2,030
216723141	TOSOT	TMSCI7H4R18	Heat pump with ducts		14,000	\$1,960
216723140	TOSOT	TMSCI7H4R42	Heat pump without ducts		40,000	\$5,600
216723139	TOSOT	TMSCI7H4R36	Heat pump without ducts		36,000	\$5,040
216723138	TOSOT	TMSCI7H4R30	Heat pump without ducts		28,000	\$3,920
216723137	TOSOT	TMSCI7H4R24	Heat pump without ducts		23,600	\$3,304
216723136	TOSOT	TMSCI7H4R18	Heat pump without ducts		15,000	\$2,100
216618258	TOSOT	TM48D6MO	Combination heat pumps with or without ducts		40,000	\$5,600
216618257	TOSOT	TM48D6MO	Heat pump with ducts		40,000	\$5,600
216618256	TOSOT	TM48D6MO	Heat pump without ducts		40,000	\$5,600
216573588	TOSOT	SU-COSMO30-230/O	SU-COSMO30-230/I		24,000	\$3,360
216571403	TOSOT	TM42D6MO	Combination heat pumps with or without ducts		40,000	\$5,600
216571402	TOSOT	TM36D6MO	Combination heat pumps with or without ducts		36,000	\$5,040
216571401	TOSOT	TM30D6MO	Combination heat pumps with or without ducts		27,600	\$3,864
216571400	TOSOT	TM24D6MO	Combination heat pumps with or without ducts		23,000	\$3,220
216571399	TOSOT	TM42D6MO	Heat pump with ducts		40,000	\$5,600
216571398	TOSOT	TM36D6MO	Heat pump with ducts		36,000	\$5,040
216571397	TOSOT	TM30D6MO	Heat pump with ducts		27,200	\$3,808
216571396	TOSOT	TM24D6MO	Heat pump with ducts		22,000	\$3,080
216571395	TOSOT	TM18D6MO	Combination heat pumps with or without ducts		15,400	\$2,156
216571394	TOSOT	TM18D6MO	Heat pump with ducts		15,000	\$2,100
216571393	TOSOT	TM42D6MO	Heat pump without ducts		40,000	\$5,600
216571392	TOSOT	TM36D6MO	Heat pump without ducts		36,000	\$5,040
216571391	TOSOT	TM30D6MO	Heat pump without ducts		28,000	\$3,920
216571390	TOSOT	TM24D6MO	Heat pump without ducts		23,600	\$3,304
216571389	TOSOT	TM18D6MO	Heat pump without ducts		16,000	\$2,240
216426824	TOSOT	TWH18AV29D6DO	TWH18AV29D6DI		15,500	\$2,170
216426823	TOSOT	TWH24AV29D6DO	TWH24AV29D6DI		20,000	\$2,800
216030814	TOSOT	TW24HAY32A1DOC	TW24HAY32A1DIC		20,000	\$2,800
216030813	TOSOT	TW24HC32A5DOC	TW24HC32A5DIC		19,200	\$2,688

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216030810	TOSOT	TW18HAY32A1DOC	TW18HAY32A1DIC		15,500	\$2,170
216030806	TOSOT	TW18HP32A2DOC	TW18HP32A2DIC		14,700	\$2,058
216030805	TOSOT	TW12HAY32A1DOC	TW12HAY32A1DIC		10,300	\$1,442
216030804	TOSOT	TWH12AG25D6DO	TWH12AG25D6DI		10,000	\$1,400
216030802	TOSOT	TW12HC32A5DOC	TW12HC32A5DIC		9,700	\$1,358
216030800	TOSOT	TW12HC32A5AOC	TW12HC32A5AIC		9,700	\$1,358
216030798	TOSOT	TW12HP32A2DOC	TW12HP32A2DIC		10,000	\$1,400
215708467	TOSOT	MZ-COSMO36/O	Combination heat pumps with or without ducts		36,000	\$5,040
215708466	TOSOT	MZ-COSMO30/O	Combination heat pumps with or without ducts		27,600	\$3,864
215708465	TOSOT	MZ-COSMO24/O	Combination heat pumps with or without ducts		23,000	\$3,220
215708464	TOSOT	MZ-COSMO18/O	Combination heat pumps with or without ducts		15,400	\$2,156
215708463	TOSOT	MZ-COSMO36/O	Heat pump with ducts		36,000	\$5,040
215708462	TOSOT	MZ-COSMO30/O	Heat pump with ducts		27,200	\$3,808
215708461	TOSOT	MZ-COSMO24/O	Heat pump with ducts		22,000	\$3,080
215708460	TOSOT	MZ-COSMO18/O	Heat pump with ducts		15,000	\$2,100
215708459	TOSOT	MZ-COSMO36/O	Heat pump without ducts		36,000	\$5,040
215708458	TOSOT	MZ-COSMO30/O	Heat pump without ducts		28,000	\$3,920
215708457	TOSOT	MZ-COSMO24/O	Heat pump without ducts		23,600	\$3,304
215708456	TOSOT	MZ-COSMO18/O	Heat pump without ducts		16,000	\$2,240
215405712	TOSOT	TW12HP32A2DO	TW12HP32A2DI		10,000	\$1,400
215405584	TOSOT	TW24HAY32A1DO	TW24HAY32A1DI		20,000	\$2,800
215399271	TOSOT	TW12HP32A2DO	TW12HCL32A5DI		10,000	\$1,400
215399261	TOSOT	TM42H32MO	Combination heat pumps with or without ducts		40,000	\$5,600
215399260	TOSOT	TM36H32MO	Combination heat pumps with or without ducts		36,000	\$5,040
215399259	TOSOT	TM30H32MO	Combination heat pumps with or without ducts		27,600	\$3,864
215399258	TOSOT	TM24H32MO	Combination heat pumps with or without ducts		23,000	\$3,220
215399257	TOSOT	TM42H32MO	Heat pump with ducts		40,000	\$5,600
215399256	TOSOT	TM36H32MO	Heat pump with ducts		36,000	\$5,040
215399255	TOSOT	TM30H32MO	Heat pump with ducts		27,200	\$3,808
215399254	TOSOT	TM24H32MO	Heat pump with ducts		22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215399253	TOSOT	TM18H32MO	Combination heat pumps with or without ducts		15,400	\$2,156
215399252	TOSOT	TM18H32MO	Heat pump with ducts		15,000	\$2,100
215399251	TOSOT	TM42H32MO	Heat pump without ducts		40,000	\$5,600
215399250	TOSOT	TM36H32MO	Heat pump without ducts		36,000	\$5,040
215399249	TOSOT	TM30H32MO	Heat pump without ducts		28,000	\$3,920
215399248	TOSOT	TM24H32MO	Heat pump without ducts		23,600	\$3,304
215399247	TOSOT	TM18H32MO	Heat pump without ducts		16,000	\$2,240
214728902	TOSOT	GWH24QEXF-D3DND4D/O	GWH24AFEXF-D3DN***/I		20,000	\$2,800
214389463	TOSOT	TM18HPO	Heat pump without ducts		15,200	\$2,128
212365397	TOSOT	TW18HXP2A1DO	TM18HSFDI		14,600	\$2,044
211727025	TOSOT	TM42HMO	Heat pump without ducts		35,600	\$4,984
211727024	TOSOT	TM36HMO	Heat pump without ducts		30,800	\$4,312
211727023	TOSOT	TM30HMO	Heat pump without ducts		27,200	\$3,808
211727022	TOSOT	TM24HMO	Heat pump without ducts		23,600	\$3,304
211727021	TOSOT	TM18HMO	Heat pump without ducts		15,000	\$2,100
211164221	TOSOT	TW12HXCA5DO	TW12HXCA5DI		9,700	\$1,358
210485379	TOSOT	TWH12ATCXB-D3DNA3CO	TWH12ATCXB-D3DNA3CI		9,700	\$1,358
216770146	TOSOT	TU60W-FDU	TCAC60H/NXA		35,200	\$4,928
216770145	TOSOT	TU60W-FDU	TCAC48H/NXA		31,200	\$4,368
216770144	TOSOT	TU36W-FDU	TCAC36F/NXA		22,000	\$3,080
216770143	TOSOT	TU36W-FDU	TCAC24F/NXA		15,000	\$2,100
216770142	TOSOT	TU60W-EDU	TCAC60H/NHA		35,200	\$4,928
216770141	TOSOT	TU60W-EDU	TCAC48H/NHA		31,200	\$4,368
216770140	TOSOT	TU36W-EDU	TCAC36F/NHA		22,000	\$3,080
216770139	TOSOT	TU36W-EDU	TCAC24F/NHA		15,000	\$2,100
216626004	TOSOT	TU60W-GDU	TUD60AH2-GDU		43,000	\$6,020
216626003	TOSOT	TU60W-GDU	TUD48AH2-GDU		38,500	\$5,390
215390439	TOSOT	TU60W-EDU	TUD60AH2-EDU		45,000	\$6,300
215390438	TOSOT	TU48W-EDU	TUD48AH2-EDU		39,500	\$5,530
215390437	TOSOT	TU36W-EDU	TUD36AH2-EDU		28,200	\$3,948
215390436	TOSOT	TU24W-EDU	TUD24AH2-EDU		20,600	\$2,884
215351154	TOSOT	TU60-R32WEDU	TUD60-R32AHEDU		45,000	\$6,300
215351153	TOSOT	TU36-R32WEDU	TUD36-R32AHEDU		28,200	\$3,948
215351152	TOSOT	TU60-32WEDU	TUD60-32AH2EDU		45,000	\$6,300
215351151	TOSOT	TU48-32WEDU	TUD48-32AH2EDU		39,500	\$5,530

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215351150	TOSOT	TU36-32WEDU	TUD36-32AH2EDU		28,200	\$3,948
215351149	TOSOT	TU24-32WEDU	TUD24-32AH2EDU		20,600	\$2,884
214731127	TOSOT	HP-A60/O	HP-A60/I		44,000	\$6,160
214731126	TOSOT	HP-A36/O	HP-A36/I		29,000	\$4,060
214333172	TOSOT	TUD24W/A-D(U)	TCAT24F/NAA		20,000	\$2,800
212361368	TOSOT	TU60-48WADU	TCAT60H/NAA		44,500	\$6,230
212361367	TOSOT	TU60-48WADU	TCAT48H/NAA		39,000	\$5,460
212361366	TOSOT	TU36-24WADU	TCAT36F/NAA		23,200	\$3,248
212361365	TOSOT	TU36-24WADU	TCAT24F/NAA		19,600	\$2,744
212925897	TOSOT	TU36-24WADU	D(A,C,E)25B34+TDR		15,000	\$2,100
212925887	TOSOT	TU36-24WADU	D(A,C,E)24C34+TDR		15,000	\$2,100
212925886	TOSOT	TU36-24WADU	D(A,C,E)24A44+TDR		15,000	\$2,100
212925894	TOSOT	TU36-24WADU	C(A,C,D,E)24B34+TDR		15,000	\$2,100
212925888	TOSOT	TU36-24WADU	D(A,C,E)24D34+TDR		15,000	\$2,100
211174360	TOSOT	TM42HX4O	Combination heat pumps with or without ducts		34,000	\$4,760
211174359	TOSOT	TM36HX4O	Combination heat pumps with or without ducts		30,400	\$4,256
211174358	TOSOT	TM30HX4O	Combination heat pumps with or without ducts		27,000	\$3,780
211174357	TOSOT	TM24HX4O	Combination heat pumps with or without ducts		23,200	\$3,248
211174356	TOSOT	TM18HX4O	Combination heat pumps with or without ducts		14,300	\$2,002
213386671	TOSOT	TK-H02TCNAA-TU			23,400	\$3,276
213386669	TOSOT	TK-H04TCNAA-TU			36,000	\$5,040
213307926	TOSOT	TK-H05TCNAA-TU			37,000	\$5,180
9128593	TOSOT	TMVRF-36KUH	Heat pump with ducts		29,400	\$4,116
206322338	TOSOT	TU60-48WADU	TU48-60AADU		32,800	\$4,592
204743191	TOSOT	TU36-24WADU	TU36-24AADU		24,400	\$3,416
205756439	TOSOT	TU36-24WADU	TU24-36AADU		16,300	\$2,282
205984662	TOSOT	TU60-24WADU	TU48-24AADU		33,000	\$4,620
205724740	TOSOT	TU60-24WADU	TU60-24AADU		38,000	\$5,320
205724741	TOSOT	TU60-48WADU	TU60-48AADU		37,200	\$5,208
216767267	TRANE	5TWX7060A1	5TXCD010AS3	S9X2D120U5PSB	33,600	\$4,704
216767268	TRANE	5TWX7060A1	5TXCD010AS3	S9X2C100U5PSB	34,400	\$4,816
216767269	TRANE	5TWX7060A1	5TXCD010AS3	S9X2C080U5PSB	34,200	\$4,788
216767262	TRANE	5TWX7060A1	5TXCD010AS3	S9X1D120U5PSB	33,600	\$4,704

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216767261	TRANE	5TWX7060A1	5TXCD010AS3	S9X1C100U5PSB	34,400	\$4,816
216767259	TRANE	5TWX7060A1	5TXCD010AS3	S9X1C080U5PSB	34,200	\$4,788
216764538	TRANE	5TWX7060A1	5TXCD010AS3	S9V2D120U5VSB	34,000	\$4,760
216764535	TRANE	5TWX7060A1	5TXCD010AS3	S9V2D120U5PSC	34,000	\$4,760
216767264	TRANE	5TWX7060A1	5TXCD010AS3	S9V2C080U5VSB	34,000	\$4,760
216764536	TRANE	5TWX7060A1	5TXCD010AS3	S9V2C080U5PSC	34,000	\$4,760
216765121	TRANE	5TWX7060A1	5TXCD010AS3	S8X2D120M5PTC	33,800	\$4,732
216765115	TRANE	5TWX7060A1	5TXCD010AS3	S8X2D120M5PSC	33,800	\$4,732
216765120	TRANE	5TWX7060A1	5TXCD010AS3	S8X2C100M5PTC	34,200	\$4,788
216765117	TRANE	5TWX7060A1	5TXCD010AS3	S8X2C100M5PSC	34,200	\$4,788
216765123	TRANE	5TWX7060A1	5TXCD010AS3	S8X2C080M5PTC	34,000	\$4,760
216765116	TRANE	5TWX7060A1	5TXCD010AS3	S8X2C080M5PSC	34,000	\$4,760
216765119	TRANE	5TWX7060A1	5TXCD010AS3	S8X1D120M5PTC	33,800	\$4,732
216764537	TRANE	5TWX7060A1	5TXCD010AS3	S8X1D120M5PSC	33,800	\$4,732
216765122	TRANE	5TWX7060A1	5TXCD010AS3	S8X1C100M5PTC	34,200	\$4,788
216764534	TRANE	5TWX7060A1	5TXCD010AS3	S8X1C100M5PSC	34,200	\$4,788
216765118	TRANE	5TWX7060A1	5TXCD010AS3	S8X1C080M5PTC	34,000	\$4,760
216764533	TRANE	5TWX7060A1	5TXCD010AS3	S8X1C080M5PSC	34,000	\$4,760
216767260	TRANE	5TWX7060A1	5TXCD010AS3	S8V2D120M5PDB	33,800	\$4,732
216767263	TRANE	5TWX7060A1	5TXCD010AS3	S8V2D120M5PCB	33,800	\$4,732
216767272	TRANE	5TWX7060A1	5TXCD010AS3	S8V2C100M5PDB	34,000	\$4,760
216767271	TRANE	5TWX7060A1	5TXCD010AS3	S8V2C100M5PCB	34,000	\$4,760
216767258	TRANE	5TWX7060A1	5TXCD010AS3	S8V2C080M5PDB	34,000	\$4,760
216767265	TRANE	5TWX7060A1	5TXCD010AS3	S8V2C080M5PCB	34,000	\$4,760
216764532	TRANE	5TWX7060A1	5TXCD010AS3	L9X1C100U5VSA	34,400	\$4,816
216764531	TRANE	5TWX7060A1	5TXCD010AS3	L8V1C100U5VSB	34,000	\$4,760
216767256	TRANE	5TWX7060A1	5TXCD008AS3	S9X2D120U5PSB	34,000	\$4,760
216767242	TRANE	5TWX7060A1	5TXCD008AS3	S9X2C100U5PSB	34,600	\$4,844
216767257	TRANE	5TWX7060A1	5TXCD008AS3	S9X2C080U5PSB	34,400	\$4,816
216767246	TRANE	5TWX7060A1	5TXCD008AS3	S9X1D120U5PSB	34,000	\$4,760
216767247	TRANE	5TWX7060A1	5TXCD008AS3	S9X1C100U5PSB	34,600	\$4,844
216767248	TRANE	5TWX7060A1	5TXCD008AS3	S9X1C080U5PSB	34,400	\$4,816
216764528	TRANE	5TWX7060A1	5TXCD008AS3	S9V2D120U5VSB	34,200	\$4,788
216764529	TRANE	5TWX7060A1	5TXCD008AS3	S9V2D120U5PSC	34,200	\$4,788
216767249	TRANE	5TWX7060A1	5TXCD008AS3	S9V2C100U5VSB	34,800	\$4,872
216764530	TRANE	5TWX7060A1	5TXCD008AS3	S9V2C100U5PSC	34,800	\$4,872
216767250	TRANE	5TWX7060A1	5TXCD008AS3	S9V2C080U5VSB	34,200	\$4,788
216764527	TRANE	5TWX7060A1	5TXCD008AS3	S9V2C080U5PSC	34,200	\$4,788

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216765112	TRANE	5TWX7060A1	5TXCD008AS3	S8X2D120M5PSC	34,400	\$4,816
216765110	TRANE	5TWX7060A1	5TXCD008AS3	S8X2C100M5PTC	34,400	\$4,816
216765113	TRANE	5TWX7060A1	5TXCD008AS3	S8X2C100M5PSC	34,400	\$4,816
216765111	TRANE	5TWX7060A1	5TXCD008AS3	S8X2C080M5PTC	34,400	\$4,816
216765114	TRANE	5TWX7060A1	5TXCD008AS3	S8X2C080M5PSC	34,400	\$4,816
216765107	TRANE	5TWX7060A1	5TXCD008AS3	S8X1D120M5PTC	34,400	\$4,816
216764522	TRANE	5TWX7060A1	5TXCD008AS3	S8X1D120M5PSC	34,400	\$4,816
216765108	TRANE	5TWX7060A1	5TXCD008AS3	S8X1C100M5PTC	34,400	\$4,816
216764521	TRANE	5TWX7060A1	5TXCD008AS3	S8X1C100M5PSC	34,400	\$4,816
216765109	TRANE	5TWX7060A1	5TXCD008AS3	S8X1C080M5PTC	34,400	\$4,816
216764520	TRANE	5TWX7060A1	5TXCD008AS3	S8X1C080M5PSC	34,400	\$4,816
216767245	TRANE	5TWX7060A1	5TXCD008AS3	S8V2D120M5PDB	34,000	\$4,760
216767251	TRANE	5TWX7060A1	5TXCD008AS3	S8V2D120M5PCB	34,000	\$4,760
216767244	TRANE	5TWX7060A1	5TXCD008AS3	S8V2C100M5PDB	34,400	\$4,816
216767252	TRANE	5TWX7060A1	5TXCD008AS3	S8V2C100M5PCB	34,400	\$4,816
216767243	TRANE	5TWX7060A1	5TXCD008AS3	S8V2C080M5PDB	34,400	\$4,816
216767253	TRANE	5TWX7060A1	5TXCD008AS3	S8V2C080M5PCB	34,400	\$4,816
216764523	TRANE	5TWX7060A1	5TXCD008AS3	N/A	34,800	\$4,872
216764524	TRANE	5TWX7060A1	5TXCD008AS3	L9X1C100U5VSA	34,800	\$4,872
216764525	TRANE	5TWX7060A1	5TXCD008AS3	L8V1C100U5VSB	34,200	\$4,788
216764526	TRANE	5TWX7060A1	5TXCD008AS3	*UHMD120CCV5	34,600	\$4,844
216764519	TRANE	5TWX7060A1	5TEMCD07AV51+TD	N/A	33,600	\$4,704
216764518	TRANE	5TWX7060A1	5TEMCD06AV41+TD	N/A	33,600	\$4,704
216764517	TRANE	5TWX7060A1	5TEM6D07AV51+TD	N/A	33,400	\$4,676
216764516	TRANE	5TWX7060A1	5TEM6D06AV41+TD	N/A	33,400	\$4,676
216770122	TRANE	5TWX7060A1	5TAMXD07AV51	N/A	33,600	\$4,704
216770121	TRANE	5TWX7060A1	5TAMXD06AV41	N/A	34,200	\$4,788
216770120	TRANE	5TWX7060A1	5TAM5D07AC51	N/A	33,400	\$4,676
216770119	TRANE	5TWX7060A1	5TAM5D06AC41	N/A	33,600	\$4,704
216767232	TRANE	5TWX7060A1	5PX*DD10AS3	S9X2D120D5PSB	33,800	\$4,732
216767233	TRANE	5TWX7060A1	5PX*DD10AS3	S9X2C100D5PSB	34,200	\$4,788
216767234	TRANE	5TWX7060A1	5PX*DD10AS3	S9X1D120D5PSB	33,800	\$4,732
216767235	TRANE	5TWX7060A1	5PX*DD10AS3	S9X1C100D5PSB	34,200	\$4,788
216767236	TRANE	5TWX7060A1	5PX*DD10AS3	S9V2D120D5VSB	33,800	\$4,732
216764515	TRANE	5TWX7060A1	5PX*DD10AS3	S9V2D120D5PSC	33,800	\$4,732
216765101	TRANE	5TWX7060A1	5PX*DD10AS3	S8X2D120M5PTC	34,000	\$4,760
216765106	TRANE	5TWX7060A1	5PX*DD10AS3	S8X2C100M5PTC	34,000	\$4,760
216765104	TRANE	5TWX7060A1	5PX*DD10AS3	S8X2C100M5PSC	34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216765103	TRANE	5TWX7060A1	5PX*DD10AS3	S8X2C080M5PTC	34,000	\$4,760
216765105	TRANE	5TWX7060A1	5PX*DD10AS3	S8X2C080M5PSC	34,000	\$4,760
216765100	TRANE	5TWX7060A1	5PX*DD10AS3	S8X1D120M5PTC	34,000	\$4,760
216764514	TRANE	5TWX7060A1	5PX*DD10AS3	S8X1D120M5PSC	34,000	\$4,760
216765099	TRANE	5TWX7060A1	5PX*DD10AS3	S8X1C100M5PTC	34,000	\$4,760
216764510	TRANE	5TWX7060A1	5PX*DD10AS3	S8X1C100M5PSC	34,000	\$4,760
216765102	TRANE	5TWX7060A1	5PX*DD10AS3	S8X1C080M5PTC	34,000	\$4,760
216764511	TRANE	5TWX7060A1	5PX*DD10AS3	S8X1C080M5PSC	34,000	\$4,760
216767237	TRANE	5TWX7060A1	5PX*DD10AS3	S8V2D120M5PCB	33,600	\$4,704
216767231	TRANE	5TWX7060A1	5PX*DD10AS3	S8V2C100M5PDB	34,000	\$4,760
216767238	TRANE	5TWX7060A1	5PX*DD10AS3	S8V2C100M5PCB	34,000	\$4,760
216767230	TRANE	5TWX7060A1	5PX*DD10AS3	S8V2C080M5PDB	34,000	\$4,760
216767239	TRANE	5TWX7060A1	5PX*DD10AS3	S8V2C080M5PCB	34,000	\$4,760
216764513	TRANE	5TWX7060A1	5PX*DD10AS3	N/A	34,200	\$4,788
216764512	TRANE	5TWX7060A1	5PX*DD10AS3	*DHMD120CCV5	34,000	\$4,760
216767228	TRANE	5TWX7060A1	5PX*D010AS3	S9X2D120U5PSB	33,600	\$4,704
216767227	TRANE	5TWX7060A1	5PX*D010AS3	S9X2C100U5PSB	34,400	\$4,816
216767226	TRANE	5TWX7060A1	5PX*D010AS3	S9X2C080U5PSB	34,200	\$4,788
216767221	TRANE	5TWX7060A1	5PX*D010AS3	S9X1D120U5PSB	33,600	\$4,704
216767220	TRANE	5TWX7060A1	5PX*D010AS3	S9X1C100U5PSB	34,400	\$4,816
216767219	TRANE	5TWX7060A1	5PX*D010AS3	S9X1C080U5PSB	34,200	\$4,788
216764507	TRANE	5TWX7060A1	5PX*D010AS3	S9V2D120U5VSB	33,800	\$4,732
216764505	TRANE	5TWX7060A1	5PX*D010AS3	S9V2D120U5PSC	33,800	\$4,732
216767218	TRANE	5TWX7060A1	5PX*D010AS3	S9V2C080U5VSB	33,800	\$4,732
216764506	TRANE	5TWX7060A1	5PX*D010AS3	S9V2C080U5PSC	33,800	\$4,732
216765091	TRANE	5TWX7060A1	5PX*D010AS3	S8X2D120M5PTC	34,000	\$4,760
216765094	TRANE	5TWX7060A1	5PX*D010AS3	S8X2D120M5PSC	34,000	\$4,760
216765095	TRANE	5TWX7060A1	5PX*D010AS3	S8X2C100M5PTC	34,000	\$4,760
216765097	TRANE	5TWX7060A1	5PX*D010AS3	S8X2C100M5PSC	34,000	\$4,760
216765096	TRANE	5TWX7060A1	5PX*D010AS3	S8X2C080M5PTC	34,000	\$4,760
216765098	TRANE	5TWX7060A1	5PX*D010AS3	S8X2C080M5PSC	34,000	\$4,760
216765090	TRANE	5TWX7060A1	5PX*D010AS3	S8X1D120M5PTC	34,000	\$4,760
216764508	TRANE	5TWX7060A1	5PX*D010AS3	S8X1D120M5PSC	34,000	\$4,760
216765092	TRANE	5TWX7060A1	5PX*D010AS3	S8X1C100M5PTC	34,000	\$4,760
216764501	TRANE	5TWX7060A1	5PX*D010AS3	S8X1C100M5PSC	34,000	\$4,760
216765093	TRANE	5TWX7060A1	5PX*D010AS3	S8X1C080M5PTC	34,000	\$4,760
216764502	TRANE	5TWX7060A1	5PX*D010AS3	S8X1C080M5PSC	34,000	\$4,760
216767216	TRANE	5TWX7060A1	5PX*D010AS3	S8V2D120M5PDB	33,800	\$4,732

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216767217	TRANE	5TWX7060A1	5PX*D010AS3	S8V2D120M5PCB	33,800	\$4,732
216767215	TRANE	5TWX7060A1	5PX*D010AS3	S8V2C100M5PDB	34,000	\$4,760
216767225	TRANE	5TWX7060A1	5PX*D010AS3	S8V2C100M5PCB	34,000	\$4,760
216767229	TRANE	5TWX7060A1	5PX*D010AS3	S8V2C080M5PDB	34,000	\$4,760
216767224	TRANE	5TWX7060A1	5PX*D010AS3	S8V2C080M5PCB	34,000	\$4,760
216764503	TRANE	5TWX7060A1	5PX*D010AS3	N/A	34,400	\$4,816
216764504	TRANE	5TWX7060A1	5PX*D010AS3	L9X1C100U5VSA	34,400	\$4,816
216764509	TRANE	5TWX7060A1	5PX*D010AS3	L8V1C100U5VSB	33,800	\$4,732
216767212	TRANE	5TWX7060A1	5PX*D008AS3	S9X2D120U5PSB	34,000	\$4,760
216767211	TRANE	5TWX7060A1	5PX*D008AS3	S9X2C100U5PSB	34,600	\$4,844
216767210	TRANE	5TWX7060A1	5PX*D008AS3	S9X2C080U5PSB	34,400	\$4,816
216767208	TRANE	5TWX7060A1	5PX*D008AS3	S9X1D120U5PSB	34,000	\$4,760
216767207	TRANE	5TWX7060A1	5PX*D008AS3	S9X1C100U5PSB	34,600	\$4,844
216767206	TRANE	5TWX7060A1	5PX*D008AS3	S9X1C080U5PSB	34,400	\$4,816
216764492	TRANE	5TWX7060A1	5PX*D008AS3	S9V2D120U5VSB	34,200	\$4,788
216764493	TRANE	5TWX7060A1	5PX*D008AS3	S9V2D120U5PSC	34,200	\$4,788
216764494	TRANE	5TWX7060A1	5PX*D008AS3	S9V2C100U5PSC	34,800	\$4,872
216767205	TRANE	5TWX7060A1	5PX*D008AS3	S9V2C080U5VSB	34,200	\$4,788
216764495	TRANE	5TWX7060A1	5PX*D008AS3	S9V2C080U5PSC	34,200	\$4,788
216765089	TRANE	5TWX7060A1	5PX*D008AS3	S8X2D120M5PTC	34,400	\$4,816
216765085	TRANE	5TWX7060A1	5PX*D008AS3	S8X2D120M5PSC	34,400	\$4,816
216765086	TRANE	5TWX7060A1	5PX*D008AS3	S8X2C100M5PTC	34,400	\$4,816
216765081	TRANE	5TWX7060A1	5PX*D008AS3	S8X2C100M5PSC	34,400	\$4,816
216765087	TRANE	5TWX7060A1	5PX*D008AS3	S8X2C080M5PTC	34,400	\$4,816
216765082	TRANE	5TWX7060A1	5PX*D008AS3	S8X2C080M5PSC	34,400	\$4,816
216765088	TRANE	5TWX7060A1	5PX*D008AS3	S8X1D120M5PTC	34,400	\$4,816
216764496	TRANE	5TWX7060A1	5PX*D008AS3	S8X1D120M5PSC	34,400	\$4,816
216765083	TRANE	5TWX7060A1	5PX*D008AS3	S8X1C100M5PTC	34,400	\$4,816
216764497	TRANE	5TWX7060A1	5PX*D008AS3	S8X1C100M5PSC	34,400	\$4,816
216765084	TRANE	5TWX7060A1	5PX*D008AS3	S8X1C080M5PTC	34,400	\$4,816
216764498	TRANE	5TWX7060A1	5PX*D008AS3	S8X1C080M5PSC	34,400	\$4,816
216767201	TRANE	5TWX7060A1	5PX*D008AS3	S8V2D120M5PDB	34,000	\$4,760
216767204	TRANE	5TWX7060A1	5PX*D008AS3	S8V2D120M5PCB	34,000	\$4,760
216767213	TRANE	5TWX7060A1	5PX*D008AS3	S8V2C100M5PDB	34,400	\$4,816
216767203	TRANE	5TWX7060A1	5PX*D008AS3	S8V2C100M5PCB	34,400	\$4,816
216767209	TRANE	5TWX7060A1	5PX*D008AS3	S8V2C080M5PDB	34,400	\$4,816
216767202	TRANE	5TWX7060A1	5PX*D008AS3	S8V2C080M5PCB	34,400	\$4,816
216764499	TRANE	5TWX7060A1	5PX*D008AS3	N/A	34,800	\$4,872

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764490	TRANE	5TWX7060A1	5PX*D008AS3	L9X1C100U5VSA	34,800	\$4,872
216764491	TRANE	5TWX7060A1	5PX*D008AS3	L8V1C100U5VSB	34,200	\$4,788
216764500	TRANE	5TWX7060A1	5PX*D008AS3	*UHMD120CCV5	34,600	\$4,844
216767177	TRANE	5TWX7048A1	5TXCD008AS3	S9X2C080U5PSB	30,200	\$4,228
216767182	TRANE	5TWX7048A1	5TXCD008AS3	S9X1C080U5PSB	30,200	\$4,228
216767165	TRANE	5TWX7048A1	5TXCC009AS3	S9V2C100U5VSB	29,400	\$4,116
216764467	TRANE	5TWX7048A1	5TXCC009AS3	S9V2C100U5PSC	29,400	\$4,116
216764464	TRANE	5TWX7048A1	5TXCC009AS3	L9X1C100U5VSA	30,200	\$4,228
216764454	TRANE	5TWX7048A1	5PX*D010AS3	N/A	29,800	\$4,172
216764445	TRANE	5TWX7048A1	5PX*D010AS3	L9X1C100U5VSA	30,200	\$4,228
216767121	TRANE	5TWX7048A1	5PX*D008AS3	S9X2C080U5PSB	30,200	\$4,228
216767127	TRANE	5TWX7048A1	5PX*D008AS3	S9X1C080U5PSB	30,200	\$4,228
216767109	TRANE	5TWX7048A1	5PX*C009AS3	S9V2C100U5VSB	29,400	\$4,116
216764428	TRANE	5TWX7048A1	5PX*C009AS3	S9V2C100U5PSC	29,400	\$4,116
216764422	TRANE	5TWX7048A1	5PX*C009AS3	L9X1C100U5VSA	30,200	\$4,228
216767099	TRANE	5TWX7036A1	5TXCD010AS3	S9X2D120U5PSB	21,200	\$2,968
216767097	TRANE	5TWX7036A1	5TXCD010AS3	S9X1D120U5PSB	21,200	\$2,968
216764418	TRANE	5TWX7036A1	5TXCD010AS3	S9V2D120U5VSB	21,200	\$2,968
216764420	TRANE	5TWX7036A1	5TXCD010AS3	S9V2D120U5PSC	21,200	\$2,968
216767098	TRANE	5TWX7036A1	5TXCD010AS3	S8V2D120M5PDB	21,200	\$2,968
216764419	TRANE	5TWX7036A1	5TXCD010AS3	*UHMD120CCV5	21,200	\$2,968
216767092	TRANE	5TWX7036A1	5TXCD008AS3	S9X2D120U5PSB	21,200	\$2,968
216767091	TRANE	5TWX7036A1	5TXCD008AS3	S9X2D120D5PSB	21,000	\$2,940
216767094	TRANE	5TWX7036A1	5TXCD008AS3	S9X1D120U5PSB	21,200	\$2,968
216767093	TRANE	5TWX7036A1	5TXCD008AS3	S9X1D120D5PSB	21,000	\$2,940
216764413	TRANE	5TWX7036A1	5TXCD008AS3	S9V2D120U5VSB	21,400	\$2,996
216764412	TRANE	5TWX7036A1	5TXCD008AS3	S9V2D120U5PSC	21,400	\$2,996
216765025	TRANE	5TWX7036A1	5TXCD008AS3	S8X2D120M5PTC	21,000	\$2,940
216765026	TRANE	5TWX7036A1	5TXCD008AS3	S8X2D120M5PSC	21,000	\$2,940
216765027	TRANE	5TWX7036A1	5TXCD008AS3	S8X1D120M5PTC	21,000	\$2,940
216764414	TRANE	5TWX7036A1	5TXCD008AS3	S8X1D120M5PSC	21,000	\$2,940
216767096	TRANE	5TWX7036A1	5TXCD008AS3	S8V2D120M5PDB	21,400	\$2,996
216767095	TRANE	5TWX7036A1	5TXCD008AS3	S8V2D120M5PCB	21,400	\$2,996
216764416	TRANE	5TWX7036A1	5TXCD008AS3	N/A	22,000	\$3,080
216764415	TRANE	5TWX7036A1	5TXCD008AS3	*UHMD120CCV5	21,200	\$2,968
216764417	TRANE	5TWX7036A1	5TXCD008AS3	*DHMD120CCV5	21,000	\$2,940
216767082	TRANE	5TWX7036A1	5TXCC009AS3	S9X2C100U5PSB	21,200	\$2,968
216767083	TRANE	5TWX7036A1	5TXCC009AS3	S9X2C080U5PSB	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216767086	TRANE	5TWX7036A1	5TXCC009AS3	S9X1C100U5PSB	21,200	\$2,968
216767090	TRANE	5TWX7036A1	5TXCC009AS3	S9X1C080U5PSB	21,400	\$2,996
216767080	TRANE	5TWX7036A1	5TXCC009AS3	S9V2C100U5VSB	21,000	\$2,940
216764407	TRANE	5TWX7036A1	5TXCC009AS3	S9V2C100U5PSC	21,200	\$2,968
216764408	TRANE	5TWX7036A1	5TXCC009AS3	S9V2C100U4VSB	21,200	\$2,968
216767081	TRANE	5TWX7036A1	5TXCC009AS3	S9V2C080U5VSB	21,200	\$2,968
216764409	TRANE	5TWX7036A1	5TXCC009AS3	S9V2C080U5PSC	21,200	\$2,968
216770115	TRANE	5TWX7036A1	5TXCC009AS3	S8X2C100M5PTC	21,400	\$2,996
216770114	TRANE	5TWX7036A1	5TXCC009AS3	S8X2C100M5PSC	21,400	\$2,996
216765023	TRANE	5TWX7036A1	5TXCC009AS3	S8X2C080M5PTC	21,200	\$2,968
216765022	TRANE	5TWX7036A1	5TXCC009AS3	S8X2C080M5PSC	21,200	\$2,968
216770111	TRANE	5TWX7036A1	5TXCC009AS3	S8X1C100M5PTC	21,400	\$2,996
216770112	TRANE	5TWX7036A1	5TXCC009AS3	S8X1C100M5PSC	21,400	\$2,996
216765024	TRANE	5TWX7036A1	5TXCC009AS3	S8X1C080M5PTC	21,200	\$2,968
216764410	TRANE	5TWX7036A1	5TXCC009AS3	S8X1C080M5PSC	21,200	\$2,968
216767085	TRANE	5TWX7036A1	5TXCC009AS3	S8V2C100M5PDB	21,200	\$2,968
216767089	TRANE	5TWX7036A1	5TXCC009AS3	S8V2C100M5PCB	21,200	\$2,968
216767084	TRANE	5TWX7036A1	5TXCC009AS3	S8V2C080M5PDB	21,400	\$2,996
216767088	TRANE	5TWX7036A1	5TXCC009AS3	S8V2C080M5PCB	21,400	\$2,996
216764411	TRANE	5TWX7036A1	5TXCC009AS3	N/A	21,600	\$3,024
216770113	TRANE	5TWX7036A1	5TXCC009AS3	L9X1C100U5VSA	21,200	\$2,968
216764406	TRANE	5TWX7036A1	5TXCC009AS3	L8V1C100U5VSB	21,200	\$2,968
216764405	TRANE	5TWX7036A1	5TXCC009AS3	*UHMC100CCV4	21,000	\$2,940
216767078	TRANE	5TWX7036A1	5TXCC007AS3	S9X2C100U5PSB	21,400	\$2,996
216767079	TRANE	5TWX7036A1	5TXCC007AS3	S9X2C100D5PSB	21,000	\$2,940
216767077	TRANE	5TWX7036A1	5TXCC007AS3	S9X2C080U5PSB	21,600	\$3,024
216767072	TRANE	5TWX7036A1	5TXCC007AS3	S9X1C100U5PSB	21,400	\$2,996
216767074	TRANE	5TWX7036A1	5TXCC007AS3	S9X1C100D5PSB	21,000	\$2,940
216767071	TRANE	5TWX7036A1	5TXCC007AS3	S9X1C080U5PSB	21,600	\$3,024
216767070	TRANE	5TWX7036A1	5TXCC007AS3	S9V2C100U5VSB	21,400	\$2,996
216764401	TRANE	5TWX7036A1	5TXCC007AS3	S9V2C100U5PSC	21,400	\$2,996
216764400	TRANE	5TWX7036A1	5TXCC007AS3	S9V2C100U4VSB	21,400	\$2,996
216767073	TRANE	5TWX7036A1	5TXCC007AS3	S9V2C100D5VSB	21,000	\$2,940
216764398	TRANE	5TWX7036A1	5TXCC007AS3	S9V2C100D5PSC	21,000	\$2,940
216764403	TRANE	5TWX7036A1	5TXCC007AS3	S9V2C100D4VSB	21,000	\$2,940
216767069	TRANE	5TWX7036A1	5TXCC007AS3	S9V2C080U5VSB	21,400	\$2,996
216764399	TRANE	5TWX7036A1	5TXCC007AS3	S9V2C080U5PSC	21,400	\$2,996
216765017	TRANE	5TWX7036A1	5TXCC007AS3	S8X2C100M5PTC	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216765016	TRANE	5TWX7036A1	5TXCC007AS3	S8X2C100M5PSC	21,200	\$2,968
216765018	TRANE	5TWX7036A1	5TXCC007AS3	S8X2C080M5PTC	21,400	\$2,996
216765021	TRANE	5TWX7036A1	5TXCC007AS3	S8X2C080M5PSC	21,400	\$2,996
216765020	TRANE	5TWX7036A1	5TXCC007AS3	S8X1C100M5PTC	21,200	\$2,968
216764404	TRANE	5TWX7036A1	5TXCC007AS3	S8X1C100M5PSC	21,200	\$2,968
216765019	TRANE	5TWX7036A1	5TXCC007AS3	S8X1C080M5PTC	21,400	\$2,996
216764397	TRANE	5TWX7036A1	5TXCC007AS3	S8X1C080M5PSC	21,400	\$2,996
216767076	TRANE	5TWX7036A1	5TXCC007AS3	S8V2C100M5PDB	21,400	\$2,996
216767068	TRANE	5TWX7036A1	5TXCC007AS3	S8V2C100M5PCB	21,400	\$2,996
216767075	TRANE	5TWX7036A1	5TXCC007AS3	S8V2C080M5PDB	21,400	\$2,996
216767067	TRANE	5TWX7036A1	5TXCC007AS3	S8V2C080M5PCB	21,400	\$2,996
216764396	TRANE	5TWX7036A1	5TXCC007AS3	N/A	21,800	\$3,052
216764395	TRANE	5TWX7036A1	5TXCC007AS3	L9X1C100U5VSA	21,200	\$2,968
216764394	TRANE	5TWX7036A1	5TXCC007AS3	L8V1C100U5VSB	21,400	\$2,996
216764393	TRANE	5TWX7036A1	5TXCC007AS3	*UHMC100CCV4	21,200	\$2,968
216764402	TRANE	5TWX7036A1	5TXCC007AS3	*DHMC100CCV4	21,000	\$2,940
216767061	TRANE	5TWX7036A1	5TXCC005AS3	S9X2C100U5PSB	21,200	\$2,968
216767062	TRANE	5TWX7036A1	5TXCC005AS3	S9X1C100U5PSB	21,200	\$2,968
216767065	TRANE	5TWX7036A1	5TXCC005AS3	S9X1C080U5PSB	21,200	\$2,968
216767056	TRANE	5TWX7036A1	5TXCC005AS3	S9V2C100U5VSB	21,200	\$2,968
216764391	TRANE	5TWX7036A1	5TXCC005AS3	S9V2C100U5PSC	21,000	\$2,940
216764392	TRANE	5TWX7036A1	5TXCC005AS3	S9V2C100U4VSB	21,000	\$2,940
216767057	TRANE	5TWX7036A1	5TXCC005AS3	S9V2C080U5VSB	21,200	\$2,968
216764390	TRANE	5TWX7036A1	5TXCC005AS3	S9V2C080U5PSC	21,000	\$2,940
216765012	TRANE	5TWX7036A1	5TXCC005AS3	S8X2C100M5PTC	21,600	\$3,024
216765013	TRANE	5TWX7036A1	5TXCC005AS3	S8X2C100M5PSC	21,600	\$3,024
216765010	TRANE	5TWX7036A1	5TXCC005AS3	S8X2C080M5PTC	21,200	\$2,968
216765011	TRANE	5TWX7036A1	5TXCC005AS3	S8X2C080M5PSC	21,200	\$2,968
216765014	TRANE	5TWX7036A1	5TXCC005AS3	S8X1C100M5PTC	21,600	\$3,024
216764384	TRANE	5TWX7036A1	5TXCC005AS3	S8X1C100M5PSC	21,600	\$3,024
216765015	TRANE	5TWX7036A1	5TXCC005AS3	S8X1C080M5PTC	21,200	\$2,968
216764385	TRANE	5TWX7036A1	5TXCC005AS3	S8X1C080M5PSC	21,200	\$2,968
216767064	TRANE	5TWX7036A1	5TXCC005AS3	S8V2C100M5PDB	21,200	\$2,968
216767058	TRANE	5TWX7036A1	5TXCC005AS3	S8V2C100M5PCB	21,200	\$2,968
216767063	TRANE	5TWX7036A1	5TXCC005AS3	S8V2C080M5PDB	21,200	\$2,968
216767059	TRANE	5TWX7036A1	5TXCC005AS3	S8V2C080M5PCB	21,200	\$2,968
216764386	TRANE	5TWX7036A1	5TXCC005AS3	N/A	21,800	\$3,052
216764387	TRANE	5TWX7036A1	5TXCC005AS3	L9X1C100U5VSA	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764388	TRANE	5TWX7036A1	5TXCC005AS3	L8V1C100U5VSB	21,400	\$2,996
216764389	TRANE	5TWX7036A1	5TXCC005AS3	*UHMC100CCV4	21,200	\$2,968
216767042	TRANE	5TWX7036A1	5TXCB006AS3	S9X2B080U4PSB	21,200	\$2,968
216767035	TRANE	5TWX7036A1	5TXCB006AS3	S9X2B080D4PSB	21,000	\$2,940
216767041	TRANE	5TWX7036A1	5TXCB006AS3	S9X2B060U4PSB	21,200	\$2,968
216767039	TRANE	5TWX7036A1	5TXCB006AS3	S9X2B060D3PSB	21,000	\$2,940
216767034	TRANE	5TWX7036A1	5TXCB006AS3	S9X2B040U3PSB	21,400	\$2,996
216767040	TRANE	5TWX7036A1	5TXCB006AS3	S9X2B040D3PSB	21,400	\$2,996
216767047	TRANE	5TWX7036A1	5TXCB006AS3	S9X1B080U4PSB	21,200	\$2,968
216767043	TRANE	5TWX7036A1	5TXCB006AS3	S9X1B080D4PSB	21,000	\$2,940
216767048	TRANE	5TWX7036A1	5TXCB006AS3	S9X1B060U4PSB	21,200	\$2,968
216767044	TRANE	5TWX7036A1	5TXCB006AS3	S9X1B060D3PSB	21,000	\$2,940
216767049	TRANE	5TWX7036A1	5TXCB006AS3	S9X1B040U3PSB	21,400	\$2,996
216767045	TRANE	5TWX7036A1	5TXCB006AS3	S9X1B040D3PSB	21,400	\$2,996
216764376	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B080U4VSB	21,400	\$2,996
216764375	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B080U4PSC	21,400	\$2,996
216764361	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B080D4VSB	20,800	\$2,912
216764382	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B080D4PSC	20,800	\$2,912
216767050	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B060U4VSB	21,400	\$2,996
216764374	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B060U4PSC	21,200	\$2,968
216764373	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B060U3VSB	21,200	\$2,968
216764381	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B060D3VSB	20,800	\$2,912
216764380	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B060D3PSC	20,800	\$2,912
216764372	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B040U3VSB	21,200	\$2,968
216764371	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B040U3PSC	21,200	\$2,968
216767046	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B040D3VSB	20,800	\$2,912
216764379	TRANE	5TWX7036A1	5TXCB006AS3	S9V2B040D3PSC	20,800	\$2,912
216765006	TRANE	5TWX7036A1	5TXCB006AS3	S8X2B080M4PTC	21,200	\$2,968
216765003	TRANE	5TWX7036A1	5TXCB006AS3	S8X2B080M4PSC	21,200	\$2,968
216765007	TRANE	5TWX7036A1	5TXCB006AS3	S8X2B060M4PTC	21,400	\$2,996
216765008	TRANE	5TWX7036A1	5TXCB006AS3	S8X2B060M4PSC	21,400	\$2,996
216765001	TRANE	5TWX7036A1	5TXCB006AS3	S8X2A040M3PTC	21,600	\$3,024
216765002	TRANE	5TWX7036A1	5TXCB006AS3	S8X2A040M3PSC	21,600	\$3,024
216765009	TRANE	5TWX7036A1	5TXCB006AS3	S8X1B080M4PTC	21,200	\$2,968
216764370	TRANE	5TWX7036A1	5TXCB006AS3	S8X1B080M4PSC	21,200	\$2,968
216765005	TRANE	5TWX7036A1	5TXCB006AS3	S8X1B060M4PTC	21,400	\$2,996
216764369	TRANE	5TWX7036A1	5TXCB006AS3	S8X1B060M4PSC	21,400	\$2,996
216765004	TRANE	5TWX7036A1	5TXCB006AS3	S8X1A040M3PTC	21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764368	TRANE	5TWX7036A1	5TXCB006AS3	S8X1A040M3PSC	21,600	\$3,024
216767036	TRANE	5TWX7036A1	5TXCB006AS3	S8V2B080M4PDB	21,400	\$2,996
216767051	TRANE	5TWX7036A1	5TXCB006AS3	S8V2B080M4PCB	21,400	\$2,996
216767037	TRANE	5TWX7036A1	5TXCB006AS3	S8V2B060M4PDB	21,200	\$2,968
216767052	TRANE	5TWX7036A1	5TXCB006AS3	S8V2B060M4PCB	21,200	\$2,968
216767038	TRANE	5TWX7036A1	5TXCB006AS3	S8V2A040M3PDB	21,400	\$2,996
216767055	TRANE	5TWX7036A1	5TXCB006AS3	S8V2A040M3PCB	21,400	\$2,996
216764367	TRANE	5TWX7036A1	5TXCB006AS3	N/A	21,800	\$3,052
216764366	TRANE	5TWX7036A1	5TXCB006AS3	L9X1B070U4VSA	21,600	\$3,024
216764360	TRANE	5TWX7036A1	5TXCB006AS3	L9X1A050U3VSA	21,600	\$3,024
216764383	TRANE	5TWX7036A1	5TXCB006AS3	L8V1B080U4VSB	21,400	\$2,996
216764362	TRANE	5TWX7036A1	5TXCB006AS3	L8V1A060U3VSB	21,400	\$2,996
216764363	TRANE	5TWX7036A1	5TXCB006AS3	L8V1A040U3VSB	21,400	\$2,996
216764364	TRANE	5TWX7036A1	5TXCB006AS3	*UHMB080CCV3	21,200	\$2,968
216764365	TRANE	5TWX7036A1	5TXCB006AS3	*UHMB060CCV3	21,200	\$2,968
216764378	TRANE	5TWX7036A1	5TXCB006AS3	*DHMB080CCV3	20,800	\$2,912
216764377	TRANE	5TWX7036A1	5TXCB006AS3	*DHMB060CCV3	21,200	\$2,968
216767020	TRANE	5TWX7036A1	5TXCB004AS3	S9X2B080U4PSB	21,000	\$2,940
216767031	TRANE	5TWX7036A1	5TXCB004AS3	S9X2B060U4PSB	21,000	\$2,940
216767028	TRANE	5TWX7036A1	5TXCB004AS3	S9X2B040U3PSB	21,200	\$2,968
216767021	TRANE	5TWX7036A1	5TXCB004AS3	S9X1B080U4PSB	21,000	\$2,940
216767023	TRANE	5TWX7036A1	5TXCB004AS3	S9X1B060U4PSB	21,000	\$2,940
216767024	TRANE	5TWX7036A1	5TXCB004AS3	S9X1B040U3PSB	21,200	\$2,968
216764358	TRANE	5TWX7036A1	5TXCB004AS3	S9V2B080U4VSB	21,200	\$2,968
216764357	TRANE	5TWX7036A1	5TXCB004AS3	S9V2B080U4PSC	21,200	\$2,968
216767025	TRANE	5TWX7036A1	5TXCB004AS3	S9V2B060U4VSB	20,800	\$2,912
216764356	TRANE	5TWX7036A1	5TXCB004AS3	S9V2B060U4PSC	21,200	\$2,968
216764355	TRANE	5TWX7036A1	5TXCB004AS3	S9V2B060U3VSB	21,200	\$2,968
216764354	TRANE	5TWX7036A1	5TXCB004AS3	S9V2B040U3VSB	21,200	\$2,968
216764353	TRANE	5TWX7036A1	5TXCB004AS3	S9V2B040U3PSC	21,200	\$2,968
216764995	TRANE	5TWX7036A1	5TXCB004AS3	S8X2B080M4PTC	21,000	\$2,940
216764992	TRANE	5TWX7036A1	5TXCB004AS3	S8X2B080M4PSC	21,000	\$2,940
216764994	TRANE	5TWX7036A1	5TXCB004AS3	S8X2B060M4PTC	21,000	\$2,940
216764993	TRANE	5TWX7036A1	5TXCB004AS3	S8X2B060M4PSC	21,000	\$2,940
216764996	TRANE	5TWX7036A1	5TXCB004AS3	S8X2A040M3PTC	21,400	\$2,996
216764997	TRANE	5TWX7036A1	5TXCB004AS3	S8X2A040M3PSC	21,400	\$2,996
216764998	TRANE	5TWX7036A1	5TXCB004AS3	S8X1B080M4PTC	21,000	\$2,940
216764352	TRANE	5TWX7036A1	5TXCB004AS3	S8X1B080M4PSC	21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764999	TRANE	5TWX7036A1	5TXCB004AS3	S8X1B060M4PTC	21,000	\$2,940
216764351	TRANE	5TWX7036A1	5TXCB004AS3	S8X1B060M4PSC	21,000	\$2,940
216765000	TRANE	5TWX7036A1	5TXCB004AS3	S8X1A040M3PTC	21,400	\$2,996
216764350	TRANE	5TWX7036A1	5TXCB004AS3	S8X1A040M3PSC	21,400	\$2,996
216767019	TRANE	5TWX7036A1	5TXCB004AS3	S8V2B080M4PDB	21,000	\$2,940
216767026	TRANE	5TWX7036A1	5TXCB004AS3	S8V2B080M4PCB	21,000	\$2,940
216767027	TRANE	5TWX7036A1	5TXCB004AS3	S8V2B060M4PDB	21,200	\$2,968
216767032	TRANE	5TWX7036A1	5TXCB004AS3	S8V2B060M4PCB	21,200	\$2,968
216767022	TRANE	5TWX7036A1	5TXCB004AS3	S8V2A040M3PDB	21,000	\$2,940
216767033	TRANE	5TWX7036A1	5TXCB004AS3	S8V2A040M3PCB	21,000	\$2,940
216764349	TRANE	5TWX7036A1	5TXCB004AS3	N/A	21,800	\$3,052
216764348	TRANE	5TWX7036A1	5TXCB004AS3	L9X1B070U4VSA	21,600	\$3,024
216764347	TRANE	5TWX7036A1	5TXCB004AS3	L9X1A050U3VSA	21,800	\$3,052
216764346	TRANE	5TWX7036A1	5TXCB004AS3	L8V1B080U4VSB	21,400	\$2,996
216764345	TRANE	5TWX7036A1	5TXCB004AS3	L8V1A060U3VSB	20,800	\$2,912
216764344	TRANE	5TWX7036A1	5TXCB004AS3	L8V1A040U3VSB	21,200	\$2,968
216764343	TRANE	5TWX7036A1	5TXCB004AS3	*UHMB080CCV3	21,000	\$2,940
216764359	TRANE	5TWX7036A1	5TXCB004AS3	*UHMB060CCV3	21,000	\$2,940
216764342	TRANE	5TWX7036A1	5TEMCD07AV51+TD	N/A	21,000	\$2,940
216764341	TRANE	5TWX7036A1	5TEMCD06AV41+TD	N/A	21,000	\$2,940
216764340	TRANE	5TWX7036A1	5TEMCD05AV41+TD	N/A	21,200	\$2,968
216764339	TRANE	5TWX7036A1	5TEMCD04AV31+TD	N/A	21,200	\$2,968
216764337	TRANE	5TWX7036A1	5TEM6D07AV51+TD	N/A	21,000	\$2,940
216764336	TRANE	5TWX7036A1	5TEM6D06AV41+TD	N/A	21,000	\$2,940
216764335	TRANE	5TWX7036A1	5TEM6D05AV41+TD	N/A	21,200	\$2,968
216764334	TRANE	5TWX7036A1	5TEM6D04AV31+TD	N/A	21,200	\$2,968
216770110	TRANE	5TWX7036A1	5TAMXD06AV41	N/A	21,400	\$2,996
216770109	TRANE	5TWX7036A1	5TAMXD05AV41	N/A	21,200	\$2,968
216770106	TRANE	5TWX7036A1	5TAM5D05AC31	N/A	21,400	\$2,996
216767016	TRANE	5TWX7036A1	5PX*DD10AS3	S9X2D120D5PSB	21,200	\$2,968
216767018	TRANE	5TWX7036A1	5PX*DD10AS3	S9X1D120D5PSB	21,200	\$2,968
216767017	TRANE	5TWX7036A1	5PX*DD10AS3	S8V2D120M5PDB	21,200	\$2,968
216767015	TRANE	5TWX7036A1	5PX*DD10AS3	S8V2D120M5PCB	21,200	\$2,968
216764332	TRANE	5TWX7036A1	5PX*DD10AS3	N/A	21,600	\$3,024
216764331	TRANE	5TWX7036A1	5PX*DD10AS3	*DHMD120CCV5	21,200	\$2,968
216767013	TRANE	5TWX7036A1	5PX*D010AS3	S9X2D120U5PSB	21,000	\$2,940
216767012	TRANE	5TWX7036A1	5PX*D010AS3	S9X1D120U5PSB	21,000	\$2,940
216764330	TRANE	5TWX7036A1	5PX*D010AS3	S9V2D120U5VSB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764328	TRANE	5TWX7036A1	5PX*D010AS3	S9V2D120U5PSC	21,200	\$2,968
216767011	TRANE	5TWX7036A1	5PX*D010AS3	S8V2D120M5PDB	21,200	\$2,968
216767014	TRANE	5TWX7036A1	5PX*D010AS3	S8V2D120M5PCB	21,200	\$2,968
216764327	TRANE	5TWX7036A1	5PX*D010AS3	N/A	21,600	\$3,024
216764329	TRANE	5TWX7036A1	5PX*D010AS3	*UHMD120CCV5	21,000	\$2,940
216767006	TRANE	5TWX7036A1	5PX*D008AS3	S9X2D120U5PSB	21,200	\$2,968
216767010	TRANE	5TWX7036A1	5PX*D008AS3	S9X2D120D5PSB	21,000	\$2,940
216767009	TRANE	5TWX7036A1	5PX*D008AS3	S9X1D120U5PSB	21,200	\$2,968
216767007	TRANE	5TWX7036A1	5PX*D008AS3	S9X1D120D5PSB	21,000	\$2,940
216764325	TRANE	5TWX7036A1	5PX*D008AS3	S9V2D120U5VSB	21,400	\$2,996
216764324	TRANE	5TWX7036A1	5PX*D008AS3	S9V2D120U5PSC	21,400	\$2,996
216764991	TRANE	5TWX7036A1	5PX*D008AS3	S8X2D120M5PTC	21,000	\$2,940
216764990	TRANE	5TWX7036A1	5PX*D008AS3	S8X2D120M5PSC	21,000	\$2,940
216764989	TRANE	5TWX7036A1	5PX*D008AS3	S8X1D120M5PTC	21,000	\$2,940
216764323	TRANE	5TWX7036A1	5PX*D008AS3	S8X1D120M5PSC	21,000	\$2,940
216767005	TRANE	5TWX7036A1	5PX*D008AS3	S8V2D120M5PDB	21,400	\$2,996
216767008	TRANE	5TWX7036A1	5PX*D008AS3	S8V2D120M5PCB	21,400	\$2,996
216764322	TRANE	5TWX7036A1	5PX*D008AS3	N/A	22,000	\$3,080
216764321	TRANE	5TWX7036A1	5PX*D008AS3	*UHMD120CCV5	21,200	\$2,968
216764326	TRANE	5TWX7036A1	5PX*D008AS3	*DHMD120CCV5	21,000	\$2,940
216767002	TRANE	5TWX7036A1	5PX*CD09AS3	S9X2C100D5PSB	21,400	\$2,996
216767001	TRANE	5TWX7036A1	5PX*CD09AS3	S9X1C100D5PSB	21,400	\$2,996
216766997	TRANE	5TWX7036A1	5PX*CD09AS3	S9V2C100D5VSB	21,000	\$2,940
216764318	TRANE	5TWX7036A1	5PX*CD09AS3	S9V2C100D5PSC	21,000	\$2,940
216764319	TRANE	5TWX7036A1	5PX*CD09AS3	S9V2C100D4VSB	21,000	\$2,940
216770105	TRANE	5TWX7036A1	5PX*CD09AS3	S8X2C100M5PTC	21,400	\$2,996
216770102	TRANE	5TWX7036A1	5PX*CD09AS3	S8X2C100M5PSC	21,400	\$2,996
216764987	TRANE	5TWX7036A1	5PX*CD09AS3	S8X2C080M5PTC	21,200	\$2,968
216764986	TRANE	5TWX7036A1	5PX*CD09AS3	S8X2C080M5PSC	21,200	\$2,968
216770103	TRANE	5TWX7036A1	5PX*CD09AS3	S8X1C100M5PTC	21,400	\$2,996
216770104	TRANE	5TWX7036A1	5PX*CD09AS3	S8X1C100M5PSC	21,400	\$2,996
216764988	TRANE	5TWX7036A1	5PX*CD09AS3	S8X1C080M5PTC	21,200	\$2,968
216764320	TRANE	5TWX7036A1	5PX*CD09AS3	S8X1C080M5PSC	21,200	\$2,968
216767000	TRANE	5TWX7036A1	5PX*CD09AS3	S8V2C100M5PDB	21,200	\$2,968
216767003	TRANE	5TWX7036A1	5PX*CD09AS3	S8V2C100M5PCB	21,200	\$2,968
216767004	TRANE	5TWX7036A1	5PX*CD09AS3	S8V2C080M5PDB	21,200	\$2,968
216766999	TRANE	5TWX7036A1	5PX*CD09AS3	S8V2C080M5PCB	21,200	\$2,968
216764317	TRANE	5TWX7036A1	5PX*CD09AS3	N/A	21,600	\$3,024

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764316	TRANE	5TWX7036A1	5PX*CD09AS3	*DHMC100CCV4	21,000	\$2,940
216766991	TRANE	5TWX7036A1	5PX*CD07AS3	S9X2C100D5PSB	21,800	\$3,052
216766995	TRANE	5TWX7036A1	5PX*CD07AS3	S9X1C100D5PSB	21,800	\$3,052
216766994	TRANE	5TWX7036A1	5PX*CD07AS3	S9V2C100D5VSB	21,600	\$3,024
216764314	TRANE	5TWX7036A1	5PX*CD07AS3	S9V2C100D5PSC	21,600	\$3,024
216764310	TRANE	5TWX7036A1	5PX*CD07AS3	S9V2C100D4VSB	21,600	\$3,024
216764984	TRANE	5TWX7036A1	5PX*CD07AS3	S8X2C100M5PTC	21,400	\$2,996
216764982	TRANE	5TWX7036A1	5PX*CD07AS3	S8X2C100M5PSC	21,400	\$2,996
216764980	TRANE	5TWX7036A1	5PX*CD07AS3	S8X1C100M5PTC	21,400	\$2,996
216764311	TRANE	5TWX7036A1	5PX*CD07AS3	S8X1C100M5PSC	21,400	\$2,996
216764313	TRANE	5TWX7036A1	5PX*CD07AS3	N/A	22,000	\$3,080
216766982	TRANE	5TWX7036A1	5PX*CD05AS3	S8V2C100M5PDB	21,600	\$3,024
216766981	TRANE	5TWX7036A1	5PX*CD05AS3	S8V2C100M5PCB	21,600	\$3,024
216764308	TRANE	5TWX7036A1	5PX*CD05AS3	N/A	22,000	\$3,080
216766970	TRANE	5TWX7036A1	5PX*C009AS3	S9X2C100U5PSB	21,200	\$2,968
216766980	TRANE	5TWX7036A1	5PX*C009AS3	S9X2C080U5PSB	21,400	\$2,996
216766973	TRANE	5TWX7036A1	5PX*C009AS3	S9X1C100U5PSB	21,200	\$2,968
216766974	TRANE	5TWX7036A1	5PX*C009AS3	S9X1C080U5PSB	21,400	\$2,996
216766975	TRANE	5TWX7036A1	5PX*C009AS3	S9V2C100U5VSB	21,200	\$2,968
216764304	TRANE	5TWX7036A1	5PX*C009AS3	S9V2C100U5PSC	21,200	\$2,968
216764299	TRANE	5TWX7036A1	5PX*C009AS3	S9V2C100U4VSB	21,200	\$2,968
216766976	TRANE	5TWX7036A1	5PX*C009AS3	S9V2C080U5VSB	21,200	\$2,968
216764302	TRANE	5TWX7036A1	5PX*C009AS3	S9V2C080U5PSC	21,200	\$2,968
216770099	TRANE	5TWX7036A1	5PX*C009AS3	S8X2C100M5PTC	21,400	\$2,996
216770100	TRANE	5TWX7036A1	5PX*C009AS3	S8X2C100M5PSC	21,400	\$2,996
216764975	TRANE	5TWX7036A1	5PX*C009AS3	S8X2C080M5PTC	21,200	\$2,968
216764974	TRANE	5TWX7036A1	5PX*C009AS3	S8X2C080M5PSC	21,200	\$2,968
216770101	TRANE	5TWX7036A1	5PX*C009AS3	S8X1C100M5PTC	21,400	\$2,996
216770098	TRANE	5TWX7036A1	5PX*C009AS3	S8X1C100M5PSC	21,400	\$2,996
216764976	TRANE	5TWX7036A1	5PX*C009AS3	S8X1C080M5PTC	21,200	\$2,968
216764303	TRANE	5TWX7036A1	5PX*C009AS3	S8X1C080M5PSC	21,200	\$2,968
216766971	TRANE	5TWX7036A1	5PX*C009AS3	S8V2C100M5PDB	21,200	\$2,968
216766977	TRANE	5TWX7036A1	5PX*C009AS3	S8V2C100M5PCB	21,200	\$2,968
216766972	TRANE	5TWX7036A1	5PX*C009AS3	S8V2C080M5PDB	21,400	\$2,996
216766978	TRANE	5TWX7036A1	5PX*C009AS3	S8V2C080M5PCB	21,400	\$2,996
216764298	TRANE	5TWX7036A1	5PX*C009AS3	N/A	21,600	\$3,024
216770097	TRANE	5TWX7036A1	5PX*C009AS3	L9X1C100U5VSA	21,200	\$2,968
216764301	TRANE	5TWX7036A1	5PX*C009AS3	L8V1C100U5VSB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764300	TRANE	5TWX7036A1	5PX*C009AS3	*UHMC100CCV4	21,000	\$2,940
216766960	TRANE	5TWX7036A1	5PX*C007AS3	S9X2C100U5PSB	21,400	\$2,996
216766959	TRANE	5TWX7036A1	5PX*C007AS3	S9X2C100D5PSB	21,200	\$2,968
216766964	TRANE	5TWX7036A1	5PX*C007AS3	S9X1C100U5PSB	21,400	\$2,996
216766962	TRANE	5TWX7036A1	5PX*C007AS3	S9X1C100D5PSB	21,200	\$2,968
216766965	TRANE	5TWX7036A1	5PX*C007AS3	S9X1C080U5PSB	21,600	\$3,024
216766966	TRANE	5TWX7036A1	5PX*C007AS3	S9V2C100U5VSB	21,400	\$2,996
216764289	TRANE	5TWX7036A1	5PX*C007AS3	S9V2C100U5PSC	21,400	\$2,996
216764290	TRANE	5TWX7036A1	5PX*C007AS3	S9V2C100U4VSB	21,400	\$2,996
216766963	TRANE	5TWX7036A1	5PX*C007AS3	S9V2C100D5VSB	21,000	\$2,940
216764286	TRANE	5TWX7036A1	5PX*C007AS3	S9V2C100D5PSC	21,000	\$2,940
216764287	TRANE	5TWX7036A1	5PX*C007AS3	S9V2C100D4VSB	21,000	\$2,940
216766967	TRANE	5TWX7036A1	5PX*C007AS3	S9V2C080U5VSB	21,400	\$2,996
216764291	TRANE	5TWX7036A1	5PX*C007AS3	S9V2C080U5PSC	21,400	\$2,996
216764970	TRANE	5TWX7036A1	5PX*C007AS3	S8X2C100M5PTC	21,200	\$2,968
216764969	TRANE	5TWX7036A1	5PX*C007AS3	S8X2C100M5PSC	21,200	\$2,968
216764973	TRANE	5TWX7036A1	5PX*C007AS3	S8X2C080M5PTC	21,400	\$2,996
216764968	TRANE	5TWX7036A1	5PX*C007AS3	S8X2C080M5PSC	21,400	\$2,996
216764972	TRANE	5TWX7036A1	5PX*C007AS3	S8X1C100M5PTC	21,200	\$2,968
216764292	TRANE	5TWX7036A1	5PX*C007AS3	S8X1C100M5PSC	21,200	\$2,968
216764971	TRANE	5TWX7036A1	5PX*C007AS3	S8X1C080M5PTC	21,400	\$2,996
216764293	TRANE	5TWX7036A1	5PX*C007AS3	S8X1C080M5PSC	21,400	\$2,996
216766957	TRANE	5TWX7036A1	5PX*C007AS3	S8V2C100M5PDB	21,400	\$2,996
216766968	TRANE	5TWX7036A1	5PX*C007AS3	S8V2C100M5PCB	21,400	\$2,996
216766958	TRANE	5TWX7036A1	5PX*C007AS3	S8V2C080M5PDB	21,400	\$2,996
216766961	TRANE	5TWX7036A1	5PX*C007AS3	S8V2C080M5PCB	21,400	\$2,996
216764295	TRANE	5TWX7036A1	5PX*C007AS3	N/A	22,000	\$3,080
216764294	TRANE	5TWX7036A1	5PX*C007AS3	L9X1C100U5VSA	21,200	\$2,968
216764296	TRANE	5TWX7036A1	5PX*C007AS3	L8V1C100U5VSB	21,400	\$2,996
216764297	TRANE	5TWX7036A1	5PX*C007AS3	*UHMC100CCV4	21,200	\$2,968
216764288	TRANE	5TWX7036A1	5PX*C007AS3	*DHMC100CCV4	21,000	\$2,940
216766950	TRANE	5TWX7036A1	5PX*C005AS3	S9X2C100U5PSB	21,200	\$2,968
216766949	TRANE	5TWX7036A1	5PX*C005AS3	S9X2C080U5PSB	21,200	\$2,968
216766956	TRANE	5TWX7036A1	5PX*C005AS3	S9X1C100U5PSB	21,200	\$2,968
216766952	TRANE	5TWX7036A1	5PX*C005AS3	S9X1C080U5PSB	21,200	\$2,968
216766953	TRANE	5TWX7036A1	5PX*C005AS3	S9V2C100U5VSB	21,200	\$2,968
216764284	TRANE	5TWX7036A1	5PX*C005AS3	S9V2C100U4VSB	21,000	\$2,940
216766954	TRANE	5TWX7036A1	5PX*C005AS3	S9V2C080U5VSB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764283	TRANE	5TWX7036A1	5PX*C005AS3	S9V2C080U5PSC	21,000	\$2,940
216764967	TRANE	5TWX7036A1	5PX*C005AS3	S8X2C100M5PTC	21,600	\$3,024
216764962	TRANE	5TWX7036A1	5PX*C005AS3	S8X2C100M5PSC	21,600	\$3,024
216764966	TRANE	5TWX7036A1	5PX*C005AS3	S8X2C080M5PTC	21,200	\$2,968
216764963	TRANE	5TWX7036A1	5PX*C005AS3	S8X2C080M5PSC	21,200	\$2,968
216764965	TRANE	5TWX7036A1	5PX*C005AS3	S8X1C100M5PTC	21,600	\$3,024
216764282	TRANE	5TWX7036A1	5PX*C005AS3	S8X1C100M5PSC	21,600	\$3,024
216764964	TRANE	5TWX7036A1	5PX*C005AS3	S8X1C080M5PTC	21,200	\$2,968
216764285	TRANE	5TWX7036A1	5PX*C005AS3	S8X1C080M5PSC	21,200	\$2,968
216766951	TRANE	5TWX7036A1	5PX*C005AS3	S8V2C100M5PDB	21,200	\$2,968
216766948	TRANE	5TWX7036A1	5PX*C005AS3	S8V2C100M5PCB	21,200	\$2,968
216766955	TRANE	5TWX7036A1	5PX*C005AS3	S8V2C080M5PDB	21,200	\$2,968
216766947	TRANE	5TWX7036A1	5PX*C005AS3	S8V2C080M5PCB	21,200	\$2,968
216764281	TRANE	5TWX7036A1	5PX*C005AS3	N/A	21,800	\$3,052
216764280	TRANE	5TWX7036A1	5PX*C005AS3	L9X1C100U5VSA	21,200	\$2,968
216764278	TRANE	5TWX7036A1	5PX*C005AS3	L8V1C100U5VSB	21,400	\$2,996
216764279	TRANE	5TWX7036A1	5PX*C005AS3	*UHMC100CCV4	21,200	\$2,968
216766938	TRANE	5TWX7036A1	5PX*BD06AS3	S9X2B080D4PSB	21,600	\$3,024
216766940	TRANE	5TWX7036A1	5PX*BD06AS3	S9X2B040D3PSB	21,600	\$3,024
216766932	TRANE	5TWX7036A1	5PX*BD06AS3	S9X1B080D4PSB	21,600	\$3,024
216766931	TRANE	5TWX7036A1	5PX*BD06AS3	S9X1B040D3PSB	21,600	\$3,024
216764277	TRANE	5TWX7036A1	5PX*BD06AS3	S9V2B080D4VSB	21,400	\$2,996
216764276	TRANE	5TWX7036A1	5PX*BD06AS3	S9V2B080D4PSC	21,400	\$2,996
216764275	TRANE	5TWX7036A1	5PX*BD06AS3	S9V2B060D3VSB	21,600	\$3,024
216764274	TRANE	5TWX7036A1	5PX*BD06AS3	S9V2B060D3PSC	21,600	\$3,024
216764957	TRANE	5TWX7036A1	5PX*BD06AS3	S8X2B080M4PTC	21,800	\$3,052
216764954	TRANE	5TWX7036A1	5PX*BD06AS3	S8X2B080M4PSC	21,800	\$3,052
216764960	TRANE	5TWX7036A1	5PX*BD06AS3	S8X2B060M4PTC	21,400	\$2,996
216764953	TRANE	5TWX7036A1	5PX*BD06AS3	S8X2B060M4PSC	21,400	\$2,996
216764961	TRANE	5TWX7036A1	5PX*BD06AS3	S8X1B080M4PTC	21,800	\$3,052
216764272	TRANE	5TWX7036A1	5PX*BD06AS3	S8X1B080M4PSC	21,800	\$3,052
216764959	TRANE	5TWX7036A1	5PX*BD06AS3	S8X1B060M4PTC	21,400	\$2,996
216764271	TRANE	5TWX7036A1	5PX*BD06AS3	S8X1B060M4PSC	21,400	\$2,996
216766942	TRANE	5TWX7036A1	5PX*BD06AS3	S8V2B060M4PDB	21,600	\$3,024
216766934	TRANE	5TWX7036A1	5PX*BD06AS3	S8V2B060M4PCB	21,600	\$3,024
216766943	TRANE	5TWX7036A1	5PX*BD06AS3	S8V2A040M3PDB	21,400	\$2,996
216766935	TRANE	5TWX7036A1	5PX*BD06AS3	S8V2A040M3PCB	21,400	\$2,996
216764269	TRANE	5TWX7036A1	5PX*BD06AS3	N/A	22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764268	TRANE	5TWX7036A1	5PX*BD06AS3	*DHMB080CCV3	21,400	\$2,996
216766926	TRANE	5TWX7036A1	5PX*BD04AS3	S9X2B080D4PSB	21,600	\$3,024
216766927	TRANE	5TWX7036A1	5PX*BD04AS3	S9X2B060D3PSB	21,800	\$3,052
216766928	TRANE	5TWX7036A1	5PX*BD04AS3	S9X2B040D3PSB	22,000	\$3,080
216766929	TRANE	5TWX7036A1	5PX*BD04AS3	S9X1B080D4PSB	21,600	\$3,024
216766919	TRANE	5TWX7036A1	5PX*BD04AS3	S9X1B060D3PSB	21,800	\$3,052
216766920	TRANE	5TWX7036A1	5PX*BD04AS3	S9X1B040D3PSB	22,000	\$3,080
216764261	TRANE	5TWX7036A1	5PX*BD04AS3	S9V2B080D4VSB	21,600	\$3,024
216764265	TRANE	5TWX7036A1	5PX*BD04AS3	S9V2B080D4PSC	21,600	\$3,024
216764264	TRANE	5TWX7036A1	5PX*BD04AS3	S9V2B060D3VSB	21,600	\$3,024
216764263	TRANE	5TWX7036A1	5PX*BD04AS3	S9V2B060D3PSC	21,600	\$3,024
216766921	TRANE	5TWX7036A1	5PX*BD04AS3	S9V2B040D3VSB	21,800	\$3,052
216764262	TRANE	5TWX7036A1	5PX*BD04AS3	S9V2B040D3PSC	21,800	\$3,052
216764952	TRANE	5TWX7036A1	5PX*BD04AS3	S8X2A040M3PTC	21,800	\$3,052
216764947	TRANE	5TWX7036A1	5PX*BD04AS3	S8X2A040M3PSC	21,800	\$3,052
216764945	TRANE	5TWX7036A1	5PX*BD04AS3	S8X1A040M3PTC	21,800	\$3,052
216764259	TRANE	5TWX7036A1	5PX*BD04AS3	S8X1A040M3PSC	21,800	\$3,052
216766918	TRANE	5TWX7036A1	5PX*BD04AS3	S8V2B080M4PDB	21,600	\$3,024
216766922	TRANE	5TWX7036A1	5PX*BD04AS3	S8V2B080M4PCB	21,600	\$3,024
216766930	TRANE	5TWX7036A1	5PX*BD04AS3	S8V2B060M4PDB	21,600	\$3,024
216766923	TRANE	5TWX7036A1	5PX*BD04AS3	S8V2B060M4PCB	21,600	\$3,024
216764258	TRANE	5TWX7036A1	5PX*BD04AS3	N/A	22,000	\$3,080
216764257	TRANE	5TWX7036A1	5PX*BD04AS3	*DHMB080CCV3	21,600	\$3,024
216764256	TRANE	5TWX7036A1	5PX*BD04AS3	*DHMB060CCV3	21,800	\$3,052
216766913	TRANE	5TWX7036A1	5PX*B006AS3	S9X2B080U4PSB	21,200	\$2,968
216766914	TRANE	5TWX7036A1	5PX*B006AS3	S9X2B060U4PSB	21,200	\$2,968
216766912	TRANE	5TWX7036A1	5PX*B006AS3	S9X2B060D3PSB	21,200	\$2,968
216766900	TRANE	5TWX7036A1	5PX*B006AS3	S9X2B040U3PSB	21,800	\$3,052
216766905	TRANE	5TWX7036A1	5PX*B006AS3	S9X1B080U4PSB	21,200	\$2,968
216766906	TRANE	5TWX7036A1	5PX*B006AS3	S9X1B060U4PSB	21,200	\$2,968
216766903	TRANE	5TWX7036A1	5PX*B006AS3	S9X1B060D3PSB	21,200	\$2,968
216766907	TRANE	5TWX7036A1	5PX*B006AS3	S9X1B040U3PSB	21,800	\$3,052
216764239	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B080U4VSB	21,200	\$2,968
216764240	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B080U4PSC	21,200	\$2,968
216764235	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B080D4VSB	21,200	\$2,968
216764236	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B080D4PSC	21,200	\$2,968
216766908	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B060U4VSB	21,200	\$2,968
216764241	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B060U4PSC	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764242	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B060U3VSB	21,200	\$2,968
216764243	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B040U3VSB	21,200	\$2,968
216764244	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B040U3PSC	21,200	\$2,968
216766904	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B040D3VSB	21,400	\$2,996
216764237	TRANE	5TWX7036A1	5PX*B006AS3	S9V2B040D3PSC	21,400	\$2,996
216764942	TRANE	5TWX7036A1	5PX*B006AS3	S8X2B080M4PTC	21,200	\$2,968
216764938	TRANE	5TWX7036A1	5PX*B006AS3	S8X2B080M4PSC	21,200	\$2,968
216764941	TRANE	5TWX7036A1	5PX*B006AS3	S8X2B060M4PTC	21,400	\$2,996
216764937	TRANE	5TWX7036A1	5PX*B006AS3	S8X2B060M4PSC	21,400	\$2,996
216764940	TRANE	5TWX7036A1	5PX*B006AS3	S8X2A040M3PTC	21,600	\$3,024
216764936	TRANE	5TWX7036A1	5PX*B006AS3	S8X2A040M3PSC	21,600	\$3,024
216764944	TRANE	5TWX7036A1	5PX*B006AS3	S8X1B080M4PTC	21,200	\$2,968
216764245	TRANE	5TWX7036A1	5PX*B006AS3	S8X1B080M4PSC	21,200	\$2,968
216764943	TRANE	5TWX7036A1	5PX*B006AS3	S8X1B060M4PTC	21,400	\$2,996
216764255	TRANE	5TWX7036A1	5PX*B006AS3	S8X1B060M4PSC	21,400	\$2,996
216764939	TRANE	5TWX7036A1	5PX*B006AS3	S8X1A040M3PTC	21,600	\$3,024
216764254	TRANE	5TWX7036A1	5PX*B006AS3	S8X1A040M3PSC	21,600	\$3,024
216766911	TRANE	5TWX7036A1	5PX*B006AS3	S8V2B080M4PDB	21,400	\$2,996
216766902	TRANE	5TWX7036A1	5PX*B006AS3	S8V2B080M4PCB	21,400	\$2,996
216766910	TRANE	5TWX7036A1	5PX*B006AS3	S8V2B060M4PDB	21,200	\$2,968
216766901	TRANE	5TWX7036A1	5PX*B006AS3	S8V2B060M4PCB	21,200	\$2,968
216766917	TRANE	5TWX7036A1	5PX*B006AS3	S8V2A040M3PDB	21,200	\$2,968
216766909	TRANE	5TWX7036A1	5PX*B006AS3	S8V2A040M3PCB	21,200	\$2,968
216764253	TRANE	5TWX7036A1	5PX*B006AS3	N/A	22,000	\$3,080
216764252	TRANE	5TWX7036A1	5PX*B006AS3	L9X1B070U4VSA	21,600	\$3,024
216764251	TRANE	5TWX7036A1	5PX*B006AS3	L9X1A050U3VSA	21,400	\$2,996
216764250	TRANE	5TWX7036A1	5PX*B006AS3	L8V1B080U4VSB	21,400	\$2,996
216764249	TRANE	5TWX7036A1	5PX*B006AS3	L8V1A060U3VSB	21,400	\$2,996
216764248	TRANE	5TWX7036A1	5PX*B006AS3	L8V1A040U3VSB	21,400	\$2,996
216764247	TRANE	5TWX7036A1	5PX*B006AS3	*UHMB080CCV3	21,200	\$2,968
216764246	TRANE	5TWX7036A1	5PX*B006AS3	*UHMB060CCV3	21,200	\$2,968
216764238	TRANE	5TWX7036A1	5PX*B006AS3	*DHMB080CCV3	21,200	\$2,968
216766888	TRANE	5TWX7036A1	5PX*B004AS3	S9X2B080U4PSB	21,000	\$2,940
216766889	TRANE	5TWX7036A1	5PX*B004AS3	S9X2B060U4PSB	21,000	\$2,940
216766890	TRANE	5TWX7036A1	5PX*B004AS3	S9X2B040U3PSB	21,200	\$2,968
216766887	TRANE	5TWX7036A1	5PX*B004AS3	S9X1B080U4PSB	21,000	\$2,940
216766886	TRANE	5TWX7036A1	5PX*B004AS3	S9X1B060U4PSB	21,000	\$2,940
216766899	TRANE	5TWX7036A1	5PX*B004AS3	S9X1B040U3PSB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764233	TRANE	5TWX7036A1	5PX*B004AS3	S9V2B080U4VSB	21,200	\$2,968
216764234	TRANE	5TWX7036A1	5PX*B004AS3	S9V2B080U4PSC	21,200	\$2,968
216766892	TRANE	5TWX7036A1	5PX*B004AS3	S9V2B060U4VSB	21,000	\$2,940
216764231	TRANE	5TWX7036A1	5PX*B004AS3	S9V2B060U4PSC	21,200	\$2,968
216764230	TRANE	5TWX7036A1	5PX*B004AS3	S9V2B060U3VSB	21,200	\$2,968
216764219	TRANE	5TWX7036A1	5PX*B004AS3	S9V2B040U3VSB	21,200	\$2,968
216764933	TRANE	5TWX7036A1	5PX*B004AS3	S8X2B080M4PTC	21,000	\$2,940
216764930	TRANE	5TWX7036A1	5PX*B004AS3	S8X2B080M4PSC	21,000	\$2,940
216764929	TRANE	5TWX7036A1	5PX*B004AS3	S8X2B060M4PTC	21,000	\$2,940
216764932	TRANE	5TWX7036A1	5PX*B004AS3	S8X2B060M4PSC	21,000	\$2,940
216764928	TRANE	5TWX7036A1	5PX*B004AS3	S8X2A040M3PTC	21,400	\$2,996
216764934	TRANE	5TWX7036A1	5PX*B004AS3	S8X1B080M4PTC	21,000	\$2,940
216764220	TRANE	5TWX7036A1	5PX*B004AS3	S8X1B080M4PSC	21,000	\$2,940
216764935	TRANE	5TWX7036A1	5PX*B004AS3	S8X1B060M4PTC	21,000	\$2,940
216764221	TRANE	5TWX7036A1	5PX*B004AS3	S8X1B060M4PSC	21,000	\$2,940
216764931	TRANE	5TWX7036A1	5PX*B004AS3	S8X1A040M3PTC	21,400	\$2,996
216764222	TRANE	5TWX7036A1	5PX*B004AS3	S8X1A040M3PSC	21,400	\$2,996
216766894	TRANE	5TWX7036A1	5PX*B004AS3	S8V2B080M4PDB	21,000	\$2,940
216766895	TRANE	5TWX7036A1	5PX*B004AS3	S8V2B080M4PCB	21,000	\$2,940
216766893	TRANE	5TWX7036A1	5PX*B004AS3	S8V2B060M4PDB	21,200	\$2,968
216766898	TRANE	5TWX7036A1	5PX*B004AS3	S8V2B060M4PCB	21,200	\$2,968
216766891	TRANE	5TWX7036A1	5PX*B004AS3	S8V2A040M3PDB	21,000	\$2,940
216766897	TRANE	5TWX7036A1	5PX*B004AS3	S8V2A040M3PCB	21,000	\$2,940
216764223	TRANE	5TWX7036A1	5PX*B004AS3	N/A	21,800	\$3,052
216764232	TRANE	5TWX7036A1	5PX*B004AS3	L9X1B070U4VSA	21,600	\$3,024
216764229	TRANE	5TWX7036A1	5PX*B004AS3	L9X1A050U3VSA	21,800	\$3,052
216764228	TRANE	5TWX7036A1	5PX*B004AS3	L8V1B080U4VSB	21,400	\$2,996
216764227	TRANE	5TWX7036A1	5PX*B004AS3	L8V1A060U3VSB	20,800	\$2,912
216764226	TRANE	5TWX7036A1	5PX*B004AS3	L8V1A040U3VSB	21,200	\$2,968
216764225	TRANE	5TWX7036A1	5PX*B004AS3	*UHMB080CCV3	21,000	\$2,940
216764224	TRANE	5TWX7036A1	5PX*B004AS3	*UHMB060CCV3	21,000	\$2,940
216770096	TRANE	5TWX7024A1	5TXCC009AS3	*UHMC100CCV4	15,100	\$2,114
216764218	TRANE	5TWX7024A1	5TXCC009AS3	*DHMC100CCV4	14,800	\$2,072
216770095	TRANE	5TWX7024A1	5TXCC007AS3	*UHMC100CCV4	15,200	\$2,128
216764217	TRANE	5TWX7024A1	5TXCC007AS3	*DHMC100CCV4	14,900	\$2,086
216764216	TRANE	5TWX7024A1	5TXCC005AS3	N/A	15,700	\$2,198
216770094	TRANE	5TWX7024A1	5TXCC005AS3	*UHMC100CCV4	15,000	\$2,100
216764215	TRANE	5TWX7024A1	5TXCC005AS3	*DHMC100CCV4	15,100	\$2,114

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766873	TRANE	5TWX7024A1	5TXCB006AS3	S9X2B080D4PSB	15,100	\$2,114
216766870	TRANE	5TWX7024A1	5TXCB006AS3	S9X2B060U4PSB	15,400	\$2,156
216766872	TRANE	5TWX7024A1	5TXCB006AS3	S9X2B060D3PSB	15,000	\$2,100
216766869	TRANE	5TWX7024A1	5TXCB006AS3	S9X2B040U3PSB	15,500	\$2,170
216766871	TRANE	5TWX7024A1	5TXCB006AS3	S9X2B040D3PSB	15,100	\$2,114
216766867	TRANE	5TWX7024A1	5TXCB006AS3	S9X1B080D4PSB	15,100	\$2,114
216766881	TRANE	5TWX7024A1	5TXCB006AS3	S9X1B060U4PSB	15,400	\$2,156
216766884	TRANE	5TWX7024A1	5TXCB006AS3	S9X1B060D3PSB	15,000	\$2,100
216766880	TRANE	5TWX7024A1	5TXCB006AS3	S9X1B040U3PSB	15,500	\$2,170
216766883	TRANE	5TWX7024A1	5TXCB006AS3	S9X1B040D3PSB	15,100	\$2,114
216764207	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B080U4VSB	15,500	\$2,170
216764206	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B080U4PSC	15,500	\$2,170
216764214	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B080D4VSB	15,200	\$2,128
216764213	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B080D4PSC	15,200	\$2,128
216766879	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B060U4VSB	15,500	\$2,170
216764205	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B060U4PSC	15,500	\$2,170
216764204	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B060U3VSB	15,500	\$2,170
216764212	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B060D3VSB	15,100	\$2,114
216764211	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B060D3PSC	15,100	\$2,114
216764203	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B040U3VSB	15,500	\$2,170
216764202	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B040U3PSC	15,500	\$2,170
216766882	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B040D3VSB	15,200	\$2,128
216764210	TRANE	5TWX7024A1	5TXCB006AS3	S9V2B040D3PSC	15,200	\$2,128
216766868	TRANE	5TWX7024A1	5TXCB006AS3	S8V2B080M4PDB	15,500	\$2,170
216766878	TRANE	5TWX7024A1	5TXCB006AS3	S8V2B080M4PCB	15,500	\$2,170
216766885	TRANE	5TWX7024A1	5TXCB006AS3	S8V2B060M4PDB	15,400	\$2,156
216766877	TRANE	5TWX7024A1	5TXCB006AS3	S8V2B060M4PCB	15,400	\$2,156
216766866	TRANE	5TWX7024A1	5TXCB006AS3	S8V2A040M3PDB	15,500	\$2,170
216766876	TRANE	5TWX7024A1	5TXCB006AS3	S8V2A040M3PCB	15,500	\$2,170
216764201	TRANE	5TWX7024A1	5TXCB006AS3	L8V1B080U4VSB	15,400	\$2,156
216764200	TRANE	5TWX7024A1	5TXCB006AS3	L8V1A060U3VSB	15,500	\$2,170
216764199	TRANE	5TWX7024A1	5TXCB006AS3	L8V1A040U3VSB	15,500	\$2,170
216764198	TRANE	5TWX7024A1	5TXCB006AS3	*UHMB080CCV3	15,400	\$2,156
216764197	TRANE	5TWX7024A1	5TXCB006AS3	*UHMB060CCV3	15,400	\$2,156
216764209	TRANE	5TWX7024A1	5TXCB006AS3	*DHMB080CCV3	15,300	\$2,142
216764208	TRANE	5TWX7024A1	5TXCB006AS3	*DHMB060CCV3	15,200	\$2,128
216766854	TRANE	5TWX7024A1	5TXCB004AS3	S9X2B080D4PSB	15,000	\$2,100
216766851	TRANE	5TWX7024A1	5TXCB004AS3	S9X2B060U4PSB	15,300	\$2,142

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766853	TRANE	5TWX7024A1	5TXCB004AS3	S9X2B060D3PSB	15,100	\$2,114
216766850	TRANE	5TWX7024A1	5TXCB004AS3	S9X2B040U3PSB	15,300	\$2,142
216766852	TRANE	5TWX7024A1	5TXCB004AS3	S9X2B040D3PSB	14,900	\$2,086
216766861	TRANE	5TWX7024A1	5TXCB004AS3	S9X1B080D4PSB	15,000	\$2,100
216766849	TRANE	5TWX7024A1	5TXCB004AS3	S9X1B060U4PSB	15,300	\$2,142
216766860	TRANE	5TWX7024A1	5TXCB004AS3	S9X1B060D3PSB	15,100	\$2,114
216766848	TRANE	5TWX7024A1	5TXCB004AS3	S9X1B040U3PSB	15,300	\$2,142
216766859	TRANE	5TWX7024A1	5TXCB004AS3	S9X1B040D3PSB	14,900	\$2,086
216764185	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B080U4VSB	15,300	\$2,142
216764184	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B080U4PSC	15,300	\$2,142
216764193	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B080D4VSB	15,000	\$2,100
216764196	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B080D4PSC	15,000	\$2,100
216766847	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B060U4VSB	15,300	\$2,142
216764183	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B060U4PSC	15,300	\$2,142
216764182	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B060U3VSB	15,300	\$2,142
216764195	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B060D3VSB	15,000	\$2,100
216764194	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B060D3PSC	15,000	\$2,100
216764181	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B040U3VSB	15,400	\$2,156
216764180	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B040U3PSC	15,300	\$2,142
216766858	TRANE	5TWX7024A1	5TXCB004AS3	S9V2B040D3VSB	15,100	\$2,114
216764919	TRANE	5TWX7024A1	5TXCB004AS3	S8X2B080M4PTC	15,100	\$2,114
216764924	TRANE	5TWX7024A1	5TXCB004AS3	S8X2B080M4PSC	15,100	\$2,114
216764920	TRANE	5TWX7024A1	5TXCB004AS3	S8X2B060M4PTC	15,200	\$2,128
216764921	TRANE	5TWX7024A1	5TXCB004AS3	S8X2A040M3PTC	15,300	\$2,142
216764925	TRANE	5TWX7024A1	5TXCB004AS3	S8X2A040M3PSC	15,300	\$2,142
216764927	TRANE	5TWX7024A1	5TXCB004AS3	S8X1B080M4PTC	15,100	\$2,114
216764179	TRANE	5TWX7024A1	5TXCB004AS3	S8X1B080M4PSC	15,100	\$2,114
216764926	TRANE	5TWX7024A1	5TXCB004AS3	S8X1B060M4PTC	15,200	\$2,128
216764178	TRANE	5TWX7024A1	5TXCB004AS3	S8X1B060M4PSC	15,200	\$2,128
216764922	TRANE	5TWX7024A1	5TXCB004AS3	S8X1B040M2PTC	15,200	\$2,128
216764177	TRANE	5TWX7024A1	5TXCB004AS3	S8X1B040M2PSC	15,200	\$2,128
216764923	TRANE	5TWX7024A1	5TXCB004AS3	S8X1A040M3PTC	15,300	\$2,142
216764176	TRANE	5TWX7024A1	5TXCB004AS3	S8X1A040M3PSC	15,300	\$2,142
216766857	TRANE	5TWX7024A1	5TXCB004AS3	S8V2B080M4PDB	15,300	\$2,142
216766865	TRANE	5TWX7024A1	5TXCB004AS3	S8V2B080M4PCB	15,300	\$2,142
216766856	TRANE	5TWX7024A1	5TXCB004AS3	S8V2B060M4PDB	15,400	\$2,156
216766864	TRANE	5TWX7024A1	5TXCB004AS3	S8V2B060M4PCB	15,400	\$2,156
216766855	TRANE	5TWX7024A1	5TXCB004AS3	S8V2A040M3PDB	15,500	\$2,170

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766863	TRANE	5TWX7024A1	5TXCB004AS3	S8V2A040M3PCB	15,500	\$2,170
216764175	TRANE	5TWX7024A1	5TXCB004AS3	L9X1B070U4VSA	15,200	\$2,128
216764174	TRANE	5TWX7024A1	5TXCB004AS3	L9X1A050U3VSA	15,700	\$2,198
216764188	TRANE	5TWX7024A1	5TXCB004AS3	L8V1B080U4VSB	15,400	\$2,156
216764189	TRANE	5TWX7024A1	5TXCB004AS3	L8V1A060U3VSB	15,400	\$2,156
216764190	TRANE	5TWX7024A1	5TXCB004AS3	L8V1A040U3VSB	15,400	\$2,156
216764191	TRANE	5TWX7024A1	5TXCB004AS3	*UHMB080CCV3	15,300	\$2,142
216764192	TRANE	5TWX7024A1	5TXCB004AS3	*UHMB060CCV3	15,300	\$2,142
216764187	TRANE	5TWX7024A1	5TXCB004AS3	*DHMB080CCV3	15,000	\$2,100
216764186	TRANE	5TWX7024A1	5TXCB004AS3	*DHMB060CCV3	14,900	\$2,086
216764173	TRANE	5TWX7024A1	5TEMCD05AV41+TD	N/A	15,200	\$2,128
216764172	TRANE	5TWX7024A1	5TEMCD04AV31+TD	N/A	15,200	\$2,128
216764171	TRANE	5TWX7024A1	5TEMCB03AV31+TD	N/A	15,500	\$2,170
216764170	TRANE	5TWX7024A1	5TEMCB02AV21+TD	N/A	15,600	\$2,184
216764169	TRANE	5TWX7024A1	5TEM6D05AV41+TD	N/A	15,500	\$2,170
216764168	TRANE	5TWX7024A1	5TEM6D04AV31+TD	N/A	15,500	\$2,170
216764167	TRANE	5TWX7024A1	5TEM6B03AV21+TD	N/A	15,600	\$2,184
216764166	TRANE	5TWX7024A1	5TEM6B02AV21+TD	N/A	15,600	\$2,184
216770093	TRANE	5TWX7024A1	5TAMXD04AV31	N/A	15,400	\$2,156
216770092	TRANE	5TWX7024A1	5TAMXC03AV31	N/A	15,300	\$2,142
216770091	TRANE	5TWX7024A1	5TAM5C03AC21	N/A	15,100	\$2,114
216770090	TRANE	5TWX7024A1	5PX*CD09AS3	*DHMC100CCV4	15,100	\$2,114
216770089	TRANE	5TWX7024A1	5PX*CD07AS3	*DHMC100CCV4	15,300	\$2,142
216770088	TRANE	5TWX7024A1	5PX*C009AS3	*UHMC100CCV4	15,100	\$2,114
216764165	TRANE	5TWX7024A1	5PX*C009AS3	*DHMC100CCV4	14,800	\$2,072
216770087	TRANE	5TWX7024A1	5PX*C007AS3	*UHMC100CCV4	15,200	\$2,128
216764164	TRANE	5TWX7024A1	5PX*C007AS3	*DHMC100CCV4	15,200	\$2,128
216764162	TRANE	5TWX7024A1	5PX*C005AS3	N/A	15,700	\$2,198
216770086	TRANE	5TWX7024A1	5PX*C005AS3	*UHMC100CCV4	15,000	\$2,100
216764163	TRANE	5TWX7024A1	5PX*C005AS3	*DHMC100CCV4	15,100	\$2,114
216766833	TRANE	5TWX7024A1	5PX*BD06AS3	S9X2B080D4PSB	15,400	\$2,156
216766832	TRANE	5TWX7024A1	5PX*BD06AS3	S9X2B060D3PSB	15,500	\$2,170
216766831	TRANE	5TWX7024A1	5PX*BD06AS3	S9X2B040D3PSB	15,400	\$2,156
216766830	TRANE	5TWX7024A1	5PX*BD06AS3	S9X1B080D4PSB	15,400	\$2,156
216766844	TRANE	5TWX7024A1	5PX*BD06AS3	S9X1B060D3PSB	15,500	\$2,170
216766843	TRANE	5TWX7024A1	5PX*BD06AS3	S9X1B040D3PSB	15,400	\$2,156
216764160	TRANE	5TWX7024A1	5PX*BD06AS3	S9V2B080D4VSB	15,500	\$2,170
216764161	TRANE	5TWX7024A1	5PX*BD06AS3	S9V2B080D4PSC	15,500	\$2,170

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764159	TRANE	5TWX7024A1	5PX*BD06AS3	S9V2B060D3VSB	15,500	\$2,170
216764155	TRANE	5TWX7024A1	5PX*BD06AS3	S9V2B060D3PSC	15,500	\$2,170
216766842	TRANE	5TWX7024A1	5PX*BD06AS3	S9V2B040D3VSB	15,500	\$2,170
216764158	TRANE	5TWX7024A1	5PX*BD06AS3	S9V2B040D3PSC	15,500	\$2,170
216766836	TRANE	5TWX7024A1	5PX*BD06AS3	S8V2B080M4PDB	15,500	\$2,170
216766841	TRANE	5TWX7024A1	5PX*BD06AS3	S8V2B080M4PCB	15,500	\$2,170
216766835	TRANE	5TWX7024A1	5PX*BD06AS3	S8V2B060M4PDB	15,500	\$2,170
216766840	TRANE	5TWX7024A1	5PX*BD06AS3	S8V2B060M4PCB	15,500	\$2,170
216766834	TRANE	5TWX7024A1	5PX*BD06AS3	S8V2A040M3PDB	15,600	\$2,184
216766839	TRANE	5TWX7024A1	5PX*BD06AS3	S8V2A040M3PCB	15,600	\$2,184
216764157	TRANE	5TWX7024A1	5PX*BD06AS3	*DHMB080CCV3	15,500	\$2,170
216764156	TRANE	5TWX7024A1	5PX*BD06AS3	*DHMB060CCV3	15,600	\$2,184
216766826	TRANE	5TWX7024A1	5PX*BD04AS3	S9X2B060D3PSB	15,400	\$2,156
216766825	TRANE	5TWX7024A1	5PX*BD04AS3	S9X1B060D3PSB	15,400	\$2,156
216764153	TRANE	5TWX7024A1	5PX*BD04AS3	S9V2B080D4VSB	15,300	\$2,142
216764152	TRANE	5TWX7024A1	5PX*BD04AS3	S9V2B080D4PSC	15,300	\$2,142
216766820	TRANE	5TWX7024A1	5PX*BD04AS3	S9V2B040D3VSB	15,400	\$2,156
216764154	TRANE	5TWX7024A1	5PX*BD04AS3	S9V2B040D3PSC	15,400	\$2,156
216766824	TRANE	5TWX7024A1	5PX*BD04AS3	S8V2B080M4PDB	15,300	\$2,142
216766821	TRANE	5TWX7024A1	5PX*BD04AS3	S8V2B080M4PCB	15,300	\$2,142
216766828	TRANE	5TWX7024A1	5PX*BD04AS3	S8V2B060M4PDB	15,400	\$2,156
216766822	TRANE	5TWX7024A1	5PX*BD04AS3	S8V2B060M4PCB	15,400	\$2,156
216766827	TRANE	5TWX7024A1	5PX*BD04AS3	S8V2A040M3PDB	15,400	\$2,156
216766823	TRANE	5TWX7024A1	5PX*BD04AS3	S8V2A040M3PCB	15,400	\$2,156
216764151	TRANE	5TWX7024A1	5PX*BD04AS3	N/A	15,800	\$2,212
216764150	TRANE	5TWX7024A1	5PX*BD04AS3	*DHMB060CCV3	15,400	\$2,156
216766804	TRANE	5TWX7024A1	5PX*B006AS3	S9X2B080D4PSB	15,100	\$2,114
216766806	TRANE	5TWX7024A1	5PX*B006AS3	S9X2B060U4PSB	15,400	\$2,156
216766805	TRANE	5TWX7024A1	5PX*B006AS3	S9X2B060D3PSB	15,200	\$2,128
216766800	TRANE	5TWX7024A1	5PX*B006AS3	S9X2B040U3PSB	15,500	\$2,170
216766807	TRANE	5TWX7024A1	5PX*B006AS3	S9X2B040D3PSB	15,100	\$2,114
216766808	TRANE	5TWX7024A1	5PX*B006AS3	S9X1B080D4PSB	15,100	\$2,114
216766812	TRANE	5TWX7024A1	5PX*B006AS3	S9X1B060U4PSB	15,400	\$2,156
216766809	TRANE	5TWX7024A1	5PX*B006AS3	S9X1B060D3PSB	15,200	\$2,128
216766813	TRANE	5TWX7024A1	5PX*B006AS3	S9X1B040U3PSB	15,500	\$2,170
216766810	TRANE	5TWX7024A1	5PX*B006AS3	S9X1B040D3PSB	15,100	\$2,114
216764144	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B080U4VSB	15,500	\$2,170
216764145	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B080U4PSC	15,500	\$2,170

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764137	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B080D4VSB	15,200	\$2,128
216764138	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B080D4PSC	15,200	\$2,128
216766814	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B060U4VSB	15,500	\$2,170
216764146	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B060U4PSC	15,500	\$2,170
216764147	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B060U3VSB	15,500	\$2,170
216764139	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B060D3VSB	15,300	\$2,142
216764140	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B060D3PSC	15,300	\$2,142
216764148	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B040U3VSB	15,500	\$2,170
216764149	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B040U3PSC	15,500	\$2,170
216766811	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B040D3VSB	15,000	\$2,100
216764141	TRANE	5TWX7024A1	5PX*B006AS3	S9V2B040D3PSC	15,200	\$2,128
216766801	TRANE	5TWX7024A1	5PX*B006AS3	S8V2B080M4PDB	15,500	\$2,170
216766815	TRANE	5TWX7024A1	5PX*B006AS3	S8V2B080M4PCB	15,500	\$2,170
216766802	TRANE	5TWX7024A1	5PX*B006AS3	S8V2B060M4PDB	15,500	\$2,170
216766816	TRANE	5TWX7024A1	5PX*B006AS3	S8V2B060M4PCB	15,500	\$2,170
216766803	TRANE	5TWX7024A1	5PX*B006AS3	S8V2A040M3PDB	15,600	\$2,184
216766819	TRANE	5TWX7024A1	5PX*B006AS3	S8V2A040M3PCB	15,600	\$2,184
216764136	TRANE	5TWX7024A1	5PX*B006AS3	L8V1B080U4VSB	15,400	\$2,156
216764132	TRANE	5TWX7024A1	5PX*B006AS3	L8V1A060U3VSB	15,500	\$2,170
216764133	TRANE	5TWX7024A1	5PX*B006AS3	L8V1A040U3VSB	15,500	\$2,170
216764134	TRANE	5TWX7024A1	5PX*B006AS3	*UHMB080CCV3	15,400	\$2,156
216764135	TRANE	5TWX7024A1	5PX*B006AS3	*UHMB060CCV3	15,400	\$2,156
216764142	TRANE	5TWX7024A1	5PX*B006AS3	*DHMB080CCV3	15,300	\$2,142
216764143	TRANE	5TWX7024A1	5PX*B006AS3	*DHMB060CCV3	15,100	\$2,114
216766793	TRANE	5TWX7024A1	5PX*B004AS3	S9X2B080D4PSB	15,000	\$2,100
216766794	TRANE	5TWX7024A1	5PX*B004AS3	S9X2B060U4PSB	15,300	\$2,142
216766790	TRANE	5TWX7024A1	5PX*B004AS3	S9X2B060D3PSB	15,100	\$2,114
216766792	TRANE	5TWX7024A1	5PX*B004AS3	S9X2B040U3PSB	15,400	\$2,156
216766791	TRANE	5TWX7024A1	5PX*B004AS3	S9X2B040D3PSB	15,000	\$2,100
216766795	TRANE	5TWX7024A1	5PX*B004AS3	S9X1B080D4PSB	15,000	\$2,100
216766799	TRANE	5TWX7024A1	5PX*B004AS3	S9X1B060U4PSB	15,300	\$2,142
216766796	TRANE	5TWX7024A1	5PX*B004AS3	S9X1B060D3PSB	15,100	\$2,114
216766782	TRANE	5TWX7024A1	5PX*B004AS3	S9X1B040U3PSB	15,400	\$2,156
216766797	TRANE	5TWX7024A1	5PX*B004AS3	S9X1B040D3PSB	15,000	\$2,100
216764124	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B080U4VSB	15,300	\$2,142
216764123	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B080U4PSC	15,300	\$2,142
216764108	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B080D4VSB	15,000	\$2,100
216764130	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B080D4PSC	15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766783	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B060U4VSB	15,300	\$2,142
216764122	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B060U4PSC	15,300	\$2,142
216764121	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B060U3VSB	15,300	\$2,142
216764129	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B060D3VSB	15,100	\$2,114
216764128	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B060D3PSC	15,100	\$2,114
216764120	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B040U3VSB	15,300	\$2,142
216764119	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B040U3PSC	15,300	\$2,142
216766780	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B040D3VSB	15,000	\$2,100
216764127	TRANE	5TWX7024A1	5PX*B004AS3	S9V2B040D3PSC	15,000	\$2,100
216764911	TRANE	5TWX7024A1	5PX*B004AS3	S8X2B080M4PTC	15,100	\$2,114
216764915	TRANE	5TWX7024A1	5PX*B004AS3	S8X2B080M4PSC	15,100	\$2,114
216764912	TRANE	5TWX7024A1	5PX*B004AS3	S8X2B060M4PTC	15,200	\$2,128
216764916	TRANE	5TWX7024A1	5PX*B004AS3	S8X2B060M4PSC	15,200	\$2,128
216764918	TRANE	5TWX7024A1	5PX*B004AS3	S8X2A040M3PTC	15,300	\$2,142
216764917	TRANE	5TWX7024A1	5PX*B004AS3	S8X2A040M3PSC	15,300	\$2,142
216764913	TRANE	5TWX7024A1	5PX*B004AS3	S8X1B080M4PTC	15,100	\$2,114
216764118	TRANE	5TWX7024A1	5PX*B004AS3	S8X1B080M4PSC	15,100	\$2,114
216764909	TRANE	5TWX7024A1	5PX*B004AS3	S8X1B060M4PTC	15,200	\$2,128
216764117	TRANE	5TWX7024A1	5PX*B004AS3	S8X1B060M4PSC	15,200	\$2,128
216764910	TRANE	5TWX7024A1	5PX*B004AS3	S8X1B040M2PTC	15,200	\$2,128
216764116	TRANE	5TWX7024A1	5PX*B004AS3	S8X1B040M2PSC	15,200	\$2,128
216764914	TRANE	5TWX7024A1	5PX*B004AS3	S8X1A040M3PTC	15,300	\$2,142
216764115	TRANE	5TWX7024A1	5PX*B004AS3	S8X1A040M3PSC	15,300	\$2,142
216766789	TRANE	5TWX7024A1	5PX*B004AS3	S8V2B080M4PDB	15,300	\$2,142
216766784	TRANE	5TWX7024A1	5PX*B004AS3	S8V2B080M4PCB	15,300	\$2,142
216766788	TRANE	5TWX7024A1	5PX*B004AS3	S8V2B060M4PDB	15,400	\$2,156
216766785	TRANE	5TWX7024A1	5PX*B004AS3	S8V2B060M4PCB	15,400	\$2,156
216766787	TRANE	5TWX7024A1	5PX*B004AS3	S8V2A040M3PDB	15,400	\$2,156
216766786	TRANE	5TWX7024A1	5PX*B004AS3	S8V2A040M3PCB	15,400	\$2,156
216764114	TRANE	5TWX7024A1	5PX*B004AS3	N/A	15,700	\$2,198
216764113	TRANE	5TWX7024A1	5PX*B004AS3	L9X1B070U4VSA	15,200	\$2,128
216764112	TRANE	5TWX7024A1	5PX*B004AS3	L9X1A050U3VSA	15,700	\$2,198
216764111	TRANE	5TWX7024A1	5PX*B004AS3	L8V1B080U4VSB	15,500	\$2,170
216764107	TRANE	5TWX7024A1	5PX*B004AS3	L8V1A060U3VSB	15,400	\$2,156
216764131	TRANE	5TWX7024A1	5PX*B004AS3	L8V1A040U3VSB	15,400	\$2,156
216764109	TRANE	5TWX7024A1	5PX*B004AS3	*UHMB080CCV3	15,300	\$2,142
216764110	TRANE	5TWX7024A1	5PX*B004AS3	*UHMB060CCV3	15,300	\$2,142
216764126	TRANE	5TWX7024A1	5PX*B004AS3	*DHMB080CCV3	15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764125	TRANE	5TWX7024A1	5PX*B004AS3	*DHMB060CCV3	14,900	\$2,086
215865073	TRANE	5TWV8X60A1	5TXCC007AS3	P0V0C000M50SD+LRP	50,000	\$7,000
215864985	TRANE	5TWV8X48A1	5TXCD010AS3	S9V2C100U5PSC+LRP	42,000	\$5,880
215864979	TRANE	5TWV8X48A1	5TXCD010AS3	S9V2C100U4VSB+LRP	42,000	\$5,880
215864981	TRANE	5TWV8X48A1	5TXCD010AS3	S9V2C080U5PSC+LRP	42,500	\$5,950
215864983	TRANE	5TWV8X48A1	5TXCD010AS3	S8V2D120M5PDB	42,500	\$5,950
215864995	TRANE	5TWV8X48A1	5TXCD010AS3	S8V2D120M5PCB	42,500	\$5,950
215864987	TRANE	5TWV8X48A1	5TXCD010AS3	S8V2C100M5PDB	42,500	\$5,950
215864989	TRANE	5TWV8X48A1	5TXCD010AS3	S8V2C100M5PCB	42,500	\$5,950
215864991	TRANE	5TWV8X48A1	5TXCD010AS3	S8V2C080M5PDB	42,000	\$5,880
215864993	TRANE	5TWV8X48A1	5TXCD010AS3	S8V2C080M5PCB	42,000	\$5,880
215865113	TRANE	5TWV8X48A1	5TXCD010AS3	P0V0D000M50SD+LRP	41,500	\$5,810
215865111	TRANE	5TWV8X48A1	5TXCD010AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864977	TRANE	5TWV8X48A1	5TXCD010AS3	L8V1C100U5VSB+LRP	42,000	\$5,880
215864975	TRANE	5TWV8X48A1	5TXCD010AS3	*UHMD120CCV5+LRP	42,000	\$5,880
215864957	TRANE	5TWV8X48A1	5TXCD008AS3	S9V2C100U5PSC+LRP	42,500	\$5,950
215864959	TRANE	5TWV8X48A1	5TXCD008AS3	S9V2C100U4VSB+LRP	42,500	\$5,950
215864961	TRANE	5TWV8X48A1	5TXCD008AS3	S9V2C080U5PSC+LRP	43,000	\$6,020
215864963	TRANE	5TWV8X48A1	5TXCD008AS3	S8V2D120M5PDB	42,500	\$5,950
215864965	TRANE	5TWV8X48A1	5TXCD008AS3	S8V2D120M5PCB	42,500	\$5,950
215864967	TRANE	5TWV8X48A1	5TXCD008AS3	S8V2C100M5PDB	42,500	\$5,950
215864969	TRANE	5TWV8X48A1	5TXCD008AS3	S8V2C100M5PCB	42,500	\$5,950
215864971	TRANE	5TWV8X48A1	5TXCD008AS3	S8V2C080M5PDB	42,500	\$5,950
215864973	TRANE	5TWV8X48A1	5TXCD008AS3	S8V2C080M5PCB	42,500	\$5,950
215865109	TRANE	5TWV8X48A1	5TXCD008AS3	P0V0D000M50SD+LRP	42,500	\$5,950
215865107	TRANE	5TWV8X48A1	5TXCD008AS3	P0V0C000M50SD+LRP	42,500	\$5,950
215864953	TRANE	5TWV8X48A1	5TXCD008AS3	L8V1C100U5VSB+LRP	42,500	\$5,950
215864955	TRANE	5TWV8X48A1	5TXCD008AS3	*UHMD120CCV5+LRP	42,500	\$5,950
215864945	TRANE	5TWV8X48A1	5TXCC009AS3	S9V2C100U5PSC+LRP	42,500	\$5,950
215864939	TRANE	5TWV8X48A1	5TXCC009AS3	S9V2C100U4VSB+LRP	42,500	\$5,950
215864941	TRANE	5TWV8X48A1	5TXCC009AS3	S8V2C100M5PDB	42,500	\$5,950
215864943	TRANE	5TWV8X48A1	5TXCC009AS3	S8V2C100M5PCB	42,500	\$5,950
215864951	TRANE	5TWV8X48A1	5TXCC009AS3	S8V2C080M5PCB	42,000	\$5,880
215865105	TRANE	5TWV8X48A1	5TXCC009AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864947	TRANE	5TWV8X48A1	5TXCC009AS3	L8V1C100U5VSB+LRP	42,000	\$5,880
215864949	TRANE	5TWV8X48A1	5TXCC009AS3	*UHMC100CCV4+LRP	42,000	\$5,880
215869122	TRANE	5TWV8X48A1	5TXCC007AS3	S9V2C100U5VSB+LRP	43,000	\$6,020
215864923	TRANE	5TWV8X48A1	5TXCC007AS3	S9V2C100U5PSC+LRP	43,000	\$6,020

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864925	TRANE	5TWV8X48A1	5TXCC007AS3	S9V2C100U4VSB+LRP	43,000	\$6,020
215864927	TRANE	5TWV8X48A1	5TXCC007AS3	S9V2C080U5PSC+LRP	43,000	\$6,020
215864929	TRANE	5TWV8X48A1	5TXCC007AS3	S8V2C100M5PDB	43,000	\$6,020
215864931	TRANE	5TWV8X48A1	5TXCC007AS3	S8V2C100M5PCB	43,000	\$6,020
215864933	TRANE	5TWV8X48A1	5TXCC007AS3	S8V2C080M5PDB	42,500	\$5,950
215864935	TRANE	5TWV8X48A1	5TXCC007AS3	S8V2C080M5PCB	42,500	\$5,950
215865103	TRANE	5TWV8X48A1	5TXCC007AS3	P0V0C000M50SD+LRP	42,500	\$5,950
215864921	TRANE	5TWV8X48A1	5TXCC007AS3	L8V1C100U5VSB+LRP	42,500	\$5,950
215864937	TRANE	5TWV8X48A1	5TXCC007AS3	*UHMC100CCV4+LRP	42,500	\$5,950
215865069	TRANE	5TWV8X48A1	5TXCC005AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864665	TRANE	5TWV8X48A1	5TXCB006AS3	S9V2B080U4VSB+LRP	43,000	\$6,020
215864667	TRANE	5TWV8X48A1	5TXCB006AS3	S9V2B080U4PSC+LRP	43,000	\$6,020
215869120	TRANE	5TWV8X48A1	5TXCB006AS3	S9V2B060U4VSB+LRP	43,000	\$6,020
215864669	TRANE	5TWV8X48A1	5TXCB006AS3	S9V2B060U4PSC+LRP	43,000	\$6,020
215864671	TRANE	5TWV8X48A1	5TXCB006AS3	S8V2B080M4PDB	43,000	\$6,020
215864673	TRANE	5TWV8X48A1	5TXCB006AS3	S8V2B080M4PCB	43,000	\$6,020
215864675	TRANE	5TWV8X48A1	5TXCB006AS3	S8V2B060M4PDB	43,000	\$6,020
215864677	TRANE	5TWV8X48A1	5TXCB006AS3	S8V2B060M4PCB	43,000	\$6,020
215865067	TRANE	5TWV8X48A1	5TXCB006AS3	P0V0B000M40SD+LRP	42,500	\$5,950
215864663	TRANE	5TWV8X48A1	5TXCB006AS3	L8V1B080U4VSB+LRP	43,000	\$6,020
215865043	TRANE	5TWV8X48A1	5TEMCD07AV51+TD	N/A	42,000	\$5,880
215865041	TRANE	5TWV8X48A1	5TEMCD05AV41+TD	N/A	42,000	\$5,880
216057014	TRANE	5TWV8X48A1	5TAMXD07AV51	N/A	41,500	\$5,810
216057012	TRANE	5TWV8X48A1	5TAMXD06AV41	N/A	42,500	\$5,950
216057010	TRANE	5TWV8X48A1	5TAMXD05AV41	N/A	42,500	\$5,950
215864909	TRANE	5TWV8X48A1	5PX*DD10AS3	S9V2C100D5PSC+LRP	42,000	\$5,880
215864905	TRANE	5TWV8X48A1	5PX*DD10AS3	S9V2C100D4VSB+LRP	42,000	\$5,880
215864907	TRANE	5TWV8X48A1	5PX*DD10AS3	S8V2D120M5PDB	42,500	\$5,950
215864919	TRANE	5TWV8X48A1	5PX*DD10AS3	S8V2D120M5PCB	42,500	\$5,950
215864911	TRANE	5TWV8X48A1	5PX*DD10AS3	S8V2C100M5PDB	42,000	\$5,880
215864913	TRANE	5TWV8X48A1	5PX*DD10AS3	S8V2C100M5PCB	42,000	\$5,880
215864915	TRANE	5TWV8X48A1	5PX*DD10AS3	S8V2C080M5PDB	42,000	\$5,880
215864917	TRANE	5TWV8X48A1	5PX*DD10AS3	S8V2C080M5PCB	42,000	\$5,880
215865101	TRANE	5TWV8X48A1	5PX*DD10AS3	P0V0D000M50SD+LRP	41,500	\$5,810
215865099	TRANE	5TWV8X48A1	5PX*DD10AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864903	TRANE	5TWV8X48A1	5PX*DD10AS3	*DHMC100CCV4+LRP	42,000	\$5,880
215864889	TRANE	5TWV8X48A1	5PX*D010AS3	S9V2C100U5PSC+LRP	42,000	\$5,880
215864891	TRANE	5TWV8X48A1	5PX*D010AS3	S9V2C100U4VSB+LRP	42,000	\$5,880

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864893	TRANE	5TWW8X48A1	5PX*D010AS3	S9V2C080U5PSC+LRP	42,000	\$5,880
215864895	TRANE	5TWW8X48A1	5PX*D010AS3	S8V2D120M5PDB	42,500	\$5,950
215864897	TRANE	5TWW8X48A1	5PX*D010AS3	S8V2D120M5PCB	42,500	\$5,950
215864899	TRANE	5TWW8X48A1	5PX*D010AS3	S8V2C100M5PDB	42,000	\$5,880
215864901	TRANE	5TWW8X48A1	5PX*D010AS3	S8V2C100M5PCB	42,000	\$5,880
215864887	TRANE	5TWW8X48A1	5PX*D010AS3	S8V2C080M5PDB	42,000	\$5,880
215864881	TRANE	5TWW8X48A1	5PX*D010AS3	S8V2C080M5PCB	42,000	\$5,880
215865095	TRANE	5TWW8X48A1	5PX*D010AS3	P0V0D000M50SD+LRP	41,500	\$5,810
215865097	TRANE	5TWW8X48A1	5PX*D010AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864883	TRANE	5TWW8X48A1	5PX*D010AS3	L8V1C100U5VSB+LRP	42,000	\$5,880
215864885	TRANE	5TWW8X48A1	5PX*D010AS3	*UHMD120CCV5+LRP	42,000	\$5,880
215864867	TRANE	5TWW8X48A1	5PX*D008AS3	S9V2C100U5PSC+LRP	42,500	\$5,950
215864877	TRANE	5TWW8X48A1	5PX*D008AS3	S9V2C100U4VSB+LRP	42,500	\$5,950
215864875	TRANE	5TWW8X48A1	5PX*D008AS3	S9V2C080U5PSC+LRP	43,000	\$6,020
215864873	TRANE	5TWW8X48A1	5PX*D008AS3	S8V2D120M5PDB	42,500	\$5,950
215864871	TRANE	5TWW8X48A1	5PX*D008AS3	S8V2D120M5PCB	42,500	\$5,950
215864869	TRANE	5TWW8X48A1	5PX*D008AS3	S8V2C100M5PDB	42,500	\$5,950
215864879	TRANE	5TWW8X48A1	5PX*D008AS3	S8V2C100M5PCB	42,500	\$5,950
215864865	TRANE	5TWW8X48A1	5PX*D008AS3	S8V2C080M5PDB	42,500	\$5,950
215864859	TRANE	5TWW8X48A1	5PX*D008AS3	S8V2C080M5PCB	42,500	\$5,950
215865091	TRANE	5TWW8X48A1	5PX*D008AS3	P0V0D000M50SD+LRP	42,500	\$5,950
215865093	TRANE	5TWW8X48A1	5PX*D008AS3	P0V0C000M50SD+LRP	42,500	\$5,950
215864861	TRANE	5TWW8X48A1	5PX*D008AS3	L8V1C100U5VSB+LRP	42,500	\$5,950
215864863	TRANE	5TWW8X48A1	5PX*D008AS3	*UHMD120CCV5+LRP	42,500	\$5,950
215864845	TRANE	5TWW8X48A1	5PX*CD09AS3	S9V2C100D5PSC+LRP	42,500	\$5,950
215864857	TRANE	5TWW8X48A1	5PX*CD09AS3	S9V2C100D4VSB+LRP	42,500	\$5,950
215864855	TRANE	5TWW8X48A1	5PX*CD09AS3	S8V2C100M5PDB	42,500	\$5,950
215864853	TRANE	5TWW8X48A1	5PX*CD09AS3	S8V2C100M5PCB	42,500	\$5,950
215864851	TRANE	5TWW8X48A1	5PX*CD09AS3	S8V2C080M5PDB	42,000	\$5,880
215864849	TRANE	5TWW8X48A1	5PX*CD09AS3	S8V2C080M5PCB	42,000	\$5,880
215865089	TRANE	5TWW8X48A1	5PX*CD09AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864847	TRANE	5TWW8X48A1	5PX*CD09AS3	*DHMC100CCV4+LRP	42,000	\$5,880
215864841	TRANE	5TWW8X48A1	5PX*C009AS3	S9V2C100U5PSC+LRP	42,500	\$5,950
215864827	TRANE	5TWW8X48A1	5PX*C009AS3	S9V2C100U4VSB+LRP	42,500	\$5,950
215864829	TRANE	5TWW8X48A1	5PX*C009AS3	S9V2C080U5PSC+LRP	42,500	\$5,950
215864831	TRANE	5TWW8X48A1	5PX*C009AS3	S8V2C100M5PDB	42,500	\$5,950
215864833	TRANE	5TWW8X48A1	5PX*C009AS3	S8V2C100M5PCB	42,500	\$5,950
215864835	TRANE	5TWW8X48A1	5PX*C009AS3	S8V2C080M5PDB	42,000	\$5,880

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864837	TRANE	5TWW8X48A1	5PX*C009AS3	S8V2C080M5PCB	42,000	\$5,880
215865087	TRANE	5TWW8X48A1	5PX*C009AS3	P0V0C000M50SD+LRP	42,000	\$5,880
215864839	TRANE	5TWW8X48A1	5PX*C009AS3	L8V1C100U5VSB+LRP	42,000	\$5,880
215864843	TRANE	5TWW8X48A1	5PX*C009AS3	*UHMC100CCV4+LRP	42,000	\$5,880
215869118	TRANE	5TWW8X48A1	5PX*C007AS3	S9V2C100U5VSB+LRP	43,000	\$6,020
215864649	TRANE	5TWW8X48A1	5PX*C007AS3	S9V2C100U5PSC+LRP	43,000	\$6,020
215864651	TRANE	5TWW8X48A1	5PX*C007AS3	S9V2C100U4VSB+LRP	43,000	\$6,020
215869116	TRANE	5TWW8X48A1	5PX*C007AS3	S9V2C080U5VSB+LRP	43,000	\$6,020
215864653	TRANE	5TWW8X48A1	5PX*C007AS3	S9V2C080U5PSC+LRP	43,000	\$6,020
215864655	TRANE	5TWW8X48A1	5PX*C007AS3	S8V2C100M5PDB	43,000	\$6,020
215864657	TRANE	5TWW8X48A1	5PX*C007AS3	S8V2C100M5PCB	43,000	\$6,020
215864659	TRANE	5TWW8X48A1	5PX*C007AS3	S8V2C080M5PDB	42,500	\$5,950
215864661	TRANE	5TWW8X48A1	5PX*C007AS3	S8V2C080M5PCB	43,000	\$6,020
215865065	TRANE	5TWW8X48A1	5PX*C007AS3	P0V0C000M50SD+LRP	42,500	\$5,950
215864647	TRANE	5TWW8X48A1	5PX*C007AS3	L8V1C100U5VSB+LRP	42,500	\$5,950
215864645	TRANE	5TWW8X48A1	5PX*C007AS3	*UHMC100CCV4+LRP	42,500	\$5,950
215864811	TRANE	5TWW8X48A1	5PX*B006AS3	S9V2B080U4VSB+LRP	43,000	\$6,020
215864813	TRANE	5TWW8X48A1	5PX*B006AS3	S9V2B080U4PSC+LRP	43,000	\$6,020
215869114	TRANE	5TWW8X48A1	5PX*B006AS3	S9V2B060U4VSB+LRP	43,000	\$6,020
215864815	TRANE	5TWW8X48A1	5PX*B006AS3	S9V2B060U4PSC+LRP	43,000	\$6,020
215864817	TRANE	5TWW8X48A1	5PX*B006AS3	S8V2B080M4PDB	43,000	\$6,020
215864825	TRANE	5TWW8X48A1	5PX*B006AS3	S8V2B080M4PCB	43,000	\$6,020
215864821	TRANE	5TWW8X48A1	5PX*B006AS3	S8V2B060M4PDB	43,000	\$6,020
215864823	TRANE	5TWW8X48A1	5PX*B006AS3	S8V2B060M4PCB	43,000	\$6,020
215865085	TRANE	5TWW8X48A1	5PX*B006AS3	P0V0B000M40SD+LRP	42,500	\$5,950
215864819	TRANE	5TWW8X48A1	5PX*B006AS3	L8V1B080U4VSB+LRP	43,000	\$6,020
216571324	TRANE	5TWW8X36A1	5TXCD010AS3	S8V2D120M5PDB	31,000	\$4,340
216571322	TRANE	5TWW8X36A1	5TXCD010AS3	S8V2D120M5PCB	31,000	\$4,340
216571318	TRANE	5TWW8X36A1	5TXCD008AS3	S8V2D120M5PDB	31,200	\$4,368
216571320	TRANE	5TWW8X36A1	5TXCD008AS3	S8V2D120M5PCB	31,200	\$4,368
216571308	TRANE	5TWW8X36A1	5TXCC009AS3	S8V2C100M5PDB	31,000	\$4,340
216571310	TRANE	5TWW8X36A1	5TXCC009AS3	S8V2C100M5PCB	31,000	\$4,340
216571312	TRANE	5TWW8X36A1	5TXCC009AS3	S8V2C080M5PDB	30,800	\$4,312
216571314	TRANE	5TWW8X36A1	5TXCC009AS3	S8V2C080M5PCB	30,800	\$4,312
216571316	TRANE	5TWW8X36A1	5TXCC009AS3	*UHMC100CCV4+LRP	30,800	\$4,312
215869112	TRANE	5TWW8X36A1	5TXCC007AS3	S9V2C100U5VSB+LRP	31,200	\$4,368
215869110	TRANE	5TWW8X36A1	5TXCC007AS3	S9V2C080U5VSB+LRP	31,200	\$4,368
216571302	TRANE	5TWW8X36A1	5TXCC007AS3	S8V2C100M5PDB	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216571298	TRANE	5TWV8X36A1	5TXCC007AS3	S8V2C100M5PCB	31,200	\$4,368
216571304	TRANE	5TWV8X36A1	5TXCC007AS3	S8V2C080M5PDB	31,000	\$4,340
216571306	TRANE	5TWV8X36A1	5TXCC007AS3	S8V2C080M5PCB	31,000	\$4,340
216571300	TRANE	5TWV8X36A1	5TXCC007AS3	*UHMC100CCV4+LRP	31,000	\$4,340
215869108	TRANE	5TWV8X36A1	5TXCC005AS3	S9V2C100U5VSB+LRP	31,200	\$4,368
215864637	TRANE	5TWV8X36A1	5TXCC005AS3	S9V2C100U5PSC+LRP	31,000	\$4,340
215864631	TRANE	5TWV8X36A1	5TXCC005AS3	S9V2C100U4VSB+LRP	31,200	\$4,368
215869106	TRANE	5TWV8X36A1	5TXCC005AS3	S9V2C080U5VSB+LRP	31,000	\$4,340
215864629	TRANE	5TWV8X36A1	5TXCC005AS3	S9V2C080U5PSC+LRP	31,000	\$4,340
215864633	TRANE	5TWV8X36A1	5TXCC005AS3	S8V2C100M5PDB	31,000	\$4,340
215864635	TRANE	5TWV8X36A1	5TXCC005AS3	S8V2C100M5PCB	31,400	\$4,396
215864643	TRANE	5TWV8X36A1	5TXCC005AS3	S8V2C080M5PDB	31,200	\$4,368
215864639	TRANE	5TWV8X36A1	5TXCC005AS3	S8V2C080M5PCB	31,200	\$4,368
215865063	TRANE	5TWV8X36A1	5TXCC005AS3	P0V0C000M50SD+LRP	31,000	\$4,340
215864641	TRANE	5TWV8X36A1	5TXCC005AS3	*UHMC100CCV4+LRP	30,800	\$4,312
215864599	TRANE	5TWV8X36A1	5TXCB006AS3	S9V2B080U4VSB+LRP	31,200	\$4,368
215864601	TRANE	5TWV8X36A1	5TXCB006AS3	S9V2B080U4PSC+LRP	31,200	\$4,368
215869104	TRANE	5TWV8X36A1	5TXCB006AS3	S9V2B060U4VSB+LRP	31,400	\$4,396
215864603	TRANE	5TWV8X36A1	5TXCB006AS3	S9V2B060U4PSC+LRP	31,400	\$4,396
215864605	TRANE	5TWV8X36A1	5TXCB006AS3	S9V2B060U3VSB+LRP	31,400	\$4,396
215864607	TRANE	5TWV8X36A1	5TXCB006AS3	S9V2B040U3VSB+LRP	31,400	\$4,396
215864609	TRANE	5TWV8X36A1	5TXCB006AS3	S9V2B040U3PSC+LRP	31,400	\$4,396
215864611	TRANE	5TWV8X36A1	5TXCB006AS3	S8V2B080M4PDB	31,400	\$4,396
215864613	TRANE	5TWV8X36A1	5TXCB006AS3	S8V2B080M4PCB	31,400	\$4,396
215864627	TRANE	5TWV8X36A1	5TXCB006AS3	S8V2B060M4PDB	31,200	\$4,368
215864625	TRANE	5TWV8X36A1	5TXCB006AS3	S8V2B060M4PCB	31,200	\$4,368
215864623	TRANE	5TWV8X36A1	5TXCB006AS3	S8V2A040M3PDB	31,200	\$4,368
215864621	TRANE	5TWV8X36A1	5TXCB006AS3	S8V2A040M3PCB	31,200	\$4,368
215865061	TRANE	5TWV8X36A1	5TXCB006AS3	P0V0A000M30SD+LRP	31,200	\$4,368
215864619	TRANE	5TWV8X36A1	5TXCB006AS3	L8V1B080U4VSB+LRP	31,400	\$4,396
215864617	TRANE	5TWV8X36A1	5TXCB006AS3	L8V1A060U3VSB+LRP	31,400	\$4,396
215864615	TRANE	5TWV8X36A1	5TXCB006AS3	L8V1A040U3VSB+LRP	31,400	\$4,396
215864597	TRANE	5TWV8X36A1	5TXCB006AS3	*UHMB080CCV3+LRP	31,200	\$4,368
215864595	TRANE	5TWV8X36A1	5TXCB006AS3	*UHMB060CCV3+LRP	31,400	\$4,396
215864591	TRANE	5TWV8X36A1	5TXCB004AS3	S9V2B080U4VSB+LRP	31,000	\$4,340
215864593	TRANE	5TWV8X36A1	5TXCB004AS3	S9V2B080U4PSC+LRP	31,000	\$4,340
215869102	TRANE	5TWV8X36A1	5TXCB004AS3	S9V2B060U4VSB+LRP	30,800	\$4,312
215864589	TRANE	5TWV8X36A1	5TXCB004AS3	S9V2B060U4PSC+LRP	31,200	\$4,368

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864569	TRANE	5TWV8X36A1	5TXCB004AS3	S9V2B060U3VSB+LRP	31,200	\$4,368
215864571	TRANE	5TWV8X36A1	5TXCB004AS3	S9V2B040U3VSB+LRP	30,800	\$4,312
215864573	TRANE	5TWV8X36A1	5TXCB004AS3	S9V2B040U3PSC+LRP	31,000	\$4,340
215864575	TRANE	5TWV8X36A1	5TXCB004AS3	S8V2B080M4PDB	31,200	\$4,368
215864577	TRANE	5TWV8X36A1	5TXCB004AS3	S8V2B080M4PCB	31,200	\$4,368
215864579	TRANE	5TWV8X36A1	5TXCB004AS3	S8V2B060M4PDB	31,000	\$4,340
215864581	TRANE	5TWV8X36A1	5TXCB004AS3	S8V2B060M4PCB	31,000	\$4,340
215865059	TRANE	5TWV8X36A1	5TXCB004AS3	P0V0A000M30SD+LRP	31,000	\$4,340
215864583	TRANE	5TWV8X36A1	5TXCB004AS3	L8V1B080U4VSB+LRP	31,200	\$4,368
216571296	TRANE	5TWV8X36A1	5TXCB004AS3	L8V1A060U3VSB+LRP	31,200	\$4,368
215864585	TRANE	5TWV8X36A1	5TXCB004AS3	*UHMB080CCV3+LRP	31,000	\$4,340
215864587	TRANE	5TWV8X36A1	5TXCB004AS3	*UHMB060CCV3+LRP	31,200	\$4,368
215865039	TRANE	5TWV8X36A1	5TEMCD05AV41+TD	N/A	31,000	\$4,340
215865037	TRANE	5TWV8X36A1	5TEMCB03AV31+TD	N/A	32,200	\$4,508
216057008	TRANE	5TWV8X36A1	5TAMXD07AV51	N/A	30,400	\$4,256
216057006	TRANE	5TWV8X36A1	5TAMXD06AV41	N/A	31,200	\$4,368
216057004	TRANE	5TWV8X36A1	5TAMXD05AV41	N/A	31,000	\$4,340
216057002	TRANE	5TWV8X36A1	5TAMXD04AV31	N/A	31,000	\$4,340
216057000	TRANE	5TWV8X36A1	5TAMXC03AV31	N/A	31,600	\$4,424
216571292	TRANE	5TWV8X36A1	5PX*DD10AS3	S8V2D120M5PDB	30,800	\$4,312
216571294	TRANE	5TWV8X36A1	5PX*DD10AS3	S8V2D120M5PCB	30,800	\$4,312
216571290	TRANE	5TWV8X36A1	5PX*D010AS3	S8V2D120M5PDB	30,800	\$4,312
216571288	TRANE	5TWV8X36A1	5PX*D010AS3	S8V2D120M5PCB	30,800	\$4,312
216571286	TRANE	5TWV8X36A1	5PX*D008AS3	S8V2D120M5PDB	31,200	\$4,368
216571284	TRANE	5TWV8X36A1	5PX*D008AS3	S8V2D120M5PCB	31,200	\$4,368
216571278	TRANE	5TWV8X36A1	5PX*CD09AS3	S8V2C100M5PDB	31,000	\$4,340
216571282	TRANE	5TWV8X36A1	5PX*CD09AS3	S8V2C100M5PCB	31,000	\$4,340
216571276	TRANE	5TWV8X36A1	5PX*CD09AS3	S8V2C080M5PDB	30,800	\$4,312
216571280	TRANE	5TWV8X36A1	5PX*CD09AS3	S8V2C080M5PCB	30,800	\$4,312
216571274	TRANE	5TWV8X36A1	5PX*CD09AS3	*DHMC100CCV4+LRP	30,800	\$4,312
215864805	TRANE	5TWV8X36A1	5PX*CD07AS3	S8V2C100M5PDB	31,800	\$4,452
215864807	TRANE	5TWV8X36A1	5PX*CD07AS3	S8V2C100M5PCB	31,800	\$4,452
215864809	TRANE	5TWV8X36A1	5PX*CD07AS3	S8V2C080M5PDB	31,600	\$4,424
215864803	TRANE	5TWV8X36A1	5PX*CD07AS3	S8V2C080M5PCB	31,600	\$4,424
215864801	TRANE	5TWV8X36A1	5PX*CD07AS3	*DHMC100CCV4+LRP	31,600	\$4,424
215869100	TRANE	5TWV8X36A1	5PX*CD05AS3	S9V2C100D5VSB+LRP	31,600	\$4,424
215864565	TRANE	5TWV8X36A1	5PX*CD05AS3	S9V2C100D5PSC+LRP	31,600	\$4,424
215864555	TRANE	5TWV8X36A1	5PX*CD05AS3	S9V2C100D4VSB+LRP	31,600	\$4,424

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864557	TRANE	5TWV8X36A1	5PX*CD05AS3	S8V2C100M5PDB	31,800	\$4,452
215864559	TRANE	5TWV8X36A1	5PX*CD05AS3	S8V2C100M5PCB	31,800	\$4,452
215864561	TRANE	5TWV8X36A1	5PX*CD05AS3	S8V2C080M5PDB	31,600	\$4,424
215864563	TRANE	5TWV8X36A1	5PX*CD05AS3	S8V2C080M5PCB	31,600	\$4,424
215864567	TRANE	5TWV8X36A1	5PX*CD05AS3	*DHMC100CCV4+LRP	31,800	\$4,452
216571268	TRANE	5TWV8X36A1	5PX*C009AS3	S8V2C100M5PDB	31,000	\$4,340
216571266	TRANE	5TWV8X36A1	5PX*C009AS3	S8V2C100M5PCB	31,000	\$4,340
216571270	TRANE	5TWV8X36A1	5PX*C009AS3	S8V2C080M5PDB	30,800	\$4,312
216571264	TRANE	5TWV8X36A1	5PX*C009AS3	S8V2C080M5PCB	30,800	\$4,312
216571272	TRANE	5TWV8X36A1	5PX*C009AS3	*UHMC100CCV4+LRP	30,800	\$4,312
215869096	TRANE	5TWV8X36A1	5PX*C007AS3	S9V2C100U5VSB+LRP	31,200	\$4,368
215864553	TRANE	5TWV8X36A1	5PX*C007AS3	S9V2C100U5PSC+LRP	31,200	\$4,368
215864545	TRANE	5TWV8X36A1	5PX*C007AS3	S9V2C100U4VSB+LRP	31,200	\$4,368
215869098	TRANE	5TWV8X36A1	5PX*C007AS3	S9V2C080U5VSB+LRP	31,200	\$4,368
215864543	TRANE	5TWV8X36A1	5PX*C007AS3	S9V2C080U5PSC+LRP	31,200	\$4,368
215864541	TRANE	5TWV8X36A1	5PX*C007AS3	S8V2C100M5PDB	31,200	\$4,368
215864539	TRANE	5TWV8X36A1	5PX*C007AS3	S8V2C100M5PCB	31,200	\$4,368
215864551	TRANE	5TWV8X36A1	5PX*C007AS3	S8V2C080M5PDB	31,000	\$4,340
215864547	TRANE	5TWV8X36A1	5PX*C007AS3	S8V2C080M5PCB	31,000	\$4,340
215865057	TRANE	5TWV8X36A1	5PX*C007AS3	P0V0C000M50SD+LRP	31,000	\$4,340
215864549	TRANE	5TWV8X36A1	5PX*C007AS3	*UHMC100CCV4+LRP	31,000	\$4,340
215869092	TRANE	5TWV8X36A1	5PX*C005AS3	S9V2C100U5VSB+LRP	31,000	\$4,340
215864537	TRANE	5TWV8X36A1	5PX*C005AS3	S9V2C100U5PSC+LRP	30,800	\$4,312
215864535	TRANE	5TWV8X36A1	5PX*C005AS3	S9V2C100U4VSB+LRP	30,800	\$4,312
215869094	TRANE	5TWV8X36A1	5PX*C005AS3	S9V2C080U5VSB+LRP	31,000	\$4,340
215864533	TRANE	5TWV8X36A1	5PX*C005AS3	S9V2C080U5PSC+LRP	31,000	\$4,340
215864531	TRANE	5TWV8X36A1	5PX*C005AS3	S8V2C100M5PDB	31,000	\$4,340
215864529	TRANE	5TWV8X36A1	5PX*C005AS3	S8V2C100M5PCB	31,000	\$4,340
215864527	TRANE	5TWV8X36A1	5PX*C005AS3	S8V2C080M5PDB	31,000	\$4,340
215864525	TRANE	5TWV8X36A1	5PX*C005AS3	S8V2C080M5PCB	31,000	\$4,340
215865055	TRANE	5TWV8X36A1	5PX*C005AS3	P0V0C000M50SD+LRP	30,800	\$4,312
215864523	TRANE	5TWV8X36A1	5PX*C005AS3	*UHMC100CCV4+LRP	30,800	\$4,312
215864799	TRANE	5TWV8X36A1	5PX*BD06AS3	S9V2B080D4VSB+LRP	31,800	\$4,452
215864797	TRANE	5TWV8X36A1	5PX*BD06AS3	S9V2B060D3VSB+LRP	31,800	\$4,452
215864795	TRANE	5TWV8X36A1	5PX*BD06AS3	S9V2B040D3PSC+LRP	32,000	\$4,480
215864793	TRANE	5TWV8X36A1	5PX*BD06AS3	S8V2B080M4PDB	32,000	\$4,480
215864791	TRANE	5TWV8X36A1	5PX*BD06AS3	S8V2B080M4PCB	32,000	\$4,480
215864789	TRANE	5TWV8X36A1	5PX*BD06AS3	S8V2B060M4PDB	32,000	\$4,480

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864787	TRANE	5TWW8X36A1	5PX*BD06AS3	S8V2B060M4PCB	32,000	\$4,480
215864785	TRANE	5TWW8X36A1	5PX*BD06AS3	S8V2A040M3PDB	31,800	\$4,452
215864783	TRANE	5TWW8X36A1	5PX*BD06AS3	S8V2A040M3PCB	31,800	\$4,452
215864781	TRANE	5TWW8X36A1	5PX*BD06AS3	*DHMB080CCV3+LRP	31,800	\$4,452
215864511	TRANE	5TWW8X36A1	5PX*BD04AS3	S9V2B080D4VSB+LRP	31,800	\$4,452
215864499	TRANE	5TWW8X36A1	5PX*BD04AS3	S9V2B080D4PSC+LRP	31,800	\$4,452
215864501	TRANE	5TWW8X36A1	5PX*BD04AS3	S9V2B060D3VSB+LRP	31,800	\$4,452
215864503	TRANE	5TWW8X36A1	5PX*BD04AS3	S9V2B060D3PSC+LRP	31,800	\$4,452
215869090	TRANE	5TWW8X36A1	5PX*BD04AS3	S9V2B040D3VSB+LRP	32,000	\$4,480
215864505	TRANE	5TWW8X36A1	5PX*BD04AS3	S9V2B040D3PSC+LRP	32,000	\$4,480
215864507	TRANE	5TWW8X36A1	5PX*BD04AS3	S8V2B080M4PDB	32,000	\$4,480
215864509	TRANE	5TWW8X36A1	5PX*BD04AS3	S8V2B080M4PCB	32,000	\$4,480
215864521	TRANE	5TWW8X36A1	5PX*BD04AS3	S8V2B060M4PDB	32,000	\$4,480
215864513	TRANE	5TWW8X36A1	5PX*BD04AS3	S8V2B060M4PCB	32,000	\$4,480
216571262	TRANE	5TWW8X36A1	5PX*BD04AS3	S8V2A040M3PDB	31,800	\$4,452
215864515	TRANE	5TWW8X36A1	5PX*BD04AS3	S8V2A040M3PCB	31,800	\$4,452
215865053	TRANE	5TWW8X36A1	5PX*BD04AS3	P0V0A000M30SD+LRP	31,800	\$4,452
215864517	TRANE	5TWW8X36A1	5PX*BD04AS3	*DHMB080CCV3+LRP	31,800	\$4,452
215864519	TRANE	5TWW8X36A1	5PX*BD04AS3	*DHMB060CCV3+LRP	32,000	\$4,480
215869088	TRANE	5TWW8X36A1	5PX*B006AS3	S9V2B060U4VSB+LRP	31,400	\$4,396
216571244	TRANE	5TWW8X36A1	5PX*B006AS3	S8V2B080M4PDB	31,400	\$4,396
216571246	TRANE	5TWW8X36A1	5PX*B006AS3	S8V2B080M4PCB	31,400	\$4,396
216571248	TRANE	5TWW8X36A1	5PX*B006AS3	S8V2B060M4PDB	31,200	\$4,368
216571250	TRANE	5TWW8X36A1	5PX*B006AS3	S8V2B060M4PCB	31,200	\$4,368
216571252	TRANE	5TWW8X36A1	5PX*B006AS3	S8V2A040M3PDB	31,200	\$4,368
216571254	TRANE	5TWW8X36A1	5PX*B006AS3	S8V2A040M3PCB	31,200	\$4,368
216571256	TRANE	5TWW8X36A1	5PX*B006AS3	L8V1B080U4VSB+LRP	31,400	\$4,396
216571258	TRANE	5TWW8X36A1	5PX*B006AS3	L8V1A060U3VSB+LRP	31,400	\$4,396
216571260	TRANE	5TWW8X36A1	5PX*B006AS3	L8V1A040U3VSB+LRP	31,400	\$4,396
216571242	TRANE	5TWW8X36A1	5PX*B006AS3	*UHMB080CCV3+LRP	31,200	\$4,368
216571240	TRANE	5TWW8X36A1	5PX*B006AS3	*UHMB060CCV3+LRP	31,400	\$4,396
215864477	TRANE	5TWW8X36A1	5PX*B004AS3	S9V2B080U4VSB+LRP	31,000	\$4,340
215864479	TRANE	5TWW8X36A1	5PX*B004AS3	S9V2B080U4PSC+LRP	31,000	\$4,340
215869086	TRANE	5TWW8X36A1	5PX*B004AS3	S9V2B060U4VSB+LRP	30,800	\$4,312
215864481	TRANE	5TWW8X36A1	5PX*B004AS3	S9V2B060U4PSC+LRP	31,200	\$4,368
215864483	TRANE	5TWW8X36A1	5PX*B004AS3	S9V2B060U3VSB+LRP	31,200	\$4,368
215864485	TRANE	5TWW8X36A1	5PX*B004AS3	S9V2B040U3VSB+LRP	30,600	\$4,284
215864487	TRANE	5TWW8X36A1	5PX*B004AS3	S9V2B040U3PSC+LRP	31,000	\$4,340

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864489	TRANE	5TWV8X36A1	5PX*B004AS3	S8V2B080M4PDB	31,200	\$4,368
215864491	TRANE	5TWV8X36A1	5PX*B004AS3	S8V2B080M4PCB	31,200	\$4,368
215864493	TRANE	5TWV8X36A1	5PX*B004AS3	S8V2B060M4PDB	31,000	\$4,340
215864495	TRANE	5TWV8X36A1	5PX*B004AS3	S8V2B060M4PCB	31,000	\$4,340
215865051	TRANE	5TWV8X36A1	5PX*B004AS3	P0V0A000M30SD+LRP	31,000	\$4,340
215864497	TRANE	5TWV8X36A1	5PX*B004AS3	L8V1B080U4VSB+LRP	31,200	\$4,368
216571238	TRANE	5TWV8X36A1	5PX*B004AS3	L8V1A060U3VSB+LRP	31,200	\$4,368
215864475	TRANE	5TWV8X36A1	5PX*B004AS3	*UHMB080CCV3+LRP	31,000	\$4,340
215864473	TRANE	5TWV8X36A1	5PX*B004AS3	*UHMB060CCV3+LRP	31,200	\$4,368
215865035	TRANE	5TWV8X24A1	5TEMCB03AV31+TD	N/A	22,400	\$3,136
216056998	TRANE	5TWV8X24A1	5TAMXD04AV31	N/A	22,400	\$3,136
216056996	TRANE	5TWV8X24A1	5TAMXC03AV31	N/A	22,600	\$3,164
216569816	TRANE	5TWV8X24A1	5TAMXB02AV21	N/A	23,000	\$3,220
216599681	TRANE	5TWV8X24A1	5PX*BD06AS3	S9V2B080D4PSC+LRP	23,200	\$3,248
216571210	TRANE	5TWV8X24A1	5PX*BD06AS3	S8V2B080M4PDB	23,200	\$3,248
216571212	TRANE	5TWV8X24A1	5PX*BD06AS3	S8V2B080M4PCB	23,200	\$3,248
216571214	TRANE	5TWV8X24A1	5PX*BD06AS3	S8V2B060M4PDB	23,000	\$3,220
216571216	TRANE	5TWV8X24A1	5PX*BD06AS3	S8V2B060M4PCB	23,000	\$3,220
216571222	TRANE	5TWV8X24A1	5PX*BD06AS3	S8V2A040M3PDB	23,000	\$3,220
216571220	TRANE	5TWV8X24A1	5PX*BD06AS3	S8V2A040M3PCB	23,000	\$3,220
216571218	TRANE	5TWV8X24A1	5PX*BD06AS3	*DHMB080CCV3+LRP	23,200	\$3,248
216571224	TRANE	5TWV8X24A1	5PX*BD06AS3	*DHMB060CCV3+LRP	23,000	\$3,220
216599679	TRANE	5TWV8X24A1	5PX*B006AS3	S9V2B080U4PSC+LRP	22,800	\$3,192
216571200	TRANE	5TWV8X24A1	5PX*B006AS3	S8V2B080M4PDB	22,800	\$3,192
216571202	TRANE	5TWV8X24A1	5PX*B006AS3	S8V2B080M4PCB	22,800	\$3,192
216571204	TRANE	5TWV8X24A1	5PX*B006AS3	S8V2B060M4PDB	22,600	\$3,164
216571206	TRANE	5TWV8X24A1	5PX*B006AS3	S8V2B060M4PCB	22,600	\$3,164
216571198	TRANE	5TWV8X24A1	5PX*B006AS3	S8V2A040M3PDB	22,600	\$3,164
216571208	TRANE	5TWV8X24A1	5PX*B006AS3	S8V2A040M3PCB	22,600	\$3,164
216571196	TRANE	5TWV8X24A1	5PX*B006AS3	L8V1B080U4VSB+LRP	22,600	\$3,164
216571194	TRANE	5TWV8X24A1	5PX*B006AS3	L8V1A060U3VSB+LRP	22,800	\$3,192
216571192	TRANE	5TWV8X24A1	5PX*B006AS3	L8V1A040U3VSB+LRP	22,800	\$3,192
216571190	TRANE	5TWV8X24A1	5PX*B006AS3	*UHMB080CCV3+LRP	22,400	\$3,136
216571188	TRANE	5TWV8X24A1	5PX*B006AS3	*UHMB060CCV3+LRP	22,600	\$3,164
216453137	TRANE	5TWV0X36A1	5TXCD010AS3	S8V2D120M5PDB	31,200	\$4,368
216453139	TRANE	5TWV0X36A1	5TXCD010AS3	S8V2D120M5PCB	31,200	\$4,368
216440216	TRANE	5TWV0X36A1	5TXCC009AS3	S9V2C100U5VSB+LRP	30,400	\$4,256
216440226	TRANE	5TWV0X36A1	5TXCC009AS3	S9V2C100U5PSC+LRP	30,400	\$4,256

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216440224	TRANE	5TWV0X36A1	5TXCC009AS3	S9V2C100U4VSB+LRP	30,400	\$4,256
216440218	TRANE	5TWV0X36A1	5TXCC009AS3	S9V2C080U5VSB+LRP	30,400	\$4,256
216440222	TRANE	5TWV0X36A1	5TXCC009AS3	S9V2C080U5PSC+LRP	30,400	\$4,256
216571072	TRANE	5TWV0X36A1	5TXCC009AS3	S8V2C100M5PDB	31,400	\$4,396
216571076	TRANE	5TWV0X36A1	5TXCC009AS3	S8V2C100M5PCB	31,400	\$4,396
216571068	TRANE	5TWV0X36A1	5TXCC009AS3	S8V2C080M5PDB	31,200	\$4,368
216571070	TRANE	5TWV0X36A1	5TXCC009AS3	S8V2C080M5PCB	31,200	\$4,368
216440220	TRANE	5TWV0X36A1	5TXCC009AS3	P0V0C000M50SD+LRP	30,400	\$4,256
216571074	TRANE	5TWV0X36A1	5TXCC009AS3	*UHMC100CCV4+LRP	31,000	\$4,340
216440118	TRANE	5TWV0X36A1	5TEMCD05AV41+TD	N/A	31,600	\$4,424
216440114	TRANE	5TWV0X36A1	5TAMXD06AV41	N/A	31,600	\$4,424
216440112	TRANE	5TWV0X36A1	5TAMXD05AV41	N/A	31,600	\$4,424
216453113	TRANE	5TWV0X36A1	5PX*DD10AS3	S8V2D120M5PDB	31,200	\$4,368
216453115	TRANE	5TWV0X36A1	5PX*DD10AS3	S8V2D120M5PCB	31,200	\$4,368
216453109	TRANE	5TWV0X36A1	5PX*D010AS3	S8V2D120M5PDB	31,200	\$4,368
216453111	TRANE	5TWV0X36A1	5PX*D010AS3	S8V2D120M5PCB	31,200	\$4,368
216571016	TRANE	5TWV0X36A1	5PX*CD09AS3	S8V2C100M5PDB	31,400	\$4,396
216571014	TRANE	5TWV0X36A1	5PX*CD09AS3	S8V2C100M5PCB	31,400	\$4,396
216571012	TRANE	5TWV0X36A1	5PX*CD09AS3	S8V2C080M5PDB	31,200	\$4,368
216571010	TRANE	5TWV0X36A1	5PX*CD09AS3	S8V2C080M5PCB	31,200	\$4,368
216571008	TRANE	5TWV0X36A1	5PX*CD09AS3	*DHMC100CCV4+LRP	31,000	\$4,340
216440096	TRANE	5TWV0X36A1	5PX*C009AS3	S9V2C100U5VSB+LRP	30,400	\$4,256
216440088	TRANE	5TWV0X36A1	5PX*C009AS3	S9V2C100U5PSC+LRP	30,400	\$4,256
216440098	TRANE	5TWV0X36A1	5PX*C009AS3	S9V2C100U4VSB+LRP	30,400	\$4,256
216440094	TRANE	5TWV0X36A1	5PX*C009AS3	S9V2C080U5VSB+LRP	30,400	\$4,256
216440090	TRANE	5TWV0X36A1	5PX*C009AS3	S9V2C080U5PSC+LRP	30,400	\$4,256
216571000	TRANE	5TWV0X36A1	5PX*C009AS3	S8V2C100M5PDB	31,400	\$4,396
216570998	TRANE	5TWV0X36A1	5PX*C009AS3	S8V2C100M5PCB	31,400	\$4,396
216570996	TRANE	5TWV0X36A1	5PX*C009AS3	S8V2C080M5PDB	31,200	\$4,368
216570994	TRANE	5TWV0X36A1	5PX*C009AS3	S8V2C080M5PCB	31,200	\$4,368
216440092	TRANE	5TWV0X36A1	5PX*C009AS3	P0V0C000M50SD+LRP	30,400	\$4,256
216570992	TRANE	5TWV0X36A1	5PX*C009AS3	*UHMC100CCV4+LRP	31,000	\$4,340
216612217	TRANE	5TWV0X24A1	5TXCB006AS3	S9V2B080U4VSB+LRP	22,000	\$3,080
216612215	TRANE	5TWV0X24A1	5TXCB006AS3	S9V2B080U4PSC+LRP	22,000	\$3,080
216612213	TRANE	5TWV0X24A1	5TXCB006AS3	S9V2B060U4VSB+LRP	22,200	\$3,108
216612223	TRANE	5TWV0X24A1	5TXCB006AS3	S9V2B060U4PSC+LRP	22,200	\$3,108
216612221	TRANE	5TWV0X24A1	5TXCB006AS3	S8V2B080M4PCB	22,000	\$3,080
216612219	TRANE	5TWV0X24A1	5TXCB006AS3	S8V2B060M4PCB	22,000	\$3,080

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216612225	TRANE	5TWV0X24A1	5TXCB006AS3	L8V1B080U4VSB+LRP	22,000	\$3,080
216439976	TRANE	5TWV0X24A1	5TEMCB03AV31+TD	N/A	22,800	\$3,192
216439974	TRANE	5TWV0X24A1	5TAMXD04AV31	N/A	21,800	\$3,052
216439972	TRANE	5TWV0X24A1	5TAMXC03AV31	N/A	22,000	\$3,080
216569814	TRANE	5TWV0X24A1	5TAMXB02AV21	N/A	22,200	\$3,108
216612211	TRANE	5TWV0X24A1	5PX*BD06AS3	S9V2B080D4VSB+LRP	22,400	\$3,136
216599673	TRANE	5TWV0X24A1	5PX*BD06AS3	S9V2B080D4PSC+LRP	22,400	\$3,136
216439970	TRANE	5TWV0X24A1	5PX*BD06AS3	S9V2B040D3VSB+LRP	21,800	\$3,052
216439968	TRANE	5TWV0X24A1	5PX*BD06AS3	S9V2B040D3PSC+LRP	21,800	\$3,052
216453083	TRANE	5TWV0X24A1	5PX*BD06AS3	S8V2B080M4PDB	22,400	\$3,136
216453081	TRANE	5TWV0X24A1	5PX*BD06AS3	S8V2B080M4PCB	22,400	\$3,136
216570892	TRANE	5TWV0X24A1	5PX*BD06AS3	S8V2B060M4PDB	22,400	\$3,136
216570894	TRANE	5TWV0X24A1	5PX*BD06AS3	S8V2B060M4PCB	22,400	\$3,136
216570900	TRANE	5TWV0X24A1	5PX*BD06AS3	S8V2A040M3PDB	22,400	\$3,136
216570898	TRANE	5TWV0X24A1	5PX*BD06AS3	S8V2A040M3PCB	22,400	\$3,136
216448740	TRANE	5TWV0X24A1	5PX*BD06AS3	P0V0A000M30SD+LRP	21,800	\$3,052
216570902	TRANE	5TWV0X24A1	5PX*BD06AS3	*DHMB080CCV3+LRP	22,400	\$3,136
216570896	TRANE	5TWV0X24A1	5PX*BD06AS3	*DHMB060CCV3+LRP	22,400	\$3,136
216612201	TRANE	5TWV0X24A1	5PX*BD04AS3	S9V2B080D4VSB+LRP	22,200	\$3,108
216612209	TRANE	5TWV0X24A1	5PX*BD04AS3	S8V2B080M4PDB	22,200	\$3,108
216612207	TRANE	5TWV0X24A1	5PX*BD04AS3	S8V2B080M4PCB	22,200	\$3,108
216612203	TRANE	5TWV0X24A1	5PX*BD04AS3	S8V2B060M4PDB	22,200	\$3,108
216612205	TRANE	5TWV0X24A1	5PX*BD04AS3	S8V2B060M4PCB	22,200	\$3,108
216612199	TRANE	5TWV0X24A1	5PX*B006AS3	S9V2B080U4VSB+LRP	22,000	\$3,080
216599671	TRANE	5TWV0X24A1	5PX*B006AS3	S9V2B080U4PSC+LRP	22,000	\$3,080
216439960	TRANE	5TWV0X24A1	5PX*B006AS3	S9V2B060U4VSB+LRP	22,200	\$3,108
216439958	TRANE	5TWV0X24A1	5PX*B006AS3	S9V2B060U4PSC+LRP	22,200	\$3,108
216439964	TRANE	5TWV0X24A1	5PX*B006AS3	S9V2B060U3VSB+LRP	21,200	\$2,968
216439962	TRANE	5TWV0X24A1	5PX*B006AS3	S9V2B040U3VSB+LRP	21,000	\$2,940
216439966	TRANE	5TWV0X24A1	5PX*B006AS3	S9V2B040U3PSC+LRP	21,000	\$2,940
216453077	TRANE	5TWV0X24A1	5PX*B006AS3	S8V2B080M4PDB	22,000	\$3,080
216453079	TRANE	5TWV0X24A1	5PX*B006AS3	S8V2B080M4PCB	22,000	\$3,080
216570876	TRANE	5TWV0X24A1	5PX*B006AS3	S8V2B060M4PDB	22,000	\$3,080
216570878	TRANE	5TWV0X24A1	5PX*B006AS3	S8V2B060M4PCB	22,000	\$3,080
216570880	TRANE	5TWV0X24A1	5PX*B006AS3	S8V2A040M3PDB	21,800	\$3,052
216570882	TRANE	5TWV0X24A1	5PX*B006AS3	S8V2A040M3PCB	21,800	\$3,052
216570884	TRANE	5TWV0X24A1	5PX*B006AS3	L8V1B080U4VSB+LRP	22,000	\$3,080
216570886	TRANE	5TWV0X24A1	5PX*B006AS3	L8V1A060U3VSB+LRP	22,200	\$3,108

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216570888	TRANE	5TWW0X24A1	5PX*B006AS3	L8V1A040U3VSB+LRP	22,200	\$3,108
216570874	TRANE	5TWW0X24A1	5PX*B006AS3	*UHMB080CCV3+LRP	21,800	\$3,052
216570890	TRANE	5TWW0X24A1	5PX*B006AS3	*UHMB060CCV3+LRP	21,800	\$3,052
216766754	TRANE	5TWR7060A1	5TXCD010AS3	S9X2D120U5PSB	33,600	\$4,704
216766764	TRANE	5TWR7060A1	5TXCD010AS3	S9X2C100U5PSB	34,400	\$4,816
216766766	TRANE	5TWR7060A1	5TXCD010AS3	S9X2C080U5PSB	34,200	\$4,788
216766778	TRANE	5TWR7060A1	5TXCD010AS3	S9X1D120U5PSB	33,600	\$4,704
216766750	TRANE	5TWR7060A1	5TXCD010AS3	S9X1C100U5PSB	34,400	\$4,816
216766772	TRANE	5TWR7060A1	5TXCD010AS3	S9X1C080U5PSB	34,200	\$4,788
216764105	TRANE	5TWR7060A1	5TXCD010AS3	S9V2D120U5VSB	34,000	\$4,760
216764103	TRANE	5TWR7060A1	5TXCD010AS3	S9V2D120U5PSC	34,000	\$4,760
216766774	TRANE	5TWR7060A1	5TXCD010AS3	S9V2C080U5VSB	34,000	\$4,760
216764093	TRANE	5TWR7060A1	5TXCD010AS3	S9V2C080U5PSC	34,000	\$4,760
216764901	TRANE	5TWR7060A1	5TXCD010AS3	S8X2D120M5PTC	33,800	\$4,732
216764903	TRANE	5TWR7060A1	5TXCD010AS3	S8X2D120M5PSC	33,800	\$4,732
216764899	TRANE	5TWR7060A1	5TXCD010AS3	S8X2C100M5PTC	34,200	\$4,788
216764907	TRANE	5TWR7060A1	5TXCD010AS3	S8X2C100M5PSC	34,200	\$4,788
216764905	TRANE	5TWR7060A1	5TXCD010AS3	S8X2C080M5PTC	34,000	\$4,760
216764095	TRANE	5TWR7060A1	5TXCD010AS3	S8X1D120M5PSC	33,800	\$4,732
216764897	TRANE	5TWR7060A1	5TXCD010AS3	S8X1C100M5PTC	34,200	\$4,788
216764097	TRANE	5TWR7060A1	5TXCD010AS3	S8X1C100M5PSC	34,200	\$4,788
216764895	TRANE	5TWR7060A1	5TXCD010AS3	S8X1C080M5PTC	34,000	\$4,760
216766762	TRANE	5TWR7060A1	5TXCD010AS3	S8V2D120M5PDB	33,800	\$4,732
216766776	TRANE	5TWR7060A1	5TXCD010AS3	S8V2D120M5PCB	33,800	\$4,732
216766768	TRANE	5TWR7060A1	5TXCD010AS3	S8V2C100M5PDB	34,000	\$4,760
216766752	TRANE	5TWR7060A1	5TXCD010AS3	S8V2C100M5PCB	34,000	\$4,760
216766770	TRANE	5TWR7060A1	5TXCD010AS3	S8V2C080M5PDB	34,000	\$4,760
216766756	TRANE	5TWR7060A1	5TXCD010AS3	S8V2C080M5PCB	34,000	\$4,760
216764099	TRANE	5TWR7060A1	5TXCD010AS3	L9X1C100U5VSA	34,400	\$4,816
216764101	TRANE	5TWR7060A1	5TXCD010AS3	L8V1C100U5VSB	34,000	\$4,760
216766736	TRANE	5TWR7060A1	5TXCD008AS3	S9X2D120U5PSB	34,000	\$4,760
216766738	TRANE	5TWR7060A1	5TXCD008AS3	S9X2C100U5PSB	34,200	\$4,788
216766740	TRANE	5TWR7060A1	5TXCD008AS3	S9X2C080U5PSB	34,400	\$4,816
216766720	TRANE	5TWR7060A1	5TXCD008AS3	S9X1D120U5PSB	34,000	\$4,760
216766722	TRANE	5TWR7060A1	5TXCD008AS3	S9X1C100U5PSB	34,200	\$4,788
216766724	TRANE	5TWR7060A1	5TXCD008AS3	S9X1C080U5PSB	34,400	\$4,816
216770078	TRANE	5TWR7060A1	5TXCD008AS3	S9V2D120U5VSB	34,200	\$4,788
216770084	TRANE	5TWR7060A1	5TXCD008AS3	S9V2D120U5PSC	34,200	\$4,788

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766726	TRANE	5TWR7060A1	5TXCD008AS3	S9V2C100U5VSB	34,800	\$4,872
216766728	TRANE	5TWR7060A1	5TXCD008AS3	S9V2C080U5VSB	34,200	\$4,788
216770076	TRANE	5TWR7060A1	5TXCD008AS3	S8X2D120M5PTC	34,400	\$4,816
216770074	TRANE	5TWR7060A1	5TXCD008AS3	S8X2D120M5PSC	34,400	\$4,816
216770072	TRANE	5TWR7060A1	5TXCD008AS3	S8X1D120M5PTC	34,400	\$4,816
216770080	TRANE	5TWR7060A1	5TXCD008AS3	S8X1D120M5PSC	34,400	\$4,816
216766744	TRANE	5TWR7060A1	5TXCD008AS3	S8V2D120M5PDB	34,000	\$4,760
216766730	TRANE	5TWR7060A1	5TXCD008AS3	S8V2D120M5PCB	34,000	\$4,760
216766746	TRANE	5TWR7060A1	5TXCD008AS3	S8V2C100M5PDB	34,400	\$4,816
216766732	TRANE	5TWR7060A1	5TXCD008AS3	S8V2C100M5PCB	34,400	\$4,816
216766748	TRANE	5TWR7060A1	5TXCD008AS3	S8V2C080M5PDB	34,400	\$4,816
216766742	TRANE	5TWR7060A1	5TXCD008AS3	S8V2C080M5PCB	34,400	\$4,816
216764089	TRANE	5TWR7060A1	5TXCD008AS3	N/A	34,800	\$4,872
216770082	TRANE	5TWR7060A1	5TXCD008AS3	L8V1C100U5VSB	34,200	\$4,788
216764091	TRANE	5TWR7060A1	5TXCD008AS3	*UHMD120CCV5	34,600	\$4,844
216764087	TRANE	5TWR7060A1	5TEMCD07AV51+TD	N/A	33,600	\$4,704
216764085	TRANE	5TWR7060A1	5TEMCD06AV41+TD	N/A	33,600	\$4,704
216764083	TRANE	5TWR7060A1	5TEM6D07AV51+TD	N/A	33,400	\$4,676
216764081	TRANE	5TWR7060A1	5TEM6D06AV41+TD	N/A	33,400	\$4,676
216770070	TRANE	5TWR7060A1	5TAMXD07AV51	N/A	33,600	\$4,704
216770068	TRANE	5TWR7060A1	5TAMXD06AV41	N/A	34,000	\$4,760
216770066	TRANE	5TWR7060A1	5TAM5D07AC51	N/A	34,400	\$4,816
216770064	TRANE	5TWR7060A1	5TAM5D06AC41	N/A	33,600	\$4,704
216766698	TRANE	5TWR7060A1	5PX*DD10AS3	S9X2D120D5PSB	33,800	\$4,732
216766706	TRANE	5TWR7060A1	5PX*DD10AS3	S9X2C100D5PSB	34,000	\$4,760
216766704	TRANE	5TWR7060A1	5PX*DD10AS3	S9X1D120D5PSB	33,800	\$4,732
216766718	TRANE	5TWR7060A1	5PX*DD10AS3	S9X1C100D5PSB	34,000	\$4,760
216766712	TRANE	5TWR7060A1	5PX*DD10AS3	S9V2D120D5VSB	33,800	\$4,732
216764077	TRANE	5TWR7060A1	5PX*DD10AS3	S9V2D120D5PSC	33,800	\$4,732
216764893	TRANE	5TWR7060A1	5PX*DD10AS3	S8X2D120M5PTC	33,800	\$4,732
216764885	TRANE	5TWR7060A1	5PX*DD10AS3	S8X2D120M5PSC	33,800	\$4,732
216764891	TRANE	5TWR7060A1	5PX*DD10AS3	S8X2C100M5PTC	34,000	\$4,760
216764883	TRANE	5TWR7060A1	5PX*DD10AS3	S8X2C100M5PSC	34,000	\$4,760
216764889	TRANE	5TWR7060A1	5PX*DD10AS3	S8X2C080M5PTC	34,000	\$4,760
216764881	TRANE	5TWR7060A1	5PX*DD10AS3	S8X2C080M5PSC	34,000	\$4,760
216764879	TRANE	5TWR7060A1	5PX*DD10AS3	S8X1D120M5PTC	33,800	\$4,732
216764075	TRANE	5TWR7060A1	5PX*DD10AS3	S8X1D120M5PSC	33,800	\$4,732
216764877	TRANE	5TWR7060A1	5PX*DD10AS3	S8X1C100M5PTC	34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764079	TRANE	5TWR7060A1	5PX*DD10AS3	S8X1C100M5PSC	34,000	\$4,760
216764887	TRANE	5TWR7060A1	5PX*DD10AS3	S8X1C080M5PTC	34,000	\$4,760
216764071	TRANE	5TWR7060A1	5PX*DD10AS3	S8X1C080M5PSC	34,000	\$4,760
216766708	TRANE	5TWR7060A1	5PX*DD10AS3	S8V2D120M5PDB	33,600	\$4,704
216766714	TRANE	5TWR7060A1	5PX*DD10AS3	S8V2D120M5PCB	33,600	\$4,704
216766710	TRANE	5TWR7060A1	5PX*DD10AS3	S8V2C100M5PDB	34,000	\$4,760
216766716	TRANE	5TWR7060A1	5PX*DD10AS3	S8V2C100M5PCB	34,000	\$4,760
216766700	TRANE	5TWR7060A1	5PX*DD10AS3	S8V2C080M5PDB	34,000	\$4,760
216766694	TRANE	5TWR7060A1	5PX*DD10AS3	S8V2C080M5PCB	34,000	\$4,760
216764073	TRANE	5TWR7060A1	5PX*DD10AS3	N/A	34,200	\$4,788
216770062	TRANE	5TWR7060A1	5PX*DD10AS3	*DHMD120CCV5	34,000	\$4,760
216766686	TRANE	5TWR7060A1	5PX*D010AS3	S9X2D120U5PSB	33,600	\$4,704
216766684	TRANE	5TWR7060A1	5PX*D010AS3	S9X2C100U5PSB	34,400	\$4,816
216766682	TRANE	5TWR7060A1	5PX*D010AS3	S9X2C080U5PSB	34,200	\$4,788
216766668	TRANE	5TWR7060A1	5PX*D010AS3	S9X1D120U5PSB	33,600	\$4,704
216766670	TRANE	5TWR7060A1	5PX*D010AS3	S9X1C100U5PSB	34,400	\$4,816
216766672	TRANE	5TWR7060A1	5PX*D010AS3	S9X1C080U5PSB	34,200	\$4,788
216764053	TRANE	5TWR7060A1	5PX*D010AS3	S9V2D120U5VSB	33,800	\$4,732
216764055	TRANE	5TWR7060A1	5PX*D010AS3	S9V2D120U5PSC	33,800	\$4,732
216766674	TRANE	5TWR7060A1	5PX*D010AS3	S9V2C080U5VSB	33,800	\$4,732
216764057	TRANE	5TWR7060A1	5PX*D010AS3	S9V2C080U5PSC	33,800	\$4,732
216764867	TRANE	5TWR7060A1	5PX*D010AS3	S8X2D120M5PTC	34,000	\$4,760
216764875	TRANE	5TWR7060A1	5PX*D010AS3	S8X2D120M5PSC	34,000	\$4,760
216764869	TRANE	5TWR7060A1	5PX*D010AS3	S8X2C100M5PTC	34,000	\$4,760
216764863	TRANE	5TWR7060A1	5PX*D010AS3	S8X2C100M5PSC	34,000	\$4,760
216764871	TRANE	5TWR7060A1	5PX*D010AS3	S8X2C080M5PTC	34,000	\$4,760
216764865	TRANE	5TWR7060A1	5PX*D010AS3	S8X2C080M5PSC	34,000	\$4,760
216764873	TRANE	5TWR7060A1	5PX*D010AS3	S8X1D120M5PTC	34,000	\$4,760
216764059	TRANE	5TWR7060A1	5PX*D010AS3	S8X1D120M5PSC	34,000	\$4,760
216764859	TRANE	5TWR7060A1	5PX*D010AS3	S8X1C100M5PTC	34,000	\$4,760
216764061	TRANE	5TWR7060A1	5PX*D010AS3	S8X1C100M5PSC	34,000	\$4,760
216764861	TRANE	5TWR7060A1	5PX*D010AS3	S8X1C080M5PTC	34,000	\$4,760
216764063	TRANE	5TWR7060A1	5PX*D010AS3	S8X1C080M5PSC	34,000	\$4,760
216766692	TRANE	5TWR7060A1	5PX*D010AS3	S8V2D120M5PDB	33,800	\$4,732
216766676	TRANE	5TWR7060A1	5PX*D010AS3	S8V2D120M5PCB	33,800	\$4,732
216766666	TRANE	5TWR7060A1	5PX*D010AS3	S8V2C100M5PDB	34,000	\$4,760
216766678	TRANE	5TWR7060A1	5PX*D010AS3	S8V2C100M5PCB	34,000	\$4,760
216766680	TRANE	5TWR7060A1	5PX*D010AS3	S8V2C080M5PCB	34,000	\$4,760

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764065	TRANE	5TWR7060A1	5PX*D010AS3	N/A	34,400	\$4,816
216764067	TRANE	5TWR7060A1	5PX*D010AS3	L9X1C100U5VSA	34,400	\$4,816
216764069	TRANE	5TWR7060A1	5PX*D010AS3	L8V1C100U5VSB	33,800	\$4,732
216766636	TRANE	5TWR7060A1	5PX*D008AS3	S9X2D120U5PSB	34,000	\$4,760
216766664	TRANE	5TWR7060A1	5PX*D008AS3	S9X2C100U5PSB	34,200	\$4,788
216766662	TRANE	5TWR7060A1	5PX*D008AS3	S9X2C080U5PSB	34,400	\$4,816
216766654	TRANE	5TWR7060A1	5PX*D008AS3	S9X1D120U5PSB	34,000	\$4,760
216766652	TRANE	5TWR7060A1	5PX*D008AS3	S9X1C100U5PSB	34,200	\$4,788
216766650	TRANE	5TWR7060A1	5PX*D008AS3	S9X1C080U5PSB	34,400	\$4,816
216764033	TRANE	5TWR7060A1	5PX*D008AS3	S9V2D120U5VSB	34,200	\$4,788
216764035	TRANE	5TWR7060A1	5PX*D008AS3	S9V2D120U5PSC	34,200	\$4,788
216766648	TRANE	5TWR7060A1	5PX*D008AS3	S9V2C100U5VSB	34,800	\$4,872
216764037	TRANE	5TWR7060A1	5PX*D008AS3	S9V2C100U5PSC	34,800	\$4,872
216766646	TRANE	5TWR7060A1	5PX*D008AS3	S9V2C080U5VSB	34,200	\$4,788
216764039	TRANE	5TWR7060A1	5PX*D008AS3	S9V2C080U5PSC	34,200	\$4,788
216764851	TRANE	5TWR7060A1	5PX*D008AS3	S8X2D120M5PTC	34,400	\$4,816
216764857	TRANE	5TWR7060A1	5PX*D008AS3	S8X2D120M5PSC	34,400	\$4,816
216764853	TRANE	5TWR7060A1	5PX*D008AS3	S8X2C100M5PTC	34,400	\$4,816
216764843	TRANE	5TWR7060A1	5PX*D008AS3	S8X2C100M5PSC	34,400	\$4,816
216764855	TRANE	5TWR7060A1	5PX*D008AS3	S8X2C080M5PTC	34,400	\$4,816
216764841	TRANE	5TWR7060A1	5PX*D008AS3	S8X2C080M5PSC	34,400	\$4,816
216764845	TRANE	5TWR7060A1	5PX*D008AS3	S8X1D120M5PTC	34,400	\$4,816
216764051	TRANE	5TWR7060A1	5PX*D008AS3	S8X1D120M5PSC	34,400	\$4,816
216764847	TRANE	5TWR7060A1	5PX*D008AS3	S8X1C100M5PTC	34,400	\$4,816
216764043	TRANE	5TWR7060A1	5PX*D008AS3	S8X1C100M5PSC	34,400	\$4,816
216764849	TRANE	5TWR7060A1	5PX*D008AS3	S8X1C080M5PTC	34,400	\$4,816
216764045	TRANE	5TWR7060A1	5PX*D008AS3	S8X1C080M5PSC	34,400	\$4,816
216766660	TRANE	5TWR7060A1	5PX*D008AS3	S8V2D120M5PDB	34,000	\$4,760
216766644	TRANE	5TWR7060A1	5PX*D008AS3	S8V2D120M5PCB	34,000	\$4,760
216766658	TRANE	5TWR7060A1	5PX*D008AS3	S8V2C100M5PDB	34,400	\$4,816
216766642	TRANE	5TWR7060A1	5PX*D008AS3	S8V2C100M5PCB	34,400	\$4,816
216766656	TRANE	5TWR7060A1	5PX*D008AS3	S8V2C080M5PDB	34,400	\$4,816
216766640	TRANE	5TWR7060A1	5PX*D008AS3	S8V2C080M5PCB	34,400	\$4,816
216764047	TRANE	5TWR7060A1	5PX*D008AS3	N/A	34,800	\$4,872
216764041	TRANE	5TWR7060A1	5PX*D008AS3	L9X1C100U5VSA	34,800	\$4,872
216764049	TRANE	5TWR7060A1	5PX*D008AS3	L8V1C100U5VSB	34,200	\$4,788
216766602	TRANE	5TWR7048A1	5TXCD008AS3	S9X2C080U5PSB	30,200	\$4,228
216766584	TRANE	5TWR7048A1	5TXCD008AS3	S9X1C080U5PSB	30,200	\$4,228

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766568	TRANE	5TWR7048A1	5TXCC009AS3	S9V2C100U5VSB	29,400	\$4,116
216770038	TRANE	5TWR7048A1	5TXCC009AS3	S9V2C100U5PSC	29,400	\$4,116
216770018	TRANE	5TWR7048A1	5TXCC009AS3	L9X1C100U5VSA	30,200	\$4,228
216763973	TRANE	5TWR7048A1	5PX*D010AS3	N/A	29,800	\$4,172
216763975	TRANE	5TWR7048A1	5PX*D010AS3	L9X1C100U5VSA	30,200	\$4,228
216766486	TRANE	5TWR7048A1	5PX*D008AS3	S9X2C080U5PSB	30,200	\$4,228
216766490	TRANE	5TWR7048A1	5PX*D008AS3	S9X1C080U5PSB	30,200	\$4,228
216766442	TRANE	5TWR7048A1	5PX*C009AS3	S9V2C100U5VSB	29,400	\$4,116
216763935	TRANE	5TWR7048A1	5PX*C009AS3	S9V2C100U5PSC	29,400	\$4,116
216763925	TRANE	5TWR7048A1	5PX*C009AS3	L9X1C100U5VSA	30,200	\$4,228
216766428	TRANE	5TWR7036A1	5TXCD010AS3	S9X2D120U5PSB	21,200	\$2,968
216766432	TRANE	5TWR7036A1	5TXCD010AS3	S9X1D120U5PSB	21,200	\$2,968
216763919	TRANE	5TWR7036A1	5TXCD010AS3	S9V2D120U5VSB	21,200	\$2,968
216763921	TRANE	5TWR7036A1	5TXCD010AS3	S9V2D120U5PSC	21,200	\$2,968
216766434	TRANE	5TWR7036A1	5TXCD010AS3	S8V2D120M5PDB	21,200	\$2,968
216766430	TRANE	5TWR7036A1	5TXCD010AS3	S8V2D120M5PCB	21,200	\$2,968
216763917	TRANE	5TWR7036A1	5TXCD010AS3	*UHMD120CCV5	21,200	\$2,968
216766426	TRANE	5TWR7036A1	5TXCD008AS3	S9X2D120U5PSB	21,200	\$2,968
216766420	TRANE	5TWR7036A1	5TXCD008AS3	S9X2D120D5PSB	21,000	\$2,940
216766424	TRANE	5TWR7036A1	5TXCD008AS3	S9X1D120U5PSB	21,200	\$2,968
216766418	TRANE	5TWR7036A1	5TXCD008AS3	S9X1D120D5PSB	21,000	\$2,940
216770004	TRANE	5TWR7036A1	5TXCD008AS3	S9V2D120U5PSC	21,400	\$2,996
216769998	TRANE	5TWR7036A1	5TXCD008AS3	S8X2D120M5PTC	21,000	\$2,940
216769996	TRANE	5TWR7036A1	5TXCD008AS3	S8X2D120M5PSC	21,000	\$2,940
216770002	TRANE	5TWR7036A1	5TXCD008AS3	S8X1D120M5PTC	21,000	\$2,940
216770000	TRANE	5TWR7036A1	5TXCD008AS3	S8X1D120M5PSC	21,000	\$2,940
216766416	TRANE	5TWR7036A1	5TXCD008AS3	S8V2D120M5PDB	21,400	\$2,996
216766422	TRANE	5TWR7036A1	5TXCD008AS3	S8V2D120M5PCB	21,400	\$2,996
216763913	TRANE	5TWR7036A1	5TXCD008AS3	N/A	21,800	\$3,052
216763911	TRANE	5TWR7036A1	5TXCD008AS3	*UHMD120CCV5	21,200	\$2,968
216763915	TRANE	5TWR7036A1	5TXCD008AS3	*DHMD120CCV5	21,000	\$2,940
216766400	TRANE	5TWR7036A1	5TXCC009AS3	S9X2C100U5PSB	21,200	\$2,968
216766398	TRANE	5TWR7036A1	5TXCC009AS3	S9X2C080U5PSB	21,400	\$2,996
216766414	TRANE	5TWR7036A1	5TXCC009AS3	S9X1C100U5PSB	21,200	\$2,968
216766412	TRANE	5TWR7036A1	5TXCC009AS3	S9X1C080U5PSB	21,400	\$2,996
216766410	TRANE	5TWR7036A1	5TXCC009AS3	S9V2C100U5VSB	21,200	\$2,968
216769994	TRANE	5TWR7036A1	5TXCC009AS3	S9V2C100U5PSC	21,200	\$2,968
216769980	TRANE	5TWR7036A1	5TXCC009AS3	S9V2C100U4VSB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766408	TRANE	5TWR7036A1	5TXCC009AS3	S9V2C080U5VSB	21,200	\$2,968
216769978	TRANE	5TWR7036A1	5TXCC009AS3	S9V2C080U5PSC	21,200	\$2,968
216769976	TRANE	5TWR7036A1	5TXCC009AS3	S8X2C100M5PTC	21,400	\$2,996
216769974	TRANE	5TWR7036A1	5TXCC009AS3	S8X2C100M5PSC	21,400	\$2,996
216769992	TRANE	5TWR7036A1	5TXCC009AS3	S8X2C080M5PTC	21,200	\$2,968
216769990	TRANE	5TWR7036A1	5TXCC009AS3	S8X2C080M5PSC	21,200	\$2,968
216769988	TRANE	5TWR7036A1	5TXCC009AS3	S8X1C100M5PTC	21,400	\$2,996
216769986	TRANE	5TWR7036A1	5TXCC009AS3	S8X1C100M5PSC	21,400	\$2,996
216769984	TRANE	5TWR7036A1	5TXCC009AS3	S8X1C080M5PTC	21,200	\$2,968
216769982	TRANE	5TWR7036A1	5TXCC009AS3	S8X1C080M5PSC	21,200	\$2,968
216766396	TRANE	5TWR7036A1	5TXCC009AS3	S8V2C100M5PDB	21,200	\$2,968
216766406	TRANE	5TWR7036A1	5TXCC009AS3	S8V2C100M5PCB	21,200	\$2,968
216766394	TRANE	5TWR7036A1	5TXCC009AS3	S8V2C080M5PDB	21,400	\$2,996
216766404	TRANE	5TWR7036A1	5TXCC009AS3	S8V2C080M5PCB	21,400	\$2,996
216763909	TRANE	5TWR7036A1	5TXCC009AS3	N/A	21,600	\$3,024
216769972	TRANE	5TWR7036A1	5TXCC009AS3	L9X1C100U5VSA	21,200	\$2,968
216769970	TRANE	5TWR7036A1	5TXCC009AS3	L8V1C100U5VSB	21,200	\$2,968
216763907	TRANE	5TWR7036A1	5TXCC009AS3	*UHMC100CCV4	21,000	\$2,940
216766366	TRANE	5TWR7036A1	5TXCC007AS3	S9X2C100U5PSB	21,400	\$2,996
216766370	TRANE	5TWR7036A1	5TXCC007AS3	S9X2C100D5PSB	21,000	\$2,940
216766368	TRANE	5TWR7036A1	5TXCC007AS3	S9X2C080U5PSB	21,600	\$3,024
216766380	TRANE	5TWR7036A1	5TXCC007AS3	S9X1C100U5PSB	21,400	\$2,996
216766376	TRANE	5TWR7036A1	5TXCC007AS3	S9X1C100D5PSB	21,000	\$2,940
216766382	TRANE	5TWR7036A1	5TXCC007AS3	S9X1C080U5PSB	21,600	\$3,024
216766384	TRANE	5TWR7036A1	5TXCC007AS3	S9V2C100U5VSB	21,400	\$2,996
216763897	TRANE	5TWR7036A1	5TXCC007AS3	S9V2C100U5PSC	21,400	\$2,996
216763899	TRANE	5TWR7036A1	5TXCC007AS3	S9V2C100U4VSB	21,400	\$2,996
216766378	TRANE	5TWR7036A1	5TXCC007AS3	S9V2C100D5VSB	21,000	\$2,940
216763905	TRANE	5TWR7036A1	5TXCC007AS3	S9V2C100D5PSC	21,000	\$2,940
216763903	TRANE	5TWR7036A1	5TXCC007AS3	S9V2C100D4VSB	21,000	\$2,940
216766386	TRANE	5TWR7036A1	5TXCC007AS3	S9V2C080U5VSB	21,400	\$2,996
216763901	TRANE	5TWR7036A1	5TXCC007AS3	S9V2C080U5PSC	21,400	\$2,996
216764747	TRANE	5TWR7036A1	5TXCC007AS3	S8X2C100M5PTC	21,200	\$2,968
216764749	TRANE	5TWR7036A1	5TXCC007AS3	S8X2C100M5PSC	21,200	\$2,968
216764751	TRANE	5TWR7036A1	5TXCC007AS3	S8X2C080M5PTC	21,400	\$2,996
216764745	TRANE	5TWR7036A1	5TXCC007AS3	S8X2C080M5PSC	21,400	\$2,996
216764753	TRANE	5TWR7036A1	5TXCC007AS3	S8X1C100M5PTC	21,200	\$2,968
216763885	TRANE	5TWR7036A1	5TXCC007AS3	S8X1C100M5PSC	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216764755	TRANE	5TWR7036A1	5TXCC007AS3	S8X1C080M5PTC	21,400	\$2,996
216763887	TRANE	5TWR7036A1	5TXCC007AS3	S8X1C080M5PSC	21,400	\$2,996
216766372	TRANE	5TWR7036A1	5TXCC007AS3	S8V2C100M5PDB	21,400	\$2,996
216766388	TRANE	5TWR7036A1	5TXCC007AS3	S8V2C100M5PCB	21,400	\$2,996
216766374	TRANE	5TWR7036A1	5TXCC007AS3	S8V2C080M5PDB	21,400	\$2,996
216766390	TRANE	5TWR7036A1	5TXCC007AS3	S8V2C080M5PCB	21,400	\$2,996
216763889	TRANE	5TWR7036A1	5TXCC007AS3	N/A	21,800	\$3,052
216763891	TRANE	5TWR7036A1	5TXCC007AS3	L9X1C100U5VSA	21,200	\$2,968
216763893	TRANE	5TWR7036A1	5TXCC007AS3	L8V1C100U5VSB	21,400	\$2,996
216763895	TRANE	5TWR7036A1	5TXCC007AS3	*UHMC100CCV4	21,200	\$2,968
216763883	TRANE	5TWR7036A1	5TXCC007AS3	*DHMC100CCV4	21,000	\$2,940
216766356	TRANE	5TWR7036A1	5TXCC005AS3	S9X2C100U5PSB	21,400	\$2,996
216766364	TRANE	5TWR7036A1	5TXCC005AS3	S9X2C080U5PSB	21,200	\$2,968
216766358	TRANE	5TWR7036A1	5TXCC005AS3	S9X1C100U5PSB	21,400	\$2,996
216766352	TRANE	5TWR7036A1	5TXCC005AS3	S9X1C080U5PSB	21,200	\$2,968
216766350	TRANE	5TWR7036A1	5TXCC005AS3	S9V2C100U5VSB	21,000	\$2,940
216769952	TRANE	5TWR7036A1	5TXCC005AS3	S9V2C100U5PSC	21,000	\$2,940
216769954	TRANE	5TWR7036A1	5TXCC005AS3	S9V2C100U4VSB	21,000	\$2,940
216766348	TRANE	5TWR7036A1	5TXCC005AS3	S9V2C080U5VSB	21,000	\$2,940
216769956	TRANE	5TWR7036A1	5TXCC005AS3	S9V2C080U5PSC	21,000	\$2,940
216769958	TRANE	5TWR7036A1	5TXCC005AS3	S8X2C100M5PTC	21,000	\$2,940
216769960	TRANE	5TWR7036A1	5TXCC005AS3	S8X2C100M5PSC	21,000	\$2,940
216769962	TRANE	5TWR7036A1	5TXCC005AS3	S8X2C080M5PTC	21,200	\$2,968
216769964	TRANE	5TWR7036A1	5TXCC005AS3	S8X2C080M5PSC	21,200	\$2,968
216769966	TRANE	5TWR7036A1	5TXCC005AS3	S8X1C100M5PTC	21,000	\$2,940
216769968	TRANE	5TWR7036A1	5TXCC005AS3	S8X1C100M5PSC	21,000	\$2,940
216769950	TRANE	5TWR7036A1	5TXCC005AS3	S8X1C080M5PTC	21,200	\$2,968
216769942	TRANE	5TWR7036A1	5TXCC005AS3	S8X1C080M5PSC	21,200	\$2,968
216766360	TRANE	5TWR7036A1	5TXCC005AS3	S8V2C100M5PDB	21,200	\$2,968
216766346	TRANE	5TWR7036A1	5TXCC005AS3	S8V2C100M5PCB	21,200	\$2,968
216766362	TRANE	5TWR7036A1	5TXCC005AS3	S8V2C080M5PDB	21,400	\$2,996
216766344	TRANE	5TWR7036A1	5TXCC005AS3	S8V2C080M5PCB	21,400	\$2,996
216763881	TRANE	5TWR7036A1	5TXCC005AS3	N/A	22,000	\$3,080
216769944	TRANE	5TWR7036A1	5TXCC005AS3	L9X1C100U5VSA	21,200	\$2,968
216769946	TRANE	5TWR7036A1	5TXCC005AS3	L8V1C100U5VSB	21,400	\$2,996
216769948	TRANE	5TWR7036A1	5TXCC005AS3	*UHMC100CCV4	21,000	\$2,940
216766306	TRANE	5TWR7036A1	5TXCB006AS3	S9X2B080U4PSB	21,600	\$3,024
216766334	TRANE	5TWR7036A1	5TXCB006AS3	S9X2B080D4PSB	21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766308	TRANE	5TWR7036A1	5TXCB006AS3	S9X2B060U4PSB	21,400	\$2,996
216766336	TRANE	5TWR7036A1	5TXCB006AS3	S9X2B060D3PSB	21,000	\$2,940
216766310	TRANE	5TWR7036A1	5TXCB006AS3	S9X2B040U3PSB	21,400	\$2,996
216766304	TRANE	5TWR7036A1	5TXCB006AS3	S9X2B040D3PSB	21,400	\$2,996
216766328	TRANE	5TWR7036A1	5TXCB006AS3	S9X1B080U4PSB	21,600	\$3,024
216766300	TRANE	5TWR7036A1	5TXCB006AS3	S9X1B080D4PSB	21,000	\$2,940
216766332	TRANE	5TWR7036A1	5TXCB006AS3	S9X1B060U4PSB	21,400	\$2,996
216766302	TRANE	5TWR7036A1	5TXCB006AS3	S9X1B060D3PSB	21,000	\$2,940
216766330	TRANE	5TWR7036A1	5TXCB006AS3	S9X1B040U3PSB	21,400	\$2,996
216766324	TRANE	5TWR7036A1	5TXCB006AS3	S9X1B040D3PSB	21,400	\$2,996
216763852	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B080U4VSB	21,400	\$2,996
216763854	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B080U4PSC	21,400	\$2,996
216763838	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B080D4VSB	20,800	\$2,912
216763840	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B080D4PSC	20,800	\$2,912
216766312	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B060U4VSB	21,200	\$2,968
216763856	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B060U4PSC	21,200	\$2,968
216763858	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B060U3VSB	21,200	\$2,968
216763842	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B060D3VSB	20,800	\$2,912
216763844	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B060D3PSC	20,800	\$2,912
216763860	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B040U3VSB	21,200	\$2,968
216763879	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B040U3PSC	21,200	\$2,968
216766326	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B040D3VSB	20,800	\$2,912
216763846	TRANE	5TWR7036A1	5TXCB006AS3	S9V2B040D3PSC	20,800	\$2,912
216764729	TRANE	5TWR7036A1	5TXCB006AS3	S8X2B080M4PTC	21,400	\$2,996
216764741	TRANE	5TWR7036A1	5TXCB006AS3	S8X2B080M4PSC	21,400	\$2,996
216764733	TRANE	5TWR7036A1	5TXCB006AS3	S8X2B060M4PTC	21,400	\$2,996
216764739	TRANE	5TWR7036A1	5TXCB006AS3	S8X2B060M4PSC	21,400	\$2,996
216764727	TRANE	5TWR7036A1	5TXCB006AS3	S8X2A040M3PTC	21,200	\$2,968
216764731	TRANE	5TWR7036A1	5TXCB006AS3	S8X2A040M3PSC	21,200	\$2,968
216764735	TRANE	5TWR7036A1	5TXCB006AS3	S8X1B080M4PTC	21,400	\$2,996
216763877	TRANE	5TWR7036A1	5TXCB006AS3	S8X1B080M4PSC	21,400	\$2,996
216764737	TRANE	5TWR7036A1	5TXCB006AS3	S8X1B060M4PTC	21,400	\$2,996
216763875	TRANE	5TWR7036A1	5TXCB006AS3	S8X1B060M4PSC	21,400	\$2,996
216764743	TRANE	5TWR7036A1	5TXCB006AS3	S8X1A040M3PTC	21,200	\$2,968
216763873	TRANE	5TWR7036A1	5TXCB006AS3	S8X1A040M3PSC	21,200	\$2,968
216766338	TRANE	5TWR7036A1	5TXCB006AS3	S8V2B080M4PDB	21,400	\$2,996
216766314	TRANE	5TWR7036A1	5TXCB006AS3	S8V2B080M4PCB	21,400	\$2,996
216766340	TRANE	5TWR7036A1	5TXCB006AS3	S8V2B060M4PDB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766316	TRANE	5TWR7036A1	5TXCB006AS3	S8V2B060M4PCB	21,200	\$2,968
216766342	TRANE	5TWR7036A1	5TXCB006AS3	S8V2A040M3PDB	21,400	\$2,996
216766318	TRANE	5TWR7036A1	5TXCB006AS3	S8V2A040M3PCB	21,400	\$2,996
216763871	TRANE	5TWR7036A1	5TXCB006AS3	N/A	21,800	\$3,052
216763869	TRANE	5TWR7036A1	5TXCB006AS3	L9X1B070U4VSA	21,600	\$3,024
216763867	TRANE	5TWR7036A1	5TXCB006AS3	L9X1A050U3VSA	21,600	\$3,024
216763865	TRANE	5TWR7036A1	5TXCB006AS3	L8V1B080U4VSB	21,200	\$2,968
216763862	TRANE	5TWR7036A1	5TXCB006AS3	L8V1A060U3VSB	21,200	\$2,968
216763850	TRANE	5TWR7036A1	5TXCB006AS3	L8V1A040U3VSB	21,400	\$2,996
216763834	TRANE	5TWR7036A1	5TXCB006AS3	*UHMB080CCV3	21,200	\$2,968
216763836	TRANE	5TWR7036A1	5TXCB006AS3	*UHMB060CCV3	21,200	\$2,968
216763848	TRANE	5TWR7036A1	5TXCB006AS3	*DHMB080CCV3	20,800	\$2,912
216763832	TRANE	5TWR7036A1	5TXCB006AS3	*DHMB060CCV3	21,200	\$2,968
216766282	TRANE	5TWR7036A1	5TXCB004AS3	S9X2B080U4PSB	21,000	\$2,940
216766284	TRANE	5TWR7036A1	5TXCB004AS3	S9X2B060U4PSB	21,400	\$2,996
216766286	TRANE	5TWR7036A1	5TXCB004AS3	S9X2B040U3PSB	21,200	\$2,968
216766274	TRANE	5TWR7036A1	5TXCB004AS3	S9X1B080U4PSB	21,000	\$2,940
216766276	TRANE	5TWR7036A1	5TXCB004AS3	S9X1B060U4PSB	21,400	\$2,996
216766278	TRANE	5TWR7036A1	5TXCB004AS3	S9X1B040U3PSB	21,200	\$2,968
216763820	TRANE	5TWR7036A1	5TXCB004AS3	S9V2B080U4VSB	21,200	\$2,968
216763818	TRANE	5TWR7036A1	5TXCB004AS3	S9V2B080U4PSC	21,200	\$2,968
216766280	TRANE	5TWR7036A1	5TXCB004AS3	S9V2B060U4VSB	21,200	\$2,968
216763816	TRANE	5TWR7036A1	5TXCB004AS3	S9V2B060U4PSC	21,200	\$2,968
216763814	TRANE	5TWR7036A1	5TXCB004AS3	S9V2B060U3VSB	21,200	\$2,968
216763812	TRANE	5TWR7036A1	5TXCB004AS3	S9V2B040U3VSB	21,200	\$2,968
216763810	TRANE	5TWR7036A1	5TXCB004AS3	S9V2B040U3PSC	21,200	\$2,968
216764715	TRANE	5TWR7036A1	5TXCB004AS3	S8X2B080M4PTC	21,600	\$3,024
216764719	TRANE	5TWR7036A1	5TXCB004AS3	S8X2B080M4PSC	21,600	\$3,024
216764723	TRANE	5TWR7036A1	5TXCB004AS3	S8X2B060M4PTC	21,200	\$2,968
216764713	TRANE	5TWR7036A1	5TXCB004AS3	S8X2B060M4PSC	21,200	\$2,968
216764709	TRANE	5TWR7036A1	5TXCB004AS3	S8X2A040M3PTC	21,400	\$2,996
216764711	TRANE	5TWR7036A1	5TXCB004AS3	S8X2A040M3PSC	21,400	\$2,996
216764717	TRANE	5TWR7036A1	5TXCB004AS3	S8X1B080M4PTC	21,600	\$3,024
216763808	TRANE	5TWR7036A1	5TXCB004AS3	S8X1B080M4PSC	21,600	\$3,024
216764721	TRANE	5TWR7036A1	5TXCB004AS3	S8X1B060M4PTC	21,200	\$2,968
216763824	TRANE	5TWR7036A1	5TXCB004AS3	S8X1B060M4PSC	21,200	\$2,968
216764725	TRANE	5TWR7036A1	5TXCB004AS3	S8X1A040M3PTC	21,400	\$2,996
216763822	TRANE	5TWR7036A1	5TXCB004AS3	S8X1A040M3PSC	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766298	TRANE	5TWR7036A1	5TXCB004AS3	S8V2B080M4PDB	21,200	\$2,968
216766292	TRANE	5TWR7036A1	5TXCB004AS3	S8V2B080M4PCB	21,200	\$2,968
216766290	TRANE	5TWR7036A1	5TXCB004AS3	S8V2B060M4PDB	21,200	\$2,968
216766294	TRANE	5TWR7036A1	5TXCB004AS3	S8V2B060M4PCB	21,200	\$2,968
216766288	TRANE	5TWR7036A1	5TXCB004AS3	S8V2A040M3PDB	21,200	\$2,968
216766296	TRANE	5TWR7036A1	5TXCB004AS3	S8V2A040M3PCB	21,200	\$2,968
216763806	TRANE	5TWR7036A1	5TXCB004AS3	N/A	21,600	\$3,024
216763804	TRANE	5TWR7036A1	5TXCB004AS3	L9X1B070U4VSA	21,600	\$3,024
216763802	TRANE	5TWR7036A1	5TXCB004AS3	L9X1A050U3VSA	21,800	\$3,052
216763800	TRANE	5TWR7036A1	5TXCB004AS3	L8V1B080U4VSB	21,200	\$2,968
216763798	TRANE	5TWR7036A1	5TXCB004AS3	L8V1A060U3VSB	21,000	\$2,940
216763830	TRANE	5TWR7036A1	5TXCB004AS3	L8V1A040U3VSB	21,400	\$2,996
216763828	TRANE	5TWR7036A1	5TXCB004AS3	*UHMB080CCV3	21,000	\$2,940
216763826	TRANE	5TWR7036A1	5TXCB004AS3	*UHMB060CCV3	21,000	\$2,940
216763796	TRANE	5TWR7036A1	5TEMCD07AV51+TD	N/A	21,000	\$2,940
216763794	TRANE	5TWR7036A1	5TEMCD06AV41+TD	N/A	21,000	\$2,940
216763792	TRANE	5TWR7036A1	5TEMCD05AV41+TD	N/A	21,200	\$2,968
216763790	TRANE	5TWR7036A1	5TEMCD04AV31+TD	N/A	21,200	\$2,968
216763786	TRANE	5TWR7036A1	5TEM6D07AV51+TD	N/A	21,000	\$2,940
216763784	TRANE	5TWR7036A1	5TEM6D06AV41+TD	N/A	21,000	\$2,940
216763782	TRANE	5TWR7036A1	5TEM6D05AV41+TD	N/A	21,200	\$2,968
216763780	TRANE	5TWR7036A1	5TEM6D04AV31+TD	N/A	21,200	\$2,968
216763776	TRANE	5TWR7036A1	5TAMXD07AV51	N/A	21,000	\$2,940
216763774	TRANE	5TWR7036A1	5TAMXD06AV41	N/A	21,400	\$2,996
216763772	TRANE	5TWR7036A1	5TAMXD05AV41	N/A	21,200	\$2,968
216763768	TRANE	5TWR7036A1	5TAMXC03AV31	N/A	21,400	\$2,996
216763766	TRANE	5TWR7036A1	5TAM5D05AC31	N/A	21,400	\$2,996
216766262	TRANE	5TWR7036A1	5PX*DD10AS3	S9X2D120D5PSB	21,200	\$2,968
216766268	TRANE	5TWR7036A1	5PX*DD10AS3	S9X1D120D5PSB	21,200	\$2,968
216766264	TRANE	5TWR7036A1	5PX*DD10AS3	S8V2D120M5PDB	21,200	\$2,968
216766266	TRANE	5TWR7036A1	5PX*DD10AS3	S8V2D120M5PCB	21,200	\$2,968
216763760	TRANE	5TWR7036A1	5PX*DD10AS3	N/A	21,600	\$3,024
216769940	TRANE	5TWR7036A1	5PX*DD10AS3	*DHMD120CCV5	20,800	\$2,912
216766258	TRANE	5TWR7036A1	5PX*D010AS3	S9X2D120U5PSB	21,000	\$2,940
216766260	TRANE	5TWR7036A1	5PX*D010AS3	S9X1D120U5PSB	21,000	\$2,940
216763756	TRANE	5TWR7036A1	5PX*D010AS3	S9V2D120U5VSB	21,200	\$2,968
216763754	TRANE	5TWR7036A1	5PX*D010AS3	S9V2D120U5PSC	21,200	\$2,968
216766254	TRANE	5TWR7036A1	5PX*D010AS3	S8V2D120M5PDB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766256	TRANE	5TWR7036A1	5PX*D010AS3	S8V2D120M5PCB	21,200	\$2,968
216763752	TRANE	5TWR7036A1	5PX*D010AS3	N/A	21,600	\$3,024
216763758	TRANE	5TWR7036A1	5PX*D010AS3	*UHMD120CCV5	21,000	\$2,940
216766250	TRANE	5TWR7036A1	5PX*D008AS3	S9X2D120U5PSB	21,200	\$2,968
216766252	TRANE	5TWR7036A1	5PX*D008AS3	S9X2D120D5PSB	21,000	\$2,940
216766244	TRANE	5TWR7036A1	5PX*D008AS3	S9X1D120U5PSB	21,200	\$2,968
216766246	TRANE	5TWR7036A1	5PX*D008AS3	S9X1D120D5PSB	21,000	\$2,940
216763750	TRANE	5TWR7036A1	5PX*D008AS3	S9V2D120U5VSB	21,400	\$2,996
216763746	TRANE	5TWR7036A1	5PX*D008AS3	S9V2D120U5PSC	21,400	\$2,996
216764703	TRANE	5TWR7036A1	5PX*D008AS3	S8X2D120M5PTC	21,000	\$2,940
216764707	TRANE	5TWR7036A1	5PX*D008AS3	S8X2D120M5PSC	21,000	\$2,940
216764705	TRANE	5TWR7036A1	5PX*D008AS3	S8X1D120M5PTC	21,000	\$2,940
216763748	TRANE	5TWR7036A1	5PX*D008AS3	S8X1D120M5PSC	21,000	\$2,940
216766248	TRANE	5TWR7036A1	5PX*D008AS3	S8V2D120M5PDB	21,400	\$2,996
216766242	TRANE	5TWR7036A1	5PX*D008AS3	S8V2D120M5PCB	21,400	\$2,996
216763744	TRANE	5TWR7036A1	5PX*D008AS3	N/A	21,800	\$3,052
216769938	TRANE	5TWR7036A1	5PX*D008AS3	*UHMD120CCV5	21,200	\$2,968
216769936	TRANE	5TWR7036A1	5PX*D008AS3	*DHMD120CCV5	21,000	\$2,940
216766236	TRANE	5TWR7036A1	5PX*CD09AS3	S9X2C100D5PSB	21,400	\$2,996
216766226	TRANE	5TWR7036A1	5PX*CD09AS3	S9X1C100D5PSB	21,400	\$2,996
216766228	TRANE	5TWR7036A1	5PX*CD09AS3	S9V2C100D5VSB	21,000	\$2,940
216763736	TRANE	5TWR7036A1	5PX*CD09AS3	S9V2C100D5PSC	21,000	\$2,940
216763738	TRANE	5TWR7036A1	5PX*CD09AS3	S9V2C100D4VSB	21,000	\$2,940
216769934	TRANE	5TWR7036A1	5PX*CD09AS3	S8X2C100M5PTC	21,400	\$2,996
216769932	TRANE	5TWR7036A1	5PX*CD09AS3	S8X2C100M5PSC	21,400	\$2,996
216764699	TRANE	5TWR7036A1	5PX*CD09AS3	S8X2C080M5PTC	21,200	\$2,968
216764701	TRANE	5TWR7036A1	5PX*CD09AS3	S8X2C080M5PSC	21,200	\$2,968
216769930	TRANE	5TWR7036A1	5PX*CD09AS3	S8X1C100M5PTC	21,400	\$2,996
216769928	TRANE	5TWR7036A1	5PX*CD09AS3	S8X1C100M5PSC	21,400	\$2,996
216764697	TRANE	5TWR7036A1	5PX*CD09AS3	S8X1C080M5PTC	21,200	\$2,968
216763740	TRANE	5TWR7036A1	5PX*CD09AS3	S8X1C080M5PSC	21,200	\$2,968
216766240	TRANE	5TWR7036A1	5PX*CD09AS3	S8V2C100M5PDB	21,200	\$2,968
216766230	TRANE	5TWR7036A1	5PX*CD09AS3	S8V2C100M5PCB	21,200	\$2,968
216766238	TRANE	5TWR7036A1	5PX*CD09AS3	S8V2C080M5PDB	21,200	\$2,968
216766232	TRANE	5TWR7036A1	5PX*CD09AS3	S8V2C080M5PCB	21,200	\$2,968
216763742	TRANE	5TWR7036A1	5PX*CD09AS3	N/A	21,800	\$3,052
216769926	TRANE	5TWR7036A1	5PX*CD09AS3	*DHMC100CCV4	21,000	\$2,940
216766224	TRANE	5TWR7036A1	5PX*CD07AS3	S9X2C100D5PSB	21,800	\$3,052

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766214	TRANE	5TWR7036A1	5PX*CD07AS3	S9X1C100D5PSB	21,800	\$3,052
216766216	TRANE	5TWR7036A1	5PX*CD07AS3	S9V2C100D5VSB	21,600	\$3,024
216763732	TRANE	5TWR7036A1	5PX*CD07AS3	S9V2C100D5PSC	21,600	\$3,024
216763734	TRANE	5TWR7036A1	5PX*CD07AS3	S9V2C100D4VSB	21,600	\$3,024
216764691	TRANE	5TWR7036A1	5PX*CD07AS3	S8X2C100M5PTC	21,400	\$2,996
216764687	TRANE	5TWR7036A1	5PX*CD07AS3	S8X2C100M5PSC	21,400	\$2,996
216764693	TRANE	5TWR7036A1	5PX*CD07AS3	S8X1C100M5PTC	21,400	\$2,996
216763728	TRANE	5TWR7036A1	5PX*CD07AS3	S8X1C100M5PSC	21,400	\$2,996
216766210	TRANE	5TWR7036A1	5PX*CD07AS3	S8V2C100M5PDB	21,800	\$3,052
216766218	TRANE	5TWR7036A1	5PX*CD07AS3	S8V2C100M5PCB	21,800	\$3,052
216766212	TRANE	5TWR7036A1	5PX*CD07AS3	S8V2C080M5PDB	21,800	\$3,052
216766222	TRANE	5TWR7036A1	5PX*CD07AS3	S8V2C080M5PCB	21,800	\$3,052
216763726	TRANE	5TWR7036A1	5PX*CD07AS3	N/A	21,800	\$3,052
216766204	TRANE	5TWR7036A1	5PX*CD05AS3	S8V2C100M5PDB	21,600	\$3,024
216766196	TRANE	5TWR7036A1	5PX*CD05AS3	S8V2C100M5PCB	21,600	\$3,024
216766206	TRANE	5TWR7036A1	5PX*CD05AS3	S8V2C080M5PDB	21,600	\$3,024
216766198	TRANE	5TWR7036A1	5PX*CD05AS3	S8V2C080M5PCB	21,600	\$3,024
216763718	TRANE	5TWR7036A1	5PX*CD05AS3	N/A	22,000	\$3,080
216766192	TRANE	5TWR7036A1	5PX*C009AS3	S9X2C100U5PSB	21,200	\$2,968
216766190	TRANE	5TWR7036A1	5PX*C009AS3	S9X2C080U5PSB	21,400	\$2,996
216766172	TRANE	5TWR7036A1	5PX*C009AS3	S9X1C100U5PSB	21,200	\$2,968
216766186	TRANE	5TWR7036A1	5PX*C009AS3	S9X1C080U5PSB	21,400	\$2,996
216766176	TRANE	5TWR7036A1	5PX*C009AS3	S9V2C100U5VSB	21,200	\$2,968
216763710	TRANE	5TWR7036A1	5PX*C009AS3	S9V2C100U5PSC	21,200	\$2,968
216763712	TRANE	5TWR7036A1	5PX*C009AS3	S9V2C100U4VSB	21,200	\$2,968
216766178	TRANE	5TWR7036A1	5PX*C009AS3	S9V2C080U5VSB	21,200	\$2,968
216763714	TRANE	5TWR7036A1	5PX*C009AS3	S9V2C080U5PSC	21,200	\$2,968
216769920	TRANE	5TWR7036A1	5PX*C009AS3	S8X2C100M5PTC	21,400	\$2,996
216769922	TRANE	5TWR7036A1	5PX*C009AS3	S8X2C100M5PSC	21,400	\$2,996
216764673	TRANE	5TWR7036A1	5PX*C009AS3	S8X2C080M5PTC	21,200	\$2,968
216764675	TRANE	5TWR7036A1	5PX*C009AS3	S8X2C080M5PSC	21,200	\$2,968
216769924	TRANE	5TWR7036A1	5PX*C009AS3	S8X1C100M5PTC	21,400	\$2,996
216769918	TRANE	5TWR7036A1	5PX*C009AS3	S8X1C100M5PSC	21,400	\$2,996
216764677	TRANE	5TWR7036A1	5PX*C009AS3	S8X1C080M5PTC	21,200	\$2,968
216763716	TRANE	5TWR7036A1	5PX*C009AS3	S8X1C080M5PSC	21,200	\$2,968
216766174	TRANE	5TWR7036A1	5PX*C009AS3	S8V2C100M5PDB	21,200	\$2,968
216766180	TRANE	5TWR7036A1	5PX*C009AS3	S8V2C100M5PCB	21,200	\$2,968
216766188	TRANE	5TWR7036A1	5PX*C009AS3	S8V2C080M5PDB	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766182	TRANE	5TWR7036A1	5PX*C009AS3	S8V2C080M5PCB	21,400	\$2,996
216763708	TRANE	5TWR7036A1	5PX*C009AS3	N/A	21,600	\$3,024
216769914	TRANE	5TWR7036A1	5PX*C009AS3	L9X1C100U5VSA	21,200	\$2,968
216763706	TRANE	5TWR7036A1	5PX*C009AS3	L8V1C100U5VSB	21,200	\$2,968
216769916	TRANE	5TWR7036A1	5PX*C009AS3	*UHMC100CCV4	21,000	\$2,940
216766168	TRANE	5TWR7036A1	5PX*C007AS3	S9X2C100U5PSB	21,400	\$2,996
216766156	TRANE	5TWR7036A1	5PX*C007AS3	S9X2C100D5PSB	21,200	\$2,968
216766166	TRANE	5TWR7036A1	5PX*C007AS3	S9X2C080U5PSB	21,600	\$3,024
216766148	TRANE	5TWR7036A1	5PX*C007AS3	S9X1C100U5PSB	21,400	\$2,996
216766152	TRANE	5TWR7036A1	5PX*C007AS3	S9X1C100D5PSB	21,200	\$2,968
216766146	TRANE	5TWR7036A1	5PX*C007AS3	S9X1C080U5PSB	21,600	\$3,024
216766144	TRANE	5TWR7036A1	5PX*C007AS3	S9V2C100U5VSB	21,400	\$2,996
216763702	TRANE	5TWR7036A1	5PX*C007AS3	S9V2C100U5PSC	21,400	\$2,996
216763700	TRANE	5TWR7036A1	5PX*C007AS3	S9V2C100U4VSB	21,400	\$2,996
216766150	TRANE	5TWR7036A1	5PX*C007AS3	S9V2C100D5VSB	21,000	\$2,940
216763686	TRANE	5TWR7036A1	5PX*C007AS3	S9V2C100D5PSC	21,000	\$2,940
216763704	TRANE	5TWR7036A1	5PX*C007AS3	S9V2C100D4VSB	21,000	\$2,940
216766158	TRANE	5TWR7036A1	5PX*C007AS3	S9V2C080U5VSB	21,400	\$2,996
216763698	TRANE	5TWR7036A1	5PX*C007AS3	S9V2C080U5PSC	21,400	\$2,996
216764667	TRANE	5TWR7036A1	5PX*C007AS3	S8X2C100M5PTC	21,600	\$3,024
216764663	TRANE	5TWR7036A1	5PX*C007AS3	S8X2C100M5PSC	21,600	\$3,024
216764665	TRANE	5TWR7036A1	5PX*C007AS3	S8X2C080M5PTC	21,400	\$2,996
216764661	TRANE	5TWR7036A1	5PX*C007AS3	S8X2C080M5PSC	21,400	\$2,996
216764671	TRANE	5TWR7036A1	5PX*C007AS3	S8X1C100M5PTC	21,600	\$3,024
216763696	TRANE	5TWR7036A1	5PX*C007AS3	S8X1C100M5PSC	21,600	\$3,024
216764669	TRANE	5TWR7036A1	5PX*C007AS3	S8X1C080M5PTC	21,400	\$2,996
216763694	TRANE	5TWR7036A1	5PX*C007AS3	S8X1C080M5PSC	21,400	\$2,996
216766154	TRANE	5TWR7036A1	5PX*C007AS3	S8V2C100M5PDB	21,400	\$2,996
216766160	TRANE	5TWR7036A1	5PX*C007AS3	S8V2C100M5PCB	21,400	\$2,996
216766170	TRANE	5TWR7036A1	5PX*C007AS3	S8V2C080M5PDB	21,400	\$2,996
216766162	TRANE	5TWR7036A1	5PX*C007AS3	S8V2C080M5PCB	21,400	\$2,996
216763692	TRANE	5TWR7036A1	5PX*C007AS3	N/A	21,800	\$3,052
216763690	TRANE	5TWR7036A1	5PX*C007AS3	L9X1C100U5VSA	21,200	\$2,968
216763688	TRANE	5TWR7036A1	5PX*C007AS3	L8V1C100U5VSB	21,400	\$2,996
216769910	TRANE	5TWR7036A1	5PX*C007AS3	*UHMC100CCV4	21,200	\$2,968
216769912	TRANE	5TWR7036A1	5PX*C007AS3	*DHMC100CCV4	21,000	\$2,940
216766140	TRANE	5TWR7036A1	5PX*C005AS3	S9X2C100U5PSB	21,200	\$2,968
216766142	TRANE	5TWR7036A1	5PX*C005AS3	S9X2C080U5PSB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766134	TRANE	5TWR7036A1	5PX*C005AS3	S9X1C100U5PSB	21,200	\$2,968
216766138	TRANE	5TWR7036A1	5PX*C005AS3	S9X1C080U5PSB	21,200	\$2,968
216766136	TRANE	5TWR7036A1	5PX*C005AS3	S9V2C100U5VSB	21,000	\$2,940
216763680	TRANE	5TWR7036A1	5PX*C005AS3	S9V2C100U5PSC	21,000	\$2,940
216763670	TRANE	5TWR7036A1	5PX*C005AS3	S9V2C100U4VSB	21,000	\$2,940
216766126	TRANE	5TWR7036A1	5PX*C005AS3	S9V2C080U5VSB	21,000	\$2,940
216763672	TRANE	5TWR7036A1	5PX*C005AS3	S9V2C080U5PSC	21,000	\$2,940
216764655	TRANE	5TWR7036A1	5PX*C005AS3	S8X2C100M5PTC	21,000	\$2,940
216764651	TRANE	5TWR7036A1	5PX*C005AS3	S8X2C100M5PSC	21,000	\$2,940
216764649	TRANE	5TWR7036A1	5PX*C005AS3	S8X2C080M5PTC	21,600	\$3,024
216764653	TRANE	5TWR7036A1	5PX*C005AS3	S8X2C080M5PSC	21,600	\$3,024
216764659	TRANE	5TWR7036A1	5PX*C005AS3	S8X1C100M5PTC	21,000	\$2,940
216763674	TRANE	5TWR7036A1	5PX*C005AS3	S8X1C100M5PSC	21,000	\$2,940
216764657	TRANE	5TWR7036A1	5PX*C005AS3	S8X1C080M5PTC	21,600	\$3,024
216763676	TRANE	5TWR7036A1	5PX*C005AS3	S8X1C080M5PSC	21,600	\$3,024
216766132	TRANE	5TWR7036A1	5PX*C005AS3	S8V2C100M5PDB	21,200	\$2,968
216766122	TRANE	5TWR7036A1	5PX*C005AS3	S8V2C100M5PCB	21,200	\$2,968
216766124	TRANE	5TWR7036A1	5PX*C005AS3	S8V2C080M5PDB	21,400	\$2,996
216766130	TRANE	5TWR7036A1	5PX*C005AS3	S8V2C080M5PCB	21,400	\$2,996
216763682	TRANE	5TWR7036A1	5PX*C005AS3	N/A	22,000	\$3,080
216763684	TRANE	5TWR7036A1	5PX*C005AS3	L9X1C100U5VSA	21,800	\$3,052
216763678	TRANE	5TWR7036A1	5PX*C005AS3	L8V1C100U5VSB	21,400	\$2,996
216769908	TRANE	5TWR7036A1	5PX*C005AS3	*UHMC100CCV4	21,000	\$2,940
216766108	TRANE	5TWR7036A1	5PX*BD06AS3	S9X2B040D3PSB	22,000	\$3,080
216766104	TRANE	5TWR7036A1	5PX*BD06AS3	S9X1B040D3PSB	22,000	\$3,080
216763654	TRANE	5TWR7036A1	5PX*BD06AS3	S9V2B060D3VSB	21,600	\$3,024
216763652	TRANE	5TWR7036A1	5PX*BD06AS3	S9V2B060D3PSC	21,600	\$3,024
216766106	TRANE	5TWR7036A1	5PX*BD06AS3	S9V2B040D3VSB	21,600	\$3,024
216763666	TRANE	5TWR7036A1	5PX*BD06AS3	S9V2B040D3PSC	21,600	\$3,024
216764633	TRANE	5TWR7036A1	5PX*BD06AS3	S8X2B080M4PTC	21,800	\$3,052
216764639	TRANE	5TWR7036A1	5PX*BD06AS3	S8X2B080M4PSC	21,800	\$3,052
216764631	TRANE	5TWR7036A1	5PX*BD06AS3	S8X2A040M3PTC	21,800	\$3,052
216764647	TRANE	5TWR7036A1	5PX*BD06AS3	S8X2A040M3PSC	21,800	\$3,052
216764635	TRANE	5TWR7036A1	5PX*BD06AS3	S8X1B080M4PTC	21,800	\$3,052
216763660	TRANE	5TWR7036A1	5PX*BD06AS3	S8X1B080M4PSC	21,800	\$3,052
216764645	TRANE	5TWR7036A1	5PX*BD06AS3	S8X1A040M3PTC	21,800	\$3,052
216763662	TRANE	5TWR7036A1	5PX*BD06AS3	S8X1A040M3PSC	21,800	\$3,052
216766118	TRANE	5TWR7036A1	5PX*BD06AS3	S8V2B080M4PDB	21,400	\$2,996

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766114	TRANE	5TWR7036A1	5PX*BD06AS3	S8V2B080M4PCB	21,400	\$2,996
216766094	TRANE	5TWR7036A1	5PX*BD06AS3	S8V2B060M4PDB	21,600	\$3,024
216766092	TRANE	5TWR7036A1	5PX*BD06AS3	S8V2B060M4PCB	21,600	\$3,024
216766116	TRANE	5TWR7036A1	5PX*BD06AS3	S8V2A040M3PDB	21,400	\$2,996
216766120	TRANE	5TWR7036A1	5PX*BD06AS3	S8V2A040M3PCB	21,400	\$2,996
216763668	TRANE	5TWR7036A1	5PX*BD06AS3	N/A	21,800	\$3,052
216766086	TRANE	5TWR7036A1	5PX*BD04AS3	S9X2B080D4PSB	21,600	\$3,024
216766088	TRANE	5TWR7036A1	5PX*BD04AS3	S9X2B060D3PSB	21,800	\$3,052
216766090	TRANE	5TWR7036A1	5PX*BD04AS3	S9X2B040D3PSB	22,000	\$3,080
216766070	TRANE	5TWR7036A1	5PX*BD04AS3	S9X1B080D4PSB	21,600	\$3,024
216766072	TRANE	5TWR7036A1	5PX*BD04AS3	S9X1B060D3PSB	21,800	\$3,052
216766074	TRANE	5TWR7036A1	5PX*BD04AS3	S9X1B040D3PSB	22,000	\$3,080
216763650	TRANE	5TWR7036A1	5PX*BD04AS3	S9V2B080D4VSB	21,600	\$3,024
216763648	TRANE	5TWR7036A1	5PX*BD04AS3	S9V2B080D4PSC	21,600	\$3,024
216763646	TRANE	5TWR7036A1	5PX*BD04AS3	S9V2B060D3VSB	21,600	\$3,024
216763642	TRANE	5TWR7036A1	5PX*BD04AS3	S9V2B060D3PSC	21,600	\$3,024
216766084	TRANE	5TWR7036A1	5PX*BD04AS3	S9V2B040D3VSB	21,800	\$3,052
216763644	TRANE	5TWR7036A1	5PX*BD04AS3	S9V2B040D3PSC	21,800	\$3,052
216764613	TRANE	5TWR7036A1	5PX*BD04AS3	S8X2A040M3PTC	21,800	\$3,052
216764621	TRANE	5TWR7036A1	5PX*BD04AS3	S8X2A040M3PSC	21,800	\$3,052
216764625	TRANE	5TWR7036A1	5PX*BD04AS3	S8X1A040M3PTC	21,800	\$3,052
216763638	TRANE	5TWR7036A1	5PX*BD04AS3	S8X1A040M3PSC	21,800	\$3,052
216766066	TRANE	5TWR7036A1	5PX*BD04AS3	S8V2B080M4PDB	21,600	\$3,024
216766076	TRANE	5TWR7036A1	5PX*BD04AS3	S8V2B080M4PCB	21,600	\$3,024
216766068	TRANE	5TWR7036A1	5PX*BD04AS3	S8V2B060M4PDB	21,600	\$3,024
216766078	TRANE	5TWR7036A1	5PX*BD04AS3	S8V2B060M4PCB	21,600	\$3,024
216763640	TRANE	5TWR7036A1	5PX*BD04AS3	N/A	22,000	\$3,080
216766058	TRANE	5TWR7036A1	5PX*B006AS3	S9X2B080U4PSB	21,600	\$3,024
216766060	TRANE	5TWR7036A1	5PX*B006AS3	S9X2B060U4PSB	21,400	\$2,996
216766034	TRANE	5TWR7036A1	5PX*B006AS3	S9X2B060D3PSB	21,200	\$2,968
216766062	TRANE	5TWR7036A1	5PX*B006AS3	S9X2B040U3PSB	21,400	\$2,996
216766040	TRANE	5TWR7036A1	5PX*B006AS3	S9X1B080U4PSB	21,600	\$3,024
216766042	TRANE	5TWR7036A1	5PX*B006AS3	S9X1B060U4PSB	21,400	\$2,996
216766036	TRANE	5TWR7036A1	5PX*B006AS3	S9X1B060D3PSB	21,200	\$2,968
216766044	TRANE	5TWR7036A1	5PX*B006AS3	S9X1B040U3PSB	21,400	\$2,996
216763614	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B080U4VSB	21,200	\$2,968
216763612	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B080U4PSC	21,200	\$2,968
216763620	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B080D4VSB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763618	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B080D4PSC	21,200	\$2,968
216766046	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B060U4VSB	21,400	\$2,996
216763622	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B060U4PSC	21,200	\$2,968
216763624	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B060U3VSB	21,200	\$2,968
216763626	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B040U3VSB	21,200	\$2,968
216763628	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B040U3PSC	21,200	\$2,968
216766038	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B040D3VSB	21,400	\$2,996
216763616	TRANE	5TWR7036A1	5PX*B006AS3	S9V2B040D3PSC	21,400	\$2,996
216764601	TRANE	5TWR7036A1	5PX*B006AS3	S8X2B080M4PTC	21,400	\$2,996
216764607	TRANE	5TWR7036A1	5PX*B006AS3	S8X2B080M4PSC	21,400	\$2,996
216764595	TRANE	5TWR7036A1	5PX*B006AS3	S8X2B060M4PTC	21,400	\$2,996
216764609	TRANE	5TWR7036A1	5PX*B006AS3	S8X2B060M4PSC	21,400	\$2,996
216764603	TRANE	5TWR7036A1	5PX*B006AS3	S8X2A040M3PTC	21,200	\$2,968
216764611	TRANE	5TWR7036A1	5PX*B006AS3	S8X2A040M3PSC	21,200	\$2,968
216764597	TRANE	5TWR7036A1	5PX*B006AS3	S8X1B080M4PTC	21,400	\$2,996
216763606	TRANE	5TWR7036A1	5PX*B006AS3	S8X1B080M4PSC	21,400	\$2,996
216764599	TRANE	5TWR7036A1	5PX*B006AS3	S8X1B060M4PTC	21,400	\$2,996
216763608	TRANE	5TWR7036A1	5PX*B006AS3	S8X1B060M4PSC	21,400	\$2,996
216764605	TRANE	5TWR7036A1	5PX*B006AS3	S8X1A040M3PTC	21,200	\$2,968
216763610	TRANE	5TWR7036A1	5PX*B006AS3	S8X1A040M3PSC	21,200	\$2,968
216766054	TRANE	5TWR7036A1	5PX*B006AS3	S8V2B080M4PDB	21,400	\$2,996
216766048	TRANE	5TWR7036A1	5PX*B006AS3	S8V2B080M4PCB	21,400	\$2,996
216766032	TRANE	5TWR7036A1	5PX*B006AS3	S8V2B060M4PDB	21,400	\$2,996
216766050	TRANE	5TWR7036A1	5PX*B006AS3	S8V2B060M4PCB	21,400	\$2,996
216766030	TRANE	5TWR7036A1	5PX*B006AS3	S8V2A040M3PDB	21,200	\$2,968
216766052	TRANE	5TWR7036A1	5PX*B006AS3	S8V2A040M3PCB	21,200	\$2,968
216763598	TRANE	5TWR7036A1	5PX*B006AS3	N/A	21,800	\$3,052
216763632	TRANE	5TWR7036A1	5PX*B006AS3	L9X1B070U4VSA	21,600	\$3,024
216763602	TRANE	5TWR7036A1	5PX*B006AS3	L9X1A050U3VSA	21,400	\$2,996
216763604	TRANE	5TWR7036A1	5PX*B006AS3	L8V1B080U4VSB	21,200	\$2,968
216763600	TRANE	5TWR7036A1	5PX*B006AS3	L8V1A060U3VSB	21,200	\$2,968
216763630	TRANE	5TWR7036A1	5PX*B006AS3	L8V1A040U3VSB	21,200	\$2,968
216769904	TRANE	5TWR7036A1	5PX*B006AS3	*UHMB080CCV3	21,200	\$2,968
216769902	TRANE	5TWR7036A1	5PX*B006AS3	*UHMB060CCV3	21,200	\$2,968
216769906	TRANE	5TWR7036A1	5PX*B006AS3	*DHMB080CCV3	21,200	\$2,968
216766000	TRANE	5TWR7036A1	5PX*B004AS3	S9X2B080U4PSB	21,000	\$2,940
216766028	TRANE	5TWR7036A1	5PX*B004AS3	S9X2B060U4PSB	21,400	\$2,996
216766002	TRANE	5TWR7036A1	5PX*B004AS3	S9X2B040U3PSB	21,200	\$2,968

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216766004	TRANE	5TWR7036A1	5PX*B004AS3	S9X1B080U4PSB	21,000	\$2,940
216766012	TRANE	5TWR7036A1	5PX*B004AS3	S9X1B060U4PSB	21,400	\$2,996
216766014	TRANE	5TWR7036A1	5PX*B004AS3	S9X1B040U3PSB	21,200	\$2,968
216763580	TRANE	5TWR7036A1	5PX*B004AS3	S9V2B080U4VSB	21,200	\$2,968
216763568	TRANE	5TWR7036A1	5PX*B004AS3	S9V2B080U4PSC	21,200	\$2,968
216766016	TRANE	5TWR7036A1	5PX*B004AS3	S9V2B060U4VSB	21,200	\$2,968
216763584	TRANE	5TWR7036A1	5PX*B004AS3	S9V2B060U4PSC	21,200	\$2,968
216763586	TRANE	5TWR7036A1	5PX*B004AS3	S9V2B060U3VSB	21,200	\$2,968
216763588	TRANE	5TWR7036A1	5PX*B004AS3	S9V2B040U3VSB	21,200	\$2,968
216763590	TRANE	5TWR7036A1	5PX*B004AS3	S9V2B040U3PSC	21,200	\$2,968
216764591	TRANE	5TWR7036A1	5PX*B004AS3	S8X2B080M4PTC	21,600	\$3,024
216764579	TRANE	5TWR7036A1	5PX*B004AS3	S8X2B080M4PSC	21,600	\$3,024
216764589	TRANE	5TWR7036A1	5PX*B004AS3	S8X2B060M4PTC	21,200	\$2,968
216764587	TRANE	5TWR7036A1	5PX*B004AS3	S8X2A040M3PTC	21,400	\$2,996
216764581	TRANE	5TWR7036A1	5PX*B004AS3	S8X2A040M3PSC	21,400	\$2,996
216764583	TRANE	5TWR7036A1	5PX*B004AS3	S8X1B080M4PTC	21,600	\$3,024
216763592	TRANE	5TWR7036A1	5PX*B004AS3	S8X1B080M4PSC	21,600	\$3,024
216764593	TRANE	5TWR7036A1	5PX*B004AS3	S8X1B060M4PTC	21,200	\$2,968
216763594	TRANE	5TWR7036A1	5PX*B004AS3	S8X1B060M4PSC	21,200	\$2,968
216764585	TRANE	5TWR7036A1	5PX*B004AS3	S8X1A040M3PTC	21,400	\$2,996
216763596	TRANE	5TWR7036A1	5PX*B004AS3	S8X1A040M3PSC	21,400	\$2,996
216766010	TRANE	5TWR7036A1	5PX*B004AS3	S8V2B080M4PDB	21,200	\$2,968
216766018	TRANE	5TWR7036A1	5PX*B004AS3	S8V2B080M4PCB	21,200	\$2,968
216766008	TRANE	5TWR7036A1	5PX*B004AS3	S8V2B060M4PDB	21,200	\$2,968
216766020	TRANE	5TWR7036A1	5PX*B004AS3	S8V2B060M4PCB	21,200	\$2,968
216766006	TRANE	5TWR7036A1	5PX*B004AS3	S8V2A040M3PDB	21,200	\$2,968
216766026	TRANE	5TWR7036A1	5PX*B004AS3	S8V2A040M3PCB	21,200	\$2,968
216763582	TRANE	5TWR7036A1	5PX*B004AS3	N/A	21,600	\$3,024
216763570	TRANE	5TWR7036A1	5PX*B004AS3	L9X1B070U4VSA	21,600	\$3,024
216763572	TRANE	5TWR7036A1	5PX*B004AS3	L9X1A050U3VSA	21,800	\$3,052
216763574	TRANE	5TWR7036A1	5PX*B004AS3	L8V1B080U4VSB	21,200	\$2,968
216763576	TRANE	5TWR7036A1	5PX*B004AS3	L8V1A060U3VSB	20,800	\$2,912
216763578	TRANE	5TWR7036A1	5PX*B004AS3	L8V1A040U3VSB	21,400	\$2,996
216769898	TRANE	5TWR7036A1	5PX*B004AS3	*UHMB080CCV3	21,000	\$2,940
216769900	TRANE	5TWR7036A1	5PX*B004AS3	*UHMB060CCV3	21,000	\$2,940
216769894	TRANE	5TWR7024A1	5TXCC009AS3	*UHMC100CCV4	15,100	\$2,114
216769896	TRANE	5TWR7024A1	5TXCC009AS3	*DHMC100CCV4	14,800	\$2,072
216769892	TRANE	5TWR7024A1	5TXCC007AS3	*UHMC100CCV4	15,200	\$2,128

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763566	TRANE	5TWR7024A1	5TXCC007AS3	*DHMC100CCV4	14,900	\$2,086
216763564	TRANE	5TWR7024A1	5TXCC005AS3	N/A	15,800	\$2,212
216769888	TRANE	5TWR7024A1	5TXCC005AS3	*UHMC100CCV4	15,000	\$2,100
216769890	TRANE	5TWR7024A1	5TXCC005AS3	*DHMC100CCV4	15,100	\$2,114
216765964	TRANE	5TWR7024A1	5TXCB006AS3	S9X2B080D4PSB	15,100	\$2,114
216765970	TRANE	5TWR7024A1	5TXCB006AS3	S9X2B060U4PSB	15,400	\$2,156
216765966	TRANE	5TWR7024A1	5TXCB006AS3	S9X2B060D3PSB	15,000	\$2,100
216765972	TRANE	5TWR7024A1	5TXCB006AS3	S9X2B040U3PSB	15,500	\$2,170
216765968	TRANE	5TWR7024A1	5TXCB006AS3	S9X2B040D3PSB	15,100	\$2,114
216765974	TRANE	5TWR7024A1	5TXCB006AS3	S9X1B080D4PSB	15,100	\$2,114
216765998	TRANE	5TWR7024A1	5TXCB006AS3	S9X1B060U4PSB	15,400	\$2,156
216765976	TRANE	5TWR7024A1	5TXCB006AS3	S9X1B060D3PSB	15,000	\$2,100
216765984	TRANE	5TWR7024A1	5TXCB006AS3	S9X1B040U3PSB	15,500	\$2,170
216765978	TRANE	5TWR7024A1	5TXCB006AS3	S9X1B040D3PSB	15,100	\$2,114
216763550	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B080U4VSB	15,500	\$2,170
216763548	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B080U4PSC	15,500	\$2,170
216763554	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B080D4VSB	15,200	\$2,128
216763556	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B080D4PSC	15,200	\$2,128
216765986	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B060U4VSB	15,500	\$2,170
216763546	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B060U4PSC	15,500	\$2,170
216763544	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B060U3VSB	15,500	\$2,170
216763558	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B060D3VSB	14,900	\$2,086
216763560	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B060D3PSC	14,900	\$2,086
216763542	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B040U3VSB	15,500	\$2,170
216763540	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B040U3PSC	15,500	\$2,170
216765980	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B040D3VSB	15,200	\$2,128
216763562	TRANE	5TWR7024A1	5TXCB006AS3	S9V2B040D3PSC	15,200	\$2,128
216765982	TRANE	5TWR7024A1	5TXCB006AS3	S8V2B080M4PDB	15,500	\$2,170
216765988	TRANE	5TWR7024A1	5TXCB006AS3	S8V2B080M4PCB	15,500	\$2,170
216765960	TRANE	5TWR7024A1	5TXCB006AS3	S8V2B060M4PDB	15,400	\$2,156
216765990	TRANE	5TWR7024A1	5TXCB006AS3	S8V2B060M4PCB	15,400	\$2,156
216765962	TRANE	5TWR7024A1	5TXCB006AS3	S8V2A040M3PDB	15,500	\$2,170
216765992	TRANE	5TWR7024A1	5TXCB006AS3	S8V2A040M3PCB	15,500	\$2,170
216763538	TRANE	5TWR7024A1	5TXCB006AS3	L8V1B080U4VSB	15,400	\$2,156
216763536	TRANE	5TWR7024A1	5TXCB006AS3	L8V1A060U3VSB	15,500	\$2,170
216763534	TRANE	5TWR7024A1	5TXCB006AS3	L8V1A040U3VSB	15,500	\$2,170
216763530	TRANE	5TWR7024A1	5TXCB006AS3	*UHMB080CCV3	15,400	\$2,156
216763528	TRANE	5TWR7024A1	5TXCB006AS3	*UHMB060CCV3	15,400	\$2,156

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763532	TRANE	5TWR7024A1	5TXCB006AS3	*DHMB080CCV3	15,100	\$2,114
216763552	TRANE	5TWR7024A1	5TXCB006AS3	*DHMB060CCV3	15,100	\$2,114
216765930	TRANE	5TWR7024A1	5TXCB004AS3	S9X2B080D4PSB	15,000	\$2,100
216765936	TRANE	5TWR7024A1	5TXCB004AS3	S9X2B060U4PSB	15,300	\$2,142
216765932	TRANE	5TWR7024A1	5TXCB004AS3	S9X2B060D3PSB	15,100	\$2,114
216765938	TRANE	5TWR7024A1	5TXCB004AS3	S9X2B040U3PSB	15,300	\$2,142
216765934	TRANE	5TWR7024A1	5TXCB004AS3	S9X2B040D3PSB	15,000	\$2,100
216765926	TRANE	5TWR7024A1	5TXCB004AS3	S9X1B080D4PSB	15,000	\$2,100
216765944	TRANE	5TWR7024A1	5TXCB004AS3	S9X1B060U4PSB	15,300	\$2,142
216765928	TRANE	5TWR7024A1	5TXCB004AS3	S9X1B060D3PSB	15,100	\$2,114
216765954	TRANE	5TWR7024A1	5TXCB004AS3	S9X1B040U3PSB	15,300	\$2,142
216765940	TRANE	5TWR7024A1	5TXCB004AS3	S9X1B040D3PSB	15,000	\$2,100
216763484	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B080U4VSB	15,300	\$2,142
216763482	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B080U4PSC	15,300	\$2,142
216763514	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B080D4VSB	15,000	\$2,100
216763516	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B080D4PSC	15,000	\$2,100
216765950	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B060U4VSB	15,300	\$2,142
216763480	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B060U4PSC	15,300	\$2,142
216763488	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B060U3VSB	15,300	\$2,142
216763518	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B060D3VSB	15,100	\$2,114
216763520	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B060D3PSC	15,200	\$2,128
216763490	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B040U3VSB	15,300	\$2,142
216763492	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B040U3PSC	15,400	\$2,156
216765942	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B040D3VSB	15,100	\$2,114
216763522	TRANE	5TWR7024A1	5TXCB004AS3	S9V2B040D3PSC	15,100	\$2,114
216764569	TRANE	5TWR7024A1	5TXCB004AS3	S8X2B080M4PTC	15,100	\$2,114
216764567	TRANE	5TWR7024A1	5TXCB004AS3	S8X2B080M4PSC	15,100	\$2,114
216764577	TRANE	5TWR7024A1	5TXCB004AS3	S8X2B060M4PTC	15,200	\$2,128
216764573	TRANE	5TWR7024A1	5TXCB004AS3	S8X2B060M4PSC	15,200	\$2,128
216764571	TRANE	5TWR7024A1	5TXCB004AS3	S8X2A040M3PTC	15,300	\$2,142
216764575	TRANE	5TWR7024A1	5TXCB004AS3	S8X2A040M3PSC	15,300	\$2,142
216764559	TRANE	5TWR7024A1	5TXCB004AS3	S8X1B080M4PTC	15,100	\$2,114
216763494	TRANE	5TWR7024A1	5TXCB004AS3	S8X1B080M4PSC	15,100	\$2,114
216764561	TRANE	5TWR7024A1	5TXCB004AS3	S8X1B060M4PTC	15,200	\$2,128
216763496	TRANE	5TWR7024A1	5TXCB004AS3	S8X1B060M4PSC	15,200	\$2,128
216764563	TRANE	5TWR7024A1	5TXCB004AS3	S8X1B040M2PTC	15,200	\$2,128
216763498	TRANE	5TWR7024A1	5TXCB004AS3	S8X1B040M2PSC	15,200	\$2,128
216764565	TRANE	5TWR7024A1	5TXCB004AS3	S8X1A040M3PTC	15,300	\$2,142

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763500	TRANE	5TWR7024A1	5TXCB004AS3	S8X1A040M3PSC	15,300	\$2,142
216765952	TRANE	5TWR7024A1	5TXCB004AS3	S8V2B080M4PDB	15,300	\$2,142
216765948	TRANE	5TWR7024A1	5TXCB004AS3	S8V2B080M4PCB	15,300	\$2,142
216765920	TRANE	5TWR7024A1	5TXCB004AS3	S8V2B060M4PDB	15,400	\$2,156
216765946	TRANE	5TWR7024A1	5TXCB004AS3	S8V2B060M4PCB	15,400	\$2,156
216765922	TRANE	5TWR7024A1	5TXCB004AS3	S8V2A040M3PDB	15,400	\$2,156
216765956	TRANE	5TWR7024A1	5TXCB004AS3	S8V2A040M3PCB	15,400	\$2,156
216763502	TRANE	5TWR7024A1	5TXCB004AS3	L9X1B070U4VSA	15,200	\$2,128
216763504	TRANE	5TWR7024A1	5TXCB004AS3	L9X1A050U3VSA	15,700	\$2,198
216763506	TRANE	5TWR7024A1	5TXCB004AS3	L8V1B080U4VSB	15,400	\$2,156
216763508	TRANE	5TWR7024A1	5TXCB004AS3	L8V1A060U3VSB	15,400	\$2,156
216763512	TRANE	5TWR7024A1	5TXCB004AS3	L8V1A040U3VSB	15,400	\$2,156
216763510	TRANE	5TWR7024A1	5TXCB004AS3	*UHMB080CCV3	15,300	\$2,142
216763526	TRANE	5TWR7024A1	5TXCB004AS3	*UHMB060CCV3	15,300	\$2,142
216763524	TRANE	5TWR7024A1	5TXCB004AS3	*DHMB080CCV3	15,100	\$2,114
216763486	TRANE	5TWR7024A1	5TXCB004AS3	*DHMB060CCV3	15,200	\$2,128
216763478	TRANE	5TWR7024A1	5TEMCD05AV41+TD	N/A	15,200	\$2,128
216763476	TRANE	5TWR7024A1	5TEMCD04AV31+TD	N/A	15,200	\$2,128
216763474	TRANE	5TWR7024A1	5TEMCB03AV31+TD	N/A	15,500	\$2,170
216763472	TRANE	5TWR7024A1	5TEMCB02AV21+TD	N/A	15,600	\$2,184
216763470	TRANE	5TWR7024A1	5TEM6D05AV41+TD	N/A	15,400	\$2,156
216763468	TRANE	5TWR7024A1	5TEM6D04AV31+TD	N/A	15,400	\$2,156
216763466	TRANE	5TWR7024A1	5TEM6B03AV21+TD	N/A	15,600	\$2,184
216763464	TRANE	5TWR7024A1	5TEM6B02AV21+TD	N/A	15,600	\$2,184
216763462	TRANE	5TWR7024A1	5TAMXD05AV41	N/A	15,200	\$2,128
216763460	TRANE	5TWR7024A1	5TAMXD04AV31	N/A	15,300	\$2,142
216763458	TRANE	5TWR7024A1	5TAMXC03AV31	N/A	15,300	\$2,142
216769886	TRANE	5TWR7024A1	5TAM5C04AC31	N/A	15,200	\$2,128
216763456	TRANE	5TWR7024A1	5TAM5C03AC21	N/A	15,100	\$2,114
216769884	TRANE	5TWR7024A1	5PX*CD09AS3	*DHMC100CCV4	15,100	\$2,114
216769882	TRANE	5TWR7024A1	5PX*CD07AS3	*DHMC100CCV4	15,300	\$2,142
216763454	TRANE	5TWR7024A1	5PX*CD05AS3	N/A	15,800	\$2,212
216769880	TRANE	5TWR7024A1	5PX*C009AS3	*UHMC100CCV4	15,100	\$2,114
216763452	TRANE	5TWR7024A1	5PX*C009AS3	*DHMC100CCV4	14,800	\$2,072
216769878	TRANE	5TWR7024A1	5PX*C007AS3	*UHMC100CCV4	15,200	\$2,128
216763450	TRANE	5TWR7024A1	5PX*C007AS3	*DHMC100CCV4	15,200	\$2,128
216763446	TRANE	5TWR7024A1	5PX*C005AS3	N/A	15,800	\$2,212
216769876	TRANE	5TWR7024A1	5PX*C005AS3	*UHMC100CCV4	15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763448	TRANE	5TWR7024A1	5PX*CO05AS3	*DHMC100CCV4	15,100	\$2,114
216765900	TRANE	5TWR7024A1	5PX*BD06AS3	S9X2B080D4PSB	15,400	\$2,156
216765892	TRANE	5TWR7024A1	5PX*BD06AS3	S9X2B060D3PSB	15,500	\$2,170
216765890	TRANE	5TWR7024A1	5PX*BD06AS3	S9X2B040D3PSB	15,400	\$2,156
216765896	TRANE	5TWR7024A1	5PX*BD06AS3	S9X1B080D4PSB	15,400	\$2,156
216765898	TRANE	5TWR7024A1	5PX*BD06AS3	S9X1B060D3PSB	15,500	\$2,170
216765914	TRANE	5TWR7024A1	5PX*BD06AS3	S9X1B040D3PSB	15,400	\$2,156
216763440	TRANE	5TWR7024A1	5PX*BD06AS3	S9V2B080D4VSB	15,500	\$2,170
216763444	TRANE	5TWR7024A1	5PX*BD06AS3	S9V2B080D4PSC	15,500	\$2,170
216763432	TRANE	5TWR7024A1	5PX*BD06AS3	S9V2B060D3VSB	15,500	\$2,170
216763438	TRANE	5TWR7024A1	5PX*BD06AS3	S9V2B060D3PSC	15,500	\$2,170
216765902	TRANE	5TWR7024A1	5PX*BD06AS3	S9V2B040D3VSB	15,500	\$2,170
216763436	TRANE	5TWR7024A1	5PX*BD06AS3	S9V2B040D3PSC	15,400	\$2,156
216765888	TRANE	5TWR7024A1	5PX*BD06AS3	S8V2B080M4PDB	15,500	\$2,170
216765904	TRANE	5TWR7024A1	5PX*BD06AS3	S8V2B080M4PCB	15,500	\$2,170
216765886	TRANE	5TWR7024A1	5PX*BD06AS3	S8V2B060M4PDB	15,500	\$2,170
216765906	TRANE	5TWR7024A1	5PX*BD06AS3	S8V2B060M4PCB	15,500	\$2,170
216765894	TRANE	5TWR7024A1	5PX*BD06AS3	S8V2A040M3PDB	15,600	\$2,184
216765908	TRANE	5TWR7024A1	5PX*BD06AS3	S8V2A040M3PCB	15,600	\$2,184
216763434	TRANE	5TWR7024A1	5PX*BD06AS3	*DHMB080CCV3	15,500	\$2,170
216763442	TRANE	5TWR7024A1	5PX*BD06AS3	*DHMB060CCV3	15,600	\$2,184
216765870	TRANE	5TWR7024A1	5PX*BD04AS3	S9X2B060D3PSB	15,400	\$2,156
216765872	TRANE	5TWR7024A1	5PX*BD04AS3	S9X1B060D3PSB	15,400	\$2,156
216763422	TRANE	5TWR7024A1	5PX*BD04AS3	S9V2B080D4VSB	15,300	\$2,142
216763424	TRANE	5TWR7024A1	5PX*BD04AS3	S9V2B080D4PSC	15,300	\$2,142
216765884	TRANE	5TWR7024A1	5PX*BD04AS3	S9V2B040D3VSB	15,400	\$2,156
216763426	TRANE	5TWR7024A1	5PX*BD04AS3	S9V2B040D3PSC	15,400	\$2,156
216765878	TRANE	5TWR7024A1	5PX*BD04AS3	S8V2B080M4PDB	15,300	\$2,142
216765876	TRANE	5TWR7024A1	5PX*BD04AS3	S8V2B080M4PCB	15,300	\$2,142
216765880	TRANE	5TWR7024A1	5PX*BD04AS3	S8V2B060M4PDB	15,400	\$2,156
216765874	TRANE	5TWR7024A1	5PX*BD04AS3	S8V2B060M4PCB	15,400	\$2,156
216765882	TRANE	5TWR7024A1	5PX*BD04AS3	S8V2A040M3PDB	15,400	\$2,156
216765866	TRANE	5TWR7024A1	5PX*BD04AS3	S8V2A040M3PCB	15,400	\$2,156
216763430	TRANE	5TWR7024A1	5PX*BD04AS3	N/A	15,800	\$2,212
216763428	TRANE	5TWR7024A1	5PX*BD04AS3	*DHMB060CCV3	15,400	\$2,156
216765846	TRANE	5TWR7024A1	5PX*B006AS3	S9X2B080D4PSB	15,100	\$2,114
216765840	TRANE	5TWR7024A1	5PX*B006AS3	S9X2B060U4PSB	15,400	\$2,156
216765844	TRANE	5TWR7024A1	5PX*B006AS3	S9X2B060D3PSB	15,200	\$2,128

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216765838	TRANE	5TWR7024A1	5PX*B006AS3	S9X2B040U3PSB	15,500	\$2,170
216765842	TRANE	5TWR7024A1	5PX*B006AS3	S9X2B040D3PSB	15,100	\$2,114
216765830	TRANE	5TWR7024A1	5PX*B006AS3	S9X1B080D4PSB	15,100	\$2,114
216765862	TRANE	5TWR7024A1	5PX*B006AS3	S9X1B060U4PSB	15,400	\$2,156
216765828	TRANE	5TWR7024A1	5PX*B006AS3	S9X1B060D3PSB	15,200	\$2,128
216765860	TRANE	5TWR7024A1	5PX*B006AS3	S9X1B040U3PSB	15,500	\$2,170
216765826	TRANE	5TWR7024A1	5PX*B006AS3	S9X1B040D3PSB	15,100	\$2,114
216763398	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B080U4VSB	15,500	\$2,170
216763396	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B080U4PSC	15,500	\$2,170
216763416	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B080D4VSB	15,200	\$2,128
216763418	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B080D4PSC	15,200	\$2,128
216765858	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B060U4VSB	15,500	\$2,170
216763394	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B060U4PSC	15,500	\$2,170
216763392	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B060U3VSB	15,500	\$2,170
216763388	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B060D3VSB	15,300	\$2,142
216763420	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B060D3PSC	15,300	\$2,142
216763390	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B040U3VSB	15,500	\$2,170
216763412	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B040U3PSC	15,500	\$2,170
216765864	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B040D3VSB	15,200	\$2,128
216763386	TRANE	5TWR7024A1	5PX*B006AS3	S9V2B040D3PSC	15,200	\$2,128
216765836	TRANE	5TWR7024A1	5PX*B006AS3	S8V2B080M4PDB	15,500	\$2,170
216765856	TRANE	5TWR7024A1	5PX*B006AS3	S8V2B080M4PCB	15,500	\$2,170
216765834	TRANE	5TWR7024A1	5PX*B006AS3	S8V2B060M4PDB	15,500	\$2,170
216765854	TRANE	5TWR7024A1	5PX*B006AS3	S8V2B060M4PCB	15,500	\$2,170
216765832	TRANE	5TWR7024A1	5PX*B006AS3	S8V2A040M3PDB	15,600	\$2,184
216765852	TRANE	5TWR7024A1	5PX*B006AS3	S8V2A040M3PCB	15,600	\$2,184
216763410	TRANE	5TWR7024A1	5PX*B006AS3	L8V1B080U4VSB	15,400	\$2,156
216763408	TRANE	5TWR7024A1	5PX*B006AS3	L8V1A060U3VSB	15,500	\$2,170
216763414	TRANE	5TWR7024A1	5PX*B006AS3	L8V1A040U3VSB	15,500	\$2,170
216763406	TRANE	5TWR7024A1	5PX*B006AS3	*UHMB080CCV3	15,400	\$2,156
216763404	TRANE	5TWR7024A1	5PX*B006AS3	*UHMB060CCV3	15,400	\$2,156
216763402	TRANE	5TWR7024A1	5PX*B006AS3	*DHMB080CCV3	15,300	\$2,142
216763400	TRANE	5TWR7024A1	5PX*B006AS3	*DHMB060CCV3	15,200	\$2,128
216765814	TRANE	5TWR7024A1	5PX*B004AS3	S9X2B080D4PSB	15,000	\$2,100
216765808	TRANE	5TWR7024A1	5PX*B004AS3	S9X2B060U4PSB	15,300	\$2,142
216765812	TRANE	5TWR7024A1	5PX*B004AS3	S9X2B060D3PSB	15,100	\$2,114
216765806	TRANE	5TWR7024A1	5PX*B004AS3	S9X2B040U3PSB	15,300	\$2,142
216765810	TRANE	5TWR7024A1	5PX*B004AS3	S9X2B040D3PSB	15,000	\$2,100

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216765788	TRANE	5TWR7024A1	5PX*B004AS3	S9X1B080D4PSB	15,000	\$2,100
216765816	TRANE	5TWR7024A1	5PX*B004AS3	S9X1B060U4PSB	15,300	\$2,142
216765822	TRANE	5TWR7024A1	5PX*B004AS3	S9X1B060D3PSB	15,100	\$2,114
216765786	TRANE	5TWR7024A1	5PX*B004AS3	S9X1B040U3PSB	15,300	\$2,142
216765820	TRANE	5TWR7024A1	5PX*B004AS3	S9X1B040D3PSB	15,000	\$2,100
216763364	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B080U4VSB	15,300	\$2,142
216763362	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B080U4PSC	15,300	\$2,142
216763380	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B080D4VSB	15,000	\$2,100
216763376	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B080D4PSC	15,000	\$2,100
216765824	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B060U4VSB	15,400	\$2,156
216763360	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B060U4PSC	15,300	\$2,142
216763358	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B060U3VSB	15,300	\$2,142
216763374	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B060D3VSB	15,100	\$2,114
216763372	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B060D3PSC	15,100	\$2,114
216763356	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B040U3VSB	15,300	\$2,142
216763354	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B040U3PSC	15,400	\$2,156
216765818	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B040D3VSB	15,000	\$2,100
216763370	TRANE	5TWR7024A1	5PX*B004AS3	S9V2B040D3PSC	15,000	\$2,100
216764541	TRANE	5TWR7024A1	5PX*B004AS3	S8X2B080M4PTC	15,100	\$2,114
216764539	TRANE	5TWR7024A1	5PX*B004AS3	S8X2B080M4PSC	15,100	\$2,114
216764543	TRANE	5TWR7024A1	5PX*B004AS3	S8X2B060M4PTC	15,200	\$2,128
216764555	TRANE	5TWR7024A1	5PX*B004AS3	S8X2B060M4PSC	15,200	\$2,128
216764545	TRANE	5TWR7024A1	5PX*B004AS3	S8X2A040M3PTC	15,300	\$2,142
216764547	TRANE	5TWR7024A1	5PX*B004AS3	S8X2A040M3PSC	15,300	\$2,142
216764557	TRANE	5TWR7024A1	5PX*B004AS3	S8X1B080M4PTC	15,100	\$2,114
216763352	TRANE	5TWR7024A1	5PX*B004AS3	S8X1B080M4PSC	15,100	\$2,114
216764549	TRANE	5TWR7024A1	5PX*B004AS3	S8X1B060M4PTC	15,200	\$2,128
216763350	TRANE	5TWR7024A1	5PX*B004AS3	S8X1B060M4PSC	15,200	\$2,128
216764551	TRANE	5TWR7024A1	5PX*B004AS3	S8X1B040M2PTC	15,200	\$2,128
216763348	TRANE	5TWR7024A1	5PX*B004AS3	S8X1B040M2PSC	15,200	\$2,128
216764553	TRANE	5TWR7024A1	5PX*B004AS3	S8X1A040M3PTC	15,300	\$2,142
216763346	TRANE	5TWR7024A1	5PX*B004AS3	S8X1A040M3PSC	15,300	\$2,142
216765802	TRANE	5TWR7024A1	5PX*B004AS3	S8V2B080M4PDB	15,300	\$2,142
216765792	TRANE	5TWR7024A1	5PX*B004AS3	S8V2B080M4PCB	15,300	\$2,142
216765800	TRANE	5TWR7024A1	5PX*B004AS3	S8V2B060M4PDB	15,400	\$2,156
216765790	TRANE	5TWR7024A1	5PX*B004AS3	S8V2B060M4PCB	15,400	\$2,156
216765804	TRANE	5TWR7024A1	5PX*B004AS3	S8V2A040M3PDB	15,400	\$2,156
216765796	TRANE	5TWR7024A1	5PX*B004AS3	S8V2A040M3PCB	15,400	\$2,156

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216763382	TRANE	5TWR7024A1	5PX*B004AS3	N/A	15,800	\$2,212
216763344	TRANE	5TWR7024A1	5PX*B004AS3	L9X1B070U4VSA	15,200	\$2,128
216763342	TRANE	5TWR7024A1	5PX*B004AS3	L9X1A050U3VSA	15,700	\$2,198
216763340	TRANE	5TWR7024A1	5PX*B004AS3	L8V1B080U4VSB	15,500	\$2,170
216763338	TRANE	5TWR7024A1	5PX*B004AS3	L8V1A060U3VSB	15,400	\$2,156
216763336	TRANE	5TWR7024A1	5PX*B004AS3	L8V1A040U3VSB	15,400	\$2,156
216763384	TRANE	5TWR7024A1	5PX*B004AS3	*UHMB080CCV3	15,300	\$2,142
216763378	TRANE	5TWR7024A1	5PX*B004AS3	*UHMB060CCV3	15,300	\$2,142
216763368	TRANE	5TWR7024A1	5PX*B004AS3	*DHMB080CCV3	15,100	\$2,114
216763366	TRANE	5TWR7024A1	5PX*B004AS3	*DHMB060CCV3	15,200	\$2,128
216772256	TRANE	5HCL5036A1	5TEM5B04AC31		31,200	\$4,368
9150127	TRANE	4TXK3824A10NU**	4MXW3824A10NU**		20,000	\$2,800
9150125	TRANE	4TXK3818A10NU**	4MXW3818A10NU**		15,100	\$2,114
9150123	TRANE	4TXK3812A10NU**	4MXW3812A10NU**		10,300	\$1,442
214056971	TRANE	4TXD2036A10NU**	D(A,C,E)36B34+TDR		15,000	\$2,100
214056970	TRANE	4TXD2036A10NU**	D(A,C,E)24A44+TDR		14,900	\$2,086
202703126	TRANE	4TXK2324A10N0**	4MXW2324A10N0**	N/A	14,600	\$2,044
207526597	TRANE	4TWV0X48A1	4TXCC009DS3	P0V0C000M50SA+RP	35,600	\$4,984
204780384	TRANE	4TWV0048A1	4TXCC009DS3	P0V0C000M50SA+RP	35,600	\$4,984
204780482	TRANE	4TWV8049A1	4TXCC009DS3	P0V0C000M50SA+RP	35,600	\$4,984
204780447	TRANE	4TWV8048A1	4TXCD010DS3	P0V0C000M50SA+RP	35,200	\$4,928
207526644	TRANE	4TWV8X48A1	4TXCD010DS3	P0V0C000M50SA+RP	35,200	\$4,928
212361353	TRANE	4TXD2036A10NU**	4RXC024AS3HC**		16,800	\$2,352
10153709	TRANE	4TWV0060A1	TEM8A0D48V41+TDR		49,500	\$6,930
204340536	TRANE	4TXM2324A13NU**	Heat pump without ducts	N/A	17,900	\$2,506
204340534	TRANE	4TXM2318A12NU**	Heat pump without ducts	N/A	17,000	\$2,380
10153740	TRANE	4TWV8060A1	TEM8A0D48V41+TDR		49,500	\$6,930
210435408	TRANE	4TXM2136A14N0**	Heat pump without ducts		30,800	\$4,312
210435409	TRANE	4TXM2142A15N0**	Heat pump without ducts		35,600	\$4,984
208141271	TRANE	4TXD2060A10NU**	4MXA2048A10NU**	N/A	32,000	\$4,480
208141270	TRANE	4TXD2036A10NU**	4MXA2036A10NU**	N/A	24,000	\$3,360
208141272	TRANE	4TXD2060A10NU**	4MXA2060A10NU**	N/A	36,000	\$5,040
208141269	TRANE	4TXD2036A10NU**	4MXA2024A10NU**	N/A	16,300	\$2,282
216607269	TURBOFIN	HP36R	THAH-AIRHANDLER36		24,000	\$3,360
214606645	TURBOFIN	HP36R410A	THAH-AIRHANDLER36		24,000	\$3,360
208978291	TURBOFIN	THTU-HEATPUMP24	THAH-AIRHANDLER36		24,000	\$3,360
215569824	VISSMANN	DLCMBH36DAK	Heat pump without ducts		35,000	\$4,900

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215569883	VISSMANN	DLCMHBH36DAK	Combination heat pumps with or without ducts		35,000	\$4,900
215569823	VISSMANN	DLCMHBH48EAK	Heat pump with ducts		36,000	\$5,040
215569835	VISSMANN	DLCPRBH18AAK	DLFPHBH18XAK		20,200	\$2,828
215569787	VISSMANN	DLCSRBH12AAK	DLFSCAH12XAK		9,900	\$1,386
215569788	VISSMANN	DLCSRBH12AAK	DLFSDAH12XAK		10,600	\$1,484
215569789	VISSMANN	DLCSRBH12AAK	DLFSFAH12XAK		9,600	\$1,344
215569798	VISSMANN	DLCSRBH12AAK	DLFSHBH12XAK		10,300	\$1,442
215569839	VISSMANN	DLCSRBH12AAK	DLFSHCH12XAK		10,000	\$1,400
215569857	VISSMANN	DLCSRBH12AAK	DLFSFBH12XAK		10,200	\$1,428
215569861	VISSMANN	DLCSRBH12AAK	DLFSOAH18XAK		9,500	\$1,330
215569864	VISSMANN	DLCSRBH12AAK	DLFSDAH12XHK		9,700	\$1,358
215569791	VISSMANN	DLCSRBH18AAK	DLFSDAH18XAK		15,000	\$2,100
215569792	VISSMANN	DLCSRBH18AAK	DLFSFAH18XAK		12,000	\$1,680
215569799	VISSMANN	DLCSRBH18AAK	DLFSHBH18XAK		11,100	\$1,554
215569844	VISSMANN	DLCSRBH18AAK	DLFSHCH18XAK		15,000	\$2,100
215569856	VISSMANN	DLCSRBH18AAK	DLFCCA18XAK		14,500	\$2,030
215569860	VISSMANN	DLCSRBH18AAK	DLFSOAH18XAK		14,500	\$2,030
215569862	VISSMANN	DLCSRBH18AAK	DLFSDAH18XHK		15,700	\$2,198
215569794	VISSMANN	DLCSRBH24AAK	DLFSDAH24XAK		21,000	\$2,940
215569795	VISSMANN	DLCSRBH24AAK	DLFSFAH24XAK		19,000	\$2,660
215569800	VISSMANN	DLCSRBH24AAK	DLFSHBH24XAK		18,900	\$2,646
215569840	VISSMANN	DLCSRBH24AAK	DLFSHCH24XAK		21,200	\$2,968
215569868	VISSMANN	DLCSRBH24AAK	DLFSDAH24XHK		21,000	\$2,940
215569772	VISSMANN	DLCSRBH18AAK	DLFSABH18XBK		15,400	\$2,156
215569773	VISSMANN	DLCSRBH24AAK	DLFSABH24XBK		16,900	\$2,366
215569754	VISSMANN	DLCURAH18ABK	DLFUAH18XAK		13,500	\$1,890
215569755	VISSMANN	DLCURAH24ABK	DLFUAH24XAK		19,200	\$2,688
215569766	VISSMANN	DLCURAH24ABK	DLFULAH24XBX + CI		21,000	\$2,940
215569762	VISSMANN	DLCURAH30ABK	DLFUAH30XAK		21,000	\$2,940
215569767	VISSMANN	DLCURAH30ABK	DLFULAH36XCX + CI		22,600	\$3,164
215569761	VISSMANN	DLCURAH36ABK	DLFUAH36XAK		30,400	\$4,256
215569768	VISSMANN	DLCURAH36ABK	DLFULAH36XBX + CI		27,400	\$3,836
215569769	VISSMANN	DLCURAH36ABK	DLFULAH36XCX + CI		33,000	\$4,620
215569757	VISSMANN	DLCURAH48ABK	DLFUAH48XAK		36,000	\$5,040
215569763	VISSMANN	DLCURAH60ABK	DLFUAH60XAK		42,000	\$5,880
210627719	WABBAN	BB18HXP2A1DO	BB18HXP2A1DI		11,000	\$1,540
210627717	WABBAN	BB12HXP2A1DO	BB12HXP2A1DI		7,000	\$980

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207196961	WABBAN	BB36-24WADU	BBD24-24AH2ADU		16,000	\$2,240
207196958	WABBAN	BB36-24WADU	BBD36-24AH2ADU		24,000	\$3,360
211174354	WABBAN	BBM36HX4O	Heat pump without ducts		30,800	\$4,312
211174355	WABBAN	BBM42HX4O	Heat pump without ducts		35,600	\$4,984
207196959	WABBAN	BB60-48WADU	BBD48-24AH2ADU		36,000	\$5,040
207196960	WABBAN	BB60-48WADU	BBD60-24AH2ADU		31,400	\$4,396
212521243	WABBAN	BB36-24WADU	TCAT24F/NaA		15,000	\$2,100
213319280	WABBAN	BB24HXP2A1DO	BBM24HSFDI		14,900	\$2,086
201903175	WABBAN	BB24HQ3D6DO	BB24HQ3D6DI		15,500	\$2,170
201903174	WABBAN	BB18HQ3D6DO	BB18HQ3D6DI		14,200	\$1,988
201903168	WABBAN	BB24HQ2A3DO	BB24HQ2A3DI		14,600	\$2,044
201903167	WABBAN	BB18HQ2A3DO	BB18HQ2A3DI		12,400	\$1,736
207683313	Weathermaker	38MARBQ24AA3	40MBCAQ24XA3		21,000	\$2,940
207614956	Weathermaker	38MPRBQ12AA3	DHMPHBQ12XA3		10,400	\$1,456
207826655	Weathermaker	38MPRBQ18AA3	DHMPHBQ18XA3		20,200	\$2,828
208447912	WEATHERMAKER	38MURAQ18AB3	40MUAAQ18XA3		13,500	\$1,890
208447914	WEATHERMAKER	38MURAQ24AB3	40MUAAQ24XA3		19,200	\$2,688
208447910	WEATHERMAKER	38MURAQ36AB3	40MUAAQ36XA3		30,400	\$4,256
215323778	WEATHERMAKER	37MAHAQ18AA3	D5MAHAQ18XA3		16,600	\$2,324
215357747	WEATHERMAKER	37MGHAQ30EA3	Combination heat pumps with or without ducts		31,400	\$4,396
215357746	WEATHERMAKER	37MGHAQ30EA3	Heat pump with ducts		33,000	\$4,620
215357745	WEATHERMAKER	37MGHAQ30EA3	Heat pump without ducts		30,000	\$4,200
215357773	WEATHERMAKER	37MGRAQ48FA3	Heat pump with ducts		37,000	\$5,180
215357756	WEATHERMAKER	37MGHAQ55FA3	Combination heat pumps with or without ducts		44,500	\$6,230
215357755	WEATHERMAKER	37MGHAQ55FA3	Heat pump with ducts		45,000	\$6,300
215357754	WEATHERMAKER	37MGHAQ55FA3	Heat pump without ducts		44,000	\$6,160
215357753	WEATHERMAKER	37MGHAQ48FA3	Combination heat pumps with or without ducts		44,000	\$6,160
215357752	WEATHERMAKER	37MGHAQ48FA3	Heat pump with ducts		44,500	\$6,230
215357751	WEATHERMAKER	37MGHAQ48FA3	Heat pump without ducts		44,000	\$6,160
215323779	WEATHERMAKER	37MAHAQ24AA3	D5MAHAQ24XA3		21,000	\$2,940
215323996	WEATHERMAKER	37MAHAQ18AA3	45MBDAQ18XA3		15,000	\$2,100
215323994	WEATHERMAKER	37MAHAQ18AA3	45MBFAQ16XA3		14,200	\$1,988
215323993	WEATHERMAKER	37MAHAQ18AA3	45MBCAQ18XA3		14,900	\$2,086
215323992	WEATHERMAKER	37MAHAQ18AA3	45MCCAQ18XA3		14,500	\$2,030
215323990	WEATHERMAKER	37MAHAQ12AA3	45MBDAQ12XA3		9,600	\$1,344

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215323989	WEATHERMAKER	37MAHAQ12AA3	45MBFAQ12XA3		9,800	\$1,372
215323988	WEATHERMAKER	37MAHAQ12AA3	45MBCAQ12XA3		10,000	\$1,400
215323987	WEATHERMAKER	37MAHAQ12AA3	45MCCAQ12XA3		9,600	\$1,344
215323777	WEATHERMAKER	37MAHAQ12AA3	D5MAHAQ12XA3		9,800	\$1,372
215323723	WEATHERMAKER	37MUHAQ36AA3	45MUHAQ36XX3		31,000	\$4,340
215323999	WEATHERMAKER	37MAHAQ24AA3	45MCFAQ24XA3		20,200	\$2,828
215323998	WEATHERMAKER	37MAHAQ24AA3	45MBCAQ24XA3		20,400	\$2,856
215323995	WEATHERMAKER	37MAHAQ18AA3	45MCFAQ18XA3		14,400	\$2,016
215324032	WEATHERMAKER	37MBHAQ58AA3	45MBDAQ58XH3		45,000	\$6,300
215324030	WEATHERMAKER	37MBHAQ48AA3	45MBDAQ48XH3		45,000	\$6,300
215324027	WEATHERMAKER	37MBHAQ36AA3	45MBDAQ36XH3		31,600	\$4,424
215323780	WEATHERMAKER	37MAHAQ33AA3	D5MAHAQ33XA3		30,000	\$4,200
215324000	WEATHERMAKER	37MAHAQ24AA3	45MBDAQ24XH3		21,600	\$3,024
215413162	WEATHERMAKER	37MPRAQ18AA3	D5MPHAQ18XA3		19,300	\$2,702
215413161	WEATHERMAKER	37MPRAQ12AA3	D5MPHAQ12XA3		11,000	\$1,540
215357750	WEATHERMAKER	37MGHAQ36EA3	Combination heat pumps with or without ducts		31,400	\$4,396
215357749	WEATHERMAKER	37MGHAQ36EA3	Heat pump with ducts		33,000	\$4,620
215357748	WEATHERMAKER	37MGHAQ36EA3	Heat pump without ducts		30,000	\$4,200
215357744	WEATHERMAKER	37MGHAQ27DA3	Combination heat pumps with or without ducts		24,000	\$3,360
215357743	WEATHERMAKER	37MGHAQ27DA3	Heat pump with ducts		23,000	\$3,220
215357742	WEATHERMAKER	37MGHAQ27DA3	Heat pump without ducts		25,000	\$3,500
215357738	WEATHERMAKER	37MGHAQ18CA3	Combination heat pumps with or without ducts		17,300	\$2,422
215357737	WEATHERMAKER	37MGHAQ18CA3	Heat pump with ducts		17,000	\$2,380
215357736	WEATHERMAKER	37MGHAQ18CA3	Heat pump without ducts		17,600	\$2,464
215323997	WEATHERMAKER	37MAHAQ18AA3	45MBDAQ18XH3		15,000	\$2,100
215323991	WEATHERMAKER	37MAHAQ12AA3	45MBDAQ12XH3		10,200	\$1,428
215324031	WEATHERMAKER	37MBHAQ58AA3	45MCFAQ58XA3		41,000	\$5,740
215324029	WEATHERMAKER	37MBHAQ48AA3	45MCFAQ48XA3		38,500	\$5,390
215324028	WEATHERMAKER	37MBHAQ48AA3	45MBCAQ48XA3		44,000	\$6,160
215324026	WEATHERMAKER	37MBHAQ36AA3	45MCFAQ36XA3		30,200	\$4,228
215324025	WEATHERMAKER	37MBHAQ36AA3	45MBCAQ36XA3		30,600	\$4,284
215318855	WEATHERMAKER	37MBHAQ58AA3	45MBAAQ60XA3		41,000	\$5,740
215318847	WEATHERMAKER	37MUHAQ48AA3	45MUHAQ60XX3		34,000	\$4,760
215318846	WEATHERMAKER	37MUHAQ30AA3	45MUHAQ36XX3		24,000	\$3,360
215318845	WEATHERMAKER	37MUHAQ18AA3	45MUHAQ24XX3		14,700	\$2,058

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215318853	WEATHERMAKER	37MBHAQ36AA3	45MBAAQ36XA3		28,000	\$3,920
215318843	WEATHERMAKER	37MURAQ48AA3	45MUAQ48XX3		32,400	\$4,536
215318840	WEATHERMAKER	37MURAQ24AA3	45MUAQ24XX3		20,000	\$2,800
215318838	WEATHERMAKER	37MUHAQ60AA3	45MUHAQ60XX3		35,000	\$4,900
215318837	WEATHERMAKER	37MUHAQ60AA3	45MUAQ60XX3		45,000	\$6,300
215318836	WEATHERMAKER	37MUHAQ48AA3	45MUAQ48XX3		37,000	\$5,180
215318835	WEATHERMAKER	37MUHAQ36AA3	45MUAQ36XX3		31,800	\$4,452
215318834	WEATHERMAKER	37MUHAQ30AA3	45MUAQ30XX3		23,800	\$3,332
215318833	WEATHERMAKER	37MUHAQ24AA3	45MUHAQ24XX3		19,000	\$2,660
215318832	WEATHERMAKER	37MUHAQ24AA3	45MUAQ24XX3		20,000	\$2,800
215318831	WEATHERMAKER	37MUHAQ18AA3	45MUAQ18XX3		15,000	\$2,100
215318854	WEATHERMAKER	37MBHAQ48AA3	45MBAAQ48XA3		40,000	\$5,600
215318850	WEATHERMAKER	37MAHAQ33AA3	45MBAAQ36XB3		27,400	\$3,836
215318849	WEATHERMAKER	37MAHAQ24AA3	45MBAAQ24XB3		16,900	\$2,366
215318848	WEATHERMAKER	37MAHAQ18AA3	45MBAAQ18XB3		14,000	\$1,960
208447913	WEATHERMAKER	38MURAQ18AB3	40MUAQ18XA3		13,500	\$1,890
207801581	WEATHERMAKER	38MARBQ18AA3	40MBDQ24---3		12,600	\$1,764
213372235	WEATHERMAKER	38MURAQ60AB3	40MULAQ60DX + CI		37,000	\$5,180
213372231	WEATHERMAKER	38MURAQ30AB3	40MULAQ36XCX + CI		22,600	\$3,164
205921382	WEATHERMAKER	38MAQB24R--3	40MBAAQ24XA3		17,500	\$2,450
206350364	WEATHERMAKER	38MARBQ12AA3	40MBFQ12--3		8,400	\$1,176
206350362	WEATHERMAKER	38MARBQ12AA3	40MBCQ12--3		7,900	\$1,106
206396059	WEATHERMAKER	38MAQB12R--3	DHMAHBQ12XA3		7,500	\$1,050
206350363	WEATHERMAKER	38MARBQ12AA3	40MBDQ12--3		8,300	\$1,162
206350369	WEATHERMAKER	38MARBQ24AA3	40MBDQ24--3		14,500	\$2,030
206350367	WEATHERMAKER	38MARBQ18AA3	40MBFQ18--3		12,000	\$1,680
206350370	WEATHERMAKER	38MARBQ24AA3	40MBFQ24--3		14,500	\$2,030
206350368	WEATHERMAKER	38MARBQ24AA3	40MBCQ24--3		14,500	\$2,030
206350326	WEATHERMAKER	38MARBQ24AA3	DHMAHBQ24XA3		19,800	\$2,772
206350325	WEATHERMAKER	38MARBQ18AA3	DHMAHBQ18XA3		10,800	\$1,512
206350324	WEATHERMAKER	38MARBQ12AA3	DHMAHBQ12XA3		7,500	\$1,050
206188274	WEATHERMAKER	38MARBQ24AA3	40MBAAQ24XA3		16,500	\$2,310
206350366	WEATHERMAKER	38MARBQ18AA3	40MBDQ18--3		12,700	\$1,778
207642956	WEATHERMAKER	38MGHBQ36DA3	Combination heat pumps with or without ducts		23,000	\$3,220
207642953	WEATHERMAKER	38MGHBQ48EA3	Combination heat pumps with or without ducts		29,000	\$4,060

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
207642947	WEATHERMAKER	38MGHBQ30DA3	Combination heat pumps with or without ducts		18,200	\$2,548
207642955	WEATHERMAKER	38MGHBQ36DA3	Heat pump with ducts		23,000	\$3,220
207642952	WEATHERMAKER	38MGHBQ48EA3	Heat pump with ducts		28,000	\$3,920
207642946	WEATHERMAKER	38MGHBQ30DA3	Heat pump with ducts		19,000	\$2,660
207642954	WEATHERMAKER	38MGHBQ36DA3	Heat pump without ducts		23,200	\$3,248
207642951	WEATHERMAKER	38MGHBQ48EA3	Heat pump without ducts		30,000	\$4,200
207642945	WEATHERMAKER	38MGHBQ30DA3	Heat pump without ducts		17,500	\$2,450
208447909	WEATHERMAKER	38MURAQ48AB3	40MUAQA48XA3		36,000	\$5,040
207826674	WEATHERMAKER	38MARBQ18AA3	40MBABQ18XB3		12,000	\$1,680
215864047	WELLS	WOS-18PRE/230	WIHW-18MOC/230		14,400	\$2,016
215864046	WELLS	WOS-12PRE/230	WIHW-12MOC/230		10,000	\$1,400
213286783	WELLS	WMCA-48HFMO	Combination heat pumps with or without ducts		37,400	\$5,236
213286785	WELLS	WMCA-55HFMO	Heat pump with ducts		35,200	\$4,928
213286786	WELLS	WMCA-55HFMO	Combination heat pumps with or without ducts		35,000	\$4,900
213307899	WELLS	WUCA-24HFMO	WUA-24HFMAH		19,200	\$2,688
213286775	WELLS	WMCA-18HFMO	Heat pump without ducts		13,500	\$1,890
213286784	WELLS	WMCA-55HFMO	Heat pump without ducts		34,800	\$4,872
213307900	WELLS	WUCA-30HFMO	WUA-30HFMAH		21,000	\$2,940
213307901	WELLS	WUCA-36HFMO	WUA-36HFMAH		30,400	\$4,256
214421470	WELLS	WSA-12HFMO	WSA-12HFMI		10,300	\$1,442
214421471	WELLS	WSA-18HFMO	WSA-18HFMI		11,100	\$1,554
214421472	WELLS	WSA-24HFMO	WSA-24HFMI		18,900	\$2,646
213286776	WELLS	WMCA-18HFMO	Heat pump with ducts		16,000	\$2,240
213286781	WELLS	WMCA-48HFMO	Heat pump without ducts		39,000	\$5,460
213286782	WELLS	WMCA-48HFMO	Heat pump with ducts		36,000	\$5,040
213286777	WELLS	WMCA-18HFMO	Combination heat pumps with or without ducts		14,700	\$2,058
217022364	WELLS	WDHP-24HH	WDCA-18/24A		19,700	\$2,758
217022369	WELLS	WDHP-30HH	WDCA-30/36C		25,000	\$3,500
217022367	WELLS	WDHP-30HH	WDCA-30/36B		25,000	\$3,500
217022368	WELLS	WDHP-36HH	WDCA-30/36B		29,200	\$4,088
217022365	WELLS	WDHP-24HH	WDCA-18/24B		19,700	\$2,758
217022371	WELLS	WDHP-48HH	WDCM-48/60C		34,400	\$4,816
217022372	WELLS	WDHP-60HH	WDCM-48/60C		37,800	\$5,292
217022373	WELLS	WDHP-60HH	WDCA-48/60D		36,000	\$5,040

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
217022370	WELLS	WDHP-36HH	WDCA-30/36C		29,200	\$4,088
215864086	WELLS	WOS-12PRE/230	WICS-12MOC/230		9,800	\$1,372
215864027	WELLS	WDHP-24HH	WDAH-24MOC		20,000	\$2,800
215864029	WELLS	WDHP-36HH	WDAH-36MOC		31,800	\$4,452
215864084	WELLS	WOS-24PRE/230	WIDH-24MOC/230		21,600	\$3,024
215864083	WELLS	WOS-18PRE/230	WIDH-18MOC/230		15,000	\$2,100
215864080	WELLS	WOS-18PRE/230	WIDL-18MOC/230		15,000	\$2,100
215864082	WELLS	WOS-12PRE/230	WIDH-12MOC/230		10,200	\$1,428
215864079	WELLS	WOS-12PRE/230	WIDL-12MOC/230		9,600	\$1,344
215864100	WELLS	WOM-48RH6/230	Heat pump with ducts		37,000	\$5,180
215864119	WELLS	WOM-60HH6/230	Combination heat pumps with or without ducts		45,000	\$6,300
215864118	WELLS	WOM-60HH6/230	Heat pump with ducts		45,000	\$6,300
215864117	WELLS	WOM-60HH6/230	Heat pump without ducts		45,000	\$6,300
215864116	WELLS	WOM-48HH6/230	Combination heat pumps with or without ducts		42,500	\$5,950
215864115	WELLS	WOM-48HH6/230	Heat pump with ducts		44,500	\$6,230
215864114	WELLS	WOM-48HH6/230	Heat pump without ducts		40,500	\$5,670
215864113	WELLS	WOM-36HH5/230	Combination heat pumps with or without ducts		34,800	\$4,872
215864112	WELLS	WOM-36HH5/230	Heat pump with ducts		33,000	\$4,620
215864111	WELLS	WOM-36HH5/230	Heat pump without ducts		36,600	\$5,124
215864110	WELLS	WOM-27HH4/230	Combination heat pumps with or without ducts		23,200	\$3,248
215864109	WELLS	WOM-27HH4/230	Heat pump with ducts		23,000	\$3,220
215864108	WELLS	WOM-27HH4/230	Heat pump without ducts		23,600	\$3,304
215864107	WELLS	WOM-18HH3/230	Combination heat pumps with or without ducts		16,700	\$2,338
215864106	WELLS	WOM-18HH3/230	Heat pump with ducts		17,000	\$2,380
215864105	WELLS	WOM-18HH3/230	Heat pump without ducts		16,400	\$2,296
215864049	WELLS	WOS-33PRE/230	WIHW-33MOC/230		29,600	\$4,144
215864089	WELLS	WOS-24PRE/230	WIFC-24MOC/230		20,200	\$2,828
215864072	WELLS	WOS-24PRE/230	WI4C-24MOC/230		20,400	\$2,856
215864088	WELLS	WOS-18PRE/230	WIFC-18MOC/230		14,400	\$2,016
215864087	WELLS	WOS-18PRE/230	WICS-16MOC/230		14,200	\$1,988
215864071	WELLS	WOS-18PRE/230	WI4C-18MOC/230		14,900	\$2,086
215864076	WELLS	WOS-18PRE/230	WI1C-18MOC/230		14,500	\$2,030
215864070	WELLS	WOS-12PRE/230	WI4C-12MOC/230		10,000	\$1,400

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215864075	WELLS	WOS-12PRE/230	WI1C-12MOC/230		9,600	\$1,344
215864048	WELLS	WOS-24PRE/230	WIHW-24MOC/230		21,600	\$3,024
215864031	WELLS	WDHP-60HH	WDAH-60MOC		45,000	\$6,300
215864030	WELLS	WDHP-48HH	WDAH-48MOC		37,000	\$5,180
215864028	WELLS	WDHP-30HH	WDAH-30MOC		23,800	\$3,332
215864024	WELLS	WOS-33PRE/230	WIAH-36MOC/230		27,400	\$3,836
215864023	WELLS	WOS-24PRE/230	WIAH-24MOC/230		16,900	\$2,366
215864022	WELLS	WOS-18PRE/230	WIAH-18MOC/230		14,000	\$1,960
213307907	WELLS	WUCA-30HFMO	WUA-36BHFM		19,600	\$2,744
213307904	WELLS	WUCA-36HFMO	WUA-36BHFM		27,400	\$3,836
213286778	WELLS	WMCA-27HFMO	Heat pump without ducts		22,400	\$3,136
213307896	WELLS	WMCA-36HFMO	Heat pump without ducts		27,400	\$3,836
213927635	WELLS	WUCB-36HFMO	WUA-36HFMAH		31,800	\$4,452
213927636	WELLS	WUCB-36HFMO	WUA-36BHFM		27,000	\$3,780
214421473	WELLS	WSA-33HFMO	WSA-33HFMI		27,800	\$3,892
213307906	WELLS	WUCA-60HFMO	WUA-60DHFM		37,000	\$5,180
213307903	WELLS	WUCA-60HFMO	WUA-60HFMAH		42,000	\$5,880
213307902	WELLS	WUCA-48HFMO	WUA-48HFMAH		36,000	\$5,040
213307898	WELLS	WMCA-36HFMO	Combination heat pumps with or without ducts		28,600	\$4,004
213307897	WELLS	WMCA-36HFMO	Heat pump with ducts		30,000	\$4,200
213286780	WELLS	WMCA-27HFMO	Combination heat pumps with or without ducts		22,600	\$3,164
205417838	WESTINGHOUSE	WHP24SZA21S	WHP24WMA21S		14,500	\$2,030
207237543	WESTINGHOUSE	WHU24SZA21S	WHU24DHA21S		19,300	\$2,702
214609736	WILLIS	PUHW18KCH23S2-O	PUHW18KCH23S2-I		10,800	\$1,512
214609737	WILLIS	PUHW24KCH25S2-O	PUHW24KCH25S2-I		15,000	\$2,100
214609738	WILLIS	PUHW12KCH24S2-O	PUHW12KCH24S2-I		7,000	\$980
214137765	WILLIS	FLEX24/36KUH	FLEXAH24/36K		24,000	\$3,360
214810330	WILLIS	MZUHW42KCH21S2-O	Heat pump without ducts		35,600	\$4,984
214810329	WILLIS	MZUHW36KCH21S2-O	Heat pump without ducts		30,800	\$4,312
214810333	WILLIS	MZUHW30KCH21S2-O	Heat pump without ducts		27,200	\$3,808
214810332	WILLIS	MZUHW24KCH21S2-O	Heat pump without ducts		23,600	\$3,304
214810331	WILLIS	MZUHW18KCH21S2-O	Heat pump without ducts		14,700	\$2,058
216720958	WILLIS	FLEX60KUH32	FLEXAH60KR32		45,000	\$6,300
216720957	WILLIS	FLEX60KUH32	FLEXAH48KR32		39,500	\$5,530
216720956	WILLIS	FLEX48KUH32	FLEXAH48KR32		39,500	\$5,530
216720955	WILLIS	FLEX36KUH32	FLEXAH36KR32		28,200	\$3,948

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216720954	WILLIS	FLEX36KUHR32	FLEXAH24KR32		20,600	\$2,884
216720953	WILLIS	FLEX24KUHR32	FLEXAH24KR32		20,600	\$2,884
217007966	WILLIS	AUHW24KR32-O	AUHW24KR32-I		15,000	\$2,100
217007960	WILLIS	PUHW12KR32-O	PUHW12KR32-I		10,000	\$1,400
217007958	WILLIS	PUHW36KR32-O	PUHW36KR32-I		27,400	\$3,836
217007957	WILLIS	PUHW30KR32-O	PUHW30KR32-I		24,000	\$3,360
216772322	WILLIS	MZUHW42KR32-O	Combination heat pumps with or without ducts		40,000	\$5,600
216772318	WILLIS	MZUHW42KR32-O	Heat pump with ducts		40,000	\$5,600
216772312	WILLIS	MZUHW42KR32-O	Heat pump without ducts		40,000	\$5,600
216772321	WILLIS	MZUHW36KR32-O	Combination heat pumps with or without ducts		36,000	\$5,040
216772317	WILLIS	MZUHW36KR32-O	Heat pump with ducts		36,000	\$5,040
216772311	WILLIS	MZUHW36KR32-O	Heat pump without ducts		36,000	\$5,040
216772320	WILLIS	MZUHW30KR32-O	Combination heat pumps with or without ducts		27,600	\$3,864
216772316	WILLIS	MZUHW30KR32-O	Heat pump with ducts		27,200	\$3,808
216772310	WILLIS	MZUHW30KR32-O	Heat pump without ducts		28,000	\$3,920
216772319	WILLIS	MZUHW24KR32-O	Combination heat pumps with or without ducts		23,000	\$3,220
216772315	WILLIS	MZUHW24KR32-O	Heat pump with ducts		22,000	\$3,080
216772309	WILLIS	MZUHW24KR32-O	Heat pump without ducts		23,600	\$3,304
216772314	WILLIS	MZUHW18KR32-O	Combination heat pumps with or without ducts		15,400	\$2,156
216772313	WILLIS	MZUHW18KR32-O	Heat pump with ducts		15,000	\$2,100
216772308	WILLIS	MZUHW18KR32-O	Heat pump without ducts		16,000	\$2,240
214567597	WILLIS	FLEX24/36KUH	CC36V1		22,000	\$3,080
214567596	WILLIS	FLEX24/36KUH	CC24V1		15,000	\$2,100
214797686	WILLIS	FLEX48/60KUH	FLEXAH48/60K		36,000	\$5,040
214797687	WILLIS	FLEX48/60KUH	CC48V1		31,200	\$4,368
214797688	WILLIS	FLEX48/60KUH	CC60V1		35,200	\$4,928
9038619	WILLIS	WUHO12KW22S	WUHI12KHW		7,800	\$1,092
9038621	WILLIS	WUHO24KW20S	WUHI24KHW		15,400	\$2,156
212615066	YONAN	YS-12HRFN1-E0OU	YS-12HRFN1-E0		10,400	\$1,456
208106987	YONAN	YOE-48HFN1	YUE-48HFN1		29,000	\$4,060
214396212	YORK	HH836E2S11	CTF36C5CDS1	TM9E080C20MP12	29,000	\$4,060
214396122	YORK	HH836E2S11	CTM36C5CDS1	TM9E080C20MP12	29,000	\$4,060
214395826	YORK	HH836E2S11	CTM36C5CDS1	TM9Y100C20MP11	30,000	\$4,200

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214395907	YORK	HH836E2S11	CTF36C5CDS1	TM9E100C20MP12	29,000	\$4,060
214396009	YORK	HH836E2S11	CTM36C5CDS1	TM9E100C20MP12	29,000	\$4,060
214395697	YORK	HH836E2S11	CTF36C5CDS1	TM9Y100C20MP11	28,600	\$4,004
214395914	YORK	HH836E2S11	CTF36C5CDS1	Y81E100C20SMPS1	28,600	\$4,004
214395825	YORK	HH836E2S11	CTF36C5CDS1	Y81E080C20SMPS1	29,400	\$4,116
214395822	YORK	HH836E2S11	CTM36C5CDS1	Y81E100C20SMPS1	28,600	\$4,004
214395919	YORK	HH836E2S11	CTM36C5CDS1	TL9E100C20UH11	28,400	\$3,976
214395807	YORK	HH836E2S11	CTF36C5CDS1	Y81E120C16SMPS1	28,000	\$3,920
215853282	YORK	HH836E2S11	CTM36C5CDS1	Y91E080C20SMPS1	28,600	\$4,004
214395701	YORK	HH836E2S11	CTM36C5CDS1	Y81E120C20SMPS1	28,600	\$4,004
214395908	YORK	HH836E2S11	CTF36C5CDS1	TL9E100C20UH11	28,600	\$4,004
214396202	YORK	HH836E2S11	CTM36C5CDS1	Y81E080C16SMPS1	27,600	\$3,864
214395703	YORK	HH836E2S11	CTF36C5CDS1	Y81E080C16SMPS1	27,600	\$3,864
214396014	YORK	HH836E2S11	CTM36C5CDS1	Y81E120C16SMPS1	28,000	\$3,920
214395916	YORK	HH836E2S11	CTM36C5CDS1	Y81E080C20SMPS1	28,400	\$3,976
214396118	YORK	HH836E2S11	CTM36C5CDS1	Y81E100C16SMPS1	28,200	\$3,948
216374505	YORK	HH836E2S11	CTF36C5CDS1	Y92E100C20SMPS1	27,600	\$3,864
214396197	YORK	HH836E2S11	CTF36C5CDS1	Y81E100C16SMPS1	28,200	\$3,948
214396208	YORK	HH836E2S11	CTM36C5CDS1	TL8E100C20UH11	27,400	\$3,836
214395903	YORK	HH836E2S11	CTF36C5CDS1	TL8E100C20UH11	27,600	\$3,864
214395827	YORK	HH836E2S11	CTM36C5CDS1	TL8E080C16UH11	28,600	\$4,004
214396101	YORK	HH836E2S11	CTF36C5CDS1	TL8E080C16UH11	28,600	\$4,004
214606574	YORK	HH836E2S11	CTF36C5CDS1		28,000	\$3,920
216374506	YORK	HH836E2S11	CTF36C5CDS1	Y92E080C16SMPS1	27,600	\$3,864
214395913	YORK	HH836E2S11	CTM36C5CDS1	TL9E080C16UH11	29,000	\$4,060
214606573	YORK	HH836E2S11	CTF36B5CDS1		27,800	\$3,892
214396119	YORK	HH836E2S11	CTF36C5CDS1	TL9E080C16UH11	28,200	\$3,948
214606576	YORK	HH836E2S11	CTM36C5CDS1		27,600	\$3,864
216374509	YORK	HH836E2S11	CTM36C5CDS1	Y92E080C16SMPS1	27,600	\$3,864
214396117	YORK	HH836E2S11	CTM36C5CDS1	YPLC100C16MP13	28,600	\$4,004
214396116	YORK	HH836E2S11	CTM36C5CDS1	YPLC080C16MP13	28,600	\$4,004
214396115	YORK	HH836E2S11	CTM36C5CDS1	TPLC100C16MP13	28,600	\$4,004
214396114	YORK	HH836E2S11	CTM36C5CDS1	TPLC080C16MP13	28,600	\$4,004
214396113	YORK	HH836E2S11	CTM36C5CDS1	TMLV100C16MP12	28,600	\$4,004
214396112	YORK	HH836E2S11	CTM36C5CDS1	TM8V080C16MP12	28,600	\$4,004
214396111	YORK	HH836E2S11	CTM36C5CDS1	TM8V100C16MP12	28,600	\$4,004
214396005	YORK	HH836E2S11	CTF36C5CDS1	YP9C100C20MP13	29,600	\$4,144
214396004	YORK	HH836E2S11	CTF36C5CDS1	TP9C100C20MP13	29,600	\$4,144

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396003	YORK	HH836E2S11	CTF36C5CDS1	TM9V100C20MP12	29,600	\$4,144
215853285	YORK	HH836E2S11	CTM36C5CDS1+JMET16CS2N1		27,800	\$3,892
214807388	YORK	HH860E2S11	CTU60D5XHS1+JMET18DS2N1+TXV		36,600	\$5,124
214395677	YORK	HH860E2S11	CTF60D5CHS1+JMET18DS2N1		36,600	\$5,124
214606578	YORK	HH860E2S11	CTF60D5CJS1		38,000	\$5,320
214395896	YORK	HH860E2S11	CTF60D5CJS1	TM9Y120D20MP11	38,500	\$5,390
214833516	YORK	HH860E2S11	JSE60D5CJ2SS1		37,200	\$5,208
214833515	YORK	HH860E2S11	JSC60D5CJ2SS1		37,200	\$5,208
214395992	YORK	HH860E2S11	JHC60D5CJ2SS1		37,200	\$5,208
214421504	YORK	HH860E2S11	CTM60C5CHS1+JMET16CS2N1		36,800	\$5,152
214396080	YORK	HH824E2S11	CTM30B5ACS1	YP9C060B12MP13	18,100	\$2,534
214396079	YORK	HH824E2S11	CTM30B5ACS1	TP9C060B12MP13	18,100	\$2,534
214396078	YORK	HH824E2S11	CTM30B5ACS1	TM9V060B12MP12	18,100	\$2,534
214395977	YORK	HH824E2S11	CTM30B5ACS1	TL9E060B12UH11	18,100	\$2,534
214807386	YORK	HH824E2S11	CTU30B5XCS1+JME12B2SN1+TXV		17,500	\$2,450
214395773	YORK	HH824E2S11	CTF30B5ACS1+JME12B2SN1		17,500	\$2,450
215853271	YORK	HH824E2S11	CTM30B5ACS1+JMET08BS2N1		17,900	\$2,506
214606584	YORK	HH860E2S11	CTM60C5CGS1		34,800	\$4,872
216374504	YORK	HH836E2S11	CTM36B5CDS1	Y92E060B12SMPS1	28,200	\$3,948
214807375	YORK	HH836E2S11	CTU36B5XDS1+JME12B2SN1+TXV		26,800	\$3,752
214396210	YORK	HH836E2S11	CTF36B5CDS1+JME12B2SN1		26,800	\$3,752
214396008	YORK	HH836E2S11	CTM36B5CDS1	TM9E060B12MP12	27,400	\$3,836
214395909	YORK	HH836E2S11	CTF36C5CDS1	TM9E080C16MP12	28,000	\$3,920
214396207	YORK	HH836E2S11	CTF36C5CDS1	YP9C080C16MP13	28,200	\$3,948
214396206	YORK	HH836E2S11	CTF36C5CDS1	TP9C080C16MP13	28,200	\$3,948
214396205	YORK	HH836E2S11	CTF36C5CDS1	TM9V080C16MP12	28,200	\$3,948
214395811	YORK	HH836E2S11	CTM36B5CDS1	TM9Y080B12MP11	27,800	\$3,892
214395818	YORK	HH836E2S11	CTM36C5CDS1	YP9C080C16MP13	28,200	\$3,948
214395817	YORK	HH836E2S11	CTM36C5CDS1	TP9C080C16MP13	28,200	\$3,948
214395816	YORK	HH836E2S11	CTM36C5CDS1	TM9V080C16MP12	28,200	\$3,948

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853294	YORK	HH836E2S11	CTM36C5CDS1+JMV17CC2N1		28,200	\$3,948
214395806	YORK	HH836E2S11	CTF36C5CDS1+JMC16C2SN1		28,000	\$3,920
214396196	YORK	HH836E2S11	CTF36C5CDS1+JMET16CS2N1		27,800	\$3,892
215853286	YORK	HH836E2S11	CTM36C5CDS1+JMC17C2SN1		28,200	\$3,948
214719783	YORK	HH836E2S11	CTU48C5XFS1+TXV	TM9E100C20MP12	26,400	\$3,696
214395630	YORK	HH836E2S11	CTF48C5CFS1	TM9E100C20MP12	26,400	\$3,696
214719748	YORK	HH836E2S11	CTU48C5XFS1+TXV	TM9Y080C16MP11	25,800	\$3,612
214395834	YORK	HH836E2S11	CTF48C5CFS1	TM9Y080C16MP11	25,800	\$3,612
214609031	YORK	HH836E2S11	CTM48C5CFS1	Y91E080C16SMPS1	26,400	\$3,696
214396025	YORK	HH836E2S11	CTM48C5CFS1+JME16C2SN1		25,800	\$3,612
214396131	YORK	HH836E2S11	CTM48C5CFS1+JMV16CC2N1		25,800	\$3,612
214395728	YORK	HH836E2S11	CTM48C5CFS1+JME12C2SN1		25,800	\$3,612
214719747	YORK	HH836E2S11	CTU48C5XFS1+JMET12CS2N1+TXV		25,800	\$3,612
214395689	YORK	HH836E2S11	CTF48C5CFS1+JMET12CS2N1		25,800	\$3,612
214606513	YORK	HH836E2S11	CTM36B5CDS1		27,000	\$3,780
216374538	YORK	HH860E2S11	CTM60C5CHS1	Y92E100C20SMPS1	37,400	\$5,236
214650286	YORK	HH860E2S11	CTU60D5XHS1+TXV	TM9E120D20MP12	37,800	\$5,292
214396187	YORK	HH860E2S11	CTF60D5CHS1	TM9E120D20MP12	37,800	\$5,292
214395780	YORK	HH860E2S11	CTF60C5CHS1+JMC17C2SN1		36,400	\$5,096
214396182	YORK	HH860E2S11	CTM60D5CHS1+JME18D2SN1		36,600	\$5,124
214719743	YORK	HH860E2S11	CTU60C5XGS1+TXV	TL9E080C16UH11	33,000	\$4,620
214396054	YORK	HH860E2S11	CTF60C5CGS1	TL9E080C16UH11	33,000	\$4,620
214395887	YORK	HH860E2S11	CTM60C5CHS1+JMV17CC2N1		36,400	\$5,096
215853265	YORK	HH860E2S11	CTM60D5CJS1	YP9C120D20MP13	38,000	\$5,320
215853264	YORK	HH860E2S11	CTM60D5CJS1	TP9C120D20MP13	38,000	\$5,320
215853263	YORK	HH860E2S11	CTM60D5CJS1	TM9V120D20MP12	38,000	\$5,320

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396190	YORK	HH860E2S11	CTF60D5CJS1+JMET18DS2 N1		37,200	\$5,208
214606582	YORK	HH860E2S11	CTM60D5CHS1		34,800	\$4,872
214807390	YORK	HH860E2S11	CTU60D5XHS1+JMC20D2S N1+TXV		36,600	\$5,124
214396181	YORK	HH860E2S11	CTF60D5CHS1+JMC20D2SN 1		36,600	\$5,124
214395974	YORK	HH824E2S11	CTM30B5ACS1	YP9C080B12MP13	18,000	\$2,520
214395973	YORK	HH824E2S11	CTM30B5ACS1	TP9C080B12MP13	18,000	\$2,520
214395972	YORK	HH824E2S11	CTM30B5ACS1	TM9V080B12MP12	18,000	\$2,520
214650587	YORK	HH824E2S11	CTU30B5XCS1+TXV	TM9E080B12MP12	17,800	\$2,492
214396077	YORK	HH824E2S11	CTF30B5ACS1	TM9E080B12MP12	17,800	\$2,492
214650315	YORK	HH824E2S11	CTU30B5XCS1+TXV	YP9C060B12MP13	18,000	\$2,520
214650311	YORK	HH824E2S11	CTU30B5XCS1+TXV	TP9C060B12MP13	18,000	\$2,520
214650307	YORK	HH824E2S11	CTU30B5XCS1+TXV	TM9V060B12MP12	18,000	\$2,520
214395674	YORK	HH824E2S11	CTF30B5ACS1	YP9C060B12MP13	18,000	\$2,520
214395673	YORK	HH824E2S11	CTF30B5ACS1	TP9C060B12MP13	18,000	\$2,520
214395672	YORK	HH824E2S11	CTF30B5ACS1	TM9V060B12MP12	18,000	\$2,520
214395671	YORK	HH824E2S11	CTM30B5ACS1	YPLC080B12MP13	18,100	\$2,534
214395969	YORK	HH824E2S11	CTM30B5ACS1	TM9Y080B12MP11	18,000	\$2,520
214396076	YORK	HH824E2S11	JHE24B5AC2SS1		18,600	\$2,604
214606579	YORK	HH860E2S11	CTF60D5CGS1		34,800	\$4,872
214396002	YORK	HH836E2S11	CTF36C5CDS1+JMC17C2SN 1		27,600	\$3,864
214728358	YORK	HH836E2S11	CTU36B5XDS1+TXV	YPLC080B12MP13	27,200	\$3,808
214395614	YORK	HH836E2S11	CTF36B5CDS1	YPLC080B12MP13	27,200	\$3,808
214395821	YORK	HH836E2S11	CTM36C5CDS1	YP9C100C16MP13	28,000	\$3,920
214395820	YORK	HH836E2S11	CTM36C5CDS1	TP9C100C16MP13	28,000	\$3,920
214395819	YORK	HH836E2S11	CTM36C5CDS1	TM9V100C16MP12	28,000	\$3,920
214396200	YORK	HH836E2S11	CTF36C5CDS1+JME16C2SN 1		28,200	\$3,948
214395805	YORK	HH836E2S11	CTF36C5CDS1+JMET12CS2 N1		27,800	\$3,892
214719826	YORK	HH836E2S11	CTU48C5XFS1+TXV	TM9E080C20MP12	26,200	\$3,668
214395735	YORK	HH836E2S11	CTF48C5CFS1	TM9E080C20MP12	26,200	\$3,668
214719770	YORK	HH836E2S11	CTU48C5XFS1+TXV	TL9E100C20UH11	26,200	\$3,668
214395928	YORK	HH836E2S11	CTF48C5CFS1	TL9E100C20UH11	26,200	\$3,668
214719782	YORK	HH836E2S11	CTU48C5XFS1+TXV	TL9E080C16UH11	26,000	\$3,640
214395927	YORK	HH836E2S11	CTF48C5CFS1	TL9E080C16UH11	26,000	\$3,640

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214719808	YORK	HH836E2S11	CTU48C5XFS1+TXV	TM9E080C16MP12	26,000	\$3,640
214395629	YORK	HH836E2S11	CTF48C5CFS1	TM9E080C16MP12	26,000	\$3,640
214395625	YORK	HH836E2S11	CTM48C5CFS1	YP9C080C16MP13	25,800	\$3,612
214395624	YORK	HH836E2S11	CTM48C5CFS1	TP9C080C16MP13	25,800	\$3,612
214395623	YORK	HH836E2S11	CTM48C5CFS1	TM9V080C16MP12	25,800	\$3,612
214395840	YORK	HH836E2S11	CTM48C5CFS1+JMC16C2S N1		25,800	\$3,612
214719790	YORK	HH836E2S11	CTU48C5XFS1+TXV	TM9Y100C20MP11	26,600	\$3,724
214396023	YORK	HH836E2S11	CTF48C5CFS1	TM9Y100C20MP11	26,600	\$3,724
214719767	YORK	HH836E2S11	CTU48C5XFS1+TXV	TM9E100C16MP12	26,000	\$3,640
214395616	YORK	HH836E2S11	CTF48C5CFS1	TM9E100C16MP12	26,000	\$3,640
214396193	YORK	HH836E2S11	CTM48C5CFS1	TL9E080C16UH11	26,000	\$3,640
214606575	YORK	HH836E2S11	CTM48C5CFS1		26,000	\$3,640
214395693	YORK	HH836E2S11	JHC36B5CD2SS1		26,600	\$3,724
214395984	YORK	HH860E2S11	CTM60C5CHS1+JMC17C2S N1		36,400	\$5,096
214395760	YORK	HH860E2S11	CTM60D5CGS1	TM9Y120D20MP11	32,400	\$4,536
214807645	YORK	HH860E2S11	CTU60C5XGS1+TXV	YP9C100C16MP13	32,200	\$4,508
214807644	YORK	HH860E2S11	CTU60C5XGS1+TXV	TP9C100C16MP13	32,200	\$4,508
214807627	YORK	HH860E2S11	CTU60C5XGS1+TXV	TM9V100C16MP12	32,200	\$4,508
214396045	YORK	HH860E2S11	CTF60C5CGS1	YP9C100C16MP13	32,200	\$4,508
214396044	YORK	HH860E2S11	CTF60C5CGS1	TP9C100C16MP13	32,200	\$4,508
214396043	YORK	HH860E2S11	CTF60C5CGS1	TM9V100C16MP12	32,200	\$4,508
215853276	YORK	HH860E2S11	JHE60C5CH2SS1		37,000	\$5,180
215853268	YORK	HH860E2S11	CTM60D5CJS1	TM9Y120D20MP11	38,500	\$5,390
214606519	YORK	HH860E2S11	CTM60D5CJS1		38,000	\$5,320
214395894	YORK	HH860E2S11	JHE60D5CJ2SS1		37,400	\$5,236
214650563	YORK	HH824E2S11	CTU30B5XCS1+TXV	TM9Y080B12MP11	17,900	\$2,506
214396075	YORK	HH824E2S11	CTF30B5ACS1	TM9Y080B12MP11	17,900	\$2,506
214650656	YORK	HH824E2S11	CTU30B5XCS1+TXV	YP9C080B12MP13	17,900	\$2,506
214650652	YORK	HH824E2S11	CTU30B5XCS1+TXV	TP9C080B12MP13	17,900	\$2,506
214650648	YORK	HH824E2S11	CTU30B5XCS1+TXV	TM9V080B12MP12	17,900	\$2,506
214395776	YORK	HH824E2S11	CTF30B5ACS1	YP9C080B12MP13	17,900	\$2,506
214395775	YORK	HH824E2S11	CTF30B5ACS1	TP9C080B12MP13	17,900	\$2,506
214395774	YORK	HH824E2S11	CTF30B5ACS1	TM9V080B12MP12	17,900	\$2,506
214650456	YORK	HH824E2S11	CTU30B5XCS1+TXV	TM9E060B12MP12	17,900	\$2,506
214396172	YORK	HH824E2S11	CTF30B5ACS1	TM9E060B12MP12	17,900	\$2,506

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853270	YORK	HH824E2S11	CTM30B5ACS1+JMET12BS2 N1		17,800	\$2,492
214606583	YORK	HH860E2S11	CTM60D5CGS1		34,800	\$4,872
216374503	YORK	HH836E2S11	CTU36B5XDS1+TXV	Y92E060B12SMPS1	28,200	\$3,948
216374502	YORK	HH836E2S11	CTF36B5CDS1	Y92E060B12SMPS1	28,200	\$3,948
214395906	YORK	HH836E2S11	CTM36B5CDS1	YP9C080B12MP13	27,000	\$3,780
214395905	YORK	HH836E2S11	CTM36B5CDS1	TP9C080B12MP13	27,000	\$3,780
214395904	YORK	HH836E2S11	CTM36B5CDS1	TM9V080B12MP12	27,000	\$3,780
214728353	YORK	HH836E2S11	CTU36B5XDS1+TXV	YP9C060B12MP13	27,200	\$3,808
214728352	YORK	HH836E2S11	CTU36B5XDS1+TXV	TP9C060B12MP13	27,200	\$3,808
214728351	YORK	HH836E2S11	CTU36B5XDS1+TXV	TM9V060B12MP12	27,200	\$3,808
214396108	YORK	HH836E2S11	CTF36B5CDS1	YP9C060B12MP13	27,200	\$3,808
214396107	YORK	HH836E2S11	CTF36B5CDS1	TP9C060B12MP13	27,200	\$3,808
214396106	YORK	HH836E2S11	CTF36B5CDS1	TM9V060B12MP12	27,200	\$3,808
214395710	YORK	HH836E2S11	CTF36C5CDS1	YP9C100C16MP13	27,800	\$3,892
214395709	YORK	HH836E2S11	CTF36C5CDS1	TP9C100C16MP13	27,800	\$3,892
214395708	YORK	HH836E2S11	CTF36C5CDS1	TM9V100C16MP12	27,800	\$3,892
214395815	YORK	HH836E2S11	CTM36C5CDS1	TM9Y080C16MP11	27,200	\$3,808
214396011	YORK	HH836E2S11	CTM36C5CDS1	TM9E080C16MP12	29,400	\$4,116
215853293	YORK	HH836E2S11	CTU36B5XDS1+TXV	TL9E060B12UH11	27,200	\$3,808
215853292	YORK	HH836E2S11	CTF36B5CDS1	TL9E060B12UH11	27,200	\$3,808
215853290	YORK	HH836E2S11	CTM36C5CDS1+JMVT16CC 2N1		28,200	\$3,948
214396100	YORK	HH836E2S11	CTF36C5CDS1+JMVT17CC2 N1		28,000	\$3,920
215853278	YORK	HH836E2S11	CTM36B5CDS1	Y91E080B12SMPS1	27,600	\$3,864
214395923	YORK	HH836E2S11	CTM48C5CFS1	YP9C100C20MP13	26,400	\$3,696
214395922	YORK	HH836E2S11	CTM48C5CFS1	TP9C100C20MP13	26,400	\$3,696
214395921	YORK	HH836E2S11	CTM48C5CFS1	TM9V100C20MP12	26,400	\$3,696
214719824	YORK	HH836E2S11	CTU48C5XFS1+TXV	TM9Y100C16MP11	26,000	\$3,640
214396094	YORK	HH836E2S11	CTF48C5CFS1	TM9Y100C16MP11	26,000	\$3,640
214807381	YORK	HH836E2S11	CTU48C5XFS1+JME16C2SN 1+TXV		25,800	\$3,612
214395997	YORK	HH836E2S11	CTF48C5CFS1+JME16C2SN 1		25,800	\$3,612
214395620	YORK	HH836E2S11	CTM48C5CFS1+JMC17C2S N1		25,600	\$3,584
215853273	YORK	HH836E2S11	CTU48C5XFS1+JMET16CS2 N1+TXV		25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396022	YORK	HH836E2S11	CTF48C5CFS1+JMET16CS2 N1		25,800	\$3,612
214396015	YORK	HH836E2S11	JHE36C5CD2SS1		27,200	\$3,808
216374535	YORK	HH860E2S11	CTM60D5CHS1	Y92E120D20SMPS1	38,000	\$5,320
214395983	YORK	HH860E2S11	CTM60C5CHS1+JME16C2S N1		36,600	\$5,124
214807391	YORK	HH860E2S11	CTU60D5XHS1+JME18D2SN 1+TXV		36,600	\$5,124
214396084	YORK	HH860E2S11	CTF60D5CHS1+JME18D2SN 1		36,600	\$5,124
214395886	YORK	HH860E2S11	CTF60C5CHS1+JME16C2SN 1		36,600	\$5,124
214807642	YORK	HH860E2S11	CTU60D5XGS1+JME18D2S N1+TXV		34,400	\$4,816
214396151	YORK	HH860E2S11	CTF60D5CGS1+JME18D2SN 1		34,400	\$4,816
214396191	YORK	HH860E2S11	CTM60D5CJS1+JME18D2SN 1		37,200	\$5,208
214606580	YORK	HH860E2S11	CTF60D5CHS1		34,600	\$4,844
214396188	YORK	HH860E2S11	JHE60D5CH2SS1		36,800	\$5,152
214395971	YORK	HH824E2S11	CTM30B5ACS1+JMC12B2S N1		17,600	\$2,464
214395778	YORK	HH824E2S11	CTM30B5ACS1	TM9E080B12MP12	17,900	\$2,506
214650129	YORK	HH824E2S11	CTU30B5XCS1+TXV	TL9E060B12UH11	18,000	\$2,520
214395779	YORK	HH824E2S11	CTF30B5ACS1	TL9E060B12UH11	18,000	\$2,520
215853272	YORK	HH824E2S11	CTM30B5ACS1+JMV12BC2 N1		17,600	\$2,464
214807385	YORK	HH824E2S11	CTU30B5XCS1+JMC12B2SN 1+TXV		17,600	\$2,464
214396074	YORK	HH824E2S11	CTF30B5ACS1+JMC12B2SN 1		17,600	\$2,464
214807382	YORK	HH824E2S11	CTU30B5XCS1+JME08B2SN 1+TXV		17,600	\$2,464
214395771	YORK	HH824E2S11	CTF30B5ACS1+JME08B2SN 1		17,600	\$2,464
216374501	YORK	HH836E2S11	CTM36B5CDS1	Y92E080B12SMPS1	28,000	\$3,920
214395628	YORK	HH836E2S11	CTF48C5CFS1	YP9C100C20MP13	26,600	\$3,724
214395627	YORK	HH836E2S11	CTF48C5CFS1	TP9C100C20MP13	26,600	\$3,724
214395626	YORK	HH836E2S11	CTF48C5CFS1	TM9V100C20MP12	26,600	\$3,724

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214395924	YORK	HH836E2S11	CTM48C5CFS1	TM9Y080C16MP11	25,800	\$3,612
214807378	YORK	HH836E2S11	CTU48C5XFS1+JMVT17CC2 N1+TXV		25,800	\$3,612
214395920	YORK	HH836E2S11	CTF48C5CFS1+JMVT17CC2 N1		25,800	\$3,612
214395617	YORK	HH836E2S11	CTM48C5CFS1+JMVT17CC2 N1		25,600	\$3,584
214807379	YORK	HH836E2S11	CTU48C5XFS1+JMC17C2SN 1+TXV		25,800	\$3,612
214396024	YORK	HH836E2S11	CTF48C5CFS1+JMC17C2SN 1		25,800	\$3,612
214421499	YORK	HH836E2S11	CTM48C5CFS1+JMET16CS2 N1		25,800	\$3,612
216374534	YORK	HH860E2S11	CTF60C5CHS1	Y92E100C20SMPS1	37,400	\$5,236
214395794	YORK	HH860E2S11	CTM60C5CHS1	TM9E080C20MP12	38,000	\$5,320
214395678	YORK	HH860E2S11	CTM60D5CHS1+JMVT20DC 2N1		36,600	\$5,124
214609023	YORK	HH860E2S11	CTM60C5CGS1	Y91E100C16SMPS1	33,600	\$4,704
214650591	YORK	HH860E2S11	CTU60D5XGS1+TXV	TM9Y120D20MP11	32,400	\$4,536
214395955	YORK	HH860E2S11	CTF60D5CGS1	TM9Y120D20MP11	32,400	\$4,536
214807389	YORK	HH860E2S11	CTU60D5XHS1+JMVT20DC2 N1+TXV		37,000	\$5,180
214396083	YORK	HH860E2S11	CTF60D5CHS1+JMVT20DC2 N1		37,000	\$5,180
214395796	YORK	HH860E2S11	CTF60D5CJS1+JMC20D2SN 1		37,000	\$5,180
214606530	YORK	HH860E2S11	CTM60C5CHS1		34,600	\$4,844
214421496	YORK	HH860E2S11	CTF60C5CHS1+JMET16CS2 N1		36,800	\$5,152
214807384	YORK	HH824E2S11	CTU30B5XCS1+JMVT12BC2 N1+TXV		17,600	\$2,464
214395970	YORK	HH824E2S11	CTF30B5ACS1+JMVT12BC2 N1		17,600	\$2,464
214650575	YORK	HH824E2S11	CTU30B5XCS1+TXV	TM9Y060B12MP11	18,000	\$2,520
214396173	YORK	HH824E2S11	CTF30B5ACS1	TM9Y060B12MP11	18,000	\$2,520
214395772	YORK	HH824E2S11	CTM30B5ACS1+JME12B2SN 1		17,600	\$2,464
214807383	YORK	HH824E2S11	CTU30B5XCS1+JMET08BS2 N1+TXV		17,800	\$2,492

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396171	YORK	HH824E2S11	CTF30B5ACS1+JMET08BS2 N1		17,800	\$2,492
214606572	YORK	HH824E2S11	CTM30B5ACS1		18,800	\$2,632
214807639	YORK	HH860E2S11	CTU60D5XGS1+JMVT20DC2 N1+TXV		33,800	\$4,732
214395639	YORK	HH860E2S11	CTF60D5CGS1+JMVT20DC2 N1		33,800	\$4,732
216374508	YORK	HH836E2S11	CTU36B5XDS1+TXV	Y92E080B12SMPS1	28,000	\$3,920
216374507	YORK	HH836E2S11	CTF36B5CDS1	Y92E080B12SMPS1	28,000	\$3,920
216374500	YORK	HH836E2S11	CTF36C5CDS1	Y92E100C16SMPS1	26,800	\$3,752
215853280	YORK	HH836E2S11	CTF36C5CDS1	Y91E080C16SMPS1	27,000	\$3,780
214396013	YORK	HH836E2S11	CTM36B5CDS1	TM9E080B12MP12	28,200	\$3,948
214728355	YORK	HH836E2S11	CTU36B5XDS1+TXV	TM9Y060B12MP11	27,800	\$3,892
214396123	YORK	HH836E2S11	CTF36B5CDS1	TM9Y060B12MP11	27,800	\$3,892
214395711	YORK	HH836E2S11	CTM36C5CDS1	TM9E100C16MP12	28,000	\$3,920
214719721	YORK	HH836E2S11	CTU36B5XDS1+TXV	TM9Y080B12MP11	27,800	\$3,892
214396201	YORK	HH836E2S11	CTF36B5CDS1	TM9Y080B12MP11	27,800	\$3,892
214807371	YORK	HH836E2S11	CTU36B5XDS1+JMVT12BC2 N1+TXV		27,800	\$3,892
214396001	YORK	HH836E2S11	CTF36B5CDS1+JMVT12BC2 N1		27,800	\$3,892
214779453	YORK	HH836E2S11	CTU36B5XDS1+JMET12BS2 N1+TXV		28,200	\$3,948
214421495	YORK	HH836E2S11	CTF36B5CDS1+JMET12BS2 N1		28,200	\$3,948
214395902	YORK	HH836E2S11	CTF36C5CDS1+JMVT16CC2 N1		28,000	\$3,920
214395814	YORK	HH836E2S11	CTM36B5CDS1	TM9Y060B12MP11	27,600	\$3,864
214396211	YORK	HH836E2S11	CTF36C5CDS1+JME12C2SN 1		27,000	\$3,780
214421498	YORK	HH836E2S11	CTM48C5CFS1+JMET12CS2 N1		25,800	\$3,612
214395730	YORK	HH836E2S11	CTM48C5CFS1	TM9Y100C16MP11	25,800	\$3,612
214395801	YORK	HH836E2S11	CTM48C5CFS1	YP9C100C16MP13	25,800	\$3,612
214395800	YORK	HH836E2S11	CTM48C5CFS1	TP9C100C16MP13	25,800	\$3,612
214395874	YORK	HH824E2S11	CTM30B5ACS1+JME08B2SN 1		17,700	\$2,478
214606477	YORK	HH824E2S11	CTF30B5ACS1		18,800	\$2,632
214606581	YORK	HH860E2S11	CTF60C5CGS1		34,800	\$4,872

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216374499	YORK	HH836E2S11	CTM36C5CDS1	Y92E100C16SMPS1	28,000	\$3,920
214728350	YORK	HH836E2S11	CTU36B5XDS1+TXV	TM9E060B12MP12	27,400	\$3,836
214396099	YORK	HH836E2S11	CTF36B5CDS1	TM9E060B12MP12	27,400	\$3,836
215853301	YORK	HH836E2S11	CTM36C5CDS1+JME12C2SN1		26,800	\$3,752
214395721	YORK	HH836E2S11	CTF36C5CDS1	YPLC100C16MP13	28,200	\$3,948
214395720	YORK	HH836E2S11	CTF36C5CDS1	YPLC080C16MP13	28,200	\$3,948
214728354	YORK	HH836E2S11	CTU36B5XDS1+TXV	TM9E080B12MP12	28,200	\$3,948
214396209	YORK	HH836E2S11	CTF36B5CDS1	TM9E080B12MP12	28,200	\$3,948
215853295	YORK	HH836E2S11	JHE36B5CD2SS1		28,400	\$3,976
214807373	YORK	HH836E2S11	CTU36B5XDS1+JMC12B2SN1+TXV		27,800	\$3,892
214396110	YORK	HH836E2S11	CTF36B5CDS1+JMC12B2SN1		27,800	\$3,892
215853279	YORK	HH836E2S11	CTM36C5CDS1+JMET12CS2N1		27,800	\$3,892
215853277	YORK	HH836E2S11	CTM36C5CDS1+JMC16C2SN1		28,200	\$3,948
214396143	YORK	HH836E2S11	CTM48C5CFS1	TL9E100C20UH11	26,200	\$3,668
214396036	YORK	HH836E2S11	CTM48C5CFS1	YPLC100C16MP13	25,800	\$3,612
214396035	YORK	HH836E2S11	CTM48C5CFS1	YPLC080C16MP13	25,800	\$3,612
214395729	YORK	HH836E2S11	CTM48C5CFS1	TM9Y100C20MP11	26,600	\$3,724
214395798	YORK	HH836E2S11	CTM48C5CFS1	TM9E100C16MP12	26,000	\$3,640
215853275	YORK	HH836E2S11	CTU48C5XFS1+JMC16C2SN1+TXV		25,800	\$3,612
214395832	YORK	HH836E2S11	CTF48C5CFS1+JMC16C2SN1		25,800	\$3,612
214719787	YORK	HH836E2S11	CTU48C5XFS1+TXV	YP9C080C16MP13	26,000	\$3,640
214719789	YORK	HH836E2S11	CTU48C5XFS1+TXV	TP9C080C16MP13	26,000	\$3,640
214719788	YORK	HH836E2S11	CTU48C5XFS1+TXV	TM9V080C16MP12	26,000	\$3,640
214395726	YORK	HH836E2S11	CTF48C5CFS1	YP9C080C16MP13	26,000	\$3,640
214395725	YORK	HH836E2S11	CTF48C5CFS1	TP9C080C16MP13	26,000	\$3,640
214395724	YORK	HH836E2S11	CTF48C5CFS1	TM9V080C16MP12	26,000	\$3,640
214395615	YORK	HH836E2S11	JHC42C5CF2SS1		25,800	\$3,612
214606577	YORK	HH836E2S11	CTF48C5CFS1		26,000	\$3,640
214395981	YORK	HH860E2S11	CTF60C5CHS1	YP9C100C20MP13	37,000	\$5,180
214395980	YORK	HH860E2S11	CTF60C5CHS1	TP9C100C20MP13	37,000	\$5,180
214395979	YORK	HH860E2S11	CTF60C5CHS1	TM9V100C20MP12	37,000	\$5,180
214807666	YORK	HH860E2S11	CTU60C5XGS1+TXV	Y91E100C20SMPS1	33,800	\$4,732

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214609029	YORK	HH860E2S11	CTF60C5CGS1	Y91E100C20SMPS1	33,800	\$4,732
214396048	YORK	HH860E2S11	CTM60D5CGS1+JME18D2S N1		32,000	\$4,480
215853266	YORK	HH860E2S11	CTF60D5CJS1	Y91E120D20SMPS1	37,600	\$5,264
214609036	YORK	HH824E2S11	CTM30B5ACS1	Y91E060B12SMPS1	17,900	\$2,506
214609020	YORK	HH860E2S11	CTM60C5CGS1	Y91E080C20SMPS1	32,600	\$4,564
215853298	YORK	HH836E2S11	CTM36B5CDS1	Y91E060B12SMPS1	27,400	\$3,836
215853284	YORK	HH836E2S11	CTF36C5CDS1	Y91E100C20SMPS1	29,600	\$4,144
214609016	YORK	HH860E2S11	CTM60C5CHS1	Y91E080C20SMPS1	37,400	\$5,236
214609046	YORK	HH824E2S11	CTM36B5ADS1	Y91E060B12SMPS1	18,300	\$2,562
215853296	YORK	HH836E2S11	CTF36C5CDS1	Y91E100C16SMPS1	29,200	\$4,088
214609033	YORK	HH836E2S11	CTM48C5CFS1	Y91E080C20SMPS1	26,200	\$3,668
214650373	YORK	HH860E2S11	CTU60D5XHS1+TXV	Y91E120D20SMPS1	37,000	\$5,180
214609018	YORK	HH860E2S11	CTF60D5CHS1	Y91E120D20SMPS1	37,000	\$5,180
215853260	YORK	HH860E2S11	CTM60D5CJS1	Y91E120D20SMPS1	38,000	\$5,320
214609021	YORK	HH860E2S11	CTM60C5CGS1	Y91E100C20SMPS1	34,600	\$4,844
215853297	YORK	HH836E2S11	CTM36C5CDS1	Y91E100C16SMPS1	29,200	\$4,088
214719794	YORK	HH836E2S11	CTU48C5XFS1+TXV	Y91E080C20SMPS1	26,200	\$3,668
214609034	YORK	HH836E2S11	CTF48C5CFS1	Y91E080C20SMPS1	26,200	\$3,668
214609014	YORK	HH860E2S11	CTF60C5CHS1	Y91E080C20SMPS1	37,200	\$5,208
214650606	YORK	HH824E2S11	CTU36B5XDS1+TXV	Y91E060B12SMPS1	18,400	\$2,576
214609042	YORK	HH824E2S11	CTF36B5ADS1	Y91E060B12SMPS1	18,400	\$2,576
214650133	YORK	HH860E2S11	CTU60D5XGS1+TXV	Y91E120D20SMPS1	34,400	\$4,816
214609025	YORK	HH860E2S11	CTF60D5CGS1	Y91E120D20SMPS1	34,400	\$4,816
215853283	YORK	HH836E2S11	CTF36C5CDS1	Y91E080C20SMPS1	28,600	\$4,004
214609019	YORK	HH860E2S11	CTM60D5CHS1	Y91E120D20SMPS1	37,000	\$5,180
214650265	YORK	HH824E2S11	CTU30B5XCS1+TXV	Y91E060B12SMPS1	17,900	\$2,506
214609039	YORK	HH824E2S11	CTF30B5ACS1	Y91E060B12SMPS1	17,900	\$2,506
214807668	YORK	HH860E2S11	CTU60C5XGS1+TXV	Y91E080C16SMPS1	33,200	\$4,648
214609028	YORK	HH860E2S11	CTF60C5CGS1	Y91E080C16SMPS1	33,200	\$4,648
215853300	YORK	HH836E2S11	CTU36B5XDS1+TXV	Y91E060B12SMPS1	27,600	\$3,864
215853299	YORK	HH836E2S11	CTF36B5CDS1	Y91E060B12SMPS1	27,600	\$3,864
215853288	YORK	HH836E2S11	CTU36B5XDS1+TXV	Y91E080B12SMPS1	27,800	\$3,892
215853287	YORK	HH836E2S11	CTF36B5CDS1	Y91E080B12SMPS1	27,800	\$3,892
214609017	YORK	HH860E2S11	CTF60C5CHS1	Y91E100C20SMPS1	37,200	\$5,208
214650149	YORK	HH824E2S11	CTU30B5XCS1+TXV	Y91E080B12SMPS1	17,900	\$2,506
214609038	YORK	HH824E2S11	CTF30B5ACS1	Y91E080B12SMPS1	17,900	\$2,506
214609024	YORK	HH860E2S11	CTM60D5CGS1	Y91E120D20SMPS1	34,400	\$4,816

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215853289	YORK	HH836E2S11	CTM36C5CDS1	Y91E080C16SMPS1	27,600	\$3,864
214609015	YORK	HH860E2S11	CTM60C5CHS1	Y91E100C20SMPS1	37,200	\$5,208
214395386	YORK	HH836E2S11	JHC36C5CD2SS1		26,600	\$3,724
214395384	YORK	HH824E2S11	JHC24B5AC2SS1		18,400	\$2,576
214395828	YORK	HH836E2S11	JHE42C5CF2SS1		25,800	\$3,612
216013288	YORK	HH824E2S11	JHE36B5AD2SS1		18,200	\$2,548
214396066	YORK	HH824E2S11	JHC36B5AD2SS1		18,400	\$2,576
214395960	YORK	HH824E2S11	JHE30B5AD2SS1		17,700	\$2,478
216411166	YORK	HH824E2S11	CTF30A5ADS1	Y92E040A10SMPS1	17,200	\$2,408
216374540	YORK	HH860E2S11	CTM60D5CJS1	Y92E120D20SMPS1	38,500	\$5,390
216374539	YORK	HH860E2S11	CTF60D5CJS1	Y92E120D20SMPS1	39,000	\$5,460
216374537	YORK	HH860E2S11	CTU60D5XHS1+TXV	Y92E120D20SMPS1	38,000	\$5,320
216374536	YORK	HH860E2S11	CTF60D5CHS1	Y92E120D20SMPS1	38,000	\$5,320
216374533	YORK	HH860E2S11	CTM60C5CGS1	Y92E100C20SMPS1	35,400	\$4,956
216374532	YORK	HH860E2S11	CTM60C5CGS1	Y92E100C16SMPS1	34,000	\$4,760
216374531	YORK	HH860E2S11	CTU60C5XGS1+TXV	Y92E100C16SMPS1	34,000	\$4,760
216374530	YORK	HH860E2S11	CTF60C5CGS1	Y92E100C16SMPS1	34,000	\$4,760
216374529	YORK	HH860E2S11	CTM60D5CGS1	Y92E120D20SMPS1	33,400	\$4,676
216374528	YORK	HH860E2S11	CTU60D5XGS1+TXV	Y92E120D20SMPS1	33,200	\$4,648
216374527	YORK	HH860E2S11	CTF60D5CGS1	Y92E120D20SMPS1	33,200	\$4,648
216374526	YORK	HH860E2S11	CTM60C5CGS1	Y92E080C16SMPS1	33,200	\$4,648
216374525	YORK	HH860E2S11	CTU60C5XGS1+TXV	Y92E080C16SMPS1	33,200	\$4,648
216374524	YORK	HH860E2S11	CTF60C5CGS1	Y92E080C16SMPS1	33,200	\$4,648
216374523	YORK	HH860E2S11	CTU60C5XGS1+TXV	Y92E100C20SMPS1	33,800	\$4,732
216374522	YORK	HH860E2S11	CTF60C5CGS1	Y92E100C20SMPS1	33,800	\$4,732
216374521	YORK	HH824E2S11	CTM36B5ADS1	Y92E060B12SMPS1	18,600	\$2,604
216374520	YORK	HH824E2S11	CTU36B5XDS1+TXV	Y92E080B12SMPS1	17,600	\$2,464
216374519	YORK	HH824E2S11	CTF36B5ADS1	Y92E080B12SMPS1	17,600	\$2,464
216374518	YORK	HH824E2S11	CTU36B5XDS1+TXV	Y92E060B12SMPS1	18,600	\$2,604
216374517	YORK	HH824E2S11	CTF36B5ADS1	Y92E060B12SMPS1	18,600	\$2,604
216374516	YORK	HH824E2S11	CTM36B5ADS1	Y92E080B12SMPS1	17,500	\$2,450
216374515	YORK	HH836E2S11	CTM48C5CFS1	Y92E100C16SMPS1	26,000	\$3,640
216374514	YORK	HH836E2S11	CTM48C5CFS1	Y92E080C16SMPS1	29,000	\$4,060
216374513	YORK	HH836E2S11	CTU48C5XFS1+TXV	Y92E080C16SMPS1	29,000	\$4,060
216374512	YORK	HH836E2S11	CTF48C5CFS1	Y92E080C16SMPS1	29,000	\$4,060
216374511	YORK	HH836E2S11	CTU48C5XFS1+TXV	Y92E100C16SMPS1	27,600	\$3,864
216374510	YORK	HH836E2S11	CTF48C5CFS1	Y92E100C16SMPS1	27,600	\$3,864
216374498	YORK	HH824E2S11	CTM30B5ACS1	Y92E060B12SMPS1	18,000	\$2,520

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
216374497	YORK	HH824E2S11	CTU30B5XCS1+TXV	Y92E080B12SMPS1	17,900	\$2,506
216374496	YORK	HH824E2S11	CTF30B5ACS1	Y92E080B12SMPS1	17,900	\$2,506
216374495	YORK	HH824E2S11	CTM30B5ACS1	Y92E080B12SMPS1	17,900	\$2,506
216374494	YORK	HH824E2S11	CTU30B5XCS1+TXV	Y92E060B12SMPS1	17,900	\$2,506
216374493	YORK	HH824E2S11	CTF30B5ACS1	Y92E060B12SMPS1	17,900	\$2,506
213296649	YORK	HMH72B341	XAFB36DBC1	Y92E060B12SMPS1	26,000	\$3,640
213296697	YORK	HMH72B341	XAFC36DBC1	Y92E100C16SMPS1	26,600	\$3,724
213296518	YORK	HMH72B341	XAHC36DBC1	Y92E100C16SMPS1	25,800	\$3,612
213296564	YORK	HMH72B341	XAFB36DBC1	Y92E080B12SMPS1	25,800	\$3,612
213296610	YORK	HMH72B341	XAFB36DBC1	Y92E040A10SMPS1	25,800	\$3,612
213296608	YORK	HMH72B341	XAFC36DBC1	Y92E080B12SMPS1	25,800	\$3,612
213296699	YORK	HMH72B341	XAFC36DBC1	Y92E060B12SMPS1	26,000	\$3,640
215912267	YORK	HH824E2S11	CTM36B5ADS1	TM9E080B12MP12	18,500	\$2,590
216010727	YORK	HH824E2S11	CTM36B5ADS1	TL9E060B12UH11	18,600	\$2,604
216010724	YORK	HH824E2S11	CTM36B5ADS1+JMC12B2S N1		18,300	\$2,562
216010726	YORK	HH824E2S11	CTM36B5ADS1+JME08B2SN 1		17,600	\$2,464
216010725	YORK	HH824E2S11	CTM36B5ADS1+JME12B2SN 1		18,100	\$2,534
215912263	YORK	HH824E2S11	CTM36B5ADS1	TM9Y080B12MP11	18,200	\$2,548
215912269	YORK	HH824E2S11	CTM36B5ADS1	TM9E060B12MP12	18,000	\$2,520
215912268	YORK	HH824E2S11	CTM36B5ADS1	TM9Y060B12MP11	17,600	\$2,464
215912265	YORK	HH860E2S11	JSE48D5CG2SS1		33,600	\$4,704
215912264	YORK	HH860E2S11	JSC48D5CG2SS1		33,600	\$4,704
214807367	YORK	HH824E2S11	CTM36B5ADS1	YP9C060B12MP13	17,100	\$2,394
214807366	YORK	HH824E2S11	CTM36B5ADS1	TP9C060B12MP13	17,100	\$2,394
214810256	YORK	HH824E2S11	CTM36B5ADS1	TM9V060B12MP12	17,100	\$2,394
214650178	YORK	HH824E2S11	CTU36B5XDS1+TXV	Y91E080B12SMPS1	18,300	\$2,562
214609043	YORK	HH824E2S11	CTF36B5ADS1	Y91E080B12SMPS1	18,300	\$2,562
214650444	YORK	HH824E2S11	CTU36B5XDS1+TXV	YP9C060B12MP13	18,500	\$2,590
214650439	YORK	HH824E2S11	CTU36B5XDS1+TXV	TP9C060B12MP13	18,500	\$2,590
214395765	YORK	HH824E2S11	CTF30A5ADS1	TM9E060A10MP12	17,700	\$2,478
214807370	YORK	HH824E2S11	CTM36B5ADS1	YP9C080B12MP13	18,100	\$2,534
214807369	YORK	HH824E2S11	CTM36B5ADS1	TP9C080B12MP13	18,100	\$2,534
214810255	YORK	HH824E2S11	CTM36B5ADS1	TM9V080B12MP12	18,100	\$2,534
214395658	YORK	HH824E2S11	CTF30A5ADS1	TM9E040A10MP12	17,600	\$2,464
214650369	YORK	HH824E2S11	CTU36B5XDS1+TXV	YP9C080B12MP13	18,100	\$2,534

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214650365	YORK	HH824E2S11	CTU36B5XDS1+TXV	TP9C080B12MP13	18,100	\$2,534
214650360	YORK	HH824E2S11	CTU36B5XDS1+TXV	TM9V080B12MP12	18,100	\$2,534
214395872	YORK	HH824E2S11	CTF36B5ADS1	YP9C080B12MP13	18,100	\$2,534
214395871	YORK	HH824E2S11	CTF36B5ADS1	TP9C080B12MP13	18,100	\$2,534
214395870	YORK	HH824E2S11	CTF36B5ADS1	TM9V080B12MP12	18,100	\$2,534
214650281	YORK	HH824E2S11	CTU36B5XDS1+TXV	TM9E080B12MP12	18,500	\$2,590
214396168	YORK	HH824E2S11	CTF36B5ADS1	TM9E080B12MP12	18,500	\$2,590
214650477	YORK	HH824E2S11	CTU36B5XDS1+TXV	TM9Y080B12MP11	18,300	\$2,562
214395968	YORK	HH824E2S11	CTF36B5ADS1	TM9Y080B12MP11	18,300	\$2,562
214650435	YORK	HH824E2S11	CTU36B5XDS1+TXV	TM9V060B12MP12	18,500	\$2,590
214395770	YORK	HH824E2S11	CTF36B5ADS1	YP9C060B12MP13	18,500	\$2,590
214395769	YORK	HH824E2S11	CTF36B5ADS1	TP9C060B12MP13	18,500	\$2,590
214395768	YORK	HH824E2S11	CTF36B5ADS1	TM9V060B12MP12	18,500	\$2,590
214395660	YORK	HH824E2S11	CTF30A5ADS1	TM9V040A10MP12	17,300	\$2,422
214807365	YORK	HH824E2S11	CTM36B5ADS1	YPLC080B12MP13	17,200	\$2,408
214609041	YORK	HH824E2S11	CTF30A5ADS1	Y91E026A08SMPS1	17,700	\$2,478
214395964	YORK	HH824E2S11	CTF30A5ADS1	TM9Y040A10MP11	17,600	\$2,464
214650211	YORK	HH824E2S11	CTU36B5XDS1+TXV	TM9Y060B12MP11	18,100	\$2,534
214396068	YORK	HH824E2S11	CTF36B5ADS1	TM9Y060B12MP11	18,100	\$2,534
214807363	YORK	HH824E2S11	CTU36B5XDS1+JME12B2SN 1+TXV		18,200	\$2,548
214395764	YORK	HH824E2S11	CTF36B5ADS1+JME12B2SN 1		18,200	\$2,548
214650145	YORK	HH824E2S11	CTU36B5XDS1+TXV	TL9E060B12UH11	18,600	\$2,604
214396067	YORK	HH824E2S11	CTF36B5ADS1	TL9E060B12UH11	18,600	\$2,604
214807360	YORK	HH824E2S11	CTU36B5XDS1+JMC12B2SN 1+TXV		18,200	\$2,548
214395867	YORK	HH824E2S11	CTF36B5ADS1+JMC12B2SN 1		18,200	\$2,548
214807359	YORK	HH824E2S11	CTU36B5XDS1+JMT12BC2 N1+TXV		18,200	\$2,548
214395763	YORK	HH824E2S11	CTF36B5ADS1+JMT12BC2 N1		18,200	\$2,548
214807358	YORK	HH824E2S11	CTU36B5XDS1+JMET08BS2 N1+TXV		17,400	\$2,436
214396165	YORK	HH824E2S11	CTF36B5ADS1+JMET08BS2 N1		17,400	\$2,436
214807362	YORK	HH824E2S11	CTU36B5XDS1+JMET12BS2 N1+TXV		17,700	\$2,478

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214395659	YORK	HH824E2S11	CTF36B5ADS1+JMET12BS2 N1		17,700	\$2,478
214807361	YORK	HH824E2S11	CTU36B5XDS1+JME08B2SN 1+TXV		17,600	\$2,464
214396166	YORK	HH824E2S11	CTF36B5ADS1+JME08B2SN 1		17,600	\$2,464
214609040	YORK	HH824E2S11	CTF30A5ADS1	Y91E040A10SMPS1	17,200	\$2,408
214650174	YORK	HH824E2S11	CTU36B5XDS1+TXV	YPLC080B12MP13	18,200	\$2,548
214395963	YORK	HH824E2S11	CTF36B5ADS1	YPLC080B12MP13	18,200	\$2,548
214396170	YORK	HH824E2S11	CTF30A5ADS1	TM9E026A08MP12	17,900	\$2,506
214609045	YORK	HH824E2S11	CTF30A5ADS1	Y91E060A10SMPS1	18,200	\$2,548
214609044	YORK	HH824E2S11	CTM36B5ADS1	Y91E080B12SMPS1	18,300	\$2,562
214650410	YORK	HH824E2S11	CTU36B5XDS1+TXV	TM9E060B12MP12	18,900	\$2,646
214396071	YORK	HH824E2S11	CTF36B5ADS1	TM9E060B12MP12	18,900	\$2,646
214395933	YORK	HH860E2S11	CTM60C5CGS1	TM9Y080C16MP11	33,000	\$4,620
214719771	YORK	HH860E2S11	CTU60C5XGS1+TXV	TM9Y100C16MP11	33,000	\$4,620
214395632	YORK	HH860E2S11	CTF60C5CGS1	TM9Y100C16MP11	33,000	\$4,620
214396147	YORK	HH860E2S11	JHC48D5CG2SS1		33,600	\$4,704
214807610	YORK	HH860E2S11	CTU60C5XGS1+JMET16CS2 N1+TXV		34,400	\$4,816
214396148	YORK	HH860E2S11	CTF60C5CGS1+JMET16CS2 N1		34,400	\$4,816
214395944	YORK	HH860E2S11	CTM60C5CGS1+JME16C2S N1		32,200	\$4,508
214807665	YORK	HH860E2S11	CTU60C5XGS1+TXV	TL9E100C20UH11	32,600	\$4,564
214396164	YORK	HH860E2S11	CTF60C5CGS1	TL9E100C20UH11	32,600	\$4,564
214807667	YORK	HH860E2S11	CTU60C5XGS1+TXV	Y91E080C20SMPS1	32,600	\$4,564
214609022	YORK	HH860E2S11	CTF60C5CGS1	Y91E080C20SMPS1	32,600	\$4,564
214719765	YORK	HH860E2S11	CTU60C5XGS1+TXV	TM9E080C16MP12	34,200	\$4,788
214395862	YORK	HH860E2S11	CTF60C5CGS1	TM9E080C16MP12	34,200	\$4,788
214395854	YORK	HH860E2S11	CTM60C5CGS1	TM9Y100C20MP11	35,000	\$4,900
214396158	YORK	HH860E2S11	CTM60C5CGS1	TM9E080C16MP12	34,200	\$4,788
214395756	YORK	HH860E2S11	CTM60C5CGS1	YPLC120C20MP13	33,000	\$4,620
214395755	YORK	HH860E2S11	CTM60C5CGS1	YPLC100C20MP13	33,000	\$4,620
214807647	YORK	HH860E2S11	CTU60C5XGS1+JMC16C2S N1+TXV		33,600	\$4,704
214396046	YORK	HH860E2S11	CTF60C5CGS1+JMC16C2S N1		33,600	\$4,704
214395945	YORK	HH860E2S11	CTM60C5CGS1	TM9E100C20MP12	33,200	\$4,648

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214807641	YORK	HH860E2S11	CTU60C5XGS1+JME16C2S N1+TXV		32,200	\$4,508
214395853	YORK	HH860E2S11	CTF60C5CGS1+JME16C2SN 1		32,200	\$4,508
214395860	YORK	HH860E2S11	CTM60D5CGS1+JMTV20DC 2N1		33,200	\$4,648
214807640	YORK	HH860E2S11	CTU60D5XGS1+JMC20D2S N1+TXV		34,600	\$4,844
214395745	YORK	HH860E2S11	CTF60D5CGS1+JMC20D2S N1		34,600	\$4,844
214395740	YORK	HH860E2S11	CTM60C5CGS1	YP9C080C16MP13	33,800	\$4,732
214395739	YORK	HH860E2S11	CTM60C5CGS1	TP9C080C16MP13	33,800	\$4,732
214395738	YORK	HH860E2S11	CTM60C5CGS1	TM9V080C16MP12	33,800	\$4,732
214396041	YORK	HH860E2S11	CTM60C5CGS1	TM9Y100C16MP11	33,000	\$4,620
214719798	YORK	HH860E2S11	CTU60C5XGS1+TXV	TM9Y080C16MP11	33,000	\$4,620
214396146	YORK	HH860E2S11	CTF60C5CGS1	TM9Y080C16MP11	33,000	\$4,620
214396049	YORK	HH860E2S11	CTM60C5CGS1	TL9E080C16UH11	34,400	\$4,816
214719807	YORK	HH860E2S11	CTU60C5XGS1+TXV	TM9E100C16MP12	34,400	\$4,816
214395950	YORK	HH860E2S11	CTF60C5CGS1	TM9E100C16MP12	34,400	\$4,816
214719821	YORK	HH860E2S11	CTU60C5XGS1+TXV	YP9C100C20MP13	33,400	\$4,676
214719822	YORK	HH860E2S11	CTU60C5XGS1+TXV	TP9C100C20MP13	33,400	\$4,676
214719820	YORK	HH860E2S11	CTU60C5XGS1+TXV	TM9V100C20MP12	33,400	\$4,676
214395953	YORK	HH860E2S11	CTF60C5CGS1	YP9C100C20MP13	33,400	\$4,676
214395952	YORK	HH860E2S11	CTF60C5CGS1	TP9C100C20MP13	33,400	\$4,676
214395951	YORK	HH860E2S11	CTF60C5CGS1	TM9V100C20MP12	33,400	\$4,676
214395650	YORK	HH860E2S11	CTM60C5CGS1	YP9C100C20MP13	32,800	\$4,592
214395649	YORK	HH860E2S11	CTM60C5CGS1	TP9C100C20MP13	32,800	\$4,592
214395648	YORK	HH860E2S11	CTM60C5CGS1	TM9V100C20MP12	32,800	\$4,592
214396157	YORK	HH860E2S11	CTM60C5CGS1	TM9E100C16MP12	34,400	\$4,816
214395657	YORK	HH860E2S11	CTM60C5CGS1	TL9E100C20UH11	32,600	\$4,564
214395633	YORK	HH860E2S11	JHE48C5CG2SS1		32,200	\$4,508
214719823	YORK	HH860E2S11	CTU60C5XGS1+TXV	Y91E100C16SMPS1	34,200	\$4,788
214609027	YORK	HH860E2S11	CTF60C5CGS1	Y91E100C16SMPS1	34,200	\$4,788
214719745	YORK	HH860E2S11	CTU60C5XGS1+TXV	YP9C080C16MP13	32,600	\$4,564
214719746	YORK	HH860E2S11	CTU60C5XGS1+TXV	TP9C080C16MP13	32,600	\$4,564
214719744	YORK	HH860E2S11	CTU60C5XGS1+TXV	TM9V080C16MP12	32,600	\$4,564
214395655	YORK	HH860E2S11	CTF60C5CGS1	YP9C080C16MP13	32,600	\$4,564
214395654	YORK	HH860E2S11	CTF60C5CGS1	TP9C080C16MP13	32,600	\$4,564

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214395653	YORK	HH860E2S11	CTF60C5CGS1	TM9V080C16MP12	32,600	\$4,564
214396064	YORK	HH860E2S11	CTM60C5CGS1	YPLC100C16MP13	32,800	\$4,592
214396063	YORK	HH860E2S11	CTM60C5CGS1	YPLC080C16MP13	32,800	\$4,592
214395934	YORK	HH860E2S11	JHE48D5CG2SS1		33,200	\$4,648
214807626	YORK	HH860E2S11	CTU60C5XGS1+TXV	YPLC100C16MP13	32,200	\$4,508
214807625	YORK	HH860E2S11	CTU60C5XGS1+TXV	YPLC080C16MP13	32,200	\$4,508
214395941	YORK	HH860E2S11	CTF60C5CGS1	YPLC100C16MP13	32,200	\$4,508
214395940	YORK	HH860E2S11	CTF60C5CGS1	YPLC080C16MP13	32,200	\$4,508
214396053	YORK	HH860E2S11	CTM60D5CGS1+JMC20D2S N1		34,000	\$4,760
214395757	YORK	HH860E2S11	CTM60C5CGS1+JMTV17CC 2N1		33,600	\$4,704
214807646	YORK	HH860E2S11	CTU60D5XGS1+JMET18DS2 N1+TXV		34,200	\$4,788
214395742	YORK	HH860E2S11	CTF60D5CGS1+JMET18DS2 N1		34,200	\$4,788
214421501	YORK	HH860E2S11	CTM60D5CGS1+JMET18DS 2N1		34,000	\$4,760
214719815	YORK	HH860E2S11	CTU60C5XGS1+TXV	TM9Y100C20MP11	33,600	\$4,704
214395841	YORK	HH860E2S11	CTF60C5CGS1	TM9Y100C20MP11	33,600	\$4,704
214421500	YORK	HH860E2S11	CTM60C5CGS1+JMET16CS 2N1		34,400	\$4,816
214807611	YORK	HH860E2S11	CTU60C5XGS1+JMTV17CC2 N1+TXV		31,800	\$4,452
214395741	YORK	HH860E2S11	CTF60C5CGS1+JMTV17CC2 N1		31,800	\$4,452
214807612	YORK	HH860E2S11	CTU60C5XGS1+JMC17C2S N1+TXV		31,800	\$4,452
214395844	YORK	HH860E2S11	CTF60C5CGS1+JMC17C2S N1		31,800	\$4,452
214650100	YORK	HH860E2S11	CTU60D5XGS1+TXV	TM9E120D20MP12	35,600	\$4,984
214395761	YORK	HH860E2S11	CTF60D5CGS1	TM9E120D20MP12	35,600	\$4,984
214395859	YORK	HH860E2S11	CTM60C5CGS1	YP9C100C16MP13	32,200	\$4,508
214395858	YORK	HH860E2S11	CTM60C5CGS1	TP9C100C16MP13	32,200	\$4,508
214395857	YORK	HH860E2S11	CTM60C5CGS1	TM9V100C16MP12	32,200	\$4,508
214395861	YORK	HH860E2S11	CTM60C5CGS1+JMC17C2S N1		33,000	\$4,620
214807638	YORK	HH860E2S11	CTU60C5XGS1+JMTV16CC2 N1+TXV		33,600	\$4,704

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
214396150	YORK	HH860E2S11	CTF60C5CGS1+JMV16CC2 N1		33,600	\$4,704
214395943	YORK	HH860E2S11	CTM60C5CGS1+JMC16C2S N1		33,600	\$4,704
214395852	YORK	HH860E2S11	CTM60C5CGS1+JMV16CC 2N1		32,400	\$4,536
216013291	YORK	HH824E2S11	CTM36B5ADS1+JMV12BC2 N1		18,300	\$2,562
216013290	YORK	HH824E2S11	CTM36B5ADS1+JMET12BS2 N1		17,600	\$2,464
216013289	YORK	HH824E2S11	CTM36B5ADS1+JMET08BS2 N1		17,400	\$2,436
211377679	YORK	HMH72B341	XAUB36DXXN1+TXV	YP9C080B12MP13	25,800	\$3,612
211377667	YORK	HMH72B341	XAUB36DXXN1+TXV	TM9V080B12MP12	25,800	\$3,612
211377658	YORK	HMH72B341	XAFB36DXXN1+TXV	TP9C080B12MP13	25,800	\$3,612
211377655	YORK	HMH72B341	XAFB36DXXN1+TXV	TM9V080B12MP12	25,800	\$3,612
211377673	YORK	HMH72B341	XAUB36DXXN1+TXV	TP9C080B12MP13	25,800	\$3,612
211377661	YORK	HMH72B341	XAFB36DXXN1+TXV	YP9C080B12MP13	25,800	\$3,612
211377774	YORK	HMH72B341	XAFB36DXXN1+TXV	YP9C060B12MP13	25,600	\$3,584
211377768	YORK	HMH72B341	XAFB36DXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211377438	YORK	HMH72B341	XAUB36DXXN1+TXV	TM9Y060B12MP11	25,600	\$3,584
211377780	YORK	HMH72B341	XAUB36DXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211377771	YORK	HMH72B341	XAFB36DXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211377396	YORK	HMH72B341	XAUB36DXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211377786	YORK	HMH72B341	XAUB36DXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211377391	YORK	HMH72B341	XAFB36DXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211377792	YORK	HMH72B341	XAUB36DXXN1+TXV	YP9C060B12MP13	25,600	\$3,584
211377432	YORK	HMH72B341	XAFB36DXXN1+TXV	TM9Y060B12MP11	25,600	\$3,584
10309025	YORK	YZV48B21	CM50DE3A1+MVC20DN21		42,500	\$5,950
10525230	YORK	YZV48B21	CM50DE3A1	TP9C120D20MP13	44,000	\$6,160
10525210	YORK	YZV48B21	CM50CE3A1	TM9V100C20MP12	44,000	\$6,160
10524907	YORK	YZV36B21	CM38CE2A1	YP9C080C16MP13	31,800	\$4,452
10524903	YORK	YZV36B21	CM38CE2A1	TP9C080C16MP13	31,800	\$4,452
10524900	YORK	YZV36B21	CM38CE2A1	TM9V100C16MP12	31,600	\$4,424
10309021	YORK	YZV36B21	CM38CE2A1+MVC16CN21		33,400	\$4,676
10524904	YORK	YZV36B21	CM38CE2A1	TP9C100C16MP13	31,600	\$4,424
10525231	YORK	YZV48B21	CM50DE3A1	YP9C120D20MP13	44,000	\$6,160
10525224	YORK	YZV48B21	CM50CE3A1	YP9C100C20MP13	44,000	\$6,160
10525217	YORK	YZV48B21	CM50CE3A1	TP9C100C20MP13	44,000	\$6,160

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
10524899	YORK	YZV36B21	CM38CE2A1	TM9V080C16MP12	31,800	\$4,452
10309024	YORK	YZV48B21	CM50CE3A1+MVC16CN21		43,500	\$6,090
10525229	YORK	YZV48B21	CM50DE3A1	TM9V120D20MP12	44,000	\$6,160
10524908	YORK	YZV36B21	CM38CE2A1	YP9C100C16MP13	31,600	\$4,424
10309022	YORK	YZV48B21	AVV50CE321		43,500	\$6,090
211377664	YORK	HMH72B341	XAFB36DBCN1	TM9V080B12MP12	25,000	\$3,500
211377676	YORK	HMH72B341	XAFB36DBCN1	YP9C080B12MP13	25,000	\$3,500
211377670	YORK	HMH72B341	XAFB36DBCN1	TP9C080B12MP13	25,000	\$3,500
211380152	YORK	HMH72B341	XAFC48FBCN1	TL9E060B12UH11	25,800	\$3,612
211380125	YORK	HMH72B341	XAHC48FBCN1	TL9E080C16UH11	25,200	\$3,528
211380116	YORK	HMH72B341	XAHD48FXXN1+TXV	TL9E080C16UH11	25,200	\$3,528
211380113	YORK	HMH72B341	XAUC48FXXN1+TXV	TL9E100C20UH11	25,400	\$3,556
211380097	YORK	HMH72B341	XAHC48FXXN1+TXV	TL9E100C20UH11	25,000	\$3,500
211380091	YORK	HMH72B341	XAHD48FXXN1+TXV	TL9E100C20UH11	25,000	\$3,500
211379493	YORK	HMH72B341	XAFC48FBCN1	TM9E060B12MP12	25,800	\$3,612
211379490	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211379484	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9E060B12MP12	25,200	\$3,528
211379466	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9E080C16MP12	26,000	\$3,640
211379460	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9E080C16MP12	26,000	\$3,640
211379457	YORK	HMH72B341	XAFD48FBCN1	TM9E080C16MP12	26,000	\$3,640
211379454	YORK	HMH72B341	XAFD48FXXN1+TXV	TM9E080C16MP12	26,000	\$3,640
211379451	YORK	HMH72B341	XAHC48FBCN1	TM9E080C16MP12	25,600	\$3,584
211379443	YORK	HMH72B341	XAHD48FXXN1+TXV	TM9E080C16MP12	25,600	\$3,584
211379429	YORK	HMH72B341	XAFD48FXXN1+TXV	TM9E100C16MP12	25,400	\$3,556
211379426	YORK	HMH72B341	XAHC48FBCN1	TM9E100C16MP12	24,800	\$3,472
211379412	YORK	HMH72B341	XAFC48FBCN1	YP9C060B12MP13	25,600	\$3,584
211379404	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211379396	YORK	HMH72B341	XAFC48FXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211379384	YORK	HMH72B341	XAHC48FBCN1	TM9V060B12MP12	25,200	\$3,528
211379381	YORK	HMH72B341	XAHC48FXXN1+TXV	YP9C060B12MP13	25,200	\$3,528
211379339	YORK	HMH72B341	XAHC48FBCN1	TM9V080B12MP12	25,200	\$3,528
211379324	YORK	HMH72B341	XAFC48FBCN1	YP9C080C16MP13	25,400	\$3,556
211379315	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211379309	YORK	HMH72B341	XAFC48FXXN1+TXV	YP9C080C16MP13	25,400	\$3,556
211379303	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211379297	YORK	HMH72B341	XAFD48FBCN1	TP9C080C16MP13	25,400	\$3,556
211379294	YORK	HMH72B341	XAFD48FBCN1	TM9V080C16MP12	25,400	\$3,556
211379291	YORK	HMH72B341	XAFD48FXXN1+TXV	YP9C080C16MP13	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211379273	YORK	HMH72B341	XAHC48FXXN1+TXV	YP9C080C16MP13	24,800	\$3,472
211379267	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9V080C16MP12	24,800	\$3,472
211379255	YORK	HMH72B341	XAHD48FXXN1+TXV	YP9C080C16MP13	25,000	\$3,500
211379243	YORK	HMH72B341	XAFC48FBCN1	YP9C100C16MP13	25,400	\$3,556
211379238	YORK	HMH72B341	XAFC48FBCN1	TP9C100C16MP13	25,400	\$3,556
211379232	YORK	HMH72B341	XAFC48FBCN1	TM9V100C16MP12	25,400	\$3,556
211379229	YORK	HMH72B341	XAFC48FXXN1+TXV	YP9C100C16MP13	25,400	\$3,556
211379220	YORK	HMH72B341	XAFC48FBCN1	TP9C100C16MP13	25,400	\$3,556
211379203	YORK	HMH72B341	XAHC48FBCN1	TP9C100C16MP13	24,800	\$3,472
211379197	YORK	HMH72B341	XAHC48FXXN1+TXV	YP9C100C16MP13	24,800	\$3,472
211379188	YORK	HMH72B341	XAHD48FBCN1	YP9C100C16MP13	24,800	\$3,472
211379185	YORK	HMH72B341	XAHD48FBCN1	TP9C100C16MP13	24,800	\$3,472
211379173	YORK	HMH72B341	XAHD48FXXN1+TXV	TM9V100C16MP12	24,800	\$3,472
211379167	YORK	HMH72B341	XAFC48FBCN1	YP9C100C20MP13	25,800	\$3,612
211379161	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9V100C20MP12	25,800	\$3,612
211379157	YORK	HMH72B341	XAFC48FBCN1	TM9V100C20MP12	25,800	\$3,612
211379151	YORK	HMH72B341	XAFC48FXXN1+TXV	TP9C100C20MP13	25,800	\$3,612
211379139	YORK	HMH72B341	XAFC48FBCN1	TM9V100C20MP12	25,600	\$3,584
211379137	YORK	HMH72B341	XAFC48FXXN1+TXV	TP9C100C20MP13	25,600	\$3,584
211379122	YORK	HMH72B341	XAHC48FXXN1+TXV	YP9C100C20MP13	25,000	\$3,500
211379113	YORK	HMH72B341	XAHD48FBCN1	YP9C100C20MP13	25,200	\$3,528
211379098	YORK	HMH72B341	XAHD48FXXN1+TXV	TM9V100C20MP12	25,200	\$3,528
211379095	YORK	HMH72B341	XAFC48FBCN1	YP9C120D20MP13	25,400	\$3,556
211379086	YORK	HMH72B341	XAFC48FXXN1+TXV	YP9C120D20MP13	25,400	\$3,556
211379083	YORK	HMH72B341	XAFC48FXXN1+TXV	TP9C120D20MP13	25,400	\$3,556
211379077	YORK	HMH72B341	XAHD48FBCN1	YP9C120D20MP13	24,800	\$3,472
211379068	YORK	HMH72B341	XAHD48FXXN1+TXV	YP9C120D20MP13	24,800	\$3,472
211379065	YORK	HMH72B341	XAHD48FXXN1+TXV	TP9C120D20MP13	24,800	\$3,472
211379033	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9Y080C16MP11	25,800	\$3,612
211379024	YORK	HMH72B341	XAFC48FBCN1	TM9Y080C16MP11	25,400	\$3,556
211379013	YORK	HMH72B341	XAHD48FBCN1	TM9Y080C16MP11	25,000	\$3,500
211378991	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9Y100C16MP11	25,200	\$3,528
211378988	YORK	HMH72B341	XAHD48FBCN1	TM9Y100C16MP11	25,200	\$3,528
211378981	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9Y120D20MP11	25,400	\$3,556
211378975	YORK	HMH72B341	XAHD48FXXN1+TXV	TM9Y120D20MP11	25,000	\$3,500
211378932	YORK	HMH72B341	JHVT36DBCC2N1		25,400	\$3,556
211378861	YORK	HMH72B341	XAFC36DBCN1	TL9E060B12UH11	25,600	\$3,584
211378847	YORK	HMH72B341	XAHC36DXXN1+TXV	TL9E060B12UH11	24,400	\$3,416

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211378841	YORK	HMH72B341	XAFC36DBCN1	TL9E080C16UH11	25,800	\$3,612
211378832	YORK	HMH72B341	XAHC36DBCN1	TL9E080C16UH11	25,400	\$3,556
211378822	YORK	HMH72B341	XAFC36DXXN1+TXV	TL9E100C20UH11	26,200	\$3,668
211378368	YORK	HMH72B341	XAHB36DXXN1+TXV	YPLC060A12MP13	25,200	\$3,528
211377948	YORK	HMH72B341	XAHB36DXXN1+TXV	TM9E060A10MP12	24,600	\$3,444
211377917	YORK	HMH72B341	XAHB36DXXN1+TXV	TM9E060B12MP12	25,200	\$3,528
211377900	YORK	HMH72B341	XAUB36DXXN1+TXV	TM9E080B12MP12	25,400	\$3,556
211377888	YORK	HMH72B341	XAFC36DBCN1	TM9E080B12MP12	25,800	\$3,612
211377884	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9E080B12MP12	25,800	\$3,612
211377862	YORK	HMH72B341	XAFC36DBCN1	TM9E080C16MP12	25,200	\$3,528
211377858	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9E080C16MP12	25,600	\$3,584
211377852	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9E100C16MP12	25,200	\$3,528
211377840	YORK	HMH72B341	XAHC36DBCN1	TM9E100C20MP12	25,000	\$3,500
211377816	YORK	HMH72B341	XAHB36DBCN1	TM9V040A10MP12	24,800	\$3,472
211377789	YORK	HMH72B341	XAFB36DBCN1	YP9C060B12MP13	25,400	\$3,556
211377783	YORK	HMH72B341	XAFB36DBCN1	TP9C060B12MP13	25,400	\$3,556
211377754	YORK	HMH72B341	XAFC36DXXN1+TXV	YP9C060B12MP13	25,600	\$3,584
211377734	YORK	HMH72B341	XAHB36DBCN1	TP9C060B12MP13	25,000	\$3,500
211377722	YORK	HMH72B341	XAHB36DXXN1+TXV	TM9V060B12MP12	25,000	\$3,500
211377707	YORK	HMH72B341	XAHC36DBCN1	TP9C060B12MP13	25,200	\$3,528
211377704	YORK	HMH72B341	XAHC36DBCN1	TM9V060B12MP12	25,200	\$3,528
211377631	YORK	HMH72B341	XAFC36DXXN1+TXV	TP9C080B12MP13	25,800	\$3,612
211377587	YORK	HMH72B341	XAHC36DBCN1	TP9C080B12MP13	25,000	\$3,500
211377584	YORK	HMH72B341	XAHC36DBCN1	TM9V080B12MP12	25,000	\$3,500
211377581	YORK	HMH72B341	XAHC36DXXN1+TXV	YP9C080B12MP13	25,000	\$3,500
211377524	YORK	HMH72B341	XAFC36DBCN1	YP9C100C16MP13	25,400	\$3,556
211377518	YORK	HMH72B341	XAFC36DBCN1	TM9V100C16MP12	25,400	\$3,556
211377515	YORK	HMH72B341	XAFC36DXXN1+TXV	YP9C100C16MP13	25,400	\$3,556
211377488	YORK	HMH72B341	XAHC36DXXN1+TXV	YP9C100C16MP13	25,000	\$3,500
211377468	YORK	HMH72B341	XAFC36DBCN1	TP9C100C20MP13	26,000	\$3,640
211377459	YORK	HMH72B341	XAFC36DXXN1+TXV	TP9C100C20MP13	26,000	\$3,640
211377456	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9V100C20MP12	26,000	\$3,640
211377441	YORK	HMH72B341	XAFB30CXXN1+TXV	TM9Y060B12MP11	26,600	\$3,724
211377405	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9Y060B12MP11	25,200	\$3,528
211377381	YORK	HMH72B341	XAHB36DXXN1+TXV	TM9Y080B12MP11	24,800	\$3,472
211377375	YORK	HMH72B341	XAHC36DBCN1	TM9Y080B12MP11	25,400	\$3,556
211377340	YORK	HMH72B341	XAHC36DBCN1	TM9Y100C16MP11	25,400	\$3,556
211377337	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9Y100C16MP11	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211212440	YORK	YZV60B21	JHVVC60HE4C2N1+CC		48,000	\$6,720
211207042	YORK	YZV48B21	XAMC48HE3N1+CC	YPLC100C20MP13	41,500	\$5,810
211207034	YORK	YZV48B21	XAMC48HE3N1+CC	TM9V080C16MP12	41,500	\$5,810
211207025	YORK	YZV60B21	XAMC60HE4N1+CC	TM9V100C20MP12	47,000	\$6,580
211207021	YORK	YZV36B21	XAMB36DE2N1+CC	YP9C080B12MP13	34,600	\$4,844
211207017	YORK	YZV36B21	XAMC36DE2N1+CC	TP9C080C16MP13	34,400	\$4,816
211207009	YORK	YZV24B21	XAMB24DE1N1+CC	YP9C060B12MP13	23,200	\$3,248
211010176	YORK	YZV24B21	JHVVB24DE1C2N1+CC		22,800	\$3,192
211010175	YORK	YZV48B21	JHVVC48HE3C2N1+CC		43,500	\$6,090
211377393	YORK	HMH72B341	XAFB36DBCN1	TM9Y080B12MP11	25,200	\$3,528
211380222	YORK	HMH72B341	JHVTC42FBCC2N1		25,000	\$3,500
211380216	YORK	HMH72B341	XAFC48FBCN1+JMET12CS2 N1		25,400	\$3,556
211380214	YORK	HMH72B341	XAFC48FXXN1+JMET12CS2 N1+TXV		25,400	\$3,556
211380211	YORK	HMH72B341	XAHC48FBCN1+JMET12CS2 N1		24,800	\$3,472
211380155	YORK	HMH72B341	XAUC48FXXN1+TXV	TL9E060B12UH11	25,800	\$3,612
211380149	YORK	HMH72B341	XAFC48FXXN1+TXV	TL9E060B12UH11	25,800	\$3,612
211380146	YORK	HMH72B341	XAHC48FBCN1	TL9E060B12UH11	25,200	\$3,528
211380137	YORK	HMH72B341	XAFC48FBCN1	TL9E080C16UH11	25,800	\$3,612
211380122	YORK	HMH72B341	XAHC48FXXN1+TXV	TL9E080C16UH11	25,200	\$3,528
211380111	YORK	HMH72B341	XAFC48FBCN1	TL9E100C20UH11	25,400	\$3,556
211380105	YORK	HMH72B341	XAFD48FBCN1	TL9E100C20UH11	25,400	\$3,556
211380102	YORK	HMH72B341	XAFD48FXXN1+TXV	TL9E100C20UH11	25,400	\$3,556
211380099	YORK	HMH72B341	XAHC48FBCN1	TL9E100C20UH11	25,000	\$3,500
211379736	YORK	HMH72B341	XAHC48FBCN1	YPLC100C16MP13	25,400	\$3,556
211379481	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9E080B12MP12	25,600	\$3,584
211379475	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9E080B12MP12	25,600	\$3,584
211379463	YORK	HMH72B341	XAFC48FBCN1	TM9E080C16MP12	26,000	\$3,640
211379449	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9E080C16MP12	25,600	\$3,584
211379446	YORK	HMH72B341	XAHD48FBCN1	TM9E080C16MP12	25,600	\$3,584
211379409	YORK	HMH72B341	XAUC48FXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211379398	YORK	HMH72B341	XAFC48FXXN1+TXV	YP9C060B12MP13	25,600	\$3,584
211379389	YORK	HMH72B341	XAHC48FBCN1	YP9C060B12MP13	25,200	\$3,528
211379379	YORK	HMH72B341	XAHC48FXXN1+TXV	TP9C060B12MP13	25,200	\$3,528
211379367	YORK	HMH72B341	XAUC48FXXN1+TXV	TP9C080B12MP13	25,600	\$3,584
211379364	YORK	HMH72B341	XAFC48FBCN1	TP9C080B12MP13	25,600	\$3,584

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211379361	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9V080B12MP12	25,600	\$3,584
211379348	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9V080B12MP12	25,600	\$3,584
211379330	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9V080B12MP12	25,200	\$3,528
211379312	YORK	HMH72B341	XAFC48FBCN1	TM9V080C16MP12	25,400	\$3,556
211379300	YORK	HMH72B341	XAFD48FBCN1	YP9C080C16MP13	25,400	\$3,556
211379279	YORK	HMH72B341	XAHC48FBCN1	TP9C080C16MP13	24,800	\$3,472
211379276	YORK	HMH72B341	XAHC48FBCN1	TM9V080C16MP12	24,800	\$3,472
211379223	YORK	HMH72B341	XAFD48FBCN1	YP9C100C16MP13	25,400	\$3,556
211379209	YORK	HMH72B341	XAFD48FXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211379182	YORK	HMH72B341	XAHD48FBCN1	TM9V100C16MP12	24,800	\$3,472
211379179	YORK	HMH72B341	XAHD48FXXN1+TXV	YP9C100C16MP13	24,800	\$3,472
211379163	YORK	HMH72B341	XAFC48FBCN1	TP9C100C20MP13	25,800	\$3,612
211379128	YORK	HMH72B341	XAHC48FBCN1	TP9C100C20MP13	25,000	\$3,500
211379110	YORK	HMH72B341	XAHD48FBCN1	TP9C100C20MP13	25,200	\$3,528
211379101	YORK	HMH72B341	XAHD48FXXN1+TXV	TP9C100C20MP13	25,200	\$3,528
211379074	YORK	HMH72B341	XAHD48FBCN1	TP9C120D20MP13	24,800	\$3,472
211379060	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9Y060B12MP11	25,800	\$3,612
211379049	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9Y060B12MP11	25,400	\$3,556
211379045	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211379043	YORK	HMH72B341	XAFC48FBCN1	TM9Y080B12MP11	25,800	\$3,612
211379040	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211379039	YORK	HMH72B341	XAHC48FBCN1	TM9Y080B12MP11	25,400	\$3,556
211379009	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9Y100C16MP11	25,800	\$3,612
211379003	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9Y100C16MP11	25,800	\$3,612
211378994	YORK	HMH72B341	XAHC48FBCN1	TM9Y100C16MP11	25,200	\$3,528
211378867	YORK	HMH72B341	XAFB36DXXN1+TXV	TL9E060B12UH11	25,000	\$3,500
211378858	YORK	HMH72B341	XAFC36DXXN1+TXV	TL9E060B12UH11	25,600	\$3,584
211378829	YORK	HMH72B341	XAHC36DXXN1+TXV	TL9E080C16UH11	25,400	\$3,556
211377957	YORK	HMH72B341	XAFB36DXXN1+TXV	TM9E060A10MP12	25,400	\$3,556
211377951	YORK	HMH72B341	XAHB36DBCN1	TM9E060A10MP12	24,600	\$3,444
211377926	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211377911	YORK	HMH72B341	XAHC36DBCN1	TM9E060B12MP12	25,200	\$3,528
211377878	YORK	HMH72B341	XAHB36DBCN1	TM9E080B12MP12	25,000	\$3,500
211377813	YORK	HMH72B341	XAHB36DXXN1+TXV	TM9V040A10MP12	24,800	\$3,472
211377756	YORK	HMH72B341	XAFC36DBCN1	TP9C060B12MP13	25,600	\$3,584
211377749	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211377696	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9V060B12MP12	25,200	\$3,528
211377634	YORK	HMH72B341	XAFC36DXXN1+TXV	YP9C080B12MP13	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211377605	YORK	HMH72B341	XAHB36DXXN1+TXV	TP9C080B12MP13	25,200	\$3,528
211377580	YORK	HMH72B341	XAHC36DXXN1+TXV	TP9C080B12MP13	25,000	\$3,500
211377579	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9V080B12MP12	25,000	\$3,500
211377521	YORK	HMH72B341	XAFC36DBCN1	TP9C100C16MP13	25,400	\$3,556
211377509	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211377497	YORK	HMH72B341	XAHC36DBCN1	YP9C100C16MP13	25,000	\$3,500
211377491	YORK	HMH72B341	XAHC36DBCN1	TM9V100C16MP12	25,000	\$3,500
211377471	YORK	HMH72B341	XAFC36DBCN1	YP9C100C20MP13	26,000	\$3,640
211377426	YORK	HMH72B341	XAFC36DBCN1	TM9Y060B12MP11	25,600	\$3,584
211377423	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9Y060B12MP11	25,600	\$3,584
211377414	YORK	HMH72B341	XAHB36DXXN1+TXV	TM9Y060B12MP11	25,000	\$3,500
211377408	YORK	HMH72B341	XAHC36DBCN1	TM9Y060B12MP11	25,200	\$3,528
211377402	YORK	HMH72B341	XAUB30CXXN1+TXV	TM9Y080B12MP11	26,800	\$3,752
211377384	YORK	HMH72B341	XAHB36DBCN1	TM9Y080B12MP11	24,800	\$3,472
211377366	YORK	HMH72B341	XAFC36DBCN1	TM9Y080C16MP11	25,800	\$3,612
211377334	YORK	HMH72B341	XAHC36DBCN1	TM9Y100C20MP11	25,600	\$3,584
211239259	YORK	YZV36B21	JHVVC36DE2C2N1+CC		34,000	\$4,760
211207050	YORK	YZV48B21	XAMC48HE3N1+CC	YPLC100C16MP13	41,500	\$5,810
211207049	YORK	YZV48B21	XAMC48HE3N1+CC	YPLC080C16MP13	41,500	\$5,810
211207043	YORK	YZV48B21	XAMC48HE3N1+CC	YPLC120C20MP13	41,500	\$5,810
211207036	YORK	YZV48B21	XAMC48HE3N1+CC	YP9C080C16MP13	41,500	\$5,810
211207024	YORK	YZV36B21	XAMB36DE2N1+CC	YPLC080B12MP13	34,600	\$4,844
211207018	YORK	YZV36B21	XAMC36DE2N1+CC	YP9C080C16MP13	34,400	\$4,816
211207013	YORK	YZV36B21	XAMC36DE2N1+CC	TM9V100C16MP12	34,400	\$4,816
211207008	YORK	YZV24B21	XAMB24DE1N1+CC	TP9C060B12MP13	23,200	\$3,248
211207007	YORK	YZV24B21	XAMB24DE1N1+CC	TM9V060B12MP12	23,200	\$3,248
211379051	YORK	HMH72B341	XAHC48FBCN1	TM9Y060B12MP11	25,400	\$3,556
211377728	YORK	HMH72B341	XAHB36DXXN1+TXV	YP9C060B12MP13	25,000	\$3,500
211377545	YORK	HMH72B341	XAHC36DBCN1	TM9V080C16MP12	25,000	\$3,500
211377399	YORK	HMH72B341	XAFB30CXXN1+TXV	TM9Y080B12MP11	26,800	\$3,752
211207032	YORK	YZV48B21	XAMC48HE3N1+CC	TP9C100C16MP13	41,500	\$5,810
211207014	YORK	YZV36B21	XAMC36DE2N1+CC	TP9C100C16MP13	34,400	\$4,816
211380219	YORK	HMH72B341	XAUC48FXXN1+JMET12CS2 N1+TXV		25,400	\$3,556
211380208	YORK	HMH72B341	XAHC48FXXN1+JMET12CS2 N1+TXV		24,800	\$3,472
211380140	YORK	HMH72B341	XAUC48FXXN1+TXV	TL9E080C16UH11	25,800	\$3,612
211380134	YORK	HMH72B341	XAFC48FXXN1+TXV	TL9E080C16UH11	25,800	\$3,612

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211380128	YORK	HMH72B341	XAFD48FXXN1+TXV	TL9E080C16UH11	25,600	\$3,584
211380108	YORK	HMH72B341	XAFC48FXXN1+TXV	TL9E100C20UH11	25,400	\$3,556
211380094	YORK	HMH72B341	XAHD48FBCN1	TL9E100C20UH11	25,000	\$3,500
211379478	YORK	HMH72B341	XAFC48FBCN1	TM9E080B12MP12	25,600	\$3,584
211379440	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9E100C16MP12	25,400	\$3,556
211379438	YORK	HMH72B341	XAFC48FBCN1	TM9E100C16MP12	25,400	\$3,556
211379423	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9E100C16MP12	24,800	\$3,472
211379421	YORK	HMH72B341	XAHD48FBCN1	TM9E100C16MP12	24,800	\$3,472
211379418	YORK	HMH72B341	XAHD48FXXN1+TXV	TM9E100C16MP12	24,800	\$3,472
211379393	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9V060B12MP12	25,600	\$3,584
211379370	YORK	HMH72B341	XAFC48FBCN1	YP9C080B12MP13	25,600	\$3,584
211379354	YORK	HMH72B341	XAFC48FXXN1+TXV	YP9C080B12MP13	25,600	\$3,584
211379351	YORK	HMH72B341	XAFC48FXXN1+TXV	TP9C080B12MP13	25,600	\$3,584
211379345	YORK	HMH72B341	XAHC48FBCN1	YP9C080B12MP13	25,200	\$3,528
211379333	YORK	HMH72B341	XAHC48FXXN1+TXV	TP9C080B12MP13	25,200	\$3,528
211379306	YORK	HMH72B341	XAFC48FXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211379285	YORK	HMH72B341	XAFD48FXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211379282	YORK	HMH72B341	XAHC48FBCN1	YP9C080C16MP13	24,800	\$3,472
211379258	YORK	HMH72B341	XAHD48FBCN1	TM9V080C16MP12	25,000	\$3,500
211379246	YORK	HMH72B341	XAUC48FXXN1+TXV	YP9C100C16MP13	25,400	\$3,556
211379240	YORK	HMH72B341	XAUC48FXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211379225	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211379212	YORK	HMH72B341	XAFD48FXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211379194	YORK	HMH72B341	XAHC48FXXN1+TXV	TP9C100C16MP13	24,800	\$3,472
211379191	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9V100C16MP12	24,800	\$3,472
211379170	YORK	HMH72B341	XAUC48FXXN1+TXV	YP9C100C20MP13	25,800	\$3,612
211379164	YORK	HMH72B341	XAUC48FXXN1+TXV	TP9C100C20MP13	25,800	\$3,612
211379145	YORK	HMH72B341	XAFD48FBCN1	YP9C100C20MP13	25,600	\$3,584
211379142	YORK	HMH72B341	XAFD48FBCN1	TP9C100C20MP13	25,600	\$3,584
211379131	YORK	HMH72B341	XAHC48FBCN1	YP9C100C20MP13	25,000	\$3,500
211379125	YORK	HMH72B341	XAHC48FBCN1	TM9V100C20MP12	25,000	\$3,500
211379119	YORK	HMH72B341	XAHC48FXXN1+TXV	TP9C100C20MP13	25,000	\$3,500
211379116	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9V100C20MP12	25,000	\$3,500
211379104	YORK	HMH72B341	XAHD48FXXN1+TXV	YP9C100C20MP13	25,200	\$3,528
211379092	YORK	HMH72B341	XAFD48FBCN1	TP9C120D20MP13	25,400	\$3,556
211379089	YORK	HMH72B341	XAFD48FBCN1	TM9V120D20MP12	25,400	\$3,556
211379080	YORK	HMH72B341	XAFD48FXXN1+TXV	TM9V120D20MP12	25,400	\$3,556
211379071	YORK	HMH72B341	XAHD48FBCN1	TM9V120D20MP12	24,800	\$3,472

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211379064	YORK	HMH72B341	XAHD48FXXN1+TXV	TM9V120D20MP12	24,800	\$3,472
211379054	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9Y060B12MP11	25,800	\$3,612
211379030	YORK	HMH72B341	XAFC48FBCN1	TM9Y080C16MP11	25,800	\$3,612
211379018	YORK	HMH72B341	XAHC48FBCN1	TM9Y080C16MP11	25,200	\$3,528
211378987	YORK	HMH72B341	XAHD48FXXN1+TXV	TM9Y100C16MP11	25,200	\$3,528
211378978	YORK	HMH72B341	XAHD48FBCN1	TM9Y120D20MP11	25,000	\$3,500
211378939	YORK	HMH72B341	JHETB36DBCS2N1		25,400	\$3,556
211378870	YORK	HMH72B341	XAFB36DBCN1	TL9E060B12UH11	25,000	\$3,500
211378850	YORK	HMH72B341	XAHC36DBCN1	TL9E060B12UH11	24,400	\$3,416
211378838	YORK	HMH72B341	XAFC36DXXN1+TXV	TL9E080C16UH11	25,800	\$3,612
211378823	YORK	HMH72B341	XAFC36DBCN1	TL9E100C20UH11	26,200	\$3,668
211377960	YORK	HMH72B341	XAFB36DBCN1	TM9E060A10MP12	25,400	\$3,556
211377939	YORK	HMH72B341	XAUB36DXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211377936	YORK	HMH72B341	XAFB36DBCN1	TM9E060B12MP12	25,800	\$3,612
211377933	YORK	HMH72B341	XAFB36DXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211377920	YORK	HMH72B341	XAHB36DBCN1	TM9E060B12MP12	25,200	\$3,528
211377897	YORK	HMH72B341	XAFB36DBCN1	TM9E080B12MP12	25,400	\$3,556
211377894	YORK	HMH72B341	XAFB36DXXN1+TXV	TM9E080B12MP12	25,400	\$3,556
211377875	YORK	HMH72B341	XAHB36DXXN1+TXV	TM9E080B12MP12	25,000	\$3,500
211377870	YORK	HMH72B341	XAHC36DBCN1	TM9E080B12MP12	25,000	\$3,500
211377859	YORK	HMH72B341	XAHC36DBCN1	TM9E080C16MP12	25,600	\$3,584
211377855	YORK	HMH72B341	XAFC36DBCN1	TM9E100C16MP12	25,200	\$3,528
211377846	YORK	HMH72B341	XAHC36DBCN1	TM9E100C16MP12	24,800	\$3,472
211377828	YORK	HMH72B341	XAUB36DXXN1+TXV	TM9V040A10MP12	25,200	\$3,528
211377757	YORK	HMH72B341	XAFC36DBCN1	YP9C060B12MP13	25,600	\$3,584
211377752	YORK	HMH72B341	XAFC36DXXN1+TXV	TP9C060B12MP13	25,600	\$3,584
211377731	YORK	HMH72B341	XAHB36DBCN1	TM9V060B12MP12	25,000	\$3,500
211377710	YORK	HMH72B341	XAHC36DBCN1	YP9C060B12MP13	25,200	\$3,528
211377643	YORK	HMH72B341	XAFC36DBCN1	YP9C080B12MP13	25,800	\$3,612
211377616	YORK	HMH72B341	XAHB36DBCN1	YP9C080B12MP13	25,200	\$3,528
211377608	YORK	HMH72B341	XAHB36DXXN1+TXV	YP9C080B12MP13	25,200	\$3,528
211377602	YORK	HMH72B341	XAHB36DXXN1+TXV	TM9V080B12MP12	25,200	\$3,528
211377590	YORK	HMH72B341	XAHC36DBCN1	YP9C080B12MP13	25,000	\$3,500
211377550	YORK	HMH72B341	XAHC36DBCN1	YP9C080C16MP13	25,000	\$3,500
211377548	YORK	HMH72B341	XAHC36DBCN1	TP9C080C16MP13	25,000	\$3,500
211377542	YORK	HMH72B341	XAHC36DXXN1+TXV	YP9C080C16MP13	25,000	\$3,500
211377512	YORK	HMH72B341	XAFC36DXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211377494	YORK	HMH72B341	XAHC36DBCN1	TP9C100C16MP13	25,000	\$3,500

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211377485	YORK	HMH72B341	XAHC36DXXN1+TXV	TP9C100C16MP13	25,000	\$3,500
211377465	YORK	HMH72B341	XAFC36DBCN1	TM9V100C20MP12	26,000	\$3,640
211377462	YORK	HMH72B341	XAFC36DXXN1+TXV	YP9C100C20MP13	26,000	\$3,640
211377444	YORK	HMH72B341	XAUB30CXXN1+TXV	TM9Y060B12MP11	26,600	\$3,724
211377429	YORK	HMH72B341	XAFC30CXXN1+TXV	TM9Y060B12MP11	26,600	\$3,724
211377417	YORK	HMH72B341	XAHB36DBCN1	TM9Y060B12MP11	25,000	\$3,500
211377389	YORK	HMH72B341	XAFC30CXXN1+TXV	TM9Y080B12MP11	26,800	\$3,752
211377387	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9Y080B12MP11	25,800	\$3,612
211377363	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9Y080C16MP11	25,800	\$3,612
211377357	YORK	HMH72B341	XAHC36DBCN1	TM9Y080C16MP11	25,400	\$3,556
211377331	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9Y100C20MP11	25,600	\$3,584
211207035	YORK	YZV48B21	XAMC48HE3N1+CC	TP9C080C16MP13	41,500	\$5,810
211207033	YORK	YZV48B21	XAMC48HE3N1+CC	YP9C100C16MP13	41,500	\$5,810
211207030	YORK	YZV48B21	XAMC48HE3N1+CC	YP9C100C20MP13	41,500	\$5,810
211207027	YORK	YZV60B21	XAMC60HE4N1+CC	YP9C100C20MP13	47,000	\$6,580
211207026	YORK	YZV60B21	XAMC60HE4N1+CC	TP9C100C20MP13	47,000	\$6,580
211010173	YORK	YZV36B21	JHVVB36DE2C2N1+CC		35,800	\$5,012
211380224	YORK	HMH72B341	JHETC42FBCS2N1		25,200	\$3,528
211380143	YORK	HMH72B341	XAHC48FXXN1+TXV	TL9E060B12UH11	25,200	\$3,528
211380131	YORK	HMH72B341	XAFD48FBCN1	TL9E080C16UH11	25,600	\$3,584
211380119	YORK	HMH72B341	XAHD48FBCN1	TL9E080C16UH11	25,200	\$3,528
211379496	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9E060B12MP12	25,800	\$3,612
211379487	YORK	HMH72B341	XAHC48FBCN1	TM9E060B12MP12	25,200	\$3,528
211379472	YORK	HMH72B341	XAHC48FBCN1	TM9E080B12MP12	25,000	\$3,500
211379469	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9E080B12MP12	25,000	\$3,500
211379435	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9E100C16MP12	25,400	\$3,556
211379432	YORK	HMH72B341	XAFD48FBCN1	TM9E100C16MP12	25,400	\$3,556
211379415	YORK	HMH72B341	XAUC48FXXN1+TXV	YP9C060B12MP13	25,600	\$3,584
211379406	YORK	HMH72B341	XAFC48FBCN1	TP9C060B12MP13	25,600	\$3,584
211379401	YORK	HMH72B341	XAFC48FBCN1	TM9V060B12MP12	25,600	\$3,584
211379386	YORK	HMH72B341	XAHC48FBCN1	TP9C060B12MP13	25,200	\$3,528
211379376	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9V060B12MP12	25,200	\$3,528
211379373	YORK	HMH72B341	XAUC48FXXN1+TXV	YP9C080B12MP13	25,600	\$3,584
211379357	YORK	HMH72B341	XAFC48FBCN1	TM9V080B12MP12	25,600	\$3,584
211379342	YORK	HMH72B341	XAHC48FBCN1	TP9C080B12MP13	25,200	\$3,528
211379336	YORK	HMH72B341	XAHC48FXXN1+TXV	YP9C080B12MP13	25,200	\$3,528
211379327	YORK	HMH72B341	XAUC48FXXN1+TXV	YP9C080C16MP13	25,400	\$3,556
211379321	YORK	HMH72B341	XAUC48FXXN1+TXV	TP9C080C16MP13	25,400	\$3,556

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211379318	YORK	HMH72B341	XAFC48FBCN1	TP9C080C16MP13	25,400	\$3,556
211379288	YORK	HMH72B341	XAFD48FXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211379270	YORK	HMH72B341	XAHC48FXXN1+TXV	TP9C080C16MP13	24,800	\$3,472
211379264	YORK	HMH72B341	XAHD48FBCN1	YP9C080C16MP13	25,000	\$3,500
211379261	YORK	HMH72B341	XAHD48FBCN1	TP9C080C16MP13	25,000	\$3,500
211379252	YORK	HMH72B341	XAHD48FXXN1+TXV	TP9C080C16MP13	25,000	\$3,500
211379249	YORK	HMH72B341	XAHD48FXXN1+TXV	TM9V080C16MP12	25,000	\$3,500
211379236	YORK	HMH72B341	XAUC48FXXN1+TXV	TM9V100C16MP12	25,400	\$3,556
211379226	YORK	HMH72B341	XAFC48FXXN1+TXV	TP9C100C16MP13	25,400	\$3,556
211379217	YORK	HMH72B341	XAFD48FBCN1	TM9V100C16MP12	25,400	\$3,556
211379214	YORK	HMH72B341	XAFD48FXXN1+TXV	YP9C100C16MP13	25,400	\$3,556
211379206	YORK	HMH72B341	XAHC48FBCN1	YP9C100C16MP13	24,800	\$3,472
211379200	YORK	HMH72B341	XAHC48FBCN1	TM9V100C16MP12	24,800	\$3,472
211379176	YORK	HMH72B341	XAHD48FXXN1+TXV	TP9C100C16MP13	24,800	\$3,472
211379154	YORK	HMH72B341	XAFC48FXXN1+TXV	YP9C100C20MP13	25,800	\$3,612
211379148	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9V100C20MP12	25,800	\$3,612
211379138	YORK	HMH72B341	XAFD48FXXN1+TXV	YP9C100C20MP13	25,600	\$3,584
211379134	YORK	HMH72B341	XAFD48FXXN1+TXV	TM9V100C20MP12	25,600	\$3,584
211379107	YORK	HMH72B341	XAHD48FBCN1	TM9V100C20MP12	25,200	\$3,528
211379057	YORK	HMH72B341	XAFC48FBCN1	TM9Y060B12MP11	25,800	\$3,612
211379036	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9Y080B12MP11	25,400	\$3,556
211379027	YORK	HMH72B341	XAFC48FXXN1+TXV	TM9Y080C16MP11	25,800	\$3,612
211379021	YORK	HMH72B341	XAFD48FXXN1+TXV	TM9Y080C16MP11	25,400	\$3,556
211379015	YORK	HMH72B341	XAHC48FXXN1+TXV	TM9Y080C16MP11	25,200	\$3,528
211379012	YORK	HMH72B341	XAHD48FXXN1+TXV	TM9Y080C16MP11	25,000	\$3,500
211379006	YORK	HMH72B341	XAFC48FBCN1	TM9Y100C16MP11	25,800	\$3,612
211379000	YORK	HMH72B341	XAFD48FBCN1	TM9Y100C16MP11	25,400	\$3,556
211378997	YORK	HMH72B341	XAFD48FXXN1+TXV	TM9Y100C16MP11	25,400	\$3,556
211378984	YORK	HMH72B341	XAFD48FBCN1	TM9Y120D20MP11	25,400	\$3,556
211378935	YORK	HMH72B341	JHVTB36DBCC2N1		25,200	\$3,528
211378873	YORK	HMH72B341	XAUB36DXXN1+TXV	TL9E060B12UH11	25,000	\$3,500
211378816	YORK	HMH72B341	XAHC36DBCN1	TL9E100C20UH11	25,600	\$3,584
211378813	YORK	HMH72B341	XAHC36DXXN1+TXV	TL9E100C20UH11	25,600	\$3,584
211377963	YORK	HMH72B341	XAUB36DXXN1+TXV	TM9E060A10MP12	25,400	\$3,556
211377928	YORK	HMH72B341	XAFC36DBCN1	TM9E060B12MP12	25,800	\$3,612
211377908	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9E060B12MP12	25,200	\$3,528
211377867	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9E080B12MP12	25,000	\$3,500
211377861	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9E080C16MP12	25,200	\$3,528

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211377843	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9E100C16MP12	24,800	\$3,472
211377837	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9E100C20MP12	25,000	\$3,500
211377825	YORK	HMH72B341	XAFB36DBCN1	TM9V040A10MP12	25,200	\$3,528
211377822	YORK	HMH72B341	XAFB36DXXN1+TXV	TM9V040A10MP12	25,200	\$3,528
211377777	YORK	HMH72B341	XAFB36DBCN1	TM9V060B12MP12	25,400	\$3,556
211377755	YORK	HMH72B341	XAFC36DBCN1	TM9V060B12MP12	25,600	\$3,584
211377737	YORK	HMH72B341	XAHB36DBCN1	YP9C060B12MP13	25,000	\$3,500
211377725	YORK	HMH72B341	XAHB36DXXN1+TXV	TP9C060B12MP13	25,000	\$3,500
211377701	YORK	HMH72B341	XAHC36DXXN1+TXV	YP9C060B12MP13	25,200	\$3,528
211377699	YORK	HMH72B341	XAHC36DXXN1+TXV	TP9C060B12MP13	25,200	\$3,528
211377640	YORK	HMH72B341	XAFC36DBCN1	TP9C080B12MP13	25,800	\$3,612
211377637	YORK	HMH72B341	XAFC36DBCN1	TM9V080B12MP12	25,800	\$3,612
211377628	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9V080B12MP12	25,800	\$3,612
211377614	YORK	HMH72B341	XAHB36DBCN1	TP9C080B12MP13	25,200	\$3,528
211377611	YORK	HMH72B341	XAHB36DBCN1	TM9V080B12MP12	25,200	\$3,528
211377575	YORK	HMH72B341	XAFC36DBCN1	YP9C080C16MP13	25,400	\$3,556
211377574	YORK	HMH72B341	XAFC36DBCN1	TP9C080C16MP13	25,400	\$3,556
211377572	YORK	HMH72B341	XAFC36DBCN1	TM9V080C16MP12	25,400	\$3,556
211377568	YORK	HMH72B341	XAFC36DXXN1+TXV	YP9C080C16MP13	25,400	\$3,556
211377565	YORK	HMH72B341	XAFC36DXXN1+TXV	TP9C080C16MP13	25,400	\$3,556
211377562	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9V080C16MP12	25,400	\$3,556
211377539	YORK	HMH72B341	XAHC36DXXN1+TXV	TP9C080C16MP13	25,000	\$3,500
211377536	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9V080C16MP12	25,000	\$3,500
211377482	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9V100C16MP12	25,000	\$3,500
211377388	YORK	HMH72B341	XAFC36DBCN1	TM9Y080B12MP11	25,800	\$3,612
211377372	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9Y080B12MP11	25,400	\$3,556
211377355	YORK	HMH72B341	XAHC36DXXN1+TXV	TM9Y080C16MP11	25,400	\$3,556
211377349	YORK	HMH72B341	XAFC36DBCN1	TM9Y100C16MP11	25,800	\$3,612
211377346	YORK	HMH72B341	XAFC36DXXN1+TXV	TM9Y100C16MP11	25,800	\$3,612
211207031	YORK	YZV48B21	XAMC48HE3N1+CC	TM9V100C16MP12	41,500	\$5,810
211207029	YORK	YZV48B21	XAMC48HE3N1+CC	TP9C100C20MP13	41,500	\$5,810
211207028	YORK	YZV48B21	XAMC48HE3N1+CC	TM9V100C20MP12	41,500	\$5,810
211207020	YORK	YZV36B21	XAMB36DE2N1+CC	TP9C080B12MP13	34,600	\$4,844
211207019	YORK	YZV36B21	XAMB36DE2N1+CC	TM9V080B12MP12	34,600	\$4,844
211207016	YORK	YZV36B21	XAMC36DE2N1+CC	TM9V080C16MP12	34,400	\$4,816
211207015	YORK	YZV36B21	XAMC36DE2N1+CC	YP9C100C16MP13	34,400	\$4,816
211207012	YORK	YZV24B21	XAMB24DE1N1+CC	YPLC080B12MP13	23,000	\$3,220
211010174	YORK	YZV60B21	JHVVD60HE4C2N1+CC		46,500	\$6,510

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
211377435	YORK	HMH72B341	XAFB36DBCN1	TM9Y060B12MP11	25,200	\$3,528
10309007	YORK	YZV36B21	AVV38CE221		33,400	\$4,676
214609037	YORK	HH824E2S11	CTM30B5ACS1	Y91E080B12SMPS1	18,400	\$2,576
214396142	YORK	HH836E2S11	CTF48C5CFS1	YPLC100C16MP13	26,000	\$3,640
214396141	YORK	HH836E2S11	CTF48C5CFS1	YPLC080C16MP13	26,000	\$3,640
214395996	YORK	HH860E2S11	CTF60D5CJS1	YP9C120D20MP13	38,000	\$5,320
214395995	YORK	HH860E2S11	CTF60D5CJS1	TP9C120D20MP13	38,000	\$5,320
214395994	YORK	HH860E2S11	CTF60D5CJS1	TM9V120D20MP12	38,000	\$5,320
214395993	YORK	HH860E2S11	CTM60D5CJS1+JMC20D2SN1		37,000	\$5,180
214395990	YORK	HH860E2S11	CTM60C5CHS1	YP9C100C20MP13	37,000	\$5,180
214395989	YORK	HH860E2S11	CTM60C5CHS1	TP9C100C20MP13	37,000	\$5,180
214395988	YORK	HH860E2S11	CTM60C5CHS1	TM9V100C20MP12	37,000	\$5,180
214396204	YORK	HH836E2S11	CTF36C5CDS1	TM9Y100C16MP11	27,400	\$3,836
214395810	YORK	HH836E2S11	CTM36B5CDS1	YPLC080B12MP13	26,800	\$3,752
214395688	YORK	HH860E2S11	CTF60D5CJS1	TM9E120D20MP12	37,400	\$5,236
214421497	YORK	HH860E2S11	CTF60D5CJS1+JMT20DC2N1		37,000	\$5,180
214395652	YORK	HH860E2S11	CTM60C5CGS1	TM9E080C20MP12	35,800	\$5,012
213296781	YORK	HMH72B341	XAFB36DBCN1+JMET12BS2N1		25,200	\$3,528
213296644	YORK	HMH72B341	XAFB36DBCN1+JMT12BC2N1		25,000	\$3,500
213296604	YORK	HMH72B341	XAHC36DBCN1+JMET12CS2N1		24,600	\$3,444
213296729	YORK	HMH72B341	XAHB36DBCN1+JMT12BC2N1		24,400	\$3,416
213296731	YORK	HMH72B341	XAFC36DBCN1+JMET12CS2N1		25,400	\$3,556
214395958	YORK	HH860E2S11	CTM60D5CGS1	YP9C120D20MP13	32,400	\$4,536
214395957	YORK	HH860E2S11	CTM60D5CGS1	TP9C120D20MP13	32,400	\$4,536
214395956	YORK	HH860E2S11	CTM60D5CGS1	TM9V120D20MP12	32,400	\$4,536
214396038	YORK	HH836E2S11	CTM48C5CFS1	TM9E100C20MP12	26,400	\$3,696
214396000	YORK	HH836E2S11	CTM36C5CDS1	TM9Y100C16MP11	27,400	\$3,836
214396091	YORK	HH860E2S11	CTF60D5CJS1+JME18D2SN1		37,200	\$5,208
214396089	YORK	HH860E2S11	JHC60D5CH2SS1		36,200	\$5,068
214396179	YORK	HH824E2S11	CTF30B5ACS1	YPLC080B12MP13	18,200	\$2,548
214396174	YORK	HH824E2S11	CTM30B5ACS1	TM9Y060B12MP11	18,700	\$2,618

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
213296728	YORK	HMH72B341	XAHB36DXXN1+JMTV12BC2 N1+TXV		24,400	\$3,416
213296694	YORK	HMH72B341	XAHB30CXXN1+JMTV12BC2 N1+TXV		25,800	\$3,612
213296782	YORK	HMH72B341	XAUB36DXXN1+JMET12BS2 N1+TXV		25,200	\$3,528
213296780	YORK	HMH72B341	XAFB36DXXN1+JMET12BS2 N1+TXV		25,200	\$3,528
213296646	YORK	HMH72B341	XAHB30CXXN1+JMET12BS2 N1+TXV		25,600	\$3,584
213296695	YORK	HMH72B341	XAFC30CXXN1+JMET12CS2 N1+TXV		26,400	\$3,696
213296603	YORK	HMH72B341	XAHC36DXXN1+JMET12CS2 N1+TXV		24,600	\$3,444
213296730	YORK	HMH72B341	XAFC36DXXN1+JMET12CS2 N1+TXV		25,400	\$3,556
213296602	YORK	HMH72B341	XAHC30CXXN1+JMET12CS2 N1+TXV		26,000	\$3,640
213296606	YORK	HMH72B341	XAUB30CXXN1+JMET12BS2 N1+TXV		26,000	\$3,640
213296605	YORK	HMH72B341	XAFB30CXXN1+JMET12BS2 N1+TXV		26,000	\$3,640
213348171	YORK	HMH72B341	JHVTB24CXXC2N1+TXV		25,800	\$3,612
213348172	YORK	HMH72B341	JHETB30DXXS2N1+TXV		24,800	\$3,472
213348173	YORK	HMH72B341	JHETB24CXXS2N1+TXV		25,200	\$3,528
213296645	YORK	HMH72B341	XAUB36DXXN1+JMTV12BC2 N1+TXV		25,000	\$3,500
213296643	YORK	HMH72B341	XAFB36DXXN1+JMTV12BC2 N1+TXV		25,000	\$3,500
213296779	YORK	HMH72B341	XAUB30CXXN1+JMTV12BC2 N1+TXV		26,600	\$3,724
213296778	YORK	HMH72B341	XAFB30CXXN1+JMTV12BC2 N1+TXV		26,600	\$3,724
211378941	YORK	HMH72B341	JHETB30DBAS2N1		24,800	\$3,472
10309006	YORK	YZV24B21	CM25BE1A1+MVC12BN21		22,400	\$3,136
10309023	YORK	YZV48B21	AVV50DE321		44,000	\$6,160
207827123	ZENAIR TECHNOLOGIES	ZEN-WM12HP23S/O	ZEN-WM12HP23S/I		10,300	\$1,442
207911500	ZENAIR TECHNOLOGIES	ZEN-PC48HP20S/O	ZEN-PC48HP20S/I		36,000	\$5,040
215414826	ZEPHYR	ZE-24CB22O	ZE-24CB22I		21,000	\$2,940

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215414825	ZEPHYR	ZE-18CB22O	ZE-18CB22I		14,800	\$2,072
206346128	ZEPHYR	ZE-18M222SCO	Heat pump without ducts		12,700	\$1,778
206346129	ZEPHYR	ZE-18M222SCO	Combination heat pumps with or without ducts		12,700	\$1,778
206346130	ZEPHYR	ZE-24M322SCO	Heat pump without ducts		15,000	\$2,100
206346131	ZEPHYR	ZE-24M322SCO	Combination heat pumps with or without ducts		14,800	\$2,072
206347270	ZEPHYR	ZE-36M422SCO	Heat pump without ducts		22,400	\$3,136
206347271	ZEPHYR	ZE-36M422SCO	Combination heat pumps with or without ducts		22,600	\$3,164
206346134	ZEPHYR	ZE-42M522SCO	Heat pump without ducts		27,000	\$3,780
206346135	ZEPHYR	ZE-42M522SCO	Combination heat pumps with or without ducts		27,600	\$3,864
207036640	ZEPHYR	ZE-24HPB	AH-24B		16,000	\$2,240
207036646	ZEPHYR	ZE-48HPB	AH-48B		31,000	\$4,340
207036642	ZEPHYR	ZE-36HPB	AH-36B		24,000	\$3,360
216684169	ZEPHYR	ZE-542M525	Combination heat pumps with or without ducts		27,800	\$3,892
216684166	ZEPHYR	ZE-527M325	Combination heat pumps with or without ducts		18,000	\$2,520
216684163	ZEPHYR	ZE-518M225	Combination heat pumps with or without ducts		11,700	\$1,638
216684172	ZEPHYR	ZE-536M425	Combination heat pumps with or without ducts		21,800	\$3,052
216684171	ZEPHYR	ZE-536M425	Heat pump without ducts		22,600	\$3,164
216684170	ZEPHYR	ZE-536M425	Heat pump with ducts		21,000	\$2,940
216684168	ZEPHYR	ZE-542M525	Heat pump without ducts		28,200	\$3,948
216684167	ZEPHYR	ZE-542M525	Heat pump with ducts		27,400	\$3,836
216684165	ZEPHYR	ZE-527M325	Heat pump with ducts		18,200	\$2,548
216684164	ZEPHYR	ZE-527M325	Heat pump without ducts		17,600	\$2,464
216684162	ZEPHYR	ZE-518M225	Heat pump with ducts		11,900	\$1,666
216684161	ZEPHYR	ZE-518M225	Heat pump without ducts		11,500	\$1,610
215414834	ZEPHYR	ZE-12DB25O	ZE-12DB25I		9,300	\$1,302
215414832	ZEPHYR	ZE-24CB25O	ZE-24CB25I		22,000	\$3,080
215414831	ZEPHYR	ZE-18CB25O	ZE-18CB25I		18,000	\$2,520
215414830	ZEPHYR	ZE-12CB25O	ZE-12CB25I		10,800	\$1,512
215381148	ZEPHYR	ZE-660HPA	AH-660A		37,000	\$5,180
215381147	ZEPHYR	ZE-648HPA	AH-648A		36,600	\$5,124
215381146	ZEPHYR	ZE-636HPA	AH-636A		32,000	\$4,480

AHRI No.	Brand	Model No. of outdoor unit	Model No. of indoor unit	Model No. of furnace (if applicable)	Heating output (-8 °C)	Financial assistance
215381145	ZEPHYR	ZE-624HPA	AH-624A		20,400	\$2,856
205306852	ZEPHYR	ZE-36HPA	AH-36		25,000	\$3,500
217138410	ZERO	Z4SOV-48HDMB-US	Heat pump with ducts		37,000	\$5,180
216097675	ZERO	ZMSB-18HV-USHHCR2-O	ZMSB-18HV-USHHCR2-I		14,400	\$2,016
216097674	ZERO	ZMSB-12HV-USHHCR2-O	ZMSB-12HV-USHHCR2-I		10,000	\$1,400
213732670	ZERO	Z5SOV-48HDM-US	Combination heat pumps with or without ducts		37,400	\$5,236
214421475	ZERO	ZMSB-12HV-USHHC-O	ZMSB-12HV-USHHC-I		10,300	\$1,442
214232448	ZERO	ZMSB-12HV-USHHC	ZMSB-12HV-USHHC		10,300	\$1,442
214232449	ZERO	ZMSB-18HV-USHHC	ZMSB-18HV-USHHC		11,100	\$1,554
214421476	ZERO	ZMSB-18HV-USHHC-O	ZMSB-18HV-USHHC-I		11,100	\$1,554
214421477	ZERO	ZMSB-24HV-USHHC-O	ZMSB-24HV-USHHC-I		18,900	\$2,646
214232450	ZERO	ZMSB-24HV-USHHC	ZMSB-24HV-USHHC		18,900	\$2,646
213732668	ZERO	Z5SOV-48HDM-US	Heat pump without ducts		39,000	\$5,460
213732669	ZERO	Z5SOV-48HDM-US	Heat pump with ducts		36,000	\$5,040
216980493	ZERO	ZSOVA-48HDMB-US	ZAVA-48HDMB-US		32,400	\$4,536
216980490	ZERO	ZSOVA-24HDMB-US	ZAVA-24HDMB-US		20,000	\$2,800
216980500	ZERO	ZSOVA-60HDMB-USHH	ZAVA-60HDMB-US		45,000	\$6,300
216980499	ZERO	ZSOVA-48HDMB-USHH	ZAVA-48HDMB-US		37,000	\$5,180
216980498	ZERO	ZSOVA-36HDMB-USHH	ZAVA-36HDMB-US		31,800	\$4,452
216980497	ZERO	ZSOVA-30HDMB-USHH	ZAVA-30HDMB-US		23,800	\$3,332
216980496	ZERO	ZSOVA-24HDMB-USHH	ZAVA-24HDMB-US		20,000	\$2,800
216980495	ZERO	ZSOVA-18HDMB-USHH	ZAVA-18HDMB-US		15,000	\$2,100
216097677	ZERO	ZMSB-33HV-USHHCR2-O	ZMSB-33HV-USHHCR2-I		29,600	\$4,144
216097676	ZERO	ZMSB-24HV-USHHCR2-O	ZMSB-24HV-USHHCR2-I		21,600	\$3,024
212928566	ZERO	ZSOV-48HDM-US	ZEV-48HDM-US		29,000	\$4,060